
Title List of Documents Made Publicly Available

October 1-31, 1983

Office of Administration
U.S. Nuclear Regulatory Commission



Available from

NRC/GPO Sales Program

Superintendent of Documents
Government Printing Office
Washington, D. C. 20402

A year's subscription consists of 12 issues for
this publication.

Single copies of this publication
are available from National Technical
Information Service, Springfield, VA 22161

Microfiche of single copies are
available from NRC/GPO Sales Program
Washington, D. C. 20555

Title List of Documents Made Publicly Available

October 1-31, 1983

Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555



CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket Items by Facility Name	xv
Docketed Items	1
Low Level Radwaste Disposal Sites — Docket 27	1
Domestic Licensing of Source Material — Docket 40	1
Domestic Licensing of Production and Utilization Facilities — Docket 50	6
Domestic Licensing of Special Nuclear Material — Docket 70	379
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71	388
Licensing of Independent Spent Fuel Storage — Docket 72	394
Nondocketed Items	395
10 CFR — Commission Meeting Records	395
ACRS — Advisory Committee on Reactor Safeguards	396
ADVCM — NRC Advisory Committees	396
COMMISSION — NRC Commissioners	396
CONTRACT — NRC Contracts and Modifications	398
FOIA — Freedom of Information Act Requests and Releases	407
GEN TECH IS — Generic Technical Issues	442
I&E — Inspection and Enforcement	444
MISC — Public Document Room Miscellaneous	447
NUREG — NUREG Reports and Related Correspondence	448
ORG — Correspondence with Other Organizations	464
PR — Proposed Rule	465
PRM — Petition for Rulemaking	466
PROJ — Projects - Predocket Licensing	466
PT21 — Noncompliance Reports and Related Correspondence	467
QA999 — Quality Assurance Inspections	469
REGGD — Regulatory Guides	474
RES — Research and Technical Assistance Reports	474
REVIEW GROUP — NRC Research Review Groups	474
SECY — Position Papers Before the Commission	474
STATE PROG — State Programs	476
TOPREP — Vendor Reports and Related Correspondence	476
WASH—Regulatory Publications—Pre-NUREG Series	480
WASTE MGT — Nuclear Waste Management	481
XPORTLIC — Export and Import Licenses	482
Personal Author Index	489
Corporate Source Index	523
Report Number Index	553
Cross Reference of Enclosures to Principal Documents	555
Appendix A — Definitions of Docket 50 Categories	A-1
Appendix B — Definitions of Nondocketed Categories	B-1

PREFACE

The *Title List of Documents Made Publicly Available* is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, *docketed* does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences. LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence

- W. Decommissioning stage documents and correspondence
- X. Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

① P. Operating license stage documents & correspondence

② 8203090028 ③ Responds to 820201 ltr requesting documents re environ qualification of electrical equipment. All nonproprietary repts will be provided to Franklin Research Ctr by 820408. Proprietary repts will be provided to NRC by 820510.
 ④ MILLS, L.M. ⑤ Tennessee Valley Authority. ⑥ 82/03/04. ⑦ VASSALLO, D.B.
 Operating Reactors Branch 2. ⑧ 1p. 1216:254. 24XFiche: 50-259, 82/03/04, 8203090028.
 ⑨ ⑩ ⑪ ⑫

1. NRC/PDR Document category (see Appendix A).
2. NRC Accession Number (year, month, day, and sequence number of item).
3. Description of information contained in the document.
4. Personal author(s). An asterisk in this position indicates that there is no personal author.
5. Corporate, agency or nonindividual source.
6. Date of document described.
7. Recipient of document and NRC or corporate affiliation.
8. Pages in this document.
9. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
10. This three-digit portion of this entry is the number of the frame on which this document starts.
11. The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
12. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS


The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are:

- 10CFR — Commission Meeting Records
- ACRS — Advisory Committee on Reactor Safeguards
- COMMISSION — NRC Commissioners
- CONTRACT — NRC Contracts and Modifications
- DISCLOSURE — Financial Disclosure Information
- FOIA — Freedom of Information Act Requests and Releases
- GEN TECH IS — Generic Technical Issues

I&E — Inspection and Enforcement
 MISC — Public Document Room Miscellaneous
 NUREG — NUREG Reports and Related Correspondence
 ORG — Correspondence with Other Organizations
 PR — Proposed Rule
 PRM — Petition for Rulemaking
 PROJ — Projects—Predocket Licensing
 PT21 — Noncompliance Reports and Related Correspondence
 QA999 — Quality Assurance Inspections
 REGGD — Regulatory Guides
 RES — Research and Technical Assistance Reports
 REVIEW GRP — NRC Research Review Groups
 RM — Rulemakings
 SECY — Position Papers Before the Commission
 STATE PROG — State Programs
 TOPREP — Vendor Reports and Related Correspondence
 WASH — Regulatory Publications—Pre-NUREG Series
 WASTE MGT — Nuclear Waste Management
 XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



1. Nondocketed category
2. NRC Accession Number (year, month, day, and sequence number of item)
3. NRC Report Number
4. Title and description of information contained in the document
5. Personal author(s). An asterisk in this position indicates that there is no personal author.
6. Corporate, agency or other nonindividual source.
7. Contract or financial (FIN) number (if any). If the document has a secondary report number, it will appear following this entry.
8. Secondary report number assigned by originator.
9. Date of document described.
10. NRC organizational recipient.
11. Pages in document.
12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
13. Price for which NRC sells the document.

14. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
15. This three-digit portion of this entry is the number of the frame on which this document starts.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service
Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W.
Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is \$0.05 per page except for oversized documents and engineering drawings, which vary from \$0.50 to \$1.00 per square foot; (2) microform to paper is \$0.05 a page for pages on microfiche and is \$0.20 a square foot for a full-size print or \$0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is \$0.10 per microfiche and \$0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
Low Level Radwaste Disposal Sites — Docket 27			40-8452	Bear Creek Uranium Co , Casper, WY	4
27-039	Shelfield, IL, U S Ecology, Inc	1	40-8502	Wyoming Mineral Corp , Lakewood, CO	5
27-048	Richland, WA, U S Ecology, Inc	1	40-8584	Minerals Exploration Co , Los Angeles, CA	5
Domestic Licensing of Source Material — Docket 40			40-8599	Air Force, Dept. of, Brooks AFB, TX	5
40-0017	Dow Chemical Co , Midland, MI	1	40-8674	Plateau Resources, Ltd , Grand Junction, CO	5
40-0086	W R. Grace & Co , Pompton Plains, NJ	1	40-8681	Energy Fuels Nuclear, Inc , Denver, CO	5
40-0299	Union Carbide Corp., Grand Junction, CO	1	40-8697	Rocky Mountain Energy Co , Denver, CO	5
40-0462	Dow Chemical Co , Midland, MI	2	40-8698	Plateau Resources, Ltd , Grand Junction, CO	5
40-0672	Nuclear Metals, Inc , Concord, MA	2	40-8714	Cleveland-Cliffs Iron Co , Cleveland, OH	6
40-1341	Tennessee Valley Authority, Chattanooga, TN	2	40-8745	Ogle Petroleum, Inc , Casper, WY	6
40-2061	Kerr-McGee Chemical Corp , Oklahoma City, OK	2	40-8768	Kerr-McGee Nuclear Corp., Oklahoma City, OK	6
40-2259	Pathfinder Mines Corp , Riverton, WY	3	40-8781	Teton Exploration Drilling Co., Inc., Casper, WY	6
40-3392	Allied Chemical Corp , Morristown, NJ	3	40-8783	Uranerz USA, Inc., Casper, WY	6
40-3453	Atlas Minerals, Inc., Denver, CO	3	40-8786	Uranium Resources, Inc , Richardson, TX	6
40-4492	Federal-American Partners, Riverton, WY	3	40-8794	Molycorp, Inc., Los Angeles, CA	6
40-4931	Navy, Dept. of, Annapolis, MD	3	40-8801	Radiation Management Corp., Northbrook, IL	6
40-6500	Energy, Dept of, Canonsburg, PA	3	40-8807	Air Force, Dept. of, Tinker APB, OK	6
40-6622	Pathfinder Mines Corp., Shirley Basin, WY	3	40-8829	Wyoming Fuel Co., Lakewood, CO	6
40-6659	Getty Oil Co.-Petrochemicals Co., Shirley Basin, WY	3	40-8839	Santa Fe Mining, Inc., Albuquerque, NM	6
40-6940	Kawecki Berylco Industries, Inc., Boyertown, PA	4	Domestic Licensing of Production and Utilization Facilities— Docket 50		
40-7869	Plateau Resources, Ltd , Grand Junction, CO	4	50-2	Univ. of Michigan Research Reactor	6
40-8027	Kerr-McGee Nuclear Corp., Oklahoma City, OK	4	50-3	Indian Point Station, Unit 1	7
40-8035	Cotter Corp., Roswell, NM	4	50-5	Pennsylvania State Univ. Research Reactor	8
40-8064	Exxon Minerals Co., USA, Houston, TX	4	50-10	Dresden Nuclear Power Station, Unit 1	8
40-8084	Rio Algom Corp., Moab, UT	4	50-18	Vallecitos Boiling Water Reactor	9
40-8102	Exxon Co., USA, Houston, TX	4	50-20	Massachusetts Institute of Technology Research Reactor	9
40-8348	Minerals Exploration Co., Los Angeles, CA	4	50-27	Washington State Univ. Research Reactor	10
40-8380	Rocky Mountain Energy Co., Broomfield, CO	4	50-29	Yankee-Rowe Nuclear Power Station	10

Docket	Name	Page	Docket	Name	Page
50-54	Union Carbide Research Reactor	12	50-220	Nine Mile Point Nuclear Station, Unit 1	29
50-57	State Univ of New York Research Reactor	12	50-223	Univ of Lowell Research Reactor	31
50-59	Texas A&M Univ Research Reactor	12	50-224	Univ of California Research Reactor	31
50-62	Univ of Virginia Research Reactor	12	50-225	RPI Critical Experiment	31
50-70	General Electric Test Reactor	13	50-228	Aerotest Radiography & Research Reactor	32
50-73	General Electric Nuclear Test Reactor	13	50-237	Dresden Nuclear Power Station, Unit 2	32
50-83	Univ of Florida Training Reactor	13	50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	35
50-87	Westinghouse Critical Experiment	13	50-245	Millstone Nuclear Power Station, Unit 1	37
50-89	General Atomic Co	13	50-247	Indian Point Station, Unit 2	38
50-112	Univ of Oklahoma Research Reactor	13	50-249	Dresden Nuclear Power Station, Unit 3	40
50-116	Iowa State Univ. Research Reactor	13	50-250	Turkey Point Plant, Unit 3	43
50-123	Univ of Missouri Research Reactor	14	50-251	Turkey Point Plant, Unit 4	45
50-124	Virginia Polytechnic Institute Training Reactor	14	50-254	Quad-Cities Station, Unit 1	47
50-128	Texas A&M Univ Research Reactor	14	50-255	Palisades Nuclear Plant	49
50-133	Humboldt Bay Power Plant, Unit 3	14	50-259	Browns Ferry Nuclear Power Station, Unit 1	51
50-134	Worcester Polytechnic Institute Research Reactor	15	50-260	Browns Ferry Nuclear Power Station, Unit 2	55
50-139	Univ. of Washington Research Reactor	15	50-261	H B Robinson Plant, Unit 2	57
50-142	UCLA Training Reactor	15	50-263	Monticello Nuclear Generating Plant	60
50-148	Univ. of Kansas Research Reactor	15	50-265	Quad-Cities Station, Unit 2	62
50-155	Big Rock Point Nuclear Plant	16	50-266	Point Beach Nuclear Plant, Unit 1	64
50-163	General Atomic Co	21	50-267	Fort St Vrain Nuclear Generating Station	67
50-166	Univ of Maryland Research Reactor	21	50-269	Oconee Nuclear Station, Unit 1	70
50-170	National Naval Medical Center	22	50-270	Oconee Nuclear Station, Unit 2	72
50-171	Peach Bottom Atomic Power Station, Unit 1	22	50-271	Vermont Yankee Nuclear Power Station	75
50-183	Vallecitos Experimental Superheat Reactor	22	50-272	Salem Nuclear Generating Station, Unit 1	76
50-186	Univ of Missouri Research Reactor	22	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	78
50-188	Kansas State Univ Research Reactor	22	50-277	Peach Bottom Atomic Power Station, Unit 2	88
50-192	Univ. of Texas Research Reactor	22	50-278	Peach Bottom Atomic Power Station, Unit 3	91
50-193	Rhode Island & Providence Plantations AEC	22	50-280	Surry Power Station, Unit 1	93
50-199	Manhattan College Research Reactor	23	50-281	Surry Power Station, Unit 2	95
50-201	West Valley Reprocessing Plant	23	50-282	Prairie Island Nuclear Station, Unit 1	97
50-206	San Onofre Nuclear Station, Unit 1	24	50-285	Fort Calhoun Station, Unit 1	99
50-213	Haddam Neck Plant	26	50-286	Indian Point Station, Unit 3	102
50-219	Oyster Creek Nuclear Power Plant	28	50-287	Oconee Nuclear Station, Unit 3	103
			50-289	Three Mile Island Nuclear Station, Unit 1	106

Docket	Name	Page	Docket	Name	Page
50-293	Pilgrim Nuclear Power Station, Unit 1	114	50-344	Trojan Nuclear Plant	213
50-295	Zion Nuclear Power Station, Unit 1	115	50-346	Davis-Besse Nuclear Power Station, Unit 1	215
50-296	Browns Ferry Nuclear Power Station, Unit 3	117	50-348	Joseph M. Farley Nuclear Plant, Unit 1	218
50-298	Cooper Nuclear Station	120	50-352	Limerick Generating Station, Unit 1	221
50-301	Point Beach Nuclear Plant, Unit 2	122	50-353	Limerick Generating Station, Unit 2	225
50-302	Crystal River Nuclear Plant, Unit 3	124	50-354	Hope Creek Nuclear Station, Unit 1	229
50-304	Zion Nuclear Power Station, Unit 2	127	50-358	William H. Zimmer Nuclear Station, Unit 1	230
50-305	Kewaunee Nuclear Power Plant	129	50-361	San Onofre Nuclear Station, Unit 2	234
50-306	Prairie Island Nuclear Station, Unit 2	131	50-362	San Onofre Nuclear Station, Unit 3	237
50-309	Maine Yankee Atomic Power Plant	133	50-364	Joseph M. Farley Nuclear Plant, Unit 2	239
50-311	Salem Nuclear Generating Station, Unit 2	135	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	242
50-312	Rancho Seco Nuclear Generating Station	138	50-367	Bailly Generating Station	245
50-313	Arkansas Nuclear One, Unit 1	141	50-368	Arkansas Nuclear One, Unit 2	245
50-315	Donald C. Cook Nuclear Power Plant, Unit 1	143	50-369	William B. McGuire Nuclear Station, Unit 1	247
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	146	50-370	William B. McGuire Nuclear Station, Unit 2	250
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	149	50-373	LaSalle County Station, Unit 1	253
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	151	50-374	LaSalle County Station, Unit 2	255
50-320	Three Mile Island Nuclear Station, Unit 2	153	50-382	Waterford Generating Station, Unit 3	258
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	159	50-387	Susquehanna Steam Electric Station, Unit 1	262
50-322	Shoreham Nuclear Power Station	161	50-388	Susquehanna Steam Electric Station, Unit 2	265
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	164	50-389	St. Lucie Plant, Unit 2	267
50-324	Brunswick Steam Electric Plant, Unit 2	171	50-390	Watts Bar Nuclear Plant, Unit 1	269
50-325	Brunswick Steam Electric Plant, Unit 1	175	50-391	Watts Bar Nuclear Plant, Unit 2	273
50-327	Sequoyah Nuclear Plant, Unit 1	179	50-395	Virgil C. Summer Nuclear Station, Unit 1	277
50-328	Sequoyah Nuclear Plant, Unit 2	181	50-397	WPPSS Nuclear Project, Unit 2	279
50-329	Midland Plant, Unit 1	184	50-400	Shearon Harris Nuclear Power Plant, Unit 1	282
50-330	Midland Plant, Unit 2	191	50-401	Shearon Harris Nuclear Power Plant, Unit 2	288
50-331	Duane Arnold Energy Center	198	50-406	Tuskegee Institute Research Reactor	293
50-333	James A. Fitzpatrick Nuclear Power Plant	200	50-409	La Crosse Boiling Water Reactor	293
50-334	Beaver Valley Power Station, Unit 1	202	50-410	Nine Mile Point Nuclear Station, Unit 2	295
50-335	St. Lucie Plant, Unit 1	204	50-412	Beaver Valley Power Station, Unit 2	296
50-336	Millstone Nuclear Power Station, Unit 2	206	50-413	Catawba Nuclear Station, Unit 1	298
50-338	North Anna Power Station, Unit 1	207	50-414	Catawba Nuclear Station, Unit 2	302
50-339	North Anna Power Station, Unit 2	209	50-416	Grand Gulf Nuclear Station, Unit 1	306
50-341	Enrico Fermi Atomic Power Plant, Unit 2	211	50-417	Grand Gulf Nuclear Station, Unit 2	311

Docket	Name	Page	Docket	Name	Page
50-423	Millstone Nuclear Power Station, Unit 3	312	STN-50-499	South Texas Project, Unit 2	363
50-424	Alvin W Vogtle Nuclear Plant, Unit 1	313	STN-50-508	WPPSS Nuclear Project, Unit 3	365
50-425	Alvin W Vogtle Nuclear Plant, Unit 2	314	50-513	WPPSS Nuclear Project, Unit 4	366
50-433	UC-Santa Barbara Research Reactor	315	50-514	Pebble Springs Nuclear Plant, Unit 1	366
50-434	Surry Power Station, Unit 3	315	50-515	Pebble Springs Nuclear Plant, Unit 2	366
50-438	Bellefonte Nuclear Plant, Unit 1	315	50-522	Skagit Nuclear Power Project, Unit 1	367
50-439	Bellefonte Nuclear Plant, Unit 2	317	50-523	Skagit Nuclear Power Project, Unit 2	367
50-440	Perry Nuclear Power Plant, Unit 1	319	STN-50-528	Palo Verde Nuclear Station, Unit 1	368
50-441	Perry Nuclear Power Plant, Unit 2	322	STN-50-529	Palo Verde Nuclear Station, Unit 2	370
50-443	Seabrook Nuclear Station, Unit 1	324	STN-50-530	Palo Verde Nuclear Station, Unit 3	373
50-444	Seabrook Nuclear Station, Unit 2	328	50-537	Clinch River Breeder Reactor	375
50-445	Comanche Peak Steam Electric Station, Unit 1	332	STN-50-546	Marble Hill Nuclear Station, Unit 1	376
50-446	Comanche Peak Steam Electric Station, Unit 2	336	STN-50-547	Marble Hill Nuclear Station, Unit 2	377
STN-50-447	GESSAR-238	340	STN-50-553	Phipps Bend Nuclear Station, Unit 1	378
STN-50-454	Byron Station, Unit 1	340	STN-50-554	Phipps Bend Nuclear Station, Unit 2	378
STN-50-455	Byron Station, Unit 2	344	STN-50-556	Black Fox Station, Unit 1	378
STN-50-456	Braidwood Station, Unit 1	346	STN-50-557	Black Fox Station, Unit 2	379
STN-50-457	Braidwood Station, Unit 2	348	Domestic Licensing of Special Nuclear Material — Docket 70		
50-458	River Bend Station, Unit 1	350	70-0025	Rockwell International Corp , Canoga Park, CA	379
50-459	River Bend Station, Unit 2	352	70-0027	Babcock & Wilcox Co , Lynchburg, VA	379
50-460	WPPSS Nuclear Project, Unit 1	353	70-0036	Combustion Engineering, Inc , Windsor, CT	380
50-461	Clinton Power Station, Unit 1	354	70-0135	Babcock & Wilcox Co , Apollo, PA	380
50-462	Clinton Power Station, Unit 2	355	70-0143	Nuclear Fuel Services, Inc , Erwin, TN	380
STN-50-470	CESSAR System 80	355	70-0364	Babcock & Wilcox Co., Apollo, PA	382
50-471	Pilgrim Nuclear Power Station, Unit 2	356	70-0371	UNC Naval Products, Inc , Uncasville, CT	382
STN-50-482	Wolf Creek Generating Station	356	70-0474	Upsala College, East Orange, NJ	383
STN-50-483	Callaway Plant, Unit 1	357	70-0572	Monsanto Research Corp , Dayton, OH	383
STN-50-486	Callaway Plant, Unit 2	359	70-0698	Westinghouse Electric Corp., Pittsburgh, PA	383
STN-50-491	Cherokee Nuclear Station, Unit 1	360	70-0734	GA Technologies, Inc., San Diego, CA	383
STN-50-492	Cherokee Nuclear Station, Unit 2	360	70-0754	General Electric Co , Pleasanton, CA	383
STN-50-493	Cherokee Nuclear Station, Unit 3	360	70-0820	United Nuclear Corp , Wood River Junction, RI	383
50-496	Montague Nuclear Power Station, Unit 1	360	70-0824	Babcock & Wilcox Co., Lynchburg, VA	383
50-497	Montague Nuclear Power Station, Unit 2	360	70-0984	Battelle Memorial Institute, Richland, WA	384
STN-50-498	South Texas Project, Unit 1	361	70-1100	Combustion Engineering, Inc., Windsor, CT	384

Docket	Name	Page	Docket	Name	Page
70-1113	General Electric Co , Wilmington, NC	384	71-0503	Penn Inspection Co	388
70-1143	Westinghouse Electric Corp , Pittsburgh, PA	385	71-0504	Texas Utility Generating Co	388
70-1144	Ohmart Corp , Cincinnati, OH	385	71-0505	Southwest Research Institute	388
70-1151	Westinghouse Electric Corp , Pittsburgh, PA	385	71-0506	Babcock & Wilcox Co.	388
70-1201	Babcock & Wilcox Co., Lynchburg, VA	386	71-4909	Model. GE-21PF-1, General Electric Co	389
70-1257	Exxon Nuclear Co , Inc , Richland, WA	386	71-5059	Model NFS-Uranyl Nit , Nuclear Fuel Services, Inc	389
70-1308	General Electric Co , San Jose, CA	386	71-5088	Model: D34710-1, D34710-2, Rockwell International Corp	389
70-1426	Transnuclear, Inc., Falls Church, VA	386	71-5450	Model RCC -1, -2, -3, -4, Westinghouse Electric Corp	389
70-1462	Harper Hospital, Detroit, MI	386	71-5595	Model: L&M ORNL Uranium Shielded Cask, Energy, Dept. of	389
70-1487	Dow Chemical USA, Midland, MI	386	71-5797	Model: Inner & Outer HFIR UN, Energy, Dept of	389
70-1795	George Washington Univ , Washington, DC	387	71-5805	Model: CNS 3-55, Chem-Nuclear Systems, Inc.	389
70-2067	Union Carbide Corp , Marietta, OH	387	71-5828	Model: TREAT, Energy, Dept. of	389
70-2319	Our Lady of Lourdes Hospital, Camden, NJ	387	71-5908	Model DOT-6M Type B, Babcock & Wilcox Co	389
70-2430	Mercer Medical Center, Trenton, NJ	387	71-5939	Model: GE-1500, General Electric Co.	389
70-2808	Westmoreland Hospital, Greensburg, PA	387	71-5957	Model: BMI-1, Battelle Columbus Laboratory	389
70-2941	Tennessee Valley Authority, Chattanooga, TN	387	71-5971	Model: GE-200, General Electric Co.	389
70-2945	Union Electric Co , St Louis, MO	387	71-6003	Model: M-130, Energy, Dept. of	389
70-2946	Louisiana Power & Light Co., New Orleans, LA	387	71-6144	Model: B-2, U.S. Ecology, Inc.	389
70-2949	Arizona Public Service Co., Phoenix, AZ	387	71-6166	Model: 0.5T, Energy, Dept. of	390
70-2950	Washington Public Power Supply System, Richland, WA	387	71-6346	Model: FSV-1, GA Technologies, Inc.	390
70-2960	Kansas Gas & Electric Co , Wichita, KS	387	71-6400	Model: 6400, Westinghouse Electric Corp.	390
70-2968	Cleveland Electric Illuminating Co., Cleveland, OH	387	71-6478	Model: 4T, Energy, Dept. of	390
70-2973	Commonwealth Edison Co., Chicago, IL	387	71-6550	Model: 6-GS-1, Energy, Dept. of	390
70-2977	Detroit Edison Co., Detroit, MI	388	71-6574	HN-200, Hittman Nuclear & Development Corp.	390
70-2983	Pennsylvania Power & Light Co., Allentown, PA	388	71-6601	Model CNS 8-120, Chem-Nuclear Systems, Inc.	390
70-2988	Philadelphia Electric Co., Philadelphia, PA	388	71-6679	Model: 6679, U.S. Ecology, Inc.	390
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71			71-6697	Model: GE-8500, General Electric Co.	390
71-0037	Navy, Dept of	388	71-6771	Model: SN-1, Metropolitan Edison Co.	390
71-0059	General Electric Co.	388	71-9009	Model: FL 10-1, General Electric Co.	390
71-0137	Metals Testing Co , Inc.	388	71-9010	Model: NLI-1/2, NL Industries, Inc.	390
71-0148	United Engineers & Constructors, Inc.	388	71-9016	Model: TN-9, No Users	391
71-0466	Minnesota Mining & Manufacturing Co. (3M Co.)	388			

Docket	Name	Page	Docket	Name	Page
71-9027	Model 741 & 741E, Technical Operations, Inc.	391	71-9126	Model. 20, 20A, 50, 50A, Gamma Industries	392
71-9032	Model 650, Technical Operations, Inc	391	71-9127	Model 100, 100A, 200, 200A, Gamma Industries	392
71-9033	Model 660 & 660E, Technical Operations, Inc	391	71-9128	Model: C-8, Gamma Industries	392
71-9039	Model: 715, Technical Operations, Inc	391	71-9132	Model T-3, Energy, Dept of	392
71-9044	Model: GE-1600, General Electric Co	391	71-9143	Model: 920, Technical Operations, Inc	392
71-9070	Model N-55, Energy, Dept. of	391	71-9145	Model: NUPAC 50-1 5L, -2 5L, -3 0L & -4 0L, No Users	393
71-9080	Model: 9080, Hittman Nuclear & Development Corp	391	71-9147	Model. 850, Technical Operations, Inc	393
71-9086	Model HN-100, Series 1, Hittman Nuclear & Development Corp	391	71-9151	Model. HN-100, Series 3, Hittman Nuclear & Development Corp	393
71-9089	Model: HN-100S, Hittman Nuclear & Development Corp.	391	71-9152	Model: CNS 1-13C II, Chem-Nuclear Systems, Inc	393
71-9092	Model: HN-300, Hittman Nuclear & Development Corp.	392	71-9158	Model, CNS 3-70, Ridihalgh, Eggers & Associates	393
71-9093	Model HN-400, Hittman Nuclear & Development Corp.	392	71-9159	Model: NUPAC 14/190L, /190M & /190H, Nuclear Packaging, Inc.	393
71-9096	Model: CNS 21-300, Chem-Nuclear Systems, Inc	392	71-9160	Model: 20-VS & 40-VS Gulf Nuclear, Inc.	393
71-9100	Model: KKP-20-4950, Kerr-McGee Nuclear Corp.	392	71-9163	Model: GNG-20, Gulf Nuclear, Inc	393
71-9105	Model: Rad-Waste CR.I, Chem-Nuclear Systems, Inc.	392	71-9181	Model: PAS-2, Nuclear Packaging, Inc.	393
71-9107	Model. 771, Technical Operations, Inc	392	71-9182	Model: Husman Irradiator, Agriculture, Dept. of	393
71-9108	Model CNS 6-75, Chem-Nuclear Systems, Inc	392	71-9184	Model: PAS-1, Nuclear Packaging, Inc	393
71-9111	Model: CNS 6-80-2 & CNS 6-80-2A, Chem-Nuclear Systems, Inc	392	71-9510	Model GPHS, Energy, Dept of	393
			71-9852	Model DT-14, Energy, Dept. of	393
			Licensing of Independent Spent Fuel Storage — Docket 72		
			72-0001	Morris Operations, General Electric Co	394

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Low Level Radwaste Disposal Sites — Docket 27			Ogle Petroleum, Inc , Casper, WY	40-8745	6
Richland, WA, U.S Ecology, Inc	27-048	1	Pathfinder Mines Corp , Riverton, WY	40-2259	3
Sheffield, IL, U S Ecology, Inc	27-039	1	Pathfinder Mines Corp , Shirley Basin, WY	40-6622	3
Domestic Licensing of Source Material — Docket 40			Plateau Resources, Ltd., Grand Junction, CO	40-7869	4
Air Force, Dept of, Brooks AFB, TX	40-8599	5	Plateau Resources, Ltd , Grand Junction, CO	40-8674	5
Air Force, Dept of, Tinker AFB, OK	40-8807	6	Plateau Resources, Ltd , Grand Junction, CO	40-8698	5
Allied Chemical Corp , Morristown, NJ	40-3392	3	Radiation Management Corp , Northbrook, IL	40-8801	6
Atlas Minerals, Inc., Denver, CO	40-3453	3	Rio Algom Corp , Moab, UT	40-8084	4
Bear Creek Uranium Co., Casper, WY	40-8452	4	Rocky Mountain Energy Co., Broomfield, CO	40-8380	4
Cleveland-Cliffs Iron Co., Cleveland, OH	40-8714	6	Rocky Mountain Energy Co , Denver, CO	40-8697	5
Cotter Corp., Roswell, NM	40-8035	4	Santa Fe Mining, Inc , Albuquerque, NM	40-8839	6
Dow Chemical Co , Midland, MI	40-0017	1	Tennessee Valley Authority, Chattanooga, TN	40-1341	2
Dow Chemical Co., Midland, MI	40-0462	2	Teton Exploration Drilling Co., Inc., Casper, WY	40-8781	6
Energy Fuels Nuclear, Inc , Denver, CO	40-8681	5	Union Carbide Corp , Grand Junction, CO	40-0299	1
Energy, Dept. of, Canonsburg, PA	40-6500	3	Uranerz USA, Inc., Casper, WY	40-8783	6
Exxon Co., USA, Houston, TX	40-8102	4	Uranium Resources, Inc., Richardson, TX	40-8786	6
Exxon Minerals Co., USA, Houston, TX	40-8064	4	W. R Grace & Co., Pompton Plains, NJ	40-0086	1
Federal-American Partners, Riverton, WY	40-4492	3	Wyoming Fuel Co , Lakewood, CO	40-8829	6
Getty Oil Co.-Petrochemicals Co., Shirley Basin, WY	40-6659	3	Wyoming Mineral Corp , Lakewood, CO	40-8502	5
Kawecki Berylco Industries, Inc , Boyertown, PA	40-6940	4	Domestic Licensing of Production and Utilization Facilities — Docket 50		
Kerr-McGee Chemical Corp., Oklahoma City, OK	40-2061	2	Aerotest Radiography & Research Reactor	50-228	32
Kerr-McGee Nuclear Corp , Oklahoma City, OK	40-8027	4	Alvin W Vogtle Nuclear Plant, Unit 1	50-424	313
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8768	6	Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	314
Minerals Exploration Co., Los Angeles, CA	40-8348	4	Arkansas Nuclear One, Unit 1	50-313	141
Minerals Exploration Co., Los Angeles, CA	40-8584	5	Arkansas Nuclear One, Unit 2	50-368	245
Molycorp, Inc., Los Angeles, CA	40-8794	6	Bailly Generating Station	50-367	245
Navy, Dept. of, Annapolis, MD	40-4931	3	Beaver Valley Power Station, Unit 1	50-334	202
Nuclear Metals, Inc., Concord, MA	40-0672	2			

Name	Docket	Page	Name	Docket	Page
Beaver Valley Power Station, Unit 2	50-412	296	Diablo Canyon Nuclear Power Plant, Unit 2	50-323	164
Bellefonte Nuclear Plant, Unit 1	50-438	315	Donald C. Cook Nuclear Power Plant, Unit 1	50-315	143
Bellefonte Nuclear Plant, Unit 2	50-439	317	Donald C. Cook Nuclear Power Plant, Unit 2	50-316	146
Big Rock Point Nuclear Plant	50-155	16	Dresden Nuclear Power Station, Unit 1	50-10	8
Black Fox Station, Unit 1	STN-50-556	378	Dresden Nuclear Power Station, Unit 2	50-237	32
Black Fox Station, Unit 2	STN-50-557	379	Dresden Nuclear Power Station, Unit 3	50-249	40
Braidwood Station, Unit 1	STN-50-456	346	Duane Arnold Energy Center	50-331	198
Braidwood Station, Unit 2	STN-50-457	348	Edwin I. Hatch Nuclear Plant, Unit 1	50-321	159
Browns Ferry Nuclear Power Station, Unit 1	50-259	51	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	242
Browns Ferry Nuclear Power Station, Unit 2	50-260	55	Enrico Fermi Atomic Power ² Plant, Unit 2	50-341	211
Browns Ferry Nuclear Power Station, Unit 3	50-296	117	Fort Calhoun Station, Unit 1	50-285	99
Brunswick Steam Electric Plant, Unit 1	50-325	175	Fort St. Vrain Nuclear Generating Station	50-267	67
Brunswick Steam Electric Plant, Unit 2	50-324	171	General Atomic Co	50-163	21
Byron Station, Unit 1	STN-50-454	340	General Atomic Co	50-89	13
Byron Station, Unit 2	STN-50-455	344	General Electric Nuclear Test Reactor	50-73	13
Callaway Plant, Unit 1	STN-50-483	357	General Electric Test Reactor	50-70	13
Callaway Plant, Unit 2	STN-50-486	359	GESSAR-238	STN-50-447	340
Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	149	Grand Gulf Nuclear Station, Unit 1	50-416	306
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	151	Grand Gulf Nuclear Station, Unit 2	50-417	311
Catawba Nuclear Station, Unit 1	50-413	298	H. B. Robinson Plant, Unit 2	50-261	57
Catawba Nuclear Station, Unit 2	50-414	302	Haddam Neck Plant	50-213	26
CESSAR System 80	STN-50-470	355	Hope Creek Nuclear Station, Unit 1	50-354	229
Cherokee Nuclear Station, Unit 1	STN-50-491	360	Humboldt Bay Power Plant, Unit 3	50-133	14
Cherokee Nuclear Station, Unit 2	STN-50-492	360	Indian Point Station, Unit 1	50-3	7
Cherokee Nuclear Station, Unit 3	STN-50-493	360	Indian Point Station, Unit 2	50-247	38
Clinch River Breeder Reactor	50-537	375	Indian Point Station, Unit 3	50-286	102
Clinton Power Station, Unit 1	50-461	354	Iowa State Univ. Research Reactor	50-116	13
Clinton Power Station, Unit 2	50-462	355	James A. Fitzpatrick Nuclear Power Plant	50-333	200
Comanche Peak Steam Electric Station, Unit 1	50-445	332	Joseph M. Farley Nuclear Plant, Unit 1	50-348	218
Comanche Peak Steam Electric Station, Unit 2	50-446	336	Joseph M. Farley Nuclear Plant, Unit 2	50-364	239
Cooper Nuclear Station	50-298	120	Kansas State Univ. Research Reactor	50-188	22
Crystal River Nuclear Plant, Unit 3	50-302	124	Kewaunee Nuclear Power Plant	50-305	129
Davis-Besse Nuclear Power Station, Unit 1	50-346	215	La Crosse Boiling Water Reactor	50-409	293
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	78	LaSalle County Station, Unit 1	50-373	253
			LaSalle County Station, Unit 2	50-374	255

Name	Docket	Page	Name	Docket	Page
Limerick Generating Station, Unit 1	50-352	221	Perry Nuclear Power Plant, Unit 2	50-441	322
Limerick Generating Station, Unit 2	50-353	225	Phipps Bend Nuclear Station, Unit 1	STN-50-553	378
Maine Yankee Atomic Power Plant	50-309	133	Phipps Bend Nuclear Station, Unit 2	STN-50-554	378
Manhattan College Research Reactor	50-199	23	Pilgrim Nuclear Power Station, Unit 1	50-293	114
Marble Hill Nuclear Station, Unit 1	STN-50-546	376	Pilgrim Nuclear Power Station, Unit 2	50-471	350
Marble Hill Nuclear Station, Unit 2	STN-50-547	377	Point Beach Nuclear Plant, Unit 1	50-266	64
Massachusetts Institute of Technology Research Reactor	50-20	9	Point Beach Nuclear Plant, Unit 2	50-301	122
Midland Plant, Unit 1	50-329	184	Prairie Island Nuclear Station, Unit 1	50-282	97
Midland Plant, Unit 2	50-330	191	Prairie Island Nuclear Station, Unit 2	50-306	131
Millstone Nuclear Power Station, Unit 1	50-245	37	Quad-Cities Station, Unit 1	50-254	47
Millstone Nuclear Power Station, Unit 2	50-336	206	Quad-Cities Station, Unit 2	50-265	62
Millstone Nuclear Power Station, Unit 3	50-423	312	Rancho Seco Nuclear Generating Station	50-312	138
Montague Nuclear Power Station, Unit 1	50-496	360	Rhode Island & Providence Plantations AEC	50-193	22
Montague Nuclear Power Station, Unit 2	50-497	360	River Bend Station, Unit 1	50-458	350
Monticello Nuclear Generating Plant	50-263	60	River Bend Station, Unit 2	50-459	352
National Naval Medical Center	50-170	22	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	35
Nine Mile Point Nuclear Station, Unit 1	50-220	29	RPI Critical Experiment	50-225	31
Nine Mile Point Nuclear Station, Unit 2	50-410	295	Salem Nuclear Generating Station, Unit 1	50-272	76
North Anna Power Station, Unit 1	50-338	207	Salem Nuclear Generating Station, Unit 2	50-311	135
North Anna Power Station, Unit 2	50-339	209	San Onofre Nuclear Station, Unit 1	50-206	24
Oconee Nuclear Station, Unit 1	50-269	70	San Onofre Nuclear Station, Unit 2	50-361	234
Oconee Nuclear Station, Unit 2	50-270	72	San Onofre Nuclear Station, Unit 3	50-362	237
Oconee Nuclear Station, Unit 3	50-287	103	Seabrook Nuclear Station, Unit 1	50-443	324
Oyster Creek Nuclear Power Plant	50-219	28	Seabrook Nuclear Station, Unit 2	50-444	328
Palisades Nuclear Plant	50-255	49	Sequoyah Nuclear Plant, Unit 1	50-327	179
Palo Verde Nuclear Station, Unit 1	STN-50-528	368	Sequoyah Nuclear Plant, Unit 2	50-328	181
Palo Verde Nuclear Station, Unit 2	STN-50-529	370	Shearon Harris Nuclear Power Plant, Unit 1	50-400	282
Palo Verde Nuclear Station, Unit 3	STN-50-530	373	Shearon Harris Nuclear Power Plant, Unit 2	50-401	288
Peach Bottom Atomic Power Station, Unit 1	50-171	22	Shoreham Nuclear Power Station	50-322	161
Peach Bottom Atomic Power Station, Unit 2	50-277	88	Skagit Nuclear Power Project, Unit 1	50-522	367
Peach Bottom Atomic Power Station, Unit 3	50-278	91	Skagit Nuclear Power Project, Unit 2	50-523	367
Pebble Springs Nuclear Plant, Unit 1	50-514	366	South Texas Project, Unit 1	STN-50-498	361
Pebble Springs Nuclear Plant, Unit 2	50-515	366	South Texas Project, Unit 2	STN-50-499	363
Pennsylvania State Univ. Research Reactor	50-5	8	St. Lucie Plant, Unit 1	50-335	204
Perry Nuclear Power Plant, Unit 1	50-440	319	St. Lucie Plant, Unit 2	50-389	267

Name	Docket	Page	Name	Docket	Page
State Univ. of New York Research Reactor	50-57	12	Waterford Generating Station, Unit 3	50-382	258
Surry Power Station, Unit 1	50-280	93	Watts Bar Nuclear Plant, Unit 1	50-390	269
Surry Power Station, Unit 2	50-281	95	Watts Bar Nuclear Plant, Unit 2	50-391	273
Surry Power Station, Unit 3	50-434	315	West Valley Reprocessing Plant	50-201	23
Susquehanna Steam Electric Station, Unit 1	50-387	262	Westinghouse Critical Experiment	50-87	13
Susquehanna Steam Electric Station, Unit 2	50-388	265	William B. McGuire Nuclear Station, Unit 1	50-369	247
Texas A&M Univ. Research Reactor	50-128	14	William B. McGuire Nuclear Station, Unit 2	50-370	250
Texas A&M Univ. Research Reactor	50-59	12	William H. Zimmer Nuclear Station, Unit 1	50-358	230
Three Mile Island Nuclear Station, Unit 1	50-289	106	Wolf Creek Generating Station	STN-50-482	356
Three Mile Island Nuclear Station, Unit 2	50-320	153	Worcester Polytechnic Institute Research Reactor	50-134	15
Trojan Nuclear Plant	50-344	213	WPPSS Nuclear Project, Unit 1	50-460	353
Turkey Point Plant, Unit 3	50-250	43	WPPSS Nuclear Project, Unit 2	50-397	279
Turkey Point Plant, Unit 4	50-251	45	WPPSS Nuclear Project, Unit 3	STN-50-508	365
Tuskegee Institute Research Reactor	50-406	293	WPPSS Nuclear Project, Unit 4	50-513	366
UC-Santa Barbara Research Reactor	50-433	315	Yankee-Rowe Nuclear Power Station	50-29	10
UCLA Training Reactor	50-142	15	Zion Nuclear Power Station, Unit 1	50-295	115
Union Carbide Research Reactor	50-54	12	Zion Nuclear Power Station, Unit 2	50-304	127
Univ. of California Research Reactor	50-224	31	Domestic Licensing of Special Nuclear Material — Docket 70		
Univ. of Florida Training Reactor	50-83	13	Arizona Public Service Co., Phoenix, AZ	70-2949	387
Univ. of Kansas Research Reactor	50-148	15	Babcock & Wilcox Co., Apollo, PA	70-0135	380
Univ. of Lowell Research Reactor	50-223	31	Babcock & Wilcox Co., Apollo, PA	70-0364	382
Univ. of Maryland Research Reactor	50-166	21	Babcock & Wilcox Co., Lynchburg, VA	70-1201	386
Univ. of Michigan Research Reactor	50-2	6	Babcock & Wilcox Co., Lynchburg, VA	70-0824	383
Univ. of Missouri Research Reactor	50-186	22	Babcock & Wilcox Co., Lynchburg, VA	70-0027	379
Univ. of Missouri Research Reactor	50-123	14	Battelle Memorial Institute, Richland, WA	70-0984	384
Univ. of Oklahoma Research Reactor	50-112	13	Cleveland Electric Illuminating Co., Cleveland, OH	70-2968	387
Univ. of Texas Research Reactor	50-192	22	Combustion Engineering, Inc., Windsor, CT	70-1100	384
Univ. of Virginia Research Reactor	50-62	12	Combustion Engineering, Inc., Windsor, CT	70-0036	380
Univ. of Washington Research Reactor	50-139	15	Commonwealth Edison Co., Chicago, IL	70-2973	387
Vallecitos Boiling Water Reactor	50-18	9	Detroit Edison Co., Detroit, MI	70-2977	388
Vallecitos Experimental Superheat Reactor	50-183	22	Dow Chemical USA, Midland, MI	70-1487	386
Vermont Yankee Nuclear Power Station	50-271	75	Exxon Nuclear Co., Inc., Richland, WA	70-1257	386
Virgil C. Summer Nuclear Station, Unit 1	50-395	277	GA Technologies, Inc., San Diego, CA	70-0734	383
Virginia Polytechnic Institute Training Reactor	50-124	14	General Electric Co., Pleasanton, CA	70-0754	383
Washington State Univ. Research Reactor	50-27	10			

Name	Docket	Page	Name	Docket	Page
General Electric Co , San Jose, CA	70-1308	386	Model 0 5T, Energy, Dept of	71-6166	390
General Electric Co , Wilmington, NC	70-1113	384	Model 100, 100A, 200, 200A, Gamma Industries	71-9127	392
George Washington Univ , Washington, DC	70-1795	387	Model 20, 20A, 50, 50A, Gamma Industries	71-9126	392
Harper Hospital, Detroit, MI	70-1462	386	Model 20-VS & 40-VS, Gulf Nuclear, Inc	71-9160	393
Kansas Gas & Electric Co , Wichita, KS	70-2960	387	Model 4T, Energy, Dept of	71-6478	390
Louisiana Power & Light Co , New Orleans, LA	70-2946	387	Model: 6-GS-1, Energy, Dept of	71-6550	390
Mercer Medical Center, Trenton, NJ	70-2430	387	Model 6400, Westinghouse Electric Corp	71-6400	390
Monsanto Research Corp., Dayton, OH	70-0572	383	Model 650, Technical Operations, Inc	71-9032	391
Nuclear Fuel Services, Inc , Erwin, TN	70-0143	380	Model 660 & 660E Technical Operations, Inc	71-9033	391
Ohmart Corp , Cincinnati, OH	70-1144	385	Model: 6679, U S Ecology, Inc.	71-6679	390
Our Lady of Lourdes Hospital, Camden, NJ	70-2319	387	Model 715, Technical Operations, Inc	71-9039	391
Pennsylvania Power & Light Co , Allentown, PA	70-2983	388	Model 741 & 741E, Technical Operations, Inc.	71-9027	391
Philadelphia Electric Co., Philadelphia, PA	70-2988	388	Model 771, Technical Operations, Inc.	71-9107	392
Rockwell International Corp , Canoga Park, CA	70-0025	379	Model 850, Technical Operations, Inc	71-9147	393
Tennessee Valley Authority, Chattanooga, TN	70-2941	387	Model: 9080, Hittman Nuclear & Development Corp	71-9080	391
Transnuclear, Inc., Falls Church, VA	70-1426	386	Model: 920, Technical Operations, Inc	71-9143	392
UNC Naval Products, Inc , Uncasville, CT	70-0371	382	Model B-2, U.S. Ecology, Inc	71-6144	389
Union Carbide Corp , Marietta, OH	70-2067	387	Model: BMI-1, Battelle Columbus Laboratory	71-5957	389
Union Electric Co., St Louis, MO	70-2945	387	Model C-8, Gamma Industries	71-9128	392
United Nuclear Corp , Wood River Junction, RI	70-0820	383	Model CNS 1-13C II, Chem-Nuclear Systems, Inc.	71-9152	393
Upsala College, East Orange, NJ	70-0474	383	Model CNS 21-300, Chem-Nuclear Systems, Inc.	71-9096	392
Washington Public Power Supply System, Richland, WA	70-2950	387	Model: CNS 3-55, Chem-Nuclear Systems, Inc.	71-5805	389
Westinghouse Electric Corp., Pittsburgh, PA	70-1143	385	Model CNS 3-70, Ridihalgh, Eggers & Associates	71-9158	393
Westinghouse Electric Corp., Pittsburgh, PA	70-1151	385	Model. CNS 6-75, Chem-Nuclear Systems, Inc.	71-9108	392
Westinghouse Electric Corp., Pittsburgh, PA	70-0698	383	Model- CNS 6-80-2 & CNS 6-80-2A, Chem-Nuclear Systems, Inc.	71-9111	392
Westmoreland Hospital, Greensburg, PA	70-2808	387	Model: CNS 8-120, Chem-Nuclear Systems, Inc.	71-6601	390
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71			Model: D34710-1, D34710-2, Rockwell International Corp.	71-5088	389
Babcock & Wilcox Co.	71-0506	388	Model. DOT-6M Type B, Babcock & Wilcox Co.	71-5908	389
General Electric Co	71-0059	388	Model: DT-14, Energy, Dept. of	71-9852	393
Metals Testing Co , Inc.	71-0137	388			
Minnesota Mining & Manufacturing Co. (3M Co.)	71-0466	388			

Name	Docket	Page	Name	Docket	Page
Model FL 10-1, General Electric Co	71-9009	390	Model M-130, Energy, Dept of	71-6003	389
Model FSV-1, GA Technologies, Inc.	71-6346	390	Model N-55, Energy, Dept of	71-9070	391
Model GE-1500, General Electric Co	71-5939	389	Model NFS-Uranyl Nit , Nuclear Fuel Services, Inc.	71-5059	389
Model GE-1600, General Electric Co	71-9044	391	Model NLI-1/2, NL Industries, Inc.	71-9010	390
Model GE-200, General Electric Co.	71-5971	389	Model NUPAC 14/190L, /190M & /190H, Nuclear Packaging	71-9159	393
Model GE-21PF-1, General Electric Co.	71-4909	389	Model NUPAC 50-1 5L, -2 5L, -3.0L & -4 0L, No Users	71-9145	393
Model GE-8500, General Electric Co.	71-6697	390	Model PAS-1, Nuclear Packaging, Inc	71-9184	393
Model GNG-20, Gulf Nuclear, Inc.	71-9163	393	Model PAS-2, Nuclear Packaging, Inc	71-9181	393
Model GPHS, Energy, Dept. of	71-9510	393	Model Rad-Waste CR.I, Chem-Nuclear Systems, Inc	71-9105	392
Model HN-100, Series 1, Hittman Nuclear & Development Corp.	71-9086	391	Model RCC, -1, -2, -3, -4, Westinghouse Electric Corp.	71-5450	389
Model HN-100, Series 3, Hittman Nuclear & Development Corp.	71-9151	393	Model SN-1, Metropolitan Edison Co.	71-6771	390
Model HN-100S, Hittman Nuclear & Development Corp	71-9089	391	Model T-3, Energy, Dept. of	71-9132	392
Model HN-200, Hittman Nuclear & Development Corp	71-6574	390	Model TN-9, No Users	71-9016	391
Model HN-300, Hittman Nuclear & Development Corp	71-9092	392	Model TREAT, Energy, Dept of	71-5828	389
Model HN-400, Hittman Nuclear & Development Corp.	71-9093	392	Navy, Dept of	71-0037	388
Model Husman Irradiator, Agriculture, Dept. of	71-9182	393	Penn Inspection Co	71-0503	388
Model Inner & Outer HFIR UN, Energy, Dept. of	71-5797	389	Southwest Research Institute	71-0505	388
Model KKP-20-4950, Kerr-McGee Nuclear Corp.	71-9100	392	Texas Utility Generating Co	71-0504	388
Model L&M ORNL Uranium Shielded Cask, Energy, Dept of	71-5595	389	United Engineers & Constructors, Inc	71-0148	388
			Licensing of Independent Spent Fuel Storage — Docket 72		
			Morris Operations, General Electric Co	72-0001	394

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL, U S ECOLOGY, INC

8310120063 Quarterly monitoring data of piezometers & wells in vicinity of Trench 1B & Trench 1B sumps for Oct 1982 - Jul 1983
W/830915 ltr
HIPSHER, W M US Ecology, Inc (formerly Nuclear Engineering)
83/07/31 ESSIG, T H Region 3, Office of Director App
20697 167

8310060140 Notification of contract execution, Mod 9 to "Sheffield Trench Cap Study" Contractor Univ of Illinois
DELOATCH, V Technical Assistance Contracts Branch FIN B-6965-3
83/09/23 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director SHAFFNER, J NRC - No Detailed Affiliation Given 1p 20660 361

--8310060184 Mod 9, adding funds to Article III for contractor to attend conference in Denver, CO to "Sheffield Trench Cap Study"
* Illinois, Univ of, Urbana, IL GUSTAVE, R P Division of Contracts FIN B-6965-3 83/09/23 1p 20660 362

8310040194 Memorandum & order requiring parties to rept jointly on status of settlement negotiations by 831031 Issues to be addressed in rept listed
COTTER, B P, KLINE, J R, LUEDKE, E A Atomic Safety and Licensing Board Panel 83/09/30 3pp 20608 247

8310170390 Summary of quarterly monitoring data of piezometers & wells in vicinity of Trench 1B & Trench 1B sumps for Jul-Sept 1983 W/830929 ltr
ARMORUST, A J US Ecology, Inc (formerly Nuclear Engineering)
83/09/30 ESSIG, T H Region 2, Office of Director 2pp
20785 033

8310050557 Joint motion to continue proceedings through 840229 to permit addl time for settlement negotiation Certificate of Bvc encl
WETTERHAHN, M J US Ecology, Inc (formerly Nuclear Engineering)
LESSY, R P Hearing Branch 3 83/10/03 Atomic Safety and Licensing Board Panel App 20632 174

8310250049 Motion for 15-day extension to rept jointly on status of settlement negotiations w/NRC & licensee, due to change in responsible parties & party location Certificate of Bvc encl
CHASNOFF, B A Illinois, State of 83/10/19 4pp 20894 170

8310250051 Notice of change of address & of addition of DL Etchison to svc list Related correspondence
CHASNOFF, B A Illinois, State of 83/10/19 1p 20894 178

8310260268 Order granting State of IL 831021 motion for 15-day extension to rept jointly on status of settlement negotiations Rept due by 831115
COTTER, B P Atomic Safety and Licensing Board Panel 83/10/24 Illinois, State of 1p 20912 021

DOCKET 27-048 RICHLAND, WA, U S ECOLOGY, INC

8310280080 Forwards correspondence w/EPA for past 3 yrs, including EPA 830817 response re duality of regulation for nuclear waste sites at Hanford, WA & Beatty, NV
EASON, C F US Ecology, Inc (formerly Nuclear Engineering)
83/09/30 LOHAUS, P Division of Waste Management 7pp 20765 060

8310280281 Requests approval for recommended disposal scenario for proposed waste packages to bury B&W low level radwaste
HIPSHER, W M US Ecology, Inc (formerly Nuclear Engineering)
83/10/12 SCHAFFNER, J Low Level Waste Licensing Branch 2pp
20962 316

8310310207 Forwards SNM receipt & burial rept for Sept 1983 & rept of isotopic activity w/o encl
WRIGHT, S V US Ecology, Inc (formerly Nuclear Engineering)
83/10/14 BROWNING, B Low Level Waste Licensing Branch 1p
20765 302

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0017 DOW CHEMICAL CO, MIDLAND, MI

8310110065 Further response to FOIA request for records re incineration of radioactive matls by Dow Chemical Co Midland, MI plant
Forwards App 8 documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/06/20 GARDE, B P Government Accountability Project 2pp 20704 001

--8310110108 Forwards Insp Findings & Licensee Ack re activities under Licenses 21-00265-04, STD-527 & BMB-111 & Div of Compliance Form AEC-992 concerning noncompliance activities under Licenses 21-00265-02 & 21-00265-06
GRIER, B H Atomic Energy Commission 70/06/08 SILVERSTEIN, L Dow Chemical Co 1p 20704 092

--8310110115 Insp Findings & Licensee Ack dtd 700519-20 of Licenses STD-527, BMB-111 & 21-000265 04 Insp findings no noncompliance noted Related info encl
SCHULTZ, W H Atomic Energy Commission 70/06/08 16pp
20704 053

DOCKET 40-0086 W R GRACE & CO, POMPTON PLAINS, NJ

83101/0143 Responds to 830529 ltr & forwards guidelines for decontamination of facilities
KINNEHAN, J D Region 1, Office of Director 83/09/23 TONGUE, T O W R Grace & Co 1p 20786 213

--8310170151 Requests guidelines for decontamination of facilities & equipment prior to release for unrestricted use or termination of licenses for byproduct source or SNMiger
IE Insp Rept 40-0086/74-01
TONGUE, T O W R Grace & Co 83/09/25 KINNEHAN, J D Region 1, Office of Director 1p 20786 214

--8310170157 "Guidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use or Termination of Licenses for Byproduct, Source or SNM"
* Atomic Energy Commission, Directorate of Licensing 73/12/31 4pp 20786 215

--8310170165 "Guidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use or Termination of Licenses for Byproduct, Source or SNM"
* Division of Fuel Cycle & Material Safety 82/07/31 4pp.
20786 217

8310170011 "Radiological Survey of WR Grace Property, Wayne, NJ, Addendum," final rept
FRAME, P W, BEROER, J D, CONDRA, R D Oak Ridge National Laboratory
FIN A-9093-0 83/09/30 Division of Safeguards 14pp
20814 052

DOCKET 40-0299 UNION CARBIDE CORP, GRAND JUNCTION, CO

8310260416 Forwards plan for testing clay cap & cover matl & availability for final reclamation of inactive tailing area re Amend 18 to License SUA-648
LYONS, P J L Union Carbide Corp 83/06/16 WOODSEY, R Uranium Recovery Field Office 17pp 20926 337

DOCKETED ITEMS

B310040100 Monthly rept of water level elevations for monitor wells around pumpback well for B30801-0901 W/B30909 ltr
HORTON, G Union Carbide Corp 83/09/01 PETTINGILL, H Uranium
Recovery Field Office 3pp 20634 352

B310200009 Raises objections to initial exploration drilling plans for determining existence of possible confining zones in Upper Wind River Aquifer
PETTINGILL, H J Uranium Recovery Field Office 83/09/14 Union
Carbide Corp 1p 20844 265

B310280165 Forwards Rev 1 to B30328 application for amend to License SUA-64B, increasing capacity of A-9 pit tailings area, in response to NRC B30818 request Approval should be obtained by B31001 to permit const
LYONS, P J L Union Carbide Corp 83/09/21 PETTINGILL, H Uranium
Recovery Field Office 4pp 20946 267

--B310280167 Rev 1 to B30328 application for amend to License SUA-64B, increasing capacity of A-9 pit tailings area
* Union Carbide Corp 83/09/30 53pp 20946 271

--B310280170 Rev 1 to "Impact of Increased A-9 Pit Tailings Disposal Facility on Subsurface Hydrologic Conditions"
DAVIS, L A, WARDWELL, R E Water, Waste & Land, Inc 83/09/30
20pp 20946 324

--B310280175 Rev 1 to "Embankment Stability for A-9 Pit Increased Tailings Disposal Capacity Plan" W/one oversize map.
Aperture card is available in PDR
WARDWELL, R E Water, Waste & Land, Inc 83/09/30 10pp
20946 344

--B310280177 Rev 1 to "Final Rept on Club Mesa Spray Sys Disposal Capacity"
MARTIN, R K, KYLE, W C Union Carbide Corp 83/09/30 13pp
20946 355

--B310280178 "Evaluation of Ground Water Seepage Collection Sys at A-9 Pit Below Grade Tailings" W/two oversize maps Aperture cards are available in PDR
HOWLETT, L H, HOFFMAN, G L Hydro-Engineering 83/09/30 49pp
20947 005

B310210146 Submits questions re inactive tailings area horizontal drains Questions must be addressed before issuance of permit to construct
HERMANSKY, J Wyoming, State of 83/09/23 WARDWELL, R E Water, Waste & Land, Inc 1p 20883 355

B310310406 EN-B3-070 on B31103, notice of violation and proposed imposition of civil penalty will be issued in amount of \$4,000 Action based on breakdown in mgt oversight & control of radiation safety program
FLACK, E, AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/10/27 1p 20959 183

DOCKET 40-0462 DOW CHEMICAL CO, MIDLAND, MI

B310110065 Further response to FOIA request for records re incineration of radioactive metals by Dow Chemical Co Midland, MI plant
Forwards App B documents Documents also available in PDR
FELTON, J H Division of Rules and Records 83/06/20 GARDE, B P
Government Accountability Project 2pp 20704 001

--B310110108 Forwards Insp Findings & Licensee Ack re activities under Licenses 21-00265-04, 518-527 & 518-111 & Div of Compliance
Form AEC-592 concerning noncompliance activities under Licenses 21-00265-02 & 21-00265-06
GRIER, B H Atomic Energy Commission 70/06/08 SILVERSTEIN, L
Dow Chemical Co 1p 20704 052

--B310110119 Insp Findings & Licensee Ack dtd 700519-20 of Licenses 518-527, 518-111 & 21-00265-04 Insp findings re noncompliance noted Related info encl
SCHULTZ, W H Atomic Energy Commission 70/06/08 16pp
20704 053

DOCKET 40-0672 NUCLEAR METALS, INC, CONCORD, MA

B31005016 Responds to NRC B30901 ltr re violations noted in IE Insp Rept on B30525-27 & 0608-10 & forwards remittance for civil penalty Corrective actions exposures to workers hands reevaluated Health physics staff will meet weekly
JHACQ, F J Nuclear Metals, Inc 83/09/30 Director's Office,
Office of Inspection and Enforcement 5pp 20634 121

B310270635 Responds to B30927 memo re civil penalties imposed on George Washington Univ Medical Ctr & Nuclear Metals, Inc Ltrs to licensees, notices of violation & Insp repts encl
DIRCKS, W J Office of the Executive Director for Operations
83/10/03 GILJNSKY, V Commissioners 1p 20946 041

--B310270637 Discusses IE Insp on B30601-02 & forwards notice of violation & proposed imposition of civil penalty
MURLEY, T E Region 1, Office of Director 83/09/01 LLONARD, F
George Washington Univ Medical Center Wash DC 3pp 20946 042

--B310270644 Notice of violation & proposed imposition of civil penalty in amount of \$2,500 Noncompliance noted adequate survey not performed to assure compliance w/10CFR20 106(a) re radioactive releases
MURLEY, T E Region 1, Office of Director 83/09/01 5pp
20946 045

--B310270647 Discusses IE Insp on B30525-27 & forwards notice of violation & proposed imposition of civil penalty
MURLEY, T E Region 1, Office of Director 83/09/01 TUFFIN, W B
Nuclear Metals, Inc 4pp 20946 074

--B310270652 Notice of violation & proposed imposition of civil penalty in amount of \$9,500 Noncompliance noted during Fourth Quarter 1982 & First Quarter 1983, 10-15 individuals exposed to high contamination levels
MURLEY, T E Region 1, Office of Director 83/09/01 4pp
20946 078

--B310270656 Requests description of noncompliances identified at George Washington Univ Medical Ctr & Nuclear Metals, Inc which resulted in proposed fines of \$2,500 & \$9,000 respectively
GILJNSKY, V Commissioners 83/09/21 AXELRAD, J Director's
Office, Office of Inspection and Enforcement 1p 20946 078

B310190226 Ack receipt of \$9,600 in full payment of civil penalties proposed on B30901
AXELRAD, J A Enforcement Staff 83/10/13 TUFFIN, W B Nuclear
Metals, Inc 2pp 20838 092

DOCKET 40-1341 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN

B310280321 Forwards info showing results of radiological/geotechnical hydrological investigations per decommissioning design project to assess suitability of Pond 10 as evaporation pond W/one oversize map Aperture card is available in PDR
MILLS, L M Tennessee Valley Authority 83/09/06 SMITH, R D
Uranium Recovery Field Office 24pp 20963 191

--B310280322 "Design Notes for Special Decommissioning Aspects, Geotechnical Evaluation of Pond 10"
* McLaren Engineers, Inc * Golder Associates 83/01/31
71pp 20963 217

B310260364 Forwards descriptions of two work activities planned to begin B31001 & to be completed before B31101, in support of Edgemont U Mill decommissioning project Activities will be conducted within existing license conditions
MILLS, L M Tennessee Valley Authority 83/09/21 SMITH, R D
Uranium Recovery Field Office 5pp 20918 351

DOCKET 40-2061 KERR-MCGEE CHEMICAL CORP, OKLAHOMA CITY, OK

B310170698 Advises that no comments have been received on EIA re state authorization to develop & enforce environ stds Future Federal capital grant requests should be enforced Requests copy of FES upon completion
CURTIS, M Illinois, State of 83/09/02 PAGE, R O Kerr-McGee
Chemical Corp (subs of Kerr-McGee Corp) 2pp 20798 157

B310120310 Advises that M Krippel will replace SC Munson as health physicist at West Chicago facility
SHELLEY, W J Kerr-McGee Corp 83/09/28 HIND, J Region 3, Office
of Director 1p 20701 010

B310120314 Responds to NRC B30831 ltr re violations noted in IE Insp Rept 40-2061/B3-02 Actions to reduce Pb-212 concentrations undertaken Rescission of notice of violation requested
DENNY, J L Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp)
83/09/30 KEPPLER, J O Region 3, Office of Director 8pp
20700 308

DOCKETED ITEMS

3

8310180392 Requests NRC written concurrence w/burial of PCB contaminated soil in EPA approved PCB landfill Thorium-natural soil concentrations, PCB contaminated soil table encl
SHELLEY, W J Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp)
83/07/30 NIXON, W A Uranium Fuel Licensing Branch 3pp
20829 360

8310250662 Requests notice of violation contained in IE Insp Rept
40-2061/83-02 be withdrawn
SHELLEY, W J Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp)
83/07/30 NIXON, W A Uranium Fuel Licensing Branch 1p
20900 109

8310310356 Ack receipt of 830930 request that citations contained in notice of violation in IE Insp Rept 40-2061/83-02 be rescinded as inappropriate Pertinent air sampling data currently under review
KEPPLER, J G Region 3, Office of Director 83/10/26 RAINEY, J L
Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) 1p
20960 285

--8310310362 Responds to NRC 830831 ltr re violations noted in IE Insp Rept 40-2061/83-02 on 830804 Citations re radiation surveys contained in notice of violation inappropriate & should be rescinded
DENNY, J L Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp)
83/07/30 KEPPLER, J G Region 3, Office of Director 8pp
20960 286

DOCKET 40-2259 PATHFINDER MINES CORP , RIVERTON, WY

8310030205 Submits personnel overexposure rept for Jan-June 1983, per Amend 16 to Condition 25 of License SUA-672 Two individuals exceeded 15-uCi natural U/liter limit of urine action level
* Pathfinder Mines Corp 83/08/30 Uranium Recovery Field Office 2pp 20602 358

8310280323 Forwards one oversize general land use map in response to NRC request Aperture card is available in PDR
SMITH, P J Pathfinder Mines Corp 83/09/15 WOODLEY, R J Uranium Recovery Field Office 1p 20964 361

8310260003 Forwards annual soil survey data not available when semiannual effluent monitoring rept, dtd 830831, submitted for License SUA-672
HARDORQUE, T W Pathfinder Mines Corp 83/09/26 WOODLEY, R J Uranium Recovery Field Office 1p 20928 048

--8310260006 Soil samples from 830615, omitted from 830831 semiannual effluent monitoring rept
* Pathfinder Mines Corp 83/09/26 4pp 20928 049

DOCKET 40-3392 ALLIED CHEMICAL CORP , MORRISTOWN, NJ

8310170623 Forwards amend to Allied Chemical License SUB-526, adding license conditions to Jul 1982 renewal application
CIPOLLA, A J Allied Chemical Corp 83/09/30 KOSLA, D Uranium Fuel Licensing Branch 2pp 20798 171

--8310170633 Revised application for amend to License SUB-526, adding license conditions section
* Allied Chemical Corp 83/09/30 29pp 20798 173

DOCKET 40-3453 ATLAS MINERALS, INC , DENVER, CO

8310190106 Responds to NRC 830825 ltr re violations noted in IE insp of License SUA-917 on 830726-28 Corrective actions alpha survey meter properly calibr using correct probe area dimensions
BLUBAUOH, R E Atlas Minerals 83/09/23 BROWN, O D Region 4, Office of Director, 3pp, 20822 107

8310190017 Ack receipt of 830923 ltr informing NRC of steps taken to correct violations noted in IE insp of License SUA-917
BROWN, O D NRC - No Detailed Affiliation Given 83/10/11
BLUBAUOH, R E Atlas Minerals 1p 20823 134

DOCKET 40-4192 FEDERAL AMERICAN PARTNERS, RIVERTON, WY

8310140299 Forwards supplementary info "Cleanup of Windblown Tailings Contamination to be Conducted W/Rerouting of Willow Springs Draw Near Federal American Partners U Milling Facilities at West Gas Hills, WY"
ANDRUB, N J American Nuclear Corp 83/08/22 GILLIN, D Uranium Recovery Field Office, 2pp 20794 084

--8310140297 Supplementary info "Cleanup of Windblown Tailings Contamination to be Conducted W/Rerouting of Willow Springs Draw Near Federal American Partners U Milling Facilities at West Gas Hills, WY" W/one oversize map Aperture card in PDR
* American Nuclear Corp 83/08/12 8pp 20794 086

DOCKET 40-4931 NAVY, DEPT OF, ANNAPOLIS, MD

8310210300 IE Insp Findings & Licensee Ack dtd 830923 of License SUB-564 Insp findings no noncompliance noted
* Region 1, Office of Director 83/09/23 1p 20855 214

DOCKET 40-6500 ENERGY, DEPT OF, CANONSBURG, PA

8310070211 Discusses items of interest Meeting held on 830921 w/C-E & Windsor, CT re C-E proposed license amend application to modify air sampling sys On 830915, NRC concurred in DOE remedial action plan for Canonsburg, PA site
PAGE, R G Uranium Fuel Licensing Branch 83/09/22 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 1p
20679 353

8310110441 Summary of 830915 & 21 meetings w/DOE & C-E re remedial action plan & proposed license amend application concerning mod of air sampling sys in Windsor plant, respectively
PAGE, R G Uranium Fuel Licensing Branch 83/09/22 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 1p
20714 341

8310180403 Summary of data from radon monitoring network in Canonsburg, PA area during 830428-0728 W/830930 ltr
RUDY, C R Monsanto Research Corp 83/09/30 CREW, W T Uranium Fuel Licensing Branch 4pp 20825 355

8310210099 Summary of 831007 meetings w/DOE in Canonsburg, PA & Silver Spring, MD re remedial actions to be taken to stabilize radioactive matl on Canonsburg site & decontamination of Latty Avenue site & vicinity properties
PAGE, R G Uranium Fuel Licensing Branch 83/10/12 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 1p
20883 315

DOCKET 40-6622 PATHFINDER MINES CORP , SHIRLEY BASIN, WY

8310030224 "Environ Monitoring Data W/Dose Calculations, Second Quarter 1983" W/830909 ltr
SMITH, J C Pathfinder Mines Corp 83/06/30 Uranium Recovery Field Office 30pp 20604 182

8308300607 Forwards "First Quarter 1983 Environ Monitoring Data w/Dose Calculations," per License Condition 37 Ingestion doses calculated for previous two quarters too large by factor of five
SMITH, J C Pathfinder Mines Corp 83/07/08 BROWN, O D Region 4, Office of Director 1p 20208 166

--8308300610 "First Quarter 1983 Environ Monitoring Data w/Dose Calculations"
* Pathfinder Mines Corp 83/07/08 26pp 20208 167

8310200456 Recommends License SUA-442 be amended by revising License Condition 36 to change frequency for exchanging & reading TLD chips from monthly to quarterly
GARCIA, P J, PETTENIILL, H Uranium Recovery Field Office 83/08/25 Uranium Recovery Field Office 2pp 20861 137

8310200471 Advises of issuance of amend to License SUA-442 revising Condition 36 by changing frequency for exchanging & reading TLD chips used for radon monitoring from monthly to quarterly
SMITH, R D Uranium Recovery Field Office 83/08/29 RUSSELL, J E Pathfinder Mines Corp 2pp 20844 348

8310250169 Requests answers to listed questions re Hinton & Whicker research paper "Field Experiment on Radon Flux From Reclaimed U Mill Tailings"
BEACH, O Wyoming, State of 83/09/08 HINTON, T Pathfinder Mines Corp 1p 20908 324

DOCKET 40-6659 GETTY OIL CO - PETROTONICS CO., SHIRLEY BASIN, WY

8310270545 Forwards rev to environ rept, dtd 810401, updating gamma, dust, radon & exposure data through 1982 & in some cases, through Aug 1983
PFAFF, S J Getty/Petrotonics Co 83/09/22 GARCIA, P Uranium Recovery Field Office 6pp 20938 039

DOCKETED ITEMS

B310030502 Forwards summary of data for leach area & dryer control room verification samples taken on 830517 No response required
Variation in U content will be pursued w/technical staff
EVERETT, R J Region 4, Office of Director 83/09/26 WHITMAN, J H
Getty/Petrochemicals Co 2pp 20601 167

B310260348 Forwards application to amend License SUA-551, reflecting current conditions or practices or to correlate w/monitoring frequency per Reg Guides B 30 & B 31
PFAFF, B J Getty/Petrochemicals Co 83/09/27 GARCIA, P Uranium Recovery Field Office 1p 20928 083

--B310260392 Application for amend to License SUA-551, reflecting current conditions or practices or to correlate w/monitoring frequency per Reg Guides B 30 & B 31
* Getty/Petrochemicals Co 83/09/22 11pp 20928 084

DOCKET 40-6940 KAWECKI BERYL CO IND., INC., BERYTOWN, PA

B310270576 Summarizes items of interest from DOE B31013 meeting, DDT B31014 meeting, Kerr-McGee B31018 meeting & Applied Health Physics, Inc B31018 meeting
PAGE, R O Uranium Fuel Licensing Branch 83/10/20 DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 1p 20944 001

DOCKET 40-7869 PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO

B310070402 Application for amend to License SUA-1013 to extend expiration date to 840331 Time will allow completion of decommissioning, submission of final rept & NRC site insp to terminate license
GERDEMAN, F W Plateau Resources, Ltd 83/09/02 SMITH, R D NRC - No Detailed Affiliation Given 1p 20664 272

B310200371 Advises of issuance of Amend 4 to License SUA-1013, revising Condition 4 to extend expiration date to 840630
SMITH, R D Uranium Recovery Field Office 83/09/30 Plateau Resources, Ltd 1p 20874 070

--B310200373 Safety evaluation supporting Amend 4 to License SUA-1013
HAWKINS, E F, LINEMAN, J J Uranium Recovery Field Office 83/09/30 2pp 20874 071

DOCKET 40-8027 KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK

B310180038 Forwards State of TX statutes & regulations defining "source matl," "byproduct matl" & "radioactive," NRC regulations defining "byproduct matl" & "source matl" & ltr from TX Dept of Health to Kerr-McGee
KOFFMAN, B Kerr-McGee Corp 83/09/20 CUNNINGHAM, R Division of Fuel Cycle & Material Safety 10pp 20838 074

B310070034 Advises of issuance of Amend 23 to License SUB-1010, in response to 830621 request to exempt treated raffinate storage ponds from spare pond requirements
PAGE, R O Uranium Fuel Licensing Branch 83/09/28 SHELLEY, W J Kerr-McGee Corp 1p 20671 358

--B310070037 Safety evaluation supporting Amend 23 to License SUB-1010, per 830621 request for continuation to 840901 of exemption from spare ponding requirements
KOSLA, B M, CROW, W T Uranium Fuel Licensing Branch 83/09/27 2pp 20671 359

B310270576 Summarizes items of interest from DOE B31013 meeting, DDT B31014 meeting, Kerr-McGee B31018 meeting & Applied Health Physics, Inc B31018 meeting
PAGE, R O Uranium Fuel Licensing Branch 83/10/20 DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 1p 20944 001

DOCKET 40-8035 COTTER CORP., ROSWELL, NM

B31010099 Summary of B31007 meetings w/DOE in Canonsburg, PA & Silver Spring, MD re remedial actions to be taken to stabilize radioactive matl on Canonsburg site & decontamination of Latty Avenue site & vicinity properties
PAGE, R O Uranium Fuel Licensing Branch 83/10/12 DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 1p 20883 315

DOCKET 40-8064 EXXON MINERALS CO., USA, HOUSTON, TX

B310260357 Forwards estimated reclamation bond approved by WY Dept of Environ Quality for Exxon Highland U operation re Licenses SUA-1139 & SUA-1064 Bond estimate revised annually to reflect current land status & reclamation plans
SHANNON, J B Exxon Corp 83/08/31 SMITH, R D Uranium Recovery Field Office 3pp 20918 298

DOCKET 40-8084 RIO ALGOM CORP., MOAB, UT

B310310375 Forwards IE Insp Rept 40-8084/B3-01 on 830523-26 No noncompliance noted
BROWN, G D Region 4, Office of Director 83/07/19 LAHTON, M D Rio Algom, Ltd 2pp 20960 002

--B310310380 IE Insp Rept 40-8084/B3-01 on 830523-26 No noncompliance noted Major areas inspected U milling operations & radiation safety program, including organization mgt & training & internal exposure & contamination control
SHOPENN, N M, EVERETT, R J Region 4, Office of Director 83/07/07 7pp 20960 004

B310060302 Forwards one oversize revised land use survey map, indicating changes in Township 29 South Range 24 East since 830215
Aperture card is available in PDR
PATTISON, R S Rio Algom, Ltd 83/09/12 SMITH, R D NRC - No Detailed Affiliation Given 1p 20664 145

DOCKET 40-8102 EXXON CO., USA, HOUSTON, TX

B310260357 Forwards estimated reclamation bond approved by WY Dept of Environ Quality for Exxon Highland U operation re Licenses SUA-1139 & SUA-1064 Bond estimate revised annually to reflect current land status & reclamation plans
SHANNON, J B Exxon Corp 83/08/31 SMITH, R D Uranium Recovery Field Office 3pp 20918 298

B310200349 Recommends administrative changes to License SUA-1139 re deletion of License Conditions 36 & 37 & rev of License Condition 35, per Low Level Waste Licensing Branch summary of environ monitoring data
PANGBURN, G C Uranium Recovery Field Office 83/09/28 Uranium Recovery Field Office 2pp 20874 270

B310200412 Supports amend to License SUA-1139 deleting reporting requirements under 40CFR190 Changes constitute Amend 5 to license Amend initiated by NRC for benefit of Commission & is exempt from fees
PANGBURN, G C Uranium Recovery Field Office 83/09/28 MILLER, W O License Fee Management Branch 1p 20844 360

B310240092 Advises of issuance of amend to License SUA-1139 deleting Conditions 36 & 37 & revising Condition 35 re environ & effluent monitoring procedures
SMITH, R D Uranium Recovery Field Office 83/09/28 Exxon Corp 1p 20903 197

DOCKET 40-8348 MINERALS EXPLORATION CO., LOS ANGELES, CA

B310180125 Advises that licensee intends to continue monitoring A-3 project site Sampling of wells will begin on 830926
VOLK, W G Union Oil Co of California 83/09/19 WASTLER, S Uranium Recovery Field Office 1p 20827 095

DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO., BROOMFIELD, CO

B310040601 Confirms 830913 telcon re draft review of licensee groundwater restoration repts for acid lixiviant test patterns at Nine Mile Lake facility Evaluation of potential environ impacts recommended
BROWN, W L Region 4, Office of Director 83/09/15 LINEHAN, J J NRC - No Detailed Affiliation Given 1p 20627 349

DOCKET 40-8452 BEAR CREEK URANIUM CO., CASPER, WY

B310030199 "Semiannual Environ Monitoring Rept, Jan-June 1983" w/B30030 ltr
BLOSSOM, J N Bear Creek Uranium Co 83/06/30 Uranium Recovery Field Office 17pp 20603 131

DOCKETED ITEMS

5

8310030241 Forwards tailings dam erosion analysis (App K to Nov 1981 tailings mgt plan), per Amend 20 to Condition 39 of License SUA-1310 Reduction of dam slope not necessary to meet goal of long-term erosion protection
MEDLOCK, R L Bear Creek Uranium Co 83/09/08 SMITH, R D Uranium Recovery Field Office 2pp 20604 151

--8310030250 "Bear Creek U Co Tailings Dam Erosion Analysis (App K to Nov 1981 Tailings Mgt Plan)"
* Bear Creek Uranium Co 83/09/30 29pp 20604 153

8310200419 Advises of issuance of Amend 21 to License SUA-1310 re expansion of present tailings disposal area
SMITH, R D Uranium Recovery Field Office 83/09/30 Bear Creek Uranium Co App 20844 356

8310240094 Advises of issuance of amend to License SUA-1310, revising Condition 51 by deleting previous language barring const of expanded disposal area until NRC authorization given & adding Subparagraphs e-i to license
PANGBURN, G C, PETTENGILL, H J Uranium Recovery Field Office 83/09/30 Uranium Recovery Field Office 7pp 20903 190

DOCKET 40-8502 WYOMING MINERAL CORP, LAKWOOD, CO

8310040605 Requests current form for application for permit to mine nr amend to permit to mine form needed to incorporate 800718 application for in situ R&D license w/B20201 rev to application to mine, per 830802 request
RUTLEDGE, C Wyoming Mineral Corp 83/09/08 CHANCELLOR, R A Wyoming, State of 1p 20627 350

8310210102 Forwards application for renewal of Source Matl License SUA-1241
RUTLEDGE, C Wyoming Mineral Corp 83/09/28 Division of Fuel Cycle & Material Safety 2pp 20883 273

--8310210107 Application for renewal of Source Matl license SUA-1241
RUTLEDGE, C Wyoming Mineral Corp 83/09/26 40pp 20883 275

DOCKET 40-8584 MINERALS EXPLORATION CO, LOS ANGELES, CA

8310030221 Forwards summary of environ monitoring & meteorological conditions, per Section 5 & Conditions 34, 43 & 48 of License SUA-1350 Environ monitoring will be modified by Amend 12 to reflect suspension of milling operations
KLEIN, T J Union 76 Minerals Exploration Co 83/08/31 SMITH, R D Uranium Recovery Field Office 78pp 20604 073

8310030203 Forwards "Rept of Engineering Assessment, Present Pond Liner Sys Tailings Impoundment, Sweetwater U Project, Near Rawlins, WY for Minerals Exploration Co" & "Tailings Impoundment Leak Analysis"
KLEIN, T J Union 76 Minerals Exploration Co 83/09/07 SMITH, R D Uranium Recovery Field Office 2pp 20603 078

--8310030210 "Rept of Engineering Assessment, Present Pond Liner Sys Tailings Impoundment, Sweetwater U Project Near Rawlins, WY for Minerals Exploration Co"
BODDY, J R Union 76 Minerals Exploration Co 83/07/29 19pp 20603 080

--8310030215 "Tailings Impoundment Leak Analysis"
* Water, Waste & Land, Inc 83/09/30 32pp 20603 097

8310200446 Discusses Amend 12 to Source Matl License SUA-1350 to reduce or suspend certain environ & in-plant monitoring requirements during period of shutdown & reduction in monitoring programs
GARCIA, P J, PETTENGILL, H J Uranium Recovery Field Office 83/09/22 Uranium Recovery Field Office 5pp 20859 334

8310200438 Advises of amend to License SUA-1350 adding Condition 53 re reducing or suspending air particulate sample requirements during period of suspended operations at Sweetwater Mill
SMITH, R D Uranium Recovery Field Office 83/09/23 HILL, C Z Minerals Exploration Co (subs of Union Oil Co of California) 2pp 20859 332

8310240045 Submits const analysis of single vs double liner leak detection sys at U Mill Tailings Pond TFR 1 5/294, per 830510 meeting w/NRC & Minerals Exploration Co
LIDSTONE, C Wyoming State of 83/09/23 BEACH, G Wyoming, State of 4pp 20903 230

DOCKET 40-8599 AIR FORCE, DEPT OF, DROOKS AFB, TX

8310270417 Responds to NRC 830913 ltr re special safety insp of license SMO-1314 Maint work scheduled to prevent further leakage into process sewer sys at Weldon Spring Chemical Plant
REGISTER, B F Army, Dept of 83/10/18 Region 3, Office of Director 3pp 20923 082

DOCKET 40-8674 PLATEAU RESOURCES, LTD, GRAND JUNCTION, CO

8310180133 Effluent monitoring rept for Jan-June 1983 W/830826 ltr
GERDEMAN, F W Plateau Resources, Ltd 83/06/30 Region 4, Office of Director 10pp 20827 067

8310200452 Recommends changes to License Conditions 10 & 19 to License SUA-1326 re organizational changes for Ore Buying Station
JOHNSON, T L, LINEHAN, J J Uranium Recovery Field Office 83/08/25 Uranium Recovery Field Office 3pp 20861 134

8310200470 Advises of issuance of amend to License SUA-1326, revising Conditions 10 & 19 re occupational radiation safety program & ALARA program, respectively
SMITH, R D Uranium Recovery Field Office 83/08/25 Plateau Resources, Ltd 2pp 20844 350

DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC, DENVER, CO

8310240090 Advises of issuance of amend to License SUA-135B adding Condition 27 to establish revised tailings reclamation plan & setting requirements for rev to reclamation configuration as tailings disposal increases
SMITH, R D Uranium Recovery Field Office 83/09/12 Energy Fuels Nuclear, Inc 2pp 20903 198

--8310240095 Discusses vendor 830521 request for Amend 22 to License SUA-135B amending requirements re tailings reclamation cover License Condition 27 should be revised
GILLEN, D M, LINEHAN, J J Uranium Recovery Field Office 83/09/12 Uranium Recovery Field Office 5pp 20903 200

DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO, DENVER, CO

8310200342 Application for extension of License SUA-1338 to authorize final site-closure activities
NEUMANN, M R Rocky Mountain Energy Co 83/08/30 LINEHAN, J Uranium Recovery Field Office 1p 20874 069

DOCKET 40-8698 PLATEAU RESOURCES, LTD, GRAND JUNCTION, CO

8310180104 Effluent monitoring rept for Jan-June 1983 W/830826 ltr
GERDEMAN, F W Plateau Resources, Ltd 83/06/30 Region 4, Office of Director 52pp 20823 306

8310180384 Submits review of licensee environ monitoring repts for 1982 Licensee has met all license requirements for interim period prior to plant operation but failed to provide chemical parameter data for groundwater samples
JOHNSON, T L Uranium Recovery Field Office 83/07/25 Uranium Recovery Field Office 9pp 20827 001

8310180129 Addendum to effluent monitoring rept for 1982 W/830902 ltr
GERDEMAN, F W Plateau Resources, Ltd 83/08/30 SMITH, R D Uranium Recovery Field Office 15pp 20827 080

8310270519 Advises that License SUA-1371 amended by modifying Conditions 38 & 39, approving revised reclamation plan & deleting requirement for submittal of revised surety instrument
SMITH, R D Uranium Recovery Field Office 83/09/27 Plateau Resources, Ltd 3pp 20937 206

--8310270524 Discusses vendor 830412 & 0620 requests for Amend 8 to License SUA-1371, requesting changes to existing reclamation plan & decreasing amount of surety Rev to License Conditions 38 & 39 recommended
JOHNSON, J L, LINEHAN, J J Uranium Recovery Field Office 83/09/27 Uranium Recovery Field Office 5pp 20937 209

DOCKETED ITEMS

DOCKET 40-8714 CLEVELAND-CLIFFS IRON CO , CLEVELAND, OH

8310240052 Submits info to document use of best practicable technology to restore groundwater quality at Collins Draw Project site
LOUDERBACK, T E Cleveland-Cliffs Iron Co 83/09/23 SHAFFER, R
Wyoming, State of 15pp 20903 216

DOCKET 40-8745 OGLE PETROLEUM, INC , CASPER, WY

8310180172 "Fourth Semiannual Rept.830219-0826 " W/830916 ltr
CATCHPOLE, G J Ogle Petroleum, Inc 83/08/26 SMITH, D Uranium
Recovery Field Office 152pp 20824 130

DOCKET 40-8768 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK

8310180138 Recommends that R&D license for "D" Sand Project not be issued
Results of second pump test, baseline water quality & monitor well water quality must be received before license can be issued
OGLE, M M Energy, Dept of 83/09/16 Energy, Dept of 5pp
20827 059

8310260377 Forwards responses to WY Dept of Environ Quality 830526 comments & questions re G-Sand ISL project, per D Gillen request
FREEMAN, M D Kerr-McGee Nuclear Corp 83/10/03 LINEHAN, J J
Uranium Recovery Field Office 26pp 20921 194

8310260411 Application for amend to License SUA-1387 increasing total dissolved solids & sulfate levels for monitor well GHW-1
Table confirming increased levels due to natural groundwater quality fluctuations & license amend fee encl
FREEMAN, M Kerr-McGee Nuclear Corp 83/10/05 LINEHAN, J J
Uranium Recovery Field Office 10pp 20918 335

DOCKET 40-8781 TETON EXPLORATION DRILLING CO , INC , CASPER, WY

8310270141 Forwards Source Matl License SUA-1403
SMITH, R D Uranium Recovery Field Office 83/09/30 APPEL, R
Teton Exploration Drilling Co , Inc 1pp 20939 108

-8310270157 Source Matl License SUA-140J for UNC Teton Exploration Drilling, Inc authorizing U recovery & processing & const of evaporation pond areas
Uranium Recovery Field Office 83/09/30 11pp 20939 109

DOCKET 40-8783 URANERZ USA, INC , CASPER, WY

8310260414 Forwards application for amend to License SUA-1401 proposing reduced well number for stabilization monitoring period
Approval requested prior to start of restoration phase of Ruth ISL R&D project
SCHERVILLE, M O Uranerz USA, Inc 83/09/29 LINEHAN, J J Uranium
Recovery Field Office 1p 20928 073

-8310260418 Application for amend to License SUA-1401, proposing reduced well number for stabilization monitoring period
Uranerz USA, Inc 83/09/29 8pp 20928 074

DOCKET 40-8786 URANIUM RESOURCES, INC , RICHARDSON, TX

8310030559 Comments on MS Pelizza 830808 ltr re addl decommissioning plans for License 10RD Sand & sludge removal from evaporation ponds recommended
RANCEN, L D , SMITH, M A Wyoming, State of 83/09/12 LINEHAN, J J
Uranium Recovery Field Office 1p 20607 361

8310210123 Forwards gamma survey for North Platte well field & documents commitment to maintain at least 6 inches of water in two solar evaporation ponds or removal of all sand & sludge within pond
PELIZZA, M S Uranium Resources, Inc 83/09/22 JOHNSON, T NRC -
No Detailed Affiliation Given 2pp 20883 329

DOCKET 40-8794 MOLYCORP, INC , LOS ANGELES, CA

8310070087 Forwards amend fee in response to 830726 approval of 830704 proposal to discontinue personal dosimetry badge program
DOUGLASS, S J MolyCorp, Inc 83/08/02 WEISS, D License Fee
Management Branch 1p 20681 024

--8310070090 Requests payment of fee for review of 830706 request for amend to License SNB-140U
WEISS, D License Fee Management Branch 83/07/24 DOUGLASS, S J
MolyCorp, Inc 1p 20681 025

--8310070092 Application for amend to License SNB-140U, deleting dosimetry program Dosimetry badge results & radiation monitoring repts for 1983 encl
DOUGLASS, S J MolyCorp, Inc 83/07/06 SOONG, A L NRC - No
Detailed Affiliation Given 17pp 20681 026

8310050177 Issues Amend 3 to License SNB-140U authorizing discontinuation of personnel dosimeter monitoring program at York Facility Safety evaluation encl
PAGE, R G Uranium Fuel Licensing Branch 83/09/21 WARRICK, W M
MolyCorp, Inc 1p 20639 359

--8310050181 Safety evaluation supporting Amend 3 to License SNB-140U
SOONG, A L Uranium Fuel Licensing Branch 83/09/20 2pp
20639 360

DOCKET 40-8801 RADIATION MANAGEMENT CORP , NORTHBROOK, IL

8310170308 Summarizes 830830 visit to West Lake Landfill Site in St Louis, MO Second visit expected on 830921 to obtain info on landfill from MO Dept of Natural Resources & City of Bridgton Files
O'CONNOR, J T , BANERJI, S K Missouri, Univ of, Columbia, MO
83/09/19 WYNGARDEN, S NRC - No Detailed Affiliation Given
BERGER, J Oak Ridge Associated Univ App 20794 129

8310200409 Requests permission to perform radioactivity measurements, soil, surface & water in West Lake landfill area, to confirm Radiation Mgt Corp study
BANERJI, S K , O'CONNOR, J T Missouri, Univ of, Columbia, MO
83/09/29 WYNGARDEN, S NRC - No Detailed Affiliation Given 1p
20859 218

DOCKET 40-8807 AIR FORCE, DEPT OF, TINKER AFB, OK

8310030400 IE Insp Findings & Licensee Ack dtd 830824 of License STB-1407 Insp Findings no violations observed
HODGER, C A Region 4, Office of Director 83/08/24 1p
20593 074

DOCKET 40-8829 WYOMING FUEL CO , LAKEWOOD, CO

8310260373 Forwards State of NE Game & Parks Commission & NE State Historical Soc ltrs re impact of Crowe Butte project on cultural resources & endangered species, per J Linchan 830/04 request
STOUT, D M Wyoming Fuel Co 83/10/06 WASTLER, S Uranium Recovery
Field Office 3pp 20918 350

DOCKET 40-8839 SANTA FE MINING, INC , ALBUQUERQUE, NM

8310180136 Advises that as result of 830414 meeting & addl review of Neuman-Hutherspoon theory, adjustment of proposed pump test made
HOFFMAN, G L Hydro-Engineering 83/09/21 LINEHAN, J NRC - No
Detailed Affiliation Given WILLIAMS, R R C Williams & Associates
Inc BOKICH, J Santa Fe Engineers, Inc 3pp 20827 064

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV OF MICHIGAN RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8310210124 Forwards Amend 28 to License R-79 re updates to physical security plan Changes meet requirements of 10CFR/73 & 74
THOMAS, C D Standardization & Special Projects Branch 83/10/17
KERR, W F Michigan, Univ of, Ann Arbor, MI 3pp 20883 316 24X
Fiche 50-002, 83/10/17, 8310210124

--8310210132 Amend 28 to License R-79, incorporating latest requirements for updated physical security plan
THOMAS, C D Standardization & Special Projects Branch 83/10/17
2pp 20883 319 24X Fiche 50-002, 83/10/17, 8310210124

DOCKETED ITEMS

7

F Operating license stage documents & correspondence

8310210124 Forwards Amend 28 to License R-79 re updates to physical security plan changes meet requirements of 10CFR73.67
THOMAS, C O Standardization & Special Projects Branch 83/10/17
KERR, W F Michigan, Univ of, Ann Arbor, MI 3pp 20883 316 24X
Fiche 50-002, 83/10/17, 8310210124

--8310210132 Amend 28 to License R-79, incorporating latest requirements for updated physical security plan
THOMAS, C O Standardization & Special Projects Branch 83/10/17
2pp 20883 319 24X Fiche 50-002, 83/10/17, 8310210124

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8310050548 Forwards post-exercise/post-drill assessments, per JS Bragg 830608 commitment Previously noted deficiencies corrected
MCLOUGHLIN, D Federal Emergency Management Agency 83/09/29
DIRCKS, W J Office of the Executive Director for Operations 2pp
20629 267 24X Fiche 50-003, 83/09/29, 8310050548

--8310050552 Post-exercise assessment of 830824-25 exercise, Rockland County, for Indian Point Nuclear Power Station
* Federal Emergency Management Agency 83/09/26 56pp
20629 269 24X Fiche 50-003, 83/09/29, 8310050548

--8310050554 Post-drill assessment of 830823 drill of Westchester County bus evacuation procedures for Indian Point Nuclear Power Station
* Federal Emergency Management Agency 83/09/15 7pp
20629 328 24X Fiche 50-003, 83/09/29, 8310050548

8310130111 Forwards application for amend to Licenses DPR-5 & DPR-26 incorporating changes to facility organization structure re position of fire protection & safety administrator
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/09/29
VARQA, S A Operating Reactors Branch 1 2pp 20726 294 24X
Fiche 50-003, 83/09/29, 8310130111

--8310130115 Application for amend to Licenses DPR-5 & DPR-26 incorporating changes to facility organization structure re position of fire protection & safety administrator
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/09/29
2pp 20726 296 24X Fiche 50-003, 83/09/29, 8310130111

--8310130119 Proposed Tech Spec incorporating changes to facility organization structure re fire protection & safety administrator
* Consolidated Edison Co of New York, Inc 83/09/29 10pp
20726 298 24X Fiche 50-003, 83/09/29, 8310130111

8310260304 Forwards mods to physical security plan, per 821109 request Mods withheld (ref 10CFR2 790 & 10CFR73 21)
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/10/14
VARQA, S A Operating Reactors Branch 1 2pp 20910 324 24X
Fiche 50-003, 83/10/14, 8310260304

8310280253 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/25 Document
Management Branch 1p 20962 318 24X Fiche 50-003, 83/10/25, 8310280253

--8310280261 Forwards public version of revised emergency plan implementing procedures, including Procedures IP-1002 re emergency notification & communication & IP-1023 re operational support ctr
O'TOOLE, J D, GAUNY, R D Consolidated Edison Co of New York, Inc 83/05/06
ALLAN, J M Region 1, Office of Director 3pp
20962 319 24X Fiche 50-003, 83/10/25, 8310280253

--8310280267 Public version of revised emergency plan implementing procedures, including Procedures IP-1002 re emergency notification & communication & IP-1023 re operational support ctr
* Consolidated Edison Co of New York, Inc 83/05/02 56pp
20962 322 24X Fiche 50-003, 83/10/25, 8310280253

F Operating license stage documents & correspondence

8310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR
CONNER, L Affiliation Unknown 83/05/02 NRC - No Detailed
Affiliation Given, 1p 21004 270 24X Fiche 50-000, 83/05/02, 8310310017,

8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which repts are unavailable
FELTON, J M Division of Rules and Records 83/07/06 CONNER, L
Affiliation Unknown 1p 21004 271 24X Fiche 50-000, 83/07/06, 8310310031

8310130111 Forwards application for amend to Licenses DPR-5 & DPR-26 incorporating changes to facility organization structure re position of fire protection & safety administrator
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/09/29
VARQA, S A Operating Reactors Branch 1 2pp 20726 294 24X
Fiche 50-003, 83/09/29, 8310130111

--8310130115 Application for amend to Licenses DPR-5 & DPR-26 incorporating changes to facility organization structure re position of fire protection & safety administrator
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/09/29
2pp 20726 296 24X Fiche 50-003, 83/09/29, 8310130111

--8310130119 Proposed Tech Spec incorporating changes to facility organization structure re fire protection & safety administrator
* Consolidated Edison Co of New York, Inc 83/09/29 10pp
20726 298 24X Fiche 50-003, 83/09/29, 8310130111

Q Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Holder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20777 350 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR80 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning, Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761.

T Hearing transcripts on non-antitrust matters

8310120029 Transcript of 831003 open session in Washington, DC re emergency planning Pp 1-28 Supporting documentation encl
* Commissioners 83/10/03 11pp 20750 076 24X
Fiche 50-003, 83/10/03, 8310120029

DOCKETED ITEMS

DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

8310180382 Forwards IE Mgt Meeting Rept 50-005/83-58 on 830812
STAROSTECKI, R Region 1, Office of Director 83/10/03 LEVINE, S
Pennsylvania State Univ, University Park, PA 2pp 20803 203 24X
Fiche 50-005, 83/10/03, 8310180382

--8310180386 IE Mgt Meeting Rept 50-005/83-58 on 830812 Major areas
discussed impact of decentralization of operator licensing
FERLIC, K, KELLER, R Region 1, Office of Director 83/09/26
2pp 20803 205 24X Fiche 50-005, 83/10/03, 8310180382

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8310040121 Releases public version of revised emergency plan
implementing procedure
FELTON, J M Division of Rules and Records 83/09/22 Document
Management Branch 1p 20634 341 24X Fiche 50-010, 83/09/22,
8310040121

--8310040136 Public version of Rev 0 to Emergency Plan Implementing
Procedure EPIP 300-16, "Radiation Surveys Under Accident
Conditions " W/830913 ltr receipt form procedure history &
safety evaluation
SCOTT, D J Commonwealth Edison Co 83/09/09 10pp 20634 342
24X Fiche 50-010, 83/09/22, 8310040121

8310270009 Releases public version of revised emergency plan
implementing procedure
FELTON, J M Division of Rules and Records 83/10/21 Document
Management Branch 1p 20940 167 24X Fiche 50-010, 83/10/21,
8310270009

--8310270017 Public version of Rev 5 to Emergency Plan Implementing
Procedure EPIP 300-1, "Initial Notifications & Generating
Station Emergency Plan Responses (Primary Responsibility -
Station Director) " W/831014 ltr
SCOTT, D J Commonwealth Edison Co 83/10/03 DENTON, H R Office
of Nuclear Reactor Regulation, Director 20pp 20940 168 24X
Fiche 50-010, 83/10/21, 8310270009

8310270526 Releases public version of revised emergency plan
implementing procedure
FELTON, J M Division of Rules and Records 83/10/21 Document
Management Branch 1p 20937 216 24X Fiche 50-000, 83/10/21,
8310270526

3310270937 Public version of Rev 2 to Emergency Plan Implementing
Procedure EDF-6, "Administration & Logistics Manager " W/831017 ltr & receipt form
NELLIS, C A, HESSNER, R, MOORE, R D Commonwealth Edison Co
83/02/18 DENTON, H R NRC - No Detailed Affiliation Given 7pp
20937 217 24X Fiche 50-000, 83/10/21, 8310270526

10280307 Releases public version of revised generating stations
emergency plan telephone directory
FELTON, J M Division of Rules and Records 83/10/25 Document
Management Branch 1p 20963 126 24X Fiche 50-000, 83/10/25,
8310280307

--8310280314 Public version of revised generating stations emergency
plan telephone directory
GALLE, D P, MOORE, R D Commonwealth Edison Co 83/08/11
DENTON, H R Office of Nuclear Reactor Regulation, Director 64pp
20963 127 24X Fiche 50-000, 83/10/25, 8310280307

8310280191 Releases public version of revised emergency plan
implementing procedure
FELTON, J M Division of Rules and Records 83/10/26 Document
Management Branch 1p 20962 266 24X Fiche 50-000, 83/10/26,
8310280191

--8310280209 Public version of Rev 1 to Emergency Plan Implementing
Procedure EDF-15, "Emergency Operations Facility
Activation " MOORE, R D Commonwealth Edison Co 83/08/02 50pp 20962 267
24X Fiche 50-000, 83/10/26, 8310280191

G Adjudicatory correspondence

8310070156 Forwards Director's Decision 83-14, denying 830909 10CFR2 206
petition re transport of spent nuclear fuel from
West Valley
DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director
83/09/30 CELEBREZZE, A J Ohio, State of 2pp 20680 308 24X
Fiche 50-000, 83/09/30, 8310070156

--8310070161 Forwards Director's Decision 83-14, denying 830824 10CFR2 206
petition re transport of spent nuclear fuel from
West Valley
DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 83/09/30 RESNIKOFF, M Sierra Club 1p
20680 309 24X Fiche 50-000, 83/09/30, 8310070156

--8310070147 Notice of issuance of Director's Decision 83-14, denying
State of OH & Sierra Club 830909 & 0824, respectively,
10CFR2 206 petitions re transport of spent nuclear fuel from
West Valley
DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 83/09/30 2pp 20680 310 24X
Fiche 50-000, 83/09/30, 8310070156

--8310070171 Director's Decision 83-14, denying State of OH & Sierra Club
830909 & 0824, respectively, 10CFR2 206 petitions re
transport of spent nuclear fuel from West Valley Request for
hearing & for preparation of EIS denied
DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 83/09/30 18pp 20680 312 24X
Fiche 50-000, 83/09/30, 8310070156

8310270297 Order extending time until 831128 for Commission to nrt ltr
review Director's Decision DD-83-14, denying Sierra Club &
State of OH requests
CHILK, S J Office of the Secretary of the Commission 83/10/25
Commissioners 1p 20923 195 24X Fiche 50-000, 83/10/25,
8310270297

J Insurance & indemnity information

8310240071 Forwards Endorsements 149 & 150 to NELIA Policy NF-43 &
Endorsements 126 & 127 to MALLU Policy MF-22
OSTER, J Commonwealth Edison Co 83/10/13 BALTZMAN, J Assistant
Director for State & License Relations 5pp 20881 335 24X
Fiche 50-010, 83/10/13, 8310240071

P Operating license stage documents & correspondence

8310070020 Ack receipt of 830824 ltr requesting Commission publish
notice of pending license amend in FR re New York State
Energy R&D Authority license for utils w/irradiated fuel
storage facilities
DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director
83/09/22 RESNIKOFF, M Sierra Club 1p 20671 361 24X
Fiche 50-000, 83/09/22, 8310070020

--8310070025 Notice of issuance of Sierra Club request that Commission
take action to amend New York State Energy R&D Authority
license for utils w/irradiated fuel storage facilities
DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 83/09/22 1p 20671 362 24X
Fiche 50-000, 83/09/22, 8310070020

8310260001 Forwards addl info requested in NRC 830316 ltr re util
response to SEP Topic 111-4 A, "Tornado Missiles " Cooling
water to HXs is supplied from svc water sys which is
independent from condensate storage tank
RYBAK, B Commonwealth Edison Co 83/10/18 GILBERT, R Operating
Reactors Branch 5 18pp 20912 206 24X Fiche 50-010, 83/10/18,
8310260001

8310280147 Forwards 830930 Director's Decision 83-14, denying State of
OH & Sierra Club 10CFR2 206 petitions re transportation of
spent fuel from West Valley facility, per 830930 request
CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 83/10/18
MILLER, F Environmental Policy Institute 2pp 20961 329 24X
Fiche 50-000, 83/10/18, 8310280147

G Inspection reports, IE Bulletins & correspondence

8308030340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder
Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308030340

DOCKETED ITEMS

9

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20777 350 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 119pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310200124 Forwards IE Mgt Meeting Repts 50-010/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIUS, C E Division of Project & Resident Programs 83/10/04
REED, C Commonwealth Edison Co 2pp 20834 098 24X
Fiche 50-000, 83/10/04, 8310200124

--8310200148 IE Mgt Meeting Repts 50-020/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIUS, C E Division of Project & Resident Programs DAVIS, A H
Region 3, Office of Director 83/10/03 App 20834 100 24X
Fiche 50-000, 83/10/04, 8310200124

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8310210053 Forwards IE Insp Repts 50-010/83-17, 50-237/83-26 & 50-249/83-24 on 830829-31, 0901, 02 & 08 & notice of violation
PAPERIELLO, C J Region 3, Office of Director 83/10/07 REED, C
Commonwealth Edison Co 2pp 20855 286 24X Fiche 50-010, 83/10/07, 8310210053

--8310210061 Notice of violation from insp on 830829-31, 0901, 02 & 08
PAPERIELLO, C J Region 3, Office of Director 83/10/07 2pp
20855 288 24X Fiche 50-010, 83/10/07, 8310210053

--8310210074 IE Insp Repts 50-010/83-17, 50-237/83-26 & 50-249/83-24 on 830829-31, 0901, 02 & 08 Noncompliance noted inadequate calibr of D-1 & D-2/3 chimney monitors & failure to follow procedures re radiation protection
PAUL, R A, HUETER, L J, GREGER, L R Region 3, Office of Director 83/10/07 8pp 20885 290 24X Fiche 50-010, 83/10/07, 8310210053

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310140036 Ack receipt of 830922 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/83-09, 50-237/83-14 & 50-249/83-13
NORELIUS, C Division of Project & Resident Programs 83/10/11
REED, C Commonwealth Edison Co 1p 20767 341 24X
Fiche 50-010, 83/10/11, 8310140036

--8310140049 Responds to NRC 830823 ltr re violations noted in IE Insp Repts 50-010/83-09, 50-237/83-14 & 50-249/83-13 Corrective actions operations personnel closed & latched all battery charger cabinets
FARRAR, D L Commonwealth Edison Co 83/09/22 KEPPLER, J O
Region 3, Office of Director 5pp 20767 342 24X
Fiche 50-010, 83/10/11, 8310140036

8310140099 Ack receipt of 830916 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/83-12, 50-237/83-20 & 50-249/83-18
NORELIUS, C E Division of Project & Resident Programs 83/10/11
REED, C Commonwealth Edison Co 1p 20766 099 24X
Fiche 50-010, 83/10/11, 8310140099

--8310140104 Responds to NRC 830721 ltr re violations noted in IE Insp Repts 50-010/83-12, 50-237/83-20 & 50-249/83-18 Corrective actions scope & general method of training program completely detailed in training procedures
FARRAR, D L Commonwealth Edison Co 83/09/16 KEPPLER, J O
Region 3, Office of Director 8pp 20766 100 24X
Fiche 50-010, 83/10/11, 8310140099

8310180268 Clarifies NRC position re procedures for admitting NRC personnel to facilities Access should be afforded to Region III personnel listed in encl Update will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 REED, C
Commonwealth Edison Co 7pp 20802 302 24X Fiche 50-010, 83/10/14, 8310180268

S Reportable occurrences, LERs & related correspondence

8310260008 Addl response to FOIA request for 17 categories of records Forwards documents listed in Apps B, C & D Info re fraudulent practices of Ray Miller, Inc available in PDR
FELTON, J M Division of Rules and Records 83/06/23 CLEWEY, J
Public Citizen Litigation Group 15pp 20290 001 24X
Fiche 50-000, 83/06/23, 8310260008

--8310260096 Describes facility 821203 flood & corrective actions taken Chronology of events encl, including notification of event & procedure for briefing commissioner
PERKINS, K E NRC - No Detailed Affiliation Given 83/06/08
DEVYUNG, R C Director's Office, Office of Inspection and Enforcement 11pp 20721 136 24X Fiche 50-010, 83/06/23, 8310260008

8310060428 PNO-III-83-089 on 830929, temporary restraining order requested to prevent shipment of spent reactor fuel through State of OH denied Pretrial conference set for 831006 Local govt's alleged inadequate preparation by local agencies
STRASMA, J, MENCZER, W Region 3, Office of Director 83/09/30
2pp 20641 221 24X Fiche 50-000, 83/09/30, 8310060428

8310070301 Potential Part 21 rept re underrange characteristic of Model N-E10M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERDERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X
Fiche 50-000, 83/09/30, 8310070301

DOCKET 50-18 VALLECITOS BOILING WATER REACTOR

Q Inspection reports, IE Bulletins & correspondence

8310040391 Forwards IE Insp Repts 50-018/83-01 & 50-183/83-01 on 830907 No noncompliance noted
WENSLAWSKI, F Region 5, Office of Director, 83/09/15
DARRITZEL, R W General Electric Co 2pp 20620 124 24X
Fiche 50-018, 83/09/15, 8310040391

--8310040399 IE Insp Repts 50-018/83-01 & 50-183/83-01 on 830907 No noncompliance noted Major areas inspected organization, procedures, surveys, posting & annual repts
SHERMAN, C I, WENSLAWSKI, F A Region 5, Office of Director 83/09/15 3pp 20620 126 24X Fiche 50-018, 83/09/15, 8310040391.

DOCKET 50-20 MASSACHUSETTS INST OF TECH RES REACTOR

F Security, medical, emergency & fire protection plans

8310130216 Requests extension until 840120 for implementation of emergency plan per 830624 ltr Addl time will allow for exchange of ideas during reactor managers meeting & intl symposium on uses of low & medium flux research reactors
CLARK, L Massachusetts Institute of Technology, Cambridge, MA 83/10/05 THOMAS, C O Standardization & Special Projects Branch.
1p 20725 049 24X Fiche 50-020, 83/10/05, 8310130216.

DOCKETED ITEMS

DOCKET 50-27 WASHINGTON STATE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

B310030143 Requests extension of B31019 submittal date for changes to B01220 security plan to B31115, per B30919 ltr
 WILSON, W E Washington State Univ., Pullman, WA 83/09/27
 THOMAS, C O Standardization & Special Projects Branch 1p
 20590 038 24X Fiche 50-027, B3/09/27, B310030143

--B310030151 Advises of Region V assumption of responsibility for review of changes to licensee security plans, safeguards contingency plans & guard training & qualification plans, per 10CFR50.54(p)
 SCHUSTER, H D Region 5, Office of Director 83/09/21
 WILSON, W E Washington State Univ., Pullman, WA 1p 20590 039
 24X Fiche 50-027, B3/09/27, B310030143

B310210088 Responds to B30927 request to extend submittal of security plan changes until B31115 Changes requested do not fall within scope of 10CFR50.54(p) Extension denied
 THOMAS, C O Standardization & Special Projects Branch 83/10/17
 WILSON, W E Washington State Univ., Pullman, WA 1p 20883 338
 24X Fiche 50-027, B3/10/17, B310210088

G Inspection reports, IE Bulletins & correspondence

B310310239 Forwards IE Insp Rept 50-027/B3-01 on B30919-21 & notice of violation w/o notice of violation
 SCARANO, R A Division of Radiological Safety & Safeguards Program 83/10/14
 WILSON, W E Washington State Univ., Pullman, WA 2pp
 20947 195 24X Fiche 50-027, B3/10/14, B310310239

--B310310241 IE Insp Rept 50-027/B3-01 on B30919-21 Noncompliance noted failure to calibr continuous air monitor sys as required by Tech Spec 4.3.3
 SHERMAN, C I, MENSLANSKI, F A Region 5, Office of Director 83/10/14 6pp
 20947 197 24X Fiche 50-027, B3/10/14, B310310239

DOCKET 50-29 YANKEE-ROHE NUCLEAR POWER STATION

F Security, medical, emergency & fire protection plans

B310120137 Forwards IE Safeguards Insp Rept 50-029/B3-10 on B30725-29 & notice of violation
 MARTIN, T T Division of Engineering & Technical Programs 83/09/10
 HEIDER, L H Yankee Atomic Electric Co 2pp 20695 281 24X
 Fiche 50-029, B3/09/10, B310120137

--B310120139 Notice of violation from insp on B30725-29
 * Region 1, Office of Director 83/09/10 1p 20695 283 24X
 Fiche 50-029, B3/09/10, B310120137

--B310120143 IE Safeguards Insp Rept 50-029/B3-10 on B30725-29 Noncompliance noted failure to record required training data
 DUNLOP, J M, MARTIN, W C, GODY, A T Region 1, Office of Director 83/09/09 3pp
 20695 284 24X Fiche 50-029, B3/09/10, B310120137

B310270184 Forwards IE Insp Rept 50-029/B3-12 on B30823-25 No noncompliance noted
 MARTIN, T T Division of Engineering & Technical Programs 83/10/07
 HEIDER, L H Yankee Atomic Electric Co 2pp 20924 176 24X
 Fiche 50-029, B3/10/07, B310270184

--B310270194 IE Insp Rept 50-029/B3-12 on B30823-25 No noncompliance noted Major areas inspected Phase II of annual emergency exercise performed on B30824
 SMITH, R H Region 1, Office of Director CROCKER, H W Division of Engineering & Technical Programs 83/09/28 6pp
 20924 178 24X Fiche 50-029, B3/10/07, B310270184

B310270532 Releases public version of changed page to emergency plan
 FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p
 20938 028 24X Fiche 50-029, B3/10/21, B310270532

--B310270534 Public version of Change 2 to Page 7 9 of emergency plan w/B30722 ltr & receipt form
 MARKT, D E Yankee Atomic Electric Co 82/07/22 3pp 20938 031
 24X Fiche 50-029, B3/10/21, B310270532

J Insurance & indemnity information

B310240026 Forwards Endorsements 1,2 & 3 to NELIA & MAELU Certificate N-4 & M-4, respectively
 SINISI, J M Marsh & McLennan, Inc 83/10/14 SALTZMAN, J D
 Assistant Director for State & License Relations 25pp 20882 00
 24X Fiche 50-029, B3/10/14, B310240026

B310240148 Forwards Endorsement 106 to NELIA Policy NF-76 & Endorsement 88 to MAELU Policy MF-26
 SINISI, J M Marsh & McLennan, Inc 83/10/14 SALTZMAN, J D
 Assistant Director for State & License Relations 3pp 20881 173
 24X Fiche 50-029, B3/10/14, B310240148

P Operating license stage documents & correspondence

B310310017 FOIA request for documents re integrated leak rate tests & listed facilities to be placed in PDR
 CONNER, L Affiliation Unknown 83/05/02 NRC - No Detailed Affiliation Given 1p
 21004 270 24X Fiche 50-000, B3/05/02, B310310017

B310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which repts are unavailable
 FELTON, J M Division of Rules and Records 83/07/06 CONNER, L
 Affiliation Unknown 1p 21004 271 24X Fiche 50-000, B3/07/06, B310310031

B310050054 Informs that steam generator level transmitters classified as qualification not yet established (Category II A) Final resolution of category items will be included in NRC overall review of equipment qualification program
 CRUTCHFIELD, D Operating Reactors Branch 5 83/09/27 KAY, J A
 Yankee Atomic Electric Co 4pp 20650 151 24X
 Fiche 50-029, B3/09/27, B310050054

B310040108 Provides addl info re inadequate core cooling instrumentation implementation schedule & equipment qualification, per B30927 & 29 requests concerning B30728 proposed mods All mods will be complete by 1985 refueling
 KAY, J A Yankee Atomic Electric Co 83/09/29 CRUTCHFIELD, D
 Operating Reactors Branch 5 1p 20608 003 24X
 Fiche 50-029, B3/09/29, B310040108

B310040330 Forwards "Yankee Nuclear Power Station Process Control Program," for solid waste, per Tech Spec Section 3/4 II 3 Review & approval requested
 KAY, J A Yankee Atomic Electric Co 83/09/30 CRUTCHFIELD, D
 Operating Reactors Branch 5 2pp 20617 094 24X
 Fiche 50-029, B3/09/30, B310040330

--B310040333 "Yankee Nuclear Power Station Process Control Program," solid waste
 * Yankee Atomic Electric Co 83/09/30 22pp 20617 096 24X
 Fiche 50-029, B3/09/30, B310040330

B310050166 Submits desired wording re core-wide transient analysis methods, ref in B30921 telcon & described in "Methods for Analysis of BHRs Sys Transient Analysis Model (RETRAN)"
 SINCLAIR, J B Vermont Yankee Nuclear Power Corp 83/09/30 NRC
 No Detailed Affiliation Given 1p 20628 288 24X
 Fiche 50-029, B3/09/30, B310050166

B310060003 Summary of B30916 meeting w/utills, Natl Weather Svc & FERC Bethesda, MD re Natl Weather Svc draft rept establishing 22-inch PHP level at facility Attendance list encl
 DUDLEY, R F Operating Reactors Branch 5 83/10/03 Operating Reactors Branch 5 4pp
 20649 281 24X Fiche 50-029, B3/10/03, B310060003

B310120369 Forwards "PHP for Upper Deerfield River Basin MA/VT Including Orographic Mod," final rept Rept completes studies under NRC-03-B3-102, dtd B30309 Project & financial status listed
 MILLER, J F Commerce, Dept of, Natl Oceanographic & Atmospheric Administration FIN B-8640 83/10/03 STALEY, G Division of Engineering 1p
 20699 203 24X Fiche 50-029, B3/10/03, B310120369

--B310120374 "PHP for Upper Deerfield River Basin MA/VT Including Orographic Mod"
 MILLER, J F, HANSEN, E M, FENN, D D Commerce, Dept of, Natl Oceanographic & Atmospheric Administration FIN B-8640 83/09/30 NRC - No Detailed Affiliation Given 43pp
 20699 204 24X
 Fiche 50-029, B3/10/03, B310120369

B310110161 Forwards SER supporting startup program for Cycle XVI, based on June 1983 addl info
 CRUTCHFIELD, D Operating Reactors Branch 5 83/10/05 KAY, J A
 Yankee Atomic Electric Co 2pp 20666 275 24X
 Fiche 50-029, B3/10/05, B310110161

DOCKETED ITEMS

11

--8310110166 SER supporting low power physics tests for Cycle XVI
* Office of Nuclear Reactor Regulation, Director 83/10/05 2pp
20666 277 24X Fiche 50-029,83/10/05,8310110161

8310120329 Responds to 821201 request for exemption from requirements of 10CFR50.44(c)(3)(ii) re hydrogen recombiner capability. Review revealed until misinterpreted recombiner capability requirement Informal opinion encl
EISENHUT, D G Division of Licensing 83/10/05 KAY, J A Yankee Atomic Electric Co 3pp 20699 282 24X Fiche 50-029,83/10/05,8310120329

--8207150081 Responds to 820216 & 0303 requests for interpretation of 10CFR50.44 requiring until to provide purging sys Under interim requirements, until must either install internal recombiner or provide capacity for external recombiner
OLHSTEAD, W J Regulations Division 82/05/13 DIGNAN, T G Repes & Gray DIGNAN, T G Vermont Yankee Nuclear Power Corp 7pp 20699 287 24X Fiche 50-029,83/10/05,8310120329

--8310120333 Marked-up memo forwarding W Olmstead ltr to Dignan re hydrogen recombiner capability Change to cover ltr provided W/O encl
SCINTO, J NRC - No Detailed Affiliation Given 83/09/01
CRUTCHFIELD, D NRC - No Detailed Affiliation Given 1p 20699 294 24X Fiche 50-029,83/10/05,8310120329

8310120354 Requests completion schedules presented in integrated plant safety assessment rept be updated within 30 days of ltr receipt Immediate milestones should be established for evaluation methods & acceptance criteria review
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/06 KAY, J A Yankee Atomic Electric Co 2pp 20699 193 24X
Fiche 50-029,83/10/06,8310120354

8310120203 Informs that future FR monthly publications will be submitted w/o transmittal ltr
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/07 KAY, J A Yankee Atomic Electric Co 2pp 20696 104 24X
Fiche 50-029,83/10/07,8310120203

8310190097 Forwards Rev 14 to operational QA program Rev addresses organizational & programmatic changes to QA program
SHEPARD, A M Yankee Atomic Electric Co 83/10/12 MURLEY, T E Region 1, Office of Director 1p 20822 117 24X
Fiche 50-000,83/10/12,8310190097

--8310190105 Rev 14 to operational QA program
PETERSON, W K, SHEPARD, A M, MURPHY, W P Yankee Atomic Electric Co YOGAP-1-A R14 83/10/12 134pp 20822 118 24X
Fiche 50-000,83/10/12,8310190097

8310170360 Provides status of Harriman Dam stability analysis currently under review by FERC Results of PMP study performed by Natl Weather Svc & seismic input recommendations to be used in analysis provided to FERC
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/14 KAY, J A Yankee Atomic Electric Co 3pp 20786 171 24X
Fiche 50-029,83/10/14,8310170360

8310250463 Informs that facility will be in compliance w/NUREG-0737, Item 11.1.2 re inadequate core cooling instrumentation, per 830728 ltr, in response to 830627 safety evaluation, pending completion of upgraded procedures
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/24 KAY, J A Yankee Atomic Electric Co 5pp 20897 149 24X
Fiche 50-029,83/10/24,8310250463

8310270238 Advises that until Bill 124 response to Generic Ltr 81-21 provides reasonable assurance that steam formation at upper head of reactor vessel during natural circulation cooldown will not occur, per TMI Action Plan Item 1 C 1
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/25 KAY, J A Yankee Atomic Electric Co 6pp 20924 091 24X
Fiche 50-029,83/10/25,8310270238

8310310283 Requests description of mechanical tube plugging program, to complete review instigated by findings of IE Insp Rept 50-029/B2-12 Documents referenced in Westinghouse 821122 ltr should be included Response due in 60 days
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/27 KAY, J A Yankee Atomic Electric Co 2pp 20961 284 24X
Fiche 50-029,83/10/27,8310310283

8310310360 Informs that request for extension to submit response to Generic Ltr 83-28 re Salem ATWS events denied Info should be submitted by 831105
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/27 KAY, J A Yankee Atomic Electric Co 3pp 20961 122 24X
Fiche 50-029,83/10/27,8310310360

G Inspection reports, IE Bulletins & correspondence

8310120137 Forwards IE Safeguards Insp Rept 50-029/83-10 on 830725-27 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/09/10
HEIDER, L H Yankee Atomic Electric Co 2pp 20695 281 24X
Fiche 50-029,83/09/10,8310120137

--8310120139 Notice of violation from insp on 830725-29
* Region 1, Office of Director 83/09/10 1p 20695 283 24X
Fiche 50-029,83/09/10,8310120137

--8310120143 IE Safeguards Insp Rept 50-029/83-10 on 830725-29
Noncompliance noted failure to record required training data
DUNLOP, J H, MARTIN, W G, GOODY, A T Region 1, Office of Director 83/09/09 3pp 20695 284 24X Fiche 50-029,83/09/10,8310120137

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/O 10CFR50.59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752

8310270184 Forwards IE Insp Rept 50-029/83-12 on 830823-25 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/10/07, HEIDER, L H Yankee Atomic Electric Co 2pp 20924 176 24X
Fiche 50-029,83/10/07,8310270184

--8310270194 IE Insp Rept 50-029/83-12 on 830823-25 No noncompliance noted Major areas inspected Phase II of annual emergency exercise performed on 830824
SMITH, R H Region 1, Office of Director CROCKER, H W Division of Engineering & Technical Programs 83/09/28 6pp 20924 178 24X Fiche 50-029,83/10/07,8310270184

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

8310270013 Notification of Significant Licensee Meeting 83-91 on 831114 in Rowe, MA to discuss SALP
COLLINS, B T Region 1, Office of Director 83/10/20 Region 1, Office of Director 2pp 20940 168 24X Fiche 50-029,83/10/20,8310270013

DOCKETED ITEMS

8310310283 Requests description of mechanical tube plugging program, to complete review instigated by findings of IE Insp Rept 50-029/82-12 Documents referenced in Westinghouse 821122 ltr should be included Response due in 60 days
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/27 KAY, J A
Yankee Atomic Electric Co 2pp 20951 284 24X
Fiche 50-029, 83/10/27, 8310310283

R Periodic operating reports & related correspondence

8310190012 Monthly operating rept for Aug 1983 W/830909 ltr
BATTERSON, S, HEIDER, L H Yankee Atomic Electric Co 83/09/09
Division of Data Automation & Management Information 6pp
20822 095 24X Fiche 50-029, 83/09/09, 8310190012

S Reportable occurrences, LERs & related correspondence

8310270340 FOIA request for placement of listed LERs in PDR
GRABER, L D NUS Corp 83/09/08 Division of Rules and Records
2pp 20938 058 24X Fiche 50-000, 83/09/08, 8310270340

8310250523 LER 83-027/01T-0 on 830831, while performing Procedure OP-2100 "Plant Startup from Cold Shutdown," LPS1 & HPS1 pump breaker 1 found inoperable, contrary to Tech Specs Caused by procedural error Procedure revised W/830914 ltr
MAY, E L, ST LAURENT, N N Yankee Atomic Electric Co 83/09/14
MURLEY, T E Region 1, Office of Director 3pp 20901 296 24X
Fiche 50-029, 83/09/14, 8310250523

8310270347 Responds to FOIA request for release of 23 LERs to PDR
Forwards 12 LERs to be released Documents also available in PDR One LER canceled Eight LERs not received
FELTON, J M Division of Rules and Records 83/09/29 GRABER, L D
NUS Corp 1p 20938 060 24X Fiche 50-000, 83/09/29, 8310270347

8310250232 LER 83-028/03L-0 on 830901, during heatup in Mode 3, leak discovered in elbow in high pressure steam drain line upstream of TV-406 Caused by steam erosion on piping elbow Elbow & piping replaced W/830930 ltr
FRENCH, L D, ST LAURENT, N N Yankee Atomic Electric Co 83/09/30
MURLEY, T E Region 1, Office of Director 2pp 20899 121 24X
Fiche 50-029, 83/09/30, 8310250232

8310250418 LER 83-029/03L-0 on 830902, during recovery from 1 wk maint outage, main coolant sys subcooling margin monitor failed Caused by loss of one in-core thermocouple input 0-10 Input replaced by refueling channel thermocouple A-5 W/830930 ltr
ELLIS, D W, ST LAURENT, N N Yankee Atomic Electric Co 83/09/30
MURLEY, T E Region 1, Office of Director 2pp 20897 197 24X
Fiche 50-029, 83/09/30, 8310250418

8310250421 LER 83-030/03L-0 on 830902, while in Mode 2, leak discovered on body to bonnet flange on trap bypass valve AS-V-641 Caused by failed body bonnet flange gasket Gasket replaced Valve reassembled W/830930 ltr
RICE, D A, ST LAURENT, N N Yankee Atomic Electric Co 83/09/30
MURLEY, T E Region 1, Office of Director 2pp 20897 004 24X
Fiche 50-029, 83/09/30, 8310250421

8310140082 PND-I-83-105 on 831007, seismic event occurred in northwestern US w/magnitude of 5.2 on Richter scale in NY & 4.0 in NH No damage to equipment identified
GALLD, R M, GREENMAN, E G Region 1, Office of Director 83/10/07
1p 20766 116 24X Fiche 50-000, 83/10/07, 8310140082

8310250327 LER 83-031/03L-0 on 830913, primary meteorological sys removed for mod to data signal transmission sys Secondary sys continued in svc No corrective action necessary W/ 831013 ltr
RICE, D A, ST LAURENT, N N Yankee Atomic Electric Co 83/10/13
MURLEY, T E Region 1, Office of Director 2pp 20897 338 24X
Fiche 50-029, 83/10/13, 8310250327

8310250277 LER 83-032/03L-0 on 830915, while in Mode 1, main coolant sys subcooling margin monitor failed Caused by loss of one of eight in-core thermocouple F-7 inputs Thermocouple F-7 input replaced by thermocouple H-7 W/831014 ltr
ELLIS, D W, ST LAURENT, N N Yankee Atomic Electric Co 83/10/14
MURLEY, T E Region 1, Office of Director 2pp 20899 185 24X
Fiche 50-029, 83/10/14, 8310250277

8310280018 LER 83-033/03L-0 on 830918, during Mode 1 operation, primary vent stack noble gas monitor channel failed Caused by improper reinstallation of drainage bottle Detector dried out W/831018 ltr
FRENCH, L D, ST LAURENT, N N Yankee Atomic Electric Co 83/10/18
MURLEY, T E Region 1, Office of Director 2pp 20934 173 24X
Fiche 50-029, 83/10/18, 8310280018

8310280015 LER 83-034/99T-0 on 830919, underground fire main section for yard hydrants 14 & 15 isolated Caused by deliberate removal of section from svc for waste compacting const Sys will be modified W/831019 ltr
MAY, E L, ST LAURENT, N N Yankee Atomic Electric Co 83/10/19
MURLEY, T E Region 1, Office of Director 3pp 20934 175 24X
Fiche 50-029, 83/10/19, 8310280015

DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR

U Congressional/Executive Correspondence

8310110617 Responds to 830901 questions re proposed retransfer of License R-B1 Transfer precluded under law since transferee, Cintichem, Inc, is US corp whose parent corp, F Hoffman-La Roche & Co, Ltd, is Switzerland corp
PALLADINO, N J Commissioners 83/09/22 SIMPSON, A K Senate, Environment & Public Works 13pp 20701 338 24X
Fiche 50-054, 83/09/22, 8310110617

--8310110620 Poses questions on NRC position that proposed transfer of License R-B1 from Union Carbide Subsidiary B to Cintichem, Inc is prohibited
SIMPSON, A K Senate, Environment & Public Works 83/09/01
PALLADINO, N J Commissioners 2pp 20701 351 24X
Fiche 50-054, 83/09/22, 8310110617

DOCKET 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR

P Operating license stage documents & correspondence

8310270232 Forwards Amend 19 to License R-77 Amend makes editorial changes to Table 3.1, corrects related editorial errors on Page 21 & allows change in testing interval of dry chamber door interlock
THOMAS, C D Standardization & Special Projects Branch 83/10/13
HENRY, L G New York, State Univ of, Buffalo, NY 3pp 20943 055 24X Fiche 50-057, 83/10/13, 8310270232

--8310270243 Amend 19 to License R-77, making editorial changes to Table 3.1, correcting related editorial errors on Page 21 & allowing changes in testing interval of dry chamber door interlock
THOMAS, C D Standardization & Special Projects Branch 83/10/13
3pp 20943 060 24X Fiche 50-057, 83/10/13, 8310270232

R Periodic operating reports & related correspondence

8310140222 Rept of changes, tests & experiments conducted w/o prior Commission approval during Jul 1982 - June 1983
ORLOSKY, P M New York, State Univ of, Buffalo, NY 83/10/03
Region 1, Office of Director 1p 20761 181 24X
Fiche 50-057, 83/10/03, 8310140222

DOCKET 50-59 TEXAS A&M UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8310250673 Releases public version of licensee 831013 ltr advising emergency plan implementation within 120-day requirement
FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20908 356 24X Fiche 50-059, 83/10/21, 8310250673

--8310250683 Submits public version of indication that emergency plan implemented within 120-day requirement
ERDMAN, C A Texas A&M Univ, College Station, TX 83/10/13
THOMAS, C D Standardization & Special Projects Branch 1p 20908 357 24X Fiche 50-059, 83/10/21, 8310250673

DOCKET 50-62 UNIV OF VIRGINIA RESEARCH REACTOR

S Reportable occurrences, LERs & related correspondence

8310060092 EN-83-062 on 831006, notices of violation & proposed imposition of \$1,000 civil penalty to be issued Action based on violation of Tech Specs re alterations made to core configuration
CRAIG, J J, AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/10/03 1p 20647 177 24X Fiche 50-062, 83/10/03, 8310060092

DOCKETED ITEMS

13

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

G Adjudicatory correspondence

8310120372 Memorandum & order granting J Turk 830915 request for 60-day extension of deadline for filing amendments to contentions & petition
FRYE, J H Atomic Safety and Licensing Board Panel 83/10/07
TURK, J Turk, J Ip 20699 253 24X Fiche 50-070, 83/10/07, 8310120372

DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

G Inspection reports, IE Bulletins & correspondence

8310310233 Forwards IE Insp Rept 50-073/BJ-02 on 830813-15 No noncompliance noted
WENSLAWSKI, F A Region 5, Office of Director 83/10/17
DARMITZEL, R W General Electric Co 2pp 20947 115 24X Fiche 50-073, 83/10/17, 8310310233

--8310310249 IE Insp Rept 50-073/BJ-02 on 830813-15 No noncompliance noted Major areas inspected radiation protection/environmental protection, transportation activities & Tech Spec requirements
GARCIA, E M, WENSLAWSKI, F A Region 5, Office of Director 83/10/17 5pp 20947 117 24X Fiche 50-073, 83/10/17, 8310310233

DOCKET 50 83 UNIV OF FLORIDA TRAINING REACTOR

F Security, medical, emergency & fire protection plans

8310050028 Grants extension until 831015 for receipt of amended emergency plan, in response to 830915 request
THOMAS, C D Standardization & Special Projects Branch 83/09/26
DIAZ, N J Florida, Univ of, Gainesville, FL 2pp 20650 244 24X Fiche 50-083, 83/09/26, 8310050028

8310110362 Releases public version of licensee request for extension to submit amendments to emergency plan
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch Ip 20713 220 24X Fiche 50-083, 83/10/05, 8310110362

--8310110366 Forwards public version of licensee request for addl 30-day extension until 831015 to submit amendments to emergency plan
DIAZ, N J Florida, Univ of, Gainesville, FL 83/09/15
THOMAS, C Standardization & Special Projects Branch Ip 20713 221 24X Fiche 50-083, 83/10/05, 8310110362

8310210162 Responds to 830331 Rev 6 to physical security plan re request for clarification of ambiguous terminology Change acceptable
THOMAS, C D Standardization & Special Projects Branch 83/10/17
DIAZ, N J Florida, Univ of, Gainesville, FL 2pp 20884 081 24X Fiche 50-083, 83/10/17, 8310210162

DOCKET 50-87 WESTINGHOUSE CRITICAL EXPERIMENT

G Inspection reports, IE Bulletins & correspondence

8310050559 Forwards IE Insp Rept 50-087/B3-03 on 830908 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 83/09/21
SCHOLAND, G W Westinghouse Electric Corp 2pp 20633 177 24X Fiche 50-087, 83/09/21, 8310050559

--8310050564 IE Insp Rept 50-087/B3-03 on 830908 No noncompliance noted Major areas inspected radiation protection & radwaste mgt programs, qualifications, audits, training, radiation protection procedures, instruments & equipment
GRANT, W B, GREGOR, L R Region 3, Office of Director 83/09/19 4pp 20633 179 24X Fiche 50-087, 83/09/21, 8310050559

G Reportable occurrences, LLRs & related correspondence

8310310275 PNO-III-83-106 on 831025, two men in pickup truck parked outside facility delivered bomb threat Training reactor shut down & bldg searched No bomb discovered
KERS, D A, CRILL, J R Region 3, Office of Director 83/10/24 Ip 20947 114 24X Fiche 50-087, 83/10/26, 8310310275

DOCKET 50 89 GENERAL ATOMIC CO

P Operating license stage documents & correspondence

8310180319 Comments on amendments to Licenses R-38 & R-47 to reflect name change to GA Technologies Co Amends unnecessary since facilities operational through 1983
HOGAN, J P GA Technologies, Inc /General Atomic Co 83/10/13
THOMAS, C D Standardization & Special Projects Branch 2pp 20806 231 24X Fiche 50-089, 83/10/13, 8310180319

DOCKET 50-112 UNIV OF OKLAHOMA RESEARCH REACTOR

E NRC Safety Evaluation Report (SER), supplements & correspondence

8310180071 SAFETY EVALUATION REPORT RELATED TO THE RENEWAL OF THE OPERATING LICENSE FOR THE UNIVERSITY OF OKLAHOMA RESEARCH REACTOR Docket No 50-112
* Division of Licensing NUREG-0996 83/09/30 57pp 20826 174 24X Fiche 50-112, 83/09/30, 8310180071

DOCKET 50-116 IOWA STATE UNIV RESEARCH REACTOR

E NRC Safety Evaluation Report (SER), supplements & correspondence

8310180169 SAFETY EVALUATION REPORT RELATED TO THE RENEWAL OF THE OPERATING LICENSE FOR THE RESEARCH REACTOR AT THE IOWA STATE UNIVERSITY Docket No 50-116
* Division of Licensing NUREG-1016 83/09/30 83pp Available at NRC \$4.75 20825 089 24X Fiche 50-116, 83/09/30, 8310180169

F Security, medical, emergency & fire protection plans

8310030123 Forwards responses to NRC 830815 questions Portable health physics instruments & fire protection sys described
HENDRICKSON, R Iowa State Univ, Ames, IA 83/09/28 THOMAS, C D Standardization & Special Projects Branch 9pp 20590 042 24X Fiche 50-116, 83/09/28, 8310030123

P Operating license stage documents & correspondence

8310030093 Forwards rev to Tech Specs for UTR-10 reactor Rev details operating & special reports distribution
HENDRICKSON, R Iowa State Univ, Ames, IA 83/09/28 CHU, A Standardization & Special Projects Branch Ip 20590 064 24X Fiche 50-116, 83/09/28, 8310030093

--8310030100 Rev to Tech Specs detailing operating & special reports distribution
* Iowa State Univ, Ames, IA 83/09/28 4pp 20590 065 24X Fiche 50-116, 83/09/28, 8310030093

8310170731 Advises that AT Chu assigned as project manager for facility
THOMAS, C D Standardization & Special Projects Branch 83/10/03
HENDRICKSON, R Iowa State Univ, Ames, IA 2pp 20797 393 24X Fiche 50-116, 83/10/05, 8310170731

G Inspection reports, IE Bulletins & correspondence

8310120202 Forwards IE Insp Rept 50-116/B3-02 on 830913-14 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 83/09/23 PAPERIELLO, C J Iowa State Univ, Ames, IA 2pp 20696 108 24X Fiche 50-116, 83/09/23, 8310120202

--8310120204 IE Insp Rept 50-116/B3-02 on 830913-14 No noncompliance noted Major areas inspected radiation protection & radwaste mgt programs, including qualifications, audits, training, radiation protection procedures & instruments & equipment
GRANT, W B, GREGOR, L R Region 3, Office of Director 83/09/23 5pp 20696 110 24X Fiche 50-116, 83/09/23, 8310120202

8310030123 Forwards responses to NRC 830815 questions Portable health physics instruments & fire protection sys described
HENDRICKSON, R Iowa State Univ, Ames, IA 83/09/28 THOMAS, C D Standardization & Special Projects Branch 9pp 20590 042 24X Fiche 50-116, 83/09/28, 8310030123

DOCKETED ITEMS

DOCKET 50-123 UNIV OF MISSOURI RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8310200242 Forwards IE Insp Rept 50-123/83-02 on 830913-16 & notices of violation & deviation
 NORELIUS, C E Division of Project & Resident Programs 83/10/07
 WARNER, D L Missouri, Univ of, Rolla 2pp 20830 103 24X
 Fiche 50-123, 83/10/07, 8310200242

P Operating license stage documents & correspondence

8310170734 Forwards preliminary questions & comments associated w/ application for renewal of OL Responses should be available by 831114 for site visit by LASL & NRC
 THOMAS, C O Standardization & Special Projects Branch 83/10/06
 BOLON, A E Missouri, Univ of, Rolla 10pp 20797 342 24X
 Fiche 50-123, 83/10/06, 8310170734

Q Inspection reports, IE Bulletins & correspondence

8310200242 Forwards IE Insp Rept 50-123/83-02 on 830913-16 & notices of violation & deviation
 NORELIUS, C E Division of Project & Resident Programs 83/10/07
 WARNER, D L Missouri, Univ of, Rolla 2pp 20830 103 24X
 Fiche 50-123, 83/10/07, 8310200242

--8310200250 Notice of violation from insp on 830913-16
 NORELIUS, C E Division of Project & Resident Programs 83/10/07
 1p 20830 105 24X Fiche 50-123, 83/10/07, 8310200242

--8310200255 Notice of deviation from insp on 830913-16
 * Region 3, Office of Director 83/10/07 1p 20830 106 24X
 Fiche 50-123, 83/10/07, 8310200242

--8310200268 IE Insp Rept 50-123/83-02 on 830913-16 Noncompliance noted failure to provide analysis of possible hazards associated w/experiments performed on 830223 & 0917
 Deviation noted failure to follow std procedures
 RIDGWAY, K R, DEFAVETTE, R, TAMBLING, T N Region 3, Office of Director 83/10/05 11pp 20830 107 24X Fiche 50-123, 83/10/07, 8310200242

R Periodic operating reports & related correspondence

8310110099 Forwards Rev 1 to operator requalification program & "Progress Rept 1982-1983, Univ of Missouri - Rolla Nuclear Reactor Facility " Staff now consists of three senior reactor operators & two reactor operators
 BOLON, A E Missouri, Univ of, Rolla 83/10/05 THOMAS, C O Standardization & Special Projects Branch 1p 20668 280 24X
 Fiche 50-123, 83/10/05, 8310110099

8310110113 "Progress Rept 1982-1983, Univ of Missouri - Rolla Nuclear Reactor Facility "
 BOLON, A E Missouri, Univ of, Rolla 83/03/31 135pp
 20668 301 24X Fiche 50-123, 83/10/05, 8310110099

Operator Examinations

8310110099 Forwards Rev 1 to operator requalification program & "Progress Rept 1982-1983, Univ of Missouri - Rolla Nuclear Reactor Facility " Staff now consists of three senior reactor operators & two reactor operators
 BOLON, A E Missouri, Univ of, Rolla 83/10/05 THOMAS, C O Standardization & Special Projects Branch 1p 20668 280 24X
 Fiche 50-123, 83/10/05, 8310110099

--8310110110 Rev 1 to operator requalification program for Univ of Missouri - Rolla nuclear reactor facility
 * Missouri, Univ of, Rolla 81/03/31 20pp 20668 281 24X
 Fiche 50-123, 83/10/05, 8310110099

--8310110113 "Progress Rept 1982-1983, Univ of Missouri - Rolla Nuclear Reactor Facility "
 BOLON, A E Missouri, Univ of, Rolla 83/03/31 135pp
 20668 301 24X Fiche 50-123, 83/10/05, 8310110099

DOCKET 50-124 VIRGINIA POLYTECH INST TRAINING REACTOR

F Security, medical, emergency & fire protection plans

8310210299 Forwards Revs 1 & 2 to physical security plan Revs withheld
 * Virginia Polytechnic Institute & State Univ, Blacksburg, VA
 83/09/27 CARLSON, D Division of Safeguards 1p 20855 215 24X
 Fiche 50-124, 83/09/27, 8310210299

DOCKET 50-128 TEXAS A&M UNIV RICHFARCH REACTOR

F Security, medical, emergency & fire protection plans

8310200268 IE Insp Rept 50-123/83-02 on 830913-16 Noncompliance noted failure to provide analysis of possible hazards associated w/experiments performed on 830223 & 0917
 Deviation noted failure to follow std procedures
 RIDGWAY, K R, DEFAVETTE, R, TAMBLING, T N Region 3, Office of Director 83/10/05 11pp 20830 107 24X Fiche 50-123, 83/10/07, 8310200242

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

8310210159 Responds to util 830808 ltr re change to Rev 2 to security plan Changes consistent w/provisions of 10CFR50 34(p), do not decrease effectiveness of plan & are acceptable
 CRUTCHFIELD, D Operating Reactors Branch 5 83/10/17
 SCHUYLER, J O Pacific Gas & Electric Co 2pp 20884 079 24X
 Fiche 50-133, 83/10/17, 8310210159

P Operating license stage documents & correspondence

8310250113 Forwards topical outline for submitting info for decommissioning facility for placement in PDN under docket
 PEARSON, W R Chemical Engineering Branch 83/10/24 Division of Technical Information & Document Control 10pp 20896 050 24X
 Fiche 50-133, 83/10/24, 8310250113

Q Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Wildfire Qualification Tests " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD bypass Loops Used in Westinghouse Plants " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 77pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Malfunction Causes Production of Noxious Gases " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

DOCKETED ITEMS

15

R Periodic operating reports & related correspondence

8310190260 Monthly operating rept for Aug 1983 W/830908 ltr
DERAS, P S, WELKS, E D Pacific Gas & Electric Co 83/09/08
Division of Data Automation & Management Information 5pp
20818 064 24X Fiche 50-134, 83/09/08, 8310190260

DOCKET 50-134 WORCESTER POLYTECH INST RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8310270291 Forwards IE Insp Rept 50-134/BJ-02 on 830818-19 No
noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/10/11
WILBUR, L C Worcester Polytechnic Inst 2pp 20923 221 24X
Fiche 50-134, 83/10/11, 8310270291

--8310270295 IE Insp Rept 50-134/BJ-02 on 830818-19 No noncompliance
noted Major areas inspected effect of Washburn Lab
renovation on reactor facility, radiation control, emergency
plan & environ monitoring
KINNEY, W W, ELGASSER, T C Region 1, Office of Director
83/10/07 7pp 20923 224 24X Fiche 50-134, 83/10/11, 8310270291

G Inspection reports, IE Bulletins & correspondence

8310270291 Forwards IE Insp Rept 50-134/BJ-02 on 830818 19 No
noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/10/11
WILBUR, L C Worcester Polytechnic Inst 2pp 20923 221 24X
Fiche 50-134, 83/10/11, 8310270291

--8310270295 IE Insp Rept 50-134/BJ-02 on 830818-19 No noncompliance
noted Major areas inspected effect of Washburn Lab
renovation on reactor facility, radiation control, emergency
plan & environ monitoring
KINNEY, W W, ELGASSER, T C Region 1, Office of Director
83/10/07 7pp 20923 224 24X Fiche 50-134, 83/10/11, 8310270291

DOCKET 50-139 UNIV OF WASHINGTON RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

8310310352 Forwards IE Insp Rept 50-139/BJ-01 on 830921-23 & notice of
violation w/o notice of violation
SCARANO, R A Division of Radiological Safety & Safeguards Program
83/10/13 BOHLN, J R Washington, Univ of, Seattle, WA 2pp
20960 294 24X Fiche 50-139, 83/10/13, 8310310352

--8310310357 IE Insp Rept 50-139/BJ-01 on 830921-23 Noncompliance noted
Failure to calibrate flow measuring devices installed in Tech
Spec required effluent monitors
SHERMAN, C I, WENSLAWSKI, F A Region 5, Office of Director
83/10/13 7pp 20960 296 24X Fiche 50-139, 83/10/13, 8310310357

DOCKET 50-142 UCLA TRAINING REACTOR

G Adjudicatory correspondence

8310030394 Response to Committer to Bridge the Gap 830830 comments on
IE insp rept on SNM possession Gap alleged discrepancies
based on conjecture & misinterpretation of reported info
Certificate of BvC encl
CORMIER, W H California, Univ of, Los Angeles, CA 83/09/09 5pp
20593 047 24X Fiche 50-142, 83/09/09, 8310030394

8310040172 Memorandum & order ruling on UCLA & NRC scope objections to
Committee to Bridge the Gap prefiled direct testimony
Objections overruled w/exception of Panel 1, Paragraphs 4-6
& Panel 11, Paragraph 15
BRIGHT, O D, LUEDKE, E A, FRYE, J H Atomic Safety and Licensing
Board Panel 83/09/30 California, Univ of, Los Angeles, CA
10pp 20608 093 24X Fiche 50-142, 83/09/30, 8310040172

8310110054 Memorandum & order memorializing 831003 telcon re rebuttal
testimony, technical issues, expert interrogatories,
photographs & official notice
FRYE, J H Atomic Safety and Licensing Board Panel 83/10/04 3pp
20668 241 24X Fiche 50-142, 83/10/04, 8310110054

8310260263 Memorandum & Order LHP-83-67, granting NRC petition for
reconsideration of LBP-83-25A, Section B & denying NRC
petition for reconsideration of LBP-83-25A, Section L &
Committee to Bridge the Gap objections to SNM inventory
LUEDKE, E A, BRIGHT, O D, FRYE, J H Atomic Safety and Licensing
Board Panel 83/10/24 Office of the Executive Legal Director
13pp 20912 008 24X Fiche 50-142, 83/10/24, 8310260263

8310310240 Notice of resumption of evidentiary hearing re proposed
renewal of OL Hearing will commence on 831129 in Los
Angeles, CA & will continue through 831102
FRYE, J H Atomic Safety and Licensing Board Panel 83/10/27 1p
20947 127 24X Fiche 50-142, 83/10/27, 8310310240

H General correspondence

8310180135 Opposes relicensing of potentially dangerous reactor Reactor
should be shut down until all safety questions resolved
JOACHIM, M Affiliation Unknown 83/10/07 FRYE, J H Atomic Safety
and Licensing Board Panel 1p 20809 185 24X
Fiche 50-142, 83/10/07, 8310180135

8310260302 Opposes relicensing of nuclear reactor at UCLA
LEVY, D Affiliation Unknown 83/10/25 FRYE, J H Atomic Safety
and Licensing Board Panel 1p 20911 034 24X
Fiche 50-142, 83/10/25, 8310260302

T Hearing transcripts on non-antitrust matters

8310190121 Transcript of 831011 hearing in Los Angeles, CA re proposed
renewal of facility license Pp 2,507-2,630 Supporting
documentation encl
* Atomic Safety and Licensing Board Panel 83/10/11 144pp
20819 100 24X Fiche 50-142, 83/10/11, 8310190121

8310190123 Transcript of 831012 hearing in Los Angeles, CA re proposed
renewal of facility license Pp 2,631-2,827 Supporting
documentation encl
* Atomic Safety and Licensing Board Panel 83/10/12 24pp
20821 130 24X Fiche 50-142, 83/10/12, 8310190123

8310200116 Transcript of 831013 hearing in Los Angeles, CA re proposed
renewal of OL Pp 2,828-3,030 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/10/13 307pp
20837 125 24X Fiche 50-142, 83/10/13, 8310200116

8310200112 Transcript of 831014 hearing in Los Angeles, CA re proposed
renewal of OL Pp 3,031-3,192 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/10/14 215pp
20836 067 24X Fiche 50-142, 83/10/14, 8310200112

8310280016 Forwards missing pages from 830802 & 1014 hearing
transcripts re proposed renewal of OL Corrected pages to
831014 hearing transcript also encl
EYSTER, R E Taylor Associates 83/10/21 FRYE, J H, LUEBKEL, I A,
BRIGHT, O D Atomic Safety and Licensing Board Panel 1p
20932 279 24X Fiche 50-142, 83/10/21, 8310280016

--8310280020 Pages from 830802 & 1014 hearing transcripts re OL renewal
inadvertently omitted from original & corrected pages to
831014 transcript
* Atomic Safety and Licensing Board Panel 83/10/21 16pp
20932 280 24X Fiche 50-142, 83/10/21, 8310280016

DOCKET 50-148 UNIV OF KANSAS RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8310170735 Releases public version of revised emergency preparedness
plan
FELTON, J H Division of Rules and Records 83/10/06 Document
Management Branch 1p 20799 303 24X Fiche 50-148, 83/10/06,
8310170735

--8310170738 Public version of revised emergency preparedness plan
* Kansas, Univ of, Lawrence, KS 83/08/31 39pp 20797 304
24X Fiche 50-148, 83/10/06, 8310170735

8310210237 Forwards addendum to Section 4, "Site Surroundings," to
hazards summary rept
MESLER, R B Kansas, Univ of, Lawrence, KS 83/10/11 BERNHARD, H
Division of Licensing 1p 20852 036 24X Fiche 50-148, 83/10/11,
8310210237

--8310210239 Addendum to Section 4, "Site & Surroundings," to hazards
summary rept
* Kansas, Univ of, Lawrence, KS 83/10/11 2pp 20853 037
24X Fiche 50-148, 83/10/11, 8310210237

P Operating license stage documents & correspondence

8310170728 Advises that AT Chu assigned as project manager for
facility
THOMAS, C D Standardization & Special Projects Branch 83/10/05
MESLER, R B Kansas, Univ of, Lawrence, KS 2pp 20797 356 24X
Fiche 50-148, 83/10/05, 8310170728

DOCKETED ITEMS

DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

8310110019 Releases public version of revised emergency plan implementing procedure
 FELTON, J M Division of Rules and Records 83/10/05 Document
 Management Branch 1p 20687 357 24X Fiche 50-000, 83/10/05.
 8310110019

--8310110074 Public version of Rev 6 to Emergency Plan Implementing Procedure EDI-7, "Offsite Dose Worksheet (Protective Actions)" W/930922 ltr & receipt form
 BRADLEY, J Consumers Power Co 83/07/18 Document Management Branch 2pp 20687 358 24X Fiche 50-000, 83/10/05, 8310110019

8310110255 Releases public version of revised emergency plan
 FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20687 359 24X Fiche 50-155, 83/10/05.
 8310110255

--8310110259 Public version of Rev 70 to emergency plan W/830926 ltr & receipt form
 * Consumers Power Co 83/09/23 4pp 20682 360 24X Fiche 50-155, 83/10/05, 8310110255

8310180614 Advises that 830817 proposed changes to physical security plan, Rev 9, acceptable per 10CFR50.54(p) Requested 25% variance does not meet 10CFR73.55(g)(4) Encls to ltr withheld (ref 10CFR73.21)
 CRUTCHFIELD, D Operating Reactors Branch 5 83/10/11
 VANDEWALLE, D J Consumers Power Co 4pp 20817 339 24X Fiche 50-155, 83/10/11, 8310180614

8310180335 Forwards, for info, listed documents which will not be introduced into evidence Oversize map encl Aperture card available in PDR
 GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co 83/10/14 BLOCH, P B, PARIS, O H, SHDN, T J Atomic Safety and Licensing Board Panel 733pp 20809 279 24X Fiche 50-155, 83/10/14, 8310180335

8310200410 Releases public version of revised emergency plan implementing procedures
 FELTON, J M Division of Rules and Records 83/10/17 Document Management Branch 1p 20859 217 24X Fiche 50-155, 83/10/17, 8310200410

8310200417 Forwards public version of Rev 34 to Emergency Plan Implementing Procedure EPIP 4A, "Plant Superintendent" & Rev 35 to Procedure EPIP 6B, "Personnel Monitoring Evaluation & Reassembly" Receipt form encl
 * Consumers Power Co 83/09/27 NRC - No Detailed Affiliation Given 2pp 20859 220 24X Fiche 50-155, 83/10/17, 8310200410

8310200473 Public version of Rev 34 to Emergency Plan Implementing Procedure EPIP 4A, "Plant Superintendent" & Rev 35 to Procedure EPIP 6B, "Personnel Monitoring Evaluation & Reassembly"
 * Consumers Power Co 83/09/26 11pp 20859 222 24X Fiche 50-155, 83/10/17, 8310200410

8310250522 Forwards SALP Rept 50-155/83-15 for Jul 1982 - June 1983 Util has improved rating in five functional areas including satisfactory resolution of previously identified concerns
 KEEPLER, J G Region 3, Office of Director 83/10/20 DEWITT, R H Consumers Power Co 2pp 20900 316 24X Fiche 50-155, 83/10/20, 8310250522

--8310250535 SALP Rept 50-155/83-15 for Jul 1982 - June 1983 Licensee should develop & implement program to identify applicable regulatory requirements & licensee commitments to ensure compliance w/QA activities All other areas acceptable
 * Region 3, Office of Director 83/10/20 24pp 20900 318 24X Fiche 50-155, 83/10/20, 8310250522

8310260118 Forwards exemption requests from certain requirements of 10CFR50, App R, Section III G 3 re fire detection & fixed fire suppression requirements
 VANDEWALLE, D Consumers Power Co 83/10/20 CRUTCHFIELD, D Operating Reactors Branch 5 7pp 20915 236 24X Fiche 50-155, 83/10/20, 8310260118

8310270491 Releases public version of revised controlled copyholder list of emergency plan implementing procedures
 FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20928 377 24X Fiche 50-000, 83/10/21, 8310270491

--8310270510 Forwards public version of Rev 2 to controlled copyholder list of general ofc ctr/emergency operations facility emergency implementing procedures & list depicting location of proprietary info in procedures
 CARLEY, A Consumers Power Co 83/09/15 Office of Nuclear Reactor Regulation, Director 7pp 20928 338 24X Fiche 50-000, 83/10/21, 8310270491

8310270590 Releases public version of revised general ofc control ctr/emergency operations facility emergency implementing procedures
 FELTON, J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20944 327 24X Fiche 50-000, 83/10/25, 8310270590

--8310270593 Forwards public version of revised general ofc control ctr/emergency operations facility emergency implementing procedures, including Procedure GEN-2 re emergency telephone numbers Receipt form encl
 CARLEY, A Consumers Power Co 83/10/13 Document Management Branch 4pp 20944 323 24X Fiche 50-000, 83/10/25, 8310270590

--8310270597 Public version of revised general ofc control ctr/emergency operations facility emergency implementing procedures, including Procedure GEN-2 re emergency telephone numbers
 * Consumers Power Co 83/10/11 42pp 20944 327 24X Fiche 50-000, 83/10/25, 8310270590

G Adjudicatory correspondence

8309130169 Submits preliminary list of witnesses & testimony on Contention II-D re air crash & small civilian aircraft sighted over plant Extension for testimony filing date to 830930 requested Related correspondence
 O'NEILL, J O'Neill, J 83/09/07 BLOCH, P B, PARIS, O H, SHDN, T J Atomic Safety and Licensing Board Panel 1p 20756 281 24X Fiche 50-155, 83/09/07, 8309130169

8310040184 Memorandum & Order LBP-83-62 denying Christa Maria 8310024 motion to reopen record on criticality Alleged grounds for reopening moot
 BLOCH, P B, PARIS, O H, SHDN, T J Atomic Safety and Licensing Board Panel 83/09/30 Christa Maria 5pp 20608 247 24X Fiche 50-155, 83/09/30, 8310040184

8310040267 Order extending time until 831007 for Commission to act to review ALAB-725
 CHILK, S J Office of the Secretary of the Commission 83/09/10 Commissioners 1p 20612 342 24X Fiche 50-155, 83/09/30, 8310040267

8310050483 Motion for leave to file util testimony out of time on Contention 9(B) Delay due to irreconcilable differences between witnesses, necessitating reappraisal of util case Certificate of Svc encl
 GALLO, J Consumers Power Co GALLO, J Isham, Lincoln & Beale 83/10/02 Atomic Safety and Licensing Board Panel 5pp 20633 236 24X Fiche 50-155, 83/10/02, 8310050483

--8310050486 Forwards RW Sinderman, RD Klimm, E Muma, F Welch & GT Lasater testimony on emergency planning Contention 9(B)
 GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co 83/10/02 BLOCH, P B, PARIS, O H, SHDN, T J Atomic Safety and Licensing Board Panel 4pp 20633 241 24X Fiche 50-155, 83/10/02, 8310050483

--8310050489 Testimony of RW Sinderman re Christa-Maria Contention 9(B) on summer & winter emergency plans Evacuation time estimates take into account seasonal factors Plan adequately addresses summer & winter conditions
 SINDERMAN, R W Consumers Power Co 83/10/02 34pp 20633 244 24X Fiche 50-155, 83/10/02, 8310050483

--8310050491 Testimony of RD Klimm re Christa-Maria Contention 9(B) on summer & winter emergency plans Evacuation time estimate studies address summer & winter conditions
 KLIMM, R D Consumers Power Co KLIMM, R D HMM Associates, Inc 83/10/02 17pp 20633 278 24X Fiche 50-155, 83/10/02, 8310050483

--8310050494 Testimony of E Muma re Christa-Maria Contention 9(B) on summer & winter emergency plans County emergency plan flexible enough to accommodate influx of seasonal population during summer & adverse winter weather
 MUMA, E Consumers Power Co MUMA, E Charlevoix, MI 83/10/02 7pp 20633 295 24X Fiche 50-155, 83/10/02, 8310050483

--8310050501 Testimony of GT Lasater re Christa-Maria Contention 9(B) on summer & winter emergency plans Summer/winter conditions will not have effects significant enough to require separate planning
 LASATER, G T Consumers Power Co LASATER, G T Charlevoix, MI 83/10/02 7pp 20633 302 24X Fiche 50-155, 83/10/02, 8310050483

DOCKETED ITEMS

17

--831009050/ Testimony of F Welch re Christa-Maria Contention 9(b) on summer & winter emergency plans Emergency plan will accommodate difficulties posed by winter weather
WELCH, F Consumers Power Co WELCH, F Charlevoix, MI 83/10/07 10pp 20633 309 24X Fiche 50-155,83/10/02,8310050483

8310110207 Forwards list of witnesses & documents for 831024-1106 hearing re spent fuel pool mod Testimony of AJ Schwartz will be forwarded if requested Related correspondence
O'NEILL, J O'Neill, J 83/10/03 BLOCH, P B, PARIS, D H, SHON, F J Atomic Safety and Licensing Board Panel 11pp 20665 031 24X Fiche 50-155,83/10/03,8310110207

8310110063 Motion for extension of time for filing testimony of CP Betourne & RM Marusich from 830930 to 831008 Witness has not received all documentation needed Certificate of Svc encl
GALLO, J Consumers Power Co GALLO, J Isham, Lincoln & Beale 83/10/04 Atomic Safety and Licensing Board Panel 5pp 20667 307 24X Fiche 50-155,83/10/04,8310110063

8310120365 Application for subpoenas directing GT Lasater, F Numa & JF Iless to testify Util has reason to believe witnesses will not appear except upon issuance of subpoena Draft subpoenas & Certificate of Svc encl
COPELAND, V G Consumers Power Co COPELAND, V G Isham, Lincoln & Beale 83/10/04 Atomic Safety and Licensing Board Panel 14pp 20699 303 24X Fiche 50-155,83/10/04,8310120365

8310140039 Advises of inability to testify at 831024-1106 hearing due to teaching & counseling duties
SCHWARTZ, A J Michigan, Univ of, Ann Arbor, MI 83/10/04 BLOCH, P B, SHON, F J, PARIS, D H Atomic Safety and Licensing Board Panel 1p 20748 084 24X Fiche 50-155,83/10/04,8310140039

8310130051 Informs that parties agreed to listed order of presentation of issues at 831025-1104 evidentiary hearings & P Yanov testifying out of order during first wk of hearings
GODDARD, R J Hearing Branch 3 83/10/11 BLOCH, P B, SHON, F J, PARIS, D H Atomic Safety and Licensing Board Panel 2pp 20725 063 24X Fiche 50-155,83/10/11,8310130051

8310130194 Notice expressing ASLB concern over licensee limited interpretation of aircraft crash issue in spent fuel pool expansion proceeding
BLOCH, P B Atomic Safety and Licensing Board Panel 83/10/12 1p 20719 147 24X Fiche 50-155,83/10/12,8310130194

8310170420 Motion for order & subpoena calling J Hennigan as ASLB witness Hennigan believes testifying would be improper or constitute conflict of interest w/duties as state employee Draft testimony & Certificate of Svc encl
GALLO, J Consumers Power Co GALLO, J Isham, Lincoln & Beale 83/10/12 Atomic Safety and Licensing Board Panel 16pp 20784 021 24X Fiche 50-155,83/10/12,8310170420

8310140242 Advises that time for Commission to review ALAB-725 expired Commission declined review Decision became final agency action on 831007 Commissioner Olinisky separate views encl
CHILK, S J Office of the Secretary of the Commission 83/10/13 BIER, J Affiliation Unknown 2pp 20761 323 24X Fiche 50-155,83/10/13,8310140242

8310140247 Advises that time for Commission to review ALAB-725 expired Commission declined review Decision became final agency action on 831007 Commissioner Olinisky separate views encl
CHILK, S J Office of the Secretary of the Commission 83/10/13 O'NEILL, J O'Neill, J 2pp 20761 237 24X Fiche 50-155,83/10/13,8310140247

8310180230 Response opposing Christa-Maria 831007 motion for early recess on Halloween & for site visit Normal 5 PM recess provides ample time for Halloween festivities Site visit welcomed Certificate of Svc encl
GALLO, J Consumers Power Co GALLO, J Isham, Lincoln & Beale 83/10/13 Atomic Safety and Licensing Board Panel 4pp 20808 181 24X Fiche 50-155,83/10/13,8310180230

8310180348 Forwards prof qualifications of HJ Eckert & MK Prabhakara, inadvertently omitted from 830930 testimony
GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co 83/10/13 BLOCH, P B Atomic Safety and Licensing Board Panel PARIS, D H, SHON, F J Atomic Safety and Licensing Appeal Panel 3pp 20803 008 24X Fiche 50-155,83/10/13,8310180348

8310180335 Forwards, for info, listed documents which will not be introduced into evidence Oversize map encl Aperture card available in PDR
GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co 83/10/14 BLOCH, P B, PARIS, D H, SHON, F J Atomic Safety and Licensing Board Panel 73pp 20809 2/9 24X Fiche 50-155,83/10/14,8310180335

8310180222 Forwards VB Hallman affidavit & photo of US Air Force B-52 bomber flying over containment bldg
GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co 83/10/15 BLOCH, P B, PARIS, D H, SHON, F J Atomic Safety and Licensing Board Panel 2pp 20808 185 24X Fiche 50-155,83/10/15,8310180222

--8310180224 Affidavit of VB Hallman attesting that US Air Force B-52 bomber flew directly over facility in June 1966 Photograph encl
HALLMAN, V B Consumers Power Co 83/09/20 2pp 20808 187 24X Fiche 50-155,83/10/15,8310180224

8310240128 Advises that L Reiter 820917 deposition re O'Neill Contention 11C on development of site-specific spectrum & work performed by TERA Corp & LLL may be used as cross-examination tool &/or offered into evidence
GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co 83/10/19 BLOCH, P B, PARIS, D H, SHON, F J Atomic Safety and Licensing Board Panel 2pp 20881 154 24X Fiche 50-155,83/10/19,8310240128

--8310240132 Motion to strike Mr Phillips testimony re Christa-Maria Contention 9, Subparts 1,6,8 & 9 Testimony beyond scope of contention & irrelevant Certificate of Svc encl
GALLO, J, THORNTON, P Consumers Power Co GALLO, J Isham, Lincoln & Beale 83/10/19 Atomic Safety and Licensing Board Panel 8pp 20881 156 24X Fiche 50-155,83/10/19,8310240132

8310250160 Informs that TM Cheng will replace D Persinko as co-sponsor for NRC testimony on O'Neill Contention 11C re seismic crane issue Prof qualifications encl
BACHMAN, R G Hearing Branch 1 83/10/19 BLOCH, P B, SHON, F J, PARIS, D H Atomic Safety and Licensing Board Panel 3pp 20896 290 24X Fiche 50-155,83/10/19,8310250160

8310250307 Advises that ASLB June 1982 hearing in Bayne Falls, MI re proposed expansion of spent fuel storage capacity at Facility will reconvene on 831025 in Petoskey, MI Response to written limited appearance statement encl
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/21 WILL, C W Affiliation Unknown 67pp 20896 005 24X Fiche 50-155,83/10/21,8310250307

8310310206 Motion to quash hearing subpoena directed to RJ Rajewski Licensee not served w/copy of subpoena application, clearly violating 10CFR2 701(b) & 10CFR2 712(b) Testimony would be irrelevant Certificate of Svc encl
GALLO, J, COPELAND, V G Consumers Power Co GALLO, J Isham, Lincoln & Beale 83/10/24 Atomic Safety and Licensing Board Panel 5pp 20958 324 24X Fiche 50-155,83/10/24,8310310206

8310310139 Motion to strike P Chen testimony re Christa Maria Contention 8 & O'Neill Contention 11E-2 genuine issue of fact Testimony beyond scope of genuine issue Certificate of Svc encl
GALLO, J, THORNTON, P Consumers Power Co GALLO, J Isham, Lincoln & Beale 83/10/25 Atomic Safety and Licensing Board Panel 5pp 20959 060 24X Fiche 50-155,83/10/25,8310310139

8310310145 Notice of appearance in proceeding Certificate of Svc encl
FITZGERALD, R Consumers Power Co FITZGERALD, R Isham, Lincoln & Beale 83/10/25 3pp 20959 011 24X Fiche 50-155,83/10/25,8310310145

8310310391 Motion to quash J Hol 831025 subpoena to appear at 831026 hearing re Christa-Maria Contention 9(b) & O'Neill Contention 11D Subpoena not relevant to contention issue Certificate of Svc encl
GALLO, J, FITZGERALD, R Consumers Power Co GALLO, J Isham, Lincoln & Beale 83/10/26 Atomic Safety and Licensing Board Panel 7pp 20959 275 24X Fiche 50-155,83/10/26,8310310391

P Operating license stage documents & correspondence

8310110004 Responds to FOIA request for five documents Forwards documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/07/01 PEDRO, J NUB Corp 2pp 20704 137 24X Fiche 50-000,83/07/01,8310110004

8310050005 Summary of 830915 meeting w/util & Structural Mechanics Assoc in Bethesda, MD re seismic capability of semigantry crane
EMCH, R L Operating Reactors Branch 5 83/09/26 Operating Reactors Branch 5 8pp 20650 247 24X Fiche 50-155,83/09/26,8310050005

DOCKETED ITEMS

- 8310040264 Forwards Rev 1 to "Confirmatory Analysis, Support Wall Stress Analysis," in response to NRC 830813 ltr Analysis conservatively demonstrates & quantifies that adequate safety margins inherent in walls Commitment closed
BORDINE, T C Consumers Power Co 83/09/28 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 20613 136 24X
Fiche 50-155, 83/09/28, 8310040264
- 8310040266 Rev 1 to "Confirmatory Analysis, Support Wall Stress Analysis"
* Consumers Power Co 83/09/28 37pp 20613 137 24X
Fiche 50-155, 83/09/28, 8310040264
- 8310030492 Forwards suppl to 810515 SER re application for design changes in spent fuel pool makeup line & thermal & structural analyses of pool at 150 F Design acceptable
CRUTCHFIELD, D Operating Reactors Branch 5 83/09/30
VANDEWALLE, D J Consumers Power Co 3pp 20601 097 24X
Fiche 50-155, 83/09/30, 8310030492
- 8310030497 Supplemental safety evaluation accepting mod to spent fuel storage pool makeup line & 150 F operation temp
* Office of Nuclear Reactor Regulation, Director 83/09/30
21pp 20601 090 24X Fiche 50-155, 83/09/30, 8310030492
- 8310060024 Forwards "Environ Equipment Qualification - Results of Failure Modes & Effects Analysis (FM&EA)" Results show safety functions of equipment performed after event will not affect functions or mislead operator
TOMER, K A Consumers Power Co 83/09/30 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 20647 107 24X Fiche 50-155, 83/09/30, 8310060024
- 8310060030 "Environ Equipment Qualification - Results of Failure Modes & Effects Analysis (FM&EA)"
* Consumers Power Co 83/09/30 19pp 20647 107 24X
Fiche 50-155, 83/09/30, 8310060024
- 8310060080 Requests exemption from requirements of 10CFR50.54(m)(2) & (3), licensed operator staffing Second shift supervisor not necessary due to plant size & simplicity Tech Specs correcting current staffing differences submitted 821220
VANDEWALLE, D J Consumers Power Co 83/10/03 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 20648 333 24X
Fiche 50-155, 83/10/03, 8310060080
- 8310180452 Forwards notice of consideration of issuance of amend to License DPR-6 to incorporate MARLHOR limits for fuel assemblies G13 & G14 into Tech Specs, per util 830907 application
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/04
VANDEWALLE, D J Consumers Power Co 3pp 20802 112 24X
Fiche 50-155, 83/10/04, 8310180452
- 8310180457 Notice of consideration of issuance of amend to License DPR-6 to incorporate MARLHOR limits for fuel assemblies G13 & G14 into Tech Specs, per util 830907 application
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/04 6pp
20802 113 24X Fiche 50-155, 83/10/04, 8310180452
- 8310120274 Advises that FR, containing Commission monthly notices which afford public opportunities for hearing on requests for action, will be transmitted w/o forwarding ltr in future
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/07
VANDEWALLE, D J Consumers Power Co 3pp 20691 047 24X
Fiche 50-000, 83/10/07, 8310120274
- 8310130296 Forwards formal responses to NRC 830817 & 0915 requests for addl info re seismic capability of semigantry crane
Responses transmitted informally on 830825 & 0923
BORDINE, T C Consumers Power Co 83/10/07 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 20719 275 24X
Fiche 50-155, 83/10/07, 8310130296
- 8310130297 "CPC Responses," discussing semigantry crane
* Whiting Corp 83/08/25 10pp 20719 276 24X
Fiche 50-155, 83/10/07, 8310130296
- 8310130298 "Seismic Risk Contribution of Reactor Bldg Crane to Big Rock Point Spent Fuel Pool"
* Structural Mechanics Associates 83/08/25 18pp 20719 286 24X Fiche 50-155, 83/10/07, 8310130296
- 8310130299 "CPC Responses," comparing SRP Section 3.7.2 w/bldg & crane analyses
* D'Appolonia Consulting Engineers, Inc 83/09/23 20pp
20719 304 24X Fiche 50-155, 83/10/07, 8310130296
- 8310130301 "Analysis Methodology, Crane Seismic Rept 75/57 Ton Gantry, Crane 8577"
* Whiting Corp 83/09/23 3pp 20719 324 24X
Fiche 50-155, 83/10/07, 8310130296
- 8310130302 "Uncertainty in Variables Affecting Crane Responses"
* Structural Mechanics Associates 83/09/23 8pp 20719 327 24X Fiche 50-155, 83/10/07, 8310130296
- 8310270219 Application for amend to License DPR-6, changing Tech Spec reactor vessel pressure/temp limits
VANDEWALLE, D J Consumers Power Co 83/10/24 CRUTCHFIELD, D
Operating Reactors Branch 5 3pp 20924 077 24X
Fiche 50-155, 83/10/24, 8310270219
- 8310270221 Proposed Tech Spec Table 4-1 changing hydrostatic test pressure/temp limits, heatup pressure/temp limits & cooldown pressure/temp limits to 18 HFF
* Consumers Power Co 83/10/24 16pp 20924 080 24X
Fiche 50-155, 83/10/24, 8310270219
- 8310310376 Forwards supplemental application for amend to License DPR-6, revising Tech Specs to expand spent fuel pool storage capacity, per 790626 application
VANDEWALLE, D J Consumers Power Co 83/10/25 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 20959 242 24X
Fiche 50-155, 83/10/25, 8310310376
- 8310310379 Supplemental application for amend to License DPR-6, revising Tech Specs to expand spent fuel pool storage capacity, per 790626 application
DEWITT, R B Consumers Power Co 83/10/25 3pp 20959 244 24X
Fiche 50-155, 83/10/25, 8310310376
- 8310310383 Proposed Tech Specs re spent fuel pool storage capacity expansion
* Consumers Power Co 83/10/25 5pp 20959 247 24X
Fiche 50-155, 83/10/25, 8310310376
- 0 Inspection reports, IE Bulletins & correspondence
- 8310060360 Forwards IE Insp Rept 50-155/BJ-14 on 830723-0909 & notice of violation
SHAFER, W D Region 3, Office of Director 83/09/21 DEWITT, R B
Consumers Power Co 2pp 20646 110 24X Fiche 50-155, 83/09/21, 8310060360
- 8310060372 Notice of violation from insp on 830723-0909
SHAFER, W D Region 3, Office of Director 83/09/21 1p
20646 112 24X Fiche 50-155, 83/09/21, 8310060360
- 8310060374 IE Insp Rept 50-155/BJ-14 on 830723-0909 Noncompliance noted failure to implement control of tools
WRIGHT, G C, BOYD, D C Region 3, Office of Director 83/09/20
7pp 20646 113 24X Fiche 50-155, 83/09/21, 8310060360
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349
- 8310120326 Ack receipt of 830921 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-155/83-12
NDRELIUS, C E Division of Project & Resident Programs 83/10/05
DEWITT, R B Consumers Power Co 1p 20700 267 24X
Fiche 50-155, 83/10/05, 8310120326
- 8310120327 Responds to NRC 830822 ltr re violations noted in IE Insp Rept 50-155/83-12 Corrective actions caution signs on breaker cabinets modified & administrative procedures & training will be revised by 831215
VANDEWALLE, D J Consumers Power Co 83/09/21 KEPLER, J O
Region 3, Office of Director 3pp 20700 268 24X
Fiche 50-155, 83/10/05, 8310120326

DOCKETED ITEMS

19

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180262 Clarifies NRC position re procedures for admitting NRC personnel to Facilities Access should be afforded to Region III personnel listed in encl Update will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 DEWITT, R B Consumers Power Co 7pp 20802 282 24X Fiche 50-155, 83/10/14, 8310180262

8310180551 Notification of 831021 meeting w/DWR licensees in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking
MIRAGLIA, F J Assistant Director for Safety Assessment 83/10/14 EISENHUT, D O Division of Licensing 5pp 20823 358 24X Fiche 50-000, 83/10/14, 8310180551

8310250191 Forwards final SALP Rept 50-255/83-21 for Jul 1982 - June 1983 Licensee improvement since earlier assessments noted
KEPPLER, J O Region 3, Office of Director 83/10/20 DEWITT, R B Consumers Power Co 2pp 20894 001 24X Fiche 50-000, 83/10/20, 8310250191

--8310250203 Informs that licensee will meet all commitments in plant regulatory performance improvement program in response to NRC 830909 ltr transmitting SALP for Jul 1982 - June 1983
VANDEWALLE, D J Consumers Power Co 83/09/26 KEPPLER, J O Region 3, Office of Director 1p 20894 036 24X Fiche 50-000, 83/10/20, 8310250191

8310250522 Forwards SALP Rept 50-155/83-15 for Jul 1982 - June 1983 Util has improved rating in five functional areas including satisfactory resolution of previously identified concerns
KEPPLER, J O Region 3, Office of Director 83/10/20 DEWITT, R B Consumers Power Co 2pp 20900 316 24X Fiche 50-155, 83/10/20, 8310250522

--8310250535 SALP Rept 50-155/83-15 for Jul 1982 - June 1983 Licensee should develop & implement program to identify applicable regulatory requirements & licensee commitments to ensure compliance w/GA activities All other areas acceptable
* Region 3, Office of Director 83/10/20 24pp 20900 318 24X Fiche 50-155, 83/10/20, 8310250522

--8310250548 Discusses proposed 830916 meeting to discuss SALP for Jul 1982 - June 1983 SALP rept documenting analyses, conclusions & recommendations provided for review prior to meeting
Comments on rept to be discussed at meeting
HIND, J A Division of Radiological & Materials Safety Programs 83/09/09 DEWITT, R B Consumers Power Co 3pp 20900 342 24X Fiche 50-155, 83/10/20, 8310250522

B Reportable occurrences, LERs & related correspondence

8310120110 LER 83-011/03L-0 on 830828, packing leak occurred on inlet valve M07062 in loop 1 of emergency condenser Caused by inlet valve opening time being slower than outlet valve time Packing replaced W/830928 ltr
BORDINE, T C Consumers Power Co 83/09/28 KEPPLER, J O Region 3, Office of Director 2pp 20696 171 24X Fiche 50-155, 83/09/20, 8310120110

8310170465 Updated LER 82-023/03X-1 on 820801, backup core spray valve M0-7071 opening stroke found approx 1/2 normal full stroke Caused by marginal clutch New model operator installed W/831006 ltr
BORDINE, T C Consumers Power Co 83/10/06 KEPPLER, J O Region 3, Office of Director 2pp 20783 250 24X Fiche 50-155, 83/10/06, 8310170465

8310170486 Updated LER 82-021/03X-1 on 820707, during quarterly test of backup core spray valve M0-701, both open & closed position indication lights remained on w/valve returned to normal closed position Caused by worn clutch W/831006 ltr
BORDINE, T C Consumers Power Co 83/10/06 KEPPLER, J O Region 3, Office of Director 2pp 20783 340 24X Fiche 50-155, 83/10/06, 8310170486

8310170552 Updated LER 82-017/03X-1 on 820503, backup core spray sys automatic valve M0-7071 made inoperable in closed position for repair & troubleshooting Limit switch in closing control circuit adjusted W/831006 ltr
BORDINE, T C Consumers Power Co 83/10/06 KEPPLER, J O Region 3, Office of Director 1p 20780 349 24X Fiche 50-155, 83/10/06, 8310170552

8310270245 LER 83-013/03L-0 on 830921, following lightning strike, blwnw fuse observed on static inverter equipment for one of two containment vacuum relief loops Telephone & security equipment & domestic water controls affected W/831020 ltr
BORDINE, T C Consumers Power Co 83/10/20 KEPPLER, J O Region 3, Office of Director 2pp 20724 047 24X Fiche 50-155, 83/10/20, 8310270245

T Hearing transcripts on non-antitrust matters

8310040620 Testimony of Christa-Maria, Bier & Mills on Christa-Maria Contention 8 & O'Neill Contention III-2 re makeup water line
CHRISTA-MARIA Christa-Maria 83/09/25 12pp 20626 062 24X Fiche 50-155, 83/09/25, 8310040620

--8310040621 Testimony of Christa-Maria, Bier & Mills on Christa-Maria Contention 2 & O'Neill Contention IIA re south wall workers
CHRISTA-MARIA Christa-Maria 83/09/28 5pp 20626 074 24X Fiche 50-155, 83/09/25, 8310040620

--8310040624 Testimony of Christa-Maria, Bier & Mills on O'Neill Contention II E 4 re adequate containment shielding Certificate of Svc encl
CHRISTA-MARIA Christa-Maria 83/09/30 3pp 20626 077 24X Fiche 50-155, 83/09/25, 8310040620

8310040553 Forwards testimony of RW Sinderman re Christa-Maria emergency planning Contention 9 Testimony concludes that no justification exists for enlarging size of present emergency planning zones
GALLD, J Isham, Lincoln & Beale GALLD, J Consumers Power Co 83/09/29 BLOCH, P B, SHON, F J, PARIS, O H Atomic Safety and Licensing Board Panel 2pp 20623 212 24X Fiche 50-155, 83/09/29, 8310040553

--8310040557 Testimony of RW Sinderman on Christa-Maria Contention 9 re size of emergency planning zones
SINDERMAN, R W Consumers Power Co 83/09/29 35pp 20623 214 24X Fiche 50-155, 83/09/29, 8310040557

8310040365 Forwards CE Axtell, RW Sinderman & EF Benz testimony re Christa-Maria Contention 2 & O'Neill Contention IIA
GALLD, J Isham, Lincoln & Beale GALLD, J Consumers Power Co 83/09/30 BLOCH, P B, PARIS, O H, SHON, F J Atomic Safety and Licensing Board Panel 2pp 20621 017 24X Fiche 50-155, 83/09/30, 8310040365

--8310040367 Testimony of RW Sinderman re Christa-Maria Contention 2 & O'Neill Contention IIA on use of appropriate coefficients & ALARA program Util has implemented comprehensive radiation safety program
SINDERMAN, R W Consumers Power Co 83/09/30 10pp 20621 019 24X Fiche 50-155, 83/09/30, 8310040365

--8310040369 Testimony of EF Benz re Christa-Maria Contention 2 & O'Neill Contention IIA on radiation dose rate measurement outside south wall from spent fuel stored in spent fuel pool
BENZ, E F Consumers Power Co 83/09/30 14pp 20621 029 24X Fiche 50-155, 83/09/30, 8310040365

--8310040373 Testimony of CE Axtell re Christa-Maria Contention 2 & O'Neill Contention IIA on dimensions of south wall of spent fuel pool Discrepancy has no effect on radiation dose calculations provided by util
AXTELL, C E Consumers Power Co 83/09/30 186pp 20621 043, 24X Fiche 50-155, 83/09/30, 8310040365

8310040376 Forwards HJ Eckert & MK Prabhakara testimony re Contentions 8 & III E-2 on structural integrity of spent fuel pool concrete
GALLD, J Isham, Lincoln & Beale GALLD, J Consumers Power Co 83/09/30 BLOCH, P B, PARIS, O H, SHON, F J Atomic Safety and Licensing Board Panel 2pp 20618 001 24X Fiche 50-155, 83/09/30, 8310040376

DOCKETED ITEMS

- B310040381 Testimony of HJ Eckert & MK Prabhakara re Christa-Maria Contention 8 & O'Neill Contention III E-2 on structural integrity of concrete spent fuel pool if pool coolant temp rises to 150 F for extended period of time
ECKERT, H J, PRABHAKARA, M K Consumers Power Co ECKERT, H J NU
Corp 83/09/30 37pp 20618 003 24X Fiche 50-155, 83/09/30, 8310040376
- B310040505 Forwards JV Lyczkowski & W Hickey joint testimony re O'Neill Contention IA re Ohio Natl Guard flights in plant vicinity
Related correspondence
GALLD, J Isham, Lincoln & Beale GALLD, J Consumers Power Co
83/09/30 BLOCH, P B, PARIS, D H, SHON, F J Atomic Safety and
Licensing Board Panel 1p 20625 245 24X Fiche 50-155, 83/09/30, 8310040505
- B310040519 Testimony of JV Lyczkowski & WP Hickey re O'Neill Contention IID on Ohio Natl Guard flights in plant vicinity
Chance of accident at plant is less than one in one hundred million
LYCZKOWSKI, J V, HICKEY, W P Consumers Power Co LYCZKOWSKI, J V
Ohio, State of 83/09/30 21pp 20625 246 24X
Fiche 50-155, 83/09/30, 8310040505
- B310040545 Testimony of Christa-Maria on emergency planning & risk of aircraft contentions
CHRISTA-MARIA Christa-Maria 83/09/30 62pp 20623 147 24X
Fiche 50-155, 83/09/30, 8310040545
- B310040548 Forwards testimony of RW Sinderman re O'Neill Contention IIE-4 Testimony justifies adequacy of containment shell
GALLD, J Isham, Lincoln & Beale GALLD, J Consumers Power Co
83/09/30 BLOCH, P B, PARIS, D H, SHON, F J Atomic Safety and
Licensing Board Panel 2pp 20622 121 24X Fiche 50-155, 83/09/30, 8310040548
- B31004056B Testimony of RW Sinderman re O'Neill Contention IIE-4
witnessing adequacy of steel containment shell
SINDERMAN, R W Consumers Power Co 83/09/30 /pp 20622 123
24X Fiche 50-155, 83/09/30, 8310040548
- B310040551 Forwards CE Artell & RM Marusich testimony re Christa Maria emergency planning Contention 9(a)
GALLD, J Isham, Lincoln & Beale GALLD, J Consumers Power Co
83/09/30 BLOCH, P B, PARIS, D H, SHON, F J Atomic Safety and
Licensing Board Panel 1p 20622 130 24X Fiche 50-155, 83/09/30, 8310040551
- B310040560 Testimony of RM Marusich re Christa-Maria Contention 9(a) on emergency planning - radiation monitoring
Util has capability to assess degree of core damage promptly following accident
MARUSICH, R M Consumers Power Co 83/09/30 16pp 20622 131
24X Fiche 50-155, 83/09/30, 8310040551
- B310040564 Testimony of CE Artell re Christa-Maria Contention 9(a) on emergency planning - radiation monitoring
Use of noble gas effluent monitors, in-plant iodine instruments & containment high-range radiation monitors discussed
ATELL, C E Consumers Power Co 83/09/30 13pp 20622 147 24X
Fiche 50-155, 83/09/30, 8310040551
- 0040594 Forwards AE Tome testimony on O'Neill Contention II-D re risk of accident from crashes of certain aircraft
ALLO, J Isham, Lincoln & Beale GALLD, J Consumers Power Co
83/09/30 BLOCH, P B, PARIS, D H, SHON, F J Atomic Safety and
Licensing Board Panel 2pp 20626 189 24X Fiche 50-155, 83/09/30, 8310040594
- B310040611 Testimony of AE Tome on O'Neill Contention II-D re risks from unscheduled general aviation flights
TOME, A E Consumers Power Co TOME, A E Wood-Leaver & Associates, Inc 83/09/30 44pp 20626 191 24X
Fiche 50-155, 83/09/30, 8310040594
- B310050461 Testimony of KM Campe on O'Neill Contention II D re aircraft hazards at plant
Risk of aircraft crash & impact on plant sufficiently low so aircraft impacts need not be design basis for plant
CAMPE, K M Site Analysis Branch 83/09/30 88pp 20624 041 24X
Fiche 50-155, 83/09/30, 8310050461
- B31005047B Testimony of S Block re Christa-Maria Contention 2 & O'Neill Contention II A Util calculations of dose rate at south boundary of spent fuel pool acceptable
BLOCK, S Division of Systems Integration (post 811005) 83/09/30
7pp 20629 132 24X Fiche 50-155, 83/09/30, 8310050461
- B310050481 Testimony of ML Wohl re O'Neill Contention II E 4 Adequate shielding of containment bldg exists to protect public from potential radioactivity releases from expanded spent fuel pool
WOHL, M L Accident Evaluation Branch 83/09/30 7pp 20627 141
24X Fiche 50-155, 83/09/30, 8310050461
- B310050485 Testimony of MP Phillips re Christa-Maria Contention 9, Subparts 1, 6, B & 9 Discusses how possibility of fuel pool accident considered in determining planning basis for size of emergency planning zone
PHILLIPS, M P Division of Radiological & Materials Safety
Programs 83/09/30 56pp 20629 148 24X Fiche 50-155, 83/09/30, 8310050461
- B310050495 Testimony of D Persinko re Christa-Maria Contention 8 & O'Neill Contention III E-2, Genuine Issue of Fact 5 Spent fuel structure adequate to withstand increased load from pool expansion for water temp up to 150 F
PERSINKO, D Systematic Evaluation Program Branch 83/09/30 7p
20629 204 24X Fiche 50-155, 83/09/30, 8310050461
- B310050500 Testimony of P Chen re Christa-Maria Contention II & O'Neill Contention III E-2, Genuine Issue of Fact 1 Spent fuel pool makeup line adequately designed for seismic loads
CHEN, P Systematic Evaluation Program Branch 83/09/30 10pp
20629 211 24X Fiche 50-155, 83/09/30, 8310050461
- B310050504 Testimony of MA Caruso re Christa-Maria Contention II & O'Neill Contention II E 2, Genuine Issue of Fact 5 Temp gradients acceptable for input into structural analysis
CARUSO, M A Operating Reactors Assessment Branch 83/09/30 7p
20629 221 24X Fiche 50-155, 83/09/30, 8310050461
- B310050514 Testimony of F Clemenson & RL Emch re Christa-Maria Contention 8 & O'Neill Contention II E-2, Genuine Issue of Fact 1 Remotely activated makeup water sys is reliable
Certificate of Bvt encl
CLEMENSCH, F Auxiliary Systems Branch EMCH, R I Division of
Licensing 83/09/30 39pp 20629 228 24X Fiche 50-155, 83/09/30, 8310050461
- B310050483 Motion for leave to file until testimony out of time on Contention 9(a) Delay due to irreconcilable differences between witnesses, necessitating reappraisal of util case
Certificate of Bvt encl
GALLD, J Consumers Power Co GALLD, J Isham, Lincoln & Beale
83/10/02 Atomic Safety and Licensing Board Panel 5pp
20633 236 24X Fiche 50-155, 83/10/02, 8310050483
- B310050486 Forwards RW Sinderman, RD Klimm, E Muma, F Welch & GT Lasater testimony on emergency planning Contention 9(a)
GALLD, J Isham, Lincoln & Beale GALLD, J Consumers Power Co
83/10/02 BLOCH, P B, PARIS, D H, SHON, F J Atomic Safety and
Licensing Board Panel 3pp 20633 241 24X Fiche 50-155, 83/10/02, 8310050483
- B310050489 Testimony of RW Sinderman re Christa-Maria Contention 5 on summer & winter emergency plans
Evacuation time estimates take into account seasonal factors
Plan adequately addresses summer & winter conditions
SINDERMAN, R W Consumers Power Co 83/10/02 34pp 20633 244
24X Fiche 50-155, 83/10/02, 8310050483
- B310050491 Testimony of RD Klimm re Christa-Maria Contention 9(a) summer & winter emergency plans
Evacuation time estimate studies address summer & winter conditions
KLIMM, R D Consumers Power Co KLIMM, R D IHM Associates, Inc
83/10/02 17pp 20633 276 24X Fiche 50-155, 83/10/02, 8310050483
- B310050494 Testimony of E Muma re Christa-Maria Contention 9(a) on summer & winter emergency plans
County emergency plan flexible enough to accommodate influx of seasonal population during summer & adverse winter weather
MUMA, E Consumers Power Co MUMA, E Charlevoix, MI 83/10/02
7pp 20633 295 24X Fiche 50-155, 83/10/02, 8310050483
- B310050501 Testimony of GT Lasater re Christa-Maria Contention 9(a) summer & winter emergency plans
Summer/winter conditions will not have effects significant enough to require separate planning
LASATER, G T Consumers Power Co LASATER, G T Charlevoix, MI
83/10/02 7pp 20633 302 24X Fiche 50-155, 83/10/02, 8310050483
- B310050507 Testimony of F Welch re Christa-Maria Contention 9(a) summer & winter emergency plans
Emergency plan will accommodate difficulties posed by winter weather
WELCH, F Consumers Power Co WELCH, F Charlevoix, MI 83/10/02
10pp 20633 309 24X Fiche 50-155, 83/10/02, 8310050483

DOCKETED ITEMS

21

10110045 Forwards R Marusich testimony on O'Neill Contention II D
GALLD, J Isham, Lincoln & Beale GALLD, J Consumers Power Co
03/10/04 BLOCH, P B , PARIS, D H , SHON, F J Atomic Safety and
Licensing Board Panel 2pp 20665 27B 24X Fiche 50-155, 03/10/04,
0310110045

0310110293 Testimony of RM Marusich re O'Neill Contention II-D on
risks from unscheduled general aviation flights Probability
of crash within SRP criterion
MARUSICH, R M Consumers Power Co 03/10/04 7pp 20665 28U
24X Fiche 50-155, 03/10/04, 0310110045

10130001 Testimony of NC Chokshi & D Persinko re O'Neill Contention
II C as restated in ASLB 020217 order, i.e spent fuel pool
mod Prof qualifications encl
CHOKSHI, N C Structural & Geotechnical Engineering Branch
PERSINKO, D Systematic Evaluation Program Branch 03/10/07 10pp
20725 236 24X Fiche 50-155, 03/10/07, 0310130001

0310130002 Testimony of L Reiter re site specific spectra (earthquake
ground motion) Prof qualifications & Certificate of Svc
encl
REITER, L Geosciences Branch 03/10/07 23pp 20725 254 24X
Fiche 50-155, 03/10/07, 0310130001

110120211 Forwards CR Norman, YF Chan, SB Beachum, RB Jenkins, PI Yaney,
AJ Eggenberger & DJ VandeWalle testimony on O'Neill
Contention IIC re seismic stability of overhead containment
crane
GALLD, J Isham, Lincoln & Beale GALLD, J Consumers Power Co
03/10/08 BLOCH, P B , PARIS, D H , SHON, F J Atomic Safety and
Licensing Board Panel 2pp 20688 065 24X Fiche 50-155, 03/10/08,
0310120211

-0310120215 Testimony of CR Norman re O'Neill Contention IIC on seismic
stability of overhead crane Crane will not deform
permanently, become unstable or tip over due to postulated
seismic loading
NORMAN, C R Consumers Power Co NORMAN, C R Whiting Corp
03/10/08 140pp 20688 067 24X Fiche 50-155, 03/10/08,
0310120211

-0310120218 Testimony of YF Chan re O'Neill Contention IIC on seismic
stability of overhead crane Crane supports & crane stops
structurally sound & able to withstand loadings associated
w/postulated seismic event, w/mod to connection as noted
CHAN, Y F Consumers Power Co 03/10/08 38pp 20688 230 24X
Fiche 50-155, 03/10/08, 0310120211

-0310120221 Testimony of SB Beachum & RB Jenkins re O'Neill
Contention IIC on seismic stability of overhead crane Mods
to crane provide added safety re earthquake loading No
anchorage component found deficient
BEACHUM, S B , JENKINS, R B Consumers Power Co 03/10/08 18pp
20688 269 24X Fiche 50-155, 03/10/08, 0310120211

-0310120225 Testimony of AJ Eggenberger re O'Neill Contention IIC on
seismic stability of containment crane Summarizes results of
methodology used in analyses performed by Whiting Crane
Corp & Structural Mechanics Assoc, Inc
EGGENBERGER, A Consumers Power Co EGGENBERGER, A D'Appolonia
Consulting Engineers, Inc 03/10/08 373pp 20688 286 24X
Fiche 50-155, 03/10/08, 0310120211

-0310120229 Testimony of DJ VandeWalle re O'Neill Contention IIC on
seismic stability of containment crane Explains applicable
seismic design criteria & genesis & licensing status of
earthquake peak ground acceleration
VANDEWALLE, D J Consumers Power Co 03/10/08 9pp 20689 277
24X Fiche 50-155, 03/10/08, 0310120211

-0310120233 Testimony of PI Yaney re O'Neill Contention IIC on seismic
stability of containment crane Crane, w/mods, will safely
perform function during & after earthquake associated w/
postulated ground acceleration of 17g
YANEV, P I Consumers Power Co YANEV, P I EQE, Inc 03/10/08
125pp 20689 308 24X Fiche 50-155, 03/10/08, 0310120211

0310130214 Forwards QP Betourne testimony on Contention IID re risk of
accident from crash of B-52 bomber
GALLD, J Isham, Lincoln & Beale GALLD, J Consumers Power Co
03/10/08 BLOCH, R B , PARIS, D H , SHON, F J Atomic Safety and
Licensing Board Panel 2pp 20725 026 24X Fiche 50-155, 03/10/08,
0310130214

--0310130218 Testimony of QP Betourne on O'Neill Contention IID re risk
of B-52 bomber crash Strategic Air Command prohibited use of
plant as navigational offset
BETOURNE, Q P Consumers Power Co 03/10/08 20pp 20725 028
24X Fiche 50-155, 03/10/08, 0310130214

0310140074 Forwards J Hess testimony & C Muma revised testimony re
Christa-Maria Contention 9(B) on summer & winter emergency
plans
GALLD, J Isham, Lincoln & Beale GALLD, J Consumers Power Co
03/10/10 BLOCH, P B , PARIS, D H , SHON, F J Atomic Safety and
Licensing Board Panel 2pp 2076B 023 24X Fiche 50-155, 03/10/10,
0310140074

--0310140076 Testimony of JF Hess re Christa-Maria Contention 9(B) on
summer & winter emergency plans Charlevoix emergency plan
adequately considers effects of heavy tourism in summer &
adverse winter weather conditions
HESS, J F Consumers Power Co HESS, J F Charlevoix, MI
03/10/13 4pp 2076B 025 24X Fiche 50-155, 03/10/10, 0310140074

--0310140078 Revised testimony of E Muma re Christa-Maria Contention 9(B)
on summer & winter emergency plans Charlevoix emergency plan
allows different seasonal conditions to be considered
MUMA, E Consumers Power Co MUMA, E Charlevoix, MI 03/10/13
6pp 2076B 029 24X Fiche 50-155, 03/10/10, 0310140074

0310130174 Forwards DJ VandeWalle new testimony on O'Neill Contention
IIC re seismic stability of containment crane Final revs
inadvertently omitted
GALLD, J Isham, Lincoln & Beale GALLD, J Consumers Power Co
03/10/11 BLOCH, P B , PARIS, D H , SHON, F J Atomic Safety and
Licensing Board Panel 1p 20724 305 24X Fiche 50-155, 03/10/11,
0310130174

--0310130179 Testimony of DJ VandeWalle re O'Neill Contention IIC on
seismic stability of containment crane Explains applicable
seismic design criteria & genesis & licensing status of
earthquake peak ground acceleration
VANDEWALLE, D J Consumers Power Co 03/10/11 9pp 20724 306
24X Fiche 50-155, 03/10/11, 0310130174

0310310350 Transcript of 031025 hearing in Petoskey, MI Pp 2, 720-2, 976
Supporting documentation encl
* Atomic Safety and Licensing Board Panel 03/10/25 357pp
20936 075 24X Fiche 50-155, 03/10/25, 0310310350

V Operator Examinations

0310250522 Forwards SALP Rept 50-155/03-15 for Jul 1982 - June 1983
Util has improved rating in five functional areas including
satisfactory resolution of previously identified concerns
KEPPLER, J O Region 3, Office of Director 03/10/20 DEWITT, R B
Consumers Power Co 2pp 20900 316 24X Fiche 50-155, 03/10/20,
0310250522

--0310250535 SALP Rept 50-155/03-15 for Jul 1982 - June 1983 Licensee
should develop & implement program to identify applicable
regulatory requirements & licensee commitments to ensure
compliance w/QA activities All other areas acceptable
* Region 3, Office of Director 03/10/20 24pp 20900 318 24X
Fiche 50-155, 03/10/20, 0310250522

DOCKET 50-163 GENERAL ATOMIC CO

P Operating license stage documents & correspondence

0310180319 Comments on Amends to Licenses R-38 & R-67 to reflect name
change to QA Technologies Co Amends unnecessary since
facilities operational through 1983
MOGAN, J P QA Technologies, Inc /General Atomic Co 03/10/13
THOMAS, C O Standardization & Special Projects Branch 2pp
20806 231 24X Fiche 50-089, 03/10/13, 0310180319

DOCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

031004025Q Requests extension until 031031 to submit emergency plan.
Written agreement w/Montgomery County Fire Dept & Univ of
Maryland College Park Campus Police Dept awaited
TOLL, J S Maryland, Univ of, College Park, MD 03/09/29
THOMAS, C O Standardization & Special Projects Branch 1p
20617 274 24X Fiche 50-166, 03/09/29, 031004025B

0310240147 Responds to 030929 request for extension in responding to
emergency plan questions Final extension until 031031
granted
THOMAS, C O Standardization & Special Projects Branch 03/10/17
TOLL, J S Maryland, Univ of, College Park, MD 1p 20884, 341
24X Fiche 50-166, 03/10/17, 0310240147

DOCKETED ITEMS

V Operator Examinations

8310140118 Rev 3 to "Reactor Operator Requalification Program for Maryland Univ Training Reactor " W/830930 ltr
TOLL, J S Maryland Univ of, College Park, MD 83/06/01
THOMAS, C Standardization & Special Projects Branch 18pp
20763 05B 24X Fiche 50-166, 83/06/01, 8310140118

8310210138 Requests technical assistance in reviewing & providing evaluation rpt re Rev 3 to reactor operator requalification program Rpt should identify criteria used to establish bases for program acceptability
THOMAS, C O Standardization & Special Projects Branch 83/10/17
BOOHER, H R Licensee Qualifications Branch 1p 20883 35i 24X
Fiche 50-166, 83/10/17, 8310210138

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

F Security, medical, emergency & fire protection plans

8310210412 Releases public version of licensee notification of emergency plan implementation
FELTON, J M Division of Rules and Records 83/10/17 Document
Management Branch 1p 20882 340 24X Fiche 50-170, 83/10/17, 8310210412

--8310210413 Submits public version of notification that Oct 1982 emergency plan implemented & placed into effect on 831007
ADCOCK, B R Defense, Dept of, Defense Nuclear Agency 83/10/11
THOMAS, C O Standardization & Special Projects Branch 1p
20882 34i 24X Fiche 50-170, 83/10/17, 8310210412

DOCKET 50-171 PEACH BOTTOM ATOMIC POWER STATION, UNIT 1

P Operating license stage documents & correspondence

8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which rpts are unavailable
FELTON, J M Division of Rules and Records 83/07/06 CONNER, L
Affiliation Unknown 1p 21004 27i 24X Fiche 50-000, 83/07/06, 8310310031

DOCKET 50-183 VALLECITOS EXPERIMENTAL SUPERHEAT REACTOR

Q Inspection reports, IE Bulletins & correspondence

8310040391 Forwards IE Insp Rpts 50-018/83-01 & 50-183/83-01 on 830907 No noncompliance noted
WENSLAHEKI, F Region 5, Office of Director 83/09/15
DARMITZEL, R H General Electric Co 2pp 20620 124 24X
Fiche 50-018, 83/09/15, 8310040391

--8310040399 IE Insp Rpts 50-018/83-01 & 50-183/83-01 on 830907 No noncompliance noted Major areas inspected organization, procedures, surveys, posting & annual rpts
SHERMAN, C I, WENSLAHEKI, F A Region 5, Office of Director 83/09/15 3pp 20620 126 24X Fiche 50-018, 83/09/15, 8310040399

DOCKET 50-186 UNIV OF MISSOURI RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8310190347 Forwards request for route approval for shipment from Columbia, MO to Idaho Falls, ID per 10CFR73.37 Same route as approved in 1982 Info re planned shipping dates will be forwarded
MEYER, H A Missouri Univ of, Columbia, MO 83/09/16 HILLMAN, C
Division of Safeguards App 20843 173 24X Fiche 50-186, 83/09/16, 8310190347

8310210158 Advises that proposed route to be used for transport of spent reactor fuel, per 820916 ltr, acceptable Approval does not provide relief from assuring highway safety nor local or state legislation Spent nuclear fuel route survey encl
SHEER, T B Material Transfer Safeguards Licensing Branch 83/10/07
MEYER, H A Missouri Univ of, Columbia, MO 2pp 20884 062 24X
Fiche 50-186, 83/10/07, 8310210158

--8310210163 "Spent Nuclear Fuel Route Survey Columbia, MO to Idaho Falls, ID"
* NRC - No Detailed Affiliation Given 83/10/31 15pp
50-186, 83/10/07, 8310210158

DOCKET 50-188 KANSAS STATE UNIV RESEARCH REACTOR

R Periodic operating reports & related correspondence

8310130090 Annual operating rpt for Oct 1982 - Sept 1983
FAW, R E Kansas State Univ 83/10/07 MILLER, J R Standardization
& Special Projects Branch 2pp 20724 059 24X
Fiche 50-188, 83/10/07, 8310130090

DOCKET 50-192 UNIV OF TEXAS RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8310110380 Releases public version of revised emergency plan & emergency procedures
FELTON, J M Division of Rules and Records 83/10/05 Document
Management Branch 1p 20713 23i 24X Fiche 50-192, 83/10/05, 8310110380

--8310110386 Forwards public version of revised emergency plan & emergency procedures, including Procedures 2 O re emergency classification procedures, 51 re emergency call list & 52 re emergency equipment
BAUER, T L Texas Univ of, Austin, TX 83/07/21 THOMAS, C O
Standardization & Special Projects Branch 1p 20713 23i 24X
Fiche 50-192, 83/10/05, 8310110380

--8310110390 Public version of revised emergency plan
* Texas Univ of, Austin, TX 83/07/31 29pp 20713 23i 24X
Fiche 50-192, 83/10/05, 8310110380

--8310110392 Public version of revised emergency plan implementing procedures, including Procedures 2 O re emergency classification procedures, 51 re emergency call list & 52 re emergency equipment
* Texas Univ of, Austin, TX 83/07/31 9pp 20713 22i 24X
Fiche 50-192, 83/10/05, 8310110380

8310110424 Releases public version of licensee ltr transmitting ltr of agreement to be included w/ revised emergency plan
FELTON, J M Division of Rules and Records 83/10/05 Document
Management Branch 1p 20706 32i 24X Fiche 50-192, 83/10/05, 8310110424

--8310110429 Public version of ltr of agreement to be included w/ revised emergency plan dtd 830721 One add'l ltr of agreement w/ local hosp not yet received W/830902 ltr
BAUER, T L Texas Univ of, Austin, TX 83/09/02 THOMAS, C O
Standardization & Special Projects Branch App 20706 322 24X
Fiche 50-192, 83/10/05, 8310110424

DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC

F Security, medical, emergency & fire protection plans

8310250597 Forwards IE Safeguards Insp Rept 50-193/83-02 on 830824-25 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/10/04
DINEGLIO, A F Rhode Island, State of 2pp 20900 272 24X
Fiche 50-193, 83/10/04, 8310250597

--8310250603 IE Safeguards Insp Rept 50-193/83-02 on 830824-25 No noncompliance noted Major areas inspected physical protection measures for protecting SNM of moderate strategic significance
DUNLAP, J M, GODY, A T Region 1, Office of Director 83/09/30
2pp 20900 274 24X Fiche 50-193, 83/10/04, 8310250597

Q Inspection reports, IE Bulletins & correspondence

8310250597 Forwards IE Safeguards Insp Rept 50-193/83-02 on 830824-25 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/10/04
DINEGLIO, A F Rhode Island, State of 2pp 20900 272 24X
Fiche 50-193, 83/10/04, 8310250597

--8310250603 IE Safeguards Insp Rept 50-193/83-02 on 830824-25 No noncompliance noted Major areas inspected physical protection measures for protecting SNM of moderate strategic significance
DUNLAP, J M, GODY, A T Region 1, Office of Director 83/09/30
2pp 20900 274 24X Fiche 50-193, 83/10/04, 8310250597

DOCKET 50-199 MANHATTAN COLLEGE RESEARCH REACTOR

P Operating license stage documents & correspondence

8310050044 Forwards FR notice of consideration of 830826 application for renewal of License R-74
THOMAS, C O Standardization & Special Projects Branch 83/09/23
KANE, R S Manhattan College, Riverdale, NY 2pp 20650 281 24X
Fiche 50-199, 83/09/23, 8310050044

--8310050047 Notice of consideration of Manhattan College 830826 application for renewal of License R-74
THOMAS, C O Standardization & Special Projects Branch 83/09/23
5pp 20650 283 24X Fiche 50-199, 83/09/23, 8310050044

Q Inspection reports, IE Bulletins & correspondence

8310180377 Ack receipt of 830805 & 17 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-199/83-01
STAROSTECKI, R Division of Project & Resident Programs 83/10/07
KANE, R Manhattan College, Riverdale, NY 2pp 20603 192 24X
Fiche 50-199, 83/10/07, 8310180377

--8310180380 Responds to NRC 830711 ltr re violations noted in IE Insp Rept 50-199/83-01 Requests 3-wk extension to provide complete reply due to changes in personnel Extension will enable implementation of operator requalification program
KANE, R S Manhattan College, Riverdale, NY 83/08/05
STAROSTECKI, R Division of Project & Resident Programs 2pp
20603 194 24X Fiche 50-199, 83/10/07, 8310180377

--8310180383 Responds to NRC 830711 ltr re violations noted in IE Insp Rept 50-199/83-01 Corrective actions requalification program will be conducted continuously over 2-yr cycles & revised as needed to account for changes in equipment
KANE, R S Manhattan College, Riverdale, NY 83/08/17
STAROSTECKI, R Division of Project & Resident Programs 5pp
20603 196 24X Fiche 50-199, 83/10/07, 8310180377

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

Q Adjudicatory correspondence

8310070156 Forwards Director's Decision 83-14, denying 830909 10CFR2 206 petition re transport of spent nuclear fuel from West Valley
DAVIS, J Q Office of Nuclear Material Safety & Safeguards, Director
83/09/30 CELEDREZZE, A J Ohio, State of 2pp 20680 308 24X
Fiche 50-000, 83/09/30, 8310070156

--8310070161 Forwards Director's Decision 83-14, denying 830824 10CFR2 206 petition re transport of spent nuclear fuel from West Valley
DAVIS, J Q Office of Nuclear Material Safety & Safeguards, Director 83/09/30 REGNIKOFF, M Sierra Club 1p
20680 309 24X Fiche 50-000, 83/09/30, 8310070156

--8310070167 Notice of issuance of Director's Decision 83-14, denying State of OH & Sierra Club 830909 & 0824, respectively, 10CFR2 206 petitions re transport of spent nuclear fuel from West Valley
DAVIS, J Q Office of Nuclear Material Safety & Safeguards, Director 83/09/30 2pp 20680 310 24X
Fiche 50-000, 83/09/30, 8310070156

--8310070171 Director's Decision 83-14, denying State of OH & Sierra Club 830909 & 0824, respectively, 10CFR2, 206 petitions re transport of spent nuclear fuel from West Valley Request for hearing & for preparation of EIS denied
DAVIS, J Q Office of Nuclear Material Safety & Safeguards, Director 83/09/30 18pp 20680 312 24X
Fiche 50-000, 83/09/30, 8310070156

8310270297 Order extending time until 831128 for Commission to act to review Director's Decision 83-14, denying Sierra Club & State of OH requests
CHILKIS, J Office of the Secretary of the Commission 83/10/25
Commissioners 1p 20923 195 24X Fiche 50-000, 83/10/25, 8310270297

I Financial information

8310120005 FOIA request for documents re costs & const of & improvements to Western New York Nuclear Svc Ctr, West Valley, NY
ARNOLD, O A Shaw, Pittman, Potts & Trowbridge 83/06/27 Office of Administration 2pp 20751 069 24X Fiche 50-201, 83/06/27, 8310120005

8310120006 Responds to FOIA request for documents re costs & const of & improvements to Western New York Nuclear Svc Ctr, West Valley, NY Forwards documents listed in App A Documents also available in PDR
FELTON, J M Division of Rules and Records 83/07/14 ARNOLD, O A Shaw, Pittman, Potts & Trowbridge 3pp 20751 071 24X
Fiche 50-201, 83/07/14, 8310120006

--8310120008 Forwards schedule showing source & application of funds for Mar-June 1966 to demonstrate that vendor has necessary funds to continue const of facility, per 660322 ltr
RUNION, T C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 66/03/28 MCBRIDE, J A Atomic Energy Commission 2pp
20751 074 24X Fiche 50-201, 83/07/14, 8310120006

--8310120009 Forwards schedule showing vendor consolidated balance sheet as of 660228 & consolidated balance sheet projected for 660331 Addl line of credit of \$1,000,000 received from Mfg & Traders Trust Co Ltr encl
RUNION, T C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 66/03/22 MCBRIDE, J A Atomic Energy Commission 5pp
20751 076 24X Fiche 50-201, 83/07/14, 8310120006

--8310120011 Forwards "Info Subsequent to CP Submission 5," from vendor, requesting extension of const completion date to 660630 Request includes financial data to cover period through 660630
BECHHOEFER, D O Scharfeld, Bechhoefer & Baron 66/02/25 MCBRIDE, J A Atomic Energy Commission 1p 20751 081 24X
Fiche 50-201, 83/07/14, 8310120006

--8310120012 Application to amend License CSF-1, extending const completion date to 660630 Certificate of Svc & consolidated balance sheet encl
RUNION, T C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 66/02/24 7pp 20751 082 24X Fiche 50-201, 83/07/14, 8310120006

--8310120013 Forwards "Info Subsequent to CP Submission 3," containing suppl info requested by NRC Info in Part 1 covers statement of general financial responsibility Info contained in second part should be withheld (ref 10CFR2 790)
RUNION, T C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 65/08/25 MCBRIDE, J A Atomic Energy Commission 1p 20751 091 24X
Fiche 50-201, 83/07/14, 8310120006

--8310120014 Application to amend License CSF-1, supplementing or replacing & superseding Paragraph 7 re applicant financial responsibility
RUNION, T C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 65/08/25 4pp 20751 092 24X Fiche 50-201, 83/07/14, 8310120006

--8310120015 Forwards "Info Subsequent to CP Submission 2," dtd 650719, Certificate of Svc & marked-up "Info Subsequent to CP Submission 1"
BECHHOEFER, D O Scharfeld, Bechhoefer & Baron 65/07/19 MCBRIDE, J A Atomic Energy Commission 1p 20751 096 24X
Fiche 50-201, 83/07/14, 8310120006

--8310120020 Discusses current appraisal of NFB reprocessing project Summary of most current cost review encl Addl data will be included in semiannual rept to be filed in Oct 1964, in connection w/ licensing procedure.
RUNION, T C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 64/08/17 SCABORO, O T Atomic Energy Commission 3pp
20751 137 24X Fiche 50-201, 83/07/14, 8310120006

--8310120023 Notifies that on 640402, substantially all fixed assets & portion of quick assets of fuel fabrication facility at Port Hope were sold & transferred by NFB to Canadian Westinghouse Co, Ltd
BECHHOEFER, D O Scharfeld, Bechhoefer & Baron 64/05/15 JOHNSON, L E Atomic Energy Commission 1p 20751 140 24X
Fiche 50-201, 83/07/14, 8310120006

--8310120026 Order amending provisional CP CPCSF-2 to require NFB to file rept covering 6-month period ending Mar 31 & Sept 30 of each yr w/ Director of Div of Licensing
RIGGS, E, HOLMAN, A, CALLIHAN, D Atomic Safety and Licensing Board Panel 63/11/29 Nuclear Fuel Services, Inc (subs of Getty Oil Co) 4pp 20751 141 24X Fiche 50-201, 83/07/14, 8310120006

--8310120028 Response to applicant motion for amend to provisional CP CPCSF-2 Info provided by applicant in proposed "NFB Exhibit E" & in statement of Commission 630316 memorandum & order
CONNER, T B Nuclear Fuel Services, Inc (subs of Getty Oil Co) CONNER, T B New York, State of CONNER, T B Atomic Energy Commission 63/11/14 7pp 20751 145 24X Fiche 50-201, 83/07/14, 8310120006

DOCKETED ITEMS

--8310120030 Statement in support of NFS 631023 motion requesting Commission take actions on loan arrangements & submittal of financial repts Draft NFS motion, Certificate of Svc & term loan agreement encl
RUEBKAUSEN, O M New York, State of * Affiliation Unknown
63/10/29 23pp 20751 192 24X Fiche 50-201, 83/07/14, 8310120006

--8310120032 Memorandum & order amending CPCSF-2 by incorporating condition to require applicants to furnish evidence of financial qualifications adequate to constitute proper basis for required finding
MCCOOL, W O Atomic Energy Commission 83/09/13 Nuclear Fuel Services, Inc (subs of Getty Oil Co) App 20751 175 24X
Fiche 50-201, 83/07/14, 8310120006

--8310120034 Forwards Amend 1 to NFS 630130 CP application submitted by NY State Atomic & Space Development Authority Certificate of Svc encl
RUEBKAUSEN, O M Debevoise & Plimpton 63/04/07 MCCOOL, W O Atomic Energy Commission 1p 20751 119 24X
Fiche 50-201, 83/07/14, 8310120006

--8310120036 Memorandum of Agreement between NY State Dfc of Atomic Development & NY State Atomic R&D Authority to coordinate respective responsibilities for development of Atomic Energy Certificate of Svc encl
AYELRAD, M Atomic Energy Commission THOMSEN, D J, FERGUSON, W New York, State of 63/03/21 13pp 20751 184 24X
Fiche 50-201, 83/07/14, 8310120006

--8310120039 Responds to 630213 ltr re NFS application for licenses Memorandum of Agreement between NY State Dfc of Atomic Development & NY State Atomic R&D Authority from Governor of State of NY encl
THOMSEN, D New York, State of 63/04/08 LOWENSTEIN, R Atomic Energy Commission 2pp 20751 197 24X Fiche 50-201, 83/07/14, 8310120006

--8310120042 Forwards Amend 4 to Part A of NFS CP application re financial qualifications & related info
STUHLER, A Scharfeld, Bechhoefer & Baron 63/03/29 CONNER, T B Atomic Energy Commission 1p 20751 197 24X
Fiche 50-201, 83/07/14, 8310120006

--8310120044 Amend 4 to CP application to construct spent fuel reprocessing plant Amend responds to Commission 630314 ltr, requesting addl financial data re pending application Addl financial info encl
RUNION, T C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 63/03/29 20pp 20751 200 24X Fiche 50-201, 83/07/14, 8310120006

--8310120047 Forwards Amend 1 to Part A of NFS application for license to construct & operate spent fuel processing plant
BECHHOEFER, B G Scharfeld, Bechhoefer & Baron 63/02/13 Atomic Energy Commission 1p 20751 220 24X
Fiche 50-201, 83/07/14, 8310120006

--8310120049 Amend 1 to Part A of application for license to construct & operate spent fuel processing plant Certificate of Svc & financial info encl
RUNION, T C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 63/02/12 32pp 20751 221 24X Fiche 50-201, 83/07/14, 8310120006

8310120207 Application to amend License CSF-1, revising Paragraph 5 of original application re applicant financial qualifications
RUNION, T C Nuclear Fuel Services, Inc (subs of Getty Oil Co) * Scharfeld, Bechhoefer & Baron 63/07/13 26pp 20751 097 24X Fiche 50-201, 83/07/14, 8310120006

Operating license stage documents & correspondence

9310070020 Ack receipt of 830824 ltr requesting Commission publish notice of pending license amend in FR re New York State Energy R&D Authority license for utility w/irradiated fuel storage facilities
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 83/07/22 REBNIKOFF, M Sierra Club 1p 20671 361 24X
Fiche 50-000, 83/09/22, 8310070020

10280147 Forwards 830930 Director's Decision 83-14, denying State of OH & Sierra Club 10CFR206 petitions re transportation of spent fuel from West Valley facility, per 830930 request
RUNNINGHAM, R E Division of Fuel Cycle & Material Safety 83/10/18 MILLER, F Environmental Policy Institute 2pp 20961 329 24X
Fiche 50-000, 83/10/18, 8310280147

DOCKET 50-206 SAN ONOFRE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8310030110 Forwards revs to physical security plan Revs withheld (ref 10CFR73.21)
MEDFORD, M D Southern California Edison Co 83/09/29 Division of Licensing 2pp 20590 051 24X Fiche 50-206, 83/09/29, 8310030110

8310130012 Forwards two errata pages to Rev 11 to Mar 1981 physical security plan Safeguards contingency plan submitted on 830923 will replace Chapter B of physical security plan by 831215 Pages withheld (ref 10CFR/J 21)
MEDFORD, M D Southern California Edison Co 83/10/07 Division of Licensing 1p 20725 208 24X Fiche 50-206, 83/10/07, 8310130012

8310130127 Forwards Aug 1983 "SEP Topic III-5 A High Energy Line Break Analysis Inside Containment" Evaluation will be conducted per implementation of mods required by 10CFR90, App R
KRIEGER, R W Southern California Edison Co 83/10/11 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 20720 001 24X
Fiche 50-206, 83/10/11, 8310130127

--8310130131 "SEP Topic III-5 A High Energy Line Break Analysis Inside Containment" For San Onofre Nuclear Generating Station, Unit 1
Bechtel Corp 83/08/09 23pp 20720 003 24X
Fiche 50-206, 83/10/11, 8310130127

8310130424 Requests Fee due per 830211 revised physical security plan be remitted within 15 days of receipt of ltr
MILLER, W O License Fee Management Branch 83/10/11 DIETCH, R Southern California Edison Co 2pp 20769 242 24X
Fiche 50-206, 83/10/11, 8310130424

H General correspondence

8310050091 Responds to 830822 ltr re seismic upgrading requirements Encl orders relate to seismic upgrading & post-TMI-related issues Util intends to submit plan for early restart for NRC review & approval
CRUTCHFIELD, D Operating Reactors Branch 5 83/09/27 MERTENS, J Affiliation Unknown 2pp 20639 277 24X Fiche 50-206, 83/09/27, 8310050091

8310190008 Informs of organizational & personnel changes resulting from Jan 1980 centralization of nuclear engineering & operations dept Revs to Tech Specs being prepared for future submittal
FOGARTY, D J Southern California Edison Co 83/10/17 DENTON, R R Office of Nuclear Reactor Regulation, Director 2pp 20823 304 24X Fiche 50-206, 83/10/17, 8310190008

P Operating license stage documents & correspondence

8310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR
CONNER, L Affiliation Unknown 83/05/02 NRC - No Detailed Affiliation Given 1p 21004 210 24X Fiche 50-000, 83/05/02, 8310310017

8309240501 Provides status of actions requested in 830401 clarification of 82120 SER on environ qualification of safety-related electrical equipment "Equipment Environ Qualification," technical evaluation rept no longer considered proprietary
BASKIN, K P Southern California Edison Co 83/05/20 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 20932 296 24X
Fiche 50-206, 83/05/20, 8305240501

--8104070444 "Equipment Environ Qualification, San Onofre Unit 1," proprietary technical evaluation rept released for PDR, per license 830520 ltr
CRANE, C J Franklin Institute/Franklin Research Center NRC-03-79-118 TER-CS257-179 81/04/03 LOMBARDI, J NRC No Detailed Affiliation Given 210pp 20932 307 24X
Fiche 50-206, 83/05/20, 8305240501

8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which repts are unavailable
FELTON, J M Division of Rules and Records 83/07/06 CONNER, L Affiliation Unknown 1p 21004 271 24X Fiche 50-000, 83/07/06, 8310310031

8310070283 Forwards multiple response spectra verification for M101 computer code per SEP Topic III-6, in response to 830802 ltr
KRIEGER, R W Southern California Edison Co 83/09/28 CRUTCHFIELD, D Operating Reactors Branch 5 421pp 20655 288 24X
Fiche 50-206, 83/09/28, 8310070283

DOCKETED ITEMS

25

8310120278 Forwards response to J Mertens 830805 request for addl info re open items involving damaged snubbers & water hammer Assessment of areas complete
RAY, H B Southern California Edison Co 83/09/29 MARTIN, J B
Region 5, Office of Director 3pp 20693 078 24X
Fiche 50-206, 83/09/29, 8310120278

8310140223 Advises that an initial evaluation of SEP Topic VI-4, "Containment Isolation Sys (Electrical)," penetrations erroneously evaluated against GDC 55 instead of GDC 57
Addl mods to plant configuration unnecessary
KRUEGER, R W Southern California Edison Co 83/09/30
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 20761 179 24X
Fiche 50-206, 83/09/30, 8310140223

8310060195 Forwards final evaluation of SEP Topic XV-7, "Reactor Coolant Pump Motor Seizure & Reactor Coolant Pump Shaft Break" facility design meets current criteria Evaluation will be basic input to integrated safety assessment
PAULSON, W A Operating Reactors Branch 5 83/10/05 DIETCH, R
Southern California Edison Co 7pp 20647 137 24X
Fiche 50-206, 83/10/05, 8310060195

8310120170 Forwards comments on draft SK of SEP Topics II-3 A, II-3 B, II-3 B 1 & II-3 C re hydrology requirements, capability & safety-related water supply, respectively Aerial survey data drawings encl
KRUEGER, R W Southern California Edison Co 83/10/05
CRUTCHFIELD, D Operating Reactors Branch 5 7pp 20693 119 24X
Fiche 50-206, 83/10/05, 8310120170

8310120393 Informs that transmittal ltr will no longer accompany monthly FR notices Recipients should carefully peruse publication for applicable hearing opportunity notices
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/07 DIETCH, R
Southern California Edison Co 2pp 20649 105 24X
Fiche 50-206, 83/10/07, 8310120393

8310130127 Forwards Aug 1983 "SEP Topic III-5 A High Energy Line Break Analysis Inside Containment" Evaluation will be conducted per Implementation of mods required by 10CFR50, App R
KRUEGER, R W Southern California Edison Co 83/10/11
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 20720 001 24X
Fiche 50-206, 83/10/11, 8310130127

--8310130131 "SEP Topic III-5 A High Energy Line Break Analysis Inside Containment," for San Onofre Nuclear Generating Station, Unit 1
Bechtel Corp 83/08/05 23pp 20720 003 24X
Fiche 50-206, 83/10/11, 8310130131

8310130316 Forwards Addendum 1 to supplemental study rept on SEP Topic III-5 B, "Effects of Pipe Break Outside Containment"
KRUEGER, R W Southern California Edison Co 83/10/11
CRUTCHFIELD, D Operating Reactors Branch 5 1p 20717 101 24X
Fiche 50-206, 83/10/11, 8310130316

--8310130323 Addendum 1 to "Supplemental Study Rept on Effects of Piping Bys Break Outside Containment"
Bechtel Corp 83/08/19 53pp 20717 102 24X
Fiche 50-206, 83/10/11, 8310130323

8310200284 Addresses SEP Topic V-6, "Reactor Vessel Integrity," documented in NUREG-0569, "Evaluation of Integrity of SEP Reactor Vessels" SEP Topic V-6 resolved as result of evaluation performed per pressurized thermal shock issue
KRUEGER, R W Southern California Edison Co 83/10/13
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 20829 320 24X
Fiche 50-206, 83/10/13, 8310200284

8310250124 Forwards Rev 1 to Calculation SK-CC-01 1, "Reevaluation of Spent Fuel Storage Racks," in response to NRC 830724 request Racks in fully loaded condition fail to meet seismic criteria
MEDFORD, H O Southern California Edison Co 83/10/17
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 20898 183 24X
Fiche 50-206, 83/10/17, 8310250124

--8310250128 Rev 1 to "Reevaluation of Spent Fuel Storage Racks" w/ four oversize drawings Aperture cards are available in PBR
KUNDALKAR, R, DAY, R S Bechtel Corp SK-CC-01 1 R01 83/08/30
34pp 20898 187 24X Fiche 50-206, 83/10/17, 8310250124

8310250196 Discuss SEP Topic III-10 A, "Thermal Overload Protection for Motors of Motor Operated Valves," per B10724 safety evaluation Mod of valve motors to bypass thermal overload devices unnecessary
KRUEGER, R W Southern California Edison Co 83/10/17
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 20898 354 24X
Fiche 50-206, 83/10/17, 8310250196

8310250254 Summary of 831005 meeting w/util & Westinghouse re methodology being used to prioritize backfit projects
Viewgraphs encl
PAULSON, W A Operating Reactors Branch 5 83/10/20 Operating Reactors Branch 5 7pp 20898 221 24X Fiche 50-206, 83/10/20, 8310250254

8310250630 Forwards proprietary viewgraphs provided at 831005 meeting w/util & Westinghouse Viewgraphs withheld per NRC Manual Chapter 9 5(4) since matl intended for general info & will not be used as basis for NRC actions
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/24
WIESEMAN, R A Westinghouse Electric Corp 3pp 20899 316 24X
Fiche 50-206, 83/10/24, 8310250630

8310270101 Revised Proposed Change 120 to Tech Specs, clarifying 830720 & 090/ submittals re boron dilution, reactor criticality & primary plant makeup pump NRC analysis of proposed change should be limited to refueling mode analysis & results
MEDFORD, H O Southern California Edison Co 83/10/25 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 20925 026 24X Fiche 50-206, 83/10/25, 8310270101

8310280141 Advises that commitments in util 830930 ltr re SEP Topic VI-4, "Containment Isolation Sys (Electrical)," NUREG-0578 & NUREG-0737, Item II E 4 2 acceptable No mods to steam generator sample & blowdown lines required
PAULSON, W A Operating Reactors Branch 5 83/10/27 DIETCH, R
Southern California Edison Co 4pp 20929 042 24X
Fiche 50-206, 83/10/27, 8310280141

0 Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310120298 Submits comments on 830826 SALP analyses Operator errors primarily result of inadequate procedures or training
Actions taken to improve training & operating experience feedback in maint program
FOGARTY, D J Southern California Edison Co 83/09/28 MARTIN, J B
Region 5, Office of Director 2pp 20693 170 24X
Fiche 50-206, 83/09/28, 8310120298

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation" Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310120258 Responds to 830830 confirmatory action ltr re potential cracks in Transamerica Delaval diesel crankshaft No cracks identified in crankshafts Cracked connecting rod bolt washer discovered on rod cap nut 5 of generator 2
RAY, H B Southern California Edison Co 83/09/29 MARTIN, J B
Region 5, Office of Director 2pp 20691 328 24X
Fiche 50-206, 83/09/29, 8310120258

8310200208 Forwards IE Insp Repts 50-206/83-19, 50-361/83-29 & 50-362/83-27 on 830804-0916 No noncompliance noted
BISHOP, T W Division of Resident Reactor Project & Engineering Programs 83/10/04 MCCARTHY, C B Southern California Edison Co
2pp 20834 128 24X Fiche 50-206, 83/10/04, 8310200208

--8310200214 IE Insp Repts 50-206/83-19, 50-361/83-29 & 50-362/83-27 on 830804-0916 No noncompliance noted Major areas inspected operational safety verification, witnessing pre-criticality, initial criticality & low power physics testing
CHAFFE, A E, D'ANGELO, A, SIEMART, J P Region 5, Office of Director 83/09/30 18pp 20834 130 24X Fiche 50-206, 83/10/04, 8310200208

DOCKETED ITEMS

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edition Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edition Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edition Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edition Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310200220 Forwards IE Mgt Meeting Repts 50-206/83-22, 50-361/83-36 & 50-362/83-34 on 830908 re SALP rept for Jul 1982 - May 1983
MARTIN, J B Region 5, Office of Director 83/10/14 MCCARTHY, C D Southern California Edison Co 2pp 20829 327 24X Fiche 50-206, 83/10/14, 8310200220

--8310200224 IE Mgt Meeting Repts 50-206/83-22, 50-361/83-36 & 50-362/83-34 on 830908 Major areas discussed SALP rept for Jul 1982 - May 1983
KIRSCH, D F Region 5, Office of Director 83/10/13 2pp 20829 329 24X Fiche 50-206, 83/10/14, 8310200220

--8310200228 SALP rept for Jul 1982 - May 1983
* Region 5, Office of Director 83/07/13 42pp 20829 331 24X Fiche 50-206, 83/10/14, 8310200220

--8310200232 Summarizes major investigative activities involving facilities for SALP board review covering Jul 1982 - May 1983
SHACKLETON, D C Office of Investigation 83/06/06 BISHOP, T W Region 5, Office of Director 2pp 20830 011 24X Fiche 50-206, 83/10/14, 8310200232

--8306230142 Evaluates plant LERs for Jul 1982 - May 1983 to assist in SALP review Areas re personnel error & saltwater cooling require further evaluation
SEYFRIT, K V Reactor Operations Analysis Branch 83/06/15 STERNBERG, D Division of Resident, Reactor Project & Engineering Programs 2pp 20830 013 24X Fiche 50-206, 83/10/14, 8310200220

--8306170106 Forwards observations from evaluation of LERs for 820701-830530, to assist in SALP review licensee submittals above average in terms of reporting completeness & factual accuracy
SEYFRIT, K V Reactor Operations Analysis Branch 83/06/10 STERNBERG, D Division of Resident, Reactor Project & Engineering Programs 6pp 20830 013 24X Fiche 50-206, 83/10/14, 8310200220

--8306170442 Forwards evaluation of LERs for period 820701 to 830530 in support of ongoing SALP review
SEYFRIT, K V Director's Office 83/06/10 STERNBERG, D Division of Resident, Reactor Project & Engineering Programs 4pp 20830 021 24X Fiche 50-206, 83/10/14, 8310200220

I Periodic operating reports & related correspondence

8310190010 Monthly operating rept for Aug 1983 W/830915 ltr
SPEER, M J, RAY, H B Southern California Edison Co 83/09/15 Office of Resource Management, Director 6pp 20823 298 24X Fiche 50-206, 83/09/15, 8310190010

S Reportable occurrences, LERs & related correspondence

8310120184 RD 83-004 on 830927, leakage path for introduction of unfiltered outside air into CREATS created as result of work performed on air conditioning sys during Apr 1981
Ventilation duct capped on 830921
RAY, H B Southern California Edison Co 83/09/28 MARTIN, J B Region 5, Office of Director 2pp 20695 296 24X Fiche 50-206, 83/09/28, 8310120184

8310040396 PNO-V-83-041 on 830929, approx 60 items discovered in unrestricted storage areas Surveys continuing Press release expected
WENSLAWSKI, F, KIRSCH, D Region 5, Office of Director 83/09/29 1p 20619 168 24X Fiche 50-206, 83/09/29, 8310040396

8310070301 Potential Part 21 rept re underrange characteristic of Model N-L110H transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBENIAN, M J Fairbairn Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X Fiche 50-000, 83/09/30, 8310070301

8310250495 LER 83-004/DIT-0 on 830927, evaluation confirmed operator observation that path for outside air to enter control room existed from Apr 1981 to 830921, bypassing control room emergency air treatment sys filters W/831012 ltr
HAYNES, J G Southern California Edison Co 83/10/12 MARTIN, J B Region 5, Office of Director 4pp 20697 109 24X Fiche 50-206, 83/10/12, 8310250495

8310250355 PNO-V-83-049 on 831018, const craft person injured working c-12 kV circuit breaker Workman accidentally contacted hot const power supply circuit Smoke observed coming from manhole Plant unaffected
MORRILL, P Region 5, Office of Director 83/10/19 1p 20878 122 24X Fiche 50-206, 83/10/19, 8310250355

8310310284 PNS-V-83-011 on 831024, San Francisco Chronicle published article re use & sale of illegal drugs by current & former facility personnel Drug-related accidents or injuries not cited Repts believed to be untrue or exaggerated
SCHAEFER, D W, NORDERHAUG, L R Region 5, Office of Director 83/10/24 1p 20961 282 24X Fiche 50-206, 83/10/24, 8310310284

V Operator Examinations

8310030109 Requests, by 831028, schedule for requalification training & exams for 1984 Schedule needed for periodic audits of licensed operator requalification programs
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 83/09/26 FOGARTY, D J Southern California Edison Co 2pp 20590 093 24X Fiche 50-206, 83/09/26, 8310030109

DOCKET 50-213 HADDAM NECK PLANT

F Security, medical, emergency & fire protection plans

8310180439 Forwards 1C Insp Rept 50-213/83-16 on 830523-0626 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/09/28 COUNSEL, W G Connecticut Yankee Atomic Power Co 2pp 20802 149 24X Fiche 50-213, 83/09/28, 8310180439

--8310180447 IE Insp Rept 50-213/83-16 on 830523-0626 No noncompliance noted Major areas inspected review of period repts, shift logs & operating records, physical security, atmospheric checks of cleaning facility & plant tips
REBELOWSKI, T A Region 1, Office of Director ELSASSER, T C Division of Project & Resident Programs 83/09/27 11pp 20802 150 24X Fiche 50-213, 83/09/28, 8310180439

8310060256 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/09/30 Document Management Branch 1p 20660 233 24X Fiche 50-213, 83/09/30, 8310060256

--8310060262 Public version of Rev 15 to Emergency Plan Implementing Procedure [PIP] 1 5-2, "Notification & Communication"
COUNSEL, W G Connecticut Yankee Atomic Power Co 83/06/09 EISENHUT, D G Division of Licensing 41pp 20660 233 24X Fiche 50-213, 83/09/30, 8310060256

8310110193 Notification of 831013 meeting w/util in Bethesda, MD to discuss control room fire protection & alternative safe shutdown capability
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/05 ERICKSON, P Operating Reactors Branch 5 3pp 20665 008 24X Fiche 50-213, 83/10/05, 8310110193

8310270003 Notification of 831015 meeting w/util, WESTEC, States of CT & MA & FEMA in West Springfield, MA to discuss results of consequences of Quabbin Dam flooding & emergency procedures for flooding events
BROWN, S W Systematic Evaluation Program Branch 83/10/19 GRIMES, C I Systematic Evaluation Program Branch 2pp 20934 121 24X Fiche 50-213, 83/10/19, 8310270003

8310270018 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20940 190 24X Fiche 50-213, 83/10/21, 8310270018

DOCKETED ITEMS

27

--8310270071 Public version of Rev 0 to Emergency Plan Implementing Procedure EP/P 1 5-43, "Personnel Radiation Exposure Control During Nuclear Emergencies " W/831011 ltr
FERGUSON, J H, COUNCIL, W G Connecticut Yankee Atomic Power Co
83/10/01 EISENHUT, D G Division of Licensing 8pp 20940 191
24X Fiche 50-213, 83/10/21, 8310270071

8310280311 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/25 Document
Management Branch 1p 20963 083 24X Fiche 50-213, 83/10/25, 8310280311

--8310280313 Public version of Rev 16 to Emergency Plan Implementing Procedure EP/P 1 5-2, "Notification & Communication " W/
830811 ltr
COUNCIL, W G Connecticut Yankee Atomic Power Co 83/08/01
EISENHUT, D G Division of Licensing 42pp 20963 084 24X
Fiche 50-213, 83/10/25, 8310280311

P Operating license stage documents & correspondence

8310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR
CONNOR, L Affiliation Unknown 83/05/02 NRC - No Detailed
Affiliation Given 1p 21004 270 24X Fiche 50-000, 83/05/02, 8310310017

8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR
FELTON, J M Division of Rules and Records 83/07/06 CONNER, L
Affiliation Unknown 1p 21004 271 24X Fiche 50-000, 83/07/06, 8310310031

8310030140 Comments on potential for flooding of plant site resulting from failure of Goodnough Dam &/or Windsor Dam at Quabbin Reservoir Based on Franklin Research Ctr analysis, flooding protection measures provide protection against dam failure
CRUTCHFIELD, D Operating Reactors Branch 5 83/09/26 COUNCIL, W G
Connecticut Yankee Atomic Power Co 4pp 20591 071 24X
Fiche 50-213, 83/09/26, 8310030140

--8308300317 "Quabbin Dam Failure Flooding Consequences at Haddam Neck Plant," technical evaluation rept
SCHERRER, J S Franklin Institute/Franklin Research Center
NRC-03-81-130 TER-C5506-412 83/08/25 CHERY, D NRC - No
Detailed Affiliation Given 26pp 20591 075 24X
Fiche 50-213, 83/09/26, 8310030140

8310120375 Responds to 830726 request to review training program & confirm that stated items addressed in Generic Ltr 81-21, "Natural Circulation Cutdown " Training given to all
licensed operators in 1981 addressed listed items
COUNCIL, W G Connecticut Yankee Atomic Power Co 83/09/27
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 20699 201 24X
Fiche 50-213, 83/09/27, 8310120375

8310060213 Responds to 830914 proposal to develop integrated review for pending licensing actions Meeting to discuss proposed review requested
EISENHUT, D G Division of Licensing 83/10/05 COUNCIL, W G
Connecticut Yankee Atomic Power Co COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 5pp 20647 131 24X
Fiche 50-000, 83/10/05, 8310060213

8310120308 Requests update of completion schedules presented in integrated plant safety assessment rept within 30 days
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/06 COUNCIL, W G
Connecticut Yankee Atomic Power Co COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 5pp 20701 004 24X
Fiche 50-000, 83/10/06, 8310120308

8310120411 Notifies that util will no longer receive portions of FR containing Commission monthly notices w/transmittal ltr Util should carefully peruse publication for hearing opportunity notices
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/07 COUNCIL, W G
Connecticut Yankee Atomic Power Co 2pp 20699 041 24X
Fiche 50-000, 83/10/07, 8310120411

8310180344 Revises schedule for submittal of svc water sys analysis identified in Integrated Plant Safety Assessment, NUREG-0826 & associated SEP Topic IX-3 Delays due to upgrades per NUREG-0777, Item III D 3 4 Analysis expected by 831230
COUNCIL, W G Connecticut Yankee Atomic Power Co 83/10/07
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 20802 358 24X
Fiche 50-213, 83/10/07, 8310180344

8310180409 Forwards listed revs to "Corporate Organization For Nuclear Incidents (CONI) Procedure Manual," per Section V of App E to 10CFR50 W/o encl
COUNCIL, W G Connecticut Yankee Atomic Power Co COUNCIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNCIL, W G Northeast Utilities 83/10/12 EISENHUT, D G
Division of Licensing 1p 20803 173 24X Fiche 50-000, 83/10/12, 8310180409

8310280112 Denies 830906 request for 120-day extension to respond to Generic Ltr 83-28 re generic implications of Salem ATWS events NRC review schedule does not permit extension
Response due by 831105
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/26 COUNCIL, W G
Connecticut Yankee Atomic Power Co COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 20929 261 24X
Fiche 50-000, 83/10/26, 8310280112

G Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins For Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310180204 Forwards IE Insp Rept 50-213/83-17 on 830627-0731 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/09/27
COUNCIL, W G Connecticut Yankee Atomic Power Co 2pp 20808 226
24X Fiche 50-213, 83/09/27, 8310180204

--8310180209 IE Insp Rept 50-213/83-17 on 830627-0731 No noncompliance noted Major areas inspected licensee action on previous insp findings, plant operations, shift logs & operation records & review of periodic repts
REDELOWSKI, T A Region 1, Office of Director ELASBER, T C
Division of Project & Resident Programs 83/09/21 6pp
20808 228 24X Fiche 50-213, 83/09/27, 8310180204

8310180439 Forwards IE Insp Rept 50-213/83-16 on 830523-0626 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/09/28
COUNCIL, W G Connecticut Yankee Atomic Power Co 2pp 20802 148
24X Fiche 50-213, 83/09/28, 8310180439

--8310180447 IE Insp Rept 50-213/83-16 on 830523-0626 No noncompliance noted Major areas inspected review of period repts, shift logs & operating records, physical security, atmospheric checks of cleaning facility & plant trips
REDELOWSKI, T A Region 1, Office of Director ELASBER, T C
Division of Project & Resident Programs 83/09/27 11pp
20802 150 24X Fiche 50-213, 83/09/28, 8310180439

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/27 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/27, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

DOCKETED ITEMS

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

R Periodic operating reports & related correspondence

8310190007 Monthly operating rept for Aug 1983 W/830914 ltr
ELMS, A J, GRAVES, R H Connecticut Yankee Atomic Power Co 83/08/31
Office of Resource Management, Director 10pp 20823 117 24X
Fiche 50-213, 83/08/31, 8310190007

S Reportable occurrences, LERs & related correspondence

8310250315 LER 83-016/03L-0 on 830901, during normal operation charging pump B declared inoperable after pump outboard motor revealed high temp alarm caused by broken thermocouple wires. Wires repaired W/830926 ltr
CLOSIOUS, G J, GRAVES, R H Connecticut Yankee Atomic Power Co 83/09/26 MURLEY, T E Region 1, Office of Director 2pp 20898 017 24X Fiche 50-213, 83/09/26, 8310250315

8310250321 LER 83-015/03L-0 on 830831, during surveillance testing on Channel 1 of pressure level instrumentation, trip relay failure discovered. Caused by stuck relay. Relay manually cycled & lubricated W/830926 ltr
CLOSIOUS, G J, GRAVES, R H Connecticut Yankee Atomic Power Co 83/09/26 MURLEY, T E Region 1, Office of Director 2pp 20898 001 24X Fiche 50-213, 83/09/26, 8310250321

8310070301 Potential Part 21 rept re underrange characteristic of Model N-ELIGH transmitter. Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input. End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X Fiche 50-000, 83/09/30, 8310070301

DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

Security, medical, emergency & fire protection plans

110110385 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/09/30 Document Management Branch 1p 20715 228 24X Fiche 50-219, 83/09/30, 8310110385

--8310110399 Public version of revised Emergency Plan Implementing Procedures. EPIP-1 re classification of emergency conditions, EPIP-4 re site emergency & EPIP-5 re general emergency
FIEDLER, P B Jersey Central Power & Light Co 83/05/20 54pp 20715 229 24X Fiche 50-219, 83/09/30, 8310110399

8310270155 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/83-20
STAROSTECKI, R Division of Project & Resident Programs 83/10/21 FIEDLER, P B General Public Utilities - GPU Service Corp 2pp 20925 015 24X Fiche 50-219, 83/10/21, 8310270155

--8310270158 Responds to NRC 830902 ltr re violations noted in IE Insp Rept 50-219/83-20. Corrective actions individual appropriately disciplined. Details withheld (ref 10CFR73.2f)
FIEDLER, P B General Public Utilities - GPU Service Corp 83/09/30 STAROSTECKI, R Division of Project & Resident Programs 3pp 20925 017 24X Fiche 50-219, 83/10/21, 8310270155

vc list encl
BLAKE, E L
KOH, J H, KOHL, C N
72 351 24X

8310070020 Ack receipt of 830824 ltr requesting Commission publish notice of pending license amend in FR in New York State Energy R&D Authority license for utility w/irradiated fuel storage facilities
DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 83/09/22 RESNIKOFF, M Sierra Club 1p 20671 361 24X Fiche 50-000, 83/09/22, 8310070020

8310030263 Forwards Amend 6B to License DPR-16 & safety evaluation. Amend authorizes changes to administrative organization allocating personnel between maint div & matl dept
CRUTCHFIELD, D Operating Reactors Branch 5 83/09/28 FIEDLER, P B General Public Utilities - GPU Service Corp 3pp 20591 041 24X Fiche 50-219, 83/09/28, 8310030263

--8310030268 Amend 6B to License DPR-16, authorizing changes to administrative organization by allocating personnel between maint & const div & newly established plant matl dept
CRUTCHFIELD, D Operating Reactors Branch 5 83/09/28 10pp 20591 044 24X Fiche 50-219, 83/09/28, 8310030268

--8310030272 Safety evaluation supporting Amend 6B to License DPR-16
Office of Nuclear Reactor Regulation, Director 83/09/28 2pp 20591 054 24X Fiche 50-219, 83/09/28, 8310030272

8310030443 Informs that Section 4.31 of integrated plant safety assessment rept (NUREG-0822) dtd Jan 1983 complete, except for implementation of mods to diesel generator trips by end of Cycle 11 outage & IE post-implementation review
CRUTCHFIELD, D Operating Reactors Branch 5 83/09/29 FIEDLER, P B General Public Utilities - GPU Service Corp 2pp 20602 061 24X Fiche 50-219, 83/09/29, 8310030443

8310110217 Forwards status of NUREG-0822 issues requiring refined engineering analysis or continuation of ongoing evaluation, per 830810 request. Addl submittal dates inadvertently omitted by NRC, indicated by asterisks
FIEDLER, P B General Public Utilities - GPU Service Corp 83/10/01 CRUTCHFIELD, D Operating Reactors Branch 5 4pp 20665 056 24X Fiche 50-219, 83/10/01, 8310110217

8310120334 Advises that future Commission FR monthly notices will be forwarded w/o transmittal ltr. Perusal of each publication for hearing opportunity notices recommended
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/07 FIEDLER, P B General Public Utilities - GPU Service Corp 2pp 20699 275 24X Fiche 50-219, 83/10/07, 8310120334

8310170335 Application to amend license DPR-16 consisting of New 1 to Tech Spec Change Request 104 reflecting visual insp of all accessible core spray spargers, repair assemblies & core spray piping internal to reactor vessel
FIEDLER, P B General Public Utilities - GPU Service Corp 83/10/11 NRC - No Detailed Affiliation Given 3pp 20786 152 24X Fiche 50-219, 83/10/11, 8310170335

8310200211 Forwards INPO evaluations on util mgt Svc list encl
BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, E L Metropolitan Edison Co 83/10/18 EDLES, G J, BUCK, J H, KOHL, C N Atomic Safety and Licensing Appeal Panel 47pp 20832 381 24X Fiche 50-000, 83/10/18, 8310200211

8310210249 Forwards corrected pages to INPD rept provided on 831018
BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, E L Metropolitan Edison Co 83/10/19 EDLES, G J, BUCK, J H, KOHL, C N Atomic Safety and Licensing Appeal Panel 6pp 20831 049 24X Fiche 50-000, 83/10/19, 8310210249

8310210209 Notification of 831027 meeting w/util in Bethesda, MD to discuss proposed expanded safety sys facility
LOMBARD, J J Operating Reactors Branch 5 83/10/20 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 20895 110 24X Fiche 50-219, 83/10/20, 8310210209

8310270180 Discusses 831007 mgt meeting held in Region 1 ofc to inform region of results of INPD recent assessment of Facility List of attendees encl
MURLEY, T E Region 1, Office of Director 83/10/20 DIECKAMP, H General Public Utilities - GPU Service Corp 2pp 20924 358 24X Fiche 50-219, 83/10/20, 8310270180

8310240124 Notification of 831108 meeting w/util in Parsippany, NJ to discuss SEP integrated plant safety assessment rept suppl, full-term OL conversion process & status of Cycle 10 refueling/maint outage
LOMBARD, J J Operating Reactors Branch 5 83/10/21 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 20891 150 24X Fiche 50-219, 83/10/21, 8310240124

/ 24X

DOCKETED ITEMS

29

8310270331 Ack receipt of 830906 request for extension to submit 170-day response to Generic Ltr 83-28 re Salem ATWS events. Request denied info re schedules for final implementation should be provided by 831105
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/26 FIEDLER, P B General Public Utilities - GPU Service Corp 3pp 20923 140 24X Fiche 50-219, 83/10/26, 8310270331

Q Inspection reports, IE Bulletins & correspondence

8308300340 IC Info Notice 83-61, "Alleged Use of Stand Ins for Wilder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20794 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IC Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 110pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IC Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTU Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310170335 Application to amend License NHR-16 consisting of Rev 1 to Tech Spec Change Request 104 reflecting visual insp of all accessible core spray spargers, repair assemblies & core spray piping internal to reactor vessel
FIEDLER, P B General Public Utilities - GPU Service Corp 83/10/11 NRC - No Detailed Affiliation Given 3pp 20786 152 24X Fiche 50-219, 83/10/11, 8310170335

8310180551 Notification of 831021 meeting w/UHR licensees in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking
MIRAGLIA, J Assistant Director for Safety Assessment 83/10/14 EISENHUT, D O Division of Licensing 5pp 20823 358 24X Fiche 50-000, 83/10/14, 8310180551

8310270159 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/83-20
STAROSTECKI, R Division of Project & Resident Programs 83/10/21 FIEDLER, P B General Public Utilities - GPU Service Corp 2pp 20925 015 24X Fiche 50-219, 83/10/21, 8310270159

--8310270158 Responds to NRC 830902 ltr re violations noted in IE Insp Rept 50-219/83-20 Corrective actions individual appropriately disciplined Details withheld (ref 10CFR79.21)
FIEDLER, P B General Public Utilities - GPU Service Corp 83/09/30 STAROSTECKI, R Division of Project & Resident Programs 3pp 20925 017 24X Fiche 50-219, 83/10/21, 8310270158

R Periodic operating reports & related correspondence

8310190031 Monthly operating rept for Aug 1983 W/830916 ltr
MOLNAR, J R, FIEDLER, P B, BARAN, R General Public Utilities - GPU Service Corp 83/09/06 Division of Data Automation & Management Information 8pp 20823 241 24X Fiche 50-219, 83/09/06, 8310190031

S Reportable occurrences, LLRs & related correspondence

8310270527 FOIA request for three categories of documents re 830606 gas leak at facility
ARGYROS, D Chamlin, Schottland, Rosen, Cavanagh & Uliano 83/06/22 NRC - No Detailed Affiliation Given 1p 20937 224 24X Fiche 50-219, 83/06/22, 8310270527

8310270541 Responds to FOIA request for three categories of documents re 830606 gas leak at facility Forwards App A documents
FELTON, J M Division of Rules and Records 83/07/22 ARGYROS, D L Chamlin, Schottland, Rosen, Cavanagh & Uliano 2pp 20937 225 24X Fiche 50-000, 83/07/22, 8310270541

--8310270547 Submits morning rept for Region I, listing 830606 & 07 events
ALLAN, J M Region I, Office of Director 83/06/07 BLAHA, J Program Support Branch 1p 20937 228 24X Fiche 50-000, 83/07/22, 8310270547

8310200161 LER 83-017/01T-0 on 830826, arming relay for diesel generator protective relay set at value possibly causing breaker to open during fast start Caused by design deficiency Betting changed W/830919 ltr
DICKINSON, A C, FIEDLER, P B General Public Utilities - GPU Service Corp 83/09/19 MURLEY, T E Region I, Office of Director 6pp 20834 08/ 24X Fiche 50-219, 83/09/19, 8310200161

DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8310060149 Forwards emergency preparedness exercise objectives for exercise planned for 830928, per 811026 ltr Meeting tentatively scheduled for 830118 at facility Draft scenario for initial review will be provided
MANOAN, C V Niagara Mohawk Power Corp 83/07/08 MURLEY, T E Region I, Office of Director 6pp 20648 344 24X Fiche 50-220, 83/07/08, 8310060149

8310060361 Forwards Rev 0 to "Niagara Mohawk Power Corp Nine Mile Point Unit 1 Emergency Preparedness Exercise Scenario 3A," per NRC 811026 request Exercise scheduled for 830928
LCHPOES, T C Niagara Mohawk Power Corp 83/08/03 MURLEY, T E Region I, Office of Director 21pp 20642 121 24X Fiche 50-220, 83/08/03, 8310060361

8310120090 Forwards IE Insp Rept 50-220/83-20 on 830721 & 25-0826 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/09/20 RHODE, G K Niagara Mohawk Power Corp 2pp 20697 128 24X Fiche 50-220, 83/09/20, 8310120090

--8310120096 IE Insp Rept 50-220/83-20 on 830721 & 25-0826 No noncompliance noted Major areas inspected licensee action on previous insp findings, operational safety verification, physical security surveillance testing & safety sys
HUBSON, G D, MCBREARTY, R A Region I, Office of Director LAZARUS, W J Division of Project & Resident Programs 81/09/16 12pp 20697 120 24X Fiche 50-220, 83/09/20, 8310120096

J Insurance & indemnity information

8310140043 Forwards Endorsement 69 to MACU Policy NF-46
RUSHMORE, J W Niagara Mohawk Power Corp 83/10/03 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 20768 278 24X Fiche 50-220, 83/10/03, 8310140043

8310140154 Forwards Endorsement 83 to NEI A Policy NF-161
RUSHMORE, J W Niagara Mohawk Power Corp 83/10/03 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 20762 360 24X Fiche 50-220, 83/10/03, 8310140154

P Operating license stage documents & correspondence

8310060581 Requests util analyze potential for flooding of safety-related structures, sys & components caused by location of security fence for Unit 2 for rainfall events up to PMP
Response due in 45 days
VASSALLO, D B Operating Reactors Branch 2 83/09/19 RHODE, G K Niagara Mohawk Power Corp 5pp 20661 207 24X Fiche 50-220, 83/09/19, 8310060581

DOCKETED ITEMS

8310060574 Forwards safety evaluation of Util 791217 & 820127 responses re operability of containment vent & purge valves Addl info requested within 15 days
VASSALLO, D B Operating Reactors Branch 2 83/09/21 RHODE, G K
Niagara Mohawk Power Corp 3pp 20651 229 24X
Fiche 50-220, 83/09/21, 8310060574

--8310060978 Safety evaluation re demonstration of containment purge & vent valve operability (B-24) Util info failed to demonstrate operability of 20-inch & 24-inch valves to close against buildup of containment pressure in event of LOCA
* NRC - No Detailed Affiliation Given 83/09/21 3pp
20661 232 24X Fiche 50-220, 83/09/21, 8310060978

8310120406 Forwards application to amend License DPR-63, consisting of proposed change to Tech Specs re reporting requirements for reactor vessel matl surveillance specimen
MANGAN, C V Niagara Mohawk Power Corp 83/09/26 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 20699 025 24X
Fiche 50-220, 83/09/26, 8310120406

--8310120416 Application to amend License DPR-63, revising Tech Specs to incorporate current reporting requirements for reactor vessel matl surveillance specimen, per recent rev to 10CFR50, App H Supporting info encl
MANGAN, C V Niagara Mohawk Power Corp 83/10/06 7pp
20699 026 24X Fiche 50-220, 83/09/26, 8310120406

8310040597 Forwards response to draft technical evaluation rept assessing conformance w/general load handling guidelines of NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants,"
Addl response will be provided by 831115
LEHFGES, T E Niagara Mohawk Power Corp 83/09/30 EISENHUT, D G
Division of Licensing 9pp 20625 327 24X Fiche 50-220, 83/09/30, 8310040597

310040631 Forwards sys component evaluation worksheets resolving outstanding environ qualification items for electrical equipment per Schedule 1 of App C to Util 830520 & 0709
It's No equipment yet determined unacceptable
MANGAN, C V Niagara Mohawk Power Corp 83/09/30 VASSALLO, D B
Operating Reactors Branch 2 3pp 20625 352 24X
Fiche 50-220, 83/09/30, 8310040631

8310180098 Forwards "Summary Rept & Program Plan for Control Room Design Review," per 830707 ltr re NUREG-0737, Item I D 1 activities
MANGAN, C V Niagara Mohawk Power Corp 83/09/30 VASSALLO, D B
Operating Reactors Branch 2 1p 20807 184 24X
Fiche 50-220, 83/09/30, 8310180098

--8310180102 "Summary Rept & Program Plan for Control Room Design Review"
* Niagara Mohawk Power Corp 83/09/30 23pp 20807 185 24X
Fiche 50-220, 83/09/30, 8310180098

10120097 Forwards response to 830908 request for addl info re criticality analysis, supporting application for spent fuel storage capacity expansion
MANGAN, C V Niagara Mohawk Power Corp 83/10/05 VASSALLO, D B
Operating Reactors Branch 2 8pp 20497 120 24X
Fiche 50-220, 83/10/05, 8310120097

310120205 Forwards revised Tech Spec Table 3 & 4a re safety-related hydraulic mechanical snubbers info supercedes 80041B & B10320 submittals
MANGAN, C V Niagara Mohawk Power Corp 83/10/05 VASSALLO, D B
Operating Reactors Branch 2 1p 20496 115 24X
Fiche 50-220, 83/10/05, 8310120205

--8310120208 Revised Tech Specs Table 3 & 4a & b re safety-related hydraulic snubbers
* Niagara Mohawk Power Corp 83/10/05 7pp 20496 116 24X
Fiche 50-220, 83/10/05, 8310120205

1310120373 Requests 2-yr extension to implementation date in amended rule 10CFR50.44(m) requiring min number of licensed operators & senior operators on shift at all times TMI Item 1 A 1 3 implemented using shift technical advisor
MANGAN, C V Niagara Mohawk Power Corp 83/10/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 20699 197 24X
Fiche 50-220, 83/10/06, 8310120373

8310170586 Responds to NRC 830921 ltr requesting assessment of operability of containment vent & purge isolation valves & closure of valves until adequate info provided Final evaluation will be submitted by 831114
MANGAN, C V Niagara Mohawk Power Corp 83/10/11 VASSALLO, D B
Operating Reactors Branch 2 3pp 20700 229 24X
Fiche 50-220, 83/10/11, 8310170586

8310140221 Responds to 830823 request for position re NUREG-0737, Item I E 4 2(7), "Containment Isolation on High Radiation"
Completion of evaluation anticipated by 831201
MANGAN, C V Niagara Mohawk Power Corp 83/10/12 VASSALLO, D B
Operating Reactors Branch 2 1p 20761 187 24X
Fiche 50-220, 83/10/12, 8310140221

8310210171 Outlines proposed program for integration of engineering evaluations & plant improvements resulting from current & anticipated regulatory requirements & reliability improvement needs
MANGAN, C V Niagara Mohawk Power Corp 83/10/19 VASSALLO, D B
Operating Reactors Branch 2 13pp 20055 126 24X
Fiche 50-220, 83/10/19, 8310210171

0 Inspection reports, IE Bulletin & correspondence

8310070114 Forwards safety evaluation of licensee 800502 & 820730 requests for relief from inservice insp requirements of Section XI of ASME Boiler & Pressure Vessel Code Relief from impractical requirements granted
VASSALLO, D B Operating Reactors Branch 2 83/09/19 RHODE, G K
Niagara Mohawk Power Corp 3pp 20600 085 24X
Fiche 50-220, 83/09/19, 8310070114

--8310070119 Safety evaluation of licensee 800502 & 820730 requests for relief from inservice insp requirements of Section XI of ASME Boiler & Pressure Vessel Code Relief from impractical requirements granted
* Office of Nuclear Reactor Regulation, Director 83/09/19 9pp
20680 088 24X Fiche 50-220, 83/09/19, 8310070114

--8209200334 "Nine Mile Point Unit 1 Inservice Insp Program," technical evaluation rept
* Science Applications, Inc NRC-03-82-096 SAI-186-028-11
82/09/17 NRC - No Detailed Affiliation Given 30pp
20680 097 24X Fiche 50-220, 83/09/19, 8310070114

--8310070123 Notice of grant of relief from impractical ASME Boiler & Pressure Vessel Code insp requirements
VASSALLO, D B Operating Reactors Branch 2 83/09/19 2pp
20680 127 24X Fiche 50-220, 83/09/19, 8310070114

8310120090 Forwards IE Insp Rept 50-220/83-20 on 830721 & 25-0824 re noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/09/20
RHODE, G K Niagara Mohawk Power Corp 2pp 20697 128 24X
Fiche 50-220, 83/09/20, 8310120090

--8310120096 IE Insp Rept 50-220/83-20 on 830721 & 25-0824 re noncompliance noted Major areas inspected licensee action on previous insp findings, operational safety verification, physical security surveillance testing & safety sys
HAZARD, S D, MC CREARY, R A Region 1, Office of Director
LAZARUS, W J Division of Project & Resident Programs 83/09/16
12pp 20697 130 24X Fiche 50-220, 83/09/20, 8310120090

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 110pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.57 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310060005 EN-83-061 on 831006, notice of violation & proposed imposition of \$40,000 civil penalty will be issued based on util failure to place main steam line high radiation trip sys in tripped condition when both channels inoperable
KLEINER, G, AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/10/03 1p 20649 294 24X Fiche 50-220, 83/10/03, 8310060005

DOCKETED ITEMS

31

8310270581 Discusses IE insps on 830607-24, 0805, 12-15 & 18-22 & forwards notice of violation & proposed imposition of civil penalty
MURLEY, T E Region 1, Office of Director 83/10/06 RHODE, G K
Niagara Mohawk Power Corp App 20943 355 24X
Fiche 50-220, 83/10/06, 8310270581

--8310270585 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Noncompliance noted inadequate review of shift checks, inadequate monitoring of plant parameters & inadequate understanding of Tech Specs
MURLEY, T E Region 1, Office of Director 83/10/06 App 20943 359 24X Fiche 50-220, 83/10/06 8310270581

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310160551 Notification of 831021 meeting w/BWR licensees in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking
MIRAGLIA, F J Assistant Director for Safety Assessment 83/10/14 EISENHUT, D G Division of Licensing App 20823 358 24X
Fiche 50-000, 83/10/14, 8310160551

8310270207 Ack receipt of 830901 & 07 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-220/83-16
Violation reduced to Level V to ack 1981 verification & Jul 1983 reverification of design adequacy
MARTIN, T T Division of Engineering & Technical Programs 83/10/10 RHODE, G K, SEIBERT, C R Niagara Mohawk Power Corp 2pp 20924 101 24X Fiche 50-220, 83/10/10, 8310270207

--8310270212 Responds to 830904 telcon request for addl info re 830901 response to violation Item B noted in IE Insp Rept 50-220/83-16 Engineering Procedure LP 090, "Control of Design & Design Verification" forms forwarded W/o encl
LEMPGES, T E Niagara Mohawk Power Corp 83/09/07 BRIGGS, L Region 1, Office of Director 2pp 20924 103 24X
Fiche 50-220, 83/10/10, 8310270212

--8310270217 Responds to NRC 830803 ltr re violations noted in IE Insp Rept 50-220/83-16 Corrective actions valve operators on listed valves removed, closed & modified & seismic calculations performed on cooling lines
LEMPGES, T E Niagara Mohawk Power Corp 83/09/01 MARTIN, T T Division of Engineering & Technical Programs 3pp 20924 105 24X Fiche 50-220, 83/10/10, 8310270217

R Periodic operating reports & related correspondence

8310140111 Monthly operating rept for Sept 1983 W/831007 ltr
ROMAN, T W, LEMPGES, T E Niagara Mohawk Power Corp 83/10/05 Director's Office, Office of Inspection and Enforcement 5pp 20766 111 24X Fiche 50-220, 83/10/05, 8310140111

S Reportable occurrences, LLRs & related correspondence

8310190169 Updated RD 83-23 on 830809, circuit breaker for core spray pump suction valve 81-21 taken out of svc for preventive maint while leaving valve in open position Event did not violate Tech Spec 3.3.4 b as previously reported
LEMPGES, T E Niagara Mohawk Power Corp 83/09/24 MURLEY, T E Region 1, Office of Director 1p 20661 089 24X
Fiche 50-220, 83/09/26 8310190169

8310310359 LER 83-024/03L-0 on 830826, one of two inadequate core cooling reactor core level indicators failed surveillance test Caused by high register value due to bad contacts Sys reinitialized & register zeroed W/830724 ltr
KESEL, D T, LEMPGES, T E Niagara Mohawk Power Corp 83/09/26 MURLEY, T E Region 1, Office of Director 2pp 20761 125 24X
Fiche 50-220, 83/09/26, 8310310359

8310070301 Potential Part 21 rept re underrange characteristic of Model N HIGM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X
Fiche 50-000, 83/09/30, 8310070301

DOCKET 50-223 UNIV OF LOWELL RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8310120153 Forwards IE Insp Rept 50-223/83-01 on 830822-23 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/09/21 BEGHIAN, L E Lowell, Univ of 2pp 20698 085 24X
Fiche 50-223, 83/09/21, 8310120153

--8310120156 IE Insp Rept 50-223/83-01 on 830822-23 No noncompliance noted Major areas inspected physical protection measures for SNM of moderate strategic significance
DUNLAP, J M, GDDY, A T Region 1, Office of Director 83/09/20 2pp 20698 087 24X Fiche 50-223, 83/09/21, 8310120153

G Inspection reports, IE Bulletins & correspondence

8310120153 Forwards IE Insp Rept 50-223/83-01 on 830822-23 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/09/21 BEGHIAN, L E Lowell, Univ of 2pp 20698 085 24X
Fiche 50-223, 83/09/21, 8310120153

--8310120156 IE Insp Rept 50-223/83-01 on 830822-23 No noncompliance noted Major areas inspected physical protection measures for SNM of moderate strategic significance
DUNLAP, J M, GDDY, A T Region 1, Office of Director 83/09/20 2pp 20698 087 24X Fiche 50-223, 83/09/21, 8310120153

DOCKET 50-224 UNIV OF CALIFORNIA RESEARCH REACTOR

S Reportable occurrences, LLRs & related correspondence

8310200176 PNO-V-83-047 on 831011, licensee received notification from Radiation Detection Co of one film badge indicating potential whole body exposure of 18 rem film badge not representative of exposure
BIERMAN, C, WENSLAWSKI, F Region 5, Office of Director 83/10/12 1p 20835 315 24X Fiche 50-224, 83/10/12, 8310200176

DOCKET 50-225 RPI CRITICAL EXPERIMENT

P Operating license stage documents & correspondence

831010121 Application to amend License CX-22 changing Tech Specs as part of license renewal process
WICKS, F Rensselaer Polytechnic Inst, Troy, NY 83/10/05 THOMAS, C O Standardization & Special Projects Branch 1p 20666 300 24X Fiche 50-225, 83/10/05, 831010121

--831010122 Amended Tech Specs re License CX-22 renewal
* Rensselaer Polytechnic Inst, Troy, NY 83/10/05 31pp 20666 309 24X Fiche 50-225, 83/10/05, 831010121

8310200051 Forwards ltr dtd 831012 to replace 831005 ltr re Tech Specs Original ltr missing signatures
HARRIS, D R Rensselaer Polytechnic Inst, Troy, NY 83/10/13 THOMAS, C O Standardization & Special Projects Branch 1p 20837 008 24X Fiche 50-225, 83/10/13, 8310200051

--8310200055 Forwards amended Tech Specs W/o encls
HARRIS, D R, WICKS, F Rensselaer Polytechnic Inst, Troy, NY 83/10/13 THOMAS, C O Standardization & Special Projects Branch 1p 20837 009 24X Fiche 50-225, 83/10/13, 8310200055

DOCKETED ITEMS

Q Inspection reports, IE Bulletins & correspondence

B310240110 Forwards IE Insp Rept 50-225/83-03 on B30810-12 No noncompliance noted
 STAROSTICKI, R Division of Project & Resident Programs B3/10/04
 LAHEY, R T Rensselaer Polytechnic Inst, Troy, NY 2pp 20941 08/ 24X Fiche 50-225 B3/10/04, B310240110

--B310240115 IE Insp Rept 50-225/83-03 on B30810-12 No noncompliance noted Major areas inspected license action on previous insp findings, facility operations, radiation controls & environ monitoring
 KINNEY, W W, ELBASSER, T C Region 1, Office of Director B3/10/03 4pp 20881 08/ 24X Fiche 50-225, B3/10/04, B310240110

DOCKET 50-228 AEROTEST RADIOGRAPHY & RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

B310210254 Forwards IE Insp Rept 50-228/83-02 on B30928-29 No noncompliance noted
 WENSLAWSKI, F A Region 5, Office of Director B3/10/07
 NEWACHEK, R Aerotest Operations, Inc 2pp 20851 15/ 24X Fiche 50-228, B3/10/07, B310210254

--B310210256 IE Insp Rept 50-228/83-02 on B30928-29 No noncompliance noted Major areas inspected radiation protection program, organization, posting & labeling, instrument calibr, personnel monitoring, effluent releases & surveys
 CILLIS, M, WENSLAWSKI, F A Region 5, Office of Director B3/10/07 8pp 20851 25/ 24X Fiche 50-228, B3/10/07, B310210254

DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B310040121 Releases public version of revised emergency plan implementing procedure
 FELTON, J M Division of Rules and Records B3/09/22 Document Management Branch 1p 20634 34/ 24X Fiche 50-010, B3/09/22, B310040121

--B310040136 Public version of Rev 0 to Emergency Plan Implementing Procedure EPIP 300-16, "Radiation Surveys Under Accident Conditions" W/B30913 ltr, receipt form, procedure history & safety evaluation
 SCOTT, D J Commonwealth Edison Co B3/09/09 10pp 20674 24/ 24X Fiche 50-010, B3/09/22, B310040121

B310140262 Forwards IE Insp Repts 50-237/83-28 & 50-249/83-26 on B30913-16 No noncompliance noted
 PAPERIELLO, C J Region 3, Office of Director B3/09/30 NEED, C Commonwealth Edison Co 2pp 20761 24/ 24X Fiche 50-237, B3/09/30, B310140262

--B310140267 IE Insp Repts 50-237/83-28 & 50-249/83-26 on B30913-16 No noncompliance noted Major areas inspected emergency preparedness exercise
 FLOSKI, T, GLOERSEN, W, SNELL, W Region 3, Office of Director B3/09/30 10pp 20761 29/ 24X Fiche 50-237, B3/09/30, B310140262

B310270009 Releases public version of revised emergency plan implementing procedure
 FELTON, J M Division of Rules and Records B3/10/21 Document Management Branch 1p 20940 16/ 24X Fiche 50-010, B3/10/21, B310270009

--B310270017 Public version of Rev 5 to Emergency Plan Implementing Procedure EPIP 300-1, "Initial Notifications & Generating Station Emergency Plan Responses (Primary Responsibility - Station Director)" W/B31014 ltr
 SCOTT, D J Commonwealth Edison Co B3/10/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 20pp 20940 16/ 24X Fiche 50-010, B3/10/21, B310270009

B310270526 Releases public version of revised emergency plan implementing procedure
 FELTON, J M Division of Rules and Records B3/10/21 Document Management Branch 1p 20937 21/ 24X Fiche 50-000, B3/10/21, B310270526

--B310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure EIP-6, "Administration & Logistics Manager" W/B31017 ltr & receipt form
 NEULIS, C A, HESSNER, R, MOORE, R D Commonwealth Edison Co B3/02/18 DENTON, H R NRC - No Detailed Affiliation Given 2pp 20937 21/ 24X Fiche 50-000, B3/10/21, B310270526

B310280307 Releases public version of revised generating stations emergency plan telephone directory
 FELTON, J M Division of Rules and Records B3/10/21 Document Management Branch 1p 20963 17/ 24X Fiche 50-000, B3/10/21, B310280307

--B310280314 Public version of revised generating stations emergency plan telephone directory
 GALLE, D R, MOORE, R D Commonwealth Edison Co B3/03/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 20pp 20963 12/ 24X Fiche 50-000, B3/10/21, B310280307

B310280191 Releases public version of revised emergency plan implementing procedure
 FELTON, J M Division of Rules and Records B3/10/26 Document Management Branch 1p 20962 26/ 24X Fiche 50-000, B3/10/26, B310280191

--B310280209 Public version of Rev 1 to Emergency Plan Implementing Procedure EPI-15, "Emergency Operations Facility Activation"
 MOORE, R D Commonwealth Edison Co B3/08/02 50pp 20961 27/ 24X Fiche 50-000, B3/10/26, B310280191

G Adjudicatory correspondence

B310070156 Forwards Director's Decision B3-14, denying B70909 10th ltr, petition re transport of spent nuclear fuel from West Valley
 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director B3/09/30 CELLBREZZI, A J Ohio, State of 2pp 20680 30/ 24X Fiche 50-000, B3/09/30, B310070156

--B310070161 Forwards Director's Decision B3-14, denying B70824 2nd ltr, petition re transport of spent nuclear fuel from West Valley
 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director B3/09/30 KLIKUL, M Illinois, Club 1p 20680 30/ 24X Fiche 50-000, B3/09/30, B310070156

--B310070167 Notice of issuance of Director's Decision B3-14, denying B30909 & B824, respectively, 10th & 206 petitions re transport of spent nuclear fuel from West Valley
 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director B3/09/30 10pp 20680 31/ 24X Fiche 50-000, B3/09/30, B310070156

--B310070171 Director's Decision B3-14, denying State of OH & Sierra Club B30909 & B824, respectively, 10th & 206 petitions re transport of spent nuclear fuel from West Valley Request for hearing & for preparation of EIS denied
 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director B3/09/30 18pp 20680 31/ 24X Fiche 50-000, B3/09/30, B310070156

B310270277 Order extending time until B31128 for Commission to act to review Director's Decision B3 B3-14, denying Sierra Club & State of OH requests
 CHILK, S J Office of the Secretary of the Commission B3/10/21 Commissioners 1p 20923 17/ 24X Fiche 50-000, B3/10/21, B310270277

P Operating license stage documents & correspondence

B310040471 Submits addl info to allow issuance of full-term OH ltr 40 yrs from original provisional UL issued 6/12/72 Request consistent w/Atomic Energy Act & NRC regulations
 RYBAK, D Commonwealth Edison Co B3/09/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20621 27/ 24X Fiche 50-237, B3/09/27, B310040471

B310040320 Commits to formal submittal of proposed radiological ltr amend by 640106
 RYBAK, D Commonwealth Edison Co B3/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20620 28/ 24X Fiche 50-237, B3/09/28, B310040471

B310070264 Forwards proprietary "Dresden 2/3 Nuclear Generating Plant, Unit 1 Suppression Pool Temp Response," "EI Hatch Nuclear Power Station Units 1 & 2 Suppression Pool Temp Response" & Mark I B30825 meeting viewgraphs Repts withheld (ref 10C16, 7/00)
 PFEFFERLEN, H C General Electric Co B3/09/30 VASSALLO, D R Operating Reactors Branch 2 8pp 20611 29/ 24X Fiche 50-000, B3/09/30, B310070156

B310050524 Forwards SER re util response to NUREG-0737, Item 11 B3-1, "RCS Vents" Item complete
 CRUTCHFIELD, D D Operating Reactors Branch 4 B3/10/03 FARRAN, R J Commonwealth Edison Co 4pp 20632 30/ 24X Fiche 50-237, B3/10/03, B310050524

DOCKETED ITEMS

33

- 8310090534 Selected Operating Reactor Issues Program II HLB Units (NURF 0/1), Item II B 1), Final technical evaluation report for Dresden Units 2 & 3
HELD, J. I. Lawrence Livermore Laboratory FIN A-0240
TF-380/0823A 83/04/06 ALBERTHAL, G NRC - No Detailed
Affiliation Given 4pp 2063, 341 24X Fiche 50-237, 83/10/03,
831005054

8310120189 Forwards response to NRC 830316 questions & request for additional info re SLP Topic III-B-A concerning pipe breaks inside containment
RYBAK, B Commonwealth Edison Co 83/10/03 GILBERT, R Operating Reactors Branch 5 5pp 20695 349 24X Fiche 50-237, 83/10/04,
8310120189

8310110168 Corrects Paragraph 3 M 5 of Amend 75 to License DPR-19 re 821221 request for Cycle 7 operation w/ reload fuel supplied by Exxon Nuclear Co
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/05 FARRAR, D I Commonwealth Edison Co 3pp 20666 234 24X Fiche 50-237, 83/10/05,
8310110168

8310200273 Forwards schedules for equipment qualification test program for facilities per 810528 ltr Dates given for current qualification activities should be viewed as "target dates" & not as firm dates
BARNES, P L Commonwealth Edison Co 83/10/05 KEMPLER, J G Region 3, Office of Director 10pp 20830 034 24X Fiche 50-000, 83/10/05,
8310200273

8310120424 Requests formal update of completion schedules from integrated plant safety assessment report to facilitate overall SLP resolution Response requested within 30 days
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/04 FARRAR, D I Commonwealth Edison Co 2pp 20698 240 24X Fiche 50-237, 83/10/04,
8310120424

8310120303 Notifies that monthly publication of FR notices will be provided w/o transmittal ltr
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/07 FARRAR, D I Commonwealth Edison Co 2pp 20690 336 24X Fiche 50-237, 83/10/07,
8310120303

8310260001 Forwards addl info requested in NRC 830316 ltr re util response to SLP Topic III-A, "Tornado Missiles" (cooling water to HXs is supplied from svc water sys which is independent from condensate storage tank)
RYBAK, B Commonwealth Edison Co 83/10/18 GILBERT, R Operating Reactors Branch 5 18pp 20712 206 24X Fiche 50-010, 83/10/18,
8310260001

8310280147 Forwards 830730 Director's Decision 83-14, denying State of OH & Sierra Club 10CFR2.206 petitions re transportation of spent fuel from West Valley facility, per 830930 request
CUNNINGHAM, R I Division of Fuel Cycle & Material Safety 83/10/10 MILLER, I Environmental Policy Institute 2pp 20761 347 24X Fiche 50-000, 83/10/18, 8310280147

8310250188 Forwards Amends 76 & 67 to Licenses DPR-19 & DPR-25, respectively & safety evaluation Amend changes Tech Specs re operability requirements for ECCS ring header snubbers
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/21 FARRAR, D I Commonwealth Edison Co 2pp 20693 344 24X Fiche 50-237, 83/10/21,
8310250188

--8310250195 Amends 76 & 67 to Licenses DPR-19 & DPR-25, respectively, changing Tech Specs re operability requirements for ECCS ring header snubbers, per 830613 application
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/21 14pp 20893 346 24X Fiche 50-237, 83/10/21, 8310250195

--8310250200 Safety evaluation supporting Amends 76 & 67 to Licenses DPR-19 & DPR-25, respectively
* Office of Nuclear Reactor Regulation, Director 83/10/21 2pp 20893 360 24X Fiche 50-237, 83/10/21, 8310250200

8310310052 Denies 830702 request for extension to submit formal response to Generic Ltr 83-28 re Salem ATWS event Info must be submitted by 831105 Participation in owners group for issues requiring long-range planning acceptable
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/26 FARRAR, D I Commonwealth Edison Co 3pp 20751 046 24X Fiche 50-237, 83/10/26,
8310310052

Q Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand Ins for Welder Qualification Test" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20774 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detector, Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA 1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o IECIN 59 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 116pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310140262 Forwards IE Insp Repts 50-237/83-28 & 50-249/83-26 on 830913-16 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 83/09/30 HELD, C Commonwealth Edison Co 2pp 20761 495 24X Fiche 50-237, 83/09/30,
8310140262

--8310140267 IE Insp Repts 50-237/83-28 & 50-249/83-26 on 830913-16 No noncompliance noted Major areas inspected emergency preparedness exercise
PLOSKE, T, GLOERSEN, W, SNELL, W Region 3, Office of Director 83/09/30 10pp 20761 297 24X Fiche 50-237, 83/09/30, 8310140267

8310200124 Forwards IE Mgt Meeting Repts 50-010/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORCLIVUS, C E Division of Project & Resident Programs 83/10/04 REED, C Commonwealth Edison Co 2pp 20834 098 24X Fiche 50-000, 83/10/04, 8310200124

--8310200148 IE Mgt Meeting Repts 50-020/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORCLIVUS, C I Division of Project & Resident Programs DAVIS, A I Region 3, Office of Director 83/10/03 4pp 20834 100 24X Fiche 50-000, 83/10/04, 8310200148

8310110140 Discusses concerns re licensee actions following failure of certain ECCS/containment isolation valves, per review of info in LER 83-006/01 O & IE Insp Repts 50-237/83-07 & 50-249/83-06 License amend application requested
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/05 FARRAR, D I Commonwealth Edison Co 5pp 20666 243 24X Fiche 50-237, 83/10/05,
8310110140

8310170337 Submits status of as-built reviews of safe shutdown piping supports for II Bulletin 79-14 As result of review of Quad Cities, two piping sys found to have addl discrepancies Seven new hangers added
RYBAK, B Commonwealth Edison Co 83/10/06 KEMPLER, J G Region 3, Office of Director 2pp 20785 155 24X Fiche 50-000, 83/10/06,
8310170337

8308300378 IE Info Notice 83-65, "Surveillance of Flow in R1B Bypass Loops Used in Westinghouse Plants" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 77pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8310210053 Forwards IE Insp Repts 50-010/83-17, 50-237/83-26 & 50-249/83-24 on 830829-31, 0901, 02 & 08 & notice of violation
PAPERIELLO, C J Region 3, Office of Director 83/10/07 HELD, C Commonwealth Edison Co 2pp 20855 286 24X Fiche 50-010, 83/10/07,
8310210053

--8310210061 Notice of violation from insp on 830829-31, 0901, 02 & 08
PAPERIELLO, C J Region 3, Office of Director 83/10/07 2pp 20855 288 24X Fiche 50-010, 83/10/07, 8310210061

--8310210074 IE Insp Repts 50-010/83-17, 50-237/83-26 & 50-249/83-24 on 830829-31, 0901, 02 & 08 Noncompliance noted inadequate calibr of D-1 & D-2/3 chimney monitors & failure to follow procedures re radiation protection
PAUL, R A, HELD, L J, GREGG, L R Region 3, Office of Director 83/10/07 5pp 20855 290 24X Fiche 50-010, 83/10/07, 8310210074

DOCKETED ITEMS

- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761
- 8310140036 Ack receipt of 830922 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/83-09, 50-237/83-20 & 50-249/83-13
NORELIUS, C Division of Project & Resident Programs 83/10/11
REED, C Commonwealth Edison Co 1p 20767 341 24X
Fiche 50-010, 83/10/11, 8310140036
- 8310140049 Responds to NRC 830823 ltr re violations noted in IE Insp Repts 50-010/83-09, 50-237/83-20 & 50-249/83-13 Corrective actions operations personnel closed & latched all battery charger cabinets
FARRAR, D L Commonwealth Edison Co 83/09/22 KEPPLE, J G
Region 3, Office of Director 4pp 20767 342 24X
Fiche 50-010, 83/10/11, 8310140049
- 8310140099 Ack receipt of 830916 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/83-12, 50-237/83-20 & 50-249/83-18
NORELIUS, C Division of Project & Resident Programs 83/10/11
REED, C Commonwealth Edison Co 1p 20766 099 24X
Fiche 50-010, 83/10/11, 8310140099
- 8310140104 Responds to NRC 830721 ltr re violations noted in IE Insp Repts 50-010/83-12, 50-237/83-20 & 50-249/83-18 Corrective actions scope & general method of training program completely detailed in training procedures
FARRAR, D L Commonwealth Edison Co 83/09/16 KEPPLE, J G
Region 3, Office of Director 4pp 20766 100 24X
Fiche 50-010, 83/10/11, 8310140104
- 10180268 Clarifies NRC position re procedures for admitting NRC personnel to facilities Access should be afforded to Region III personnel listed in encl Update will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 REED, C
Commonwealth Edison Co 7pp 20802 352 24X Fiche 50-010, 83/10/14, 8310180268
- 8310180551 Notification of 831021 meeting w/NUREG licensees in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking
MIRAGLIA, F J Assistant Director for Safety Assessment 83/10/14
EISENHUT, D G Division of Licensing 5pp 20823 350 24X
Fiche 50-000, 83/10/14, 8310180551
- Periodic operating reports & related correspondence
- 10120273 Monthly operating repts for Sept 1983 W/831003 ltr
SCHROEDER, D A, SCOTT, D J Commonwealth Edison Co 83/10/03
Director's Office, Office of Inspection and Enforcement 16pp
20693 091 24X Fiche 50-237, 83/10/03, 8310120273
- Reportable occurrences, LERs & related correspondence
- 831010425 FOIA request for info re PNO-111-83-027 concerning faulty valve radiographs, PNO-111-83-026 concerning use of lubricant on valve seats & info on DGE/NRC 830419-20 meetings concerning geologic repository in salt program
HIAAT, S L Ohio Citizens for Responsible Energy 83/05/10
FELTON, J M Division of Rules and Records 1p 20706 001 24X
Fiche 50-000, 83/05/10, 831010425
- 831010430 Responds to FOIA request for four different categories of documents described in 830510 ltr Forwards matl listed in App A responsive to Items 1, 2 & 4 DOE should be contacted for matl requested in Item 3 of ltr
FELTON, J M Division of Rules and Records 83/06/14 HIAAT, S L
Ohio Citizens for Responsible Energy 3pp 20706 002 24X
Fiche 50-000, 83/06/14, 831010430
- 831010441 Excerpt from notification of events at two different facilities re deficiency concerning control complex chilled water sys & info received that grease incorrectly used on MSIVs, respectively Related info encl
* Region 3, Office of Director 83/04/08 11pp 20706 044 24X
Fiche 50-000, 83/06/14, 831010441
- 831010446 Daily rept re events at three different facilities (A) (P) experienced scram due to low water level PNO-111-83-026 updates use of lubricants on valve seats
* Region 3, Office of Director 83/04/13 1p 20706 044 24X
Fiche 50-000, 83/06/14, 831010446
- 831010448 Responds to 830413 ltr requesting info re use of lubricants on valve seating surfaces Lubricants & cleaning solvents used on valve component surfaces per vendor recommendations & maint practices
FARRAR, D L Commonwealth Edison Co 83/04/22 KEPPLE, J G
Region 3, Office of Director 4pp 20706 063 24X
Fiche 50-000, 83/06/14, 831010448
- 8310260008 Addl response to FOIA request for 1/ categories of records Forwards documents listed in Apps B, C & D info re fraudulent practices of Ray Miller, Inc available in PNO FELTON, J M Division of Rules and Records 83/06/23 (LFW) 11, 1
Public Citizen Litigation Group 19pp 20920 001 24X
Fiche 50-000, 83/06/23, 8310260008
- 8310260096 Describes facility 831203 flood & corrective action, LER Chronology of events encl, including notification of event & procedure for briefing commissioner
PERKINS, K L NRC - No Detailed Affiliation Given 83/06/01
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 11pp 20921 136 24X Fiche 50-010, 83/06/01, 8310260096
- 8310070301 Potential Part 21 rept re underrange characteristic of Model N-ELIOM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X
Fiche 50-000, 83/09/30, 8310070301
- 8310060373 LER 83-064/03L-0 on 830905 control rod drive scram discharge vol continuous ultrasonic test indication displayed erratic info caused by heating steam line leak above monitor cabinet Leak repaired Module replaced W/831003 ltr
RHEE, S, SCOTT, D J Commonwealth Edison Co 83/10/03 KEPPLE, J G
Region 3, Office of Director 3pp 20646 069 24X
Fiche 50-237, 83/10/03, 8310060373
- 8310101040 Discusses concerns re licensee actions following failure of certain ECCS/containment isolation valves, per review of info in LER 83-006/01T-0 & IE Insp Repts 50-237/83-07 & 50-249/83-08 License amend application requested
GRUTCH, E L D, Operating Reactors Branch 5 83/10/08 HIAAT, S L
Commonwealth Edison Co 5pp 20666 293 24X Fiche 50-237, 83/10/08, 8310101040
- 8310170553 Responds to item of concern in NRC 830901 ltr re LER 83-011-83-081 events involving discovery of holes in expansion bellows on torus to drywell vacuum breaker lines Corrective actions enumerated
RYBAK, B Commonwealth Edison Co 83/10/07 BENJON, H R (Office of Nuclear Reactor Regulation, Director 4pp 20760 207 24X
Fiche 50-237, 83/10/07, 8310170553
- 8310210127 LER 83-068/01T-0 on 831002, during HPCI surveillance 11:23:00-8, motor operated valve 2301-35 failed to open on receiving open signal Caused by limit torque valve operator terminal & broken lug connector lug replaced W/831012 ltr
ANANDAPPA, A, SCOTT, D J Commonwealth Edison Co 83/10/12 KEPPLE, J G
Region 3, Office of Director 4pp 20855 214 24X
Fiche 50-237, 83/10/12, 8310210127
- 8310210297 LER 83-065/03L-0 on 830917, scram discharge vol vent valve 2-0399-534 found locked closed instead of locked open Caused by valve left open during previous scram discharge vol Test DOS 300-7 All locked valves checked W/831012 ltr
WHALEN, R J, SCOTT, D J Commonwealth Edison Co 83/10/12 KEPPLE, J G
Region 3, Office of Director 3pp 20855 214 24X
Fiche 50-237, 83/10/12, 8310210297
- 8310210313 LER 83-066/03L-0 on 830918, MSIV 2D 2 5 s closure time exceeded Tech Spec requirement of 4 to 5 s Caused by timing mechanism out of adjustment Mechanism adjusted W/831012 ltr
MAXWELL, D, SCOTT, D J Commonwealth Edison Co 83/10/12 KEPPLE, J G
Region 3, Office of Director 3pp 20855 214 24X
Fiche 50-237, 83/10/12, 8310210313

DOCKETED ITEMS

35

DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8310120344 Notification of 8310/27 meeting w/util in Bethesda, MD to discuss mods to fire protection safe shutdown plan
DICK, G J Operating Reactors Branch 5 83/10/07 (KUTCHFIELD, D)
Operating Reactors Branch 5 Jpp 20/00 25/ 24X
Fiche 50-244, 83/10/07, 8310120344

8310270076 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/20 Document
Management Branch 1p 20942 05/ 24X Fiche 50-244, 83/10/20, 8310270076

--8310270086 Forwards public version of revised emergency plan implementing procedures, including Procedures SC-607 re station call list, SC-606 re specialized notification list & SC-233 re search & rescue operation
MAIER, J E Rochester Gas & Electric Corp 83/10/07 MURPHY, T E
Region 1, Office of Director 1p 20942 05/ 24X
Fiche 50-244, 83/10/20, 8310270076

--8310270094 Public version of revised emergency plan implementing procedures, including Procedures SC-607 re station call list, SC-606 re specialized notification list & SC-233 re search & rescue operation
BODINE, J C, SPECTER, S M Rochester Gas & Electric Corp
83/10/05 5pp 20942 05/ 24X Fiche 50-244, 83/10/20, 8310270076

P Operating license stage documents & correspondence

8310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR
CONNER, L Affiliation Unknown 83/09/02 NH - No Detailed
Affiliation Given 1p 21004 2/0 24X Fiche 50-000, 83/09/07, 8310310017

8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which repts are unavailable
FELTON, J M Division of Rules and Records 83/07/06 CONNER, L
Affiliation Unknown 1p 21004 271 24X Fiche 50-000, 83/07/06, 8310310031

--8310310073 Forwards "Reactor Containment Bldg Integrated Leak Rate Test," including analysis & interpretation of Type A test results & summary analysis of Type B & C tests performed since last Type A test in Oct 1972
WHITE, L D Rochester Gas & Electric Corp 76/05/19 PURPLE, R A
Office of Nuclear Reactor Regulation, Director 1p 21007 075
24X Fiche 50-000, 83/07/06, 8310310031

--8310310076 "Reactor Containment Bldg Integrated Leak Rate Test"
* Rochester Gas & Electric Corp 76/02/28 120pp 2100/ 076
24X Fiche 50-000, 83/07/06, 8310310031

8310070020 Ack receipt of 830824 ltr requesting Commission publish notice of pending license amend in FR re New York State Energy R&D Authority license for util w/irradiated fuel storage facility
DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director
83/09/22 REBNIKOFF, M Sierra Club 1p 20671 361 24X
Fiche 50-000, 83/09/22, 8310070020

8310040451 Forwards safety evaluation supporting Westinghouse licensee responses to NUREG-0737, Items 11 K 3 1, "Automatic PORV Isolation" & 11 K 3 2, "Rept on PORVs" & Franklin Research Ctr "Operating Reactor PORV Repts (H-3/1), TMI Action"
CRUTCHFIELD, D Operating Reactors Branch 5 83/09/27 MAIER, J E
Rochester Gas & Electric Corp 17pp 20624 106 24X
Fiche 50-244, 83/09/27, 8310040451

8310030080 Forwards safety evaluation accepting snow sampling & vent procedures suby to described mod to Item 6 35 of Procedure SC-452 License Conditions 2 C(7) through 20 (ref NUREG-0716) satisfied
CRUTCHFIELD, D Operating Reactors Branch 5 83/09/29 MAIER, J E
Rochester Gas & Electric Corp 2pp 20590 069 24X
Fiche 50-244, 83/09/29, 8310030080

--8310030082 Safety evaluation supporting snow sampling & vent procedures suby to mod to Procedure SC 452
* Office of Nuclear Reactor Regulation, Director 83/09/29 App
20590 071 24X Fiche 50-244, 83/09/29, 8310030080

8310070365 Forwards Amend 57 to License DPR-18 & safety evaluation Amend changes Tech Specs to keep releases of radioactive matl to unrestricted areas during normal operations ALARA
CRUTCHFIELD, D Operating Reactors Branch 5 83/09/29 MAIER, J E
Rochester Gas & Electric Corp 6pp 20664 147 24X
Fiche 50-244, 83/09/29, 8310070365

--8310070368 Amend 57 to License DPR-18, changing Tech Specs to keep releases of radioactive matl to unrestricted areas during normal operations ALARA
CRUTCHFIELD, D Operating Reactors Branch 5 83/09/29 Bipp
20664 153 24X Fiche 50-244, 83/09/29, 8310070365

--8310070372 Safety evaluation supporting Amend 57 to License DPR-18
* Office of Nuclear Reactor Regulation, Director 83/09/28 Bipp
20664 234 24X Fiche 50-244, 83/09/29, 8310070365

--8310120240 "Radiological Effluent Tech Spec Implementation (A-2)," technical evaluation rept
CHEN, S Franklin Institute/Franklin Research Center
NRC-03-81-130 TER-C5506-93 83/01/19 CONGEL, F NRC - No
Detailed Affiliation Given 30pp 20664 242 24X
Fiche 50-244, 83/09/39, 8310070365

8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves
EISENHUT, D G Division of Licensing 83/10/06 FALLADINO, N J
GILINSKY, V, ROBERTS, T M Commissioners 3pp 20818 001 24X
Fiche 50-000, 83/10/06, 8308300771

--8310050206 Comments on Franklin Research Ctr qualification methodology research test of ASCO solenoid valves issuance of notification to licensees & applicants requiring response re valves failing test recommended
VOLLMER, R H Division of Engineering 83/09/28 EISENHUT, D G
Division of Licensing 5pp 20918 032 24X Fiche 50-000, 83/10/06, 8308300771

8310120328 Advises that monthly publication of portions of FR notice will be forwarded w/o transmittal ltr Addressees listed on svc list should pursue monthly publication for pertinent hearing opportunity notices
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/07 MAIER, J E
Rochester Gas & Electric Corp 2pp 20700 271 24X
Fiche 50-244, 83/10/07, 8310120328

8310180192 Responds to request for addl info re 821208 proposed Tech Spec for plant heatup & cooldown curves based on results of capsule T Info supplied by Westinghouse Chart summary of neutron flux monitor encl
MAIER, J E Rochester Gas & Electric Corp 83/10/10 CRUTCHFIELD, D
Operating Reactors Branch 5 6pp 20808 343 24X
Fiche 50-244, 83/10/10, 8310180192

8310180193 Forwards response to requests for addl info re special lifting devices used for control of heavy loads
(ref NUREG-0612)
MAIER, J E Pacific Gas & Electric Co 83/10/12 CRUTCHFIELD, D
Operating Reactors Branch 5 22pp 20809 061 24X
Fiche 50-244, 83/10/12, 8310180193

8310250681 Forwards SER (NUREG-0944) & FR notice re full-term OL application Provisional OL/Full-term OL conversion issue will be resolved by ASLB w/o SER
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/14 MAIER, J E
Rochester Gas & Electric Corp 2pp 20908 351 24X
Fiche 50-244, 83/10/14, 8310250681

--8310250682 Notice of availability of SER for full-term OL (NUREG-0944)
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/14 1p
20908 353 24X Fiche 50-244, 83/10/14, 8310250681

8310260353 Forwards SER (NUREG-0821) "Integrated Plant SAR" for full committee review on util full term OL application w/o encl
MIRAGLIA, F J Division of Licensing 83/10/14 RAY, J J ACRS
Advisory Committee on Reactor Safeguards 1p 20918 332 24X
Fiche 50-244, 83/10/14, 8310260353

Q Inspection reports, IE Bulletins & correspondence

8310060017 Forwards IE Insp Rept 50-244/83-20 on 830816-19 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/09/22
MAIER, J E Rochester Gas & Electric Corp 2pp 20649 253 24X
Fiche 50-244, 83/09/22, 8310060017

DOCKETED ITEMS

--8310060019 IE Insp Rept 50-244/83-20 on 830816-19 No noncompliance noted Major areas inspected radiation protection program including QA & QC in radioactive matls shipping & receipt & preparation & shipment of radioactive matls
COLLINS, D J, BHANBARY, M M Region 1, Office of Director
83/09/16 7pp 20649 255 24X Fiche 50-244, 83/09/22, 8310060019

8310060044 Forwards IE Insp Rept 50-244/83-18 on 830802-05 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/09/22
MAIER, J E Rochester Gas & Electric Corp 2pp 20647 0/4 24X
Fiche 50-244, 83/09/22, 8310060044

--8310060048 IE Insp Rept 50-244/83-18 on 830802-05 No noncompliance noted Major areas inspected licensee actions in response to IE Bulletins 79-02, 79-14 & 80-11
VARELA, A A, BURR, J P Region 1, Office of Director 83/09/16
8pp 20647 076 24X Fiche 50-244, 83/09/22, 8310060048

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 11pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 11pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 11pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc 11pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310210214 Forwards IE Insp Rept 50-244/83-19 on 830808-0911 & notice of violation
TAROSTECKI, R Division of Project & Resident Programs 83/10/05
MAIER, J E Rochester Gas & Electric Corp 2pp 20852 089 24X
Fiche 50-244, 83/10/05, 8310210214

8310210217 Notice of violation from Insp on 830808-0911
* Region 1, Office of Director 83/10/05 1p 20852 091 24X
Fiche 50-244, 83/10/05, 8310210217

8310210220 IE Insp Rept 50-244/83-19 on 830808-0911 Noncompliance noted Failure to take prompt corrective action on Audit Finding 80-36 re status of Quality Group B & C sys leakage exams
ZIMMERMAN, R P, LAZARUS, W J Region 1, Office of Director
83/10/05 10pp 20852 092 24X Fiche 50-244, 83/10/05, 8310210214

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 7pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 7pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc 11pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc 12pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310270143 Forwards SER re restart following steam generator tube rupture event on 820125, per NUREG-0916 Generator tube fiber optic insp acceptable, based on info in utli 821122 ltr
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/25 MAIER, J E
Rochester Gas & Electric Corp 2pp 20924 138 24X
Fiche 50-244, 83/10/25, 8310270143

--8310270149 Safety evaluation supporting steam generator tube fiber optic insp
* Office of Nuclear Reactor Regulation, Director 83/10/25 2pp
20924 140 24X Fiche 50-244, 83/10/25, 8310270149

R Periodic operating reports & related correspondence

8310190032 Monthly operating rept for Aug 1983 W/830906 ltr
MCNAHARA, A C, SNOW, B A Rochester Gas & Electric Corp 83/09/06
NRC - No Detailed Affiliation Given 6pp 20823 230 24X
Fiche 50-244, 83/09/06, 8310190032

S Reportable occurrences, LERs & related correspondence

8310250305 LER 83-026/01T-0 on 830915, boric acid storage tank solution concentration less than Tech Spec requirements caused by leakage of reactor makeup water through valve FCV-110A & check valve 355 Sampling increased W/830929 ltr
FELKINS, D L, MAIER, J E Rochester Gas & Electric Corp 83/09/29
MURLEY, T E Region 1, Office of Director 4pp 20899 004 24X
Fiche 50-244, 83/09/29, 8310250305

8310070301 Potential Part 21 rept re underrange characteristic of Model N-C110M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 1pp 20651 064 24X
Fiche 50-000, 83/09/30, 8310070301

8310110204 Forwards safety evaluation re thermal-hydraulic analysis of 820125 steam generator tube rupture incident item / resolved Reviews of Items 1, 3, 4, 5 & 17 complete Remaining items still under review
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/05 MAIER, J E
Rochester Gas & Electric Corp 2pp 20665 308 24X
Fiche 50-244, 83/10/05, 8310110204

--8310110206 Safety evaluation supporting licensee evaluation of 830725 steam generator tube rupture incident, per NUREG-0916
* Office of Nuclear Reactor Regulation, Director 83/10/05 6pp
20665 310 24X Fiche 50-244, 83/10/05, 8310110204

8310250217 LER 83-027/03L-0 on 830916, while reducing power, trip occurred from 1/4 power resulting in violations of Tech Specs 3.1.1a & c Caused by low-low steam generator level in loop B Operator counseled W/831006 ltr
BEATTY, E J, MAIER, J E Rochester Gas & Electric Corp 83/10/06
MURLEY, T E Region 1, Office of Director 3pp 20893 307 24X
Fiche 50-244, 83/10/06, 8310250217

8310140082 PND-I-83-109 on 831007, seismic event occurred in northeastern US w/magnitude of 5.2 on Richter scale in NY & 4.0 in NH No damage to equipment identified
GALLO, R M Region 1, Office of Director 83/10/07 1p 20766 116
24X Fiche 50-000, 83/10/07, 8310140082

8310170373 Forwards SER re reactor coolant pump trip & restart criteria after 820125 tube failure incident Adequate steps taken addressing items, based on info provided in 821122 ltr & 830422 response to Generic Ltr 83-10d Items 8 & 9 resolved
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/14 MAIER, J E
Rochester Gas & Electric Corp 2pp 20785 005 24X
Fiche 50-244, 83/10/14, 8310170373

--8310170378 SER supporting resolution of SER Items 8 & 9 re reactor coolant pump trip & restart criteria after 820125 tube failure incident
* Office of Nuclear Reactor Regulation, Director 83/10/14 5pp
20785 007 24X Fiche 50-244, 83/10/14, 8310170373

8310190029 Summary of 831005 meeting w/utli, INPD & ANL re INPD simulation of steam generator tube rupture event Summary & agenda encl
DICK, G F Operating Reactors Branch 5 83/10/14 Operating Reactors Branch 5 14pp 20823 141 24X Fiche 50-244, 83/10/14, 8310190029

8310270143 Forwards SER re restart following steam generator tube rupture event on 820125, per NUREG-0916 Generator tube fiber optic insp acceptable, based on info in utli 821122 ltr
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/25 MAIER, J E
Rochester Gas & Electric Corp 2pp 20924 138 24X
Fiche 50-244, 83/10/25, 8310270143

DOCKETED ITEMS

37

--B310270147 Safety evaluation supporting steam generator tube fiber optic insp
* Office of Nuclear Reactor Regulation, Director B3/10/25 2pp
20924 140 24X Fiche 50-244, B3/10/25, B310270143

DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B310060035 Forwards matl for B31005 emergency response exercise info needed for obtaining security & radiation protection clearances for NRC personnel requested by B30914 Exercise objectives for licensee encl W/o encl
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities B3/08/08
MURLEY, T E Region 1, Office of Director 5pp 20647 245 24X
Fiche 50-245, B3/08/08, B310060035

B310060205 Forwards draft exercise controller manual for upcoming B31005 full-scale emergency preparedness exercise info re NRC personnel participation & roles requested to allow inclusion in final manual W/o encl
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities B3/08/22
MURLEY, T E Region 1, Office of Director 2pp 20647 035 24X
Fiche 50-245, B3/08/22, B310060205

B310120259 Forwards "Re-Entry & Recovery Scenario" section of emergency preparedness exercise controllers manual limited distribution requested, until completion of B31005 exercise
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) B3/09/27 MURLEY, T E Region 1, Office of Director 25pp 20693 145 24X Fiche 50-245, B3/09/27, B310120259

J Insurance & indemnity information

B310270461 Forwards Endorsements B9 & B0 to NELIA Policy NF-173 & MAELU Policy NF-52, respectively, Endorsement 4 to NELIA Certificates NF-15 & NF-16 & MAELU Certificates NF-15 & NF-16
SINISI, J M Marsh & McLennan, Inc B3/10/21 SALTZMAN, J D Assistant Director for State & License Relations /pp 20923 126 24X Fiche 50-245, B3/10/21, B310270461

P Operating license stage documents & correspondence

B310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR
CONNER, L Affiliation Unknown B3/05/02 NRC - No Detailed Affiliation Given 1p 21004 270 24X Fiche 50-000, B3/05/02, B310310017

B310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which repts are unavailable
FELTON, J M Division of Rules and Records B3/07/06 CONNER, L Affiliation Unknown 1p 21004 271 24X Fiche 50-000, B3/07/06, B310310031

--B310310072 "Reactor Containment Bldg Integrated Leak Rate Test" W/30612 ltr
* Millstone Point Co /3/03/31 170pp 21006 334 24X
Fiche 50-000, B3/07/06, B310310031

B310030428 Requests that proposed Tech Spec change per D01015 ltr be reviewed considering schedule for integrated primary containment leak rate test to be conducted during upcoming refueling outage
COUNSIL, W G, BEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) BEARS, C F Northeast Utilities B3/09/22
CRUTCHFIELD, D Operating Reactors Branch 5 1p 20593 177 24X
Fiche 50-245, B3/09/22, B310030428

B310170656 Requests rev to confirmatory order contained in B30314 ltr for NUREG-0737 Items 11 F 1 & 11 F 2 to specify new B40101 completion date Replacement of Geiger-Mueller in detectors will be completed by B40101
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities B3/09/27
MILLER, J G Operating Reactors Branch 3 2pp 20782 070 24X
Fiche 50-245, B3/09/27, B310170656

B310170504 Application to amend Licenses DPR-21 & DPR-65, revising Tech Spec Section 6 re administrative controls to comply w/final rule on licensed operator staffing at nuclear power units per 44FR31611
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities B3/10/04
MILLER, J R Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 20784 137 24X Fiche 50-245, B3/10/04 B310170504

--B310170508 Proposed Tech Spec Section 6 re administrative controls for licensed operator staffing & qualification of radiation protection manager
* Northeast Nuclear Energy Co (subs of Northeast Utilities) B3/10/04 8pp 20784 140 24X Fiche 50-245, B3/10/04, B310170504

B310060213 Responds to B30914 proposal to develop integrated review for pending licensing actions Meeting to discuss proposed review requested
EISENHUT, D G Division of Licensing B3/10/05 COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 5pp 20647 131 24X
Fiche 50-000, B3/10/05, B310060213

B310120308 Requests update of completion schedules presented in integrated plant safety assessment rept within 30 days
CRUTCHFIELD, D Operating Reactors Branch 5 B3/10/06 COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 5pp 20701 004 24X
Fiche 50-000, B3/10/06, B310120308

B310120411 Notifies that util will no longer receive portions of FR containing Commission monthly notices w/transmittal ltr Util should carefully peruse publication for hearing opportunity notices
CRUTCHFIELD, D Operating Reactors Branch 5 B3/10/07 COUNSIL, W G Connecticut Yankee Atomic Power Co 2pp 20699 041 24X
Fiche 50-000, B3/10/07, B310120411

B310180469 Submits addl info re NRC request to expand results of B21203 analysis of stack failure consequences to include failure of stack at foundation since GIP Topic III-2 had determined limiting foundation capacities
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities B3/10/07
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 20802 051 24X
Fiche 50-245, B3/10/07, B310180469

B310180409 Forwards listed revs to "Corporate Organization for Nuclear Incidents (CONI) Procedure Manual," per Section V of App E to 10CFR50 W/o encl
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities B3/10/12 EISENHUT, D G Division of Licensing 1p 20803 173 24X Fiche 50-000, B3/10/12, B310180409

B310280112 Denies B30906 request for 120-day extension to respond to Generic Ltr B3-28 re generic implications of Salem ATWS events NRC review schedule does not permit extension
Response due by B31105
CRUTCHFIELD, D Operating Reactors Branch 5 B3/10/26 COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 20929 261 24X
Fiche 50-000, B3/10/26, B310280112

Q Inspection reports, IE Bulletins & correspondence

B308300340 IE Info Notice B3-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, B3/09/26, B308300340

B308300342 IE Info Notice B3-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, B3/09/26, B308300342

B308300345 IE Info Notice B3-63, "Potential Failures of Westinghouse Type 5A-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co of New York, Inc 110pp 20778 001 24X Fiche 50-000, B3/09/26, B308300345

B308300349 IE Info Notice B3-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, B3/09/29, B308300349

B308300378 IE Info Notice B3-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, B3/10/07, B308300378

DOCKETED ITEMS

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New
York, Inc 79pp 20662 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New
York, Inc. 120pp 20627 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180351 Notification of 831021 meeting w/BWR licensees in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking
MIRAGLIA, F. J. Assistant Director for Safety Assessment 83/10/14
EISENHUT, D. G. Division of Licensing 5pp 20823 358 24X
Fiche 50-000, 83/10/14, 8310180351

8310270193 Summary of 831021 meeting w/util re future insps for intergranular stress corrosion cracking Viewgraphs encl
BHEA, J. J. Operating Reactors Branch 5 83/10/24 Operating
Reactors Branch 5 18pp 20924 338 24X Fiche 50-245, 83/10/24, 8310270193

R Periodic operating reports & related correspondence

8310190015 Monthly operating rept for Aug 1983 W/830914 ltr
HARRAN, G., MRDCZKA, E. J. Northeast Nuclear Energy Co (subs of
Northeast Utilities) MRDCZKA, E. J. Northeast Utilities 83/09/06
Division of Data Automation & Management Information 6pp
20823 128 24X Fiche 50-245, 83/09/06, 8310190015

8310200129 Monthly operating rept for Sept 1983 W/831014 ltr
HARRAN, G., MRDCZKA, E. J. Northeast Nuclear Energy Co (subs of
Northeast Utilities) 83/10/02 Office of Resource Management,
Director 7pp 20836 343 24X Fiche 50-245, 83/10/02, 8310200129

Reportable occurrences, LERs & related correspondence

8310180336 Updated LER 82-029/03X-1 on 821207, levels of five water storage tanks A & B found below Tech Spec limits Caused by stripped gear in make-up valve operator A & sticking brake & binding valve in motor operator B W/830631 ltr
THULL, T. B., MRDCZKA, E. J. Northeast Utilities MRDCZKA, E. J. Northeast Nuclear Energy Co (subs of Northeast Utilities)
83/08/31 MURLEY, T. E. Region 1, Office of Director 4pp,
20802 394 24X Fiche 50-245, 83/08/31, 8310180336

8310070163 Part 21 rept re potential defects in molded case of 100-amp frame, multi-pole E & HE series circuit breakers
Initially reported on 830902
ERHARDT, J. V., Gould, Inc 83/09/26 MURLEY, T. E. Region 1, Office of Director 10pp, 20699 095 24X Fiche 50-000, 83/09/26, 8310070163

8310250263 LER 83-027/03L-0 on 830829 & 0926, time delay relay 595-117A tripped at 14 & 15 s, respectively Caused by instrument drift Relay reset W/830928 ltr
THULL, T. B., MRDCZKA, E. J. Northeast Utilities MRDCZKA, E. J. Northeast Nuclear Energy Co (subs of Northeast Utilities)
83/09/28 MURLEY, T. E. Region 1, Office of Director 3pp
20898 232 24X Fiche 50-245, 83/09/28, 8310250263

8310070301 Potential Part 21 rept re underdrange characteristic of Model N-E110M transmitter Underdrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN, M. J. Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20631 064 24X
Fiche 50-000, 83/09/30, 8310070301

DOCKET 50-247 INDIAN POINT STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8310040228 Forwards Suppl 1 to "Evaluation of Indian Point 2 Fire Protection Program," per 830110 commitment, in response to 820810 ltr Addl exemptions requested from requirements of 10CFR50.48 & App R
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc 83/07/13
EISENHUT, D. G. Division of Licensing 2pp 20612 175 24X
Fiche 50-247, 83/07/13, 8310040228

--8310040225 Suppl 1 to "Evaluation of Indian Point 2 Fire Protection Program"
* TERA Corp 83/06/30 50pp 20612 177 24X
Fiche 50-247, 83/07/13, 8310040228

8310050548 Forwards post-exercise/post-drill assessment, per J5 Brail 830608 commitment Previously noted deficiencies corrected
MCLUGHLIN, D. Federal Emergency Management Agency 83/09/14
DIRCKS, W. J. Office of the Executive Director for Operations 2pp
20629 267 24X Fiche 50-003, 83/09/29, 8310050548

--8310050552 Post-exercise assessment of 830824-25 exercise, Rockland County, for Indian Point Nuclear Power Station
* Federal Emergency Management Agency 83/09/24 56pp
20629 269 24X Fiche 50-003, 83/09/29, 8310050552

--8310050554 Post-drill assessment of 830823 drill of Westchester Co., bus evacuation procedures for Indian Point Nuclear Power Station
* Federal Emergency Management Agency 83/09/15 5pp
20629 328 24X Fiche 50-003, 83/09/29, 8310050554

8310130111 Forwards application for amend to Licenses DPR-5 & DPR-26 incorporating changes to facility organization structure re position of fire protection & safety administrator
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc 83/09/29
VARGA, S. A. Operating Reactors Branch 1 2pp 20726 294 24X
Fiche 50-003, 83/09/29, 8310130111

--8310130115 Application for amend to Licenses DPR-5 & DPR-26 incorporating changes to facility organization structure re position of fire protection & safety administrator
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc 83/09/29
2pp 20726 296 24X Fiche 50-003, 83/09/29, 8310130115

--8310130119 Proposed Tech Spec incorporating changes to facility organization structure re fire protection & safety administrator
* Consolidated Edison Co. of New York, Inc 83/09/29 10pp
20726 298 24X Fiche 50-003, 83/09/29, 8310130119

8310130305 Forwards FEMA 830929 ltr transmitting FEMA Region II post-exercise assessment of 830824 exercise of State of NY radiological emergency response interim plan for implementing compensating measures for Rockland County
HASSELL, D. F. Hearing Branch 1 83/10/04 GLEASON, O. P.,
PARRIS, O. H., SHON, F. J. Atomic Safety and Licensing Board Panel 1p
20719 204 24X Fiche 50-247, 83/10/04, 8310130305

8310170321 Staff requirements memo re Commission 831003 briefing by FEMA on recent emergency planning exercises in vicinity of facilities Commission noted successful completion of exercise Enforcement action unnecessary
CHILK, S. J. Office of the Secretary of the Commission 83/10/11
Office of the Secretary of the Commission 1p 20795 277 24X
Fiche 50-247, 83/10/11, 8310170321

8310260304 Forwards memo to physical security plan, per 821109 request Memo withheld (ref 10CFR2 790 & 10CFR73.21)
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc 83/10/14
VARGA, S. A. Operating Reactors Branch 1 2pp 20910 324 24X
Fiche 50-003, 83/10/14, 8310260304

8310280253 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records 83/10/25 Document
Management Branch 1p 20962 318 24X Fiche 50-003, 83/10/25, 8310280253

--8310280261 Forwards public version of revised emergency plan implementing procedures, including Procedures IP-1002 re emergency notification & communication & IP-1023 re operational support ctr
O'TOOLE, J. D., GAUNY, R. D. Consolidated Edison Co. of New York, Inc 83/05/06
ALLAN, J. M. Region 1, Office of Director 3pp
20962 319 24X Fiche 50-003, 83/10/25, 8310280261

--8310280267 Public version of revised emergency plan implementing procedures, including Procedures IP-1002 re emergency notification & communication & IP-1023 re operational support ctr
* Consolidated Edison Co. of New York, Inc 83/05/02 56pp
20962 322 24X Fiche 50-003, 83/10/25, 8310280267

DOCKETED ITEMS

3

G Adjudicatory correspondence

8310130305 Forwards FEMA B30929 ltr transmitting FEMA Region 11 post-exercise assessment of B30824 exercise of State of NY radiological emergency response interim plan for implementing compensating measures for Rockland County HASSELL, D F Hearing Branch 1 83/10/04 GLEASON, O P, PARRIS, O H, SHON, F J Atomic Safety and Licensing Board Panel 1p 20719 204 24X Fiche 50-247, 83/10/04, 8310130305

8310180145 Advises that SM Bohinski & JF Meyer employed as legal & technical assistants, respectively Bohinski & Meyer under refusal re Indian Point special proceeding due to previous employment contact BERNTHAL, F Commissioners 83/10/17 Atomic Safety and Licensing Board Panel 1p 20809 169 24X Fiche 50-247, 83/10/17, 8310180145

8310190085 Order advising that ASLB expects to issue recommendations to Commission by 831024 GLEASON, J P Atomic Safety and Licensing Board Panel 83/10/17 1p 20822 267 24X Fiche 50-247, 83/10/17, 8310190085

8310240187 Forwards RH Bogardus B30920 ltr re adequacy of radiological emergency response plan HERBEK, R New York, State of 83/10/17 NRC - No Detailed Affiliation Given 3pp 20878 089 24X Fiche 50-247, 83/10/17, 8310240187

8310260224 Opinion & recommendations to Commission on societal significance of risk estimates ASLB recommended safety improvements necessary to ensure plant will be operated w/ reasonable assurance that public safety will be protected SHON, F J, PARRIS, O H, GLEASON, J P Atomic Safety and Licensing Board Panel 83/10/24 506pp 20913 033 24X Fiche 50-247, 83/10/24, 8310260224

8310270307 Errata correcting Pages 3 & 436 of ASLB 831074 recommendations to Commission GLEASON, J P Atomic Safety and Licensing Board Panel 83/10/25 1p 20923 192 24X Fiche 50-247, 83/10/25, 8310270307

P Operating license stage documents & correspondence

8310120242 Forwards identification & listing of electrical equipment important to safety, per 10CFR50.49 & schedule for either qualification or replacement of unqualified equipment Response to B30502 request for clarification also encl O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/05/20 VARGA, S A Operating Reactors Branch 1 2pp 20692 124 24X Fiche 50-247, 83/05/20, 8310120242

--8310120243 "Identification & Listing of Electrical Equipment Important to Safety, Per 10CFR50.49" * Consolidated Edison Co of New York, Inc 83/05/20 35pp 20692 126 24X Fiche 50-247, 83/05/20, 8310120242

8310120277 Forwards addl justifications for continued operation for specific items of unqualified equipment in response to B30502 request for clarification of environ qualification O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/06/09 VARGA, S A Operating Reactors Branch 1 9pp 20692 115 24X Fiche 50-247, 83/06/09, 8310120277

8310050148 Forwards safety evaluation re NUREG-0737, Item II K 3 2 & Westinghouse Owners Group Rept WCAP-9804 based on results encl in Franklin Research Ctr technical evaluation rept Automatic PORV isolation sys not required VARGA, S A Operating Reactors Branch 1 83/09/13 O'TOOLE, J D Consolidated Edison Co of New York, Inc 14pp 20639 100 24X Fiche 50-247, 83/09/13, 8310050148

8310110460 Forwards safety evaluation re util responses to NUREG 0737, Item II 1 1 4, "Containment Pressure Monitor," Item II F 1 5, "Containment Water Level Monitor" & Item II F 1 6, "Containment Hydrogen Monitor" Items resolved VARGA, S A Operating Reactors Branch 1 83/09/21 O'TOOLE, J D Consolidated Edison Co of New York, Inc 10pp 20707 393 24X Fiche 50-247, 83/09/21, 8310110460

8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class 1 piping sys Info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway EISENHUT, D G Division of Licensing 83/09/29 PALLADINO, N J, GILINSKY, V, ROBERTS, T Commissioners 3pp 20632 001 24X Fiche 50-000, 83/09/29, 8308300357

--8310050538 "Interaction Between Piping & Pipe Clamps" Distribution lists encl TERAD, D Division of Engineering 83/08/31 83pp 20632 004 24X Fiche 50-247, 83/09/29, 8308300357

8310130111 Forwards application for amend to Licenses DPN-5 & DPN-24 incorporating changes to facility organization structure re position of fire protection & safety administrator O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/09/29 VARGA, S A Operating Reactors Branch 1 2pp 20726 294 24X Fiche 50-003, 83/09/29, 8310130111

--8310130115 Application for amend to Licenses DPN-5 & DPN-24 incorporating changes to facility organization structure re position of fire protection & safety administrator O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/09/29 2pp 20726 296 24X Fiche 50-003, 83/09/29, 8310130111

--8310130119 Proposed Tech Spec incorporating changes to facility organization structure re fire protection & safety administrator * Consolidated Edison Co of New York, Inc 83/09/29 10pp 20726 298 24X Fiche 50-003, 83/09/29, 8310130111

8310180579 Forwards safety evaluation supporting completion of generic issues re containment venting & purging (Multi-plant Action B-24) & NUREG-0737, Item II E 4 2 VARGA, S A Operating Reactors Branch 1 83/09/29 O'TOOLE, J D Consolidated Edison Co of New York, Inc 14pp 20824 301 24X Fiche 50-247, 83/09/29, 8310180579

8310120194 Forwards addl info on NUREG-0737, Item II K 3 17, "Rept on Outages of ECCS", per B30829 telcon & NRC B30819 ltr Addl data factored into probabilistic safety study submitted on 830305 O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/09/30 VARGA, S A Operating Reactors Branch 1 5pp 20696 090 24X Fiche 50-247, 83/09/30, 8310120194

8308300763 Board Notification 83-151 provides info re desirability of current ECCS actuation logic for Westinghouse plants, in light of recent info concerning steam generator tube rupture procedure for Borssele Nuclear Power Station EISENHUT, D G Division of Licensing 83/10/04 PALLADINO, N J, GILINSKY, V, ROBERTS, T Commissioners 2pp 20698 033 24X Fiche 50-000, 83/10/04, 8308300763

--8310110574 Requests board notification be issued re rev to ECCS actuation logic of pre-TMI accident configuration in Borssele Nuclear Power Plant Westinghouse Owners Group will be requested to evaluate benefits of rev W/O encl MATTHEWS, R J Division of Systems Integration (post 811005) 83/09/26 EISENHUT, D G Division of Licensing 17pp 67005 190 24X Fiche 50-000, 83/10/04, 8308300763

8310120366 Requests 6-month extension to 840506 for submittal of summary technical rept re matl surveillance programs per 10CFR50, App H Reactor vessel surveillance capsule withdrawn on 821106 O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/10/04 VARGA, S A Operating Reactors Branch 1 1p 20699 102 24X Fiche 50-247, 83/10/04, 8310120366

8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves EISENHUT, D G Division of Licensing 83/10/06 PALLADINO, N J Commissioners 31pp 20818 001 24X Fiche 50-000, 83/10/06, 8308300771

8310270602 Informs that requirements of NUREG-0737, Item II K 3 17, "Rept on Outages of ECCS," met Review of item complete VARGA, S A Operating Reactors Branch 1 83/10/19 O'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp 20746 259 24X Fiche 50-247, 83/10/19, 8310270602

G Inspection reports, IE Bulletins & correspondence

8310030158 Notifies that QA program description review insp resched for 831003, per B30823 & 26 telcon requests MARTIN, T T Division of Engineering & Technical Programs 83/09 O'TOOLE, J D Consolidated Edison Co of New York, Inc 1p 20590 029 24X Fiche 50-247, 83/09/12, 8310030158

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Weld Qualification Tests" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineer Response (Post 830103) 83/09/26 Consolidated Edison York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26,

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300341

DOCKETED ITEMS

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTU Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/11, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

S Reportable occurrences, LERs & related correspondence

8310190143 LER 83-033/03L-0 on 830828, while in hot shutdown, MSIV for loop 21 failed to completely close during isolation of secondary plant for maint caused by insufficient lubrication of valve stem packing Stem packing lubricated W/830927 ltr
BIDDLE, J D Consolidated Edison Co of New York, Inc 83/09/27
MURLEY, T E Region 1, Office of Director 2pp 20821 056 24X Fiche 50-247, 83/09/27, 8310190143

710070301 Potential Part 21 rept re underrange characteristic of Model N-ELIOM transmitter underrange zero offset may occur when transmitter initially pressurized from atmospheric to depressed zero input End users notified
ERBERIAN, H J Fairboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X Fiche 50-000, 83/09/30, 8310070301

0120124 PNO-1-83-103 on 831004, licensee commenced 4-day outage to repair moisture separator reheater tube leaks Leaks indicated in four of six reheaters Unit will be maintained in hot shutdown Cooling fan motors replaced
KENNY, T KISTER, H Region 1, Office of Director 83/10/05 1p 20696 154 24X Fiche 50-247, 83/10/05, 8310120124

110280094 RO on 831004, 138-kV station auxiliary power supply lost when pilot wire receiver relay tripped Cause under investigation Supply reestablished to all 6 9-kV buses Also reported per Part 21
JACKSON, C W Consolidated Edison Co of New York, Inc 83/10/05
MURLEY, T E Region 1, Office of Director 1p 20935 065 24X Fiche 50-247, 83/10/05, 8310280094

10140082 PNO-1-83-105 on 831007, seismic event occurred in northeastern US w/magnitude of 5.2 on Richter scale in NY & 4.0 in NH No damage to equipment identified
GALLLO, R M Region 1, Office of Director 83/10/07 1p 20766 116 24X Fiche 50-000, 83/10/07, 8310140082

8310170310 PNO-1-83-103A on 831004, licensee began unscheduled outage to repair moisture separator reheater tube leaks NRC notified on 831011 of reactor coolant leak on steam generator 22 hot leg Manway Plant will be in cold shutdown for repairs
FOLEY, T JACOBBS, R NORRHOHL, L Region 1, Office of Director 83/10/12 1p 20786 151 24X Fiche 50-247, 83/10/12, 8310170310

810200165 Part 21 rept re static temp calibr check on transmitters Initially reported on 831013 Caused by irregular setpoint for pressurizer pressure safety injection function New 1,824 pig setpoint recommended
RAHE, E P Westinghouse Electric Corp 83/10/13 DELYONG, R C Director's Office, Office of Inspection and Enforcement 2pp 20834 078 24X Fiche 50-000, 83/10/13, 8310200165

T Hearing transcripts on non-antitrust matters

8310120029 Transcript of 831003 open session in Washington, DC re emergency planning Pg 1-28 Supporting documentation encl
Commissioners 83/10/03 111pp 20750 076 24X Fiche 50-003, 83/10/03, 8310120029

DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8310040121 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/09/22 Document Management Branch 1p 20634 341 24X Fiche 50-010, 83/09/22, 8310040121

--8310040136 Public version of Rev C to Emergency Plan Implementing Procedure EPIP 300-14, "Radiation Surveys Under Accident Conditions " W/830913 ltr, receipt form, procedure history & safety evaluation
SCOTT, D J Commonwealth Edison Co 83/09/09 10pp 20674 347 24X Fiche 50-010, 83/09/22, 8310040136

8310140262 Forwards IE Insp Repts 50-237/83-28 & 50-249/83-26 on 830913-14 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 83/09/30 NED, C Commonwealth Edison Co 2pp 20761 295 24X Fiche 50-237, 83/09/30, 8310140262

--8310140267 IE Insp Repts 50-237/83-28 & 50-249/83-26 on 830913-14, noncompliance noted Major areas inspected emergency preparedness exercise
FLOSKI, T KERS, L PHILLIPS, M Region 3, Office of Director 83/09/30 10pp 20761 297 24X Fiche 50-237, 83/09/30, 8310140267

8310270009 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20940 167 24X Fiche 50-010, 83/10/21, 8310270009

--8310270017 Public version of Rev 5 to Emergency Plan Implementing Procedure EPIP 300-1, "Initial Notifications & Generating Station Emergency Plan Responses (Primary Responsibility Station Director) " W/831014 ltr
SCOTT, D J Commonwealth Edison Co 83/10/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 20pp 20940 140 24X Fiche 50-010, 83/10/21, 8310270009

8310270526 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20937 216 24X Fiche 50-000, 83/10/21, 8310270526

--8310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure EDF-6, "Administration & Logistics Manager " W/831017 ltr & receipt form
NELLIS, C A HESSNER, R MOORE, R D Commonwealth Edison Co 83/02/18 DENTON, H R NRC - No Detailed Affiliation Given 4p 20937 217 24X Fiche 50-000, 83/10/21, 8310270526

8310280307 Releases public version of revised generating stations emergency plan telephone directory
FELTON, J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20963 126 24X Fiche 50-000, 83/10/25, 8310280307

--8310280314 Public version of revised generating stations emergency plan telephone directory
GALLE, D F MOORE, R D Commonwealth Edison Co 83/08/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 4p 20963 127 24X Fiche 50-000, 83/10/25, 8310280307

8310280191 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/26 Document Management Branch 1p 20962 266 24X Fiche 50-000, 83/10/26, 8310280191

--8310280209 Public version of Rev 1 to Emergency Plan Implementing Procedure EDF-13, "Emergency Operations Facility Activation " MOORE, R D Commonwealth Edison Co 83/08/02 50pp 20962 267 24X Fiche 50-000, 83/10/26, 8310280191

DOCKETED ITEMS

41

G Adjudicatory correspondence

8310070156 Forwards Director's Decision 83-14, denying 830909 10CFR2 206 petition re transport of spent nuclear fuel from West Valley
DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director
83/09/30 CELEBREZZE, A J Ohio, State of 2pp 20680 308 24X
Fiche 50-000, 83/09/30, 8310070156

--8310070161 Forwards Director's Decision 83-14, denying 830824 10CFR2 206 petition re transport of spent nuclear fuel from West Valley
DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director
83/09/30 REBNIKOFF, M Sierra Club 1p
20680 309 24X Fiche 50-000, 83/09/30, 8310070156

--8310070167 Notice of issuance of Director's Decision 83-14, denying State of OH & Sierra Club 830909 & 0824, respectively, 10CFR2 206 petitions re transport of spent nuclear fuel from West Valley
DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director
83/09/30 2pp 20680 310 24X
Fiche 50-000, 83/09/30, 8310070156

--8310070171 Director's Decision 83-14, denying State of OH & Sierra Club 830909 & 0824, respectively, 10CFR2 206 petitions re transport of spent nuclear fuel from West Valley Request for hearing & for preparation of LIS denied
DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director
83/09/30 18pp 20680 312 24X
Fiche 50-000, 83/09/30, 8310070156

8310270297 Order extending time until 831128 for Commission to act to review Director's Decision 83-14, denying Sierra Club & State of OH requests
CHILK, S J Office of the Secretary of the Commission
83/10/25 Commissioners 1p 20923 195 24X Fiche 50-000, 83/10/25, 8310270297

P Operating license stage documents & correspondence

8310040320 Commits to formal submittal of proposed radiological ETS amend by 840106
RYBAK, B Commonwealth Edison Co 83/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20620 218 24X
Fiche 50-237, 83/09/28, 8310040320

8310070264 Forwards proprietary "Dresden 2/3 Nuclear Generating Plant Suppression Pool Temp Response," "EI Hatch Nuclear Power Station Units 1 & 2 Suppression Pool Temp Response" & Mark I 830825 meeting viewgraphs Repts withheld (ref 10CFR2 790)
PFEEFERLE, H C General Electric Co 83/09/30, VASSALLO, D B Operating Reactors Branch 2 61pp 20811 292 24X
Fiche 50-000, 83/09/30, 8310070264

8310050524 Forwards SER re util response to NUREG-0737, Item II B 1, "RCS Vents" Item complete
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/03 FARRAR, D L Commonwealth Edison Co 6pp 20632 335 24X Fiche 50-237, 83/10/03, 8310050524

--8310050534 "Selected Operating Reactor Issues Program II, RCS Vents (NUREG-0737, Item II B 1), Final technical evaluation rept for Dresden Units 2 & 3
HELD, J Y Lawrence Livermore Laboratory FIN A-0250
TF-380/0823A 83/04/06 ALBERTHAL, G NRC - No Detailed Affiliation Given 4pp 20632 341 24X Fiche 50-237, 83/10/03, 8310050524

8310200273 Forwards schedules for equipment qualification test programs for facilities, per 810528 ltr Dates given for current qualification activities should be viewed as "target-dates" & not as firm dates
BARNES, P L Commonwealth Edison Co 83/10/05 KEPPLER, J G Region 3, Office of Director 10pp 20830 034 24X Fiche 50-000, 83/10/05, 8310200273

8310120303 Notifies that monthly publication of FR notices will be provided w/o transmittal ltr
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/07 FARRAR, D L Commonwealth Edison Co 2pp 20690 336 24X Fiche 50-237, 83/10/07, 8310120303

8310260001 Forwards addl info requested in NRC 830316 ltr re util response to SER Topic III-4 A, "Tornado Missiles" Cooling water to HXs is supplied from svc water sys which is independent from condensate storage tank
RYBAK, B Commonwealth Edison Co 83/10/18 QILBERT, R Operating Reactors Branch 5 18pp 20912 206 24X Fiche 50-010, 83/10/18, 8310260001

8310280147 Forwards 830930 Director's Decision 83-14, denying State of OH & Sierra Club 10CFR2 206 petitions re transportation of spent fuel from West Valley Facility, per 830930 request
CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 83/10/18 MILLER, F Environmental Policy Institute 2pp 20961 329 24X
Fiche 50-000, 83/10/18, 8310280147

8310250188 Forwards Amends 76 & 67 to Licenses DPR-19 & DPR-25, respectively & safety evaluation Amend changes Tech Specs re operability requirements for ECCS ring header snubbers
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/21 FARRAR, D L Commonwealth Edison Co 2pp 20893 344 24X Fiche 50-237, 83/10/21, 8310250188

--8310250195 Amends 76 & 67 to Licenses DPR-19 & DPR-25, respectively, changing Tech Specs re operability requirements for ECCS ring header snubbers, per 830613 application
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/21 14pp 20893 346 24X Fiche 50-237, 83/10/21, 8310250188

--8310250200 Safety evaluation supporting Amends 76 & 67 to Licenses DPR-19 & DPR-25, respectively
* Office of Nuclear Reactor Regulation, Director 83/10/21 2pp, 20893 360 24X Fiche 50-237, 83/10/21, 8310250188

8310310052 Denies 830702 request for extension to submit formal response to Generic Ltr 83-28 re Salem ATWS event Info must be submitted by 831105 Participation in owners group for issues requiring long-range planning acceptable
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/26 FARRAR, D L Commonwealth Edison Co 3pp 20951 046, 24X Fiche 50-237, 83/10/26, 8310310052

G Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310140262 Forwards IE Insp Repts 50-237/83-28 & 50-249/83-26 on 830913-16 No noncompliance noted.
PAPERIELLO, C J Region 3, Office of Director 83/09/30 REED, C Commonwealth Edison Co 2pp 20761 295 24X Fiche 50-237, 83/09/30, 8310140262

--8310140267 IE Insp Repts 50-237/83-28 & 50-249/83-26 on 830913-16, No noncompliance noted Major areas inspected emergency preparedness exercise
PLOSKE, T, QLOERSEN, W, SNELL, W Region 3, Office of Director, 83/09/30 10pp 20761 297 24X Fiche 50-237, 83/09/30, 8310140262

8310200124 Forwards IE Mgt Meeting Repts 50-010/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIOUS, C E Division of Project & Resident Programs 83/10/04, REED, C, Commonwealth Edison Co 2pp 20834 098 24X
Fiche 50-000, 83/10/04, 8310200124

--8310200148 IE Mgt Meeting Repts 50-020/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIOUS, C E Division of Project & Resident Programs, DAVIS, A. B, Region 3, Office of Director 83/10/03 4pp 20834 100 24X
Fiche 50-000, 83/10/04, 8310200124

DOCKETED ITEMS

8310110140 Discusses concerns re licensee actions following failure of certain ECCS/containment isolation valves, per review of info in LER 83-006/OIT-O & IE Insp Repts 50-237/83-07 & 50-249/83-06 License amend application requested
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/05 FARRAR, D L
Commonwealth Edison Co 5pp 20666 293 24X Fiche 50-237, 83/10/05, 8310110140

8310170337 Submits status of as-built reviews of safe shutdown piping supports for IE Bulletin 79-14 As result of review of Quad Cities, two piping sys found to have addl discrepancies
Seven new hangers added
RYBAK, B Commonwealth Edison Co 83/10/06 KEPLER, J G Region 3, Office of Director 2pp 20786 155 24X Fiche 50-000, 83/10/06, 8310170337

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8310210053 Forwards IE Insp Repts 50-010/83-17, 50-237/83-26 & 50-249/83-24 on 830829-31, 0901, 02 & 08 & notice of violation
PAPERIELLO, C J Region 3, Office of Director 83/10/07 REED, C Commonwealth Edison Co 2pp 20855 286 24X Fiche 50-010, 83/10/07, 8310210053

--8310210061 Notice of violation from insp on 830829-31, 0901, 02 & 08
PAPERIELLO, C J Region 3, Office of Director 83/10/07 2pp 20855 288 24X Fiche 50-010, 83/10/07, 8310210053

--8310210074 IE Insp Repts 50-010/83-17, 50-237/83-26 & 50-249/83-24 on 830829-31, 0901, 02 & 08 Noncompliance noted inadequate calibr of D-1 & D-2/3 chimney monitors & failure to follow procedures re radiation protection
PAUL, R A, KREIER, L J, GREGER, L R Region 3, Office of Director 83/10/07 8pp 20855 290 24X Fiche 50-010, 83/10/07, 8310210053

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

0140036 Ack receipt of 830922 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/83-09, 50-237/83-14 & 50-249/83-13
NORELIUS, C Division of Project & Resident Programs 83/10/11 REED, C Commonwealth Edison Co 1p 20767 341 24X Fiche 50-010, 83/10/11, 8310140036

--8310140049 Responds to NRC 830823 ltr re violations noted in IE Insp Repts 50-010/83-09, 50-237/83-14 & 50-249/83-13 Corrective actions operations personnel closed & latched all battery charger cabinets
FARRAR, D L Commonwealth Edison Co 83/09/22 KEPLER, J G Region 3, Office of Director 5pp 20767 342 24X Fiche 50-010, 83/10/11, 8310140036

310140099 Ack receipt of 830916 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/83-12, 50-237/83-20 & 50-249/83-18
NORELIUS, C Division of Project & Resident Programs 83/10/11 REED, C Commonwealth Edison Co 1p 20766 099 24X Fiche 50-010, 83/10/11, 8310140099

--8310140104 Responds to NRC 830721 ltr re violations noted in IE Insp Repts 50-010/83-12, 50-237/83-20 & 50-249/83-18 Corrective actions scope & general method of training program completely detailed in training procedures
FARRAR, D L Commonwealth Edison Co 83/09/16 KEPLER, J G Region 3, Office of Director 8pp 20766 100 24X Fiche 50-010, 83/10/11, 8310140099

8310180268 Clarifies NRC position re procedures for admitting NRC personnel to facilities Access should be afforded to Region III personnel listed in encl Update will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 REED, C Commonwealth Edison Co 7pp 20802 302 24X Fiche 50-010, 83/10/14, 8310180268

R Periodic operating reports & related correspondence

8310120273 Monthly operating repts for Sept 1983 W/831003 ltr
SCHROEDER, B A, SCOTT, D J Commonwealth Edison Co 83/10/03 Director's Office, Office of Inspection and Enforcement 16pp 20693 081 24X Fiche 50-237, 83/10/03, 8310120273

S Reportable occurrences, LERs & related correspondence

8310260096 Describes facility 821203 flood & corrective actions taken
Chronology of events encl, including notification of event & procedure for briefing commissioner assistants
PERKINS, K E NRC - No Detailed Affiliation Given 83/06/08
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 11pp 20921 136 24Y Fiche 50-010, 83/06/23, 8310260096

8310110430 Responds to FOIA request for four different categories of documents described in 830510 ltr Forwards matl listed in App A, responsive to Items 1, 2 & 4 NDE should be contacted for matl requested in Item 3 of ltr
FELTON, J M Division of Rules and Records 83/06/14 HIATT, B I Ohio Citizens for Responsible Energy 3pp 20706 002 24X Fiche 50-000, 83/06/14, 8310110430

--8310110478 Responds to 830413 ltr requesting info re use of foreign matls on valve seating surfaces Lubricants & cleaning solvents used on valve component surfaces per vendor recommendations & maint practices
FARRAR, D L Commonwealth Edison Co 83/04/22 KEPLER, J G Region 3, Office of Director 4pp 20706 063 24X Fiche 50-000, 83/06/14, 8310110430

8310260008 Addl response to FOIA request for 17 categories of records
Forwards documents listed in Apps B, C & D Info re fraudulent practices of Ray Miller, Inc available in PDR
FELTON, J M Division of Rules and Records 83/06/23 CLCHETT, J Public Citizen Litigation Group 15pp 20920 001 24X Fiche 50-000, 83/06/23, 8310260008

8310070301 Potential Part 21 rept re underrange characteristic of Model N-EIGH transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X Fiche 50-000, 83/09/30, 8310070301

8310110140 Discusses concerns re licensee actions following failure of certain ECCS/containment isolation valves, per review of info in LER 83-006/OIT-O & IE Insp Repts 50-237/83-07 & 50-249/83-06 License amend application requested
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/05 FARRAR, D L Commonwealth Edison Co 5pp 20666 293 24X Fiche 50-237, 83/10/05, 8310110140

8310120309 PNO-111-83-093 on 830930, facility shut down for scheduled refueling outage Licensee expected to conduct ultrasonic testing of large diameter stainless steel pipe in drywell, per NRC order Insp will continue for 16 wks
TONGUE, T, WALKER, R Region 3, Office of Director 83/10/05 1p 20701 009 24X Fiche 50-249, 83/10/05, 8310120309

8310210165 LER 83-035/OIT-O on 831004, during drywell insp, water observed leaking from recirculation pump bowl drain A
Caused by 2-inch crack on tee Affected piping will be cut out isolation valves & tee will be replaced W/831013 ltr
MERRITT, S, SCOTT, D J Commonwealth Edison Co 83/10/13 KEPLER, J G Region 3, Office of Director 4pp 20856 090 24X Fiche 50-249, 83/10/13, 8310210165

8310270477 LER 83-032/O3L-O on 830921, valve LPCI 1501-11B closed during installation of terminal jumper Caused by technician inadvertently placing terminal jumper on 903-3 panel instead of 903-10 panel W/831019 ltr
CHRISTEL, B, SCOTT, D J Commonwealth Edison Co 83/10/18 KEPLER, J G Region 3, Office of Director 3pp 20922 013 24X Fiche 50-249, 83/10/18, 8310270477

DOCKETED ITEMS

43

10270424 LER 83-034/03L-0 on 830723, during normal operation, mobile crane hit wet pipe sprinkler drain valve, breaking valve & spraying water on trackway caused by personnel error Valve repaired Personnel counseled W/831019 ltr
MERRITT, S., SCOTT, D J Commonwealth Edison Co 83/10/19
KEPPLER, J Q Region 3, Office of Director 3pp 20923 108 24X
Fiche 50-249, 83/10/17, 8310270424

KET 50-250 TURKEY POINT PLANT, UNIT 3

Security, medical, emergency & fire protection plans

0040145 Forwards supplemental info re 10CFR50, App R re fire protection, per 830408 submittal thermal fixed temp & rate of rise fire detection will be provided in auxiliary feedwater control valve (Fire Zones 113 & 116) areas
UHRIG, R E Florida Power & Light Co 83/09/30 VARGA, S A Operating Reactors Branch 1 2pp 20608 024 24X
Fiche 50-250, 83/09/30, 8310040145

0170240 Forwards "Alternate Shutdown Capability Rept 10CFR50, App R, Section III L for Turkey Point Units 3 & 4 " Site visit will be arranged for NRC reviewers upon request
UHRIG, R E Florida Power & Light Co 83/10/07 EISENHUT, D O Division of Licensing 2pp 20790 309 24X Fiche 50-250, 83/10/07, 8310170240

310170244 "Alternate Shutdown Capability Rept 10CFR50, App R, Section III L for Turkey Point Units 3 & 4 " W/20 oversize figures Aperture cards are available in PDR
Bechtel Corp 83/10/07 5pp 20790 311 24X
Fiche 50-250, 83/10/07, 8310170240

3270365 Forwards corrected Page 3 of IE Safeguards Insp Repts 50-250/83-28 & 50-251/83-28 re protected area intrusion detection sys Encl withheld (ref 10CFR73 P1)
DANCE, H C Division of Project & Resident Programs 83/10/18 UHRIG, R E Florida Power & Light Co 1p 20924 007 24X
Fiche 50-250, 83/10/18, 8310270365

judicatory correspondence

130164 Forwards status rept on hybrid hearing procedures under section 134 of Nuclear Waste Policy Act Proposed rule on implementation of procedures awaits Commission action
MININGHAM, G H Office of the Executive Legal Director 83/10/07 HUNT, A Office of the Executive Director for Operations 2pp 724 291 24X Fiche 50-000, 83/10/07, 8310130164

general correspondence

180298 Responds to 830926 request to be added to svc list re proposed spent fuel pool expansion & criteria for svc list request to be added to svc list denied Notification re preliminary NSMC will be provided
DONALD, D O Operating Reactors Branch 1 83/10/12 LORION, J iter for Nuclear Responsibility 1p 20826 357 24X
Fiche 50-250, 83/10/12, 8310180298

operating license stage documents & correspondence

10530 "Assessment of Radiation Risks," util-medical dialogue sent at 800922-23 Intl Inst of Safety & Health um in Washington, DC
P, R E International Institute of Safety & Health 80/09/23 p 20714 161 24X Fiche 50-000, 80/09/23, 831010530

10017 FOIA request for documents re integrated leak rate tests for ted facilities to be placed in PDR
NER, L Affiliation Unknown 83/05/02 NRC - No Detailed ikation Given 1p 21004 270 24X Fiche: 50-000, 83/05/02, 8310017

10031 Responds to FOIA request for documents re integrated leak tests for facilities to be placed in PDR Forwards ments to be place in PDR & list of facilities for which s are unavailable
ON, J M Division of Rules and Records 83/07/06 CONNER, L ikation Unknown, 1p 21004 271 24X Fiche 50-000, 83/07/06, 8310031

310067 "Reactor Containment Bldg Integrated Leak Rate Test," mmary technical rept
MAN, W D Ebasco Services, Inc (subs of Enserch Corp.) /02/14 56pp 21006, 063 24X Fiche 50-000, 83/07/06, 8310310031

310068 Operating Procedure 13100 L, "Integrated Leak Rate Test " MAN, W D Ebasco Services, Inc (subs of Enserch Corp.) /11/01 200pp 21006 159 24X Fiche 50-000, 83/07/06, 10310031

--8310310070 "Containment Leak Rate Tests," Type B & C test repts
* Florida Power & Light Co 76/02/14 9pp 21006 325 24X
Fiche 50-000, 83/07/06, 8310310031

8310030659 Requests site visit to continue review of 821027 & 830307 requests for rev to inservice test program for pumps & valves Encl questions & comments will serve as agenda
VARGA, S A Operating Reactors Branch 1 83/09/20 UHRIG, R E Florida Power & Light Co 9pp 20626 342 24X
Fiche 50-250, 83/09/20, 8310030659

831010296 Forwards response to NRC concerns discussed in 830815 telcon re Tech Spec changes to F delta H limit Impact of change limited to expected cycle-wide power distribution differences
UHRIG, R E Florida Power & Light Co 83/10/04 EISENHUT, D O Division of Licensing 3pp 20666 075 24X Fiche 50-250, 83/10/04, 831010296

8310130125 Forwards Class II & III amend fees for 830818 request to amend Licenses DPR-31 & DPR-41 re F delta H/FQ
UHRIG, R E Florida Power & Light Co 83/10/06 EISENHUT, D O Division of Licensing 1p 20725 052 24X Fiche 50-250, 83/10/06, 8310130125

8310180324 Forwards revised Tech Spec page re RHR pump operability per 831013 telcon request for addl info concerning proposed license amend
WILLIAMS, J W Florida Power & Light Co 83/10/13 EISENHUT, D O Division of Licensing 3pp 20806 159 24X Fiche 50-250, 83/10/13, 8310180324

--8310180327 Proposed Tech Spec re RHR pump operability
* Florida Power & Light Co 83/10/13 1p 20806 161 24X
Fiche 50-250, 83/10/13, 8310180324

8310240258 Forwards order for mod of Licenses DPR-31 & DPR-41, requiring Tech Spec 3 4 1b be modified, on interim basis, to permit operation in hot shutdown mode while inoperable RHR pump repaired
VARGA, S A Operating Reactors Branch 1 83/10/14 UHRIG, R E Florida Power & Light Co 2pp 20908 003 24X
Fiche 50-250, 83/10/14, 8310240258

--8310240261 Order for mod of Licenses DPR-31 & DPR-41, requiring Tech Spec 3 4 1b be modified, on interim basis, to permit operation in hot shutdown mode while inoperable RHR pump repaired
PURPLE, R A Division of Licensing 83/10/14 Florida Power & Light Co 3pp 20908 005 24X Fiche: 50-250, 83/10/14, 8310240258

--8310240264 Safety evaluation supporting interim Tech Spec mod to permit operation in hot shutdown mode while inoperable RHR pump repaired
* Office of Nuclear Reactor Regulation, Director 83/10/14 3pp, 20908 008 24X Fiche 50-250, 83/10/14, 8310240258

8310270129 Forwards Amends 96 & 90 to Licenses DPR-31 & DPR-41, respectively & safety evaluation Amends add requirements for visual insps & periodic testing of mechanical snubbers
MCDONALD, D O Operating Reactors Branch 1 83/10/14 UHRIG, R E Florida Power & Light Co 2pp 20939 076 24X
Fiche 50-250, 83/10/14, 8310270129

--8310270153 Amends 96 & 90 to Licensee DPR-31 & DPR-41, respectively, adding requirements for visual insps & periodic testing of mechanical snubbers to ensure operability & capability to perform safety-related function
VARGA, S A Operating Reactors Branch 1 83/10/14 25pp 20939 078 24X Fiche 50-250, 83/10/14, 8310270129

--8310270161 Safety evaluation supporting Amends 96 & 90 to Licenses DPR-31 & DPR-41, respectively
* Office of Nuclear Reactor Regulation, Director 83/10/14 5pp, 20939 103 24X Fiche 50-250, 83/10/14, 8310270129

8310210075 Requests remittance of fee due for 830503 application to delete terrestrial & other monitoring programs from Tech Specs within 15 days.
MILLER, W O License Fee Management Branch 83/10/17 UHRIG, R E Florida Power & Light Co 1p 20883 343 24X Fiche 50-250, 83/10/17, 8310210075

Q Inspection reports, IE Bulletins & correspondence

8310040305 Forwards IE Insp Repts 50-250/83-29 & 50-251/83-29 on 830804-05 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/08/30, UHRIG, R E Florida Power & Light Co 2pp, 20612 333 24X
Fiche 50-250, 83/08/30, 8310040305

DOCKETED ITEMS

- 8310040316 IE Insp Repts 50-250/83-29 & 50-251/83-29 on 830804-05 No noncompliance noted Major areas inspected welder concerns re unsatisfactory/unsafe welds
KLEINBORGE, H P Region 2, Office of Director BLAKE, J J
Division of Engineering & Operational Programs 83/08/23 5pp
20612 355 24X Fiche 50-250,83/08/30,8310040305
- 8310040504 Forwards IE Insp Repts 50-250/83-30 & 50-251/83-30 on 830823-26 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/09
UHRIG, R E Florida Power & Light Co 2pp 20622 353 24X
Fiche 50-250,83/09/09,8310040504
- 8310040517 IE Insp Repts 50-250/83-30 & 50-251/83-30 on 830823-26 No noncompliance noted Major areas inspected GC of analytical measurements, mgt & administrative controls, status review of environ monitoring stations & state/NRC split samples
CUNNINGHAM, A L Region 2, Office of Director MONTGOMERY, D M
Division of Engineering & Operational Programs 83/09/07 5pp
20622 355 24X Fiche 50-250,83/09/09,8310040504
- 8310040405 Confirms telcon re 831021 mgt meeting in Miami, FL to discuss results of first phase of SALP review for period Jul 1982 - June 1983 Proposed agenda encl
LEWIS, R C Division of Project & Resident Programs 83/09/22
UHRIG, R E Florida Power & Light Co 2pp 20619 092 24X
Fiche: 50-000,83/09/22,8310040405
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340
- 18300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342
- 8300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 118pp. 20778 001 24X Fiche 50-000,83/09/26,8308300345
- 0050078 Ack receipt of 830909 ltr & payment of civil penalty imposed by NRC on 830815 Corrective actions will be examined during future insp
KELRAH, J A Enforcement Staff 83/09/26 ADDAMAT, E A Florida Power & Light Co 2pp. 20650 187 24X Fiche 50-250,83/09/26,8310050078
- 8300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349
- 0110138 Requests approval to use 1980 Edition & Addenda through Inter 1981 Addenda of ASME Section XI Code, per 10CFR50 53a g1(4)(iv), to extend inservice insp interval due to lengthy team generator repair outages
UHRIG, R E Florida Power & Light Co 83/10/03 EISENHUT, D O
Division of Licensing O'REILLY, J P. Region 2, Office of Director
pp 20665 001. 24X Fiche, 50-250,83/10/03,8310110138
- 8300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass loops Used in Westinghouse Plants," Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 76pp 20827 213 24X Fiche, 50-000,83/10/07,8308300378
- 08300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 79pp. 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8310180381 Supple 830720 response to Generic Ltr 81-07, "Control of Heavy Loads," in response to NRC finding in IE Insp Rept 83-11, dtd 830620, info documents util methodology for compliance w/NUREG-0612 & ANSI N 14.6
UHRIG, R E Florida Power & Light Co 83/10/07 EISENHUT, D O
Division of Licensing. 2pp 20803 201 24X Fiche, 50-250,83/10/07,8310180381
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Malfunction Causes Production of Noxious Gases," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761
- 8310250426 Ack receipt of 830720 & 0922 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/83-19 & 50-251/83-19
LEWIS, R C Division of Project & Resident Programs 83/10/11
UHRIG, R E Florida Power & Light Co 1p 20897 006 24X
Fiche 50-250,83/10/11,8310250426
- 8310250431 Updates 830720 response to NRC 830620 ltr re violations noted in IE Insp Repts 50-250/83-19 & 50-251/83-19
Corrective actions Quality Procedure 16.1 revised to address requirements for audit responses in GP 18.1
UHRIG, R E Florida Power & Light Co 83/09/22 O'REILLY, J P
Region 2, Office of Director 1p 20897 007 24X
Fiche 50-250,83/10/11,8310250431
- 8310250437 Responds to NRC 830620 ltr re violations noted in IE Insp Repts 50-250/83-19 & 50-251/83-19
Corrective actions GC personnel responsible for preparing audits instructed to list dates & responsible personnel for all commitments
UHRIG, R E Florida Power & Light Co 83/07/20 O'REILLY, J P
Region 2, Office of Director 3pp 20897 008 24X
Fiche 50-250,83/10/11,8310250437
- 8310250442 Forwards IE Insp Repts 50-250/83-19 & 50-251/83-19 on 830916-20 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/06/20
UHRIG, R E Florida Power & Light Co 2pp 20897 011 24X
Fiche 50-250,83/10/11,8310250442
- 8310250446 Notice of violation from insp on 830916-20
* Region 2, Office of Director 83/06/20 1p 20897 013 24X
Fiche 50-250,83/10/11,8310250446
- 8310250449 IE Insp Repts 50-250/83-19 & 50-251/83-19 on 830916-20
Noncompliance noted audit responses did not include commitment date for actions not completed.
DEBBAGE, A G Region 2, Office of Director UPRIG, C M Division of Engineering & Operational Programs 83/06/15 7pp 20897 014 24X Fiche 50-250,83/10/11,8310250449
- 8310270129 Forwards Amends 96 & 90 to Licenses DPR-31 & UPR-41, respectively & safety evaluation Amends add requirements for visual insps & periodic testing of mechanical snubbers
MCDONALD, D O Operating Reactors Branch 1 83/10/14 UHRIG, R E
Florida Power & Light Co 2pp 20939 076 24X
Fiche 50-250,83/10/14,8310270129
- 8310270133 Amends 96 & 90 to Licensee DPR-31 & DPR-41, respectively, adding requirements for visual insps & periodic testing of mechanical snubbers to ensure operability & capability to perform safety-related function
VARGAS, S A Operating Reactors Branch 1 83/10/14 29pp 20939 078 24X Fiche 50-250,83/10/14,8310270133
- 8310270365 Forwards corrected Page 3 of IE Safeguards Insp Repts 50-250/83-28 & 50-251/83-28 re protected area intrusion detection sys Encl withheld (ref 10CFR73 21)
DANCE, H C Division of Project & Resident Programs 83/10/18 UHRIG, R E
Florida Power & Light Co 1p 20924 067 24X
Fiche 50-250,83/10/18,8310270365
- 8310270249 Corrects 831003 Ltr L-83-505 requesting updated endorsement code requirements for sys hydro (h temp) pressure tests & extended insp intervals Insp program based on 1974 edition of Section XI of ASME Code
WILLIAMS, J W Florida Power & Light Co 83/10/21 EISENHUT, D O
Division of Licensing 2pp 20923 235 24X Fiche 50-250,83/10/21,8310270249
- R Periodic operating reports & related correspondence
- 8310190023 Monthly operating reports for Aug 1983 w/830915 ltr
GRANT, N W WILLIAMS, J W Florida Power & Light Co 83/09/15
Office of Resource Management, Director 17pp 20822 017. 24X
Fiche 50-000,83/09/15,8310190023

DOCKETED ITEMS

45

S Reportable occurrences, LERs & related correspondence

8310050071 Comments on AD rept to Congress for Second Quarter CY83 containing AD 83-4, "Unavailability of Auxiliary Feedwater Sys (Turkey Point Unit 3) " Marked-up update of AD 75-5 encl
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/09/27 HELTEMES, C J Director's Office 8pp 20650 157 24X
Fiche 50-250, 83/09/27, 8310050071

8310180359 RD several fire barrier penetrations breached for longer than 7 days, due to implementation of approved design changes, including new computer room auxiliary power upgrade & App R Hourly fire watch established
WILLIAMS, J W Florida Power & Light Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20803 043 24X
Fiche 50-250, 83/10/13, 8310180359

DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

F Security, medical, emergency & fire protection plans

8310040145 Forwards supplemental info re 10CFR50, App R re fire protection, per 830408 submittal Thermal fixed temp & rate of rise fire detection will be provided in auxiliary feedwater control valve (fire Zones 113 & 116) areas
UHRIG, R E Florida Power & Light Co 83/09/30 VARGA, S A Operating Reactors Branch 1 2pp 20608 024 24X
Fiche 50-250, 83/09/30, 8310040145

8310170240 Forwards "Alternate Shutdown Capability Rept 10CFR50, App R, Section III L for Turkey Point Units 3 & 4 " Site visit will be arranged for NRC reviewers upon request
UHRIG, R E Florida Power & Light Co 83/10/07 EISENHUT, D O Division of Licensing 2pp 20790 309 24X Fiche 50-250, 83/10/07, 8310170240

--8310170244 "Alternate Shutdown Capability Rept 10CFR50, App R, Section III L for Turkey Point Units 3 & 4 " W/PD oversize figures. Appendix cards are available in PDR
* Bechtel Corp 83/10/07 5pp 20790 311 24X
Fiche 50-250, 83/10/07, 8310170244

8310270365 Forwards corrected Page 3 of IE Safeguards Insp Repts 50-250/83-28 & 50-251/83-28 re protected area intrusion detection sys Encl withheld (ref 10CFR71.21)
DANCE, H C Division of Project & Resident Programs 83/10/18 UHRIG, R E Florida Power & Light Co 1p 20924 007 24X
Fiche 50-250, 83/10/18, 8310270365

G Adjudicatory correspondence

8310130164 Forwards status rept on hybrid hearing procedures under Section 134 of Nuclear Waste Policy Act Proposed rule on implementation of procedures awaits Commission action
CUNNINGHAM, G H Office of the Executive Legal Director 83/10/07 REHM, T A Office of the Executive Director for Operations 2pp 20724 291 24X Fiche 50-000, 83/10/07, 8310130164

H General correspondence

8310180298 Responds to 830926 request to be added to svc list re proposed spent fuel pool expansion & criteria for svc list Request to be added to svc list denied Notification re preliminary NSHC will be provided
MCDONALD, D O Operating Reactors Branch 1 83/10/12 LORION, J Center for Nuclear Responsibility 1p 20826 357 24X
Fiche 50-250, 83/10/12, 8310180298

P Operating license stage documents & correspondence

8310110530 "Assessment of Radiation Risks," util-medical dialogue presented at 800922-23 Intl Inst of Safety & Health forum in Washington, DC
LAPP, R E International Institute of Safety & Health 80/09/23 52pp 20714 161 24X Fiche 50-000, 80/09/23, 8310110530

8310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR
CONNER, L Affiliation Unknown 83/05/02 NRC - No Detailed Affiliation Given 1p 21004 270 24X Fiche 50-000, 83/05/02, 8310310017

8310030659 Requests site visit to continue review of 821027 & 830307 requests for rev to inservice test program for pumps & valves Encl questions & comments will serve as agenda
VARGA, S A Operating Reactors Branch 1 83/09/20 UHRIG, R E Florida Power & Light Co 9pp 20626 347 24X
Fiche 50-250, 83/09/20, 8310030659

8310110296 Forwards response to NRC concerns discussed in 830815 telcon re Tech Spec changes to F delta H limit Impact of change limited to expected cycle-wide power distribution differences
UHRIG, R E Florida Power & Light Co 83/10/04 EISENHUT, D O Division of Licensing 5pp 20666 075 24X Fiche 50-250, 83/10/04, 8310110296

8310130125 Forwards Class II & III amend fees for 830818 request to amend Licenses DPR-31 & DPR-41 re F delta H/FG
UHRIG, R E Florida Power & Light Co 83/10/06 EISENHUT, D O Division of Licensing 1p 20725 052 24X Fiche 50-250, 83/10/06, 8310130125

8310180324 Forwards revised Tech Spec page re RHR pump operability per 831013 telcon request for addl info concerning proposed license amend
WILLIAMS, J W Florida Power & Light Co 83/10/13 EISENHUT, D O Division of Licensing 3pp 20806 159 24X Fiche 50-250, 83/10/13, 8310180324

--8310180327 Proposed Tech Spec re RHR pump operability
* Florida Power & Light Co 83/10/13 1p 20806 161 24X
Fiche 50-250, 83/10/13, 8310180324

8310240258 Forwards order for mod of Licenses DPR-31 & DPR-41, requiring Tech Spec 3.4.1b be modified, on interim basis, to permit operation in hot shutdown mode while inoperable RHR pump repaired
VARGA, S A Operating Reactors Branch 1 83/10/14 UHRIG, R E Florida Power & Light Co 2pp 20908 007 24X
Fiche 50-250, 83/10/14, 8310240258

--8310240261 Order for mod of Licenses DPR-31 & DPR-41, requiring Tech Spec 3.4.1b be modified, on interim basis, to permit operation in hot shutdown mode while inoperable RHR pump repaired
PURPLE, R A Division of Licensing 83/10/14 Florida Power & Light Co 3pp 20908 005 24X Fiche 50-250, 83/10/14, 8310240258

--8310240264 Safety evaluation supporting interim Tech Spec mod to permit operation in hot shutdown mode while inoperable RHR pump repaired
* Office of Nuclear Reactor Regulation, Director 83/10/14 3pp 20908 008 24X Fiche 50-250, 83/10/14, 8310240258

8310270129 Forwards Amends 96 & 90 to Licenses DPR-31 & DPR-41, respectively & safety evaluation Amends add requirements for visual insps & periodic testing of mechanical snubbers
MCDONALD, D O Operating Reactors Branch 1 83/10/14 UHRIG, R E Florida Power & Light Co 2pp 20939 076 24X
Fiche 50-250, 83/10/14, 8310270129

--8310270153 Amends 96 & 90 to Licenses DPR-31 & DPR-41, respectively, adding requirements for visual insps & periodic testing of mechanical snubbers to ensure operability & capability to perform safety-related function
VARGA, S A Operating Reactors Branch 1 83/10/14 25pp 20939 078 24X Fiche 50-250, 83/10/14, 8310270129

--8310270161 Safety evaluation supporting Amends 96 & 90 to Licenses DPR-31 & DPR-41, respectively
* Office of Nuclear Reactor Regulation, Director 83/10/14 5pp 20939 103 24X Fiche 50-250, 83/10/14, 8310270129

8310210075 Requests remittance of fee due for 830505 application to delete terrestrial & other monitoring programs from Tech Specs within 15 days
MILLER, W D License Fee Management Branch 83/10/17 UHRIG, R E Florida Power & Light Co 1p 20883 343 24X Fiche 50-250, 83/10/17, 8310210075

Q Inspection reports, IE Bulletins & correspondence

8310040305 Forwards IE Insp Repts 50-250/83-29 & 50-251/83-29 on 830804-05 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/08/30 UHRIG, R E Florida Power & Light Co 2pp 20612 353 24X
Fiche 50-250, 83/08/30, 8310040305

--8310040316 IE Insp Repts 50-250/83-29 & 50-251/83-29 on 830804-05 No noncompliance noted Major areas inspected welder concerns re unsatisfactory/unsafe welds
KLEINSORGE, W P Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/08/23 5pp 20612 355 24X Fiche 50-250, 83/08/30, 8310040305

8310040504 Forwards IE Insp Repts 50-250/83-30 & 50-251/83-30 on 830823-26 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/09 UHRIG, R E Florida Power & Light Co 2pp 20622 353 24X
Fiche 50-250, 83/09/09, 8310040504

DOCKETED ITEMS

- 8310040517 IE Insp Repts 50-250/83-30 & 50-251/83-30 on 830823-26 No noncompliance noted Major areas inspected GC of analytical measurements, mgt & administrative controls, status review of environ monitoring stations & state/NRC split samples
CUNNINGHAM, A L Region 2, Office of Director MONTGOMERY, D M Division of Engineering & Operational Programs 83/09/07 5pp 20622 355 24X Fiche 50-250, 83/09/09, 8310040504
- 8310040405 Confirms telcon re 831021 mgt meeting in Miral, FL to discuss results of first phase of SALP review for period Ju 1982 - June 1983 Proposed agenda encl
LEWIS, R C Division of Project & Resident Programs 83/09/22 UHRIQ, R E Florida Power & Light Co 2pp 20619 092 24X Fiche 50-000, 83/09/22, 8310040405
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345
- 8310050078 Ack receipt of 830909 ltr & payment of civil penalty proposed by NRC on 830813 Corrective actions will be examined during future insp
AXELRAD, J A Enforcement Staff 83/09/26 ADDHAT, E A Florida Power & Light Co 2pp 20650 187 24X Fiche 50-250, 83/09/26, 8310050078
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349
- 101010138 Requests approval to use 1980 Edition & Addenda through Winter 1981 Addenda of ASME Section XI Code, per 10CFR50 55a (g)(4)(iv), to extend inservice insp interval due to lengthy steam generator repair outages
UHRIQ, R E Florida Power & Light Co 83/10/03 EISENHUT, D O Division of Licensing O'REILLY, J P Region 2, Office of Director 2pp 20685 001 24X Fiche 50-250, 83/10/03, 831010138
- 108300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378
- 108300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752
- 1010180381 Suppls 830720 response to Generic Ltr 81-07, "Control of Heavy Loads," in response to NRC finding in IE Insp Rept 83-11, dtd 830620 Info documents until methodology for compliance w/NUREG-0612 & ANSI N 14.6
UHRIQ, R E Florida Power & Light Co 83/10/07 EISENHUT, D O Division of Licensing 2pp 20803, 201 24X Fiche 50-250, 83/10/07, 8310180381
- 108300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759
- 8308300741 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300741
- 8310250426 Ack receipt of 830720 & 0922 ltrs informing NRC of slip taken to correct violations noted in IE Insp Repts 50-250/83-19 & 50-251/83-19
LEWIS, R C Division of Project & Resident Programs 83/10/11 UHRIQ, R E Florida Power & Light Co 1p 20897 006 24X Fiche 50-250, 83/10/11, 8310250426
- 8310250431 Updates 830720 response to NRC 830620 ltr re violations noted in IE Insp Repts 50-250/83-19 & 50-251/83-19 Corrective actions Quality Procedure 16.1 revised to address requirements for audit responses in OP 18.1
UHRIQ, R E Florida Power & Light Co 83/09/22 O'REILLY, J P Region 2, Office of Director 1p 20897 007 24X Fiche 50-250, 83/10/11, 8310250431
- 8310250437 Responds to NRC 830620 ltr re violations noted in IE Insp Repts 50-250/83-19 & 50-251/83-19 Corrective actions GC personnel responsible for preparing audits instructed to list dates & responsible personnel for all commitments
UHRIQ, R E Florida Power & Light Co 83/07/20 O'REILLY, J P Region 2, Office of Director 3pp 20897 008 24X Fiche 50-250, 83/10/11, 8310250437
- 8310250442 Forwards IE Insp Repts 50-250/83-19 & 50-251/83-19 on 830516-20 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/09/20 UHRIQ, R E Florida Power & Light Co 2pp 20897 011 24X Fiche 50-250, 83/10/11, 8310250442
- 8310250446 Notice of violation from insp on 830516-20
* Region 2, Office of Director 83/06/20 1p 20897 013 24X Fiche 50-250, 83/10/11, 8310250446
- 8310250449 IE Insp Repts 50-250/83-19 & 50-251/83-19 on 830516-20 Noncompliance noted audit responses did not include commitment date for actions not completed
DEBAGIS, A G Region 2, Office of Director UPRIGHT, C M Division of Engineering & Operational Programs 83/06/15 9pp 20897 014 24X Fiche 50-250, 83/10/11, 8310250449
- 8310270129 Forwards Amends 96 & 90 to Licenses DPR-31 & DPR-41, respectively & safety evaluation Amends add requirements for visual insps & periodic testing of mechanical snubbers
MCDONALD, D G Operating Reactors Branch 1 83/10/14 UHRIQ, R E Florida Power & Light Co 2pp 20739 076 24X Fiche 50-250, 83/10/14, 8310270129
- 8310270153 Amends 96 & 90 to Licenses DPR-31 & DPR-41, respectively, adding requirements for visual insps & periodic testing of mechanical snubbers to ensure operability & capability to perform safety-related function
VARQA, S A Operating Reactors Branch 1 83/10/14 23pp 20939 078 24X Fiche 50-250, 83/10/14, 8310270153
- 8310270368 Forwards corrected Page 3 of IE Safeguards Insp Repts 50-250/83-28 & 50-251/83-28 re protected area intrusion detection sys encl withheld (ref 10CFR 1.21)
DANCE, H C Division of Project & Resident Programs 83/10/18 UHRIQ, R E Florida Power & Light Co 1p 20924 007 24X Fiche 50-250, 83/10/18, 8310270368
- 8310270249 Corrects 831003 Ltr L-83-505 requesting updated endorsed code requirements for sys hydro (& temp) pressure tests & extended insp intervals Insp program based on 1974 edition of Section XI of ASME Code
WILLIAMS, J W Florida Power & Light Co 83/10/21 EISENHUT, D O Division of Licensing 2pp 20923 236 24X Fiche 50-250, 83/10/21, 8310270249
- R Periodic operating reports & related correspondence
- 8310190023 Monthly operating repts for Aug 1983 W/830915 ltr
GRANT, N W, WILLIAMS, J W Florida Power & Light Co 83/09/15 Office of Resource Management, Director 17pp 20822 017 24X Fiche 50-000, 83/09/15, 8310190023
- S Reportable occurrences, LERs & related correspondence
- 8310270340 FOIA request for placement of listed LERs in PRR
GRABER, L D NUS Corp 83/09/08 Division of Rules and Records 2pp 20938 058 24X Fiche 50-000, 83/09/08, 8310270340
- 8310030262 LER 83-013/03L-0 on 830825, while performing safeguards test emergency load sequencer 4A failed caused by normal end of life for open-circuited timer 4A Agastat relay replaced & sequencer tested & returned to svc W/830926 ltr
WILLIAMS, J W, ARIAS, J Florida Power & Light Co 83/09/26 O'REILLY, J P Region 2, Office of Director 2pp 20591 056 24X Fiche 50-251, 83/09/26, 8310030262

DOCKETED ITEMS

47

8310060171 Forwards, for review & comment, "Low Temp Overpressure Events at Turkey Point Unit 4," draft case study rept
HELTEMES, C J Director's Office 83/09/26 DENTON, H R Office of Nuclear Reactor Regulation, Director DEYOUNG, R C Director's Office, Office of Inspection and Enforcement MINOQUE, R B Office of Nuclear Regulatory Research, Director 2pp 20661 020 24X
Fiche 50-251, 83/09/26, 8310060171

--8310060175 Forwards, for review & comment, "Low Temp Overpressure Events at Turkey Point Unit 4," draft case study rept
HELTEMES, C J Director's Office 83/09/26 WILKINSON, E P Institute of Nuclear Power Operations 2pp 20661 022 24X
Fiche 50-251, 83/09/26, 8310060171

--8310060179 Forwards, for review & comment, "Low Temp Overpressure Events at Turkey Point Unit 4," draft case study rept
HELTEMES, C J Director's Office 83/09/26 ROSSIN, D Nuclear Safety Analysis Center 2pp 20661 024 24X
Fiche 50-251, 83/09/26, 8310060171

--8310060185 Forwards, for review & comment, "Low Temp Overpressure Events at Turkey Point Unit 4," draft case study rept
HELTEMES, C J Director's Office 83/09/26 UHRIG, R E Florida Power & Light Co 2pp 20661 026 24X Fiche 50-251, 83/09/26, 8310060171

--8310060190 Forwards, for review & comment, "Low Temp Overpressure Events at Turkey Point Unit 4," draft case study rept
HELTEMES, C J Director's Office 83/09/26 RAHE, F P Westinghouse Electric Corp 2pp 20661 028 24X
Fiche 50-251, 83/09/26, 8310060171

--8310060194 Forwards, for review & comment, "Low Temp Overpressure Events at Turkey Point Unit 4," draft case study rept
HELTEMES, C J Director's Office 83/09/26 MARSHALL, J Arkansas Power & Light Co 2pp 20661 030 24X Fiche 50-251, 83/09/26, 8310060171

--8310060199 "Low Temp Overpressure Events at Turkey Point Unit 4," draft case study rept
LANNING, W D Director's Office 83/08/31 56pp 20661 032 24X
Fiche 50-251, 83/09/26, 8310060171

8310270347 Responds to FOIA request for release of 23 LERs to PDR
Forwards 12 LERs to be released Documents also available in
PDR One LER canceled Eight LERs not received
FELTON, J M Division of Rules and Records 83/09/29 GRAHER, L D
NUS Corp 1p 20938 060 24X Fiche 50-000, 83/09/29, 8310270347

--8310270354 LER 83-002/017-0 on 830405, spent fuel assembly X-13 dropped back into rack from fully lifted position Caused by cable stress due to limit switch failure Insp for cladding damage will be conducted W/830419 1tr
BARRY, Z E, WILLIAMS, J W Florida Power & Light Co 83/04/19
O'REILLY, J P Region 2, Office of Director 4pp 20938 061 24X
Fiche 50-000, 83/09/29, 8310270347

8310180359 RO several fire barrier penetrations breached for longer than 7 days, due to implementation of approved design changes, including new computer room auxiliary power upgrade & App R Hourly fire watch established
WILLIAMS, J W Florida Power & Light Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20803 043 24X
Fiche 50-250, 83/10/13, 8310180359

8310210223 LER 83-015/03L-0 on 830913, local leak rate test on containment personnel hatch airlock revealed leakage in excess of Tech Specs Caused by equalizing vent valve on inner door not fully closed Valve tightened W/831013 1tr
BERRY, Z E, WILLIAMS, J W Florida Power & Light Co 83/10/13
O'REILLY, J P Region 2, Office of Director 2pp 20852 074 24X
Fiche 50-251, 83/10/13, 8310210223

8310270277 LER 83-016/01Y-0 on 831004, manual discharge valves on containment spray pumps 4A & 4B discovered locked in closed position Caused by personnel error Valve for pump 4B opened W/831018 1tr
ARIAS, J, WILLIAMS, J W Florida Power & Light Co 83/10/18
O'REILLY, J P Region 2, Office of Director 3pp 20923 256 24X
Fiche 50-251, 83/10/18, 8310270277

DOCKET 50 254 GUAD CITIES STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8310140261 Forwards IE Insp Repts 50-254/83-26 & 50-265/83-25 on 830822-26 & 31 & 0909 & notice of violation
HIND, J A Division of Radiological & Materials Safety Programs 83/09/29 REED, C Commonwealth Edison Co 2pp 20762 040 24X
Fiche 50-254, 83/09/29, 8310140261

--8310140264 Notice of violation from insp on 830822-26 & 31 & 0909
HIND, J A Division of Radiological & Materials Safety Programs 83/09/28 2pp 20762 050 24X Fiche 50-254, 83/09/29, 8310140261

--8310140271 IE Insp Repts 50-254/83-26 & 50-265/83-25 on 830822-26 & 31 & 0909 Noncompliance noted failure to distribute controlled emergency plan procedure revs to NRC
PHILLIPS, M P, PLOSKI, T J, PAPERIELLO, C J Region 3, Office of Director 83/09/29 17pp 20762 052 24X Fiche 50-254, 83/09/29, 8310140261

8310060541 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/09/30 Document Management Branch 1p 20662 001 24X Fiche 50-254, 83/09/30, 8310060541

--8310060545 Public version of revised emergency plan implementing procedures, including Procedures QEP 550-0 re emergency equipment & supplies & QEP 550-T4 re emergency operations facility supplies
KOVACK, T J, GERNER, L Commonwealth Edison Co 83/09/08 300pp 20662 002 24X Fiche 50-254, 83/09/30, 8310060541

8310110325 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20685 231 24X Fiche 50-254, 83/10/05, 8310110325

--8310110327 Public version of revised Emergency Plan Implementing Procedures QEP 110-2 re acting station director (shift director) & Procedure QEP 310-1 re initial notification
TIETZ, G Commonwealth Edison Co 83/09/08 24pp 20685 232 24X
Fiche 50-254, 83/10/05, 8310110325

8310200079 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/14 Document Management Branch 1p 20844 218 24X Fiche 50-254, 83/10/14, 8310200079

--8310200082 Public version of Rev 2 to Emergency Plan Implementing Procedure QEP 450-1, "Environ Surveillance Stations"
KOVACK, T J, CARSDON, R Commonwealth Edison Co 83/09/28 6pp 20844 219 24X Fiche 50-254, 83/10/14, 8310200079

8310270024 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20940 199 24X Fiche 50-254, 83/10/21, 8310270024

--8310270028 Forwards public version of revised emergency plan implementing procedures, including Procedures QEP 550-1 re first aid & decontamination facilities & QEP 550-T1 re environ sampling supplies
TIETZ, G, GERNER, L Commonwealth Edison Co 83/10/06 NRC - No Detailed Affiliation Given 2pp 20940 200 24X
Fiche 50-254, 83/10/21, 8310270024

--8310270032 Public version of revised emergency plan implementing procedures, including Procedures QEP 550-1 re first aid & decontamination facilities, QEP 550-2 re emergency equipment inventory & QEP 550-T1 re environ sampling supplies
Commonwealth Edison Co 83/10/06 24pp 20940 202 24X
Fiche 50-254, 83/10/21, 8310270024

8310270526 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20937 216 24X Fiche 50-000, 83/10/21, 8310270526

--8310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure EDF-6, "Administration & Logistics Manager"
W/831017 1tr & receipt form
NEILLIS, C A Commonwealth Edison Co 83/02/18 DENTON, H R NRC - No Detailed Affiliation Given 7pp 20937 217 24X
Fiche 50-000, 83/10/21, 8310270526

8310280307 Releases public version of revised generating stations emergency plan telephone directory
FELTON, J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20963 126 24X Fiche 50-000, 83/10/25, 8310280307

--8310280314 Public version of revised generating stations emergency plan telephone directory
GALL, D P Commonwealth Edison Co 83/08/11, DENTON, H R Office of Nuclear Reactor Regulation, Director 64pp 20963 127 24X
Fiche 50-000, 83/10/25, 8310280307

DOCKETED ITEMS

8310280191 Releases public version of revised emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records 83/10/26 Document
Management Branch 1p 20762 266 24X Fiche 50-000, 83/10/26,
8310280191

--8310280209 Public version of Rev 1 to Emergency Plan Implementing
Procedure EOP-15, "Emergency Operations Facility
Activation"
MOORE, R. D. Commonwealth Edison Co 83/08/02 50pp 20762 267
24X Fiche 50-000, 83/10/26, 8310280191

P Operating license stage documents & correspondence

8310200273 Forwards schedules for equipment qualification test programs
for facilities per 810528 ltr Dates given for current
qualification activities should be viewed as "target dates"
& not as firm dates
BARNES, P. L. Commonwealth Edison Co 83/10/05 KEPLER, J. O. Region 3,
Office of Director 10pp 20830 034 24X Fiche 50-000, 83/10/05,
8310200273

8310120253 Suppl 830531 ltr re containment integrated leak rate test
frequency Type A test should be performed during upcoming
refueling outage Tests should also be performed during plant
shutdowns until 10CFR50, App J criteria met
SPESERARD, R. L. Region 3, Office of Director 83/10/07 REED, C.
Commonwealth Edison Co 1p 20691 320 24X Fiche 50-254, 83/10/07,
8310120253

1310170345 Provides addl info re NUREG-0737, Item II, K 3 P2, justifying
use of HPCI logic for RCIC suction switchover RCIC sys not
safety-related & is not intended as backup for HPCI sys
RYBAK, B. Commonwealth Edison Co 83/10/07 DENTON, H. R. Office of
Nuclear Reactor Regulation, Director 1p 20784 320 24X
Fiche 50-254, 83/10/07, 8310170345

8310310054 Advises that pipe stresses & support loads due to dead
weight of water in pipe, concurrent thermal effects & effects
of postulated earthquake within design allowables reviewed;
per NUREG-0737, Item II D 1
RYBAK, B. Commonwealth Edison Co 83/10/20 DENTON, H. R. Office of
Nuclear Reactor Regulation, Director 2pp 20951 146 24X
Fiche 50-254, 83/10/20, 8310310054

1310250293 Forwards Rev 10 to Offsite Dose Calculation Manual for
LaSalle & Quad Cities & Rev 9 to Offsite Dose Calculation
Manual for Braidwood, consisting of Chapters 7 2 & B 0
BENNETT, C. J. Commonwealth Edison Co 83/10/21 CASE, E. G. Office
of Nuclear Reactor Regulation, Director 1p 20894 259 24X
Fiche 50-000, 83/10/21, 8310250293

--8310250298 Rev 10 to Offsite Dose Calculation Manual for LaSalle & Quad
Cities
* Commonwealth Edison Co 83/09/30 44pp 20894 260 24X
Fiche 50-000, 83/10/21, 8310250293

--8310250302 Rev 9 to Offsite Dose Calculation Manual for Braidwood,
consisting of Chapters 7 2 & B 0
* Commonwealth Edison Co 83/08/31 56pp 20894 304 24X
Fiche 50-000, 83/10/21, 8310250293

G Inspection reports, IE Bulletins & correspondence

8310140133 Responds to notice of violation & proposed imposition of
civil penalties re insertion of control rods during reactor
shutdown on 830310 & 11 Shift turnover procedures revised
Info sessions for control room personnel conducted
THOMAS, B. L. Commonwealth Edison Co 83/08/12 KEPLER, J. O. Region 3,
Office of Director 11pp 20763 354 24X Fiche 50-254, 83/08/12,
8310140133

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder
Qualification Tests" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
Detectors Positioned at Control Room Ventilation Air
Intakes" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse
Type A-1 Differential Relays" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to
Safety-Related Sys W/o 10CFR50 59 Evaluation" Svc list
encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New
York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310140261 Forwards IE Insp Repts 50-254/83-26 & 50-265/83-25 on
830822-26 & 31 & 0909 & notice of violation
HIND, J. A. Division of Radiological & Materials Safety Programs
83/09/29 REED, C. Commonwealth Edison Co 2pp 20762 048 24X
Fiche 50-254, 83/09/29, 8310140261

--8310140264 Notice of violation from insp on 830822-26 & 31 & 0909
HIND, J. A. Division of Radiological & Materials Safety Programs
83/09/28 2pp 20762 050 24X Fiche 50-254, 83/09/29, 8310140264

--8310140271 IE Insp Repts 50-254/83-26 & 50-265/83-25 on 830822-26
& 0909 Noncompliance noted failure to distribute controlled
emergency plan procedure revs to NRC
PHILLIPS, M. P., PLOSKI, T. J., PAPERIELLO, C. J. Region 3, Office of
Director 83/09/29 17pp 20762 052 24X Fiche 50-254, 83/09/29,
8310140261

8310200124 Forwards IE Mgt Meeting Repts 50-010/83-18, 50-237/83-27,
50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19,
50-304/83-20, 50-373/83-38, 50-374/83-38, 50-434/83-44,
50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIOUS, C. E. Division of Project & Resident Programs 83/10/04
REED, C. Commonwealth Edison Co 2pp 20834 098 24X
Fiche 50-000, 83/10/04, 8310200124

--8310200148 IE Mgt Meeting Repts 50-020/83-18, 50-237/83-27, 50-249/83-25,
50-254/83-27, 50-265/83-26, 50-295/83-19, 50-304/83-20,
50-373/83-38, 50-374/83-38, 50-434/83-44, 50-455/83-33,
50-456/83-14 & 50-457/83-13
NORELIOUS, C. E. Division of Project & Resident Programs 83/10/04
2pp 20834 100 24X Fiche 50-000, 83/10/04, 8310200124

8310170337 Submits status of as-built reviews of safe shutdown pip.
supports for IE Bulletin 79-14. As result of review of
Quad Cities, two piping sys found to have addl discrepancies
Seven new hangers added
RYBAK, B. Commonwealth Edison Co 83/10/06 KEPLER, J. O. Region 3,
Office of Director 2pp 20786 155 24X Fiche 50-000, 83/10/06,
8310170337

8308300378 IE Info Notice 83-65, "Surveillance of Flow in R1D Upper
Loops Used in Westinghouse Plants" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of
New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical
Facility" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of
New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Hall Ex
Causes Production of Noxious Gases" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of
New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defect:
Self-Contained Breathing Apparatus Air Cylinders" Svc list
encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of
New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180238 Clarifies procedures for admitting NRC personnel to
facilities Access lists identifying authorized clearances
encl Update will be provided every 6 months
AXELSON, W. L. Region 3, Office of Director 83/10/14 REED, C.
Commonwealth Edison Co 7pp 20808 234 24X Fiche 50-254, 83/10/14,
8310180238

8310180551 Notification of 831021 meeting w/DWR licensees in Bath
MD to discuss future insps for intergranular stress
corrosion cracking
HIRAOLIA, F. J. Assistant Director for Safety Assessment 83/10/10
EISENHUT, D. Q. Division of Licensing 3pp 20823 358 24X
Fiche 50-000, 83/10/14, 8310180551

8310250605 Forwards IE Insp Repts 50-254/83-25 & 50-265/83-24 on
830802-0930 No noncompliance noted
SHAFER, W. D. Region 3, Office of Director 83/10/18 REED, C.
Commonwealth Edison Co 2pp 20900 274 24X Fiche 50-254, 83/10/18,
8310250605

DOCKETED ITEMS

49

--B310250613 IE Insp Repts 50-254/83-25 & 50-265/83-24 on B30807-09J0 No noncompliance noted Major areas inspected design changes & mods, organization & administration, procedures, onsite review committee, operational safety & maint
CHRISTIANOS, N., MORRONGIELLO, A., WALKER, R D Region 3, Office of Director 83/10/18 7pp 20900 278 24X Fiche 50-254, 83/10/18, B310250605

B310270435 Ack receipt of B30825 ltr re schedule for implementation of multiple peak resolution & peak reclassification enhancements to AAIS per IC Insp Repts 50-254/82-13 & 50-265/82-15
PAPERIELLO, C J Region 3, Office of Director 83/10/25 HYBAK, B Commonwealth Edison Co 1p 20923 057 24X Fiche 50-254, 83/10/25, B310270435

R Periodic operating reports & related correspondence

B310180109 Revised monthly operating repts for Jul & Aug 1983 W/B31003 ltr
KALIVIANAKIS, N Commonwealth Edison Co 83/08/31 Director's Office, Office of Inspection and Enforcement 2pp 20008 169 24X Fiche 50-254, 83/08/31, B310180109

B310170353 Forwards listing of changes, tests & experiments completed during Sept 1983 Summary of safety evaluation reported per 10CFR50.59
KALIVIANAKIS, N Commonwealth Edison Co 83/10/03 CASE, E G Office of Nuclear Reactor Regulation, Director 6pp 20786 165 24X Fiche 50-254, 83/10/03, B310170353

B310180263 Monthly operating repts for Sept 1983 W/B31003 ltr
MISAK, A L, KALIVIANAKIS, N Commonwealth Edison Co 83/10/03 Director's Office, Office of Inspection and Enforcement 26pp 20807 052 24X Fiche 50-254, 83/10/03, B310180263

S Reportable occurrences, LIRs & related correspondence

B310110430 Responds to FOIA request for four different categories of documents described in B30510 ltr forwards matl listed in App A responsive to Items 1, 2 & 4 DOE should be contacted for matl requested in Item 3 of ltr
FELTON, J M Division of Rules and Records 83/06/14 HIAff, 9 Ohio Citizens For Responsible Energy 3pp 20706 002 24X Fiche 50-000, 83/06/14, B310110430

--B310110478 Responds to B30413 ltr requesting info re use of foreign matls on valve seating surfaces Lubricants & cleaning solvents used on valve component surfaces per vendor recommendations & maint practices
FARRAR, D L Commonwealth Edison Co 83/04/22 KLEPPLER, J G Region 3, Office of Director 4pp 20706 063 24X Fiche 50-000, 83/04/22, B310110478

B310120158 LER B3-032/03L-0 on B30901, while preparing for refuel outage, secondary containment capability test revealed vacuum attainment of 0.13-inch water Caused by aged gaskets on personnel access doors Gaskets replaced W/B30926 ltr
PREUSS, M, KALIVIANAKIS, N Commonwealth Edison Co 83/09/26 KLEPPLER, J G Region 3, Office of Director 3pp 20696 027 24X Fiche 50-254, 83/09/26, B310120158

B310170491 LER B3-034/03L-0 on B30908, LPCI loop select for RHX loop A declared inoperable due to inability to close recirculation pump 1A discharge valve HQ 1-202-5A Caused by shorted control cables on valve Cables replaced W/B31003 ltr
IDEN, C, KALIVIANAKIS, N Commonwealth Edison Co 83/10/03 KLEPPLER, J G Region 3, Office of Director 4pp 20784 119 24X Fiche 50-254, 83/10/03, B310170491

B310170271 LER B3-035/03L-0 on B30915, Target Rock valve 1-203-3A stuck open Caused by eroded second-stage pilot seat Valve replaced & tested satisfactorily on B30922 W/B31005 ltr
CDDK, D, KALIVIANAKIS, N Commonwealth Edison Co 83/10/04 KLEPPLER, J G Region 3, Office of Director 4pp 20786 209 24X Fiche 50-254, 83/10/04, B310170271

B310270400 LER B3-036/03L-0 on B30920, discovered ripped ventilation & fire stop boot Caused by extended exposure of boot to heat & normal wear Urethane foam matl installed & boot replaced W/B31018 ltr
FUHS, A, KALIVIANAKIS, N Commonwealth Edison Co 83/10/18 KLEPPLER, J G Region 3, Office of Director 3pp 20924 012 24X Fiche 50-254, 83/10/18, B310270400

B310270404 LER B3-037/03L-0 on B30923, while inerting primary containment, containment oxygen not reduced to Tech Spec requirement Caused by sample response time & probable source of air in-leakage through compressor W/B31020 ltr
MISAK, A, KALIVIANAKIS, N Commonwealth Edison Co 83/10/20 KLEPPLER, J G Region 3, Office of Director 4pp 20924 015 24X Fiche 50-254, 83/10/20, B310270404

DOCKET 50-255 PALISADES NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

B310040250 Forwards IE Insp Rept 50-255/83-19 on B30801-31 No noncompliance noted
SHAFER, W D Region 3, Office of Director 83/09/13 DEWITT, R B Consumers Power Co 2pp 20613 065 24X Fiche 50-255, 83/09/13, B310040250

--B310040255 IE Insp Rept 50-255/83-19 on B30801-31 No noncompliance noted Major areas inspected operational safety preparations for refueling, maint surveillance, procedures & preparations for union employee strike
JORGENSEN, B L, HELLER, J K, BOYD, D C Region 3, Office of Director 83/09/13 7pp 20613 067 24X Fiche 50-255, 83/09/13, B310040250

B310180464 Forwards proposed implementation schedule on intrusion detection sys. in response to NRC B30912 request Schedule withheld (ref 10CFR73.21)
VANDEWALLE, D J Consumers Power Co 83/09/23 CRUTCHFIELD, D Operating Reactors Branch 5 1p 20802 053 24X Fiche 50-255, 83/09/23, B310180464

B310110019 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20687 357 24X Fiche 50-000, 83/10/05, B310110019

--B310110024 Public version of Rev 6 to Emergency Plan Implementing Procedure EDF-7, "Offsite Dose Worksheet (Protective Actions)" W/B30923 ltr & receipt form
BRADLEY, J Consumers Power Co 83/07/10 Document Management Branch 2pp 20687 358 24X Fiche 50-000, 83/10/05, B310110019

B310170243 Responds to B30817 ltr re changes to security plan Changes consistent w/provisions of 10CFR50.54(p) & acceptable
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/11 VANDEWALLE, D J Consumers Power Co 2pp 20796 265 24X Fiche 50-255, 83/10/11, B310170243

B310270491 Releases public version of revised controlled copyholder list of emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20928 337 24X Fiche 50-000, 83/10/21, B310270491

--B310270510 Forwards public version of Rev 2 to controlled copyholder list of general ofc ctr/emergency operations facility emergency implementing procedures & list depicting location of proprietary info in procedures
CARLEY, A Consumers Power Co 83/09/15 Office of Nuclear Reactor Regulation, Director 7pp 20428 338 24X Fiche 50-000, 83/10/21, B310270491

B310270590 Releases public version of revised general ofc control ctr/emergency operations facility emergency implementing procedures
FELTON, J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20944 322 24X Fiche 50-000, 83/10/25, B310270590

--B310270593 Forwards public version of revised general ofc control ctr/emergency operations facility emergency implementing procedures, including Procedure GEN-2 re emergency telephone numbers Receipt form encl
CARLEY, A Consumers Power Co 83/10/13 Document Management Branch 4pp 20944 323 24X Fiche 50-000, 83/10/25, B310270590

--B310270597 Public version of revised general ofc control ctr/emergency operations facility emergency implementing procedures, including Procedure GEN-2 re emergency telephone numbers
Consumers Power Co 83/10/11 42pp 20944 327 24X Fiche 50-000, 83/10/25, B310270590

P Operating license stage documents & correspondence

B310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR
CONNER, L Affiliation Given 83/03/02 NRC - Nu Detailed Affiliation Given 1p 21004 270 24X Fiche 50-000, 83/05/02, B310310017

DOCKETED ITEMS

- 830705051J Forwards proposed generic issue "PORV & block Valve Reliability", per NRC GFC Ltr 40 guidelines PORV & block valve sys established as safety-grade components required to be operable during plant operation
DIIANNI, D C Operating Reactors Branch 3 83/06/06 MINNERS, W
Safety Program Evaluation Branch 6pp 66892 312 24X
Fiche 50-255, 83/06/08, 830705051J
- 830906001J Informs of review of PORV upgrade issued in Board Notification 83-47 Upgrade does not constitute new generic requirement, but case-specific application of existing requirements
DENTON, H Office of Nuclear Reactor Regulation, Director
83/04/27 BIELLO, V Regional Operations & Generic Requirements
1p 66770 320 24X Fiche 50-255, 83/06/08, 830705051J
- 830420004K Requests plans for submitting proposed new generic requirement for primary sys depressurization capability in PWRs for CRGR review
BIELLO, V Regional Operations & Generic Requirements 83/04/11
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p
66753 008 24X Fiche 50-255, 83/06/08, 830705051J
- 830209073J Comments on validity of NUREG-0737, Item II K 3 / re evaluation of PORV opening probability during overexposure transients, in response to 830419 memo concerning 791004 & 800219 memoranda
MATTSON, R J Division of Systems Integration (post 811005)
83/01/13 LEBENHUT, D G Division of Licensing 3pp 66613 057
24X Fiche 50-255, 83/06/08, 830705051J
- 830323048J Forwards response to 830401 questions re NUREG-0737, Item II K 3 / re PORV opening probability Challenge frequency should be reduced & reliability should be upgraded
CHOW, E Reliability & Risk Assessment Branch 83/03/14
THADANI, A Reliability & Risk Assessment Branch 16pp
66700 076 24X Fiche 50-255, 83/06/08, 830705051J
- 820527043J Recommends TMI Item II K 3 /, "Power Operated Relief Valve Opening Probability," be re-evaluated for possible cancellation or redirection from technical viewpoint New contract cannot be justified until matter is resolved
DIIANNI, D C Operating Reactors Branch 3 82/04/01
EISENBERG, D G Division of Licensing 3pp 66086 203 24X
Fiche 50-255, 83/06/08, 830705051J
- 831031003J Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which reports are unavailable
FELTON, J M Division of Rules and Records 83/07/06 CONNELL, L
Affiliation Unknown 1p 21004 271 24X Fiche 50-000, 83/07/06, 831031003J
- 831009046J Forwards application to amend License DPR-20, modifying basis for limiting safety sys settings for reactor protection sys
VANDEWALLE, D J Consumers Power Co 83/09/29 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 20630 055 24X
Fiche 50-255, 83/09/29, 831009046J
- 831005046J Application to amend License DPR-20, modifying basis for limiting safety sys setting for reactor protection sys, required by 830403 LER corrective actions
VANDEWALLE, D J Consumers Power Co 83/09/29 3pp 20630 056
24X Fiche 50-255, 83/09/29, 831005046J
- 831005046J Proposed Tech Spec changes re limiting safety sys settings for reactor protection sys
Consumers Power Co 83/09/29 Operating Reactors Branch 5
3pp 20630 059 24X Fiche 50-255, 83/09/29, 831005046J
- 831005047J "Rod Withdrawal Transient Reanalysis for Palisades Reactor"
FRYER, D C, CHANDLER, J C, KAYBER, W V Exxon Nuclear Co, Inc
(subs of Exxon Corp) XN-NF-83-37 83/08/26 59pp 20630 064
24X Fiche 50-255, 83/09/29, 831005046J
- 831006004J Forwards commitments for evaluation of mods to MSIV/main steam sys, per SEP Topic XV-2, "Spectrum of Steam Piping Failures Inside & Outside Containment (PWR)"
TOMER, K A Consumers Power Co 83/09/29 CRUTCHFIELD, D Operating
Reactors Branch 5 4pp 20648 322 24X Fiche 50-255, 83/09/29, 831006004J
- 831007017J Notifies that response to technical evaluation rept, Items 7B, 80, B1 & B2 re 2,400-volt motors mfg by Westinghouse, GE & Louis Allis, will not be submitted until 040228, due to extensive nature of documentation research effort
TOMER, K A Consumers Power Co 83/10/03 CRUTCHFIELD, D Operating
Reactors Branch 5 1p 20659 114 24X Fiche 50-255, 83/10/03, 831007017J
- 831013013J Approves 830731 request on behalf of C-E Owners Group for withholding from public disclosure App A to "Response to Questions on RCS Asymmetric Loads Evaluation Program," per 10CFR2.740
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/03
LUNDVALL, A E Baltimore Gas & Electric Co 6pp 20777 046 24X
Fiche 50-000, 83/10/03, 831013013J
- 831012027J Advises that FR, containing Commission monthly notices which afford public opportunity for hearing on requests for action, will be transmitted w/o forwarding ltr in future
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/07
VANDEWALLE, D J Consumers Power Co 3pp 20691 047 24X
Fiche 50-000, 83/10/07, 831012027J
- 831025043J Forwards safety evaluation of C-E Owners Group Rept (EN-17) compliance w/NUREG-0737, Item II K 2 17, "Voiding in RCS During Transients" Requirements met item closed
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/19
VANDEWALLE, D J Consumers Power Co 9pp 20897 037 24X
Fiche 50-255, 83/10/19, 831025043J
- 831028000J Forwards safety evaluation & Franklin Research Ctr technical evaluation rept re NUREG-0737, Items II K 3 1, "Automatic PORV Isolation" & II K 3 2, "Kept on PORVs" Response acceptable
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/20
VANDEWALLE, D J Consumers Power Co 3pp 20934 109 24X
Fiche 50-255, 83/10/20, 831028000J
- 831025007J Notification of 831025 meeting w/util in Bethesda, MD to discuss proprietary portions of NRC review of Westinghouse safety parameter display sys
WAMBACH, T V Operating Reactors Branch 5 83/10/21 CRUTCHFIELD, D
Operating Reactors Branch 5 3pp 20894 078 24X
Fiche 50-255, 83/10/21, 831025007J
- Q Inspection reports, IE Bulletins & correspondence
- 831012031J Amends 830318 response to NRC 830222 ltr re noncompliance noted in IE Insp Rept 50-255/83-01 Addl corrective action new list of effective pages completed for Tech Specs & issued to all copy holders to ascertain correct rev status
VANDEWALLE, D J Consumers Power Co 83/08/26 KCPPLER, J O Reg
3, Office of Director 2pp 20700 308 24X Fiche 50-255, 83/08/26, 831012031J
- 831004025J Forwards IE Insp Rept 50-255/83-19 on 830801-31 No noncompliance noted
SHAPER, W D Region 3, Office of Director 83/09/13 DEWITT, R J
Consumers Power Co 2pp 20613 065 24X Fiche 50-255, 83/09/13, 831004025J
- 831004025J IE Insp Rept 50-255/83-19 on 830801-31 No noncompliance noted Major areas inspected operational safety preparations for refueling, maint surveillance, procedures & preparations for union employee strike
JORGENSEN, B L, HELLER, J K, BOYD, D C Region 3, Office of
Director 83/09/13 7pp 20613 067 24X Fiche 50-255, 83/09/13, 831004025J
- 830830034J IE Info Notice 83-61, "Alleged Use of Stand-Ins For Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of N.Y., Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 830830034J
- 830830034J IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of N.Y., Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 830830034J
- 830830034J IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of N.Y., Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 830830034J
- 830830034J IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of N.Y., Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 830830034J
- 830830037J IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of N.Y., Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 830830037J

DOCKETED ITEMS

51

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 77pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency User Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180203 Clarifies NRC position on procedures for admitting NRC personnel to Facility Access to vital areas should be afforded to listed Region III personnel Update will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 DEWITT, R H
Consumers Power Co 7pp 20809 036 24X Fiche 50-255, 83/10/14, 8310180203

8310270446 Forwards IE Insp Rept 50-255/83-23 on 830919-20 No noncompliance noted
LITTLE, W B Region 3, Office of Director 83/10/14 DEWITT, R H
Consumers Power Co 2pp 20923 117 24X Fiche 50-255, 83/10/14, 8310270446

--8310270450 IE Insp Rept 50-255/83-23 on 830919-20 No noncompliance noted Major areas inspected data developed for SBRW tank support structure surveillance prior to repairs & auxiliary bldg mod procedures & const
KEATING, D E, DANIELSON, D H Region 3, Office of Director 83/10/14 4pp 20923 119 24X Fiche 50-255, 83/10/14, 8310270450

8310280256 Requests extension of 30 days for response to Action Item K of IE Bulletin 82-02, "Degradation of threaded Fasteners in RCPB of PWRs " Threaded fastener insp being performed w/normal component insps during inservice insp program
VANDEWALLE, D J Consumers Power Co 83/10/17 CRUICKSHANK, D
Operating Reactors Branch 5 1p 20830 101 24X
Fiche 50-255, 83/10/17, 8310280256

8310270493 Ack receipt of 83042/ 1tr & forwards check in amount of \$20,000 for payment of civil penalties imposed by NRC 830824
1tr Corrective actions will be examined during future insps
AXELRAD, J A Enforcement Staff 83/10/17 DEWITT, R H Consumers
Power Co 2pp 20938 102 24X Fiche 50-255, 83/10/17, 8310270493

8310250191 Forwards Final SALP Rept 50-255/83-21 for Jul 1982 - June 1983 License improvement since earlier assessments noted
KEPPLER, J G Region 3, Office of Director 83/10/20 DEWITT, R H
Consumers Power Co 2pp 20894 001 24X Fiche 50-000, 83/10/20, 8310250191

--8310250193 SALP Rept 50-255/83-21 for Jul 1982 - June 1983
Region 3, Office of Director 83/10/20 29pp 20894 003 24X
Fiche 50-000, 83/10/20, 8310250193

--8310250197 Forwards summary of significant findings of SALP rept for Jul 1982 - June 1983, as background info for 830916 meeting
Comments on SALP rept may be provided within 20 days after meeting
HIND, J A Region 3, Office of Director 83/09/09 DEWITT, R H
Consumers Power Co 4pp 20894 032 24X Fiche 50-000, 83/10/20, 8310250197

--8310250203 Informs that licensee will meet all commitments in plant regulatory performance improvement program in response to NRC 830909 1tr transmitting SALP for Jul 1982 - June 1983
VANDEWALLE, D J Consumers Power Co 83/09/26 KEPPLER, J G
Region 3, Office of Director 1p 20894 036 24X
Fiche 50-000, 83/10/20, 8310250203

R Periodic operating reports & related correspondence

8310120254 Monthly operating rept for Sept 1983 W/831003 1tr
PETERSON, D A, KENNEDY, D M Consumers Power Co 83/10/01 NRC -
No Detailed Affiliation Given 4pp 20491 316 24X
Fiche 50-255, 83/10/01, 8310120254

S Reportable occurrences, LERs & related correspondence

8310120249 LER 83-062/03L-0 on 830828, while plant shut down for refueling, routine refueling duration surveillance revealed unpredictable zero shifts in pressurizer pressure transmitters Caused by inaccurate settings W/830927 1tr
JOHNSON, B D Consumers Power Co 83/09/27 KEPPLER, J G Region 3,
Office of Director 2pp 20692 113 24X Fiche 50-255, 83/09/27, 8310120249

8310120331 Requests withdrawal of LERs 83-037 & 83-042 Addl occurrences re loss of control of either auxiliary feedwater control valves CV-0737A & CV-0736A in manner similar to referenced LERs not required to be reported to NRC
JOHNSON, B D Consumers Power Co 83/09/27 KEPPLER, J G Region 3,
Office of Director 2pp 20700 263 24X Fiche 50-255, 83/09/27, 8310120331

8310060221 Potential Part 21 rept re defective ITT-Grinnell hydraulic snubbers Initially reported in 830928 telcon Deficient snubber valve blocks will be remachined & snubbers rebuilt
JOHNSON, B D Consumers Power Co 83/09/30 KEPPLER, J G Region 3,
Office of Director 4pp 20647 021 24X Fiche 50-255, 83/09/30, 8310060221

8310120064 Supplemental RD 82-034 panel C-47 will be modified & fire deluge sys reflash capability will be provided for panel C-13
JOHNSON, B D Consumers Power Co 83/10/03 KEPPLER, J G Region 3,
Office of Director 1p 20697 173 24X Fiche 50-255, 83/10/03, 8310120064

8310170351 Telecopy RD on 831006, walkdown of safety injection sys pipe hangers revealed overloaded condition on base plate & anchor bolts of hanger H214 Caused by error in design analysis Hanger support to be redesigned
KRICH, R H Consumers Power Co 83/10/07 Region 3, Office of Director 1p 20786 164 24X Fiche 50-255, 83/10/07, 8310170351

8310210151 PNO-III-83-098 on 831014, Region III informed of discovery of circumferential crack indications in steam generator tubes near & in support plates, identified during eddy current testing Util estimates 20 to 50% of tubes affected
HOLZMER, H, BOYD, D Region 3, Office of Director 83/10/14 1p
20835 318 24X Fiche 50-255, 83/10/14, 8310210151

8310250250 LER 83-063/03L-0 on 830917, during functional testing, ITT-Grinnell hydraulic snubber 52 failed to lock-up as required Caused by generic mfg deficiency in snubber valve block, affecting shuttle valve travel W/831017 1tr
JOHNSON, B D Consumers Power Co 83/10/17 KEPPLER, J G Region 3,
Office of Director 4pp 20899 026 24X Fiche 50-255, 83/10/17, 8310250250

8310250462 LER 83-064/03L-0 on 830916, during routine surveillance test, as-found lift pressure of pressurized relief valve RC-1039 exceeded acceptance criteria range Cause unknown Valve lift setting adjusted to proper value W/831017 1tr
JOHNSON, B D Consumers Power Co 83/10/17 KEPPLER, J G Region 3,
Office of Director 2pp 20897 079 24X Fiche 50-255, 83/10/17, 8310250462

8310270162 LER 83-065/01T-0 on 831005, during walkdown of safety injection sys pipe hangers, discovered overload condition on baseplate & anchor bolts of hanger H214 Caused by design analysis error Hanger support redesigned W/831018 1tr
JOHNSON, B D Consumers Power Co 83/10/18 KEPPLER, J G Region 3,
Office of Director 2pp 20923 013 24X Fiche 50-255, 83/10/18, 8310270162

DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8310210032 Forwards IE Safeguards Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26 on 830706-0/ & notice of violation Notice of violation withheld (ref 10CFR73 21)
O'REILLY, J P Region 2, Office of Director 83/09/01 PARRIS, H G
Tennessee Valley Authority 2pp 20853 320 24X
Fiche 50-259, 83/09/01, 8310210032

--8310210034 IE Safeguards Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26 on 830706-0/ Noncompliance noted in area of access control - vital areas Details withheld (ref 10CFR73 21)
MODRE, D E Region 2, Office of Director 83/07/29 1p
20853 322 24X Fiche 50-259, 83/09/01, 8310210032

DOCKETED ITEMS

8310040452 Submits central emergency control ctr meteorological data availability statistics for Apr-June 1983 Data availability reports will be discontinued due to consistently high data availability through previous report periods
MILLS, L. M. Tennessee Valley Authority 83/09/28 ADENSAH, E.
Licensing Branch 4 2pp 20623 326 24X Fiche 50-000, 83/07/24,
8310040452

8310110193 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records 83/10/05 Document
Management Branch 1p 20682 113 24X Fiche 50-259, 83/10/05,
8310110193

--8310110199 Forwards public version of revised emergency plan implementing procedures, including Procedures IP-3 re alert, IP-4 re site area emergency & IP-5 re general emergency
MILLS, L. M. Tennessee Valley Authority 83/07/12 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 1p 20682 114
24X Fiche 50-259, 83/10/05, 8310110195

--8310110203 Public version of revised emergency plan implementing procedures, including Procedures IP-3 re alert, IP-4 re site area emergency & IP-5 re general emergency
HEBB, W. E. Tennessee Valley Authority 83/04/07 168pp
20682 115 24X Fiche 50-259, 83/10/05, 8310110195

8310310387 Forwards revs to security plan Revs withheld (ref 10CFR73 21)
MILLS, L. M. Tennessee Valley Authority 83/10/06 O'REILLY, J. P.
Region 2, Office of Director 1p 20959 327 24X
Fiche 50-259, 83/10/06, 8310310387

8310170189 Forwards IE Safeguards Insp Repts 50-259/83-37, 50-260/83-37 & 50-296/83-37 on 830927-30 No noncompliance noted
VERRELLI, D. Division of Project & Resident Programs 83/10/12
PARRIS, H. G. Tennessee Valley Authority 2pp 20786 358 24X
Fiche 50-259, 83/10/12, 8310170189

--8310170238 IE Safeguards Insp Repts 50-259/83-37, 50-260/83-37 & 50-296/83-37 on 830927-30 No noncompliance noted Major areas inspected security organization & mgt & personnel response Details withheld (ref 10CFR73 21)
MOORE, D. E. Region 2, Office of Director 83/10/11 1p
20786 360 24X Fiche 50-259, 83/10/12, 8310170189

8310240139 Forwards safety evaluation re proposed mods & alternate capabilities for achieving safe shutdown, per 10CFR50, App R, Sections III Q 3 & III L, Fire protection rule Proposed mods acceptable
VASSALLO, D. B. Operating Reactors Branch 2 83/10/12 PARRIS, H. G.
Tennessee Valley Authority 2pp 20884 342 24X
Fiche 50-259, 83/10/12, 8310240139

--8310240141 Safety evaluation supporting proposed mods & alternate capabilities for achieving safe shutdown, per 10CFR50, App R, Sections III Q 3 & III L, Fire protection rule
Office of Nuclear Reactor Regulation, Director 83/10/12 7pp
20884 344 24X Fiche 50-259, 83/10/12, 8310240139

8310210071 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26
O'REILLY, J. P. Region 2, Office of Director 83/10/17 PARRIS, H. G.
Tennessee Valley Authority 1p 20858 192 24X
Fiche 50-259, 83/10/17, 8310210071

--8310210078 Responds to NRC 830901 ltr re violations noted in IE Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26 Corrective actions withheld (ref 10CFR73 21)
MILLS, L. M. Tennessee Valley Authority 83/09/30 O'REILLY, D. P.
Region 2, Office of Director 1p 20858 193 24X
Fiche 50-259, 83/10/17, 8310210071

8310210362 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records 83/10/17 Document
Management Branch 1p 20883 001 24X Fiche 50-259, 83/10/17,
8310210362

--8310210383 Forwards public version of revised emergency plan implementing procedures, including Muscle Shoals Emergency Ctr Implementing Procedure MSEC IP-9, "Emergency Radiological Monitoring Procedures"
MILLS, L. M. Tennessee Valley Authority 83/10/06 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 1p 20883 002
24X Fiche 50-259, 83/10/17, 8310210362

--8310210385 Public version of revised emergency plan implementing procedures, including Muscle Shoals Emergency Ctr Implementing Procedure MSEC IP-9, "Emergency Radiological Monitoring Procedures"
* Tennessee Valley Authority 83/09/28 150pp 20883 001 24X
Fiche 50-259, 83/10/17, 8310210362

P Operating license stage documents & correspondence

8310060583 Comments on proposed design for compliance w/NUREG-0737, Item 11 K 3 13, "Separate HPCI & HCIC Initiation Levels" re automatic restart Proposal acceptable
VASSALLO, D. B. Operating Reactors Branch 2 83/09/19 PARRIS, H. G.
Tennessee Valley Authority 3pp 20661 204 24X
Fiche 50-259, 83/09/19, 8310060583

8310070395 Requests info describing proposed Tech Spec mods re addition of analog trip sys, including reliability, accuracy, response time of replacement instrumentation, separation criteria & single failure criterion
VASSALLO, D. B. Operating Reactors Branch 2 83/09/20 PARRIS, H. G.
Tennessee Valley Authority 3pp 20664 304 24X
Fiche 50-259, 83/09/20, 8310070395

8310070061 Forwards request for addl info re licensee insp. analyses repair of pipe cracks, including info requested by IE Bulletin 83-02 Response required to approve startup
VASSALLO, D. B. Operating Reactors Branch 2 83/09/21 PARRIS, H. G.
Tennessee Valley Authority 4pp 20671 340 24X
Fiche 50-259, 83/09/21, 8310070061

8310070068 Requests submittal of final radiological effluent tech spec & offsite dose calculation manual within 30 days
VASSALLO, D. B. Operating Reactors Branch 2 83/09/21 PARRIS, H. G.
Tennessee Valley Authority 3pp 20671 334 24X
Fiche 50-259, 83/09/21, 8310070068

8310070397 Forwards request for addl info re 830713 requested changes to Tech Specs on extensive replacement of critical plant instrumentation w/analog trip sys
VASSALLO, D. B. Operating Reactors Branch 2 83/09/21 PARRIS, H. G.
Tennessee Valley Authority 3pp, 20664 285 24X
Fiche 50-259, 83/09/21, 8310070397

8310070063 Forwards request for addl info re 830713 application for amend to License DPR-33 re reload & plant mods concerning scram discharge vol & scram discharge instrument vol
VASSALLO, D. B. Operating Reactors Branch 2 83/09/27 PARRIS, H. G.
Tennessee Valley Authority 3pp 20671 337 24X
Fiche 50-259, 83/09/27, 8310070063

8310110521 Forwards Amends 90, 86 & 59 to Licenses DPR-33, DPR-52 & DPR-68, respectively & safety evaluation Amends change Tech Specs to modify required surveillance interval for standby gas treatment sys
CLARK, R. J. Operating Reactors Branch 2 83/09/28 PARRIS, H. G.
Tennessee Valley Authority 3pp 20711 302 24X
Fiche 50-259, 83/09/28, 8310110521

--8310110536 Amends 90, 86 & 59 to Licenses DPR-33, DPR-52 & DPR-68, respectively, revising Tech Specs for testing standby gas treatment sys from once per yr to once per operating cycle
VASSALLO, D. B. Operating Reactors Branch 2 83/09/28 12pp
20711 305 24X Fiche 50-259, 83/09/28, 8310110521

--8310110551 Safety evaluation supporting Amends 90, 86 & 59 to Licenses DPR-33, DPR-52 & DPR-68, respectively
Office of Nuclear Reactor Regulation, Director 83/09/28 3pp
20711 317 24X Fiche 50-259, 83/09/28, 8310110521

8310180422 Requests relief from scheduler requirements of 830325 confirmatory orders to install redundant in-containment radiation monitors, per NUREG-0737, Item 11 F 1 3 requirement Mod will be completed before startup in Cycle 7
KAMMER, D. B. Tennessee Valley Authority 83/10/12 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 2pp 20803 338
24X Fiche 50-259, 83/10/12, 8310180422

8310240154 Forwards request for addl info re reactor protection sys power monitoring sys design mod, per 811030 request Model Tech Specs for electric power monitoring & analysis drawings not provided Submittal date requested
VASSALLO, D. B. Operating Reactors Branch 2 83/10/12 PARRIS, H. G.
Tennessee Valley Authority 3pp 20884 329 24X
Fiche 50-259, 83/10/12, 8310240154

8310240243 Forwards SER & technical evaluation rept re NUREG-0737, Item 1 A 2 1 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & 11 B 4, "Training for Mitigating Core Damage" Requirements met
VASSALLO, D. B. Operating Reactors Branch 2 83/10/12 PARRIS, H. G.
Tennessee Valley Authority 4pp 20891 123 24X
Fiche 50-259, 83/10/12, 8310240243

DOCKETED ITEMS

53

--B308310352 'Improvements In Training & Requalification Programs As Required By LMI Action Items 1 A 2 J & 11 B 4 for Browns Ferry Nuclear Plants, Units 1, 2 & 3," technical evaluation rept
* Science Applications, Inc NRC-03-82-076 SA1-186-024-50
B2/08/25 NRC - No Detailed Affiliation Given 15pp
A6280 216 24X Fiche 50-000, 83/10/12, 8310240243

B310280148 Forwards "Analysis of Vessel Wall Neutron Dosimeter From Browns Ferry Units 1, 2 & 3 Pressure Vessel," in response to NRC request for addl info to support util 830921 request to change Tech Specs TS 191
MILLS, L. M Tennessee Valley Authority 83/10/19 DENTON, H. R
Office of Nuclear Reactor Regulation, Director 1/pp 20929 061
24X Fiche 50-259, 83/10/19, 8310280148

--B310280149 "Analysis of Vessel Wall Neutron Dosimeter From Browns Ferry Unit 1 Pressure Vessel"
NORRIS, E. B., LINDHOLM, U. S. Southwest Research Institute
78/08/31 31pp 20929 080 24X Fiche 50-259, 83/10/19, 8310280148

--B310280150 "Analysis of Vessel Wall Neutron Dosimeter From Browns Ferry Unit 2 Pressure Vessel"
NORRIS, E. B., LINDHOLM, U. S. Southwest Research Institute
79/09/30 26pp 20929 111 24X Fiche 50-259, 83/10/19, 8310280148

--B310280151 "Analysis of Vessel Wall Neutron Dosimeter From Browns Ferry Unit 3 Pressure Vessel"
NORRIS, E. B., LINDHOLM, U. S. Southwest Research Institute
79/09/30 74pp 20929 137 24X Fiche 50-259, 83/10/19, 8310280148

B310310142 Forwards response to 830921 request for addl info re insp & repair of pipe cracks. Listed items not addressed since response would delay rept response to listed items will be submitted by 840201 Startup approval requested by 831121
MILLS, L. M Tennessee Valley Authority 83/10/19 DENTON, H. R
Office of Nuclear Reactor Regulation, Director 225pp 20947 177
24X Fiche 50-259, 83/10/19, 8310310142

B310250082 Forwards responses to 830920 & 21 requests for addl info re analog instrumentation installation Startup projected for 831128
MILLS, L. M Tennessee Valley Authority 83/10/20 DENTON, H. R
Office of Nuclear Reactor Regulation, Director 64pp 20896 077
24X Fiche 50-259, 83/10/20, 8310250082

B310270523 Notification of 831115 meeting w/util in Bethesda, MD to discuss insp & repairs of cracks in stainless steel piping prior to startup
CLARK, R. J. Operating Reactors Branch 2 83/10/21 VASSALLO, D. B.
Operating Reactors Branch 2 2pp 20937 214 24X
Fiche 50-259, 83/10/21, 8310270523

A Inspection reports, IE Bulletins & correspondence

B310250229 Updates 830624 response to violations noted in IE Insp Repts 50-259/83-14, 50-260/83-14 & 50-296/83-14 Extension of schedule to eliminate backlog of CARs/LRs until 830901 requested
MILLS, L. M Tennessee Valley Authority 83/08/08 O'REILLY, J. P
Region 2, Office of Director 1p 20899 067 24X
Fiche 50-259, 83/08/08, 8310250229

B310210032 Forwards IE Safeguards Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26 on 830706-07 & notice of violation Notice of violation withheld (ref 10CFR73 21)
O'REILLY, J. P Region 2, Office of Director 83/09/01 PARRIS, H. O
Tennessee Valley Authority 2pp 20893 320 24X
Fiche 50-259, 83/09/01, 8310210032

--B310210034 IE Safeguards Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26 on 830706-07 Noncompliance noted in area of access control - vital areas Details withheld
(ref 10CFR73 21)
MONROE, D. E Region 2, Office of Director MCQUINN, D. R Division of Engineering & Operational Programs 83/07/29 1p 20853 322
24X Fiche 50-259, 83/09/01, 8310210032

B310040265 Ack receipt of 830824 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-24, 50-260/83-24 & 50-296/83-24
VERRELLI, D. M Region 2, Office of Director 83/09/14 PARRIS, H. O
Tennessee Valley Authority 1p 20613 123 24X
Fiche 50-259, 83/09/14, 8310040265

--B310040271 Responds to NRC 830725 ltr re violations noted in IE Insp Repts 50-259/83-24, 50-260/83-24 & 50-296/83-24 Corrective actions, LMI examiners barred from performing addl intergranular stress corrosion cracking exams
MILLS, L. M Tennessee Valley Authority 83/08/24 O'REILLY, J. P
Region 2, Office of Director 3pp 20613 124 24X
Fiche 50-259, 83/09/14, 8310040265

--B310040275 Forwards IE Insp Repts 50-259/83-24, 50-260/83-24 & 50-296/83-24 on 830621-24 & notice of violation
VERRELLI, D. M Division of Project & Resident Programs 83/07/25
PARRIS, H. O Tennessee Valley Authority 2pp 20613 127 24X
Fiche 50-259, 83/09/14, 8310040265

--B310040278 Notice of violation from insp on 830621-24
* Region 2, Office of Director 83/07/24 1p 20613 129 24X
Fiche 50-259, 83/09/14, 8310040265

--B310040283 IE Insp Repts 50-259/83-24, 50-260/83-24 & 50-296/83-24 on 830621-24 Noncompliance noted failure to follow IE Bulletin 83-02 for requiring documented training in intergranular stress corrosion cracking
COLEY, J. L Region 2, Office of Director BLAKE, J. J Division of Engineering & Operational Programs 83/07/21 6pp 20613 130
24X Fiche 50-259, 83/09/14, 8310040265

B310070061 Forwards request for addl info re licensee insp, analyses repair of pipe cracks, including info requested by IE Bulletin 83-02 Response required to approve startup
VASSALLO, D. B Operating Reactors Branch 2 83/09/21 PARRIS, H. O
Tennessee Valley Authority 4pp 20671 340 24X
Fiche 50-259, 83/09/21, 8310070061

B308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

B308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

B308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays" Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

B310040487 Concurs w/corrective actions taken to rectify violations noted in IE Insp Repts 50-259/83-18, 50-260/83-18 & 50-296/83-18 Acceptable finding permits initiation of fuel movement in & out of core
O'REILLY, J. P Region 2, Office of Director 83/09/26 PARRIS, H. O
Tennessee Valley Authority 2pp 20625 165 24X
Fiche 50-259, 83/09/26, 8310040487

B308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation" Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

B310250166 Ack receipt of 830926 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-27, 50-260/83-27 & 50-296/83-27
LEWIS, R. C Division of Project & Resident Programs 83/10/04
PARRIS, H. O Tennessee Valley Authority 1p 20893 231 24X
Fiche 50-259, 83/10/04, 8310250166

--B310250170 Responds to NRC 830824 ltr re violations noted in IE Insp Repts 50-259/83-27, 50-260/83-27 & 50-296/83-27 Corrective actions test pressure gauges removed, fuse identification program being established & panel 25-32 cleaned
MILLS, L. M Tennessee Valley Authority 83/09/26 O'REILLY, J. P
Region 2, Office of Director 7pp 20893 252 24X
Fiche 50-259, 83/10/04, 8310250166

--B310250174 Forwards IE Insp Repts 50-259/83-27, 50-260/83-27 & 50-296/83-27 on 830626-0725 & notices of violation & deviation
LEWIS, R. C Division of Project & Resident Programs 83/08/24
PARRIS, H. O Tennessee Valley Authority 2pp 20893 261, 24X
Fiche 50-259, 83/10/04, 8310250166

--B310250179 Notice of violation from insp on 830626-0725
* Region 2, Office of Director 83/08/24 3pp 20893 263 24X
Fiche 50-259, 83/10/04, 8310250166

--B310250185 Notice of deviation from insp on 830626-0725
* Region 2, Office of Director 83/08/24 1p 20893 266, 24X
Fiche 50-259, 83/10/04, 8310250166

DOCKETED ITEMS

--8310250190 IE Insp Repts 50-259/83-27, 50-260/83-27 & 50-296/83-27 on B30625-0725 Noncompliances noted Failure to meet requirements for operational safety & absence of safety wires on backup control ctr
PAULK, G L Region 2, Office of Director CANTRELL, F S Division of Project & Resident Programs 83/08/19 10pp 20893 267 24X
Fiche 50-259, 83/10/04, 8310250166

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 7pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 7pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8310250131 Ack receipt of 830816 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-11, 50-260/83-11 & 50-296/83-11
LEWIS, R C Division of Project & Resident Programs 83/10/07
PARRIS, H G Tennessee Valley Authority 1p 20897 272 24X
Fiche 50-259, 83/10/07, 8310250131

--8310250128 Responds to NRC 830726 ltr re violations noted in IE Insp Repts 50-259/83-11, 50-260/83-11 & 50-296/83-11 Corrective actions radioactive lab manual revised to incorporate Reg Guide 4.15 interim guidance
MILLS, L M Tennessee Valley Authority 83/09/16 O'REILLY, J P Region 2, Office of Director 3pp 20897 273 24X
Fiche 50-259, 83/10/07, 8310250131

8310250234 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-28, 50-260/83-28 & 50-296/83-28
VERRELLI, D M Division of Project & Resident Programs 83/10/07
PARRIS, H G Tennessee Valley Authority 1p 20899 123 24X
Fiche 50-259, 83/10/07, 8310250234

--8310250240 Responds to NRC 830901 ltr re violations noted in IE Insp Repts 50-259/83-28, 50-260/83-28 & 50-296/83-28 Corrective actions requirements for receipt insp of QA-level matl established & wire brushes marked
MILLS, L M Tennessee Valley Authority 83/09/30 O'REILLY, J P Region 2, Office of Director 4pp 20899 124 24X
Fiche 50-259, 83/10/07, 8310250234

--8310250247 Forwards IE Insp Repts 50-259/83-28, 50-260/83-28 & 50-296/83-28 on 830725-29 & 0808 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/09/01
PARRIS, H G Tennessee Valley Authority 2pp 20899 126 24X
Fiche 50-259, 83/10/07, 8310250234

--8310250251 Notice of violation from insp on 830725-29 & 0808
Region 2, Office of Director 83/09/01 2pp 20899 130 24X
Fiche 50-259, 83/10/07, 8310250234

--8310250259 IE Insp Repts 50-259/83-28, 50-260/83-28 & 50-296/83-28 on 830725-29 & 0808 Noncompliance noted failure of receiving insp to control welding filler matls & to establish positive controls for tools used on austenitic steel
COLEY, J L Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/08/29 7pp 20899 132 24X Fiche 50-259, 83/10/07, 8310250234

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310170189 Forwards IE Safeguards Insp Repts 50-259/83-37, 50-260/83-37 & 50-296/83-37 on 830927-30 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/10/12
PARRIS, H G Tennessee Valley Authority 2pp 20786 398 24X
Fiche 50-259, 83/10/12, 8310170189

--8310170238 IE Safeguards Insp Repts 50-259/83-37, 50-260/83-37 & 50-296/83-37 on 830927-30 No noncompliance noted Major areas inspected security organization & mgt & personnel response Details withheld (ref 10CFR73.21)
MOORE, D E, MCQUIRE, D R Region 2, Office of Director 83/10/11 1p 20786 360 24X Fiche 50-259, 83/10/12, 8310170189

8310180551 Notification of 831021 meeting w/DWR licensees in ERM. MD to discuss future insps for intergranular stress corrosion cracking
MIRALIA, F J Assistant Director for Safety Assessment
EISENHUT, D G Division of Licensing 5pp 20823: 358 83/10/14, 8310180551 24X

8310210071 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26
O'REILLY, J P Region 2, Office of Director 83/10/17 Tennessee Valley Authority 1p 20898 192 24X
Fiche 50-259, 83/10/17, 8310210071

--8310210078 Responds to NRC 830901 ltr re violations noted in IE Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26 Corrective actions withheld (ref 10CFR73.21)
MILLS, L M Tennessee Valley Authority 83/09/30 O'REILLY, J P Region 2, Office of Director 1p 20890 193 24X
Fiche 50-259, 83/10/17, 8310210071

8310310142 Forwards response to 830921 request for addl info re repair of pipe cracks Listed items not addressed since response would delay rept Response to listed items will be submitted by 840201 Startup approval requested by 831121
MILLS, L M Tennessee Valley Authority 83/10/19 O'REILLY, J P Office of Nuclear Reactor Regulation, Director 225pp 20949 24X Fiche 50-259, 83/10/19, 8310310142

8310270523 Notification of 831115 meeting w/util in Bethesda, MD to discuss insp & repairs of cracks in stainless steel piping prior to startup
CLARK, R J Operating Reactors Branch 2 83/10/21 VASSALLO, D F Operating Reactors Branch 2 2pp 20947 214 24X
Fiche 50-259, 83/10/21, 8310270523

R Periodic operating reports & related correspondence

8310190186 Monthly operating repts for Aug 1983 W/830909 ltr.
THOM, T, JONES, G T Tennessee Valley Authority 83/09/01
Fiche 50-259, 83/09/01, 8310190186

S Reportable occurrences, LERs & related correspondence

8310210329 Responds to FOIA request for all documents re significant high rate of equipment failures for GE BWR/4 rated at 2,426 MW Forwards App A documents Documents also available in FDR
FELTON, J M Division of Rules and Records 83/07/28 HAFNER, J Suffolk Nuclear Study Group 2pp 20882 223 24X
Fiche 50-000, 83/07/28, 8310210329

--8302180539 Discusses results of evaluation of LERs for Jul 1981-1982, for SALP rept quality & quantity of LERs within range of average BWR facility
SEYFRIT, K V Reactor Operations Analysis Branch 83/02/09
LEWIS, R C Division of Project & Resident Programs 3pp 20882 257 24X Fiche 50-000, 83/07/28, 8310210329

8310030432 LER 83-051/03L-0 on 830824, during refueling, continuous ventilation 1-90-250 declared inoperable due to broken drive belt Caused by normal wear due to continuous operation Belt replaced W/830922 ltr
NORWOOD, D W, GREEN, H J Tennessee Valley Authority 83/09/22 O'REILLY, J P Region 2, Office of Director 3pp 20601: 224 24X
Fiche 50-259, 83/09/22, 8310030432

8310070301 Potential Part 21 rept re underrange characteristic of Model N-E110M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, O&E of Inspection and Enforcement 11pp 20651 064 24X
Fiche 50-000, 83/09/30, 8310070301

8310140129 LER 83-053/03L-0 on 830314, control room emergency ventilation train A flow control damper found in full open position Caused by loose damper arm Damper reset to proper position W/831004 ltr.
MCPHERSON, B R, GREEN, H J Tennessee Valley Authority 83/10/04 O'REILLY, J P Region 2, Office of Director 3pp 20763 041 24X
Fiche 50-259, 83/10/04, 8310140129

8310210226 LER 83-052/03L-0 on 830912, while performing surveillance Instruction 4.11 C.3 & 4 on reactor bldg Elevation 593 fixed spray zone IE heat detector relay discovered inoperable. Caused by random failure Relay replaced W/831011 ltr.
COLEY, S W, GREEN, H J Tennessee Valley Authority 83/10/11 O'REILLY, J P Region 2, Office of Director 3pp 20852: 071, 24X
Fiche 50-259, 83/10/11, 8310210226

DOCKETED ITEMS

55

- 8310250045 PND-11-83-084 licensee identified & reported to NRC that contractor welding svc employee received 59 mrem occupational overexposure during third Quarter 1983. Licensee reviewing all circumstances associated w/event DEBS, B., O'DONN, A F Region 2, Office of Director 83/10/20 1p 20896 085 24X Fiche 50-259, 83/10/20, 8310250045
- DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2
F Security, medical, emergency & fire protection plans
- 8310210032 Forwards IE Safeguards Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26 on 830706-07 & notice of violation Notice of violation withheld (ref 10CFR73 21) O'REILLY, J P Region 2, Office of Director 83/09/01 PARRIS, H G Tennessee Valley Authority 2pp 20895 320 24X Fiche 50-259, 83/09/01, 8310210032
- 8310210034 IE Safeguards Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26 on 830706-07 Noncompliance noted in area of access control - vital areas Details withheld (ref 10CFR73 21) MOORE, D E Region 2, Office of Director 83/07/27 1p 20895 322 24X Fiche 50-259, 83/09/01, 8310210032
- 8310040452 Submits central emergency control ctr Meteorological data availability statistics for Apr-June 1983 Data availability repts will be discontinued due to consistently high data availability through previous rept periods MILLS, L M Tennessee Valley Authority 83/09/28 ADENSAH, E Licensing Branch 4 2pp 20623 326 24X Fiche 50-000, 83/09/28, 8310040452
- 8310110195 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20682 113 24X Fiche 50-259, 83/10/05, 8310110195
- 8310110194 Forwards public version of revised emergency plan implementing procedures, including Procedures IP-3 re alert, IP-4 re site area emergency & IP-5 re general emergency MILLS, L M Tennessee Valley Authority 83/07/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20682 114 24X Fiche 50-259, 83/10/05, 8310110195
- 8310110203 Public version of revised emergency plan implementing procedures, including Procedures IP-3 re alert, IP-4 re site area emergency & IP-5 re general emergency WEBB, W E Tennessee Valley Authority 83/04/07 168pp 20682 115 24X Fiche 50-259, 83/10/05, 8310110195
- 8310310387 Forwards revs to security plan Revs withheld (ref 10CFR73 21) MILLS, L M Tennessee Valley Authority 83/10/06 O'REILLY, J P Region 2, Office of Director 1p 20959 327 24X Fiche 50-259, 83/10/06, 8310310387
- 8310170189 Forwards IE Safeguards Insp Repts 50-259/83-37, 50-260/83-37 & 50-296/83-37 on 830927-30 No noncompliance noted VERRELLI, D Division of Project & Resident Programs 83/10/12 PARRIS, H G Tennessee Valley Authority 2pp 20786 358 24X Fiche 50-259, 83/10/12, 8310170189
- 8310170238 IE Safeguards Insp Repts 50-259/83-37, 50-260/83-37 & 50-296/83-37 on 830927-30 No noncompliance noted Major areas inspected security organization & mgt & personnel response Details withheld (ref 10CFR73 21) MOORE, D E Region 2, Office of Director 83/10/11 1p 20786 360 24X Fiche 50-259, 83/10/12, 8310170189
- 8310240139 Forwards safety evaluation re proposed mods & alternate capabilities for achieving safe shutdown, per 10CFR50, App R, Sections III Q 3 & III L, fire protection rule Proposed mods acceptable VASSALLO, D B Operating Reactors Branch 2 83/10/12 PARRIS, H G Tennessee Valley Authority 2pp 20884 342 24X Fiche 50-259, 83/10/12, 8310240139
- 8310240141 Safety evaluation supporting proposed mods & alternate capabilities for achieving safe shutdown, per 10CFR50, App R, Sections III Q 3 & III L, fire protection rule * Office of Nuclear Reactor Regulation, Director 83/10/12 7pp 20884 344 24X Fiche 50-259, 83/10/12, 8310240139
- 8310210071 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26 O'REILLY, J P Region 2, Office of Director 83/10/17 PARRIS, H G Tennessee Valley Authority 1p 20898 192 24X Fiche 50-259, 83/10/17, 8310210071
- 8310210078 Responds to NRC 830901 ltr re violations noted in IE Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26 Corrective actions withheld (ref 10CFR73 21) MILLS, L M Tennessee Valley Authority 83/09/30 O'REILLY, J P Region 2, Office of Director 1p 20858 193 24X Fiche 50-259, 83/10/17, 8310210071
- 8310210362 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/10/17 Document Management Branch 1p 20883 001 24X Fiche 50-259, 83/10/17, 8310210362
- 8310210383 Forwards public version of revised emergency plan implementing procedures, including Muscle Shoals Emergency Ctr Implementing Procedure MSEC IP-9, "Emergency Radiological Monitoring Procedures" MILLS, L M Tennessee Valley Authority 83/10/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20883 002 24X Fiche 50-259, 83/10/17, 8310210362
- 8310210386 Public version of revised emergency plan implementing procedures, including Muscle Shoals Emergency Ctr Implementing Procedure MSEC IP-9, "Emergency Radiological Monitoring Procedures" * Tennessee Valley Authority 83/09/22 150pp 20883 003 24X Fiche 50-259, 83/10/17, 8310210362
- P Operating license stage documents & correspondence
- 8310060583 Comments on proposed design for compliance w/NUREG-0737, Item II K 3 13, "Separate HPCI & RCIC Initiation Levels" re automatic restart Proposal acceptable VASSALLO, D B Operating Reactors Branch 2 83/09/19 PARRIS, H G Tennessee Valley Authority 3pp 20661 204 24X Fiche 50-259, 83/09/19, 8310060583
- 8310070068 Requests submittal of final radiological effluent Tech Specs & offsite dose calculation manual within 30 days VASSALLO, D B Operating Reactors Branch 2 83/09/21 PARRIS, H G Tennessee Valley Authority 3pp 20671 334 24X Fiche 50-259, 83/09/21, 8310070068
- 8310110521 Forwards Amends 90, B6 & 59 to Licenses DPR-33, DPR-52 & DPR-68, respectively & safety evaluation Amends change Tech Specs to modify required surveillance interval for standby gas treatment sys CLARK, R J Operating Reactors Branch 2 83/09/28 PARRIS, H G Tennessee Valley Authority 3pp 20711 302 24X Fiche 50-259, 83/09/28, 8310110521
- 8310110536 Amends 90, B6 & 59 to Licenses DPR-33, DPR-52 & DPR-68, respectively, revising Tech Specs for testing standby gas treatment sys from once per yr to once per operating cycle VASSALLO, D B Operating Reactors Branch 2 83/09/28 12pp 20711 305 24X Fiche 50-259, 83/09/28, 8310110521
- 8310110551 Safety evaluation supporting Amends 90, B6 & 59 to Licenses DPR-33, DPR-52 & DPR-68, respectively * Office of Nuclear Reactor Regulation, Director 83/09/28 3pp 20711 317 24X Fiche 50-259, 83/09/28, 8310110521
- 8310240154 Forwards request for addl info re reactor protection sys power monitoring sys design mod, per 811030 request Model Tech Specs for electric power monitoring & analysis drawings not provided Submittal date requested VASSALLO, D B Operating Reactors Branch 2 83/10/12 PARRIS, H G Tennessee Valley Authority 3pp 20884 329 24X Fiche 50-259, 83/10/12, 8310240154
- 8310240243 Forwards SER & technical evaluation rept re NUREG-0737, Items I A 2 1 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B 4, "Training for Mitigating Core Damage" Requirements met VASSALLO, D B Operating Reactors Branch 2 83/10/12 PARRIS, H G Tennessee Valley Authority 4pp 20891 123 24X Fiche 50-259, 83/10/12, 8310240243
- 8208310352 "Improvements in Training & Requalification Programs As Required By TMI Action Items I A 2 1 & II B 4 for Browns Ferry Nuclear Plants, Units 1, 2 & 3," technical evaluation rept * Science Applications, Inc NRC-03-82-096 SA1-186-029-50 82/08/25 NRC - No Detailed Affiliation Given, 13pp 66280 216 24X Fiche 50-000, 83/10/12, 8310240243
- 8310280148 Forwards "Analysis of Vessel Wall Neutron Dosimeter From Browns Ferry Units 1, 2 & 3 Pressure Vessel," in response to NRC request for addl info to support util 830922 request to change Tech Specs TS 191 MILLS, L M Tennessee Valley Authority 83/10/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 17pp 20929 063 24X Fiche 50-259, 83/10/19, 8310280148

DOCKETED ITEMS

- 8310280150 "Analysis of Vessel Wall Neutron Dosimeter From Browns Ferry Unit 2 Pressure Vessel"
NORRIS, E B, LINDHOLM, U S Southwest Research Institute
7/9/09/30 26pp 20929 111 24X Fiche 50-259, 83/10/19, 8310280150
- G Inspection reports, IE Bulletins & correspondence
- 8310250229 Updates 830624 response to violations noted in IE Insp Repts 50-259/83-14, 50-260/83-14 & 50-296/83-14 Extension of schedule to eliminate backlog of CARs/DRs until 830901 requested
MILLS, L M Tennessee Valley Authority 83/08/08 O'REILLY, J P
Region 2, Office of Director 1p 20899 067 24X
Fiche 50-259, 83/08/08, 8310250229
- 8310210032 Forwards IE Safeguards Insp Repts 50-259/83-26, 50-260/83-24 & 50-296/83-26 on 830706-07 & notice of violation Notice of violation withheld (ref 10CFR73 21)
O'REILLY, J P Region 2, Office of Director 83/09/01 PARRIS, H G
Tennessee Valley Authority 2pp 20855 320 24X
Fiche 50-259, 83/09/01, 8310210032
- 8310210034 IE Safeguards Insp Repts 50-259/83-26, 50-260/83-24 & 50-296/83-26 on 830706-07 Noncompliance noted in area of access control - vital areas Details withheld (ref 10CFR73 21)
MOORE, D E Region 2, Office of Director MCQUIRE, D R Division of Engineering & Operational Programs 83/07/29 1p 20855 322 24X
Fiche 50-259, 83/09/01, 8310210032
- 8310040265 Ack receipt of 830824 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-24, 50-260/83-24 & 50-296/83-24
VERRELLI, D M Region 2, Office of Director 83/09/14 PARRIS, H G
Tennessee Valley Authority 1p 20613 123 24X
Fiche 50-259, 83/09/14, 8310040265
- 8310040271 Responds to NRC 830725 ltr re violations noted in IE Insp Repts 50-259/83-24, 50-260/83-24 & 50-296/83-24 Corrective actions LMF examiners barred from performing add'l intergranular stress corrosion cracking exams
MILLS, L M Tennessee Valley Authority 83/08/24 O'REILLY, J P
Region 2, Office of Director 3pp 20613 124 24X
Fiche 50-259, 83/09/14, 8310040265
- 8310040275 Forwards IE Insp Repts 50-259/83-24, 50-260/83-24 & 50-296/83-24 on 830621-24 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/07/25 PARRIS, H G
Tennessee Valley Authority 2pp 20613 127 24X
Fiche 50-259, 83/09/14, 8310040265
- 8310040283 IE Insp Repts 50-259/83-24, 50-260/83-24 & 50-296/83-24 on 830621-24 Noncompliance noted failure to follow IE Bulletin 83-02 for requiring documented training in intergranular stress corrosion cracking
COLEY, J L Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/07/21 6pp 20613 130 24X
Fiche 50-259, 83/09/14, 8310040265
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20734 022 24X Fiche 50-000, 83/09/26, 8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345
- 8310040487 Concurs w/corrective actions taken to rectify violations noted in IE Insp Repts 50-259/83-18, 50-260/83-18 & 50-296/83-18 Acceptable finding permits initiation of fuel movement in & out of core
O'REILLY, J P Region 2, Office of Director 83/09/26 PARRIS, H G
Tennessee Valley Authority 2pp 20625 165 24X
Fiche 50-259, 83/09/26, 8310040487
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Buss W/o 10CFR50 59 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 113pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349
- 8310250166 Ack receipt of 830924 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-27, 50-260/83-27 & 50-296/83-27
LEWIS, R C Division of Project & Resident Programs 83/10/04 PARRIS, H G
Tennessee Valley Authority 1p 20893 251 24X
Fiche 50-259, 83/10/04, 8310250166
- 8310250170 Responds to NRC 830824 ltr re violations noted in IE Insp Repts 50-259/83-27, 50-260/83-27 & 50-296/83-27 Corrective actions test pressure gauges removed, fuse identification program being established & panel 25-32 cleaned
MILLS, L M Tennessee Valley Authority 83/09/26 O'REILLY, J P
Region 2, Office of Director 9pp 20493 251 24X
Fiche 50-259, 83/10/04, 8310250166
- 8310250174 Forwards IE Insp Repts 50-259/83-27, 50-260/83-27 & 50-296/83-27 on 830626-0725 & notices of violation & deviation
LEWIS, R C Division of Project & Resident Programs 83/08/24 PARRIS, H G
Tennessee Valley Authority 2pp 20893 261 24X
Fiche 50-259, 83/10/04, 8310250166
- 8310250179 Notice of violation from insp on 830626-0725
* Region 2, Office of Director 83/08/24 3pp 20893 263 24X
Fiche 50-259, 83/10/04, 8310250166
- 8310250185 Notice of deviation from insp on 830626-0725
* Region 2, Office of Director 83/08/24 1p 20893 266 24X
Fiche 50-259, 83/10/04, 8310250166
- 8310250190 IE Insp Repts 50-259/83-27, 50-260/83-27 & 50-296/83-27 on 830626-0725 Noncompliance noted failure to meet requirements for operational safety & absence of safety wires on backup control ctr.
PAULK, G L Region 2, Office of Director CANTRELL, G Division of Project & Resident Programs 83/08/19 10pp 20893 267 24X
Fiche 50-259, 83/10/04, 8310250166
- 8308300378 IE Info Notice 83-65, "Surveillance of Flaw in R1D Bypass Loops Used in Westinghouse Plants" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378
- 8308300732 IE Info Notice 83-66, "Fatality at Argentine Critical Facility" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300732
- 8310250131 Ack receipt of 830816 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-11, 50-260/83-11 & 50-296/83-11
LEWIS, R C Division of Project & Resident Programs 83/10/07 PARRIS, H G
Tennessee Valley Authority 1p 20897 272 24X
Fiche 50-259, 83/10/07, 8310250131
- 8310250138 Responds to NRC 830726 ltr re violations noted in IE Insp Repts 50-259/83-11, 50-260/83-11 & 50-296/83-11 Corrective actions radiochemical lab manual revised to incorporate Reg Guide 4.15 interim guidance
MILLS, L M Tennessee Valley Authority 83/08/16 O'REILLY, J P
Region 2, Office of Director 3pp 20897 273 24X
Fiche 50-259, 83/10/07, 8310250131
- 8310250234 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-28, 50-260/83-28 & 50-296/83-28
VERRELLI, D M Division of Project & Resident Programs 83/10/07 PARRIS, H G
Tennessee Valley Authority 1p 20899 123 24X
Fiche 50-259, 83/10/07, 8310250234
- 8310250240 Responds to NRC 830701 ltr re violations noted in IE Insp Repts 50-259/83-28, 50-260/83-28 & 50-296/83-28 Corrective actions requirements for receipt insp of QA-level mail established & wire brushes marked
MILLS, L M Tennessee Valley Authority 83/09/30 O'REILLY, J P
Region 2, Office of Director 4pp 20899 124 24X
Fiche 50-259, 83/10/07, 8310250234
- 8310250247 Forwards IE Insp Repts 50-259/83-28, 50-260/83-28 & 50-296/83-28 on 830725-29 & 0808 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/09/01 PARRIS, H G
Tennessee Valley Authority 2pp 20899 128 24X
Fiche 50-259, 83/10/07, 8310250234
- 8310250259 IE Insp Repts 50-259/83-28, 50-260/83-28 & 50-296/83-28 on 830725-29 & 0808 Noncompliance noted failure of receiving insp to control welding filler metals & to establish positive controls for tools used on austenitic steel
COLEY, J L Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/08/29 7pp 20899 132 24X
Fiche 50-259, 83/10/07, 8310250234

DOCKETED ITEMS

57

8308300759 IE Info Notice 83-47, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, L L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-48, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, L L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

8310170189 Forwards IE Safeguards Insp Repts 50-259/83-37, 50-260/83-37 & 50-296/83-37 on 830927-30 No noncompliance noted
VERRELLI, D Division of Project & Resident Programs 83/10/12
PARRIS, H O Tennessee Valley Authority 2pp 20786 358 24X
Fiche 50-259,83/10/12,8310170189

--8310170238 IE Safeguards Insp Repts 50-259/83-37, 50-260/83-37 & 50-296/83-37 on 830927-30 No noncompliance noted Major areas inspected security organization & mgt & personnel response Details withheld (ref 10CFR73 21)
HOGUE, D C, MCQUIRE, D R Region 2, Office of Director 83/10/11
1p 20786 360 24X Fiche 50-259,83/10/12,8310170189

8310180551 Notification of 831021 meeting w/DWR licensees in Bethesda, MD to discuss Future Insps for intergranular stress corrosion cracking
MIRAGLIA, F J Assistant Director for Safety Assessment 83/10/14
EICHENHUT, D G Division of Licensing 5pp 20823 358 24X
Fiche 50 000,83/10/14,8310180551

8310210071 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26
O'REILLY, J P Region 2, Office of Director 83/10/17 PARRIS, H O
Tennessee Valley Authority 1p 20858 192 24X
Fiche 50-259,83/10/17,8310210071

--8310210078 Responds to NRC 830901 ltr re violations noted in IE Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26 Corrective actions withheld (ref 10CFR73 21)
MILLER, L M Tennessee Valley Authority 83/09/30 O'REILLY, J P
Region 2, Office of Director 1p 20858 193 24X
Fiche 50-259,83/10/17,8310210071

R Periodic operating reports & related correspondence

8310190186 Monthly operating repts for Aug 1983 W/830907 ltr
TINKM, T, JONES, Q T Tennessee Valley Authority 83/09/01 Office
of Resource Management, Director 40pp 20820 163 24X
Fiche 50-259,83/09/01,8310190186

S Reportable occurrences, LLRs & related correspondence

8310210327 Responds to FOIA request for all documents re significantly high rate of equipment failures for GE BWR/4 rated at 2.436 MW Forwards App A documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/07/28 HAFNER, B
Suffolk Nuclear Study Group 2pp 20002 223 24X
Fiche 50-000,83/07/28,8310210327

--8302180539 Discusses results of evaluation of LERs for Jul 1981 - Dec 1982, for BAP rept Quality & quantity of LERs within range of average BWR Facility
BEYFRIT, K V Reactor Operations Analysis Branch 83/02/09
LEWIS, R C Division of Project & Resident Programs 3pp
20882 257 24X Fiche 50-000,83/07/28,8310210327

8310030405 LER 83-050/03L-0 on 830823, while performing B14 2 B-57, RHR pump 2C cooler fan would not operate Caused by tripping of overload relay, GE Model CR124C028 Overload relay reset & surveillance instruction completed W/830921 ltr
CHRISTOPHER, W, GREEN, H J Tennessee Valley Authority 83/09/21
O'REILLY, J P Region 2, Office of Director 3pp 20593 145 24X
Fiche 50-260,83/09/21,8310030405

8310060380 LER 83-052/03L-0 on 830827, hydrogen analyzer B H2AN-76-104 found inoperable due to loss of flow Caused by residue collection in sensing line, causing inboard isolation valve to stick closed, Line blown W/830723 ltr
CHAMBERS, Q T, GREEN, H J Tennessee Valley Authority, 83/09/23
O'REILLY, J P Region 2, Office of Director 3pp 20646 059 24X
Fiche 50-260,83/09/23,8310060380

8310070301 Potential Part 21 rept re underrange characteristic of Model N-E11GM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office
of Inspection and Enforcement 11pp 20651 064 24X
Fiche 50-000,83/09/30,8310070301

8310140200 LER 83-053/03L-0 on 830907, during normal operation, while performing whole core low power range monitor calibr, P-1 indicated R factor less than required Caused by uncalibr monitor due to changes in reactor shape W/831004 ltr
SCHEIB, G N, GREEN, H J Tennessee Valley Authority 83/10/04
O'REILLY, J P Region 2, Office of Director 3pp 20761 244 24X
Fiche 50-260,83/10/04,8310140200

8310140127 Telecopy RD 83061 on 831004, hydrogen-oxygen analyzer sample pump B determined inoperable following notification from Metal Bellows Corp of generic deficiency Pump replaced w/ upgraded model in stock on 831005
JONES, Q T Tennessee Valley Authority 83/10/06 Region 2
Office of Director 2pp 20763 039 24X Fiche 50-260,83/10/06,8310140127

8310250360 Telecopy RD on 831013, routine analysis of 831007 scram revealed that 2-LT-B5-45A did not initiate trip when SDIV exceeded 50 gallons On 831014, testing of transmitter revealed slow & erratic response to measured variable
JONES, Q T Tennessee Valley Authority 83/10/14 Region 2,
Office of Director 1p 20898 093 24X Fiche 50-260,83/10/14,8310250360

8310270073 LER 83-054/03L-0 on 830916, west side scram discharge vol high water level switch LS-B5-45C would not reset following scram Caused by setpoint drift Switch recalibr W/831014 ltr
CHAMBERS, Q T, GREEN, H J Tennessee Valley Authority 83/10/14
O'REILLY, J P Region 2, Office of Director 3pp 20924 121 24X
Fiche 50-260,83/10/14,8310270073

8310250065 PNO-II-83-084 licensee identified & reported to NRC that contractor welding svc employee received 59 mrem occupational overexposure during Third Quarter 1983 Licensee reviewing all circumstances associated w/event
DEBS, B, O'BRIEN, A F Region 2, Office of Director 83/10/20 1p
20896 085 24X Fiche 50-259,83/10/20,8310250065

DOCKET 50-261 H B ROBINSON PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8310250322 Forwards IE Insp Rept 50-261/83-21 on 830709-0809 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/08/31
UTLEY, E E Carolina Power & Light Co 2pp 20897 349 24X
Fiche 50-261,83/08/31,8310250322

--8310250339 IE Insp Rept 50-261/83-21 on 830709-0809 Noncompliance noted failure to implement procedures for receipt of vendor documents
WEISE, B Region 2, Office of Director BEHIS, P Division of
Project & Resident Programs 83/08/30 12pp 20897 352 24X
Fiche 50-261,83/08/31,8310250322

8310040347 Requests update of encl info re layout of technical support ctrs & emergency operations facilities
VERRELLI, D M Division of Project & Resident Programs 83/09/12
UTLEY, E E Carolina Power & Light Co 17pp 20625 183 24X
Fiche 50-000,83/09/12,8310040347

8310110145 Forwards supplemental info to 830607 ltr re reactor coolant pump lube oil collection App R exemption request, per 830909 & 13 telcons, reflecting commitment to automatically actuate closed-head sys in lieu of manual actuation
CUTTER, A B Carolina Power & Light Co 83/10/05 VARQA, B A
Operating Reactors Branch 1 5pp 20666 282 24X
Fiche 50-261,83/10/05,8310110145

8310170520 Forwards IE Safeguards Insp Rept 50-261/83-29 on 830920-23 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/10/13
UTLEY, E E Carolina Power & Light Co 2pp 20784 239 24X
Fiche 50-261,83/10/13,8310170520

--8310170522 IE Safeguards Insp Rept 50-261/83-29 on 830920-23 No noncompliance noted Major areas inspected review of corrective actions to 830119 security response, records & barriers Details withheld (ref 10CFR73 21)
TOBIN, W, MCQUIRE, D R Region 2, Office of Director 83/10/12
1p 20784 241 24X Fiche 50-261,83/10/13,8310170520

DOCKETED ITEMS

8310310027 Application for amend to License DPR-23, incorporating radiological effluent Tech Specs & requirements to perform audits of emergency preparedness program & security plan
MCDUFFIE, M A Carolina Power & Light Co 83/10/25 VARGA, S A
Operating Reactors Branch 1 10pp 20966 028 24X
Fiche 50-261, 83/10/25, 8310310027

--8310310032 Proposed radiological effluent Tech Specs, incorporating requirements to perform audits of emergency preparedness program & security plan
* Carolina Power & Light Co 83/10/31 272pp 20966 038 24X
Fiche 50-261, 83/10/25, 8310310027

Q Adjudicatory correspondence

8310040473 Affidavit of RB Starkey re util answers to Hartsville Group first set of interrogatories Certificate of Svc encl
STARKEY, R B Carolina Power & Light Co 83/09/08 Hartsville
Group 3pp 20623 294 24X Fiche 50-261, 83/09/08, 8310040473

8310050447 Forwards D Basdelas 820429, 0504, 1203 & 14 correspondence to Commission re Hartsville Interrogatories 3-1, 3-2 & 3-3 w/o encls
KARMAN, M Hearing Branch 1 83/09/26 MARGULIES, M B, KLINE, J R, HETRICK, D L Atomic Safety and Licensing Board Panel 1p
20631 358 24X Fiche 50-261, 83/09/26, 8310050447

8310040282 Further answers to first set of interrogatories per 830901 1tr agreement Certificate of Svc encl
MORRIS, R E, PARSONS, R M, WEBSTER, B H Carolina Power & Light Co 83/09/30 Hartsville Group 19pp 20614 216 24X
Fiche 50-261, 83/09/30, 8310040282

8310040478 Affidavit of CR Dietz re util further answers to Hartsville Group first set of interrogatories Certificate of Svc encl
DIETZ, C R Carolina Power & Light Co 83/09/30 Hartsville
Group 3pp 20623 097 24X Fiche 50-261, 83/09/30, 8310040478

P Operating license stage documents & correspondence

8310030161 Advises that organizational changes for GA program & changes to FSARS & mgt capability rept will be forwarded when completed
UTLEY, E E Carolina Power & Light Co 83/09/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 20590 028 24X
Fiche 50-000, 83/09/13, 8310030161

8310040354 Summarizes 830821 meeting w/util re plans for restructuring corporate organization
O'REILLY, J P Region 2, Office of Director 83/09/22 UTLEY, E E
Carolina Power & Light Co 2pp 20620 331 24X
Fiche 50-000, 83/09/22, 8310040354

8310070406 Forwards SER re util 791231 submittal concerning design of RCS vents Vent sys in conformance w/guidelines of NUREG-0737, Item 11.9.1 item closed
VARGA, S A Operating Reactors Branch 1 83/09/23 UTLEY, E E
Carolina Power & Light Co 14pp 20676 330 24X
Fiche 50-261, 83/09/23, 8310070406

310060347 Forwards safety evaluation of util 81119 response to Generic Ltr 81-21, "Natural Circulation Cooldown"
Reasonable assurance exists that steam formation at reactor vessel upper head will not occur during cooldown
VARGA, S A Licensing Branch 1 83/09/27 UTLEY, E E Carolina
Power & Light Co 2pp 20662 310 24X Fiche 50-261, 83/09/27, 8310060347

310060352 Safety evaluation supporting util 81119 response to Generic Ltr 81-21, "Natural Circulation Cooldown"
* MRC - No Detailed Affiliation Given 83/09/27 8pp
20662 312 24X Fiche 50-261, 83/09/27, 8310060347

0060413 Forwards "HB Robinson Fluence Reduction Analysis for Partial-Length Shield Assembly Concept," documenting results of flux reduction program to resolve pressurized thermal shock issue
UTTER, A B Carolina Power & Light Co 83/09/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20641 291
24X Fiche 50-261, 83/09/30, 8310060413

310060418 "HB Robinson Fluence Reduction Analysis for Partial-Length Shield Assembly Concept"
* Technology for Energy Corp * Carolina Power & Light Co R-83-030 83/09/30 198pp 20641 293 24X Fiche 50-261, 83/09/30, 8310060413

0180174 "Robinson Unit 2 Steam Generator Replacement Study for OI and Proceeding," Certificate of Svc encl
Carolina Power & Light Co 83/09/30 43pp 20809 195 24X
Fiche 50-261, 83/09/30, 8310180174

8310120407 Forwards nonproprietary rept & Suppl 1 to "HB Robinson Unit 2, Cycle 10 SAR" Also forwards proprietary "ECGB & Plant Transient Analyses" & "Mechanical Design Rept" Repts withheld (ref 10CFR2790)
UTLEY, E E Carolina Power & Light Co 83/10/05 VARGA, S A
Operating Reactors Branch 1 14pp 20697 176 24X
Fiche 50-261, 83/10/05, 8310120407

--8310120415 Nonproprietary "HB Robinson Unit 2, Cycle 10 SAR"
STONE, I Z, ADAMS, F T, LAMBERT, W L Exxon Nuclear Co, Inc
(subs of Exxon Corp) XN-NF-83-72 83/09/01 37pp 20697 180
24X Fiche 50-261, 83/10/05, 8310120407

--8310120422 Nonproprietary Suppl 1 to "HB Robinson Unit 2, Cycle 10 SAR"
STONE, I Z, ADAMS, F T, LAMBERT, W L Exxon Nuclear Co, Inc
(subs of Exxon Corp) XN-NF-83-72 801 83/09/14 20pp
20697 227 24X Fiche 50-261, 83/10/05, 8310120407

8310210046 Application for amend to License DPR-23, incorporating new heatup & cooldown limitation curves
MCDUFFIE, M A Carolina Power & Light Co 83/10/14 VARGA, S A
Operating Reactors Branch 1 2pp 20855 306 24X
Fiche 50-261, 83/10/14, 8310210046

--8310210048 Proposed Tech Specs revising heatup & cooldown limitation curves
* Carolina Power & Light Co 83/10/14 7pp 20855 300 24X
Fiche 50-261, 83/10/14, 8310210046

8310210245 Application to amend License DPR-23 revising Tech Specs to clarify qualification requirements for alternate members of plant nuclear safety committee
MCDUFFIE, M A Carolina Power & Light Co 83/10/14 VARGA, S A
Operating Reactors Branch 1 2pp 20851 277 24X
Fiche 50-261, 83/10/14, 8310210245

--8310210246 Proposed Tech Spec changes clarifying qualification requirements for alternate members of plant nuclear safety committee
* Carolina Power & Light Co 83/10/14 23pp 20851 274 24X
Fiche 50-261, 83/10/14, 8310210245

8310240126 Reviews DES Alternative 1 preferable Rating of LO-1 assigned since no significant adverse environ consequences anticipated
MOORE, S N Environmental Protection Agency 83/10/19 RLOVA, C
Office of Nuclear Reactor Regulation, Director 1p 20801 151 24X
Fiche 50-261, 83/10/19, 8310240126

8310270292 Advises that review of DES re repair of steam generators & resulted in no comments
O'RESHAM, B C Transportation, Dept of, Federal Highway
Administration 83/10/24 Division of Licensing 1p 20763 321
24X Fiche 50-261, 83/10/24, 8310270292

8310310027 Application for amend to License DPR-23, incorporating radiological effluent Tech Specs & requirements to perform audits of emergency preparedness program & security plan
MCDUFFIE, M A Carolina Power & Light Co 83/10/25 VARGA, S A
Operating Reactors Branch 1 10pp 20966 028 24X
Fiche 50-261, 83/10/25, 8310310027

--8310310032 Proposed radiological effluent Tech Specs, incorporating requirements to perform audits of emergency preparedness program & security plan
* Carolina Power & Light Co 83/10/31 272pp 20966 038 24X
Fiche 50-261, 83/10/25, 8310310027

Q Inspection reports, IE Bulletins & correspondence

8310250322 Forwards IE Insp Rept 50-261/83-21 on 830709-0809 & notice of violation
VERRELL, D M Division of Project & Resident Programs 83/08/31
UTLEY, E E Carolina Power & Light Co 2pp 20897 344 24X
Fiche 50-261, 83/08/31, 8310250322

--8310250329 Notice of violation from insp on 830709-0809
* Region 2, Office of Director 83/08/31 1p 20897 351 24X
Fiche 50-261, 83/08/31, 8310250322

--8310250339 IE Insp Rept 50-261/83-21 on 830709-0809 Noncompliance noted failure to implement procedures for receipt of vendor documents
WEISE, S Region 2, Office of Director BEMIS, P Division of
Project & Resident Programs 83/08/30 12pp 20897 332 24X
Fiche 50-261, 83/08/31, 8310250322

DOCKETED ITEMS

59

8310040037 Forwards IE Insp Rept 50-261/83-23 on 830815-19 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/09/02
UTLEY, E E Carolina Power & Light Co 2pp 20608 125 24X
Fiche 50-261,83/09/02,8310040037

--8310040043 IE Insp Rept 50-261/83-23 on 830815-19 No noncompliance noted Major areas inspected licensee action on previous enforcement matters, GA program annual review, improvement program, test & experiment program & audit program
DEBBAGE, A G, UPRIGHT, C M Region 2, Office of Director 83/08/31 11pp 20608 127 24X Fiche 50-261,83/09/02,8310040037

8310040166 Forwards IE Insp Rept 50-261/83-17 on 830725-29 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/09/07
UTLEY, E E Carolina Power & Light Co 2pp 20608 044 24X
Fiche 50-261,83/09/07,8310040166

--8310040168 IE Insp Rept 50-261/83-17 on 830725-29 No noncompliance noted Major areas inspected corrective action for previous violations, transportation of radioactive materials, breathing air line contamination event & posting, labeling & control
ALBRIGHT, R H, BARR, K P Region 2, Office of Director 83/09/02 8pp 20608 046 24X Fiche 50-261,83/09/07,8310040166

8310040269 Ack receipt of 830901 ltr requesting extension to complete corrective actions in response to violations noted in IE Insp Rept 50-261/82-20
LEWIS, R C Division of Project & Resident Programs 83/09/13
UTLEY, E E Carolina Power & Light Co 1p 20614 06B 24X
Fiche 50-261,83/09/13,8310040269

--8310040285 Amends response to NRC 820820 ltr re violations noted in IE Insp Rept 50-261/82-20 Completion of flow diagrams & corresponding procedures for Q-list portion of sys extended to 831231
STARKEY, R B Carolina Power & Light Co 83/09/01 O'REILLY, J P Region 2, Office of Director 2pp 20614 069 24X
Fiche 50-261,83/09/13,8310040269

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

8310170520 Forwards IE Safeguards Insp Rept 50-261/83-29 on 830920-23 No noncompliance noted
VERRELLI, D Division of Project & Resident Programs 83/10/13
UTLEY, E E Carolina Power & Light Co 2pp 20784 239 24X
Fiche 50-261,83/10/13,8310170520

--8310170522 IE Safeguards Insp Rept 50-261/83-29 on 830920-23 No noncompliance noted Major areas inspected review of corrective actions to 820114 security response, records & barriers Details withheld (ref 10CFR73 21)
TOBIN, W, MCQUIRE, D R Region 2, Office of Director 83/10/12, 1p 20784 241 24X Fiche 50-261,83/10/13,8310170520

8310190162 Forwards proposed scope of 4 5 EFPM eddy current insp program scheduled to begin on 831210 Scope includes insp of all unplugged tubes
ZIMMERMAN, S R Carolina Power & Light Co 83/10/17 VARQA, S A Operating Reactors Branch 1 4pp 20821 058 24X
Fiche 50-261,83/10/17,8310190162

8310250588 Ack receipt of supplemental 830930 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/83-15
VERRELLI, D M Division of Project & Resident Programs 83/10/17
UTLEY, E E Carolina Power & Light Co 1p 20900 090 24X
Fiche 50-261,83/10/17,8310250588

--8310250596 Suppls response to NRC 830824 ltr re violations noted in IE Insp Rept 50-261/83-15 Corrective actions six capped instrument tubes & respective caps in Sleeve 18 fitted w/shrink tubing so operators could identify cap tampering
MORGAN, R E Carolina Power & Light Co 83/09/30 O'REILLY, J P Region 2, Office of Director 2pp 20900 091 24X
Fiche 50-261,83/10/17,8310250588

--8310250601 Ack receipt of 830812 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/83-15
VERRELLI, D M Division of Project & Resident Programs 83/08/24
UTLEY, E E Carolina Power & Light Co 1p 20900 093 24X
Fiche 50-261,83/10/17,8310250588

--8310250608 Responds to NRC 830115 ltr re violations noted in IE Insp Rept 50-261/83-15 Corrective actions daily check of low temp overpressure protection sys nitrogen pressure when sys required operable proceduralized in min equipment list
STARKEY, R B Carolina Power & Light Co 83/08/12 O'REILLY, J P Region 2, Office of Director 3pp 20900 094 24X
Fiche 50-261,83/10/17,8310250588

--8310250618 Forwards IE Insp Rept 50-261/83-15 on 830510-0610 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/07/15
UTLEY, E E Carolina Power & Light Co 2pp 20900 099 24X
Fiche 50-261,83/10/17,8310250588

--8310250620 Notice of violation from insp on 830510-0610
* Division of Project & Resident Programs 83/07/15 2pp, 20900 101 24X Fiche 50-261,83/10/17,8310250588

--8310250627 IE Insp Rept 50-261/83-15 on 830510-0610 Noncompliance noted failure to take adequate corrective action re backup nitrogen pressure & failure to establish adequate procedures re instrument tubing lines
WEISE, S Region 2, Office of Director BEMIS, P Division of Project & Resident Programs 83/07/06 13pp 20900 103 24X
Fiche 50-261,83/10/17,8310250588

8310250571 Comments on detection of deficiencies in quality resulting from suppliers fraudulent actions, described in IE Info Notices 83-07 & 83-01 & IC Bulletins 83-06 & 83-07 Use of addl insp & testing during receipt insps investigated
MCDOUFFIE, M A Carolina Power & Light Co 83/10/21 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 20900 347 24X Fiche 50-000,83/10/21,8310250571

8 Reportable occurrences, LERs & related correspondence

8310030426 RO on 830916, Tech Spec instantaneous release limit for radioiodine exceeded Investigation continuing
MORGAN, R E Carolina Power & Light Co 83/09/19 O'REILLY, J P Region 2, Office of Director 1p 20593 180 24X
Fiche 50-261,83/09/19,8310030426

8310040516 RO on 830926, svc water leak discovered on containment fan cooler HVH-2 Cooler declared inoperable Repairs initiated Event considered degradation of containment boundary per IE Bulletin 80-24
MORGAN, R E Carolina Power & Light Co 83/09/27 O'REILLY, J P Region 2, Office of Director 1p 20623 092 24X
Fiche 50-261,83/09/27,8310040516

DOCKETED ITEMS

8310070308 RD on 830928, svc water leak discovered on containment fan cooler HVH-2 Event considered degradation of containment boundary per IE Bulletin 80-24
MORGAN, R E Carolina Power & Light Co 83/09/29 O'REILLY, J P
Region 2, Office of Director 1p 20652 214 24X
Fiche 50-261, 83/09/29, 8310070308

8310070136 Updated LER 80-030/031-1 on 801202 & 03, charging pumps A,B & C discharge line pressure gauge tap pipe sockets found leaking Caused by svx design deficiencies allowing high vibration Leaks repaired & design modified W/830930 ltr
WRIGHT, C L, MORGAN, R E Carolina Power & Light Co 83/09/30
O'REILLY, J P Region 2, Office of Director App 20659 064 24X
Fiche 50-261, 83/09/30, 8310070136

8310070322 LER 83-024/01T-0 on 830916, Tech Spec instantaneous release limit for radioiodine exceeded through plant stack Cause not stated Equipment which provided pathway shut down Iodine level remained normal during testing W/830930 ltr
MORGAN, R E, WRIGHT, C L Carolina Power & Light Co 83/09/30
O'REILLY, J P Region 2, Office of Director App 20652 148 24X
Fiche 50-261, 83/09/30, 8310070322

8310170541 LER 83-025/01T-0 on 830926, svc water leak discovered on containment fan cooler HVH-2 Svc water isolated & unit declared inoperable Caused by corrosion/erosion of coolant tubing Tube bundle repaired W/831010 ltr
WRIGHT, C L, MORGAN, R E Carolina Power & Light Co 83/10/10
O'REILLY, J P Region 2, Office of Director 3pp 20782 100 24X
Fiche 50-261, 83/10/10, 8310170541

DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT

Security, medical, emergency & fire protection plans

10060573 Forwards exemption from 10CFR50 48(c) scheduler requirements, per 820630, 830608 & 0422 requests
VASSALLO, D B Operating Reactors Branch 2 83/09/21 MUSOLF, D M
Northern States Power Co 3pp 20661 83/ 24X
Fiche 50-263, 83/09/21, 8310060573

-8310060576 Exemption from 10CFR50 48(c) scheduler requirements, per 820630, 830608 & 0422 requests Implementation dates for 10CFR50 48(c)(2) & (c)(3) extended 9 months & to before startup of Cycle 12, respectively
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/09/21 Northern States Power Co 7pp 20661 240 24X
Fiche 50-263, 83/09/21, 8310060576

8310070157 Notification of 831012 meeting w/util & consultants in Bethesda, MD to discuss design basis for alternate safe shutdown capability
NICOLARAS, H Licensing Branch 2 83/10/03 VASSALLO, D B
Licensing Branch 2 2pp 20680 304 24X Fiche 50-263, 83/10/03, 8310070157

831010176 Releases public version of revised emergency response plan implementing procedures
FELTON, J M Division of Rules and Records, 83/10/09 Document
Management Branch 1p 20703 286 24X Fiche 50-263, 83/10/09, 831010176

10101080 Forwards public version of revised emergency plan implementing procedures, including Procedures A 2-001 re emergency organization, A 2-204 re offsite protective action recommendations & A 2-304 re thyroid prophylaxis
FEY, F L Northern States Power Co 83/09/13 Region 3, Office of Director 1p 20703 287 24X Fiche 50-263, 83/10/09, 831010176

10101084 Public version of revised emergency plan implementing procedures, including Procedures A 2-001 re emergency organization, A 2-204 re offsite protective action recommendations & A 2-304 re thyroid prophylaxis
HATHAU, C Northern States Power Co 83/09/01 58pp 20703 288 24X Fiche 50-263, 83/10/05, 831010176

0120267 Ack receipt of 830614, 17 & 0728 ltrs forwarding changes to ev & to corporate emergency plan & Rev 3 to plant emergency changes acceptable, per 10CFR50 54(a) requirements
O'REILLY, J P Region 3, Office of Director 83/10/06
SDN, C E Northern States Power Co 1p 20690 348 24X
he 50-000, 83/10/06, 8310120267

50538 Forwards final SALP 4 Rept 50-263/83-17 for Jul 1982 - June 83
PLEER, J O Region 3, Office of Director 83/10/20, LARSDON, C E
thern States Power Co 2pp 20902 143 24X
he 50-000, 83/10/20, 8310250538

--8310250542 Final SALP 4 Rept 50-263/83-17 for Jul 1982 - June 1983
* Region 3, Office of Director 83/10/20 27pp 20902 143 24X
Fiche 50-000, 83/10/20, 8310250538

--8310250550 Forwards summary of significant findings in SALP Rept 50-263/83-17 for Jul 1982 - June 1983 to be discussed at 830921 meeting
HIND, J A Division of Radiological & Materials Safety Programs
83/09/14 GILBERTS, D E Northern States Power Co 3pp
20902 172 24X Fiche 50-000, 83/10/20, 8310250538

8310260431 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/21 Document
Management Branch 1p 20926 253 24X Fiche 50-263, 83/10/21, 8310260431

--8310260435 Forwards public version of revised Emergency Plan Implementing Procedures A 2-101 re classification of emergencies, A 2-105 re general emergency & A 2-702 re response to emergency at Prairie Island
FEY, F L Northern States Power Co 83/10/17 Region 3, Office of Director App 20926 254 24X Fiche 50-263, 83/10/21, 8310260431

--8310260438 Public version of revised Emergency Plan Implementing Procedures A 2-101 re classification of emergencies, A 2-105 re general emergency & A 2-702 re response to emergency at Prairie Island
* Northern States Power Co 83/09/26 70pp 20926 254 24X
Fiche 50-263, 83/10/21, 8310260431

H General correspondence

8310120432 Informs of DE Nevinski promotion to plant superintendent, engineering & radiation protection Tech Spec Figure 6.1.2 will be revised
MUSOLF, D Northern States Power Co 83/10/04 Office of Nuclear
Reactor Regulation, Director 1p 20698 277 24X
Fiche 50-263, 83/10/04, 8310120432

J Insurance & indemnity information

8310250237 Forwards Endorsements 56 & 57 to MAELU Policy MF 71 & Endorsements 68 & 69 to NELIA Policy NF-174 for Monticello & Endorsements 48 & 49 to MAELU Policy MF-68 & Endorsements 56 & 57 to NELIA Policy NF-197 for Prairie Island
JOHNSON, R G Northern States Power Co 83/10/20 DUNITZ, J
Division of Engineering 9pp 20899 036 24X Fiche 50-000, 83/10/20, 8310250237

P Operating license stage documents & correspondence

8310040572 Forwards responses to 830728 request for addl info requires to resolve open items in Franklin Research Ctr technical evaluation re:pt on control of heavy loads Info on Sections 2a & 2b re turbine bldg crans to be submitted by 831024
MUSOLF, D Northern States Power Co 83/09/27 Office of Nuclear
Reactor Regulation, Director 3pp 20622 270 24X
Fiche 50-263, 83/09/27, 8310040572

8310040586 Forwards request for addl info needed to review 831024 request to allow min source range monitor channel count to drop below three counts per second when entire reactor core removed or replaced Info due within 30 days
VASSALLO, D B Operating Reactors Branch 2 83/09/27 MUSOLF, D M
Northern States Power Co 3pp 20661 201 24X
Fiche 50-263, 83/09/27, 8310040586

8310060216 Submits info on single loop operation issues ident & #3 & 4 during NRC review of 820702 Tech Spec change request, per NRC/LLL 830926 telcon Multiple setpoints will not be used
MUSOLF, D Northern States Power Co 83/09/29 Office of Nuclear
Reactor Regulation, Director 2pp 20647 023 24X
Fiche 50-263, 83/09/29, 8310060216

8310070311 Forwards Rev 1 to request for amend to License DFR 2nd. change, changing setpoint proposed for shutdown cooling isolation logic & revising wording proposed for jet pump surveillance
MUSOLF, D Northern States Power Co 83/09/29 Office of Nuclear
Reactor Regulation, Director 1p 20652 193 24X
Fiche 50-263, 83/09/29, 8310070311

--8310070314 Rev 1 to application for amend to License DFR 2nd. change, setpoint proposed for shutdown cooling isolation logic & revising wording for jet pump surveillance
* Northern States Power Co 83/09/29 3pp 20652 194 24X
Fiche 50-263, 83/09/29, 8310070311

DOCKETED ITEMS

61

--B310070316 Proposed Tech Spec changing setpoint for shutdown cooling isolation logic & revising wording for jet pump surveillance
* Northern States Power Co 83/09/29 6pp 2065, 197 24X
Fiche 50-263, 83/09/29, B310070311

B310240149 Forwards notice of consideration of issuance of amend to License DPR-22 & opportunity for prior hearing re B20/02 application changing tech specs to allow operation w/one recirculation loop out of svc
NICHOLAS, H Operating Reactors Branch 2 83/10/05 MUSOLF, D M Northern States Power Co 2pp 20884 334 24X
Fiche 50-263, 83/10/05, B310240149

- B310240152 Notice of consideration of issuance of amend to License DPR-22, revising Tech Specs to incorporate revised safety & operating limits associated w/operation w/one recirculation loop out of svc
VASSALLO, D M Operating Reactors Branch 2 83/10/05 5pp 20884 334 24X Fiche 50-263, 83/10/05, B310240149

Q Inspection reports, IE Bulletins & correspondence

B310070340 IE Info Notice B3-61, "Alleged Use of Stand-Ins For Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/26 Consolidated Edison Co of New York, Inc 11pp 20754 022 24X Fiche 50-000, 83/09/26, B308100340

B310070342 IE Info Notice B3-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intake " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/26 Consolidated Edison Co of New York, Inc 11pp 20777 210 24X Fiche 50-000, 83/09/26, B308300342

B310070345 IE Info Notice B3-63, "Potential Failures of Westinghouse Type SA 1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/26 Consolidated Edison Co of New York, Inc 11pp 20778 001 24X Fiche 50-000, 83/09/26, B308300345

B310070349 IE Info Notice B3-64, "Lead Shielding Attached to Safety-Related Bus W/o ICRHSO 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/29 Consolidated Edison Co of New York, Inc 11pp 20716 324 24X Fiche 50-000, 83/09/29, B308300349

B310170476 Forwards IE Insp Rept 50-263/B3-16 on B30802 0901 No noncompliance noted
SHAFFER, W D Region 3, Office of Director 83/09/29 LARSON, C E Northern States Power Co 2pp 20784 24/ 24X
Fiche 50-263, 83/09/29, B310170476

--B310170403 IE Insp Rept 50-263/B3-16 on B30802-0901 No noncompliance noted Major items inspected operational safety verification, onsite review committee, degraded voltage relay, traversing in-core probe sys squib valve firing & Part 21 rept
BROWN, C H ; WALKER, R D Region 3, Office of Director 83/09/21 App 20784 249 24X Fiche 50-263, 83/09/29, B310170476

B310100770 IE Info Notice B3-65, "Surveillance of Flow in RTU Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/07 Consolidated Edison Co of New York, Inc 74pp 20827 213 24X Fiche 50-000, 83/10/07, B308300378

B308300752 IE Info Notice B3-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, B308300752

B308300759 IE Info Notice B3-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/11 Consolidated Edison Co of New York, Inc 11pp 21043 075 24X Fiche 50-000, 83/10/11, B308300759

B308300761 IE Info Notice B3-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 124 24X Fiche 50-000, 83/10/11, B308300761

B310180288 Clarifies procedures for admitting NRC personnel to Facilities Access list identifying authorized clearances encl Update will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 LARSON, C E Northern States Power Co 7pp 20804 275 24X
Fiche 50-263, 83/10/14, B310180288

B310180551 Notification of B31021 meeting w/BWR licensees in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking
MIRAGLIA, J Assistant Director for Safety Assessment 83/10/14 EISENHUT, D G Division of Licensing 5pp 20823 356 24X
Fiche 50-000, 83/10/14, B310180551

B310250538 Forwards final SALP 4 Rept 50-263/B3-17 for Jul 1982 - June 1983
KEPPLER, J G Region 3, Office of Director 83/10/20 LARSON, C E Northern States Power Co 2pp 20902 143 24X
Fiche 50-000, 83/10/20, B310250538

--B310250542 Final SALP 4 Rept 50-263/B3-17 for Jul 1982 - June 1983
* Region 3, Office of Director 83/10/20 27pp 20902 145 24X
Fiche 50-000, 83/10/20, B310250538

--B310250550 Forwards summary of significant findings re SALP Rept 50-263/B3-17 for Jul 1982 - June 1983 to be discussed at B30921 meeting
HIND, J A Division of Radiological & Materials Safety Programs 83/09/14 GILBERTS, D E Northern States Power Co 3pp 20902 172 24X Fiche 50-000, 83/10/20, B310250538

--B310250561 Submits comments on B30921 meeting w/NRC to discuss SALP Rept 50-263/B3-17 for Jul 1982 - June 1983 Valuable insights gained on improving performance
GILBERTS, D E Northern States Power Co 83/09/30 KEPPLER, J G Region 3, Office of Director 1p 20902 175 24X
Fiche 50-000, 83/10/20, B310250538

R Periodic operating reports & related correspondence

B310190021 Monthly operating rept for Aug 1983 W/B30908 ltr
MYRABO, A L ; MUSOLF, D Northern States Power Co 83/09/01 Office of Resource Management, Director 5pp 20823 135 24X
Fiche 50-263, 83/09/01, B310190021

S Reportable occurrences, LERs & related correspondence

B310270340 FOIA request for placement of listed LERs in PDR
GRABER, L D NUS Corp 83/09/08 Division of Rules and Records 2pp 20938 05B 24X Fiche 50-000, 83/09/08, B310270340

B310070272 Forwards outline of proposed procedure for reanalysis of adequacy of station electric distribution sys voltages, as discussed at B30913 meeting w/NRC re B30801 actuation of degraded voltage protection logic
MUSOLF, D Northern States Power Co 83/09/26 Office of Nuclear Reactor Regulation, Director App 20656 353 24X
Fiche 50-263, 83/09/26, B310070272

B310270347 Responds to FOIA request for release of 23 LERs to PDR Forwards 12 LERs to be released Documents also available in PDR One LER canceled Eight LERs not received
FELTON, J M Division of Rules and Records 83/09/29 GRABER, L D NUS Corp 1p 20938 060 24X Fiche 50-000, 83/09/29, B310270347

--B310270359 LER B3-002/03L-0 on B30109, power loss in RCIC governor control sys occurred Caused by failed Pacific Electric 70-watt resistor Resistor replaced w/improved design W/B30204 ltr
TOLLERSON, J L ; MUSOLF, D Northern States Power Co 83/02/08 Region 3, Office of Director 3pp 20938 065 24X
Fiche 50-000, 83/09/29, B310270347

--B310270364 LER B3-003/03L-0 on B30207, RHR loop B made inoperable due to unobtainable RHR 12 HX differential pressure Caused by piston ring wear Graphite rings replaced w/spring loaded Teflon rings W/B30709 ltr
CARPENTER, G L ; MUSOLF, D Northern States Power Co 83/03/09 Region 3, Office of Director 3pp 20938 068 24X
Fiche 50-000, 83/09/29, B310270347

--B310270390 LER B3-007/03L-0 on B30411, essential motor control ctr 133 feeder breaker tripped Caused by drifted right phase overcurrent trip device Device replaced & breaker reclosed & replaced W/B30511 ltr
MUSOLF, D Northern States Power Co 83/05/11 Region 3, Office of Director 3pp 20938 074 24X Fiche 50-000, 83/09/29, B310270347

DOCKETED ITEMS

- B310270410 LER B3-008/03L-0 on B30413, leak in feedwater heater extraction steam trip outlet pipe 15A found caused by steam erosion. Leaking pipe section replaced & erosion program will be accelerated & amended W/B30516 ltr
MAIER, P., MUSOLF, D. Northern States Power Co. B3/05/13 Region 3, Office of Director 3pp 20938 077 24X Fiche 50-000, B3/09/29, B310270347
- B310270414 LER B3-009/01T-0 on B30504, HPCI Woodward Governor EGR hydraulic actuator coil discovered grounded caused by faulty wire lead insulation. Emergency generator reactor & HPCI lube oil replaced. Sample being analyzed W/B30518 ltr
WOJCZOWSKI, A V., MUSOLF, D. Northern States Power Co. B3/05/18 Region 3, Office of Director 3pp 20938 080 24X Fiche 50-000, B3/09/29, B310270347
- B310210257 Forwards detailed followup re: Number 14 bus transfer to emergency diesel generator on undervoltage on B30801, per B30831 confirmatory action ltr. Process computer alarm points reset to provide alarm at action point level
MUSOLF, D. Northern States Power Co. B3/10/14 Office of Nuclear Reactor Regulation, Director 2pp 20851 226 24X Fiche 50-263, B3/10/14, B310210257
- B310270283 LER B3-020/03L-0 on B30920, diesel generator 11 turbocharger auxiliary lube oil pump motor bearing failed. Cause not stated. Pump-motor assembly replaced W/B31019 ltr
KOLB, M. H., MUSOLF, D. Northern States Power Co. B3/10/19 Region 3, Office of Director 2pp 20923 259 24X Fiche 50-263, B3/10/19, B310270283
- V Operator Examinations
- B310070238 Requests extension to B40215 for implementation of licensed operator staffing requirements
MUSOLF, D. Northern States Power Co. B3/09/29 Office of Nuclear Reactor Regulation, Director 3pp 20659 119 24X Fiche 50-263, B3/09/29, B310070238
- DOCKET 50-265 QUAD CITIES STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- B310140261 Forwards IE Insp Repts 50-254/B3-26 & 50-265/B3-25 on B30822-26 & 31 & 0909 & notice of violation
HIND, J. A. Division of Radiological & Materials Safety Programs B3/09/29 REED, C. Commonwealth Edison Co. 2pp 20762 040 24X Fiche 50-254, B3/09/29, B310140261
- B310140264 Notice of violation from Insp on B30822-26 & 31 & 0909
HIND, J. A. Division of Radiological & Materials Safety Programs B3/09/29 2pp 20762 050 24X Fiche 50-254, B3/09/29, B310140261
- B310140271 IE Insp Repts 50-254/B3-26 & 50-265/B3-25 on B30822-26 & 31 & 0909 Noncompliance noted failure to distribute controlled emergency plan procedure revs to NRC
PHILLIPS, M. P. Region 3, Office of Director B3/09/29 17pp 20762 032 24X Fiche 50-254, B3/09/29, B310140261
- B310060341 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records B3/09/30 Document Management Branch 1p 20662 001 24X Fiche 50-254, B3/09/30, B310060341
- B310060345 Public version of revised emergency plan implementing procedures, including Procedures GEP 550-0 re emergency equipment & supplies & GEP 550-T4 re emergency operations facility supplies
KOVACK, T. J., GERNER, L. Commonwealth Edison Co. B3/09/08 300pp 20662 002 24X Fiche 50-254, B3/09/30, B310060341
- B31010325 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records B3/10/05 Document Management Branch 1p 20685 231 24X Fiche 50-254, B3/10/05, B31010325
- B31010327 Public version of revised Emergency Plan Implementing Procedures GEP 110-2 re acting station director (shift director) & Procedure GEP 310-1 re initial notification
TIETZ, O. Commonwealth Edison Co. B3/09/08 24pp 20685 235 24X Fiche 50-254, B3/10/05, B31010325
- 10200079 Releases public version of revised emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records B3/10/14 Document Management Branch 1p 20844 218 24X Fiche 50-254, B3/10/14, B310200079
- B310200082 Public version of Rev 2 to Emergency Plan Implementing Procedure GEP 450-1, "Environment Surveillance Stations"
KOVACK, T. J., CARSON, R. Commonwealth Edison Co. B3/09/28 4pp 20844 219 24X Fiche 50-254, B3/10/14, B310200079
- B310270024 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records B3/10/21 Document Management Branch 1p 20940 199 24X Fiche 50-254, B3/10/21, B310270024
- B310270028 Forwards public version of revised emergency plan implementing procedures, including Procedures GEP 550-1 re first aid & decontamination facilities & GEP 550-T1 re environ sampling supplies
TIETZ, O., GERNER, L. Commonwealth Edison Co. B3/10/06 24pp 20940 200 24X Fiche 50-254, B3/10/21, B310270024
- B310270032 Public version of revised emergency plan implementing procedures, including Procedures GEP 550-1 re first aid & decontamination facilities, GEP 550-2 re emergency equipment inventory & GEP 550-T1 re environ sampling supplies
Commonwealth Edison Co. B3/10/06 24pp 20940 202 24X Fiche 50-254, B3/10/21, B310270024
- B310270526 Releases public version of revised emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records B3/10/21 Document Management Branch 1p 20937 216 24X Fiche 50-000, B3/10/21, B310270526
- B310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure EOI-6, "Administration & Logistics Manager"
W/B31011 ltr & receipt form
NELLIS, C. A. Commonwealth Edison Co. B3/02/18 DENTON, H. H. 14C No Detailed Affiliation Given 7pp 20937 217 24X Fiche 50-000, B3/10/21, B310270526
- B310280307 Releases public version of revised generating stations emergency plan telephone directory
FELTON, J. M. Division of Rules and Records B3/10/25 Document Management Branch 1p 20963 126 24X Fiche 50-000, B3/10/25, B310280307
- B310280314 Public version of revised generating stations emergency plan telephone directory
GALLE, D. P. Commonwealth Edison Co. B3/08/11 DENTON, H. H. Office of Nuclear Reactor Regulation, Director 64pp 20963 127 24X Fiche 50-000, B3/10/25, B310280307
- B310280191 Releases public version of revised emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records B3/10/26 Document Management Branch 1p 20962 266 24X Fiche 50-000, B3/10/26, B310280191
- B310280209 Public version of Rev 1 to Emergency Plan Implementing Procedure EOI-15, "Emergency Operations Facility Activation"
MOORE, R. D. Commonwealth Edison Co. B3/08/02 50pp 20962 267 24X Fiche 50-000, B3/10/26, B310280191
- G Adjudicatory correspondence
- B310120409 Forwards list of welds not inspected for intergranular stress corrosion cracking during current outage per Section III C 2 of B30826 shutdown order. Technical justification also encl
RYBAK, B. Commonwealth Edison Co. B3/09/30 DENTON, H. H. Office of Nuclear Reactor Regulation, Director 5pp 20699 076 24X Fiche 50-265, B3/09/30, B310120409
- P Operating license stage documents & correspondence
- B310200273 Forwards schedules for equipment qualification test program for facilities, per B10528 ltr. Dates given for current qualification activities should be viewed as "target dates" & not as firm dates
BARNES, P. L. Commonwealth Edison Co. B3/10/05 KERPHER, J. G. Region 3, Office of Director 10pp 20830 034 24X Fiche 50-000, B3/10/05, B310200273
- B310170345 Provides addl info re NUREG-047, Item 11 K 3 22, justifying use of HPCI logic for RCIC suction switchover. RCIC sys not safety-related & is not intended as backup for HPCI sys
RYBAK, B. Commonwealth Edison Co. B3/10/07 DENTON, H. H. Office of Nuclear Reactor Regulation, Director 1p 20784 320 24X Fiche 50-254, B3/10/07, B310170345

DOCKETED ITEMS

63

B310310054 Advises that pipe stresses & support loads due to dead weight of water in pipe, concurrent thermal effects & effects of postulated earthquake within design allowables reviewed, per NUREG-0737, Item 11 D 1
RYBAK, B Commonwealth Edison Co 83/10/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 20951 146 24X Fiche 50-254, 83/10/20, B310310054

B310250293 Forwards Rev 10 to Offsite Dose Calculation Manual for LaSalle & Quad Cities & Rev 9 to Offsite Dose Calculation Manual for Braidwood, consisting of Chapters 7, 2 & B 0
BENNETT, C J Commonwealth Edison Co 83/10/21 CASE, E Q Office of Nuclear Reactor Regulation, Director 1p 20894 259 24X Fiche 50-000, 83/10/21, B310250293

--B310250298 Rev 10 to Offsite Dose Calculation Manual for LaSalle & Quad Cities
Commonwealth Edison Co 83/09/30 44pp 20894 260 24X Fiche 50-000, 83/10/21, B310250293

D Inspection reports, IE Bulletins & correspondence

B308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 082 24X Fiche 50-000, 83/09/26, B308300340

B308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, B308300342

B308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 9A-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, B308300345

B308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, B308300349

B310140261 Forwards IE Insp Repts 50-254/83-26 & 50-265/83-25 on 830822-26 & 31 & 0909 & notice of violation
HIND, J A Division of Radiological & Materials Safety Programs 83/09/29 REED, C Commonwealth Edison Co 2pp 20762 048 24X Fiche 50-254, 83/09/29, B310140261

--B310140264 Notice of violation from insp on 830822-26 & 31 & 0909
HIND, J A Division of Radiological & Materials Safety Programs 83/09/28 2pp 20762 050 24X Fiche 50-254, 83/09/29, B310140261

--B310140271 IE Insp Repts 50-254/83-26 & 50-265/83-25 on 830822-26 & 31 & 0909 Noncompliance noted failure to distribute controlled emergency plan procedure revs to NRC
PHILLIPS, H P, PLOSKI, T J, PAPERIELLO, C J Region 3, Office of Director 83/09/29 17pp 20762 052 24X Fiche 50-254, 83/09/29, B310140261

B310120409 Forwards list of welds not inspected for intergranular stress corrosion cracking during current outage per Section III C 2 of B30826 shutdown order Technical justification also encl
RYBAK, B Commonwealth Edison Co 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 20699 036 24X Fiche 50-265, 83/09/30, B310120409

B310120061 Responds to IE Bulletin 83-03 re diesel generator cooling water pump discharge check valve Valve found to operate normally
BARNES, P L Commonwealth Edison Co 83/10/04 KEPPLER, J G Region 3, Office of Director 2pp 20697 174 24X Fiche 50-265, 83/10/04, B310120061

B310200124 Forwards IE Mgt Meeting Repts 50-010/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-26, 50-265/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIUS, C E Division of Project & Resident Programs 83/10/04 REED, C Commonwealth Edison Co 2pp 20834 098 24X Fiche 50 000, 83/10/04, B310200124

--B310200148 IE Mgt Meeting Repts 50-020/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIUS, C E Division of Project & Resident Programs 83/10/03 4pp 20834 100 24X Fiche 50-000, 83/10/04, B310200124

B310170337 Submits status of as-built reviews of safe shutdown piping supports for IE Bulletin 79-14 As result of review of Quad Cities, two piping sys found to have addl discrepancies Seven new hangers added
RYBAK, B Commonwealth Edison Co 83/10/06 KEPPLER, J G Region 3, Office of Director 2pp 20786 135 24X Fiche 50-000, 83/10/06, B310170337

B308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, B308300378

B308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, B308300752

B308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, B308300759

B308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20927 129 24X Fiche 50-000, 83/10/11, B308300761

B310180238 Clarifies procedures for admitting NRC personnel to facilities Access lists identifying authorized clearances encl Update will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 REED, C Commonwealth Edison Co 7pp 20808 234 24X Fiche 50-254, 83/10/14, B310180238

B310250605 Forwards IE Insp Repts 50-254/83-25 & 50-265/83-24 on 830802-0930 No noncompliance noted
SHAFER, W D Region 3, Office of Director 83/10/18 REED, C Commonwealth Edison Co 2pp 20900 2/6 24X Fiche 50-254, 83/10/18, B310250605

--B310250613 IE Insp Repts 50-254/83-25 & 50-265/83-24 on 830802-0930 No noncompliance noted Major areas inspected design changes & mods, organization & administration, procedures, onsite review committee, operational safety & maint
CHRISTOTIMOS, N, MORRONGIELLO, A, WALKER, R D Region 3, Office of Director 83/10/18 7pp 20900 278 24X Fiche 50-254, 83/10/18, B310250605

B310270435 Ack receipt of 830825 ltr re schedule for implementation of multiple peak resolution & peak reclassification enhancements to AALS per IE Insp Repts 50-254/82-13 & 50-265/83-15
PAPERIELLO, C J Region 3, Office of Director 83/10/25 RYBAK, B Commonwealth Edison Co 1p 20923 037 24X Fiche 50-254, 83/10/25, B310270435

R Periodic operating reports & related correspondence

B310170353 Forwards listing of changes, tests & experiments completed during Sept 1983 Summary of safety evaluation reported per 10CFR50 59
KALIVIANAKIS, N Commonwealth Edison Co 83/10/03 CASE, E Q Office of Nuclear Reactor Regulation, Director 4pp 20786 165 24X Fiche 50-254, 83/10/03, B310170353

B310180263 Monthly operating repts for Sept 1983 W/831003 ltr
MISAK, A L, KALIVIANAKIS, N Commonwealth Edison Co 83/10/03 Director's Office, Office of Inspection and Enforcement 26pp 20807 052 24X Fiche 50-254, 83/10/03, B310180263

S Reportable occurrences, LERs & related correspondence

B310110430 Responds to FOIA request for four different categories of documents described in B30510 ltr Forwards matl listed in App A, responsive to Items 1, 2 & 4 DOE should be contacted for matl requested in Item 3 of ltr
FELTON, J M Division of Rules and Records 83/06/14 HIATT, S L Ohio Citizens for Responsible Energy 3pp 20706 002 24X Fiche 50-000, 83/06/14, B310110430

DOCKETED ITEMS

--B310110478 Responds to B30413 ltr requesting info re use of foreign
mils on valve seating surfaces Lubricants & cleaning
solvents used on valve component surfaces per vendor
recommendations & maint practices
FARRAR, D L Commonwealth Edison Co 83/04/22 KEPPLER, J O
Region 3, Office of Director 4pp 20706 043 24X
Fiche 50-000, 83/04/14, B310110430

B310060249 LER 83-014/03L-0 on B30906, while performing local leak rate
test, SIV 2-203-2A found leaking in excess of Tech Spec
limit Cause unknown Work request written to identify cause &
corrective action Suppl rept will be submitted W/B30928 ltr
EAGLE, J, KALIVIANAKIS, N Commonwealth Edison Co 83/09/28
KEPPLER, J Region 3, Office of Director 2pp 20647 097 24X
Fiche 50-265, 83/09/28, B310060249

B310210016 LER 83-015/03L-0 on B30912, during refueling outage local
leak rate testing, measured combined leakage rate for
penetrations & valves found excessive Cause unknown Repairs
& corrective actions will be reported W/B31007 ltr
MENDENHALL, E, KALIVIANAKIS, N Commonwealth Edison Co 83/10/07
KEPPLER, J O Region 3, Office of Director 2pp 20858 263 24X
Fiche 50-265, 83/10/07, B310210016

B310210054 LER 83-016/03L-0 on B30912, temp switch TS-2-2370A tripped
above Tech Spec limit & switches TS-2-2370D & TS-2-2371D
failed in closed position Caused by setpoint drift &
overheating. Switches replaced W/B31007 ltr
LEAVERTON, W, KALIVIANAKIS, N Commonwealth Edison Co 83/10/07
KEPPLER, J O Region 3, Office of Director 3pp 20855 298 24X
Fiche 50-265, 83/10/07, B310210054

B310170661 Telecopy RO on B31011, during performance of ultrasonic insp
of cleanup sys piping, crack indication discovered in heat
affected zone of weld 12B-S27 of line 2-1202-6A Further
info to be provided within 14 days
KALIVIANAKIS, N Commonwealth Edison Co 83/10/12 KEPPLER, J
Region 3, Office of Director 1p 20779 285 24X
Fiche 50-265, 83/10/12, B310170661

B310180446 PNO-III-B3-096 on B31011, during routine inservice insp, small
crack discovered on 6-inch piping in reactor water cleanup
sys Crack not in sys affected by NRC B30823 order or IE
Bulletins 82-03 & 83-02 Situation being evaluated
DANIELSON, D, WALKER, R Region 3, Office of Director 83/10/13
1p 20801 343 24X Fiche 50-265, 83/10/13, B310180446

B310270419 LER 83-017/03L-0 on B30924, during RCIC turbine area high
temp switch calibr QIS-2B, temp switches TS 2-1360-15B, 16B &
14D tripped above Tech Spec limit Caused by setpoint drift
Switches replaced W/B31020 ltr
TODD, P, KALIVIANAKIS, N Commonwealth Edison Co 83/10/20
KEPPLER, J Region 3, Office of Director 3pp 20923 074 24X
Fiche 50-265, 83/10/20, B310270419

DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

B310030141 Advises that B20715 & 0930 requests for NRC to concur w/
intent to move emergency support ctr & associated functions
from Point Beach Energy Info Ctr to Milwaukee unacceptable,
per NUREG-0737, Suppl 1 & Generic Ltr DF-33
EISENHUT, D O Division of Licensing 83/09/14 BURSTEIN, S
Wisconsin Electric Power Co 4pp 20604 033 24X
Fiche 50-266, 83/09/14, B310030141

B310170087 Requests that alternate spent fuel routes approved by NRC
B30914 ltr be revised to allow use of Interstate 90
Interstate recently approved for use by State of NY, pending
consideration of insurance & indemnification issues
DANESE, F L Nuclear Assurance Corp 83/09/21 HILLMAN, C Division
of Safeguards 4pp 20798 001 24X Fiche 50-266, 83/09/21,
B310170087

B310060562 Forwards modified B30922 primary spent fuel route from
West Valley, NY to Point Beach, WI
SHERR, T S Material Transfer Safeguards Licensing Branch 83/09/27
DANESE, F L Nuclear Assurance Corp 10pp 20661 265 24X
Fiche 50-266, 83/09/27, B310060562

B310030609 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/09/28 Document
Management Branch 1p 20607 036 24X Fiche 50-266, 83/09/28,
B310030609

--B310030616 Forwards public version of revised emergency plan
implementing procedures, including Procedures EPIP 1 3 re
estimation of source term, LMP 1 4 re radiological dose
evaluation & EPIP 6 2 re plant evacuation
FAY, C W Wisconsin Electric Power Co 83/09/19 DENTON, H H
Office of Nuclear Reactor Regulation, Director 1p 20607 03/
24X Fiche 50-266, 83/09/28, B310030607

--B310030624 Public version of revised emergency plan implementing
procedures, including Procedures EPIP 1 3 re estimation of
source term, EPIP 1 4 re radiological dose evaluation & EPIP
6 2 re plant evacuation
* Wisconsin Electric Power Co 83/09/09 241pp 20607 038 24X
Fiche 50-266, 83/09/28, B310030607

B310180052 Forwards sanitized version of B31003 modified alternate
spent fuel route from West Valley, NY to Point Beach, WI
Remaining provisions of NRC B30914 ltr unchanged
SHERR, T S Material Transfer Safeguards Licensing Branch 83/10/05
DANESE, F L Nuclear Assurance Corp 10pp 20824 282 24X
Fiche 50-266, 83/10/05, B310180052

B310210044 Responds to B30914 ltr denying concurrence w/util plans to
move emergency support ctr from Two Creeks, WI to corporate
headquarters in Milwaukee, approx 100 miles from facility
Potential problems overstated by NRC
BURSTEIN, S Wisconsin Electric Power Co 83/10/14 EISENHUT, D O
Division of Licensing 2pp 20855 315 24X Fiche 50-266, 83/10/14,
B310210044

B310310370 Forwards revs to modified amended security plan Revs
withheld (ref 10CFR73 21 & 2 740)
BURSTEIN, S Wisconsin Electric Power Co 83/10/24 DENTON, H H
Office of Nuclear Reactor Regulation, Director 1p 20961 111 24X
Fiche 50-266, 83/10/24, B310310370

G Adjudicatory correspondence

B310070156 Forwards Director's Decision B3-14, denying B30909 10CFR2 206
petition re transport of spent nuclear fuel from
West Valley
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director
83/09/30 CELEBREZZE, A J Ohio, State of 2pp 20640 308 24X
Fiche 50-000, 83/09/30, B310070156

--B310070161 Forwards Director's Decision B3-14, denying B30824 10CFR2 206
petition re transport of spent nuclear fuel from
West Valley
DAVIS, J O Office of Nuclear Material Safety &
Safeguards, Director 83/09/30 RESNIKOFF, M Sierra Club 1p
20680 309 24X Fiche 50-000, 83/09/30, B310070156

--B310070167 Notice of issuance of Director's Decision B3-14, denying
State of OH & Sierra Club B30909 & 0824, respectively,
10CFR2 206 petitions re transport of spent nuclear fuel from
West Valley
DAVIS, J O Office of Nuclear Material Safety &
Safeguards, Director 83/09/30 2pp 20480 310 24X
Fiche 50-000, 83/09/30, B310070156

--B310070171 Director's Decision B3-14, denying State of OH & Sierra Club
B30909 & 0824, respectively, 10CFR2 206 petitions re
transport of spent nuclear fuel from West Valley Request for
hearing & for preparation of EIS denied
DAVIS, J O Office of Nuclear Material Safety &
Safeguards, Director 83/09/30 18pp 20680 312 24X
Fiche 50-000, 83/09/30, B310070156

B310060197 Order extending time until B31012 for Commission to act to
review ALAB-719
CHILK, S J Office of the Secretary of the Commission 83/10/04
Commissioners 1p 20647 104 24X Fiche 50-266, 83/10/04,
B310060197

B31010274 Informs that licensee will file response to Wisconsin
Environ Decade, Inc petition served on B30923 by B31017 Bv
list encl
CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge CHURCHILL, B W
Wisconsin Electric Power Co 83/10/07 CHILK, S J Office of the
Secretary of the Commission 4pp 20666 200 24X
Fiche 50-266, 83/10/07, B31010274

B310170493 Answer in opposition to Wisconsin Environ Decade B30923
petition for review of ASLAB B30907 Decision ALAB-719,
affirming ASLD B30204 authorization for issuance of license
amend issue not raised before ASLAB Certificate of Svr encl
BACHMANN, R O Hearing Branch 1 83/10/11 Commissioners 14pp
20789 123 24X Fiche 50-266, 83/10/11, B310170493

8310140250 Order extending time until 831019 for Commission to act to review ALAB-719
CHILK, S J Office of the Secretary of the Commission 83/10/12
Commissioners 1p 20762 041 24X Fiche 50-266, 83/10/12,
8310140250

8310200102 Response opposing Wisconsin Environ Decade 830923 petition for review of ALAB-739 re steam generator tubes repaired by sleeving Nexus between sleeving & tube failure shown Certificate of Gvc encl
CHURCHILL, B W Wisconsin Electric Power Co CHURCHILL, B W Shaw, Pittman, Potts & Troubridge 83/10/17 Commissioners 13pp 20836 350 24X Fiche 50-266, 83/10/17, 8310200102

8310190091 Order extending time until 831101 for Commission to act to review Director's Decision DD 83-13
CHILK, S J Office of the Secretary of the Commission 83/10/18
Commissioners 1p 20822 265 24X Fiche 50-266, 83/10/18,
8310190091

8310260241 Order extending time until 831123 for Commission to act to review ALAB-739
CHILK, S J Office of the Secretary of the Commission 83/10/24
Commissioners 1p 20907 266 24X Fiche 50-266, 83/10/24,
8310260241

8310270297 Order extending time until 831128 for Commission to act to review Director's Decision DD-83-14, denying Sierra Club & State of OH requests
CHILK, S J Office of the Secretary of the Commission 83/10/25
Commissioners 1p 20923 195 24X Fiche 50-000, 83/10/25,
8310270297

H General correspondence

8310040623 Forwards rev to health physics organization chart for steam generator replacement project, per request
FAY, C W Wisconsin Electric Power Co 83/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 1p 20625 348 24X Fiche 50-266, 83/09/28, 8310040623

J Insurance & indemnity information

8310110187 Forwards Endorsement 59 to MAE/U Policy MF-53 & Endorsement 72 to NELIA Policy NF-178
DUNDAS, W J Wisconsin Electric Power Co 83/10/03 NRC - No Detailed Affiliation Given 3pp 20665 011 24X Fiche 50-266, 83/10/03, 8310110187

P Operating license stage documents & correspondence

8310110530 "Assessment of Radiation Risks," util-medical dialogue presented at 800922-23 Intl Inst of Safety & Health forum in Washington, DC
LAPP, R E International Institute of Safety & Health 80/09/23 52pp 20714 161 24X Fiche 50-000, 80/09/23, 8310110530

8310110504 Ack receipt of 830906 ltr withdrawing request for amends to Tech Specs re operation at reduced thermal design flow
Safety evaluation & 830408 ltr encl w/o encls
MILLER, J R Operating Reactors Branch 3 83/09/20 FAY, C W Wisconsin Electric Power Co 2pp 20715 173 24X Fiche 50-266, 83/09/20, 8310110504

8310070020 Ack receipt of 830824 ltr requesting Commission publish notice of pending license amend in FR re New York State Energy R&D Authority license for utils w/irradiated fuel storage facilities
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 83/09/22 REBNIKOFF, M Sierra Club 1p 20671 361 24X Fiche 50-000, 83/09/22, 8310070020

8310270555 Forwards safety evaluation supporting design of reactor coolant vent sys per requirement of 10CFR30.44(c)(3)(iii) & NUREG-0737, Item II B 1
MILLER, J R Operating Reactors Branch 3 83/09/22 FAY, C W Wisconsin Electric Power Co 7pp 20444 003 24X Fiche 50-266, 83/09/22, 8310270555

8310040310 Forwards addl info requested in 830810 telcon re Franklin Research Ctr 830617 draft technical evaluation rept on util response to Phase I of NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants"
FAY, C W Wisconsin Electric Power Co 83/09/28 MILLER, J R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 8pp 20613 096 24X Fiche 50-266, 83/09/28, 8310040310

8310070439 FINAL ENVIRONMENTAL STATEMENT RELATED TO STEAM GENERATOR REPAIR AT THE POINT BEACH NUCLEAR PLANT, UNIT 1 Docket No 50-266 (Wisconsin Electric Power Company)
COLBURN, T G Division of Licensing NUREG-1011 83/09/30 60pp Available at NRC \$4 50 20672 299 24X Fiche 50-266, 83/09/30, 8310070439

8310110446 Forwards FES (NUREG-1011) re repair of steam generators & notice of availability w/o encl
MILLER, J R Operating Reactors Branch 3 83/09/30 PERRIN, B Environmental Protection Agency 2pp 20704 331 24X Fiche 50-266, 83/09/30, 8310110446

8310110457 Notice of availability of FES (NUREG-1011) re steam generator repair
MILLER, J R Operating Reactors Branch 3 83/09/30 2pp 20706 317 24X Fiche 50-266, 83/09/30, 8310110457

8310130033 Forwards Amend 75 to License DPR-24, safety evaluation & notice of issuance & availability Amend approves steam generator repair program & requires that repair operations be conducted in accordance w/ licensee commitments
MILLER, J R Operating Reactors Branch 3 83/09/30 FAY, C W Wisconsin Electric Power Co 4pp 20776 255 24X Fiche 50-266, 83/09/30, 8310130033

--8310130036 Amend 75 to License DPR-24, approving steam generator repair program & requiring that repair operations be conducted in accordance w/ licensee commitments identified in approved steam generator repair rept dtd 820809 & revised 830301
MILLER, J R Operating Reactors Branch 3 83/09/30 2pp 20776 259 24X Fiche 50-266, 83/09/30, 8310130033

--8310130040 Safety evaluation supporting Amend 75 to License DPR-24
* NRC - No Detailed Affiliation Given 83/09/30 50pp 20776 261 24X Fiche 50-266, 83/09/30, 8310130033

--8310130044 Notice of issuance & availability of Amend 75 to License DPR-24
MILLER, J R Operating Reactors Branch 3 83/09/30 3pp 20776 319 24X Fiche 50-266, 83/09/30, 8310130033

8310130052 Forwards Amends 74 & 79 to Licenses DPR-24 & DPR-27, respectively & safety evaluation Amends revise degraded grid voltage relay setpoint & associated time delay in Table 15.3.5-1 of Tech Specs
COLBURN, T G Operating Reactors Branch 3 83/09/30 FAY, C W Wisconsin Electric Power Co 2pp 20776 220 24X Fiche 50-266, 83/09/30, 8310130052

--8310130056 Amends 74 & 79 to Licenses DPR-24 & DPR-27, respectively, revising degraded grid voltage relay setpoint & associated time delay in Table 15.3.5-1 of Tech Specs
MILLER, J R Operating Reactors Branch 3 83/09/30 4pp 20776 222 24X Fiche 50-266, 83/09/30, 8310130052

--8310130062 Safety evaluation supporting Amends 74 & 79 to Licenses DPR-24 & DPR-27, respectively
* Office of Nuclear Reactor Regulation, Director 83/09/30 3pp 20776 228 24X Fiche 50-266, 83/09/30, 8310130052

8310170723 Forwards FES re steam generator repair (NUREG-1011) w/o encl
MILLER, J R Operating Reactors Branch 3 83/09/30 FAY, C W Wisconsin Electric Power Co 2pp 20798 096 24X Fiche 50-266, 83/09/30, 8310170723

8310240116 Forwards Amends 77 & 81 to Licenses DPR-24 & DPR-27, respectively & safety evaluation Amends revise Tech Specs to permit location of spent fuel pool neutron absorber surveillance specimen adjacent to divider wall
COLBURN, T G Operating Reactors Branch 3 83/10/05 FAY, C W Wisconsin Electric Power Co 2pp 20891 338 24X Fiche 50-266, 83/10/05, 8310240116

--8310240122 Amends 77 & 81 to Licenses DPR-24 & DPR-27, respectively, revising Tech Specs to permit location of spent fuel pool neutron absorber surveillance specimen adjacent to spent fuel pool divider wall
MILLER, J R Operating Reactors Branch 3 83/10/17 7pp 20891 340 24X Fiche 50-266, 83/10/05, 8310240116

--8310240125 Safety evaluation supporting Amends 77 & 81 to Licenses DPR-24 & DPR-27, respectively
* Office of Nuclear Reactor Regulation, Director 83/10/05 3pp 20891 347 24X Fiche 50-266, 83/10/05, 8310240116

DOCKETED ITEMS

0130199 Forwards Amends 76 & 80 to Licenses DPR-24 & DPR-27, respectively & safety evaluation Amend clarifies terminology used in limiting condition for operation & language re periodic calibr interval requirement
CLBURN, T O Operating Reactors Branch 3 83/10/06 FAY, C W
Wisconsin Electric Power Co 2pp 20777 195 24X
Fiche 50-266, 83/10/06, 8310130199

0130202 Amends 76 & 80 to Licenses DPR-24 & DPR-27, respectively, making administrative changes to Tech Specs to clarify terminology used in limiting condition for operation & language re periodic calibr interval requirement
MILLER, J R Operating Reactors Branch 3 83/10/06 10pp
20777 197 24X Fiche 50-266, 83/10/06, 8310130199

0130205 Safety evaluation supporting Amends 76 & 80 to Licenses DPR-24 & DPR-27, respectively
* Office of Nuclear Reactor Regulation, Director 83/10/06 2pp
20777 207 24X Fiche 50-266, 83/10/06, 8310130199

0180490 Application to amend Licenses DPR-24 & DPR-27 modifying each Spec Change Request 33 reflecting changes in effluent monitoring instrumentation resulting from recently installed approved radiation monitoring sys
FAY, C W Wisconsin Electric Power Co 83/10/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 20799 114
X Fiche 50-266, 83/10/07, 8310180490

0180492 Proposed radiological effluent Tech Specs reflecting mods to radiation monitoring sys
* Wisconsin Electric Power Co 83/09/30 47pp 20799 117 24X
Fiche 50-266, 83/10/07, 8310180490

0180495 Rev O to "Offsite Dose Calculation Manual "
* Wisconsin Electric Power Co 83/09/30 65pp 20799 164 24X
Fiche 50-266, 83/10/07, 8310180490

0180497 Rev 2 to "Environ Monitoring Manual "
* Wisconsin Electric Power Co 82/06/30 33pp 20799 227 24X
Fiche 50-266, 83/10/07, 8310180490

0180502 "Process Control Program "
* Wisconsin Electric Power Co 83/09/30 218pp 20799 204 24X
Fiche 50-266, 83/10/07, 8310180490

280098 Confirms arrangements for NRC site visit on 831101-03 to obtain addl info to complete evaluation of inservice testing program for pumps & valves
MILLER, J R Operating Reactors Branch 3 83/10/07 FAY, C W
Wisconsin Electric Power Co 2pp 20961 360 24X
Fiche 50-266, 83/10/07, 8310280098

130004 Discusses 831013 meeting to resolve deficiencies noted in Enklin Research Ctr technical evaluation rept re environ qualification of safety-related electrical equipment Agenda supporting documentation encl
BURSTEIN, S Wisconsin Electric Power Co 83/10/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 30pp 20726 207 24X
Fiche 50-266, 83/10/10, 8310130004

180421 Informs of proposed minor changes to commitments made in response to implementation instructions of NUREG-0578, re short-term lessons learned Duty technical advisor quarters will be incorporated in boundary control ctr
FAY, C W Wisconsin Electric Power Co 83/10/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20803 506
X Fiche 50-266, 83/10/10, 8310180421

170079 Notification of 831013 meeting w/util in Bethesda, MD to discuss method for achieving final qualification of safety-related electrical equipment Final rept will be used based on meeting results
CLBURN, T O Operating Reactors Branch 3 83/10/11 MILLER, J R
Operating Reactors Branch 3 3pp 20798 014 24X
Fiche 50-266, 83/10/11, 8310170079

160150 Requests to be removed from list of addresses for steam generator repair CIS
FINY, J Transportation, Dept of 83/10/11 MILLER, J R
Operating Reactors Branch 3 1p 20915 196 24X
Fiche 50-266, 83/10/11, 8310260150

80147 Forwards 830930 Director's Decision 83-14, denying State of & Sierra Club 10CFR2 206 petitions re transportation of spent fuel from West Valley facility, per 830930 request
NINOHAN, R E Division of Fuel Cycle & Material Safety 83/10/11
MILLER, F Environmental Policy Institute 2pp 20961 329 24X
Fiche 50-000, 83/10/18, 8310280147

0 Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310030447 Forwards list of Ray Miller products installed at facilities, in response to IE Bulletin 83-07 Investigation of subter suppliers in progress
FAY, C W Wisconsin Electric Power Co 83/09/26 KIEPLER, J G
Region 3, Office of Director 4pp 20601 038 24X
Fiche 50-266, 83/09/26, 8310030447

8310120089 Responds to IE Info Notice 83-01 & IE Bulletin 83-07 re investigation of applicability of Ray Miller, Inc fraudulent practices Identified items have no adverse safety significance List of installed products encl
FAY, C W Wisconsin Electric Power Co 83/09/26 KIEPLER, J G
Region 3, Office of Director 4pp 20696 187 24X
Fiche 50-266, 83/09/26, 8310120089

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 74pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180261 Clarifies NRC position re procedures for admitting NRC personnel to facilities Access should be provided to Region III personnel listed in encl Update will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 BURSIFIN, S
Wisconsin Electric Power Co 7pp 20802 275 24X
Fiche 50-266, 83/10/14, 8310180261

8310270294 Forwards IE Insp Repts 50-266/83-17 & 50-301/83-16 on 830808-0922 & notice of violation
PAPERIELLO, C J Region 3, Office of Director 83/10/14
BURSTEIN, S Wisconsin Electric Power Co 2pp 20923 196 24X
Fiche 50-266, 83/10/14, 8310270294

--8310270303 Notice of violation from Insp on 830808-0922
PAPERIELLO, C J Region 3, Office of Director 83/10/13 1p
20923 198 24X Fiche 50-266, 83/10/14, 8310270294

--8310270313 IE Insp Repts 50-266/83-17 & 50-301/83-16 on 830808-0922 Noncompliance noted failure to perform appropriate contamination survey of radioactive matls shipment
LOVENDALE, P C, PAUL, R A, HAGUE, R L Region 3, Office of Director 83/10/12 8pp 20923 199 24X Fiche 50-266, 83/10/14, 8310270294

DOCKETED ITEMS

67

8310240042 Ack receipt of 830924 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/83-13 & 50-301/83-13 Fuel handling training must be completed by 831201
SHAFER, W D Region 3, Office of Director 83/10/18 BURSTLIN, S Wisconsin Electric Power Co 1p 20881 348 24X
Fiche 50-266, 83/10/18, 8310240042

--8310240051 Responds to NRC 830823 ltr re violations noted in IE Insp Repts 50-266/83-13 & 50-301/83-13 Corrective actions, supervisor instructed on use of procedures & good engineering practices when operating refueling equipment
CASSIDY, T J Wisconsin Electric Power Co 83/09/22 KCPPIR, J G Region 3, Office of Director 3pp 20881 349 24X
Fiche 50-266, 83/10/18, 8310240042

R Periodic operating reports & related correspondence

8310180119 Monthly operating repts for Sept 1983 W/831010 ltr
FAY, C W Wisconsin Electric Power Co 83/10/05 NRC - NW Detailed Affiliation Given 9pp 20801 175 24X
Fiche 50-266, 83/10/05, 8310180119

S Reportable occurrences, LERs & related correspondence

8310280079 Responds to FOIA request for A&OD re: "Loss of Shutdown Cooling & Subsequent Boron Dilution at San Onofre P." dtd 830425 & documents re fuel rod degradation problem described in IE Info Notice 82-27 Forwards App A documents
FELTON, J M Division of Rules and Records 83/07/28 HATTA, S I Ohio Citizens for Responsible Energy 2pp 20962 156 24X
Fiche 50 000, 83/07/28, 8310280079

--8310280168 LER 50-266/75-18 on 751217, during Cycle 3-4 refueling, discovered section of fuel rod missing Caused by water impingement through baffle plate while failed assembly in Cycle 2 position 11-1 Investigation in progress W/751230 ltr
BOBE, P E, BURSTEIN, S Wisconsin Electric Power Co 75/12/30 RUSCHE, D C Office of Nuclear Reactor Regulation, Director 10pp 20962 253 24X Fiche 50-000, 83/07/28, 8310280079

--8310280171 LER 50-266/76-12 on 761222, wall cladding defects noted in one rod of fuel assembly 007 Caused by rod vibrating against rod retaining grid springs Peening of core baffle plate joints, completed in Nov 1976, should prevent recurrence
BOBE, P E Wisconsin Electric Power Co 77/01/04 3pp 20962 263 24X Fiche 50-000, 83/07/28, 8310280079

8310270380 LER 83-004/03L-0 on 830210, measured flow of 3,100 cfm for train B standby gas treatment did not meet min Tech Spec requirement of 3,150 cfm Caused by clogged demisters
Demisters cleaned & procedure will be revised W/830311 ltr
IVERSON, D, MUSDOLF, D Northern States Power Co 83/03/11 Region 3, Office of Director 3pp 20938 071 24X Fiche 50-000, 83/09/29, 8310270347

8310060428 PNO-III-83-089 on 830924, temporary restraining order requested to prevent shipment of spent reactor fuel through State of OH denied Pretrial conference set for 831006 Local govt alleged inadequate preparation by local agencies.
STRASMA, J, MENCZER, W Region 3, Office of Director 83/09/30 2pp 20641 221 24X Fiche 50-000, 83/09/30, 8310060428

8310070301 Potential Part 21 re: re underrange characteristic of Model N-C11GM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X
Fiche 50-000, 83/09/30, 8310070301

8310060264 PNO-III-83-091 on 831001, 6-month outage commenced for refueling, routine maint & replacement of two steam generators Authorization to replace generators received on 830930
JACKIN, I, SHAFER, W Region 3, Office of Director 83/10/03 1p 20645 265 24X Fiche 50-266, 83/10/03, 8310060264

8310140255 PNO-III-83-094 on 830930, contamination found on empty spent fuel cask shipped from facility Trailer used to transport empty spent fuel casks experienced brake problems on 831005 All shipments under insp
LOVENDALE, P, GREGER, L R Region 3, Office of Director 83/10/06 2pp 20759 238 24X Fiche 50-266, 83/10/06, 8310140255

V. Operator Examinations

8310070303 Requests extension of effective date of compliance w/ 10CFR50 re licensed operator staffing to 871010
FAY, C W Wisconsin Electric Power Co 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20651 070 24X Fiche 50-266, 83/09/30, 8310070303

DOCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION

F Security, medical, emergency & fire protection plans

8310030446 Forwards IE Insp Rept 50-267/83-13 on 830613-16 No noncompliance noted
MADSEN, G L Region 4, Office of Director 83/08/08 LEE, D R Public Service Co of Colorado 2pp 20601 022 24X
Fiche 50-267, 83/08/08, 8310030446

--8310030457 IE Insp Rept 50-267/83-13 on 830613-16 No noncompliance noted Major areas inspected licensee performance & capabilities during exercise of emergency plans & procedures
MONTGOMERY, J L, HACKNEY, C A, WISE, R Region 4, Office of Director 83/08/04 14pp 20601 074 24X Fiche 50-267, 83/08/08, 8310030446

8310180196 Informs that based on review of 830414 submittal, licensee forward command post (emergency operations facility) complies w/requirements of Table 1 to Suppl 1 of NUREG-0737
MADSEN, G L Region 4, Office of Director 83/08/16 LEE, D R Public Service Co of Colorado 1p 20808 341 24X
Fiche 50-267, 83/08/16, 8310180196

8310040558 Forwards IE Insp Rept 50-267/83-20 on 830725-29 & notice of violation
MADSEN, G L Region 4, Office of Director 83/09/06 LEE, D R Public Service Co. of Colorado 2pp 20625 344 24X
Fiche 50-267, 83/09/06, 8310040558

--8310040566 Notice of violation from insp on 830725-29
* Region 4, Office of Director 83/09/06 1p 20625 346 24X
Fiche 50-267, 83/09/06, 8310040558

--8310040644 IE Insp Rept 50-267/83-20 on 830725-29 Noncompliance noted failure to distribute security program audit to corporate mgt Details withheld (ref 10CFR73 21)
EVANS, C A, KELLY, J, HUNNICUTT, D Region 4, Office of Director 83/09/01 1p 20625 347 24X Fiche 50-267, 83/09/06, 8310040558

8310040169 Responds to NRC 830819 ltr re violations noted in IE Insp on 830801-05 Corrective actions Change Notice 1377 will be reissued to identify Door 66 as Class 1 & control room door holes filled
BREV, M L Public Service Co of Colorado 83/09/19 MADSEN, G L Region 4, Office of Director 4pp 20A08 214 24X
Fiche 50-267, 83/09/19, 8310040169

8310040276 Responds to NRC 830902 ltr re violations noted in IE Insp Rept 50-267/83-16 Corrective actions guard force personnel retrained
WAREMBOURG, D W Public Service Co of Colorado 83/09/20 COLLINS, J T Region 4, Office of Director 3pp 20613 008 24X
Fiche 50-267, 83/09/20, 8310040276

8310130236 Responds to NRC 830906 ltr re violations noted in IE Insp Rept 50-267/83-20 Corrective actions security program audit distribution matrix developed & utilized beginning 830408 & rev to Procedure G-18 effective 830624
QAHM, J W Public Service Co of Colorado 83/09/23 COLLINS, J T Region 4, Office of Director 3pp 20723 283 24X
Fiche 50-267, 83/09/23, 8310130236

8310110234 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20606 006 24X Fiche 50-267, 83/10/05, 8310110234

--8310110236 Forwards public version of revised emergency plan implementing procedures W/o encl
WAREMBOURG, D W Public Service Co of Colorado 83/09/16 COLLINS, J T Region 4, Office of Director 3pp 20606 008 24X
Fiche 50-267, 83/10/05, 8310110234

8310180385 Forwards list of new licensing actions, completed actions & action summary During Last Quarter FY83, considerable time spent on Rev 1 to update FSAR & preparation of confirmatory order for NUREG-0737 items in Suppl 1
WAGNER, P C Region 4, Office of Director 83/10/06 MADSEN, G L Region 4, Office of Director 6pp 20803 207 24X
Fiche 50-267, 83/10/06, 8310180385

DOCKETED ITEMS

Operating license stage documents & correspondence

- 8310310384 Forwards Amend 35 to License DPR-34 & EIA Amend revises nonradiological ETS by substitution of environ protection plan
WAGNER, P C Region 4, Office of Director 83/08/10 LEE, D R
Public Service Co of Colorado 2pp 20959 328 24X
Fiche 50-267, 83/08/10, 8310310384
- 8310310388 Amend 35 to License DPR-34, revising nonradiological ETS by substitution of environ protection plan More restrictive scale for aerial photography incorporated
MADSEN, O L Region 4, Office of Director 83/08/10 13pp
20959 330 24X Fiche 50-267, 83/08/10, 8310310384
- 8310310393 EIA supporting Amend 35 to License DPR-34
* Region 4, Office of Director 83/08/10 6pp 20959 343 24X
Fiche 50-267, 83/08/10, 8310310394
- 831080212 Act receipt of 830610 ltr transmitting current RA program per 10CFR50.55(f) Program being reviewed
MADSEN, O L Region 4, Office of Director 83/08/15 LEE, D R
Public Service Co of Colorado 1p 20800 316 24X
Fiche: 50-267, 83/08/15, 831080212
- 8310040325 Concurs w/NRC conclusion that Tech Spec Slt 5.1.1 sufficient to demonstrate control rod operability & NRC recommendation to revise second paragraph re control rod drop max temp monitoring Future license amend rev provided
WAREMBOURG, D Public Service Co of Colorado 83/09/21
COLLINS, J T Region 4, Office of Director 2pp 20620 216 24X
Fiche 50-267, 83/09/21, 8310040325
- 8310040407 Forwards comments & suggestions re rewording Rev 1 to delegation & assignment to Region IV of certain licensing functions Author does not concur in memo due to belief that authority & responsiveness of Region IV harmfully affected
COLLINS, J T Region 4, Office of Director 83/09/22 CASE, E
Office of Nuclear Reactor Regulation, Director 3pp 20619 054
24X Fiche 50-267, 83/09/22, 8310040407
- 8312130165 Delegates & assigns certain licensing functions for plant to region Specific delegations & assignments listed
DIRCKX, W J Office of the Executive Director for Operations 82/12/03
COLLINS, J T Region 4, Office of Director 2pp
20619 057 24X Fiche 50-267, 83/09/22, 8310040407
- 8310040454 Forwards safety evaluation of NUREG-0737, Item II B 3, "Post-Accident Sampling Sys" Util meets six of 11 criteria Comments requested within 30 days W/o encl
MADSEN, O L NRC - No Detailed Affiliation Given 83/09/22
LEE, D R Public Service Co of Colorado 1p 20624 225 24X
Fiche 50-267, 83/09/22, 8310040454
- 8310310193 Forwards revised application for amend to License DPR-34, proposing supplemental changes to administrative controls Tech Specs re min shift crew composition & plant operations review committee, per Generic Ltrs 82-12, 82-21 & 82-23
LEE, D R Public Service Co of Colorado 83/09/28 COLLINS, J T
Region 4, Office of Director 3pp 20724 332 24X
Fiche 50-267, 83/09/28, 8310310193
- 8310310200 Revised application for amend to License DPR-34, proposing supplemental changes to administrative controls Tech Specs re min shift crew composition requirements & plant operations review committee
LEE, D R Public Service Co of Colorado 83/09/28 4pp
20724 335 24X Fiche 50-267, 83/09/28, 8310310193
- 8310310204 Proposed changes to administrative controls Tech Specs re min shift crew composition requirements & plant operations review committee
* Public Service Co of Colorado 83/09/28 29pp 20724 339
24X Fiche 50-267, 83/09/28, 8310310193
- 8310310260 Forwards application for amend to License DPR-34, changing radiological ETS to incorporate changes in nuclear facility safety committee responsibilities & requirements for effluent & environ monitoring
LEE, D R Public Service Co of Colorado 83/09/28 COLLINS, J T
Region 4, Office of Director 3pp 20722 107 24X
Fiche: 50-267, 83/09/28, 8310310260
- 8310310324 Application for amend to License DPR-34, changing radiological ETS to incorporate changes in nuclear facility safety committee responsibilities & requirements for effluent & environ monitoring
LEE, D R Public Service Co of Colorado 83/09/28 4pp
20722 110 24X Fiche 50-267, 83/09/28, 8310310260
- 8310310328 Proposed Tech Specs re environ monitoring program, radiological disposal sys & radiological monitoring program Significant hazards considerations analysis encl
* Public Service Co of Colorado 83/09/28 12pp 20722 114
24X Fiche 50-267, 83/09/28, 8310310260
- 8310310272 Forwards application for amend to License DPR-34, authorizing receipt, possession & use of addl activity of Cs-137 & Kr-85 for calibr of newly acquired portable radiation instrumentation
LEE, D R Public Service Co of Colorado 83/09/28 COLLINS, J T
Region 4, Office of Director 2pp 20723 205 24X
Fiche 50-267, 83/09/28, 8310310272
- 8310310275 Application for amend to License DPR-34, authorizing receipt, possession & use of addl activity of Cs-137 & Kr-85 for calibr of newly acquired portable radiation instrumentation
LEE, D R Public Service Co of Colorado 83/09/28 5pp
20723 207 24X Fiche 50-267, 83/09/28, 8310310272
- 8310310279 Proposed Tech Specs re addl activity of Cs-137 & Kr-85 for calibr of newly acquired portable radiation instrumentation Significant hazards considerations analysis encl
* Public Service Co of Colorado 83/09/28 3pp 20723 212
24X Fiche 50-267, 83/09/28, 8310310272
- 8310310281 Application for amend to License DPR-34, ensuring capability of primary RCS components to maintain primary reactor coolant envelope as fission product barrier
LEE, D R Public Service Co of Colorado 83/09/28 COLLINS, J T
Region 4, Office of Director 4pp 20723 147 24X
Fiche 50-267, 83/09/28, 8310310281
- 8310310284 Proposed Tech Specs ensuring capability of primary RCS component to maintain primary reactor coolant envelope as fission product barrier
* Public Service Co of Colorado 83/09/28 45pp 20723 151
24X Fiche 50-267, 83/09/28, 8310310281
- 8310310300 Forwards application for amend to License DPR-34, changing Tech Specs Sections 4.3.10 & 5.3.8 to incorporate supplemental changes re snubber functional testing plans
LEE, D R Public Service Co of Colorado 83/09/28 COLLINS, J T
Region 4, Office of Director 3pp 20719 153 24X
Fiche 50-267, 83/09/28, 8310310300
- 8310310303 Application for amend to License DPR-34, changing Tech Specs Sections 4.3.10 & 5.3.8 to incorporate supplemental changes re snubber functional testing plans
LEE, D R Public Service Co of Colorado 83/09/28 4pp
20719 156 24X Fiche 50-267, 83/09/28, 8310310300
- 8310310304 Proposed changes to Tech Specs Sections 4.3.10 & 5.3.8 to incorporate supplemental changes re snubber functional testing plans
* Public Service Co of Colorado 83/09/28 44pp 20719 160
24X Fiche 50-267, 83/09/28, 8310310300
- 8310210293 Notifies that submittal of addl info for H-451 graphite postponed to 831028, per NRC 830802 ltr Postponement due to unforeseen difficulties w/computer codes Analysis work, referred to in 830815 ltr, performed
BREY, H L Public Service Co of Colorado 83/10/04 COLLINS, J T
Region 4, Office of Director 2pp 20051 261 24X
Fiche 50-267, 83/10/04, 8310210293
- 831080385 Forwards list of new licensing actions, completed actions & action summary During Last Quarter FY83, considerable time spent on Rev 1 to update FSAR & preparation of confirmatory order for NUREG-0737 items in Suppl 1
WAGNER, P C Region 4, Office of Director 83/10/06 MADSEN, O L
Region 4, Office of Director 6pp 20003 207 24X
Fiche 50-267, 83/10/06, 831080385
- 8310310433 Forwards Amend 36 to License DPR-34 & safety evaluation Amend revises administrative Tech Specs to incorporate various editorial & format corrections, per NUREG-0737, Item I A 1.3
WAGNER, P C Region 4, Office of Director 83/10/13 LEE, D R
Public Service Co of Colorado 2pp 20959 194 24X
Fiche 50-267, 83/10/13, 8310310433
- 8310310435 Amend 36 to License DPR-34, revising administrative Tech Specs to incorporate various editorial & format corrections, per NUREG-0737, Item I A 1.3
JOHNSON, E H Region 4, Office of Director 83/10/13 34pp
20959 196 24X Fiche 50-267, 83/10/13, 8310310433

DOCKETED ITEMS

69

O Inspection reports, IE Bulletins & correspondence

8310030344 Forwards IE Insp Rept 50-267/83-18 on 830601-30 & notice of violation
MADSEN, G L Region 4, Office of Director 83/07/21 LCF, O R
Public Service Co of Colorado 2pp 20590 185 24X
Fiche 50-267, 83/07/21, 8310030344

--8310030347 Notice of violation from insp on 830601-30
* Region 4, Office of Director 83/07/21 3pp 20590 187 24X
Fiche 50-267, 83/07/21, 8310030344

--8310030350 IE Insp Rept 50-267/83-18 on 830601-30 Noncompliance noted
Failure to follow procedures re equipment clearances &
surveillance testing program
DICKERSON, M W, PLUMLEE, G L, HUNNICUTT, D M Region 4, Office of
Director 83/07/18 15pp 20590 190 24X Fiche 50-267, 83/07/21,
8310030344

8310030446 Forwards IE Insp Rept 50-267/83-13 on 830613-16 No
noncompliance noted
MADSEN, G L Region 4, Office of Director 83/08/08 LCF, O R
Public Service Co of Colorado 2pp 20601 022 24X
Fiche 50-267, 83/08/08, 8310030446

--8310030457 IE Insp Rept 50-267/83-13 on 830613-16 No noncompliance
noted Major areas inspected licensed performance &
capabilities during exercise of emergency plans &
procedures
MONTGOMERY, J L, HACKNEY, C A, WISE, R Region 4, Office of
Director 83/08/04 14pp 20601 024 24X Fiche 50-267, 83/08/08,
8310030456

8310060013 Forwards IE Insp Rept 50-267/83-17 on 830621-24 & notice
of violation
MADSEN, G L Region 4, Office of Director 83/08/22 LCF, O R
Public Service Co of Colorado 2pp 20649 243 24X
Fiche 50-267, 83/08/22, 8310060013

--8310060014 Notice of violation from insp on 830621-24
* Region 4, Office of Director 83/08/22 1p 20649 244 24X
Fiche 50-267, 83/08/22, 8310060013

--8310060015 IE Insp Rept 50-267/83-17 on 830621-24 Noncompliance noted
Failure to locate records of reactor bldg exhaust filter
tests from previous insp
HOLLEY, W L, MURRAY, D, HUNNICUTT, D Region 4, Office of Director
83/08/15 7pp 20649 246 24X Fiche 50-267, 83/08/22, 8310060013

8310040580 Forwards IE Insp Rept 50-267/83-22 on 830701-31 & notice
of violation
MADSEN, G L Region 4, Office of Director 83/08/24 LCF, O R
Public Service Co of Colorado 2pp 20622 283 24X
Fiche 50-267, 83/08/24, 8310040580

--8310040583 Notice of violation from insp on 830701-31
* Region 4, Office of Director 83/08/24 3pp 20622 285 24X
Fiche 50-267, 83/08/24, 8310040580

--8310040589 IE Insp Rept 50-267/83-22 on 830701-31 Noncompliance noted
Failure to follow procedures re safety practices for welding
in elevated areas, issuance of surveillance test deviation
rept & entries in operator log
PLUMLEE, G L, HUNNICUTT, D M Region 4, Office of Director
83/08/18 18pp 20622 288 24X Fiche 50-267, 83/08/24, 8310040580

8310040558 Forwards IE Insp Rept 50-267/83-20 on 830725-29 & notice of
violation
MADSEN, G L Region 4, Office of Director 83/09/06 LCF, O R
Public Service Co of Colorado 2pp 20625 344 24X
Fiche 50-267, 83/09/06, 8310040558

--8310040566 Notice of violation from insp on 830725-29
* Region 4, Office of Director 83/09/06 1p 20625 346 24X
Fiche 50-267, 83/09/06, 8310040558

--8310040644 IE Insp Rept 50-267/83-20 on 830725-29 Noncompliance noted
Failure to distribute security program audit to corporate
mgt Details withheld (ref 10CFR73.21)
EVANS, C A, KELLY, J, HUNNICUTT, D Region 4, Office of Director
83/09/01 1p 20625 347 24X Fiche 50-267, 83/09/06, 8310040558

8310040169 Responds to NRC 830819 ltr re violations noted in IE insp on
830801-05 Corrective actions (change Notice 1377 will be
reissued to identify Door 46 as Class 1 & control room door
holes filled
BREY, H L Public Service Co of Colorado 83/09/19 MADSEN, G L
Region 4, Office of Director 4pp 20608 214 24X
Fiche 50-267, 83/09/19, 8310040169

8310040210 Responds to NRC 830824 ltr re violations noted in IE Insp
Rept 50-267/83-22 Corrective actions welder received
documented, verbal reprimand re failure to follow proper
procedures for welding in elevated areas
WAREMBOURG, D W Public Service Co of Colorado 83/09/19
COLLINS, J T Region 4, Office of Director 6pp 20615 001 24X
Fiche 50-267, 83/09/19, 8310040169

8310130286 Responds to IE Bulletin 83-06, "Nonconforming Matls
Supplied by Tube-Line Corp " Tube-Line Corp never supplied
matl to util for use in safety-related sys
BREY, H L Public Service Co of Colorado 83/09/19 WAGNER, R C
Region 4, Office of Director 1p 20719 148 24X
Fiche 50-267, 83/09/19, 8310130286

8310040276 Responds to NRC 830902 ltr re violations noted in IE Insp
Rept 50-267/83-16 Corrective actions guard force personnel
retrained
WAREMBOURG, D W Public Service Co of Colorado 83/09/20
COLLINS, J T Region 4, Office of Director 3pp 20613 088 24X
Fiche 50-267, 83/09/20, 8310040276

8310130236 Responds to NRC 830906 ltr re violations noted in IE Insp
Rept 50-267/83-20 Corrective actions security program audit
distribution matrix developed & utilized beginning 830408 &
rev to Procedure G-18 effective 830624
GAHM, J W Public Service Co of Colorado 83/09/23 COLLINS, J T
Region 4, Office of Director 3pp 20723 283 24X
Fiche 50-267, 83/09/23, 8310130236

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder
Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
Detectors Positioned at Control Room Ventilation Air
Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse
Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to
Safety-Related Sys W/o 10CFR50.59 Evaluation " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/27 Consolidated Edison Co of New
York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass
Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical
Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8310180180 Notification of 831012 significant licensee meeting in
Arlington, TX to discuss potential enforcement action re
out-of-svc diesel generator & failure to verify operability
of backup diesel generator
* Region 4, Office of Director 83/10/07 Region 4, Office of
Director 1p 20808 342 24X Fiche 50-267, 83/10/07, 8310180180

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect
Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective
Self-Contained Breathing Apparatus Air Cylinders " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

DOCKETED ITEMS

10310422 Confirms commitments from 831012 enforcement conference re diesel generator test requirements in Tech Spec 4.6.1 Revs to electrical portions will be submitted prior to end of next refueling outage
COLLINS, J T Region 4, Office of Director 83/10/13 LEC, O R
Public Service Co of Colorado 2pp 20759 184 24X
Fiche 50-267, 83/10/13, 8310310422

10310294 Forwards Structural & Geotechnical Engineering Branch SCR re IE Bulletin 80-11, "Masonry Wall Design," based on encl Franklin Research Ctr technical evaluation rept All masonry walls, except 17 credited as structural elements, acceptable
JOHNSON, E H Region 4, Office of Director 83/10/18 LEC, O R
Public Service Co of Colorado 2pp 20961 234 24X
Fiche 50-267, 83/10/18, 8310310294

8310310302 SER re IE Bulletin 80-11, "Masonry Wall Design " Items 2(b) & 3 of bulletin acceptable, w/exception of 17 walls requiring use of joint reinforcement
* Structural & Geotechnical Engineering Branch 83/10/18 Ppp
20961 236 24X Fiche 50-267, 83/10/18, 8310310294

8309200506 "Masonry Wall Design, Fort St Vrain Nuclear Plant," technical evaluation rept
LEA, K, CON, V N Franklin Institute/Franklin Research Center
NRC-03-81-130 TER-0506-242 83/09/16 CHOKSHI, N C NRC - No Detailed Affiliation Given 31pp 20961 238 24X
Fiche 50-267, 83/10/18, 8310310294

8308310512 "Use of Joint Reinforcement in Block Masonry Walls," technical evaluation rept
BECIA, I J Franklin Institute/Franklin Research Center
HAMID, A A, HARRIS, H O Drexel Univ, Philadelphia, PA
NRC-03-31-130 83/03/31 NRC - No Detailed Affiliation Given 9pp 20961 269 24X Fiche 50-267, 83/10/18, 8310310274

10310298 Act receipt of 830926 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-267/83-22 Reply responsive to NRC concerns
JOHNSON, E H Region 4, Office of Director 83/10/18 LEC, O R
Public Service Co of Colorado 1p 20961 134 24X
Fiche 50-267, 83/10/18, 8310310298

Periodic operating reports & related correspondence

10170260 Monthly Operating Rept 116 for Sept 1983 W/831012 ltr
FULLER, C H, WAREMBOURG, D Public Service Co of Colorado
83/10/07 Director's Office, Office of Inspection and Enforcement 9pp 20707 091 24X Fiche 50-267, 83/10/07, 8310170260

Reportable occurrences, LERs & related correspondence

10040315 Forwards LERs 83-031/03L-0 & 83-032/03L-0 & updated LER 82-049/01X-1 Detailed summary encl
WAREMBOURG, D Public Service Co of Colorado 83/09/16
COLLINS, J T Region 4, Office of Director 25pp 20620 140 24X
Fiche 50-267, 83/09/16, 8310040315

8310040322 Updated LER 82-049/01X-1 on 821208, secondary-to-primary side leak discovered in loop 2 steam generator Cause unidentified but appears random in nature Tube ends plugged & capped
NOVACHEK, F J, HELLER, R A, MCBRIDE, L M Public Service Co of Colorado 83/09/16 Region 4, Office of Director 5pp
20620 165 24X Fiche 50-267, 83/09/16, 8310040315

8310040324 LER 83-031/03L-0 on 830818, one hydraulic snubber found inoperable Caused by leaking reservoir fittings allowing loss of oil Snubber replaced w/rebuilt snubber
FRYE, D L, NOVACHEK, F J, MCBRIDE, L M Public Service Co of Colorado 83/09/16 Region 4, Office of Director 3pp
20620 170 24X Fiche 50-267, 83/09/16, 8310040315

8310040328 LER 83-032/03L-0 on 830819, motor driven boiler feed pump removed from svc to repair leaking water valve Caused by normal wear Valve, pipe & flange assembly prefabricated & installed
NOVACHEK, F J, DICKERSON, R A, MCBRIDE, L M Public Service Co of Colorado 83/09/16 Region 4, Office of Director 4pp
20620 173 24X Fiche 50-267, 83/09/16, 8310040315

0040207 LER 83-033/03L-0 on 830827, gas waste vacuum tank rupture (sc found ruptured Date of rupture undeterminable Cause not stated Disc disassembled, replaced & returned to svc W/830926 ltr
NOVACHEK, F J, WAREMBOURG, D, BANAGAS, L J Public Service Co of Colorado 83/09/26 COLLINS, J T Region 4, Office of Director 1pp 20614 326 24X Fiche 50-267, 83/09/26, 8310040307

8310180180 Notification of 831012 significant licensee meeting in Arlington, TX to discuss potential enforcement action re out-of-svc diesel generator & failure to verify operability of backup diesel generator
* Region 4, Office of Director 83/10/07 Region 4, Office of Director 1p 20808 342 24X Fiche 50-267, 83/10/07, 8310180180

DOCKET 50-269 DCDNEE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plan

8310070134 Releases public version of revised crisis mgt plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/04 Document Management Branch 1p 20670 001 24X Fiche 50-000, 83/10/04, 8310070134

--8310070143 Forwards public version of revised crisis mgt plan implementing procedures, including Procedures 5.1.1 re recovery manager & immediate staff group plan & 5.1.4 re scheduling/planning support group
TUCKER, H B Duke Power Co 83/07/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20670 002 24X
Fiche 50-000, 83/10/04, 8310070134

--8310070152 Public version of revised crisis mgt plan implementing procedures, including Procedure 5.3.1 re recovery manager & immediate staff group plan & 5.3.4 re scheduling/planning support group
* Duke Power Co 83/07/01 457pp 20670 005 24X
Fiche 50-000, 83/10/04, 8310070134

8310110067 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20709 160 24X Fiche 50-269, 83/10/05, 8310110067

--8310110076 Forwards public version of revised emergency plan implementing procedures, including Procedure CP/D/B/4003/01 re environ surveillance following large unplanned release of gaseous radioactivity Receipt form encl
TUCKER, H B, MCINTOSH, J T Duke Power Co 83/09/14 O'REILLY, J P Region 2, Office of Director 2pp 20709 161 24X
Fiche 50-269, 83/10/05, 8310110067

--8310110080 Public version of revised emergency plan implementing procedures, including Procedure CP/D/B/4003/01 re environ surveillance following large unplanned release of gaseous radioactivity
SMITH, J E Duke Power Co 83/09/08 50pp 20709 163 24X
Fiche 50-269, 83/10/05, 8310110067

8310110135 Releases public version of rev to emergency procedure
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20707 319 24X Fiche 50-269, 83/10/05, 8310110135

--8310110141 Public version of Rev 83-5 to Emergency Procedure AP/D/B/1000/07, "Procedure for Offsite Dose Calculation by Control Room Personnel or Emergency Coordinator During Radiological Accident " W/830830 ltr
SMITH, J E, TUCKER, H B, MCINTOSH, J T Duke Power Co 83/07/22 O'REILLY, J P Region 2, Office of Director 19pp 20707 320 24X Fiche 50-269, 83/10/05, 8310110135

8310250354 Forwards IE Insp Repts 50-269/83-27, 50-270/83-27 & 50-287/83-27 on 830912-16 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/10/05 TUCKER, H B Duke Power Co 2pp 20708 123 24X
Fiche 50-269, 83/10/05, 8310250354

--8310250363 IE Insp Repts 50-269/83-27, 50-270/83-27 & 50-287/83 27 on 830912-16 No noncompliance noted Major areas inspected emergency detection & classification, protective action decisionmaking, public info program & shift staffing
DECKER, T R Region 2, Office of Director 83/09/30 5pp 20898 125 24X Fiche 50-269, 83/10/05, 8310250354

8310180444 Responds to request for crisis mgt ctr staff to participate in emergency exercises at same frequency as technical support ctr staff Crisis mgt team will be activated in full-scale exercise involving full state participation
TUCKER, H B Duke Power Co 83/10/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20802 121 24X
Fiche 50-000, 83/10/10, 8310180444

8310250635 Informs that periodic evaluation of SALP complete Rept approved
O'REILLY, J P Region 2, Office of Director 83/10/17 TUCKER, H B Duke Power Co 3pp 20900 205 24X Fiche 50-000, 83/10/17, 8310250635

DOCKETED ITEMS

71

--8310250692 SALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 For June 1982 - Apr 1983
* Region 2, Office of Director 83/08/02 56pp 20900 211 24X
Fiche 50-000, 83/10/17, 8310250692

8310280029 Forwards request for exemption from fire protection requirements of 10CFR50, App B, Section III J re emergency lighting in control room, stairwells/corridors, outside auxiliary bldg & standby shutdown facility
TUCKER, H B Duke Power Co 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 4pp 20934 285 24X Fiche 50-269, 83/10/24, 8310280029

8310280124 Supplis 830603 ltr re exemption request from location requirements of emergency operations facility Significant benefits not achieved by near-site facility up to 70 miles from plant Meeting w/NRC requested
TUCKER, H B Duke Power Co 83/10/25 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 20929 266 24X Fiche 50-269, 83/10/25, 8310280124

P Operating license stage documents & correspondence

8310040111 Responds to 830531 & 0826 ltrs requesting amnd to 830318 confirmatory order re NUREG-0437, Item II F 1.5: "Containment Water Level Monitor." Amend not required. Invoiron qualification will be addressed in 10CFR50.49 audit
STOLZ, J F Operating Reactors Branch 4 83/09/02 TUCKER, H B Duke Power Co 5pp 20627 351 24X Fiche 50-269, 83/09/02, 8310040111

8310040647 Forwards SER accepting Arkansas Power & Light Co (APL) 830607 proposed mods to reactor trip breakers for B&W plants Requested info should be provided when APL generic design endorsed in response to Generic Ltr 83-28
STOLZ, J F Operating Reactors Branch 4 83/09/12 TUCKER, H B Duke Power Co 2pp 20627 303 24X Fiche 50-269, 83/09/12, 8310040647

831010545 Forwards Amends 123, 123, & 120 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & CIA Amends allow increase in spent fuel storage capacity from 474 to max of 825 fuel assemblies in Unit 3 spent fuel pool
STOLZ, J F Operating Reactors Branch 4 83/09/29 TUCKER, H B Duke Power Co 2pp 20711 265 24X Fiche 50-269, 83/09/29, 831010545

--831010561 Amends 123, 123 & 120 to Licenses DPR-38, DPR-47 & DPR-55, respectively, changing Tech Specs to allow increase in spent fuel storage capacity from 474 to max of 825 fuel assemblies in Unit 3 spent fuel pool
STOLZ, J F Operating Reactors Branch 4 83/09/29 11pp 20711 267 24X Fiche 50-269, 83/09/29, 831010561

--831010569 Safety evaluation supporting Amends 123, 123 & 120 to Licenses DPR-38, DPR-47 & DPR-55, respectively
* Office of Nuclear Reactor Regulation, Director 83/09/29 14pp 20711 278 24X Fiche 50-269, 83/09/29, 831010569

--831010575 EIA supporting Amends 123, 123 & 120 to Licenses DPR-38, DPR-47 & DPR-55, respectively
* Office of Nuclear Reactor Regulation, Director 83/09/29 10pp 20711 292 24X Fiche 50-269, 83/09/29, 831010575

8310140143 Forwards proprietary "Rancho Seco Cycle 7 Reload Rept - Vol I - Mark B2 Fuel Assembly Design Rept," in support of Cycle 7 reload planned for late 1984 Rept withheld (ref 10CFR2.790)
TUCKER, H B Duke Power Co 83/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 20766 067 24X Fiche 50-000, 83/10/07, 8310140143

--8310140145 Forwards proprietary "Rancho Seco Cycle 7 Reload Rept - Vol I - Mark B2 Fuel Assembly Design Rept," Apr 1983 Affidavit supporting determination of proprietary nature of rept encl
TAYLOR, J H Babcock & Wilcox Co 83/09/15 MINER, B Office of Nuclear Reactor Regulation, Director Bpp 20766 069 24X Fiche 50-000, 83/10/07, 8310140145

8310140253 Forwards info re inservice pump & valve testing program W/a encl
TUCKER, H B Duke Power Co 83/10/10 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 20761 332 24X Fiche 50-269, 83/10/10, 8310140253

8310240151 Forwards steam generator operating history info valid through 821231
TUCKER, H B Duke Power Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 44pp 20881 176 24X Fiche 50-269, 83/10/13, 8310240151

8310310489 Summary of 830826 meeting w/B&W Owners Group re implementation of Generic Ltr 83-28 concerning defenses against ATWS & proposed ATWS rule for B&W plants List of attendees & viewpoints encl
KADAMBI, P Operating Reactors Branch 4 83/10/20 Operating Reactors Branch 4 13pp 20963 147 24X Fiche 50-000, 83/10/20, 8310310489

8310280105 Forwards update of progress of control room habitability mods, per 830922 ltr re TMI Item III D J 4 HVAC equipment operating at approx 2/3 design capacity Updated work list & schedules encl
TUCKER, H B Duke Power Co 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 20935 324 24X Fiche 50-269, 83/10/24, 8310280105

Q Inspection reports, IE Bulletins & correspondence

8310040290 Forwards IE Insp Repts 50-269/83-24, 50-270/83-24 & 50-287/83-24 on 830725-0803 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/08/30 TUCKER, H B Duke Power Co 2pp 20617 268 24X Fiche 50-269, 83/08/30, 8310040290

--8310040294 IE Insp Repts 50-269/83-24, 50-270/83-24 & 50-287/83-24 on 830725-0803 No noncompliance noted Major areas inspected containment integrated leakage rate testing & followup on previous items
BROOKS, C H Region 2, Office of Director JAFFE, F Division of Engineering & Operational Programs 83/08/26 4pp 20617 270 24X Fiche 50-269, 83/08/30, 8310040290

8310040375 Responds to IE Bulletin 83-05, "ASME Nuclear Code Pumps & Spare Parts Mfg by Hayward Tyler Pump Co." One Hayward Tyler pump currently installed in Unit 1 & 2 spent fuel cooling sys Twelve pumps to be installed in radwaste facility
TUCKER, H B Duke Power Co 83/09/08 O'REILLY, J P Region 2, Office of Director 5pp 20622 278 24X Fiche 50-269, 83/09/08, 8310040375

8310040247 Forwards IE Insp Repts 50-269/83-25, 50-270/83-25 & 50-287/83-25 on 830809-11 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/09 TUCKER, H B Duke Power Co 2pp 20613 194 24X Fiche 50-269, 83/09/09, 8310040247

--8310040253 IE Insp Repts 50-269/83-25, 50-270/83-25 & 50-287/83-25 on 830809-11 No noncompliance noted Major areas inspected zero power physics testing & power escalation testing
DAVENPORT, W E Region 2, Office of Director JAFFE, F Division of Engineering & Operational Programs 83/09/07 5pp 20613 196 24X Fiche 50-269, 83/09/09, 8310040247

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340.

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310250248 Forwards IE Insp Repts 50-269/83-28, 50-270/83-28 & 50-287/83-28 on 830811-0910 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/27 TUCKER, H B Duke Power Co 1p 20899 074 24X Fiche 50-269, 83/09/27, 8310250248

--8310250256 IE Insp Repts 50-269/83-28, 50-270/83-28 & 50-287/83-28 on 830811-0910 No noncompliance noted Major areas inspected operations, maint surveillance, training & NUREG-0737 items.
BRYANT, J. FALCONER, D Region 2, Office of Director BROWNLEE, V Division of Project & Resident Programs 83/09/27 10pp 20899 075 24X Fiche 50-269, 83/09/27, 8310250248

8310040484 Ack receipt of 830919 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-269/83-26
DANCE, H C Division of Project & Resident Programs 83/09/28 TUCKER, H B Duke Power Co 1p 20625 170 24X Fiche 50-269, 83/09/28, 8310040484

DOCKETED ITEMS

- 8310040492 Responds to NRC 830824 ltr re violations noted in IF Insp Repts 50-269/83-26, 50-270/83-26 & 50-287/83-26 Corrective actions recirculation & release procedures revised to verify sign off for closing valves
TUCKER, H B Duke Power Co 83/09/19 O'REILLY, J P Region 2, Office of Director 2pp 20625 171 24X Fiche 50-269, 83/09/28, 8310040494
- 8310040495 Forwards IE Insp Repts 50-269/83-26, 50-270/83-26 & 50-287/83-26 on 830711-0810 & notice of violation
DANCE, H C Division of Project & Resident Programs 83/08/24
TUCKER, H B Duke Power Co 2pp 20625 173 24X
Fiche 50-269, 83/09/28, 8310040484
- 8310040500 Notice of violation from insp on 830711-0810
* Region 2, Office of Director 83/08/24 1p 20625 175 24X
Fiche 50-269, 83/09/28, 8310040484
- 8310040507 IE Insp Repts 50-269/83-26, 50-270/83-26 & 50-287/83-26 on 830711-0810 Noncompliance noted Failure to follow chemistry procedure resulting in unplanned release of radioactive water
BRYANT, J, FALCONER, D Region 2, Office of Director BROWN, F C, V Division of Project & Resident Programs 83/08/23 7pp 20625 174 24X Fiche 50-269, 83/09/28, 8310040484
- 8308300349 IE Info Notice 83-44, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 11pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349
- 8310250354 Forwards IE Insp Repts 50-269/83-27, 50-270/83-27 & 50-287/83-27 on 830912-16 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 03/10/05
TUCKER, H B Duke Power Co 2pp 20848 123 24X
Fiche 50-269, 83/10/05, 8310250354
- 8310250363 IE Insp Repts 50-269/83-27, 50-270/83-27 & 50-287/83-27 on 830912-16 No noncompliance noted Major areas inspected emergency detection & classification, protective action decisionmaking, public info program & shift staffing
DECKER, T R Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/09/30 5pp 20898 125 24X Fiche 50-269, 83/10/05, 8310250354
- 108300378 IE Info Notice 83-45, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 7pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378
- 8308300752 IE Info Notice 83-46, "Fatality at Argentine Critical Facility" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 7pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752
- 8308300759 IE Info Notice 83-47, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 11pp 21043 078 24X Fiche 50-000, 83/10/11, 8308300759
- 8308300761 IE Info Notice 83-48, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 12pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761
- 8310250635 Informs that periodic evaluation of SALP complete Rept approved.
O'REILLY, J P Region 2, Office of Director 83/10/17 TUCKER, H B Duke Power Co 3pp 20900 205 24X Fiche 50-000, 83/10/17, 8310250635
- 8310250646 Forwards SALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983
LEWIS, R C Division of Project & Resident Programs 83/08/02
TUCKER, H B Duke Power Co 3pp 20900 208 24X
Fiche 50-000, 83/10/17, 8310250635
- 8310250652 SALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983
* Region 2, Office of Director 83/08/02 5pp 20900 211 24X
Fiche 50-000, 83/10/17, 8310250635.
- 8310250655 Responds to 830802 ltr re SALP board rept Rept incomplete & premature in certain areas in general, until endorses observations re facility performance
TUCKER, H B Duke Power Co 83/08/29 O'REILLY, J P Region 2, Office of Director 2pp 20900 267 24X Fiche 50-000, 83/10/17, 8310250635
- 8310270079 Forwards response to Action Item 3 of IE Bulletin BU 11, "Masonry Wall Design" Design assumptions appropriate considering physical condition of boundary joints
TUCKER, H B Duke Power Co 83/10/20 DENTON, H R Office of Nuclear Reactor Regulation, Director STULZ, J F Operating Reactor Branch 4 3pp 20724 360 24X Fiche 50-269, 83/10/20, 8310270077
- R Periodic operating reports & related correspondence
- 8310180167 Monthly operating repts for Supt 1983 W/831014 ltr
REAVIS, J A, TUCKER, H B Duke Power Co 83/09/30 Director's Office, Office of Inspection and Enforcement 19pp 20809 095 24X
Fiche 50-269, 83/09/30, 8310180167
- B Reportable occurrences, LERs & related correspondence
- 8310260008 Addl response to FOIA request for 17 categories of records
Forwards documents listed in Apps B, C & D Info re fraudulent practices of Ray Miller, Inc available in PDR
FELTON, J M Division of Rules and Records 83/06/23 CLEWERT, J Public Citizen Litigation Group 15pp 20920 001 24X
Fiche 50-000, 83/06/23, 8310260008
- 8207260091 Discusses licensee Mar 1982 testing & evaluations of steam extraction line elbow which ruptured on 820628, in response to 820709 request for addl steam line break info
EISENHUT, D G Division of Licensing 82/07/14 RLHM, T A Office of the Executive Director for Operations 2pp 20920 020 24X
Fiche 50-000, 83/06/23, 8310260008
- 8310060426 RD on 830922, w/both Keowee hydro units out of svc for planned maint, Lee 6C gas turbine, being used to energize buses, tripped off line Both standby buses deenergized & Units 1 & 3 placed in degraded mode
TUCKER, H B Duke Power Co 83/09/27 O'REILLY, J P Region 2, Office of Director 3pp 20641 224 24X Fiche 50-269, 83/09/27, 8310060426
- 8310170536 LER 83-016/03L-0 on 830902, while performing in-place bus test for hydrogen purge unit, discharge flow instrument FT-100 damaged Caused by personnel error FT-100 repaired W/830930 ltr
PETTY, J C, TUCKER, H B Duke Power Co 83/09/30 O'REILLY, J P Region 2, Office of Director 4pp 2084 321 24X
Fiche 50-269, 83/09/30, 8310170536
- 8310140159 RD on 830929, while energizing 4,160-volt standby buses, Lee 6C gas turbine tripped off-line, deenergizing both standby buses & placing two operating units in degraded mode. Cause undetermined since unit has no event recorder
TUCKER, H B Duke Power Co 83/10/04 O'REILLY, J P Region 2, Office of Director 3pp 20765, 067 24X Fiche 50-269, 83/10/04, 8310140159
- 8310270412 RD on 831012, standby buses deenergized to allow for operability performance testing of standby bus breakers per Tech Specs Testing caused degraded mode beyond Tech Spec limit
TUCKER, H B Duke Power Co 83/10/17 O'REILLY, J P Region 2, Office of Director 2pp 20924 010 24X Fiche 50-269, 83/10/17, 8310270412
- V Operator Examinations
- 8310040425 Notifies that operator & senior operator licensing exams scheduled for wk of 831205 NRC requirements for administration of exams encl
DANCE, H C Division of Project & Resident Programs 83/09/28
TUCKER, H B Duke Power Co 3pp 20619 124 24X
Fiche 50-269, 83/09/28, 8310040425
- DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- 8310070134 Releases public version of revised crisis mgt plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/04 Document Management Branch 1p 20670, 001 24X Fiche 50-000, 83/10/04, 8310070134

DOCKETED ITEMS

73

--8310070143 Forwards public version of revised crisis mgt plan implementing procedures, including Procedures 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group
TUCKER, H B Duke Power Co 83/07/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20670 002 24X Fiche 50-000, 83/10/04, 8310070134

--8310070152 Public version of revised crisis mgt plan implementing procedures, including Procedure 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group
* Duke Power Co 83/07/01 457pp 20670 005 24X Fiche 50-000, 83/10/04, 8310070134

8310110067 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20709 160 24X Fiche 50-269, 83/10/05, 8310110067

--8310110076 Forwards public version of revised emergency plan implementing procedures, including Procedure CP/D/B/4003/01 re environ surveillance following large unplanned release of gaseous radioactivity Receipt form encl
TUCKER, H B, MCINTOSH, J T Duke Power Co 83/09/19 O'REILLY, J P Region 2, Office of Director 2pp 20709 161 24X Fiche 50-269, 83/10/05, 8310110067

--8310110080 Public version of revised emergency plan implementing procedures, including Procedure CP/D/B/4003/01 re environ surveillance following large unplanned release of gaseous radioactivity
SMITH, J E Duke Power Co 83/09/08 50pp 20709 163 24X Fiche 50-269, 83/10/05, 8310110067

8310110135 Releases public version of rev to emergency procedure
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20707 319 24X Fiche 50-269, 83/10/05, 8310110135

--8310110141 Public version of Rev 83-b to Emergency Procedure AP/D/B/1000/07, "Procedure for Offsite Dose Calculation by Control Room Personnel or Emergency Coordinator During Radiological Accident" W/630830 ltr
SMITH, J E, TUCKER, H B, MCINTOSH, J T Duke Power Co 83/07/22 O'REILLY, J P Region 2, Office of Director 19pp 20707 320 24X Fiche 50-269, 83/10/05, 8310110135

8310250354 Forwards IE Insp Repts 50-269/83-27, 50-270/83-27 & 50-287/83-27 on 830912-16 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/10/05 TUCKER, H B Duke Power Co 2pp 20698 123 24X Fiche 50-269, 83/10/05, 8310250354

--8310280363 IE Insp Repts 50-269/83-27, 50-270/83-27 & 50-287/83-27 on 830912-16 No noncompliance noted Major areas inspected emergency detection & classification, protective action decisionmaking, public info program & shift staffing
DECKER, T R Region 2, Office of Director 83/09/30 5pp 20698 125 24X Fiche 50-269, 83/10/05, 8310250354

8310180444 Responds to request for crisis mgt ctr staff to participate in emergency exercises at same frequency as technical support ctr staff Crisis mgt team will be activated in full-scale exercise involving full state participation
TUCKER, H B Duke Power Co 83/10/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20802 121 24X Fiche 50-000, 83/10/10, 8310180444

8310250635 Informs that periodic evaluation of BALP complete Rept approved
O'REILLY, J P Region 2, Office of Director 83/10/17 TUCKER, H B Duke Power Co 3pp 20900 205 24X Fiche 50-000, 83/10/17, 8310250635

--8310250652 BALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983
* Region 2, Office of Director 83/08/02 56pp 20900 211 24X Fiche 50-000, 83/10/17, 8310250635

8310280029 Forwards request for exemption from fire protection requirements of 10CFR50, App B, Section III J re emergency lighting in control room, stairwells/corridors, outside auxiliary bldg & standby shutdown facility
TUCKER, H B Duke Power Co 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 4pp 20934 285 24X Fiche 50-269, 83/10/24, 8310280029

8310280124 Supplis 830603 ltr re exemption request from location requirements of emergency operations Facility Significant benefits not achieved by near-site facility up to 20 miles from plant Meeting w/NRC requested
TUCKER, H B Duke Power Co 83/10/25 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 20929 266 24X Fiche 50-269, 83/10/25, 8310280124

P Operating license stage documents & correspondence

8310040111 Responds to 830531 & 0826 ltrs requesting amend to 830318 confirmatory order re NUREG-0737, Item II F 1 5, "Containment Water Level Monitor" Amend not required Environ qualification will be addressed in 10CFR50 49 audit
STOLZ, J F Operating Reactors Branch 4 83/09/02 TUCKER, H B Duke Power Co 5pp 20627 351 24X Fiche 50-269, 83/09/02, 8310040111

8310040647 Forwards SER accepting Arkansas Power & Light Co (APL) 830607 proposed mods to reactor trip breakers for B&W plants Requested info should be provided when APL generic design endorsed in response to Generic Ltr 83-28
STOLZ, J F Operating Reactors Branch 4 83/09/12 TUCKER, H B Duke Power Co 2pp 20627, 303 24X Fiche 50-269, 83/09/12, 8310040647

8310110545 Forwards Amends 123, 123, & 120 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & EIA Amends allow increase in spent fuel storage capacity from 474 to max of 825 fuel assemblies in Unit 3 spent fuel pool
STOLZ, J F Operating Reactors Branch 4 83/09/29 TUCKER, H B Duke Power Co 2pp 20711 265 24X Fiche 50-269, 83/09/29, 8310110545

--8310110561 Amends 123, 123 & 120 to Licenses DPR-38, DPR-47 & DPR-55, respectively, changing Tech Specs to allow increase in spent fuel storage capacity from 474 to max of 825 fuel assemblies in Unit 3 spent fuel pool
STOLZ, J F Operating Reactors Branch 4 83/09/29 11pp 20711 267 24X Fiche 50-269, 83/09/29, 8310110545

--8310110569 Safety evaluation supporting Amends 123, 123 & 120 to Licenses DPR-38, DPR-47 & DPR-55, respectively
* Office of Nuclear Reactor Regulation, Director 83/09/29 14pp 20711 278 24X Fiche 50-269, 83/09/29, 8310110545

--8310110575 EIA supporting Amends 123, 123 & 120 to Licenses DPR-38, DPR-47 & DPR-55, respectively
* Office of Nuclear Reactor Regulation, Director 83/09/29 10pp 20711 292 24X Fiche 50-269, 83/09/29, 8310110545

8310140253 Forwards info re inservice pump & valve testing program. W/o encl
TUCKER, H B Duke Power Co 83/10/10 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 20761 332 24X Fiche 50-269, 83/10/10, 8310140253

8310240151 Forwards steam generator operating history info valid through 821231
TUCKER, H B Duke Power Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 44pp 20881 176 24X Fiche 50-269, 83/10/13, 8310240151

8310310489 Summary of 830826 meeting w/B&W Owners Group re implementation of Generic Ltr 83-28 concerning defenses against ATWS & proposed ATWS rule for B&W plants list of attendees & viewgraphs encl
KADAMBI, P Operating Reactors Branch 4 83/10/20 Operating Reactors Branch 4 13pp 20965 147 24X Fiche 50-000, 83/10/20, 8310310489

8310280105 Forwards update of progress of control room habitability mods, per 830922 ltr re TMI item III D 3 4 HVAC equipment operating at approx 2/3 design capacity Updated work list & schedules encl
TUCKER, H B Duke Power Co 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 20935 324 24X Fiche 50-269, 83/10/24, 8310280105

0 Inspection reports, IE Bulletins & correspondence

8310040290 Forwards IE Insp Repts 50-269/83-24, 50-270/83-24 & 50-287/83-24 on 830725-0803 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/08/30 TUCKER, H B Duke Power Co 2pp 20617 268 24X Fiche 50-269, 83/08/30, 8310040290

DOCKETED ITEMS

- B310040294 IE Insp Repts 50-269/83-24, 50-270/83-24 & 50-287/83-24 on 830725-0803 No noncompliance noted Major areas inspected containment integrated leakage rate testing & followup on previous items
BROOKS, E H Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs 83/08/26 App 20617 270 24X Fiche 50-269, 83/08/30, 8310040290
- B310040575 Responds to IE Bulletin 83-05, "ASME Nuclear Code Pumps & Spare Parts Mfg by Hayward Tyler Pump Co " One Hayward Tyler pump currently installed in Unit 1 & 2 spent fuel cooling sys. Twelve pumps to be installed in radwaste facility
TUCKER, H B Duke Power Co 83/09/08 O'REILLY, J P Region 2, Office of Director App 20622 278 24X Fiche 50-269, 83/09/08, 8310040575
- B310040247 Forwards IE Insp Repts 50-269/83-25, 50-270/83-25 & 50-287/83-25 on 830809-11 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/07
TUCKER, H B Duke Power Co App 20613 194 24X
Fiche 50-269, 83/09/09, 8310040247
- B310040253 IE Insp Repts 50-269/83-25, 50-270/83-25 & 50-287/83-25 on 830809-11 No noncompliance noted Major areas inspected term power physics testing & power escalation testing
DAVENPORT, K E Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs 83/09/07 App 20613 196 24X Fiche 50-269, 83/09/09, 8310040247
- B308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20734 022 24X Fiche 50-000, 83/09/26, 8308300340
- B308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342
- B308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345
- B310250248 Forwards IE Insp Repts 50-269/83-28, 50-270/83-28 & 50-287/83-28 on 830811-0910 No noncompliance noted.
DANCE, H C Division of Project & Resident Programs 83/09/27
TUCKER, H B Duke Power Co App 20699 074 24X
Fiche 50-269, 83/09/27, 8310250248
- B310250256 IE Insp Repts 50-269/83-28, 50-270/83-28 & 50-287/83-28 on 830811-0910 No noncompliance noted Major areas inspected operations, maint surveillance, training & NUREG-0737 items
BRYANT, J, FALCONER, D Region 2, Office of Director BROWNLEE, V Division of Project & Resident Programs 83/09/27 10pp 20699 075 24X Fiche 50-269, 83/09/27, 8310250248
- B310040484 Ack receipt of 830919 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-269/83-26
DANCE, H C Division of Project & Resident Programs 83/09/28
TUCKER, H B Duke Power Co App 20625 170 24X
Fiche 50-269, 83/09/28, 8310040484
- B310040492 Responds to NRC 830824 ltr re violations noted in IE Insp Repts 50-269/83-26, 50-270/83-26 & 50-287/83-26 Corrective actions recirculation & release procedures revised to verify sign off for closing valves
TUCKER, H B Duke Power Co 83/09/19 O'REILLY, J P Region 2, Office of Director App 20625 171 24X Fiche 50-269, 83/09/28, 8310040484
- B310040493 Forwards IE Insp Repts 50-269/83-26, 50-270/83-26 & 50-287/83-26 on 830711-0810 & notice of violation
DANCE, H C Division of Project & Resident Programs 83/08/24
TUCKER, H B Duke Power Co App 20625 173 24X
Fiche 50-269, 83/09/28, 8310040484
- B310040507 IE Insp Repts 50-269/83-26, 50-270/83-26 & 50-287/83-26 on 830711-0810 Noncompliance noted, failure to follow chemistry procedure resulting in unplanned release of radioactive water
BRYANT, J, FALCONER, D Region 2, Office of Director BROWNLEE, V Division of Project & Resident Programs 83/08/23 7pp 20625 176, 24X Fiche 50-269, 83/09/28, 8310040484
- B308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20716 144 24X Fiche 50-000, 83/09/26, 8308300349
- B310250354 Forwards IE Insp Repts 50-269/83-27, 50-270/83-27 & 50-287/83-27 on 830712-16 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/10/05
TUCKER, H B Duke Power Co App 20699 133 24X
Fiche 50-269, 83/10/05, 8310250354
- B310250363 IE Insp Repts 50-269/83-27, 50-270/83-27 & 50-287/83-27 on 830712-16 No noncompliance noted Major areas inspected emergency detection & classification, protective action decisionmaking, public info program & shift staffing
DECKER, T R Region 2, Office of Director BROWNLEE, V Division of Emergency Preparedness & Materials Safety 83/09/20 App 20699 125 24X Fiche 50-269, 83/10/05, 8310250363
- B308300370 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 211 24X Fiche 50-000, 83/10/07, 8308300370
- B308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 77pp 20832 026 24X Fiche 50-000, 83/10/07, 8308300752
- B308300759 IE Info Notice 83-67, "Emergency Use Respirator Malfunction Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 073 24X Fiche 50-000, 83/10/11, 8308300759
- B308300761 IE Info Notice 83-68, "Respirator User Wearing Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761
- B310250635 Informs that periodic evaluation of HARP complete Rept approved
O'REILLY, J P Region 2, Office of Director 83/10/17 TUCKER, H B Duke Power Co App 20700 210 24X Fiche 50-000, 83/10/17, 8310250635
- B310250646 Forwards HARP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-24, 50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983
LEWIS, H C Division of Project & Resident Programs 83/09/02
TUCKER, H B Duke Power Co App 20700 208 24X
Fiche 50-000, 83/10/17, 8310250646
- B310250652 HARP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-24, 50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983
Region 2, Office of Director 83/09/02 App 20700 211 24X Fiche 50-000, 83/10/17, 8310250652
- B310250665 Responds to 830802 ltr re HARP board rept Rept incomplete & premature in certain areas in general, until endorep observations re facility performance
TUCKER, H B Duke Power Co 83/09/29 O'REILLY, J P Region 2, Office of Director App 20700 267 24X Fiche 50-000, 83/10/17, 8310250665
- B310270079 Forwards response to Action Item 3 of IE Bulletin 80-11, "Masonry Wall Design " Design assumptions appropriate considering physical condition of boundary joints
TUCKER, H B Duke Power Co 83/10/20 DINTON, H H Office of Nuclear Reactor Regulation, Director STOKER, J J Operating Reactor Branch 4 App 20924 360 24X Fiche 50-269, 83/10/30, 8310270079
- R Periodic operating reports & related correspondence
- B310180167 Monthly operating repts for Sept 1983 W/831014 ltr
REAVIS, J A, TUCKER, H B Duke Power Co 83/09/30, Director's Office, Office of Inspection and Enforcement, 19pp 20809 095 24X Fiche 50-269, 83/09/30, 8310180167

DOCKETED ITEMS

75

S Reportable occurrences, LERs & related correspondence

8310260008 Addl response to FOIA request for 17 categories of records
Forwards documents listed in Apps B, C & D info re
fraudulent practices of Ray Miller, Inc available in PDR
FELTON, J M Division of Rules and Records 83/06/23 CLEWETT, J
Public Citizen Litigation Group 13pp 20290 001 24X
Fiche 50-000, 83/06/23, 8310260008

--8207260091 Discusses licensee Mar 1982 testing & evaluations of steam
extraction line elbow which ruptured on 820628, in response
to 820709 request for addl steam line break info
EISENHUT, D G Division of Licensing 82/07/14 REHM, J A Office
of the Executive Director for Operations 2pp 20920 020 24X
Fiche 50-000, 83/06/23, 8310260008

--8310260027 Forwards initial info re 830628 steamline break event at
facility, per 830702 telcon request Review of licensee
actions continuing
MARTIN, R D Region 2, Office of Director 83/07/07 REHM, J A
Office of the Executive Director for Operations 5pp 20920 022
24X Fiche 50-000, 83/06/23, 8310260008

8310060426 RO on 830922, w/both Keowee hydro units out of svc for
planned maint, Lee 6C gas turbine, being used to energize
buses, tripped off line Both standby buses deenergized &
Units 1 & 3 placed in degraded mode
TUCKER, H B Duke Power Co 83/09/27 O'REILLY, J P Region 2,
Office of Director 3pp 20641 224 24X Fiche 50-269, 83/09/27,
8310060426

8310140157 RO on 830929, while energizing 4, 160-volt standby buses, Lee
6C gas turbine tripped off-line, deenergizing both standby
buses & placing two operating units in degraded mode Cause
undetermined since unit has no event recorder
TUCKER, H B Duke Power Co 83/10/04 O'REILLY, J P Region 2,
Office of Director 3pp 20765 067 24X Fiche 50-269, 83/10/04,
8310140157

8310270412 RO on 831012, standby buses deenergized to allow for
operability performance testing of standby bus breakers per
Tech Specs Testing caused degraded mode beyond Tech Spec
limit
TUCKER, H B Duke Power Co 83/10/17 O'REILLY, J P Region 2,
Office of Director 2pp 20924 010 24X Fiche 50-269, 83/10/17,
8310270412

V Operator Examinations

8310040425 Notifies that operator & senior operator licensing exams
scheduled for wk of 831205 NRC requirements for
administration of exams encl
DANCE, H C Division of Project & Resident Programs 83/09/28
TUCKER, H B Duke Power Co 3pp 20619 124 24X
Fiche 50-269, 83/09/28, 8310040425

DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION

F Security, medical, emergency & fire protection plans

8310140240 Forwards IE Insp Rept 50-271/83-21 on 830801-0905 No
noncompliance noted
STAROSTECKI, P Division of Project & Resident Programs 83/09/27
MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp 20762 006
24X Fiche 50-271, 83/09/27, 8310140240

--8310140245 IE Insp Rept 50-271/83-21 on 830801-0905 No noncompliance
noted Major areas inspected action on previous insp
findings, plant power operations, including status &
operational records, physical security & maint activities
RAYMOND, W J, HOLDEN, C F, GALLO, R M Region 1, Office of
Director 83/09/26 32pp 20762 008 24X Fiche 50-271, 83/09/27,
8310140240

8310040259 Advises that assessment of two viable options for location
of primary emergency operations facilities, per Suppl 1 to
NUREG-0737, scheduled for completion in early Nov 1983 Final
decision expected by 831117
MURPHY, W P Vermont Yankee Nuclear Power Corp 83/09/29
VASSALLO, D B Operating Reactors Branch 2 2pp 20617 266 24X
Fiche 50-271, 83/09/29, 8310040259

8310310307 Submits results of engineering evaluation of two possible
modes to automatic depressurization sys logic per NUREG-0737,
Item II K 3 B Problem better addressed by using
symptom-based emergency operating procedure
MURPHY, W P Vermont Yankee Nuclear Power Corp 83/10/26
VASSALLO, D B Operating Reactors Branch 2 2pp 20761 274 24X
Fiche 50-271, 83/10/26, 8310310307

P Operating license stage documents & correspondence

8310310017 FOIA request for documents re integrated leak rate tests for
listed facilities to be placed in PDR
CONNER, L Affiliation Unknown 83/05/02 NRC - No Detailed
Affiliation Given 1p 21004 270 24X Fiche 50-000, 83/05/02,
8310310017

8310310031 Responds to FOIA request for documents re integrated leak
rate tests for facilities to be placed in PDR Forwards
documents to be placed in PDR & list of facilities for which
repts are unavailable
FELTON, J M Division of Rules and Records 83/07/06 CONNER, L
Affiliation Unknown 1p 21004 271 24X Fiche 50-000, 83/07/06,
8310310031

--8310310061 "Integrated Primary Containment Leakage Rate Test "
TARNUZZER, E C Vermont Yankee Nuclear Power Corp YAE-1055
72/02/07 67pp 21005 280 24X Fiche 50-000, 83/07/06, 8310310031

8310120312 Forwards technical rept "Mark 1 Containment Program Plant-
Unique Analysis Rept of Torus Attached Piping for Vermont
Yankee Nuclear Power Plant "
SINGLAIR, J B Vermont Yankee Nuclear Power Corp 83/10/06
VASSALLO, D B Operating Reactors Branch 2 1p 20697 258 24X
Fiche 50-271, 83/10/06, 8310120312

--8310120315 "Mark 1 Containment Program Plant-Unique Analysis Rept of
Torus Attached Piping for Vermont Yankee Nuclear Power
Plant "
* Teledyne Engineering Services TR-9319-2 83/10/03 95pp
20697 256 24X Fiche 50-271, 83/10/06, 8310120312

8310190097 Forwards Rev 14 to operational QA program Rev addresses
organizational & programmatic changes to QA program
SHEPARD, A H Vermont Yankee Nuclear Power Corp 83/10/12 MURLEY, T E
Region 1, Office of Director 1p 20822 117 24X
Fiche 50-000, 83/10/12, 8310190097

--8310190105 Rev 14 to operational QA program
PETERSON, W K, SHEPARD, A H, MURPHY, W P Vermont Atomic Electric
Co YOGAP-1-A R14 83/10/12 134pp 20822 118 24X
Fiche 50-000, 83/10/12, 8310190097

8310210310 Forwards response to 830104 request for addl info re
NUREG-0737, Item II D 1 "Relief & Safety Valve Test
Requirements " "Tee" quencher utilized at discharge pipe
exit
SINGLAIR, J B Vermont Yankee Nuclear Power Corp 83/10/17
VASSALLO, D B Operating Reactors Branch 2 13pp 20851 137 24X
Fiche 50-271, 83/10/17, 8310210310

8310310266 Summarizes key points of 831021 presentation on
intergranular stress corrosion cracking Weld sample selected
at facility biased towards susceptible welds All 12-inch
riser welds inspected, per IE Bulletin 83-02
MURPHY, W P Vermont Yankee Nuclear Power Corp 83/10/26
DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp
20947 136 24X Fiche 50-271, 83/10/26, 8310310266

Q Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins For Welder
Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New
York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
Detectors Positioned at Control Room Ventilation Air
Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New
York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse
Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New
York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310140234 Forwards IE Insp Rept 50-271/83-24 on 830726-28 No
noncompliance noted
MARTIN, T T Region 1, Office of Director 83/09/26 MURPHY, W P
Vermont Yankee Nuclear Power Corp 2pp 20761 314 24X
Fiche 50-271, 83/09/26, 8310140234

DOCKETED ITEMS

--8310140236 IE Insp Rept 50-271/83-24 on 830726-28 No noncompliance noted Major areas inspected licensee evaluations of alpha activity in plant sys & associated radiological health hazards
MCBRIDE, M. JANG, J. THOMPSON, T Region 1, Office of Director
83/09/22 5pp 20761 316 24X Fiche 50-271, 83/09/26, 8310140234

8310140240 Forwards IE Insp Rept 50-271/83-21 on 830801-0905 No noncompliance noted
STAROSTECKI, P Division of Project & Resident Programs 83/09/27
MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp 20762 006
24X Fiche 50-271, 83/09/27, 8310140240

--8310140245 IE Insp Rept 50-271/83-21 on 830801-0905 No noncompliance noted Major areas inspected action on previous insp findings, plant power operations, including status & operational records, physical security & maint activities
RAYMOND, W J, HOLDEN, C F, GALLO, R M Region 1, Office of Director 83/09/26 32pp 20762 008 24X Fiche 50-271, 83/09/27, 8310140240

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310200088 Forwards IE Insp Rept 50-271/83-22 on 830711-15 & 18-20 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/09/30
MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp 20836 020
24X Fiche 50-271, 83/09/30, 8310200088

--8310200090 Notice of violation from insp on 830711-15 & 18-20
a Region 1, Office of Director 83/09/30 3pp 20836 022 24X
Fiche 50-271, 83/09/30, 8310200088

--8310200092 IE Insp Rept 50-271/83-22 on 830711-15 & 18-20 Noncompliance noted operational testing & acceptance criteria, required prior to returning equipment to svc, not defined or specified on maint requests & matl issue slip numbers not documented
SHAUB, E, NAPUDA, O, GOLDBERG, S Region 1, Office of Director 83/09/27 23pp 20836 025 24X Fiche 50-271, 83/09/30, 8310200088

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882-026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180551 Notification of 831021 meeting w/BWR licensees in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking.
MIRAGLIA, F J Assistant Director for Safety Assessment 83/10/14
EISENHUT, D O Division of Licensing 5pp 20823 358 24X
Fiche 50-000, 83/10/14, 8310180551

8310310266 Summarizes key points of 831021 presentation on intergranular stress corrosion cracking Weld sample selected at facility biased towards susceptible welds All 12-inch riser welds inspected, per IE Bulletin 83-02
MURPHY, W P Vermont Yankee Nuclear Power Corp 83/10/26
DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20947 136 24X Fiche 50-271, 83/10/26, 8310310266

R Periodic operating reports & related correspondence

8310180096 Monthly operating rept for Sept 1983 W/831009 ltr
BURGER, F J, MURPHY, W P Vermont Yankee Nuclear Power Corp.
83/10/09 NRC - No Detailed Affiliation Given 7pp 20807 215
24X Fiche 50-271, 83/10/09, 8310180096

S Reportable occurrences, LERs & related correspondence

8310210329 Responds to FOIA request for all documents re significantly high rate of equipment failures for GE BWR/4 rated at 2,436 MW Forwards App A documents Documents also available in PDH
FELTON, J M Division of Rules and Records 83/07/28 HAFNER, B
Suffolk Nuclear Study Group 2pp 20882 223 24X
Fiche 50-000, 83/07/28, 8310210329

--8306010008 Discusses evaluation of LERs submitted during appraisal period May 1982-Apr 1983 for technical accuracy, completeness & intelligibility Screening for trends & patterns produced few cases which could indicate potential mgt weakness
SEYFRIT, K V Reactor Operations Analysis Branch 83/05/18
STAROSTECKI, R Division of Project & Resident Programs Jpp 20882 276 24X Fiche 50-000, 83/07/28, 8310210329

8310250531 LER 83-021/03L-0 on 830830, during surveillance on drywell pressure ECCS indicators, PT-10-101D(M) actuated at 2.57 psig Caused by instrument drift Trip unit replaced w/calibr unit W/830929 ltr
PELLETIER, J P Vermont Yankee Nuclear Power Corp 83/09/29
MURLEY, T E Region 1, Office of Director 3pp 20702 139 24X
Fiche 50-271, 83/09/29, 8310250531

8310250626 LER 83-025/01P-0 on 830928, during normal operation, main steam line radiation monitor RM-17-251A trip setpoint greater than 3 times normal background at rated power Caused by inadequate procedure Trips reset W/830929 ltr
PELLETIER, J P Vermont Yankee Nuclear Power Corp 83/09/29
MURLEY, T E Region 1, Office of Director 2pp 20700 165 24X
Fiche 50-271, 83/09/29, 8310250626

8310140082 PNO-1-83-105 on 831007, seismic event occurred in northeastern US w/magnitude of 5.2 on Richter scale in NY & 4.0 in NH No damage to equipment identified
GALLO, R M Region 1, Office of Director 83/10/07 1p 20766 116
24X Fiche 50-000, 83/10/07, 8310140082

8310250334 LER 83-025/01T-0 on 830928, main steam line rod monitor found w/trip setpoint greater than three times normal background required by Tech Specs Caused by procedural inadequacy Procedure being revised W/831012 ltr
PELLETIER, J P Vermont Yankee Nuclear Power Corp 83/10/12
MURLEY, T E Region 1, Office of Director 2pp 20897 333 24X
Fiche 50-271, 83/10/12, 8310250334

8310250379 LER 83-023/03L-0 on 830923, health physics sampling program revealed high Co-60 concentration at north storm drain outfall Caused by low level airborne releases from turbine bldg roof vents Sample point added W/831012 ltr
PELLETIER, J P Vermont Yankee Nuclear Power Corp 83/10/12
HAYNES, R C Region 1, Office of Director 3pp 20899 175 24X
Fiche 50-271, 83/10/12, 8310250379

8310250308 LER 83-022/03L-0 on 830913, reactor water cleanup sys outboard isolation valve malfunctioned Caused by faulty torque switch in valve operator Torque switch replaced & syn tested satisfactorily W/831012 ltr
PELLETIER, J P Vermont Yankee Nuclear Power Corp 83/10/13
MURLEY, T E Region 1, Office of Director 3pp 20899 001 24X
Fiche 50-271, 83/10/13, 8310250308

DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8309190260 Forwards correct page revs to security plan & security training & qualification plan Page revs withheld (ref 10CFR73 21)
* Public Service Electric & Gas Co of New Jersey 83/09/12
MARTIN, T T Division of Engineering & Technical Programs 1p 20415 362 24X Fiche 50-272, 83/09/12, 8309190260

8310210199 Forwards marked-up revised 1983 emergency exercise Rev incorporates NRC & FEMA comments from 830804 meeting Addl info re operational data & engineering problems will be submitted 2 wks prior to exercise
MOELLER, P A Public Service Electric & Gas Co of New Jersey 83/09/12
MURLEY, T E Region 1, Office of Director 143pp 20846 147 24X Fiche 50-272, 83/09/12, 8310210199

8310250512 Forwards IE Safeguards Insp Repts 50-272/83-28 & 50-311/83-28 on 830907-09 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/10/04
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp 20901 052 24X Fiche 50-272, 83/10/04, 8310250512

DOCKETED ITEMS

77

--B310250529 IE Safeguards Insp Repts 50-272/B3-28 & 50-311/B3-28 on B30907-09 No noncompliance noted Major areas inspected security sys power supply, detection aids - vital areas & licensee implementing procedure evaluation SMITH, G C, GUDY, A T Region 1, Office of Director B3/10/03 2pp 20701 054 24X Fiche 50-272, B3/10/04, B310250512

G Adjudicatory correspondence

B310250038 Petition for leave to intervene & request for hearing on proposed issuance of amend to License DPR-70 re inservice integrated leak tests Affidavit of Mailing encl SILVERMAN, F S, DELANEY, C E Delaware, State of B3/10/21 Commissioners 6pp 20894 184 24X Fiche 50-272, B3/10/21, B310250038

K Utility Final Safety Analysis Report (FSAR) & amends

B310180251 Forwards Rev 2 to updated FSAR, consisting of drawings updated since B30802 Rev 1 LIDEN, E A Public Service Electric & Gas Co of New Jersey B3/10/12 VARGA, S A Operating Reactors Branch 1 2pp 20809 230 24X Fiche 50-272, B3/10/12, B310180251

--B310180253 Rev 2 to updated FSAR, consisting of drawings updated since B30802 Rev 1 * Public Service Electric & Gas Co of New Jersey B3/09/21 39pp 20809 240 24X Fiche 50-272, B3/10/12, B310180251

P Operating license stage documents & correspondence

B310050199 Forwards "Plan for Improvement of Nuclear Dept Operations." in response to Basic Energy Technology Assoc, Inc rept & cross ref document, "Rept on Review of Corrective Action Program re Reactor Trip Breaker Failures" UDERITZ, R A Public Service Electric & Gas Co of New Jersey B3/08/26 VARGA, S A Operating Reactors Branch 1 2pp 20632 170 24X Fiche 50-272, B3/08/26, B310050199

--B310050164 "Plan for Improvement of Nuclear Dept Operations" * Public Service Electric & Gas Co of New Jersey B3/08/26 57pp 20632 180 24X Fiche 50-272, B3/08/26, B310050199

--B310050174 "Response to Basic Energy Technology Assoc, Inc Rept on Review of Corrective Action Program re Reactor Trip Breaker Failures at Salem Generating Station, Unit 1" Cross ref encl * Public Service Electric & Gas Co of New Jersey B3/08/26 23pp 20632 241 24X Fiche 50-272, B3/08/26, B310050199

B310060557 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept of util response to TMI Item II K 3 17, "Rept on Outages of ECCS" VARGA, S A Licensing Branch 1 B3/09/27 UDERITZ, R A Public Service Electric & Gas Co of New Jersey App. 20664 127 24X Fiche 50-272, B3/09/27, B310060557

--B310010087 "ECCS Repts (F-47) TMI Action Plan Requirements, PSL&Q, Salem Nuclear Generating Station Unit 1," technical evaluation rept VOSBURY, F W, OVERBECK, O J, LUDINGTON, B W Franklin Institute/Franklin Research Center NRC-03-80-130 TER-C5506-294 B2/09/28 CHOW, E NRC - No Detailed Affiliation Given 14pp 20664 131 24X Fiche 50-272, B3/09/27, B310060557

B310070097 Forwards safety evaluation of design of RCS vents Design conforms w/requirements of NUREG-0/37, Item II B 1, GDC 1, 2, 4, 14, 30 & 31 & 10CFR50 44(c)(3)(iii) w/exception of positive valve position indication VARGA, S A Operating Reactors Branch 1 B3/09/27 UDERITZ, R A Public Service Electric & Gas Co of New Jersey App 20673 349 24X Fiche 50-272, B3/09/27, B310070097

--B310070103 Safety evaluation of RCS vent design Design complies w/ NUREG-0737, Item II B 1, GDC 1, 2, 4, 14, 30 & 31 & 10CFR50 44 * NRC - No Detailed Affiliation Given B3/05/17 6pp 20673 352 24X Fiche 50-272, B3/09/27, B310070097

--B306080112 "Selected Operating Reactor Issues Program II RCS Vents (NUREG-0737, Item II B 1)," final technical evaluation rept for Salem 1 & 2 HELD, J J Energy Incorporated FIN A-0250 TF-343/0809A B3/02/23 ALBERTHAL, G Division of Licensing 6pp 20673 358 24X Fiche 50-272, B3/09/27, B310070097

B310070166 Advises that automatic PORV isolation will not be provided & PORV & block valve control sys will not be modified, based on "Probabilistic Analysis & Operational Data in Response to NUREG-0737, Item II K 3 2 for Westinghouse NSSS Plants" LIDEN, E A Public Service Electric & Gas Co of New Jersey B3/09/27 VARGA, S A Operating Reactors Branch 1 2pp 20699 108 24X Fiche 50-272, B3/09/27, B310070166

B310070003 Forwards remittance for License Change Requests B3-07, B3-10 & B3-11 LIDEN, E A Public Service Electric & Gas Co of New Jersey B3/09/30 VARGA, S A Operating Reactors Branch 1 1p 20658 245 24X Fiche 50-272, B3/09/30, B310070003

B310170039 Forwards SER & technical evaluation rept re licensee responses to NUREG-0737, Items II K 3 1, "Automatic PORV Isolation" & II K 3 2, "Rept on PORVs" VARGA, S A Operating Reactors Branch 1 B3/10/05 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 3pp 20812 162 24X Fiche 50-272, B3/10/05, B310170039

B310210285 Forwards addl fee required for Class 1 amend re Rev 1 to License Change Request 79-01 Original fee paid for single Class III amend only LIDEN, E A Public Service Electric & Gas Co of New Jersey B3/10/13 VARGA, S A Operating Reactors Branch 1 1p 20855 265, 24X Fiche 50-272, B3/10/13, B310210285

G Inspection reports, IE Bulletins & correspondence

B308300340 IE Info Notice B3-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, B3/09/26, B308300340

B308300342 IE Info Notice B3-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, B3/09/26, B308300342

B308300345 IE Info Notice B3-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, B3/09/26, B308300345

B310140276 Forwards IE Insp Repts 50-272/B3-25 & 50-311/B3-26 on B30810-0906 No noncompliance noted STAROSTECKI, R Division of Project & Resident Programs B3/09/26 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp 20761 214 24X Fiche 50-272, B3/09/26, B310140276

--B310140279 IE Insp Repts 50-272/B3-25 & 50-311/B3-26 on B30810-0906 No noncompliance noted Major areas inspected conformance w/Tech Specs, log & record reviews, followups on previous insp items & review of licensee events LINVILLE, J C, SUMMERS, R J, JACOBS, R H Region 1, Office of Director B3/09/26 15pp 20761 216 24X Fiche 50-272, B3/09/26, B310140276

B308300349 IE Info Notice B3-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, B3/09/29, B308300349

B310040214 EN-B3-032A on B30505, notices of violation & proposed imposition of civil penalty in amount of \$850,000 issued to util based on violation of Tech Spec requirement & failure to adequately implement aspects of QA program KLINGLER, G, AXELRAD, J Director's Office, Office of Inspection and Enforcement B3/09/29 1p 20617 240 24X Fiche 50-272, B3/09/29, B310040214

B310110381 Discusses util B30706 & 0722 responses to B30505 notice of violation & proposed imposition of civil penalty identified during review of ATWS events on B30222 & 25 Order encl imposing civil penalty in amount of \$850,000 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B3/09/29 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp 20713 281 24X Fiche 50-272, B3/09/29, B310110381

DOCKETED ITEMS

--831010387 Order imposing civil monetary penalties in amount of \$850,000 re violation of Tech Spec 3.3.1.1 requiring two reactor trip breakers to be operable when reactor operating in Modes 1 & 2
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/09/29 Public Service Electric & Gas Co. of New Jersey 14pp 20713 283 24X Fiche 50-272, 83/09/29, 831010387

8310250512 Forwards IE Safeguards Insp Repts 50-272/83-28 & 50-311/83-28 on 830907-09 No noncompliance noted Major areas inspected security sys power supply, detection aids - vital areas & licensee implementing procedure evaluation
MARTIN, T T Division of Engineering & Technical Programs 83/10/04 UDERITZ, R A Public Service Electric & Gas Co. of New Jersey 2pp 20701 052 24X Fiche 50-272, 83/10/04, 8310250512

--8310250527 IE Safeguards Insp Repts 50-272/83-28 & 50-311/83-28 on 830907-09 No noncompliance noted Major areas inspected security sys power supply, detection aids - vital areas & licensee implementing procedure evaluation
SMITH, Q C, GDDY, A T Region 1, Office of Director 83/10/03 2pp 20701 054 24X Fiche 50-272, 83/10/04, 8310250512

8310180391 Ack receipt of 830829 & 0922 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-13 & 50-311/83-19
STAROSTECKI, R Division of Project & Resident Programs 83/10/05 UDERITZ, R A Public Service Electric & Gas Co. of New Jersey 1p 20803 313 24X Fiche 50-272, 83/10/05, 8310180391

--8310180398 Responds to NRC 830729 ltr re violations noted in IE Insp Repts 50-272/83-13 & 50-311/83-19 Corrective actions ECCO throttle valve positions corrected & verified & TRIS worksheet footnote revised re ECCO throttle valves
LIDEN, E A Public Service Electric & Gas Co. of New Jersey 83/09/22 STAROSTECKI, R Division of Project & Resident Programs 3pp 20803 314 24X Fiche 50-272, 83/10/05, 8310180391

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-64, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc 117pp 21043 075 24X Fiche: 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

R Periodic operating reports & related correspondence

8310030346 "NPDES Discharge Monitoring Rept for Aug 1983 " W/830906 ltr
MILLER, L K Public Service Electric & Gas Co. of New Jersey 83/09/23 21pp 20590 164 24X Fiche 50-272, 83/09/23, 8310030346

8310200174 Monthly operating rept for Sept 1983 W/831010 ltr
MILLER, L K, ZUPKO, J M Public Service Electric & Gas Co. of New Jersey 83/10/10 Director's Office, Office of Inspection and Enforcement 16pp 20835 339 24X Fiche 50-272, 83/10/10, 8310200174

S Reportable occurrences, LERs & related correspondence

8310050159 Forwards "Plan for Improvement of Nuclear Dept Operations," in response to Basic Energy Technology Assoc. Inc rept & cross ref document, "Rept on Review of Corrective Action Program re Reactor Trip Breaker Failures "
UDERITZ, R A Public Service Electric & Gas Co. of New Jersey 83/08/26 VARGA, B A Operating Reactors Branch 1 2pp 20632 170 24X Fiche 50-272, 83/08/26, 8310050159

--8310050174 "Response to Basic Energy Technology Assoc. Inc Rept on Review of Corrective Action Program re Reactor Trip Breaker Failures at Salem Generating Station, Unit 1 " Cross ref encl
Public Service Electric & Gas Co. of New Jersey 83/08/26 23pp 20632 241 24X Fiche 50-272, 83/08/26, 8310050159

8310040213 PNS-1-83-019 on 830923, licensee contract security organization suspended two security guards Guard admitted to bringing illegal substance on site Other guard did not rpt incident Both guards terminated 830926
MADDEN, W, GDDY, A Region 1, Office of Director 83/09/28 1p 20614 273 24X Fiche 50-272, 83/09/28, 8310040213

8310110179 Notification of Significant Licensee Meeting 83-87 on 831011 at site to discuss ATWS event corrective action program
KISTER, H B Region 1, Office of Director 83/09/29 Region 1, Office of Director 1pp 20687 353 24X Fiche 50-272, 83/09/29, 8310110179

831010381 Discusses util 830706 & 0722 responses to 830505 notice of violation & proposed imposition of civil penalty identified during review of ATWS events on 830222 & 25 Order encl imposing civil penalty in amount of \$850,000
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/09/29 UDERITZ, R A Public Service Electric & Gas Co. of New Jersey 2pp 20713 281 24X Fiche 50-272, 83/09/29, 831010381

--831010387 Order imposing civil monetary penalties in amount of \$850,000 re violation of Tech Spec 3.3.1.1 requiring two reactor trip breakers to be operable when reactor operating in Modes 1 & 2
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/09/29 Public Service Electric & Gas Co. of New Jersey 14pp 20713 283 24X Fiche 50-272, 83/09/29, 831010387

8310250325 LER 83-041/03L-0 on 830915, discovered containment air particulate detector filter failure alarm illuminated Caused by inadequate supply of filter paper New filter paper installed W/831012 ltr
FRAMMER, J ZUPKO, J M Public Service Electric & Gas Co. of New Jersey 83/10/12 MURLEY, T E Region 1, Office of Director 4pp 20897 345 24X Fiche 50-272, 83/10/12, 8310250325

8310250390 LER 83-040/03L-0 on 830916, reactor trip breaker 1 post maint surveillance not completed within 1 h interval Caused by addl testing incorporated into surveillance License change request will be submitted to increase interval W/831012 ltr
FRAMMER, J ZUPKO, J M Public Service Electric & Gas Co. of New Jersey 83/10/12 MURLEY, T E Region 1, Office of Director 4pp 20898 147 24X Fiche 50-272, 83/10/12, 8310250390

8310250230 LER 83-042/04L-0 on 830914, routine release of radioactive liquid from chemical & vol control monitoring tank 11 performed w/o verification of operability of release line effluent monitor Procedure revised W/831014 ltr
FRAMMER, J ZUPKO, J M Public Service Electric & Gas Co. of New Jersey 83/10/14 MURLEY, T E Region 1, Office of Director 4pp 20899 139 24X Fiche 50-272, 83/10/14, 8310250230

8310280024 LER 83-043/03L-0 on 830920, during routine operation, delta temp/delta pressure station auxiliary performer chart recorder indication failed Caused by P-290 computer electronic lockup Computer rebooted W/831014 ltr
FRAMMER, J ZUPKO, J M Public Service Electric & Gas Co. of New Jersey 83/10/14 MURLEY, T E Region 1, Office of Director 4pp 20933 204 24X Fiche 50-272, 83/10/14, 8310280024

V Operator Examinations

8310250257 Responds to J Buzy telcon re licensed operator requalification Training Procedure TP-305 Exam will be completely changed at least every 6 wks
LIDEN, E A Public Service Electric & Gas Co. of New Jersey 83/10/17 VARGA, B A Operating Reactors Branch 1 2pp 20948 359 24X Fiche 50-272, 83/10/17, 8310250257

DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

E NRC Safety Evaluation Report (SER), supp's & correspondence

8310120404 Provides clarification for certain designations in FSAR Figures & tables re steam generator blowdown isolation per SSER 18 Classification & installation of relays will be completed prior to full power operation
SCHUYLER, J D Pacific Gas & Electric Co 83/10/06 EISENHUT, B O Division of Licensing 2pp 20699 022 24X Fiche 50-275, 83/10/06, 8310120404

8310170917 Forwards clarifications &/or addl info re 830830 & 0906 & 09 responses to SSER 18 open items Items 3, 4, 7, 10 & 17 resolved, Encl info resolves Items 1, 16, 17, 18, 23, 24 & 27
SCHUYLER, J D Pacific Gas & Electric Co 83/10/06 EISENHUT, B O Division of Licensing 16pp 20784 218 24X Fiche 50-275, 83/10/06, 8310170917

DOCKETED ITEMS

79

8308300766 Board Notification 87-154 forwards Rev 1 to "Diablo Canyon Unit 1 IDVP Verification of Corrective Action Turbine Bldg," Rev 1 to "Information Items re Large Bore Piping" & transcript of 830728 meeting w/utlir
EISENHUT, D G Division of Licensing 83/10/07 PALLADINO, N J, GILINSKY, V, ROBERTS, T M Commissioners 3pp 20782 188 24X Fiche 50-275, 83/10/07, 8308300766

--8310170318 Transcript of 830728 technical conference w/utlir & PNI in Bethesda, MD re SSER open items Pp 1-104
* Commissioners 83/07/28 416pp 20782 191 24X Fiche 50-275, 83/10/07, 8308300766

8310170514 Forwards revised Attachment 6 re power operated valves to Encl 2 of 830909 response to SSER 18 potential unresolved items Mods to valves FCV-3/ & 3B determined unnecessary
Description of mods encl
SCHUYLER, J D Pacific Gas & Electric Co 83/10/07 EISENHUT, D G Division of Licensing 3pp 20784 148 24X Fiche 50-275, 83/10/07, 8310170514

8310170657 Forwards clarifications &/or addl info on SSER 18, Open Item 30 re rupture restraints Crushable bumpers/rupture restraints inside containment designed per Design Criteria
Memo DCH-644
SCHUYLER, J D Pacific Gas & Electric Co 83/10/11 EISENHUT, D G Division of Licensing 2pp 20779 280 24X Fiche 50-275, 83/10/11, 8310170657

8310180463 Forwards clarification &/or addl info on SSER 18 Open Item 29 re jet impingement Original design basis validated
No further evaluation necessary
SCHUYLER, J D Pacific Gas & Electric Co 83/10/12 EISENHUT, D G Division of Licensing 9pp 20802 054 24X Fiche 50-275, 83/10/12, 8310180463

8310190137 Forwards clarifications &/or addl info re SSER 18, Open Item 2, "Response Spectra Cutoff Frequency"
SCHUYLER, J D Pacific Gas & Electric Co 83/10/12 EISENHUT, D G Division of Licensing 15pp 20820 261 24X Fiche 50-275, 83/10/12, 8310190137

8310190063 Informs that util will provide addl info re SSER 18, Open Items 1, 2 & 17 (as listed in SECY-83-366, Encl 5), per NRC review of listed previous responses
SCHUYLER, J D Pacific Gas & Electric Co 83/10/14 EISENHUT, D G Division of Licensing 1p 20822 334 24X Fiche 50-275, 83/10/14, 8310190063

8310200131 Forwards Rev 1 to Figures 1 & 2 of 831006 response to SSER 18 on Open Item 1 (SECY-83-366) re raw response spectra & raw-smoothed response spectra
SCHUYLER, J D Pacific Gas & Electric Co 83/10/14 EISENHUT, D G Division of Licensing 3pp 20834 104 24X Fiche 50-275, 83/10/14, 8310200131

F Security, medical, emergency & fire protection plans

8310040221 Forwards IE Insp Repts 50-275/83-25 & 50-323/83-18 on 830718-22 & 0818 No noncompliance noted
NORDERHAUG, L R Region 5, Office of Director 83/09/20
SCHUYLER, J D Pacific Gas & Electric Co 2pp 20617 250 24X Fiche 50-275, 83/09/20, 8310040221

--8310040226 IE Insp Repts 50-275/83-25 & 50-323/83-18 on 830718-22 & 0818 No noncompliance noted Major areas inspected emergency preparedness program, including emergency detection & classification & protective action decisionmaking
SCOWN, K, SCHUSTER, M D Region 5, Office of Director 83/09/19 13pp 20617 252 24X Fiche 50-275, 83/09/20, 8310040221

8310040141 Forwards addl info re emergency lighting capability & evaluation & reactor coolant pump lube oil sys info should clarify 830715 rept justifying differences between fire protection features & 10CFR50, App R requirements
SCHUYLER, J D Pacific Gas & Electric Co 83/09/23 EISENHUT, D G Division of Licensing 24pp 20617 005 24X Fiche 50-275, 83/09/23, 8310040141

8310070236 Forwards addl info on App R review re fire doors & panels, clarifying & supplementing 830715 & 0923 submittals, Approx 40 of 120 door & frame assemblies modified for security reasons
SCHUYLER, J D Pacific Gas & Electric Co 83/10/03 EISENHUT, D G Division of Licensing 9pp 20658 240 24X Fiche 50-275, 83/10/03, 8310070236

8310120402 Forwards list of proposed mods to be completed prior to initial criticality which will provide level of compliance equivalent to 10CFR50, App R fire door requirements will be determined after UL insp scheduled for wk of 831010
SCHUYLER, J D Pacific Gas & Electric Co 83/10/06 EISENHUT, D G Division of Licensing 9pp 20699 012 24X Fiche 50-275, 83/10/06, 8310120402

8310170539 Forwards Amend 6 to License DPR-76 & safety evaluation
Safety evaluation withheld (ref 10CFR73 21) Amend requires implementation of approved physical security plan
KNIGHTON, G W Licensing Branch 3 83/10/11 FURBUSH, M H Pacific Gas & Electric Co 4pp 20784 203 24X Fiche 50-275, 83/10/11, 8310170539

--8310170542 Amend 6 to License DPR-76, changing vital area access controls
EISENHUT, D G Division of Licensing 83/10/11 2pp 20784 207 24X Fiche 50-275, 83/10/11, 8310170539

8310170565 Provides addl info on App R review re schedule for fire door mods Door manufacturers will inspect unlabeled doors & frames constructed to UL specs on 831010-13 Doors/Frames not within specs will be replaced
SCHUYLER, J D Pacific Gas & Electric Co 83/10/11 EISENHUT, D G Division of Licensing 2pp 20780 343 24X Fiche 50-275, 83/10/11, 8310170565

8310180620 Advises that 830803 proposed changes to Rev 11 to physical security plan & Rev 2 to safeguards contingency plan acceptable per 10CFR50 54(p) Encls to ltr withheld (ref 10CFR73 21)
KNIGHTON, G W Licensing Branch 3 83/10/12 SCHUYLER, J D Pacific Gas & Electric Co 3pp 20817 336 24X Fiche 50-275, 83/10/12, 8310180620

8310210154 Requests publication of FR notice of consideration of issuance of amend to License DPR-76 & proposed NBHC determination & opportunity for hearing re physical security plan NBHC determination available in Central Files
KNIGHTON, G W Licensing Branch 3 83/10/13 MILLER, J R Operating Reactors Branch 3 2pp 20883 359 24X Fiche 50-275, 83/10/13, 8310210154

8310200144 Submits addl info on App R review re schedule for fire door mods Installation of directional closed head sprinkler protection on both sides of panels & transoms suggested
SCHUYLER, J D Pacific Gas & Electric Co 83/10/14 EISENHUT, D G Division of Licensing 1p 20836 294 24X Fiche 50-275, 83/10/14, 8310200144

8310280061 Provides addl info to 831014 submittal re App R review of panels, transoms & door mods Actions for components which cannot meet UL approved configurations listed
SCHUYLER, J D Pacific Gas & Electric Co 83/10/21 EISENHUT, D G Division of Licensing 2pp 20933 338 24X Fiche 50-275, 83/10/21, 8310280061

8310270566 Releases public version of revised corporate emergency response plan & revised emergency response plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20945 007 24X Fiche 50-275, 83/10/25, 8310270566

--8310270572 Forwards public version of Rev 2 to corporate emergency response plan & revised emergency response plan implementing procedures
SCHUYLER, J D Pacific Gas & Electric Co 83/10/10 MARTIN, J B Region 5, Office of Director 3pp 20945 008 24X Fiche 50-275, 83/10/25, 8310270566

--8310270575 Public version of Rev 2 to corporate emergency response plan
SCHUYLER, J D Pacific Gas & Electric Co 83/09/12 85pp 20945 011 24X Fiche 50-275, 83/10/25, 8310270566

--8310270580 Public version of revised corporate emergency response plan implementing procedures, including Procedures 3 1 re governmental relations, 3 2 re corporate communications dept & 3 3 re law
SCHUYLER, J D Pacific Gas & Electric Co 83/10/04 300pp 20945 096 24X Fiche 50-275, 83/10/25, 8310270566

8310270582 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20946 099 24X Fiche 50-275, 83/10/25, 8310270582

DOCKETED ITEMS

-B310270586 Forwards public version of revised emergency plan implementing procedures, including Procedures 2 1 re plant maint, 3 4 re insurance & 3 6 re security
SCHUYLER, J D Pacific Gas & Electric Co 83/09/12 NARFIN, J B
Region 5, Office of Director 3pp 20946 100 24X
Fiche 50-275, 83/10/25, 8310270582

-B310270588 Public version of revised emergency plan implementing procedures, including Procedures 2 1 re plant maint, 3 4 re insurance & 3 6 re security
SCHUYLER, J D Pacific Gas & Electric Co 83/08/14 150pp
20946 103 24X Fiche 50-275, 83/10/25, 8310270582

Adjudicatory correspondence

010260277 Contentions on design GA re verification of samples for IDVP
STRUMWASSER, M California, State of REYNOLDS, J Joint
Intervenors-Diablo Canyon REYNOLDS, J Center for Law in the Public
Interest 83/09/08 Atomic Safety and Licensing Appeal Panel
103pp 20911 039 24X Fiche 50-275, 83/09/08, 8310260277

010030371 Confirms 830920 telcon re Governor Deukmejian 830902 request
for documents List of requested documents will be sent by
831004
MCOURREN, H J Hearing Branch 3 83/09/26 DURBIN, S California,
State of 1p 20630 334 24X Fiche 50-275, 83/09/26, 8310030371

010050454 Response opposing Joint Intervenors 830926 request for
hearing on lifting of license suspension No legal basis
presented to support hearing Certificate of Svc encl
CHANDLER, L J Hearing Branch 2 83/09/26 Commissioners 15pp
20630 040 24X Fiche 50-275, 83/09/26, 8310050454

010040251 First supplemental responses to interrogatories
Certification of counsel & Certificate of Svc encl Related
correspondence
LUBBOCK, D G Pacific Gas & Electric Co 83/09/28 California,
State of 7pp 20613 042 24X Fiche 50-275, 83/09/28, 8310040251

010040288 First supplemental answers to third set of interrogatories
Prof qualifications & Certificate of Svc encl Related
correspondence
STRUMWASSER, M California, State of 83/09/28 Pacific Gas &
Electric Co 26pp 20614 167 24X Fiche 50-275, 83/09/28,
8310040288

010050396 First supplemental response to third set of interrogatories
Certificate of Svc encl Related correspondence
LUBBOCK, D G Pacific Gas & Electric Co 83/09/28 California,
State of 66pp 20634 186 24X Fiche 50-275, 83/09/28, 8310050396

010030384 Motion for sanctions against Governor Deukmejian & Joint
Intervenors for failure to suppl interrogatories seasonably
Intervenors have engaged in concrete course of conduct to
delay proceedings Certificate of Svc encl
CRANE, P A Pacific Gas & Electric Co 83/09/29 Atomic Safety
and Licensing Appeal Panel 18pp 20592 154 24X
Fiche 50-275, 83/09/29, 8310030384

010040209 Motion for mod of schedule established in ASLB 830907 order
re design GA hearing Delay in completion of IDVP renders
schedule impossible to meet
KAUFMAN, P H California, State of 83/09/29 Atomic Safety and
Licensing Appeal Panel 17pp 20614 335 24X Fiche 50-275,
83/09/29, 8310040209

-B310040212 Addl contentions on design GA
KAUFMAN, P H California, State of REYNOLDS, J Joint
Intervenors-Diablo Canyon REYNOLDS, J Center for Law in the
Public Interest 83/09/29 Atomic Safety and Licensing Appeal
Panel 4pp 20614 352 24X Fiche 50-275, 83/09/29, 8310040209

-B310040219 Application for expedited ruling on motion for mod of
hearing schedule Motion should be ruled on quickly since
testimony due 831008 Certificate of Svc encl
KAUFMAN, P H California, State of 83/09/29 Atomic Safety and
Licensing Appeal Panel 6pp 20614 356 24X
Fiche 50-275, 83/09/29, 8310040209

010040339 Supplemental response to second set of interrogatories
Certification of counsel & Certificate of Svc encl Related
correspondence
HAVIAN, E R Joint Intervenors-Diablo Canyon HAVIAN, E R Center
for Law in the Public Interest 83/09/29 Pacific Gas & Electric
Co 7pp 20624 019 24X Fiche 50-275, 83/09/29, 8310040339

010040302 Order extending time until 831007 for Commission to act to
review ALAD-72B
CHILK, B J Office of the Secretary of the Commission 83/09/30
Commissioners 1p 20614 168 24X Fiche 50-275, 83/09/30,
8310040302

8310040525 Forwards author notice of appearance Certificate of Svc
encl
LUBBOCK, D G Pacific Gas & Electric Co 83/09/30 Docketing &
Services Branch 4pp 20624 226 24X Fiche 50-275, 83/09/30,
8310040525

8310070209 Staff requirements memo re 830927 discussion of proceeding
schedule Commission will hold 831028 public meeting in
Washington, DC re issues related to fuel loading
CHILK, B J Office of the Secretary of the Commission 83/09/30
Office of the Secretary of the Commission 1p 20676 362 24X
Fiche 50-275, 83/09/30, 8310070209

8310050421 Fourth supplemental response to first set of
interrogatories Certificate of Svc encl
REYNOLDS, J Joint Intervenors-Diablo Canyon REYNOLDS, J Center
for Law in the Public Interest 83/10/03 Pacific Gas & Electric
Co 9pp 20630 334 24X Fiche 50-275, 83/10/03, 8310050421

8310110053 Answer opposing util motion for sanctions for alleged
failures to suppl interrogatory answer seasonably Motion
wholly unfounded & should be denied Declaration of counsel
& Certificate of Svc encl
STRUMWASSER, M California, State of 83/10/04 Atomic Safety and
Licensing Appeal Panel 21pp 20668 244 24X Fiche 50-275,
83/10/04, 8310110053

8310110058 Forwards Page 41 of Nuclear Svcs Corp audit of Pullman
Power Products filed w/Joint Intervenors 830909 suppl to
motion to reopen record on const GA issue
REYNOLDS, J Center for Law in the Public Interest REYNOLDS, J
Joint Intervenors-Diablo Canyon 83/10/04 Atomic Safety and
Licensing Appeal Panel 2pp 20668 239 24X Fiche 50-275, 83/10/04,
8310110058

8310110073 Response opposing Governor Deukmejian & Joint Intervenors
830929 addl contentions on GA contentions lack specificity
&/or fail to meet criteria for late-filed contentions
Certificate of Svc encl
LOCKER, R F Pacific Gas & Electric Co 83/10/04 Atomic Safety
and Licensing Appeal Panel 6pp 20667 299 24X
Fiche 50-275, 83/10/04, 8310110073

8310110120 Response opposing Governor Deukmejian 830907 motion to
modify schedule for conduct of hearings Motion is only
another unsubstantiated ploy for delay Certificate of Svc
encl
NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke,
Berry & French 83/10/04 Atomic Safety and Licensing Appeal
Panel 12pp 20666 212 24X Fiche 50-275, 83/10/04, 8310110120

8310110127 Response opposing licensee motions for sanctions against
Governor Deukmejian & Joint Intervenors Intervenors
supplemented interrogatory answers in timely manner
Certificate of Svc encl
REYNOLDS, J Joint Intervenors-Diablo Canyon REYNOLDS, J Center
for Law in the Public Interest 83/10/04 Atomic Safety and
Licensing Appeal Panel 8pp 20666 204 24X Fiche 50-275, 83/10/04,
8310110127

8310110317 Response supporting Governor Deukmejian 830929 motion for
mod of hearing schedule Deposition schedule not completed &
time for filing contentions expired prior to issuance of
IDVP repts Certificate of Svc encl
REYNOLDS, J Joint Intervenors-Diablo Canyon REYNOLDS, J Center
for Law in the Public Interest 83/10/04 Atomic Safety and
Licensing Appeal Panel 6pp 20665 358 24X Fiche 50-275, 83/10/04,
8310110317

8310120418 Response of IDVP to Interrogatory 57 in third set of
interrogatories Certificate of Svc encl Related
correspondence
RASKIN, D B Lowenstein, Newman, Reis, Axelrad & Toll 83/10/05
STRUMWASSER, M California, State of 9pp 20699 044 24X
Fiche 50-275, 83/10/05, 8310120418

8310130017 Response opposing Governor Deukmejian 830929 motion for 2-wk
extension of discovery schedule set in ASI AB 830907 order
Governor began discovery process only 3 wks before hearing
Extension would delay hearing
CHANDLER, L J Hearing Branch 2 83/10/05 Atomic Safety and
Licensing Appeal Panel 7pp 20725 191 24X Fiche 50-275, 83/10/05,
8310130017

--8310130019 Response supporting licensee 830929 motion for sanctions
upon Governor Deukmejian/Joint Intervenors Depositions of
Apostolakis, Kempthorne & Hubbard should be held during wk of
831010-14, Certificate of Svc encl
CHANDLER, L J Hearing Branch 2 83/10/05 Atomic Safety and
Licensing Appeal Panel 6pp 20725 198 24X
Fiche 50-275, 83/10/05, 8310130017

DOCKETED ITEMS

81

- 8310130163 Response to 830902 document request consisting of computer printout listing documents in docket since 811101 Documents to be copied should be identified
MCGURREN, H J Hearing Branch 1 83/10/05 DURBIN, S L California, State of App 20724 280 24X Fiche 50-275, 83/10/05, 8310130163
- 831010298 Application for subpoena for G Apostolakis for 831011 deposition & production of documents
NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke, Berry & French 83/10/06 Atomic Safety and Licensing Appeal Panel App 20666 100 24X Fiche 50-275, 83/10/06, 831010298
- 831010301 Notice of G Apostolakis deposition on 831011 in San Francisco, CA Certificate of Svc encl
NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke, Berry & French 83/10/06 App 20666 104 24X Fiche 50-275, 83/10/06, 831010298
- 8310120376 Second supplemental answers to first set of interrogatories Certification of counsel & prof qualifications encl
DURBIN, S L California, State of 83/10/07 Pacific Gas & Electric Co 28pp 20699 133 24X Fiche 50-275, 83/10/07, 8310120376
- 8310120381 First supplemental answers to second set of interrogatories Certification of counsel encl
DURBIN, S L California, State of 83/10/07 Pacific Gas & Electric Co 17pp 20699 160 24X Fiche 50-275, 83/10/07, 8310120376
- 8310120386 First supplemental answers to fourth set of interrogatories Certification of counsel & (certificate of Svc encl)
DURBIN, S L California, State of 83/10/07 Pacific Gas & Electric Co 8pp 20699 177 24X Fiche 50-275, 83/10/07, 8310120376
- 8310120385 Order confirming 831005 oral rulings during telcon re reopened proceeding on design QA Governor Deukmejian 830927 motion for mod of schedule granted in part
SHOENMAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/07 8pp 20699 185 24X Fiche 50-275, 83/10/07, 8310120385
- 8310120412 Order extending time until 831017 for Commission to act to review ALAB-72R
CHILK, S J Office of the Secretary of the Commission 83/10/07 Commissioners 1p 20698 052 24X Fiche 50-275, 83/10/07, 8310120412
- 8310130243 Fifth supplemental response to first set of interrogatories Portions of RB Hubbard & FJ Samaniego 831021 direct testimony & Certificate of Svc encl
REYNOLDS, J Joint Intervenor-Diablo Canyon REYNOLDS, J Center for Law in the Public Interest 83/10/07 Pacific Gas & Electric Co 19pp 20723 253 24X Fiche 50-275, 83/10/07, 8310130243
- 8310180160 Motion for leave to file reply to NRC & util responses to Joint Intervenor 830909 suppl to motion to reopen record on const QA Responses raised defenses & relied on documents not previously part of record Certificate of Svc encl
REYNOLDS, J Joint Intervenor-Diablo Canyon REYNOLDS, J Center for Law in the Public Interest 83/10/13 Atomic Safety and Licensing Appeal Panel App 20809 147 24X Fiche 50-275, 83/10/13, 8310180160
- 8310180248 Response to Governor Deukmejian, NRC & util replies to Joint Intervenor 830909 suppl to motion to reopen record on const QA NSC audit rept provides irrefutable evidence of breakdown in Pullman QA program Certificate of Svc encl
REYNOLDS, J Joint Intervenor-Diablo Canyon REYNOLDS, J Center for Law in the Public Interest 83/10/13 Atomic Safety and Licensing Appeal Panel 12pp 20802 320 24X Fiche 50-275, 83/10/13, 8310180248
- 8310190219 Motion for order of enforcement of ASLAB 831007 order directing Governor Deukmejian & Joint Intervenor to supply interrogatory responses & documents requested Parties failed to provide required documents Certificate of Svc encl
CRANE, P A Pacific Gas & Electric Co 83/10/13 Atomic Safety and Licensing Appeal Panel App 20810 057 24X Fiche 50-275, 83/10/13, 8310190219
- 8310180328 Second supplemental response to third set of interrogatories Certificate of Svc encl Related correspondence
LUBBOCK, D O Pacific Gas & Electric Co 83/10/14 DEUKMEJIAN, California, State of 14pp 20806 161 24X Fiche 50-275, 83/10/14, 8310180328
- 8310210228 Forwards P/J Kempthorne & FJ Samaniego testimony REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J R Joint Intervenor-Diablo Canyon 83/10/15 MOORE, T S, JOHNSON, W R, BUCK, J H Atomic Safety and Licensing Appeal Panel 1p 20853 047 24X Fiche 50-275, 83/10/15, 8310210228
- 8310210242 Exhibit list Certificate of Svc encl
REYNOLDS, J Joint Intervenor-Diablo Canyon REYNOLDS, J Center for Law in the Public Interest 83/10/15 6pp 20852 065 24X Fiche 50-275, 83/10/15, 8310210228
- 8310200178 Testimony of RB Hubbard re design QA Verification program has not yet demonstrated plant design complies w/all applicable NRC regulatory requirements & all util licensing Criteria Related correspondence
HUBBARD, R B California, State of HUBBARD, R B HNB Technical Associates 83/10/16 79pp 20835 129 24X Fiche 50-275, 83/10/16, 8310200178
- 8310200195 List of exhibits identified per ASLAB 831007 order Certificate of Svc encl
STRUHASSER, M California, State of 83/10/16 7pp 20835 289 24X Fiche 50-275, 83/10/16, 8310200178
- 8310190054 Forwards documents NRC delivered to Commissioner Gilinsky during 831017 briefing on plant design reverification
GILINSKY, V Commissioners 83/10/17 Office of the Executive Legal Director 20pp 20823 259 24X Fiche 50-275, 83/10/17, 8310190054
- 8310190261 Order extending time until 831028 for Commission to act to review ALAB-72H
CHILK, S J Office of the Secretary of the Commission 83/10/17 Commissioners 1p 20818 082 24X Fiche 50-275, 83/10/17, 8310190261
- 8310270338 Forwards addl copies of direct testimony & accompanying matls Sky Courier & Eastern Airlines lost original transmittals Inconvenience regretted
STRUHASSER, M California, State of 83/10/17 MOORE, T S Atomic Safety and Licensing Appeal Panel 1p 20923 302 24X Fiche 50-275, 83/10/17, 8310270338
- 8310270348 Answer opposing util 831013 motion for order of enforcement Util violated order several times Grounds for requested relief nonexistent
STRUHASSER, M California, State of 83/10/17 Atomic Safety and Licensing Appeal Panel 7pp 20923 303 24X Fiche 50-275, 83/10/17, 8310270338
- 8310270377 Affidavit of RB Hubbard re safety-related aspects of QA programs Prof qualifications & Certificate of Svc encl
HUBBARD, R B California, State of 83/10/21 17pp 20923 310 24X Fiche 50-275, 83/10/21, 8310270338
- 8310250283 Forwards US Court of Appeals, DC Circuit, 831007 amended opinion affirming NRC denial of Atty General Bellotti's petition to intervene
CHANDLER, L J Hearing Branch 2 83/10/18 CHILK, S J Office of the Secretary of the Commission 23pp 20894 232 24X Fiche 50-275, 83/10/18, 8310250283
- 8310240158 Motion for revocation of License DPR-76, or in alternative, for continuation of suspension Continuing nature of matl false statements & unresolved questions re adequacy of const unacceptable Certificate of Svc encl
REYNOLDS, J Joint Intervenor-Diablo Canyon REYNOLDS, J Center for Law in the Public Interest 83/10/20 Commissioners 68pp 20881 224 24X Fiche 50-275, 83/10/20, 8310240158
- 8310240174 Objection to Joint Intervenor proposed Exhibits 128 & 129 & State of CA Governor Exhibit 11 re design QA Exhibits irrelevant & immaterial to proceeding Certificate of Svc encl
CRANE, P A Pacific Gas & Electric Co 83/10/20 Atomic Safety and Licensing Appeal Panel App 20810 030 24X Fiche 50-275, 83/10/20, 8310240174
- 8310230043 Objections to util & NRC exhibits & testimony, per ASLAB 831007 order Certificate of Svc encl
HAVIAN, E Joint Intervenor-Diablo Canyon HAVIAN, E Center for Law in the Public Interest 83/10/20 Atomic Safety and Licensing Appeal Panel App 20894 081 24X Fiche 50-275, 83/10/20, 8310230043
- 8310250467 Comments on Joint Intervenor & Governor Deukmejian testimony & proposed exhibits, per ASLAB 831007 order Governor Exhibits 27-31 not provided for review Exhibits 129 & 132 acceptable
CHANDLER, L J Hearing Branch 2 83/10/21 MOORE, T S, BUCK, J H, JOHNSON, W R Atomic Safety and Licensing Board Panel 2pp 20897 102 24X Fiche 50-275, 83/10/21, 8310250467

DOCKETED ITEMS

- 8310260234 Submits suppl to 830901 comments on IDVP final rept & SSER 1B re reissuance of suspended license for fuel loading & low power operation License reissuance opposed Certificate of Svc encl
REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J R
Joint Intervenor-Diablo Canyon 83/10/24 PALLADINO, N J
GILINSKY, V, ROBERTS, T Commissioners 14pp 20912 192 24X
Fiche 50-275, 83/10/24, 8310260276
- 8310260270 Order denying Joint Intervenor 830510 & Governor Deukmejian 830517 motions to reopen record re adequacy of applicant const QA program Motions fail to meet stds
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/24
Joint Intervenor-Diablo Canyon 2pp 20911 304 24X
Fiche 50-275, 83/10/24, 8310260270
- 8310310141 Notice of withdrawal of Contentions 3c, d, e, g, j, k & n re design QA failures Contentions found to be within licensing criteria or were resolved by addl technical info Certificate of Svc encl
DURBIN, B L California, State of REYNOLDS, J R Joint Intervenor-Diablo Canyon REYNOLDS, J R Center for Law in the Public Interest 83/10/24 16pp 20999 019 24X
Fiche 50-275, 83/10/24, 8310310141
- 8310270263 Answer opposing Joint Intervenor 831020 motion for revocation of OK or for continuation of suspension Applicant has not misrepresented or failed to disclose facts Certificate of Svc encl
CRANE, P A Pacific Gas & Electric Co 83/10/25 Commissioners 13pp 20922 028 24X Fiche 50-275, 83/10/25, 8310270263
- 8310270358 Forwards Joint Intervenor & Governor Deukmejian revised contentions on design QA, replacing Exhibit 1 transmitted w/831024 ltr
REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J R Joint Intervenor-Diablo Canyon 83/10/25 PALLADINO, N J, GILINSKY, V, ROBERTS, T Commissioners 1p 20923 294 24X
Fiche 50-275, 83/10/25, 8310270358
- 8310270361 Issues to be contested by Governor Deukmejian & Joint Intervenor
Joint Intervenor-Diablo Canyon 83/10/24 1pp 20927 295 24X Fiche 50-275, 83/10/25, 8310270358
- 8310280097 Reply to util objections to Joint Intervenor proposed exhibits Objections should be overruled Certificate of Svc encl
HAVIAN, E Joint Intervenor-Diablo Canyon HAVIAN, E Center for Law in the Public Interest 83/10/25 Atomic Safety and Licensing Appeal Panel 8pp 20935 066 24X Fiche 50-275, 83/10/25, 8310280097
- 8310310181 Requests DC Treppa encl 831021 ltr be placed in PDR & copies served on parties to proceeding
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/27 Docketing & Services Branch 1p 20958 361 24X
Fiche 50-275, 83/10/27, 8310310181
- 8310310184 Expresses concern re reissuing low power test license for facility License should be revoked & facility ordered to shut down
TREPPA, D C Affiliation Unknown 83/10/21 ROSENTHAL, A S NRC - No Detailed Affiliation Given 1p 20958 362 24X
Fiche 50-275, 83/10/27, 8310310181
- 1 General correspondence
- 8310180270 Clarifies position of interjurisdictional planning committee for agencies surrounding facility, emphasizing importance of FEMA coordination of Federal agency responses to nuclear plant accidents
COLEMAN, R J San Clemente, CA 83/10/10 NRC - No Detailed Affiliation Given 2pp 20807 050 24X Fiche 50-275, 83/10/10, 8310180270
- 8310200175 Responds to 820712 & 830820 ltrs re safety & redundancy of valve failure modes (E Insp Repts 50-275/82-26, 50-323/82-13 & 50-275/82-42 encl) Further investigation revealed tracking & documentation of repts out of date
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 83/10/17 COOPER, J H Affiliation Unknown 2pp 20833 316 24X Fiche 50-275, 83/10/17, 8310200175
- Operating license stage documents & correspondence
- 831010034 Further response to FOIA request for records re NUREG 0862 investigative rept & investigations concerning facilities
Forwards App A documents Commissioner Bradford 811217 memo withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/06/15 REYNOLDS, J Center for Law in the Public Interest 4pp 20713 001 24X
Fiche 50-275, 83/06/15, 831010034
- 8208010014 Requests issuance of final statement clearing RL Cloud Associates from allegations of wrongdoing in preparation of "Preliminary Rept. Seismic Verification Program," per NRC investigation results in NUREG-0862, Issue 1
CLOUD, R L Robert L Cloud Associates, Inc 82/08/24 PALLADINO, N J Commissioners 3pp 20713 032 24X
Fiche 50-275, 83/06/15, 831010034
- 831010039 Forwards draft ltrs to Subcommittee on Energy & Environ & Subcommittee on Energy Conservation & Power transmitting NRC review of NUREG-0862 Comments requested by 820811
HAMMERER, C Office of Congressional Affairs 83/08/04 BICKWIT, L Office of the General Counsel CUMMINGS, J Office of Inspector & Auditor FITZGERALD, J Office of Investigation 4pp 20713 008 24X Fiche 50-275, 83/06/15, 831010034
- 831010046 Responds to 811217 ltr expressing concern re delays in licensing process Immediate issue concerns acceptability of util proposed auditors, RL Cloud Assoc investigation scheduled for completion on 821108 & 830201
HAMMERER, C Office of Congressional Affairs 83/01/10 ROUSSELOT, J H House of Rep 1p 20713 013 24X
Fiche 50-275, 83/06/15, 831010034
- 831010048 "Chronology of Events"
Affiliation Unknown 83/06/15 6pp 20713 015 24X
Fiche 50-275, 83/06/15, 831010034
- 831010057 Draft ltrs re adequacy of NRC investigation into development of RL Cloud Assoc Rept, per NUREG-0862, "Insp Rept of Preliminary Rept. Seismic Verification Program at Diablo Canyon Nuclear Power Plant"
PALLADINO, N Commissioners 83/06/15 UDALL, M K House of Rep, Interior & Insular Affairs GILLINGER, R, DINGELL, J House of Rep, Energy & Commerce 7pp 20713 024 24X
Fiche 50-275, 83/06/15, 831010034
- 831010095 Forwards RL Cloud 820824 request for final statement on conclusions of Cloud/util investigation to clear Cloud prof reputation Matter presented in NUREG-0862 & SECY-82/89 Commission guidance requested
DIRCKS, W J Office of the Executive Director for Operations 83/09/08 PALLADINO, N Commissioners 1p 20713 031 24X
Fiche 50-275, 83/06/15, 831010034
- 831010107 Forwards summary documenting record actions of peer review group
REHM, T A Office of the Executive Director for Operations, 82/02/18 PALLADINO, N, GILINSKY, V, BRADFORD, P Commissioners 1p 20713 036 24X Fiche 50-275, 83/06/15, 831010034
- 831010111 Forwards summary of Region V peer review group assistance w/ investigation of RL Cloud Assoc Related info encl
CORNELI, E K Office of the Executive Director for Operations CASE, E O Office of Nuclear Reactor Regulation, Director SNIEZKA, J H Director's Office, Office of Inspection and Enforcement 82/02/18 DIRCKS, W J Office of the Executive Director for Operations 4pp 20713 037 24X
Fiche 50-275, 83/06/15, 831010034
- 8310270255 FOIA request for Polk & Schierling 830218 memo to Knighton & Lear re reverification program to be placed in PDR
BUCKLES, R NUS Corp 83/06/30 Division of Rules and Records 1p 20943 066 24X Fiche 50-275, 83/06/30, 8310270255
- 8310270250 Responds to FOIA request for Polk & Schierling 830218 memo to Knighton & Lear re reverification program Memo placed in PDR
FELTON, J M Division of Rules and Records 83/07/15 BUCKLES, R NUS Corp 1p 20943 065 24X Fiche 50-275, 83/07/15, 8310270250
- 8310180609 FOIA request for complete set of BNL repts on seismic design of facilities
CALSOYAS, C D Affiliation Unknown 83/08/16 Region 5, Office of Director 4pp 20824 315 24X Fiche 50-275, 83/08/16, 8310180609
- 8310180610 Responds to FOIA request for complete set of BNL repts on seismic design of facilities Documents listed in app available in PDR
FELTON, J M Division of Rules and Records 83/09/01 CALSOYAS, C D Affiliation Unknown 2pp 20824 319 24X Fiche 50-275, 83/09/01, 8310180610
- 8310180613 Summary & evaluation rept of RL Cloud & Assoc rept, "Diablo Canyon Unit 1 IDVP Verification Program for PC&L Corrective Action"
Brookhaven National Laboratory 83/09/01 4pp 20824 311 24X Fiche 50-275, 83/09/01, 8310180610

DOCKETED ITEMS

83

--B310180615 Summary & evaluation rept of RF Reedy rept, "Development of Svc-Related Contractor List for Nonseismic Design Work Performed for Diablo Canyon Nuclear Power Plant, Unit 1 Prior to 7B0601, Phase 11"
* Brookhaven National Laboratory 83/09/01 3pp 20824 325
24X Fiche 50-275, 83/09/01, B310180610

--B310180617 Summary & evaluation rept of RL Cloud & Assoc rept, "Diablo Canyon Unit 1 IDVP - Verification of Design Analysis Hosgill Spectra"
* Brookhaven National Laboratory 83/09/01 3pp 20824 326
24X Fiche 50-275, 83/09/01, B310180610

--B310180619 Summary & evaluation rept of RL Cloud & Assoc rept "Diablo Canyon Unit 1 IDVP - Soils - Intake Structure"
* Brookhaven National Laboratory 83/09/01 3pp 20824 331
24X Fiche 50-275, 83/09/01, B310180610

--B310180621 Summary & evaluation rept of RL Cloud & Assoc rept, "Diablo Canyon Unit 1 IDVP - Soil - Outdoor Water Storage Tanks"
* Brookhaven National Laboratory 83/09/01 3pp 20824 334
24X Fiche 50-275, 83/09/01, B310180610

--B310180623 Summary & evaluation rept of RL Cloud & Assoc rept, "Diablo Canyon Unit 1 IDVP - Small Bore Piping Rept"
* Brookhaven National Laboratory 83/09/01 6pp 20824 337
24X Fiche 50-275, 83/09/01, B310180610

--B310180624 Summary & evaluation rept of RL Cloud & Assoc rept, "Diablo Canyon Unit 1 IDVP - HVAC Components"
* Brookhaven National Laboratory 83/09/01 5pp 20824 343
24X Fiche 50-275, 83/09/01, B310180610

--B310180626 Summary & evaluation rept of RL Cloud & Assoc rept, "IDVP Valves"
* Brookhaven National Laboratory 83/09/01 4pp 20824 348
24X Fiche 50-275, 83/09/01, B310180610

--B310180627 Summary & evaluation rept of RL Cloud & Assoc rept, "IDVP - HVAC Duct & Supports Rept"
* Brookhaven National Laboratory 83/09/01 5pp 20824 352
24X Fiche 50-275, 83/09/01, B310180610

B310060509 Forwards FR monthly notice of applications & amends to OLs involving NSHC, dtd 830823
* Office of Nuclear Reactor Regulation, Director 83/09/09
SCHUYLER, J O Pacific Gas & Electric Co 65pp 20663 187 24X
Fiche 50-275, 83/09/09, B310060509

B308300355 Board Notification 83-66A advises that position re rod drop issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycle
EISENHUT, D G Division of Licensing 83/09/29 PALLADINO, N J, QILINSKY, V, ROBERTS, T M Commissioners 10pp 20632 106 24X
Fiche 50-000, 83/09/29, B308300355

B308300357 Board Notification 82-105A Forwards evaluation of allegations re design deficiencies in Class I piping sys info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway
EISENHUT, D G Division of Licensing 83/09/29 PALLADINO, N J, QILINSKY, V, ROBERTS, T M Commissioners 3pp 20632 001 24X
Fiche 50-000, 83/09/29, B308300357

B310040570 Responds to B30328 request for info determining effect of plant operation & maint on archaeological Site Ca-SLO-2 ROs re heavy rainfall & fire causing erosion on B30127 & 0427 and
SCHUYLER, J O Pacific Gas & Electric Co 83/09/29 KNIGHTON, G W Licensing Branch 3 3pp 20622 320 24X Fiche 50-275, 83/09/29, B310040570

--B310040578 RO on B30127, personnel noticed erosion near northeastern border of SLO-2 site Caused by excessive runoff from slopes to east due to barren watershed being saturated by heavy rains Corrective actions being assessed
CRANE, P A Pacific Gas & Electric Co 83/02/28 ENGELKEN, R H Region 5, Office of Director 2pp 20622 323 24X
Fiche 50-275, 83/09/29, B310040570

--B310040585 Submits corrective action plan for erosion incident reported on B30228 Corrective actions gully will be backfilled & new concrete lined drainage ditch will be constructed Actions will be implemented by B30701
SCHUYLER, J O Pacific Gas & Electric Co 83/05/27 MARTIN, J B Region 5, Office of Director 2pp 20622 325 24X
Fiche 50-275, 83/09/29, B310040570

--B310040591 RO on B30427, shell midden for SLO-2 site bladed to max depth of 6 inches Caused by personnel error Disturbed area will be covered w/6 inches of fill Work procedure to increase control being developed
SCHUYLER, J O Pacific Gas & Electric Co 83/05/27 MARTIN, J B Region 5, Office of Director 2pp 20622 327 24X
Fiche 50-275, 83/09/29, B310040570

--B310040598 RO on B30627, penetration approx 20 inches deep & 4-ft wide dug in midden on southern extremity of Site SLO-2 Caused by const personnel error Hole lined w/polyethylene sheet & filled w/road base matl
SCHUYLER, J O Pacific Gas & Electric Co 83/07/27 MARTIN, J B Region 5, Office of Director 1p 20622 329 24X
Fiche 50-275, 83/09/29, B310040570

B308300358 Board Notification 83-150 forwards listed repts re facility IDVP Info will be considered in final evaluation of verification of plant mods & matters to be completed for license activities
EISENHUT, D G Division of Licensing 83/09/30 PALLADINO, N J, QILINSKY, V, ROBERTS, T M Commissioners 3pp 20644 032 24X
Fiche 50-275, 83/09/30, B308300358

B310170185 Trip rept of B30906-07 site visit re mods resulting from verification program to structures, sys & components
SCHIERLING, H Licensing Branch 3 83/09/30 KNIGHTON, G W Licensing Branch 3 5pp 20813 029 24X Fiche 50-275, 83/09/30, B310170185

B308300763 Board Notification 83-151 provides info re desirability of current ECCB actuation logic for Westinghouse plants, in light of recent info concerning steam generator tube rupture procedure for Borssele Nuclear Power Station
EISENHUT, D G Division of Licensing 83/10/04 PALLADINO, N J, QILINSKY, V, ROBERTS, T M Commissioners 2pp 20698 033 24X
Fiche 50-000, 83/10/04, B308300763

B310120078 Forwards diagram of forces & stresses at OHST foundation, in response to NRC request
DENIBON, E Robert L Cloud Associates, Inc 83/10/04 SCHIERLING, H Office of Nuclear Reactor Regulation, Director 2pp 20696 165 24X Fiche 50-275, 83/10/04, B310120078

B308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves
EISENHUT, D G Division of Licensing 83/10/06 PALLADINO, N J Commissioners 31pp 20818 001 24X Fiche 50-000, 83/10/06, B308300771

B310140121 Submits current status rept of actions taken in response to Generic Ltr 83-28 re generic implications of Salem ATWS event Actions to be taken include surveillance testing required by IE Bulletin 83-01
SCHUYLER, J O Rochester Gas & Electric Corp 83/10/07 KNIGHTON, G W Licensing Branch 3 2pp 20763 076 24X
Fiche 50-275, 83/10/07, B310140121

B310170489 Forwards addl info re alternate methods of statistical evaluation of Superstrut spot weld shear strength test data, in response to NRC request Test data evaluation presented in B30701 rept remains reasonable & valid
SCHUYLER, J O Pacific Gas & Electric Co 83/10/07 EISENHUT, D G Division of Licensing 3pp 20783 315 24X Fiche 50-275, 83/10/07, B310170489

B310170285 Augments B30701 submittal re masonry walls Addl info re turbine bldg tornado loads sufficient to completely address allegation on tornado design criteria re masonry walls, per DS Fleischaker B30328 ltr
SCHUYLER, J O Pacific Gas & Electric Co 83/10/11 EISENHUT, D G Division of Licensing 3pp 20786 194 24X Fiche 50-275, 83/10/11, B310170285

B310180458 Forwards addl info on containment integrity, per NRC request, Description of work involved in adding attachments to containment liner provided
SCHUYLER, J O Pacific Gas & Electric Co 83/10/12 EISENHUT, D G Division of Licensing 2pp 20802 066 24X Fiche 50-275, 83/10/12, B310180458

B310210154 Requests publication of FR notice of consideration of issuance of amend to License DPR-76 & proposed NSHC determination & opportunity for hearing re physical security plan NSHC determination available in Central Files
KNIGHTON, G W Licensing Branch 3 83/10/13 MILLER, J R Operating Reactors Branch 3 2pp 20883 359 24X Fiche 50-275, 83/10/13, B310210154

DOCKETED ITEMS

8310210227 Forwards "Seismically Induced Sys Interaction Program (SISIP) Completion of Containment Activities" SCHUYLER, J D Pacific Gas & Electric Co 83/10/13 EISENHUT, D G Division of Licensing 1p 20852 112 24X Fiche 50-275, 83/10/13, 8310210227

--8310210229 "Seismically Induced Sys Interaction Program (SISIP) Completion of Containment Activities" Bechtel Corp 83/10/13 262pp 20852 113 24X Fiche 50-275, 83/10/13, 8310210227

8310280157 Forwards transmittal pages to Rev 3 to DCNP-IDVP-PP-007 covering HV-104, "Computer Output," addl info re pad bending stress for support 55S/41A & calculations for U-192-J DENISON, E Robert L Cloud Associates, Inc 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director MARTIN, J B Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 4pp 20929 242 24X Fiche 50-275, 83/10/13, 8310280157

8308300775 Board Notification 83-135A forwards 830919 revised draft of "GA Case Study Working Paper - Case C," & cover & transmittal memos re Diablo Canyon EISENHUT, D G Division of Licensing 83/10/14 PALLADINO, N J, GILINSKY, V, ROBERTS, T Commissioners 3pp 20799 001 24X Fiche 50-000, 83/10/14, 8308300775

--8310180505 Informs that working papers for three GA case studies complete, per 830923 memo Case C re Diablo Canyon, dtd 830919, is rev to 830717 draft transmitted in Board Notification 83-135 on 830902 Papers & transmittal ltrs forwarded TAYLOR, J M GA Branch 83/09/28 EISENHUT, D G Division of Licensing 2pp 20799 004 24X Fiche 50-000, 83/10/14, 8308300775

--8310180311 Forwards case study working papers for site, per review of GA program for plant design & const Final Congressional rept will contain consolidated summary of case study conclusions TAYLOR, J M GA Branch 83/08/02 MANEATIS, G A Pacific Gas & Electric Co 1p 20799 006 24X Fiche 50-000, 83/10/14, 8308300775

--8310180517 Forwards revised draft of "GA Case Study Working Paper Case C" ALTMAN, W D NRC - No Detailed Affiliation Given 83/09/27 NRC - No Detailed Affiliation Given 1p 20799 007 24X Fiche 50-000, 83/10/14, 8308300775

--8310180521 Revised draft of "GA Case Study Working Paper - Case C" * NRC - No Detailed Affiliation Given 83/09/19 NRC - No Detailed Affiliation Given 42pp 20799 008 24X Fiche 50-000, 83/10/14, 8308300775

8310190197 Advises that qualification tests for special rods & couplers revealed straight rods removed from Unit 2 rupture restraints had heat exhibited ductilities less than design Rods will be reannealed or replaced SCHUYLER, J D Pacific Gas & Electric Co 83/10/04 EISENHUT, D G, Division of Licensing 2pp 20818 102 24X Fiche 50-275, 83/10/14, 8310190197

8310200260 Responds to EG&G Phase I recommendations re special lifting device, per NUREG-0612, "Control of Heavy Loads," Util 830509 commitment to restrict crane hoist speeds reduced possibility of overstress in lifting devices SCHUYLER, J D Pacific Gas & Electric Co 83/10/14 KNIGHTON, O W Licensing Branch 3 8pp 20830 078 24X Fiche 50-275, 83/10/14, 8310200260

8310210247 Forwards addl info to identify all masonry walls associated w/ 16 kV vital switchgear & cable spreading rooms located in turbine bldg, including clarification of evaluation methods & criteria used SCHUYLER, J D Pacific Gas & Electric Co 83/10/14 EISENHUT, D G Division of Licensing 4pp 20851 271 24X Fiche 50-275, 83/10/14, 8310210247

831090054 Forwards documents NRC delivered to Commissioner Gilinsky during 831017 briefing on plant design reverification GILINSKY, V Commissioners 83/10/17 Office of the Executive Legal Director 20pp 20823 259 24X Fiche 50-275, 83/10/17, 831090054

8308310029 Board Notification 83-161 forwards anonymous ltr alleging errors in design/documentation of safety-related sys, structures & components at Unit 1 EISENHUT, D G Division of Licensing 83/10/18 PALLADINO, N J, GILINSKY, V, ROBERTS, T Commissioners 4pp 20900 075 24X Fiche 50-275, 83/10/18, 8308310029

--8310290348 Requests that NRR take lead responsibility for resolution of allegations re errors in design/documentation of safety-related structures, sys & components, documented in encl anonymous ltr BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 83/10/12 EISENHUT, D G Division of Licensing 1p 20900 080 24X Fiche 50-275, 83/10/18, 8308310029

--8310250351 Anonymous ltr alleging errors in design/documentation of safety-related structures, sys & components * Affiliation Unknown 83/10/09 Region 5, Office of Director 3pp 20900 081 24X Fiche 50-275, 83/10/18, 8308310029

3 Inspection reports, IE Bulletins & correspondence

8310250416 Forwards std order for DOE work, "Specialized Insp Support - Technical Assistance for Diablo Canyon - Design Verification Program" ADAMS, C Energy, Dept of FIN B-8552 83/09/16 MARTIN, J B Region 5, Office of Director 1p 20897 184 24X Fiche 50-275, 83/09/16, 8310250416

--8310290423 Std order for DOE work "Specialized Insp Support Technical Assistance for Diablo Canyon - Design Verification Program," issued to L.L. MARTIN, J B Region 5, Office of Director MACRUSKY, J Energy, Dept of FIN B-8552 83/09/16 1p 20897 185 24X Fiche 50-275, 83/09/16, 8310290416

8310040221 Forwards IE Insp Repts 50-275/83-25 & 50-323/83 1B on 830718-22 & 0818 No noncompliance noted NORDERHAUG, L R Region 5, Office of Director 83/09/20 SCHUYLER, J D Pacific Gas & Electric Co 2pp 20617 290 24X Fiche 50-275, 83/09/20, 8310040221

--8310040226 IE Insp Repts 50-275/83-25 & 50-323/83-1B on 830718 27 & 0818 No noncompliance noted Major areas inspected emergency preparedness program, including emergency detection & classification & protective action decisionmaking SCOWN, K, SCHUSTER, M D Region 5, Office of Director 83/09/19 13pp 20617 252 24X Fiche 50-275, 83/09/20, 8310040221

8310170473 Forwards IE Insp Repts 50-275/83-28 & 50-323/83-20 on 830731-0703 No noncompliance noted BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 83/09/22 SCHUYLER, J D Pacific Gas & Electric Co 2pp 20783 305 24X Fiche 50-275, 83/09/22, 8310170473

--8310170479 IE Insp Repts 50-275/83-28 & 50-323/83-20 on 830731-0703 No noncompliance noted Major areas inspected plant operations, surveillance testing, maint, independent insp & followup of noncompliances, open items, allegation & preoperational tests CARLSON, J D, MENDONCA, M M, KIRSCH, D F Region 5, Office of Director 83/09/21 6pp 20783 307 24X Fiche 50-275, 83/09/22, 8310170473

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/24 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in R1D Bypass Loops Used in Westinghouse Plants" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

DOCKETED ITEMS

85

B308300752 IE Info Notice B3-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/10/07 Consolidated Edison Co of New
York, Inc 79pp 20882 026 24X Fiche 50-000, B3/10/07, B308300752

B310140121 Submits current status rept of actions taken in response to
Generic Ltr B3-28 re generic implications of Salem AWS
event Actions to be taken include surveillance testing
required by IE Bulletin B3 01
SCHUYLER, J D Rochester Gas & Electric Corp B3/10/07
KNIGHTON, G W Licensing Branch 3 2pp 20763 016 24X
Fiche 50-275, B3/10/07, B310140121

B308300759 IE Info Notice B3-67, "Emergency Use Respirator Matl Defect
Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000, B3/10/11, B308300759

B308300761 IE Info Notice B3-68, "Respirator User Warning Defective
Self-Contained Breathing Apparatus Air Cylinders " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000, B3/10/11, B308300761

B310170539 Forwards Amend & to license DPR-76 & safety evaluation
Safety evaluation withheld (ref IOCR7J 21) Amend requires
implementation of approved physical security plan
KNIGHTON, G W Licensing Branch 3 B3/10/11 FURUSH, M H Pacific
Gas & Electric Co 4pp 20784 203 24X Fiche 50-275, B3/10/11,
B310170539

--B310170542 Amend & to License DPR-76, changing vital area access
controls
EISENHUT, D O Division of Licensing B3/10/11 2pp 20784 207
24X Fiche 50-275, B3/10/11, B310170539

B310310332 Forwards IE Insp Repts 50-275/B3-29 & 50-323/B3-21 on
B30829-0902 & 06-09 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering
Programs B3/10/13 SCHUYLER, J D Pacific Gas & Electric Co 2pp
20960 311 24X Fiche 50-275, B3/10/13, B310310332

--B310310341 IE Insp Repts 50-275/B3-29 & 50-323/B3-21 on B30827 0702 &
06-09 No noncompliance noted Major areas inspected const
activities, including licensee action on previous insp
findings, IE info notices & deficiencies under IOCR NSO 95e
HERNANDEZ, G H, KIRSCH, D F Region 5, Office of Director
B3/10/07 11pp 20960 313 24X Fiche 50-275, B3/10/13, B310310332

--B310310346 "Insp Repts," Jul 1983
* EQ&O, Inc FIN B-8552 B3/07/31 NRC - No Detailed
Affiliation Given 12pp 20960 324 24X Fiche 50-275, B3/10/13,
B310310332

--B310310354 "Insp Repts," Aug 1983
* EQ&O, Inc FIN B-8552 B3/08/31 NRC - No Detailed
Affiliation Given 21pp 20960 336 24X Fiche 50-275, B3/10/13,
B310310332

B310200180 Ack receipt of B30927 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-275/B3-24 &
50-323/B3-17
BISHOP, T W Division of Resident, Reactor Project & Engineering
Programs B3/10/14 SCHUYLER, J D Pacific Gas & Electric Co 1p
20835 072 24X Fiche 50-275, B3/10/14, B310200180

--B310200183 Responds to NRC B30826 ltr re violations noted in IE Insp
Repts 50-275/B3-24 & 50-323/B3-17 Corrective actions lacking
devices on Unit 1 pipe support 46-9V existed on both
spring cans Turnbuckles verified by Pullman Power Products
SCHUYLER, J D Pacific Gas & Electric Co B3/09/27 MARTIN, J B
Region 5, Office of Director 8pp 20835 073 24X
Fiche 50-275, B3/10/14, B310200180

B310310246 Forwards IE Insp Repts 50-275/B3-30 & 50-323/B3-22 on
B30904-1001 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering
Programs B3/10/14 SCHUYLER, J D Pacific Gas & Electric Co 2pp
20947 182 24X Fiche 50-275, B3/10/14, B310310246

--B310310251 IE Insp Repts 50-275/B3-30 & 50-323/B3-22 on B30904-1001 No
noncompliance noted Major areas inspected surveillance
testing, maint, independent insp, followup of open items &
allegations, preoperational testing/results & plant tours
MENDONCA, M M, KIRSCH, D F Region 5, Office of Director
B3/10/13 10pp 20947 184 24X Fiche 50-275, B3/10/14, B310310246

B310280036 Ack receipt of B30916 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-275/B3-13 &
50-323/B3-10
BISHOP, T W Division of Resident, Reactor Project & Engineering
Programs B3/10/21 SCHUYLER, J D Pacific Gas & Electric Co 1p
20934 325 24X Fiche 50-275, B3/10/21, B310280036

--B310280048 Responds to NRC B30519 ltr re violations noted in IE Insp
Repts 50-275/B3-13 & 50-323/B3-10 Corrective actions sys for
maintaining welder qualification files revised Only
qualified welders on active list allowed to draw rods
SCHUYLER, J D Pacific Gas & Electric Co B3/09/16 MARTIN, J B
Region 5, Office of Director 5pp 20934 326 24X
Fiche 50-275, B3/10/21, B310280036

B310280060 Ack receipt of B31011 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-275/B3 08
BISHOP, T W Division of Resident, Reactor Project & Engineering
Programs B3/10/21 SCHUYLER, J D Pacific Gas & Electric Co 1p
20935 051 24X Fiche 50-275, B3/10/21, B310280060

--B310280067 Responds to NRC B30329 ltr re violations noted in IE Insp
Rept 50-275/B3-08 Corrective actions Procedure GCP-5A
revised to clarify requirements for stamping welders &
inspectors Addl training conducted
SCHUYLER, J D Pacific Gas & Electric Co B3/10/11 MARTIN, J B
Region 5, Office of Director 8pp 20935 052 24X
Fiche 50-275, B3/10/21, B310280060

B310310274 Forwards Allegation RV-B3-A-0047 re RHR sys Allegations
previously addressed in IE Insp Rept 50-275/B3-42 in
response to B20820 ltr Task interface agreement suggested
BISHOP, T W Division of Resident, Reactor Project & Engineering
Programs B3/10/26 EISENHUT, D O Division of Licensing 2pp
20961 303 24X Fiche 50-275, B3/10/26, B310310274

--B310310281 Ack receipt of NRC response to B20820 allegations re
facility RHR sys Allegations paraphrased by inspector in
IE Insp Rept 50-275/B3-42 misinterpreted
COOPER, J H Affiliation Unknown B3/10/20 BISHOP, T W Division
of Resident, Reactor Project & Engineering Programs 8pp
20961 305 24X Fiche 50-275, B3/10/24, B310310274

R Periodic operating reports & related correspondence

B310190051 Monthly operating rept for Aug 1983 W/B30901 ltr
KELLY, W J, THORNBERRY, R C Pacific Gas & Electric Co B3/09/01
Division of Data Automation & Management Information 3pp
20823 254 24X Fiche 50-275, B3/09/01, B310190051

B310040509 Forwards Rev 1 to "IDVP - Intake Structures," Interim
Technical Rept 50 "
DENISON, E Robert L Cloud Associates, Inc B3/10/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director MARTIN, J B Region
5, Office of Director MANEATIS, G H Pacific Gas & Electric Co
1p 20627 241 24X Fiche 50-275, B3/10/01, B310040509

--B310040515 Rev 1 to "IDVP - Intake Structures," Interim Technical
Rept 50 "
* Robert L Cloud Associates, Inc P103-4-B39-058 R01 B3/10/01
33pp 20627 242 24X Fiche 50-275, B3/10/01, B310040509

B310070208 Forwards Rev 1 to "Diablo Canyon Unit 1 IDVP Verification of
Corrective Action, Auxiliary Bldg," Interim Technical Rept
55
DENISON, E Robert L Cloud Associates, Inc B3/10/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director MANEATIS, G H
Pacific Gas & Electric Co MARTIN, J B Region 5, Office of
Director 1p 20657 201 24X Fiche 50-275, B3/10/01, B310070208

--B310070212 Rev 1 to "Diablo Canyon Unit 1 IDVP Verification of
Corrective Action, Auxiliary Bldg," Interim Technical Rept
55
STEPHENS, V M, DENISON, E Robert L Cloud Associates, Inc P
103-4-B39-055 R01 B3/10/01 110pp 20657 203 24X
Fiche 50-275, B3/10/01, B310070208

B310070086 Forwards Rev 1 to "IDVP Verification of Corrective
Action-Small Bore Piping," Interim Technical Rept 61
DENISON, E Robert L Cloud Associates, Inc B3/10/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director MARTIN, J B Region
5, Office of Director MANEATIS, G H Pacific Gas & Electric Co
1p 20658 122 24X Fiche 50-275, B3/10/02, B310070086

--B310070091 Rev 1 to "IDVP Verification of Corrective Action-Small Bore
Piping," Interim Technical Rept 61
DENISON, E, BROWNE, C I Robert L Cloud Associates, Inc P
103-4-B39-041 R01 B3/10/02 118pp 20658 123 24X
Fiche 50-275, B3/10/02, B310070086

DOCKETED ITEMS

- 8310070151 Forwards Rev 1 to "IDVP - HVAC Ducts, Electrical Raceways, Instrument Tubing & Associated Supports," Interim Technical Rept 63
DENISON, E Robert L Cloud Associates, Inc 83/10/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director MARTIN, J B Region
5, Office of Director MANEATIS, G H Pacific Gas & Electric Co
1p 20657 089 24X Fiche 50-275, 83/10/02, 8310070151
- 8310070155 Rev 1 to "IDVP - HVAC Ducts, Electrical Raceways, Instrument Tubing & Associated Supports," Interim Technical Rept 63
* Robert L Cloud Associates, Inc P105-4-839-063 R01 83/10/02
108pp 20657 091 24X Fiche 50-275, 83/10/02, 8310070151
- 8310070094 Forwards Rev 1 to "IDVP Verification of Corrective Action-Containment Bldg," Interim Technical Rept 54
DENISON, E Robert L Cloud Associates, Inc 83/10/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director MARTIN, J B Region
5, Office of Director MANEATIS, G H Pacific Gas & Electric Co
1p 20658 046 24X Fiche 50-275, 83/10/04, 8310070094
- 8310070100 Rev 1 to "IDVP Verification of Corrective Action-Containment Bldg," Interim Technical Rept 54
DENISON, E, STEPHENS, V M Robert L Cloud Associates, Inc P
105-4-839-054 R01 83/10/03 74pp 20658 047 24X
Fiche 50-275, 83/10/04, 8310070094
- 8310070215 Forwards Rev 1 to "Diablo Canyon Unit 1 IDVP Review of Corrective Action, Large & Small Bore Pipe Supports," Interim Technical Rept 60
DENISON, E Robert L Cloud Associates, Inc 83/10/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director MARTIN, J B Region
5, Office of Director MANEATIS, G H Pacific Gas & Electric Co 1p
20657 315 24X Fiche 50-275, 83/10/04, 8310070215
- 8310070227 Rev 1 to "Diablo Canyon Unit 1 IDVP Review of Corrective Action, Large & Small Bore Pipe Supports," Interim Technical Rept 60
DENISON, E Robert L Cloud Associates, Inc P105-4-839-060 R01
83/10/03 90pp 20657 317 24X Fiche 50-275, 83/10/04, 8310070215
- 8310070251 Forwards Rev 1 to "Diablo Canyon Unit 1 IDVP - Verification of Harding Lawson Assoc Soils Work," Interim Technical Rept 68
Rev completes IDVP verification of soils work
DENISON, E Robert L Cloud Associates, Inc 83/10/05 DENTON, H R
Office of Nuclear Reactor Regulation, Director MARTIN, J B Region 5,
Office of Director MANEATIS, G H Pacific Gas & Electric Co 1p
20655 029 24X Fiche 50-275, 83/10/05, 8310070251
- 8310070257 Rev 1 to "Diablo Canyon Unit 1 IDVP - Verification of Harding Lawson Assoc Soils Work," Interim Technical Rept 68
STEPHENS, V M, DENISON, E, MCNEILL, R Robert L Cloud Associates,
Inc P105-4-839-068 R01 83/10/04 127pp 20655 030 24X
Fiche 50-275, 83/10/05, 8310070251
- 808300766 Board Notification 83-194 forwards Rev 1 to "Diablo Canyon Unit 1 IDVP Verification of Corrective Action-Turbine Bldg,"
Rev 1 to "Information Items re Large Bore Piping" &
transcript of 830928 meeting w/utill
EISENHUT, D G Division of Licensing 83/10/07 PALLADINO, N J,
GILINSKY, V, ROBERTS, T M Commissioners 3pp 20782 188 24X
Fiche 50-275, 83/10/07, 8308300766
- 8310170214 Forwards Rev 0 to "Diablo Canyon Nuclear Power Plant IDVP Executive Summary"
COOPER, W E Teledyne Engineering Services 83/10/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director MANEATIS, G A
Pacific Gas & Electric Co 1p 20784 330 24X
Fiche 50-275, 83/10/10, 8310170214
- 8310170227 Rev 0 to "Diablo Canyon Nuclear Power Plant IDVP Executive Summary"
* Teledyne Engineering Services 83/10/10 15pp 20784 331
24X Fiche 50-275, 83/10/10, 8310170214
- 8310170646 Forwards Rev 0 to "Diablo Canyon Nuclear Power Plant, Unit 1 IDVP," final rept
COOPER, W E Teledyne Engineering Services 83/10/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director MARTIN, J B Region
5, Office of Director MANEATIS, G A Pacific Gas & Electric Co
6pp 20781 188 24X Fiche 50-275, 83/10/10, 8310170646
- 8310170651 Rev 0 to "Diablo Canyon Nuclear Power Plant, Unit 1 IDVP," final rept
* Teledyne Engineering Services 83/10/10 228pp 20781 200
24X Fiche 50-275, 83/10/10, 8310170646
- 8310140117 Forwards Rev 1 to "Diablo Canyon Unit 1 IDVP Verification of Diablo Canyon Plant Activities - Rupture Restraints," Interim Technical Rept 65
DENISON, E Robert L Cloud Associates, Inc. 83/10/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director MARTIN, J B Region 5,
Office of Director MANEATIS, G H Pacific Gas & Electric Co 1p
20762:229 24X Fiche 50-275, 83/10/11, 8310140117.
- 8310140119 Rev 1 to "Diablo Canyon Unit 1 IDVP Verification of Diablo Canyon Plant Activities - Rupture Restraints," Interim Technical Rept 65
DENISON, E, ANDERSON, P H Robert L Cloud Associates, Inc P
105-4-839-065 R01 83/10/11 65pp 20762 231 24X
Fiche 50-275, 83/10/11, 8310140117
- 8308300781 Board Notification 83-156 Forwards RL Cloud Assoc & Teledyne Engineering Svcs repts re IDVP
EISENHUT, D G Division of Licensing 83/10/14 PALLADINO, N J,
GILINSKY, V, ROBERTS, T M Commissioners 4pp 20875 192 24X
Fiche 50-275, 83/10/14, 8308300781
- 8310210233 Forwards "Diablo Canyon Verification Program, Semimonthly Status Rept 47," per Commission Order CLI-81-30 Rept
summarizes progress of technical work from 830920-1010
SCHUYLER, J D Pacific Gas & Electric Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director MARTIN, J B Region
5, Office of Director 2pp 20891 30P 24X Fiche 50-275, 83/10/14,
8310210233
- 8310210235 "Diablo Canyon Verification Program, Semimonthly Status Rept 47," summarizing progress from 830920-1010
* Pacific Gas & Electric Co 83/10/14 69pp 20851 304 24X
Fiche 50-275, 83/10/14, 8310210233
- 8310210284 Forwards Rev 14 to "Design Verification Program Phase 1 Final Rept"
SCHUYLER, J D Pacific Gas & Electric Co 83/10/14 EISENHUT, D G
Division of Licensing 2pp 20850 232 24X Fiche 50-275, 83/10/14,
8310210284
- 8310210288 Rev 14 to "Design Verification Program Phase 1 final Rept"
* Pacific Gas & Electric Co 83/10/14 171pp 20850 234 24X
Fiche 50-275, 83/10/14, 8310210284
- 8310260260 Forwards "IDVP," second Friday semimonthly rept for Oct 1983
COOPER, W E Teledyne Engineering Services 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director MARTIN, J B Region
5, Office of Director MANEATIS, G A Pacific Gas & Electric Co
1p 20911 327 24X Fiche 50-275, 83/10/14, 8310260260
- 8310260264 "IDVP," second Friday semimonthly rept for Oct 1983
* Teledyne Engineering Services. 83/10/14 13pp 20911 330
24X Fiche 50-275, 83/10/14, 8310260260
- 8310270241 Forwards list of effective pages to 831010 IDVP final rept
Matl replaces previous list as App G 2 in Vol IV of rept
COOPER, W E Teledyne Engineering Services 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director MANEATIS, G A
Pacific Gas & Electric Co MARTIN, J B Region 5, Office of
Director 21pp 20923 006 24X Fiche 50-275, 83/10/14, 8310270241
- 8310250115 Forwards replacement pages to 831014 final update to design
verification program Phase I final rept
SCHUYLER, J D Pacific Gas & Electric Co 83/10/19 EISENHUT, D G
Division of Licensing 13pp 20896 272 24X Fiche 50-275, 83/10/19,
8310250115
- 8 Reportable occurrences, LIRs & related correspondence
- 8310070158 LER 83-017/03L-0 on 830826, welding performed on additive
tank w/o draining tank of sodium hydroxide solution Caused
by lack of communication Effect of violation being
evaluated Additive tank will be drained w/830926 1tr
KELLY, W J, SHIFFER, J D Pacific Gas & Electric Co 83/09/26
MARTIN, J B Region 5, Office of Director 3pp 20697 081 24X
Fiche 50-275, 83/09/26, 8310070158
- 8310120280 Updated LER 83-007/01T-1 on 830509, during welding of
reinforcement pad on branch connection to loop C component
cooling water sys, water leaked from weld area Caused by
grinding on fillet overlaid Overweld removed w/830926 1tr
KELLY, W J, SHIFFER, J D Pacific Gas & Electric Co 83/09/26
MARTIN, J B Region 5, Office of Director 3pp 20693 003 24X
Fiche 50-275, 83/09/26, 8310120280
- 8310040570 Responds to 830328 request for info determining effect of
plant operation & maint on archaeological Site Ca-SLO-2
RDs re heavy rainfall & fire causing erosion on 830127 &
0427 encl
SCHUYLER, J D Pacific Gas & Electric Co 83/09/29 KNIGHTON, G W
Licensing Branch 3 3pp 20622 320 24X Fiche 50-275, 83/09/29,
8310040570

DOCKETED ITEMS

87

--B3100405/8 RD on B31012, personnel noticed erosion near northeastern border of SLD-2 site. Caused by excessive runoff from slopes to east due to barren watershed being saturated by heavy rains. Corrective actions being assessed.
CRANE, P A Pacific Gas & Electric Co 83/02/20 1406LKEN, R H
Region 5, Office of Director 2pp 20622 323 24X
Fiche 50-275, 83/09/29, B3100405/0

--B310040585 Submits corrective action plan for erosion incident reported on B30228. Corrective actions gully will be backfilled & new concrete-lined drainage ditch will be constructed. Actions will be implemented by 830701.
SCHUYLER, J O Pacific Gas & Electric Co 83/05/27 MARTIN, J B
Region 5, Office of Director 2pp 20622 325 24X
Fiche 50-275, 83/09/29, B3100405/0

--B310040591 RD on B30427, shell midden for SLD-2 site bladed to max depth of 6 inches. Caused by personnel error. Disturbed area will be covered w/4 inches of fill. Work procedure to increase control being developed.
SCHUYLER, J O Pacific Gas & Electric Co 83/05/27 MARTIN, J B
Region 5, Office of Director 2pp 20622 327 24X
Fiche 50-275, 83/09/29, B3100405/0

--B310040598 RD on B30627, penetration approx 20 inches deep & 4-ft wide dug in midden on southern extremity of Site SLD-2. Caused by const personnel error. Hole lined w/polyethylene sheet & filled w/load bare mat.
SCHUYLER, J O Pacific Gas & Electric Co 83/07/27 MARTIN, J B
Region 5, Office of Director 1p 20622 329 24X
Fiche 50-275, 83/09/29, B3100405/0

B310120136 LER B3-022/07L-0 on B30831, valve MU-0-268 shut for 36 minutes, isolating raw water reservoir from fire suppression header, rendering fire suppression water sys inoperable. Caused by broken underground water supply line W/B30930 ltr.
KELLY, W J, SHIFFER, J D Pacific Gas & Electric Co 83/09/30
MARTIN, J B Region 5, Office of Director 3pp 20695 287 24X
Fiche 50-275, 83/09/30, B310120136

B310120362 RD on B30902, during underwater environ monitoring, discovered sediment accumulation on sea floor resulting in mortality of some bottom dwelling marine invertebrates. Caused by pumping during grout mix discharge nozzle transfer.
SCHUYLER, J O Pacific Gas & Electric Co 83/10/03 MARTIN, J B
Region 5, Office of Director 2pp 20699 300 24X
Fiche 50-275, 83/10/03, B310120362

B310120666 PND-V-B3-044 on B31004, employee suffered heart attack during work. Personnel taken to hosp. No news release planned.
MORRILL, P J Region 5, Office of Director 83/10/04 1p
20676 157 24X Fiche 50-275, 83/10/04, B310120666

B310250537 LER B3-020/03L-0 on B30723, prior to fuel load, gaseous radwaste sys noble gas activity monitor KM-22 failed in svc. Caused by detector tube failure due to natural end-of-life. New tube installed & monitor tested W/B31012 ltr.
KELLY, W J, SHIFFER, J D Pacific Gas & Electric Co 83/10/12
MARTIN, J B Region 5, Office of Director 3pp 20700 055 24X
Fiche 50-275, 83/10/12, B310250537

B310250108 Advises that on B31013, Pacific Scientific Co provided info re possible defects in snubbers installed at facility. Util determined that 43 snubbers affected. Snubbers being replaced.
SHIFFER, J D Pacific Gas & Electric Co 83/10/13 MARTIN, J B
Region 5, Office of Director 1p 20846 249 24X
Fiche 50-275, 83/10/13, B310250108

B310250637 Updated LER B3-006/01L-1 on B30510, possible undersize condition discovered on reactor coolant piping weld W/B-RC-2-17 during ultrasonic testing. Weld confirmed to be above min wall requirements mechanically W/B31013 ltr.
KELLY, W J, SHIFFER, J D Pacific Gas & Electric Co 83/10/13
MARTIN, J B Region 5, Office of Director 3pp 20700 293 24X
Fiche 50-275, 83/10/13, B310250637

B310270376 Updated LER B3-019/03L-1 on B30826, welding performed on additive tank w/o first draining tank of sodium hydroxide solution. Caused by lack of communication to field. No evidence of cracks or corrosion observed W/B31020 ltr.
KELLY, W J, SHIFFER, J D Pacific Gas & Electric Co 83/10/20
MARTIN, J B Region 5, Office of Director 3pp 20723 288 24X
Fiche 50-275, 83/10/20, B310270376

T Hearing transcripts on non-antitrust matters

B310050442 Transcript of Commission B30927 briefing in Washington, DC re facility schedule. Pp 1-34. Viewgraphs & supporting documentation encl.
* Commissioners 83/09/27 52pp 20640 218 24X
Fiche 50-275, 83/09/27, B310050442

B308300766 Board Notification B3-154 forwards Rev 1 to "Diablo Canyon Unit 1 IDVP Verification of Corrective Action Turbine Bldg," Rev 1 to "Information Items re Large Bore Piping" & Transcript of B30928 meeting w/util.
EISENHUT, D G Division of Licensing 83/10/07 PALLADINO, N J,
GILINSKY, V, ROBERTS, T M Commissioners 3pp 20702 188 24X
Fiche 50-275, 83/10/07, B308300766

--B310170318 Transcript of B30928 technical conference w/util & BNL in Bethesda, MD re SSCR open items Pp 1-104.
* Commissioners 83/09/28 416pp 20782 191 24X
Fiche 50-275, 83/10/07, B308300766

B310180354 Forwards IDVP testimony.
AXELRAD, M Lowenstein, Newman, Reis, Axelrad & Toll 83/10/14
MOORE, T S, BUCK, J H, JOHNSON, W R Atomic Safety and Licensing
Appeal Panel 2pp 20804 104 24X Fiche 50-275, 83/10/14,
B310180354

--B310180361 Testimony of WE Cooper, RL Cloud, JE Krecting & RF Reedy on behalf of IDVP re Contentions 1, 2 & 5-B. Describes role of IDVP in verification of design work of plant & how IDVP performed work.
COOPER, W E, CLOUD, R L, KRECHTING, J L Lowenstein, Newman, Reis, Axelrad & Toll 83/10/14 59pp 20404 106 24X
Fiche 50-275, 83/10/14, B310180361

--B310180369 Testimony of RL Cloud, JM Buggs, MJ Holley & R Wray on behalf of IDVP re Contentions 3 & 4. Discusses allegations of internal technical program use of improper engineering stds to determine if license criteria met.
CLOUD, R L, BIGGS, J M, HOLLEY, J Lowenstein, Newman, Reis, Axelrad & Toll 83/10/14 33pp 20404 165 24X
Fiche 50-275, 83/10/14, B310180369

--B310180375 Testimony of JE Krecting & WE Cooper on behalf of IDVP re Contention 4 a -1 & a -4. Discusses allegations that IDVP accepted deviations from licensing criteria w/o adequate engineering justifications. Certificate of Svc encl.
KRECHTING, J E, COOPER, W E Lowenstein, Newman, Reis, Axelrad & Toll 83/10/14 71pp 20804 198 24X Fiche 50-275, 83/10/14,
B310180375

B310210350 Forwards NRC testimony.
MCOURREN, H J Hearing Branch 1 83/10/14 MOORE, T S, BUCK, J H,
JOHNSON, W R Atomic Safety and Licensing Appeal Panel 5pp
20849 140 24X Fiche 50-275, 83/10/14, B310210350

--B310210355 Testimony of JP Knight, HE Schierling & JS Hermiel on Governor Dukmejian & Joint Intervenor's Contentions 1a-e.
KNIGHT, J P Assistant Director for Comp & Structures Engineering (Post B30201) SCHIERLING, H E Division of Licensing
HERMIEL, J S Auxiliary Systems Branch 83/10/14 32pp
20849 145 24X Fiche 50-275, 83/10/14, B310210355

--B310210367 Testimony of JP Knight, HE Schierling & JS Hermiel on Governor Dukmejian & Joint Intervenor's Contentions 2a, 2b & 2c.
KNIGHT, J P Assistant Director for Comp & Structures Engineering (Post B30201) SCHIERLING, H E Division of Licensing
HERMIEL, J S Auxiliary Systems Branch 83/10/14 7pp
20849 177 24X Fiche 50-275, 83/10/14, B310210367

--B310210358 Testimony of JP Knight, P Kuo, H Polk, CA Miller, AJ Philippopoulos, CJ Constantino & PC Wang re Governor Dukmejian & Joint Intervenor's Contention 3.
KNIGHT, J P Assistant Director for Comp & Structures Engineering (Post B30201) KUO, P, POLK, H E Structural & Geotechnical Engineering Branch 83/10/14 25pp 20849 186 24X
Fiche 50-275, 83/10/14, B310210358

--B310210371 Testimony of JS Hermiel on Governor Dukmejian & Joint Intervenor's Contentions 4a, 4b, 4c, 4d, 4e & 4f.
HERMIEL, J S Auxiliary Systems Branch 83/10/14 10pp
20849 211 24X Fiche 50-275, 83/10/14, B310210371

--B310210382 Testimony of JL Knux re Governor Dukmejian & Joint Intervenor's Contentions 4b, 4c, 4d, 4e, 4f & 4g.
KNUX, J L Division of Systems Integration (Post B11005) 83/10/14 8pp 20849 221 24X Fiche 50-275, 83/10/14, B310210382

--B310210392 Testimony of TG Dunning re Governor Dukmejian & Joint Intervenor's Contention 4, Parts d, e & f.
DUNNING, T G Instrumentation & Control Systems Branch 83/10/14 10pp 20849 229 24X Fiche 50-275, 83/10/14, B310210392

--B310210398 Testimony of DJ Kubicki on Governor Dukmejian & Joint Intervenor's Contentions 4j, 4k & 4l.
KUBICKI, D J Chemical Engineering Branch 83/10/14 14pp
20849 239 24X Fiche 50-275, 83/10/14, B310210398

DOCKETED ITEMS

- B310210391 Testimony of P Kuo & HE Polk on Governor Deukmejian & Joint Intervenor Contentions 4n
KUO, P., POLK, H E Structural & Geotechnical Engineering Branch
83/10/14 3pp 20849 253 24X Fiche 50-275, 83/10/14, B310210390
- B310210378 Testimony of PJ Morrill on Governor Deukmejian & Joint Intervenor Contentions 5 & 8
MORRILL, P J Division of Resident, Reactor Project & Engineering Programs 83/10/14 6pp 20849 256 24X Fiche 50-275, 83/10/14, B310210350
- B310210381 Testimony of WP Haass on Governor Deukmejian & Joint Intervenor Contentions 6 & 8
HAASS, W P QA Branch 83/10/14 4pp 20849 262 24X Fiche 50-275, 83/10/14, B310210350
- B310210385 Testimony of JP Knight & HE Schierling on Governor Deukmejian & Joint Intervenor Contentions 7
KNIGHT, J P Assistant Director for Comp & Structures Engineering (Post B30201) SCHIERLING, H E Division of Licensing 83/10/14 6pp 20849 266 24X Fiche 50-275, 83/10/14, B310210350
- B310210387 Testimony of JS Hermiel on Governor Deukmejian & Joint Intervenor addl contentions on design, QA, Contention 9
HERMIEL, J S Auxiliary Systems Branch 83/10/14 168pp 20849 272 24X Fiche 50-275, 83/10/14, B310210330
- B310210358 Testimony of JP Knight, P Kuo, HE Polk, CA Miller, AJ Philippopoulos, CJ Constantino & PC Wang re Governor Deukmejian & Joint Intervenor Contentions 3
KNIGHT, J P Assistant Director for Comp & Structures Engineering (Post B30201) MILLER, C A, PHILIPPOPOULOS, NRC - No Detailed Affiliation Given 83/10/14 25pp 20849 186 24X Fiche 50-275, 83/10/14, B310210358
- B310210228 Forwards PJ Kempthorne & FJ Samaniego testimony
REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J R Joint Intervenor- Diablo Canyon 83/10/15 MOORE, T S, JOHNSON, W R, BUCK, J M Atomic Safety and Licensing Appeal Panel 1p 20852 042 24X Fiche 50-275, 83/10/15, B310210228
- B310210241 Testimony of PJ Kempthorne & FJ Samaniego re Contention 1 on IDVP conclusions in light of sampling methodology Prof qualifications encl
KEMPTHORNE, P J, SAMANIEGO, F J Joint Intervenor- Diablo Canyon 83/10/15 22pp 20852 043 24X Fiche 50-275, 83/10/15, B310210228
- B310210242 Exhibit list Certificate of Svc encl
REYNOLDS, J R Joint Intervenor- Diablo Canyon REYNOLDS, J R Center for Law in the Public Interest 83/10/15 6pp 20852 045 24X Fiche 50-275, 83/10/15, B310210228
- B310200178 Testimony of RB Hubbard re design QA Verification program has not yet demonstrated plant design complies w/all applicable NRC regulatory requirements & all util licensing criteria Related correspondence
HUBBARD, R B California, State of HUBBARD, R B HMB Technical Associates 83/10/16 79pp 20835 124 24X Fiche 50-275, 83/10/16, B310200178
- B310200184 Testimony of G Apostolakis re design QA IDVP weak since program fails to recognize implications of decision to cart IDVP in probabilistic terms & fails to use appropriate probabilistic analysis principles & methods
APOSTOLAKIS, G California, State of APOSTOLAKIS, G California, Univ of, Los Angeles, CA 83/10/16 21pp, 20835 208 24X Fiche 50-275, 83/10/16, B310200178
- B310200190 Testimony of JM Roesset re adequacy of util seismic modeling of structures & soils & of review of util work by IDVP four issues remain requiring further verification Affidavits of qualifications encl
ROESSET, J M California, State of 83/10/16 61pp 20835 229 24X Fiche 50-275, 83/10/16, B310200178
- B310200195 List of exhibits identified per ASL8 B31007 order Certificate of Svc encl
STRUMWASSER, M California, State of, 83/10/16 9pp, 20835 209 24X Fiche 50-275, 83/10/16, B310200178
- B310250326 Forwards corrected Pages 5, 6 & 8 to NRC B31014 testimony of JP Knight, HE Schierling & JS Hermiel on Governor Deukmejian & Joint Intervenor Contentions 2a-e Errors due to difficulties w/word processing
MCGURRIN, H J Hearing Branch 1 83/10/19 MOORE, T S, BUCK, J M, JOHNSON, W R Atomic Safety and Licensing Appeal Panel 2pp 20897 340 24X Fiche 50-275, 83/10/19, B310250326
- B310250332 Corrected Pages 5, 6 & 8 to JP Knight, HE Schierling & JS Hermiel testimony on Governor Deukmejian & Joint Intervenor Contentions 2a-e
KNIGHT, J P, SCHIERLING, H E, HERMIEL, J S NRC No Detailed Affiliation Given 83/10/19 3pp 20897 342 24X Fiche 50-275, 83/10/19, B310250326
- B310250176 Forwards H Schierling, W Haass & D Kubicki depositions & corrections to deposition transcripts w/o depositions
MCGURRIN, H J Hearing Branch 1 83/10/20 3pp 20892 354 24X Fiche 50-275, 83/10/20, B310250176
- B310250182 Corrections to WP Haass B30921, DJ Kubicki B30920 & HE Schierling B30921 depositions
HAASS, W P, KUBICKI, D J, SCHIERLING, H E NRC - No Detailed Affiliation Given 83/09/21 4pp 20892 355 24X Fiche 50-275, 83/10/20, B310250176
- B310280057 Transcript of witness testimony, prof qualifications & exhibits for reopened hearing re design, QA Certificate of Svc encl Related correspondence
* Pacific Gas & Electric Co 83/10/27 554pp 20935 320 24X Fiche 50-275, 83/10/27, B310280057

U Congressional/Executive Correspondence

- B31010114 Ack receipt of comments on plant licensing Commission deferred final consideration of matter until after NRC completes analysis of final IDVP rept
CHILK, B J Office of the Secretary of the Commission 83/10/05 HART, C K, CHACON, P, DAVIS, G California, State of 3pp 20668 151 24X Fiche 50-275, 83/10/05, B31010114
- B310110151 Notifies of Commission B31028 meeting to receive comments from util, Joint Intervenor & Governor Deukmejian re IDVP completion & NRC analysis & recommendation to reinstate DPH-76 to load fuel
CHILK, B J Office of the Secretary of the Commission 83/09/30 OHLBACH, R Pacific Gas & Electric Co REYNOLDS, J R Center for Law in the Public Interest STRUMWASSER, M California, State of 2pp 20668 154 24X Fiche 50-275, 83/10/05, B310110114
- B310200442 Responds to B30922 ltr re NRC handling of several working papers for case studies being conducted to support NRC right to Congress per Section 13 of NRC Authorization Act three working papers encl
PALLADINO, N J Commissioners 83/10/07 FORD, W H Senate 3pp 20871 295 24X Fiche 50-000, 83/10/07, B310200442
- B310200449 Expresses disappointment re release of draft study on QA programs at Diablo Canyon to licensee Full explanation requested
MARKEY, E J House of Rep, Interior & Insular Affairs 83/09/21 PALLADINO, N J Commissioners 2pp 20872 217 24X Fiche 50-000, 83/10/07, B310200442
- B310240169 Advises that State of CA legislator ltrs requesting delays in licensing do not represent policy of CA legislature License issuance recommended
ALQUIST, A E California, State of 83/10/17 PALLADINO, N J Commissioners 1p 20880 029 24X Fiche 50-275, 83/10/17, B310240169
- B310250045 Urges NRC to proceed w/o delay w/regulatory steps necessary to allow fuel loading, low power testing & commercial operation
DILLER, R C California, State of 83/10/19 PALLADINO, N J Commissioners 2pp 20894 089 24X Fiche 50-275, 83/10/19, B310250045

V Operator Examinations

- B310030285 Informs of periodic audits of licensed operator requalification programs Schedule for requalification training & exams requested by B31028
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 83/09/26 SCHUYLER, J D Pacific Gas & Electric Co 2pp 20591 039 24X Fiche 50-275, 83/09/26, B310030285

DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

- B310050004 Advises that NUREG-0737, Item 11 B 2 2, "Design Review of Plant Shielding - Corrective Actions for Access to Vital Areas," requirements met based on review of licensee B00102, 31, 1015, B10108, B20415, 0707 & B30513 submittals
STOLZ, J F Operating Reactors Branch 4 83/09/12 BAUER, E G Philadelphia Electric Co 5pp 20690 242 24X Fiche 50-277, 83/09/12, B310050004

DOCKETED ITEMS

89

8310040434 Forwards safety analysis re basis on which selected parameters for safety parameter display sys sufficient to assess safety status of each function for wide range of events, per Generic Ltr 82-33, Suppl 1 to NUREG-0737
GALLAGHER, J W Philadelphia Electric Co 83/09/28 EISENHUT, D G
Division of Licensing 8pp 20619 108 24X Fiche 50-277, 83/09/28, 8310040434

8310210269 Forwards IE Enforcement Conference Repts 50-277/83-23 & 50-278/83-23 on 830811 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/10/07
BOYER, V Philadelphia Electric Co 2pp 20855 248 24X
Fiche 50-277, 83/10/03, 8310210269

--8310210274 Notice of violation associated w/IE enforcement conference on 830811
* Region 1, Office of Director 83/10/03 2pp 20855 250 24X
Fiche 50-277, 83/10/03, 8310210269

--8310210278 IE Enforcement Conference Repts 50-277/83-23 & 50-278/83-23 on 830811 Major areas discussed violations from IE Insp Repts 50-277/83-16 & 50-278/83-16 re unsealed penetrations in fire barriers
BLOUGH, A R, WILLIAMS, J H, TRIPP, L I Region 1, Office of Director 83/08/22 4pp 20855 257 24X Fiche 50-277, 83/10/03, 8310210269

8310280252 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/25 Document
Management Branch 1p 20763 016 24X Fiche 50-277, 83/10/25, 8310280252

--8310280257 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-209, App A re immediate notification call list & EP-209, App D 1 re onsite emergency team leaders Affidavit encl
DALTROFF, S L Philadelphia Electric Co 83/05/13 ALLAN, J M Region 1, Office of Director 4pp 20963 017 24X
Fiche 50-277, 83/10/25, 8310280252

--8310280271 Public version of revised emergency plan implementing procedures, including Procedures EP-209, App A re immediate notification call list & EP-209, App D 1 re onsite emergency team leaders
* Philadelphia Electric Co 83/04/13 62pp 20763 021 24X
Fiche 50-277, 83/10/25, 8310280252

P Operating license stage documents & correspondence

8310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR
CONNOR, L Affiliation Unknown 83/05/02 NRC - No Detailed
Affiliation Given 1p 21004 270 24X Fiche 50-000, 83/05/02, 8310310017

8310110434 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept re NUREG-0612, "Control of Heavy Loads (Phase I) " Phase I acceptable Need for single failure-proof handling equipment will be addressed in Phase II
STOLZ, J F Operating Reactors Branch 4 83/09/21 BAUER, L G Philadelphia Electric Co 3pp 20712 076 24X
Fiche 50-277, 83/09/21, 8310110434

--8310110459 Safety evaluation re util 810618, 1222, 820520, 1029 & 830810 responses to NUREG-0612, "Control of Heavy Loads (Phase I) " Phase I acceptable
* NRC - No Detailed Affiliation Given 83/09/09 2pp 20712 079 24X Fiche 50-277, 83/09/21, 8310110434

--8309020392 "Control of Heavy Loads (C-10), Philadelphia Electric Co, Peach Bottom Atomic Power Station, Units 2 & 3," technical evaluation rept
BARONET, I H, GOMBERGER, C Franklin Institute/Franklin Research Center TER-C5506-379/380 83/08/31 SINGH, A NRC - No Detailed
Affiliation Given 32pp 20712 081 24X Fiche 50-277, 83/09/21, 8310110434

8310040189 Forwards revised pages to B11223 application for amend to Licenses DPR-44 & DPR-56, changing values of surveillance setpoints, per 830726 telcon
GALLAGHER, J W Philadelphia Electric Co 83/09/29 STOLZ, J F Operating Reactors Branch 4 2pp 20608 089 24X
Fiche 50-277, 83/09/29, 8310040189

--8310040191 Revised Tech Spec Pages 36 & 36a listing limiting conditions for operation & surveillance requirements for reactor protection sys power supply
* Philadelphia Electric Co 83/09/09 2pp 20608 091 24X
Fiche 50-277, 83/09/29, 8310040189

8310040415 Forwards "Implementation of NUREG-0619 Feedwater Nozzle Cracking," & proprietary "Peach Bottom Atomic Power Station, Unit 2, Feedwater Nozzle Fracture Mechanics Analysis to Show " Proprietary rept withheld (ref 10 CFR 2.790)
GALLAGHER, J W Philadelphia Electric Co 83/09/29 EISENHUT, D G Division of Licensing 2pp 20623 303 24X Fiche 50-277, 83/09/29, 8310040415

--8310040429 "Implementation of NUREG-0619 Feedwater Nozzle Cracking " Affidavit encl
* Philadelphia Electric Co 83/09/30 19pp 20623 305 24X
Fiche 50-277, 83/09/29, 8310040415

8310140203 Submits addl info on 830929 presentation to NRC re intergranular stress corrosion cracking insp & repairs Unit will return to svc & operate for 6 months to exhaust present fuel load Pipe will be replaced beginning Mar 1984
DALTROFF, S L Philadelphia Electric Co 83/10/06 STOLZ, J F Operating Reactors Branch 4 2pp 20762 356 24X
Fiche 50-277, 83/10/06, 8310140203

8310200016 Forwards draft SER re NUREG-0737, Item II D 3, "Post-Accident Sampling Sys " Response addressing concerns re three outstanding items requested Telcon to discuss early resolution should be arranged within 30 days of ltr receipt
STOLZ, J F Operating Reactors Branch 4 83/10/06 BAUER, L G Philadelphia Electric Co 12pp 20844 249 24X
Fiche 50-277, 83/10/06, 8310200016

8310260212 Forwards response to 831004 request re NUREG 0737, Item II E 4 2, "Containment Purge & Vent Valves," design evaluation W/13 oversize drawings Aperture cards are available in PDR
DALTROFF, S L Philadelphia Electric Co 83/10/19 STOLZ, J F Operating Reactors Branch 4 72pp 20709 277 24X
Fiche 50-277, 83/10/19, 8310260212

--8310260239 "Instruction Manual Type 9200 T-Ring Butterfly Valve Bodies " * Fisher Controls Co 74/03/31 14pp 20909 340 24X
Fiche 50-277, 83/10/19, 8310260212

G Inspection reports, IE Bulletins & correspondence

8310250419 Submits partial response to IE Bulletin 83-02, "Stress Corrosion Cracking in Large-Diameter Stainless Steel Recirculation Sys Piping at BWR Plants " Unit will be returned to svc by 831003
KEMPEN, J B Philadelphia Electric Co 83/09/15 MURLEY, T E Region 1, Office of Director 3pp 20897 186 24X
Fiche 50-277, 83/09/15, 8310250419

8310050051 Requests submittal of response to IE Bulletin 83-02, "Stress Corrosion Cracking in Large-Diameter Stainless Steel Recirculation Sys Piping at BWR Plants " Info needed to complete pipe crack review & analysis
STOLZ, J F Operating Reactors Branch 4 83/09/21 BAUER, L G Philadelphia Electric Co 7pp 20650 130 24X
Fiche 50-277, 83/09/21, 8310050051

8310120212 Forwards IE Insp Repts 50-277/83-19 & 50-278/83-19 on 830718-22 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/09/22 DALTROFF, S Philadelphia Electric Co 2pp 20692 318 24X
Fiche 50-277, 83/09/22, 8310120212

--8310120213 Notice of violation from insp on 830718-22 * Region 1, Office of Director 83/09/22 2pp 20692 320 24X
Fiche 50-277, 83/09/22, 8310120212

--8310120217 IE Insp Repts 50-277/83-19 & 50-278/83-19 on 830718-22 Noncompliances noted failure to train personnel in accordance w/Tech Specs & to perform safety evaluation for change in solidification of liquid waste procedure.
WHITE, J R, COLLINS, D J, LAMASTRA, M Region 1, Office of Director 83/09/12 16pp 20692, 322 24X Fiche 50-277, 83/09/22, 8310120212

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

DOCKETED ITEMS

- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349
- 8310210269 Forwards IE Enforcement Conference Repts 50-277/83-23 & 50-278/83-23 on 830811 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/10/03
BOYER, V Philadelphia Electric Co 2pp 20855 248 24X
Fiche 50-277, 83/10/03, 8310210269
- 8310210274 Notice of violation associated w/IE enforcement conference on 830811
* Region 1, Office of Director 83/10/03 2pp 20855 250 24X
Fiche 50-277, 83/10/03, 8310210269
- 8310210278 IE Enforcement Conference Repts 50-277/83-23 & 50-278/83-23 on 830811 Major areas discussed violations from IE Insp Repts 50-277/83-16 & 50-278/83-16 re unsealed penetrations in fire barriers.
BLOUGH, A R, WILLIAMS, J H, TRIPP, L F Region 1, Office of Director 83/08/22 4pp 20855 252 24X Fiche 50-277, 83/10/03, 8310210269
- 8310140203 Submits addl info on 830929 presentation to NRC re intergranular stress corrosion cracking insp & repairs
Unit will return to svc & operate for 6 months to exhaust present fuel load Pipe will be replaced beginning Mar 1984
DALTROFF, S L Philadelphia Electric Co 83/10/06 STOLZ, J F
Operating Reactors Branch 4 2pp 20762 356 24X
Fiche 50-277, 83/10/06, 8310140203
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Hatl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761
- 8310200162 Ack receipt of 830811 & 0923 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/83-16 & 50-278/83-16
STAROSTECKI, R Division of Project & Resident Programs 83/10/13
DALTROFF, S L Philadelphia Electric Co 1p 20835 355 24X
Fiche 50-277, 83/10/13, 8310200162
- 8310200172 Responds to NRC 830914 telcon re violations noted in IE Insp Repts 50-277/83-16 & 50-278/83-16 Corrective actions administrative procedures reexamined w/expectation that costly & impractical requirements can be eliminated
GALLAGHER, J W Philadelphia Electric Co 83/09/23
STAROSTECKI, R Division of Project & Resident Programs 2pp 20835 356 24X Fiche 50-277, 83/10/13, 8310200162
- 8310200196 Responds to NRC 830720 ltr re violations noted in IE Insp Repts 50-277/83-16 & 50-278/83-16 Corrective actions (individual) responsible for leaving door unlocked identified & denied access to protected area
DALTROFF, S L Philadelphia Electric Co 83/08/11 STAROSTECKI, R
Division of Project & Resident Programs 3pp 20835 358 24X
Fiche 50-277, 83/10/13, 8310200162
- 8310180551 Notification of 831021 meeting w/BWR licensees in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking
MIRAGLIA, F J Assistant Director for Safety Assessment 83/10/14
EISENHUT, D G Division of Licensing 5pp 20823 358 24X
Fiche 50-000, 83/10/14, 8310180551
- 8310210336 Notification of 831019 meeting w/util, GE, SWRI & LMI in King of Prussia, PA to review UI insp data on crack indication on 5 post-HSI welds
GEARS, G Operating Reactors Branch 4 83/10/18 STOLZ, J F
Operating Reactors Branch 4 2pp 20883 158 24X
Fiche 50-277, 83/10/18, 8310210336
- R Periodic operating reports & related correspondence
- 8310120313 Forwards "Regional Radiological Environ Monitoring Program Rept 18, 1982" & "Peach Bottom Atomic Power Station Environ Radiation Monitoring Program Rept 40, 1982"
WILLSEY, W B Philadelphia Electric Co 83/09/22 HAYNES, R C
Region 1, Office of Director 1p 20690 094 24X
Fiche 50-277, 83/09/22, 8310120313
- 8310120316 "Regional Radiological Environ Monitoring Program Rept 16, 1982"
* Radiation Management Corp 83/09/31 121pp 20690 095 24X
Fiche 50-277, 83/09/22, 8310120313
- 8310120319 "Peach Bottom Atomic Power Station Environs Radiation Monitoring Program Rept 40, 1982"
* Chemical Waste Management, Inc 83/07/31 120pp 20690 216 24X
Fiche 50-277, 83/09/22, 8310120313
- 8310200257 Forwards monthly operating rept for Sept 1983 & revised rept sheets for Jul & Aug 1983 for Unit 1
CODNEY, M J Philadelphia Electric Co 83/10/13 Director's
Office, Office of Inspection and Enforcement 1p 20830 046 24X
Fiche 50-277, 83/10/13, 8310200257
- 8310200261 Monthly operating rept for Sept 1983
ALDEN, W M Philadelphia Electric Co 83/10/13 10pp 20830 087 24X
Fiche 50-277, 83/10/13, 8310200257
- 8310200263 Revised rept sheets for monthly operating rept for Jul 1983
ALDEN, W M Philadelphia Electric Co 83/08/26 2pp 20830 097 24X
Fiche 50-277, 83/10/13, 8310200257
- 8310200264 Revised rept sheets for monthly operating rept for Aug 1983
ALDEN, W M Philadelphia Electric Co 83/08/26 2pp 20830 099 24X
Fiche 50-277, 83/10/13, 8310200257
- S Reportable occurrences, LERs & related correspondence
- 8310270541 Responds to FOIA request for three categories of documents re 830606 gas leak at Facility Forwards App A documents
FELTON, J M Division of Rules and Records 83/07/22 AROYROS, D L
Chamlin, Schottland, Rosen, Cavanagh & Uliano 2pp 20937 225 24X
Fiche 50-000, 83/07/22, 8310270541
- 8310270547 Submits morning rept for Region 1, listing 830606 & 07 events
ALLAN, J M Region 1, Office of Director 83/06/07 BLAHA, J
Program Support Branch 1p 20937 228 24X Fiche 50-000, 83/07/22, 8310270541
- 8310210329 Responds to FOIA request for all documents re significantly high rate of equipment failures for 06 BWR/4 rated at 2,436 MW Forwards App A documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/07/28 HAFNER, B
Suffolk Nuclear Study Group 2pp 20882 223 24X
Fiche 50-000, 83/07/28, 8310210329
- 8303240364 Summarizes evaluation of LERs for Mar 1982 - Feb 1983 LER submittals acceptable Supplemental or followup info would improve operational experience analysis
SEYFRIT, K V Reactor Operations Analysis Branch 83/03/16
STAROSTECKI, R Division of Project & Resident Programs 3pp 20882 273 24X Fiche 50-000, 83/07/28, 8310210329
- 8310270340 FOIA request for placement of listed LERs in PDR
GRABER, L D NUS Corp 83/09/08 Division of Rules and Records
2pp 20938 058 24X Fiche 50-000, 83/09/08, 8310270340
- 8310250382 LER 83-014/03L-D on 830812, control room fire barrier discovered w/o fire damper in one ventilation duct penetration caused by damper not incorporated into original ventilation sys installation New damper on order
CODNEY, M J Philadelphia Electric Co 83/09/14 MURLEY, T E
Region 1, Office of Director 1p 20897 268 24X
Fiche 50-277, 83/09/14, 8310250382

8310270347 Responds to FOIA request for release of 23 LERs to PIR
Forwards 12 LERs to be released. Documents also available in
PDR One LER canceled Eight LERs not received
FELTON, J M Division of Rules and Records 83/09/29 GRAVER, L D
NUS Corp 1p 20938 060 24X Fiche 50-000, 83/09/29, 8310270347

8310070301 Potential Part 21 rept re underrange characteristic of
Model N-EL10M transmitter Underrange zero offset may occur
when transmitter initially pressurized from atmospheric to
suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office
of Inspection and Enforcement 11pp 20651 064 24X
Fiche 50-000, 83/09/30, 8310070301

8310140068 PNO-1-83-104 on 830704, during RIR & recirculation piping
weld insp. 20 of 126 welds examined evidenced intergranular
stress corrosion cracking Licensee repairing 16 welds by
clad overlay technique
BLOUGH, A R, TRIPP, L E Region 1, Office of Director 83/10/07
1p 20766 359 24X Fiche 50-277, 83/10/07, 8310140068

8310310361 PNO-1-83-109 on 831024, licensee reported that radiographs
associated w/Class I piping improperly read by vendor during
outage mod work in 1981 & 1982 Part 21 implications under
evaluation
BLOUGH, A R, TRIPP, L E Region 1, Office of Director 83/10/25
1p 20961 121 24X Fiche 50-277, 83/10/25, 8310310361

DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8310050004 Advises that NUREG-0737, Item 11 B 2 2, "Design Review of
Plant Shielding - Corrective Actions for Access to Vital
Areas," requirements met based on review of licensee B00102,
31, 1013, B10100, B20415, 0707 & B30513 submittals
STOLZ, J F Operating Reactors Branch 4 83/09/12 BAUER, E O
Philadelphia Electric Co 5pp 20650 242 24X
Fiche 50-277, 83/09/12, 8310050004

8310040434 Forwards safety analysis re basis on which selected
parameters for safety parameter display sys sufficient to
assess safety status of each function for wide range of
events, per Generic Ltr 82-33, Suppl 1 to NUREG-0737
GALLAGHER, J W Philadelphia Electric Co 83/09/28 EISENHUT, D O
Division of Licensing 8pp 20619 108 24X Fiche 50-277, 83/09/28,
8310040434

8310210269 Forwards IE Enforcement Conference Repts 50-277/83-23 &
50-278/83-23 on 830811 & notice of violation
STARDBECK, R Division of Project & Resident Programs 83/10/03
BOYER, V Philadelphia Electric Co 2pp 20855 448 24X
Fiche 50-277, 83/10/03, 8310210269

--8310210274 Notice of violation associated w/IE enforcement conference
on 830811
* Region 1, Office of Director 83/10/03 2pp 20855 250 24X
Fiche 50-277, 83/10/03, 8310210274

--8310210278 IE Enforcement Conference Repts 50-277/83 23 & 50-278/83-23
on 830811 Major areas discussed violations from IE Insp
Repts 50-277/83-16 & 50-278/83-16 re unsealed penetrations
in fire barriers
BLOUGH, A R Region 1, Office of Director 83/08/22 4pp
20855 252 24X Fiche 50-277, 83/10/03, 8310210269

8310280252 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/10/25 Document
Management Branch 1p 20963 016 24X Fiche 50-277, 83/10/25,
8310280252

--8310280257 Forwards public version of revised emergency plan
implementing procedures, including Procedures EP-209, App A re immediate
notification call list & EP-209, App D-1 re onsite emergency team leaders Affidavit encl
DALTRUFF, S L Philadelphia Electric Co 83/05/13 ALLAN, J M
Region 1, Office of Director 4pp 20963 017 24X
Fiche 50-277, 83/10/25, 8310280252

--8310280271 Public version of revised emergency plan implementing
procedures, including Procedures EP-209, App A re immediate
notification call list & EP-209, App D-1 re onsite emergency
team leaders
* Philadelphia Electric Co 83/04/13 62pp 20963 021 24X
Fiche 50-277, 83/10/25 8310280252

P Operating license stage documents & correspondence

8310310017 FOIA request for documents re integrated leak rate tests for
listed facilities to be placed in PDR
CONNER, L Affiliation Unknown 83/05/02 NRC - No Detailed
Affiliation Given 1p 21004 270 24X Fiche 50-000, 83/05/02,
8310310017

8310310031 Responds to FOIA request for documents re integrated leak
rate tests for facilities to be placed in PDR & list of facilities for which
repts are unavailable
FELTON, J M Division of Rules and Records 83/07/06 CONNER, L
Affiliation Unknown 1p 21004 271 24X Fiche 50-000, 83/07/06,
8310310031

--8310310064 "Reactor Containment Bldg Integrated Leakage Rate Test
Rept " W/770620 1tr
ULLRICH, W T Philadelphia Electric Co 77/04/04 109pp
21005 313 24X Fiche 50-000, 83/07/06, 8310310031

8310110454 Forwards safety evaluation & Franklin Research Ctr technical
evaluation re NUREG-0612, "Control of Heavy Loads
(Phase I) " Phase I acceptable Need for single failure-proof
handling equipment will be addressed in Phase II
STOLZ, J F Operating Reactors Branch 4 83/09/21 BAUER, E O
Philadelphia Electric Co 3pp 20712 076 24X
Fiche 50-277, 83/09/21, 8310110454

--8310110459 Safety evaluation re util B10618, 1222, B20320, 1025 & B20810
responses to NUREG-0612, "Control of Heavy Loads (Phase I) "
Phase I acceptable
* NRC - No Detailed Affiliation Given 83/09/09 2pp
20712 079 24X Fiche 50-277, 83/09/21, 8310110454

--8309020392 "Control of Heavy Loads (C-10), Philadelphia Electric Co,
Peach Bottom Atomic Power Station, Units 2 & 3," technical
evaluation re
SARGENT, I H, BDMBERGER, C Franklin Institute/Franklin Research
Center TER-C5506-379/380 83/08/31 SINGH, A NRC - No Detailed
Affiliation Given 32pp 20712 081 24X Fiche 50-277, 83/09/21,
8310110454

8310040189 Forwards revised pages to B11223 application for amend to
Licenses DPR-44 & DPR-56, changing values of surveillance
setpoints, per B30726 telcon
GALLAGHER, J W Philadelphia Electric Co 83/09/29 STOLZ, J F,
Operating Reactors Branch 4 2pp 20608 089 24X
Fiche 50-277, 83/09/29, 8310040189

--8310040191 Revised Tech Spec Pages 36 & 36a listing limiting conditions
for operation & surveillance requirements for reactor
protection sys power supply
* Philadelphia Electric Co 83/09/09 2pp 20608 091 24X
Fiche 50-277, 83/09/29, 8310040189

8310040415 Forwards "Implementation of NUREG-0619 Feedwater Nozzle
Cracking," & proprietary "Peach Bottom Atomic Power Station,
Unit 2, Feedwater Nozzle Fracture Mechanics Analysis to Show
" Proprietary rept withheld (ref 10CFR2 790)
GALLAGHER, J W Philadelphia Electric Co 83/09/29 EISENHUT, D O
Division of Licensing 2pp 20623 303 24X Fiche 50-277, 83/09/29,
8310040415

--8310040429 "Implementation of NUREG-0619 Feedwater Nozzle Cracking "
Affidavit encl
* Philadelphia Electric Co 83/09/30 19pp 20623 305 24X
Fiche 50-277, 83/09/29, 8310040415

8310200016 Forwards draft SER re NUREG-0737, Item 11 B 3, "Post-Accident
Sampling Sys " Response addressing concerns re three
outstanding items requested, Telcon to discuss early
resolution should be arranged within 30 days of 1st receipt
STOLZ, J F Operating Reactors Branch 4 83/10/06 BAUER, E O
Philadelphia Electric Co 12pp 20844 249 24X
Fiche 50-277, 83/10/06, 8310200016

8310260212 Forwards response to 831004 request re NUREG-0737, Item
11 E 4 2, "Containment Purge & Vent Valves," design
evaluation W/13 oversize drawings Aperture cards are
available in PDR
DALTRUFF, S L Philadelphia Electric Co 83/10/19 STOLZ, J F
Operating Reactors Branch 4 72pp 20709 277 24X
Fiche 50-277, 83/10/19, 8310260212

Q Inspection reports, IE Bulletins & correspondence

8310120212 Forwards IE Insp Repts 50-277/83-19 & 50-278/83-19 on
830718-2P & notice of violation
MARTIN, I T Division of Engineering & Technical Programs 83/09/22
DALTRUFF, S Philadelphia Electric Co 2pp 20692 318 24X
Fiche 50-277 8310120212

DOCKETED ITEMS

-8310120213 Notice of violation from insp on 830718-22
* Region I, Office of Director 83/09/22 2pp 20692 320 24X
Fiche 50-277, 83/09/22, 8310120212

-8310120217 IE Insp Repts 50-277/83-19 & 50-278/83-19 on 830718-22
Noncompliances noted failure to train personnel in accordance w/Tech Specs & to perform safety evaluation for change in solidification of liquid waste procedure
WHITE, J. R., COLLINS, D. J., LAMASTRA, M. Region I, Office of Director 83/09/12 16pp 20692 322 24X Fiche 50-277, 83/09/22, 8310120212

308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Wilder Qualification Tests " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

310210269 Forwards IE Enforcement Conference Repts 50-277/83-23 & 50-278/83-23 on 830811 & notice of violation
STAROSTECKI, R. Division of Project & Resident Programs 83/10/03
BOYER, V. Philadelphia Electric Co 2pp 20855 248 24X
Fiche 50-277, 83/10/03, 8310210269

8310210274 Notice of violation associated w/IE enforcement conference on 830811
* Region I, Office of Director 83/10/03 2pp 20855 250 24X
Fiche 50-277, 83/10/03, 8310210269

8310210278 IE Enforcement Conference Repts 50-277/83-23 & 50-278/83-23 on 830811 Major areas discussed violations from IE Insp Repts 50-277/83-16 & 50-278/83-16 re unsealed penetrations in fire barriers
BLOUGH, A. R., WILLIAMS, J. H., TRIPP, L. C. Region I, Office of Director 83/08/22 4pp 20855 252 24X Fiche 50-277, 83/10/03, 8310210269

83080378 IE Info Notice 83-65, "Surveillance of Flow in R1D Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

83080752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

83080759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc 117pp 21043 079 24X Fiche 50-000, 83/10/11, 8308300759

83080761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

10200162 Ack receipt of 830811 & 0923 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/83-16 & 50-278/83-16
STAROSTECKI, R. Division of Project & Resident Programs 83/10/13
WALTRUFF, S. L. Philadelphia Electric Co 1p 20835 355 24X
Fiche 50-277, 83/10/13, 8310200162

--8310200172 Responds to NRC 830914 telcon re violations noted in IE Insp Repts 50-277/83-16 & 50-278/83-16 Corrective actions administrative procedures reexamined w/expectation that costly & impractical requirements can be eliminated
GALLAGHER, J. W. Philadelphia Electric Co 83/09/23
STAROSTECKI, R. Division of Project & Resident Programs 2pp 20835 356 24X Fiche 50-277, 83/10/13, 8310200162

--8310200196 Responds to NRC 830720 ltr re violations noted in IE Insp Repts 50-277/83-16 & 50-278/83-16 Corrective actions individual responsible for leaving door unlocked identified & denied access to protected area
WALTRUFF, S. L. Philadelphia Electric Co 83/08/11 STAROSTECKI, R. Division of Project & Resident Programs 3pp 20835 358 24X
Fiche 50-277, 83/10/13, 8310200162

8310180551 Notification of 831021 meeting w/BWR licensees in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking
MIRAGLIA, F. J. Assistant Director for Safety Assessment 83/10/14
EISENHUT, D. O. Division of Licensing 5pp 20823 358 24X
Fiche 50-000, 83/10/14, 8310180551

8310210336 Notification of 831019 meeting w/UTL, GE, SWRI & LMI in King of Prussia, PA to review UT insp data on crack indication on S post-1153 welds
GEARS, C. Operating Reactors Branch 4 83/10/18 STULZ, J. R. Operating Reactors Branch 4 2pp 20843 158 24X
Fiche 50-277, 83/10/18, 8310210336

R Periodic operating reports & related correspondence

8310120313 Forwards "Regional Radiological Environ Monitoring Program Rept 1B, 1982" & "Peach Bottom Atomic Power Station Environs Radiation Monitoring Program Rept 40, 1982"
WILLSEY, W. B. Philadelphia Electric Co 83/09/22 HAYNES, R. C. Region I, Office of Director 1p 20890 094 24X
Fiche 50-277, 83/09/22, 8310120313

--8310120314 "Regional Radiological Environ Monitoring Program Rept 1B, 1982"
* Radiation Management Corp 83/05/31 121pp 20690 095 24X
Fiche 50-277, 83/09/22, 8310120313

--8310120319 "Peach Bottom Atomic Power Station Environs Radiation Monitoring Program, Rept 40, 1982"
* Chemical Waste Management, Inc 83/07/31 120pp 20690 116 24X
Fiche 50-277, 83/09/22, 8310120313

8310200257 Forwards monthly operating rept for Sept 1983 & revised rept sheets for Jul & Aug 1983 for Unit 1
COONEY, M. J. Philadelphia Electric Co 83/10/13 Director's Office, Office of Inspection and Enforcement 1p 20830 086 24X
Fiche 50-277, 83/10/13, 8310200257

--8310200261 Monthly operating rept for Sept 1983
ALDEN, H. M. Philadelphia Electric Co 83/10/13 10pp 20830 087 24X
Fiche 50-277, 83/10/13, 8310200257

S Reportable occurrences, LERs & related correspondence

8310270541 Responds to FOIA request for three categories of documents re 830606 gas leak at facility forwards App A documents
FELTON, J. M. Division of Rules and Records 83/07/22 ARGYROS, D. L. Chamlin, Schottland, Rosen, Cavanagh & Uliano 2pp 20937 225 24X
Fiche 50-000, 83/07/22, 8310270541

--8310270547 Submits morning rept for Region I, listing 830606 & 07 events
ALLAN, J. M. Region I, Office of Director 83/06/07 BLAHA, J. Program Support Branch 1p 20937 228 24X
Fiche 50-000, 83/07/22, 8310270541

8310210329 Responds to FOIA request for all documents re significantly high rate of equipment failures for GL BWR/A rated at 2,436 MW forwards App A documents Documents also available in PDR
FELTON, J. M. Division of Rules and Records 83/07/28 HAFNER, R. Suffolk Nuclear Study Group 2pp 20882 223 24X
Fiche 50-000, 83/07/28, 8310210327

--8303240364 Summarizes evaluation of LLNs for Mar 1982 - Feb 1983 LERs submittable acceptable Supplemental or followup info would improve operational experience analysis
SEYFRIT, K. V. Reactor Operations Analysis Branch 83/03/16
STAROSTECKI, R. Division of Project & Resident Programs 3pp 20882 273 24X
Fiche 50-000, 83/07/28, 8310210327

DOCKETED ITEMS

93

8310250279 Followup LER 83-008/01Y-1 on 830214, during refueling outage, surveillance testing indicated combined leakage for listed valves exceeded limits or failed to meet requirements. Caused by seat surface degradation W/830913 ltr
COONEY, M J Philadelphia Electric Co 83/09/13 MURLEY, F L
Region 1, Office of Director App 20499 017 24X
Fiche 50-278, 83/09/13, 8310250279

8310200137 LER 83-009/01T-0 on 830908, during surveillance testing w/one diesel generator inoperable, breaker between diesel generator E-1 & emergency bus E-13 failed to close manually (cause unknown). Breaker tested successfully W/830912 ltr
COONEY, M J Philadelphia Electric Co 83/09/22 MURLEY, F L
Region 1, Office of Director App 20436 337 24X
Fiche 50-278, 83/09/22, 8310200137

8310070301 Potential Part 21 rept re underrange characteristic of Model M-ELIOM transmitter. Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input. End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X
Fiche 50-000, 83/09/30, 8310070301

8310310361 PNU-I-83-109 on 831024, licensee reported that radiogr.phs associated w/Class 1 piping improperly read by vendor during outage mod work in 1981 & 1982. Part 21 implications under evaluation
BLOUGH, R A, TRIPP, L E Region 1, Office of Director 83/10/25
1p 20761 121 24X Fiche 50-277, 83/10/25, 8310310361

DOCKET 50-280 SURRY POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8310040252 Forwards technical support cti & emergency operations facility floor plans, route maps to emergency response facilities & telephone listings. Requests update of info & submittal of personnel access documents
DANCE, H C Division of Project & Resident Programs 83/09/12
STEWART, W L Virginia Electric & Power Co 16pp 20613 049 24X
Fiche 50-000, 83/09/12, 8310040252

8310290388 Forwards IE Insp Repts 50-280/83-21 & 50-281/83-21 on 830822-26 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/20
STEWART, W L Virginia Electric & Power Co 2pp 20648 151 24X
Fiche 50-280, 83/09/20, 8310290388

--8310250394 IE Insp Repts 50-280/83-21 & 50-281/83-21 on 830822-26 No noncompliance noted. Major areas inspected: emergency preparedness, including audits, QA manuals & instructions & thorough discussions w/personnel
MARSTON, R R Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/09/13 8pp
20898 155 24X Fiche 50-280, 83/09/20, 8310250394

8310250320 Forwards IE Insp Repts 50-280/83-23 & 50-281/83-23 on 830816-17 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/23
STEWART, W L Virginia Electric & Power Co 2pp 20900 084 24X
Fiche 50-280, 83/09/23, 8310250320

--8310250328 IE Insp Repts 50-280/83-23 & 50-281/83-23 on 830811-17 No noncompliance noted. Major areas inspected: review of IM1 Action Item 11 B 2, plant mods for vital area access, posting, labelling & control of radiological areas
HOBBS, C M Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/09/21 4pp 20900 084 24X
Fiche 50-280, 83/09/23, 8310250328

8310030294 Forwards IE Safeguards Insp Repts 50-280/83-24 & 50-281/83-24 on 830906-09 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/20
STEWART, W L Virginia Electric & Power Co 2pp 20591 035 24X
Fiche 50-280, 83/09/28, 8310030294

--8310030305 IE Safeguards Insp Repts 50-280/83-24 & 50-281/83-24 on 830906-09 No noncompliance noted. Major areas inspected: organization mgt, site orientation, security plan & implementing procedures. Details withheld (ref 10CFR73.21)
HALL, D L Region 2, Office of Director MCQUIRE, D R Division of Emergency Preparedness & Materials Safety 83/09/28 1p
20591 037 24X Fiche 50-280, 83/09/28, 8310030305

8310060519 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/09/30 Document
Management Branch 1p 20643 147 24X Fiche 50-280, 83/09/30, 8310060519

--8310060523 Public version of Rev 2 to Emergency Plan Implementing Procedure EPIP-2 01, "Notification of State & Local Govts"
W/830916 ltr
SAUNDERS, R, STEWART, W L Virginia Electric & Power Co 83/08/25
O'REILLY, J P Region 2, Office of Director 21pp 20663 148
24X Fiche 50-280, 83/09/30, 8310060519

8310070403 Releases public version of revised corporate emergency response plan
FELTON, J M Division of Rules and Records 83/09/30 Document
Management Branch 1p 20675 182 24X Fiche 50-000, 83/09/30, 8310070403

--8310070418 Public version of revised corporate emergency response plan
W/830614 ltr
STEWART, W L Virginia Electric & Power Co 83/05/15
O'REILLY, J P Region 2, Office of Director 114pp 20675 183
24X Fiche 50-000, 83/09/30, 8310070403

8310060566 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/05 Document
Management Branch 1p 20661 248 24X Fiche 50-280, 83/10/05, 8310060566

--8310060577 Forwards public version of Rev 2 to Emergency Plan Implementing Procedure EPIP-4 20, "Health Physics Actions for Transport of Contaminated Injured Personnel" & Rev 2 to Procedure EPIP-5 01, "Transport of Personnel"
STEWART, W L Virginia Electric & Power Co 83/09/23
O'REILLY, J P Region 2, Office of Director 1p 20661 247 24X
Fiche 50-280, 83/10/05, 8310060566

--8310060584 Public version of Rev 2 to Emergency Plan Implementing Procedure EPIP-4 20, "Health Physics Actions for Transport of Contaminated Injured Personnel" & Rev 2 to Procedure EPIP-5 01, "Transport of Contaminated Injured Personnel"
WILSON, J Virginia Electric & Power Co 83/09/12 15pp
20661 250 24X Fiche 50-280, 83/10/05, 8310060566

831010186 Releases public version of radiological emergency response plan
FELTON, J M Division of Rules and Records 83/10/05 Document
Management Branch 1p 20701 020 24X Fiche 50-000, 83/10/05, 831010186

--831010189 Public version of radiological emergency response plan
W/830621 ltr
* Virginia Electric & Power Co 83/06/30 O'REILLY, J P Region 2, Office of Director 301pp 20701 021 24X
Fiche 50-000, 83/10/05, 831010186

831010237 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/05 Document
Management Branch 1p 20685 126 24X Fiche 50-280, 83/10/05, 831010237

--831010239 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP-4 22 re post-accident sampling of containment air & EPIP-4 01 re radiological assessment director
DEWANDEL, E P Virginia Electric & Power Co 83/09/23 Division of Emergency Preparedness & Engineering Response (Post 830103) 3pp 20685 127 24X
Fiche 50-280, 83/10/05, 831010237

--831010240 Public version of revised emergency plan implementing procedures, including Procedures EPIP 4 22 re post-accident sampling of containment air & EPIP-4 01 re radiological assessment director
SAUNDERS, R, COX, F Virginia Electric & Power Co 83/09/23 100pp 20685 130 24X
Fiche 50-280, 83/10/05, 831010237

831010263 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/05 Document
Management Branch 1p 20712 324 24X Fiche 50-280, 83/10/05, 831010263

--831010268 Forwards public version of Rev 2 to Emergency Plan Implementing Procedure EPIP-5 01, "Transportation of Contaminated Injured Personnel" & Rev 2 to EPIP-4 20 "Health Physics Actions for Transport of Personnel"
DEWANDEL, E P Virginia Electric & Power Co 83/09/14 Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 20712 325 24X
Fiche 50-280, 83/10/05, 831010263

8310180301 Forwards changes to security program. Changes withheld (ref 10CFR73.21)
STEWART, W L Virginia Electric & Power Co 83/10/05 MCQUIRE, D R Division of Emergency Preparedness & Materials Safety 1p
20806 351 24X Fiche 50-280, 83/10/05, 8310180301

DOCKETED ITEMS

8310260428 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/21 Document
Management Branch 1p 20926 124 24X Fiche 50-280, 83/10/21, 8310260428

--8310260432 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP-4 01 re radiological assessment director & EPIP-4 09 re source term assessment
STEWART, W L Virginia Electric & Power Co 83/10/14
O'REILLY, J P Region 2, Office of Director 1p 20926 125 24X
Fiche 50-280, 83/10/21, 8310260428

--8310260436 Public version of revised emergency plan implementing procedures, including Procedures EPIP-4 01 re radiological assessment director & EPIP-4 09 re source term assessment
COX, F. SAUNDERS, R Virginia Electric & Power Co 83/09/29
127pp 20926 126 24X Fiche 50-280, 83/10/21, 8310260428

P Operating license stage documents & correspondence

8310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR
CONNER, L Affiliation Unknown 83/05/02 NRC - No Detailed
Affiliation Given 1p 21004 270 24X Fiche 50-000, 83/05/02, 8310310017

8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forward documents to be placed in PDR & list of facilities for which repts are unavailable
FELTON, J M Division of Rules and Records 83/07/06 CONNER, L
Affiliation Unknown 1p 21004 271 24X Fiche 50-000, 83/07/06, 8310310031

8310110078 Forwards Amends 89 & 90 to Licenses DPR-37 & DPR-32, respectively & safety evaluation Amends revise Tech Specs by changing fractional power limit to 0.3 multiplier & restoring rod insertion limits for Unit 1
NEIGHBORS, J D Operating Reactors Branch 1 83/09/22 STEWART, W L
Virginia Electric & Power Co 3pp 20682 326 24X
Fiche 50-280, 83/09/22, 8310110078

--8310110081 Amends 89 & 90 to Licenses DPR-37 & DPR-32, respectively, changing Tech Specs re fractional power limit to 0.3 multiplier instead of 0.2 multiplier & restoring rod insertion limits to pre-Cycle 7 values for Unit 1
VARGA, S A Operating Reactors Branch 1 83/09/22 16pp
20682 329 24X Fiche 50-280, 83/09/22, 8310110078

--8310110084 Safety evaluation supporting Amends 89 & 90 to Licenses DPR-37 & DPR-32, respectively
NRC - No Detailed Affiliation Given 83/09/22 3pp
20682 345 24X Fiche 50-280, 83/09/22, 8310110078

8310120003 Summary of 830921 meeting w/utill in Bethesda, MD re proposal to reduce boron concentration in boron injection tanks & boric acid sys info on radiological dose savings & use of Westinghouse data will be provided by utill
NEIGHBORS, J D Operating Reactors Branch 1 83/09/29 Operating
Reactors Branch 1 31pp 20715 283 24X Fiche 50-280, 83/09/29, 8310120003

8310110137 Forwards payment of Class I & II fees for review of portion of utill 830825 application re addition of supervisor of health physics, per NRC 830915 ltr
STEWART, W L Virginia Electric & Power Co 83/10/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, H D License Fee Management Branch 1p 20666 292 24X Fiche 50-280, 83/10/04, 8310110137

8310140094 Forwards VEP-FRD-41, "Reactor Sys Transient Analyses Using RETRAN Computer Code," in response to questions raised at 830921 meeting re methodology used to analyze steam line break Meeting proposed for third wk of Oct 1983
STEWART, W L Virginia Electric & Power Co 83/10/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 2pp 20766 117 24X
Fiche 50-280, 83/10/06, 8310140094

8310190043 Forwards "VEPCO NQMD Code & Model" Rept is one of series discussing nuclear reload licensing & core follow support capabilities
STEWART, W L Virginia Electric & Power Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 2pp 20822 335 24X Fiche 50-000, 83/10/14, 8310190043

--8310190057 "VEPCO NQMD Code & Model"
BOWMAN, S M, DZIADOSZ, D, BERRYMAN, R M Virginia Electric & Power Co
VEP-NFE-1 83/09/30 118pp 20822 337 24X
Fiche 50-000, 83/10/14, 8310190043

8310200101 Provides status rept of utill progress on resolving rearing of motor-operated valves & plans for further work thirty-two valves will be rerated or replaced as needed Schedule for work completion will be provided by 840120
STEWART, W L Virginia Electric & Power Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 App 20666 060 24X
Fiche 50-280, 83/10/14, 8310200101

8310270300 Suppls 830325 response to 830111 request for addl info re NUREG-0737, Item 11 B 3, "Post-Accident Sampling" Interim core damage assessment procedure in use until Westinghouse Owners Group methodology completed by end of 1983
STEWART, W L Virginia Electric & Power Co 83/10/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 2pp 20923 193 24X Fiche 50-000, 83/10/20, 8310270300

G Inspection reports, IE Bulletins & correspondence

8310040450 Suppls 830730 response to IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc Model 1151 & 1152 Pressure Transmitters w/Either A or D Output Codes" Existing instruments to be upgraded w/type M circuit boards
STEWART, W L Virginia Electric & Power Co 83/09/16 O'REILLY, J P
Region 2, Office of Director 5pp 20623 280 24X
Fiche 50-280, 83/09/16, 8310040450

8310250388 Forwards IE Insp Repts 50-280/83-21 & 50-281/83-21 on 830822-26 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/20
STEWART, W L Virginia Electric & Power Co 2pp 20898 151 24X
Fiche 50-280, 83/09/20, 8310250388

--8310250394 IE Insp Repts 50-280/83-21 & 50-281/83-21 on 830822-26 No noncompliance noted Major areas inspected emergency preparedness, including audits, QA manuals & instructions & thorough discussions w/personnel
MARSTON, R R Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/09/13 8pp
20898 155 24X Fiche 50-280, 83/09/20, 8310250388

8310250459 Forwards IE Insp Repts 50-280/83-22 & 50-281/83-22 on 830816-17 & 29-31 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/22
STEWART, W L Virginia Electric & Power Co 2pp 20897 057 24X
Fiche 50-280, 83/09/22, 8310250459

--8310250464 IE Insp Repts 50-280/83-22 & 50-281/83-22 on 830816-17 & 29-31 No noncompliance noted Major areas inspected inservice insp, Unit 2 steam generator A birth weld ultrasonic test indications & J - tube erosion/corrosion
CROHLEY, D R, COLEY, J L Region 2, Office of Director BLAKE, J J
Division of Engineering & Operational Programs 83/09/16 8pp
20897 059 24X Fiche 50-280, 83/09/22, 8310250459

8310250320 Forwards IE Insp Repts 50-280/83-23 & 50-281/83-23 on 830816-17 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/23
STEWART, W L Virginia Electric & Power Co 2pp 20900 084 24X
Fiche 50-280, 83/09/23, 8310250320

--8310250328 IE Insp Repts 50-280/83-23 & 50-281/83-23 on 830811-17 No noncompliance noted Major areas inspected review of THJ Action Item II B 2, plant mode for vital area access, posting, labelling & control of radiological areas
HOSEY, C M Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/09/21 4pp 20900 086
24X Fiche 50-280, 83/09/23, 8310250320

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intake" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp, 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

DOCKETED ITEMS

95

8310030294 Forwards IE Safeguards Insp Repts 50-280/83-24 & 50-281/83-24 on 830906-09 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/28
STEWART, W L Virginia Electric & Power Co 2pp 20591 035 24X
Fiche 50-280, 83/09/28, 8310030294

--8310030305 IE Safeguards Insp Repts 50-280/83-24 & 50-281/83-24 on 830906-09 No noncompliance noted Major areas inspected organization-mgt, site orientation, security plan & implementing procedures Details withheld (ref 10CFR/3 21)
HALL, B L Region 2, Office of Director MCOUTRE, D R Division of Emergency Preparedness & Materials Safety 83/09/28 1p
20591 037 24X Fiche 50-280, 83/09/28, 8310030294

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 11pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310250429 Forwards IE Insp Repts 50-280/83-25 & 50-281/83-25 on 830913-16 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/10/04
STEWART, W L Virginia Electric & Power Co 2pp 20897 02J 24X
Fiche 50-280, 83/10/04, 8310250429

--8310250438 IE Insp Repts 50-280/83-25 & 50-281/83-25 on 830913-16 No noncompliance noted Major areas inspected radiological environ monitoring, including mgt & administrative controls & status review of environ monitoring
CUNNINGHAM, A L Region 2, Office of Director MONTGOMERY, D M Division of Engineering & Operational Programs 83/10/05 7pp
20897 025 24X Fiche 50-280, 83/10/04, 8310250429

8310250456 Supplemental response to IE Bulletin 80-16 Upgrading of Unit 1 Rosemount Model 1151 & 1152 pressure transmitters by installation of Type N circuit boards completed on 830927
STEWART, W L Virginia Electric & Power Co 83/10/06 O'REILLY, J P Region 2, Office of Director 1p 20897 104 24X
Fiche 50-280, 83/10/06, 8310250456

8308300378 IE Info Notice 83-65, "Surveillance of Flow in R111 Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 7pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 7pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 11pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 12pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

R Periodic operating reports & related correspondence

8310190016 Monthly operating repts for Aug 1983 W/830915 ltr
JONES, V, STEWART, W L, SAUNDERS, R Virginia Electric & Power Co 83/09/15 HALLER, N M Office of Resource Management, Director 42pp 20822 053 24X Fiche 50-280, 83/09/15, 8310190016

S Reportable occurrences LERs & related correspondence

8310040208 LER 83-039/03L-0 on 830831, svc water pump 1-BW-P-10A Failed to maintain sufficient discharge pressure when control room air conditioning unit C placed in svc Caused by insufficient NPBH Flow throttled W/830926 ltr
WILSON, J L Virginia Electric & Power Co 83/09/26 O'REILLY, J P Region 2, Office of Director 4pp 20614 331 24X
Fiche 50-280, 83/09/26, 8310040208

8310070164 LER 83-040/03L-0 on 830830, w/unit at 100% power, fire marshalled discovered that Fire Door 42 would not latch Caused by worn hinges Hinges replaced W/830930 ltr
WILSON, J L Virginia Electric & Power Co 83/09/30 O'REILLY, J P Region 2, Office of Director 3pp 20699 105 24X
Fiche 50-280, 83/09/30, 8310070164

8310210306 LER 83-041/03L-0 on 830709, while attempting to energize control room air conditioning chiller A, local control panel caught fire Chiller A removed from svc w/chiller C out of svc for maint. contrary to Tech Specs W/831007 ltr
WILSON, J L Virginia Electric & Power Co 83/10/07 O'REILLY, J P Region 2, Office of Director 3pp 20651 131 24X
Fiche 50-280, 83/10/07, 8310210306

8310250609 LER83-043/03L-0 on 830914, following reactor trip, flow control valve (FCV) failed to close upon receipt of feedwater isolation signal Caused by malfunctioning solenoid valve & FCV-148B restricted by antirotation device
WILSON, J L Virginia Electric & Power Co 83/10/14 O'REILLY, J P Region 2, Office of Director 4pp 20899 319 24X
Fiche 50-280, 83/10/14, 8310250609

8310190236 PNO-II-83-082 on 831015, control room operator trainee killed instantly when fist-sized hole blew open in wall of 24-inch carbon steel pipe attached to high pressure feedwater drain pump Cause under investigation
LANDIS, K, DANCE, H Region 2, Office of Director 83/10/17 2pp 20818 078 24X Fiche 50-280, 83/10/17, 8310190236

DOCKET 50-281 SURRY POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8310040252 Forwards technical support ctr & emergency operations facility floor plans, route maps to emergency response facilities & telephone listings Requests update of info & submittal of personnel access documents
DANCE, H C Division of Project & Resident Programs 83/09/12
STEWART, W L Virginia Electric & Power Co 16pp 20613 049 24X
Fiche 50-000, 83/09/12, 8310040252

8310250388 Forwards IE Insp Repts 50-280/83-21 & 50-281/83-21 on 830822-26 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/20
STEWART, W L Virginia Electric & Power Co 2pp 20898 193 24X
Fiche 50-280, 83/09/20, 8310250388

--8310250394 IE Insp Repts 50-280/83-21 & 50-281/83-21 on 830822-26 No noncompliance noted Major areas inspected emergency preparedness, including audits, QA manuals & instructions & thorough discussions w/personnel
MARSTON, R R Region 2, Office of Director 83/09/13 8pp 20898 155 24X Fiche 50-280, 83/09/20, 8310250388

8310250320 Forwards IE Insp Repts 50-280/83-23 & 50-281/83-23 on 830814-17 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/23
STEWART, W L Virginia Electric & Power Co 2pp 20700 084 24X
Fiche 50-280, 83/09/23, 8310250320

--8310250328 IE Insp Repts 50-280/83-23 & 50-281/83-23 on 830811-17 No noncompliance noted Major areas inspected review of TMI Action Item II B 2, plant mods for vital area access, posting, labelling & control of radiological areas
HOSEY, C M Region 2, Office of Director 83/09/21 4pp 20700 086 24X Fiche 50-280, 83/09/23, 8310250320

8310030294 Forwards IE Safeguards Insp Repts 50-280/83-24 & 50-281/83-24 on 830906-09 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/28
STEWART, W L Virginia Electric & Power Co 2pp 20591 035 24X
Fiche 50-280, 83/09/28, 8310030294

--8310030305 IE Safeguards Insp Repts 50-280/83-24 & 50-281/83-24 on 830906-09 No noncompliance noted Major areas inspected organization mgt, site orientation, security plan & implementing procedures Details withheld (ref 10CFR73 21)
HALL, B L Region 2, Office of Director 83/09/28 1p 20591 037 24X Fiche 50-280, 83/09/28, 8310030294

8310060519 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/09/30 Document Management Branch 1p 20663 147 24X Fiche 50-280, 83/09/30, 8310060519

--8310060523 Public version of Rev 3 to Emergency Plan Implementing Procedure EPIP-2 01, "Notification of State & Local Govts " W/830916 ltr
SAUNDERS, R, STEWART, W L Virginia Electric & Power Co 83/08/25 O'REILLY, J P Region 2, Office of Director 21pp 20663 148 24X Fiche 50-280, 83/09/30, 8310060519

8310070403 Releases public version of revised corporate emergency response plan
FELTON, J M Division of Rules and Records 83/09/30 Document Management Branch 1p 20675 182 24X Fiche 50-000, 83/09/30, 8310070403

DOCKETED ITEMS

- B310070418 Public version of revised corporate emergency response plan
W/B300614 1tr
STEWART, W L Virginia Electric & Power Co 83/05/15
O'REILLY, J P Region 2, Office of Director 114pp 204/5 183
24X Fiche 50-000, 83/09/30, B310070403
- B310060566 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/10/05 Document
Management Branch 1p 20661 248 24X Fiche 50-280, 83/10/05,
B310060566
- B310060577 Forwards public version of Rev 2 to Emergency Plan
Implementing Procedure EPIP-4 20, "Health Physics Actions
for Transport of Contaminated Injured Personnel" & Rev 2 to
Procedure EPIP-5 01, "Transport of Personnel"
STEWART, W L Virginia Electric & Power Co 83/09/23
O'REILLY, J P Region 2, Office of Director 1p 20661 247 24X
Fiche 50-280, 83/10/03, B310060566
- B310060584 Public version of Rev 2 to Emergency Plan Implementing
Procedure EPIP-4 20, "Health Physics Actions for Transport
of Contaminated Injured Personnel" & Rev 2 to Procedure
EPIP-5 01, "Transport of Contaminated Injured Personnel"
WILSON, J Virginia Electric & Power Co 83/09/12 15pp
20661 250 24X Fiche 50-280, 83/10/05, B310060566
- B310110186 Releases public version of radiological emergency response
plan
FELTON, J M Division of Rules and Records 83/10/05 Document
Management Branch 1p 20701 020 24X Fiche 50-000, 83/10/05,
B310110186
- B310110190 Public version of radiological emergency response plan
W/B30621 1tr
* Virginia Electric & Power Co 83/06/30 O'REILLY, J P Region
2, Office of Director 301pp 20701 021 24X
Fiche 50-000, 83/10/05, B310110186
- B310110237 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/10/05 Document
Management Branch 1p 20685 126 24X Fiche 50-280, 83/10/05,
B310110237
- B310110239 Forwards public version of revised emergency plan
implementing procedures, including Procedures EPIP-4 22 re post-accident
sampling of containment air & EPIP-4 01 re radiological
assessment director
DEWANDEL, E P Virginia Electric & Power Co 83/09/23 Division
of Emergency Preparedness & Engineering Response (Post B30103)
3pp 20685 127 24X Fiche 50-280, 83/10/05, B310110237
- B310110240 Public version of revised emergency plan implementing
procedures, including Procedures EPIP-4 22 re post-accident
sampling of containment air & EPIP-4 01 re radiological
assessment director
SAUNDERS, R, COX, F Virginia Electric & Power Co 83/09/23
100pp 20685 130 24X Fiche 50-280, 83/10/05, B310110237
- B310110263 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/10/05 Document
Management Branch 1p 20712 324 24X Fiche 50-280, 83/10/05,
B310110263
- B310110268 Forwards public version of Rev 2 to Emergency Plan
Implementing Procedure EPIP-5 01, "Transportation of
Contaminated Injured Personnel" & Rev 2 to EPIP-4 20
"Health Physics Actions for Transport of Personnel"
DEWANDEL, E P Virginia Electric & Power Co 83/09/14 Division
of Emergency Preparedness & Engineering Response (Post B30103)
2pp 20712 325 24X Fiche 50-280, 83/10/05, B310110263
- B310180301 Forwards changes to security program Changes withheld
(ref 10CFR73.21)
STEWART, W L Virginia Electric & Power Co 83/10/05 MCQUIR, D K
Division of Emergency Preparedness & Materials Safety 1p
20804 351 24X Fiche 50-280, 83/10/05, B310180301
- B310260428 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/10/21 Document
Management Branch 1p 20926 124 24X Fiche 50-280, 83/10/21,
B310260428
- B310260432 Forwards public version of revised emergency plan
implementing procedures, including Procedures EPIP-4 01 re
radiological assessment director & EPIP-4 09 re source term
assessment
STEWART, W L Virginia Electric & Power Co 83/10/14
O'REILLY, J P Region 2, Office of Director 1p 20926 125 24X
Fiche 50-280, 83/10/21, B310260428
- B310260436 Public version of revised emergency plan implementing
procedures, including Procedure EPIP 4 01 re radiological
assessment director & EPIP-4 09 re source term assessment
COX, F, SAUNDERS, R Virginia Electric & Power Co 83/09/27
127pp 20926 126 24X Fiche 50-280, 83/10/21, B310260428
- P Operating license stage documents & correspondence

- B310110070 Forwards Amends B9 & 90 to Licenses DPR-37 & DPR-34,
respectively & safety evaluation Amends revise Tech Specs by
changing fractional power limit to 0.3 multiplier &
restoring rod insertion limits for Unit 1
NEIGHBORS, J D Operating Reactors Branch 1 83/09/22 STEWART, W L
Virginia Electric & Power Co Jpp 20682 326 24X
Fiche 50-280, 83/09/22, B310110070
- B310110081 Amends B9 & 90 to Licenses DPR-37 & DPR-34, respectively,
changing Tech Specs re Fractional power limit to 0.3
multiplier instead of 0.2 multiplier & restoring rod
insertion limits to pre-cycle 7 values for Unit 1
VARQA, S A Operating Reactors Branch 1 83/09/22 16pp
20682 329 24X Fiche 50-280, 83/09/22, B310110070
- B310110084 Safety evaluation supporting Amends B9 & 90 to Licenses
DPR-37 & DPR-34, respectively
* NRC - No Detailed Affiliation Given 83/09/23 3pp
20682 345 24X Fiche 50-280, 83/09/24, B310110070
- B308300357 Board Notification B2-105A forwards evaluation of
allegations re design deficiencies in Class I piping sys
info applicable to Diablo Canyon 1 & 2 Fermi 2 & Callaway
EISENHUT, D O Division of Licensing 83/09/29 PALLADINO, N J
Commissioners 3pp 20632 001 24X Fiche 50-000, 83/09/29,
B308300357
- B310120003 Summary of B30921 meeting w/util in Bethesda, MD re proposal
to reduce boron concentration in boron injection tanks &
boric acid sys info on radiological dose savings & use of
Westinghouse data will be provided by util
NEIGHBORS, J D Operating Reactors Branch 1 83/09/29 Operating
Reactors Branch 1 31pp 20715 283 24X Fiche 50-280, 83/09/29,
B310120003
- B310110137 Forwards payment of Class I & II fees for review of portion
of util B30825 application re addition of supervisor of
health physics, per NRC B30915 1tr
STEWART, W L Virginia Electric & Power Co 83/10/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, W D License
Fee Management Branch 1p 20666 292 24X Fiche 50-280, 83/10/04,
B310110137
- B310140094 Forwards VEP-FRD-41, "Reactor Sys Transient Analysis Using
RETRAN Computer Code," in response to questions raised at
B30921 meeting re methodology used to analyze steam line
break Meeting proposed for third wk of Oct 1983
STEWART, W L Virginia Electric & Power Co 83/10/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARQA, S A
Operating Reactors Branch 1 2pp 20666 117 24X
Fiche 50-280, 83/10/06, B310140094
- B310190043 Forwards "VEPCO NDMAD Code & Model" Rept is one of series
discussing nuclear reload licensing & core follow
support capabilities
STEWART, W L Virginia Electric & Power Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D O
Division of Licensing 2pp 20822 335 24X Fiche 50-000, 83/10/14,
B310190043
- B310190057 "VEPCO NDMAD Code & Model"
BOWMAN, S M, DZIADOSZ, D, DERRYMAN, R M Virginia Electric & Power
Co VEP-NFE-1 83/09/30 118pp 20822 337 24X
Fiche 50-000, 83/10/14, B310190043
- B310200101 Provides status rept of util progress on resolving rotating
of motor-operated valves & plans for further work thirty-two
valves will be rerated or replaced as needed Schedule for
work completion will be provided by B40120
STEWART, W L Virginia Electric & Power Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARQA, S A
Operating Reactors Branch 1 4pp 20846 040 24X
Fiche 50-280, 83/10/14, B310200101
- B310270300 Suppl B30325 response to B30111 request for addl info re
NUREG-0737, Item II B.3, "Post-Accident Sampling" Interim
core damage assessment procedure in use until Westinghouse
Owners Group methodology completed by end of 1983
STEWART, W L Virginia Electric & Power Co 83/10/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D O
Division of Licensing 2pp 20923 193 24X Fiche 50-000, 83/10/20,
B310270300

DOCKETED ITEMS

97

0 Inspection reports, IE Bulletins & correspondence

8310040450 Supply B00730 response to IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc Model 1151 & 1152 Pressure Transmitters w/Either A or D Output Codes " Existing instruments to be upgraded w/Type N circuit boards
STEWART, W L Virginia Electric & Power Co 83/09/16 O'REILLY, J P
Region 2, Office of Director 5pp 20625 280 24X
Fiche 50-280, 83/09/16, 8310040450

8310250388 Forwards IE Insp Repts 50-280/83-21 & 50-281/83-21 on 830822-26 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/20
STEWART, W L Virginia Electric & Power Co 2pp 20890 15J 24X
Fiche 50-280, 83/09/20, 8310250388

--8310250394 IE Insp Repts 50-280/83-21 & 50-281/83-21 on 830822-26 No noncompliance noted Major areas inspected emergency preparedness, including audits, QA manuals & instructions & thorough discussions w/personnel
MARSTON, R R Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/09/13 8pp
20898 155 24X Fiche 50-280, 83/09/20, 8310250388

8310250459 Forwards IE Insp Repts 50-280/83-22 & 50-281/83-22 on 830816-17 & 29-31 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/22
STEWART, W L Virginia Electric & Power Co 2pp 20897 05/ 24X
Fiche 50-280, 83/09/22, 8310250459

--8310250464 IE Insp Repts 50-280/83-22 & 50-281/83-22 on 830816-17 & 29-31 No noncompliance noted Major areas inspected inservice insp, Unit 2 steam generator A girth weld ultrasonic test indications & J - tube erosion/corrosion
CRDLEY, D R , COLEY, J L Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/09/16 8pp
20897 059 24X Fiche 50-280, 83/09/22, 8310250459

8310250320 Forwards IE Insp Repts 50-280/83-23 & 50-281/83-23 on 830816-17 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/23
STEWART, W L Virginia Electric & Power Co 2pp 20900 084 24X
Fiche 50-280, 83/09/23, 8310250320

--8310250328 IE Insp Repts 50-280/83-23 & 50-281/83-23 on 830811-17 No noncompliance noted Major areas inspected review of IMI Action Item II B 2, plant mods for vital area access, posting, labelling & control of radiological areas
HOSEY, C M Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/09/21 4pp 20900 086
24X Fiche 50-280, 83/09/23, 8310250320

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310030294 Forwards IE Safeguards Insp Repts 50-280/83-24 & 50-281/83-24 on 830906-09 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/28
STEWART, W L Virginia Electric & Power Co 2pp 20591 039 24X
Fiche 50-280, 83/09/28, 8310030294

--8310030305 IE Safeguards Insp Repts 50-280/83-24 & 50-281/83-24 on 830906-09 No noncompliance noted Major areas inspected organization-mgt, site orientation, security plan & implementing procedures Details withheld (ref 10CFR73 21)
HALL, D L Region 2, Office of Director MCQUIRK, D R Division of Emergency Preparedness & Materials Safety 83/09/28 1p
20591 037 24X Fiche 50-280, 83/09/28, 8310030294

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310250429 Forwards IE Insp Repts 50-280/83-25 & 50-281/83-25 on 830913-16 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/10/04
STEWART, W L Virginia Electric & Power Co 2pp 20897 023 24X
Fiche 50-280, 83/10/04, 8310250429

--8310250438 IE Insp Repts 50-280/83-25 & 50-281/83-25 on 830913-16 No noncompliance noted Major areas inspected radiological environ monitoring, including mgt & administrative controls & status review of environ monitoring
CUNNINGHAM, A L Region 2, Office of Director MONTGOMERY, D M Division of Engineering & Operational Programs 83/10/05 7pp
20897 023 24X Fiche 50-280, 83/10/04, 8310250429

8310250456 Supplemental response to IE Bulletin 80-16 Upgrading of Unit 1 Rosemount Model 1151 & 1152 pressure transmitters by installation of Type N circuit boards completed on 830927
STEWART, W L Virginia Electric & Power Co 83/10/06 O'REILLY, J P
Region 2, Office of Director 1p 20897 104 24X
Fiche 50-280, 83/10/06, 8310250456

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

R Periodic operating reports & related correspondence

8310190016 Monthly operating repts for Aug 1983 W/830915 ltr
JONES, V , STEWART, W L , SAUNDERS, R Virginia Electric & Power Co 83/09/15 HALLER, N M Office of Resource Management, Director, 42pp 20822 033 24X Fiche 50-280, 83/09/15, 8310190016

DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8310120269 Ack receipt of 830614, 17 & 0728 ltrs forwarding changes to Rev 6 to corporate emergency plan & Rev 3 to plant emergency plan Changes acceptable, per 10CFR50 54(q) requirements
PAPERIELLO, C J Region 3, Office of Director 83/10/06
LARSON, C E Northern States Power Co 1p 20690 34B 24X
Fiche 50-000, 83/10/06, 8310120269

8310310123 Forwards safety evaluation based on util submittals re NUREG-0737, II B 2, "Design Review of Plant Shielding Access to Vital Areas " Requirements met
MILLER, J R Operating Reactors Branch 3 83/10/12 MUDOLF, D M Northern States Power Co 3pp 20965 324 24X
Fiche 50-282, 83/10/12, 8310310123

8310180195 Clarifies NRC position re procedures for admitting NRC insp personnel to facilities Lists identifying NRC personnel requiring escorted & unescorted access to vital plant areas encl Update will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 LARSON, C E Northern States Power Co 7pp 20809 054 24X
Fiche 50-282, 83/10/14, 8310180195

8310250538 Forwards final SALP 4 Rept 50-263/83-17 For Jul 1982 - June 1983
KEPLER, J O Region 3, Office of Director 83/10/20, LARSON, C E Northern States Power Co 7pp 20902 143 24X
Fiche 50-000, 83/10/20, 8310250538

DOCKETED ITEMS

J Insurance & indemnity information

B310250239 Forwards Endorsements 56 & 57 to MAELU Policy MF-51 & Endorsements 68 & 69 to NELIA Policy NF-174 for Monticello & Endorsements 48 & 49 to MAELU Policy MF-68 & Endorsements 56 & 57 to NELIA Policy NF-197 for Prairie Island
JOHNSON, R O Northern States Power Co 83/10/20 DINITZ, I
Division of Engineering 9pp 20899 036 24X Fiche 50-000, 83/10/20, B310250239

P Operating license stage documents & correspondence

B310110498 Forwards safety evaluation re extended fuel burnup reload methodology based on Exron assessment of potential radiological consequences for high exposure fuel
Justification acceptable
MILLER, J R Operating Reactors Branch 3 83/09/27 MUSOLF, D M
Northern States Power Co 2pp 20714 319 24X
Fiche 50-282, 83/09/27, B310110498

--B310110507 Safety evaluation supporting extended fuel burnup reload methodology based on Exron assessment of potential radiological consequences for high exposure fuel
* NRC - No Detailed Affiliation Given 83/09/27 5pp
20714 321 24X Fiche 50-282, 83/09/27, B310110498

B310130072 Forwards Amends 66 & 60 to Licenses DPR-42 & DPR-60, respectively & safety evaluation Amends change limit of core local flux ratio allowing localized linear heat generation rate increase factor for power uncertainty
DIAMNI, D C Operating Reactors Branch 3 83/10/03 MUSOLF, D M
Northern States Power Co 2pp 20776 137 24X
Fiche 50-282, 83/10/03, B310130072

--B310130076 Amends 66 & 60 to Licenses DPR-42 & DPR-60, respectively, changing limit of core local heat flux ratio allowing localized linear heat generation rate increase factor for power uncertainty
MILLER, J R Operating Reactors Branch 3 83/10/03 18pp
20776 139 24X Fiche 50-282, 83/10/03, B310130072

--B310130079 Safety evaluation supporting Amends 66 & 60 to Licenses DPR-42 & DPR-60, respectively
* Office of Nuclear Reactor Regulation, Director 83/10/03 5pp
20776 150 24X Fiche 50-282, 83/10/03, B310130072

B310170329 Notification of B31013 meeting w/util in Bethesda, MD to resolve seven open items in inservice test program for pumps & valves
DIAMNI, D C Operating Reactors Branch 3 83/10/11 MILLER, J R
Operating Reactors Branch 3 2pp 20795 274 24X
Fiche 50-282, 83/10/11, B310170329

Inspection reports, IE Bulletins & correspondence

108300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, B308300340

B308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, B308300342

B308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, B308300345

1308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Bus W/o 10CFR50.39 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, B308300349

310240086 Forwards IE Insp Repts 50-282/83-15 & 50-306/83-15 on B30811-0910 No noncompliance noted
SHAFFER, W D Region 3, Office of Director 83/10/05 LARSON, C E
Northern States Power Co 2pp 20881 318 24X
Fiche 50-282, 83/10/05, B310240086

--B310240102 IE Insp Repts 50-282/83-15 & 50-306/83-15 on B30811-0910 No noncompliance noted Major areas inspected plant operational safety, maint, surveillance, followups of reactor trips.
IE bulletin & LFRs
FEIERABEND, C D, WILLIAMS, D L, JACKIN, I N Region 3, Office of Director 83/10/04 8pp 20881 320 24X Fiche 50-282, 83/10/04, B310240086

B308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, B308300378

B308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, B308300752

B308300759 IE Info Notice 83-67, "Emergency Use Respirator Mail Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, B308300759

B308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, B308300761

B310310173 Forwards safety evaluation & IR notice re B30624 request for relief from ASME Boiler & Pressure Vessel Code concerning inservice insp of reactor coolant pump casing welds Request granted
MILLER, J R Operating Reactors Branch 3 83/10/12 MUSOLF, D M
Northern States Power Co 3pp 20965 278 24X
Fiche 50-282, 83/10/12, B310310173

--B310310176 Safety evaluation granting until B30624 request for relief from ASME Boiler & Pressure Vessel Code concerning inservice insp of reactor coolant pump casing welds
* Office of Nuclear Reactor Regulation, Director 83/10/12 5pp
20965 281 24X Fiche 50-282, 83/10/12, B310310173

--B310310177 Notice of granting of relief from ASME Code Section XI inservice insp requirements
MILLER, J R Operating Reactors Branch 3 83/10/12 2pp
20965 286 24X Fiche 50-282, 83/10/12, B310310173

B310180195 Clarifies NRC position re procedures for admitting NRC insp personnel to facilities Lists identifying NRC personnel requiring escorted & unescorted access to vital plant areas encl Update will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 LARSON, C E
Northern States Power Co 7pp 20809 054 24X
Fiche 50-282, 83/10/14, B310180195

B310250275 Forwards SALP Repts 50-282/83-16 & 50-306/83-17 for Jul 1982 - June 1983
KEPPLER, J O Region 3, Office of Director 83/10/20 LARSON, C E
Northern States Power Co 2pp 20895 292 24X
Fiche 50-282, 83/10/20, B310250275

--B310250278 SALP Repts 50-282/83-16 & 50-306/83-17 for Jul 1982 - June 1983 Overall rating of Category I assigned
* Region 3, Office of Director 83/10/20 24pp 20895 294 24X
Fiche 50-282, 83/10/20, B310250275

--B310250284 Forwards SALP rept for Jul 1982 - June 1983 in preparation for B30921 meeting Written comments may be provided within 20 days following meeting W/o rept
HIND, J A Division of Radiological & Materials Safety Programs 83/09/16 GILBERTS, D E Northern States Power Co 3pp
20895 318 24X Fiche 50-282, 83/10/20, B310250275

--B310250288 Comments on B30921 meeting w/NRC re SALP repts for Jul 1982 - June 1983
GILBERTS, D E Northern States Power Co 83/09/30 KEPPLER, J O
Region 3, Office of Director 1p 20895 321 24X
Fiche 50-282, 83/10/20, B310250275

B310250338 Forwards final SALP 4 Rept 50-263/83-17 for Jul 1982 - June 1983
KEPPLER, J O Region 3, Office of Director 83/10/20 LARSON, C E
Northern States Power Co 2pp 20902 143 24X
Fiche 50-000, 83/10/20, B310250338

DOCKETED ITEMS

99

--B310250561 Submits comments on B30921 meeting w/NRC to discuss SALP Rept 50-263/03-17 for Jul 1982 - June 1983 Valuable insights gained on improving performance
GILBERTS, D E Northern States Power Co B3/09/30 KEPLER, J B
Region 3, Office of Director 1p 2090P 175 24X
Fiche 50-000, B3/10/20, B310250538

R Periodic operating reports & related correspondence

B310190055 Monthly operating repts for Aug 1983 W/B30912 ltr
DUGSTAD, D , MUSOLF, D Northern States Power Co B3/09/02 Office
of Resource Management, Director 9pp 20823 189 24X
Fiche 50-282, B3/09/02, B310190055

S Reportable occurrences, LERs & related correspondence

B310270340 FOIA request for placement of listed LERs in PDR
GRABER, L D NUS Corp B3/09/08 Division of Rules and Records
2pp 20938 058 24X Fiche 50-000, B3/09/08, B310270340

B310190340 Responds to FOIA request for documents re degradation of
fuel assemblies while in spent fuel pool in US nuclear power
plants Forwards App A documents App D documents available in
PDR
FELTON, J M Division of Rules and Records B3/09/15 MAXWELL, B
Rochester Post-Bulletin, Rochester, MN 5pp 20844 058 24X
Fiche 50-282, B3/09/15, B310190340

--B301070386 Informs of preliminary assessment of fuel assembly
degradation observed in spent fuel storage pool & actions
taken to assess failure mechanism & safety implication
potential
WU, P Chemical Engineering Branch B2/12/22 BENAROVA, V
Chemical Engineering Branch 3pp 20844 074 24X
Fiche 50-282, B3/09/15, B310190340

--B304200240 Forwards matl presented by util during B30223 meeting re
fuel assembly failure in spent fuel pool Review establishing
NRC position on listed issues requested Working meeting
scheduled for B30420 Encl withheld
DIANNI, D C Operating Reactors Branch 3 B3/04/08 WU, P NRC -
No Detailed Affiliation Given 2pp 20844 129 24X
Fiche 50-282, B3/09/15, B310190340

--B305050044 Describes plan for review of Northern States Power Co &
Westinghouse submittal on fuel assembly degradation while
in spent fuel storage pool, prompted by fuel assembly
cracking incident at Prairie Island
WU, P Chemical Engineering Branch B3/04/20 BENAROVA, V
Chemical Engineering Branch 2pp 20844 131 24X
Fiche 50-282, B3/09/15, B310190340

--B305240300 Advises of informal preliminary review of potential safety
issues that may exist as result of in-core fuel assembly
nozzle separations Westinghouse analysis indicates no
problem associated w/prevention of control rod insertions
TOMAR, M Core Performance Branch B3/05/16 WU, P Chemical
Engineering Branch 2pp 20844 154 24X Fiche 50-282, B3/09/15,
B310190340

--B308180258 Forwards B30617 SCR re fuel assembly corrosion in spent fuel
pool & draft info notice addressing corrosion problems at
BWRs & PWRs Fuel assembly bulge joint B11216 failure w/o
precedent & w/o determined cause w/o encls
BENAROVA, V Chemical Engineering Branch B3/08/02 HOLAHAN, G
Operating Reactors Assessment Branch 2pp 20844 156 24X
Fiche 50-282, B3/09/15, B310190340

--B310190344 Forwards proposed subjs of discussion for upcoming NRC-
licensee-vendor meeting on spent fuel assembly failure
evaluation Main concern lies in possible generic implication
& licensee/vendor conclusion on failure mechanism
WU, P Chemical Engineering Branch B2/01/17 Chemical
Engineering Branch 4pp 20844 070 24X Fiche 50-282, B3/09/15,
B310190340

--B310190358 Forwards safety evaluation of fuel assembly failure event
during fuel handling in spent fuel pool in Dec 1981 Evidence
insufficient to deduce generic effect
JOHNSTON, W V Assistant Director for Matls, Chem & Environ
Technology (Post B30201) B3/04/20 LAINAS, G C Assistant
Director for Operating Reactors 4pp 20844 133 24X
Fiche 50-282, B3/09/15, B310190340

--B310190360 Safety evaluation concluding that evidence insufficient
to draw generic conclusions from Dec 1981 fuel pool assembly
failure event
* NRC - No Detailed Affiliation Given B3/04/20 17pp
20844 137 24X Fiche 50-282, B3/09/15, B310190340

--B310190361 Safety evaluation of spent fuel assembly degradation Event
was isolated incident No generic implications exist Draft
IE info notice re potential contamination of RCS encl
* NRC - No Detailed Affiliation Given B3/06/17 12pp
20844 160 24X Fiche 50-282, B3/09/15, B310190340

B310120102 LER B3-021/03L-0 on B30830, during Surveillance
Test MV-32035, cooling water header isolation valve B failed
to close Caused by failure of GE auxiliary switch, part
CR105X100P Switch replaced W/B30927 ltr
HUNSTAD, A A , MUSOLF, D Northern States Power Co B3/09/27
Region 3, Office of Director 2pp 20696 223 24X
Fiche 50-282, B3/09/27, B310120102

B310270347 Responds to FOIA request for release of 23 LERs to PDR
Forwards 12 LERs to be released Documents also available in
PDR One LER canceled Eight LERs not received
FELTON, J M Division of Rules and Records B3/09/29 GRABER, L D
NUS Corp 1p 20938 060 24X Fiche 50-000, B3/09/29, B310270347

--B310270415 LER B2-023/03L-0 on B21121, containment pressure sensing line
found capped Caused by personnel error Units will be
labeled W/B31230 ltr
HUNSTAD, A A Northern States Power Co B2/12/21 Region 3,
Office of Director 2pp 20938 083 24X Fiche 50-000, B3/09/29,
B310270347

--B310270418 LER B2-026/03L-0 on B21115, turbine driven auxiliary
feedwater pump 11 failed to deliver full flow of 200 gpm to
steam generators Caused by unsecured governor valve Valve
seat reinstalled & staked in position W/B21215 ltr
HUNSTAD, A A , MUSOLF, D Northern States Power Co B2/12/15
Region 3, Office of Director 2pp 20938 087 24X
Fiche 50-000, B3/09/29, B310270347

--B310270421 LER B3-001/01T-0 on B30204, Exxon ECCS analysis error
discovered Caused by input error into codes W/B30218 ltr
HUNSTAD, A A , MUSOLF, D Northern States Power Co B3/02/18
Region 3, Office of Director 3pp 20938 089 24X
Fiche 50-000, B3/09/29, B310270347

--B310270425 LER B3-007/03L-0 on B30330, steam line radiation monitors
discovered inoperable Monitors repaired & surveillance
procedure revised to include daily check W/B30429 ltr
MUSOLF, D Northern States Power Co B3/04/29 Region 3, Office
of Director 3pp 20938 092 24X Fiche 50-000, B3/09/29,
B310270347

--B310270427 LER B3-011/03L-0 on B30510, diesel generator D2 tripped
Caused by drift in Dryer pressure switch Model 1B22 1
Switch recalibr
HUNSTAD, A A , MUSOLF, D Northern States Power Co B3/03/24
Region 3, Office of Director 3pp 20938 095 24X
Fiche 50-000, B3/09/29, B310270347

B310070301 Potential Part 21 rept re underrange characteristic of
Model N-ELIOM transmitter Underrange zero offset may occur
when transmitter initially pressurized from atmospheric to
suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp B3/09/30 Director's Office, Office
of Inspection and Enforcement 11pp 20631 064 24X
Fiche 50-000, B3/09/30, B310070301

DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B310180242 Forwards IE Insp Rept 50-285/B3-21 on B30815-19 No
noncompliance noted
SEIDLE, W C Region 4, Office of Director B3/09/20 JONES, W C
Omaha Public Power District 2pp 20802 309 24X
Fiche 50-285, B3/09/20, B310180242

--B310180246 IE Insp Rept 50-285/B3-21 on B30815-19 No noncompliance
noted Major areas inspected emergency response program
MONTGOMERY, J L , BAIRD, J D , JOHNSON, W D Region 4, Office of
Director B3/09/15 9pp 20802 311 24X Fiche 50-285, B3/09/20,
B310180242

B310130306 Ack receipt of B30729 ltr informing NRC of util inability
to meet B30630 commitment date for conducting sampling &
analysis drill Alternate post-accident sample analysis
facility must be operational
SEIDLE, W C Region 4, Office of Director B3/09/22 JONES, W C
Omaha Public Power District 2pp 20719 273 24X
Fiche 50-285, B3/09/22, B310130306

DOCKETED ITEMS

- 8310050298 Forwards application for amend to License DPR-40, revising Tech Specs to incorporate administrative changes & NRC requests in Generic Ltrs 82-17 & 82-23 re audit frequency of emergency & security plans Certificate of Svc encl
 MARCOUX, W C LeDoeuf, Lamb, Leiby & MacRae MARCOUX, W C Omaha Public Power District 83/10/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20632 087 24X
 Fiche 50-285, 83/10/03, 8310050298
- 8310050310 Application for amend to License DPR-40, revising Tech Specs to incorporate administrative changes & NRC requests in Generic Ltrs 82-17 & 82-23 re audit frequency of emergency plan, site security plan & safeguards contingency plan
 JONES, W C Omaha Public Power District 83/09/27 2pp 20632 090 24X Fiche 50-285, 83/10/03, 8310050298
- 8310050315 Proposed Tech Specs re pressurizer operability, electrical sys, snubbers, surveillance requirements for RCS, reactor core parameter & environ radiological monitoring & administrative controls
 * Omaha Public Power District 83/09/27 14pp 20632 092 24X
 Fiche 50-285, 83/10/03, 8310050298
- 8310110329 Releases public version of changes to emergency plan implementing procedures
 FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20685 297 24X Fiche 50-285, 83/10/05, 8310110329
- 8310110330 Forwards public version of changes to emergency plan implementing procedures H/O encl
 JONES, W C Omaha Public Power District 83/09/12 COLLINS, J T Region 4, Office of Director 1p 20685 258 24X
 Fiche 50-285, 83/10/05, 8310110329
- 8310130307 Releases public version of revised emergency plan implementing procedures
 FELTON, J M Division of Rules and Records 83/10/06 Document Management Branch 1p 20769 053 24X Fiche 50-285, 83/10/06, 8310130307
- 8310130308 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP-08C-7 re personnel rescue & EPIP-08F-3 re emergency instruments & equipment Receipt form encl
 JONES, W C Omaha Public Power District 83/09/29, COLLINS, J T Region 4, Office of Director 3pp 20769 054 24X
 Fiche 50-285, 83/10/06, 8310130307
- 8310130309 Public version of revised emergency plan implementing procedures, including Procedures EPIP-08C-7 re personnel rescue & EPIP-08F-3 re emergency instruments & equipment
 * Omaha Public Power District 83/09/30 110pp 20769 057 24X
 Fiche 50-285, 83/10/06, 8310130307
- 8310210366 Releases public version of revised emergency plan implementing procedure
 FELTON, J M Division of Rules and Records 83/10/17 Document Management Branch 1p 20882 356 24X Fiche 50-285, 83/10/17, 8310210366
- 8310210370 Public version of Rev 2 to Emergency Plan Implementing Procedure EPIP-08C-7 W/830930 ltr & receipt form
 JONES, W C Omaha Public Power District 83/08/30 COLLINS, J T Region 4, Office of Director 4pp 20882 357 24X
 Fiche 50-285, 83/10/17, 8310210366
- 8310250660 Releases public version of section to radiological emergency response plan
 FELTON, J M Division of Rules and Records 83/10/20 Document Management Branch 1p 20908 221 24X Fiche 50-285, 83/10/20, 8310250660
- 8310250667 Public version of Section M to radiological emergency response plan entitled, "Recovery & Reentry Planning & Post-Accident Operations " W/831010 ltr
 JONES, W C Omaha Public Power District 83/08/31 COLLINS, J T Region 4, Office of Director, 6pp 20908 222 24X
 Fiche 50-285, 83/10/20, 8310250660
1. Operating license stage documents & correspondence
- 8310180405 Authorizes relief, on interim basis, from inservice insp/ testing requirements of ASME Code for pumps & valves, per util 830707 request, BER & notice of granting of relief encl
 MILLER, J R Operating Reactors Branch 3 83/09/30 JONES, W C Omaha Public Power District 3pp 20825 346 24X
 Fiche 50-285, 83/09/30, 8310180405
- 8310180408 Safety evaluation granting relief from ASME Boiler & Pressure Vessel Code, Section XI insp/testing requirements for pumps & valves
 * Office of Nuclear Reactor Regulation, Director 83/09/30 4pp 20825 349 24X Fiche 50-285, 83/09/30, 8310180405
- 8310180410 Notice of granting of relief from certain ASME Code insp/testing requirements for pumps & valves
 MILLER, J R Operating Reactors Branch 3 83/09/30 2pp 20825 353 24X Fiche 50-285, 83/09/30, 8310180405
- 8310310129 Forwards safety evaluation based on review of util responses to NUREG-0737 items Requirements of NUREG-0737, item II K 3 2 met
 MILLER, J R Operating Reactors Branch 3 83/09/30 JONES, W C Omaha Public Power District 14pp 21000 079 24X
 Fiche 50-285, 83/09/30, 8310310129
- 8310050245 Forwards application for amend to License DPR-40 revising Tech Spec Table 2-6(a) & 3-7 to update surveillance capsule removal schedule Certificate of Svc encl
 * LeDoeuf, Lamb, Leiby & MacRae 83/10/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20628 270 24X
 Fiche 50-285, 83/10/03, 8310050245
- 8310050255 Application for amend to License DPR-40 revising Tech Spec Tables 2-6(a) & 3-7 to update surveillance capsule removal schedule
 JONES, W C Omaha Public Power District 83/10/03 2pp 20628 273 24X Fiche 50-285, 83/10/03, 8310050245
- 8310050271 Proposed changes to Tech Spec Tables 2-6(a) & 3-7 to update surveillance capsule removal schedule
 * Omaha Public Power District 83/10/03 11p 20628 275 24X
 Fiche 50-285, 83/10/03, 8310050245
- 8310050298 Forwards application for amend to License DPR-40, revising Tech Specs to incorporate administrative changes & NRC requests in Generic Ltrs 82-17 & 82-23 re audit frequency of emergency & security plans Certificate of Svc encl
 MARCOUX, W C LeDoeuf, Lamb, Leiby & MacRae MARCOUX, W C Omaha Public Power District 83/10/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20632 087 24X
 Fiche 50-285, 83/10/03, 8310050298
- 8310050310 Application for amend to License DPR-40, revising Tech Specs to incorporate administrative changes & NRC requests in Generic Ltrs 82-17 & 82-23 re audit frequency of emergency plan, site security plan & safeguards contingency plan
 JONES, W C Omaha Public Power District 83/09/27 2pp 20632 090 24X Fiche 50-285, 83/10/03, 8310050298
- 8310050315 Proposed Tech Specs re pressurizer operability, electrical sys, snubbers, surveillance requirements for RCS, reactor core parameter & environ radiological monitoring & administrative controls
 * Omaha Public Power District 83/09/27 14pp 20632 092 24X
 Fiche 50-285, 83/10/03, 8310050298
- 8310130137 Approves 830731 request on behalf of C-E Owners Group for withholding from public disclosure App A to "Response to Questions on RCS Asymmetric Loads Evaluation Program," per 10CFR2 790
 CRUTCHFIELD, D Operating Reactors Branch 5 83/10/03 LUNDVALL, A E Baltimore Gas & Electric Co 6pp 20777 065 24X
 Fiche 50-000, 83/10/03, 8310130137
- 8310130061 Notification of 831012-13 meetings w/util in Omaha, NE to discuss proposed radiological effluent Tech Specs & to resolve open items
 TEVRIGNY, E G Operating Reactors Branch 3 83/10/05 MILLER, J R Operating Reactors Branch 3 2pp 20776 218 24X
 Fiche 50-285, 83/10/05, 8310130061
- 8310280087 Forwards safety evaluation re review of util submittal addressing NUREG-0737, item II K P 17, "Voiding in RCS During Anticipated Transients " Steam void will not result in unacceptable consequences
 MILLER, J R Operating Reactors Branch 3 83/10/17 JONES, W C Omaha Public Power District 9pp 20961 349 24X
 Fiche 50-285, 83/10/17, 8310280087
- 0 Inspection reports, IE Bulletins & correspondence
- 8310130168 Forwards IE Insp Rept 50-285/83-1B on 830701-29 No noncompliance noted
 SEIDLE, W C Region 4, Office of Director 83/08/10 JONES, W C Omaha Public Power District 2pp 20724, 284 24X
 Fiche 50-285, 83/08/10, 8310130168

DOCKETED ITEMS

101

--8310130171 IE Insp Rept 50-285/83-18 on 830701-29 No noncompliance noted Major areas inspected operational safety verification, surveillance testing, maint activitier & followup of violations
YANDELL, L A , JOHNSON, W D Region 4, Office of Director
83/08/08 5pp 20724 286 24X Fiche 50-285, 83/08/10, 8310130168

8310040567 Forwards IE Insp Rept 50-285/83-17 on 830627-0701 & notice of violation
SEIDLE, W C Region 4, Office of Director 83/08/19 JONL, W C
Omaha Public Power District 2pp 20622 257 24X
Fiche 50-285, 83/08/19, 8310040567

--8310040571 Notice of violation from insp on 830627-0701
* Region 4, Office of Director 83/08/19 1p 20622 259 24X
Fiche 50-285, 83/08/19, 8310040567

--8310040577 IC Insp Rept 50-285/83-17 on 830627-0701 Noncompliance noted failure to take prompt corrective action re deficiencies in program for mgmt of const records (including design & mfg records)
BOARDMAN, J R , GROSSMAN, W A , JOHNSON, W D Region 4, Office of Director 83/08/17 10pp 20622 260 24X Fiche 50-285, 83/08/19, 8310040567

8310130292 Forwards IE Insp Rept 50-285/83-19 on 830801-05 No noncompliance noted
SEIDLE, W C Region 4, Office of Director 83/08/22 JONL, W C
Omaha Public Power District 2pp 20719 335 24X
Fiche 50-285, 83/08/22, 8310130292

--8310130295 IE Insp Rept 50-285/83-19 on 830801-05 No noncompliance noted Major areas inspected action on previous insp findings, onsite committee, program for calibr & surveillance & implementation of calibr program
JAUDON, J P , JOHNSON, W D Region 4, Office of Director 83/08/19 6pp 20719 337 24X Fiche 50-285, 83/08/22, 8310130297

8310180242 Forwards IE Insp Rept 50-285/83-21 on 830815-19 No noncompliance noted
SEIDLE, W C Region 4, Office of Director 83/09/20 JONL, W C
Omaha Public Power District 2pp 20802 309 24X
Fiche 50-285, 83/09/20, 8310180242

--8310180246 IC Insp Rept 50-285/83-21 on 830815-19 No noncompliance noted Major areas inspected emergency response program
MONTGOMERY, J L , BAIRD, J B , JOHNSON, W D Region 4, Office of Director 83/09/15 9pp 20802 311 24X Fiche 50-285, 83/09/20, 8310180242

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IC Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310210008 Forwards "Omaha Power District, Fort Calhoun Station, Unit 1 Inservice Insp Program Plan for 1983-73 Interval " Plan will be placed into effect on 830726
JONES, W C Omaha Public Power District 83/09/26 MILLER, J R
Operating Reactors Branch 3 1p 20854 336 24X
Fiche 50-285, 83/09/26, 8310210008

--8310210013 "Omaha Public Power District, Fort Calhoun Station, Unit 1 Inservice Insp Program Plan for 1983-73 Interval "
* Southwest Research Institute 83/08/30 120pp 20854 337 24X Fiche 50-285, 83/09/26, 8310210008

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o ICFRHS 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310180405 Authorizes relief, on interim basis, from inservice insp/testing requirements of ASME Code for pumps & valves, per until 830707 request SER & notice of granting of relief encl
MILLER, J R Operating Reactors Branch 3 83/09/30 JONES, W C
Omaha Public Power District 3pp 20825 346 24X
Fiche 50-285, 83/09/30, 8310180405

--8310180408 Safety evaluation granting relief from ASME Boiler & Pressure Vessel Code, Section XI insp/testing requirements for pumps & valves
* Office of Nuclear Reactor Regulation, Director 83/09/30 4pp 20825 349 24X Fiche 50-285, 83/09/30, 8310180405

--8310180410 Notice of granting of relief from certain ASME Code insp/testing requirements for pumps & valves
MILLER, J R Operating Reactors Branch 3 83/09/30 2pp 20825 353 24X Fiche 50-285, 83/09/30, 8310180405

8310120094 Forwards Class III payment for approval of relief requests from ASME Boiler & Pressure Code, Section XI inservice insp requirements
JONES, W C Omaha Public Power District 83/10/05 MILLER, J R
Operating Reactors Branch 3 2pp 20696 185 24X
Fiche 50-285, 83/10/05, 8310120094

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180500 Ack receipt of 830919 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/83-17
OAGLIARDO, J E Region 4, Office of Director 83/10/13 JONES, W C
Omaha Public Power District 1p 20801 189 24X
Fiche 50-285, 83/10/13, 8310180500

--8310180506 Responds to NRC 830819 ltr re violations noted in IF Insp Rept 50-285/83-17 Corrective actions const mods to correct deficiencies re QA records file room completed on 830723 & recordkeeping improved Schedules provided
JONES, W C Omaha Public Power District 83/09/19 SEIDLE, W C
Region 4, Office of Director 6pp 20801 190 24X
Fiche 50-285, 83/10/13, 8310180500

R Periodic operating reports & related correspondence

8310180162 Monthly operating rept for Sept 1983 W/831013 ltr
MATTHEWS, T P , JONES, W C Omaha Public Power District 83/09/30
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 10pp 20809 137 24X Fiche 50-285, 83/09/30, 8310180162

S Reportable occurrences, LERs & related correspondence

8310070301 Potential Part 21 rept re underrange characteristic of Model N-E110M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X
Fiche 50-000, 83/09/30, 8310070301

DOCKETED ITEMS

DOCKET 50-286 INDIAN POINT STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8310050548 Forwards post-exercise/post-drill assessments, per JS Bragg
830608 commitment Previously noted deficiencies corrected
MCLOUGHLIN, D Federal Emergency Management Agency 83/09/29
DIRCKS, W J Office of the Executive Director for Operations 2pp
20629 267 24X Fiche 50-003, 83/09/29, 8310050548

--8310050552 Post-exercise assessment of 830824-25 exercise, Rockland
County, for Indian Point Nuclear Power Station
* Federal Emergency Management Agency 83/09/26 56pp
20629 269 24X Fiche 50-003, 83/09/29, 8310050548

--8310050554 Post-drill assessment of 830823 drill of Westchester County
bus evacuation procedures for Indian Point Nuclear Power
Station
* Federal Emergency Management Agency 83/09/15 9pp
20629 328 24X Fiche 50-003, 83/09/29, 8310050548

8310130305 Forwards FEMA 830929 ltr transmitting FEMA Region II
post-exercise assessment of 830824 exercise of State of NY
radiological emergency response interim plan for
implementing compensating measures for Rockland County
HASSELL, D F Hearing Branch I 83/10/04 OLEASON, Q P Atomic
Safety and Licensing Board Panel 1p 20719 204 24X
Fiche 50-247, 83/10/04, 8310130305

8310140195 Ack receipt of 830722 ltr re corrective actions taken in
response to 830822 ltr re IE Insp Rept 50-286/83-12
Corrective actions will be withheld (ref 10CFR73.21)
HARTIN, T T Division of Engineering & Technical Programs 83/10/04
BRONIS, J C Power Authority of the State of New York 2pp
20762 331 24X Fiche 50-286, 83/10/04, 8310140195

8310170321 Staff requirements memo re Commission 831003 briefing by
FEMA on recent emergency planning exercises in vicinity of
facilities Commission noted successful completion of
exercise Enforcement action unnecessary
CHILK, S J Office of the Secretary of the Commission 83/10/11
Office of the Secretary of the Commission 1p 20779 277 24X
Fiche 50-247, 83/10/11, 8310170321

8310240155 Forwards implementation schedule for security plan, per
830727 request Procedural portion implemented, effective
830501 NUS study re hardware portion expected 831130
Schedule for remaining hardware items expected by 840331
BAYNE, J P Power Authority of the State of New York 83/10/19
VARQA, S A Operating Reactors Branch I 2pp 20681 221 24X
Fiche 50-286, 83/10/19, 8310240155

Adjudicatory correspondence

8310130305 Forwards FEMA 830929 ltr transmitting FEMA Region II
post-exercise assessment of 830824 exercise of State of NY
radiological emergency response interim plan for
implementing compensating measures for Rockland County
HASSELL, D F Hearing Branch I 83/10/04 OLEASON, Q P
PARRIS, D H, SHON, F J Atomic Safety and Licensing Board Panel 1p
20719 204 24X Fiche 50-247, 83/10/04, 8310130305

831080145 Advises that SM Bohinski & JF Meyer employed as legal &
technical assistants, respectively Bohinski & Meyer under
recusal re Indian Point special proceeding due to previous
employment contact
BERNTHAL, F Commissioners 83/10/17 Atomic Safety and Licensing
Board Panel 1p 20809 149 24X Fiche 50-247, 83/10/17, 831080145

831090085 Order advising that ASLB expects to issue recommendations to
Commission by 831024
OLEASON, J P Atomic Safety and Licensing Board Panel 83/10/17
1p 20822 267 24X Fiche 50-247, 83/10/17, 831090085

8310240187 Forwards RH Bogardus 830920 ltr re adequacy of radiological
emergency response plan
HERBEK, R F New York, State of 83/10/17 NRC - No Detailed
Affiliation Given 3pp 20878 089 24X Fiche 50-247, 83/10/17,
8310240187

8310260224 Opinion & recommendations to Commission on societal
significance of risk estimates ASLB recommended safety
improvements necessary to ensure plant will be operated
//reasonable assurance that public safety will be protected
MON, F J, PARRIS, D H, OLEASON, J P Atomic Safety and Licensing
Board Panel 83/10/24 306pp 20913 033 24X
Fiche 50-247, 83/10/24, 8310260224

P Operating license stage documents & correspondence

8310310017 FOIA request for documents re integrated leak rate tests for
listed facilities to be placed in PDR
CONNER, L Affiliation Unknown 83/05/02 NRC - No Detailed
Affiliation Given 1p 21004 210 24X Fiche 50-000, 83/05/02,
8310310017

8310030663 Forwards evaluation of & current NRC guidelines for 83061/
process control program Final program within 30 days
requested Final radiological effluent tech Specs due 60 day,
from 870802
VARQA, S A Operating Reactors Branch I 83/09/19 BAYNE, J P
Power Authority of the State of New York 15pp 20626 371 24X
Fiche 50-286, 83/09/19, 8310030663

8310040035 Forwards safety evaluation of licensee responses to
requirements of NUREG-0737, Item II B 1, "RCS Vents " Item
completed ILL technical evaluation rept encl
VARQA, S A Operating Reactors Branch I 83/09/19 BAYNE, J P
Power Authority of the State of New York 9pp 20634 371 24X
Fiche 50-286, 83/09/19, 8310040035

--8306030372 "Selected Operating Reactor Issues Program II RCS Vents
(NUREG-0737, Item II B 1)," final technical evaluation rpt
HELD, J I Energy Incorporated * Lawrence Livermore Laboratory
FIN A-0250 TR-324/0806A 83/02/14 ALBERTHAL, G Division of
Licensing 6pp 20634 330 24X Fiche 50-286, 83/09/19, 8310040035

8310130041 Summary of 830817 meeting w/util in Bethesda, MD re suc
interaction program Util advised that mgt level meeting
should be expected in near future
POLK, P J Operating Reactors Branch I 83/09/29 Operating
Reactors Branch I 11pp 20776 242 24X Fiche 50-286, 83/09/29,
8310130041

8310070340 Forwards Suppl 1 to plant-specific evaluation of LPR1 safety
& relief valve performance testing submitted on 821215
Suppl details adequacy of inlet & discharge piping for
pressurizer safety & relief valves per TMI Item II D 1
BAYNE, J P Power Authority of the State of New York 83/09/30
VARQA, S A Operating Reactors Branch I 8pp 20652 157 24X
Fiche 50-286, 83/09/30, 8310070340

8310070349 Forwards payment of fees for 830503 & 0601 applications
for amends to License DPR-64 Payment made under protest
pending final determination of locality of fee schedule
BAYNE, J P Power Authority of the State of New York 83/09/30
MILLER, W D License Fee Management Branch 2pp 20651 077 24X
Fiche 50-286, 83/09/30, 8310070349

8310110222 Forwards application for amend to License DPR-64, changing
radiological ETS Sections 4.5.6 D, 6.9 & 6.10 to reflect
draft Rev 3 to NUREG-0472, in response to NRC 820907 ltr
BAYNE, J P Power Authority of the State of New York 83/09/30
VARQA, S A Operating Reactors Branch I 2pp 20669 138 24X
Fiche 50-286, 83/09/30, 8310110222

--8310110228 Application for amend to License DPR-64, changing
radiological ETS Sections 4.5.6 D, 6.9 & 6.10 to reflect
draft Rev 3 to NUREG-0472, in response to NRC 820907 ltr
BAYNE, J P Power Authority of the State of New York 83/09/30
9pp 20669 140 24X Fiche 50-286, 83/09/30, 8310110222

--8310110231 Proposed Tech Spec changes revising Sections 4.5.6 D,
& 9 & 6.10 to reflect draft Rev 3 to NUREG-0472
* Power Authority of the State of New York 83/09/30 96pp
20669 149 24X Fiche 50-286, 83/09/30, 8310110231

8310170200 Requests site visit be scheduled for 831101 03 to review w/
interaction study Lists personnel necessary for productive
visit
VARQA, S A Operating Reactors Branch I 83/09/30 BAYNE, J P
Power Authority of the State of New York 31pp 20812 309 24X
Fiche 50-286, 83/09/30, 8310170200

8308300763 Board Notification 83-151 provides info re desirability of
current ECS actuation logic for Westinghouse plants, in
light of recent info concerning steam generator tube rupture
procedure for Borssele Nuclear Power Station
EISENHUT, D G Division of Licensing 83/10/04 PALLADINO, N J,
GILINSKY, V, ROBERTS, T Commissioners 2pp 20698 073 24X
Fiche 50-000, 83/10/04, 8308300763

8308300771 Board Notification 83-178A forwards Equipment Qualification
Branch conclusions re potential problems w/ASCO solenoid
valves
EISENHUT, D G Division of Licensing 83/10/06 PALLADINO, N J
Commissioners 31pp 20918 001 24X Fiche 50-000, 83/10/06,
8308300771

DOCKETED ITEMS

103

8310170554 Confirms telcon agreement re submittal of final rev to snubber surveillance Tech Specs by 831209
BAYNE, J P Power Authority of the State of New York 83/10/0/
VARGA, S A Operating Reactors Branch 1 2pp 20760 211 24X
Fiche 50-286, 83/10/07, 8310170554

8310240114 Forwards revised sections to GA program in response to NRC 800923 questions Revised portions will be incorporated into 1984 annual FSAR update
BAYNE, J P Power Authority of the State of New York 83/10/1/
VARGA, S A Operating Reactors Branch 1 3Bpp 20881 102 24X
Fiche 50-286, 83/10/19, 8310240114

8310310066 Responds to 830819 request for addl info re NUREG-0/37, Item 11 B.3. "Post-Accident Sampling Sys," providing supplemental info concerning two of four open criteria & schedule for responding to remaining requests
BAYNE, J P Power Authority of the State of New York 83/10/26
VARGA, S A Operating Reactors Branch 1 8pp 20951 032 24X
Fiche 50-286, 83/10/26, 8310310066

0 Inspection reports, IE Bulletins & correspondence

8310120198 Forwards IE Insp Rept 90-286/83-16 on 830816-0915 Nu noncompliance noted
STARDSTICK, R Division of Project & Resident Programs 07/09/20
BRONS, J C Power Authority of the State of New York 2pp
20695 335 24X Fiche 50-286, 83/09/20, 8310120198

--8310120197 IE Insp Rept 50-286/83-16 on 830816-0915 No noncompliance noted Major areas inspected maint review of monthly operating rept, IMI task action plan status, licensee actions on previous insp findings, plant tour & surveillance
KENNY, T J, ROSSBACH, L W, MORRIS, L Region I, Office of Director 83/09/19 12pp 20695 337 24X Fiche 50-286, 83/09/20, 8310120197

8310110465 Forwards safety evaluation & technical evaluation rept re completion of IE Bulletin 80-11, "Masonry Wall Design " All work associated w/subj bulletin completed
VARGA, S A Operating Reactors Branch 1 83/09/23 BAYNE, J P
Power Authority of the State of New York 3pp 20712 238 24X
Fiche 50-286, 83/09/23, 8310110465

--8309160203 "Masonry Wall Design (D-59), Indian Point Nuclear Power Plant, Unit 3," technical evaluation rept
TRIGLOD, S Franklin Institute/Franklin Research Center
NRC-03-B1-130 TER-C5506-241 83/09/14 CHOKSHI, N C NRC No Detailed Affiliation Given 23pp 20712 241 24X
Fiche 50-286, 83/09/23, 8310110465

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310140195 Ack receipt of 830722 ltr re corrective actions taken in response to 830622 ltr re IE Insp Rept 50-286/83-12
Corrective actions will be withheld (ref 10CFR73 21)
MARTIN, T J Division of Engineering & Technical Programs 83/10/04
BRONS, J C Power Authority of the State of New York 2pp
20762 331 24X Fiche 50-286, 83/10/04, 8310140195

8308300378 IE Info Notice 83-65, "Surveillance of Flow in R1D Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07, Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

R Periodic operating reports & related correspondence

8310190202 Monthly operating rept for Aug 1983 W/830909 ltr
KELLEY, L, BRONS, J C Power Authority of the State of New York 83/09/01 Office of Resource Management, Director 7pp
20818 104 24X Fiche 50-286, 83/09/01, 8310190202

8310170603 Monthly operating rept for Sept 1983 W/831007 ltr
KELLEY, L, BRONS, J C Power Authority of the State of New York 83/10/01 Director's Office, Office of Inspection and Enforcement 7pp 20782 098 24X Fiche 50-286, 83/10/01, 8310170603

S Reportable occurrences, LERs & related correspondence

8310070301 Potential Part 21 rept re underrange characteristic of Model N-E110M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERDERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20691 064 24X
Fiche 50-000, 83/09/30, 8310070301

8310140082 PNO-I-83-105 on 831007, seismic event occurred in northeastern US w/magnitude of 5.2 on Richter scale in NY & 4.0 in NJ No damage to equipment identified
GALLO, R H Region I, Office of Director 83/10/07 1p 20766 116
24X Fiche 50-000, 83/10/07, 8310140082

T Hearing transcripts on non-antitrust matters

8310120029 Transcript of 831003 open session in Washington, DC re emergency planning Pp i-28 Supporting documentation encl
Commissioners 83/10/03 111pp 20750 076 24X
Fiche 50-003, 83/10/03, 8310120029

V Operator Examinations

8310070248 Requests scheduler exemption from NRC rulemaking re licensed operator staffing until 840331 Exemption would allow persons scheduled for exam in Dec 1983 to complete testing & become qualified to stand watch
BAYNE, J P Power Authority of the State of New York 83/09/30
VARGA, S A Operating Reactors Branch 1 1p 20659 127 24X
Fiche 50-286, 83/09/30, 8310070248

DOCKET 50-287 OCONEE NUCLEAR STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8310070134 Releases public version of revised crisis mgt plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/04 Document Management Branch 1p 20670 001 24X Fiche 50-000, 83/10/04, 8310070134

--8310070143 Forwards public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.1 re recovery manager & immediate staff group plan & 5.3.4 re scheduling/planning support group
TUCKER, H D Duke Power Co 83/07/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20670 002 24X
Fiche 50-000, 83/10/04, 8310070134

--8310070152 Public version of revised crisis mgt plan implementing procedures, including Procedure 5.3.1 re recovery manager & immediate staff group plan & 5.3.4 re scheduling/planning support group
* Duke Power Co 83/07/01 457pp 20670 005 24X
Fiche 50-000, 83/10/04, 8310070134

DOCKETED ITEMS

- 8310110067 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/05 Document
Management Branch 1p 20709 160 24X Fiche 50-269, 83/10/05, 8310110067
- 8310110076 Forwards public version of revised emergency plan implementing procedures, including Procedure CP/B/4803/01 re environ surveillance following large unplanned release of gaseous radioactivity Receipt form encl
TUCKER, H B, MCINTOSH, J T Duke Power Co 83/09/19
O'REILLY, J P Region 2, Office of Director 2pp 20709 161 24X
Fiche 50-269, 83/10/05, 8310110067
- 8310110080 Public version of revised emergency plan implementing procedures, including Procedure CP/D/B/4003/01 re environ surveillance following large unplanned release of gaseous radioactivity
SMITH, J E Duke Power Co 83/09/08 50pp 20709 163 24X
Fiche 50-269, 83/10/05, 8310110067
- 8310110135 Releases public version of rev to emergency procedure
FELTON, J M Division of Rules and Records 83/10/05 Document
Management Branch 1p 20707 319 24X Fiche 50-269, 83/10/05, 8310110135
- 8310110141 Public version of Rev 83-5 to Emergency Procedure AP/D/B/1000/07, "Procedure for Offsite Dose Calculation by Control Room Personnel on Emergency Coordinator During Radiological Accident" W/B30930 ltr
SMITH, J E, TUCKER, H B, MCINTOSH, J T Duke Power Co 83/07/22
O'REILLY, J P Region 2, Office of Director 19pp 20707 320 24X Fiche 50-269, 83/10/05, 8310110135
- 8310250354 Forwards IE Insp Repts 50-269/83-27, 50-270/83-27 & 50-287/83-27 on 830912-16 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/10/05
TUCKER, H B Duke Power Co 2pp 20898 123 24X
Fiche 50-269, 83/10/05, 8310250354
- 8310250363 IE Insp Repts 50-269/83-27, 50-270/83-27 & 50-287/83-27 on 830912-16 No noncompliance noted Major areas inspected emergency detection & classification, protective action decisionmaking, public info program & shift staffing
DECKER, T R Region 2, Office of Director 83/09/30 5pp
20898 125 24X Fiche 50-269, 83/10/05, 8310250354
- 8310180444 Responds to request for crisis mgt ctr staff to participate in emergency exercises at same frequency as technical support ctr staff Crisis mgt team will be activated in full-scale exercise involving full state participation
TUCKER, H B Duke Power Co 83/10/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 20802 121 24X
Fiche 50-000, 83/10/10, 8310180444
- 8310250635 Informs that periodic evaluation of BALP complete Rept approved
O'REILLY, J P Region 2, Office of Director 83/10/17 TUCKER, H B
Duke Power Co 2pp 20900 205 24X Fiche 50-000, 83/10/17, 8310250635
- 8310250652 BALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983
* Region 2, Office of Director 83/08/02 56pp 20900 211 24X
Fiche 50-000, 83/10/17, 8310250635
- 8310280029 Forwards request for exemption from fire protection requirements of 10CFR50, App R, Section III J re emergency lighting in control room, stairwells/corridors, outside auxiliary bldg & standby shutdown facility
TUCKER, H B Duke Power Co 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director STULZ, J F Operating Reactors Branch 4 4pp 20934 285 24X Fiche 50-269, 83/10/24, 8310280029
- 8310280124 Suppls 830603 ltr re exemption request from location requirements of emergency operations facility Significant benefits not achieved by near-site facility up to 20 miles from plant Meeting w/NRC requested
TUCKER, H B Duke Power Co 83/10/25 DENTON, H R Office of Nuclear Reactor Regulation, Director STULZ, J F Operating Reactors Branch 4 2pp 20929 266 24X Fiche 50-269, 83/10/25, 8310280124
- O Adjudicatory correspondence
- 8310130164 Forwards status rept on hybrid hearing procedures under Section 134 of Nuclear Waste Policy Act Proposed rule on implementation of procedures awaits Commission action
CUNNINGHAM, O H Office of the Executive Legal Director 83/10/07
REHM, T A Office of the Executive Director for Operations 2pp 20724 291 24X Fiche 50-000, 83/10/07, 8310130164
- P Operating license stage documents & correspondence
- 8310040111 Responds to 830531 & 0826 ltr requesting amend to 83018 confirmatory order re NUREG-0137, Item 11 F 1 5, "Containment Water Level Monitor" Amend not required Environ qualification will be addressed in 10CFR50.49 audit
STULZ, J F Operating Reactors Branch 4 83/09/02 TUCKER, H B
Duke Power Co 5pp 20627 351 24X Fiche 50-269, 83/09/02, 8310040111
- 8310040647 Forwards GER accepting Arkansas Power & Light Co (APL) 830607 proposed mods to reactor trip breakers for B&W plants Requested info should be provided when APL generic design endorsed in response to Generic Ltr 83-28
STULZ, J F Operating Reactors Branch 4 83/09/12 TUCKER, H B
Duke Power Co 2pp 20627 307 24X Fiche 50-269, 83/09/12, 8310040647
- 8310110545 Forwards Amends 123, 123, & 120 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & LIA Amends allow increase in spent fuel storage capacity from 474 to max of 825 fuel assemblies in Unit 3 spent fuel pool
STULZ, J F Operating Reactors Branch 4 83/09/29 TUCKER, H B
Duke Power Co 2pp 20711 263 24X Fiche 50-269, 83/09/29, 8310110545
- 8310110561 Amends 123, 123 & 120 to Licenses DPR-38, DPR-47 & DPR-55, respectively, changing Tech Specs to allow increase in spent fuel storage capacity from 474 to max of 825 fuel assemblies in Unit 3 spent fuel pool
STULZ, J F Operating Reactors Branch 4 83/09/29 11pp
20711 267 24X Fiche 50-269, 83/09/29, 8310110545
- 8310110569 Safety evaluation supporting Amends 123, 123 & 120 to Licenses DPR-38, DPR-47 & DPR-55, respectively
* Office of Nuclear Reactor Regulation, Director 83/09/29 14pp 20711 270 24X Fiche 50-269, 83/09/29, 8310110545
- 8310110575 EIA supporting Amends 123, 123 & 120 to Licenses DPR-38, DPR-47 & DPR-55, respectively
* Office of Nuclear Reactor Regulation, Director 83/09/29 10pp 20711 292 24X Fiche 50-269, 83/09/29, 8310110545
- 8310140253 Forwards info re inservice pump & valve testing program w/o encl
TUCKER, H B Duke Power Co 83/10/10 DENTON, H R Office of Nuclear Reactor Regulation, Director STULZ, J F Operating Reactors Branch 4 1p 20761 332 24X Fiche 50-269, 83/10/10, 8310140253
- 8310240151 Forwards steam generator operating history info valid through 831231
TUCKER, H B Duke Power Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director STULZ, J F Operating Reactors Branch 4 4pp 20881 176 24X Fiche 50-269, 83/10/13, 8310240151
- 8310310489 Summary of 830826 meeting w/B&W Owners Group re implementation of Generic Ltr 83-28 concerning defenses against ATWS & proposed ATWS rule for B&W plants List of attendees & viewpoints encl
KADAMB, P Operating Reactors Branch 4 83/10/20
Operating Reactors Branch 4 13pp 20765 147 24X Fiche 50-000, 83/10/20, 8310310489
- 8310280105 Forwards update of progress of control room habitability mods, per 830929 ltr re TMI Item III D 3 4 HVAC equipment operating at approx 2/3 design capacity Updated work list & schedule encl
TUCKER, H B Duke Power Co 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director STULZ, J F Operating Reactors Branch 4 2pp 20935 324 24X Fiche 50-269, 83/10/24, 8310280105
- Q Inspection reports, IE Bulletins & correspondence
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345
- 8310040290 Forwards IE Insp Repts 50-269/83-24, 50-270/83-24 & 50-287/83-24 on 830725-0803 No noncompliance noted Major areas inspected containment integrated leakage rate testing & followup on previous items
DANCE, H C Division of Project & Resident Programs 83/08/10
TUCKER, H B Duke Power Co 2pp 20617 268 24X
Fiche 50-269, 83/08/30, 8310040290
- 8310040294 IE Insp Repts 50-269/83-24, 50-270/83-24 & 50-287/83-24 on 830725-0803 No noncompliance noted Major areas inspected containment integrated leakage rate testing & followup on previous items
BRADOKS, E H Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs 83/08/26 4pp 20617, 270 24X Fiche 50-269, 83/08/30, 8310040290

DOCKETED ITEMS

105

8310040375 Responds to IE Bulletin 83-05, "ASME Nuclear Code Pump & Spare Parts Mfg by Hayward Tyler Pump Co." One Hayward Tyler pump currently installed in Unit 1 & 2 spent fuel cooling sys. Twelve pumps to be installed in radwaste facility. TUCKER, H B Duke Power Co 03/09/08 O'REILLY, J P Region 2, Office of Director 5pp 20622 278 24X Fiche 50-269, 83/09/08, 8310040375

8310040247 Forwards IE Insp Repts 50-269/83-25, 50-270/83-25 & 50-287/83-25 on 830809-11 No noncompliance noted. DANCE, H C Division of Project & Resident Programs 07/09/07 TUCKER, H B Duke Power Co 2pp 20613 194 24X Fiche 50-269, 83/09/09, 8310040247

--8310040253 IE Insp Repts 50-269/83-25, 50-270/83-25 & 50-287/83-25 on 830809-11 No noncompliance noted. Major areas inspected zero power physics testing & power escalation testing. DAVENPORT, K L Region 2, Office of Director JAPC, F Division of Engineering & Operational Programs 03/09/07 5pp 20613 194 24X Fiche 50-269, 83/09/09, 8310040247

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests." Svc list encl. JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 03/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes." Svc list encl. JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 03/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8310290248 Forwards IE Insp Rept 50-269/83-28, 50-270/83-28 & 50-287/83-28 on 830811-0910 No noncompliance noted. DANCE, H C Division of Project & Resident Programs 03/09/27 TUCKER, H B Duke Power Co 1p 20679 074 24X Fiche 50-269, 83/09/27, 8310290248

--8310290256 IE Insp Repts 50-269/83-28, 50-270/83-28 & 50-287/83-28 on 830811-0910 No noncompliance noted. Major areas inspected operations, joint surveillance, training & NUREG-O/J7 items. BRYANT, J J, FALLONER, D Region 2, Office of Director BROWNLEE, V Division of Project & Resident Programs 03/09/27 10pp 20099 075 24X Fiche 50-269, 83/09/27, 8310290248

8310040484 Ack receipt of 830917 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-269/83-26. DANCE, H C Division of Project & Resident Programs 03/09/28 TUCKER, H B Duke Power Co 1p 20625 170 24X Fiche 50-269, 83/09/28, 8310040484

--8310040492 Responds to NRC 830824 ltr re violations noted in IE Insp Repts 50-269/83-26, 50-270/83-26 & 50-287/83-26. Corrective actions recirculation & release procedures revised to verify sign off for closing valves. TUCKER, H B Duke Power Co 03/09/19 O'REILLY, J P Region 2, Office of Director 2pp 20625 171 24X Fiche 50-269, 83/09/28, 8310040484

--8310040495 Forwards IE Insp Repts 50-269/83-26, 50-270/83-26 & 50-287/83-26 on 830711-0810 & notice of violation. DANCE, H C Division of Project & Resident Programs 03/09/24 TUCKER, H B Duke Power Co 2pp 20625 173 24X Fiche 50-269, 83/09/28, 8310040484

--8310040507 IE Insp Repts 50-269/83-26, 50-270/83-26 & 50-287/83-26 on 830711-0810 Noncompliance noted failure to follow chemistry procedure resulting in unplanned release of radioactive water. BRYANT, J J, FALLONER, D Region 2, Office of Director BROWNLEE, V Division of Project & Resident Programs 03/08/23 7pp 20625 176 24X Fiche 50-269, 83/09/28, 8310040484

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o ICRN 59 Evaluation." Svc list encl. JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 03/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310250354 Forwards IE Insp Repts 50-269/83-27, 50-270/83-27 & 50-287/83-27 on 830912-16 No noncompliance noted. DANCE, H C Division of Project & Resident Programs 03/10/05 TUCKER, H B Duke Power Co 2pp 20448 123 24X Fiche 50-269, 83/10/05, 8310250354

--8310250363 IE Insp Repts 50-269/83-27, 50-270/83-27 & 50-287/83-27 on 830912-16 No noncompliance noted. Major areas inspected emergency detection & classification, protective action decisionmaking, public info program & shift staffing. DECKER, I R Region 2, Office of Director JENKINS, O R Division of Emergency Preparedness & Materials Safety 03/09/30 5pp 20898 125 24X Fiche 50-269, 83/10/05, 8310250354

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants." Svc list encl. JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 03/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility." Svc list encl. JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 03/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases." Svc list encl. JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 03/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders." Svc list encl. JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 03/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310250635 Informs that periodic evaluation of SALP complete Rept approved. O'REILLY, J P Region 2, Office of Director 83/10/17 TUCKER, H B Duke Power Co 3pp 20900 204 24X Fiche 50-000, 83/10/17, 8310250635

--8310250646 Forwards SALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983. LEWIS, R C Division of Project & Resident Programs 03/08/02 TUCKER, H B Duke Power Co 3pp 20900 208 24X Fiche 50-000, 83/10/17, 8310250635

--8310250652 SALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983. * Region 2, Office of Director 03/08/02 56pp 20900 211 24X Fiche 50-000, 83/10/17, 8310250635

--8310250665 Responds to 830802 ltr re SALP board rept incomplete & premature in certain areas in general, until endorses observations re facility performance. TUCKER, H B Duke Power Co 03/08/29 O'REILLY, J P Region 2, Office of Director 2pp 20900 267 24X Fiche 50-000, 83/10/17, 8310250635

8310270079 Forwards response to Action Item 3 of IE Bulletin 80-11, "Masonry Wall Design." Design assumptions appropriate considering physical condition of boundary joints. TUCKER, H B Duke Power Co 03/10/20 DENTON, H R Office of Nuclear Reactor Regulation, Director SLOZ, J F Operating Reactors Branch 4 3pp 20924 360 24X Fiche 50-269, 83/10/20, 8310270079

R Periodic operating reports & related correspondence

8310180167 Monthly operating repts for Sept 1983 W/831014 ltr. REAVIS, J A, TUCKER, H B Duke Power Co 03/09/30 Director's Office, Office of Inspection and Enforcement 19pp 20809 098 24X Fiche 50-269, 83/09/30, 8310180167

S Reportable occurrences, LERs & related correspondence

8310260008 Addl response to FOIA request for 17 categories of records. Forwards documents listed in Apps B, C & D Info re fraudulent practices of Ray Miller, Inc available in PDR. FELTON, J M Division of Rules and Records 03/06/23 CLEMETT, J Public Citizen Litigation Group 15pp 20920 001 24X Fiche 50-000, 83/06/23, 8310260008

--8307260091 Discusses licensee Mar 1982 testing & evaluations of steam extraction line elbow which ruptured on 820628, in response to 820709 request for addl steam line break info. EISENHUT, D Q Division of Licensing 02/07/14 REINH, T A Office of the Executive Director for Operations 2pp 20920 020 24X Fiche 50-000, 83/06/23, 8310260008

DOCKETED ITEMS

8310030423 Updated RO 287/83-07 Investigation incomplete Next report expected by 831030
TUCKER, H B Duke Power Co 83/09/16 O'REILLY, J P Region 1,
Office of Director 1p 20592 162 24X Fiche 50-287, 83/09/16,
8310030423

8310060426 RO on 830922, w/both Keowee hydro units out of svr for planned maint. Lee AC gas turbine being used to energize buses, tripped off line Both standby buses deenergized & Units 1 & 2 placed in degraded mode
TUCKER, H B Duke Power Co 87/09/27 O'REILLY, J P Region 1,
Office of Director 3pp 20743 224 24X Fiche 50-269, 83/09/27,
8310060426

8310140159 RO on 830929, while energizing 4,160-volt standby buses, Lee AC gas turbine, tripped off-line, deenergizing both standby buses & placing two operating units in degraded mode Cause undetermined since unit has no event recorder
TUCKER, H B Duke Power Co 83/10/04 O'REILLY, J P Region 1,
Office of Director 3pp 20765 067 24X Fiche 50-269, 83/10/04,
8310140159

8310270412 RO on 831012, standby buses deenergized to allow for operability performance testing of standby bus breakers per Tech Specs Testing caused degraded mode beyond Tech Spec limit
TUCKER, H B Duke Power Co 83/10/17 O'REILLY, J P Region 1,
Office of Director 2pp 20924 010 24X Fiche 50-269, 83/10/17,
8310270412

V Operator Examinations

8310040425 Notifies that operator & senior operator licensing exam scheduled for wk of 831205 NRC requirements for administration of exams entl
DANCE, H C Division of Project & Resident Programs 83/09/28
TUCKER, H B Duke Power Co 3pp 20619 124 24X
Fiche 50-269, 83/09/28, 8310040425

DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8310040061 Board Notification 83-132 Forwards NRC 830725 ltr & ltr Insp Rept 50-289/83-13 re emergency preparedness open items
EISENHUT, D G Division of Licensing 87/09/09 PALLADINO, N,
GILINSKY, P, ROBERTS, T Commissioners 4pp 20640 338 24X
Fiche 50-289, 83/09/09, 8310040061

8310200218 Forwards IE Insp Repts 50-289/83-18 & 50-320/83-10 on 830622-24 & 0711-20 & notice of violation
MARTIN, T T Region 1, Office of Director 83/09/14 KANDA, B M
General Public Utilities - GPU Service Corp 2pp 20830 123 24X
Fiche 50-289, 83/09/14, 8310200218

--8310200237 Notice of violation from insp on 830622-0720
Region 1, Office of Director 83/09/14 1p 20830 125 24X
Fiche 50-289, 83/09/14, 8310200237

--8310200270 IE Insp Repts 50-289/83-18 & 50-320/83-10 on 830622-24 & 0711-20 Noncompliance noted Failure to perform quarterly fire brigade training
PADLINO, R, PLECO, L, ANDERSON, C J Region 1, Office of Director 83/09/06 19pp 20830 124 24X Fiche 50-289, 83/09/14,
8310200270

8310170028 Forwards GPU vs B&W lawsuit review SER input for emergency planning Documents do not contain info w/potential to alter conclusions on restart certification issue
MATTHEWS, D B Emergency Preparedness Branch 83/09/17
RUSSELL, M T GPU/B&W lawsuit Review Team 3pp 20778 343 24X
Fiche 50-289, 83/09/17, 8310170028

8310050327 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/09/26 Document
Management Branch 1p 20639 216 24X Fiche 50-287, 83/09/26,
8310050327

--8310050334 Public version of revised emergency plan implementing procedures, including Procedures 1004 22, "Tornado/High Winds," 1004-20, "Activation of Technical Support Ctr" & 1004 31, "Airborne Radioactivity Sampling & Analysis"
STANGL, S J General Public Utilities - GPU Service Corp 83/09/08 60pp 20639 217 24X Fiche 50-289, 83/09/26, 8310050334

8310060529 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/09/30 Document
Management Branch 1p 20661 355 24X Fiche 50-287, 83/09/10,
8310060529

--8310060532 Public version of Rev 5 to Emergency Plan Implementing Procedure 1004 10, "Onsite/Offsite Radiological Monitoring"
STANGL, S J General Public Utilities - GPU Service Corp 83/07/14 7pp 20661 356 24X Fiche 50-289, 83/09/10, 8310060532

8310060549 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/09/30 Document
Management Branch 1p 20663 071 24X Fiche 50-287, 83/09/10,
8310060549

--8310060551 Public version of revised emergency plan implementing procedures, including Procedures 1004 4 re general emergency & 1004 6 re addl assistance & notification
STANGL, S J General Public Utilities - GPU Service Corp 83/06/29 47pp 20663 072 24X Fiche 50-289, 83/09/30, 8310060551

8310170006 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/06 Document
Management Branch 1p 20813 297 24X Fiche 50-287, 83/10/06,
8310170006

--8310170007 Public version of revised emergency plan implementing procedures, including Procedures 1005 re maintaining emergency preparedness, 1004 1 re unusual event & 1004 1 re alert
NELSON, M A, TIDDE, R J, HUKILL, H D General Public Utilities - GPU Service Corp 83/09/26 93pp 20813 300 24X
Fiche 50-289, 83/10/06, 8310170007

8310200426 Releases public version of revised emergency plan administrative & implementing procedures
FELTON, J M Division of Rules and Records 83/10/17 Document
Management Branch 1p 20839 102 24X Fiche 50-287, 83/10/17,
8310200426

--8310200430 Public version of revised emergency plan procedures including Administrative Procedure 1003 re emergency equipment readiness & Implementing Procedure 1004 10 re onsite/offsite radiological monitoring
NELSON, M A, TIDDE, R J, HUKILL, H D General Public Utilities - GPU Service Corp 83/10/04 100pp 20839 103 24X
Fiche 50-289, 83/10/17, 8310200430

8310210384 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/17 Document
Management Branch 1p 20881 342 24X Fiche 50-287, 83/10/17,
8310210384

--8310210390 Public version of Rev 4 to Emergency Plan Implementing Procedure 1004 34, "Activation of Parsippany Technical Functions Ctr"
STANGL, S J General Public Utilities - GPU Service Corp 83/09/29 6pp 20882 343 24X Fiche 50-289, 83/10/17, 8310210390

8310270117 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/31 Document
Management Branch 1p 20942 110 24X Fiche 50-289, 83/10/31,
8310270117

--8310270125 Public version of revised Emergency Plan Implementing Procedures 1004 3 re site emergency, 1004 4 re general emergency & 1004 12 re environ monitoring
STANGL, S J General Public Utilities - GPU Service Corp 83/10/06 74pp 20942 111 24X Fiche 50-289, 83/10/31, 8310270125

8310270393 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/31 Document
Management Branch 1p 20943 089 24X Fiche 50-287, 83/10/31,
8310270393

--8310270396 Public version of Rev 7 to Emergency Plan Implementing Procedure 1004 6, "Unit 2 Onsite Emergency Response Directory" & Rev 2 to 1004 35, "Activation of Annex to Hearsite Emergency Operations Facility (Crawford Station)"
BRADY, J A, STANGL, S J General Public Utilities - GPU Service Corp 83/10/10 21pp 20943 090 24X Fiche 50-287, 83/10/31,
8310270396

Q Adjudicatory correspondence

8310110632 Expresses appreciation for meeting to review GPU vs B&W lawsuit document record
RANKSON, R J Office of the Executive Legal Director 83/07/20
WISE, R F Davis, Polk & Wardwell 1p 20714 343 24X
Fiche 50-289, 83/07/22, 8310110632

DOCKETED ITEMS

107

8310140302 Forwards listing of lawsuit documents by subj area significant to GPU vs B&W record to support position to reopen restart hearing Evaluation of documents contained in SER requested
EISENHUJ, D O Division of Licensing 83/08/15 MATTSO, R J Division of Systems Integratinn (post #11005) THOMPSON, H C, TAYLOR, J L Division of Human Factors Safety 22pp 20791 24X FICHE 50-289, 83/08/15, 8310140302

8310170012 Forwards NRC produced transcripts of RW Keatnn taped interviews tape entry into document control sys as B&W Exhibits 347a-347o requested w/o encl
RUSSELL, W T GPU/B&W Lawsuit Review Team 83/08/24 SCATFOLD, INI, L, SOWER, J Public Document Branch BLUM, M Office of the General Counsel 1p 20798 361 24X FICHE 50-289, 83/08/24, 8310170012

8310030453 Comments on NRC SER re steam generator repair & return to operation NRC should perform independent assessment of acceptability of potential addl steam generator leakage GERUSKY, T M Pennsylvania, Commonwealth of, 83/09/26 Docketing & Services Branch 2pp 20601 042 24X FICHE 50-289, 83/09/26, 8310030453

8310030408 Advises that idea that plant will be run by GPU in future should be abandoned Outside organization should take over operation Qualifying outside organization would be less difficult than requalifying GPU
GILINSKY, V Commissioners 83/09/28 Commissioners 1p 20602 216 24X FICHE 50-289, 83/09/28, 8310030408

8310030351 Forwards documents relevant to GPU vs B&W lawsuit being reviewed by NRC
BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, E L Metropolitan Edison Co 83/09/29 EDLES, G J, BUCK, J H, KOHL, C N Atomic Safety and Licensing Appeal Panel 130pp 20592 001 24X FICHE 50-289, 83/09/29, 8310030351

8310030403 Forwards GPU news release & EM Stier 830923 ltr to GPU commenting on OFC of Investigations rept, "TMI-2 Allegations re Safety-Related Mods, QA Procedures & Use of Polar Crane " Svc list encl
BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, E L Metropolitan Edison Co 83/09/29 EDLES, G J, BUCK, J H, KOHL, C N Atomic Safety and Licensing Board Panel 13pp 20601 211 24X FICHE 50-289, 83/09/29, 8310030403

8310030413 Statement on Commissioner Gilinsky 830928 memo to Commission Opposes memo being made public since collegial process would be impaired
PALLADINO, N J Commissioners 83/09/30 1p 20602 215 24X FICHE 50-289, 83/09/30, 8310030413

8310030417 Forwards draft NUREG-1020, Vol 1, "GPU vs B&W Lawsuit Review & Effect on TMI-1 " Portions of Category 10 withheld since info pertains to ongoing investigations
CHILK, S J Office of the Secretary of the Commission 83/09/30 Atomic Safety and Licensing Board Panel 11pp 20602 103 24X FICHE 50-289, 83/09/30, 8310030417

8310040280 Order extending time until 831024 for Commission to act to review AI AD-729
CHILK, S J Office of the Secretary of the Commission 83/09/30 Commissioners 1p 20614 076 24X FICHE 50-289, 83/09/30, 8310040280

8310040392 Advises that 830929 ltr wrongly captioned Unit 2 instead of Unit 1 Documents being sent for Commission use include press release & records on B&W vs GPU lawsuit review Svc list encl
BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, E L Metropolitan Edison Co 83/09/30 EDLES, G J, BUCK, J H, KOHL, C N Atomic Safety and Licensing Appeal Panel 219pp 20619 183 24X FICHE 50-289, 83/09/30, 8310040392

8310070437 GPU V B&W LAWSUIT REVIEW AND ITS EFFECT ON TMI-1 General Public Utilities Corporation, et al V The Babcock & Wilcox Company, et al Three Mile Island Nuclear Station, Unit 1 Docket No 50-289
* Office of Nuclear Reactor Regulation, Director NUREG-1020 V01 83/09/30 85pp Available at NRC \$5.00 20674 126 24X FICHE 50-289, 83/09/30, 8310070437

8310070441 GPU V B&W LAWSUIT REVIEW AND ITS EFFECT ON TMI-1 General Public Utilities Corporation, et al V The Babcock & Wilcox Company, et al Three Mile Island Nuclear Station, Unit 1 Docket No 50-289
* Office of Nuclear Reactor Regulation, Director NUREG-1020 V02 83/09/30 832pp 20677 001 24X FICHE 50-289, 83/09/30, 8310070441

8310040188 Memorandum & order denying TMI Alert 830921 motion for postponement of 831018 prehearing conference in remanded proceeding ASLB on steam generator repair & ASLB on remand of mgt issues will not schedule simultaneous hearings
SMITH, I W Atomic Safety and Licensing Board Panel 83/10/03 Three Mile Island Alert 2pp 20608 252 24X FICHE 50-289, 83/10/03, 8310040188

8310040395 Forwards J Lee ltr sent to Commissioner Gilinsky ofc w/o formal indication of parties served
CLEMENTS, W L Docketing & Services Branch 83/10/03 Office of the Executive Legal Director 4pp 20619 044 24X FICHE 50-289, 83/10/03, 8310040395

8310050528 Motion to open Commission 831004 meeting to public Meeting topic is status of investigations & adjudicatory matters re TMI restart Discussion required to be open Certificate of Svc encl
WEISS, E R Union of Concerned Scientists 83/10/04 Commissioners 4pp 20630 355 24X FICHE 50-289, 83/10/04, 8310050528

8310110056 Requests release of full unexpurgated version of recently completed NUREG-1020. "GPU vs B&W Lawsuit Review & Effect on TMI-1 "
DIECKAMP, H General Public Utilities - GPU Service Corp 83/10/04 PALLADINO, N, ASSELSTINE, J K, BERNTHAL, F Commissioners 3pp 20665 003 24X FICHE 50-289, 83/10/04, 8310110056

8310110047 Memorandum & Order ALAB-744, denying UCS 830918 petition for reconsideration of ASLB 830526 opinion affirming ASLB decision that issue of environ qualification of safety-related equipment be resolved outside hearing
SHOMAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/06 Union of Concerned Scientists 4pp 20668 273 24X FICHE 50-289, 83/10/06, 8310110047

8310110050 Order denying UCS 831004 motion to open closed Commission 831006 meeting on status of investigations & adjudicatory matters re TMI restart Portion of meeting closed since disclosure might interfere w/investigations
CHILK, S J Office of the Secretary of the Commission 83/10/06 Union of Concerned Scientists 3pp 20668 269 24X FICHE 50-289, 83/10/06, 8310110050

8310110205 Response opposing TMI Alert 830921 suppl to petition to intervene Contentions satisfy none of "specificity requirements Certificate of Svc encl
BLAKE, E L Metropolitan Edison Co BLAKE, E L Shaw, Pittman, Potts & Trowbridge 83/10/06 Atomic Safety and Licensing Board Panel 42pp 20665 089 24X FICHE 50-289, 83/10/06, 8310110205

8310110224 Response to proposed contentions re steam generator repair Joint petitioners fail to identify concerns which warrant consideration Certificate of Svc encl
BLAKE, E L Metropolitan Edison Co BLAKE, E L Shaw, Pittman, Potts & Trowbridge 83/10/06 Atomic Safety and Licensing Board Panel 18pp 20666 110 24X FICHE 50-289, 83/10/06, 8310110224

8310110272 Notice of appearance in proceeding Certificate of Svc encl
TROWBRIDGE, O F, RIDGWAY, D A, BLAKE, E L Metropolitan Edison Co 83/10/06 6pp 20666 138 24X FICHE 50-289, 83/10/06, 8310110272

8310120395 Forwards info INPO provided to util at INPO conference of chief executive officers TMI-1 rated as average or in top one-sixth of all operating plants in US Svc list encl
BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, E L Metropolitan Edison Co 83/10/06 EDLES, G J, BUCK, J H, KOHL, C N Atomic Safety and Licensing Appeal Panel 48pp 20699 057 24X FICHE 50-289, 83/10/06, 8310120395

8310130048 Response to TMI Alert (TMI-A) & J Lee et al contentions re steam generator repair TMI-A should be admitted as party since Contentions 1 b & 2 b 2 admissible Certificate of Svc encl
WAGNER, H F, RAWSON, R J Hearing Branch 4 83/10/06 Atomic Safety and Licensing Board Panel 22pp 20726 237 24X FICHE 50-289, 83/10/06, 8310130048

8310110182 Responds to 830914 memorandum & order re testimony on Hartman allegations Clients not legally required to testify Author will appear before ASLB at 831018 prehearing conference
WOLFE, S, LINENBERGER, C Atomic Safety and Licensing Board Panel 3pp 20666 224 24X FICHE 50-289, 83/10/07, 8310110182

8310110223 Notice of current schedule re mgt competence & integrity issues in restart proceeding Decision on restart expected in latter half of CY84 Tentative projections of completion dates encl
CHILK, S J Office of the Secretary of the Commission 83/10/07 3pp 20666 128 24X FICHE 50-289, 83/10/07, 8310110223

DOCKETED ITEMS

- 8310110225 Order scheduling 831201 oral argument in Bethesda, MD re various appeals from ASLB Partial Initial Decisions LBP-B1-32 & LBP-B2-36 on mgt competence & integrity Parties must provide name of representative by 831117 SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/07 Office of the Executive Legal Director 2pp 20646 108 24X Fiche 50-289, 83/10/07, 8310110225
- 8310110238 Order requesting views of parties on whether Commission should stay ASLB hearing on Hartman allegations re leak rate data falsification pending Ofr of Investigation rept completion Hearing stayed pending comments CHILK, S J Office of the Secretary of the Commission 83/10/07 2pp 20666 164 24X Fiche 50-289, 83/10/07, 8310110238
- 8310130209 Memorializes 831011 telcon in which ASLB canceled dissection for submissions & scheduling of conference per ASLB 830914 memorandum & order ASLB 831011 telcon w/HH Voigt, counsel for TMI-2 employees before 790328, also memorialized WOLFE, S J Atomic Safety and Licensing Board Panel 83/10/12 GOLDBERG, J R Hearing Branch 2 BLAKE, E L Shaw, Pittman, Potts & Trowbridge WOLFEL, LING, M Pennsylvania, Commonwealth of, App 20725 024 24X Fiche 50-289, 83/10/12, 8310130209
- 8310140026 Memorandum transmitting Ofr of Investigations 831007 ltr advising that ofc does not anticipate participating in any proceeding prior to completion of investigative repts relevant to issues pending before ASLB SMITH, I W Atomic Safety and Licensing Board Panel 83/10/13 1p 20768 078 24X Fiche 50-289, 83/10/13, 8310140026
- 8310140035 Advises that ofc does not anticipate participating in any proceeding prior to completion of investigative repts relevant to issues pending before ASLB, in response to 830914 memorandum HAYES, B B Office of Investigation 83/10/07 SMITH, I W Atomic Safety and Licensing Board Panel 1p 20768 079 24X Fiche 50-289, 83/10/13, 8310140026
- 8310180355 Requests addl guidance re ASLB 831007 order & oral argument scheduled for 831201 Identification of issues of concern to ASLB would assist parties in preparation & in oral argument Svc list encl BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, E L Metropolitan Edison Co 83/10/14 EDLES, G J, BUCK, J H, KOHL, C N Atomic Safety and Licensing Appeal Panel App 20803 016 24X Fiche 50-289, 83/10/14, 8310180355
- 8310250338 Notices of appearance in proceeding Certificate of Svc encl WAGNER, M E, RAWSON, R J Hearing Branch 4 83/10/14 App 20898 026 24X Fiche 50-289, 83/10/14, 8310250338
- 8310200211 Forwards INPO evaluations on util mgt Svc list encl BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, E L Metropolitan Edison Co 83/10/18 EDLES, G J, BUCK, J H, KOHL, C N Atomic Safety and Licensing Appeal Panel 47pp 20832 351 24X Fiche 50-000, 83/10/18, 8310200211
- 8310200231 Motion to establish criteria for judging reasonable progress All long-term actions found by ASLB & ASLAB to be necessary & sufficient to protect public must be completed prior to restart Certificate of Svc encl WEISS, E R Union of Concerned Scientists 83/10/18 Commissioners 5pp 20833 047 24X Fiche 50-289, 83/10/18, 8310200231
- 8310210148 Forwards util "TMI-1 Once-Through Steam Generator Failure Analysis Rept," TDR-341, referenced in util responses to petitioner proposed contentions w/o encl TROWBRIDGE, G F Shaw, Pittman, Potts & Trowbridge TROWBRIDGE, G F Metropolitan Edison Co 83/10/18 WOLFE, S J, LAMB, J C Atomic Safety and Licensing Board Panel DOROSH, H W Three Mile Island Alert 3pp 20836 094 24X Fiche 50-289, 83/10/18, 8310210148
- 8310210249 Forwards corrected pages to INPO rept provided on 831011 BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, E L Metropolitan Edison Co 83/10/19 EDLES, G J, BUCK, J H, KOHL, C N Atomic Safety and Licensing Appeal Panel 6pp 20851 049 24X Fiche 50-000, 83/10/19, 8310210249
- 8310240166 Comments on disagreement w/N Ammodt concerning rev to joint petitioner Contention I re steam generator repair licensee will respond in writing if N Ammodt submits proposed rev Certificate of Svc encl TROWBRIDGE, G F Shaw, Pittman, Potts & Trowbridge TROWBRIDGE, G F Metropolitan Edison Co 83/10/20 WOLFE, S J, HEIRICK, D L, LAMB, J C Atomic Safety and Licensing Board Panel 3pp 20881 311 24X Fiche 50-289, 83/10/20, 8310240166
- 8310240184 Submits correction to statement re availability of IDR 389 & TDR-417 documents, made at 831017 prehearing conference Documents not available in PDR Release requested Svc list encl TROWBRIDGE, G F Shaw, Pittman, Potts & Trowbridge TROWBRIDGE, G F Metropolitan Edison Co 83/10/20 WOLFE, S J, HEIRICK, D L, LAMB, J C Atomic Safety and Licensing Board Panel 3pp 20976 086 24X Fiche 50-289, 83/10/20, 8310240184
- 8310250046 Requests 831201 oral argument be rescheduled due to author outside commitments WEISS, E R Harmon & Weiss 83/10/20 Atomic Safety and Licensing Appeal Panel 1p 20894 197 24X Fiche 50-289, 83/10/20, 8310250046
- 8310250042 Order memorializing 831017 special prehearing conference Objections due from licensee, TMI Alert & Joint Petitioners within 5 days & from NRC within 10 days WOLFE, S J Atomic Safety and Licensing Board Panel 83/10/21 App 20895 235 24X Fiche 50-289, 83/10/21, 8310250042
- 8310270372 Informs that Technical Data Repts 388 & 417 not distributed to LPDR, contrary to licensee 831017 assertion BRADFORD, L Three Mile Island Alert 83/10/21 Atomic Safety and Licensing Board Panel 2pp 20923 291 24X Fiche 50-289, 83/10/21, 8310270372
- 8310260294 Restatement of proposed Contentions 1, 2 & 3 re physical & chemical processes employed to return tubes to design basis Certificate of Svc encl AAMODT, N O Aamodts 83/10/22 Atomic Safety and Licensing Board Panel App 20911 353 24X Fiche 50-289, 83/10/22, 8310260294
- 8310260274 Response to Commission 831007 request for views on whether hearings re Hartman allegations on leak rate falsifications should be stayed Hearing process should not be stayed pending completion of Ofr of Investigations rept DOROSH, H W Three Mile Island Alert 83/10/23 6pp 20911 307 24X Fiche 50-289, 83/10/23, 8310260274
- 8310260306 Motion for leave to file response to Commission 831007 order staying remanded hearing on "Hartman allegations" pending views on continuing stay until completion of Ofr of Investigations rept WEISS, E R Union of Concerned Scientists 83/10/24 Commissioners 5pp 20910 378 24X Fiche 50-289, 83/10/24, 8310260306
- 8310260308 Response to Commission 831007 order temporarily staying remanded ASLB hearings re "Hartman allegations" & requested views of parties whether stay should remain in effect pending completion of investigation w/Certificate of Svc WEISS, E R Union of Concerned Scientists 83/10/24 5pp 20910 333 24X Fiche 50-289, 83/10/24, 8310260306
- 8310270259 Order extending time until 831110 for Commission to act to review ALAB-729 CHILK, S J Office of the Secretary of the Commission 83/10/24 Commissioners 1p 20923 246 24X Fiche 50-289, 83/10/24, 8310270259
- 8310260256 Order rescheduling 831201 oral arguments for 840111 in Bethesda, MD on appeals from ASLB partial initial decisions re mgt competence & integrity SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/25 Union of Concerned Scientists 2pp 20912 022 24X Fiche 50-289, 83/10/25, 8310260256
- 8310310198 Response to Commission 831007 order re reopened issue for restart hearings Issues do not provide basis for continued suspension of license nor basis for reopening record Certificate of Svc encl BLAKE, E L Metropolitan Edison Co BLAKE, E L Shaw, Pittman, Potts & Trowbridge 83/10/27 Commissioners 200pp 20748 153 24X Fiche 50-289, 83/10/27, 8310310198
- 8310310302 Notice of H Dieckamp speech to be delivered at AIF 831101 annual conference Speech & Svc list encl BLAKE, E L Metropolitan Edison Co BLAKE, E L Shaw, Pittman, Potts & Trowbridge 83/10/28 20pp 20957 251 24X Fiche 50-289, 83/10/28, 8310310302
- H General correspondence
- 8310110062 Responds to 830920 ltr expressing concerns re TMI-1 restart Commission Bernthal cannot address matter outside formal deliberative process Related correspondence INGRAM, F Office of Public Affairs 83/10/05 HURST, A Affiliation Unknown 1p 20667 305 24X Fiche 50-289, 83/10/05, 8310110062

DOCKETED ITEMS

109

--B310110074 Opposes TMI-1 restart
HURST, A Affiliation Unknown 83/09/20 BERNTHAL, I M
Commissioners 1p 20667 306 24X Fiche 50-289, 83/10/04,
B310110062

B310130219 Forwards Cumberland County Board of Commissioners 830919
Resolution 83-7 requesting NRC to proceed w/TMI-2
decontamination to close Units 1 & 2
PUNT, N A Cumberland County, PA 83/10/06 PALLADINO, N J
Commissioners 2pp 20723 050 24X Fiche 50-289, 83/10/06,
B310130219

B310240159 Comments on 83092/ public meeting in Middletown, PA re
TMI-1 restart & GPU vs B&W lawsuit Meeting completely
dominated by GPU/Bechtel
OSBORN, M Affiliation Unknown 83/10/14 DENTON, H R NRC - No
Detailed Affiliation Given 2pp 20081 292 24X
Fiche 50-289, 83/10/14, B310240159

P Operating license stage documents & correspondence

B310200026 FOIA request for correspondence between Chairman Palladino
& DOJ re investigation of alleged falsification of RCS leak
rate tests News article dtd 830513 from Patriot News encl
VIGOT, H H LeRoque, Lamb, Leiby & MacRae 83/05/26 Office of
Administration 2pp 20844 238 24X Fiche 50-289, 83/05/26,
B310200026

B310140296 Forwards TMI-1 GPU/B&W lawsuit review organization chart
Overtime for personnel connected w/GPU vs B&W lawsuit
authorized as noted
RUSSELL, W T Systematic Evaluation Program Branch 83/06/28 NRC
- No Detailed Affiliation Given 1p 20794 095 24X
Fiche 50-289, 83/06/28, B310140296

B310140294 Requests estimate of time needed to review documents re
TMI-2 accident & to prepare lists info needed to respond to
Congressman Udall request
CHILK, S J Office of the Secretary of the Commission 83/06/30
DIRCKS, W J Office of the Executive Director for Operations 1p
20794 098 24X Fiche 50-289, 83/06/30, B310140294

B310130114 Agrees to provide NRC w/access to computerized record of
GPU vs B&W trial record & deposition transcripts to check
completeness of NRC independent review of trial documents
ARNOLD, R C General Public Utilities - GPU Service Corp 83/07/08
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p
20777 073 24X Fiche 50-289, 83/07/08, B310130114

B310130342 Identifies NRR div responsibilities for reviewing documents
re GPU/B&W lawsuit, per Commission 830628 directive Review
due by 830901 Overview of general scope & objectives of
lawsuit review task encl
EISENHUT, D G Division of Licensing 83/07/08 MATISON, R J
Division of Systems Integration (post 811005) THOMPSON, H L
Division of Human Factors Safety VOLLHER, R H Division of
Engineering 52pp 20768 280 24X Fiche 50-289, 83/07/08,
B310130342

B310270011 Addl response to FOIA request for four documents re TMI
restart & SECY-83-980 & SECY-83-980 Items 1, 2, 4 & 5 encl
Item 3 included within Item 2 Review of Item 6 incomplete
FELTON, J M Division of Rules and Records 83/07/15
DANIELSON, L M MHB Technical Associates 1p 20940 309 24X
Fiche 50-289, 83/07/15, B310270011

B310120058 Requests individual to manage & control access to hard
copies of documents for GPU vs B&W lawsuit review
RUSSELL, W T NRC - No Detailed Affiliation Given 83/07/27
BESAH, W J Division of Technical Information & Document Control
2pp 20749 352 24X Fiche 50-289, 83/07/22, B310120058

B310130175 Forwards summary of 830721 meeting re GPU vs B&W lawsuit
documents Comments on meeting summary welcomed
RAWSON, R J NRC - No Detailed Affiliation Given 83/07/26
WARTZ, W E Davis, Polk & Wardwell 1p 20777 171 24X
Fiche 50-289, 83/07/26, B310130175

--B310130186 Summary of 830721 meeting w/Davis, Polk & Wardwell in New
York, NY re info relevant to NRC review of GPU vs B&W lawsuit
record or to reactor safety in general
RUSSELL, W T NRC - No Detailed Affiliation Given 83/07/26
EISENHUT, D G Division of Licensing 3pp 20777 172 24X
Fiche 50-289, 83/07/26, B310130186

B310170043 Summary of 830721 meeting w/B&W counsel re review of GPU vs
B&W lawsuit record & general reactor safety Operator
reluctance & responsibility for procedure writing identified
as possible generic safety issue
RUSSELL, W T GPU/B&W Lawsuit Review Team 83/07/26 EISENHUT, D G
Division of Licensing 3pp 20812 154 24X Fiche 50-289, 83/07/26,
B310170043

B310140290 Forwards emergency planning contentions, ALAB-729, 830429 rept
on NRC requirements for restart & latest status rept on
TMI-1 restart items w/o encls List of documents being
forwarded encl
MICHAELS, T S NRC - No Detailed Affiliation Given 83/07/29
HERNAN, R, GUERMANN, J, THADANI, M NRC - No Detailed Affiliation
Given 2pp 20794 106 24X Fiche 50-289, 83/07/29, B310140290

B310140291 Forwards final installment of review packages & updated list
matching GPU vs B&W lawsuit documents w/responsible divs
Draft input to rept requested within 30 days w/o encls
EISENHUT, D G Division of Licensing 83/08/02 MATISON, R J
Division of Systems Integration (post 811005) THOMPSON, H L
Division of Human Factors Safety TAYLOR, J M Division of QA,
Safeguards & Inspection Programs (Post 830103) 2pp 20794 108
24X Fiche 50-289, 83/08/02, B310140291

B310140292 Comments on Operating Reactors Assessment Branch
responsibilities & participation in GPU vs B&W lawsuit
review Table for disposition of operating experience
issues encl
MIRALIA, F Assistant Director for Safety Assessment 83/08/05
RUSSELL, W T GPU/B&W Lawsuit Review Team 5pp 20794 100 24X
Fiche 50-289, 83/08/05, B310140292

B310170717 Memorializes 830809 telcon w/H Myers of Congressman Udall
staff re Chairman Palladino 830803 ltr on significant info
in GPU vs B&W record
RUSSELL, W T GPU/B&W Lawsuit Review Team 83/08/09 DENTON, H R,
CASE, E G Office of Nuclear Reactor Regulation, Director
EISENHUT, D G Division of Licensing 1p 20798 116 24X
Fiche 50-289, 83/08/09, B310170717

B310130326 Forwards list of long-term actions that should be addressed
in SER input Only noncertification items to be addressed in
review
EISENHUT, D G Division of Licensing 83/08/12 MATISON, R J
Division of Systems Integration (post 811005) THOMPSON, H L
Division of Human Factors Safety JOHNSON, E L Division of Emergency
Preparedness & Engineering Response (Post 830103) 5pp 20754 332
24X Fiche 50-289, 83/08/12, B310130326

B310170751 Informs that D Morrisseau will be acting for F Allenspach as
leader for GPU vs B&W lawsuit review
BOEHM, H R Licensee Qualifications Branch 83/08/12
THOMPSON, H L Division of Human Factors Safety 1p 20798 219
24X Fiche 50-289, 83/08/12, B310170751

B310130108 Forwards list of specific exhibits requested on 830812 to be
used in GPU vs B&W lawsuit review
RUSSELL, W T Division of Licensing 83/08/16 LLOYD, R D
Debevoise & Liberman LLOYD, R D General Public Utilities - GPU
Service Corp 2pp 20777 071 24X Fiche 50-289, 83/08/16,
B310130108

B310170014 Forwards revised listing of subj area contents for GPU vs
B&W lawsuit review, per 830727 & 0805 & 12 ltrs
RUSSELL, W T GPU/B&W Lawsuit Review Team 83/08/18 MORISSEAU, D,
PICKETT, D, HAASS, W NRC - No Detailed Affiliation Given 14pp
20813 285 24X Fiche 50-289, 83/08/18, B310170014

B310170747 Identifies GPU vs B&W lawsuit documents not held by NRC &
recommends no further action to obtain documents
CAPRA, R A GPU/B&W Lawsuit Review Team 83/08/29 RUSSELL, W T
GPU/B&W Lawsuit Review Team 34pp 20796 318 24X
Fiche 50-289, 83/08/29, B310170747

B310170022 Advises of receipt of legible B&W lawsuit documents
requested of B&W in NRC 830816 ltr Documents received
listed
CAPRA, R A GPU/B&W Lawsuit Review Team 83/09/08 NRC - No
Detailed Affiliation Given 1p 20798 357 24X
Fiche 50-289, 83/09/08, B310170022

B310170032 Requests assistance in arranging resources for production &
publication of NRC evaluation of GPU vs B&W lawsuit review
& impact on TMI-1 restart (NUREG-1020)
RUSSELL, W T GPU/B&W Lawsuit Review Team 83/09/08 BESAH, W J
Division of Technical Information & Document Control 3pp
20798 334 24X Fiche 50-289, 83/09/08, B310170032

B310170001 Forwards 830908 memo requesting support for NRC rept on
GPU vs B&W lawsuit review Arrangements should be made to
accommodate requested schedule
STEELE, M L Division of Technical Information & Document Control
83/09/09 MCVEIGH, M D Division of Technical Information & Document
Control JOHANSEN, J Cross Branch 1p 20814 046 24X
Fiche 50-289, 83/09/09, B310170001

DOCKETED ITEMS

- B310170002 Requests assistance in arranging resources for production & publication of NRC evaluation of GPU vs B&W lawsuit review & impact on restart of TMI-1 (NUREG-1020) Flow chart w/projected milestones encl
RUSSELL, W T GPU/B&W Lawsuit Review Team 83/09/08 064AM W J
Division of Technical Information & Document Control 3pp
20814 049 24X Fiche 50-289, 83/09/09, 8310170001
- B310050144 Discusses B30307 & 17 ltrs re pressurized thermal shock flow reduction Commitment to fuel mgt plan for Cycle 6 & estimated schedules for fuel mgt plans to be used in subsequent cycles requested in 30 days
EISENHUT, D G Division of Licensing 83/09/12 HUKILL, H D
General Public Utilities - GPU Service Corp 5pp 20650 209 24X
Fiche 50-289, 83/09/12, 8310050144
- B310030418 Forwards SER on generic mods to reactor trip breakers for B&W plants to provide automatic actuation of shunt trip attachments Plant-specific info should be provided when generic design endorsed in response to Generic Ltr B3-28
STOLZ, J F Operating Reactors Branch 4 83/09/15 HUKILL, H D
General Public Utilities - GPU Service Corp 4pp 20626 309 24X
Fiche 50-289, 83/09/15, 8310030418
- B310030421 SER on generic mods to reactor trip breakers for B&W plants to provide automatic actuation of shunt trip attachments
* NRC - No Detailed Affiliation Given 83/09/15 14pp
20626 313 24X Fiche 50-289, 83/09/15, 8310030418
- B310200032 Responds to FOIA request for correspondence between Chairman Palladino & DOJ re investigation of alleged falsification of RCS leak rate tests Forwards App A documents Portions of requested documents withheld (ref FOIA Exemption 7)
FELTON, J M Division of Rules and Records 83/09/15 VOIGT, H H
LeBoeuf, Lamb, Leiby & MacRae 3pp 20844 236 24X
Fiche 50-289, 83/09/15, 8310200032
- B310200038 Ack receipt of B30517 ltr re DOJ investigation into allegations re possible criminal wrongdoing Separate NRC investigation will be initiated
PALLADINO, N J Commissioners 83/05/27 JENSON, D L Justice,
Dept of Ip 20844 240 24X Fiche 50-289, 83/09/15, 8310200032
- B310200044 Requests that DOJ investigation on allegations re falsification of RCS leak rate tests be completed by B30515
Response within 2 wks requested info partially deleted
PALLADINO, N J Commissioners 83/04/11 SMITH, W F Justice,
Dept of 2pp 20844 241 24X Fiche 50-289, 83/09/15, 8310200032
- B310200048 Responds to B30411 ltr re TMI-1 restart & DOJ investigation into allegations re mgt competence Investigation being pursued diligently but will not be completed by requested date Info partially deleted
JENSON, D L Justice, Dept of 83/05/17 PALLADINO, N J
Commissioners 4pp 20844 243 24X Fiche 50-289, 83/09/15, 8310200032
- B310170018 Forwards draft NUREG-1020, "GPU vs B&W Lawsuit Review & Effect on TMI-1" Draft does not include Chapter 10 re mgt competence/integrity Comments or concurrence requested
W/o encl
RUSSELL, W T GPU/B&W Lawsuit Review Team 83/09/19 EISENHUT, D G
Division of Licensing MATTSO, R J Division of Systems Integration
(post B11005) THOMPSON, H L Division of Human Factors Safety
2pp 20798 358 24X Fiche 50-289, 83/09/19, 8310170018
- B310280169 Appeals partial denial of FOIA request for correspondence between Chairman Palladino & DOJ re investigation of alleged falsification of RCS leak rate tests
VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 83/09/19 CHILK, S J
Office of the Secretary of the Commission 2pp 20965 055 24X
Fiche 50-289, 83/09/19, 8310280169
- B310310097 Responds to FOIA request that 16 SECYs be placed in FDR
Forwards App A documents SECY-B2-466 withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/09/19 SHOILY, S L
Union of Concerned Scientists 3pp 21000 146 24X
Fiche 50-320, 83/09/19, 8310310097
- B310310131 Informs of present status of TMI-1 restart certification effort & provides update on NUREG-0737 items status
DIRCKS, W J Office of the Executive Director for Operations
SECY-B2-483 82/12/09 14pp 21000 260 24X
Fiche 50-289, 83/09/19, 8310310097
- B310170025 Forwards final draft Chapter 10 to NUREG-1020 entitled "Mgt Competence/Integrity" Changes, comments or concurrence requested by B30922 W/o encl
EISENHUT, D G Division of Licensing 83/09/20 MATTSO, R J
Division of Systems Integration (post B11005) THOMPSON, H L
Division of Human Factors Safety TAYLOR, J M Division of QA,
Safeguards & Inspection Programs (Post B30103) 2pp 20798 314 24X
Fiche 50-289, 83/09/20, 8310170025
- B310040690 Advises that changes re sonic flow devices meet requirements of NUREG-0737, Item 11 E 1 2, "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication" & are acceptable based on review of licensee B30524 & O&E ltrs
STOLZ, J F Operating Reactors Branch 4 83/09/22 HUKILL, H D
General Public Utilities - GPU Service Corp 5pp 20627 319 24X
Fiche 50-289, 83/09/22, 8310040690
- B31010246 Board Notification B3-146 forwards info re mgt competence & integrity identified in Board Notifications B3-71 & B3-71A
Addl info re failure to satisfy NRC operator training requirements identified in GPU vs B&W lawsuit required
EISENHUT, D G Division of Licensing 83/09/22 PALLADINO, N J,
GILINSKY, V, ROBERTS, T M Commissioners 3pp 20682 356 24X
Fiche 50-289, 83/09/22, 831010246
- B31010556 Forwards marked-up copy of draft NUREG-1020, "GPU vs B&W Lawsuit Review & Effects on TMI-1" W/o encl
THOMPSON, H L Division of Human Factors Safety 83/09/22
EISENHUT, D G Division of Licensing 1p 20777 107 24X
Fiche 50-289, 83/09/22, 831010556
- B31010630 Forwards comments on NUREG-1020 re GPU vs B&W lawsuit review & effects on TMI-1 Errors in App B should be corrected to reflect findings concerning relevance & materiality of lawsuit documents
MATTSO, R J Division of Systems Integration (post B11005)
83/09/22 EISENHUT, D G Division of Licensing 3pp 20714 278 24X
Fiche 50-289, 83/09/22, 831010630
- B310030571 Board Notification B3-138A informs of change to previously stated position in NUREG-0680, Suppl 2 KCS leak rate tests contain inadequacies & deviations from regulatory & procedural requirements
EISENHUT, D G Division of Licensing 83/09/23 PALLADINO, N,
GILINSKY, V, ROBERTS, T M Commissioners 5pp 20607 323 24X
Fiche 50-289, 83/09/23, 8310030571
- B310120057 Forwards IE/Region 1 comments re Subj Area 5 of NUREG-1020 "GPU vs B&W Lawsuit Review & Effect on TMI-1," constituting concurrence w/NUREG
TAYLOR, J M Division of QA, Safeguards & Inspection Programs (Post B30103) 83/09/23 EISENHUT, D G Division of Licensing 1p
20749 354 24X Fiche 50-289, 83/09/23, 8310120057
- B310130155 Discusses review of addl GPU vs B&W lawsuit documents No changes to original SER necessary
MATTSO, R J Division of Safety Technology 83/09/23
EISENHUT, D G Division of Licensing 2pp 20777 178 24X
Fiche 50-289, 83/09/23, 8310130155
- B310030103 Informs of plans to perform analytical evaluation of natural circulation cooldown (Generic Ltr B1-21) w/o formation of voids in upper head using NEIRAN computer code, in response to B30720 ltr Analysis will be completed in Dec 1983
HUKILL, H D General Public Utilities - GPU Service Corp 83/09/26
STOLZ, J F Operating Reactors Branch 4 1p 20590 055 24X
Fiche 50-289, 83/09/26, 8310030103
- B310030620 Advises that encl B&W rept, "Response to GPU Nuclear Questions Concerning HPI Actuation at TMI-2 About 5 41 AM on 790320," completed assessment of EDS Nuclear analysis Rept provided to util on B30904 & to NRC on B30915
DIRCKS, W J Office of the Executive Director for Operations
83/09/26 PALLADINO, N Commissioners 3pp 20626 351 24X
Fiche 50-289, 83/09/26, 8310030620
- B310030622 Requests B&W be contacted to determine necessary steps for B&W to complete review & to prepare formal rept
PALLADINO, N J Commissioners 83/09/06 DIRCKS, W J Office of
the Executive Director for Operations 1p 20626 314 24X
Fiche 50-289, 83/09/26, 8310030620
- B310120054 Concurs in draft NUREG-1020 "GPU vs B&W Lawsuit Review & Effect on TMI-1"
VOLLMEYER, R M Division of Engineering 83/09/26 RUSSELL, W T NRC
- No Detailed Affiliation Given 1p 20749 355 24X
Fiche 50-289, 83/09/26, 8310120054
- B310120051 Advises that comments re NUREG-1020 "GPU vs B&W Lawsuit Review & Effect on TMI-1" were faxed to R Capra on 830920
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/09/27 EISENHUT, D G Division of
Licensing 1p 20713 327 24X Fiche 50-289, 83/09/27, 8310120051
- B310120060 Forwards NUREG-1020 "GPU vs B&W Lawsuit & Effect on TMI-1" Distribution of Category 10 section "Mgt Competence/Integrity" should be limited pending Oic of Investigations completion of investigation
DIRCKS, W J Office of the Executive Director for Operations
83/09/28 PALLADINO, N J Commissioners 2p 20715 367 24X
Fiche 50-289, 83/09/28, 8310120060

DOCKETED ITEMS

111

- 8310030403 Forwards GPU news release & EH Stier 830924 ltr to GPU commenting on Ofc of Investigations rept, "TMI-2 Allegations re Safety-Related Mads, GA Procedures & Use of Polar Crane " Svc list encl
BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, F L
Metropolitan Edison Co 83/09/29 EDLES, G J, BUCK, J H, KUHL, C N
Atomic Safety and Licensing Board Panel 13pp 20601 211 24X
Fiche 50-289, 83/09/29, 8310030403
- 8310040392 Advises that 830929 ltr wrongly captioned Unit 2 instead of Unit 1 Documents being sent for Commission use include press release & records on B&W vs GPU lawsuit review Svc list encl
BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, F L
Metropolitan Edison Co 83/09/30 EDLES, G J, BUCK, J H, KUHL, C N
Atomic Safety and Licensing Board Panel 219pp 20619 181 24X
Fiche 50-289, 83/09/30, 8310040392
- 8310060390 Discusses results of 810705 testing of onsite safety related electrical distribution sys Acceptability of voltage conditions & undervoltage relay setting on safety electric distribution sys reconfirmed
HUKILL, H D General Public Utilities - GPU Service Corp 83/09/30
STOLZ, J F Operating Reactors Branch 4 5pp 20646 054 24X
Fiche 50-289, 83/09/30, 8310060390
- 8310070076 Forwards response to 830825 safety evaluation on plant return to svc w/ repaired steam generators
HUKILL, H D General Public Utilities - GPU Service Corp 83/09/30
STOLZ, J F Operating Reactors Branch 4 7pp 20658 248 24X
Fiche 50-289, 83/09/30, 8310070076
- 8310070082 Rev 2 to Procedure TDR 406, "Steam Generator Tube Rupture Procedure Guidelines "
* General Public Utilities - GPU Service Corp 83/08/12 79pp
20658 255 24X Fiche 50-289, 83/09/30, 8310070076
- 8310270369 Responds to FOIA request for EECY-83-278 & SECY-83-270, transmitting B30624 "Rept on Adequacy & Safety of Relief Valve Testing & Performance " Forwards requested documents
FELTON, J M Division of Rules and Records 83/10/04 WEISS, F R
Union of Concerned Scientists 1p 20743 129 24X
Fiche 50-289, 83/10/04, 8310270369
- 8307270430 Forwards revised certification & noncertification status tables per B30622 request Table 1 revised to clarify insp status of certification items for which insp previously noted as not applicable
DIRCKS, W J Office of the Executive Director for Operations
SECY-83-278 83/07/11 43pp 20743 130 24X
Fiche 50-289, 83/10/04, 8310270369
- 8310110200 Provides results of preliminary evaluation of steam generator hot test program Completed series of cooldowns to place axial loads associated w/ operating transients on repaired steam generator tubes described
NILSON, R F General Public Utilities - GPU Service Corp 83/10/05
STOLZ, J F Operating Reactors Branch 4 2pp 20665 306 24X
Fiche 50-289, 83/10/05, 8310110200
- 8310170304 Forwards Amend 87 to License DPR-50 & safety evaluation Amend adds limiting conditions of operation & surveillance requirements for hydrogen recombiner sys per restart requirements
VAN VLIET, J Operating Reactors Branch 4 83/10/05 HUKILL, H D
General Public Utilities - GPU Service Corp 4pp 20796 226 24X
Fiche 50-289, 83/10/05, 8310170304
- 8310170307 Amend 87 to License DPR-50, adding limiting conditions of operation & surveillance requirements for hydrogen recombiner sys per restart requirements
STOLZ, J F Operating Reactors Branch 4 83/10/05 7pp
20796 230 24X Fiche 50-289, 83/10/05, 8310170304
- 8310170311 Safety evaluation supporting Amend 87 to License DPR-50
* Office of Nuclear Reactor Regulation, Director 83/10/05 2pp
20796 236 24X Fiche 50-289, 83/10/05, 8310170304
- 8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ ASCO solenoid valves
EISENHUT, D G Division of Licensing 83/10/06 PALLADINO, N J,
GILINSKY, V, ROBERTS, T M Commissioners 31pp 20818 001 24X
Fiche 50-000, 83/10/06, 8308300771
- 8310120395 Forwards info INPD provided to util at INPD conference of chief executive officers TMI-1 rated as average or in top one-sixth of all operating plants in US Svc list encl
BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, F L
Metropolitan Edison Co 83/10/06 EDLES, G J, BUCK, J H, KUHL, C N
Atomic Safety and Licensing Appeal Panel 48pp 20699 057 24X
Fiche 50-289, 83/10/06, 8310120395
- 8310170695 Staff requirements memo re B31006 briefing on results of GPU vs B&W trial matl & other uncontested matters re TMI-1 restart Commission made no requests & took no action
CHILK, S J Office of the Secretary of the Commission 83/10/06
Office of the Secretary of the Commission 1p 20798 158 24X
Fiche 50-289, 83/10/06, 8310170695
- 8310180092 Ack receipt of 830715 request for info concerning open issues re mgt integrity identified in 830519 & 0715 memos to Commission NRC evaluation of open issues proceeding w/ exception of GPU vs B&W lawsuit record
DIRCKS, W J Office of the Executive Director for Operations
83/10/07 DIECKAMP, H General Public Utilities - GPU Service Corp
1p 20824 125 24X Fiche 50-289, 83/10/07, 8310180092
- 8310180099 Requests NRC provide identification & evaluation of specific concerns remaining or developed as result of evaluation of open issues Also requests all related recent insp repts & basis for concern in other areas
DIECKAMP, H General Public Utilities - GPU Service Corp
83/07/15 DIRCKS, W J Office of the Executive Director for Operations 4pp 20824 128 24X Fiche 50-289, 83/10/07, 8310180092
- 8310140251 Requests extension to Mar 1984 for response to Item 2 & 2 of Generic Ltr B3-28, "Required Action Based on Generic Implications of Salem ATWS Events " Response to all other items will be submitted by 831108
HUKILL, H D General Public Utilities - GPU Service Corp 83/10/10
EISENHUT, D G Office of Nuclear Reactor Regulation, Director 1p
20761 331 24X Fiche 50-289, 83/10/10, 8310140251
- 8310310476 Approves request for withholding Rev 3 to B&W Topical Rept 00B, "Assessment of TMI-1 Plant Safety for Return to Svc After Steam Generator Repair" (ref 10CFR2 790)
STOLZ, J F Operating Reactors Branch 4 83/10/11 HUKILL, H D
General Public Utilities - GPU Service Corp 5pp 20945 183 24X
Fiche 50-289, 83/10/11, 8310310476
- 8310180347 Comments on NUREG-1020 re GPU vs B&W lawsuit review NRC did not make reasonable technical judgments, leaving issues that should have been resolved re mgt integrity as issues potentially involving integrity
DIECKAMP, H General Public Utilities - GPU Service Corp 83/10/14
PALLADINO, N J, ASSELSTINE, J K, BERNYHAL, F Commissioners 35pp
20804 301 24X Fiche 50-289, 83/10/14, 8310180347
- 8310260334 Forwards Amend 88 to License DPR-50 & safety evaluation Amend revises Tech Spec to ref new liquid effluent discharge monitor RM-112 in lieu of presently referenced monitor RM-6
VAN VLIET, J Operating Reactors Branch 4 83/10/14 HUKILL, H D
General Public Utilities - GPU Service Corp 5pp 20921 172 24X
Fiche 50-289, 83/10/14, 8310260334
- 8310260339 Amend 88 to License DPR-50, revising Tech Spec to ref new liquid effluent discharge monitor RM-112 in lieu of presently referenced monitor RM-6
STOLZ, J F Operating Reactors Branch 4 83/10/14 8pp
20921 177 24X Fiche 50-289, 83/10/14, 8310260334
- 8310260342 Safety evaluation supporting Amend 88 to License DPR-50
* Office of Nuclear Reactor Regulation, Director 83/10/14 8pp
20921 185 24X Fiche 50-289, 83/10/14, 8310260334
- 8310280172 Responds to appeal re partial denial of FOIA request for correspondence between Chairman Palladino & DDJ re investigation of alleged falsification of RCS leak rate tests Info partially withheld (ref FOIA Exemption 3)
CHILK, S J Office of the Secretary of the Commission 83/10/14,
VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 2pp 20965 057 24X
Fiche 50-289, 83/10/14, 8310280172
- 8310280179 Comments on questions raised in B30517 ltr to Chairman Palladino re communication between agencies DDJ should commit to completion date for investigation Supporting documentation encl
CUMMINGS, J J Office of Inspector & Auditor 83/05/31
JENSEN, D L Justice, Dept of App 20965 064 24X
Fiche 50-289, 83/10/14, 8310280172
- 8310210085 Advises that commitments to resolve each apparent deficiency indicated in Table 4-1 of 821210 technical evaluation rept on environ qualification will be provided in Jan 1984
HUKILL, H D General Public Utilities - GPU Service Corp 83/10/17
STOLZ, J F Operating Reactors Branch 4 1p 20857 275 24X
Fiche 50-289, 83/10/17, 8310210085
- 8310280143 Requests review of encl draft restart licensing conditions Public meeting following review suggested to receive addl info & to discuss comments on wording
STOLZ, J F Operating Reactors Branch 4 83/10/17 HUKILL, H D
General Public Utilities - GPU Service Corp 17pp 20965 102 24X
Fiche 50-289, 83/10/17, 8310280143

DOCKETED ITEMS

8310200211 Forwards INPD evaluations on util mgt Svc list encl
BLAKE, E L Shaw, Pittman, Potts & Trowbridge 83/10/18 EDLES, G J
Atomic Safety and Licensing Appeal Panel 47pp 20832 351 24X
Fiche 50-000, 83/10/18, 8310200211

8310210249 Forwards corrected pages to INPD rept provided on 831010
BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, E L
Metropolitan Edison Co 83/10/17 EDLES, G J, BUCK, J H, KO, H, C N
Atomic Safety and Licensing Appeal Panel 6pp 20851 049 24X
Fiche 50-000, 83/10/17, 8310210249

8310250261 Forwards addl info re NRC Safety Issue B-24, "Purge Valve
Operability," per NRC 830708 request Items from NRC 830708
ltr requiring amend to Tech Specs will be forwarded as rev
to Tech Spec Change Request 116 by separate ltr
HUKILL, H D General Public Utilities - GPU Service Corp 83/10/17
STOLZ, J F Operating Reactors Branch 4 22pp 20898 247 24X
Fiche 50-289, 83/10/17, 8310250261

8310310489 Summary of 830826 meeting w/B&W Owners Group re
implementation of Generic Ltr 83-28 concerning defenses
against ATWS & proposed ATWS rule for B&W plants List of
attendees & viewgraphs encl
KADAMBI, P Operating Reactors Branch 4 83/10/20 Operating
Reactors Branch 4 13pp 20963 147 24X Fiche 50-000, 83/10/20,
8310310489

8310260143 Requests guidance re reportability of BEIA & RHR repts
Inter-off memo describing reporting obligations for util
employees encl
CLARK, P R General Public Utilities - GPU Service Corp 83/10/21
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
20919 243 24X Fiche 50-289, 83/10/21, 8310260143

8310270130 Requests review & concurrence w/proposed post-accident
shielding alternate solution mod (NUREG-037, Item 1) B 21,
per 830521 & 0615 responses to Generic Ltr 82-05
HUKILL, H D General Public Utilities - GPU Service Corp 83/10/21
STOLZ, J F Operating Reactors Branch 4 6pp 20945 022 24X
Fiche 50-289, 83/10/21, 8310270130

8310280108 Forwards application for amend to License DPR-50 consisting
of Tech Spec Change Request 134 changing manager, plant
training, THI-1 position to manager, plant training, THI
HUKILL, H D General Public Utilities - GPU Service Corp 83/10/21
STOLZ, J F Operating Reactors Branch 4 1p 20929 209 24X
Fiche 50-289, 83/10/21, 8310280108

--8310280115 Application for amend to License DPR-50, consisting of Tech
Spec Change Request 134 changing manager, plant training,
THI-1 position to manager, plant training, THI
HUKILL, H D General Public Utilities - GPU Service Corp 83/10/21
83/10/21 4pp 20929 210 24X Fiche 50-289, 83/10/21, 8310280115

8310310410 Forwards B&W Owners Group Analysis Committee/Conc
Performance Committee Rept "Bounding Analytical Assessment
of NUREG-0630 Models on LOCA kW/ft Limits W/Use of FLECSSET"
HUKILL, H D General Public Utilities - GPU Service Corp 83/10/21
NOVAK, T Assistant Director for Licensing 1p 20961 001 24X
Fiche 50-289, 83/10/21, 8310310410

--8310310413 "Bounding Analytical Assessment of NUREG-0630 Models on
LOCA kW/ft Limits W/Use of FLECSSET"
Babcock & Wilcox Operating Plants Owners Group 77-1140898-01
83/09/30 104pp 20961 002 24X Fiche 50-289, 83/10/21,
8310310410

8310280123 Responds to 830912 ltr re fuel mgt plan for Cycle 6 &
estimated schedules for fuel mgt plans used to meet
pressurized thermal shock flux reduction Commit to in-out-
in fuel mgt plan
HUKILL, H D General Public Utilities - GPU Service Corp 83/10/24
EISENHUT, D O Division of Licensing 2pp 20929 264 24X
Fiche 50-289, 83/10/24, 8310280123

Inspection reports, IE Bulletins & correspondence

83070298 Appeals denial of FOIA request for placement of IE
Investigation Rept 1-83-003 in PDR.
KILCOYNE, J J, Kilcoyne, J J 83/05/31, Office of the Secretary
of the Commission 1p 20942 356 24X Fiche 50-289, 83/05/31,
83070298

1040061 Board Notification 83-132 forwards NRC 830725 ltr & IF Insp
rpt 50-289/83-13 re emergency preparedness open items
EISENHUT, D O Division of Licensing 83/09/09 PALLADINO, N
LINSKY, P, ROBERTS, T Commissioners 4pp 20640 338 24X
Fiche 50-289, 83/09/09, 831040061

8310200218 Forwards IE Insp Rpts 50-289/83-18 & 50-320/83-10 on
830622-24 & 0711-20 & notice of violation
MARTIN, T T Region 1, Office of Director 83/09/14 KANGA, E K
General Public Utilities - GPU Service Corp 2pp 20830 123 24X
Fiche 50-289, 83/09/14, 8310200218

--8310200237 Notice of violation from insp on 830622-0720
* Region 1, Office of Director 83/09/14 1p 20630 115 24X
Fiche 50-289, 83/09/14, 8310200218

--8310200270 IE Insp Rpts 50-289/83-18 & 50-320/83-10 on 830622-24 &
0711-20 Noncompliance noted failure to perform quarterly
fire brigade training
PALLADINO, R, PLISLO, L, ANDERSON, C J Region 1, Office of Director
83/09/06 19pp 20830 126 24X Fiche 50-289, 83/09/14,
8310200218

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder
Qualification Tests." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
Detectors Positioned at Control Room Ventilation Air
Intakes." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse
Type SA-1 Differential Relays." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310140162 Forwards IE Insp Rept 50-289/83-22 on 830719-0829 No
noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/09/27
HUKILL, H D General Public Utilities - GPU Service Corp 2pp
20765 078 24X Fiche 50-289, 83/09/27, 8310140162

--8310140166 IE Insp Rept 50-289/83-22 on 830719-0829, No noncompliance
noted Major areas inspected licensee action on previous insp
findings & shutdown plant operations for steam generator
post-repair testing & restart valve lineups
CONTE, R, BAUNACK, W, BELL, J Region 1, Office of Director
83/09/26 10pp 20765 080 24X Fiche 50-289, 83/09/27, 8310140162

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to
Safety-Related Sys W/o 10CFR50.59 Evaluation." Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New
York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310270304 Responds to appeal re denial of FOIA request for II
Investigation Rept 1-83-003 Forwards document Document also
available in PDR Portions of rept withheld (ref FOIA
Exemptions 5 & 7)
CHILK, S J Office of the Secretary of the Commission 83/10/03
KILCOYNE, J J Kilcoyne, J J 2pp 20942 359 24X
Fiche 50-289, 83/10/03, 8310270304

--8310270324 IE Investigation Rept 1-83-003 on 830123-0211 Status closed
Major area investigated alleged compromise of preemployment
psychological exams
CHRISTOPHER, R, HAYES, D B Office of Investigation 83/02/25
58pp 20942 361 24X Fiche 50-289, 83/10/03, 8310270304

8310180366 Act receipt of 830916 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-289/83-19
MARTIN, T T Division of Engineering & Technical Programs 83/10/05
HUKILL, H D General Public Utilities - GPU Service Corp 1p
20803 182 24X Fiche 50-289, 83/10/05, 8310180366

--8310180372 Responds to NRC 830817 ltr re violations noted in IE Insp
Rept 50-289/83-19 Corrective actions production & QC
personnel retrained in requirements for proper
installation & insp of supports
HUKILL, H D General Public Utilities - GPU Service Corp
83/09/16 MURLEY, T E Region 1, Office of Director 2pp
20803 183 24X Fiche 50-289, 83/10/05, 8310180366

8308300378 IE Info Notice 83-65, "Surveillance of Flow in R1D Bypass
Loops Used in Westinghouse Plants." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

DOCKETED ITEMS

113

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20682 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310210280 Ack receipt of 831005 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-289/83-23
MARTIN, T T Division of Engineering & Technical Programs 83/10/14
HUKILL, H D General Public Utilities - GPU Service Corp 2pp
20848 213 24X Fiche 50-289, 83/10/14, 8310210280

--8310210283 Responds to NRC 830902 ltr re violations noted in IE Insp Rept 50-289/83-23 Corrective actions production personnel will be instructed to obtain engineering evaluation & direction prior to anchor installation
HUKILL, H D General Public Utilities - GPU Service Corp 83/10/05
MURLEY, T E Region 1, Office of Director 2pp
20848 215 24X Fiche 50-289, 83/10/14, 8310210280

R Periodic operating reports & related correspondence

8310120125 Forwards "TMI Aquatic Study, Monthly Rept for Aug 1983 "
REGSLER, W C General Public Utilities - GPU Service Corp 83/10/07
HICKEY, C NRC - No Detailed Affiliation Given 1p 20696 126
24X Fiche 50-289, 83/10/07, 8310120125

--8310120128 "TMI Aquatic Study, Monthly Rept for Aug 1983 "
NARDACCI, G A Ichthyological Associates, Inc 83/08/31 10pp
20696 127 24X Fiche 50-289, 83/10/07, 8310120125

8310120360 Submits quarterly update of steam generator long-term corrosion test program All four test loops at normal operating temp for Cycles 2 & 4 Two add'l cycles will be run on each loop & should be completed by 840515
HUKILL, H D General Public Utilities - GPU Service Corp 83/10/07
STOLZ, J F Operating Reactors Branch 4 2pp 20699 321 24X
Fiche 50-289, 83/10/07, 8310120360

8310140108 Submits annual replica simulator status rept per 810027 partial initial decision on mgt issues Contract for simulator awarded to Singer-Link Corp Delivery expected 831223
HUKILL, H D General Public Utilities - GPU Service Corp 83/10/10
STOLZ, J F Operating Reactors Branch 4 1p 20766 110 24X
Fiche 50-289, 83/10/10, 8310140108

8310120037 Monthly operating rept for Sept 1983 W/831014 ltr
HUKILL, H D, SMYTH, C W General Public Utilities - GPU Service Corp 83/10/14
MCDONALD, W C Office of Administration 7pp
20855 323 24X Fiche 50-289, 83/10/14, 8310120037

S Reportable occurrences, LERs & related correspondence

8310200008 RO 83-25 on 830916, containment isolation valve found open while containment integrity required No threat to health & safety since second boundary remained closed Cause & corrective actions expected in 14-day followup rept
TOOLE, R J General Public Utilities - GPU Service Corp 83/09/19
MURLEY, T E Region 1, Office of Director 1p 20830 234 24X
Fiche 50-289, 83/09/19, 8310200008

8310200011 RO 83-26 on 830917-18, all main steam safety valves tested All but one valve lifted above allowed lift point tolerance of +1% of setpoint Caused by using incorrect main steam header
TOOLE, R J General Public Utilities - GPU Service Corp 83/09/19
MURLEY, T E Region 1, Office of Director 1p 20830 235 24X
Fiche 50-289, 83/09/19, 8310200011

8310200061 LER 83-019/03L-0 on 830823, flow to condenser exhaust monitor RM-A3 shut off when valve inadvertently closed Caused by personnel error flow restored Responsible individuals instructed W/830922 ltr
SZCZECHE, R A, HUKILL, H D General Public Utilities - GPU Service Corp 83/09/22
MURLEY, T E Region 1, Office of Director 4pp
20834 001 24X Fiche 50-289, 83/09/22, 8310200061

8310190161 LER 83-023/99X-0 on 830827, while locally checking control rod drive breakers prior to closing disconnect switches, one breaker indicated closed by mechanical indicator Caused by worn breaker operating mechanism W/830926 ltr
STEPHENSON, C J, HUKILL, H D General Public Utilities - GPU Service Corp 83/09/26
MURLEY, T E Region 1, Office of Director 4pp
20821 052 24X Fiche 50-289, 83/09/26, 8310190161

8310190164 LER 83-020/03L-0 on 830826, while taking once per shift readings, operator found no sample flow to condenser exhaust monitor Caused by moisture condensing in monitor sample line flow increased to blow out moisture W/830926 ltr
SZCZECHE, R A, HUKILL, H D General Public Utilities - GPU Service Corp 83/09/26
MURLEY, T E Region 1, Office of Director 3pp
20821 062 24X Fiche 50-289, 83/09/26, 8310190164

8310250253 LER 83-021/03L-0 on 830825, outbuildings auxiliary operator observed no flow rate on outlet valve RM-L-7 Caused by corrosion clogging valve Piping will be replaced w/stainless steel to prevent recurrence W/830930 ltr
SZCZECHE, R A, HUKILL, H D General Public Utilities - GPU Service Corp 83/09/30
MURLEY, T E Region 1, Office of Director 4pp
20898 228 24X Fiche 50-289, 83/09/30, 8310250253

8310250589 LER 83-025/01T-0 on 830915, during once-through steam generator testing, 3/4-inch vent valve which serves as containment isolation valve found open Caused by personnel error Operators counseled W/830930 ltr
STEPHENSON, C J, HUKILL, H D General Public Utilities - GPU Service Corp 83/09/30
MURLEY, T E Region 1, Office of Director 3pp
20901 250 24X Fiche 50-289, 83/09/30, 8310250589

8310070263 RO 83-032 on 830930, thermal & seismic stress criteria on instrument tubes not met Fatigue characteristics revealed allowable number of cycles exceeds actual number of heatup & cooldown cycles experienced
TOOLE, R J General Public Utilities - GPU Service Corp 83/10/03
MURLEY, T E Region 1, Office of Director 2pp 20651 058 24X
Fiche 50-289, 83/10/03, 8310070263

8310250552 RO 83-032 both thermal & seismic stress on instrument tubes reevaluated as followup to internal matl nonconformance rept Operability stresses below ASME III criteria revealed
TOOLE, R J General Public Utilities - GPU Service Corp 83/10/03
MURLEY, T E Region 1, Office of Director 2pp 20900 312 24X
Fiche 50-289, 83/10/03, 8310250552

8310250430 LER 83-026/01T-0 on 830919, while testing main steam safety valves, all valves except one lifted above allowed lift setpoint tolerance of +1% Caused by personnel error which resulted in defective procedure W/831004 ltr
KNIGHT, M R, HUKILL, H D General Public Utilities - GPU Service Corp 83/10/04
MURLEY, T E Region 1, Office of Director 3pp
20897 032 24X Fiche 50-289, 83/10/04, 8310250430

8310250606 LER 83-028/01T-0 on 830920, manual inside containment isolation valve IA-V20 in instrument air sys found open Caused by threaded stem bushing backed partially out of yoke & paint buildup on stem Parts replaced W/831004 ltr
SZCZECHE, R A, HUKILL, H D General Public Utilities - GPU Service Corp 83/10/04
MURLEY, T E Region 1, Office of Director 4pp
20900 154 24X Fiche 50-289, 83/10/04, 8310250606

8310250294 LER 83-024/99X-0 on 830827, while in cold shutdown condition, engineered safeguards actuation sys actuation relay 8321B/RB2A coil found smoking Probably caused by end of coil life or incomplete pull-in of armature W/831010 ltr
KNIGHT, M R, HUKILL, H D General Public Utilities - GPU Service Corp 83/10/10
MURLEY, T E Region 1, Office of Director 5pp
20899 008 24X Fiche 50-289, 83/10/10, 8310250294

T Hearing transcripts on non-antitrust matters

8310130372 Transcript of 831006 briefing in Washington, DC re results of GPU & B&W trial matl Pp 1-42 Supporting documentation encl
* Commissioners 83/10/06 41pp 20770 052 24X
Fiche 50-289, 83/10/06, 8310130372

8310200189 Transcript of 831017 prehearing conference re steam generator repair in Harrisburg, PA Pp 1-129
* Atomic Safety and Licensing Board Panel 83/10/17 182pp
20833 077 24X Fiche 50-289, 83/10/17, 8310200189

V Operator Examinations

8310070309 Forwards changes to licensed operator requalification program, per 820106 meeting Program to be consistent w/ current NRC exam administration Exams will be administered on 831208, 09 & 10
HUKILL, H D General Public Utilities - GPU Service Corp 82/12/02
BECKHAM, D K Operator Licensing Branch 4pp 20652 215 24X
Fiche 50-289, 82/12/02, 8310070309

DOCKETED ITEMS

DOCKET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8310180479 Application for amend to License DPR-35 consisting of Proposed Change B3-11 to Tech Specs Proposed mod should be treated as third segment of seven submittals addressing fire protection issue Requests single amend be issued
HARRINGTON, W D Boston Edison Co 83/10/13 VASSALLO, D B
Operating Reactors Branch 2 2pp 20003 158 24X
Fiche 50-293, 83/10/13, 8310180479

--8310180483 Proposed Change B3-11 to Tech Specs re Halon 1301 fire protection sys. App A, Section 3 12
* Boston Edison Co 83/10/13 5pp 20803 160 24X
Fiche 50-293, 83/10/13, 8310180479

8310180435 Forwards Rev 0 to "Detailed Control Room Design Review Program Plan, per NUREG-0737, Suppl 1 (Generic Ltr 82-33)
HARRINGTON, W D Boston Edison Co 83/10/14 VASSALLO, D B
Operating Reactors Branch 4 1p 20803 358 24X
Fiche 50-293, 83/10/14, 8310180435

--8310180438 Rev 0 to Procedure 2 2 11/040983, "Detailed Control Room Design Review Program Plan."
* Boston Edison Co 83/10/31 100pp 20803 359 24X
Fiche 50-293, 83/10/14, 8310180435

G Adjudicatory correspondence

8310040481 Petition of JF Doherty to intervene & request for hearing on util requested amend to License DPR-35 re operation w/one recirculation loop out of svc Certificate of Svc encl
DOHERTY, J F Doherty, J F 83/09/30 Commissioners 3pp
20623 120 24X Fiche 50-293, 83/09/30, 8310040481

8310250286 Response supporting JF Doherty 830930 petition to intervene & for public hearing Standing established based on location of residence, vacation activities in Cape Cod & consumption of fish from Massachusetts Bay W/Certificate of Svc
CHAN, E I Hearing Branch 2 83/10/20 Atomic Safety and Licensing Board Panel 7pp 20895 337 24X Fiche 50-293, 83/10/20, 8310250286

8310260305 Notice of ASLO constitution, BP Cotter, chairman & GA Linenberger & OH Paris, members
COTTER, D P Atomic Safety and Licensing Board Panel 83/10/21
2pp 20910 326 24X Fiche 50-293, 83/10/21, 8310260305

K Utility Final Safety Analysis Report (FSAR) & amends

8310250544 Forwards Rev 3 to updated FSAR Rev outlines intention to update Chapter 14 & App 0 List of errors identified since 830719 submittal encl Errors will be corrected in 840722 Rev 4
HARRINGTON, W D Boston Edison Co 83/10/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20902 345 24X
Fiche 50-293, 83/10/11, 8310250544

--8310250549 Rev 3 to updated FSAR
* Boston Edison Co 83/09/30 180pp 20902 346 24X
Fiche 50-293, 83/10/11, 8310250544

P Operating license stage documents & correspondence

8310070045 Forwards mod to 810113 & 820119 orders extending completion date to 850221 for installation of mods to torus catwalk extension support legs & ring girder to torus shell welds
VASSALLO, D B Operating Reactors Branch 2 83/09/22
HARRINGTON, W D Boston Edison Co 3pp 20671 330 24X
Fiche 50-293, 83/09/22, 8310070045

--8310070048 Mod of 810113 & 820119 orders extending completion date for installation of design mods from mid Lyrle 7 mod outage to before restart
EISENHUT, D G Division of Licensing 83/09/22 Boston Edison Co 5pp 20671 333 24X Fiche 50-293, 83/09/22, 8310070045

8310070045 Extension to Apr 1984 to comply w/final rule re 1M1 "Chief Maining" Justification for
83/09/27 DENTON, H R Office of
3pp 20592 340 24X

8310120307 Forwards latest change to NPLB permit effective 830700, per request
HARRINGTON, W D Boston Edison Co 83/10/05 VASSALLO, D B
Operating Reactors Branch 2 45pp 20700 320 24X
Fiche 50-293, 83/10/05, 8310120307

8310120330 Requests that open time limit on 20-inch containment purge vent valves be extended to 160 h to allow for possibility of operational problems during planned outage & any unscheduled outages required prior to 831210 shutdown
HARRINGTON, W D Boston Edison Co 83/10/07 VASSALLO, D B
Operating Reactors Branch 2 2pp 20700 265 24X
Fiche 50-293, 83/10/07, 8310120330

8310180491 Application to amend License DPR-35 containing Proposed Change B3-10 to Tech Specs re administrative changes to nuclear operations organization
HARRINGTON, W D Boston Edison Co 83/10/12 VASSALLO, D B
Operating Reactors Branch 2 4pp 20801 196 24X
Fiche 50-293, 83/10/12, 8310180491

8310180479 Application for amend to License DPR-35 consisting of Proposed Change B3-11 to Tech Specs Proposed mod should be treated as third segment of seven submittals addressing fire protection issue Requests single amend be issued
HARRINGTON, W D Boston Edison Co 83/10/13 VASSALLO, D B
Operating Reactors Branch 2 2pp 20803 158 24X
Fiche 50-293, 83/10/13, 8310180479

--8310180483 Proposed Change B3-11 to Tech Specs re Halon 1301 fire protection sys. App A, Section 3 12
* Boston Edison Co 83/10/13 5pp 20803 160 24X
Fiche 50-293, 83/10/13, 8310180479

8310260437 Notification of Significant License Meeting 83-40 on 831017 in King of Prussia, PA to discuss refueling outage plans
VASSALLO, D B Region 1, Office of Director 83/10/20 Region 1, Office of Director 1pp 20926 335 24X Fiche 50-293, 83/10/20, 8310260437

8310310144 Provides agenda & list of util attendees for upcoming meeting, per 831020 commitment Meeting topics include status of long-term program license amend & update of refueling outage schedule
HARRINGTON, W D Boston Edison Co 83/10/25 VASSALLO, D B
Operating Reactors Branch 2 2pp 20959 009 24X
Fiche 50-293, 83/10/25, 8310310144

8310310290 Forwards draft procedure "Single Loop Operation Greater than 24 H" Flow bias derived from recirculation pump flow measurement idle loop automatically accounted for in flow bias
HARRINGTON, W D Boston Edison Co 83/10/25 VASSALLO, D B
Operating Reactors Branch 2 12pp 20961 148 24X
Fiche 50-293, 83/10/25, 8310310290

8310310306 Responds to 830906 request to reevaluate position on NUREG-0737, Item II E 4 2(7) Monitor capable of promptly & reliably providing isolation signal would not be sufficiently sensitive to detect release rates
HARRINGTON, W D Boston Edison Co 83/10/25 VASSALLO, D B
Operating Reactors Branch 2 2pp 20961 227 24X
Fiche 50-293, 83/10/25, 8310310306

Q Inspection reports, IE Bulletins & correspondence

8308300740 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Wilder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300740

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 119pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

DOCKETED ITEMS

115

8310070321 Forwards minutes of 830831 mgt meeting w/uttl in Plymouth, MA re progress rpt on implementation of performance improvement program Procedure revs will be revalidated after station receipt of design document update packages
STAROSTECKI, R Division of Project & Resident Programs 83/09/30
HARRINGTON, W D Boston Edison Co 5pp 20652 172 24X
Fiche 50-293, 83/09/30, 8310070321

8308300378 IE Info Notice 83-65, "Surveillance of Flow in H/D Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 74pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 076 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310270225 Ack receipt of 83090/ ltr informing NRC of steps taken to correct violations noted in IL Insp Rept 50-293/83-17
MARTIN, T T Division of Engineering & Technical Programs 83/10/20
HARRINGTON, W D Boston Edison Co 2pp 20924 074 24X
Fiche 50-293, 83/10/20, 8310270225

--8310270230 Responds to NRC 830815 ltr re violations noted in IL Insp Rept 50-293/83-13 Corrective actions Tech Spec change being prepared to clarify review & approval of vendor (supplier) procedures Change expected by 831101
HARRINGTON, W D Boston Edison Co 83/09/07 STAROSTECKI, R Division of Project & Resident Programs 1p 20924 076 24X
Fiche 50-293, 83/10/20, 8310270230

R Periodic operating reports & related correspondence

8309190140 Monthly operating rept for Aug 1983 W/830913 ltr
WHITNEY, G O HARRINGTON, W D Boston Edison Co 83/09/13
Director's Office, Office of Inspection and Enforcement 7pp
20410 142 24X Fiche 50-293, 83/09/13, 8309190140

8310180111 Monthly operating rept for Sept 1983 W/831012 ltr
HAMILTON, P HARRINGTON, W D Boston Edison Co 83/09/30
Director's Office, Office of Inspection and Enforcement 7pp
20800 164 24X Fiche 50-293, 83/09/30, 8310180111

S Reportable occurrences, LIRs & related correspondence

8310200226 Telecopy LER 83-047/01X-0 on 830913, recirculation pump low-low water trip relay (16AKBA) found smoking Power deenergized Failure of relay contacts due to coating of smoke & varnish Relay replaced
WHITNEY, G O Boston Edison Co 83/09/15 Region 1, Office of Director 1p 20833 039 24X Fiche 50-293, 83/09/15, 8310200226

8310190174 LER 83-047/01T-0 on 830913, recirculation pump A low-low water level trip relay 16A-KBA found smoking Caused by overheated relay coil Relay replaced W/830927 ltr
WHITNEY, G O HARRINGTON, W D Boston Edison Co 83/09/27 Region 1, Office of Director 3pp 20820 204 24X Fiche 50-293, 83/09/27, 8310190174

8310060051 PNO-I-83-100 on 830929, potential overpressurization of low pressure piping at pump suction occurred Event attributed to malfunctioning check valve Seal leak repaired Valve apparently stuck partially open
JOHNSON, J GALLO, R Region 1, Office of Director 83/09/30 1p
20647 077 24X Fiche 50-293, 83/09/30 8310060051

8310280045 LER 83-048/01X-0 on 830929, while conducting HPCI logic surveillance, HPCI high suction pressure alarm & HPCI area smoke detector alarm received Caused by leaking in-line check valve in HPCI pump discharge line
WHITNEY, G O Boston Edison Co 83/09/30 Region 1, Office of Director 1p 20929 008 24X Fiche 50-293, 83/09/30 8310280045

8310250137 LER 83-049/02L-0 on 830909, during steady-state operation, recirculation pump A MG set inadvertently tripped While changing out generator brushes on A MG set brush pigtail inadvertently shorted out W/831005 ltr
WHITNEY, G O HARRINGTON, W D Boston Edison Co 83/10/05 Region 1, Office of Director 2pp 20896 346 24X Fiche 50-293, 83/10/05, 8310250137

8310140082 PNO-I-83-105 on 831007, seismic event occurred in northeastern US w/magnitude of 5.2 on Richter scale in NY & 4.0 in NH No damage to equipment identified
GALLO, R M Region 1, Office of Director 83/10/07 1p 20766 116 24X Fiche 50-000, 83/10/07, 8310140082

8310290282 LER 83-048/01T-0 on 830929, while conducting investigation into apparent overpressure condition in HPCI sys, turbine stop valve would not operate Caused by failed coil in turbine stop valve Coil replaced W/831014 ltr
WHITNEY, G O HARRINGTON, W D Boston Edison Co 83/10/14 Region 1, Office of Director 4pp 20894 255 24X Fiche 50-293, 83/10/14, 8310290282

DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8310110004 Responds to FOIA request for five documents Forwards documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/07/01 PEDRO, J NUS Corp 2pp 20704 137 24X Fiche 50-000, 83/07/01, 8310110004

--8310110010 "Appraisal of Fire Effects from Aircraft Crash At Zion Power Reactor Facility"
PINKEL, I J Atomic Energy Commission 72/07/17 35pp
20704 139 24X Fiche 50-000, 83/07/01, 8310110010

8310140173 Ack receipt of 831003 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/83-13 & 50-304/83-13
SHAFER, W D Region 3, Office of Director 83/10/06 REED, C Commonwealth Edison Co 1p 20765 001 24X Fiche 50-295, 83/10/06, 8310140173

--8310140175 Responds to NRC 830829 ltr re violations noted in IE Insp Repts 50-295/83-13 & 50-304/83-13 Corrective actions surveillance conducted on fire pump diesel engine & starting 12-volt battery bank & charger
LENTINE, F O Commonwealth Edison Co 83/10/03 KEPPNER, J O Region 3, Office of Director 2pp 20765 002 24X
Fiche 50-295, 83/10/06, 8310140175

8310240087 Forwards IE Insp Repts 50-295/83-17 & 50-304/83-18 on 830810-0920 & notice of violation
NOELIUS, C E Division of Project & Resident Programs 83/10/07
REED, C Commonwealth Edison Co 2pp 20880 348 24X
Fiche 50-295, 83/10/07, 8310240087

--8310240096 IE Insp Repts 50-295/83-17 & 50-304/83-18 on 830810-0920 Noncompliance noted Unit 2 operated w/diesel generators 2A, 2B & C inoperable on 830704-11 & 21-27, contrary to surveillance requirements
WATERS, J R DUNAWAY, F R HARTMANN, P L Region 3, Office of Director 83/10/04 11pp 20880 352 24X Fiche 50-295, 83/10/07, 8310240087

8310210374 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/17 Document Management Branch 1p 20882 349 24X Fiche 50-295, 83/10/17, 8310210374

--8310210377 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 360-4, "Radiation Sampling Under Accident Conditions " W/830926 ltr, receipt form & procedure change request form
PLIML, G Commonwealth Edison Co 03/09/22 DENTON, H R NRC - No Detailed Affiliation Given 6pp 20882 350 24X
Fiche 50-295, 83/10/17 8310210374

8310270526 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20927 216 24X Fiche 50-000, 83/10/21, 8310270526

--8310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure EPIP-4 "Administration & Logistics Manager " W/831017 ltr & receipt form
NELLIS, C A Commonwealth Edison Co 83/02/18 DENTON, H R NRC - No Detailed Affiliation Given 7pp 20927 217 24X
Fiche 50-000, 83/10/21 8310270537

DOCKETED ITEMS

8310280307 Releases public version of revised generating station emergency plan telephone directory
FELTON, J M Division of Rules and Records 83/10/25 Document
Management Branch 1p 20963 126 24X Fiche 50-000, 83/10/25,
8310280307

--8310280314 Public version of revised generating stations emergency plan telephone directory
GALLE, D P Commonwealth Edison Co 83/08/11 DENIUN, H R Office of Nuclear Reactor Regulation, Director 64pp 20963 127 24X Fiche 50-000, 83/10/25, 8310280307

8310280191 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/26 Document
Management Branch 1p 20962 266 24X Fiche 50-000, 83/10/26,
8310280191

--8310280209 Public version of Rev 1 to Emergency Plan Implementing Procedure EDF-15, "Emergency Operations Facility Activation"
MOORE, R D Commonwealth Edison Co 83/08/02 50pp 20962 267 24X Fiche 50-000, 83/10/26, 8310280191

P Operating license stage documents & correspondence

8310130415 Forwards FR notice of consideration of issuance of amendments to Licenses DPR-39 & DPR-48 to permit operation w/outly three of four primary coolant loops in svc
VARQA, S A Operating Reactors Branch 1 83/09/23 FARRAR, D L Commonwealth Edison Co 2pp 20769 008 24X Fiche 50-295, 83/09/23
8310130415

--8310130416 Notice of consideration of issuance of amendments to Licenses DPR-39 & DPR-48 & proposed NSIC determination & opportunity for hearing
VARQA, S A Operating Reactors Branch 1 83/09/23 4pp 20769 010 24X Fiche 50-295, 83/09/23, 8310130415

8310110117 Suppl to 830808 request for amend to Licenses DPR-39 & DPR-48, revising Tech Specs re containment leakage test acceptance criteria Info clarifies 10C1K50 App J calculations
LENTINE, F G Commonwealth Edison Co 83/10/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 20667 169 24X Fiche 50-295, 83/10/05, 8310110117

8310170042 Forwards request for addl info re use of optimized fuel assembly Response required to complete evaluation
VARQA, S A Operating Reactors Branch 1 83/10/05 FARRAR, D L Commonwealth Edison Co 4pp 20812 130 24X Fiche 50-295, 83/10/05, 8310170042

8310200273 Forwards schedules for equipment qualification test programs for facilities, per 810520 ltr Dates given for current qualification activities should be viewed as "target dates" & not as firm dates
BARNES, P L Commonwealth Edison Co 83/10/05 KEPLER, J G Region 3, Office of Director 10pp 20830 034 24X Fiche 50-000, 83/10/05, 8310200273

8310200151 Application for immediate & temporary amend to Licenses DPR-39 & DPR-48, changing Tech Specs to allow preventive maint to be performed on shared diesel generator Q during current refueling outage
LENTINE, F G Commonwealth Edison Co 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 20836 282 24X Fiche 50-295, 83/10/14, 8310200151

8310310049 Forwards response to NRC 831006 request for addl info re 830822 application for license amend to permit use of optimized fuel assemblies Structural analysis of mixed reactor core during seismic event encl
LENTINE, F G Commonwealth Edison Co 83/10/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 14pp 20931 131 24X Fiche 50-295, 83/10/21, 8310310049

8310310060 Submits info re Edison rod swap analysis method for review & approval Methods employed in support of control rod worth measurements using rod swap technique during reload physics testing Criteria tables encl
LENTINE, F G Commonwealth Edison Co 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 20951 024 24X Fiche 50-000, 83/10/24, 8310310060

Q Inspection reports, IE Bulletin & correspondence

8310110454 Forwards safety evaluation & technical evaluation rept re util responses to IE Bulletin 80-11, "Masonry Wall Design"
Requests actions planned & scheduled for resolution of issue within 30 days
VARQA, S A Operating Reactors Branch 1 83/09/12 FARRAR, D L Commonwealth Edison Co 4pp 20712 197 24X Fiche 50-295, 83/09/12, 8310110454

-8308030016 Revised "Masonry Wall Design (B-59), Zion Units 1 & 2," technical evaluation rept
SUBRAMONIAN, N Franklin Institute/Franklin Research Center NRC-03-B1-130 IER-C5506-243 R01 83/07/27 CHOKSHI, N C NRC No Detailed Affiliation Given 25pp 20712 202 24X Fiche 50-295, 83/09/12, 8310110454

8308300340 IE Info Notice 83-61, "Alleged Use of Stand Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62 "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 119pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310200124 Forwards IE Mgt Meeting Repts 50-010/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIUS, C E Division of Project & Resident Programs 83/10/04 REED, C Commonwealth Edison Co 2pp 20834 098 24X Fiche 50-000, 83/10/04, 8310200124

--8310200148 IE Mgt Meeting Repts 50-020/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-37, 50-456/83-14 & 50-457/83-13
NORELIUS, C E Division of Project & Resident Programs 83/10/03 4pp 20834 100 24X Fiche 50-000, 83/10/04, 8310200124

8310140173 Ack receipt of 831003 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/83-13 & 50-304/83-13
SHAFFER, W D Region 3, Office of Director 83/10/06 REED, C Commonwealth Edison Co 1p 20765 001 24X Fiche 50-295, 83/10/06, 8310140173

--8310140175 Responds to NRC 830829 ltr re violations noted in IE Insp Repts 50-295/83-13 & 50-304/83-13 Corrective actions surveillance conducted on fire pump diesel engine & starting 12-volt battery bank & charger
LENTINE, F G Commonwealth Edison Co 83/10/03 KEPLER, J G Region 3, Office of Director 4pp 20765 002 24X Fiche 50-295, 83/10/06, 8310140173

8308300378 IE Info Notice 83-65, "Surveillance of Flow in R10 Outputs Loops Used in Westinghouse Plants" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300352 IE Info Notice 83-66, "Fatality at Argentine Critical Facility" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300352

8310240087 Forwards IE Insp Repts 50-295/83-17 & 50-304/83-18 on 830810-0920 & notice of violation
NORELIUS, C E Division of Project & Resident Programs 83/10/07 REED, C Commonwealth Edison Co 2pp 20880 348 24X Fiche 50-295, 83/10/07, 8310240087

DOCKETED ITEMS

117

--8310240091 Notice of violation from insp on 830810-0920
NORELIUS, C E Division of Project & Resident Programs 83/10/07
2pp 20880 350 24X Fiche 50-295, 83/10/07, 8310240087

--8310240096 IE Insp Repts 50-295/83-17 & 50-304/83-18 on 830810 0920
Noncompliance noted Unit 2 operated w/diesel generators
2A, 2B & Q inoperable on 830704-11 & 21-27, contrary to
surveillance requirements
WATERS, J R, DUNAWAY, F R, HARTMANN, P L Region 3, Office of
Director 83/10/04 11pp 20880 332 24X Fiche 50-295, 83/10/07,
8310240087

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect
Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective
Self-Contained Breathing Apparatus Air Cylinders " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180110 Advises that plans & schedule for resolution of horizontal
joint reinforcing, per IE Bulletin 80-11, "Masonry Walls" &
NRC 830912 ltr, will be provided by 831111 Util presently
examining design of 18 walls affected by issue
LENTINE, F G Commonwealth Edison Co 83/10/12 DENTON, H R Office
of Nuclear Reactor Regulation, Director 1p 20802 258 24X
Fiche 50-295, 83/10/12, 8310180110

8310180283 Clarifies NRC position re procedures for admitting NRC
personnel to facilities List of personnel requiring access
to vital areas encl Updates will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 REED, C
Commonwealth Edison Co 7pp 20801 115 24X Fiche 50-295, 83/10/14,
8310180283

R Periodic operating reports & related correspondence

8310120108 Monthly operating repts for Sept 1983 W/831007 ltr
AUSTIN, O, GRAESSER, K L Commonwealth Edison Co 83/10/07
Director's Office, Office of Inspection and Enforcement 12pp
20696 228 24X Fiche 50-295, 83/10/07, 8310120108

S Reportable occurrences, LEAs & related correspondence

8310110430 Responds to FOIA request for four different categories of
documents described in 830910 ltr Forwards matl listed in
App A responsive to Items 1, 2 & 4 DOE should be contacted
for matl requested in Item 3 of ltr
FELTON, J M Division of Rules and Records 83/06/14 HIATT, S L
Ohio Citizens for Responsible Energy 3pp 20706 002 24X
Fiche 50-000, 83/06/14, 8310110430

--8310110478 Responds to 830413 ltr requesting info re use of foreign
matls on valve seating surfaces Lubricants & cleaning
solvents used on valve component surfaces per vendor
recommendations & maint practices
FARRAR, D L Commonwealth Edison Co 83/04/22 KEPLER, J G
Region 3, Office of Director 4pp 20706 063 24X
Fiche 50-000, 83/06/14, 8310110430

8310120174 LER 83-034/03L-0 on 830911, MSIV IC closure time exceeded
5 s during MSIV full closure test Valve closed in 31 s
Caused by nitrogen precharge leak in closing side of
accumulator Precharge restored W/830928 ltr
DAJIC, Z, GRAESSER, K L Commonwealth Edison Co 83/09/28
KEPLER, J G Region 3, Office of Director 2pp 20696 001 24X
Fiche 50-295, 83/09/28, 8310120174

8310170588 Updated LER 82-047/03X-1 on 821205, RCS loop C indication
changed, delta temp pegged low & average temp pegged high
Caused by failed resistance temp detector (RTD) Rosemount
175AF RTD replaced W/831006 ltr
PETRAK, T G, GRAESSER, K L Commonwealth Edison Co 83/10/06
KEPLER, J G Region 3, Office of Director 2pp 20780 231 24X
Fiche 50-295, 83/10/06, 8310170588

8310170561 LER 83-036/03L-0 on 830910, during hot shutdown, penetration
pressurization Zone 4 found below allowable Tech Spec
limit of 47 psig Caused by leak in buried channel weld Weld
channel isolated W/831007 ltr
KELLY, T, GRAESSER, K L Commonwealth Edison Co 83/10/07
KEPLER, J G Region 3, Office of Director 2pp 20780 225 24X
Fiche 50-295, 83/10/07, 8310170561

8310270289 LER 83-038/03L-0 on 830921, during refueling recalibr, Loop A
of reactor coolant flow transmitter IFT-414 found out of
tolerance Caused by instrumentation zero shift Transmitter
recalibr & returned to svc W/831021 ltr
WILHITE, M, GRAESSER, K L Commonwealth Edison Co 83/10/21
KEPLER, J G Region 3, Office of Director 2pp 20923 233 24X
Fiche 50-295, 83/10/21, 8310270289

8310270384 PNO-111-83-102 on 831020, security officer received bomb
threat phone call from unidentified male Shift engineer
instituted emergency procedures Search of vital areas
conducted w/negative results Threat determined hoax
DELANGER, J, CREED, J Region 3, Office of Director 83/10/21 1p
20923 287 24X Fiche 50-295, 83/10/21, 8310270384

T Hearing transcripts on non-antitrust matters

8310110004 Responds to FOIA request for five documents Forwards
documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/07/01, PEDRO, J NUS
Corp 2pp 20704 137 24X Fiche 50-000, 83/07/01, 8310110004

--8310110011 Testimony of DQ Eisenhut re Zion/Haukegan Airport
interaction
Atomic Energy Commission 83/07/01 10pp 20704 174 24X
Fiche 50-000, 83/07/01, 8310110004

DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8310210032 Forwards IE Safeguards Insp Repts 50-259/83-26, 50-260/83-26
& 50-296/83-26 on 830706-07 & notice of violation Notice
of violation withheld (ref 10CFR73 21)
O'REILLY, J P Region 2, Office of Director 83/09/01 PARRIS, H G
Tennessee Valley Authority 2pp 20855 320 24X
Fiche 50-259, 83/09/01, 8310210032

--8310210034 IE Safeguards Insp Repts 50-259/83-26, 50-260/83-26 &
50-296/83-26 on 830706-07 Noncompliance noted in area of
access control - vital areas Details withheld
(ref 10CFR73 21)
MOORE, D E Region 2, Office of Director 83/07/29 1p
20855 322 24X Fiche 50-259, 83/09/01, 8310210032

8310040452 Submits central emergency control ctr meteorological data
availability statistics for Apr-June 1983 Data availability
repts will be discontinued due to consistently high data
availability through previous rept periods
MILLS, L M Tennessee Valley Authority 83/07/28 ADENSAH, E
Licensing Branch 4 2pp 20623 326 24X Fiche 50-000, 83/09/28,
8310040452

8310110195 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/10/05 Document
Management Branch 1p 20682 113 24X Fiche 50-259, 83/10/05,
8310110195

--8310110199 Forwards public version of revised emergency plan
implementing procedures, including Procedures IP-3 re alert,
IP-4 re site area emergency & IP-5 re general emergency
MILLS, L M Tennessee Valley Authority 83/07/12 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 20682 114
24X Fiche 50-259, 83/10/05, 8310110195

--8310110203 Public version of revised emergency plan implementing
procedures, including Procedures IP-3 re alert, IP-4 re site
area emergency & IP-5 re general emergency
WEBB, W E Tennessee Valley Authority 83/04/07 168pp
20682 115 24X Fiche 50-259, 83/10/05, 8310110195

8310310387 Forwards revs to security plan Revs withheld
(ref 10CFR73 21)
MILLS, L M Tennessee Valley Authority 83/10/06 O'REILLY, J P
Region 2, Office of Director 1p 20959 327 24X
Fiche 50-259, 83/10/06, 8310310387

8310170189 Forwards IE Safeguards Insp Repts 50-259/83-37, 50-260/83-37
& 50-296/83-37 on 830927-30 No noncompliance noted
VERRELLI, D Division of Project & Resident Programs 83/10/12
PARRIS, H G Tennessee Valley Authority 2pp 20786 358 24X
Fiche 50-259, 83/10/12, 8310170189

--8310170238 IE Safeguards Insp Repts 50-259/83-37, 50-260/83-37 &
50-296/83-37 on 830927-30 No noncompliance noted Major areas
inspected security organization & mgt & personnel response
Details withheld (ref 10CFR73 21)
MOORE, D E Region 2, Office of Director 83/10/11 1p
20786 360 24X Fiche 50-259, 83/10/12, 8310170189

DOCKETED ITEMS

- 8310240139 Forwards safety evaluation re proposed mods & alternate capabilities for achieving safe shutdown, per 10CFR50, App R, Sections III G 3 & III L, Fire protection rule Proposed mods acceptable
VASSALLO, D B Operating Reactors Branch 2 83/10/12 PARRIS, H G Tennessee Valley Authority 2pp 20884 342 24X
Fiche 50-259, 83/10/12, 8310240139
- 8310240141 Safety evaluation supporting proposed mods & alternate capabilities for achieving safe shutdown, per 10CFR50, App R, Sections III G 3 & III L, Fire protection rule
* Office of Nuclear Reactor Regulation, Director 83/10/12 7pp 20884 344 24X Fiche 50-259, 83/10/12, 8310240139
- 8310210071 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26
O'REILLY, J P Region 2, Office of Director 83/10/17 PARRIS, H G Tennessee Valley Authority 1p 20858 192 24X
Fiche 50-259, 83/10/17, 8310210071
- 8310210078 Responds to NRC 830901 ltr re violations noted in IE Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26 Corrective actions withheld (ref 10CFR73 21)
MILLS, L M Tennessee Valley Authority 83/09/30 O'REILLY, J P Region 2, Office of Director 1p 20858 193 24X
Fiche 50-259, 83/10/17, 8310210071
- 8310210362 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/17 Document Management Branch 1p 20883 001 24X Fiche 50-259, 83/10/17, 8310210362
- 8310210383 Forwards public version of revised emergency plan implementing procedures, including Muscle Shoals Emergency Ctr Implementing Procedure MSEC IP-9, "Emergency Radiological Monitoring Procedures"
MILLS, L M Tennessee Valley Authority 83/10/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20883 002 24X Fiche 50-259, 83/10/17, 8310210362
- 8310210386 Public version of revised emergency plan implementing procedures, including Muscle Shoals Emergency Ctr Implementing Procedure MSEC IP-9, "Emergency Radiological Monitoring Procedures"
* Tennessee Valley Authority 83/09/22 150pp 20883 003 24X
Fiche 50-259, 83/10/17, 8310210362
- P Operating license stage documents & correspondence
- 8310060583 Comments on proposed design for compliance w/NUREG-073, Item II K 3 13, "Separate HPCI & RCIC Initiation Levels" re automatic restart Proposal acceptable
VASSALLO, D B Operating Reactors Branch 2 83/09/19 PARRIS, H G Tennessee Valley Authority 3pp 20661 204 24X
Fiche 50-259, 83/09/19, 8310060583
- 8310070068 Requests submittal of final radiological effluent Tech Specs & offsite dose calculation manual within 30 days
VASSALLO, D B Operating Reactors Branch 2 83/09/21 PARRIS, H G Tennessee Valley Authority 3pp 20671 334 24X
Fiche 50-259, 83/09/21, 8310070068
- 8310110521 Forwards Amends 90, 86 & 59 to Licenses DPR-33, DPR-52 & DPR-68, respectively & safety evaluation Amends change Tech Specs to modify required surveillance interval for standby gas treatment sys
CLARK, R J Operating Reactors Branch 2 83/09/28 PARRIS, H G Tennessee Valley Authority 3pp 20711 302 24X
Fiche 50-259, 83/09/28, 8310110521
- 8310110536 Amends 90, 86 & 59 to Licenses DPR-33, DPR-52 & DPR-68, respectively, revising Tech Specs for testing standby gas treatment sys from once per yr to once per operating cycle
VASSALLO, D B Operating Reactors Branch 2 83/09/28 12pp 20711 303 24X Fiche 50-259, 83/09/28, 8310110521
- 8310110551 Safety evaluation supporting Amends 90, 86 & 59 to Licenses DPR-33, DPR-52 & DPR-68, respectively
* Office of Nuclear Reactor Regulation, Director 83/09/28 3pp 20711 317 24X Fiche 50-259, 83/09/28, 8310110521
- 8310240154 Forwards request for addl info re reactor protection sys power monitoring sys design mod, per 831030 request Model Tech Specs for electric power monitoring & analysis drawings, not provided Submittal date requested
VASSALLO, D B Operating Reactors Branch 2 83/10/12 PARRIS, H G Tennessee Valley Authority 3pp 20884 329 24X
Fiche 50-259, 83/10/12, 8310240154
- 8310240243 Forwards SER & technical evaluation rept re NUREG-0737, Item I A 2 1 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & I B 4, "Training for Mitigating Core Damage" Requirements met
VASSALLO, D B Operating Reactors Branch 2 83/10/12 PARRIS, H G Tennessee Valley Authority 4pp 20891 123 24X
Fiche 50-259, 83/10/12, 8310240243
- 8308310352 "Improvements In Training & Requalification Programs As Required By TMI Action Items I A 2 1 & I B 4 for Browns Ferry Nuclear Plants, Units 1, 2 & 3," technical evaluation rept
* Science Applications, Inc NRC-03-82-096 SAI-186-029-50 82/08/25 NRC - No Detailed Affiliation Given 15pp 66280 216 24X Fiche 50-000, 83/10/12, 8310240243
- 8310280148 Forwards "Analysis of Vessel Wall Neutron Dosimeter From Browns Ferry Units 1, 2 & 3 Pressure Vessel," in response to NRC request for addl info to support until 830922 request to change Tech Specs TS 191
MILLS, L M Tennessee Valley Authority 83/10/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 17pp 20729 063 24X Fiche 50-259, 83/10/19, 8310280148
- 8310280151 "Analysis of Vessel Wall Neutron Dosimeter From Browns Ferry Unit 3 Pressure Vessel"
NORRIS, E B, LINDHOLM, U S Southwest Research Institute 79/09/30 74pp 20929 137 24X Fiche 50-259, 83/10/19, 8310280148
- Q Inspection reports, IE Bulletins & correspondence
- 8310250229 Updates 830624 response to violations noted in IE Insp Repts 50-259/83-14, 50-260/83-14 & 50-296/83-14 Extension of schedule to eliminate backlog of CARs/LRs until 830901 requested
MILLS, L M Tennessee Valley Authority 83/08/08 O'REILLY, J P Region 2, Office of Director 1p 20699 067 24X
Fiche 50-259, 83/08/08, 8310250229
- 8310210032 Forwards IE Safeguards Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26 on 830706-07 & notice of violation Notice of violation withheld (ref 10CFR73 21)
O'REILLY, J P Region 2, Office of Director 83/09/01 PARRIS, H G Tennessee Valley Authority 2pp 20855 320 24X
Fiche 50-259, 83/09/01, 8310210032
- 8310210034 IE Safeguards Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26 on 830706-07 Noncompliance noted in area of access control - vital areas Details withheld (ref 10CFR73 21)
MOORE, D C Region 2, Office of Director MCGUIRE, D R Division of Engineering & Operational Programs 83/07/29 1p 20855 322 24X Fiche 50-259, 83/09/01, 8310210032
- 8310040265 Ack receipt of 830824 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-24, 50-260/83-24 & 50-296/83-24
VERRELLI, D M Region 2, Office of Director 83/09/14 PARRIS, H G Tennessee Valley Authority 1p 20613 124 24X
Fiche 50-259, 83/09/14, 8310040265
- 8310040271 Responds to NRC 830725 ltr re violations noted in IE Insp Repts 50-259/83-24, 50-260/83-24 & 50-296/83-24 Corrective actions LMT examiners barred from performing addl intergranular stress corrosion cracking exams
MILLS, L M Tennessee Valley Authority 83/08/24 O'REILLY, J P Region 2, Office of Director 3pp 20613 124 24X
Fiche 50-259, 83/09/14, 8310040265
- 8310040275 Forwards IE Insp Repts 50-259/83-24, 50-260/83-24 & 50-296/83-24 on 830621-24 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/07/25 PARRIS, H G Tennessee Valley Authority 2pp 20613 127 24X
Fiche 50-259, 83/09/14, 8310040265
- 8310040283 IE Insp Repts 50-259/83-24, 50-260/83-24 & 50-296/83-24 on 830621-24 Noncompliance noted failure to follow IE Bulletin 83-02 for requiring documented training in intergranular stress corrosion cracking
COLEY, J L Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/07/21 4pp 20613 130 24X Fiche 50-259, 83/09/14, 8310040265
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20734 022 24X Fiche 50-000, 83/09/26, 8308300340

DOCKETED ITEMS

119

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 11pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300343 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 11pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300343

8310040487 Concurs w/corrective actions taken to rectify violations noted in IE Insp Repts 50-259/83-18, 50-260/83-18 & 50-296/83-18 Acceptable finding permits initiation of fuel movement in & out of core
O'REILLY, J P Region 2, Office of Director 83/09/26 PARRIS, H O Tennessee Valley Authority 2pp 20625 165 24X Fiche 50-259, 83/09/26, 8310040487

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/b 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 11pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310250166 Ack receipt of 830926 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-27, 50-260/83-27 & 50-296/83-27
LEWIS, R C Division of Project & Resident Programs 83/10/04 PARRIS, H O Tennessee Valley Authority 1p 20893 251 24X Fiche 50-259, 83/10/04, 8310250166

--8310250170 Responds to NRC 830824 ltr re violations noted in IE Insp Repts 50-259/83-27, 50-260/83-27 & 50-296/83-27 Corrective actions test pressure gauges removed, fuse identification program being established & panel 25-32 cleaned
MILLS, L M Tennessee Valley Authority 83/09/26 O'REILLY, J P Region 2, Office of Director 7pp 20893 252 24X Fiche 50-259, 83/10/04, 8310250166

--8310250174 Forwards IE Insp Repts 50-259/83-27, 50-260/83-27 & 50-296/83-27 on 830626-0725 & notices of violation & deviation
LEWIS, R C Division of Project & Resident Programs 83/08/24 PARRIS, H O Tennessee Valley Authority 2pp 20893 261 24X Fiche 50-259, 83/10/04, 8310250166

--8310250179 Notice of violation from insp on 830626-0725
* Region 2, Office of Director 83/08/24 3pp 20893 263 24X Fiche 50-259, 83/10/04, 8310250166

--8310250185 Notice of deviation from insp on 830626-0725
* Region 2, Office of Director 83/08/24 1p 20893 266 24X Fiche 50-259, 83/10/04, 8310250166

--8310250190 IE Insp Repts 50-259/83-27, 50-260/83-27 & 50-296/83-27 on 830626-0725 Noncompliances noted failure to meet requirements for operational safety & absence of safety wires on backup control ctr
PAULK, G L Region 2, Office of Director CANTRELL, F S Division of Project & Resident Programs 83/08/19 10pp 20893 267 24X Fiche 50-259, 83/10/04, 8310250166

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 7pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 7pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8310250131 Ack receipt of 830816 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-11, 50-260/83-11 & 50-296/83-11
LEWIS, R C Division of Project & Resident Programs 83/10/07 PARRIS, H O Tennessee Valley Authority 1p 20897 272 24X Fiche 50-259, 83/10/07, 8310250131

--8310250138 Responds to NRC 830726 ltr re violations noted in IE Insp Repts 50-259/83-11, 50-260/83-11 & 50-296/83-11 Corrective actions radiochemical lab manual revised to incorporate Reg Guide 4.15 interim guidance
MILLS, L M Tennessee Valley Authority 83/08/16 O'REILLY, J P Region 2, Office of Director 3pp 20897 273 24X Fiche 50-259, 83/10/07, 8310250131

8310250234 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-28, 50-260/83-28 & 50-296/83-28
VERRELLI, D M Division of Project & Resident Programs 83/10/07 PARRIS, H O Tennessee Valley Authority 1p 20899 123 24X Fiche 50-259, 83/10/07, 8310250234

--8310250240 Responds to NRC 830901 ltr re violations noted in IE Insp Repts 50-259/83-28, 50-260/83-28 & 50-296/83-28 Corrective actions requirements for receipt insp of OA-level matl established & wire brushes marked
MILLS, L M Tennessee Valley Authority 83/09/30 O'REILLY, J P Region 2, Office of Director 4pp 20899 124 24X Fiche 50-259, 83/10/07, 8310250234

--8310250247 Forwards IE Insp Repts 50-259/83-28, 50-260/83-28 & 50-296/83-28 on 830725-29 & 0808 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/09/01 PARRIS, H O Tennessee Valley Authority 2pp 20899 128 24X Fiche 50-259, 83/10/07, 8310250234

--8310250259 IE Insp Repts 50-259/83-28, 50-260/83-28 & 50-296/83-28 on 830725-29 & 0808 Noncompliance noted failure of receiving insps to control welding filler matls & to establish positive controls for tools used on austenitic steel
COLEY, J L Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/08/29 7pp 20899 132 24X Fiche 50-259, 83/10/07, 8310250234

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 11pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 12pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310170189 Forwards IE Safeguards Insp Repts 50-259/83-37, 50-260/83-37 & 50-296/83-37 on 830927-30 No noncompliance noted
VERRELLI, D Division of Project & Resident Programs 83/10/12 PARRIS, H O Tennessee Valley Authority 2pp 20786 358 24X Fiche 50-259, 83/10/12, 8310170189

--8310170238 IE Safeguards Insp Repts 50-259/83-37, 50-260/83-37 & 50-296/83-37 on 830927-30 No noncompliance noted Major areas inspected security organization & mgt & personnel response. Details withheld (ref 10CFR73 21)
MCQUIRE, D R Region 2, Office of Director 83/10/11 1p 20786 360 24X Fiche 50-259, 83/10/12, 8310170189

8310210071 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26
O'REILLY, J P Region 2, Office of Director 83/10/17 PARRIS, H O Tennessee Valley Authority 1p 20858 192 24X Fiche 50-259, 83/10/17, 8310210071

--8310210078 Responds to NRC 830901 ltr re violations noted in IE Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26 Corrective actions withheld (ref 10CFR73 21)
MILLS, L M Tennessee Valley Authority 83/09/30 O'REILLY, J P Region 2, Office of Director 1p 20858 193 24X Fiche 50-259, 83/10/17, 8310210071

R Periodic operating reports & related correspondence

8310190186 Monthly operating repts for Aug 1983 W/830909 ltr
THOM, T, JONES, O T Tennessee Valley Authority 83/09/01 Office of Resource Management, Director 40pp, 20820 163 24X Fiche 50-259, 83/09/01, 8310190186

B Reportable occurrences, LERs & related correspondence

8310210329 Responds to FOIA request for all documents re significantly high rate of equipment failures for QE DWH/4 rated at 2,436 MW Forwards App A documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/07/28 HAFNER, B, Suffolk Nuclear Study Group 2pp 20882 223 24X Fiche 50-000, 83/07/28, 8310210329

--8302180539 Discusses results of evaluation of LERs for Jul 1981 - Dec 1982, for SAMP reft Quality & quantity of LERs within range of average BWR facility
SEYFRIT, K V Reactor Operations Analysis Branch 83/02/09 LEWIS, R C Division of Project & Resident Programs 3pp 20882 257 24X Fiche 50-000, 83/07/28, 8310210329

DOCKETED ITEMS

8310030376 Telecopy RD on 830919, Surveillance 4 7 A 2 03 determined leakage rates exceeded for MSIV lines A, C & D Caused by leakage past main valve seat Beating surfaces modified JONES, G T Tennessee Valley Authority 83/09/20 Region 2, Office of Director 1p 20592 142 24X Fiche 50-296, 83/09/20, 8310030376

8310060377 LER 83-054/01T-0 on 830919, during refueling outage, while performing leakage test, combined leakage of MSIV lines A, C & D exceeded limit Caused by 26-inch global valve leaking past main seat Valve repaired W/830929 1tr HOLDER, E I, GREEN, H J Tennessee Valley Authority 83/09/29 04REILLY, J P Region 2, Office of Director 3pp 20646 062 24X Fiche 50-296, 83/09/29, 8310060377

8310060407 LER 83-053/03X-0 on 830931, hydrogen analyzer declared inoperable due to loss-of-flow light 76-B Caused by moisture collection in sample lines Lines blown down & dried Sys restored W/830929 1tr GOODWIN, D C, GREEN, H J Tennessee Valley Authority 83/09/29 04REILLY, J P Region 2, Office of Director 3pp 20641 260 24X Fiche 50-296, 83/09/29, 8310060407

8310070301 Potential Part 21 rept re underrange characteristic of Model N-E110M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 044 24X Fiche 50-000, 83/09/30, 8310070301

8310250065 PNO-II-83-084 licensee identified & reported to NRC that contractor welding svc employee received 59 mrem occupational overexposure during Third Quarter 1983 Licensee reviewing all circumstances associated w/event DEBS, B Region 2, Office of Director 83/10/20 1p 20696 085 24X Fiche 50-259, 83/10/20, 8310250065

DOCKET 50-298 COOPER NUCLEAR STATION

F Security, medical, emergency & fire protection plans

8310180156 Forwards IE Insp Rept 50-298/83-11 on 830509-13 No noncompliance noted MADSEN, G L Region 4, Office of Director 83/07/08 PILANT, J M Nebraska Public Power District 2pp 20807 083 24X Fiche 50-298, 83/07/08, 8310180156

--8310180161 IE Insp Rept 50-298/83-11 on 830509-13 No noncompliance noted Major areas inspected radiation protection program during refueling, including procedures, advanced planning & preparation, training, exposure control & ALARA program BAER, R E, MURRAY, D, WESTERMAN, T F Region 4, Office of Director 83/06/28 11pp 20807 085 24X Fiche 50-298, 83/07/08, 8310180156

10070391 Forwards exemption from certain 10CFR50 App R & 10CFR50 4B requirements Level of protection currently provided in conjunction w/proposed mods provides level of fire protection equivalent to requirements of Section III C VASSALLO, D B Operating Reactors Branch 2 83/09/21 KUNCL, L Q Nebraska Public Power District 4pp 20661 008 24X Fiche 50-298, 83/09/21, 8310070391

--8310070393 Exemption from certain 10CFR50 App R & 10CFR50 4B requirements for 3 h fire-rated boundaries for separation of fire areas EISENHUT, D O Division of Licensing 83/09/21 Nebraska Public Power District 12pp 20661 012 24X Fiche 50-298, 83/09/21, 8310070391

0180225 Forwards IE Insp Rept 50-298/83-18 on 830701-0831 & notice of violation ADSEN, G L Region 4, Office of Director 83/09/22 PILANT, J M Nebraska Public Power District 2pp 20808 237 24X Fiche 50-298, 83/09/22, 8310180225

8310180228 Notice of violation from insp on 830701-0831 * Region 4, Office of Director 83/09/22 1p 20808 261 24X Fiche 50-298, 83/09/22, 8310180228

1310180232 IE Insp Rept 50-298/83-18 on 830701-0831, Noncompliance noted failure to assure integrity of fire barrier penetration seal DUBOIS, D L, MUNNICTUTT, D M Region 4, Office of Director 83/09/22 8pp 20808 262 24X Fiche 50-298, 83/09/22, 8310180225

8310200350 Forwards advance notification documentation of shipments of spent nuclear fuel to GE Morris Operation after mid-Oct & per 10CFR73 21 regulations governing safeguards info PILANT, J M Nebraska Public Power District 83/09/26 COLLINS, J R Region 4, Office of Director KEPPLEN, J G Region 3, Office of Director KOHNETSCHER, E Nebraska, State of 7pp 20874 261 24X Fiche 50-298, 83/09/26, 8310200350

8310030358 Urges aggressive pursuit of corrective actions to emergency plan items vital to safety (identified in Enforcement Action 82-16), including item LP-1 re emergency planning coordinator COLLINS, J T Region 4, Office of Director 83/09/28 SHAUPE, RENEGH Nebraska Public Power District 2pp 20592 331 24X Fiche 50-298, 83/09/28, 8310030358

8310310279 Forwards IE Insp Rept 50-298/83-21 on 830821-26 No noncompliance noted JOHNSON, E H Region 4, Office of Director 83/10/14 PILANT, J M Nebraska Public Power District 2pp 20961 290 24X Fiche 50-298, 83/10/14, 8310310279

--8310310286 IE Insp Rept 50-298/83-21 on 830821-26 No noncompliance noted Major areas inspected public info & emergency worker protection portions of emergency response program HACHNEY, C A, DAIRD, J B, MUNNICTUTT, D M Region 4, Office of Director 83/10/14 5pp 20961 292 24X Fiche 50-298, 83/10/14, 8310310279

8310210302 Forwards Rev 3 to implementation schedule in 830415 response to Generic Ltr 82-33, Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability" HEAVER, J D Nebraska Public Power District 83/10/18 SIEGEL, D Operating Reactors Branch 2 3pp 20851 061 24X Fiche 50-298, 83/10/18, 8310210302

P Operating license stage documents & correspondence

8310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR CONNER, L Affiliation Unknown 83/05/02 NRC - No Detailed Affiliation Given 1p 21004 270 24X Fiche 50-000, 83/05/02 8310310017

8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which repts are unavailable FELTON, J M Division of Rules and Records 83/07/06 CONNER, L Affiliation Unknown 1p 21004 271 24X Fiche 50-000, 83/07/06, 8310310031

--8310310056 "Reactor Containment Bldg Integrated Leak Rate Test" * Nebraska Public Power District 76/11/30 250pp 21004 272 24X Fiche 50-000, 83/07/06, 8310310031

8310110178 Proposed Tech Spec Change 5 to License DPR-46, allowing relief from inservice insp requirements of 10CFR50 55a(g) KUNCL, L Q Nebraska Public Power District 83/09/26 VASSALLO, D B Operating Reactors Branch 2 3pp 20665 015 24X Fiche 50-298, 83/09/26, 8310110178

--8310110183 Proposed Tech Spec changes, allowing relief from inservice insp requirements of 10CFR50 55a(g) * Nebraska Public Power District 83/09/26 6pp 20665 018 24X Fiche 50-298, 83/09/26, 8310110178

8310040574 Requests extension to 831101 to meet shift manning criteria of 10CFR50 55 Currently util meets licensed operator criteria on five-shift basis in order to effect improvement in crew training, six-crew rotating shift desired PILANT, J M Nebraska Public Power District 83/09/30 VASSALLO, D B Operating Reactors Branch 2 3pp 20622 275 24X Fiche 50-298, 83/09/30, 8310040574

8310310106 Forwards safety evaluation supporting util response to TMI Item II D 1, "Safety & Relief Valve Testing" Issue resolved VASSALLO, D B Operating Reactors Branch 2 83/07/30 PILANT, J M Nebraska Public Power District 17pp 20777 027 24X Fiche 50-298, 83/09/30, 8310310106

8310180567 Forwards exemption from scheduler requirements of 10CFR50 4v re environ qualification of electrical equipment, per 830624 request VASSALLO, D B Operating Reactors Branch 2 83/10/03 KUNCL, L Q Nebraska Public Power District 2pp 20827 110 24X Fiche 50-298, 83/10/03, 8310180567

DOCKETED ITEMS

121

--B310180572 Exemption from scheduler requirements of 10CFR50 49 re environ qualification of electrical equipment
CASE, E G Office of Nuclear Reactor Regulation, Director
83/10/03 Nebraska Public Power District App 2082/ 112 24X
Fiche 50-298, 83/10/03, B310180569

B310140190 Informs that splice repairs completed on essential sys drywell penetrations, per B30728 commitment Old tape & splices removed & new splices covered w/environmentally-qualified heat shrinkable tubing
PILANT, J M Nebraska Public Power District 83/10/06
VASSALLO, D B Operating Reactors Branch 2 1p 20762 295 24X
Fiche 50-298, 83/10/06, B310140190

B310210101 Informs of decision to refund fee submitted w/B304,4 application for extension of completion date for installation of Mark I mods
MILLER, W O License Fee Management Branch 83/10/17 PILANT, J M
Nebraska Public Power District 2pp 20883 321 24X
Fiche 50-298, 83/10/17, B310210101

Q Inspection reports, IE Bulletins & correspondence

B310180156 Forwards IE Insp Rept 50-298/83-11 on B30507-13 No noncompliance noted
MADSEN, O L Region 4, Office of Director 83/07/08 PILANT, J M
Nebraska Public Power District 2pp 20807 083 24X
Fiche 50-298, 83/07/08, B310180156

--B310180161 IE Insp Rept 50-298/83-11 on B30507-13 No noncompliance noted Major areas inspected radiation protection program during refueling, including procedures, advanced planning & preparation, training, exposure control & ALARA program
BAER, R E, MURRAY, B, WESTENHMAN, I f Region 4, Office of Director
83/06/28 11pp 20807 085 24X Fiche 50-298, 83/07/08, B310180156

B310040348 Forwards response to recommendations presented in IRS Consultants, Inc rept re appraisal of site & corporate nuclear mgt organizations & functions, per B20809 order modifying license
SCHAUFELBERGER Nebraska Public Power District 83/08/15
COLLINS, J T Region 4, Office of Director 38pp 20620 177 24X
Fiche 50-298, 83/08/15, B310040348

B310130206 Forwards IE Insp Rept 50-298/83-22 on B30826-27 No noncompliance noted
MADSEN, O L Region 4, Office of Director 83/09/13 PILANT, J M
Nebraska Public Power District 2pp 20725 012 24X
Fiche 50-298, 83/09/13, B310130206

--B310130211 IE Insp Rept 50-298/83-22 on B30826-27 No noncompliance noted Major areas inspected performance of containment integrated leak rate test & independent review of test results
HUNNICUTT, D M, HALL, R C, MADSEN, O L Region 4, Office of Director 83/09/12 4pp 20725 014 24X Fiche 50-298, 83/09/13, B310130206

B310310310 Confirms BALP B31004 meeting in Columbus, NE
KUNCL, L G Nebraska Public Power District 83/09/16 COLLINS, J T
Region 4, Office of Director 1p 20961 171 24X
Fiche 50-298, 83/09/16, B310310310

B310180225 Forwards IE Insp Rept 50-298/83-18 on B30701-0831 & notice of violation
MADSEN, O L Region 4, Office of Director 83/09/22 PILANT, J M
Nebraska Public Power District 2pp 20808 259 24X
Fiche 50-298, 83/09/22, B310180225

--B310180228 Notice of violation from insp on B30701-0831
* Region 4, Office of Director 83/09/22 1p 20808 261 24X
Fiche 50-298, 83/09/22, B310180225

--B310180232 IE Insp Rept 50-298/83-18 on B30701-0831 Noncompliance noted failure to assure integrity of fire barrier penetration seal
DUBOIS, D L, HUNNICUTT, D M Region 4, Office of Director
83/09/22 8pp 20808 262 24X Fiche 50-298, 83/09/22, B310180225

B308300340 IE Info Notice B3-61, "Alleged Use of Stand-Ins for Wilder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, B308300340

B308300342 IE Info Notice B3-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, B308300342

B308300345 IE Info Notice B3-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, B308300345

B310110178 Proposed Tech Spec Change 5 to License DPN-46, allowing relief from inservice insp requirements of 10CFR50 55a(g)
KUNCL, L G Nebraska Public Power District 83/09/26 VASSALLO, D B
Operating Reactors Branch 2 3pp 20665 015 24X
Fiche 50-298, 83/09/26, B310110178

--B310110183 Proposed Tech Spec changes, allowing relief from inservice insp requirements of 10CFR50 55a(g)
* Nebraska Public Power District 83/09/26 6pp 20665 018 24X Fiche 50-298, 83/09/26, B310110178

B310030358 Urges aggressive pursuit of corrective actions to emergency plan items vital to safety identified in Enforcement Action B2-16, including Item EP-1 re emergency planning coordinator
COLLINS, J T Region 4, Office of Director 83/09/28 SCHAUFELBERGER
Nebraska Public Power District 2pp 20592 331 24X
Fiche 50-298, 83/09/28, B310030358

B308300349 IE Info Notice B3-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, B308300349

B310180471 Provides followup response to IE Bulletin B3-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators," Item 5 Detailed insp of svc water check valve internals showed traces of rust on seating surfaces
KUNCL, L G Nebraska Public Power District 83/09/30 COLLINS, J T
Region 4, Office of Director 2pp 20002 026 24X
Fiche 50-298, 83/09/30, B310180471

B308300378 IE Info Notice B3-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, B308300378

B308300752 IE Info Notice B3-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, B308300752

B308300759 IE Info Notice B3-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, B308300759

B308300761 IE Info Notice B3-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, B308300761

B310180551 Notification of B31021 meeting w/BWR licensors in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking
MIRAGLIA, J J Assistant Director for Safety Assessment 83/10/14
EISENHUT, D G Division of Licensing 5pp 20823 358 24X
Fiche 50-000, 83/10/14, B310180551

B310310279 Forwards IE Insp Rept 50-298/83-21 on B30821-26 No noncompliance noted
JOHNSON, E H Region 4, Office of Director 83/10/14 PILANT, J M
Nebraska Public Power District 2pp 20961 290 24X
Fiche 50-298, 83/10/14, B310310279

--B310310286 IE Insp Rept 50-298/83-21 on B30821-26 No noncompliance noted Major areas inspected public info & emergency worker protection portions of emergency response program
HACKNEY, C A, BAIRD, J B, HUNNICUTT, D M Region 4, Office of Director 83/10/14 5pp 20961 294 24X Fiche 50-298, 83/10/14, B310310279

R Periodic operating reports & related correspondence

B310190024 Monthly operating rept for Aug 1983 H/B30908 1p
BALLINGER, P L, THOMASON, P V Nebraska Public Power District
83/09/08 NRC - No Detailed Affiliation Given 5pp 20822 048 24X Fiche 50-298, 83/09/08, B310190024

DOCKETED ITEMS

B Reportable occurrences, LERs & related correspondence

B310060376 Forwards LER B3-013/03L-0 Detailed event analysis encl
THOMASON, P V Nebraska Public Power District 83/09/27
COLLINS, J T Region 4, Office of Director 6pp 20646 087 24X
Fiche 50-298, 83/09/27, B310060376

--B310060381 LER B3-013/03L-0 on B30831, during local leak rate test,
Procedure 6 3 1 1, 20, penetrations found leaking excessively
Caused by discs & seats being lapped Valves repaired
WALKEN, M A Nebraska Public Power District 83/09/27 Region
4, Office of Director 1p 20646 089 24X Fiche 50-298, 83/09/27,
B310060376

B310070301 Potential Part 21 rept re underdrange characteristic of
Model N-E110M transmitter Underdrange zero offset may occur
when transmitter initially pressurized from atmospheric to
suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office
of Inspection and Enforcement 11pp 20651 064 24X
Fiche 50-000, 83/09/30, B310070301

B310210174 LER B3-014/03L-0 on B30915, during surveillance testing,
pressurization of suppression chamber air space noted during
HPCI turbine operation Caused by error in vacuum breaker
design/installation Breaker replaced W/031012 ltr
MACE, E M THOMASON, P V Nebraska Public Power District 83/10/12
COLLINS, J T Region 4, Office of Director 3pp 20655 123 24X
Fiche 50-298, 83/10/12, B310210174

V Operator Examinations

B310040574 Requests extension to B31101 to meet shift manning criteria
of 10CFR50.59 Currently util meets licensed operator
criteria on five-shift basis in order to effect improvement
in crew training, six-crew rotating shift desired
PILANT, J M Nebraska Public Power District 83/09/30
VASSALLO, D D Operating Reactors Branch 2 3pp 20622 275 24X
Fiche 50-298, 83/09/30, B310040574

DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

B310030141 Advises that B20715 & 0930 requests for NRC to concur w/
intent to move emergency support ctr & associated functions
from Point Beach Energy Info Ctr to Milwaukee unacceptable,
per NUREG-0737, Suppl 1 & Generic Ltr 82-33
EISENHUT, D G Division of Licensing 83/09/14 BURSTEIN, S
Wisconsin Electric Power Co 6pp 20604 033 24X
Fiche 50-266, 83/09/14, B310030141

310030609 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/09/20 Document
Management Branch 1p 20607 036 24X Fiche 50-266, 83/09/20,
B310030609

--B310030616 Forwards public version of revised emergency plan
implementing procedures, including Procedures EPIP 1 3 re
estimation of source term, EPIP 1 4 re radiological dose
evaluation & EPIP 6 2 re plant evacuation
FAY, C W Wisconsin Electric Power Co 83/09/19 BLANTON, H R
Office of Nuclear Reactor Regulation, Director 1p 20607 037
24X Fiche 50-266, 83/09/20, B310030609

--B310030624 Public version of revised emergency plan implementing
procedures, including Procedures EPIP 1 3 re estimation of
source term, EPIP 1 4 re radiological dose evaluation & EPIP
6 2 re plant evacuation
* Wisconsin Electric Power Co 83/09/09 241pp 20607 038 24X
Fiche 50-266, 83/09/20, B310030609

B310210044 Responds to B30914 ltr denying concurrence w/util plans to
move emergency support ctr from Two Creeks, WI to corporate
headquarters in Milwaukee, approx 100 miles from facility
Potential problems overstated by NRC
BURSTEIN, S Wisconsin Electric Power Co 83/10/14 EISENHUT, D G
Division of Licensing 2pp 20655 315 24X Fiche 50-266, 83/10/14,
B310210044

B310310370 Forwards revs to modified amended security plan Revs
withheld (ref 10CFR73.21 & 2 790)
BURSTEIN, S Wisconsin Electric Power Co 83/10/24 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 20961 111 24X
Fiche 50-266, 83/10/24, B310310370

G Adjudicatory correspondence

B310070156 Forwards Director's Decision B3-14, denying B30909 10C1R2 206
petition re transport of spent nuclear fuel from
West Valley
DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director
83/09/30 CIEBREZZE, A J Ohio, State of 2pp 20680 300 24X
Fiche 50-000, 83/09/30, B310070156

--B310070161 Forwards Director's Decision B3-14, denying B30824 10C1R2 206
petition re transport of spent nuclear fuel from
West Valley
DAVIS, J G Office of Nuclear Material Safety &
Safeguards, Director 83/09/30 RESNIKOFF, M Sierra Club 1p
20680 309 24X Fiche 50-000, 83/09/30, B310070156

--B310070167 Notice of issuance of Director's Decision B3-14, denying
State of OH & Sierra Club B30909 & 03-4, respectively,
10CFR2 206 petitions re transport of spent nuclear fuel from
West Valley
DAVIS, J G Office of Nuclear Material Safety &
Safeguards, Director 83/09/30 2pp 20680 310 24X
Fiche 50-000, 83/09/30, B310070156

--B310070171 Director's Decision B3 14, denying State of OH & Sierra Club
B30909 & 0824, respectively, 10C1R2 206 petitions re
transport of spent nuclear fuel from West Valley Request for
hearing & for preparation of GJ, denied
DAVIS, J G Office of Nuclear Material Safety &
Safeguards, Director 83/09/30 18pp 20680 311 24X
Fiche 50-000, 83/09/30, B310070156

B310110274 Informs that licensee will file response to Wisconsin
Environ Decade, Inc petition served on B30923 by B31017 5vc
1st encl
CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge CHURCHILL, B W
Wisconsin Electric Power Co 83/10/07 CHILK, S J Office of the
Secretary of the Commission 4pp 20646 200 24X
Fiche 50-266, 83/10/07, B310110274

B310170493 Answer in opposition to Wisconsin Environ Decade B30923
petition for review of ASLAD B30907 Decision ALAD-139,
affirming ASLAD B30204 authorization for issuance of license
amend Issue not raised before ASLAD Certificate of Svc encl
BACHMANN, R G Hearing Branch 1 B3/10/11 Commissioner 14pp
20784 123 24X Fiche 50-266, 83/10/11, B310170493

B310200102 Response opposing Wisconsin Environ Decade B30923 petition
for review of ALAD-739 re steam generator tubes repaired by
sleeving Nexus between sleeving & tube failure shown
Certificate of Svc encl
CHURCHILL, B W Wisconsin Electric Power Co CHURCHILL, B W Shaw,
Pittman, Potts & Trowbridge 83/10/17 Commissioner's 13pp
20836 350 24X Fiche 50-266, 83/10/17, B310200102

B310190091 Order extending time until B31101 for Commission to act to
review Director's Decision DU B3-13
CHILK, S J Office of the Secretary of the Commission 83/10/18
Commissioners 1p 20822 265 24X Fiche 50-266, 83/10/18,
B310190091

B310260241 Order extending time until B31121 for Commission to act to
review ALAD-739
CHILK, S J Office of the Secretary of the Commission 83/10/14
Commissioners 1p 20909 266 24X Fiche 50-266, 83/10/24,
B310260241

B310270297 Order extending time until B3112H for Commission to act to
review Director's Decision DU-B3-14, denying Sierra Club &
State of OH requests
CHILK, S J Office of the Secretary of the Commission 83/10/16
Commissioners 1p 20923 195 24X Fiche 50-000, 83/10/25,
B310270297

J Insurance & indemnity information

B310110187 Forwards Endorsement 59 to MAIU Policy MI-53 & Endorsement
72 to NEUA Policy NF-178
DUNDAS, W J Wisconsin Electric Power Co 83/10/03 NKC - No
Detailed Affiliation Given 3pp 20665 011 24X
Fiche 50-266, 83/10/03, B310110187

P Operating license stage documents & correspondence

B310110930 "Assessment of Radiation Risks," util-medical dialogue
presented at B00922-23 Intl Inst of Safety & Health
Forum in Washington, DC
LAPP, R L International Institute of Safety & Health 80/09/23
52pp 20714 161 24X Fiche 50-000, 80/09/23, B310110930

DOCKETED ITEMS

123

B310270555 Forwards safety evaluation supporting design of reactor coolant vent sys per requirement of 10 CFR 50.44(c)(3)(iii) & NUREG-0737, Item 11 B 1
MILLER, J R Operating Reactors Branch 3 83/09/22 FAY, C W
Wisconsin Electric Power Co 4pp 20444 003 24X
Fiche 50-266, 83/09/22, B310270555

B310040310 Forwards addl info requested in B30810 telcon re Franklin Research Ctr B3061/ draft technical evaluation rept on util response to Phase 1 of NUREG-0617, "Control of Heavy Loads at Nuclear Power Plants"
FAY, C W Wisconsin Electric Power Co 83/09/28 MILLER, J R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 6pp 20413 096 24X
Fiche 50-266, 83/09/28, B310040310

B310060568 Requests remittance of Class III fee for review of B30708 application for Tech Spec change re component cooling HX insp & maint program
MILLER, W D License Fee Management Branch 83/09/30 FAY, C W
Wisconsin Electric Power Co 1p 20661 247 24X
Fiche 50-301, 83/09/30, B310060568

B310130052 Forwards Amends 74 & 79 to Licenses DPR-24 & DPR-27, respectively & safety evaluation Amend revise degraded grid voltage relay setpoint & associated time delay in Table 15 3 5-1 of Tech Specs
COLBURN, T G Operating Reactors Branch 3 83/09/30 FAY, C W
Wisconsin Electric Power Co 2pp 20776 220 24X
Fiche 50-266, 83/09/30, B310130052

--B310130056 Amends 74 & 79 to Licenses DPR-24 & DPR-27, respectively, revising degraded grid voltage relay setpoint & associated time delay in Table 15 3 5 1 of Tech Specs
MILLER, J R Operating Reactors Branch 3 83/09/30 6pp
20776 222 24X Fiche 50-266, 83/09/30, B310130056

--B310130062 Safety evaluation supporting Amends 74 & 79 to Licenses DPR-24 & DPR-27, respectively
* Office of Nuclear Reactor Regulation, Director 83/09/30 3pp
20776 228 24X Fiche 50-266, 83/09/30, B310130062

B310240116 Forwards Amends 77 & 81 to Licenses DPR-24 & DPR-27, respectively & safety evaluation Amend revise Tech Specs to permit location of spent fuel pool neutron absorber surveillance specimen adjacent to divider wall
COLBURN, T G Operating Reactors Branch 3 83/10/05 FAY, C W
Wisconsin Electric Power Co 2pp 20891 338 24X
Fiche 50-266, 83/10/05, B310240116

--B310240122 Amends 77 & 81 to Licenses DPR-24 & DPR-27, respectively, revising Tech Specs to permit location of spent fuel pool neutron absorber surveillance specimen adjacent to spent fuel pool divider wall
MILLER, J R Operating Reactors Branch 3 83/10/17 7pp
20891 340 24X Fiche 50-266, 83/10/05, B310240116

--B310240125 Safety evaluation supporting Amends 77 & 81 to Licenses DPR-24 & DPR-27, respectively
* Office of Nuclear Reactor Regulation, Director 83/10/05 3pp
20891 347 24X Fiche 50-266, 83/10/05, B310240116

B310130199 Forwards Amends 76 & 80 to Licenses DPR-24 & DPR-27, respectively & safety evaluation Amend clarifies terminology used in limiting condition for operation & language re periodic calibr interval requirement
COLBURN, T G Operating Reactors Branch 3 83/10/06 FAY, C W
Wisconsin Electric Power Co 2pp 20777 195 24X
Fiche 50-266, 83/10/06, B310130199

--B310130202 Amends 76 & 80 to Licenses DPR-24 & DPR-27, respectively, making administrative changes to Tech Specs to clarify terminology used in limiting condition for operation & language re periodic calibr interval requirement
MILLER, J R Operating Reactors Branch 3 83/10/06 10pp
20777 197 24X Fiche 50-266, 83/10/06, B310130199

--B310130205 Safety evaluation supporting Amends 76 & 80 to Licenses DPR-24 & DPR-27, respectively
* Office of Nuclear Reactor Regulation, Director 83/10/06 2pp
20777 20/ 24X Fiche 50-266, 83/10/06, B310130199

B310180490 Application to amend Licenses DPR-24 & DPR-27 modifying Tech Spec Change Request 33 reflecting changes in effluent monitoring instrumentation resulting from recently installed improved radiation monitoring sys
FAY, C W Wisconsin Electric Power Co 83/10/07 DENION, H R
Office of Nuclear Reactor Regulation, Director 3pp 20799 114 24X
Fiche 50-266, 83/10/07, B310180490

--B310180492 Proposed radiological effluent Tech Specs reflecting mod to radiation monitoring sys
* Wisconsin Electric Power Co 83/09/30 47pp 20799 117 24X
Fiche 50-266, 83/10/07, B310180490

--B310180495 Rev 0 to "Offsite Dose Calculation Manual"
* Wisconsin Electric Power Co 83/09/30 65pp 20799 161 24X
Fiche 50-266, 83/10/07, B310180490

--B310180499 Rev 2 to "Environ Monitoring Manual"
* Wisconsin Electric Power Co 82/06/30 33pp 20799 229 24X
Fiche 50-266, 83/10/07, B310180490

--B310180502 "Process Control Program"
* Wisconsin Electric Power Co 83/09/30 218pp 20799 294 24X
Fiche 50-266, 83/10/07, B310180490

B310280098 Confirms arrangements for NRC site visit on B31101-03 to obtain addl info to complete evaluation of inservice testing program for pumps & valves
MILLER, J R Operating Reactors Branch 3 83/10/07 FAY, C W
Wisconsin Electric Power Co 2pp 20761 360 24X
Fiche 50-266, 83/10/07, B310280098

B310130004 Discusses B31013 meeting to resolve deficiencies noted in Franklin Research Ctr technical evaluation rept re environ qualification of safety-related electrical equipment Agenda & supporting documentation encl
BURSTEIN, S Wisconsin Electric Power Co 83/10/10 DENION, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 30pp 20726 207 24X
Fiche 50-266, 83/10/10, B310130004

B310180421 Informs of proposed minor changes to commitments made in response to implementation instructions of NUREG-05/B, re short-term lessons learned Duty technical advisor quarters will be incorporated in boundary control ctr
FAY, C W Wisconsin Electric Power Co 83/10/10 DENION, H R
Office of Nuclear Reactor Regulation, Director 2pp 20803 206 24X
Fiche 50-266, 83/10/10, B310180421

B310170079 Notification of B31013 meeting w/util in Bethesda, MD to discuss method for achieving final qualification of safety-related electrical equipment final rept will be issued based on meeting results
COLBURN, T G Operating Reactors Branch 3 83/10/11 MILLER, J R
Operating Reactors Branch 3 3pp 20748 014 24X
Fiche 50-266, 83/10/11, B310170079

B310200202 Forwards addl review & approval fees re B30708 application concerning Tech Spec Change Request 97 on component cooling HX
FAY, C W Wisconsin Electric Power Co 83/10/14 DENION, H R
Office of Nuclear Reactor Regulation, Director MILLER, W D License Fee Management Branch 1p 20834 126 24X
Fiche 50-301, 83/10/14, B310200202

B310280147 Forwards B30930 Director's Decision 83-14, denying State of OH & Sierra Club JOCFR2 206 petitions re transportation of spent fuel from West Valley Facility, per B30930 request
CUNNINGHAM, R C Division of Fuel Cycle & Material Safety 83/10/18
MILLER, F Environmental Policy Institute 2pp 20961 344 24X
Fiche 50-000, 83/10/18, B310280147

Q Inspection reports, IE Bulletin & correspondence

B308300340 IE Info Notice 83-61, "Alleged Use of Stand Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X
Fiche 50-000, 83/09/26, B308300340

B308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X
Fiche 50-000, 83/09/26, B308300342

B308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X
Fiche 50-000, 83/09/26, B308300345

B310030447 Forwards list of Ray Miller products installed at facilities, in response to IE Bulletin 83-0/ Investigation of subter suppliers in progress
FAY, C W Wisconsin Electric Power Co 83/09/26 KEPPLER, J G
Region 3, Office of Director 4pp 20601 038 24X
Fiche 50-266, 83/09/26, B310030447

DOCKETED ITEMS

8310120087 Responds to IE Info Notice 83-01 & IE Bulletin 83-07 re investigation of applicability of Ray Miller, Inc fraudulent practices identified items have no adverse safety significance List of installed products encl
FAY, C W Wisconsin Electric Power Co 83/09/26 KEMPFLER, J J
Region 3, Office of Director 4pp 20696 187 24X
Fiche 50-266, 83/09/26, 8310120087

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/O 10CFR50.59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310060568 Requests remittance of Class III fee for review of 87u00R application for Inch Spec change re component cooling HX insp & maint program
MILLER, W O License Fee Management Branch 83/09/30 FAY, C W
Wisconsin Electric Power Co 1p 20641 247 24X
Fiche 50-301, 83/09/30, 8310060568

8310240001 Forwards IE Mgt Meeting Rept 50-301/83-11 on 830822 & notice of violation from insp on 830601-0/31
NORELIUS, C E Division of Project & Resident Programs 83/10/05
BURSTEIN, S Wisconsin Electric Power Co 2pp 20880 342 24X
Fiche 50-301, 83/10/05, 8310240001

--8310240002 Notice of violation from insp on 830601-0/31
NORELIUS, C E Division of Project & Resident Programs 83/10/05
1p 20880 344 24X Fiche 50-301, 83/10/05, 8310240002

--8310240003 IE Mgt Meeting Rept 50-301/83-11 on 830822 Items discussed concerns re noncompliance involving licensee exceeding limiting conditions for operation re inoperable radiation monitors
HAQUE, R L, JACKSON, I N Region 3, Office of Director 83/10/04
3pp 20880 345 24X Fiche 50-301, 83/10/05, 8310240003

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180261 Clarifies NRC position re procedures for admitting NRC personnel to facilities Access should be provided to Region III personnel listed in encl Update will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 BURSTEIN, S
Wisconsin Electric Power Co 7pp 20002 275 24X
Fiche 50-266, 83/10/14, 8310180261

8310270294 Forwards IE Insp Repts 50-266/83-17 & 50-301/83-16 on 830808-0922 & notice of violation
PAPERIELLO, C J Region 3, Office of Director 83/10/14
BURSTEIN, S Wisconsin Electric Power Co 2pp 20923 196 24X
Fiche 50-266, 83/10/14, 8310270294

--8310270303 Notice of violation from insp on 830808-0922
PAPERIELLO, C J Region 3, Office of Director 83/10/13 1p
20923 198 24X Fiche 50-266, 83/10/14, 8310270294

--8310270313 IE Insp Repts 50-266/83-17 & 50-301/83-16 on 830808 0922 Noncompliance noted failure to perform appropriate contamination survey of radioactive matls shipment
LOVENDALE, P C, PAUL, R A, HAQUE, R L Region 3, Office of Director 83/10/12 8pp 20923 199 24X Fiche 50-266, 83/10/14, 8310270294

8310240042 Ack receipt of 830922 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/83-13 & 50-301/83-13 Fuel handling training must be completed by 831201
SHAFER, W D Region 3, Office of Director 83/10/18 BURSTEIN, S
Wisconsin Electric Power Co 1p 20881 348 24X
Fiche 50-266, 83/10/18, 8310240042

--8310240051 Responds to NRC 830823 ltr re violations noted in IE Insp Repts 50-266/83-13 & 50-301/83-13 Corrective actions supervisor instructed on use of procedures & good engineering practices when operating refueling equipment
CASSIDY, I J Wisconsin Electric Power Co 83/09/23 KEMPFLER, J J
Region 3, Office of Director 3pp 20881 349 24X
Fiche 50-266, 83/10/18, 8310240051

R Periodic operating reports & related correspondence

8310180119 Monthly operating repts for Sept 1983 W/831010 ltr
FAY, C W Wisconsin Electric Power Co 83/10/05 NRC - Nu
Detailed Affiliation Given 7pp 20307 175 24X
Fiche 50-266, 83/10/05, 8310180119

S Reportable occurrences, LERs & related correspondence

8310060428 PNO-III-83-089 on 830929, temporary restraining order requested to prevent shipment of spent reactor fuel through State of OH denied Pretrial conference set for 831006 Local govts alleged inadequate preparation by local agencies
STRASNA, J Region 3, Office of Director 83/09/30 2pp
20641 221 24X Fiche 50-000, 83/09/30, 8310060428

8310070301 Potential Part 21 rept re underrange characteristic of Model N-411GM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 13pp 20651 064 24X
Fiche 50-000, 83/09/30, 8310070301

8310170380 Updated LER 83-011/03X-1 on 830817, RHR pump EP10W declared inoperable due to high bearing vibration levels Unit placed in degraded mode Cause uncertain failed pump replaced W/831005 ltr
FAY, C W Wisconsin Electric Power Co 83/10/05 KEMPFLER, J J
Region 3, Office of Director 4pp 20785 012 24X
Fiche 50-301, 83/10/05, 8310170380

8310140255 PNO-III-83-094 on 830930, contamination found on empty spent fuel cask shipped from facility trailer used to transport empty spent fuel casks experienced brake problems on 831005 All shipments under insp
LOVENDALE, P, GREGER, L R Region 3, Office of Director 83/10/06
2pp 20759 238 24X Fiche 50-266, 83/10/06, 8310140255

V Operator Examinations

8310070303 Requests extension of effective date of compliance w/ 10CFR50 re licensed operator staffing to 871010
FAY, C W Wisconsin Electric Power Co 83/09/30 DENISON, H H
Office of Nuclear Reactor Regulation, Director 8pp 20651 074 24X
Fiche 50-266, 83/09/30, 8310070303

DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

8310040466 Ack receipt of 830909 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/83-13
LEWIS, R C Division of Project & Resident Programs 83/09/23
WILGUS, W S Florida Power Corp 1p 20623 100 24X
Fiche 50-302, 83/09/23, 8310040466

--8310040472 Responds to NRC 830810 ltr re violations noted in IE Insp Rept 50-302/83-13 Corrective actions INPU contacted to request rapid dose assessment procedures which will be used as guidelines Procedure EM-204 will be revised by 831101
WEBSTER, Q R Florida Power Corp 83/09/09 O'REILLY, J P
Region 2, Office of Director 4pp 20623 101 24X
Fiche 50-302, 83/09/23, 8310040466

--8310040475 Forwards IE Insp Rept 50-302/83-13 on 830627-0701 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/08/10
WILGUS, W S Florida Power Corp 2pp 20623 105 24X
Fiche 50-302, 83/09/23, 8310040466

--8310040477 Notice of violation from insp on 830627-0701
+ Region 2, Office of Director 83/08/10 1p 20623 107 24X
Fiche 50-302, 83/09/23, 8310040466

DOCKETED ITEMS

125

--8310040480 IE Insp Rept 50-302/83-13 on 830627-0701 Noncompliance noted failure to establish procedure implementing emergency plan requirement for prompt notification
HUFFMAN, G N Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/08/05 10pp 20623 10B 24X Fiche 50-302 83/09/23, 8310040466

8310040420 Confirms that technical support ctr designed to be continuously habitable for 30 days following post accident release described in Reg Guide 1.4, Rev 2, dtd June 1974
Shielding conforms w/NUREG-0737, Items II K 2 & III A 1 2
WESTAFER, G R Florida Power Corp 83/09/30 DENUN, H R Office of Nuclear Reactor Regulation, Director 1p 20619 040 24Y Fiche 50-302, 83/09/30, 8310040420

8310180025 Determines that refund appropriate for review of 800111 & 820319 applications for amend to License DPR-72 re environ sampling analysis for detection capabilities & security training & qualification plan
MILLER, W D License Fee Management Branch 83/10/07 WILGUS, W S Florida Power Corp 1p 20825 054 24Y Fiche 50-302, 83/10/07, 8310180025

J Insurance & indemnity information

8310140260 Forwards Endorsement 60 to NLI A Policy NF-195 & Endorsement 46 to MA-LU Policy MF-91
BUCKA, J R Marsh & McLennan, Inc 83/10/06 SALIZMAN, Office of State Programs, Director 3pp 20761 033 24X Fiche 50-302, 83/10/06, 8310140260

P Operating license stage documents & correspondence

8310050297 Forwards safety evaluation on installation of RCS high point vents per NUREG-0737, Item II B 1, "RCS Vents" & final technical evaluation rept Vent sys acceptable subj to post implementation audit
STOLZ, J F Operating Reactors Branch 4 83/08/08 WILGUS, W S Florida Power Corp 3pp 20650 057 24X Fiche 50-302, 83/08/08, 8310050297

--8310050304 Safety evaluation supporting installation of RCW high point vents per NUREG-0737, Item II B 1, "RCS Vents"
* NRC - No Detailed Affiliation Given 83/05/26 10pp 20650 060 24X Fiche 50-302, 83/08/08, 8310050297

--8306080106 "Selected Operating Reactor Issues Program II (RCS Vents (NUREG-0737, Item II B 1), "Final technical evaluation rept HELD, J T Energy Incorporated HELD, J T Lawrence Livermore Laboratory FIN A-0250 TF-370/081/A 83/03/14 ALBERHAL, G Division of Licensing 6pp 20650 070 24X Fiche 50-302, 83/08/08, 8310050297

8310050060 Forwards BER accepting Arkansas Power & Light Co (APL) 830607 proposed mods to reactor trip breakers for B&W plants Requested info should be provided when APL generic design endorsed in response to Generic Ltr 83-28
STOLZ, J F Operating Reactors Branch 4 83/09/12 WILGUS, W S Florida Power Corp 2pp 20639 322 24X Fiche 50-302, 83/09/12, 8310050060

8310210116 Forwards notice of denial of amend to License DPR-72 & opportunity for hearing re 830331 amend application concerning Cycle 5 reload, extending time interval for shutdown surveillance to once each 24 months
HERNAN, R Operating Reactors Branch 4 83/09/20 WILGUS, W S Florida Power Corp 3pp 20883 331 24X Fiche 50-302, 83/09/20, 8310210116

--8310210117 Notice of denial of amend to License DPR-72 & opportunity for hearing re 830331 amend application concerning Cycle 5 reload, extending time interval for shutdown surveillance to once each 24 months Inadequate justification provided
STOLZ, J F Operating Reactors Branch 4 83/09/20 3pp 20883 334 24X Fiche 50-302, 83/09/20, 8310210116

8310040301 Forwards B&W "Bounding Analytical Assessment of NUREG 0630 Models on LOCA kW/Ft Limits W/Use of FLFCSEI," completing response to NUREG-0630 Compensating models documented & justification for model use provided
WESTAFER, G R Florida Power Corp 83/09/29 STOLZ, J F Operating Reactors Branch 4 2pp 20612 227 24X Fiche 50-302, 83/09/29, 8310040301

--8310040304 "Bounding Analytical Assessment of NUREG-0630 Models on LOCA kW/Ft limits W/Use of FLFCSEI"
* Babcock & Wilcox Co 77-1140898-01 83/09/30 10pp 20612 229 24X Fiche 50-302, 83/09/29, 8310040301

8310040463 Modifies 791109 commitment for nuclear support svcs dept to perform multiple equipment failure analysis Plant staff, rather than nuclear support svcs dept, will perform review
WESTAFER, G R Florida Power Corp 83/09/29 EISENHUT, D G Division of Licensing 2pp 20623 124 24X Fiche 50-302, 83/09/29, 8310040463

8310130421 Forwards safety evaluation & technical evaluation rept re NUREG-0737, TMI Items II K 3 1, "Automatic PORV Isolation" & II K 3 2, "Rept on PORVs" Requirements met
STOLZ, J F Operating Reactors Branch 4 83/09/30 WILGUS, W S Florida Power Corp 3pp 20769 167 24X Fiche 50-302, 83/09/30, 8310130421

8310130070 Notification of 831019-20 meetings w/Util & Gilbert Assoc in St Petersburg, FL to inspect present emergency feedwater sys & associated sys & to discuss planned emergency feedwater sys upgrade project
HERNAN, R Operating Reactors Branch 4 83/10/06 STOLZ, J F Operating Reactors Branch 4 2pp 20776 155 24Y Fiche 50-302, 83/10/06, 8310130070

8310180436 Informs that util will respond to all applicable sections of Generic Ltr 83-28 re ATWS events at Salem by 831104 w/exception of Section 2.2.2 Requests extension until 840302
SIMPSON, E C Florida Power Corp 83/10/06 EISENHUT, D G Division of Licensing 2pp 20802 161 24X Fiche 50-302, 83/10/06, 8310180436

8310200064 Forwards SER re NUREG-0737, Item II K 3 17, "Rept on Outages of ECCS" Review complete, however, improvement needed in area of LPIS availability Response requested within 90 days of ltr receipt
STOLZ, J F Operating Reactors Branch 4 83/10/06 WILGUS, W S Florida Power Corp 5pp 20844 277 24X Fiche 50-302, 83/10/06, 8310200064

--8306160602 "ECCS Repts (F-47) TMI Action Plan Requirements, Florida Power Corp, Crystal River Unit 3," technical evaluation rept
VOSBURY, F W, OVERBECK, G J, LUDINGTON, B W Franklin Institute/Franklin Research Center NRC-03-81-130 ICR-C5506-272 83/06/13 CHOW, E NRC - No Detailed Affiliation Given 10pp 20844 282 24Y Fiche 50-302 83/10/06, 8310200064

8310120191 Forwards info re NUREG-0737, Item II F 2, "Instrumentation for Detection of Inadequate Core Cooling," in response to 830906 request Addl info will be submitted by 840215
SIMPSON, E C Florida Power Corp 83/10/07 STOLZ, J F Operating Reactors Branch 4 6pp 20695 320 24X Fiche 50-302, 83/10/07, 8310120191

8310120387 Submits status of required items to upgrade seismic capability of emergency feedwater sys, per 830809 request
Generic Ltr B1 14 Schedule for completion of seismic upgrades to emergency feedwater sys encl
SIMPSON, E C Florida Power Corp 83/10/07 STOLZ, J F Operating Reactors Branch 4 7pp 20699 121 24X Fiche 50-302, 83/10/07, 8310120387

8310180025 Determines that refund appropriate for review of 800111 & 820319 applications for amend to License DPR-72 re environ sampling analysis for detection capabilities & security training & qualification plan
MILLER, W D License Fee Management Branch 83/10/07 WILGUS, W S Florida Power Corp 1p 20825 054 24X Fiche 50-302, 83/10/07, 8310180025

8310140079 Forwards "Reactor Containment Bldg Integrated Leak Rate Test," Jul 1983
WESTAFER, G R Florida Power Corp 83/10/11 DENUN, H R Office of Nuclear Reactor Regulation, Director 1p 20766 297 24X Fiche 50-302, 83/10/11, 8310140079

--8310140080 "Reactor Containment Bldg Integrated Leak Rate Test," Jul 1983
BLESSING, J, SHIRK, R E Gilbert/Commonwealth Co COLINS, M C Florida Power Corp 83/07/31 58pp 20766 298 24X Fiche 50-302 83/10/11, 8310140079

8310210143 Concurs that repeat of Cycle 5 in-core vs ex-core detector imbalance correlation verification testing unnecessary
STOLZ, J F Operating Reactors Branch 4 83/10/13 WILGUS, W S Florida Power Corp 3pp 20883 352 24X Fiche 50-302, 83/10/13, 8310210143

8310180473 Responds to 831006 request for addl info re changes to emergency & abnormal procedures following review of Preliminary Safety Concern 22-82, "Potential for Pressurized Thermal Shock"
WESTAFER, G R Florida Power Corp 83/10/14 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 20802 028 24X Fiche 50-302, 83/10/14, 8310180473

DOCKETED ITEMS

8310310444 REVIEW OF CRYSTAL RIVER NUCLEAR GENERATING STATION UNIT 3
EMERGENCY FEEDWATER SYSTEM RELIABILITY ANALYSIS
YOUNGDL00D, R., PAPA200LOU, I. A. Brookhaven National Laboratory. FIN
A-3393 NUREG/CR-3081 83/10/31 Division of Safety Technology
43pp Available at NRC \$3 75 21001 016 24X
Fiche 50-302, 83/10/31, 8310310444

G Inspection reports, IE Bulletins & correspondence

8310250458 Advises that commitment to redraw existing flow diagrams on
computer aided drafting sys complete per IE Insp Rept
50-302/82-11 Drawings incorporate Refuel IV mods, including
Field verification walldown markings
WESTAFER, G R Florida Power Corp 83/08/04 O'REILLY, J P Region
2, Office of Director 1p 20897 056 24X Fiche 50-302, 83/08/04,
8310250458

8310040476 Confirms 831020 mgt meeting in St Petersburg, FL to review
results of first phase of annual regulatory performance
appraisal SALP Board assessment for Jul 1982 - June 1983
will be forwarded Proposed agenda encl
LEWIS, R C Division of Project & Resident Programs 83/09/21
WILGUS, W S Florida Power Corp 2pp 20623 118 24X
Fiche 50-302, 83/09/21, 8310040476

8310040466 Ack receipt of 830909 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-302/83-13
LEWIS, R C Division of Project & Resident Programs 83/09/23
WILGUS, W S Florida Power Corp 1p 20623 100 24X
Fiche 50-302, 83/09/23, 8310040466

--8310040472 Responds to NRC 830810 ltr re violations noted in IE Insp
Rept 50-302/83-13 Corrective actions INPO contacted to
request rapid dose assessment procedures which will be used
as guidelines Procedure EH-204 will be revised by 831101
WESTAFER, G R Florida Power Corp 83/09/09 O'REILLY, J P
Region 2, Office of Director App 20623 101 24X
Fiche 50-302, 83/09/23, 8310040466

--8310040475 Forwards IE Insp Rept 50-302/83-13 on 830627-0701 & notice
of violation
LEWIS, R C Division of Project & Resident Programs 83/08/10
WILGUS, W S Florida Power Corp 2pp 20623 105 24X
Fiche 50-302, 83/09/23, 8310040466

--8310040477 Notice of violation from Insp on 830627-0701
Region 2, Office of Director 83/08/10 1p 20623 107 24X
Fiche 50-302, 83/09/23, 8310040466

-8310040480 IE Insp Rept 50-302/83-13 on 830627-0701 Noncompliance
noted failure to establish procedure implementing emergency
plant requirement for prompt notification
HUFFMAN, G N Region 2, Office of Director JENKINS, G R Division
of Emergency Preparedness & Materials Safety 83/08/05 10pp
20623 108 24X Fiche 50-302, 83/09/23, 8310040466

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder
Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 117pp 20734 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
Detectors Positioned at Control Room Ventilation Air
Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse
Type BA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300347 IE Info Notice 83-64, "Lead Shielding Attached to
Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/24 Consolidated Edison Co of New
York, Inc 115pp 20716 224 24X Fiche 50-000, 83/09/29, 8308300347

831030070 Notification of 831019-20 meetings w/util & Gilbert Assoc in
St Petersburg, FL to inspect present emergency feedwater sys
& associated sys & to discuss planned emergency feedwater
sys upgrade project
HERNAN, R Operating Reactors Branch 4 83/10/06 STOLZ, J P
Operating Reactors Branch 4 2pp 20776 155 24X
Fiche 50-302, 83/10/06, 831030070

8308300378 IE Info Notice 83-65, "Surveillance of Flow in R1D Bypass
Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical
Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8310130136 Comments on apparent increase in scope of fraudulent &
substandard activities by unscrupulous suppliers Reliability
emphasized
SCOTT, L H Florida Power Corp 83/10/10 DEYOUNG, R C Director's
Office, Office of Inspection and Enforcement 1p 20726 J10 24X
Fiche 50-302, 83/10/10, 8310130136

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect
Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective
Self-Contained Breathing Apparatus Air Cylinders " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310250350 Ack receipt of 830909 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-302/82-29
Violation A re functional test of EBF sys withdrawn
O'REILLY, J P Region 2, Office of Director 83/10/13 WILGUS, W S
Florida Power Corp 2pp 20898 077 24X Fiche 50-302, 83/10/13,
8310250350

--8310250374 Updates response to NRC 830710 ltr re violations noted in IL
Insp Rept 50-302/82-29 Violation A re failure to perform
surveillance testing denied
WESTAFER, G R Florida Power Corp 83/09/09 O'REILLY, J P
Region 2, Office of Director App 20898 079 24X
Fiche 50-302, 83/10/13, 8310250350

R Periodic operating reports & related correspondence

8310140243 Forwards Rev 1 to monthly operating rept for Aug 1983 &
monthly operating rept for Sept 1983
WESTAFER, G R Florida Power Corp 83/10/11 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 1p
20761 231 24X Fiche 50-302, 83/10/11, 8310140243

--8310140266 Rev 1 to monthly operating rept for Aug 1983
BOGART, A Florida Power Corp 83/09/01 1p 20761 232 24X
Fiche 50-302, 83/10/11, 8310140243

--8310140268 Monthly operating rept for Sept 1983
GRAHAM, D., FIELDS, D Florida Power Corp 83/10/04 App
20761 233 24X Fiche 50-302, 83/10/11, 8310140243

S Reportable occurrences, LERs & related correspondence

8310070306 LER 83-035/03L-0 on 830830, steam generator water level
exceeded Tech Spec 3.4.5 requirement Caused by misaligned
linkage arm EWP-2A manually tripped allowing water level to
drop within limits W/830927 ltr
BUFE, J L, CULLEN, D P, WESTAFER Florida Power Corp 83/09/24
O'REILLY, J P Region 2, Office of Director 3pp 20652 203 24X
Fiche 50-302, 83/09/29, 8310070306

8310070307 RO 83-023 responding to NRC 830817 ltr re fire damper
discrepancies Fire protection sys designed per 10CFR50 App R
mods to protect safe shutdown sys Audit verifying fire
protection criteria implemented performed in early Sept
WESTAFER, G R Florida Power Corp 83/10/03 LEWIS, R C Division
of Project & Resident Program 8pp 20652 206 24X
Fiche 50-302, 83/10/03, 8310070307

8310120301 Updated LER 83-023/01X-2 on 830613, personnel discovered fire
damper FD-86 missing Caused by personnel error Engineering
evaluation expected by 840331 LR-3 fire protection design
considered adequate W/831003 ltr
THOMPSON, R H, WESTAFER, G R Florida Power Corp 83/10/03
O'REILLY, J P Region 2, Office of Director 10pp 20690 331 24X
Fiche 50-302, 83/10/03, 8310120301

DOCKETED ITEMS

127

8310140187 LER 83-036/01T-0 on 830921, fuel storage pool area surveys discovered not performed at least once every 24 h from 830915-21 Caused by personnel error Procedures will be revised W/831005 ltr
BUFE, J L , HUGHES, P G , WILGUS, W S Florida Power Corp 83/10/05
O'REILLY, J P Region 2, Office of Director 4pp 20764 315 24X
Fiche 50-302, 83/10/05, 8310140187

8310140123 LER 83-038/01T-0 on 830922, followup investigation of quality audit finding uncovered procedural inadequacy allowing requirement for surveillance of certain fire barrier penetration seals to be overlooked W/831006 ltr
BUFE, J L , SIMPSON, E C Florida Power Corp 83/10/06
O'REILLY, J P Region 2, Office of Director 4pp 20764 005 24X
Fiche 50-302, 83/10/06, 8310140123

8310140233 LER 83-037/03L-0 on 830907, during performance of Surveillance Procedure SP-340 re ECCS pump operability, DHV-110 breaker tripped while cycling valve from open to closed Cause unknown Breaker replaced 830922 W/831007 ltr
BUFE, J L , HUGHES, P G , SIMPSON, E C Florida Power Corp 83/10/07
O'REILLY, J P Region 2, Office of Director 3pp 20764 047 24X
Fiche 50-302, 83/10/07, 8310140233

8310170319 Updated LER 83-034/01X-1 on 830812, during performance of SP-110, RPS functional testing, both reactor coolant pump monitors for RCP-1C bypassed, contrary to Tech Spec 3.3.1.1 Caused by interim change W/831010 ltr
CARBEINER, R E , WESTAFER, G R Florida Power Corp 83/10/07
O'REILLY, J P Region 2, Office of Director 4pp 20784 242 24X
Fiche 50-302, 83/10/07, 8310170319

8310210021 LER 83-039/03L-0 on 830913, during Mode 4 surveillance testing, twelve instruments discovered out of calibr Cause under investigation Instruments will be recalibr Transmitter replaced W/831013 ltr
BUFE, J L , CULLEN, D P , WESTAFER, G R Florida Power Corp 83/10/17
O'REILLY, J P Region 2, Office of Director 2pp 20855 176 24X
Fiche 50-302, 83/10/13, 8310210021

DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8310110004 Responds to FOIA request for five documents Forwards documents also available in IDK
FELTON, J M Division of Rules and Records 83/07/01 PEDRO, J NUH Corp 2pp 20704 137 24X Fiche 50-000, 83/07/01, 8310110004

--8310110010 "Appraisal of Fire Effects from Aircraft Crash At Zion Power Reactor Facility"
PINKEL, I I Atomic Energy Commission 72/07/11 35pp
20704 139 24X Fiche 50-000, 83/07/01, 8310110004

8310140173 Ack receipt of 831003 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/83-13 & 50-304/83-13
SHAFER, W D Region 3, Office of Director 83/10/06 REED, C Commonwealth Edison Co 1p 20765 001 24X Fiche 50-295, 83/10/06, 8310140173

--8310140175 Responds to NRC 830829 ltr re violations noted in IE Insp Repts 50-295/83-13 & 50-304/83-13 Corrective actions surveillance conducted on fire pump diesel engine & starting 12-volt battery bank & charger
LENTINE, F G Commonwealth Edison Co 83/10/03 KEPPLER, J G Region 3, Office of Director 2pp 20765 002 24X
Fiche 50-295, 83/10/06, 8310140173

8310240087 Forwards IE Insp Repts 50-295/83-17 & 50-304/83-18 on 830810-0920 & notice of violation
NORELIUS, C E Division of Project & Resident Programs 83/10/07 REED, C Commonwealth Edison Co 2pp 20880 348 24X
Fiche 50-295, 83/10/07, 8310240087

--8310240076 IE Insp Repts 50-295/83-17 & 50-304/83-18 on 830810-0920 Noncompliance noted Unit 2 operated w/diesel generators 2A, 2B & C inoperable on 830704-11 & 71-27, contrary to surveillance requirements
WATERB, J R , BOYD, D C Region 3, Office of Director 83/10/04 11pp 20880 352 24X Fiche 50-295, 83/10/07, 8310240087

8310210374 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/17 Document Management Branch 1p 20882 349 24X Fiche 50-295, 83/10/17, 8310210374

--8310210377 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 360-4, "Radiation Sampling Under Accident Conditions " W/830926 ltr, receipt form & procedure change request form
PLIML, G Commonwealth Edison Co 83/09/22 DENTON, H R NRC - No Detailed Affiliation Given 6pp 20682 350 24X
Fiche 50-295, 83/10/17, 8310210374

8310270526 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20937 216 24X Fiche 50-000, 83/10/21, 8310270526

--8310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure EPI-6, "Administration & Logistics Manager " W/831017 ltr & receipt form
NELLIS, C A Commonwealth Edison Co 83/02/18 DENTON, H R NRC - No Detailed Affiliation Given 7pp 20937 217 24X
Fiche 50-000, 83/10/21, 8310270526

8310280307 Releases public version of revised generating stations emergency plan telephone directory
FELTON, J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20963 126 24X Fiche 50-000, 83/10/25, 8310280307

--8310280314 Public version of revised generating stations emergency plan telephone directory
GALLE, D P Commonwealth Edison Co 83/08/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 64pp 20963 127 24X
Fiche 50-000, 83/10/25, 8310280307

8310280191 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/26 Document Management Branch 1p 20962 266 24X Fiche 50-000, 83/10/26, 8310280191

--8310280209 Public version of Rev 1 to Emergency Plan Implementing Procedure EDF-15, "Emergency Operations Facility Activation "
MOORE, R D Commonwealth Edison Co 83/08/02 50pp 20962 267 24X Fiche 50-000, 83/10/26, 8310280191

F Operating license stage documents & correspondence

8310130415 Forwards FR notice of consideration of issuance of amendments to Licenses DPR-39 & DPR-48 to permit operation w/only three of four primary coolant loops in svc
VARQA, S A Operating Reactors Branch 1 83/09/23 FARRAR, D L Commonwealth Edison Co 2pp 20769 008 24X Fiche 50-295, 83/09/23, 8310130415

--8310130416 Notice of consideration of issuance of amendments to Licenses DPR-39 & DPR-48 & proposed NSIC determination & opportunity for hearing
VARQA, S A Operating Reactors Branch 1 83/09/23 4pp 20769 010 24X Fiche 50-295, 83/09/23, 8310130415

8310110117 Suppl to 830808 request for amend to Licenses DPR-39 & DPR-48, revising Tech Spec re containment leakage test acceptance criteria Info clarifies 10CFR50 App J calculations
LENTINE, F G Commonwealth Edison Co 83/10/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 20667 169 24X
Fiche 50-295, 83/10/05, 8310110117

8310170042 Forwards request for addl info re use of optimized fuel assembly Response required to complete evaluation
VARQA, S A Operating Reactors Branch 1 83/10/05 FARRAR, D L Commonwealth Edison Co 4pp 20812 154 24X Fiche 50-295, 83/10/05, 8310170042

8310200273 Forwards schedules for equipment qualification test programs for facilities, per 810528 ltr Dates given for current qualification activities should be viewed as "target-dates" & not as firm dates
BARNES, P L Commonwealth Edison Co 83/10/05 KEPPLER, J G Region 3, Office of Director 10pp 20830 034 24X Fiche 50-000, 83/10/05, 8310200273

8310200151 Application for immediate & temporary amend to Licenses DPR-39 & DPR-48, changing Tech Specs to allow preventive maint to be performed on shared diesel generator D during current refueling outage
LENTINE, F G Commonwealth Edison Co 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 20836 282 24X
Fiche 50-295, 83/10/14, 8310200151

DOCKETED ITEMS

8310310049 Forwards response to NRC 831006 request for addl info re 830822 application for license amend to permit use of optimized fuel assemblies Structural analysis of mixed reactor core during seismic event encl
LENTINE, F O Commonwealth Edison Co 83/10/21 DENTON, H H Office of Nuclear Reactor Regulation, Director 14pp 20951 131 24X
Fiche 50-295, 83/10/21, 8310310049

8310310060 Submits info re Edison rod swap analysis method for review & approval Methods employed in support of control rod worth measurements using rod swap technique during reload physics testing Criteria tables encl
LENTINE, F O Commonwealth Edison Co 83/10/24 DENTON, H H Office of Nuclear Reactor Regulation, Director 8pp 20951 024 24X
Fiche 50-000, 83/10/24, 8310310060

G Inspection reports, IE Bulletins & correspondence

8310110456 Forwards safety evaluation & technical evaluation report re util responses to IE Bulletin 80-11, "Masonry Wall Design" Requests actions planned & scheduled for resolution of issue within 30 days
VARGA, S A Operating Reactors Branch 1 83/09/12 FARRAR, D L Commonwealth Edison Co 4pp 20712 197 24X Fiche 50-295, 83/09/12, 8310110456

--8308030016 Revised "Masonry Wall Design (B-59), Zion Units 1 & 2," technical evaluation report
SUBRAMONIAN, N Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-243 R01 83/07/27 CHOKSHI, N C NRC No Detailed Affiliation Given 25pp 20712 202 24X
Fiche 50-295, 83/09/12, 8310110456

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20734 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o IOPR50 59 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310200124 Forwards IE Mgt Meeting Repts 50-010/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIUS, C E Division of Project & Resident Programs 83/10/04 REED, C Commonwealth Edison Co 2pp 20834 098 24X
Fiche 50-000, 83/10/04, 8310200124

--8310200148 IE Mgt Meeting Repts 50-020/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIUS, C E Division of Project & Resident Programs 83/10/03 4pp 20834 100 24X Fiche 50-000, 83/10/04, 8310200124

8310140173 Ack receipt of 831003 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-293/83-13 & 50-304/83-11
SHAFFER, W D Region 3, Office of Director 83/10/06 REED, C Commonwealth Edison Co 1p 20765 001 24X Fiche 50-295, 83/10/06, 8310140173

--8310140175 Responds to NRC 830829 ltr re violations noted in IE Insp Repts 50-295/83-13 & 50-304/83-13, corrective actions surveillance conducted on fire pump diesel engine & starting 12-volt battery bank & charger
LENTINE, F O Commonwealth Edison Co 83/10/03 KEPPNER, J C Region 3, Office of Director 2pp 20765 002 24X
Fiche 50-295, 83/10/06, 8310140173

8308300378 IE Info Notice 83-65, "Surveillance of Flow in H1D Bypass Loops Used in Westinghouse Plants" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 40-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 77pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8310240087 Forwards IE Insp Repts 50-295/83-17 & 50-304/83-18 on 830810-0920 & notice of violation
NORELIUS, C E Division of Project & Resident Programs 83/10/07 REED, C Commonwealth Edison Co 2pp 20880 348 24X
Fiche 50-295, 83/10/07, 8310240087

--8310240091 Notice of violation from insp on 830810-0920
NORELIUS, C E Division of Project & Resident Programs 83/10/07 2pp 20880 350 24X Fiche 50-295, 83/10/07, 8310240087

--8310240096 IE Insp Repts 50-295/83-17 & 50-304/83-18 on 830810-0920 Noncompliance noted Unit 2 operated w/diesel generators 2A, 2B & C inoperable on 830704-11 & P1-27, contrary to surveillance requirements
WATERS, J R, DUNAWAY, F R, HARTMANN, P L Region 3, Office of Director 83/10/04 11pp 20880 344 24X Fiche 50-295, 83/10/07, 8310240087

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Mail Defect Causes Production of Noxious Gases" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180110 Advises that plans & schedule for resolution of horizontal joint reinforcing, per IE Bulletin 80-11, "Masonry Walls" & NRC 830912 ltr, will be provided by 831111 Util presently examining design of 18 walls affected by issue
LENTINE, F O Commonwealth Edison Co 83/10/12 DENTON, H H Office of Nuclear Reactor Regulation, Director 1p 20802 258 24X
Fiche 50-295, 83/10/12, 8310180110

8310180283 Clarifies NRC position re procedures for admitting NRC personnel to facilities List of personnel requiring access to vital areas encl Updates will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 REED, C Commonwealth Edison Co 7pp 20801 115 24X Fiche 50-295, 83/10/14, 8310180283

R Periodic operating reports & related correspondence

8310120108 Monthly operating reports for Sept 1983 W/031007 ltr
AUSTIN, G, GRAESSER, K L Commonwealth Edison Co 83/10/07 Director's Office, Office of Inspection and Enforcement 12pp 20696 228 24X Fiche 50-295, 83/10/07, 8310120108

S Reportable occurrences, LERs & related correspondence

8310110430 Responds to FOIA request for four different categories of documents described in 830510 ltr Forwards matl listed in App A, responsive to Items 1, 2 & 4 DDE should be contacted for matl requested in Item 3 of ltr
FELTON, J H Division of Rules and Records 83/06/14 HJATT, S I Ohio Citizens for Responsible Energy 3pp 20706 004 24X
Fiche 50-000, 83/06/14, 8310110430

--8310110478 Responds to 830412 ltr requesting info re use of foreign matls on valve seating surfaces Lubricants & cleaning solvents used on valve component surfaces per vendor recommendations & maint practices
FARRAR, D L Commonwealth Edison Co 83/04/22 KEPPNER, J C Region 3, Office of Director 4pp 20706 063 24X
Fiche 50-000, 83/06/14, 8310110430

8310140256 LER 83-034/03L-0 on 830906, unit operated during first half of Cycle 7 w/nonconservative IR channel 2N36 setpoints, for high flux trip & rodstop caused by inadequate guidelines leading to new setpoints Guidelines developed W/831006 ltr
GEORGE, D E, GRAESSER, K L Commonwealth Edison Co 83/10/06 KEPPNER, J C Region 3, Office of Director 3pp 20761 337 24X
Fiche 50-304, 83/10/06, 8310140256

DOCKETED ITEMS

129

8310170609 LER 83-036/03L-0 on 830911, steam generator 2B level channel 2L-549 spiked high repeatedly Deviation nonconservative for steam generator level Caused by plugging of sensing line Line blown down & channel returned to svc W/831006 ltr
CANTWELL, P F , GRAESSER, K L Commonwealth Edison Co 83/10/06
KEPPLER, J G Region 3, Office of Director 2pp 20782 170 24X
Fiche 50-304, 83/10/06, 8310170609

8310170577 LER 83-033/03L-0 on 830914, during heat trace surveillance, heater failure alarm discovered on discharge from boric acid filter 2 to boron injection tank Caused by deteriorated trace on discharge line Trace replaced W/831011 ltr
KAPLAN, S , GRAESSER, K L Commonwealth Edison Co 83/10/11
KEPPLER, J G Region 3, Office of Director 2pp 20780 327 24X
Fiche 50-304, 83/10/11, 8310170577

8310170557 LER 83-035/03L-0 on 830912, during performance test on diesel generator 2A, output breaker tripped upon Operator unable to increase or decrease load Caused by erratic motor Motor replaced & test rerun W/831012 ltr
FAKIND, G , GRAESSER, K L Commonwealth Edison Co 83/10/12
KEPPLER, J G Region 3, Office of Director 2pp 20780 347 24X
Fiche 50-304, 83/10/12, 8310170557

8310210218 LER 83-037/03L-0 on 830915, during instrument mechanic surveillance testing of passive gas failure monitor ZRT-FR15, no flow observed through monitor Cause unknown Investigation underway W/831014 ltr
KUECHLE, C , GRAESSER, K L Commonwealth Edison Co 83/10/14
KEPPLER, J G Region 3, Office of Director 2pp 20852 074 24X
Fiche 50-304, 83/10/14, 8310210218

8310270384 PNO-111-83-102 on 831020, security officer received bomb threat phone call from unidentified male Shift engineer instituted emergency procedures Search of vital areas conducted w/negative results threat determined hoax
BELANGER, J , CREED, J Region 3, Office of Director 83/10/21 1p
20923 207 24X Fiche 50-295, 83/10/21, 8310270384

T. Hearing transcripts on non-antitrust matters

8310110004 Responds to FOIA request for five documents Forwards documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/07/01 PEDRU, J NUC
Corp 2pp 20704 137 24X Fiche 50-000, 83/07/01, 8310110004

--8310110011 Testimony of DG Eisenhower re Zion/Haukegan Airport interaction
* Atomic Energy Commission 83/07/01 10pp 20704 174 24X
Fiche 50-000, 83/07/01, 8310110004

DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT

F Security, medical, emergency & fire protection plans

8310140002 Forwards IE Insp Rept 50-305/83-13 on 830827 0902 No noncompliance noted Protective action weaknesses in emergency plan discussed
PAPERIELLO, C J Region 3, Office of Director 83/09/28
QIESLER, C W Wisconsin Public Service Corp 4pp 20768 036 24X
Fiche 50-305, 83/09/28, 8310140002

--8310140013 IE Insp Rept 50-305/83-13 on 830827-0902 No noncompliance noted Major areas inspected emergency preparedness program, including actions on previously identified items, emergency detection & classification & public info program
SMELL, W O , LICKUS, R M , PHILLIPS, M P Region 3, Office of Director 83/09/28 14pp 20768 040 24X Fiche 50-305, 83/09/28, 8310140002

8310120206 Forwards 830421 revs to emergency plan implementing procedures Index encl
BAETSEN, L A Wisconsin Public Service Corp 83/09/29 SMITH, M
Region 3, Office of Director 4pp 20692 239 24X
Fiche 50-305, 83/09/29, 8310120206

--8310120209 Rev C to Procedure EP-AD-11 "Emergency Radiation Controls"
MARCHI, M L Wisconsin Public Service Corp 83/06/21 6pp
20692 245 24X Fiche 50-305, 83/09/29, 8310120206

--8310120214 Rev H to Procedure EP-ENV-3A "Environment Protection Director Actions & Directives"
MARCHI, M L Wisconsin Public Service Corp 83/06/21 17pp
20692 253 24X Fiche 50-305, 83/09/29, 8310120206

--8310120216 Rev E to Procedure EP-ENV-3H "EM Team Actions"
MARCHI, M L Wisconsin Public Service Corp 83/06/21 6pp
20692 270, 24X Fiche 50-305, 83/09/29, 8310120206

--8310120220 Procedure EP-ENV-3C "Primary Dose Projection Calculation - IBM Personal Computer"
MARCHI, M L Wisconsin Public Service Corp 83/06/21 4pp
20692 278 24X Fiche 50-305, 83/09/29, 8310120206

--8310120223 Procedure EP-ENV-3D "Primary Determination of Meteorological Data"
MARCHI, M L Wisconsin Public Service Corp 83/06/21 3pp
20692 282 24X Fiche 50-305, 83/09/29, 8310120206

--8310120227 Rev E to Procedure EP-ENV-3E "Manual Determination of X/G (KNPP Meteorological Data)"
MARCHI, M L Wisconsin Public Service Corp 83/06/21 6pp
20692 285 24X Fiche 50-305, 83/09/29, 8310120206

--8310120232 Rev D to Procedure EP-ENV-3F "Manual Determination of X/G (Green Bay Meteorological Data)"
MARCHI, M L Wisconsin Public Service Corp 83/06/21 7pp
20692 291 24X Fiche 50-305, 83/09/29, 8310120206

--8310120235 Rev D to Procedure EP-ENV-3G "Manual Projection Calculation"
MARCHI, M L Wisconsin Public Service Corp 83/06/21 6pp
20692 298 24X Fiche 50-305, 83/09/29, 8310120206

--8310120238 Rev B to Procedure EP-ENV-3H "Protective Action Recommendations"
MARCHI, M L Wisconsin Public Service Corp 83/06/21 6pp
20692 306 24X Fiche 50-305, 83/09/29, 8310120206

--8310120240 Rev A to Procedure EP-RET-3D "Containment Air Sampling Analysis Using CASP"
WINBOWSKI, W S Wisconsin Public Service Corp 83/06/21 6pp
20692 312 24X Fiche 50-305, 83/09/29, 8310120206

8310110027 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/05 Document
Management Branch 1p 20686 139 24X Fiche 50-305, 83/10/05, 8310110027

--8310110028 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-AD-7 re notification of unusual event, EP-AD-8 re notification of alert & EP-AD-9 re notification of site emergency
QIESLER, C W Wisconsin Public Service Corp 83/08/31
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
20686 139 24X Fiche 50-305, 83/10/05, 8310110027

--8310110031 Public version of revised emergency plan implementing procedures, including Procedures EP-AD-7 re notification of unusual event, EP-AD-8 re notification of alert & EP-AD-9 re notification of site emergency
* Wisconsin Public Service Corp 83/08/16 124pp 20686 141
24X Fiche 50-305, 83/10/05, 8310110027

8310120241 Ack receipt of 830811 exercise objectives for emergency exercise scheduled for 831001 Objectives acceptable Comments will be provided re 830916 detailed exercise scenario
PAPERIELLO, C J Region 3, Office of Director 83/10/06
QIESLER, C W Wisconsin Public Service Corp 1p 20692 164 24X
Fiche 50-305, 83/10/06, 8310120241

--8310120244 Forwards list of objectives for 831001 emergency exercise, per 820112 request for advance notice of scheduled exercise objectives
QIESLER, C W Wisconsin Public Service Corp 83/08/11
KEPPLER, J G Region 3, Office of Director 5pp 20692 165 24X
Fiche 50-305, 83/10/06, 8310120241

8310210389 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/17 Document
Management Branch 1p 20882 279 24X Fiche 50-305, 83/10/17, 8310210389

--8310210394 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-AD-3 re unusual event, EP-AD-4 re alert & EP-AD-5 re site emergency
QIESLER, C W Wisconsin Public Service Corp 83/10/05
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p
20882 280 24X Fiche 50-305, 83/10/17, 8310210389

--8310210396 Public version of revised emergency plan implementing procedures, including Procedures EP-AD-3 re unusual event, EP-AD-4 re alert & EP-AD-5 re site emergency
* Wisconsin Public Service Corp 83/09/29 46pp, 20882 281
24X Fiche 50-305, 83/10/17, 8310210389

DOCKETED ITEMS

8310310325 Discusses IE Emergency Preparedness Insp Rept 50-305/83-13 on 830829-0902 & forwards notice of violation
HIND, J A Region 3, Office of Director 83/10/18 GIESLER, C W
Wisconsin Public Service Corp 2pp 20961 114 24X
Fiche 50-305, 83/10/18, 8310310325

--8310310333 Notice of violation from Insp on 830829-0902 Noncompliance noted shift supervisors incapable of determining when & what type of protective measures should be considered outside site boundary due to inadequate training in procedures
HIND, J A Region 3, Office of Director 83/10/18 1p
20961 116 24X Fiche 50-305, 83/10/18, 8310310325

P Operating license stage documents & correspondence

8310040068 Forwards safety evaluation closing DHR issue based on 800620, 810713, 830824 & 0909 submittals
VARQA, S A Operating Reactors Branch 1 83/09/20 GIESLER, C W
Wisconsin Public Service Corp 2pp 20640 325 24X
Fiche 50-305, 83/09/20, 8310040068

--8310040072 Safety evaluation closing DHR issue (ref IE Bulletin 80-1)
* NRC - No Detailed Affiliation Given 83/09/20 11pp
20640 327 24X Fiche 50-305, 83/09/20, 8310040068

8310040617 Requests extension to 840701 for implementation of 10CFR50 54(m)(1) & (11) requirements re licensed operator staffing One add'l group of candidates must be prepared & examined to provide two senior reactor operators per shift
GIESLER, C W Wisconsin Public Service Corp 83/09/30 DENUNIO, H H
Office of Nuclear Reactor Regulation, Director 5pp 20626 176
24X Fiche 50-305, 83/09/30, 8310040617

8310120337 Forwards revised Surveillance Procedures SP 34-145C & SP 34-145D re low temp overpressure protection, inadvertently detached from 830923 ltr
GIESLER, C W Wisconsin Public Service Corp 83/10/05 VARQA, S A
Operating Reactors Branch 1 1p 20700 233 24X
Fiche 50-305, 83/10/05, 8310120337

--8310120341 Rev D to Surveillance Procedure SP 34-145D, "RHR Section Pressure Interlock Test & Calibr for Valves RHR-1A, 1B, 2A, 2B & 11"
MACSHAIN, D M Wisconsin Public Service Corp 82/05/21 14pp
20700 234 24X Fiche 50-305, 83/10/05, 8310120337

--8310120345 Rev C to Surveillance Procedure SP 34-145C, "RHR Section Pressure Transmitter PT 417 & PT 420 Calibr"
MACSHAIN, D M Wisconsin Public Service Corp 82/07/30 5pp
20700 248 24X Fiche 50-305, 83/10/05, 8310120337

8310180583 Forwards Amend 50 to License DPR-43 & safety evaluation Amend adds requirement for secondary water chemistry program & deletes previous water chemistry requirements
ORDENHUIS, M Operating Reactors Branch 1 83/10/06 GIESLER, C W
Wisconsin Public Service Corp 2pp 20824 030 24X
Fiche 50-305, 83/10/06, 8310180583

--8310180589 Amend 50 to License DPR-43, adding requirement for secondary water chemistry program & deleting previous water chemistry requirements
VARQA, S A Operating Reactors Branch 1 83/10/06 5pp
20824 032 24X Fiche 50-305, 83/10/06, 8310180583

--8310180598 Safety evaluation supporting Amend 50 to License DPR-43
* Office of Nuclear Reactor Regulation, Director. 83/10/06 3pp
20824 037 24X Fiche 50-305, 83/10/06, 8310180583

Q Inspection reports, IE Bulletins & correspondence

8310040051 Forwards safety evaluation of 830308 & 0719 requests for relief from exam of reactor coolant pump Relief from impractical requirements granted Notice of granting of relief encl
VARQA, S A Operating Reactors Branch 1 83/09/16 GIESLER, C W
Wisconsin Public Service Corp 2pp 20640 330 24X
Fiche 50-305, 83/09/16, 8310040051

--8310040056 Safety evaluation granting relief from exam of reactor coolant pump
* NRC - No Detailed Affiliation Given 83/09/16 5pp
20640 332 24X Fiche 50-305, 83/09/16, 8310040051

--8310040060 Notice of granting of relief from ASME Code XI requirements re inservice insp program Relief effective as of 830916
VARQA, S A Operating Reactors Branch 1 83/09/16 2pp
20640 337 24X Fiche 50-305, 83/09/16, 8310040051

8310040068 Forwards safety evaluation closing DHR issue based on 800620, 810713, 830824 & 0909 submittals
VARQA, S A Operating Reactors Branch 1 83/09/20 GIESLER, C W
Wisconsin Public Service Corp 2pp 20640 325 24X
Fiche 50-305, 83/09/20, 8310040068

--8310040072 Safety evaluation closing DHR issue (ref IE Bulletin 80-1)
* NRC - No Detailed Affiliation Given 83/09/20 11pp
20640 327 24X Fiche 50-305, 83/09/20, 8310040068

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 114pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 110pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310140002 Forwards IE Insp Rept 50-305/83-13 on 830829-0902 No noncompliance noted Protective action weaknesses in emergency plan discussed
PAPERIELLO, C J Region 3, Office of Director 83/09/28 GIESLER, C W Wisconsin Public Service Corp 4pp 20648 016 24X
Fiche 50-305, 83/09/28, 8310140002

--8310140013 IE Insp Rept 50-305/83-13 on 830829-0902 No noncompliance noted Major areas inspected emergency preparedness program, including actions on previously identified items, emergency detection & classification & public info program
SWELL, W B, LICKUS, R M, PHILLIPS, M P Region 3, Office of Director 83/09/28 16pp 20768 040 24X Fiche 50-305, 83/09/28, 8310140002

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310060330 Ack receipt of 830827 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-305/83-09 Supplemental response describing certification program for Reg Guide 1.5B compliance requested
SPESSARD, R L Division of Engineering 83/09/30 GIESLER, C W
Wisconsin Public Service Corp 2pp 20646 028 24X
Fiche 50-305, 83/09/30, 8310060330

--8310060334 Responds to NRC 830720 ltr re violations noted in IE Insp Rept 50-305/83-09 Corrective actions formal review of Tech Specs & license conditions will be performed to ensure that all appropriate requirements included in procedures
GIESLER, C W Wisconsin Public Service Corp 83/09/22 STREETER, J F Region 3, Office of Director 8pp 20646 030 24X
Fiche 50-305, 83/09/30, 8310060330

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 74pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8310120276 Confirms 831017 mgt meeting in Glen Ellyn, IL to discuss w/ 830923 response to IE Insp Rept 50-305/83-11, per 831004 telcon
HIND, J A Division of Radiological & Materials Safety Program 83/10/07 GIESLER, C W Wisconsin Public Service Corp 1p 20691 050 24X Fiche 50-305, 83/10/07, 8310120276

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

DOCKETED ITEMS

131

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310270438 Forwards IE Insp Rept 50-305/83-14 on 830912-16 No noncompliance noted
STREETER, J F Region 3, Office of Director 83/10/13 GIESLER, C W Wisconsin Public Service Corp 2pp 20923 031 24X
Fiche 50-305, 83/10/13, 8310270438

--8310270440 IE Insp Rept 50-305/83-14 on 830912-16 No noncompliance noted Major areas inspected maint program, implementation of maint program & nonroutine reporting program
CHOULES, N C, KISH, J N, HUNTER, D R Region 3, Office of Director 83/10/12 7pp 20923 033 24X Fiche 50-305, 83/10/13, 8310270438

8310180205 Clarifies NRC position on procedures for admitting NRC personnel Site-specific orientation re issuance of badges, escort duties, security briefings & emergency evaluations should be available to listed Region III personnel
AXELSON, W L Region 3, Office of Director 83/10/14 GIESLER, C W Wisconsin Public Service Corp 7pp 20808 324 24X
Fiche 50-305, 83/10/14, 8310180205

8310310325 Discusses IE Emergency Preparedness Insp Rept 50-305/83-13 on 830829-0902 & forwards notice of violation
HIND, J A Region 3, Office of Director 83/10/18 GIESLER, C W Wisconsin Public Service Corp 2pp 20961 114 24X
Fiche 50-305, 83/10/18, 8310310325

--8310310333 Notice of violation from insp on 830829-0902 Noncompliance noted shift supervisors incapable of determining when & what type of protective measures should be considered outside site boundary due to inadequate training in procedures
HIND, J A Region 3, Office of Director 83/10/18 1p 20961 114 24X Fiche 50-305, 83/10/18, 8310310325

R Periodic operating reports & related correspondence

8310170341 Monthly operating rept for Sept 1983, W/831010 ltr
RUITER, G H, GIESLER, C W Wisconsin Public Service Corp 83/09/30
Director's Office, Office of Inspection and Enforcement 5pp 20786 157 24X Fiche 50-305, 83/09/30, 8310170341

S Reportable occurrences, LERs & related correspondence

8310070301 Potential Part 21 rept re underrange characteristic of Model N-EILGM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERGERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X
Fiche 50-000, 83/09/30, 8310070301

8310210304 LER 83-019/03L-0 on 830916, component cooling water pump 1A taken out of svc on 3 separate occasions to perform corrective maint on inboard bearing oil seal leak Caused by misalignment of motor to pump Pump realigned W/831014 ltr
BERNHOF, S L, GIESLER, C W Wisconsin Public Service Corp 83/10/14 KEPLER, J G Region 3, Office of Director 2pp 20831 070 24X Fiche 50-305, 83/10/14, 8310210304

8310210317 LER 83-018/03L-0 on 830915, bonnet set screws on valve MS-100A failed to close Caused by loose electrical insulating matl Matl & contact cleaned W/831014 ltr
BERNHOF, S L, THORGERSON, J G, GIESLER, C W Wisconsin Public Service Corp 83/10/14 KEPLER, J G Region 3, Office of Director 2pp 20831 161 24X Fiche 50-305, 83/10/14, 8310210317

DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8310120269 Ack receipt of 830614.17 & 0728 ltrs forwarding changes to Rev 6 to corporate emergency plan & Rev 3 to plant emergency plan Changes acceptable, per 10CFR50.54(a) requirements
PAPERELLO, C J Region 3, Office of Director 83/10/06 LARSON, C E Northern States Power Co 1p 20690 348 24X
Fiche 50-000, 83/10/06, 8310120269

8310310123 Forwards safety evaluation based on util submittals re NUREG-0737, II B 2, "Design Review of Plant Shielding Access to Vital Areas " Requirements met
MILLER, J R Operating Reactors Branch 3 83/10/12 MUSOLF, D H Northern States Power Co 3pp 20963 324 24X
Fiche 50-282, 83/10/12, 8310310123

8310180195 Clarifies NRC position re procedures for admitting NRC insp personnel to facilities Lists identifying NRC personnel requiring escorted & unescorted access to vital plant areas encl Update will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 LARSON, C E Northern States Power Co 7pp 20809 054 24X
Fiche 50-282, 83/10/14, 8310180195

8310250538 Forwards final SALP 4 Rept 50-263/83-17 for Jul 1982 - June 1983
KEPLER, J G Region 3, Office of Director 83/10/20 LARSON, C E Northern States Power Co 2pp 20909 143 24X
Fiche 50-000, 83/10/20, 8310250538

--8310250561 Submits comments on 830921 meeting w/NRC to discuss SALP Rept 50-263/83-17 for Jul 1982 - June 1983 Valuable insights gained on improving performance
GILBERTS, D C Northern States Power Co 83/09/30 KEPLER, J G Region 3, Office of Director 1p 20902 175 24X
Fiche 50-000, 83/10/20, 8310250538

J Insurance & indemnity information

8310250239 Forwards Endorsements 56 & 57 to MAELU Policy MF-31 & Endorsements 68 & 69 to NELIA Policy NF-174 for Monticello & Endorsements 48 & 49 to MAELU Policy MI-68 & Endorsements 56 & 57 to NELIA Policy NF-19 for Prairie Island
JOHNSON, R G Northern States Power Co 83/10/20 DINI, I Division of Engineering 7pp 20899 036 24X Fiche 50-000, 83/10/20, 8310250239

P Operating license stage documents & correspondence

8310110498 Forwards safety evaluation re extended fuel burnup reload methodology based on Exxon assessment of potential radiological consequences for high exposure fuel
Justification acceptable
MILLER, J R Operating Reactors Branch 3 83/09/27 MUSOLF, D H Northern States Power Co 2pp 20714 319 24X
Fiche 50-282, 83/09/27, 8310110498

--8310110507 Safety evaluation supporting extended fuel burnup reload methodology based on Exxon assessment of potential radiological consequences for high exposure fuel
* NRC - No Detailed Affiliation Given 83/09/27 5pp 20714 321 24X Fiche 50-282, 83/09/27, 8310110498

8310130072 Forwards Amends 66 & 60 to Licenses DPR-42 & DPR-60, respectively & safety evaluation Amends change limit of core local flux ratio allowing localized linear heat generation rate increase factor for power uncertainty
DIANNI, D C Operating Reactors Branch 3 83/10/03 MUSOLF, D H Northern States Power Co 2pp 20776 137 24X
Fiche 50-282, 83/10/03, 8310130072

--8310130076 Amends 66 & 60 to Licenses DPR-42 & DPR-60, respectively, changing limit of core local heat flux ratio allowing localized linear heat generation rate increase factor for power uncertainty
MILLER, J R Operating Reactors Branch 3 83/10/03 11pp 20776 139 24X Fiche 50-282, 83/10/03, 8310130072

--8310130079 Safety evaluation supporting Amends 66 & 60 to Licenses DPR-42 & DPR-60, respectively
* Office of Nuclear Reactor Regulation, Director 83/10/03 5pp. 20776 150 24X Fiche 50-282, 83/10/03, 8310130072

8310170329 Notification of 831013 meeting w/util in Bethesda, MD to resolve seven open items in inservice test program for pumps & valves
DIANNI, D C Operating Reactors Branch 3 83/10/11 MILLER, J R Operating Reactors Branch 3 2pp 20795 274 24X
Fiche 50-282, 83/10/11, 8310170329

Q Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

DOCKETED ITEMS

8308300345 IE Info Notice 83-43, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-44, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310240086 Forwards IE Insp Repts 50-282/83-15 & 50-306/83-15 on 830811-0910 No noncompliance noted
SHAFER, W D Region 3, Office of Director 83/10/05 LARSON, C E Northern States Power Co 2pp 20881 318 24X Fiche 50-282, 83/10/05, 8310240086

--8310240102 IE Insp Repts 50-282/83-15 & 50-306/83-15 on 830811-0910 No noncompliance noted Major areas inspected plant operational safety, maint, surveillance, Followups of reactor trips.
IE bulletin & LERS
FEIERABEND, C D, WILLIAMS, D L, JACKIM, I N Region 3, Office of Director 83/10/04 8pp 20881 320 24X Fiche 50-282, 83/10/05, 8310240086

8308300378 IE Info Notice 83-45, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-46, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-47, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-48, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

10173 Forwards safety evaluation & FR notice re 830624 request for relief from ASME Boiler & Pressure Vessel Code concerning service insp of reactor coolant pump casing welds Request noted
LER, J R Operating Reactors Branch 3 83/10/12 MUSOLF, D M Northern States Power Co 3pp 20965 278 24X Fiche 50-282, 83/10/12, 8310310173

310310176 Safety evaluation granting until 830624 request for relief from ASME Boiler & Pressure Vessel Code concerning inservice insp of reactor coolant pump casing welds
* Office of Nuclear Reactor Regulation, Director 83/10/12 5pp 20965 281 24X Fiche 50-282, 83/10/12, 8310310173

--8310310177 Notice of granting of relief from ASME Code Section XI inservice insp requirements
MILLER, J R Operating Reactors Branch 3 83/10/12 2pp 20965 286 24X Fiche 50-282, 83/10/12, 8310310173

10180195 Clarifies NRC position re procedures for admitting NRC insp personnel to facilities Lists identifying NRC personnel requiring escorted & unescorted access to vital plant areas encl Update will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 LARSON, C E Northern States Power Co 7pp 20809 054 24X Fiche 50-282, 83/10/14, 8310180195

8310250275 Forwards SALP Repts 50-282/83-16 & 50-306/83-17 for Jul 1982 - June 1983
KEPPLER, J G Region 3, Office of Director 83/10/20 LARSON, C E Northern States Power Co 2pp 20895 292 24X Fiche 50-282, 83/10/20, 8310250275

--8310250278 SALP Repts 50-282/83-16 & 50-306/83-17 for Jul 1982 - June 1983 Overall rating of Category I assigned
* Region 3, Office of Director 83/10/20 24pp 20895 294 24X Fiche 50-282, 83/10/20, 8310250275

--8310250284 Forwards SALP rept for Jul 1982 - June 1983 in preparation for 830921 meeting Written comments may be provided within 20 days Following meeting W/o rept
HIND, J A Division of Radiological & Materials Safety Programs 83/09/16 GILBERTS, D E Northern States Power Co 7pp 20895 318 24X Fiche 50-282, 83/10/20, 8310250275

--8310250288 Comments on 830921 meeting w/NRC re SALP repts for Jul 1982 - June 1983
GILBERTS, D E Northern States Power Co 83/09/30 KEPPLER, J G Region 3, Office of Director 1p 20895 321 24X Fiche 50-282, 83/10/20, 8310250275

8310250538 Forwards final SALP 4 Rept 50-263/83-17 for Jul 1982 - June 1983
KEPPLER, J G Region 3, Office of Director 83/10/20 LARSON, C E Northern States Power Co 2pp 20902 143 24X Fiche 50-000, 83/10/20, 8310250538

--8310250538 Submits comments on 830921 meeting w/NRC to discuss SALP Rept 50-263/83-17 for Jul 1982 - June 1983 Valuable insights gained on improving performance
GILBERTS, D E Northern States Power Co 83/09/30 KEPPLER, J G Region 3, Office of Director 1p 20902 175 24X Fiche 50-000, 83/10/20, 8310250538

R Periodic operating reports & related correspondence

8310190055 Monthly operating repts for Aug 1983 W/830912 ltr
DUGSTAD, D, MUSOLF, D Northern States Power Co 83/09/02 Office of Resource Management, Director 9pp 20823 189 24X Fiche 50-282, 83/09/02, 8310190055

S Reportable occurrences, LERs & related correspondence

8310270340 FOIA request for placement of listed LERs in FDH
ORABEN, L D NUS Corp 83/09/08 Division of Rules and Records 2pp 20938 058 24X Fiche 50-000, 83/09/08, 8310270340

8310190340 Responds to FOIA request for documents re degradation of fuel assemblies while in spent fuel pool in US nuclear power plants Forwards App A documents App B documents available in PDR
FELTON, J M Division of Rules and Records 83/09/15 MAXWELL, B Rochester Post Bulletin, Rochester, MN 5pp 20844 058 24X Fiche 50-282, 83/09/15, 8310190340

--8304200240 Forwards matl presented by util during 830723 meeting re fuel assembly failure in spent fuel pool Review establishing NRC position on listed issues requested Working meeting scheduled for 830420 Encl withheld
DIANNI, D C Operating Reactors Branch 3 83/04/08 WU, P NRC No Detailed Affiliation Given 2pp 20844 129 24X Fiche 50-282, 83/09/15, 8310190340

--8305050044 Describes plan for review of Northern States Power Co & Westinghouse submittal on fuel assembly degradation while in spent fuel storage pool, prompted by fuel assembly cracking incident at Prairie Island
WU, P Chemical Engineering Branch 83/04/20 BENAROVA, V Chemical Engineering Branch 2pp 20844 131 24X Fiche 50-282, 83/09/15, 8310190340

--8305240300 Advises of informal preliminary review of potential safety issues that may exist as result of in-core fuel assembly nozzle separations Westinghouse analysis indicates no problem associated w/prevention of control rod insertions
TOKAR, M Core Performance Branch 83/05/16 WU, P Chemical Engineering Branch 2pp 20844 154 24X Fiche 50-282, 83/09/15, 8310190340

--8308180238 Forwards 830617 SER re fuel assembly corrosion in spent fuel pool & draft info notice addressing corrosion problems at BWRs & PWRs fuel assembly bulge joint B11216 failure w/o precedent & w/o determined cause W/o encls
BENAROVA, V Chemical Engineering Branch 83/08/02 HOLAHAN, C Operating Reactors Assessment Branch 2pp 20844 156 24X Fiche 50-282, 83/09/15, 8310190340

--8310190358 Forwards safety evaluation of fuel assembly failure event during fuel handling in spent fuel pool in Dec 1981 Evidence insufficient to deduce generic effect
JOHNSTON, W V Assistant Director for Matls, Chem & Environ Technology (Post 830201), 83/04/20 LAINAS, O C Assistant Director for Operating Reactors 4pp 20844 133 24X Fiche 50-282, 83/09/15, 8310190340

--8310190360 Safety evaluation concluding that evidence insufficient to draw generic conclusions from Dec 1981 fuel pool assembly failure event
* NRC - No Detailed Affiliation Given 83/04/20 17pp 20844 137 24X Fiche 50-282, 83/09/15, 8310190340

DOCKETED ITEMS

133

8310120340 LER 83-020/03L-0 on 830829, maint air lock door exhibited leakage of 21.000 sccm exceeding Tech Spec limit Caused by deterioration of Grafoil packing at inboard shaft seals Packing will be replaced prior to startup W/83092/ 1tr HUNSTAD, A A , NUSOLF, D Northern States Power Co 83/09/27 Region 3, Office of Director 2pp 20700 229 24X Fiche 50-306, 83/09/27, 8310120340

8310270347 Responds to FOIA request for release of 23 LERs to PMH Forwards 12 LERs to be released Documents also available in PDR One LER canceled Eight LERs not received FELTON, J M Division of Rules and Records 83/09/29 GRAUER, L D NUS Corp 1p 20938 060 24X Fiche 50-000, 83/09/29, 8310270347

--8310270429 LER 83-008/03L-0 on 830410, right hand stop valve failed Caused by separation of valve disc from clapper arm disc Valve repaired & will be replaced at next refueling outage Left hand stop valve also inspected W/830510 1tr HUNSTAD, A A , NUSOLF, D Northern States Power Co 83/05/10 Region 3, Office of Director 3pp 20938 098 24X Fiche 50-000, 83/09/29, 8310270347

8310070301 Potential Part 21 rept re underrange characteristic of Model N-E110M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERGERIAN, H J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X Fiche 50-000, 83/09/30, 8310070301

8310170641 LER 83-022/03L-0 on 830909, steam flow transmitter found out of calibr low by 1/4 Cause unknown Transmitter returned to vendor for analysis Rosemount Model 1153HA6 differential pressure transmitter replaced W/831004 1tr HUNSTAD, A A , NUSOLF, D Northern States Power Co 83/10/04 Region 3, Office of Director 2pp 20782 068 24X Fiche 50-306, 83/10/04, 8310170641

DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

F Security, medical, emergency & fire protection plans

8310270200 Provides objectives for 1983 full-scale emergency preparedness exercise scheduled for 831027, per 811026 request, constituting first milestone in development of exercise scenario package GARRITY, J H Maine Yankee Atomic Power Co 83/08/08 MURLEY, T E Region 1, Office of Director SPARKES, D M Federal Emergency Management Agency 3pp 20924 197 24X Fiche 50-309, 83/08/08, 8310270200

--8310270208 Forwards "1983 Maine Yankee Emergency Response Exercise & Evaluation Plan" for 831022 emergency preparedness exercise Exercise objectives (Attachment A of plan) revised to clarify objectives, per 830826 meeting w/NRC & FEMA WHITTIER, G D Maine Yankee Atomic Power Co 83/09/12 MURLEY, T E Region 1, Office of Director SPARKES, D M Federal Emergency Management Agency 2pp 20924 200 24X Fiche 50-309, 83/08/08, 8310270200

--8310270216 "1983 Maine Yankee Emergency Response Exercise & Evaluation Plan" * Maine Yankee Atomic Power Co 83/10/09 29pp 20924 202 24X Fiche 50-309, 83/08/08, 8310270200

8310060053 Informs that based on FEMA 830811 memo & rept, deficiencies identified in 821211 emergency exercise adequately addressed or corrected during 830601 mini-exercise No enforcement actions re deficiencies will be taken MURLEY, T E Region 1, Office of Director 83/09/27 RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 20647 056 24X Fiche 50-309, 83/09/27, 8310060053

8310180020 Forwards comments on 820812 detailed control room design review program plan Plan unacceptable per NUREG-0737, Suppl 1 Comments & response will be basis for telcon within 15 days of 1tr date MILLER, J R Operating Reactors Branch 3 83/10/04 GARRITY, J H Maine Yankee Atomic Power Co 10pp 20825 055 24X Fiche 50-309, 83/10/04, 8310180020

8310110064 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20687 152 24X Fiche 50-309, 83/10/05, 8310110064

--8310110066 Forwards public version of revised emergency plan implementing procedures, including Procedures 2 50 1 re notification of unusual events, 2 50 2 re alert & 2 50 3 re site area emergency Receipt form encl * Maine Yankee Atomic Power Co 83/09/07 Document Management Branch 1p 20687 153 24X Fiche 50-309, 83/10/05, 8310110064

--8310110069 Public version of revised emergency plan implementing procedures, including Procedures 2 50 1 re notification of unusual events, 2 50 2 re alert & 2 50 3 re site area emergency * Maine Yankee Atomic Power Co 83/08/26 164pp 20687 154 24X Fiche 50-309, 83/10/05, 8310110064

8310170163 Ack receipt of 830915 1tr supplementing response to Confirmatory Action Ltr 82-27 Long-term corrective actions will be examined during future insps STAROSTECKI, R Division of Project & Resident Programs 83/10/07 RANDAZZA, J B Maine Yankee Atomic Power Co 1p 20786 361 24X Fiche 50-309, 83/10/07, 8310170163

--8310170168 Suppls 821221 response to Confirmatory Action Ltr 82-27 re equipment tampering incident Encl withheld (ref 10CFR73 21) WHITTIER, G D Maine Yankee Atomic Power Co 83/09/15 MURLEY, T E Region 1, Office of Director 1p 20786 362 24X Fiche 50-309, 83/10/07, 8310170163

8310210265 Forwards IE Insp Rept 50-309/83-14 on 830823-25 No noncompliance noted MARTIN, T J Division of Engineering & Technical Programs 83/10/07 RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 20855 250 24X Fiche 50-309, 83/10/07, 8310210265

--8310210266 IE Insp Rept 50-309/83-14 on 830823-25 No noncompliance noted Major areas inspected public prompt notification sys CHEN, I CROCKER, H W Region 1, Office of Director 83/10/03 5pp 20855 260 24X Fiche 50-309, 83/10/07, 8310210265

8310270039 Releases public version of change to emergency plan FELTON, J M Division of Rules and Records 83/10/20 Document Management Branch 1p 20940 226 24X Fiche 50-309, 83/10/20, 8310270039

--8310270042 Public version of Change 5 to emergency plan W/831007 1tr & receipt form MARKT, D Yankee Atomic Electric Co MARKT, D Maine Yankee Atomic Power Co 83/09/01 Document Management Branch 59pp 20940 227 24X Fiche 50-309, 83/10/20, 8310270039

0 Adjudicatory correspondence

8310130167 Forwards until latest submittal on reactor vessel embrittlement, per 831005 telcon request Document being reviewed by NRC W/a encl ODDARD, R J Hearing Branch 3 83/10/11 STERN, P Maine, State of 1p 20724 297 24X Fiche 50-309, 83/10/11, 8310130167

8310180338 Order extending time until 831028 for Commission to act to review Director's Decision DD-83-15 CHILK, S J Office of the Secretary of the Commission 83/10/17 Commissioners 1p 20803 001 24X Fiche 50-309, 83/10/17, 8310180338

8310200225 Forwards NUS Corp rept, "Verification of GFLW Computer Code Using Experimental Data From Maine Yankee Spent Fuel Storage Pool" Rept referenced in Stuhmiller & Sargis testimony GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co 83/10/17 BLOCH, P B , PARIS, D H , SHON, F J Atomic Safety and Licensing Board Panel 84pp 20833 262 24X Fiche 50-309, 83/10/17, 8310200225

P Operating license stage documents & correspondence

8310110492 Requests brief summary of key points made during 830818 telcon & results of flux reduction program due to revised results for surveillance wall capsule 263 Submittal requested within 120 days of 1tr receipt MILLER, J R Operating Reactors Branch 3 83/09/24 GARRITY, J H Maine Yankee Atomic Power Co 3pp 20714, 357 24X Fiche 50-309, 83/09/24, 8310110492

8310040339 Informs that state finds no objections to proposed mods to Tech Specs re fuel handling accident inside containment MARTIN, R G Maine, State of 83/09/27 HEITNER, K, Office of Nuclear Reactor Regulation, Director 1p 20617 2/8 24X Fiche 50-309, 83/09/27, 8310040339

8310070202 Forwards sketch depicting current auxiliary feedwater sys w/planned mods (TMI Item I E 1), per 830922 1tr WHITTIER, G D Maine Yankee Atomic Power Co. 83/09/28 MILLER, J R Operating Reactors Branch 3 2pp 20659 117 24X Fiche 50-309, 83/09/28, 8310070202

DOCKETED ITEMS

8310140272 Forwards interim regulatory position on 10CFR55 31(e) re reactor operator & senior reactor operator functions. Plant manager or designee should review qualifications of operators returning to licensed functions
STAROSTECKI, R Division of Project & Resident Programs 83/09/30
RANDAZZA, J B Maine Yankee Atomic Power Co App 20761 239 24X
Fiche 50-309, 83/09/30, 8310140272

8310070159 Forwards schedule for proposed changes to Tech Specs & listing of Tech Spec changes under review by NRC Requests schedule for completion of review
WHITTIER, O D Maine Yankee Atomic Power Co 83/10/04 MILLER, J R
Operating Reactors Branch 3 3pp 20659 084 24X
Fiche 50-309, 83/10/04, 8310070159

8310170708 Advises that requirements of NUREG-0737, Item II K 3 P re test on PORVs met w/existing PORV safety valve & reactor high pressure trip setpoints Automatic PORV isolation sys (Item II K 3 I) not needed
MILLER, J R Operating Reactors Branch 3 83/10/04 GARRITY, J H
Maine Yankee Atomic Power Co 3pp 20813 200 24X
Fiche 50-309, 83/10/04, 8310170708

8310260429 Forwards request for addl info re valve inservice testing program based on review of 830808 submittal Response required within 30 days of receipt of ltr
MILLER, J R Operating Reactors Branch 3 83/10/07 GARRITY, J H
Maine Yankee Atomic Power Co 7pp 20926 328 24X
Fiche 50-309, 83/10/07, 8310260429

8310250677 Forwards SER re 830427 submittal on NUREG-0737, Item II K 2 17 re voiding in RCS during anticipated transients in C-E plants Voids generated in RCS accounted for in present analysis modes Review complete
MILLER, J R Operating Reactors Branch 3 83/10/11 GARRITY, J H
Maine Yankee Atomic Power Co 10pp 20908 339 24X
Fiche 50-309, 83/10/11, 8310250677

8310240216 Requests final submission of radiological effluent Tech Specs using NRC comments in 820901 ltr & encl Draft 7 of Rev 3 to NUREG-0472 as guidance Submittal schedule requested in 60 days W/O encl
MILLER, J R Operating Reactors Branch 3 83/10/12 GARRITY, J H
Maine Yankee Atomic Power Co 3pp 20901 315 24X
Fiche 50-309, 83/10/12, 8310240216

8310200225 Forwards NUS Corp rept, "Verification of DFIOW Computer Code Using Experimental Data From Maine Yankee Spent Fuel Storage Pool" Rept referenced in Stuhmiller & Sargis testimony
GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co
83/10/17 BLOCH, P B, PARIS, O H, SHON, F J Atomic Safety and Licensing Board Panel 84pp 20833 262 24X Fiche 50-309, 83/10/17, 8310200225

9310260358 Grants 830826 request for withholding "Seismological & Geological Studies, Miramich Area, New Brunswick & Central New Hampshire" Vols 1 & 2, "From public disclosure per OCFR2 790
MILLER, J R Operating Reactors Branch 3 83/10/17 GARRITY, J H
Maine Yankee Atomic Power Co 3pp 20910 348 24X
Fiche 50-309, 83/10/17, 8310260358

8250063 Responds to 831004 comments on util 830812 detailed control room design review plan NRC comments will be addressed in final rept
WHITTIER, O D Maine Yankee Atomic Power Co 83/10/19 MILLER, J R
Operating Reactors Branch 3 2pp 20896 076 24X
Fiche 50-309, 83/10/19, 8310250063

Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8300300342

108300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778-001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/O 10CFR50 59 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310190139 Forwards IE Insp Rept 50-309/83-10 on 830703-0904 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/10/04
RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 20820 247 24X
Fiche 50-309, 83/10/04, 8310190139

--8310190143 Notice of Violation from insp on 830703-0904
* Region 1, Office of Director 83/10/04 1p 20620 249 24X
Fiche 50-309, 83/10/04, 8310190139

--8310190139 IE Insp Rept 50-309/83-10 on 830703-0904 Noncompliance noted failure to perform safety evaluation re secondary component cooling HX B in 3 h in accordance w/10CFR50 59
SWETLAND, P, HOLDEN, C F, TRIMBLE, D Region 1, Office of Director 83/10/03 11pp 20820 250 24X Fiche 50-309, 83/10/04, 8310190139

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTU Bypass Loops Used in Westinghouse Plants" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8310170163 Ack receipt of 830915 ltr supplementing response to Confirmatory Action Ltr 82-27 Long-term corrective actions will be examined during future insps
STAROSTECKI, R Division of Project & Resident Programs 83/10/07
RANDAZZA, J B Maine Yankee Atomic Power Co 1p 20786 361 24X
Fiche 50-309, 83/10/07, 8310170163

--8310170168 Suppls 821221 response to Confirmatory Action Ltr 82-27 re equipment tampering incident Encl withheld (ref 10CFR73 21)
WHITTIER, O D Maine Yankee Atomic Power Co 83/09/15
MURLEY, T E Region 1, Office of Director 1p 20786 362 24X
Fiche 50-309, 83/10/07, 8310170163

8310210265 Forwards IE Insp Rept 50-309/83-14 on 830823-25 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/10/07
RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 20855 258 24X
Fiche 50-309, 83/10/07, 8310210265

--8310210266 IE Insp Rept 50-309/83-14 on 830823-25 No noncompliance noted Major areas inspected public prompt notification sys
COHEN, I, CROCKER, H W Region 1, Office of Director 83/10/03
5pp 20855 260 24X Fiche 50-309, 83/10/07, 8310210265

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310210185 Ack receipt of 830908 & 1003 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/83-06
STAROSTECKI, R Division of Project & Resident Programs 83/10/17
RANDAZZA, J B Maine Yankee Atomic Power Co 1p 20855 105 24X
Fiche 50-309, 83/10/17, 8310210185

--8310210194 Responds to NRC 830808 ltr re violations noted in IE Insp Rept 50-309/83-06 Corrective actions sys drawings will be placed in control room for ref Operators & engineers reviewed containment integrity valve list
WHITTIER, O D Maine Yankee Atomic Power Co 83/09/08
MURLEY, T E Region 1, Office of Director 3pp 20855 106 24X
Fiche 50-309, 83/10/17, 8310210185

DOCKETED ITEMS

135

--B310210208 Provides addl info in response to B30808 ltr re violation noted in IE Insp Rept 50-309/B3-06 Recommendations resulting from broad scope operations reviews will be included in quality improvement program
WHITTIER, Q D Maine Yankee Atomic Power Co 83/10/03
MURLEY, T E Region 1, Office of Director 1p 20855 104 24X
Fiche 50-309, 83/10/17, B310210185

B310210286 Ack receipt of B30902 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/B3-12
MARTIN, T T Division of Engineering & Technical Programs 83/10/17
RANDAZZA, J B Maine Yankee Atomic Power Co 1p 20848 207 24X
Fiche 50-309, 83/10/17, B310210286

--B310210294 Responds to NRC B3080P ltr re violations noted in IE Insp Rept 50-309/B3-12 Corrective actions procedures for control & implementation of inservice testing activities developed & operation dept procedures revised
GARRITY, J H Maine Yankee Atomic Power Co 83/09/02 MURLEY, T E
Region 1, Office of Director 4pp 20848 208 24X
Fiche 50-309, 83/10/17, B310210286

R Periodic operating reports & related correspondence

B310190033 Monthly operating rept for Aug 1983 W/B30908 ltr
BATTERSON, S , GRACE, R H Maine Yankee Atomic Power Co 83/09/08
HARTFIELD, R A Management Information Branch 5pp 20823 249 24X
Fiche 50-309, 83/09/08, B310190033

S Reportable occurrences, LERs & related correspondence

B310030308 Forwards response to B30816 memo re B30125 main feedwater line break Response based on NUREG-0918, NUREG-0691 & proposed rev to Jan-Mar AD rept
DIRCKS, W J Office of the Executive Director for Operations
83/09/21 ASSELBTINE, J K Commissioners 13pp 20604 039 24X
Fiche 50-309, 83/09/21, B310030308

--B306020357 Operating Reactor Event Memorandum B3-01 re B30125 loss-of-main-feedwater event which resulted in rupture of main feedwater line 2 Plant-specific PNA studies addressing Generic Issue A-01 on water hammer recommended
EISENHUT, D G Division of licensing 83/09/20 SPLIS, T
Division of Safety Technology VOLLMER, R Division of Engineering MATTSO, R Division of Systems Integration (post B11005) 17pp 20604 052 24X Fiche 50-309, 83/09/21, B310030308

--B310030316 Requests responses to listed questions re main feedwater line break due to water hammer
ASSELBTINE, J K Commissioners 83/08/16 DIRCKS, W J Office of the Executive Director for Operations 3pp 20604 071 24X
Fiche 50-309, 83/09/21, B310030308

B310040455 PNO-I-B3-099 on B30930, contract for bargaining unit (Util Workers Union of America, Local 497) expires IF strike occurs, insp will be provided to confirm of plant transition by mgt personnel
HOLDEN, C , HIGGINS, J , GREENMAN, E Region 1, Office of Director
83/09/29 1p 20623 325 24X Fiche 50-309, 83/09/29, B310040455

B310190231 LER B3-031/03L-0 on B30830, while at steady-state full power operation, excessive packing leakage discovered in HPFI loop injection stop valves Caused by loss of packing Related events occurred on B30831, 0912 & 19 W/B30929 ltr
MCALLISTER, S A , WHITTIER, Q D Maine Yankee Atomic Power Co
83/09/29 MURLEY, T E Region 1, Office of Director 3pp
20818 052 24X Fiche 50-309, 83/09/29, B310190231

B310250584 Forwards LER B3-031/03L-0 re HPFI valve repairs W/o encl
WHITTIER, Q D Maine Yankee Atomic Power Co 83/09/29 MURLEY, T E
Region 1, Office of Director 1p 20900 362 24X
Fiche 50-309, 83/09/29, B310250584

B310060344 Updated PNO-I-B3-099A on B30930, negotiations continuing between Util & Util Workers of America to settle terms of contract expiring at midnight Plans in place for NRC insp coverage of operations to ensure smooth mgt transition
HOLDEN, C , HIGGINS, J , GREENMAN, E Region 1, Office of Director
83/09/30 1p 20646 127 24X Fiche 50-309, 83/09/30, B310060344

B310060253 PNO-I-B3-009B on B30930, licensee & Util Workers of America negotiations failed to produce settlement Operations turned over to supervisory personnel Settlement approved by union membership on B31001
HOLDEN, C , HIGGINS, J , GREENMAN, E Region 1, Office of Director
83/10/03 1p 20647 033 24X Fiche 50-309, 83/10/03, B310060253

B310120165 Provides addl info re instances where design of main feedwater trip did not meet single failure criteria reported in LER B3-028/01T-1 Continued operation until next shutdown justified
WHITTIER, Q D Maine Yankee Atomic Power Co 83/10/03 MILLER, J R
Operating Reactors Branch 3 4pp 20695 354 24X
Fiche 50-309, 83/10/03, B310120165

B310200108 LER B3-033/03L-0 on B30906, cooling water outlet stop valve SCC-M165 to RHR HX failed to open by use of control switch from main control board Caused by internal valve mechanical problem Upgraded maint program developed W/B31006 ltr
STEVENS, J L , WHITTIER, Q D Maine Yankee Atomic Power Co 83/10/06
MURLEY, T E Region 1, Office of Director 4pp 20837 078 24X
Fiche 50-309, 83/10/06, B310200108

B310140082 PNO-I-B3-105 on B31007, seismic event occurred in northeastern US w/magnitude of 5.2 on Richter scale in NY & 4.0 in NH No damage to equipment identified
GALLLO, R M Region 1, Office of Director 83/10/07 1p 20766 116 24X
Fiche 50-000, 83/10/07, B310140082

B310250280 LER B3-034/01T-0 while at steady-state full power operations, containment integrity inadvertently compromised when inner personnel hatch door opened No containment weight of air deviations encountered
WOOD, E C Maine Yankee Atomic Power Co 83/10/14 Region 1, Office of Director 1p 20894 231 24X
Fiche 50-309, 83/10/14, B310250280

V Operator Examinations

B310040616 Request extension to Jul 1984 for compliance w/increased shift manning rule 10CFR50.54 due to ineligible senior reactor operator license candidates Region 1 evaluation not final
WHITTIER, Q D Maine Yankee Atomic Power Co 83/09/30 MILLER, J R
Operating Reactors Branch 3 2pp 20626 181 24X
Fiche 50-309, 83/09/30, B310040616

DOCKET 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B309190260 Forwards correct page revs to security plan & security training & qualification plan Page revs withheld (ref 10CFR73.21)
* Public Service Electric & Gas Co of New Jersey 83/09/12
MARTIN, T T Division of Engineering & Technical Programs 1p
20415 362 24X Fiche 50-272, 83/09/12, B309190260

B310210195 Forwards marked-up revised 1983 emergency exercise Rev incorporates NRC & FEMA comments from B30804 meeting Addl info re operational data & engineering problems will be submitted 2 wks prior to exercise
MOELLER, P A Public Service Electric & Gas Co of New Jersey
83/09/12 MURLEY, T E Region 1, Office of Director 143pp
20846 147 24X Fiche 50-272, 83/09/12, B310210195

B310250512 Forwards IE Safeguards Insp Repts 50-272/B3-28 & 50-311/B3-28 on B30907-09 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/10/04
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp
20901 052 24X Fiche 50-272, 83/10/04, B310250512

--B310250529 IE Safeguards Insp Repts 50-272/B3-28 & 50-311/B3-28 on B30907-09 No noncompliance noted Major areas inspected security sys power supply, detection aids - vital areas & licensee implementing procedure evaluation
SMITH, Q C Region 1, Office of Director 83/10/03 2pp
20901 054 24X Fiche 50-272, 83/10/04, B310250512

K Utility Final Safety Analysis Report (FSAR) & amends

B310180251 Forwards Rev 2 to updated FSAR, consisting of drawings updated since B30802 Rev 1
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/10/12 VARGA, B A Operating Reactors Branch 1 2pp 20809 238 24X
Fiche 50-272, 83/10/12, B310180251

--B310180253 Rev 2 to updated FSAR, consisting of drawings updated since B30802 Rev 1
* Public Service Electric & Gas Co of New Jersey 83/09/23
39pp 20809 240 24X Fiche 50-272, 83/10/12, B310180251

DOCKETED ITEMS

P Operating license stage documents & correspondence

8310050159 Forwards "Plan for Improvement of Nuclear Dept Operations," in response to Basic Energy Technology Assoc. Inc rept & cross ref document, "Rept on Review of Corrective Action Program re Reactor Trip Breaker Failures" UDERITZ, R A Public Service Electric & Gas Co of New Jersey 83/08/26 VARGA, S A Operating Reactors Branch 1 2pp 20632 170 24X Fiche 50-272, 83/08/26, 8310050159

--8310050164 "Plan for Improvement of Nuclear Dept Operations" * Public Service Electric & Gas Co of New Jersey 83/08/26 59pp 20632 180 24X Fiche 50-272, 83/08/26, 8310050159

8310070097 Forwards safety evaluation of design of RCS vents Design conforms w/requirements of NUREG-0737, Item II B 1, CDC J, 2, 4, 14, 30 & 31 & 10CFR50 44(c)(3)(iii) w/exception of positive valve position indication VARGA, S A Operating Reactors Branch 1 83/09/27 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 3pp 20671 347 24X Fiche 50-272, 83/09/27, 8310070097

--8310070103 Safety evaluation of RCS vent design Design complies w/ NUREG-0737, Item II B 1, CDC J, 2, 4, 14, 30 & 31 & 10CFR50 44 * NRC - No Detailed Affiliation Given 83/05/17 6pp 20673 352 24X Fiche 50-272, 83/09/27, 8310070097

--8306080112 "Selected Operating Reactor Issues Program II RCS Vents (NUREG-0737, Item II B 1)." Final technical evaluation rept for Salem 1 & 2 HELD, J T Energy Incorporated FIN A-0250 TF-343/0809A 83/02/23 ALBERTHAL, O Division of Licensing 6pp 20673 358 24X Fiche 50-272, 83/09/27, 8310070097

8310070166 Advises that automatic PORV isolation will not be provided & PORV & block valve control sys will not be modified, based on "Probabilistic Analysis & Operational Data in Response to NUREG-0737, Item II, K 3 2 for Westinghouse NSSS Plants" LIDEN, E A Public Service Electric & Gas Co of New Jersey 83/09/27 VARGA, S A Operating Reactors Branch 1 2pp 20659 100 24X Fiche 50-272, 83/09/27, 8310070166

8310060327 Application to amend License DPR-75, changing surveillance test requirement for maintaining control room at positive pressure of 1/4-inch to 1/8-inch W/O relative to outside atmosphere LIDEN, E A Public Service Electric & Gas Co of New Jersey 83/09/28 VARGA, S A Operating Reactors Branch 1 6pp 20644 021 24X Fiche 50-311, 83/09/28, 8310060327

--8310060328 Proposed Tech Spec re surveillance test requirement for maintaining control room at positive pressure of 1/4-inch to 1/8-inch W/O relative to outside atmosphere * Public Service Electric & Gas Co of New Jersey 83/09/28 1p 20644 027 24X Fiche 50-311, 83/09/28, 8310060327

830325 Application to amend License DPR-75, deleting generic requirement for steam generator upper insp ports requirement previously determined unnecessary by NRC LIDEN, E A Public Service Electric & Gas Co of New Jersey 1/29 VARGA, S A Operating Reactors Branch 1 3pp 20644 010 1che 50-311, 83/09/29, 8310060325

8303 Forwards remittance for License Change Requests 83-07, 83-10 11 LIDEN, E A Public Service Electric & Gas Co of New Jersey 1/30 VARGA, S A Operating Reactors Branch 1 1p 20658 245 1che 50-272, 83/09/30, 8310070003

70039 Forwards SER & technical evaluation rept re license changes to NUREG-0737, Items II K 3 1, "Automatic PORV Isolation" & II K 3 2, "Rept on PORVs" VARGA, S A Operating Reactors Branch 1 83/10/05 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 3pp 20812 162 4X Fiche 50-272, 83/10/05, 8310170039

8318 Forwards "Reactor Containment Bldg First Inservice Integrated Leak Rate Test & Type B & C Surveillance Test," used during first refueling outage on 830523 Summary of leak prior to first inservice Type A test also encl LIDEN, E A Public Service Electric & Gas Co of New Jersey 1/13 VARGA, S A Operating Reactors Branch 1 5pp 20830 154, Fiche 50-311, 83/10/13, 8310200318

83023 "Reactor Containment Bldg First Inservice Integrated Leak Rate Test & Type B & C Surveillance Test" LIDEN, E A Public Service Electric & Gas Co of New Jersey 83/05/31 1, 20830 164 24X Fiche 50-311, 83/10/13, 8310200318

8310210285 Forwards addl fee required for Class I amend re Rev 1 to License Change Request 79-01 Original fee paid for single Class III amend only LIDEN, E A Public Service Electric & Gas Co of New Jersey 83/10/13 VARGA, S A Operating Reactors Branch 1 1p 20855 265 24X Fiche 50-272, 83/10/13, 8310210285

Q Inspection reports, IE Bulletins & correspondence

8310310225 Forwards "Rept of Exams, Insp & Tests Conducted During 1983 First Refueling of Salem 2," per IE Circular 16-06 LIDEN, E A Public Service Electric & Gas Co of New Jersey 83/09/21 MURPHY, T E Region 1, Office of Director 2pp 20947 231 24X Fiche 50-311, 83/09/21, 8310310225

--8310310225 "Rept of Exams, Insp & Tests Conducted During 1983 First Refueling of Salem 2" * Public Service Electric & Gas Co of New Jersey 83/09/14 1p 20947 232 24X Fiche 50-311, 83/09/21, 8310310225

8308300340 IE Info Notice 83-61, "Alleged Use of Stand Ins For Welder Qualification Tests" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-i Differential Relays" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310140003 Discusses IE Insp Rept 50-311/83-18 on 830509-18 & forwards notice of violation Insp conducted to review loss of reactor vessel overpressure protection MURLEY, T C Region 1, Office of Director 83/09/26 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 3pp 20767 001 24X Fiche 50-311, 83/09/26, 8310140003

--8310140004 Notice of violation from inrp on 830509-18 Noncompliance noted RCS not depressurized w/designated RCS vent of greater than or equal to 3 14 square inches * Region 1, Office of Director 83/09/26 2pp 20767 004 24X Fiche 50-311, 83/09/26, 8310140003

8310140274 Forwards IE Insp Repts 50-272/83-25 & 50-311/83-26 on 830810-0906 No noncompliance noted STARDSTECK, R Division of Project & Resident Programs 83/09/26 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp 20761 214 24X Fiche 50-272, 83/09/26, 8310140274

--8310140279 IE Insp Repts 50-272/83-25 & 50-311/83-26 on 830810-0906 No noncompliance noted Major areas inspected conformance w/Tech Specs, log & record reviews, followups on previous insp items & review of licensee events LINVILLE, J C, SUMMERS, R J, JACOBS, R H Region 1, Office of Director 83/09/26 15pp 20761 216 24X Fiche 50-272, 83/09/26, 8310140274

8308300347 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300347

8310060325 Application to amend License DPR-75, deleting generic requirement for steam generator upper insp ports requirement previously determined unnecessary by NRC LIDEN, E A Public Service Electric & Gas Co of New Jersey 83/09/29 VARGA, S A Operating Reactors Branch 1 3pp 20644 010 24X Fiche 50-311, 83/09/29, 8310060325

8310110381 Discusses until 830706 & 0722 responses to 830505 notice of violation & proposed imposition of civil penalty identified during review of ATWS events on 830222 & 25 Order encl imposing civil penalty in amount of \$850,000 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/09/29 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp 20713 281 24X Fiche 50-272, 83/09/29, 8310110381

DOCKETED ITEMS

137

831010387 Order imposing civil monetary penalties in amount of \$850,000 re violation of Tech Spec 3.3.1.1 requiring two reactor trip breakers to be operable when reactor operating in Modes 1 & 2
DEYOUNG, K. C. Director's Office, Office of Inspection and Enforcement 87/09/29 Public Service Electric & Gas Co. of New Jersey 14pp 20710 283 24X Fiche 50-272, 83/09/29, 831010387

8310250512 Forwards IE Safeguards Insp Repts 50-272/83-28 & 50-311/83-28 on 830907-09 No noncompliance noted
MARTIN, T. I. Division of Engineering & Technical Programs 83/10/04 UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey 2pp 20901 052 24X Fiche 50-272, 83/10/04, 8310250512

8310250529 IE Safeguards Insp Repts 50-272/83-28 & 50-311/83-28 on 830907-09 No noncompliance noted Major areas inspected security sys power supply, detection aids - vital areas & licensee implementing procedure evaluation
SMITH, C. C., GODY, A. T. Region 1, Office of Director 83/10/03 2pp 20901 054 24X Fiche 50-272, 83/10/04, 8310250512

831080391 Ack receipt of 830829 & 0922 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-13 & 50-311/83-19
STAROSTECKI, R. Division of Project & Resident Programs 83/10/05 UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey 1p 20803 313 24X Fiche 50-272, 83/10/05, 831080391

831080398 Responds to NRC 830729 ltr re violations noted in IE Insp Repts 50-272/83-13 & 50-311/83-19 Corrective actions ECCS throttle valve positions corrected & verified & TRIS worksheet footnote revised re FCCS throttle valves
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey 83/09/22 STAROSTECKI, R. Division of Project & Resident Programs 3pp 20803 314 24X Fiche 50-272, 83/10/05, 831080391

83080378 IE Info Notice 83-65, "Surveillance of Flow in HTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 74pp 20827 213 24X Fiche 50-000, 83/10/07, 830803078

83080752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308030752

83080759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308030759

83080761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308030761

8280119 Forwards "1983 Inservice Exam of Class 1 & 2 Components & Sys of Salem Generating Station, Unit 2," final rept, Vols 1 & 2
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey 3/10/20 VARQA, S. A. Operating Reactors Branch 1 10pp 10929 281 24X Fiche 50-311, 83/10/20, 8310280119

8310280122 "1983 Inservice Exam of Selected Class 1 & 2 Components & Sys of Salem Generating Station, Unit 2," final rept, Vols 1 & 2
RICHTER, S. W. Southwest Research Institute FLACH, W. T. Public Service Electric & Gas Co. of New Jersey 83/07/31 1054pp 20929 299 24X Fiche 50-311, 83/10/20, 8310280119

Periodic operating reports & related correspondence

8310225 Forwards "Rept of Exams, Insps & Tests Conducted During 83 Refueling of Salem 2," per IE Circular 76-06
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey 3/09/21 MURLEY, T. E. Region 1, Office of Director 2pp 0947 231 24X Fiche 50-311, 83/09/21, 8310310225

8310310229 "Rept of Exams, Insps & Tests Conducted During 1983 First Refueling of Salem 2 "
Public Service Electric & Gas Co. of New Jersey 83/09/15 1p 20947 232 24X Fiche 50-311, 83/09/21, 8310310225

83080346 "NPDES Discharge Monitoring Rept for Aug 1983 " W/830906 tr
MILLER, L. K. Public Service Electric & Gas Co. of New Jersey 3/09/23 21pp 20590 164 24X Fiche 50-272, 83/09/23, 8310030346

831080114 Revised monthly operating rept for Aug 1983 W/830920 ltr
MILLER, L. K., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 83/10/10 Director's Office, Office of Inspection and Enforcement 2pp 20807 173 24X Fiche 50-311, 83/10/10, 831080114

8310210041 Monthly operating rept for Sept 1983 W/831010 ltr
MILLER, L. K., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 83/10/10 Director's Office, Office of Inspection and Enforcement 18pp 20955 348 24X Fiche 50-311, 83/10/10, 8310210041

S Reportable occurrences, LIRs & related correspondence

8310050159 Forwards "Plan For Improvement of Nuclear Dept Operations," in response to Basic Energy Technology Assoc, Inc rept & cross ref document, "Rept on Review of Corrective Action Program re Reactor Trip Breaker Failures "
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey 83/08/26 VARQA, S. A. Operating Reactors Branch 1 2pp 20632 170 24X Fiche 50-272, 83/08/26, 8310050159

8310190178 LER 83-038/03L-0 on 830827, vital bus 2B hydrogen analyzer channels 12 & 22 failed to restart Caused by voltage transient Channel circuits replaced & restarted & action statement terminated W/830926 ltr
FRAHM, R., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 83/09/26 MURLEY, T. E. Region 1, Office of Director 4pp 20820 207 24X Fiche 50-311, 83/09/26, 8310190178

8310250407 LER 83-048/03L-0 on 830927, attempts to demonstrate operability of pressurizer overpressure protection sys valves failed Caused by problems w/valve position indicators PORV circuitry modified W/830927 ltr
FRAHM, R., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 83/09/27 MURLEY, T. E. Region 1, Office of Director 5pp 20897 240 24X Fiche 50-311, 83/09/27, 8310250407

8310250470 Supplemental LER 82-034/03X-1 on 820501, during routine operation, two feedwater sys snubbers seized Caused by excessive shock load on sys snubbers replaced W/830927 ltr
FRAHM, R., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 83/09/27 MURLEY, T. E. Region 1, Office of Director 5pp 20897 120 24X Fiche 50-311, 83/09/27, 8310250470

8310250567 LER 83-047/03L-0 on 830829, various 2A safeguards equipment control (SEC) alarms received on 830830 vital bus 2A tripped w/o automatic transfer Cause under investigation SEC channel reset Power restored to bus W/830927 ltr
FRAHM, R., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 83/09/27 MURLEY, T. E. Region 1, Office of Director 5pp 20901 016 24X Fiche 50-311, 83/09/27, 8310250567

8310040213 PMS-I-83-019 on 830923, licensee contract security organization suspended two security guards Guard admitted to bringing illegal substance on site Other guard did not rept incident Both guards terminated 830925
MADSEN, W., GODY, A. Region 1, Office of Director 83/09/28 1p 20614 273 24X Fiche 50-272, 83/09/28, 8310040213

8310110179 Notification of Significant Licensee Meeting 83-87 on 831011 at site to discuss ATWS event corrective action program
KISTER, H. B. Region 1, Office of Director 83/09/29 Region 1, Office of Director 1pp 20687 353 24X Fiche 50-272, 83/09/29, 8310110179

8310140038 PND-I-83-106 on 831007, plant shutdown from 100% power due to apparent hydrogen leakage into generator stator water cooling sys Similar occurrence on 830819 resulted in 5-wk outage States of NJ & DE informed
LINVILLE, J., JACOBS, R., NARRIOLM, L. Region 1, Office of Director 83/10/07 1p 20768 083 24X Fiche 50-311, 83/10/07, 8310140038

8310200279 LER 83-049/01T-0 on 830923, containment compressed air supply isolation valve discovered not locked closed Caused by personnel error during verification of equipment status during mode change Operators counseled W/831007 ltr
FRAHM, R., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 83/10/07 MURLEY, T. E. Region 1, Office of Director 5pp 20829 322 24X Fiche 50-311, 83/10/07, 8310200279

8310250244 LER 83-050/03L-0 on 830916, pressure drop test surveillance of containment isolation valves 2VC5 & 2VC6 revealed that leakage past valves greater than max range of test equipment Caused by deformed elastomer lining W/831012 ltr
FRAHM, R., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 83/10/12 MURLEY, T. E. Region 1, Office of Director 4pp 20899 146 24X Fiche 50-311, 83/10/12, 8310250244

DOCKETED ITEMS

V Operator Examinations

B310250257 Responds to J Buzy telcon re licensed operator requalification Training Procedure TP-305 Exam will be completely changed at least every 6 wks.
LIDEN, E A Public Service Electric & Gas Co of New Jersey
B3/10/17 VARGA, S A Operating Reactors Branch 1 2pp 20878 357
24X Fiche 50-272, B3/10/17, B310250257

DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

E NRC Safety Evaluation Report (SER), suppl's & correspondence

B310030436 Forwards legible Pages 35 & 37 to SER transmitted on B3047
LESSY, R P Hearing Branch 3 B3/09/28 ROSENTHAL, A S, BUCK, J H,
KOHLE, C N Atomic Safety and Licensing Appeal Panel 3pp
20633 337 24X Fiche 50-312, B3/09/28, B310030436

F Security, medical, emergency & fire protection plans

B310030602 Forwards evaluation of B20528 request for exemption from Subsection III G 2 of App R re electrical penetration area of auxiliary bldg Level of fire protection does not meet requirement Exemption denied
EISENHUT, D G Division of Licensing B3/09/19 RODRIGUEZ, R J
Sacramento Municipal Utility District 8pp 20626 289 24X
Fiche 50-312, B3/09/19, B310030602

B310050117 Requests schedule for completing responses to Generic Ltr B1-12 re alternative shutdown capability, schedule for installing mods & compensatory measures to achieve hot standby & cold shutdown info requested within 2 wks
STOLZ, J F Operating Reactors Branch 4 B3/09/19 RODRIGUEZ, R J
Sacramento Municipal Utility District 5pp 20650 204 24X
Fiche 50-312, B3/09/19, B310050117

B310060021 Forwards "Control Room Design Review Program Plan," per B30415 & 0720 commitments in response to Suppl 1 to NUREG-0737
RODRIGUEZ, R J Sacramento Municipal Utility District B3/09/30
STOLZ, J F Operating Reactors Branch 4 1p 20649 262 24X
Fiche 50-312, B3/09/30, B310060021

--B310060022 "Control Room Design Review Program Plan,"
* Sacramento Municipal Utility District B3/09/30 14pp
20649 263 24X Fiche 50-312, B3/09/30, B310060022

O Adjudicatory correspondence

B310030401 Forwards util B30921 ltr to NRC reporting on radiographic insp of NPI nozzles C & D Svc list encl Related correspondence
TRAVIESO-DIAZ, Shaw, Pittman, Potts & Trowbridge TRAVIESO-DIAZ
Sacramento Municipal Utility District B3/09/27 ROSENTHAL, A S,
BUCK, J H, KOHL, C N Atomic Safety and Licensing Appeal Panel 4pp
20593 070 24X Fiche 50-312, B3/09/27, B310030401

B310050512 Responds to ASLAB request for NRC final position on review of upgraded auxiliary feedwater sys & related questions Util rescheduled completion of upgraded sys to refueling Outage B currently estimated in Apr 1986
LESSY, R P Hearing Branch 3 B3/09/27 ROSENTHAL, A S, BUCK, J H,
KOHLE, C N Atomic Safety and Licensing Appeal Panel 3pp
20634 050 24X Fiche 50-312, B3/09/27, B310050512

--B310050517 Affidavit of S Miner re ASLAB questions on installation of upgraded auxiliary feedwater sys Util rescheduled installation completion for refueling Outage B, estimated in Apr 1986
MINER, S Operating Reactors Branch 4 B3/09/27 4pp 20634 054
24X Fiche 50-312, B3/09/27, B310050517

--B310050521 Affidavit of ED Sylvester re ASLAB questions on installation of upgraded auxiliary feedwater sys per TH1 Item II E 1 i
Upgraded design will not meet current reliability guidelines SER encl
SYLVESTER, E D Auxiliary Systems Branch B3/09/27 46pp
B1034 076 24X Fiche 50-312, B3/09/27, B310050521

B310050436 Forwards legible Pages 35 & 37 to SER transmitted on B30927
LESSY, R P Hearing Branch 3 B3/09/28 ROSENTHAL, A S, BUCK, J H,
KOHLE, C N Atomic Safety and Licensing Appeal Panel 3pp
20633 337 24X Fiche 50-312, B3/09/28, B310050436

P Operating license stage documents & correspondence

B310030611 Forwards SER on generic mods to reactor trip breakers for B&W plants to provide automatic actuation of shunt trip attachments Plant-specific info should be provided when generic design endorsed in response to Generic Ltr B3-28
STOLZ, J F Operating Reactors Branch 4 B3/09/12 RODRIGUEZ, R J
Sacramento Municipal Utility District 2pp 20607 298 24X
Fiche 50-312, B3/09/12, B310030611

B310250591 Forwards Std Order For DOE Work "Operating Reactors Licensing Actions - Tech Specs for Hydraulic & Mechanical Snubbers for Trojan & Rancho Seco"
ADAMS, C Energy, Dept of FIN B-8559 B3/09/16 MARTIN, J B
Region 5, Office of Director 1p 20900 124 24X
Fiche 50-000, B3/09/16, B310250591

--B310250600 Std order for DOE Work "Operating Reactors Licensing Actions - Tech Specs for Hydraulic & Mechanical Snubbers for Trojan & Rancho Seco," issued to LLL
MARTIN, J B Region 5, Office of Director MACRUSKY, J Lawrence
Livermore Laboratory FIN B-8559 B3/08/31 1p 20900 124 24X
Fiche 50-000, B3/09/16, B310250591

--B310250625 Forwards project & budget proposal for NRC work "Operating Reactors Licensing Actions Tech Specs for Hydraulic & Mechanical Snubbers for Trojan & Rancho Seco"
STUART, K J Lawrence Livermore Laboratory FIN B-8562 B3/08/16
BISHOP, T W Region 5, Office of Director 1p 20900 124 24X
Fiche 50-000, B3/09/16, B310250591

--B310250631 Project & budget proposal for NRC work "Operating Reactors Licensing Actions Tech Specs for Hydraulic & Mechanical Snubbers for Trojan & Rancho Seco"
CLELAND, L L, WHITE, R, JOHNSON, J H Lawrence Livermore
Laboratory FIN B-8562 B3/08/16 PADOVAN, M L, ZWETZIG, G
Region 5, Office of Director 2pp 20900 127 24X
Fiche 50-312, B3/09/16, B310250591

B310040547 Withdraws 790920 request for proposed Rev 1 to Tech Specs Amend 45, per conversation between S Miner & R Colombo
RODRIGUEZ, R J Sacramento Municipal Utility District B3/09/20
EISENHUT, D G Division of Licensing 1p 20623 207 24X
Fiche 50-312, B3/09/20, B310040547

B310070133 Forwards, for consideration, project & budget proposal, "Operating Reactors Licensing Actions Tech Specs for Hydraulic & Mechanical Snubbers for Trojan & Rancho Seco Facilities"
TUSZKA, M E Lawrence Livermore Laboratory FIN B-8562 B3/09/20
BISHOP, T W Region 5, Office of Director 10pp 20659 025 24X
Fiche 50-000, B3/09/20, B310070133

B310210038 Submits results of plant review committee investigation of Cycle 6 administrative operating limits Add conservatism of retaining penalty for 30 EFPD imposed
RODRIGUEZ, R J Sacramento Municipal Utility District B3/09/20
MINER, S NRC - No Detailed Affiliation Given 2pp 20856 004 24X
Fiche 50-312, B3/09/20, B310210038

B310040317 Application for amend to License DPH-54, extending deadline to B30601 for implementing 10CFR50.54 changes re shift staffing
RODRIGUEZ, R J Sacramento Municipal Utility District B3/09/22
STOLZ, J F Operating Reactors Branch 4 5pp 20620 219 24X
Fiche 50-312, B3/09/22, B310040317

B310040033 Confirms procedure for estimating core damage since restart from recent outage in response to NRC B30902 ltr Procedure not formalized, but will be incorporated as normal plant operation procedure
LATHAM, W K Sacramento Municipal Utility District B3/09/26
STOLZ, J F Operating Reactors Branch 4 1p 20608 174 24X
Fiche 50-312, B3/09/26, B310040033

B310110471 Forwards safety evaluation of util responses to NUREG O-37, Item II E 1 i, "Auxiliary Feedwater Sys" Item 1 re protection from internal missiles unacceptable Requests commitment to NRC position within 30 days
STOLZ, J F Operating Reactors Branch 4 B3/09/26 RODRIGUEZ, R J
Sacramento Municipal Utility District 46pp 20711 320 24X
Fiche 50-312, B3/09/26, B310110471

B310110476 Forwards safety evaluation supporting installation of NRC high point vents per NUREG-0737, Item II B 1
STOLZ, J F Operating Reactors Branch 4 B3/09/27 RODRIGUEZ, R J
Sacramento Municipal Utility District 7pp 20712 245 24X
Fiche 50-312, B3/09/27, B310110476

DOCKETED ITEMS

139

--8304080055 "Selected Operating Reactor Issues Program II RCS Vents (NUREG-0737, Item 11 B 1)," final technical evaluation rept for Rancho Seco 1
HELD, J J Energy Incorporated FIN A-0250 TF-367/0817A
83/03/14 ADERTHAL, G NRC - No Detailed Affiliation Given 2pp
20712 274 24X Fiche 50-312, 83/09/27, 8310110476

8310030485 Forwards schedule for responding to 830824 request for addl info on inadequate core cooling instrumentation sys, p1
NUREG-0737, Item 11 F 2, "Inadequate Core Cooling"
RODRIGUEZ, R J Sacramento Municipal Utility District 83/09/21
STOLZ, J F Operating Reactors Branch 4 2pp 20601 077 24X
Fiche 50-312, 83/09/28, 8310030485

8310120394 Forwards response to 830824 request for addl info to complete review of spent fuel pool expansion Turbine gantry will be used to move loads in & out of spent fuel bldg
MATTIMOE, J J Sacramento Municipal Utility District 83/10/03
STOLZ, J F Operating Reactors Branch 4 5pp 20700 191 24X
Fiche 50-312, 83/10/03, 8310120394

8308300771 Board Notification 83-12BA Forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves
EISENHUT, D G Division of Licensing 83/10/06 PALADINO, N J
Commissioners 31pp 20818 001 24X Fiche 50-000, 83/10/06, 8308300771

8310120087 Forwards response to 830831 request for addl info re pump & valve inservice testing program Revised request for relief from ASME Section XI Code & revised Section 4 of valve testing program included
RODRIGUEZ, R J Sacramento Municipal Utility District 83/10/06
STOLZ, J F Operating Reactors Branch 4 29pp 20696 194 24X
Fiche 50-312, 83/10/06, 8310120087

8310140143 Forwards proprietary "Rancho Seco Cycle 7 Reload Rept - Vol 1 - Mark B2 Fuel Assembly Design Rept," in support of Cycle 7 reload planned for late 1984 Rept withheld (ref 10C1R2 790)
TUCKER, H D Duke Power Co 83/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 20766 067 24X Fiche 50-000, 83/10/07, 8310140143

--8310140145 Forwards proprietary "Rancho Seco Cycle 7 Reload Rept Vol 1 - Mark B2 Fuel Assembly Design Rept," Apr 1983 Affidavit supporting determination of proprietary nature of rept encl
TAYLOR, J H Babcock & Wilcox Co 83/09/19 MINER, S Office of Nuclear Reactor Regulation, Director 8pp 20766 069 24X
Fiche 50-000, 83/10/07, 8310140145

8310210020 Forwards proprietary version of "Rancho Seco Cycle 7 Reload Rept, Vol 1, Mark B2 Fuel Assembly Design Rept" Vol 2 will be submitted in Fall 1984 Rept withheld
MATTIMOE, J J Sacramento Municipal Utility District 83/10/18
EISENHUT, D G Division of Licensing 1p 20858 001 24X
Fiche 50-312, 83/10/18, 8310210020

8310250210 Withdraws proposed Amend B1 to License DPR-54 re Generic Item B-24, "Containment Isolation Dependability," per NRC 830914 request Util will continue to use equalizing line valves when qualified
MATTIMOE, J J Sacramento Municipal Utility District 83/10/18
STOLZ, J F Operating Reactors Branch 4 1p 20892 362 24X
Fiche 50-312, 83/10/18, 8310250210

8310310489 Summary of 830826 meeting w/B&W Owners Group re implementation of Generic Ltr 83-28 concerning defenses against AFWs & proposed AFW rule for B&W plants List of attendees & viewpoints encl
KADAMBI, P Operating Reactors Branch 4 83/10/20, Operating Reactors Branch 4 13pp 20965 147 24X Fiche 50-000, 83/10/20, 8310310489

8310280097 Forwards B&W Owners Group rept "Rounding Analytical Assessment of NUREG-0630 Models on LUCA kW/Ft Limits W/Use of FLESCFI"
RODRIGUEZ, R J Sacramento Municipal Utility District 83/10/21
STOLZ, J F Operating Reactors Branch 4 1p 20735 212 24X
Fiche 50-312, 83/10/21, 8310280097

8310280072 Notification of 831109 meeting w/util in Bethesda, MD to discuss methodology used to prepare integrated living schedule
MINER, S Operating Reactors Branch 4 83/10/26 STOLZ, J F
Operating Reactors Branch 4 2pp 20964 110 24X
Fiche 50-312, 83/10/26, 8310280072

Q Inspection reports, IE Bulletin & correspondence

8310170674 Forwards IE Insp Rept 50-312/83-16 on 830606-10, 13 & 21-22 No noncompliance noted
WENSLAWSKI, F A Region 5, Office of Director 83/09/16
RODRIGUEZ, R J Sacramento Municipal Utility District 2pp
20779 295 24X Fiche 50-312, 83/09/16, 8310170674

--8310170678 IE Insp Rept 50-312/83-16 on 830606-10, 13 & 21-22 No noncompliance noted Major areas inspected environ protection, followup on RDs, info notices, onsite events, noncompliance items & NUREG-0737, Items 11 B 3 & 11 F 1
NORTH, H S, WENSLAWSKI, F A Region 5, Office of Director 83/09/16 10pp 20779 297 24X Fiche 50-312, 83/09/16, 8310170674

8310040300 Forwards IE Insp Rept 50-312/83-24 Portions of post-accident sampling sys (NUREG-0737, Item 11 B 3) inoperable Reasonable degree of sys reliability remains undemonstrated
WENSLAWSKI, F A Region 5, Office of Director 83/09/23 STOLZ, J F
Operating Reactors Branch 4 1p 20612 338 24X
Fiche 50-312, 83/09/23, 8310040300

--8310040308 Forwards IE Insp Rept 50-312/83-24 on 830912-16 Mgt attention should be directed to insp findings re post-accident sampling sys
WENSLAWSKI, F A Region 5, Office of Director 83/09/26
RODRIGUEZ, R J Sacramento Municipal Utility District 3pp
20612 339 24X Fiche 50-312, 83/09/26, 8310040308

--8310040311 IE Insp Rept 50-312/83-24 on 830912-16 Noncompliance noted licensee unable to sample containment atmosphere using post-accident sampling sys, hydrogen monitors or reactor bldg atmosphere monitor
NORTH, H S, YUHAS, G P Region 5, Office of Director WENSLAWSKI, F A Region 4, Office of Director 83/09/23 12pp
20612 341 24X Fiche 50-312, 83/09/23, 8310040311

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310030401 Forwards util 830921 ltr to NRC reporting on radiographic insp of HPI nozzles C & D Svc list encl Related correspondence
TRAVIESO-DIAZ Shaw, Pittman, Potts & Trowbridge TRAVIESO-DIAZ
Sacramento Municipal Utility District 83/09/27 ROSENTHAL, A S,
BUCK, J H, KOHL, C N Atomic Safety and Licensing Appeal Panel App
20593 070 24X Fiche 50-312, 83/09/27, 8310030401

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310140249 Suppls response to IE Bulletin 82-02 "Degradation of Threaded Fasteners in RCPB of PWR Plants" Maint procedures revised to include requirements for torque valves & gasket installation
MATTIMOE, J J Sacramento Municipal Utility District 83/10/04
MARTIN, J D Region 5, Office of Director 8pp 20761 325 24X
Fiche 50-312, 83/10/04, 8310140249

8310120355 Ack receipt of 830921 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-312/83-12
WENSLAWSKI, F A Region 5, Office of Director 83/10/04
LATHAM, W K Sacramento Municipal Utility District 1p 20700 209
24X Fiche 50-312, 83/10/04, 8310120355

--8310120358 Responds to NRC 830517 & 0801 ltrs re violations noted in IE Insp Rept 50-312/83-12 Corrective actions Administrative Procedure AP 1 re responsibilities & authorities revised to emphasize necessity for procedure adherence
LATHAM, W K Sacramento Municipal Utility District 83/09/21
MARTIN, J D Region 5, Office of Director 1p 20700 210 24X
Fiche 50-312, 83/10/04, 8310120358

DOCKETED ITEMS

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 79pp 20892 026 24X Fiche 50-000,83/10/07,8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

8310310401 Forwards IE Insp Repts 50-312/82-41 on 821116-830217 No noncompliance noted
BISHOP, T W Division of Resident/Reactor Project & Engineering
Programs 83/10/12 RODRIGUEZ, R J Sacramento Municipal Utility
District 2pp 20959 297 24X Fiche 50-312,83/10/12,8310310401

--8310310405 IE Insp Repts 50-312/82-41 on 821116-830217 No noncompliance noted Major areas inspected safety-related concrete placement & electrical installation
D'ANGELO, A J, YOUNG, T Region 5, Office of Director 83/10/11
4pp 20959 299 24X Fiche 50-312,83/10/12,8310310401

8310310296 Forwards IE Insp Rept 50-312/83-05 on 830516-20 No noncompliance noted
BISHOP, T W Division of Resident/Reactor Project & Engineering
Programs 83/10/13 RODRIGUEZ, R J Sacramento Municipal Utility
District 2pp 20961 127 24X Fiche 50-312,83/10/13,8310310296

--8310310304 IE Insp Rept 50-312/83-05 on 830516-20 No noncompliance noted Major areas inspected allegations associated w/welding activities performed by Nuclear Power Sys
D'ANGELO, A J, YOUNG, T Region 5, Office of Director 83/10/11
5pp 20961 129 24X Fiche 50-312,83/10/13,8310310304

8310180094 Advises that final submittal re implementation of environ qualification equipment upgrades, per 830720 & 8320 1tr & IE Bulletin 79 01B, will be delayed until 831031 due to unexpectedly high post-outage workload
RODRIGUEZ, R J Sacramento Municipal Utility District 83/10/14
STOLZ, J F Operating Reactors Branch 4 1p 20807 153 24X
Fiche 50-312,83/10/14,8310180094

Periodic operating reports & related correspondence

0040419 Monthly operating rept for Aug 1983 W/830909 1tr
COLONBO, R J, RODRIGUEZ, R J Sacramento Municipal Utility District
3/09/31 Director's Office, Office of Inspection and Enforcement
7pp 20619 021 24X Fiche 50-312,83/08/31,8310040419

110120160 Forwards corrected Table 2B listing liquid effluent batch mode isotopes in "Semiannual Effluent Release Rept, Jan-June 1983 "
RODRIGUEZ, R J Sacramento Municipal Utility District 83/09/16
MARTIN, J B Region 5, Office of Director 1p 20676 023 24X
Fiche 50-312,83/09/16,8310120160

--8310120161 Corrected Table 2B listing liquid effluent batch mode isotopes in "Semiannual Effluent Release Rept, Jan-June 1983 "
" Sacramento Municipal Utility District, 83/06/30 1p
20676 024 24X Fiche 50-312,83/09/16,8310120160

8310170216 Monthly operating rept for Sept 1983 W/831007 1tr
COLONBO, R J, RODRIGUEZ, R J Sacramento Municipal Utility District,
83/09/30 Director's Office, Office of Inspection and Enforcement
4pp 20787 001 24X Fiche 50-312,83/09/30,8310170216

var Power Station Unit 1 Quarterly Repts
#1010 1tr
cipal Utility District 83/09/30
1p 20899 323 24X
17

S Reportable occurrences, LHIs & related correspondence

8310070275 RO 83-07 on 830818, heat tracing for hydrogen monitoring sys found deenergized Tracing reenergized, restoring sys to operable status Check of hydrogen monitor operability on shift frequency implemented
RODRIGUEZ, R J Sacramento Municipal Utility District 83/09/13
MARTIN, J B Region 5, Office of Director 1p 20657 025 24X
Fiche 50-312,83/09/13,8310070275

8310120145 LER 83-030/03L-0 on 830829, weekly surveillance of nitrogen gas sys discovered Xe-133 contamination Caused by installed spool piece left in place Spool piece removed & operating procedures rewritten W/830920 1tr
COLONBO, R W, RODRIGUEZ, R J Sacramento Municipal Utility District
83/09/27 MARTIN, J B Region 5, Office of Director 2pp
20676 016 24X Fiche 50-312,83/09/27,8310120145

8310120167 LER 83-033/03L-0 on 830901, Surveillance Test SP 207 O/A for NSRW pump A incorrectly signed acceptable Caused by personnel misinterpretation of data Personnel cautioned W/830920 1tr
COLONBO, R W, RODRIGUEZ, R J Sacramento Municipal Utility District
83/09/29 MARTIN, J B Region 5, Office of Director 2pp
20676 025 24X Fiche 50-312,83/09/29,8310120167

8310120150 LER 83-032/01T-0 on 830917, RCB unidentified leakage exceeded 1 gpm Caused by leaking tube /B-2 in once-through steam generator A Tube plugged & sys stabilized W/830930 1tr
COLONBO, R W, MARTINDALE, J J Sacramento Municipal Utility District
83/10/03 MARTIN, J B Region 5, Office of Director 3pp
20676 008 24X Fiche 50-312,83/10/03,8310120150

8310120186 LER 83-028/01T-0 on 830919, PURV failed open & could not be closed Caused by weight of pointer attached to pilot valve actuating arm Pointer removed & alternate method to observe arm position used W/831003 1tr
COLONBO, R W, MARTINDALE, J J Sacramento Municipal Utility District
83/10/03 MARTIN, J B Region 5, Office of Director 4pp
20675 320 24X Fiche 50-312,83/10/03,8310120186

8310120251 PNO-V-83-038A on 830917, plant shut down following discovery of steam generator A tube leak One insp lane tube (70-P) plugged on 830927 Two of 360 tubes inspected showed localized thinning of approx 25/
JOHNSON, P J, YOUNG, T Region 5, Office of Director 83/10/03 1p
20672 107 24X Fiche 50-312,83/10/03,8310120251

8310120321 PNO-V-83-039A on 830919, PURV opened at 29 psig due to addl weight of indicating rod added to operating handle during recent refueling outage Rod removed PURV closed on 830927 by placing V nitrogen bubble in pressurizer
JOHNSON, P J, YOUNG, T Region 5, Office of Director 83/10/03 1p
20700 277 24X Fiche 50-312,83/10/03,8310120321

8310250598 LER 83-034/03L-0 on 830912, monthly auxiliary feedwater sys valve Surveillance SP 210 010 not performed in correct time interval Operations personnel instructed re schedule to perform surveillance test W/831011 1tr
COLONBO, R W, LATHAM, W K Sacramento Municipal Utility District
83/10/11 MARTIN, J B Region 5, Office of Director 3pp
20700 359 24X Fiche 50-312,83/10/11,8310250598

8310270451 LER 83-035/03L-0 on 830920, component cooling water showed presence of tritium, Xe-133, I-131 & I-132 Caused by apparent leak in letdown cooler B Cooler isolated W/831018 1tr
COLONBO, R W, RODRIGUEZ, R J Sacramento Municipal Utility District
83/10/18 MARTIN, J B Region 5, Office of Director 3pp
20923 137 24X Fiche 50-312,83/10/18,8310270451

8310270452 LER 83-036/03L-0 on 830919, outboard seal in decay heat pump B (P-2610) failed, resulting in minor leakage Cause attributed to normal & expected wear on seal Seal removed & replaced W/831018 1tr
COLONBO, R W, RODRIGUEZ, R J Sacramento Municipal Utility District
83/10/18 MARTIN, J B Region 5, Office of Director 2pp
20923 097 24X Fiche 50-312,83/10/18,8310270452

8310270206 Part 21 rept re engine mounted electrical cables Defective cable not installed as 830927 1tr status Parts shipped & installed on Gulf States River Bend Site (Engine Serial 74039/40 USR 48) Instruction for cable changeout due in Nov
DOYER, R E Transamerica Delaval, Inc 83/10/20 Director's
Office, Office of Inspection and Enforcement 1p 20724 108 24X
Fiche 50-000,83/10/20,8310270206

DOCKETED ITEMS

141

V Operator Examinations

8310040317 Application for amend to license DPR-54, extending deadline to B50601 for implementing 10 CFR 50.54 changes re shift staffing
RODRIGUEZ, R J Sacramento Municipal Utility District 83/09/22
STOLZ, J F Operating Reactors Branch 1 5pp 20620 219 247
Fiche 50-312, 83/09/22, 8310040317

8310030149 Requests schedule, by 831028, for requalification training & exams for 1984 in order to coordinate Region V audit of operator requalification programs
BISHOP, T W Division of Resident Reactor Project & Engineering Programs 83/09/26 RODRIGUEZ, R J Sacramento Municipal Utility District 2pp 20590 032 247 Fiche 50-312, 83/09/26, 8310030149

DOCKET 50-313 ARKANSAS NUCLEAR INC, UNIT 1

f Security, medical, emergency & fire protection plans

8310060520 Forwards clarification of NRC positions on certain requirements of App R to 10 CFR 50.48
STOLZ, J F, MILLER, J R Operating Reactors Branch 4 83/09/14
GRIFFIN, J M Arkansas Power & Light Co 8pp 20663 139 24X
Fiche 50-313, 83/09/14, 8310060520

8310030416 submits addl info re mods to live Zones 2100-Z & 2101-AA, per 830713 request for App R scheduler exemption Delivery of pump switchgear expected in late Jan 1984
MARSHALL, J R Arkansas Power & Light Co 83/09/27 STOLZ, J F Operating Reactors Branch 4 MILLER, J R Operating Reactors Branch 3 2pp 20593 166 24X Fiche 50-313, 83/09/27, 8310030416

8310060243 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/09/30 Document Management Branch 1p 20660 276 24X Fiche 50-313, 83/09/30, 8310060243

--8310060250 Public version of Rev 4 to Emergency Plan Implementing Procedure 1903 01, "Organization & Use of Emergency Plan Implementing Procedures" & Rev 10 to Procedure 1903 10, "Emergency Action Level Response"
LEVINE, J M Arkansas Power & Light Co 83/09/19 32pp 20660 277 24X Fiche 50-313, 83/09/30, 8310060243

8310060597 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20661 092 24X Fiche 50-313, 83/10/05, 8310060597

--8310060601 Public version of Rev 8 to emergency plan W/830922 ltr
MARSHALL, J R Arkansas Power & Light Co 83/09/14 COLLINS, J T Region 4, Office of Director 56pp 20661 093 24X Fiche 50-313, 83/10/05, 8310060597

8310110437 Releases public version of rev to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20704 353 24X Fiche 50-313, 83/10/05, 8310110437

--8310110440 Public version of Rev 5 to Emergency Plan Procedure 1903 04, "Fire or Explosion" W/830912 ltr & receipt form
LEVINE, J M Arkansas Power & Light Co 83/08/11 NRC - No Detailed Affiliation Given 3pp 20704 394 24X Fiche 50-313, 83/10/05, 8310110437

8310250557 Withdraws request for scheduler exemption until 830501 to complete installation of certain 1 h rated fire barriers
MARSHALL, J R Arkansas Power & Light Co 83/10/07 STOLZ, J F Operating Reactors Branch 4 MILLER, J R Operating Reactors Branch 3 1p 20700 346 247 Fiche 50-313, 83/10/07, 8310250557

8310190291 Releases public version of amend to emergency plan
FELTON, J M Division of Rules and Records 83/10/14 Document Management Branch 1p 20640 143 24X Fiche 50-313, 83/10/14, 8310190291

--8310190292 Public version of Amend B to emergency plan
Arkansas Power & Light Co 83/09/14 60pp 20840 144 24X Fiche 50-313, 83/10/14, 8310190291

8310190294 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/14 Document Management Branch 1p 20841 341 24X Fiche 50-313, 83/10/14, 8310190294

--8310190295 Public version of Rev 11 to Emergency Plan Implementing Procedure 1903 10, "Emergency Action Level Response"
W/831004 ltr & receipt form
LEVINE, J M Arkansas Power & Light Co 83/10/01 70pp 20841 342 24X Fiche 50-313, 83/10/14, 8310190294

8310250274 Updates present status & describes basis performed over previous 6 months per requirements of Generic Ltr 82-33 & Suppl 1 to NUREG-0-37 re control room design review Figure 2-2 encl
MARSHALL, J R Arkansas Power & Light Co 83/10/20 EISENHUT, D O Division of Licensing 4pp 20702 340 24X Fiche 50-313, 83/10/20, 8310250274

J Insurance & indemnity information

8310240035 Forwards Endorsements 53, 54 & 55 to NELIA Policy NF-210 & Endorsements 46 & 47 to MALLU Policy MI 74
MARSHALL, J R Arkansas Power & Light Co 83/10/12 DINITZ, I Assistant Director for State & Licensee Relations 4pp 20881 353 24X Fiche 50-313, 83/10/12, 8310240035

P Operating license stage documents & correspondence

8310060402 Forwards NPDES Permit AR0001392, effective 830606 - B60705, per NRC 830311 ltr & util 830520 confirmation
MARSHALL, J R Arkansas Power & Light Co 83/06/10 COLLINS, J T Region 4, Office of Director 3pp 20641 229 24X Fiche 50-313, 83/06/10, 8310060402

--8310060406 NPDES Permit AR0001392, issued to Arkansas Power & Light Co
KNUDSON, M D Environmental Protection Agency 83/05/06 20pp 20641 232 24X Fiche 50-313, 83/06/10, 8310060402

8310050049 Forwards safety evaluation accepting Arkansas Power & Light 830607 proposed mods to reactor trip breakers Schedule for submittal of plant-specific info needed in 10 days
STOLZ, J F Operating Reactors Branch 4 83/09/12 GRIFFIN, J M Arkansas Power & Light Co 2pp 20650 122 24X Fiche 50-313, 83/09/12, 8310050049

8310030353 Forwards B&W Owners Group final rept, "Bounding Analytical Assessment of NUREG-0630 Models on LOCA kW/ft Limits W/Use of FLECSSET" Approval requested
MARSHALL, J R Arkansas Power & Light Co 83/09/23 STOLZ, J F Operating Reactors Branch 4 1p 20704 700 24X Fiche 50-313, 83/09/23, 8310030353

--8310030356 "Bounding Analytical Assessment of NUREG-0630 Models on LOCA kW/ft Limits W/Use of FLECSSET"
* Babcock & Wilcox Operating Plants Owners Group 77-114089B-01 83/09/30 108pp 20592 201 24X Fiche 50-313, 83/09/23, 8310030353

8310110472 Forwards Franklin Research Ctr "Operating Reactor PORV Repts (F-37)THI Action Plan Requirements Generic Rept-B&W Designed Units," technical evaluation rept & NRR safety evaluation accepting B&W response to THI Item 11 K 3 2
STOLZ, J F Operating Reactors Branch 4 83/09/26 GRIFFIN, J M Arkansas Power & Light Co 3pp 20712 004 24X Fiche 50-313, 83/09/26, 8310110472

8310110472 Forwards Franklin Research Ctr "Operating Reactor PORV Repts (F-37)THI Action Plan Requirements Generic Rept-B&W Designed Units," technical evaluation rept & NRR safety evaluation accepting B&W response to THI Item 11 K 3 2
STOLZ, J F Operating Reactors Branch 4 83/09/26 GRIFFIN, J M Arkansas Power & Light Co 3pp 20712 004 24X Fiche 50-313, 83/09/26, 8310110472

--8308310422 Forwards safety evaluation accepting B&W licensee contention that requirements of NUREG-0737, Item 11 K 3 2 met w/existing PORV, safety valve & high pressure reactor trip setpoints
ROWENOFF, F H Assistant Director for Technology Review 83/08/24 LAING, G C Assistant Director for Operating Reactors 14pp 20712 007 24X Fiche 50-313, 83/09/26, 8310110472

--8307250463 "Operating Reactor PORV Repts (F-37) THI Action Plan Requirements Generic Rept - B&W Designed Units," technical evaluation rept
OVERBECK, G J, DELCAIZO, T J Franklin Institute/Franklin Research Center NRC-03-B1-130 TER-C5506-410 83/07/20 CHOW, E NRC - No Detailed Affiliation Given 59pp 20712 019 24X Fiche 50-313, 83/09/26, 8310110472

8310030332 Updates 830520 request for extension of deadline for environ qualification of equipment Status of specific items enumerated
MARSHALL, J R Arkansas Power & Light Co 83/09/28 STOLZ, J F Operating Reactors Branch 4 MILLER, J R Operating Reactors Branch 3 4pp 20592 311 24X Fiche 50-313, 83/09/28, 8310030332

DOCKETED ITEMS

8310120447 Responds to 830912 request for schedule for providing info re reactor trip breaker automatic shunt trip actuation mode. Info will be provided as part of 120-day response to Generic Ltr 83-28
MARSHALL, J R Arkansas Power & Light Co 83/09/24 STOLZ, J F
Operating Reactors Branch 4 1p 20598 253 24X
Fiche 50-313, 83/09/29, 8310120447

8310110618 Summary of 830823 meeting w/util in Bethesda, MD re Tech Specs for mechanical & hydraulic snubbers Agenda & marked-up Tech Specs encl
VISSINO, G S Operating Reactors Branch 4 83/09/30 Operating Reactors Branch 4 13pp 20715 160 24X Fiche 50-313, 83/09/30, 8310110618

8310120079 Forwards updated radiological effluent Tech Specs & offsite dose calculation manual per 830510 request implementation date of 830101 established
GRIFFIN, J M Arkansas Power & Light Co 83/09/30 STOLZ, J F
Operating Reactors Branch 4 MILLER, J R Operating Reactors Branch 4 3pp 20596 241 24X Fiche 50-313, 83/09/30, 8310120079

--8310120081 Revs to radiological effluent Tech Specs
* Arkansas Power & Light Co 83/09/30 11pp 20696 244 24X
Fiche 50-313, 83/09/30, 8310120079

--8310120083 Revs to offsite dose calculation manual
* Arkansas Power & Light Co 83/09/30 99pp 20696 360 24X
Fiche 50-313, 83/09/30, 8310120079

8310140225 Informs that Tech Specs for low temp overpressurization protection sys will be submitted by 831121 in response to NRC 830826 request for submittal schedule
MARSHALL, J R Arkansas Power & Light Co 83/09/30 STOLZ, J F
Operating Reactors Branch 4 1p 20761 174 24X
Fiche 50-313, 83/09/30, 8310140225

8310180611 Forwards SER accepting licensee responses to NUREG-0731, item II E 1.1 re emergency feedwater sys two open items re redundant flow paths & tornado missile protection remain
Compliance schedule needed within 30 days
STOLZ, J F Operating Reactors Branch 4 83/10/04 GRIFFIN, J M
Arkansas Power & Light Co 29pp 20824 001 24X
Fiche 50-313, 83/10/06, 8310180611

8310170096 Forwards Amend B1 to License DPR-51 & safety evaluation Amend changes Tech Specs re schedules & locations of insertions of property capsules into reactor
VISSINO, G S Operating Reactors Branch 4 83/10/07 GRIFFIN, J M
Arkansas Power & Light Co 2pp 20813 127 24X
Fiche 50-313, 83/10/07, 8310170096

--8310170100 Amend B1 to License DPR-51, changing Tech Specs re schedules & locations of insertions of vessel metal property capsules into reactor
STOLZ, J F Operating Reactors Branch 4 83/10/07 3pp
20813 129 24X Fiche 50-313, 83/10/07, 8310170096

--8310170106 Safety evaluation supporting Amend B1 to License DPR-51
* Office of Nuclear Reactor Regulation, Director 83/10/07 7pp
20813 133 24X Fiche 50-313, 83/10/07, 8310170096

8310200054 Requests written confirmation of current electrical distribution sys configuration as discussed on 830707 as result of load shedding process not being utilized & one unit being locked off of startup transformer 2
STOLZ, J F Operating Reactors Branch 4 83/10/12 GRIFFIN, J M
Arkansas Power & Light Co 3pp 20844 225 24X
Fiche 50-313, 83/10/12, 8310200054

8310210080 Requests remittance of fee due for 830215 application re deletion of terrestrial monitoring programs within 15 days
MILLER, W D License Fee Management Branch 83/10/17 GRIFFIN, J M
Arkansas Power & Light Co 1p 20883 251 24X
Fiche 50-313, 83/10/17, 8310210080

8310310489 Summary of 830826 meeting w/B&W Owners Group re implementation of Generic Ltr 83-28 concerning defenses against ATWS & proposed ATWS rule for B&W plants (list of attendees & viewgraphs encl)
KADAMBI, P Operating Reactors Branch 4 83/10/20 Operating Reactors Branch 4 13pp 20465 147 24X Fiche 50-000, 83/10/20, 8310310489

G Inspection reports, IE Bulletin & correspondence

8310250141 Responds to IE Bulletin 82-02, "Degradation of threaded Fasteners in RGPU of PWR Plants," Action Item 4 Commitments re future insps withdrawn Insp will continue as appropriate under applicable codes & std.
MARSHALL, J R Arkansas Power & Light Co 83/07/25 COLLINS, J T
Region 4, Office of Director 4pp 20696 356 24X
Fiche 50-313, 83/07/25, 8310250141

8310060020 Forwards IE Insp Repts 50-313/83-13 & 90-168/83-17 on 830406-10 No noncompliance noted
SEIDLE, W C Region 4, Office of Director 83/08/01 GRIFFIN, J M
Arkansas Power & Light Co 2pp 20647 156 24X
Fiche 50-313, 83/08/01, 8310060020

--8310060026 IE Insp Repts 50-313/83-13 & 50-368/83-13 on 830406-10 No noncompliance noted Major areas inspected action on previous violations, onsite radiation protection organization, staff qualifications & training, exposure control & ALARA program
CHANEY, H D, HOILEY, W L, MURRAY, B Region 4, Office of Director 83/07/20 17pp 20647 158 24X Fiche 50-313, 83/08/01, 8310060020

8310250153 Provides status of work accomplished in response to IE Bulletin 79-02, "Pipe Support Hinge Plate Designs Using Concrete Expansion Anchor Bolts," & IE Bulletin 77-14 "Seismic Analyses for As-Built Safety-Related Piping Sys"
MARSHALL, J R Arkansas Power & Light Co 83/08/05 COLLINS, J T
Region 4, Office of Director 1p 20696 343 24X
Fiche 50-313, 83/08/05, 8310250153

8310130220 Forwards IE Insp Repts 50-313/83-15 & 50-168/83-15 on 830701-31 No noncompliance noted
SEIDLE, W C Region 4, Office of Director 83/08/10 GRIFFIN, J M
Arkansas Power & Light Co 2pp 20724 105 24X
Fiche 50-313, 83/08/10, 8310130220

--8310130226 IE Insp Repts 50-313/83-15 & 50-368/83-15 on 830701-31 No noncompliance noted Major areas inspected operational safety verification, surveillance, maint & followup on previously identified items
CALLAN, L J, CUMMINS, J C, JOHNSON, W D Region 4, Office of Director 83/08/05 12pp 20724 107 24X Fiche 50-313, 83/08/10, 8310130220

8310250417 Forwards "Exam of Once-Through Steam Generator Tubes B7-B & B112-19 from AND-1," final rept Insp adequate to determine conditions & will provide sufficient data to further evaluate failure mechanism
MARSHALL, J R Arkansas Power & Light Co 83/09/15 STOLZ, J F
Operating Reactors Branch 4 3pp 20702 176 24X
Fiche 50-313, 83/09/15, 8310250417

--8310250424 "Exam of Once-Through Steam Generator Tubes B7-B & B112-19 from AND-1," final rept
INMAN, S C Babcock & Wilcox Co RDD 84 5303-04 02 83/06/10
161pp 20907 179 24X Fiche 50-313, 83/09/15, 8310250417

8310130330 Forwards IE Insp Repts 50-313/83-21 & 50-368/83-21 on 830801-31 & notice of violation
SEIDLE, W C Region 4, Office of Director 83/09/16 GRIFFIN, J M
Arkansas Power & Light Co 2pp 20719 343 24X
Fiche 50-313, 83/09/16, 8310130330

--8310130333 Notice of violation from insp on 830801-31
* Region 4, Office of Director 83/09/16 4pp 20719 345 24X
Fiche 50-313, 83/09/16, 8310130330

--8310130335 IE Insp Repts 50-313/83-21 & 50-368/83-21 on 830801-31 Noncompliance noted failure to properly identify calculation & design changes to perform maint activities w/written procedure & to install electrical cables per procedures
CALLAN, L J, CUMMINS, J C, JOHNSON, W D Region 4, Office of Director 83/09/15 11pp 20719 349 24X Fiche 50-313, 83/09/16, 8310130330

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

DOCKETED ITEMS

143

8308300745 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 11pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300745

8310100140 Summary of 830891 meeting w/utl in Bethesda, MD re results of Dec 1982 tube insp, metallurgical exam of tubes pulled in Dec 1982 insp, results of Jul 1983 insp, cause of tube degradation & corrective actions Viewgraphs encl
VISING, G S Operating Reactors Branch 4 83/09/27 Operating Reactors Branch 4 77pp 20777 075 24X Fiche 50-113, 83/09/27, 8310100140

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o LOCRISO 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 11pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300778 IC Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300778

8308300752 IC Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 77pp 20882 076 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

R Periodic operating reports & related correspondence

8310190117 Monthly operating rpt for Aug 1983 W/830415 ltr
MARSHALL, J R , MORTON, K L Arkansas Power & Light Co 83/09/15
BASSETT, H B Division of Data Automation & Management Information
7pp 20820 333 24X Fiche 50-313, 83/09/15, 8310190117

S Reportable occurrences, LIRs & related correspondence

8310040154 LCR 83-080/03L-0 on 830828, lead hydrogen purge fan VCI-07A indicated low output flow caused by debris collected at valve HPA-173 Valve Internals Cleaned W/830920 ltr
ROGERS, P , MARSHALL, J R Arkansas Power & Light Co 83/09/20
SEIDLE, W C Region 4, Office of Director 2pp 20608 037 24X Fiche 50-313, 83/09/20, 8310040154

DOCKET 50-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8310030391 Forwards description of Class A radiation dose assessment model, per util 830419 ltr Meteorological info & dose assessment sys Class A (ACRISU) program will be primary dose assessment model in emergency operations facility
ALEXICH, M P Indiana & Michigan Electric Co 83/09/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 20593 056 24X Fiche 50-313, 83/09/27, 8310030391

8310030564 Releases public version of revised emergency plan (FSAR Chapter 12.3)
FELTON, J M Division of Rules and Records 83/09/28 Document Management Branch 1p 20605 338 24X Fiche 50-313, 83/09/28, 8310030564

--8310030579 Public version of Rev 2 to emergency plan (FSAR Chapter 12.3) W/830916 ltr
ALEXICH, M P Indiana & Michigan Electric Co 83/09/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 417pp 20605 339 24X Fiche 50-313, 83/09/28, 8310030564

8310060474 Releases public version of revised index for plant management procedures
FELTON, J M Division of Rules and Records 83/09/30 Document Management Branch 1p 20640 172 24X Fiche 50-313, 83/09/30, 8310060474

--8310060479 Public version of revised index for plant management procedures W/830919 ltr
ALEXICH, M P Indiana & Michigan Electric Co 83/09/19 NRC - No Exempt Affiliation Given 15pp 20640 173 24X Fiche 50-313, 83/09/19, 8310060474

8310110433 Releases public version of revised pages to App A of emergency plan procedures
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20704 357 24X Fiche 50-313, 83/10/05, 8310110433

--8310110434 Public version of Rev B to Pages 9a & 9b of emergency plan procedures, App A Receipt form encl
ALEXICH, M P Indiana & Michigan Electric Co 83/07/20 App 20704 357 24X Fiche 50-313, 83/10/05, 8310110433

8310240093 Forwards IE Insp Repts 50-315/83-14 & 50-316/83-15 on 830722-0909 No noncompliance noted
SHAFFER, W D Region 3, Office of Director 83/10/05 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 20881 005 24X Fiche 50-313, 83/10/05, 8310240093

--8310240100 IE Insp Repts 50-315/83-14 & 50-316/83-15 on 830722-0909 No noncompliance noted Major areas inspected operational safety, maint, surveillance, LCRs, design changes, fire protection/prevention program & refueling activities
SWANSON, E R , DUBRY, N E , BOYD, D C Region 3, Office of Director 83/10/03 10pp 20881 007 24X Fiche 50-313, 83/10/05, 8310240100

8310250391 Forwards FEMA 830928 ltr providing status of final fix for offsite preparedness State & local plans & preparedness adequate to protect public
PAPERIELLO, C J Region 3, Office of Director 83/10/21 L'Orange, J A American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 1p 20897 280 24X Fiche 50-313, 83/10/21, 8310250391

--8310250401 Comments on status of offsite emergency preparedness local plans & preparedness adequate to protect health & safety of public Approval conditional on verification of public alerting & notification sys per NUREG-0654
MCLAUGHLIN, D Federal Emergency Management Agency 83/09/20 DIRCKS, W J Office of the Executive Director for Operations 20897 281 24X Fiche 50-313, 83/10/21, 8310250391

8310270190 Ack receipt of 830916 & 30 ltr transmitting scope & objectives for 831130 emergency preparedness exercise Exercise scenario should be submitted by 831211 & completed controller package by 840105
PAPERIELLO, C J Region 3, Office of Director 83/10/24 ALEXICH, M P Indiana & Michigan Electric Co ALEXICH, M P Electric Power Service Corp 2pp 20924 185 24X Fiche 50-313, 83/10/24, 8310270190

--8310270196 Forwards scope & objectives for 831130 emergency preparedness exercise Scenario will be submitted by 831017 & completed controller/promoter package by 831110
ALEXICH, M P Indiana & Michigan Electric Co 83/09/16 KEPLER, J G Region 3, Office of Director 7pp 20924 185 24X Fiche 50-313, 83/10/24, 8310270190

J Insurance & indemnity information

8310240119 Forwards Endorsement 5 to NELIA Certificates N-45 & M-64
MAELU Certificates M-45 & M-64
BUCKLES, J A Marsh & McLennan, Inc 83/10/12 SALTZMAN, J Assistant Director for State & License Relations 5pp 20881 144 24X Fiche 50-313, 83/10/12, 8310240119

K Utility Final Safety Analysis Report (FSAR) & amendments

8310030564 Releases public version of revised emergency plan (FSAR Chapter 12.3)
FELTON, J M Division of Rules and Records 83/09/28 Document Management Branch 1p 20605 338 24X Fiche 50-313, 83/09/28, 8310030564

--8310030579 Public version of Rev 2 to emergency plan (FSAR Chapter 12.3) W/830916 ltr
ALEXICH, M P Indiana & Michigan Electric Co 83/09/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 417pp 20605 339 24X Fiche 50-313, 83/09/28, 8310030564

DOCKETED ITEMS

F Operating license stage documents & correspondence

8310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR
 CONNER, L Affiliation Unknown 83/09/02 NRC - No Detailed
 Affiliation Given 1p 21004 270 24X Fiche 50-000, 83/09/02,
 8310310017

8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR. Forwards documents to be placed in PDR & list of facilities for which repts are unavailable
 FELTON, J M Division of Rules and Records 83/07/06 CONNER, L
 Affiliation Unknown 1p 21004 271 24X Fiche 50-000, 83/07/06,
 8310310031

--8310310077 "Reactor Containment Bldg Integrated Leak Rate Test"
 * Indiana & Michigan Power Co 79/02/26 67pp 21007 215 24X
 Fiche 50-000, 83/07/06, 8310310031

8310050563 Addendum to 830511 application to amend License DPR-58 re Cycle B startup operations. Addendum includes repts to 830511 proposed Tech Specs Attachments B-H include safety evaluation replacement & answers to NRC questions.
 ALEXICH, M P Indiana & Michigan Electric Co 83/07/29 DENTON, H H
 Office of Nuclear Reactor Regulation, Director 4pp 20633 001
 24X Fiche 50-315, 83/07/29, 8310050563

--8310050567 Proposed Tech Spec repts reanalyzing worst large break LOCA case using initial fuel rod conditions determined from currently approved PAD fuel thermal safety model Attachments B-H encl
 * Indiana & Michigan Electric Co 83/07/29 150pp 20633 001
 24X Fiche 50-315, 83/07/29, 8310050563

8310050102 Advises that 830908 submittal of revised calculation results re cladding strain, oxidation & pellet cladding interaction using RDEX2 code meets requirements of license condition Request for extended license condition unnecessary
 VARGA, S A Operating Reactors Branch 1 83/09/20 DOLAN, J
 Indiana & Michigan Electric Co DOLAN, J American Electric Power
 Service Corp 2pp 20650 240 24X Fiche 50-315, 83/09/20,
 8310050102

8310070408 Forwards SER re control of heavy loads based on util response to 801222 generic ltr Guidelines in NUREG-0612, Section 5.1.1 & 5.3 satisfied
 VARGA, S A Operating Reactors Branch 1 83/09/20 DOLAN, J
 Indiana & Michigan Electric Co 2pp 20675 332 24X
 Fiche 50-315, 83/09/20, 8310070408

--8310070409 Safety evaluation re control of heavy loads Guidelines in NUREG-0612, Section 5.1.1 & 5.3 satisfied
 * NRC - No Detailed Affiliation Given 83/09/20 2pp
 20675 334 24X Fiche 50-315, 83/09/20, 8310070408

--8309060263 "Control of Heavy Loads (C-10) Indiana & Michigan Electric Co, DC Cook Nuclear Plant Units 1 & 2" technical evaluation repts
 VOSBURY, F W, BOMBERGER, C R Franklin Institute/Franklin Research
 Center NRC-03-01-130 TER-C5506-344/345 83/09/01 SINGH, A
 NRC - No Detailed Affiliation Given 33pp 20675 336 24X
 Fiche 50-315, 83/09/20, 8310070408

831010333 Forwards Amend 74 to License DPR-58 & safety evaluation Amend approves Cycle B reload & changes related Tech Specs
 WIGGINTON, D L Operating Reactors Branch 1 83/09/20 DOLAN, J
 Indiana & Michigan Electric Co DOLAN, J American Electric Power
 Service Corp 3pp 20685 259 24X Fiche 50-315, 83/09/20,
 831010333

--831010334 Amend 74 to License DPR-58, approving Cycle B reload & changing related Tech Specs
 VARGA, S A Operating Reactors Branch 1 83/09/20 65pp
 20685 262 24X Fiche 50-315, 83/09/20, 831010333

--831010335 Safety evaluation supporting Amend 74 to License DPR-58
 * Office of Nuclear Reactor Regulation, Director 83/09/20
 24pp 20685 326 24X Fiche 50-315, 83/09/20, 831010333

8310030386 Suppls & amends 830520 & 0810 requests for extensions required in 10CFR50.49 re equipment environ qualification
 ALEXICH, M P Indiana & Michigan Electric Co 83/09/26 DENTON, H H
 Office of Nuclear Reactor Regulation, Director 4pp 20592 323
 24X Fiche 50-315, 83/09/26, 8310030386

8310060028 Summary of 830913 meeting w/util in Bethesda, MD re environ qualification of electrical equipment & hydrogen control
 WIGGINTON, D Operating Reactors Branch 1 83/09/27 Operating
 Reactors Branch 1 11p 20664 110 24X Fiche 50-315, 83/09/27,
 8310060028

8310060546 Approves 830902 request to use later editions of ASME Section XI Code for test temp requirement for hydrostatic tests of Class 1 & 2 austenitic stainless steel piping & components
 VARGA, S A Operating Reactors Branch 1 83/09/20 DOLAN, J
 Indiana & Michigan Electric Co DOLAN, J American Electric Power
 Service Corp 3pp 20661 284 24X Fiche 50-315, 83/09/20,
 8310060546

8310130217 Forwards Amends 75 & 56 to Licenses DPR-58 & DPR-74, respectively Amends change Tech Spec to require redundant containment hydrogen analyzers to satisfy requirements of NUREG-0737, TMI Action Item II F 1.6
 VARGA, S A Operating Reactors Branch 1 83/09/30 DOLAN, J
 Indiana & Michigan Electric Co DOLAN, J American Electric Power
 Service Corp 3pp 20777 100 24X Fiche 50-315, 83/09/30,
 8310130217

--8310130222 Amends 75 & 56 to Licenses DPR-58 & DPR-74, respectively, changing Tech Spec to require redundant containment hydrogen analyzers to satisfy requirements of NUREG-0737, TMI Action Item II F 1.6
 VARGA, S A Operating Reactors Branch 1 83/09/30 9pp
 20777 103 24X Fiche 50-315, 83/09/30, 8310130217

8310060006 Application to amend License DPR-58, revising Tech Spec 4.5.2.f to increase total flow limit to four branch lines from 470 gpm to 500 gpm on boron injection sys (single centrifugal charging pump)
 ALEXICH, M P Indiana & Michigan Electric Co 83/10/03 DENTON, H H
 Office of Nuclear Reactor Regulation, Director VARGA, S A NRC -
 No Detailed Affiliation Given 3pp 20645 266 24X
 Fiche 50-315, 83/10/03, 8310060006

--8310060329 Proposed Tech Spec re ECCS
 * Indiana & Michigan Electric Co 83/10/03 2pp 20645 269
 24X Fiche 50-315, 83/10/03, 8310060006

8310140040 Forwards response to SA Varga 820730, 0916 & 830810 requests for addl info re hydrogen combustion & control during degraded core accidents
 ALEXICH, M P Indiana & Michigan Electric Co 83/10/10 DENTON, H H
 Office of Nuclear Reactor Regulation, Director 59pp 20760 085
 24X Fiche 50-315, 83/10/10, 8310140040

--8310140042 "Fog Inerting Analysis for PWR Ice Condenser Plants"
 TSAI, S S Westinghouse Electric Corp 81/11/30 109pp
 20768 145 24X Fiche 50-315, 83/10/10, 8310140040

--8310140046 Speech entitled "Fog Inerting Criteria for Hydrogen/Air Mixtures," presented at 821003-07 Second Intl Workshop on Impact of Hydrogen on Water Reactor Safety in Albuquerque, NM
 TSAI, S S, LIPARULO, N J Westinghouse Electric Corp 82/10/03
 15pp 20768 255 24X Fiche 50-315, 83/10/10, 8310140040

8310210036 Summarizes actions taken during scheduled refueling outage beginning 830715 Eddy current exam performed on steam generators before refueling activities Westinghouse repts on steam generator tube degradation mechanism awaited
 SMITH, W G Indiana & Michigan Electric Co 83/10/10 KEPPNER, J O
 Region 3, Office of Director 5pp 20456 006 24X
 Fiche 50-315, 83/10/10, 8310210036

8310200158 Requests extension until 831215 to submit repts on plant-specific evaluation of relief & safety valves & associated piping sys, per NUREG-0737, Item II D 1.2
 ALEXICH, M P Indiana & Michigan Electric Co 83/10/14 DENTON, H H
 Office of Nuclear Reactor Regulation, Director 2pp 20836 313
 24X Fiche 50-315, 83/10/14, 8310200158

G Inspection reports, IE Bulletins & correspondence

8310120293 Ack receipt of 830906 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/83-12 & 50-316/83-13
 SHAFER, W D Region 3, Office of Director 83/09/19 DOLAN, J E
 American Electric Power Service Corp DOLAN, J E Indiana & Michigan
 Electric Co 1p 20692 341 24X Fiche 50-315, 83/09/19, 8310120293

8310130025 Forwards SER & technical evaluation repts re responses to II Bulletin 80-11, "Masonry Wall Design" Joint reinforcement masonry walls not well established Structural element not acceptable Response requested
 VARGA, S A Operating Reactors Branch 1 83/09/20 DOLAN, J
 Indiana & Michigan Electric Co DOLAN, J American Electric Power
 Service Corp 3pp 20772 146 24X Fiche 50-315, 83/09/20,
 8310130025

--8310130026 Safety evaluation supporting mods re IE Bulletin 80-11, "Masonry Wall Design"
 * Office of Nuclear Reactor Regulation, Director 83/09/20 2pp
 20772 149 24X Fiche 50-315, 83/09/20, 8310130025

DOCKETED ITEMS

145

--B308030382 Revised "Masonry Wall Design (H-59).DL (Oak Nuclear Plant, Units 1 & 2," technical evaluation rpt
TRICLOS, CON.V N Franklin Institute/Franklin Research Center
NRC-03-B1-130 TER-C5506-241 R01 83/07/27 (HOKSHI,N 4X - H
Detailed Affiliation Given 38pp 20772 151 24X
Fiche 50-315,83/09/20,831013002%

B308030340 IE Info Notice 83-61, "Alleged Use of Stand Ins for Wilder
Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,830800340

B308030342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
Detectors Positioned at Control Room Ventilation Air
Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,830800342

B308030345 IE Info Notice 83-63, "Potential failures of Westinghouse
Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,830800345

B308030349 IE Info Notice 83-64, "Lead Shielding Attached to
Safety-Related Sys W/o ICRF50 59 Evaluation " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New
York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,830800349

B310240093 Forwards IE Insp Repts 50-315/83-14 & 50-314/83-15 on
B30722-0909 No noncompliance noted
SHAFFER, W D Region 3, Office of Director 83/10/05 DOLAN, J I
American Electric Power Service Corp DOLAN, J E Indiana & Michigan
Electric Co 2pp 20881 005 24X Fiche 50-315,83/10/05,8310240093

--B310240100 IE Insp Repts 50-315/83-14 & 50-316/83-15 on B30722 0909 No
noncompliance noted Major areas inspected operational
safety, maint, surveillance, LfTs, design changes, fire
protection/prevention program & refueling activities
SWANSON, E R, DUBRY, N E, BUDY, D L Region 3, Office of Director
83/10/03 10pp 20881 007 24X Fiche 50-315,83/10/05,8310240093

B308030378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass
Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,830800378

B3080300752 IE Info Notice 83-66, "Fatality at Argentine Critical
Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,830800752

B310210036 Summarizes actions taken during scheduled refueling outage
beginning B30715 Eddy current exam performed on steam
generators before refueling activities Westinghouse rpt on
steam generator tube degradation mechanism awaited
SMITH, W G Indiana & Michigan Electric Co 83/10/10 KEPPLER, J O
Region 3, Office of Director 5pp 20456 006 24X
Fiche 50-315,83/10/10,8310210036

B3080300759 IE Info Notice 83-67, "Emergency Use Respirator Mail Defect
Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,830800759

B3080300761 IE Info Notice 83-68, "Respirator User Warning Defective
Self-Contained Breathing Apparatus Air Cylinders " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,830800761

B310180376 Clarifies NRC position on procedures for admitting NRC
personnel to Facility Access to vital areas should be
afforded to listed Region III personnel Update will be
provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 DOLAN, J I
American Electric Power Service Corp DOLAN, J E Indiana & Michigan
Electric Co 7pp 20603 185 24X Fiche 50-315,83/10/14,8310180376

R Periodic operating reports & related correspondence

B310190070 Monthly operating rpt for Aug 1983 W/830914 ltr
GILLET, W T, SMITH, W G SWANSON, D A Indiana & Michigan Electric
Co 83/09/14 Division of Data Automation & Management
Information 6pp 20822 282 24X Fiche 50-315,83/09/14,8310190070

S Reportable occurrences, LERs & related correspondence

B310120260 LER 83-091/03L-0 on 830829, during refueling outage, fire door
leading to contractor access area inadvertently damaged when
door closed w/piece of steel between door jam & edge of
door Caused by personnel error Door repaired W/830928 ltr
WELCHER, D W, SMITH, W G Indiana & Michigan Electric Co 83/09/28
KEPPLER, J O Region 3, Office of Director 2pp 20693 008 24X
Fiche 50-315,83/09/28,8310120260

B310120343 LER 83-089/03L-0 on 830628, 31-day visual verification of
blind flange over fuel transfer tube CPN-1 deleted from all
revs Caused by verification deleted in 750407 rev Change
sheet written to include CPN-1 in procedure W/830927 ltr
STEPHENS, T R, SMITH, W G Indiana & Michigan Electric Co 83/09/28
KEPPLER, J O Region 3, Office of Director 3pp 20700 260 24X
Fiche 50-315,83/09/28,8310120343

B310060369 RO on 830929, during insp of containment lower val, one drop
per second leak discovered on nonessential svc water sys
Leak originated at packing on manual isolation valve
Followup rpt will be submitted within 14 days
SMITH, W G Indiana & Michigan Electric Co 83/09/29 KEPPLER, J O
Region 3, Office of Director 1p 20646 120 24X
Fiche 50-315,83/09/29,8310060369

B310120197 RO on 830930, while making pre-startup valve lineup,
discovered pump reversal on component cooling water supply &
return piping for containment H sampling sys Sys being
reviewed to determine effect during accident conditions
SMITH, W G Indiana & Michigan Electric Co 83/10/03 KEPPLER, J O
Region 3, Office of Director 1p 20694 103 24X
Fiche 50-315,83/10/03,8310120197

B310140029 Updated LER 83-054/03X-1 on 830526, during surveillance valve
lineup on diesel generator 1AB, Fuel oil day tank level
column high side isolation found closed Cause unknown
Investigation continuing W/831005 ltr
KRAUSE, D F, SMITH, W G Indiana & Michigan Electric Co 83/10/05
KEPPLER, J O Region 3, Office of Director 3pp 20768 080 24X
Fiche 50-315,83/10/05,8310140029

B310140084 LER 83-092/03L-0 on 830912, essential svc water pump 1W relay
timer exceeded Tech Spec tolerance Caused by instrument
drift Timer recalibr W/831005 ltr
PALMER, R A, SMITH, W G Indiana & Michigan Electric Co 83/10/05
KEPPLER, J O Region 3, Office of Director 2pp 20766 295 24X
Fiche 50-315,83/10/05,8310140084

B310170387 NPDES noncompliance notification on 830917, 24 h composite
sample from turbine room sump not collected Caused by stuck
valve Notification to State of MI encl
SMITH, W G Indiana & Michigan Electric Co 83/10/05 KEPPLER, J O
Region 3, Office of Director 2pp 20785 031 24X
Fiche 50-315,83/10/05,8310170387

B310170387 RO on 831007, wrong valves used for Ep(Z) in-core detector
computer code during Cycle VIII operation
SMITH, W G Indiana & Michigan Electric Co 83/10/10 KEPPLER, J O
Region 3, Office of Director 1p 20764 319 24X
Fiche 50-315,83/10/10,8310170387

B310210137 RO on 831003, 24 h rept notification made re incorrect
installation of containment hydrogen monitoring sys Sys
modified & reinstalled correctly on 831005
SMITH, W G Indiana & Michigan Electric Co 83/10/11 KEPPLER, J O
Region 3, Office of Director 1p 20456 079 24X
Fiche 50-315,83/10/11,8310210137

B310210040 LER 83-095/01T-0 on 830928, 3-inch gate valve manual
isolation to 1-CIT-1 containment cleanup for charcoal bed
spray nozzles found w/packing leak Caused by packing wear
Adjustment stopped leak Leaks unavoidable W/831012 ltr
PIELER, H, SMITH, W G Indiana & Michigan Electric Co 83/10/12
KEPPLER, J O Region 3, Office of Director 2pp 20855 330 24X
Fiche 50-315,83/10/12,8310210040

B310210187 Forwards updated LER 83-043/03X-1 & 83-055/03X-1 & LERs
83-093/03L-0 & 83-094/03L-0
SMITH, W G Indiana & Michigan Electric Co 83/10/12 KEPPLER, J O
Region 3, Office of Director 1p 20456 100 24X
Fiche 50-315,83/10/12,8310210187

DOCKETED ITEMS

--8310210191 Updated LER 83-043/03X-1 on 830513, control room emergency pressurization charcoal filter fire/trouble alarm activated. Cause by high prealarm & alarm resistance settings adjusted.
PALMER, R A Indiana & Michigan Electric Co 83/10/12 Region 3, Office of Director 1p 20856 101 24X Fiche 50-315, 83/10/12, 8310210187

--8310210197 Updated LER 83-059/03X-1 on 830529, west motor-driven auxiliary feed pump low suction pressure switches failed. Cause unknown. Reset values high out of spec. Switch replaced.
PALMER, R A Indiana & Michigan Electric Co 83/10/12 Region 3, Office of Director 2pp 20856 102 24X Fiche 50-315, 83/10/12, 8310210187

--8310210199 LER 83-093/03L-0 on 830915, false event recorded on diesel generator CD room peak recording accelerometer. Cause not stated. Personnel cautioned.
PALMER, R A Indiana & Michigan Electric Co 83/10/12 Region 3, Office of Director 2pp 20856 104 24X Fiche 50-315, 83/10/12, 8310210187

--8310210202 LER 83-094/03L-0 on 830922, 4-kV loss of voltage relays 27-1-T11D & 27-3-T11D exceeded tolerance. Cause by instrument drift. Relays reset.
PALMER, R A Indiana & Michigan Electric Co 83/10/12 Region 3, Office of Director 1p 20856 106 24X Fiche 50-315, 83/10/12, 8310210187

8310200165 Part 21 rept re static temp calibr check on transmitters. Initially reported on 831013. Cause by irregular setpoint for pressurizer pressure safety injection function New 1, B24 psig setpoint recommended.
RAHE, E P Westinghouse Electric Corp 83/10/13 DEYOUNG, H C Director's Office, Office of Inspection and Enforcement 2pp 20834 078 24X Fiche 50-000, 83/10/13, 8310200165

8310210113 Interim deficiency rept re calibr technique for temp compensation on Barton transmitters Westinghouse Part 21 rept described undefined errors at abnormal & accident temps. Next rept in 14 days.
SMITH, W O Indiana & Michigan Electric Co 83/10/14 KEPPLE, J O Region 3, Office of Director 1p 20858 234 24X Fiche 50-315, 83/10/14, 8310210113

8310270204 Forwards updated LER 83-077/03X-1 & LERs 83-096/03L-0 & 83-097/03L-0
SMITH, W O Indiana & Michigan Electric Co 83/10/18 KEPPLE, J O Region 3, Office of Director 1p 20923 282 24X Fiche 50-315, 83/10/18, 8310270204

8310270213 Updated LER 83-077/03X-1 on 830810, two nonessential vlv water valves missing from containment integrity procedure & one cap needed. Instrument isolations identified on air lock. Cause by personnel error.
KRAUSE, D F Indiana & Michigan Electric Co 83/10/18 Region 3, Office of Director 2pp 20923 283 24X Fiche 50-315, 83/10/18, 8310270204

10270223 LER 83-096/03L-0 on 830924, during refueling outage, Fire Door 317 would not latch properly between contractor access control & auxiliary bldg. Cause by loose active leaf latching mechanism. Mechanism tightened.
WIZNER, D O Indiana & Michigan Electric Co 83/10/18 Region 3, Office of Director 1p 20923 285 24X Fiche 50-315, 83/10/18, 8310270204

--8310270271 LER 83-097/03L-0 on 830921, during refueling outage, Fire Door 373 would not latch properly to 591 elevation vestibule area. Cause by sticky latch mechanism. Mechanism adjusted, lubricated, tested & returned to svc.
PIELKE, R H Indiana & Michigan Electric Co 83/10/18 Region 3, Office of Director 1p 20923 286 24X Fiche 50-315, 83/10/18, 8310270204

102726 LER 83-098/01T-0 on 831006, notified by vendor that wrong Jax for Ep(2) used for in-core detector computer code used by failure of personnel to update input data set card E to reflect Tech Spec changes W/831019 ltr.
PALMER, R A, SMITH, W O Indiana & Michigan Electric Co 83/10/19 PIERCE, J O Region 3, Office of Director 4pp 20924 036 24X Fiche 50-315, 83/10/19, 8310270226

DOCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2
F Security, medical, emergency & fire protection plans

8310030391 Forwards description of Class A radiation dose assessment model, per util 830415 ltr. Meteorological info & dose assessment sys Class A (ACRISU) program will be primary dose assessment model in emergency operations facility.
ALEXICH, M P Indiana & Michigan Electric Co 83/09/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 20593 056 24X Fiche 50-315, 83/09/27, 8310030391

8310030564 Releases public version of revised emergency plan (FSAR Chapter 12.3)
FELTON, J M Division of Rules and Records 83/09/28 Document Management Branch 1p 20605 338 24X Fiche 50-315, 83/09/28, 8310030564

--8310030579 Public version of Rev 2 to emergency plan (FSAR Chapter 12.3) W/830916 ltr.
ALEXICH, M P Indiana & Michigan Electric Co 83/09/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 417pp 20605 339 24X Fiche 50-315, 83/09/28, 8310030564

8310060474 Releases public version of revised index for plant manager procedures.
FELTON, J M Division of Rules and Records 83/09/30 Document Management Branch 1p 20660 172 24X Fiche 50-315, 83/09/30, 8310060474

--8310060479 Public version of revised index for plant manager procedures W/830919 ltr.
* Indiana & Michigan Electric Co 83/09/19 NR - No Detailed Affiliation Given 15pp 20660 173 24X Fiche 50-315, 83/09/30, 8310060474

8310110433 Releases public version of revised pages to App A of emergency plan procedures.
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20704 357 24X Fiche 50-315, 83/10/05, 8310110433

--8310110434 Public version of Rev B to Pages 9a & 9b of emergency plan procedures, App A Receipt form encl.
* Indiana & Michigan Electric Co 83/07/20 4pp 20704 358 24X Fiche 50-315, 83/10/05, 8310110433

8310240093 Forwards IE Insp Repts 50-315/83-14 & 50-316/83-15 on 830722-0909. No noncompliance noted.
SHAFER, W D Region 3, Office of Director 83/10/05 DULAN, J E American Electric Power Service Corp 2pp 20881 005 24X Fiche 50-315, 83/10/05, 8310240093

--8310240100 IE Insp Repts 50-315/83-14 & 50-316/83-15 on 830722-0909. No noncompliance noted. Major areas inspected: operational safety, maint, surveillance, LERs, design changes, fire protection/prevention program & refueling activities.
SWANSON, E R Region 3, Office of Director 83/10/03 10pp 20881 007 24X Fiche 50-315, 83/10/05, 8310240093

8310250391 Forwards FEMA 830928 ltr providing status of final findings of offsite preparedness. State & local plans & preparedness adequate to protect public.
PAPERIELLO, C J Region 3, Office of Director 83/10/21 DULAN, J E American Electric Power Service Corp 2pp 20897 280 24X Fiche 50-315, 83/10/21, 8310250391

--8310250401 Comments on status of offsite emergency preparedness. State & local plans & preparedness adequate to protect health & safety of public. Approval conditional on verification of public alerting & notification sys per NUREG-0654.
MC LAUGHLIN, D Federal Emergency Management Agency 83/09/28 DIRCKS, W J Office of the Executive Director for Operations 1p 20897 281 24X Fiche 50-315, 83/10/21, 8310250391

8310270190 Ack receipt of 830916 & 30 ltrs transmitting scope & objectives for 831130 emergency preparedness exercise. Exercise scenario should be submitted by 831211 & completed controller package by 840105.
PAPERIELLO, C J Region 3, Office of Director 83/10/24 ALEXICH, M P Indiana & Michigan Electric Co ALEXICH, M P American Electric Power Service Corp 2pp 20924 189 24X Fiche 50-315, 83/10/24, 8310270190

--8310270196 Forwards scope & objectives for 831130 emergency preparedness exercise. Scenario will be submitted by 831017 & completed controller/prompter package by 831110.
ALEXICH, M P Indiana & Michigan Electric Co 83/09/16 KEPPLE, J O Region 3, Office of Director 7pp 20724 187 24X Fiche 50-315, 83/10/24, 8310270190

DOCKETED ITEMS

147

J Insurance & indemnity information

8310240119 Forwards Endorsement 5 to NLLIA (certificates N-45 & N-64 & MAELU Certificates M-45 & M-64)
BUCKLES, J A Marsh & McLennan, Inc 83/10/12 SALI/HAN, J
Assistant Director For State & Licenser Relations 5pp 20881 140
24X Fiche 50-315,83/10/12,8310240119

K Utility Final Safety Analysis Report (FSAR) & amends

8310030564 Releases public version of revised emergency plan (1st Am Chapter 12 J)
FELTON, J M Division of Rules and Records 83/09/28 Document
Management Branch 1p 20605 338 24X Fiche 50-315,83/09/28,
8310030564

--8310030579 Public version of Rev 2 to emergency plan (FSAR Chapter 12 J) W/830916 ltr
ALEXICH, M P Indiana & Michigan Electric Co 83/09/16
DENTON, H R Office of Nuclear Reactor Regulation, Director
417pp 20605 339 24X Fiche 50-315,83/09/28,8310030564

P Operating license stage documents & correspondence

8310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR
CONNEL, L Affiliation Unknown 83/09/02 NRL - No Detailed
Affiliation Given 1p 21004 270 24X Fiche 50-000,83/09/02,
8310310017

8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which repts are unavailable
FELTON, J M Division of Rules and Records 83/07/06 CONNEL, L
Affiliation Unknown 1p 21004 271 24X Fiche 50-000,83/07/06,
8310310031

--8310310080 "Reactor Containment Bldg Integrated Leak Rate Test (Preoperational)"
* Indiana & Michigan Power Co * American Electric Power Co, Inc 76/04/10 121pp 21007 283 24X Fiche 50-000,83/07/06,
8310310031

8310050102 Advises that 830908 submittal of revised calculation results re cladding strain, oxidation & pellet-cladding interaction using RODEX2 code meets requirements of license condition Request for extended license condition unnecessary
VARGA, S A Operating Reactors Branch 1 83/09/20 DOLAN, J
Indiana & Michigan Electric Co DOLAN, J American Electric Power Service Corp 2pp 20650 240 24X Fiche 50-315,83/09/20,
8310050102

8310070408 Forwards BER re control of heavy loads based on Util Response to 801222 generic ltr Guidelines in NUREG-0612, Section 5.1.1 & 5.1.3 satisfied
VARGA, S A Operating Reactors Branch 1 83/09/20 DOLAN, J
Indiana & Michigan Electric Co 2pp 20675 332 24X
Fiche 50-315,83/09/20,8310070408

--8310070409 Safety evaluation re control of heavy loads Guidelines in NUREG-0612, Section 5.1.1 & 5.1.3 satisfied
* NRC - No Detailed Affiliation Given 83/09/20 2pp
20675 334 24X Fiche 50-315,83/09/20,8310070408

--8309060263 "Control of Heavy Loads (C-10) Indiana & Michigan Electric Co, DC Cook Nuclear Plant Units 1 & 2," technical evaluation reft
VOSBURY, F W, DOMBERGER, C R Franklin Institute/Franklin Research Center NRC-03-81-130 TEH-C5506-344/345 83/09/01 SJNSH, A
NRC - No Detailed Affiliation Given 33pp 20675 336 24X
Fiche 50-315,83/09/20,8310070408

8310030386 Supplis & amends 830520 & 0810 requests for extensions required in 10CFR50.49 re equipment environ qualification
ALEXICH, M P Indiana & Michigan Electric Co 83/09/26 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 20592 323
24X Fiche 50-315,83/09/26,8310030386

8310060028 Summary of 830913 meeting w/Util in Bethesda, MD re environ qualification of electrical equipment & hydrogen control
WIGGINTON, D Operating Reactors Branch 1 83/09/27 Operating
Reactors Branch 1 11p 20664 110 24X Fiche 50-315,83/09/27,
8310060028

8310060546 Approves 830902 request to use later editions of ASME Section XI Code for test temp requirement for hydrostatic tests of Class 1 & 2 austenitic stainless steel piping & components
VARGA, S A Operating Reactors Branch 1 83/09/28 DOLAN, J
Indiana & Michigan Electric Co DOLAN, J American Electric Power Service Corp 3pp 20661 284 24X Fiche 50-315,83/09/28,
8310060546

8310070225 Notification of 831013 meeting w/Util & Exxon in Bethesda, MD to discuss resolution of license conditions imposed on Cycle 4 operation & content of Cycle 5 reload submittal
WIGGINTON, D Operating Reactors Branch 1 83/09/30 VARGA, S A
Operating Reactors Branch 1 2pp 20664 360 24X
Fiche 50-316,83/09/30,8310070225

8310130217 Forwards Amends 7b & 5c to Licenses DPR-58 & DPR-74, respectively Amends change Tech Spec to require redundant containment hydrogen analyzers to satisfy requirements of NUREG-0737, TMI Action Item 11 F-1 &
VARGA, S A Operating Reactors Branch 1 83/09/30 DOLAN, J
Indiana & Michigan Electric Co DOLAN, J American Electric Power Service Corp 3pp 20777 180 24X Fiche 50-315,83/09/30,
8310130217

--8310130222 Amends 75 & 5c to licenses DPR-58 & DPR-74, respectively, changing Tech Spec to require redundant containment hydrogen analyzers to satisfy requirements of NUREG-0737, TMI Action Item 11 F-1 &
VARGA, S A Operating Reactors Branch 1 83/09/30 9pp
20777 183 24X Fiche 50-315,83/09/30,8310130217

8310140040 Forwards response to SA Varga 820730, 0916 & 830810 requests for addl info re hydrogen combustion & control during degraded core accidents
ALEXICH, M P Indiana & Michigan Electric Co 83/10/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 20768 089
24X Fiche 50-315,83/10/10,8310140040

8310200158 Requests extension until 831215 to submit rept on plant-specific evaluation of relief & safety valves & associated piping sys per NUREG-0737, Item 11 D-1.2
ALEXICH, M P Indiana & Michigan Electric Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20836 317
24X Fiche 50-315,83/10/14,8310200158

Q Inspection reports, IE Dulletins & correspondence

8310120293 Ack receipt of 830906 ltr informing NRC of steps taken to correct violations noted in IL Insp Repts 50-315/83-12 & 50-316/83-13
SHAFFER, W D Region 3, Office of Director 83/09/19 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 1p 20692 341 24X Fiche 50-315,83/09/19,8310120293

8310130025 Forwards SER & technical evaluation rept re responses to IL Bulletin 80-11, "Masonry Wall Design" Joint reinforcement masonry walls not well established Structural element not acceptable Response requested
VARGA, S A Operating Reactors Branch 1 83/09/20 DOLAN, J
Indiana & Michigan Electric Co DOLAN, J American Electric Power Service Corp 3pp 20772 146 24X Fiche 50-315,83/09/20,
8310130025

--8310130026 Safety evaluation supporting mods re IE Bulletin 80-11, "Masonry Wall Design"
* Office of Nuclear Reactor Regulation, Director 83/09/20 2pp
20772 149 24X Fiche 50-315,83/09/20,8310130025

--8308030382 Revised "Masonry Wall Design (B-59), DC Cook Nuclear Plant, Units 1 & 2," technical evaluation rept
TRILOLO, S, CON, V N Franklin Institute/Franklin Research Center NRC-03-81-130 YER-C5506-241 R01 83/07/27 CHOKSHI, N NRC - No
Detailed Affiliation Given 38pp 20772 151 24X
Fiche 50-315,83/09/20,8310130025

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342

DOCKETED ITEMS

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310240093 Forwards IE Insp Repts 50-315/83-14 & 50-316/83-15 on 830722-0907 No noncompliance noted
SHAHER, W D Region 3, Office of Director 83/10/05 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 20881 005 24X Fiche 50-315, 83/10/05, 8310240093

--8310240100 IE Insp Repts 50-315/83-14 & 50-316/83-15 on 830722 0907 No noncompliance noted Major areas inspected operational safety, maint, surveillance, LERs, design changes, fire protection/prevention program & refueling activities
SHANSON, E R, DUBRY, N E, BOYD, D C Region 3, Office of Director 83/10/03 10pp 20881 007 24X Fiche 50-315, 83/10/05, 8310240093

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180376 Clarifies NRC position on procedures for admitting NRC personnel to Facility Access to vital areas should be afforded to listed Region III personnel Update will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 7pp 20803 185 24X Fiche 50-315, 83/10/14, 8310180376

R Periodic operating reports & related correspondence

8310190064 Monthly operating rept for Aug 1983 W/830914 1t
GILLET, W T, SMITH, W G Indiana & Michigan Electric Co 83/09/14
Office of Resource Management, Director 11pp 20822 320 24X Fiche 50-316, 83/09/14, 8310190064

S Reportable occurrences, LERs & related correspondence

8310110430 Responds to FOIA request for four different categories of documents described in 830510 1tr Forwards matl listed in App A, responsive to Items 1, 2 & 4 DOE should be contacted for matl requested in Item 3 of ltr
FELTON, J M Division of Rules and Records 83/06/14 HIATT, S L Ohio Citizens for Responsible Energy 3pp 20706 002 24X Fiche 50-000, 83/06/14, 8310110430

--8310110443 Forwards PNG & morning rept re faulty Borg-Warner valve radiographs Problem may be generic Related info encl
LITTLE, W B Region 3, Office of Director 83/04/13 POTAPOVS, U Region 4, Office of Director 15pp 20706 003 24X Fiche 50-000, 83/06/14, 8310110430

8310120193 RD on 830926, carbon dioxide sys for diesel generator room left in isolated condition w/no personnel in attendance Upon discovery, sys immediately returned to operable status
SMITH, W G Indiana & Michigan Electric Co 83/09/27 KEPPLER, J C Region 3, Office of Director 1p 20693 332 24X Fiche 50-316, 83/09/27, 8310120193

8310120234 RD on 830927, during sampling process, sample valve on boron injection tank found partially open allowing boric acid solution to drain out Caused by personnel error Boron injection tank brought back into sprc
SMITH, W G Indiana & Michigan Electric Co 83/09/27 KEPPLER, J C Region 3, Office of Director 1p 20691 327 24X Fiche 50-316, 83/09/27, 8310120193

8310120443 Forwards LERs 83-084/03L-0, 83-085/03L-0 & 83-086/03L-0
SMITH, W G Indiana & Michigan Electric Co 83/09/28 KEPPLER, J C Region 3, Office of Director 1p 20693 321 24X Fiche 50-316, 83/09/28, 8310120443

--8310120445 LER 83-084/03L-0 on 830901, during controlled shutdown at approx 10E-B power, 1 average decreased below Tech Spec min of 941 t Cold shutdown terminated at 535 t temp would not return to 541 t within 15 minutes Reactor trip breakers opened
DRAPER, D M Indiana & Michigan Electric Co 83/09/28 Region 3, Office of Director 1p 20698 322 24X Fiche 50-316, 83/09/28, 8310120443

--8310120448 LER 83-085/03L-0 on 830902, during startup at 20% power, after turbine generator paralleled w/sys grid, generator load increased to prevent motoring, resulting in pressure drop below Tech Specs Caused by heater breaker trip
MURPHY, C E Indiana & Michigan Electric Co 83/09/28 Region 3, Office of Director 1p 20698 323 24X Fiche 50-316, 83/09/28, 8310120443

--8310120449 LER 83-086/03L-0 on 830905, chart paper on containment sump flow monitoring recorder: ICS-001, would not advance Cause not determined Chart paper adjusted & renumber verified operable Design change submitted
STEPHENS, T R Indiana & Michigan Electric Co 83/09/28 Region 3, Office of Director 1p 20698 324 24X Fiche 50-316, 83/09/28, 8310120443

8310120188 LER 83-087/03L-0 on 830904, pressurizer level channel 1 (NLP-151) indication drifted high Caused by water leaking from low side drain valve on pressurizer cold calibr level transmitter (NLP-151) Valve tightened W/831004 ltr
PALMER, R A, SMITH, W G Indiana & Michigan Electric Co 83/10/04 KEPPLER, J C Region 3, Office of Director 3pp 20692 236 24X Fiche 50-316, 83/10/04, 8310120188

8310120379 RD on 831004, steam jet air ejector monitor (SRA-2405) determined inoperable A B h grab sample not completed within required time frame Followup rept expected within 14 days
SMITH, W G Indiana & Michigan Electric Co 83/10/04 KEPPLER, J C Region 3, Office of Director 1p 20699 200 24X Fiche 50-316, 83/10/04, 8310120379

8310140137 Forwards LERs 83-088/03L-0, 83-089/03L-0, 83-090/03L-0 & 83-091/03L-0
SMITH, W G Indiana & Michigan Electric Co 83/10/05 KEPPLER, J C Region 3, Office of Director 1p 20763 052 24X Fiche 50-316, 83/10/05, 8310140137

--8310140138 LER 83-088/03L-0 on 830912, nonfunctional fire seal discovered Caused by fire seal pulled while installing another cable Fire seal repaired & contractor personnel restrained
SMITH, W G Indiana & Michigan Electric Co 83/10/05 Region 3, Office of Director 1p 20763 053 24X Fiche 50-316, 83/10/05, 8310140137

--8310140139 LER 83-089/03L-0 on 830915, west containment spray pump discharge valve position lights noted out & breaker open Cause could not be determined No corrective action planned
KRAUSE, D F Indiana & Michigan Electric Co 83/10/05 Region 3, Office of Director 1p 20763 054 24X Fiche 50-316, 83/10/05, 8310140137

--8310140140 LER 83-090/03L-0 on 830920, during surveillance test on solid-state protection sys, two logic positions tested unsatisfactorily Caused by defective universal card A-311 Logic card replaced
PALMER, R A Indiana & Michigan Electric Co 83/10/05 Region 3, Office of Director 1p 20763 055 24X Fiche 50-316, 83/10/05, 8310140137

--8310140141 LER 83-091/03L-0 on 830906, pressurizer pressure dropped below Tech Spec limit Caused by combination of individual pressurizer heater circuit breakers tripping & high valve seat leakage Load reduced
PALMER, R A Indiana & Michigan Electric Co 83/10/05 Region 3, Office of Director 2pp 20763 056 24X Fiche 50-316, 83/10/05, 8310140137

DOCKETED ITEMS

149

8310170387 NPDES noncompliance notification on 830917, 24 h composite sample from turbine room sump not collected (caused by stuck valve Notification to State of MI encl
SMITH, W G Indiana & Michigan Electric Co 83/10/05 KEPPLER, J C
Region 3, Office of Director 2pp 20785 031 24X
Fiche 50-315, 83/10/05, 8310170387

8310170607 Forwards LERs 83-092/011-0 & 83-093/011-0
SMITH, W G Indiana & Michigan Electric Co 83/10/10 KEPPLER, J C
Region 3, Office of Director 1p 20782 094 24X
Fiche 50-316, 83/10/10, 8310170607

--8310170611 LER 83-092/011-0 on 830926, during routine sampling of boron injection tank, sampling valves at tank outlet left partially open Caused by personnel error Appropriate administrative actions taken against individual involved
PALMER, R A Indiana & Michigan Electric Co 83/10/10 Region 3, Office of Director 2pp 20782 095 24X Fiche 50-316, 83/10/10, 8310170607

--8310170619 LER 83-093/011-0 on 830926, during normal operation, security officer found carbon dioxide switch for diesel generator room in isolate position & unattended Cause being investigated
RICHAUD, D D Indiana & Michigan Electric Co 83/10/10 Region 3, Office of Director 1p 20782 097 24X Fiche 50-316, 83/10/10, 8310170607

8310210206 Forwards updated LER 83-072/03X-1 & LER 83-094/03L-0
SMITH, W G Indiana & Michigan Electric Co 83/10/12 KEPPLER, J C
Region 3, Office of Director 1p 20852 081 24X
Fiche 50-316, 83/10/12, 8310210206

--8310210212 Updated LER 83-072/03X-1 on 830730, blowdown containment isolation valve 2-DCR-320 found w/coupling separated from valve stem & valve stem bent Probable cause is vibration Coupling valve stem & packing replaced
PIELKE, R H Indiana & Michigan Electric Co 83/10/12 Region 3, Office of Director 1p 20852 082 24X Fiche 50-316, 83/10/12, 8310210206

--8310210215 LER 83-094/03L-0 on 830914, during normal operation, Loop 4 steam line pressure Channel 2 removed from svc because of indications instrument line obstructed Cause not stated
WIZNER, D G Indiana & Michigan Electric Co 83/10/12 Region 3, Office of Director 1p 20852 083 24X Fiche 50-316, 83/10/12, 8310210206

8310210120 LER 83-095/011-0 on 831003, discovered that radiation monitor for turbine condenser evacuation sys inoperable due to sample pump feed breaker tripping open Caused by operator failure to recognize monitor failure alarm W/831014 ltr
MURPHY, C E, SMITH, W G Indiana & Michigan Electric Co 83/10/14 KEPPLER, J C Region 3, Office of Director 3pp 20858 251 24X Fiche 50-316, 83/10/14, 8310210120

8310210122 PNO-III-83-099 on 831015, unit shut down for steam generator tube leak exam & repair Unit will be shut down for 2-3 wks
Region & resident inspector will monitor course of action
BOYD, D , SHAFER, W Region 3, Office of Director 83/10/17 1p 20858 250 24X Fiche 50-316, 83/10/17, 8310210122

8310270172 LER 83-096/03L-0 on 830918, during attempt to rectify order of procedural steps re containment spray surveillance tests concerning lineup of valve A, water drained to containment Caused by personnel error W/831018 ltr
KRAUSE, D F, SMITH, W G Indiana & Michigan Electric Co 83/10/18 KEPPLER, J C Region 3, Office of Director 2pp 20925 001 24X Fiche 50-316, 83/10/18, 8310270172

DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1
F Security, medical, emergency & fire protection plans

8310040449 Accepts, in part, revs to safeguards plans addressed in licensee 830223 & 0316 ltrs Certain sections not acceptable & should be modified Corrected page revs requested within 30 days Safeguards info withheld (ref 10CFR73 21)
MARTIN, T T Division of Engineering & Technical Programs 83/09/23 BOWMAKER, N J Baltimore Gas & Electric Co 4pp 20625 276 24X Fiche 50-317, 83/09/23, 8310040449

8310050340 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/09/26 Document Management Branch 1p 20635 047 24X Fiche 50-317, 83/09/26, 8310050340

--8310050344 Public version of Rev 10 to Emergency Plan Implementing Procedure ERPIP 3 1, "Immediate Action Procedures" W/830915 ltr
WALL, C F, RUSSELL, L B Baltimore Gas & Electric Co 83/08/31 Director's Office, Office of Inspection and Enforcement 33pp 20635 048 24X Fiche 50-317, 83/09/26, 8310050340

8310200099 Forwards JE Insp Repts 50-317/83-21 & 50-318/83-21 on 830809-0913 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/10/03 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 20837 103 24X Fiche 50-317, 83/10/03, 8310200099

- 8310200107 IE Insp Repts 50-317/83-21 & 50-318/83-21 on 830809-0913 Noncompliance noted failure to follow chemistry procedures
ARCHITZEL, R E, TRIMBLE, D C, HIGGINS, J C Region 1, Office of Director 83/09/29 19pp 20837 106 24X Fiche 50-317, 83/10/03, 8310200099

8310110244 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20685 350 24X Fiche 50-317, 83/10/05, 8310110244

--8310110254 Forwards public version of Rev 0, Change 1, to Emergency Plan Implementing Procedure ERPIP 4 1 22 1, "CR/TSC Plant Parameter Rept" & Rev 10, Change 3, to ERPIP App B 1, "Emergency Response Plan Implementation Procedures"
USI, V Baltimore Gas & Electric Co 83/09/27 Assistant Director for Operating Reactors 1p 20685 351 24X Fiche 50-317, 83/10/05, 8310110244

--8310110258 Public version of Rev 0, Change 1, to Emergency Plan Implementing Procedure ERPIP 4 1 22 1, "CR/TSC Plant Parameter Rept" & Rev 10, Change 3, to ERPIP App B 1, "Emergency Response Plan Implementation Procedures"
RUSSELL, L B Baltimore Gas & Electric Co 83/09/21 15pp 20685 352 24X Fiche 50-317, 83/10/05, 8310110244

8310130312 Releases public version of licensee ltr forwarding notice canceling emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/06 Document Management Branch 1p 20754 337 24X Fiche 50-317, 83/10/06, 8310130312

--8310130313 Forwards public version of 830927 notification canceling Emergency Plan Implementing Procedure ERPIP 4 2, "Notification"
USI, V Baltimore Gas & Electric Co 83/09/29 Assistant Director for Operating Reactors 2pp 20754 338 24X Fiche 50-317, 83/10/06, 8310130312

8310170003 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/06 Document Management Branch 1p 20814 031 24X Fiche 50-317, 83/10/06, 8310170003

--8310170005 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure 4 1 22 1, "CR/TSC Plant Parameter Rept" & Rev 10 to ERPIP App B 1 Receipt form encl
USI, V Baltimore Gas & Electric Co 83/09/27 Director's Office, Office of Inspection and Enforcement 1p 20814 032 24X Fiche 50-317, 83/10/06, 8310170003

8310270481 Releases public version of revised emergency response plan
FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20938 104 24X Fiche 50-317, 83/10/21, 8310270481

--8310270485 Public version of Rev 2 to emergency response plan W/820819 ltr
Baltimore Gas & Electric Co 82/08/31 KANTOR, F EP Licensing Branch 33pp 20938 105 24X Fiche 50-317, 83/10/21, 8310270481

8310310014 Forwards safeguards info Encl withheld (ref 10CFR73 21)
JOLLEY, J R Baltimore Gas & Electric Co 83/10/24 CLARK, R A Operating Reactors Branch 3 1p 20951 143 24X Fiche 50-317, 83/10/24, 8310310014

8310310055 Forwards revs to security plan & training & qualification plan Encls withheld (ref 10CFR73 21)
BOWMAKER, N J Baltimore Gas & Electric Co 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20950 339 24X Fiche 50-317, 83/10/24, 8310310055

DOCKETED ITEMS

P Operating license stage documents & correspondence

8310310063 FOIA request for documents re const & operation of C-E plants list of info required submitted
BELL, N Coalition for Safe Power 83/03/31 Office of Administration 1p 20998 1/3 24X Fiche 50-000, 83/03/31, 8310310063

8310070176 Forwards Amends B7 & 69 to Licenses DPR-53 & DPR-69 & safety evaluation Amend revises Tech Specs re required containment isolation valve response time
JAFFE, D H Operating Reactors Branch 3 83/09/22 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 20680 277 24X Fiche 50-317, 83/09/22, 8310070176

--8310070179 Amends B7 & 69 to licenses DPR-53 & DPR-69, reflecting mod to valve 1(2)-SV-6529 response closure time
MILLER, J R Operating Reactors Branch 3 83/09/22 8pp 20680 279 24X Fiche 50-317, 83/09/22, 8310070176

--8310070180 Safety evaluation supporting Amends B7 & 69 to Licenses DPR-53 & DPR-69
* Office of Nuclear Reactor Regulation, Director 83/09/22 2pp 20680 289 24X Fiche 50-317, 83/09/22, 8310070176

8310040080 Forwards Page 4, Section 11.1 of procurement & storage manual covering Level A & Level C items
HOPPA, J L Baltimore Gas & Electric Co 83/09/26 MEYER, C Region 1, Office of Director 2pp 20608 001 24X Fiche 50-317, 83/09/26, 8310040080

8310040353 Forwards "Pressurizer Relief Valve Qualification," & Rev 1 to "Pressurizer Safety Valve Operability Rept," per NUREG-0737, Item 11 D 1 Design load stresses on piping & fittings within allowable limits
LUNDVALL, A E Baltimore Gas & Electric Co 83/09/28 MILLER, J R Operating Reactors Branch 3 4pp 20615 036 24X Fiche 50-317, 83/09/28, 8310040353

--8310040355 "Pressurizer Relief Valve Discharge Piping Qualification," rept on task 03088
SMITH, J V, VENTURA, J C Bechtel Corp 83/09/28 154pp 20615 040 24X Fiche 50-317, 83/09/28, 8310040353

--8310040357 Rev 1 to "Pressurizer Safety Valve Operability Rept"
* Combustion Engineering, Inc CEN-248(B) R01 83/09/30 100pp 20615 194 24X Fiche 50-317, 83/09/28, 8310040353

8310130137 Approves 830731 request on behalf of C-E Owners Group for withholding from public disclosure App A to "Response to Questions on RCS Asymmetric Loads Evaluation Program," per 10CFR2 790
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/03 LUNDVALL, A E Baltimore Gas & Electric Co 6pp 20777 061 24X Fiche 50-000, 83/10/03, 8310130137

10310479 Notice of consideration of issuance of amend to License DPR-53 & proposed NSHC determination & opportunity for hearing Initial NSHC determination available in Central Files
JAFFE, D, MILLER, J R NRC - No Detailed Affiliation Given WOODHEAD, C P Office of the Executive Legal Director 83/10/05 16pp 20965 341 24X Fiche 50-317, 83/10/06, 8310310479

8310240072 Application for amend to Licenses DPR-53 & DPR-69 revising Surveillance Requirement 4.7.6.1 & replacing Page 3/4 3-26 incorporating mod to measurement range for gaseous & particulate activity monitors Marked-up Tech Specs encl
LUNDVALL, A E Baltimore Gas & Electric Co 83/10/12 MILLER, J R Operating Reactors Branch 3 7pp 20681 328 24X Fiche 50-317, 83/10/12, 8310240072

8310310180 Forwards safety evaluation based on review of util response to NUREG-0737, Items 11 K 3.1, "Automatic PORV Isolation" & 11 K 3.2, "Rept on PORVs" Requirements met
MILLER, J R Operating Reactors Branch 3 83/10/12 LUNDVALL, A E Baltimore Gas & Electric Co 14pp 21000 037 24X Fiche 50-317, 83/10/12, 8310310180

8310200241 Provides proprietary & nonproprietary "Revised Zircaloy-4 Growth Correlations," per evaluation of shoulder gap clearance for Cycle 7 reload engineering & analysis Proprietary version withheld (ref 10CFR2 790)
LUNDVALL, A E Baltimore Gas & Electric Co 83/10/14 MILLER, J R Operating Reactors Branch 3 6pp 20600 145 24X Fiche 50-317, 83/10/14, 8310200241

--8310200245 Nonproprietary "Revised Zircaloy-4 Growth Correlations" Proprietary info deleted
* Combustion Engineering, Inc 83/10/04 8pp 20830 151 24X Fiche 50-317, 83/10/14, 8310200241

8310210157 Informs that refund for review of 830427 amend application forthcoming
MILLER, W O License Fee Management Branch 83/10/14 LUNDVALL, A E Baltimore Gas & Electric Co 1p 20063 061 24X Fiche 50-317, 83/10/14, 8310210157

8310240134 Provides status of mods required for Generic Ltr 83-01 re inadequate core cooling instrumentation & NUREG-0737, Item 11 F 2 Issues include environ qualification of two LTR subsystems & installation of core exit thermocouple
LUNDVALL, A E Baltimore Gas & Electric Co 83/10/14 MILLER, J R Operating Reactors Branch 3 3pp 20681 166 24X Fiche 50-317, 83/10/14, 8310240134

8310240162 Notifies of resolution of NUREG-0737, IMI Action Plan Item 11 K 2.17, "Potential for Voiding in RGS During Transients"
Results of analysis presented in CEN-197 applicable to facilities w/stated exception
LUNDVALL, A E Baltimore Gas & Electric Co 83/10/19 MILLER, J R Operating Reactors Branch 3 1p 20081 312 24X Fiche 50-317, 83/10/19, 8310240162

8310310303 Forwards response to NRC questions re reload submittal for Cycle 7, per 831014 telcon Initial mod pressure below nominal sys pressure throughout Cycle 7
LUNDVALL, A E Baltimore Gas & Electric Co 83/10/24 MILLER, J R Operating Reactors Branch 3 3pp 20961 229 24X Fiche 50-317, 83/10/24, 8310310303

0 Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-ins for Validity Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edition Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8310030340

8308300342 IE Info Notice 83-62, "Failure of Redundant Inlet Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edition Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8310030342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edition Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8310030345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edition Co of New York, Inc 119pp 20716 324 24X Fiche 50-000, 83/09/29, 8310030349

8310200099 Forwards IE Insp Repts 50-317/83-21 & 50-318/83-21 on 830807-0913 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/10/05 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 20837 107 24X Fiche 50-317, 83/10/05, 8310200099

--8310200103 Notice of violation from insp on 830807 0913
* Region 1, Office of Director 83/10/03 1p 20683 105 24X Fiche 50-317, 83/10/03, 8310200099

--8310200107 IE Insp Repts 50-317/83-21 & 50-318/83-21 on 830807 0913 Noncompliance noted failure to follow chemistry procedures
ARCHITZEL, R E, TRIMBLE, D C, HIGGINS, J C Region 1, Office of Director 83/09/29 19pp 20837 106 24X Fiche 50-317, 83/10/05, 8310200099

8310210207 Ack receipt of 830916 ltr informing NRC of steps taken to correct violations noted in IL Insp Repts 50-317/83-22 & 50-318/83-22
STAROSTECKI, R Division of Project & Resident Programs 83/10/05 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 20855 117 24X Fiche 50-317, 83/10/05, 8310210207

--8310210210 Responds to NRC ltr re violations noted in IL Insp Repts 50-317/83-22 & 50-318/83-22 Corrective actions training in areas of sys descriptions, staffing, facilities & feedback of plant events upgraded
LUNDVALL, A E Baltimore Gas & Electric Co 83/09/16 STAROSTECKI, R Division of Project & Resident Programs 4pp 20855 119 24X Fiche 50-317, 83/10/05, 8310210207

DOCKETED ITEMS

151

8308300378 IE Info Notice 83-65, "Surveillance of Flow in R1D Bypass Loops Used in Westinghouse Plant: " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Mntl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 11pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310310227 Forwards IE Enforcement Conference Repts 50-317/83-22 & 50-318/83-22 on 830902
STAROSTECKI, R Division of Project & Resident Programs 83/10/17
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 20947 224 24X Fiche 50-317, 83/10/13, 8310310227

--8310310230 IE Enforcement Conference Repts 50-317/83-22 & 50-318/83-22 on 830902 Major areas discussed results of NRC special insp which identified violation of Tech Spec limiting conditions for operation re emergency diesel generators
HIGGINS, J, ARCHITZEL, R, TRIMBLE, D Region 1, Office of Director 83/09/27 5pp 20947 226 24X Fiche 50-317, 83/10/13, 8310310230

A Periodic operating reports & related correspondence

8310190148 Monthly operating repts for Sept 1983 W/831014 1tr
LOFTIO, E M Baltimore Gas & Electric Co 83/10/14 Director's Office, Office of Inspection and Enforcement 12pp 20820 22/ 24X Fiche 50-317, 83/10/14, 8310190148

B Reportable occurrences, LERs & related correspondence

8310270341 Responds to FOIA request for three categories of documents re 830606 gas leak at facility forwards App A documents
FELTON, J M Division of Rules and Records 83/07/22 ARGYROS, D L Chamlin, Schottland, Rosen, Cavanagh & Uliano 2pp 20937 225 24X Fiche 50-000, 83/07/22, 8310270341

--8310270547 Submits morning rept for Region I, listing 830606 & 07 events
ALLAN, J M Region 1, Office of Director 83/06/07 BLAHA, J Program Support Branch 1p 20937 228 24X Fiche 50-000, 83/07/22, 8310270547

8310250410 LER 83-049/03L-0 on 830818, while performing post-maint testing on flow path from condensate storage tank 12, auxiliary feedwater pump 11 found inoperable Caused by "stage & shaft piece-balance" frozen in place W/830916 1tr
PORTER, R, FARRELL, E V, RUSSELL, L B Baltimore Gas & Electric Co 83/09/16 MURLEY, T E Region 1, Office of Director 2pp 20897 234 24X Fiche 50-317, 83/09/16, 8310250410

8310280081 Updated LER 82-035/01X-1 on 820717, discrepancy noted in narrow-range & wide-range indications for safety injection tank 11B Narrow-range indication subsequently dropped offscale Caused by sticking indicator W/830921 1tr
ANDROSIAK, R, RUSSELL, L B Baltimore Gas & Electric Co 83/09/21 MURLEY, T E Region 1, Office of Director 3pp 20935 074 24X Fiche 50-317, 83/09/21, 8310280081

8310200147 LER 83-047/03L-0 on 830822, during normal operation, control room air conditioner compressor 12 would not run when start signal initiated Investigation revealed compressor tripped on high pressure High pressure control reset W/830922 1tr
JUNGE, M A, MAHON, C R, RUSSELL, L B Baltimore Gas & Electric Co 83/09/22 MURLEY, T E Region 1, Office of Director 2pp 20836 292 24X Fiche 50-317, 83/09/22, 8310200147

8310120262 RO on 830831, reactor & turbine manually tripped due to large impingement episode, clogging travelling screens Detailed explanation, in util 830914 rept to State of MD Ofc of Environ Programs, encl
BAUERETIS, E J Baltimore Gas & Electric Co 83/09/23 Region 1, Office of Director 8pp 20693 137 24X Fiche 50-317, 83/09/24, 8310120262

8310040542 RO oyster samples collected during Aug 1983 from Camp Conoy location showed presence of Ag-110m concentration of 118+- BpCi/Kg (wet) Monthly percent capacity factors listed Doses considered insignificant consequence to public health
FUHRMAN, G R Baltimore Gas & Electric Co 83/09/26 Region 1, Office of Director 2pp 20623 301 24X Fiche 50-317, 83/09/26, 8310040542

8310250587 LER 83-045/03L-0 on 830829, containment atmospheric gaseous & particulate radiation monitor discharge solenoid valve found damaged, venting portion of flow to auxiliary bldg Cause under investigation Valve replaced W/830928 1tr
JUNGE, M A, ANDROSIAK, R, RUSSELL, L B Baltimore Gas & Electric Co 83/09/28 MURLEY, T E Region 1, Office of Director 2pp 20901 296 24X Fiche 50-317, 83/09/28, 8310250587

8310070301 Potential Part 21 rept re underrange characteristic of Model N-E110M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN, M J Fairbairn Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X Fiche 50-000, 83/09/30, 8310070301

8310250249 LER 83-050/03L-0 on 830912, during normal operation, hydrogen analyzer 12 found inoperable Caused by out of adjustment reagent gas flow controller Controller readjusted Surveillance procedures revised W/831012 1tr
PORTER, R, SYDNOR, R, RUSSELL, L B Baltimore Gas & Electric Co 83/10/12 MURLEY, T E Region 1, Office of Director 2pp 20899 150 24X Fiche 50-317, 83/10/12, 8310250249

8310240269 Responds to 830906 memo re AE0D/T314, "Improper Size of Inlet Piping to Primary Safety Valves at Millstone 2 & Calvert Cliffs 1 & 2 " Flow limiting devices for code safety valves 1 7/8-inch bore diameter discussed
EISENHUT, D O Division of Licensing 83/10/18 THOMPSON, H L Division of Human Factors Safety 1p 20907 338 24X Fiche 50-000, 83/10/18, 8310240269

DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8310040449 Accepts, in part, repts to safeguards plans addressed in licensee 830223 & 0316 1trs Certain sections not acceptable & should be modified Corrected page repts requested within 30 days Safeguards info withheld (ref 10CFR73 21)
MARTIN, T T Division of Engineering & Technical Programs 83/09/23 BOWMAKER, N J Baltimore Gas & Electric Co 4pp 20625 276 24X Fiche 50-317, 83/09/23, 8310040449

8310050340 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/09/26 Document Management Branch 1p 20635 047 24X Fiche 50-317, 83/09/26, 8310050340

--8310050344 Public version of Rev 10 to Emergency Plan implementing Procedure ERPIP 3 1, "Immediate Action Procedures " W/830915 1tr
WALL, C F, RUSSELL, L B Baltimore Gas & Electric Co 83/08/31 Director's Office, Office of Inspection and Enforcement 33pp 20635 048 24X Fiche 50-317, 83/09/26, 8310050340

8310200099 Forwards IE Insp Repts 50-317/83-21 & 50-318/83-21 on 830809-0913 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/10/03 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 20837 103 24X Fiche 50-317, 83/10/03, 8310200099

--8310200107 IE Insp Repts 50-317/83-21 & 50-318/83-21 on 830809-0913 Non-compliance noted failure to follow chemistry procedures
ARCHITZEL, R E Region 1, Office of Director 83/09/29 19pp 20837 106 24X Fiche 50-317, 83/10/03, 8310200099

8310110244 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20685 350 24X Fiche 50-317, 83/10/05, 8310110244

--8310110254 Forwards public version of Rev 0, Change 1, to Emergency Plan implementing Procedure ERPIP 4 1 22 1, "CR/TSC Plant Parameter Rept" & Rev 10, Change 3, to ERPIP App B 1, "Emergency Response Plan Implementation Procedures " USI, V Baltimore Gas & Electric Co 83/09/27 Assistant Director for Operating Reactors 1p 20685 351 24X Fiche 50-317, 83/10/05, 8310110244

DOCKETED ITEMS

--8310110258 Public version of Rev 0, Change 1, to Emergency Plan Implementing Procedure ERPIP 4 1 22 1, "CR/TSC Plant Parameter Rept" & Rev 10, Change 3, to ERPIP App B 1, "Emergency Response Plan Implementation Procedures" RUSSELL, L B Baltimore Gas & Electric Co 83/09/21 1pp 20685 352 24X Fiche 50-317, 83/10/05, 8310110244

8310130312 Releases public version of licensee ltr forwarding notice canceling emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/10/06 Document Management Branch 1p 20754 337 24X Fiche 50-317, 83/10/06, 8310130312

--8310130313 Forwards public version of 830927 notification canceling Emergency Plan Implementing Procedure ERPIP 4 2, "Notification" USI, V Baltimore Gas & Electric Co 83/09/29 Assistant Director for Operating Reactors 2pp 20754 338 24X Fiche 50-317, 83/10/06, 8310130312

8310170003 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/10/06 Document Management Branch 1p 20814 031 24X Fiche 50-317, 83/10/06, 8310170003

--8310170005 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure 4 1 22 1, "CR/TSC Plant Parameter Rept" & Rev 10 to ERPIP App B 1 Receipt form encl USI, V Baltimore Gas & Electric Co 83/09/27 Director's Office, Office of Inspection and Enforcement 1p 20814 032 24X Fiche 50-317, 83/10/06, 8310170003

8310270481 Releases public version of revised emergency response plan FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20938 104 24X Fiche 50-317, 83/10/21, 8310270481

--8310270485 Public version of Rev 2 to emergency response plan W/820819 ltr * Baltimore Gas & Electric Co 82/08/31 KANTOR, F EP Licensing Branch 33pp 20938 105 24X Fiche 50-317, 83/10/21, 8310270481

8310310014 Forwards safeguards info Encl withheld (ref 10CFR73 21) JOLLEY, J R Baltimore Gas & Electric Co 83/10/24 CLARK, R A Operating Reactors Branch 3 1p 20951 145 24X Fiche 50-317, 83/10/24, 8310310014

8310310059 Forwards revs to security plan & training & qualification plan Encls withheld (ref 10CFR73 21) BOWMAKER, N J Baltimore Gas & Electric Co 83/10/24 BENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20950 33v 24X Fiche 50-317, 83/10/24, 8310310059

P Operating license stage documents & correspondence

8310310063 FOIA request for documents re const & operation of C-C plants List of info required submitted BELL, N Coalition for Safe Power 83/03/31 Office of Administration 1p 20998 173 24X Fiche 50-000, 83/03/31, 8310310063

8310070176 Forwards Amends B7 & 69 to Licenses DPR-53 & DPR-69 & safety evaluation Amend revises Tech Specs re required containment isolation valve response time JAFFE, D H Operating Reactors Branch 3 83/09/22 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 20680 277 24X Fiche 50-317, 83/09/22, 8310070176

--8310070179 Amends B7 & 69 to Licenses DPR-53 & DPR-69, reflecting mod to valve 1(2)-SV-6529 response closure time MILLER, J R Operating Reactors Branch 3 83/09/22 8pp 20680 279 24X Fiche 50-317, 83/09/22, 8310070176

--8310070180 Safety evaluation supporting Amends B7 & 69 to Licenses DPR-53 & DPR-69 * Office of Nuclear Reactor Regulation, Director 83/09/22 2pp 20680 289 24X Fiche 50-317, 83/09/22, 8310070176

8310040080 Forwards Page 4, Section 11 1 of procurement & storage manual covering Level A & Level C items HOPPA, J L Baltimore Gas & Electric Co 83/09/26 MEYER, G Region 1, Office of Director 2pp 20608 001 24X Fiche 50-317, 83/09/26, 8310040080

8310040353 Forwards "Pressurizer Relief Valve Qualification," & Rev 1 to "Pressurizer Safety Valve Operability Rept," per NUREG-0737, Item 11 D 1 Design load stresses on piping & fittings within allowable limits LUNDVALL, A E Baltimore Gas & Electric Co 83/09/28 MILLER, J R Operating Reactors Branch 3 App 20615 036 24X Fiche 50-317, 83/09/28, 8310040353

--8310040357 Rev 1 to "Pressurizer Safety Valve Operability Rept" * Combustion Engineering, Inc. (EN-248(B) R01 83/09/30 100pp 20615 194 24X Fiche 50-317, 83/09/28, 8310040353

8310130137 Approves 830731 request on behalf of C-E Owners Group for withholding from public disclosure App A to "Response to Questions on RCS Asymmetric Loads Evaluation Program," per 10CFR2 79b CRUTCHFIELD, D Operating Reactors Branch 5 83/10/03 LUNDVALL, A E Baltimore Gas & Electric Co 6pp 20777 065 24X Fiche 50-000, 83/10/03, 8310130137

8310240072 Application for amend to Licenses DPR-53 & DPR-69 revising Surveillance Requirement 4 7 6 1 & replacing Page 3/4 3-26 incorporating mod to measurement range for gaseous & particulate activity monitors Marked-up Tech Specs encl LUNDVALL, A E Baltimore Gas & Electric Co 83/10/12 MILLER, J R Operating Reactors Branch 3 7pp 20801 328 24X Fiche 50-317, 83/10/12, 8310240072

8310310180 Forwards safety evaluation based on review of util response to NUREG-0737, Items 11 K 3 1, "Automatic PORV Isolation" & 11 K 3 2, "Rept on PORVs" Requirements met MILLER, J R Operating Reactors Branch 3 83/10/12 LUNDVALL, A E Baltimore Gas & Electric Co 14pp 21000 037 24X Fiche 50-317, 83/10/12, 8310310180

8310210157 Informs that refund for review of 830427 amend application forthcoming MILLER, W O License Fee Management Branch 83/10/14 LUNDVALL, A E Baltimore Gas & Electric Co 1p 20883 361 24X Fiche 50-317, 83/10/14, 8310210157

8310240134 Provides status of mods required for Generic Ltr 82-2b re inadequate core cooling instrumentation & NUREG-0737, Item 11 F 2 Issues include environ qualification of two ICCI subsystems & installation of core exit thermocouple LUNDVALL, A E Baltimore Gas & Electric Co 83/10/14 MILLER, J R Operating Reactors Branch 3 3pp 20801 166 24X Fiche 50-317, 83/10/14, 8310240134

8310240162 Notifies of resolution of NUREG-0737, TMI Action Plan Item 11 K 2 17, "Potential for Voiding in RCS During Transients" Results of analysis presented in GEN-194 applicable to facilities w/stated exception LUNDVALL, A E Baltimore Gas & Electric Co 83/10/19 MILLER, J R Operating Reactors Branch 3 1p 20881 312 24X Fiche 50-317, 83/10/19, 8310240162

Q Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310200099 Forwards IE Insp Repts 50-317/83-21 & 50-318/83-21 on 830809-0913 & notice of violation STARBSTECKI, R Division of Project & Resident Programs 83/10/03 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 20837 103 24X Fiche 50-317, 83/10/03, 8310200099

DOCKETED ITEMS

153

--B310200107 IE Insp Repts 50-317/83-21 & 50-318/83-21 on B30807-0913 Noncompliance noted failure to follow chemistry procedure ARCHITZEL, R E, TRIMBLE, D C, HIGGINS, J C Region 1, Office of Director B3/09/27 19pp 20837 106 24X Fiche 50-317,83/10/01, B310200079

B310210207 Ack receipt of B30916 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/83-21 & 50-318/83-22 STAROSTECKI, R Division of Project & Resident Programs B3/10/05 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 20855 117 24X Fiche 50-317,83/10/05, B310210107

--B310210210 Responds to NRC ltr re violations noted in IE Insp Repts 50-317/83-22 & 50-318/83-22 Corrective actions training in areas of sys descriptions, staffing, facilities & feedback of plant events upgraded LUNDVALL, A E Baltimore Gas & Electric Co B3/09/16 STAROSTECKI, R Division of Project & Resident Programs 4pp 20855 119 24X Fiche 50-317,83/10/05, B310210207

B308300378 IE Info Notice B3-65, "Surveillance of Flow in RTD Byones Loops Used in Westinghouse Plants " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07, B308300378

B308300752 IE Info Notice B3-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/07 Consolidated Edison Co of New York, Inc 79pp 20892 026 24X Fiche 50-000,83/10/07, B308300752

B308300759 IE Info Notice B3-67, "Emergency Use Respirator Mtl Defect Causes Production of Noxious Gases " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11, B308300759

B308300761 IE Info Notice B3-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 127 24X Fiche 50-000,83/10/11, B308300761

B310310227 Forwards IE Enforcement Conference Repts 50-317/83-22 & 50-318/83-22 on B30902 STAROSTECKI, R Division of Project & Resident Programs B3/10/13 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 20947 224 24X Fiche 50-317,83/10/13, B310310227

--B310310230 IE Enforcement Conference Repts 50-317/83-22 & 50-318/83-22 on B30902 Major areas discussed results of NRC special inrp which identified violation of Tech Spec limiting conditions for operation re emergency diesel generators HIGGINS, J, ARCHITZEL, R, TRIMBLE, D Region 1, Office of Director B3/09/27 5pp 20947 226 24X Fiche 50-317,83/10/13, B310310227

A Periodic operating reports & related correspondence

B310190148 Monthly operating repts for Sept 1983 W/B31014 ltr LOTITO, E M Baltimore Gas & Electric Co B3/10/14 Director's Office, Office of Inspection and Enforcement 12pp 20820 227 24X Fiche 50-317,83/10/14, B310190148

S Reportable occurrences, LERs & related correspondence

B310250221 LER B3-045/017-0 on B30906, discharge dampers to both penetration room exhaust fans failed to open during surveillance testing & dampers declared inoperable Caused by failure of pressure controller W/B30916 ltr PIERINGER, P, RAYNOR, J W, RUSSELL, L B Baltimore Gas & Electric Co B3/09/16 MURLEY, T E Region 1, Office of Director 3pp 20899 085 24X Fiche 50-318,83/09/16, B310250221

B310200004 Updated LER B3-002/03X-1 on B30101, pressure indicator PIC-103 failed low Caused by transmitter leads inadvertently lifted, rendering ERV-402 inoperable Personnel counseled W/B30922 ltr RAYNOR, J W, RUSSELL, L B Baltimore Gas & Electric Co B3/09/22 MURLEY, T E Region 1, Office of Director 2pp 20837 010 24X Fiche 50-318,83/09/22, B310200004

B310200047 LER B3-044/03L-0 on B30823, motor driven auxiliary feedwater flow indication declared inoperable Caused by low zero ref zero ref recalibr W/B30922 ltr PIERINGER, P, RAYNOR, J W, RUSSELL, L B Baltimore Gas & Electric Co B3/09/22 MURLEY, T E Region 1, Office of Director 2pp 20837 006 24X Fiche 50-318,83/09/22, B310200047

B310200154 LER B3-048/03L-0 on B30901, hydrogen recombiner 21 found inoperable Caused by loose hex nut allowing terminals on back of potentiometer to be twisted & pulled Potentiometer replaced W/B30922 ltr PORTER, R, BASSO, L F, RUSSELL, L B Baltimore Gas & Electric Co B3/09/22 MURLEY, T E Region 1, Office of Director 2pp 20836 319 24X Fiche 50-318,83/09/22, B310200154

B310040542 RO oyster samples collected during Aug 1983 from Camp Conoy location showed presence of Ag-110m concentration of 118+/- BpCi/Kg (wet) Monthly percent capacity factors listed Doses considered insignificant consequence to public health FUHRMAN, G R Baltimore Gas & Electric Co B3/09/26 Region 1, Office of Director 2pp 20623 301 24X Fiche 50-317,83/09/26, B310040542

B310250411 LER B3-051/03L-0 on B30901, dose equivalent I-131 determined to be 1.05 uCi/g Caused by small number of leaking fuel pins & change in power level Sampling frequency increased W/B30927 ltr JUNGE, M A, RUSSELL, L B Baltimore Gas & Electric Co B3/09/27 MURLEY, T E Region 1, Office of Director 8pp 20897 219 24X Fiche 50-318,83/09/27, B310250411

B310250287 Updated LER B3-022/03X-1 on B30411, auxiliary feedwater actuation sys channel 2F setpoint for steam generator delta pressure found out of limit Caused by deterioration of high speed switching transistor W/B30929 ltr PIERINGER, P A, BASSO, L F, RUSSELL, L B Baltimore Gas & Electric Co B3/09/29 MURLEY, T E Region 1, Office of Director 2pp 20879 355 24X Fiche 50-318,83/09/29, B310250287

B310250369 LER B3-046/03L-0 on B30906, penetration room exhaust Fan 21 would not start on CIS signal while performing Surveillance Test STP-0-22 Caused by malfunctioning CIS logic module & associated power relay W/B30929 ltr LOHR, J, BASSO, L F, RUSSELL, L B Baltimore Gas & Electric Co B3/09/29 MURLEY, T E Region 1, Office of Director 2pp 20898 084 24X Fiche 50-318,83/09/29, B310250369

B310070301 Potential Part 21 rept re underrange characteristic of Model N-El10M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERGERIAN, M J Foxboro Corp B3/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X Fiche 50-000,83/09/30, B310070301

B310250443 LER B3-049/03L-0 on B30909, pin hole leak discovered in reactor coolant charging line weld at reducing insert on tee in discharge header Caused by vibration of line Repair weld completed W/B31007 ltr PIERINGER, P, UNKLE, T J, RUSSELL, L B Baltimore Gas & Electric Co B3/10/07 MURLEY, T E Region 1, Office of Director 3pp 20897 033 24X Fiche 50-318,83/10/07, B310250443

B310250599 LER B3-053/03L-0 on B30914, control power fuse for starter cabinet blew, causing containment cooler 21 to trip Caused by Rowan 2084-EPRI-1120 indicating light socket short circuit Socket replaced W/B31007 ltr JUNGE, M A, BASSO, L F, RUSSELL, L B Baltimore Gas & Electric Co B3/10/07 MURLEY, T E Region 1, Office of Director 2pp 20900 310 24X Fiche 50-318,83/10/07, B310250599

B310180467 PNO-1-B3-107 on B31011, trip from full power occurred when main feedwater pump 22 tripped Containment sump pumping frequency increased due to stopping & restarting of reactor coolant pump Plant cooldown began B31012 to repair seal TRIMBLE, D, SWETLAND, P Region 1, Office of Director B3/10/12 1p 20802 031 24X Fiche 50-318,83/10/12, B310180467

B310240269 Responds to B30906 memo re AEUD/T314, "Improper Size of Inlet Piping to Primary Safety Valves at Millstone 2 & Calvert Cliffs 1 & 2 " Flow limiting devices for code safety valves 1 7/8-inch bore diameter discussed EISENHUT, D O Division of Licensing B3/10/18 THOMPSON, H L Division of Human Factors Safety 1p 20907 338 24X Fiche 50-000,83/10/18, B310240269

DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B310200218 Forwards IE Insp Repts 50-289/83-18 & 50-320/83-10 on B30622-24 & 0711-20 & notice of violation MARTIN, T T Region 1, Office of Director B3/09/14 KANGA, D K General Public Utilities - CPU Service Corp 2pp 20830 123 24X Fiche 50-289,83/09/14, B310200218

DOCKETED ITEMS

--B310200270 IE Insp Repts 50-289/83-18 & 50-320/83-10 on B30622-24 & 0711-20 Noncompliance noted failure to perform quarterly fire brigade training
PALLINO, R Region 1, Office of Director 83/09/06 19pp
20830 126 24X Fiche 50-289, 83/09/14, B310200270

B310170028 Forwards GPU vs B&W lawsuit review SER input for emergency planning Documents do not contain info w/potential to alter conclusions on restart certification issue
MATTHEWS, D B Emergency Preparedness Branch 83/09/19
RUSSELL, W T GPU/B&W Lawsuit Review Team 5pp 2079u 343 24X
Fiche 50-289, 83/09/19, B310170028

B310110102 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/05 Document
Management Branch 1p 20687 321 24X Fiche 50-320, 83/10/05, B310110102

--B310110106 Public version of Rev 1 to Emergency Plan Implementing Procedure 1054 22, "Tornado/High Winds"
KANGA, B K General Public Utilities - GPU Service Corp 83/09/19
7pp 20687 322 24X Fiche 50-320, 83/10/05, B310110102

B310200437 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/17 Document
Management Branch 1p 20859 295 24X Fiche 50-320, 83/10/17, B310200437

--B310200443 Public version of revised emergency plan implementing procedures, including Procedures 1054 10 re onsite/offsite radiological monitoring & 1054 30 re activation of environment assessment command ctr
BRADY, J A, STANOE, S J General Public Utilities - GPU Service Corp 83/09/23 36pp 20859 296 24X Fiche 50-320, 83/10/17, B310200437

B310270393 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/21 Document
Management Branch 1p 20943 089 24X Fiche 50-289, 83/10/21, B310270393

--B310270396 Public version of Rev 7 to Emergency Plan Implementing Procedure 1004 6, "Unit 2 Onsite Emergency Response Directory" & Rev 2 to 1004 32, "Activation of Annex to Nearsite Emergency Operations Facility (Crawford Station)"
BRADY, J A, STANOE, S J General Public Utilities - GPU Service Corp 83/10/10 21pp 20943 090 24X Fiche 50-289, 83/10/21, B310270393

B310310161 Ack receipt of B30902 & 09 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-320/83-08
Responsible technical reviewer process implemented B31010 as independent review of administrative controls
STAROSTECKI, R Division of Project & Resident Programs 83/10/25
KANGA, B K General Public Utilities - GPU Service Corp 2pp 20959 050 24X Fiche 50-320, 83/10/25, B310310161

--B310310164 Responds to NRC B30803 ltr re violations noted in IE Insp Rept 50-320/83-08 Corrective actions administrative procedures modified so only one temporary change notice may be effective on any given procedure
KANGA, B K General Public Utilities - GPU Service Corp 83/09/02
MURLEY, T E Region 1, Office of Director 4pp 20959 052 24X
Fiche 50-320, 83/10/25, B310310161

0 Adjudicatory correspondence

B310110632 Expresses appreciation for meeting to review GPU vs B&W lawsuit document record
RAMSON, R J Office of the Executive Legal Director 83/07/22
WISE, R F Davis, Polk & Hardwell 1p 20714 343 24X
Fiche 50-289, 83/07/22, B310110632

B310140302 Forwards listing of lawsuit documents by sub area significant to GPU vs B&W record to support position to reopen restart hearing Evaluation of documents contained in SER requested
EIGENHUT, D O Division of Licensing 83/08/15 MATTHEWS, R J
Division of Systems Integration (post B11005) THOMPSON, H C
TAYLOR, J L Division of Human Factors Safety 22pp 20793 360
24X Fiche 50-289, 83/08/15, B310140302

B310170012 Forwards NRC produced transcripts of RH Keaton taped interviews Tape entry into document control sys as B&W Exhibits 347a-347b requested w/o encl
RUSSELL, W T GPU/B&W Lawsuit Review Team 83/08/24 SCATTUINI, L
SOUVER, J Public Document Branch BLUME, M Office of the General Counsel 1p 20798 361 24X Fiche 50-289, 83/08/24, B310170012

B310030419 Forwards draft NUREG-1020, Vol 1, "GPU vs B&W lawsuit (Review & Effect on TMI-1)" Portions of Category 10 withheld since info pertains to ongoing investigation
CHILK, S J Office of the Secretary of the Commission 83/09/30
Atomic Safety and Licensing Board Panel 111pp 2060u 103 24X
Fiche 50-289, 83/09/30, B310030419

B310130028 Notice of NRR B30919 issuance of amend to 790720 & B06P11 orders & motion to conform proposed Tech Specs re changer to administrative controls Certificate of Svc encl
HILCOVE, M N Hearing Branch 2 83/10/11 6pp 20725 077 24X
Fiche 50-320, 83/10/11, B310130028

B310210200 Response to NRC B31011 motion to conform proposed Tech Specs in accordance w/amend to B00211 order Motion not opposed
Certificate of Svc encl
TROWBRIDGE, G F Metropolitan Edison Co TROWBRIDGE, G F Shaw
Pittman, Patts & Trowbridge 83/10/19 Atomic Safety and
Licensing Board Panel 5pp 20896 081 24X Fiche 50-320, 83/10/19, B310210200

B310250048 Memorandum & order granting NRC motion to conform proposed Tech Specs w/030919 amend of B00211 order
WOLF, J F, PARIS, D H, SHON, F J Atomic Safety and Licensing Board Panel 83/10/20 Office of the Executive Legal Director 3pp 20894 151 24X Fiche 50-320, 83/10/20, B310250048

H General correspondence

B310040483 Expresses futility of NRC B30927 meeting in Middletown, PA re polar crane safety Few positive or enlightening results gained from meetings
LEE, J Affiliation Unknown 83/09/27 PALLADINO, N J, GILINIKY, V, ROBFRTS, T Atomic Safety and Licensing Board Panel 2pp 20623 123 24X Fiche 50-320, 83/09/27, B310040483

B310120171 Forwards Resolution 70-83 calling for decontamination & plant closing
MINNICH, J E, HETRICK, N P, HOCHENDONER, L Dauphin County, PA
83/10/04 PALLADINO, N J Commissioners 2pp 20696 003 24X
Fiche 50-320, 83/10/04, B310120171

B310240159 Comments on B30927 public meeting in Middletown, PA re TMI-1 restart & GPU vs B&W lawsuit Meeting completely dominated by GPU/Bechtel
OSBORNE, M Affiliation Unknown 83/10/14 DENTON, H R NRC - No Detailed Affiliation Given 2pp 20881 292 24X
Fiche 50-289, 83/10/14, B310240159

P Operating license stage documents & correspondence

B310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR
CONNER, L Affiliation Unknown 83/05/02 NRC - No Detailed Affiliation Given 1p 21004 270 24X Fiche 50-000, 83/05/02, B310310017

B310180537 Forwards License Amend Request 3 requesting deletion of Section 2 E(3) of License DPR-73 re reserve tankage requirements
ARNOLD, R C General Public Utilities - GPU Service Corp 83/05/27
SHYDER, D J TMI Program Office 1p 20799 095 24X
Fiche 50-320, 83/05/27, B310180537

--B310180548 License Amend Request 3, requesting deletion of Section 2 E(3) of License DPR-73 re reserve tankage requirements
Class III fee encl w/Certificate of Svc
ARNOLD, R C General Public Utilities - GPU Service Corp
ARNOLD, R C Metropolitan Edison Co ARNOLD, R C Jersey Central Power & Light Co 83/05/27 5pp 20799 096 24X
Fiche 50-320, 83/05/27, B310180537

B310270035 FOIA request for all documents containing info re emission of radioactive iodine & other fission products during accident at facility
ROGERS, H A Affiliation Unknown 83/06/07 Office of the General Counsel 1p 20940 344 24X Fiche 50-320, 83/06/07, B310270035

B310140296 Forwards TMI-1 GPU/B&W lawsuit review organization chart Overtime for personnel connected w/GPU vs B&W lawsuit authorized as noted
RUSSELL, W T Systematic Evaluation Program Branch 83/06/28 NRC - No Detailed Affiliation Given 1p 20794 095 24X
Fiche 50-289, 83/06/28, B310140296

B310140294 Requests estimate of time needed to review documents re TMI-2 accident & to prepare lists info needed to respond to Congressman Udall request
CHILK, S J Office of the Secretary of the Commission 83/06/30
DICKS, W J Office of the Executive Director for Operations 1p 20794 078 24X Fiche 50-289, 83/06/30, B310140294

DOCKETED ITEMS

155

8310270040 Responds to FOIA request for documents containing info re emission of radioactive iodine & other fission products during reactor accidents forwards App A documents App B documents can be purchased from NRC
FELTON, J M Division of Rules and Records 83/07/06 ROGERS, H A Affiliation Unknown 4pp 20940 345 24X Fiche 50-320, 83/07/06, 8310270040

--8310270041 Forwards draft "Comparison of Iodine Behavior During TMI-2 Accident W/Predictions Based on WASI-1400 Methodology"
POSTMA, A K Benton City Technology 82/04/13 PASSEDAG, H I Accident Evaluation Branch 4pp 20940 349 24X Fiche 50-320, 83/07/06, 8310270040

--8310270044 Draft "Comparison of Iodine Behavior During TMI-2 Accident W/Predictions Based on WASI-1400 Methodology"
POSTMA, A K Benton City Technology 83/04/13 40pp 20940 350 24X Fiche 50-320, 83/07/06, 8310270040

8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which repts are unavailable
FELTON, J M Division of Rules and Records 83/07/06 CONNOR, G T Affiliation Unknown 1p 21004 271 24X Fiche 50-000, 83/07/06, 8310310031

8310310114 Agrees to provide NRC w/access to computerized record of GPU vs B&W trial record & deposition transcripts to check completeness of NRC independent review of trial documents
ARNOLD, R C General Public Utilities - GPU Service Corp 83/07/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20777 073 24X Fiche 50-289, 83/07/08, 8310310114

8310310342 Identifies NRC div responsibilities for reviewing documents re GPU/B&W lawsuit, per Commission 830628 directive Review due by 830901 Overview of general scope & objectives of lawsuit review task encl
EISENHUT, D G Division of Licensing 83/07/08 MATTHEW, R J Division of Systems Integration (post 811005) THOMPSON, H L Division of Human Factors Safety VOLLMER, R H Division of Engineering 52pp 20768 280 24X Fiche 50-289, 83/07/08, 8310310342

8310120058 Requests individual to manage & control access to hard copies of documents for GPU vs B&W lawsuit review
RUSSELL, W T NRC - No Detailed Affiliation Given 83/07/22 DESAH, W J Division of Technical Information & Document Control 2pp 20749 352 24X Fiche 50-289, 83/07/22, 8310120058

8310130175 Forwards summary of 830721 meeting re GPU vs B&W lawsuit documents Comments on meeting summary welcomed
RAYSON, R J NRC - No Detailed Affiliation Given 83/07/26 WARTZ, H E Davis, Polk & Wardwell 1p 20777 171 24X Fiche 50-289, 83/07/26, 8310130175

--8310130186 Summary of 830721 meeting w/Davis, Polk & Wardwell in New York, NY re info relevant to NRC review of GPU vs B&W lawsuit record or to reactor safety in general
RUSSELL, W T NRC - No Detailed Affiliation Given 83/07/26 EISENHUT, D G Division of Licensing 3pp 20777 172 24X Fiche 50-289, 83/07/26, 8310130175

8310170043 Summary of 830721 meeting w/B&W counsel re review of GPU vs B&W lawsuit record & general reactor safety Operator reliance & responsibility for procedure writing identified as possible generic safety issue
RUSSELL, W T GPU/B&W Lawsuit Review Team 83/07/26 EISENHUT, D G Division of Licensing 3pp 20812 155 24X Fiche 50-289, 83/07/26, 8310170043

8310140291 Forwards final installment of review packages & updates list matching GPU vs B&W lawsuit documents w/responsible divs Draft input to rept requested within 30 days w/o encls
EISENHUT, D G Division of Licensing 83/08/02 MATTHEW, R J Division of Systems Integration (post 811005) THOMPSON, H L Division of Human Factors Safety TAYLOR, J M Division of QA Safeguards & Inspection Programs (Post 830103) 2pp 20794 108 24X Fiche 50-289, 83/08/02, 8310140291

8310140292 Comments on Operating Reactors Assessment Branch responsibilities & participation in GPU vs B&W lawsuit review table for disposition of operating experience issues encl
MIRAGLIA, F Assistant Director for Safety Assessment 83/08/05 RUSSELL, W T GPU/B&W Lawsuit Review Team 5pp 20794 100 24X Fiche 50-289, 83/08/05, 8310140292

8310170717 Memorializes 830804 telcon w/H Myers of Congressman Udall staff re Chairman Palladino 830803 ltr on significant info in GPU vs B&W record
RUSSELL, W T GPU/B&W Lawsuit Review Team 83/08/09 DENTON, H R, CASE, E G Office of Nuclear Reactor Regulation, Director EISENHUT, D G Division of Licensing 1p 20798 116 24X Fiche 50-289, 83/08/09, 8310170717

8310170751 Informs that D Morrisseau will be acting for F Allenspach as leader for GPU vs B&W lawsuit review
BODHER, H R Licensee Qualifications Branch 83/08/12 THOMPSON, H L Division of Human Factors Safety 1p 20798 219 24X Fiche 50-289, 83/08/12, 8310170751

8310130108 Forwards list of specific exhibits requested on 830812 to be used in GPU vs B&W lawsuit review
RUSSELL, W T Division of Licensing 83/08/16 LLOYD, R D Debevoise & Liberman LLOYD, R D General Public Utilities - GPU Service Corp 2pp 20777 071 24X Fiche 50-289, 83/08/16, 8310130108

8310170014 Forwards revised listing of sub area contents for GPU vs B&W lawsuit review, per 830727 & 0805 & 12 ltrs
RUSSELL, W T GPU/B&W Lawsuit Review Team 83/08/18 MORRISSEAU, D, PICKETT, D, MAASS, W NRC - No Detailed Affiliation Given 14pp 20813 285 24X Fiche 50-289, 83/08/18, 8310170014

8310170747 Identifies GPU vs B&W lawsuit documents not held by NRC & recommends no further action to obtain documents
CAPRA, R A GPU/B&W Lawsuit Review Team 83/08/29 RUSSELL, W T GPU/B&W Lawsuit Review Team 34pp 20796 318 24X Fiche 50-289, 83/08/29, 8310170747

8310170022 Advises of receipt of legible B&W lawsuit documents requested of B&W in NRC 830816 ltr Documents received listed
CAPRA, R A GPU/B&W Lawsuit Review Team 83/09/08 NRC - No Detailed Affiliation Given 1p 20798 357 24X Fiche 50-289, 83/09/08, 8310170022

8310170032 Requests assistance in arranging resources for production & publication of NRC evaluation of GPU vs B&W lawsuit review & impact on TMI-1 restart (NURFO-1020)
RUSSELL, W T GPU/B&W Lawsuit Review Team 83/09/08 DESAH, W J Division of Technical Information & Document Control 3pp 20798 334 24X Fiche 50-289, 83/09/08, 8310170032

8310170001 Forwards 830908 memo requesting support for NRC rept on GPU vs B&W lawsuit review Arrangements should be made to accommodate requested schedule
STEELE, H L Division of Technical Information & Document Control 83/09/09 MCVLACH, H D Division of Technical Information & Document Control JOHANSEN, J Cross Branch 1p 20814 048 24X Fiche 50-289, 83/09/09, 8310170001

--8310170002 Requests assistance in arranging resources for production & publication of NRC evaluation of GPU vs B&W lawsuit review & impact on restart of TMI-1 (NURFO-1020) Flow chart w/projected milestones encl
RUSSELL, W T GPU/B&W Lawsuit Review Team 83/09/08 DESAH, W J Division of Technical Information & Document Control 3pp 20814 049 24X Fiche 50-289, 83/09/09, 8310170001

8310200032 Responds to FOIA request for correspondence between Chairman Palladino & DDJ re investigation of alleged falsification of RCS leak rate tests Forwards App A documents Portions of requested documents withheld (ref FOIA Exemption 7)
FELTON, J M Division of Rules and Records 83/09/15 VOIOT, H H LeDeouff, Lamb, Leiby & MacRae 2pp 20844 236 24X Fiche 50-289, 83/09/15, 8310200032

--8310200038 Ack receipt of 830517 ltr re DDJ investigation into allegations re possible criminal wrongdoing Separate NRC investigation will be initiated
PALLADINO, N J Commissioners 83/05/27 JENSON, D L Justice, Dept of 1p 20844 240 24X Fiche 50-289, 83/09/15, 8310200032

--8310200044 Requests that DDJ investigation on allegations re falsification of RCS leak rate tests be completed by 830515 Response within 2 wks requested Info partially deleted
PALLADINO, N J Commissioners 83/04/11 SMITH, W F Justice, Dept of 2pp 20844 241 24X Fiche 50-289, 83/09/15, 8310200032

--8310200048 Responds to 830411 ltr re TMI-1 restart & DDJ investigation into allegations re mgt competence Investigation being pursued diligently but will not be completed by requested date Info partially deleted
JENSON, D L Justice, Dept of 83/05/17 PALLADINO, N J Commissioners 4pp 20844 243 24X Fiche 50-289, 83/09/15, 8310200032

DOCKETED ITEMS

- 8310170018 Forwards draft NUREG-1020, "GPU vs B&W Lawsuit Review & Effect on TMI-1." Draft does not include Chapter 10 re mgt competence/integrity Comments or concurrence requested w/o encl.
RUSSELL, W T GPU/B&W Lawsuit Review Team 83/09/19 EISENHUT, D G Division of Licensing MATTSO, R J Division of Systems Integration (post 811005) THOMPSON, H L Division of Human Factors Safety 2pp 20798 358 24X Fiche 50-289, 83/09/19, 8310170018
- 8310280169 Appeals partial denial of FOIA request for correspondence between Chairman Palladino & DOJ re investigation of alleged falsification of RCS leak rate tests
VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 83/09/19 CHILK, S J Office of the Secretary of the Commission 2pp 20965 055 24X Fiche 50-289, 83/09/19, 8310280169
- 8310310097 Responds to FOIA request that 16 SECYs be placed in PDR Forwards App A documents SECY-82-466 withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/09/19 SHOLLY, S C Union of Concerned Scientists 3pp 21000 146 24X Fiche 50-320, 83/09/19, 8310310097
- 8204070171 Advises of current status of studies assessing potential technical, regulatory & socioeconomic impacts of proposed alternatives for accident water disposition
* Office of the Executive Director for Operations SECY-82-121 82/03/18 13pp 21000 147 24X Fiche 50-320, 83/09/19, 8310310097
- 8310170025 Forwards final draft Chapter 10 to NUREG-1020 entitled "Mgt Competence/Integrity." Changes, comments or concurrence requested by 830922 w/o encl.
EISENHUT, D G Division of Licensing 83/09/20 MATTSO, R J Division of Systems Integration (post 811005) THOMPSON, H L Division of Human Factors Safety TAYLOR, J M Division of QA, Safeguards & Inspection Programs (Post 831013) 2pp 20770 355 24X Fiche 50-289, 83/09/20, 8310170025
- 8310110556 Forwards marked-up copy of draft NUREG-1020, "GPU vs B&W Lawsuit Review & Effects on TMI-1." w/o encl.
THOMPSON, H L Division of Human Factors Safety 83/09/22 EISENHUT, D G Division of Licensing 1p 20777 209 24X Fiche 50-289, 83/09/22, 8310110556
- 8310110630 Forwards comments on NUREG-1020 re GPU vs B&W lawsuit review & effects on TMI-1 Errors in App B should be corrected to reflect findings concerning relevance & materiality of lawsuit documents
MATTSO, R J Division of Systems Integration (post 811005) 83/09/22 EISENHUT, D G Division of Licensing 3pp 20714 214 24X Fiche 50-289, 83/09/22, 8310110630
- 8310120057 Forwards IE/Region 1 comments re Subj Area 5 of NUREG-1020 "GPU vs B&W Lawsuit Review & Effect on TMI-1," constituting concurrence w/NUREG
TAYLOR, J M Division of QA, Safeguards & Inspection Programs (Post 831013) 83/09/23 EISENHUT, D G Division of Licensing 1p 20749 354 24X Fiche 50-289, 83/09/23, 8310120057
- 8310130138 Forwards Rev 4 to Procedure 13587-2-L01-100, "Design Criteria Documents," containing changes committed to in 830525 ltr w/exception that Bechtel nuclear QA manual will still be referenced
KANGA, B K General Public Utilities - GPU Service Corp 83/09/23 SNYDER, B J TMI Program Office 1p 20726 351 24X Fiche 50-320, 83/09/23, 8310130138
- 8310130141 Rev 4 to Procedure 13587-2-L01-100, "Design Criteria Documents."
* General Public Utilities - GPU Service Corp 83/08/11 58pp 20726 352 24X Fiche 50-320, 83/09/23, 8310130138
- 8310130155 Discusses review of addl GPU vs B&W lawsuit documents. No changes to original SER necessary
MATTSO, R J Division of Safety Technology 83/09/23 EISENHUT, D G Division of Licensing 2pp 20777 178 24X Fiche 50-289, 83/09/23, 8310130155
- 8310120054 Concurs in draft NUREG-1020 "GPU vs B&W Lawsuit Review & Effect on TMI-1."
VOLLMER, R H Division of Engineering 83/09/26 RUSSELL, W T NRC - No Detailed Affiliation Given 1p 20749 355 24X Fiche 50-289, 83/09/26, 8310120054
- 8310120051 Advises that comments re NUREG-1020 "GPU vs B&W Lawsuit Review & Effect on TMI-1," were faxed to R Capra on 830920
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/27 EISENHUT, D G Division of Licensing 1p 20715 327, 24X Fiche 50-289, 83/09/27, 8310120051
- 8310110531 Requests addl info on polar crane refurbishment Util should perform review of polar crane mads & testing prior to routine operational use
BARRETT, L H TMI Program Office 83/09/28 KANGA, B K General Public Utilities - GPU Service Corp 3p 20704 348 24X Fiche 50-320, 83/09/28, 8310110531
- 8310120060 Forwards NUREG-1020 "GPU vs B&W lawsuit & Effect on TMI-1." Distribution of Category 10 section "Mgt Competence/Integrity" should be limited pending life of investigations completion of investigation
DIRCKS, W J Office of the Executive Director for Operations 83/09/28 PALLADINO, N J Commissioners 2p 20715 362 24X Fiche 50-289, 83/09/28, 8310120060
- 8310030500 Forwards safety evaluation for first pass detensioning & removal of up to five studs in reactor vessel. First pass detensioning can be accomplished w/o undue risk to public. Fee for evaluation of safety issue to be provided
KANGA, B K General Public Utilities - GPU Service Corp 83/09/29 SNYDER, B J TMI Program Office 3pp 20601 197 24X Fiche 50-320, 83/09/29, 8310030500
- 8310130005 Forwards for review & approval, SER re ongoing containment bldg decontamination & dose reduction activities. Evaluation addresses in-containment decontamination & dose reduction activities for remainder of 1993 & all of 1994
KANGA, B K General Public Utilities - GPU Service Corp 83/09/29 SNYDER, B J TMI Program Office 21pp 20725 214 24X Fiche 50-320, 83/09/29, 8310130005
- 8310050055 Recovery Operations Plan Change Request 2P, submitted in conjunction w/tech Spec Change Request 43
KANGA, B K General Public Utilities - GPU Service Corp 83/09/30 BARRETT, L H TMI Program Office 7pp 20628 310 24X Fiche 50-320, 83/09/30, 8310050055
- 8310050061 Proposed Tech Specs 4 1.4 3 f 4 7 re recovery operations plan
* General Public Utilities - GPU Service Corp 83/09/30 24pp 20628 317 24X Fiche 50-320, 83/09/30, 8310050061
- 8310130082 Requests extension until funding for 1994 established to allow time to prepare appropriate plan & schedule for ALARA exception to Tech Spec surveillance Delay due to uncertainty of funding project in 1994
KANGA, B K General Public Utilities - GPU Service Corp 83/09/30 SNYDER, B J TMI Program Office 2pp 20725 061 24X Fiche 50-320, 83/09/30, 8310130082
- 8310130088 Forwards application for amend to License DPR-73, consisting of Tech Specs Change Request 43, deleting sys no longer necessary for present/future plant conditions & refs to occupational exposure considerations
ARNOLD, R C General Public Utilities - GPU Service Corp 83/09/30 SNYDER, B J TMI Program Office 1p 20726 177 24X Fiche 50-320, 83/09/30, 8310130088
- 8310130093 Application for amend to License DPR-73, consisting of Tech Spec Change Request 43, deleting sys no longer necessary for present/future plant conditions & refs to occupational exposure considerations
* General Public Utilities - GPU Service Corp 83/09/30 2pp 20726 178 24X Fiche 50-320, 83/09/30, 8310130093
- 8310130099 Proposed Tech Spec re deletion of sys no longer necessary for present/future plant conditions & rev to recovery operations plan deleting refs to occupational exposure
* General Public Utilities - GPU Service Corp 83/09/30 27pp 20726 180 24X Fiche 50-320, 83/09/30, 8310130099
- 8310190245 Advises that Generic Ltr 81-38, "Storage of Low Level Radwastes at Power Plant Reactor Sites," applicable to facility Response due within 30 days advising how util meets guidance in generic ltr
BARRETT, L H TMI Program Office 83/09/30 KANGA, B K General Public Utilities - GPU Service Corp 2pp 20838 085 24X Fiche 50-320, 83/09/30, 8310190245
- 8310130064 Forwards Fee for first pass stud detensioning SER, per 8209/4 ltr Determination of fee based on single safety issue
KANGA, B K General Public Utilities - GPU Service Corp 83/10/04 SNYDER, B J TMI Program Office 1p 20726 293 24X Fiche 50-320, 83/10/04, 8310130064
- 8310180046 Forwards info on calibr of Dillon load cells 5/N 443 & 1101 to be used in polar crane load test, per 830928 discussion. Load cell data accurate
POINDEXTER, T C TMI Program Office 83/10/04 MORRIS, A L Lancaster, PA App 20825 026 24X Fiche 50-320, 83/10/04, 8310180046

DOCKETED ITEMS

157

8310140025 Resigns as chairman of Advisory Panel for Decontamination of TMI-2 Facility should be closed Public deserves faster cleanup
MINICH, J E Advisory Council for Decontamination of TMI Unit 2
83/10/05 PALLADINO, N J Commissioner 1p 20768 077 24X
Fiche 50-320, 83/10/05, 8310140025

8310170695 Staff requirements memo re 831006 briefing on results of GPU vs B&W trial matl & other uncontested matters re TMI-1
restart Commission made no requests & took no action
CHILK, S J Office of the Secretary of the Commission 83/10/06
Office of the Secretary of the Commission 1p 20798 158 24X
Fiche 50-287, 83/10/06, 8310170695

8310130408 Staff requirements memo re 830716 periodic meeting in Washington, DC w/Advisory Panel on decontamination of TMI-2
CHILK, S J Office of the Secretary of the Commission 83/10/07
DIRCKS, W J Office of the Executive Director for Operations
FOUCHARD, J J Office of Public Affairs FRALEY, R F ACRS -
Advisory Committee on Reactor Safety Safeguards 2pp 20769 348 24X
Fiche 50-320, 83/10/07, 8310130408

8310180092 Ack receipt of 830915 request for info concerning open issues re mgt integrity identified in 830719 & 0715 memos to Commission NRC evaluation of open issues proceeding w/
exception of GPU vs B&W lawsuit record
DIRCKS, W J Office of the Executive Director for Operations
83/10/07 DIECKAMP, H General Public Utilities - GPU Service Corp
1p 20824 125 24X Fiche 50-289, 83/10/07, 8310180092

8310180099 Requests NRC provide identification & evaluation of specific concerns remaining or developed as result of evaluation of open issues Also requests all related recent insp repts & basis for concern in other areas
DIECKAMP, H General Public Utilities - GPU Service Corp
83/09/15 DIRCKS, W J Office of the Executive Director for Operations 4pp 20824 124 24X Fiche 50-287, 83/10/07, 8310180099

8310170639 Forwards Rev 3 to "SIR for Removal of TMI-2 Reactor Vessel Head," per Tech Spec Change Request 41
KANQA, B K General Public Utilities - GPU Service Corp 83/10/11
SHYDER, B J TMI Program Office 1p 20790 139 24X
Fiche 50-320, 83/10/11, 8310170639

8310170647 Rev 3 to "SER for Removal of TMI-2 Reactor Vessel Head"
* General Public Utilities - GPU Service Corp 15737-2-80/-10P
R03 83/10/31 130pp 20790 140 24X Fiche 50-320, 83/10/11, 8310170647

8310180200 Submits partial response to request for info re polar crane refurbishment No matl or design problems found Mods, testing & refurbishment under careful scrutiny Supplemental info forthcoming
KANQA, B K General Public Utilities - GPU Service Corp 83/10/11
BARRETT, L H TMI Program Office 3pp 20809 043 24X
Fiche 50-320, 83/10/11, 8310180200

8310180347 Comments on NUREG-1020 re GPU vs B&W lawsuit review NRC did not make reasonable technical judgments, leaving issues that should have been resolved re mgt integrity as issues potentially involving integrity
DIECKAMP, H General Public Utilities - GPU Service Corp 83/10/14
PALLADINO, N J, ABSELSTINE, J K, BERNHALL, F Commissioners 35pp 20804 301 24X Fiche 50-289, 83/10/14, 8310180347

8310280172 Responds to appeal re partial denial of FOIA request for correspondence between Chairman Palladino & DOJ re investigation of alleged falsification of RCS leak rate tests Info partially withheld (ref FOIA Exemption 3)
CHILK, S J Office of the Secretary of the Commission 83/10/14
VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 2pp 20765 057 24X
Fiche 50-289, 83/10/14, 8310280172

8310280179 Comments on questions raised in 830517 ltr to Chairman Palladino re communication between agencies DOJ should commit to completion date for investigation Supporting documentation encl
CUMMINGS, J J Office of Inspector & Auditor 83/05/31
JENSEN, D L Justice, Dept of App 20765 064 24X
Fiche 50-320, 83/10/14, 8310280172

8310240256 Advises that Rev 2 to QA plan acceptable for implementation, subj to completion of enumerated items
SHYDER, B J TMI Program Office 83/10/17 KANQA, B K General Public Utilities - GPU Service Corp 3pp 20707 35/ 24X
Fiche 50-320, 83/10/17, 8310240256

8310310213 Responds to 830914 ltr requesting NRC to stop lift of reactor vessel head Once polar crane qualified, reactor vessel head lift would not occur until util safety evaluation reviewed & approved by NRC FR notice encl
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/10/19 LEWIS, M I Affiliation Unknown 1p 20765 279 24X
Fiche 50-320, 83/10/19, 8310310213

8310310214 Notice of receipt of ML Lewis request for action under 10CFR2 206 to stop lifting of reactor vessel head
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/10/19 2pp 20765 300 24X Fiche 50-320, 83/10/19, 8310310213

8310280102 Updates status of Items 2 & 3 in util 831011 ltr re polar crane refurbishment ECMs approved & available for insp Test working group approval of polar crane no-load test formally documented
KANQA, B K General Public Utilities - GPU Service Corp 83/10/25
BARRETT, L H TMI Program Office 1p 20935 204 24X
Fiche 50-320, 83/10/25, 8310280102

0 Inspection reports, IE Bulletins & correspondence

8310200218 Forwards IE Insp Repts 50-287/83-18 & 50-320/83-10 on 830622-24 & 0711-20 & notice of violation
MARTIN, T I Region 1, Office of Director 83/09/14 KANQA, B K General Public Utilities - GPU Service Corp 2pp 20830 123 24X
Fiche 50-289, 83/09/14, 8310200218

8310200270 IE Insp Repts 50-289/83-18 & 50-320/83-10 on 830622-24 & 0711-20 Noncompliance noted failure to perform quarterly fire brigade training
PADLINO, R, PLISCO, L, ANDERSON, C J Region 1, Office of Director
83/09/06 19pp 20830 126 24X Fiche 50-289, 83/09/14, 8310200218

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20734 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310140132 Forwards IE Insp Rept 50-320/83-12 on 830809-0905 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/09/27
KANQA, B K General Public Utilities - GPU Service Corp 2pp 20763 001 24X Fiche 50-320, 83/09/27, 8310140132

8310140134 Notice of violation from insp on 830809-0905
* Region 1, Office of Director 83/09/27 1p 20763 003 24X
Fiche 50-320, 83/09/27, 8310140132

8310140170 IE Insp Rept 50-320/83-12 on 830809-0905 Noncompliance noted failure to provide indoctrination & training program for personnel performing safety-related activities & failure to maintain & implement procedures per Tech Spec 6 B 1
WIERE, J, BARR, K, MOSLAK, T Region 1, Office of Director
83/09/27 10pp 20763 004 24X Fiche 50-320, 83/09/27, 8310140132

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/a 10CFR50 59 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

DOCKETED ITEMS

8310140028 Forwards Ofc of Investigations rept. "TMI Nuclear Generating Unit 2 Allegations re Safety-Related Muds/OA Procedures & Use of Polar Crane. Prompt attention should be given to rig controls over Bechtel cleanup activities W/d encl. PALLADINO, N J. Commissioners. 83/10/07. KUHN, S. W. General Public Utilities - GPU Service Corp. 2pp. 20767 347 24X Fiche 50-320, 83/10/07, 8310140028

8310200454 Comments on results of TMI-2 investigation on alleged procedural & managerial issues Rept comprehensively addresses technical issues Commission should conduct special team insp to provide overall assessment of OA program. CALLAGHER, E J. Office of Policy Evaluations. 83/10/07. JAYNE, B D. Office of Investigation. 1p. 20859 341 24X Fiche 50-320, 83/10/07, 8310200454

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases." Svc list encl. JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/10/11. Consolidated Edison Co. of New York, Inc. 117pp. 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders." Svc list encl. JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/10/11. Consolidated Edison Co. of New York, Inc. 120pp. 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310310161 Ack receipt of 830902 & 09 ltrs informing NRC of steps taken to correct violations noted in IL Insp Rept 50-320/83-08. Responsible technical reviewer process implemented 831010 as independent review of administrative controls. STARDYCKI, R. Division of Project & Resident Programs. 83/10/25. KANGA, B K. General Public Utilities - GPU Service Corp. 2pp. 20959 050 24X Fiche 50-320, 83/10/25, 8310310161

--8310310164 Responds to NRC 830603 ltr re violations noted in IL Insp Rept 50-320/83-08. Corrective actions administrative procedures modified so only one temporary change notice may be effective on any given procedure. KANGA, B K. General Public Utilities - GPU Service Corp. 83/09/05. MURLEY, T E. Region I, Office of Director. 4pp. 20959 052 24X Fiche 50-320, 83/10/25, 8310310164

R Periodic operating reports & related correspondence

8310050146 Forwards TMI Program Ofc weekly status rept for wk of 830820-0902. BARRETT, L H. TMI Program Office. 83/09/02. DENTON, H R. Office of Nuclear Reactor Regulation, Director. SNYDER, B J. TMI Program Office. 10p. 20639 338 24X Fiche 50-320, 83/09/02, 8310050146

8310060181 Forwards TMI Program Ofc weekly status rept for wk of 830903-10. BARRETT, L H. TMI Program Office. 83/09/12. DENTON, H R. Office of Nuclear Reactor Regulation, Director. SNYDER, B J. TMI Program Office. 7pp. 20660 314 24X Fiche 50-320, 83/09/12, 8310060181

8310060164 Forwards TMI Program Ofc weekly status rept for wk of 830911-17. BARRETT, L H. TMI Program Office. 83/09/19. DENTON, H R. Office of Nuclear Reactor Regulation, Director. SNYDER, B J. TMI Program Office. 12p. 20660 333 24X Fiche 50-320, 83/09/19, 8310060164

8310050326 Forwards TMI Program Ofc weekly status rept for wk of 830918-24. BARRETT, L H. TMI Program Office. 83/09/26. DENTON, H R. Office of Nuclear Reactor Regulation, Director. SNYDER, B J. TMI Program Office. 11pp. 20639 348 24X Fiche 50-320, 83/09/26, 8310050326

8310180122 Forwards TMI Program Ofc weekly status rept for wk of 830925-1001. BARRETT, L H. TMI Program Office. 83/10/03. DENTON, H R. Office of Nuclear Reactor Regulation, Director. SNYDER, B J. TMI Program Office. 12pp. 20827 096 24X Fiche 50-320, 83/10/03, 8310180122

8310120125 Forwards "TMI Aquatic Study, Monthly Rept for Aug 1983." RESSLER, W C. General Public Utilities - GPU Service Corp. 83/10/07. HICKEY, C. NRC - No Detailed Affiliation Given. 1p. 20696 126 24X Fiche 50-289, 83/10/07, 8310120125

--8310120128 "TMI Aquatic Study, Monthly Rept for Aug 1983." NARDACCI, G A. Ichthyological Associates, Inc. 83/09/31. 13pp. 20696 127 24X Fiche 50-289, 83/10/07, 8310120128

8310180007 Forwards TMI Program Ofc weekly status rept for wk of 831002-08. BARRETT, L H. TMI Program Office. 83/10/10. DENTON, H R. Office of Nuclear Reactor Regulation, Director. SNYDER, B J. TMI Program Office. 9pp. 20825 079 24X Fiche 50-320, 83/10/10, 8310180007

S Reportable occurrences, LRIs & related correspondence

8310190060 LER 83-039/011-0 on 830820, several hourly fire watches determined not performed during replacement of deteriorated fire barrier seals. Caused by personnel error. Personnel counseled & roving fire watch established W/830919 ltr. CHAPLIN, S. KANGA, B K. General Public Utilities - GPU Service Corp. 83/09/19. MURLEY, T E. Region I, Office of Director. 4pp. 20822 331 24X Fiche 50-320, 83/09/19, 8310190060

8310190075 LER 83-040/071-0 on 830818, standby pressure control surge tank level transmitter 5PC-LT-3A failed low (caused by loose terminal block resistor. New resistor terminal blocks will be installed & procedure will be changed W/830919 ltr. GOULD, T L. KANGA, B K. General Public Utilities - GPU Service Corp. 83/09/19. MURLEY, T E. Region I, Office of Director. 4pp. 20822 279 24X Fiche 50-320, 83/09/19, 8310190075

8310200095 LER 83-038/011-0 on 830819, hourly firewatch not in effect for penetration fire seal 4-067-B0 in auxiliary bldg. Seal nonfunctional pending replacement. Caused by inaccurate communications. Firewatch reestablished W/830921 ltr. GOULD, T L. KANGA, B K. General Public Utilities - GPU Service Corp. 83/09/21. MURLEY, T E. Region I, Office of Director. 4pp. 20817 001 24X Fiche 50-320, 83/09/21, 8310200095

8310200155 LER 83-044/031-0 on 830822, concrete block accidentally dropped on transformer for lighting panel LPF-4E & feed breaker for panel LPF-4E did not trip before feed breaker for panel PDP-2H tripped W/830921 ltr. CHAPLIN, S. D. KANGA, B K. General Public Utilities - GPU Service Corp. 83/09/21. MURLEY, T E. Region I, Office of Director. 4pp. 20836 315 24X Fiche 50-320, 83/09/21, 8310200155

8310190173 LER 83-043/031-0 on 830827, 20 & 0912, air intake tunnel Malinsys partially disarmed (caused by interim protective action during lightning storms. Air intake tunnel structure louvers installed W/830923 ltr. GOULD, T L. KANGA, B K. General Public Utilities - GPU Service Corp. 83/09/23. MURLEY, T E. Region I, Office of Director. 4pp. 20821 090 24X Fiche 50-320, 83/09/23, 8310190173

8310250317 LER 83-045/031-0 on 830827, reactor bldg pressure transmitter 8S-P1-438U-2 found out of calibr. Caused by instrument drift. Transmitter recalibr & returned to svc W/830923 ltr. GOULD, T L. KANGA, B K. General Public Utilities - GPU Service Corp. 83/09/23. MURLEY, T E. Region I, Office of Director. 4pp. 20898 014 24X Fiche 50-320, 83/09/23, 8310250317

8310190205 Updated LER 83-024/01X-1 on 830717, standby pressure control pressure transmitter SPC PT-10 failed low & declared inoperable. Disconnected wire interrupted current loop, causing transmitter to fail low wire connected W/830926 ltr. GOULD, T L. KANGA, B K. General Public Utilities - GPU Service Corp. 83/09/26. MURLEY, T E. Region I, Office of Director. 4pp. 20818 111 24X Fiche 50-320, 83/09/26, 8310190205

8310250629 LER 83-046/031-0 on 830831 & 0901, standby pressure control surge tank level transmitter 5PC-LT-3A failed low (caused by loose or broken conductor between level transmitter & junction box/local indicator W/830930 ltr. GOULD, T L. KANGA, B K. General Public Utilities - GPU Service Corp. 83/09/30. MURLEY, T E. Region I, Office of Director. 4pp. 20900 289 24X Fiche 50-320, 83/09/30, 8310250629

8310250434 LER 83-042/011-0 on 830901, discovered that only one of two required isolation valves between RCS & non-RCS grade water sources closed on three occasions during feed & bleed operations, contrary to approved SER W/831003 ltr. CHAPLIN, S. D. KANGA, B K. General Public Utilities - GPU Service Corp. 83/10/03. MURLEY, T E. Region I, Office of Director. 4pp. 20897 075 24X Fiche 50-320, 83/10/03, 8310250434

8310250478 Updated LER 83-036/01X-1 on 830808, boom of hydraulic truck crane struck & grounded 230 kV bus 4 feedline, resulting in loss of power from unit auxiliary transformer 2A. Caused by personnel error W/831004 ltr. GOULD, T L. KANGA, B K. General Public Utilities - GPU Service Corp. 83/10/04. MURLEY, T E. Region I, Office of Director. 4pp. 20897 0911 24X Fiche 50-320, 83/10/04, 8310250478

T Hearing transcripts on non-antitrust matters

8310040117 Transcript of 830916 meeting w/Advisory Panel on Decontamination of TMI-2 in Washington, DC. Pp 1-65. * Commissioners. 83/09/16. 67pp. 20634 252 24X Fiche 50-320, 83/09/16, 8310040117

8310170312 Transcript of 830927 meeting in Middletown, PA re reactor bldg polar crane. Pp 1-72. Viewgraphs encl. * NRC - No Detailed Affiliation Given. 83/09/27. 210pp. 20795 277 24X Fiche 50-320, 83/09/27, 8310170312

DOCKETED ITEMS

159

B310190341 Transcript of B30927 public meeting in Middletown, PA re reactor bldg polar crane Pp 1-17; Supporting documentation encl
* Commissioners B3/09/27 212pp 20842 306 24X
Fiche 50-320, B3/09/27, B310190341

B310200347 Transcript of Advisory Panel for Decontamination of IMI Unit 2 B30928 public meeting in Harrisburg, PA Pp 1-109 Supporting documentation encl
* Advisory Council for Decontamination of IMI Unit 2 B3/09/28 207pp 20873 095 24X Fiche 50-320, B3/09/28, B310200347

B310130372 Transcript of B31004 briefing in Washington, DC re results of CPU & B&W trial matl Pp 1-42 Supporting documentation encl
* Commissioners B3/10/06 61pp 20770 052 24X
Fiche 50-320, B3/10/06, B310130372

U Congressional/Executive Correspondence

B310170686 Responds to B30914 ltr expressing concern re proposed release of radwaste water containing significant amounts of tritium into Susquehanna River Proposal for disposal of processed accident water not yet received
DIRCKS, W J Office of the Executive Director for Operations B3/10/03 SARBANES, P S Senate App 20798 166 24X
Fiche 50-320, B3/10/03, B310170686

--B310170690 Expresses concern re proposed release of radwaste water containing significant amounts of tritium into Susquehanna River, citing potential impact on Chesapeake Bay
SARBANES, P S Senate B3/09/14 PALLADINO, N J Commissioners 1p 20798 170 24X Fiche 50-320, B3/10/03, B310170690

DOCKET 50-321 EDWIN I HATCH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

B310040351 Forwards technical support cti & emergency operations facility floor plans, route maps to emergency response facilities & telephone listings Requests update of info & submittal of personnel access document
DANCE, H C Division of Project & Resident Programs B3/09/14
KELLY, R J Georgia Power Co Bpp 20620 323 24X
Fiche 50-321, B3/09/12, B310040351

B310040356 Ack receipt of B30813 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/B3-17 & 50-366/B3-17
LEWIS, R C Division of Project & Resident Programs B3/09/19
KELLY, R J Georgia Power Co 1p 20625 304 24X
Fiche 50-321, B3/09/19, B310040356

--B310040499 IE Insp Repts 50-321/B3-17 & 50-366/B3-17 on B30923-27 Noncompliance noted Failure to dispose of radwaste per 10CFR20.301
MAHLE, J B Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs B3/06/20 7pp 20625 312 24X Fiche 50-321, B3/09/19, B310040356

B310170741 Releases public version of revised emergency plan implementing procedures
FELTON, J H Division of Rules and Records B3/10/06 Document Management Branch 1p 20797 272 24X Fiche 50-321, B3/10/06, B310170741

--B310170743 Forwards public version of revised emergency plan implementing procedures, including Procedures HNP-B034 re contaminated tool storage & control & HNP-4861 re emergency notification network
NIX, H C, SDRRELL, E C Georgia Power Co B3/09/16 Office of Nuclear Reactor Regulation, Director App 20797 273 24X
Fiche 50-321, B3/10/06, B310170741

--B310170746 Public version of revised emergency plan implementing procedures, including Procedures HNP-B034 re contaminated tool storage & control & HNP-4861 re emergency notification network
GREENE, T, ROGERS, W H, NIX, H C Georgia Power Co B3/09/14 25pp 20797 277 24X Fiche 50-321, B3/10/06, B310170741

B310270012 Forwards IE Safeguards Insp Repts 50-321/B3-26 & 50-366/B3-28 on B30926-30 No noncompliance noted
DANCE, H C Division of Project & Resident Programs B3/10/20
KELLY, R J Georgia Power Co 2pp 20924 331 24X
Fiche 50-321, B3/10/20, B310270012

--B310270023 IE Safeguards Insp Repts 50-321/B3-26 & 50-366/B3-28 on B30926-30 No noncompliance noted Major areas inspected site orientation, review of security plan & procedures & security organization Details withheld (ref 10CFR23.21)
HALL, J L, MCGUIRE, D R Region 2, Office of Director B3/10/20 1p 20924 333 24X Fiche 50-321, B3/10/20, B310270012

O Adjudicatory correspondence

B310180364 Forwards info re util questioning of validity of notice of violation for violating 10CFR20.301 Util requested official interpretation & claimed NRC transferred regulatory authority to State of SC
LIEDERMAN, J Regional Operations & Enforcement Division B3/10/13
OLMSTEAD, B Regulations Division 32pp 20803 044 24X
Fiche 50-321, B3/10/13, B310180364

J Insurance & indemnity information

B310030301 Forwards Endorsements 01 & 02 to NELA Policy NF-215 & Endorsements 66 & 67 to MAHLU Policy MF-78
FIEDLER, J Marsh & McLennan, Inc B3/09/26 SALTZMAN, J Assistant Director for State & License Relations 5pp 20591 008 24X
Fiche 50-321, B3/09/26, B310030301

P Operating license stage documents & correspondence

B310070279 Application to amend License HPR-57, changing Tech Specs to allow increased flexibility in core design for core reconstitution schedule for Nov 1983 replacement of damaged fuel
HEAD, G F Georgia Power Co B3/09/29 STOLZ, J F Operating Reactors Branch 4 3pp 20657 002 24X Fiche 50-321, B3/09/29, B310070279

--B310070280 Proposed changes to Tech Specs re MAHLER curve design for core reconstitution
* Georgia Power Co B3/09/29 16pp 20657 005 24X
Fiche 50-321, B3/09/29, B310070279

B31010442 Informs that commitment to add high radiation signal for purge & vent valve isolation meets requirements of NUREG-0737, Item II E 4 2 7, "Primary Containment High Radiation to Close Vent & Purge Valves"
STOLZ, J F Operating Reactors Branch 4 B3/09/29 BECKMAN, J T Georgia Power Co 2pp 20706 319 24X Fiche 50-321, B3/09/29, B31010442

B310070264 Forwards proprietary "Dresden 2/3 Nuclear Generating Plant Suppression Pool Temp Response," "CI Hatch Nuclear Power Station Units 1 & 2 Suppression Pool Temp Response" & Hatch I B30825 meeting viewgraphs Repts withheld (ref 10CFR27.790)
PFEFFERLEN, H C General Electric Co B3/09/30 VASSALLO, D B Operating Reactors Branch 4 61pp 20611 292 24X
Fiche 50-000, B3/09/30, B310070264

B310070287 Requests that B30826 ltr re proposed Tech Spec changes concerning scram discharge sys be superseded by B30919 submittal
QUCHARL, T Georgia Power Co B3/10/03 STOLZ, J F Operating Reactors Branch 4 1p 20654 162 24X Fiche 50-321, B3/10/03, B310070287

B31010126 Withdraws proposed amend to Tech Specs changing requirements for HPCI & RCIC sys to require operability at pressure greater than 150 psig per H20403 ltr
QUCHARL, T Georgia Power Co B3/10/03 STOLZ, J F Operating Reactors Branch 4 1p 20666 298 24X Fiche 50-321, B3/10/03, B31010126

B310140241 Provides schedule for plant outages & activities associated w/recirculation piping insp required by IE Bulletins 02-03 & B3-02, as discussed at B30928 meeting w/NRC Replacement of piping planned for Unit 2 Viewgraphs encl
NIX, H C Georgia Power Co B3/10/05 STOLZ, J F Operating Reactors Branch 4 23pp 20761 345 24X Fiche 50-321, B3/10/05, B310140241

B310120265 Application for amend to Licenses DPR-57 & NRP-5 revising Tech Specs by transferring radiological effluent Tech Specs from App A to App B, per 781221 submittal Marked-up Tech Specs encl
HEAD, G F Georgia Power Co B3/10/06 STOLZ, J F Operating Reactors Branch 4 198pp 20698 092 24X Fiche 50-321, B3/10/06, B310120265

B310310439 Responds to B30907 request for mod to NRC B30701 order confirming util commitments to implement certain post-TMI-related items set forth in NUREG-0737 to extend completion date for Item 11 B 3 to B31201 Request acceptable
STOLZ, J F Operating Reactors Branch 4 B3/10/14 BECKMAN, J T Georgia Power Co 2pp 24X Fiche 50-321, B3/10/14, B310310439

DOCKETED ITEMS

--8310310440 Order granting extension until 831201 to complete Item 11 B 3. "Post-Accident Sampling" Commitments on applicable NUREG-0737 requirements from Generic Ltr 82-05 encl
EISENHUT, D O Division of Licensing 83/10/14 Georgia Power Co 5pp 20965 164 24X Fiche 50-321, 83/10/14, 8310310439

8310210270 Application for amend to Licenses DPR-57 & MPF-5 transferring radiological effluent Tech Spec from App B to App A
OUCHAL, L T Georgia Power Co 83/10/17 STOLZ, J F Operating Reactors Branch 4 App 20846 290 24X Fiche 50-321, 83/10/17, 8310210270

--8310210277 Proposed Tech Spec transferring radiological effluent Tech Spec from App B to App A
* Georgia Power Co 83/10/17 126pp 20846 296 24X Fiche 50-321, 83/10/17, 8310210270

--8310210279 EIS for facilities
* Georgia Power Co 83/10/17 21pp 20847 053 24X Fiche 50-321, 83/10/17, 8310210270

8310310308 Clarification to 830929 application to amend License DPR-57, revising Tech Specs to support planned shutdown for core reconstitution
OUCHAL, L T Georgia Power Co 83/10/24 STOLZ, J F Operating Reactors Branch 4 App 20961 226 24X Fiche 50-321, 83/10/24, 8310310308

G Inspection reports, IE Bulletins & correspondence

8310040012 Forwards IE Insp Repts 50-321/83-24 & 50-366/83-25 on 830817-19 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/08
KELLY, R J Georgia Power Co 2pp 20608 113 24X Fiche 50-321, 83/09/08, 8310040012

--8310040042 IE Insp Repts 50-321/83-24 & 50-366/83-25 on 830817-19 No noncompliance noted Major areas inspected license action on previous insp findings, followup on IL Bulletin 80-11 & review of bldg settlement data
LEMAHAN, J J Region 2, Office of Director CONLON, T E Division of Engineering & Operational Programs 83/09/06, 4pp 20608 115 24X Fiche 50-321, 83/09/08, 8310040012

8310040174 Forwards IE Enforcement Conference Repts 50-321/83-22 & 50-366/83-27 on 830810
O'REILLY, J P Region 2, Office of Director 83/09/15 KELLY, R J Georgia Power Co 1p 20608 222 24X Fiche 50-321, 83/09/15, 8310040174

--8310040178 IE Enforcement Conference Repts 50-321/83-22 & 50-366/83-27 on 830810 Major areas discussed MSIV leakage sys, HPCI main flow valve & ATWS recirculation pump trip signal
DANCE, H C Division of Project & Resident Programs 83/09/12, 2pp 20608 223, 24X Fiche 50-321, 83/09/15, 8310040174

8310040356 Ack receipt of 830812 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/83-17 & 50-366/83-17
LEWIS, R C Division of Project & Resident Programs 83/09/19
KELLY, R J Georgia Power Co 1p 20625 304 24X Fiche 50-321, 83/09/19, 8310040356

--8310040366 Responds to NRC 830713 ltr re violations noted in IE Insp Repts 50-321/83-17 & 50-366/83-17 Corrective actions boxes prepared for shipment elevated on one end w/drain plug removed for 24 h to allow for liquid drainage
NIX, H C Georgia Power Co 83/08/17 O'REILLY, J P Region 2, Office of Director App 20625 305 24X Fiche 50-321, 83/09/19, 8310040356

8310040468 Forwards IE Insp Repts 50-321/83-17 & 50-366/83-17 on 830523-27 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/07/13
KELLY, R J Georgia Power Co 2pp 20625 309 24X Fiche 50-321, 83/09/19, 8310040356

--8310040479 Notice of violation from insp on 830523-27
* Region 2, Office of Director 83/07/13 1p 20625 311 24X Fiche 50-321, 83/09/19, 8310040356

--8310040499 IE Insp Repts 50-321/83-17 & 50-366/83-17 on 830523-27 Noncompliance noted; failure to dispose of radwaste per 10CFR20 301
MAHLE, J B Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/06/20 7pp 20625 312 24X Fiche 50-321, 83/09/19, 8310040356

8310250519 Forwards IE Training Assessment Repts 50-321/83-23 & 50-366/83-24 on 830802-05 No noncompliance noted
LEWIS, R C Division of Project & Resident Programs 83/09/19
KELLY, R J Georgia Power Co 2pp 20701 021 24X Fiche 50-321, 83/09/19, 8310250519

--8310250560 IE Training Assessments Repts 50-321/83-23 & 50-366/83-24 on 830802-05 No noncompliance noted Major areas inspected licensed & nonlicensed operator training, requalification programs & onshift/real-time training & mgt training
HEHL, C W, MYERS, D O, SKINNLR, P H Region 2, Office of Director 83/09/15 10pp 20701 023 24X Fiche 50-321, 83/09/19, 8310250519

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Wilder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 028 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 024 24X Fiche 50-000, 83/09/29, 8308300349

8310140241 Provides schedule for plant outages & activities associated w/recirculation piping insp required by IE Bulletins 82-03 & 82-02 as discussed at 830928 meeting w/NRC Replacement of piping planned for Unit 2 Viewgraphs encl
NIX, H C Georgia Power Co 83/10/05 STOLZ, J F Operating Reactors Branch 4 23pp 20761 345 24X Fiche 50-321, 83/10/05, 8310140241

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20822 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180364 Forwards info re util questioning of validity of notice of violation for violating 10CFR20 301 Util requested official interpretation & claimed NRC transferred regulatory authority to State of SC
LIEBERMAN, J Regional Operations & Enforcement Division 83/10/13 OLMESTEAD, B Regulations Division 32pp 20803 044 24X Fiche 50-321, 83/10/13, 8310180364

8310180551 Notification of 831021 meeting w/BWR licensees in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking
MIRALTA, J Assistant Director for Safety Assessment 83/10/14 EISENHUT, D O Division of Licensing 5pp 20823 350 24X Fiche 50-000, 83/10/14, 8310180551

8310270012 Forwards IE Safeguards Insp Repts 50-321/83-26 & 50-366/83-28 on 830926-30 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/10/20
KELLY, R J Georgia Power Co 2pp 21024 331 24X Fiche 50-321, 83/10/20, 8310270012

DOCKETED ITEMS

161

--B310270023 IE Safeguards Insp Repts 50-321/83-26 & 50-366/83-28 on 830926-30 No noncompliance noted Major areas inspected site orientation, review of security plan & procedures & security organization Details withheld (ref 106FN73 21)
HALL, D L , McGuire, D R Region 2, Office of Director 83/10/10
1p 20924 333 24X Fiche 50-321, 83/10/20, 8310270012

R Periodic operating reports & related correspondence

B310190014 Monthly operating repts for Sept 1983 W/830910 ltr
CURTIS, C M , NIX, H C Georgia Power Co 83/10/10 Director's
Office, Office of Inspection and Enforcement 14pp 20823 284 24X
Fiche 50-321, 83/10/10, 8310190014

S Reportable occurrences, LLNs & isolated correspondence

B310210329 Responds to FOIA request for all documents re significantly high rate of equipment failures for 6k BWH/4 rated at 2,436 MM Forwards App A documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/07/28 HAFNER, B
Suffolk Nuclear Study Group 2pp 20442 223 24X
Fiche 50-000, 83/07/28, 8310210329

--B301180513 Evaluates LERs for Jul 1981 - Oct 1982 in support of upcoming SAIP review LERs minimally adequate in narrative sections Large number considered met deficiency-related
SEYFRIT, K V Director's Office 83/01/12 LEWIS, R Division of Project & Resident Programs 3pp 20882 225 24X
Fiche 50-000, 83/07/28, 8310210329

B310030304 Updated LER 83-023/01X-1 on 830224, 25 & 0824, various valves on reactor water cleanup sys failed to either open or close as required by Tech Specs Caused by limit switch out of adjustment & burned up motor W/830724 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/09/22 O'REILLY, J P
Region 2, Office of Director 3pp 20591 003 24X
Fiche 50-321, 83/09/22, 8310030304

B310030410 Updated LER 83-084/03X-1 on 830813, main steam line radiation monitors found to have high setpoint greater than three times normal operating background Caused by procedural inadequacy Procedure changed W/830922 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/09/22 O'REILLY, J P
Region 2, Office of Director 3pp 20493 127 24X
Fiche 50-321, 83/09/22, 8310030410

B310030481 LER 83-086/03L-0 on 830830, during routine control panel check, control room air intake monitor indicated downscale & alarmed Caused by monitor radiation source located too far from sensor Source repositioned W/830722 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/09/22 O'REILLY, J P
Region 2, Office of Director 4pp 20601 067 24X
Fiche 50-321, 83/09/22, 8310030481

B310030247 LER 83-090/03L-0 on 830825, during performance of RCIC pump operability Procedure HNP-1-3405, RCIC tripped on low bearing oil pressure Caused by setpoint drift & component failure W/830926 ltr
NIX, H C , TIPPS, S B Georgia Power Co 83/09/26 O'REILLY, J P
Region 2, Office of Director 3pp 20491 064 24X
Fiche 50-321, 83/09/26, 8310030247

B310040524 LER 83-099/03L-0 on 830901, drywell torus recorder indicated downscale & declared inoperable due to lack of power Caused by personnel error Power restored by closing power link W/830927 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/09/27 O'REILLY, J P
Region 2, Office of Director 3pp 20624 230 24X
Fiche 50-321, 83/09/27, 8310040524

B310140014 LER 83-088/03L-0 on 830913, fire protection instrumentation supervisory circuit panel 1243-P001 gave trouble light & alarm & could not be reset & cleared Caused by improperly closed relays Relays adjusted W/831006 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/10/06 O'REILLY, J P
Region 2, Office of Director 3pp 20768 060 24X
Fiche 50-321, 83/10/06, 8310140014

B310140144 LER 83-095/03L-0 on 830913, during hydrogen & oxygen analyzer instrument procedure, analyzer A 1P33-N002A found out of calibr Caused by instrument drift Analyzer recalibr W/831006 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/10/06 O'REILLY, J P
Region 2, Office of Director 4pp 20763 021 24X
Fiche 50-321, 83/10/06, 8310140144

B310170397 LER 83-097/03L-0 on 830918, operating personnel determined that position of control rod 14-43 could not be ascertained Caused by failed position switch in position indicator probe Rod moved to Position 18 W/831006 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/10/06 O'REILLY, J P
Region 2, Office of Director 4pp 20789 071 24X
Fiche 50-321, 83/10/06, 8310170397

B310170582 Updated LER 83-096/01X-1 on 830616, drywell svc air primary containment inboard isolation valve 1P51-F514 opened during plant shutdown & not closed prior to startup on 830618 Caused by procedural inadequacy Valves closed W/831006 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/10/06 O'REILLY, J P
Region 2, Office of Director 4pp 20780 331 24X
Fiche 50-321, 83/10/06, 8310170582

B310310297 LER 83-094/03L-0 on 830929, HPCI steam line pressure switches C&D actuated below Tech Spec requirements Caused by setpoint drift Switches recalibr W/831020 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/10/20 O'REILLY, J P
Region 2, Office of Director 4pp 20761 278 24X
Fiche 50-321, 83/10/20, 8310310297

V Operator Examinations

B310250519 Forwards IE Training Assessment Repts 50-321/83-23 50-366/83-24 on 830802-05 No noncompliance noted
LEWIS, R C Division of Project & Resident Programs 83/09/19
KELLY, R J Georgia Power Co 2pp 20701 021 24X
Fiche 50-321, 83/09/19, 8310250519

--B310250560 IE Training Assessments Repts 50-321/83-23 & 50-366/83-24 on 83080-05 No noncompliance noted Major areas inspected licensed & nonlicensed operator training, requalification programs & onshift/real-time training & mgt training
HEHL, C W , MYERS, D D , SKINNER, P H Region 2, Office of Director 83/09/15 10pp 20901 023 24X Fiche 50-321, 83/09/19, 8310250519

DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

A Application/construction stage documents & correspondence

B310180597 FOIA request for list of mods to containment undertaken by util in response to NUREG-0487
HAFNER, B Suffolk Nuclear Study Group 83/04/25 Office of Administration 1p 20827 124 24X Fiche 50-322, 83/04/25, 8310180597

B310110436 Responds to FOIA request for RFP RS-DRM-83-500 & SECY-83-157 RS-DRM-83-500 placed in PDR SECY-83-157 partially withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/07/20 GRABER, L
NUS Corp 2pp 20706 308 24X Fiche 50-322, 83/07/20, 8310110436

--B310110439 Requests approval of proposed order re low power license for facility
PLAINE, H H Office of the General Counsel SECY-83-157
83/05/02 4pp 20706 310 24X Fiche 50-322, 83/07/20, 8310110436

B310180600 Responds to FOIA request for info re mods to containment undertaken by util info contained in Rev 5 to Plant Design Assessment Rept Util not required to report changes but must comply w/acceptance criteria in Rev 5
FELTON, J M Division of Rules and Records 83/09/06 HAFNER, B
Suffolk Nuclear Study Group 1p 20827 125 24X
Fiche 50-322, 83/09/06, 8310180600

B310030590 Forwards request for addl info on proposed Tech Specs re instrumentation trip setpoints, allowable values & on-line testing capability Response within 30 days requested
SCHWENGER, A Licensing Branch 2 83/09/23 POLLACK, M S Long Island Lighting Co 2pp 20607 341 24X Fiche 50-322, 83/09/23, 8310030590

B310050443 Forwards Region I morning repts re emergency diesel generators for 830909-26
ODDARD, R J Hearing Branch 3 83/09/28 BRENNER, L ,
FERGUSON, G A , MORRIS, P A Atomic Safety and Licensing Board Panel 3pp 20631 345 24X Fiche 50-322, 83/09/28, 8310050443

8308300357 Board Notification 82-105A Forwards evaluation of allegations re design deficiencies in Class I piping sys info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway
EISENHUT, D G Division of Licensing 83/09/29 PALLADINO, N J
Commissioners 3pp 20632 001 24X Fiche 50-000, 83/09/29, 8308300357

B310060300 Forwards "Preliminary Metallurgical Evaluation of Failed Crankshaft From Diesel Generator 102"
EARLEY, A F Hutton & Williams EARLEY, A F Long Island Lightin Co 83/10/03 BRENNER, L , MORRIS, P A , FERGUSON, G A Atomic S and Licensing Board Panel 15pp 20646 181 24X
Fiche 50-322, 83/10/03, 8310060300

DOCKETED ITEMS

8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves
EISENHUT, D O Division of Licensing 83/10/06 PALLADINO, N J Commissioners 3pp 20818 001 24X Fiche 50-000, 83/10/06, 8308300771

8310190003 Forwards revised FSAR Section 13.1.3.25 re qualification requirements for technicians, revised in response to concern of NRC resident inspector info will be incorporated in next FSAR amend
SMITH, J L Long Island Lighting Co 83/10/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20622 102 24X Fiche 50-322, 83/10/17, 8310190003

E NRC Safety Evaluation Report (SER), supply & correspondence

8310070116 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF THE SHOREHAM NUCLEAR POWER STATION, UNIT NO. 1 DOCKET NO. 50-322 (Long Island Lighting Company)
* Division of Licensing NUREG-0420 S04 83/09/30 71pp Available at NRC 44 50 20671 122 24X Fiche 50-322, 83/09/30, 8310070116

8310170009 Forwards Suppl 4 to NUREG-0420, "SER re Operation of Shoreham Nuclear Power Station, Unit 1"
SCHWENGER, A Licensing Branch 2 83/09/30 POLLACK, H S Long Island Lighting Co 3pp 20814 067 24X Fiche 50-322, 83/09/30, 8310170009

8310120264 Forwards Rev 14 to list of active safety-related equipment at qualification level for Sept 1983, per 821123 commitment List includes balance-of-plant & NSSS equipment to assist NRC in review of SER Issue 8
SMITH, J L Long Island Lighting Co 83/10/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 52pp 20693 021 24X Fiche 50-322, 83/10/05, 8310120264

8310140231 Submits confirmatory info to facilitate NRC closeout of SER Outstanding Issue 8 Mods to RCIC turbine completed Detailed NSSS qualification documentation delivered to site for placement in permanent site file
SMITH, J L Long Island Lighting Co 83/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20762 045 24X Fiche 50-322, 83/10/07, 8310140231

F Security, medical, emergency & fire protection plans

8310050378 Forwards NRC memo requesting FEMA Regional Assistance Committee (RAC) review of applicant transition plan by 831201 Hearings on admitted contentions may commence as scheduled on 831205, in absence of completion of RAC review
BORDENICK, B M Hearing Branch 3 83/09/28 LAURENSEN, J A, LIVINGSTON, H S, KLINE, J R Atomic Safety and Licensing Board Panel 3pp 20632 348 24X Fiche 50-322, 83/09/28, 8310050378

8310050439 Forwards EL Jordan 830915 ltr requesting Regional Assistance Committee review of util transition plan of offsite emergency preparedness Findings & determinations expected by 831201
REPKA, D A Hearing Branch 3 83/09/28 ROSENTHAL, A S, EDLES, G J, WILBER, H A Atomic Safety and Licensing Appeal Panel 3pp 20630 360 24X Fiche 50-322, 83/09/28, 8310050439

8310050427 Forwards T Urbanik 830915 ltr correcting inadvertent failure to mark as adequate Section III C, "Traffic Capacity - Adverse Weather Conditions," of evaluation of evacuation time estimate
BORDENICK, B M Hearing Branch 3 83/09/30 BIRKENHEIMER, J Kirkpatrick, Lockhart, Hill, Christopher & Phillips 3pp 20633 187 24X Fiche 50-322, 83/09/30, 8310050427

10140027 Urges Commission to reject util emergency preparedness plan State of NY will not impose radiological emergency preparedness plan on Suffolk County County will refrain from implementing plan Public safety cannot be assured.
CUOMO, M New York, State of 83/10/04 PALLADINO, N J Commissioners 2pp 20767.349 24X Fiche 50-322, 83/10/04, 8310140027

Adjudicatory correspondence

10050359 Forwards NRC 830920 memo re "Huber allegations" w/o encl
BORDENICK, B M Hearing Branch 3 83/09/26 BRENNER, L., FERGUSON, G A, MORRIS, P A Atomic Safety and Licensing Board Panel 2pp 20629 361 24X Fiche 50-322, 83/09/26, 8310050359

8310030456 Notice of resolution of discovery dispute w/util which was subg of Suffolk County 830916 & 23 motions to compel answer to interrogatory on local emergency response organization workers & to depose workers Certificate of Svc encl
LETSCHKE, K J Suffolk County, NY LETSCHKE, K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/09/28 4pp 20601 044 24X Fiche 50-322, 83/09/28, 8310030456

8310050378 Forwards NRC memo requesting FEMA Regional Assistance Committee (RAC) review of applicant transition plan by 831201 Hearings on admitted contentions may commence as scheduled on 831205, in absence of completion of RAC review
BORDENICK, B M Hearing Branch 3 83/09/28 LAURENSEN, J A, LIVINGSTON, H S, KLINE, J R Atomic Safety and Licensing Board Panel 3pp 20632 348 24X Fiche 50-322, 83/09/28, 8310050378

8310050439 Forwards EL Jordan 830915 ltr requesting Regional Assistance Committee review of util transition plan of offsite emergency preparedness Findings & determinations expected by 831201
REPKA, D A Hearing Branch 3 83/09/28 ROSENTHAL, A S, EDLES, G J, WILBER, H A Atomic Safety and Licensing Appeal Panel 3pp 20630 360 24X Fiche 50-322, 83/09/28, 8310050439

8310050443 Forwards Region I morning repts re emergency diesel generators for 830909-26
GOODARD, R J Hearing Branch 3 83/09/28 BRENNER, L., FERGUSON, G A, MORRIS, P A Atomic Safety and Licensing Board Panel 5pp 20631 345 24X Fiche 50-322, 83/09/28, 8310050443

8310030496 Decision ALAB-743, affirming ASLB 830728 Order LDP-83-42 denying Citizens for Orderly Energy Policy petition to intervene Petition untimely Judge Edles dissenting opinion encl
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel 83/09/29 51pp 20601 116 24X Fiche 50-322, 83/09/29, 8310030496

8310040199 Response to requests for admissions Certificate of Svc encl
LETSCHKE, K Suffolk County, NY LETSCHKE, K Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/09/29 Long Island Lighting Co 9pp 20615 017 24X Fiche 50-322, 83/09/29, 8310040199

8310050395 Forwards Transamerica Delaval 830921 ltr re potential defect in component of standby diesel generator & in mounted fuel oil line
BORDENICK, B M Hearing Branch 3 83/09/29 BRENNER, L., FERGUSON, G A, MORRIS, P A Atomic Safety and Licensing Board Panel 4pp 20629 337 24X Fiche 50-322, 83/09/29, 8310050395

8310040196 Order ruling on objections to ASLB 830819 special prehearing conference order Intervenor objections denied as to Contentions 22, 12, 13, 26 B, 35-38 & 43 Objection to Contention 85 granted & contention admitted
LAURENSEN, J A Atomic Safety and Licensing Board Panel 83/09/30 Suffolk County, NY 8pp 20608 225 24X Fiche 50-322, 83/09/30, 8310040196

8310040202 Memorandum & order demanding NRC explanation of possible delay of completion of hearing due to FEMA review of util transition plan
LAURENSEN, J A Atomic Safety and Licensing Board Panel 83/09/30 Office of the Executive Legal Director 2pp 20614 274 24X Fiche 50-322, 83/09/30, 8310040202

8310040286 Order dismissing Suffolk County motions to compel util response to interrogatory & production of local emergency response organization workers for deposition Second discovery conference scheduled for 831003 canceled
LAURENSEN, J A Atomic Safety and Licensing Board Panel 83/09/30 Suffolk County, NY 2pp 20612 360 24X Fiche 50-322, 83/09/30, 8310040286

8310040618 Forwards LILCO counsel 830929 ltr re resolution of pending discovery dispute. Encl ltr accurately reflects resolution, w/listed clarifications Certificate of Svc encl
DYNNEER, A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips DYNNEER, A R Suffolk County, NY 83/09/30 BRENNER, L., FERGUSON, G A, MORRIS, P A Atomic Safety and Licensing Board Panel 7pp 20623 337 24X Fiche 50-322, 83/09/30, 8310040618

8310040630 Rept on mod of automatic depressurization sys logic in response to ASLB request ASLB should defer further consideration pending status rept on implementation of Option 2 due by 840115 Certificate of Svc encl
ELLIS, T S Long Island Lighting Co ELLIS, T S Hunton & Williams 83/09/30, 7pp 20626 055 24X Fiche 50-322, 83/09/30, 8310040630

DOCKETED ITEMS

163

8310050427 Forwards T Urbanik 830915 ltr correcting inadvertent failure to mark as adequate Section III C, "Traffic Capacity - Adverse Weather Conditions," of evaluation of evacuation time estimate
BORDENICK, B M Hearing Branch 3 83/09/30 BIRKENHEIMER, J Kirkpatrick, Lockhart, Hill, Christopher & Phillips 3pp 20633 187 24X Fiche 50-322, 83/09/30, 8310050427

8310050416 Responses to 830825 interrogatories & request for production of documents & to 830919 interrogatories Certificate of Svc encl
LETSCHE, K J Suffolk County, NY LETSCHE, K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/10/03 Long Island Lighting Co 3pp 20634 019 24X Fiche 50-322, 83/10/03, 8310050416

8310050537 Memorandum & order granting util request to defer further consideration of mod to automatic depressurization sys logic pending receipt of util status rept on progress of implementation of mods by 840116
BRENNER, L Atomic Safety and Licensing Board Panel 83/10/03 Long Island Lighting Co 4pp 20629 354 24X Fiche 50-322, 83/10/03, 8310050537

8310060300 Forwards "Preliminary Metallurgical Evaluation of Failed Crankshaft From Diesel Generator 102"
EARLEY, A F Hunton & Williams EARLEY, A F Long Island Lighting Co 83/10/03 BRENNER, L, MORRIS, P A, FERGUSON, G A Atomic Safety and Licensing Board Panel 15pp 20646 181 24X Fiche 50-322, 83/10/03, 8310060300

8310060192 Memorandum & order confirming rulings made during 830992/ telcon re Suffolk County 830826 motion to compel discovery on diesel crankshaft failure Util did not give timely notice of opportunity to observe disassembled diesel generators
BRENNER, L Atomic Safety and Licensing Board Panel 83/10/04 6pp 20647 037 24X Fiche 50-322, 83/10/04, 8310060192

8310130035 Forwards deposition of EB Lieberman & contentions re evacuation shadow phenomenon in preparation for testimony
Testimony due 831118 Draft should be submitted earlier for review W/o encl
REPKA, D A Hearing Branch 3 83/10/06 URBANIK, I Texas Transportation Institute 2pp 20725 075 24X Fiche 50-322, 83/10/06, 8310130035

8310120119 Forwards util diesel generator status rept per 830912 commitment
EARLEY, A F Hunton & Williams EARLEY, A F Long Island Lighting Co 83/10/07 BRENNER, L Atomic Safety and Licensing Board Panel 1p 20696 140 24X Fiche 50-322, 83/10/07, 8310120119

--8310120121 Diesel generator status rept
* Long Island Lighting Co 83/10/07 6pp 20696 141 24X Fiche 50-322, 83/10/07, 8310120121

8310140016 Advises that util believes fuel load can occur during late First Quarter 1984 or early Second Quarter 1984
REVELEY, W T Hunton & Williams REVELEY, W T Long Island Lighting Co 83/10/07 BRENNER, L, FERGUSON, G A, MORRIS, P A Atomic Safety and Licensing Board Panel 1p 20768 035 24X Fiche 50-322, 83/10/07, 8310140016

8310130245 Response to ASLB 830930 memorandum & order requesting NRC explanation of possible delay in hearing completion NRC does not anticipate that FEMA review will delay hearings
Certificate of Svc encl
BORDENICK, B M Hearing Branch 3 83/10/11 6pp 20723 247 24X Fiche 50-322, 83/10/11, 8310130245

8310170365 Schedule for completion of training matls Initial set of drill scenarios should be completed by 831021 Certificate of Svc encl
CHRISTMAN, J N Long Island Lighting Co CHRISTMAN, J N Hunton & Williams 83/10/11 5pp 20786 177 24X Fiche 50-322, 83/10/11, 8310170365

8310170409 Exceptions to ASLB 830921 partial initial decision Certificate of Svc encl
ELLIS, T S Louisiana Power & Light Co ELLIS, T S Hunton & Williams 83/10/11 Atomic Safety and Licensing Board Panel 5pp 20784 325 24X Fiche 50-322, 83/10/11, 8310170409

8310170500 Response opposing Suffolk County 830919 motion to compel discovery re emergency planning Matl not relevant but is subj to privilege Requisite showing for privilege made
Unexecuted affidavit & Certificate of Svc encl
GLASS, B M Federal Emergency Management Agency 83/10/12 Atomic Safety and Licensing Board Panel 8pp 20784 001 24X Fiche 50-322, 83/10/12, 8310170500

8310170401 Prehearing order re proposed preliminary findings of fact & conclusions of law Preliminary findings should be comprehensive & precise in order to narrow & define issues
LAURENSEN, J A Atomic Safety and Licensing Board Panel 83/10/13 3pp 20785 085 24X Fiche 50-322, 83/10/13, 8310170401

8310190056 Requests util provide Suffolk County w/prior notification of drills & practice exercises which are part of local emergency response organization training program County representatives request permission to observe
BIRKENHEIMER, J Kirkpatrick, Lockhart, Hill, Christopher & Phillips BIRKENHEIMER, J Suffolk County, NY 83/10/14 MONAGHAN, J A Hunton & Williams MONAGHAN, J A Long Island Lighting Co 1p 20823 222 24X Fiche 50-322, 83/10/14, 8310190056

8310240168 Informs that sys of advisors to each operating shift will be replaced w/experienced BWR operators
UHL, W D Long Island Lighting Co 83/10/14 ABSELSTINE, J K Commissioners 1p 20880 028 24X Fiche 50-322, 83/10/14, 8310240168

8310190209 Exceptions to ASLB 830921 Partial Initial Decision LBP-83-57 Certificate of Svc encl
LANPHER, L C Long Island Lighting Co LANPHER, L C Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/10/17 Atomic Safety and Licensing Board Panel 9pp 20818 138 24X Fiche 50-322, 83/10/17, 8310190209

8310200105 Informs that Shoreham Opponents Coalition will join in Suffolk County exceptions for ASLB 830921 partial initial decision Certificate of Svc encl
DOUGHERTY, J B Dougherty, J B DOUGHERTY, J B Shoreham Opponents Coalition 83/10/17 ROSENTHAL, A S, EDLES, G J, WILBER, H A Atomic Safety and Licensing Board Panel 3pp 20836 064 24X Fiche 50-322, 83/10/17, 8310200105

8310200217 Corrected Certificate of Svc to Suffolk County 831017 exceptions to partial initial decision
LANPHER, L C Suffolk County, NY LANPHER, L C Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/10/18 Atomic Safety and Licensing Board Panel 4pp 20833 065 24X Fiche 50-322, 83/10/18, 8310200217

8310200262 Motion for 60-day extension to file appeal brief & for permission to exceed page limitation re ASLB 831017 Partial Initial Decision LBP-83-57 Decision voluminous & issues complex Certificate of Svc encl
LANPHER, L C Long Island Lighting Co LANPHER, L C Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/10/18 Atomic Safety and Licensing Board Panel 7pp 20830 069 24X Fiche 50-322, 83/10/18, 8310200262

8310250491 Forwards final FEMA rule on review & approval of state & local radiological emergency plans & preparedness Rule effective 831028
BORDENICK, B M Hearing Branch 3 83/10/18 LAURENSEN, J A, KLINE, J R, SHON, F J Atomic Safety and Licensing Board Panel 15pp 20897 127 24X Fiche 50-322, 83/10/18, 8310250491

8310240160 Supplemental response supporting Suffolk County 830919 motion to compel FEMA to produce certain documents re emergency planning FEMA 831012 response fails to comply w/privilege assertion Certificate of Svc encl
LANPHER, L C Suffolk County, NY LANPHER, L C Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/10/19 Atomic Safety and Licensing Board Panel 14pp 20881 294 24X Fiche 50-322, 83/10/19, 8310240160

8310250122 Forwards util 830811 application for amend to Matl/Byproduct License 31-17432-01 & draft Amend 7, permitting removal of neutron sources from shipping casks & storage in spent fuel storage pool W/Certificate of Svc
BORDENICK, B M Hearing Branch 3 83/10/19 BRENNER, L, FERGUSON, G A, MORRIS, P A Atomic Safety and Licensing Board Panel 7pp 20899 269 24X Fiche 50-322, 83/10/19, 8310250122

8310310128 Forwards diesel generator status rept per 830912 commitment. Related correspondence
EARLEY, A F Hunton & Williams EARLEY, A F Long Island Lighting Co 83/10/20 BRENNER, L Atomic Safety and Licensing Board Panel 1p 20949 099 24X Fiche 50-322, 83/10/20, 8310310128

--8310310133 Diesel generator status rept
* Long Island Lighting Co 83/10/20 7pp 20949 100 24X Fiche 50-322, 83/10/20, 8310310133

8310270239 Joint scheduling submission of util, NRC, FEMA & Suffolk County re emergency planning issues Expeditious ASLB action requested Certificate of Svc encl
REPKA, D A Hearing Branch 3 MCCLESKEY, K E Long Island Lighting Co GLASS, B M Federal Emergency Management Agency 83/10/21 6pp 20924 062 24X Fiche 50-322, 83/10/21, 8310270239

DOCKETED ITEMS

8310310124 Reply supporting Suffolk County 831018 motion for extension to file brief re Contention 7D Page limit should not be raised Certificate of Svc encl
IRWIN, D P Long Island Lighting Co IRWIN, D P Hutton & Williams
83/10/25 Atomic Safety and Licensing Appeal Panel 8pp
20949 169 24X Fiche 50-322, 83/10/25, 8310310124

8310280118 Order establishing briefing schedule & page limitations for appeals to ASLB 830921 partial initial decision
SHOEMAKER, C J Atomic Safety and Licensing Board Panel 83/10/26
3pp 20929 217 24X Fiche 50-322, 83/10/26, 8310280118

8310310248 Order revising schedule contained in 830830 revised special prehearing conference order All parties ordered to submit proposed schedule for filing cross-motions for summary disposition of Contentions 1-10
LAURENSEN, J A Atomic Safety and Licensing Board Panel 83/10/26
Atomic Safety and Licensing Board Panel 4pp 20947 178 24X
Fiche 50-322, 83/10/26, 8310310248

8310310190 Amended notice of hearing Hearing will commence on 831206 & 840103 in Hauppauge, NY & on 831212 in Riverhead, NY
LAURENSEN, J A Atomic Safety and Licensing Board Panel 83/10/27
1p, 20958 260 24X Fiche 50-322, 83/10/27, 8310310190

H General correspondence

8310260217 Forwards school board 830929 resolution identifying weaknesses in emergency evaluation plan Licensing should not be permitted until plan assures adequate protection for children & school personnel
D'AMICO, L Middle Island, NY 83/10/03 LAURENSEN, J A Atomic Safety and Licensing Board Panel 4pp 20912 109 24X
Fiche 50-322, 83/10/03, 8310260217

Q Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins For Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20734 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp, 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 113pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp, 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310310222 Ack receipt of 830915 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-322/83-21
STAROSTECKI, R Division of Project & Resident Programs 83/10/25
POLLOCK, M S Long Island Lighting Co 2pp 20947 23J 24X
Fiche 50-322, 83/10/25, 8310310222

--8310310224 Responds to NRC 830815 ltr re violations noted in IE Insp Rept 50-322/83-21 Corrective actions until performing complete walkdown of relay room to ensure that method used to identify separation violations adequate
MUSELER, W J Long Island Lighting Co 83/09/15 STAROSTECKI, R Division of Project & Resident Programs 5pp 20947 235 24X
Fiche 50-322, 83/10/25, 8310310224

S Reportable occurrences, LERs & related correspondence

8308310050 Board Notification 83-160 provides info re 830812 failure of main crankshaft on one of three Transamerica Delaval emergency diesel generators at Shoreham
EISENHUT, D O Division of Licensing 83/10/14 PALLADINO, N J, GILINSKY, V, ROBERTS, T Commissioners 15pp 20966 312 24X
Fiche 50-000, 83/10/14, 8308310050

--8310310454 "Shoreham Emergency Diesel Generator 10P Crankshaft Failure Analysis/Recovery Master Plan " Stop work authorizations encl
MILLIGAN, M H, ROSE, J T, YOUNGLING, E J Long Island Lighting Co 83/09/23 17pp 20966 338 24X Fiche 50-322, 83/10/14, 8308310050

T Hearing transcripts on non-antitrust matters

8310250375 Forwards transcripts of T Urbanik & JR Sears 830914 depositions & errata sheets W/o transcripts
REPKA, D A Hearing Branch 3 83/10/13 BILLINGSLEY, W E Alderson Reporting 1p 20897 298 24X Fiche 50-322, 83/10/13, 8310250375

--8310250381 Errata sheet for T Urbanik 830914 deposition
URBANIK, T NRC - No Detailed Affiliation Given 83/09/30 1p
20897 299 24X Fiche 50-322, 83/10/13, 8310250375

--8310250384 Errata sheet for JR Sears 830914 deposition
SEARS, J R NRC - No Detailed Affiliation Given 83/10/13 1p
20897 300 24X Fiche 50-322, 83/10/13, 8310250375

U Congressional/Executive Correspondence

8310280144 Ack receipt of 830926 ltr to President Reagan re offsite emergency preparedness Emergency plan, which does not require participation of Suffolk County govt, under review by FEMA
Fuel load & low power license not permitted by ASLB
CUNNINGHAM, O H Office of the Executive Legal Director 83/10/25
BEHAN, J L New York, State of 2pp 20929 046 24X
Fiche 50-322, 83/10/25, 8310280144

--8310280146 Forwards JL Behan 830926 request for info from President Reagan re offsite emergency preparedness Direct response requested
KELLEY, B President of US & Executive Offices 83/10/11 NRC -
No Detailed Affiliation Given 6pp 20929 057 24X
Fiche 50-322, 83/10/25, 8310280144

X Onsite Storage of Low Level Waste

8310250122 Forwards until 830811 application for amend to Matl/Byproduct License 31-17432-D1 & draft Amend 7, permitting removal of neutron sources from shipping casks & storage in spent fuel storage pool W/Certificate of Svc
BORDENICK, E M Hearing Branch 3 83/10/19 BRENNER, L, FERROUSON, O A, MORRIS, P A Atomic Safety and Licensing Board Panel 7pp 20897 269 24X Fiche 50-322, 83/10/19, 8310250122

DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8310110034 Further response to FOIA request for records re NUREG-0862 investigative rept & investigations concerning facilities
Forwards App A documents Commissioner Bradford 811217 memo withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/06/15 REYNOLDS, J Center for Law in the Public Interest 4pp 20713, 001 24X
Fiche 50-275, 83/06/15, 8310110034

DOCKETED ITEMS

168

- B208010014 Requests issuance of final statement clearing RL Cloud Associates from allegations of wrongdoing in preparation of "Preliminary Rept, Seismic Verification Program," per NRC investigation results in NUREG-0862, Issue 3
CLOUD, R L Robert L. Cloud Associates, Inc 82/08/24
PALLADINO, N J Commissioners 3pp 20713 032 24X
Fiche 50-275, 83/06/15, B310110034
- B310110037 Forwards draft ltrs to Subcommittee on Energy & Environ & Subcommittee on Energy Conservation & Power transmitting NRC review of NUREG-0862 Comments requested by B20811
KAMMERER, C Office of Congressional Affairs 82/08/09
BICKWIT, L Office of the General Counsel CUMMINGS, J Office of Inspector & Auditor FITZGERALD, J Office of Investigation 5pp 20713 008 24X Fiche 50-275, 83/06/15, B310110034
- B310110046 Responds to B1121 ltr expressing concern re delays in licensing process Immediate issue concerns acceptability of util proposed auditors, RL Cloud Assoc investigation scheduled for completion on 821108 & 030201
KAMMERER, C Office of Congressional Affairs 82/01/10
RQUSSELOT, J H House of Rep 1p 20713 013 24X
Fiche 50-275, 83/06/15, B310110034
- B310110048 "Chronology of Events"
* Affiliation Unknown 83/06/15 8pp 20713 015 24X
Fiche 50-275, 83/06/15, B310110034
- B310110057 Draft ltrs re adequacy of NRC investigation into development of RL Cloud Assoc rept, per NUREG-0862, "Insp Rept of Preliminary Rept, Seismic Verification Program at Diablo Canyon Nuclear Power Plant"
PALLADINO, N Commissioners 83/06/15 UDALL, M K House of Rep, Interior & Insular Affairs OTTINGER, R, DINGELL, J House of Rep, Energy & Commerce 7pp 20713 024 24X
Fiche 50-275, 83/06/15, B310110034
- B310110095 Forwards RL Cloud B20824 request for final statement on conclusions of Cloud/util investigation to clear Cloud prof reputation Matter presented in NUREG-0862 & SECY-82-89 Commission guidance requested
DIRCKS, W J Office of the Executive Director for Operations 83/09/08 PALLADINO, N Commissioners 1p 20713 031 24X
Fiche 50-275, 83/06/15, B310110034
- B310110107 Forwards summary documenting record actions of peer review group
REHM, T A Office of the Executive Director for Operations 82/02/18 PALLADINO, N, GILINSKY, V, BRADFORD, P Commissioners 1p 20713 036 24X Fiche 50-275, 83/06/15, B310110034
- B310110111 Forwards summary of Region V peer review group assistance w/ investigation of RL Cloud Assoc Related info encl
CORNELL, E K Office of the Executive Director for Operations
CASE, E G Office of Nuclear Reactor Regulation, Director
SNIEZEK, J H Director's Office, Office of Inspection and Enforcement 82/02/18 DIRCKS, W J Office of the Executive Director for Operations 4pp 20713 037 24X
Fiche 50-275, 83/06/15, B310110034
- B310270255 FOIA request for Polk & Schierling B30218 memo to Knighton & Lear re reverification program to be placed in PDR
BUCKLES, R NUS Corp 83/06/30 Division of Rules and Records 1p 20943 066 24X Fiche 50-275, 83/06/30, B310270255
- B310270250 Responds to FOIA request for Polk & Schierling B30218 memo to Knighton & Lear re reverification program Memo placed in PDR
FELTON, J M Division of Rules and Records 83/07/15 BUCKLES, R, NUS Corp 1p 20943 065 24X Fiche 50-275, 83/07/15, B310270250
- B310180609 FOIA request for complete set of BNL repts on seismic design of facilities
CALSOYAS, C D Affiliation Unknown 83/08/16 Region 5, Office of Director 4pp 20824 315 24X Fiche 50-275, 83/08/16, B310180609
- B310180610 Responds to FOIA request for complete set of BNL repts on seismic design of facilities Documents listed in app available in PDR
FELTON, J M Division of Rules and Records 83/09/01 CALSOYAS, C D Affiliation Unknown 2pp 20824 319 24X Fiche 50-275, 83/09/01, B310180610
- B308300355 Board Notification B3-66A advises that position re rod drop issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycle
EISENHUT, D G Division of Licensing 83/09/29 PALLADINO, N J, GILINSKY, V, ROBERTS, T M Commissioners 10pp 20632 106 24X
Fiche 50-000, 83/09/29, B308300355
- B308300357 Board Notification B2-105A forwards evaluation of allegations re design deficiencies in Class 1 piping sys Info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway
EISENHUT, D G Division of Licensing 83/09/29 PALLADINO, N J, GILINSKY, V, ROBERTS, T M Commissioners 3pp 20632 001 24X
Fiche 50-000, 83/09/29, B308300357
- B308300358 Board Notification B3-150 forwards listed repts re facility IDVP Info will be considered in final evaluation of verification of plant mods & matters to be completed for license activities
EISENHUT, D G Division of Licensing 83/09/30 PALLADINO, N J, GILINSKY, V, ROBERTS, T M Commissioners 3pp 20641 032 24X
Fiche 50-275, 83/09/30, B308300358
- B308300763 Board Notification B3-151 provides info re desirability of current ECCS actuation logic for Westinghouse plants, in light of recent info concerning steam generator tube rupture procedure for Barsele Nuclear Power Station
EISENHUT, D G Division of Licensing 83/10/04 PALLADINO, N J Commissioners 2pp 20698 033 24X Fiche 50-000, 83/10/04, B308300763
- B308300771 Board Notification B3-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves
EISENHUT, D G Division of Licensing 83/10/06 PALLADINO, N J, GILINSKY, V, ROBERTS, T M Commissioners 31pp 20818 001 24X
Fiche 50-000, 83/10/06, B308300771
- B310170471 Forwards design review effort description discussing interrelationship of design verification program w/Unit 2. Review provides assurance that design conforms w/licensing commitments
SCHUYLER, J O Pacific Gas & Electric Co 83/10/06 EISENHUT, D G Division of Licensing 12pp 20783 272 24X Fiche 50-323, 83/10/06, B310170471
- B310170489 Forwards addl info re alternate methods of statistical evaluation of Superstrut spot weld shear strength test data, in response to NRC request test data evaluation presented in B30701 rept remains reasonable & valid
SCHUYLER, J O Pacific Gas & Electric Co 83/10/07 EISENHUT, D G Division of Licensing 3pp 20783 315 24X Fiche 50-275, 83/10/07, B310170489
- B310210227 Forwards "Seismically Induced Sys Interaction Program (SISIP) Completion of Containment Activities"
SCHUYLER, J O Pacific Gas & Electric Co 83/10/13 EISENHUT, D G Division of Licensing 1p 20892 112 24X Fiche 50-275, 83/10/13, B310210227
- B310210229 "Seismically Induced Sys Interaction Program (SISIP) Completion of Containment Activities"
* Bechtel Corp 83/10/13 262pp 20892 113 24X
Fiche 50-275, 83/10/13, B310210229
- B308300775 Board Notification B3-135A forwards B30919 revised draft of "QA Case Study Working Paper - Case C," & cover & transmittal memos re Diablo Canyon
EISENHUT, D G Division of Licensing 83/10/14 PALLADINO, N J, GILINSKY, V, ROBERTS, T M Commissioners 3pp 20799 001 24X
Fiche 50-000, 83/10/14, B308300775
- B310180505 Informs that working papers for three QA case studies complete, per B30923 memo Case C re Diablo Canyon, dtd B30919, is rev to B30719 draft transmitted in Board Notification B3-135 on B30902 Papers & transmittal ltrs forwarded
TAYLOR, J M QA Branch 83/09/28 EISENHUT, D G Division of Licensing 2pp 20799 004 24X Fiche 50-000, 83/10/14, B308300775
- B310180511 Forwards case study working papers for site, per review program for plant design & const Final Congressional rept will contain consolidated summary of case study conclusions
TAYLOR, J M QA Branch 83/08/02 MANEATIS, O A Pacific Gas & Electric Co 1p 20799 006 24X Fiche 50-000, 83/10/14, B308300775
- B310180517 Forwards revised draft of "QA Case Study Working Paper Case C"
ALTMAN, W D NRC - No Detailed Affiliation Given 83/09/27, - No Detailed Affiliation Given 1p 20799 007 24X
Fiche: 50-000, 83/10/14, B308300775
- B310180521 Revised draft of "QA Case Study Working Paper - Case C"
* NRC - No Detailed Affiliation Given 83/09/19 NRC - No Detailed Affiliation Given 42pp 20799 008 24X
Fiche: 50-000, 83/10/14, B308300775

DOCKETED ITEMS

8310190197 Advises that qualification tests for special rods & couplers revealed straight rods removed from Unit 2 rupture restraints had heat exhibited ductilities less than design. Rods will be reannealed or replaced.
SCHUYLER, J D Pacific Gas & Electric Co 83/10/04 EISENHUT, D G
OILINSKY, V Commissioners 83/10/17 Office of the Executive
Legal Director 20pp 20823 259 24X Fiche 50-275, 83/10/17,
8310190197

8310190054 Forwards documents NRC delivered to Commissioner Gillsky during 831017 briefing on plant design reverification.
OILINSKY, V Commissioners 83/10/17 Office of the Executive
Legal Director 20pp 20823 259 24X Fiche 50-275, 83/10/17,
8310190054

8308310029 Board Notification 83-161 forwards anonymous ltr alleging errors in design/documentation of safety-related sys. structures & components at Unit 1.
EISENHUT, D G Division of Licensing 83/10/18 PALLADINO, M,
OILINSKY, V, ROBERTS, T Commissioners 4pp 20900-075 24X
Fiche 50-275, 83/10/18, 8308310029

2 Security, medical, emergency & fire protection plans

8310040221 Forwards IE Insp Repts 50-275/83-25 & 50-323/83-18 on 830718-22 & 0818 No noncompliance noted.
NORDEHAUS, L R Region 3, Office of Director 83/09/20
SCHUYLER, J D Pacific Gas & Electric Co 2pp 20617 250 24X
Fiche 50-275, 83/09/20, 8310040221

-8310040226 IE Insp Repts 50-275/83-25 & 50-323/83-18 on 830718-22 & 0818 No noncompliance noted. Major areas inspected emergency preparedness program, including emergency detection & classification & protective action decisionmaking.
SCHUYLER, J D Region 3, Office of Director 83/09/19 13pp
20617 252 24X Fiche 50-275, 83/09/20, 8310040221

831006020 Advises that 830803 proposed changes to Rev 11 to physical security plan & Rev 2 to safeguards contingency plan acceptable per 10CFR50.54(p) Encls to ltr withheld (ref 10CFR73.21).
KNIGHTON, O H Licensing Branch 3 83/10/12 SCHUYLER, J D Pacific
Gas & Electric Co 3pp 20817 336 24X Fiche 50-275, 83/10/12,
8310180620

8310270566 Releases public version of revised corporate emergency response plan & revised emergency response plan implementing procedures.
FELDMAN, J M Division of Rules and Records 83/10/25 Document
Management Branch 1p 20945 007 24X Fiche 50-275, 83/10/25,
8310270566

-8310270572 Forwards public version of Rev 2 to corporate emergency response plan & revised emergency response plan implementing procedures.
SCHUYLER, J D Pacific Gas & Electric Co 83/10/10 MARTIN, J B
Region 3, Office of Director 3pp 20945 008 24X
Fiche 50-275, 83/10/25, 8310270566

-8310270573 Public version of Rev 2 to corporate emergency response plan.
SCHUYLER, J D Pacific Gas & Electric Co 83/09/12 85pp
20945 011 24X Fiche 50-275, 83/10/25, 8310270566

-8310270580 Public version of revised corporate emergency response plan implementing procedures, including Procedures 3.1 re governmental relations, 3.2 re corporate communications dept & 3.3 re law.
SCHUYLER, J D Pacific Gas & Electric Co 83/10/04 300pp
20945-096 24X Fiche 50-275, 83/10/25, 8310270566

8310270582 Releases public version of revised emergency plan implementing procedures.
FELDMAN, J M Division of Rules and Records 83/10/25 Document
Management Branch 1p 20946 099 24X Fiche 50-275, 83/10/25,
8310270582

8310270586 Forwards public version of revised emergency plan implementing procedures, including Procedures 2.1 re plant maint, 3.4 re insurance & 3.5 re security.
SCHUYLER, J D Pacific Gas & Electric Co 83/09/12 MARTIN, J B
Region 3, Office of Director 3pp 20946 100 24X
Fiche 50-275, 83/10/25, 8310270582

8310270588 Public version of revised emergency plan implementing procedures, including Procedures 2.1 re plant maint, 3.4 re insurance & 3.5 re security.
SCHUYLER, J D Pacific Gas & Electric Co 83/08/16 150pp
20946-103, 24X Fiche 50-275, 83/10/25, 8310270582

G Adjudicatory correspondence

8310260277 Contentions on design QA re verification of samples for IDVP.
STRUMWASSER, M California, State of REYNOLDS, J Joint
Intervenor-Diablo Canyon REYNOLDS, J Center for Law in the Public
Interest 83/09/08 Atomic Safety and Licensing Appeal Panel
103pp 20911 039 24X Fiche 50-275, 83/09/08, 8310260277

8310050371 Confirms 830920 telcon re Governor Deukmejian 830702 request for documents. List of requested documents will be sent by 831004.
MCOURRAN, H J Hearing Branch 3 83/09/26 DURBIN, S California,
State of 1p 20630 354 24X Fiche 50-275, 83/09/26, 8310050371

8310050454 Response opposing Joint Intervenor 830926 request for hearing on lifting of license suspension. No legal basis presented to support hearing. Certificate of Svc encl.
CHANDLER, L J Hearing Branch 2 83/09/26 Commissioners 15pp
20630 040 24X Fiche 50-275, 83/09/26, 8310050454

8310040251 First supplemental responses to interrogatories. Certification of counsel & Certificate of Svc encl. Related correspondence.
LUBBOCK, D G Pacific Gas & Electric Co 83/09/20 California,
State of 7pp 20613 042 24X Fiche 50-275, 83/09/28, 8310040251

8310040288 First supplemental answers to third set of interrogatories. Prof qualifications & Certificate of Svc encl. Related correspondence.
STRUMWASSER, M California, State of 83/09/28 Pacific Gas &
Electric Co 26pp 20614 169 24X Fiche 50-275, 83/09/28,
8310040288

8310050396 First supplemental response to third set of interrogatories. Certificate of Svc encl. Related correspondence.
LUBBOCK, D G Pacific Gas & Electric Co 83/09/28 California,
State of 66pp 20634 186 24X Fiche 50-275, 83/09/28, 8310050396

8310030384 Motion for sanctions against Governor Deukmejian & Joint Intervenor for failure to supply interrogatories seasonably. Intervenor has engaged in concrete course of conduct to delay proceedings. Certificate of Svc encl.
CRANE, P A Pacific Gas & Electric Co 83/09/29 Atomic Safety
and Licensing Appeal Panel 18pp 20542 154 24X
Fiche 50-275, 83/09/29, 8310030384

8310040209 Motion for mod of schedule established in ASI B 830900 order hearing QA hearing. Delay in completion of IDVP renders schedule impossible to meet.
KAUFMAN, P H California, State of 83/09/29 Atomic Safety and
Licensing Appeal Panel 17pp 20614 335 24X Fiche 50-275,
83/09/29, 8310040209

--8310040212 Addl contentions on design QA.
KAUFMAN, P H California, State of REYNOLDS, J Joint
Intervenor-Diablo Canyon REYNOLDS, J Center for Law in the
Public Interest 83/09/29 Atomic Safety and Licensing Appeal
Panel 4pp 20614 352 24X Fiche 50-275, 83/09/29, 8310040209

--8310040219 Application for expedited ruling on motion for mod of hearing schedule. Motion should be ruled on quickly since testimony due 831008. Certificate of Svc encl.
KAUFMAN, P H California, State of 83/09/29 Atomic Safety and
Licensing Appeal Panel 4pp 20614 356 24X
Fiche 50-275, 83/09/29, 8310040209

8310040539 Supplemental response to second set of interrogatories. Certification of counsel & Certificate of Svc encl. Related correspondence.
HAVIAN, E R Joint Intervenor-Diablo Canyon HAVIAN, E R Center
for Law in the Public Interest 83/09/29 Pacific Gas & Electric
Co 7pp 20624 019 24X Fiche 50-275, 83/09/29, 8310040539

8310040302 Order extending time until 831007 for Commission to act to review ALAB-728.
CHILK, S J Office of the Secretary of the Commission 83/09/30
Commissioners 1p 20614 168 24X Fiche 50-275, 83/09/30,
8310040302

8310040525 Forwards author notice of appearance. Certificate of Svc encl.
LUBBOCK, D G Pacific Gas & Electric Co 83/09/30 Docketing &
Services Branch 4pp 20624 226 24X Fiche 50-275, 83/09/30,
8310040525

8310070209 Staff requirements memo re 830927 discussion of proceeding schedule. Commission will hold 831028 public meeting in Washington, DC re issues related to fuel loading.
CHILK, S J Office of the Secretary of the Commission 83/09/30
Office of the Secretary of the Commission 1p 20676 362 21X
Fiche 50-275, 83/09/30, 8310070209

DOCKETED ITEMS

167

8310050421 Fourth supplemental response to first set of interrogatories Certificate of Svc encl
REYNOLDS, J Joint Intervenor-Diablo Canyon REYNOLDS, J Center
for Law in the Public Interest 83/10/03 Pacific Gas & Electric
Co 9pp 20630 334 24X Fiche 50-275, 83/10/03, 8310050421

8310110053 Answer opposing util motion for sanctions for alleged failures to suppl interrogatory answer seasonably Motion wholly unfounded & should be denied Declaration of counsel & Certificate of Svc encl
STRUMWASSER, M California, State of 83/10/04 Atomic Safety and Licensing Appeal Panel 21pp 20668 244 24X Fiche 50-275, 83/10/04, 8310110053

8310110058 Forwards Page 41 of Nuclear Svcs Corp audit of Pullman Power Products filed w/Joint Intervenor 830909 suppl to motion to reopen record on const QA issue
REYNOLDS, J Center for Law in the Public Interest REYNOLDS, J Joint Intervenor-Diablo Canyon 83/10/04 Atomic Safety and Licensing Appeal Panel 2pp 20668 239 24X Fiche 50-275, 83/10/04, 8310110058

8310110073 Response opposing Governor Deukmejian & Joint Intervenor 830929 addl contentions on QA Contentions lack specificity &/or fail to meet criteria for late-filed contentions Certificate of Svc encl
LOCKER, R F Pacific Gas & Electric Co 83/10/04 Atomic Safety and Licensing Appeal Panel 6pp 20667 299 24X Fiche 50-275, 83/10/04, 8310110073

8310110120 Response opposing Governor Deukmejian 830907 motion to modify schedule for conduct of hearings Motion is only another unsubstantiated ploy for delay Certificate of Svc encl
NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke, Berry & French 83/10/04 Atomic Safety and Licensing Appeal Panel 12pp 20666 212 24X Fiche 50-275, 83/10/04, 8310110120

8310110127 Response opposing licensee motions for sanctions against Governor Deukmejian & Joint Intervenor Intervenor supplemented interrogatory answers in timely manner Certificate of Svc encl
REYNOLDS, J Joint Intervenor-Diablo Canyon REYNOLDS, J Center for Law in the Public Interest 83/10/04 Atomic Safety and Licensing Appeal Panel 8pp 20666 204 24X Fiche 50-275, 83/10/04, 8310110127

8310110317 Response supporting Governor Deukmejian 830929 motion for mod of hearing schedule Deposition schedule not completed & time for filing contentions expired prior to issuance of IDVP repts Certificate of Svc encl
REYNOLDS, J Joint Intervenor-Diablo Canyon REYNOLDS, J Center for Law in the Public Interest 83/10/04 Atomic Safety and Licensing Appeal Panel 6pp 20665 358 24X Fiche 50-275, 83/10/04, 8310110317

8310120418 Response of IDVP to Interrogatory 57 in third set of interrogatories Certificate of Svc encl Related correspondence
RABKIN, D B Lowenstein, Newman, Reis, Axelrad & Toll 83/10/05 STRUMWASSER, M California, State of 7pp 20699 044 24X Fiche 50-275, 83/10/05, 8310120418

8310130017 Response opposing Governor Deukmejian 830927 motion for 2-wk extension of discovery schedule set in ASLAB 830907 order Governor began discovery process only 3 wks before hearing Extension would delay hearing
CHANDLER, L J Hearing Branch 2 83/10/05 Atomic Safety and Licensing Appeal Panel 7pp 20725 191 24X Fiche 50-275, 83/10/05, 8310130017

--8310130019 Response supporting licensee 830929 motion for sanctions upon Governor Deukmejian/Joint Intervenor Depositions of Apostolakis, Kempthorne & Hubbard should be held during wk of 831010-14 Certificate of Svc encl
CHANDLER, L J Hearing Branch 2 83/10/05 Atomic Safety and Licensing Appeal Panel 6pp 20725 198 24X Fiche 50-275, 83/10/05, 8310130019

8310130163 Response to 830902 document request consisting of computer printout listing documents in docket since 81101 Documents to be copied should be identified
MCQUARREN, H J Hearing Branch 1 83/10/05 DURBIN, S L California, State of 4pp 20724 280 24X Fiche 50-275, 83/10/05, 8310130163

8310110298 Application for subpoena for G Apostolakis for 831011 deposition & production of documents
NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke, Berry & French 83/10/06 Atomic Safety and Licensing Appeal Panel 4pp 20666 100 24X Fiche 50-275, 83/10/06, 8310110298

--8310110301 Notice of G Apostolakis deposition on 831011 in San Francisco, CA Certificate of Svc encl
NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke, Berry & French 83/10/06 4pp 20666 104 24X Fiche 50-275, 83/10/06, 8310110301

8310120376 Second supplemental answers to first set of interrogatories Certification of counsel & prof qualifications encl
DURBIN, S L California, State of 83/10/07 Pacific Gas & Electric Co 28pp 20699 132 24X Fiche 50-275, 83/10/07, 8310120376

--8310120381 First supplemental answers to second set of interrogatories Certification of counsel encl
DURBIN, S L California, State of 83/10/07 Pacific Gas & Electric Co 17pp 20699 160 24X Fiche 50-275, 83/10/07, 8310120376

--8310120386 First supplemental answers to fourth set of interrogatories Certification of counsel & Certificate of Svc encl
DURBIN, S L California, State of 83/10/07 Pacific Gas & Electric Co 8pp 20699 177 24X Fiche 50-275, 83/10/07, 8310120376

8310120385 Order confirming 831005 oral rulings during telcon re reopened proceeding on design QA Governor Deukmejian 830929 motion for mod of schedule granted in part
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/07 8pp 20699 185 24X Fiche 50-275, 83/10/07, 8310120385

8310120412 Order extending time until 831017 for Commission to act to review ALAB-728
CHILK, S J Office of the Secretary of the Commission 83/10/07 Commissioners 1p 20698 052 24X Fiche 50-275, 83/10/07, 8310120412

8310130243 Fifth supplemental response to first set of interrogatories Portions of RB Hubbard & FJ Samaniego 821221 direct testimony & Certificate of Svc encl
REYNOLDS, J Joint Intervenor-Diablo Canyon REYNOLDS, J Center for Law in the Public Interest 83/10/07 Pacific Gas & Electric Co 19pp 20723 253 24X Fiche 50-275, 83/10/07, 8310130243

8310180160 Motion for leave to file reply to NRC & util responses to Joint Intervenor 830709 suppl to motion to reopen record on const QA Responses raised defenses & relied on documents not previously part of record Certificate of Svc encl
REYNOLDS, J Joint Intervenor-Diablo Canyon REYNOLDS, J Center for Law in the Public Interest 83/10/13 Atomic Safety and Licensing Appeal Panel 6pp 20809 147 24X Fiche 50-275, 83/10/13, 8310180160

8310180248 Response to Governor Deukmejian, NRC & util replies to Joint Intervenor 830709 suppl to motion to reopen record on const QA NSC audit repts provides irrefutable evidence of breakdown in Pullman QA program Certificate of Svc encl
REYNOLDS, J Joint Intervenor-Diablo Canyon REYNOLDS, J Center for Law in the Public Interest 83/10/13 Atomic Safety and Licensing Appeal Panel 12pp 20802 320 24X Fiche 50-275, 83/10/13, 8310180248

8310190219 Motion for order of enforcement of ASLAB 831007 order directing Governor Deukmejian & Joint Intervenor to suppl interrogatory responses & documents requested Parties failed to provide required documents Certificate of Svc encl
CRANE, P A Pacific Gas & Electric Co 83/10/13 Atomic Safety and Licensing Appeal Panel 8pp 20818 037 24X Fiche 50-275, 83/10/13, 8310190219

8310180328 Second supplemental response to third set of interrogatories Certificate of Svc encl Related correspondence
LUBBOCK, D O Pacific Gas & Electric Co 83/10/14 DEUKMEJIAN California, State of 14pp 20806 162 24X Fiche 50-275, 83/10/14, 8310180328

8310210228 Forwards PJ Kempthorne & FI Samaniego testimony REYNOLDS, J R Center for Law in the Public Interest 83/10/15 MOORE, T S Atomic Safety and Licensing Appeal Panel 1p 20852 042 24X Fiche 50-275, 83/10/15, 8310210228

--8310210242 Exhibit list Certificate of Svc encl
REYNOLDS, J Joint Intervenor-Diablo Canyon REYNOLDS, J Center for Law in the Public Interest 83/10/15 6pp 20852 065 24X Fiche 50-275, 83/10/15, 8310210228

8310200178 Testimony of RB Hubbard re design QA Verification program has not yet demonstrated plant design complies w/all applicable NRC regulatory requirements & all util licensing criteria Related correspondence
HUBBARD, R B California, State of 83/10/16 7pp 20839 127 24X Fiche 50-275, 83/10/16, 8310200178

DOCKETED ITEMS

--8310200195 List of exhibits identified per ASLAB 831007 order
Certificate of Svc encl
STRUMWASSER, M California, State of 83/10/16 9pp 20834 287
24X Fiche 50-275, 83/10/16, 8310200170

8310190054 Forwards documents NRC delivered to Commissioner Gilinsky
during 831017 briefing on plant design reversionification
GILINSKY, V Commissioners 83/10/17 Office of the Executive
Legal Director 20pp 20823 259. 24X Fiche 50-275, 83/10/17,
8310190054

8310190261 Order extending time until 831028 for Commission to act to
review ALAB-728
CHILK, S J Office of the Secretary of the Commission 83/10/17
Commissioners 1p 20818 082 24X Fiche 50-275, 83/10/17,
8310190261

8310270338 Forwards addl copies of direct testimony & accompanying
matls Sky Courier & Eastern Airlines lost original
transmittals Inconvenience regretted
STRUMWASSER, M California, State of 83/10/17 MOORE, T S Atomic
Safety and Licensing Appeal Panel 1p 20923 302 24X
Fiche 50-275, 83/10/17, 8310270338

--8310270348 Answer opposing util 831013 motion for order of enforcement
Util violated order several times Grounds for requested
relief nonexistent
STRUMWASSER, M California, State of. 83/10/17 Atomic Safety
and Licensing Appeal Panel 7pp 20923 303 24X
Fiche 50-275, 83/10/17, 8310270338

--8310270377 Affidavit of RD Hubbard re safety-related aspects of QA
programs Prof qualifications & Certificate of Svc encl
HUBBARD, R B California, State of 83/10/21 17pp 20923 310.
24X Fiche 50-275, 83/10/17, 8310270338

8310250283 Forwards US Court of Appeals, DC Circuit, 831007 amended
opinion affirming NRC denial of Atty General Bellotti
petition to intervene
CHANDLER, L J Hearing Branch 2 83/10/18 CHILK, S J Office of
the Secretary of the Commission 23pp 20894 232 24X
Fiche 50-275, 83/10/18, 8310250283

8310240158 Motion for revocation of License DPR-76, or in alternative,
for continuation of suspension Continuing nature of matl
false statements & unresolved questions re adequacy of const
unacceptable Certificate of Svc encl
REYNOLDS, J Joint Intervenor-Diablo Canyon. REYNOLDS, J Center
for Law in the Public Interest 83/10/20 Commissioners 68pp
20881 224 24X Fiche 50-275, 83/10/20, 8310240158

8310240174 Objection to Joint Intervenor proposed Exhibits 12B & 129
& State of CA Governor Exhibit 11 re design QA Exhibits
irrelevant & immaterial to proceeding Certificate of Svc
encl
CRANE, P A Pacific Gas & Electric Co 83/10/20. Atomic Safety
and Licensing Appeal Panel 4pp 20880 030 24X
Fiche 50-275, 83/10/20, 8310240174

9310250043 Objections to util & NRC exhibits & testimony, per ASLAB
831007 order Certificate of Svc encl
HAVIAN, E Joint Intervenor-Diablo Canyon HAVIAN, E Center for
Law in the Public Interest 83/10/20 Atomic Safety and Licensing
Appeal Panel 6pp 20894 081 24X Fiche 50-275, 83/10/20,
8310250043

310250467 Comments on Joint Intervenor & Governor Deukmejian
testimony & proposed exhibits, per ASLB 831007 order, Governor
Exhibits 27-31 not provided for review Exhibits 129 & 132
acceptable
CHANDLER, L J Hearing Branch 2 83/10/21 MOORE, T S, BUCK, J H.
JOHNSON, W R Atomic Safety and Licensing Board Panel 2pp
20897 102 24X Fiche 50-275, 83/10/21, 8310250467

8310260236 Submits suppl to 830901 comments on IDVP final rept &
SBER 18 re reissuance of suspended license for fuel
loading & low power operation License reissuance opposed
Certificate of Svc encl
REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J R
Joint Intervenor-Diablo Canyon 83/10/24 PALLADINO, N J.
GILINSKY, V, ROBERTS, T Commissioners 14pp 20912 192 24X
Fiche 50-275, 83/10/24, 8310260236.

8310260270 Order denying Joint Intervenor 830510 & Governor
Deukmejian 830517 motions to reopen record re adequacy of
applicant const QA program. Motions fail to meet stds
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/24
Joint Intervenor-Diablo Canyon 2pp 20911 309. 24X
Fiche 50-275, 83/10/24, 8310260270

8310310141 Notice of withdrawal of Contentions 3c, d, e, g, i, j, k & n re
design QA Failures Contentions found to be within licensing
criteria or were resolved by addl technical info Certificate
of Svc encl
DURBIN, S L California, State of REYNOLDS, J R Joint
Intervenor-Diablo Canyon REYNOLDS, J R Center for Law in the
Public Interest 83/10/24 16pp 20959 019 24X
Fiche 50-275, 83/10/24, 8310310141

8310270263 Answer opposing Joint Intervenor 831020 motion for
revocation of UL or for continuation of suspension Applicant
has not misrepresented or failed to disclose facts
Certificate of Svc encl
CRANE, P A Pacific Gas & Electric Co 83/10/25 Commissioners
13pp 20922 028 24X Fiche 50-275, 83/10/25, 8310270263

8310270358 Forwards Joint Intervenor & Governor Deukmejian revised
contentions on design QA, replacing Exhibit 1 transmitted
w/831024 ltr
REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J R
Joint Intervenor-Diablo Canyon 83/10/25 PALLADINO, N J.
GILINSKY, V, ROBERTS, T Commissioners 1p 20923 294 24X
Fiche 50-275, 83/10/25, 8310270358

--8310270361 Issues to be contested by Governor Deukmejian & Joint
Intervenor
* Joint Intervenor-Diablo Canyon 83/10/24 /pp 20923 295
24X Fiche 50-275, 83/10/25, 8310270358

8310280097 Reply to util objections to Joint Intervenor proposed
exhibits Objections should be overruled Certificate of Svc
encl
HAVIAN, E Joint Intervenor-Diablo Canyon HAVIAN, E Center for
Law in the Public Interest 83/10/25 Atomic Safety and Licensing
Appeal Panel 8pp 20935 066 24X Fiche 50-275, 83/10/25,
8310280097

8310310181 Requests DC Treppa encl 831021 ltr be placed in PDR & copies
served on parties to proceeding
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/27
Docketing & Services Branch 1p 20958 361 24X
Fiche 50-275, 83/10/27, 8310310181

--8310310184 Expresses concern re reissuing low power test license for
facility License should be revoked & facility ordered to
shut down
TREPPA, D C Affiliation Unknown 83/10/21 ROSENTHAL, A S NRC -
No Detailed Affiliation Given 1p 20958 362 24X
Fiche 50-275, 83/10/27, 8310310181

H General correspondence

8310180270 Clarifies position of interjurisdictional planning
committee for agencies surrounding facility, emphasizing
importance of FEMA coordination of federal agency responses
to nuclear plant accidents
COLEMAN, R J San Clemente, CA 83/10/10 NRC - No Detailed
Affiliation Given 2pp 20807 050 24X Fiche 50-275, 83/10/10,
8310180270

8310200175 Responds to 830717 & 830820 ltrs re safety & redundancy of
valve failure modes IE Insp Repts 50-275/82-26,
50-323/82-13 & 50-275/82-42 encl further investigation
revealed tracking & documentation of repts out of date
BISHOP, T W Division of Resident Reactor Project & Engineering
Programs 83/10/17 COOPER, J H Affiliation Unknown 2pp
20825 316 24X Fiche 50-275, 83/10/17, 8310200175

d Inspection reports, IE Bulletins & correspondence

8310250414 Forwards std order for DOE work, "Specialized Insp
Support - Technical Assistance for Diablo Canyon - Design
Verification Program"
ADAMS, C Energy, Dept of FIN B-8552 83/09/16 MARTIN, J B
Region 5, Office of Director 1p 20897 184 24X
Fiche 50-275, 83/09/16, 8310250414

--8310250423 Std order for DOE work "Specialized Insp Support -
Technical Assistance for Diablo Canyon - Design Verification
Program," issued to LLL
MARTIN, J B Region 5, Office of Director MACRUSKY, J Energy,
Dept of FIN B-8552 83/09/16 1p 20897 185 24X
Fiche 50-275, 83/09/16, 8310250414

8310040221 Forwards IE Insp Repts 50-275/83-25 & 50-323/83-18 on
830718-22 & 0818 No noncompliance noted
NORDEHAUG, L R Region 5, Office of Director 83/09/20
SCHUYLER, J D Pacific Gas & Electric Co 2pp 20611 250 24X
Fiche 50-275, 83/09/20, 8310040221

DOCKETED ITEMS

169

-B310040226 IE Insp Repts 50-275/83-25 & 50-323/83-18 on B3018 12 & 0818 No noncompliance noted Major areas inspected emergency preparedness program, including emergency detection & classification & protective action decisionmaking
STOWN, K., SCHUSTER, M D Region 5, Office of Director 07/09/19 13pp 20617 252 24X Fiche 50-275, 83/09/20, B310040226

B310170473 Forwards IE Insp Repts 50-275/83-28 & 50-323/83-20 on B30731-0403 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 03/09/22 SCHUYLER, J O Pacific Gas & Electric Co 2pp 20783 305 24X Fiche 50-275, 83/09/22, B310170473

-B310170479 IE Insp Repts 50-275/83-28 & 50-323/83-20 on B30731 09/03 No noncompliance noted Major areas inspected plant operations, surveillance testing, maint, independent insp & followup of noncompliances, open items, allegation & preoperational tests
CARLSON, J D, MENDONCA, M M, KIRSCH, D F Region 5, Office of Director 03/09/21 8pp 20783 307 24X Fiche 50-275, 83/09/22, B310170479

B308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 03/09/26 Consolidated Edison Co of New York, Inc 11pp 20754 022 24X Fiche 50-000, 83/09/26, B308300340

B308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 03/09/26 Consolidated Edison Co of New York, Inc 11pp 20777 210 24X Fiche 50-000, 83/09/26, B308300342

B308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 03/09/26 Consolidated Edison Co of New York, Inc 11pp 20778 001 24X Fiche 50-000, 83/09/26, B308300345

B308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 54 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 03/09/29 Consolidated Edison Co of New York, Inc 11pp 20716 324 24X Fiche 50-000, 83/09/29, B308300349

B308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 03/10/07 Consolidated Edison Co of New York, Inc 7pp 20827 213 24X Fiche 50-000, 83/10/07, B308300378

B308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 03/10/07 Consolidated Edison Co of New York, Inc 7pp 20882 026 24X Fiche 50-000, 83/10/07, B308300752

B308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 03/10/11 Consolidated Edison Co of New York, Inc 11pp 21043 075 24X Fiche 50-000, 83/10/11, B308300759

B308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 03/10/11 Consolidated Edison Co of New York, Inc 12pp 20827 127 24X Fiche 50-000, 83/10/11, B308300761

B310310332 Forwards IE Insp Repts 50-275/83-29 & 50-323/83-21 on B30829-0902 & 06-09 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 03/10/13 SCHUYLER, J O Pacific Gas & Electric Co 2pp 20960 311 24X Fiche 50-275, 83/10/13, B310310332

-B310310341 IE Insp Repts 50-275/83-29 & 50-323/83-21 on B30829 09/02 & 06-09 No noncompliance noted Major areas inspected const activities, including licensee action on previous insp findings, IE info notices & deficiencies under 10CFR50 55e
HERNANDEZ, G H, KIRSCH, D F Region 5, Office of Director 03/10/07 11pp 20960 313 24X Fiche 50-275, 83/10/13, B310310341

-B310310346 "Insp Repts," Jul 1983
* EG&G, Inc FIN B 8552 83/07/31 NRC - No Detailed Affiliation Given 12pp 20960 324 24X Fiche 50-275, 83/10/13, B310310346

--B310310354 "Insp Repts," Aug 1983
* EG&G, Inc FIN B-8522 83/08/31 NRC - No Detailed Affiliation Given 21pp 20960 336 24X Fiche 50-275, 83/10/13, B310310354

B310200180 Ack receipt of B3092/ ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-275/83-24 & 50-323/83-17
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 03/10/14 SCHUYLER, J O Pacific Gas & Electric Co 1p 20835 072 24X Fiche 50-275, 83/10/14, B310200180

--B310200183 Responds to NRC B30824 ltr re violations noted in IE Insp Repts 50-275/83-24 & 50-323/83-17 Corrective actions locking devices on Unit 1 pipe support 46-9V existed on both spring cans Turnbuckles verified by Pullman Power Products
SCHUYLER, J O Pacific Gas & Electric Co 83/09/27 MARTIN, J B Region 5, Office of Director 6pp 20835 073 24X Fiche 50-275, 83/10/14, B310200180

B310310246 Forwards IE Insp Repts 50-275/83-30 & 50-323/83-22 on B30904-1001 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 03/10/14 SCHUYLER, J O Pacific Gas & Electric Co 2pp 20947 182 24X Fiche 50-275, 83/10/14, B310310246

--B310310251 IE Insp Repts 50-275/83-30 & 50-323/83-22 on B30904-1001 No noncompliance noted Major areas inspected surveillance testing, maint, independent insp, followup of open items & allegations, preoperational testing/results & plant tours
MENDONCA, M M, KIRSCH, D F Region 5, Office of Director 83/10/13 10pp 20947 184 24X Fiche 50-275, 83/10/14, B310310246

B310280036 Ack receipt of B30916 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-275/83-13 & 50-323/83-10
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 03/10/21 SCHUYLER, J O Pacific Gas & Electric Co 1p 20934 325 24X Fiche 50-275, 83/10/21, B310280036

--B310280048 Responds to NRC B30519 ltr re violations noted in IE Insp Repts 50-275/83-13 & 50-323/83-10 Corrective actions sys for maintaining welder qualification files revised Only qualified welders on active list allowed to draw rods
SCHUYLER, J O Pacific Gas & Electric Co 83/09/16 MARTIN, J B Region 5, Office of Director 5pp 20934 326 24X Fiche 50-275, 83/10/21, B310280036

B310310274 Forwards Allegation RV-83-A-0047 re RHR sys Allegations previously addressed in IE Insp Rept 50-275/82-42 in response to B20820 ltr Task interface agreement suggested
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 03/10/26 EISENHUT, D G Division of Licensing 2pp 20961 303 24X Fiche 50-275, 83/10/26, B310310274

--B310310281 Ack receipt of NRC response to B20820 allegations re facility RHR sys Allegations paraphrased by inspector in IE Insp Rept 50-275/82-42 misinterpreted
COOPER, J H Affiliation Unknown 83/10/20 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 8pp 20961 305 24X Fiche 50-275, 83/10/26, B310310274

R Periodic operating reports & related correspondence

B308300781 Board Notification 83-156 forwards RL Cloud Assoc & Teledyne Engineering Svcs re IDVP
EISENHUT, D G Division of Licensing 83/10/14 PALLADINO, N, OLINSKY, V, ROBERTS, T Commissioners 4pp 20875 122 24X Fiche 50-275, 83/10/14, B308300781

B310210284 Forwards Rev 14 to "Design Verification Program Phase 1 Final Rept "
SCHUYLER, J O Pacific Gas & Electric Co 83/10/14 EISENHUT, D G Division of Licensing 2pp 20850 232 24X Fiche 50-275, 83/10/14, B310210284

--B310210288 Rev 14 to "Design Verification Program Phase 1 Final Rept "
* Pacific Gas & Electric Co 83/10/14 17pp 20850 234 24X Fiche 50-275, 83/10/14, B310210284

S Reportable occurrences, LLRs & related correspondence

B310210066 PNO-V-83-044 on B31003, employee suffered heart attack during work Personnel taken to hosp No news release planned
MORRILL, P J Region 5, Office of Director 83/10/04 1p 20696 157 24X Fiche 50-275, 83/10/04, B310210066

DOCKETED ITEMS

T Hearing transcripts on non-antitrust matters

8310050442 Transcript of Commission B30927 briefing in Washington, DC re facility schedule Pp 1-34 Viewgraphs & supporting documentation encl
* Commissioners 83/09/27 52pp 20640 218 24X
Fiche 50-275,83/09/27,8310050442

8310180354 Forwards IDVP testimony
AXELRAD, M Lowenstein, Newman, Reis, Axelrad & Toll 83/10/14
MOORE, T S, BUCK, J H, JOHNSON, W R Atomic Safety and Licensing
Appeal Panel 2pp 20804 104 24X Fiche 50-275,83/10/14,
8310180354

--8310180361 Testimony of WE Cooper, RL Cloud, JE Krechting & RF Reedy on behalf of IDVP re Contentions 1,2 & 5-B Describes role of IDVP in verification of design work of plant & how IDVP performed work
COOPER, W E, CLOUD, R L, KRECHTING, J E Lowenstein, Newman, Reis, Axelrad & Toll 83/10/14 57pp 20604 106 24X
Fiche 50-275,83/10/14,8310180354

--8310180369 Testimony of RL Cloud, JM Biggs, MJ Holley & R Wray on behalf of IDVP re Contentions 3 & 4 m n Discusses allegations of internal technical program use of improper engineering stds to determine if license criteria met
CLOUD, R L, BIGGS, J M, HOLLEY, J Lowenstein, Newman, Reis, Axelrad & Toll 83/10/14 33pp 20604 165 24X
Fiche 50-275,83/10/14,8310180354

--8310180375 Testimony of JE Krechting & WE Cooper on behalf of IDVP re Contention 4 a -1 & a -u Discusses allegations that IDVP accepted deviations from licensing criteria w/o adequate engineering justifications Certificate of Svc encl
KRECHTING, J E, COOPER, W E Lowenstein, Newman, Reis, Axelrad & Toll 83/10/14 71pp 20604 198 24X Fiche 50-275,83/10/14,8310180394

8310210350 Forwards NRC testimony
MCGURREN, H J Hearing Branch 1 83/10/14 MOORE, T S, BUCK, J H, JOHNSON, W R Atomic Safety and Licensing Appeal Panel 5pp
20849 140 24X Fiche 50-275,83/10/14,8310210350

--8310210355 Testimony of JP Knight, HE Schierling & JS Wermiel on Governor Deukmejian & Joint Intervenor's Contentions 1a-e
KNIGHT, J P Assistant Director for Comp & Structures Engineering (Post 830201) SCHIERLING, H E Division of Licensing
WERMIEL, J S Auxiliary Systems Branch 83/10/14 32pp
20849 145 24X Fiche 50-275,83/10/14,8310210350

--8310210357 Testimony of JP Knight, HE Schierling & JS Wermiel on Governor Deukmejian & Joint Intervenor's Contentions 2a, 2b & 2c
KNIGHT, J P Assistant Director for Comp & Structures Engineering (Post 830201) SCHIERLING, H E Division of Licensing
WERMIEL, J S Auxiliary Systems Branch 83/10/14 9pp
20849 177 24X Fiche 50-275,83/10/14,8310210350

--8310210358 Testimony of JP Knight, P Kuo, HE Polk, CA Miller, AJ Philippopoulos, CJ Constantino & PG Wang re Governor Deukmejian & Joint Intervenor's Contention 3
KNIGHT, J P Assistant Director for Comp & Structures Engineering (Post 830201) KUO, P, POLK, H E Structural & Geotechnical Engineering Branch 83/10/14 25pp 20849 186 24X
Fiche 50-275,83/10/14,8310210350

--8310210371 Testimony of JS Wermiel on Governor Deukmejian & Joint Intervenor's Contentions 4a, 4b, 4p, 4q, 4r & 4s
WERMIEL, J S Auxiliary Systems Branch 83/10/14 10pp
20849 211 24X Fiche 50-275,83/10/14,8310210350

--8310210382 Testimony of JL Knox re Governor Deukmejian & Joint Intervenor's Contentions 4b, 4c, 4g, 4o, 4t & 4u
KNOX, J L Division of Systems Integration (post 811005)
83/10/14 8pp 20849 221 24X Fiche 50-275,83/10/14,8310210350

--8310210392 Testimony of TG Dunning re Governor Deukmejian & Joint Intervenor's Contention 4a, Parts d, e & f
DUNNING, T G Instrumentation & Control Systems Branch 83/10/14 10pp 20849 229 24X Fiche 50-275,83/10/14,8310210350

--8310210398 Testimony of DJ Kubicki on Governor Deukmejian & Joint Intervenor's Contentions 4a, 4j & 4k
KUBICKI, D J Chemical Engineering Branch 83/10/14 14pp
20849 239 24X Fiche 50-275,83/10/14,8310210350

--8310210391 Testimony of P Kuo & HE Polk on Governor Deukmejian & Joint Intervenor's Contention 4n
KUO, P, POLK, H E Structural & Geotechnical Engineering Branch 83/10/14 3pp 20849 253 24X Fiche 50-275,83/10/14,8310210350

--8310210378 Testimony of PJ Morrill on Governor Deukmejian & Joint Intervenor's Contentions 5 & 8
MORRILL, P J Division of Resident Reactor Project & Engineering Programs 83/10/14 6pp 20849 254 24X Fiche 50-275,83/10/14,8310210350

--8310210381 Testimony of WP Haass on Governor Deukmejian & Joint Intervenor's Contentions 6 & 8
HAASS, W P OA Branch 83/10/14 4pp 20849 262 24X
Fiche 50-275,83/10/14,8310210350

--8310210385 Testimony of JP Knight & HE Schierling on Governor Deukmejian & Joint Intervenor's Contention 7
KNIGHT, J P Assistant Director for Comp & Structures Engineering (Post 830201) SCHIERLING, H E Division of Licensing 83/10/14 6pp 20849 266 24X Fiche 50-275,83/10/14,8310210350

--8310210387 Testimony of JS Wermiel on Governor Deukmejian & Joint Intervenor's addl contentions on design, QA, Contention 9
WERMIEL, J S Auxiliary Systems Branch 83/10/14 168pp
20849 272 24X Fiche 50-275,83/10/14,8310210350

8310210228 Forwards PJ Kempthorne & FI Samaniego testimony
REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J R Joint Intervenor's- Diablo Canyon 83/10/15 MOORE, T S, JOHNSON, W R, BUCK, J H Atomic Safety and Licensing Appeal Panel 1p 20852 042 24X Fiche 50-275,83/10/15,8310210228

--8310210241 Testimony of PJ Kempthorne & FJ Samaniego re Contentions 1 on IDVP conclusions in light of sampling methodology Prof qualifications encl
KEMPTHORNE, P J, SAMANIEGO, F J Joint Intervenor's- Diablo Canyon 83/10/15 22pp 20852 043 24X Fiche 50-275,83/10/15,8310210228

8310200178 Testimony of RB Hubbard re design QA Verification program has not yet demonstrated plant design complies w/all applicable NRC regulatory requirements & all util licensing criteria Related correspondence
HUBBARD, R B California, State of HUBBARD, R B MHB Technical Associates 83/10/16 77pp 20835 127 24X Fiche 50-275,83/10/16,8310200178

--8310200184 Testimony of G Apostolakis re design QA IDVP weak since program fails to recognize implications of decision to cart IDVP in probabilistic terms & fails to use appropriate probabilistic analysis principles & methods
APOSTOLAKIS, G California, State of APOSTOLAKIS, G California, Univ of, Los Angeles, CA 83/10/16 21pp 20835 208 24X
Fiche 50-275,83/10/16,8310200178

--8310200170 Testimony of JM Roesset re adequacy of util seismic modeling of structures & soils & of review of util work by IDVP Four issues remain requiring further verification Affidavits of qualifications encl
ROESSET, J M California, State of 83/10/16 61pp 20835 229 24X Fiche 50-275,83/10/16,8310200178

8310250326 Forwards corrected Pages 5,6 & 8 to NRC 831014 testimony of JP Knight, HE Schierling & JS Wermiel on Governor Deukmejian & Joint Intervenor's Contentions 2a-e errors due to difficulties w/word processing
MCGURREN, H J Hearing Branch 1 83/10/19 MOORE, T S, BUCK, J H, JOHNSON, W R Atomic Safety and Licensing Appeal Panel 8pp
20897 340 24X Fiche 50-275,83/10/19,8310250326

--8310250332 Corrected Pages 5,6 & 8 to JP Knight, HE Schierling & JS Wermiel testimony on Governor Deukmejian & Joint Intervenor's Contentions 2a-e
KNIGHT, J P, SCHIERLING, H E, WERMIEL, J S NRC - No Detailed Affiliation Given 83/10/19 3pp 20897 342 24X
Fiche 50-275,83/10/19,8310250326

8310250176 Forwards H Schierling, W Haass & D Kubicki depositions & corrections to deposition transcripts w/o depositions
MCGURREN, H J Hearing Branch 1 83/10/20 Tayloe Associates 1p 20892 354 24X Fiche 50-275,83/10/20,8310250176

--8310250182 Corrections to WP Haass 830921, DJ Kubicki 830920 & HE Schierling 830921 depositions
HAASS, W P, KUBICKI, D J, SCHIERLING, H E NRC - No Detailed Affiliation Given 83/09/21 4pp 20892 355 24X
Fiche 50-275,83/10/20,8310250176

8310280057 Transcript of witness testimony, prof qualifications & exhibits for reopened hearing re design QA Certificate of Svc encl Related correspondence
* Pacific Gas & Electric Co 83/10/27 554pp 20935 328 24X
Fiche 50-275,83/10/27,8310280057

DOCKETED ITEMS

171

U Congressional/Executive Correspondence

8310110114 Ack receipt of comments on plant licensing Commission deferred final consideration of matter until after NRC completes analysis of final IDVP rept
CHILK, S J Office of the Secretary of the Commission 83/10/05 Jpp
HART, G K, CHACON, P, DAVIS, G California, State of 20668 151 24X Fiche 50-275, 83/10/05, 8310110114

8310200442 Responds to 830927 ltr re NRL handling of several working papers for case studies being conducted to support NRC rept to Congress per Section 13 of NRC Authorization Act Three working papers encl
PALLADINO, N J Commissioners 83/10/07 FORD, W H Senate 3pp 20871 295 24X Fiche 50-000, 83/10/07, 8310200442

--8310200469 Expresses disappointment re release of draft study on OA programs at Diablo Canyon to licensee Full explanation requested
MARKEY, C J House of Rep, Interior & Insular Affairs 83/07/21 PALLADINO, N J Commissioners 2pp 20872 217 24X Fiche 50-000, 83/10/07, 8310200469

8310240169 Advises that State of CA legislator ltrs requesting delays in licensing do not represent policy of CA legislature License issuance recommended
ALQUIST, A C California, State of 83/10/17 PALLADINO, N J Commissioners in 20880 029 24X Fiche 50-275, 83/10/17, 8310240169

8310250045 Urges NRC to proceed w/o delay w/regulatory steps necessary to allow fuel loading, low power testing & commercial operation
BILLS, R C California, State of 83/10/19 PALLADINO, N J Commissioners 2pp 20894 049 24X Fiche 50-275, 83/10/19, 8310250045

V Operator Examinations

8310030285 Informs of periodic audits of licensed operator requalification programs Schedule for requalification training & exams requested by 831028
BISHOP, T W Division of Resident Reactor Project & Engineering Programs 83/09/26 SCHUYLER, J O Pacific Gas & Electric Co 2pp 20591 039 24X Fiche 50-275, 83/09/26, 8310030285

DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8310250120 Forwards addl info re pending requests for exemption from 10CFR50, App R & 10CFR50 4B Info clarifies request for nine exemptions, schedule for alternate shutdown study & completed mods
HONE, P W Carolina Power & Light Co 83/05/02 VASSALLO, D B Operating Reactors Branch 2 21pp 20699 248 24X Fiche 50-324, 83/05/02, 8310250120

8310110157 Ack receipt of 830420 ltr transmitting Rev B to physical security plan Portions inconsistent w/10CFR50 54(p) Encl comments should be accommodated to modify plan Comments withheld (ref 10CFR73 21)
LEWIS, R C Division of Project & Resident Programs 83/07/12 UTLEY, E E Carolina Power & Light Co 3pp 20666 279 24X Fiche 50-324, 83/07/12, 8310110157

8310070273 Forwards IE Safeguards Insp Repts 50-324/83-24 & 50-325/83-24 on 830707 & notice of violation
O'REILLY, J P Region 2, Office of Director 83/09/01 UTLEY, E E Carolina Power & Light Co 2pp 20656 349 24X Fiche 50-324, 83/09/01, 8310070273

--8310070282 Notice of violation from insp on 830707
Region 2, Office of Director 83/09/01 1p 20656, 349 24X Fiche 50-324, 83/09/01, 8310070282

--8310070294 IE Safeguards Insp Repts 50-324/83-24 & 50-325/83-24 on 830707 Noncompliance noted authorized employee entered protected area w/o badge & w/o being physically searched Details withheld (ref 10CFR73 21)
HALL, B L Region 2, Office of Director HCGUIRE, D R Division of Emergency Preparedness & Materials Safety 83/08/01 1p 20656 352 24X Fiche 50-324, 83/09/01, 8310070294

8310040347 Requests update of encl info re layout of technical support ctrs & emergency operations facilities
VERRELLI, D M Division of Project & Resident Programs 83/09/12 UTLEY, E E Carolina Power & Light Co 17pp 20625 183 24X Fiche 50-000, 83/09/12, 8310040347

8310250565 Forwards IE Insp Repts 50-324/83-29 & 50-325/83-29 on 830815-17 No noncompliance noted
O'REILLY, J P Region 2, Office of Director 83/09/21 UTLEY, E E Carolina Power & Light Co 2pp 20902 079 24X Fiche 50-324, 83/09/21, 8310250565

--8310250578 IE Insp Repts 50-324/83-29 & 50-325/83-29 on 830815-17 No noncompliance noted Major areas inspected emergency preparedness
CLINE, W E Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/09/13 9pp 20902 061 24X Fiche 50-324, 83/09/21, 8310250565

8310040298 Ack receipt of 830830 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-26 & 50-325/83-26
VERRELLI, D M Division of Project & Resident Programs 83/09/22 UTLEY, E E Carolina Power & Light Co 1p 20621 001 24X Fiche 50-324, 83/09/22, 8310040298

--8310040306 Responds to NRC 830801 ltr re violations noted in IE Insp Repts 50-324/83-26 & 50-325/83-26 Corrective actions fire protection sys walkdown will be performed to verify sys drawings Revised drawings will be prepared as needed
DIETZ, C R Carolina Power & Light Co 83/08/30 O'REILLY, J P Region 2, Office of Director 2pp 20621 002 24X Fiche 50-324, 83/09/22, 8310040298

--8310040321 Forwards IE Insp Repts 50-324/83-26 & 50-325/83-26 on 830615-0715 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/08/01 UTLEY, E E Carolina Power & Light Co 2pp 20621 004 24X Fiche 50-324, 83/09/22, 8310040298

--8310040326 Notice of violation from insp on 830615-0715
Division of Project & Resident Programs 83/08/01 1p 20621 006 24X Fiche 50-324, 83/09/22, 8310040298

--8310040332 IE Insp Repts 50-324/83-26 & 50-325/83-26 on 830615 0715 Noncompliance noted Fire Protection Procedure OP-41 inadequately established
MYERS, D O, GARNER, L W, ORDERS, W T Region 2, Office of Director 83/07/29 10pp 20621 007 24X Fiche 50-324, 83/09/22, 8310040298

8310050451 Notification of 831006 meeting w/util in Bethesda, MD to discuss progress rept on fire protection, alternative shutdown sys, associated circuits, cable routing, addl analyses, field verification & sprinkler sys
MACKAY, S D Operating Reactors Branch 2 83/09/29 VASSALLO, D B Operating Reactors Branch 2 2pp 20650 037 24X Fiche 50-324, 83/09/29, 8310050451

8310060555 Releases public version of revised emergency plan & emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/09/30 Document Management Branch 1p 20663 001 24X Fiche 50-324, 83/09/30, 8310060555

--8310060561 Forwards public version of Rev 9 to emergency response plan & revised emergency plan implementing procedures, including Procedures PEP-03 4.1 re initial dose projections & PEP-App A re emergency response resources
ZIMMERMAN, S R Carolina Power & Light Co 83/07/15 O'REILLY, J P Region 2, Office of Director 2pp 20663 002 24X Fiche 50-324, 83/09/30, 8310060555

--8310060564 Public version of Rev 9 to emergency response plan
BOYER, L E Carolina Power & Light Co 83/06/16 29pp 20663 004 24X Fiche 50-324, 83/09/30, 8310060555

--8310060567 Public version of revised emergency plan implementing procedures, including Procedures PEP-03 4.1 re initial dose projections & PEP-App A re emergency response resources
BOYER, L E Carolina Power & Light Co 83/06/22 38pp 20663 033 24X Fiche 50-324, 83/09/30, 8310060555

8310070291 Forwards "Position Paper on Reg Guide 1.97" & "Response to NUREG-0737, Suppl 1 & Reg Guide 1.97 Application to Emergency Response Facilities"
ZIMMERMAN, S R Carolina Power & Light Co 83/09/30 VASSALLO, D B Operating Reactors Branch 2 1p 20655 177 24X Fiche 50-324, 83/09/30, 8310070291

--8310070293 "Position Paper on Reg Guide 1.97"
BROWN, W E, WASENKO, M Carolina Power & Light Co 83/08/09 33pp 20655 178 24X Fiche 50-324, 83/09/30, 8310070291

--8310070295 "Response to NUREG-0737, Suppl 1 & Reg Guide 1.97 Application to Emergency Response Facilities"
BROWN, W E, WASENKO, M Carolina Power & Light Co 83/08/09 77pp 20655 211 24X Fiche 50-324, 83/09/30, 8310070291

DOCKETED ITEMS

- 8310070211 Ack receipt of 830921 ltr informing NRC of steps taken to correct violations noted in 18 Insp Repts 50-324/83-24 & 50-325/83-21
O'REILLY, J P Region 2, Office of Director 83/10/05 UTLEY, E E
Carolina Power & Light Co 1p 20659 124 24X
Fiche 50-324, 83/10/05, 8310070211
- 8310070245 Responds to NRC 830901 ltr re violations noted in 18 Insp Repts 50-324/83-24 & 50-325/83-24 Corrective actions withheld (ref 10CFR73.21 & 10CFR2.790)
UTLEY, E E Carolina Power & Light Co 83/09/27 O'REILLY, J P
Region 2, Office of Director 2pp 20659 125 24X
Fiche 50-324, 83/10/05, 8310070245
- 8310180427 Provides supplemental response to Generic Ltr 82-33 re emergency response capability Addl interim milestones & clarification of 830415 response re safety parameter display sys & emergency operating procedures provided
UTLEY, E E Carolina Power & Light Co 83/10/14 VASSALLO, D B
Operating Reactors Branch 2 3pp 20603 300 24X
Fiche 50-324, 83/10/14, 8310180427
- 8310210064 Forwards 1E Safeguards Insp Repts 50-324/83-33 & 50-325/83-33 on 830927-29
VERRELLI, D Division of Project & Resident Programs 83/10/17
UTLEY, E E Carolina Power & Light Co 2pp 20887 266 24X
Fiche 50-324, 83/10/17, 8310210064
- 8310210070 1E Safeguards Insp Repts 50-324/83-33 & 50-325/83-33 on 830927-29 No noncompliance noted Major areas inspected review of licensee action to correct prior violations & testing Details withheld (ref 10CFR73.21)
TOBIN, W J, MCQUIRE, D R Region 2, Office of Director 83/10/14
1p 20659 266 24X Fiche 50-324, 83/10/17, 8310210064
- 8310240080 Summary of 830907 meeting w/util in Bethesda, MD re outstanding items & util progress on alternate shutdown capability assessment & mods required by 10CFR50, App R
MACKAY, S D Operating Reactors Branch 2 83/10/17
Operating Reactors Branch 2 4pp 20903 205 24X Fiche 50-324, 83/10/17, 8310240080
- 8310280129 Notification of 831103 meeting w/util in Bethesda, MD to discuss alternate shutdown sys, associated circuits, addl analyses, field verification, App R deviations & options & high-low pressure interfaces
MACKAY, S D Operating Reactors Branch 2 83/10/25 VASSALLO, D B
Operating Reactors Branch 2 2pp 20964 026 24X
Fiche 50-324, 83/10/25, 8310280129
- P Operating license stage documents & correspondence
- 8310030161 Advises that organizational changes for QA program & changes to FSARs & mgt capability rept will be forwarded when completed
UTLEY, E E Carolina Power & Light Co 83/09/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 20590 028 24X
Fiche 50-000, 83/09/13, 8310030161
- 8310040354 Summarizes 830831 meeting w/util re plans for restructuring corporate organization
O'REILLY, J P Region 2, Office of Director 83/09/22 UTLEY, E E
Carolina Power & Light Co 2pp 20620 331 24X
Fiche 50-000, 83/09/22, 8310040354
- 8310060031 Forwards Amend B1 to License DPR-62 & safety evaluation Amend revises Tech Specs re instrumentation used to monitor water level in suppression chamber of primary containment sys (NUREG-0737, Item II F 1.5)
MACKAY, S D Operating Reactors Branch 2 83/09/22 UTLEY, E E
Carolina Power & Light Co 2pp 20664 101 24X
Fiche 50-324, 83/09/22, 8310060031
- 8310060043 Amend B1 to License DPR-62, changing Tech Specs re instrumentation used to maintain water level in suppression chamber of primary containment sys
MACKAY, S D Operating Reactors Branch 2 83/09/22 5pp
20664 103 24X Fiche 50-324, 83/09/22, 8310060031
- 8310060049 Safety evaluation supporting Amend B1 to License DPR-62
* NRC - No Detailed Affiliation Given 83/09/22 2pp
20664 108 24X Fiche 50-324, 83/09/22, 8310060031
- 8310040380 Application for amend to License DPR-62, revising Paragraph 2 H of license re required operability date of augmented offgas sys mods
HOWE, P W Carolina Power & Light Co 83/09/29 VASSALLO, D B
Operating Reactors Branch 2 4pp 20620 284 24X
Fiche 50-324, 83/09/29, 8310040380
- 8310040385 Application for amend to License DPR-62 & DPR-71, changing Tech Spec re feedwater & main turbine trip/bypass sys
HOWE, P W Carolina Power & Light Co 83/09/29 VASSALLO, D B
Operating Reactors Branch 2 3pp 20617 209 24X
Fiche 50-324, 83/09/29, 8310040385
- 8310040388 Proposed Tech Spec changes re feedwater/main turbine trip sys activation instrumentation & main turbine trip sys
* Carolina Power & Light Co 83/09/29 2Bpp 20617 212 24X
Fiche 50-324, 83/09/29, 8310040385
- 8310060054 Application for amend to License DPR-71 & DPR-62, revising 18-month interval surveillance requirements & primary containment leakage requirements
HOWE, P W Carolina Power & Light Co 83/10/03 VASSALLO, D B
Operating Reactors Branch 2 3pp 20647 043 24X
Fiche 50-324, 83/10/03, 8310060054
- 8310060066 Proposed Tech Spec changes for primary containment leakage testing
* Carolina Power & Light Co 83/10/03 10pp 20647 046 24X
Fiche 50-324, 83/10/03, 8310060054
- 8310240138 Forwards notice of consideration of issuance of amend to License DPR-62 & opportunity for prior hearing on 830607 application re Tech Specs to permit operation up to 50% of rated thermal power w/one recirculation pump out of svr
MACKAY, S D Operating Reactors Branch 2 83/10/05 UTLEY, E E
Carolina Power & Light Co 2pp 20884 351 24X
Fiche 50-324, 83/10/05, 8310240138
- 8310240144 Notice of consideration of issuance of amend to License DPR-62 & opportunity for prior hearing rev to Tech Specs to permit reactor operation at power levels up to 50% of rated thermal power w/one recirculation pump out of svr
VASSALLO, D B Operating Reactors Branch 2 83/10/05 5pp
20884 353 24X Fiche 50-324, 83/10/05, 8310240138
- 8310310137 Forwards safety evaluation re review of util submittal addressing NUREG-0737 Item II K 3.17, "Rept on Outages of ECCS" Requirements met
VASSALLO, D B Operating Reactors Branch 2 83/10/14 UTLEY, E E
Carolina Power & Light Co 4pp 20965 250 24X
Fiche 50-324, 83/10/14, 8310310137
- 8306160513 "ECCS Repts (F-47) TMI Action Plan Requirements, Brunswick Steam Electric Plant, Units 1 & 2," technical evaluation rept
VOSBURY, F W, OVERBECK, O J Franklin Institute/Franklin Research Center NRC-03-B1-130 TER-C5506-174/179 83/06/13 CHOW, T
NRC - No Detailed Affiliation Given 2Bpp 20965 254 24X
Fiche 50-324, 83/10/14, 8310310137
- 8310200058 Clarifies licensee intentions re installation of effluent monitoring instrumentation referenced in 821213 proposed radiological effluent Tech Specs Summary of installation schedules encl
ZIMMERMAN, S R Carolina Power & Light Co 83/10/17 VASSALLO, D B
Operating Reactors Branch 2 4pp 20846 005 24X
Fiche 50-324, 83/10/17, 8310200058
- 8310200206 Requests extension until 831130 to provide response to 830901 request for addl info re electric distribution sys voltages
HOWE, P W Carolina Power & Light Co 83/10/17 VASSALLO, D B
Operating Reactors Branch 2 1p 20834 127 24X
Fiche 50-324, 83/10/17, 8310200206
- 8310210264 Application for amend to License DPR-71 & DPR-62, revising radiological effluent Tech Specs Justification for proposed changes & summary of revs encl
HOWE, P W Carolina Power & Light Co 83/10/17 VASSALLO, D B
Operating Reactors Branch 2 15pp 20848 282 24X
Fiche 50-324, 83/10/17, 8310210264
- 8310210268 Proposed changes to radiological effluent Tech Specs
* Carolina Power & Light Co 83/10/17 200pp, 20848 297 24X
Fiche 50-324, 83/10/17, 8310210264
- 8310250036 Requests approval to perform short duration integrated load rate test (Type A) Test would meet criteria of Bechtel Topical Rept NB-TOP-1, Tech Specs, 10CFR50, App J & ANSI Std N45.4-1972 Approval requested by 840101
HOWE, P W Carolina Power & Light Co 83/10/20 VASSALLO, D B
Operating Reactors Branch 2 2pp 20895 272 24X
Fiche 50-324, 83/10/20, 8310250036

DOCKETED ITEMS

173

8310260141 Forwards program outlines, "Demonstration of Raychem Cable for Qualified Use in Class IE Svc " & "Measure of Voltage Withstand Level on Raychem Cable Samples After Exposure to Simulated LOCA " Programs expected to begin by Jan 1984
HOWE, P W Carolina Power & Light Co 83/10/20 VAS9ALI, D R
Operating Reactors Branch 2 2pp 20915 197 24X
Fiche 50-324, 83/10/20, 8310260141

--8310260145 Rev 2 to "Demonstration of Raychem Cable for Qualified Use in Class IE Svc Primary & Secondary Containment for Brunswick Steam Electric Plant, Units 1 & 2 "
PARKS, D, WALDORF, J M Carolina Power & Light Co 83/08/24 2/pp
20915 199 24X Fiche 50-324, 83/10/20, 8310260141

--8310260148 Rev 0 to "Measure of Voltage Withstand Level on Raychem Cable Samples After Exposure to Simulated LOCA "
PARKS, D, WALDORF, J M Carolina Power & Light Co 83/08/24 5pp
20915 226 24X Fiche 50-324, 83/10/20, 8310260141

3 Inspection reports, IE Bulletins & correspondence

8310040182 Forwards IE Insp Repts 50-324/83-28 & 50-325/83-28 on 830801-05 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/08/30
UTLEY, E E Carolina Power & Light Co 2pp 20617 241 24X
Fiche 50-324, 83/08/30, 8310040182

--8310040203 IE Insp Repts 50-324/83-28 & 50-325/83-28 on 830801-05 No noncompliance noted Major areas inspected licensee action on previous enforcement matters, GA program annual review & audit program implementation
DEBBAOE, A G Region 2, Office of Director UPRIGH, C M Division of Engineering & Operational Programs 83/08/25 7pp 20617 241
24X Fiche 50-324, 83/08/30, 8310040182

8310070273 Forwards IE Safeguards Insp Repts 50-324/83-24 & 50-325/83-24 on 830707 & notice of violation
O'REILLY, J P Region 2, Office of Director 83/09/01 UTLEY, E E
Carolina Power & Light Co 2pp 20656 349 24X
Fiche 50-324, 83/09/01, 8310070273

--8310070282 Notice of violation from insp on 830707
* Region 2, Office of Director 83/09/01 1p 20656 351 24X
Fiche 50-324, 83/09/01, 8310070273

--8310070294 IE Safeguards Insp Repts 50-324/83-24 & 50-325/83-24 on 830707 Noncompliance noted authorized employees entered protected area w/o badge & w/o being physically searched
Details withheld (ref 10CFR73 21)
HALL, B L Region 2, Office of Director MCQUIRE, D R Division of Emergency Preparedness & Materials Safety 83/08/01 1p
20656 352 24X Fiche 50-324, 83/09/01, 8310070273

8310250565 Forwards IE Insp Repts 50-324/83-29 & 50-325/83-29 on 830815-17 No noncompliance noted
O'REILLY, J P Region 2, Office of Director 83/09/21 UTLEY, E E
Carolina Power & Light Co 2pp 20902 059 24X
Fiche 50-324, 83/09/21, 8310250565

--8310250578 IE Insp Repts 50-324/83-29 & 50-325/83-29 on 830815-17 No noncompliance noted Major areas inspected emergency preparedness
CLINE, W E Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/09/13 9pp
20902 061 24X Fiche 50-324, 83/09/21, 8310250565

8310040298 Ack receipt of 830830 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-26 & 50-325/83-26
VERRELLI, D M Division of Project & Resident Programs 83/09/22
UTLEY, E E Carolina Power & Light Co 1p 20621 001 24X
Fiche 50-324, 83/09/22, 8310040298

--8310040306 Responds to NRC 830801 ltr re violations noted in IE Insp Repts 50-324/83-26 & 50-325/83-26 Corrective actions fire protection sys walkdown will be performed to verify sys drawings Revised drawings will be prepared as needed
DIETZ, C R Carolina Power & Light Co 83/08/30 O'REILLY, J P
Region 2, Office of Director 2pp 20621 002 24X
Fiche 50-324, 83/09/22, 8310040298

--8310040321 Forwards IE Insp Repts 50-324/83-26 & 50-325/83-26 on 830615-0715 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/08/01
UTLEY, E E Carolina Power & Light Co 2pp 20621 004 24X
Fiche 50-324, 83/09/22, 8310040298

--8310040326 Notice of violation from insp on 830615-0715
* Division of Project & Resident Programs 83/08/01 1p
20621 006 24X Fiche 50-324, 83/09/22, 8310040298

--8310040332 IE Insp Repts 50-324/83-26 & 50-325/83-26 on 830615-0715 Noncompliance noted Fire Protection Procedure DP-41 inadequately established
MYERS, D O, GARNER, L W, ORBER, W T Region 2, Office of Director
83/07/29 10pp 20621 007 24X Fiche 50-324, 83/09/22, 8310040298

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 119pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310070241 Ack receipt of 830927 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-24 & 50-325/83-24
O'REILLY, J P Region 2, Office of Director 83/10/05 UTLEY, E E
Carolina Power & Light Co 1p 20659 124 24X
Fiche 50-324, 83/10/05, 8310070241

--8310070246 Responds to NRC 830901 ltr re violations noted in IE Insp Repts 50-324/83-24 & 50-325/83-24 Corrective actions withheld (ref 10CFR73 21 & 10CFR2 790)
UTLEY, E E Carolina Power & Light Co 83/09/27 O'REILLY, J P
Region 2, Office of Director 2pp 20659 125 24X
Fiche 50-324, 83/10/05, 8310070241

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310250474 Ack receipt of 830923 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-23 & 50-325/83-23
O'REILLY, J P Region 2, Office of Director 83/10/11 UTLEY, E E
Carolina Power & Light Co 1p 20900 061 24X
Fiche 50-324, 83/10/11, 8310250474

--8310250480 Responds to NRC 830825 ltr re violations noted in IE Insp Repts 50-324/83-23 & 50-325/83-23 Corrective actions procedure will be implemented by 831130 to ensure revs to certificates of compliance will be identified
HOWE, P W Carolina Power & Light Co 83/09/23 O'REILLY, J P
Region 2, Office of Director 3pp 20900 062 ;
Fiche 50-324, 83/10/11, 8310250474

DOCKETED ITEMS

- B310250488 Forwards IE Insp Repts 50-324/83-23 & 50-325/83-23 on B30626-30 & notice of violation Requests response to circumstances surrounding radioactive matl shipment to another licensee, per B30727 enforcement conference at site
O'REILLY, J P Region 2, Office of Director 83/08/25 UTLEY, E E
Carolina Power & Light Co 2pp 20900 065 24X
Fiche 50-324, 83/10/11, B310250474
- B310250493 Notice of violation from insp on B30626-30
* Region 2, Office of Director 83/08/25 1p 20790 067 24X
Fiche 50-324, 83/10/11, B310250474
- B310250501 IE Insp Repts 50-324/83-23 & 50-325/83-23 on B30626-30
Noncompliance noted large quantity shipment in CNS-3-55
shipping cask not leak tested prior to delivery of package
to carrier for transport
ALBRIGHT, R H, BARR, K P Region 2, Office of Director 83/08/05
7pp 20900 068 24X Fiche 50-324, 83/10/11, B310250474
- B310200166 Forwards Rev 13 to Engineering Procedure ENP-16, "Procedure for Administrative Control of Inservice Insp Activities"
List providing status of existing relief/exemption requests
encl
HOME, P W Carolina Power & Light Co 83/10/12 VASSALL, D B
Operating Reactors Branch 2 2pp 20828 001 24X
Fiche 50-324, 83/10/12, B310200166
- B310200168 Rev 13 to Engineering Procedure ENP-16, "Procedure for Administrative Control of Inservice Insp Activities"
* Carolina Power & Light Co 83/08/26 280pp 20828 003 24X
Fiche 50-324, 83/10/12, B310200166
- B310200143 Responds to B30826 confirmatory order re intergranular stress corrosion cracking insps of BHR stainless steel piping
List of recirculation & reactor water cleanup sys
welds to be inspected in Nov 1983 & Mar 1984 encl
UTLEY, E E Carolina Power & Light Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 11pp 20836 326 24X
Fiche 50-324, 83/10/14, B310200143
- B310210064 Forwards IE Safeguards Insp Repts 50-324/83-33 & 50-325/83-33 on B30927-29
VERRELLI, D Division of Project & Resident Programs 83/10/17
UTLEY, E E Carolina Power & Light Co 2pp 20857 265 24X
Fiche 50-324, 83/10/17, B310210064
- B310210070 IE Safeguards Insp Repts 50-324/83-33 & 50-325/83-33 on B30927-29
No noncompliance noted Major areas inspected - review of licensee action to correct prior violations & testing details withheld (ref 10CFR73.21)
TOBIN, M J, MCQUIRE, D R Region 2, Office of Director 83/10/14
1p 20857 268 24X Fiche 50-324, 83/10/17, B310210064
- B310250451 Ack receipt of B30804 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-18 & 50-325/83-18
Violation re worker whose body count remains
O'REILLY, J P Region 2, Office of Director 83/10/17 UTLEY, E E
Carolina Power & Light Co 2pp 20877 081 24X
Fiche 50-324, 83/10/17, B310250451
- B310250457 Ack receipt of B30804 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-18 & 50-325/83-18
LEWIS, R C Division of Project & Resident Programs 83/08/30
UTLEY, E E Carolina Power & Light Co 1p 20877 083 24X
Fiche 50-324, 83/10/17, B310250451
- B310250460 Responds to NRC B30705 ltr re violations noted in IE Insp Repts 50-324/83-18 & 50-325/83-18
Corrective actions special ventilation hood installed from HEPA filtration unit in bag cutting/insp station
DIETZ, C R Carolina Power & Light Co 83/08/04 O'REILLY, J P
Region 2, Office of Director 4pp 20877 084 24X
Fiche 50-324, 83/10/17, B310250451
- B310250468 Forwards IE Insp Repts 50-324/83-18 & 50-325/83-18 on B30523-27 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/07/05
UTLEY, E E Carolina Power & Light Co 2pp 20877 088 24X
Fiche 50-324, 83/10/17, B310250451
- B310250473 Notice of violation from insp on B30523-27
* Region 2, Office of Director 83/07/05 1p 20877 090 24X
Fiche 50-324, 83/10/17, B310250451
- B310250477 IE Insp Repts 50-324/83-18 & 50-325/83-18 on B30523-27
Noncompliance noted failure to perform adequate air sampling
ALBRIGHT, R H, BARR, K P Region 2, Office of Director 83/07/01
7pp 20877 091 24X Fiche 50-324, 83/10/17, B310250451
- B310250571 Comments on detection of deficiencies in quality resulting from suppliers fraudulent actions, described in IE Info Notices B3-07 & B3-01 & IE Bulletins Q1-06 & B3-07
Use of addl insp & testing during receipt insps investigated
MCDOUFFIE, M A Carolina Power & Light Co 83/10/21 DEYOUNG, H C
Director's Office, Office of Inspection and Enforcement 1p 20900 347 24X
Fiche 50-000, 83/10/21, B310250571
- R Periodic operating reports & related correspondence
- B310130124 Monthly operating repts for Sept 1983 W/B31006 ltr
HARRISON, F, DIETZ, C R Carolina Power & Light Co 83/10/06
DEYOUNG, H C Director's Office, Office of Inspection and Enforcement 14pp 20726 311 24X
Fiche 50-324, 83/10/06, B310130124
- S Reportable occurrences, LERs & related correspondence
- B310210329 Responds to FOIA request for all documents re significantly high rate of equipment failures for GC BWR/4 rated at 2,436 MW
Forwards App A documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/07/20 HANFMAN, B
Suffolk Nuclear Study Group 2pp 20802 223 24X
Fiche 50-000, 83/07/28, B310210329
- B303240341 Summarizes evaluation of LCHs for 1982 (IR submitted), usually acceptable Potential mgt weaknesses indicated by large number of procedural deficiencies, lack of followup repts committed to & possible training problems
SEYFRIT, K V Reactor Operations Analysis Branch 83/07/15
LEWIS, R C Division of Project & Resident Programs 4pp 20882 269 24X
Fiche 50-000, 83/07/28, B310210329
- B310040362 LER B3-07B/03L-0 on B30807, during startup, reactor recirculation sys jet pump operability discovered not performed while in Mode 2, in violation of Tech Spec requirement Cause by misinterpretation W/B30906 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/09/06
O'REILLY, J P Region 2, Office of Director 2pp 20620 233 24X
Fiche 50-324, 83/09/06, B310040362
- B310040593 RO 2-B3-B3 on B30905, weekly fire protection test determined valve 2-FP-V39 shut & under clearance Clearance valve tag inadvertently placed on wrong valve Valve opened
Investigation pending
DIETZ, C R Carolina Power & Light Co 83/09/06 O'REILLY, J P
Region 2, Office of Director 1p 20625 234 24X
Fiche 50-324, 83/09/06, B310040593
- B309200175 LER B2-123/03L-2 on B21010, while attempting to automatically transfer bus 2D to startup transformer, loss of 4160-volt emergency bus L-3 occurred Diesel generator 3 determined inoperable Cause by breaker failure to close W/B30912 ltr
POULK, R M, DIETZ, C R Carolina Power & Light Co 83/09/12
O'REILLY, J P Region 2, Office of Director 4pp 20431 168 24X
Fiche 50-324, 83/09/12, B309200175
- B310030202 LER B3-069/03L-0 on B30825, while attempting to place 111V room coolers 2A & 2B into svc, neither room cooler would start Cause by fan start switch of 2A out of adjustment w/airflow dampers of 2B mechanically binding W/B30921 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/09/21
O'REILLY, J P Region 2, Office of Director 3pp 20590 140 24X
Fiche 50-324, 83/09/21, B310030202
- B310030209 LER B3-059/03L-0 on B30822, discovered automatic depressurization sys initiation logic A switch 2C11-PG-N016A would not respond to applied test signal Cause by corrosion of switch internals & setpoint drift W/B30921 ltr
DIETZ, C R, PASTVA, M J Carolina Power & Light Co 83/09/21
O'REILLY, J P Region 2, Office of Director 2pp 20590 151 24X
Fiche 50-324, 83/09/21, B310030209
- B310030422 LER B3-073/03L-0 on B30824, during surveillance, instrument indication of reactor water cleanup sys differential flow indicator 2-Q31-R615, OE Model 180, indicated high Cause by entrapped air in transmitter sensing lines W/B30921 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/09/21
O'REILLY, J P Region 2, Office of Director 3pp 20593 163 24X
Fiche 50-324, 83/09/21, B310030422
- B310060237 LER B3-082/03L-0 on B30902, suppression pool level exceeded specs w/valve of -26.25 inches Cause by failure of operator to adequately monitor level while instrumentation out of svc due to plant mod Level returned to specs W/B30924 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/09/24
O'REILLY, J P Region 2, Office of Director 3pp 20644 097 24X
Fiche 50-324, 83/09/29, B310060237

DOCKETED ITEMS

175

8310060383 LER 83-080/03L-0 on 830831, following scram, while utilizing HPCI sys as heat sink for reactor, suppression pool water level exceeded Tech Specs. Caused by HPCI pump min flow valve failing in open position. Valve closed W/830929 ltr
PASTVA, M J, POULK, R M, DIETZ, C R Carolina Power & Light Co
83/09/29 O'REILLY, J P Region 2, Office of Director App
20646 065 24X Fiche 50-324, 83/09/29, 8310060383

8310060075 LER 83-084/03L-0 on 830902, rod worth minimizer went to control rod Group 4 while last two control rods of Group 3 still fully inserted. Cause to be determined during future reactor startup W/830930 ltr
POULK, R M, DIETZ, C R Carolina Power & Light Co 83/09/30
O'REILLY, J P Region 2, Office of Director 2pp 20647 149 24X
Fiche 50-324, 83/09/30, 8310060075

8310120426 LER 83-070/03L-0 on 830907, core spray or RHR pumps running. Announcement received w/no abnormalities or pumps running. Caused by microswitch NO20A failure. Switch replaced W/831003 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/10/03
O'REILLY, J P Region 2, Office of Director 2pp 20658 270 24X
Fiche 50-324, 83/10/03, 8310120426

8310170604 LER 83-086/03L-0 on 830916, during power operation, main steam line radiation monitor 2-D12-IRM-K603D showed indication less than indicated by redundant instrumentation. Caused by instrument drift. Channel recalibr W/831006 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/10/06
O'REILLY, J P Region 2, Office of Director 2pp 20782 105 24X
Fiche 50-324, 83/10/06, 8310170604

8310170596 Updated LER 83-069/03L-1 on 830825, while attempting to place RHR room coolers 2A & 2B into svc, neither cooler would start. Caused by fan start limit switch out of adjustment & mechanical binding of airflow dampers W/831007 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/10/07
O'REILLY, J P Region 2, Office of Director 3pp 20782 110 24X
Fiche 50-324, 83/10/07, 8310170596

8310190238 Updated LER 81-118/03L-1 on 811201, five secondary containment fire seals unable to meet test acceptance criteria & declared inoperable. Caused by degradation due to cracking or shrinking. Seals repaired W/831011 ltr
ALLEN, M T, DIETZ, C R Carolina Power & Light Co 83/10/11
O'REILLY, J P Region 2, Office of Director 2pp 20818 080 24X
Fiche 50-324, 83/10/11, 8310190238

8310250237 Updated LER 83-042/03L-1 on 830330, suppression pool level indicators 2-CAC-LI-2601-1, 2601-3 & 2-CAC-LI-3342 showed upward trend in level indication. Caused by closed demineralized water root valve. Valve reopened W/831017 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/10/17
O'REILLY, J P Region 2, Office of Director 2pp 20699 068 24X
Fiche 50-324, 83/10/17, 8310250237

8310250396 Updated LER 83-034/03L-1 on 830530, following high/low alarm announcement, RTGB suppression pool level indicator 2-CAC-LI-2601-1, 3 & 2-CAC-LI-3342 levels found below Tech Spec limit. Caused by spraying water W/831017 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/10/17
O'REILLY, J P Region 2, Office of Director 3pp 20897 293 24X
Fiche 50-324, 83/10/17, 8310250396

DOCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8310250120 Forwards addl info re pending requests for exemption from 10CFR50, App R & 10CFR50 4B info clarifies request for nine exemptions, schedule for alternate shutdown study & completed mods
HOWE, P W Carolina Power & Light Co 83/05/02 VASSALLO, D B
Operating Reactors Branch 2 21pp 20699 248 24X
Fiche 50-324, 83/05/02, 8310250120

8310110157 Ack receipt of 830420 ltr transmitting Rev B to physical security plan. Portions inconsistent w/10CFR50 54(p) Encl comments should be accommodated to modify plan. Comments withheld (ref 10CFR73 21)
LEWIS, R C Division of Project & Resident Programs 83/07/12
UTLEY, E E Carolina Power & Light Co 3pp 20646 249 24X
Fiche 50-324, 83/07/12, 8310110157

8310070273 Forwards IE Safeguards Insp Repts 50-324/83-24 & 50-325/83-24 on 830707 & notice of violation
O'REILLY, J P Region 2, Office of Director 83/09/01 UTLEY, E E
Carolina Power & Light Co 2pp 20656 349 24X
Fiche 50-324, 83/09/01, 8310070273

--8310070282 Notice of violation from insp on 830707
* Region 2, Office of Director 83/09/01 1p 20656 341 24X
Fiche 50-324, 83/09/01, 8310070273

--8310070294 IE Safeguards Insp Repts 50-324/83-24 & 50-325/83-24 on 830707. Noncompliance noted. Authorized employee entered protected area w/o badge & w/o being physically searched. Details withheld (ref 10CFR73 21)
HALL, B L Region 2, Office of Director 83/08/01 1p
20656 352 24X Fiche 50-324, 83/09/01, 8310070273

8310040347 Requests update of encl info re layout of technical support ctrs & emergency operations facilities
VERRELLI, D M Division of Project & Resident Programs 83/09/12
UTLEY, E E Carolina Power & Light Co 17pp 20625 183 24X
Fiche 50-000, 83/09/12, 8310040347

8310250565 Forwards IE Insp Repts 50-324/83-29 & 50-325/83-29 on 830815-19. No noncompliance noted.
O'REILLY, J P Region 2, Office of Director 83/09/21 UTLEY, E E
Carolina Power & Light Co 2pp 20902 059 24X
Fiche 50-324, 83/09/21, 8310250565

--8310250578 IE Insp Repts 50-324/83-29 & 50-325/83-29 on 830815-19. No noncompliance noted. Major areas inspected emergency preparedness
CLINE, W E Region 2, Office of Director 83/09/13 9pp
20782 061 24X Fiche 50-324, 83/09/21, 8310250565

8310040298 Ack receipt of 830830 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-26 & 50-325/83-26
VERRELLI, D M Division of Project & Resident Programs 83/09/22
UTLEY, E E Carolina Power & Light Co 1p 20621 001 24X
Fiche 50-324, 83/09/22, 8310040298

--8310040306 Responds to NRC 830801 ltr re violations noted in IE Insp Repts 50-324/83-26 & 50-325/83-26. Corrective actions fire protection sys walkdown will be performed to verify sys drawings. Revised drawings will be prepared as needed.
DIETZ, C R Carolina Power & Light Co 83/08/30 O'REILLY, J P
Region 2, Office of Director 2pp 20621 002 24X
Fiche 50-324, 83/09/22, 8310040298

--8310040321 Forwards IE Insp Repts 50-324/83-26 & 50-325/83-26 on 830615-0715 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/08/01
UTLEY, E E Carolina Power & Light Co 2pp 20621 004 24X
Fiche 50-324, 83/09/22, 8310040298

--8310040326 Notice of violation from insp on 830615-0715
* Division of Project & Resident Programs 83/08/01 1p
20621 006 24X Fiche 50-324, 83/09/22, 8310040298

--8310040332 IE Insp Repts 50-324/83-26 & 50-325/83-26 on 830615-0715. Noncompliance noted. Fire Protection Procedure OP-41 inadequately established.
MYERS, D O Region 2, Office of Director BENIG, P R Division of Project & Resident Programs 83/07/29 10pp 20621 007 24X
Fiche 50-324, 83/09/22, 8310040298

8310050451 Notification of 831006 meeting w/util in Bethesda, MD to discuss progress re: on fire protection, alternative shutdown sys, associated circuits, cable routing, addl analyses, field verification & sprinkler sys.
MACKAY, S D Operating Reactors Branch 2, 83/09/29 VASSALLO, D B
Operating Reactors Branch 2 2pp 20650 037 24X
Fiche 50-324, 83/09/29, 8310050451

8310060555 Releases public version of revised emergency plan & emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/09/30 Document
Management Branch 1p 20663 001 24X Fiche 50-324, 83/09/30, 8310060555

--8310060561 Forwards public version of Rev 9 to emergency response plan & revised emergency plan implementing procedures, including Procedures PEP-03 4.1 re initial dose projections & PEP-App A re emergency response resources
ZIMMERMAN, S R Carolina Power & Light Co 83/07/15
O'REILLY, J P Region 2, Office of Director 2pp 20663 002 24X
Fiche 50-324, 83/09/30, 8310060555

--8310060564 Public version of Rev 9 to emergency response plan
BOYER, L E Carolina Power & Light Co 83/06/16 27pp
20663 004 24X Fiche 50-324, 83/09/30, 8310060555

--8310060567 Public version of revised emergency plan implementing procedures, including Procedures PEP-03 4.1 re initial dose projections & PEP-App A re emergency response resources
BOYER, L E Carolina Power & Light Co 83/06/22 30pp 20663 033
24X Fiche 50-324, 83/09/30, 8310060555

DOCKETED ITEMS

8310070291 Forwards "Position Paper on Reg Guide 1.97" & "Response to NUREG-0737, Suppl 1 & Reg Guide 1.97 Application to Emergency Response Facilities"
ZIMMERMAN, S R Carolina Power & Light Co 83/09/30 VASSALLO, D B
Operating Reactors Branch 2 1p 20655 177 24X
Fiche 50-324, 83/09/30, 8310070291

--8310070293 "Position Paper on Reg Guide 1.97"
BROWN, W E, WASENKO, M Carolina Power & Light Co 83/08/09
33pp 20655 178 24X Fiche 50-324, 83/09/30, 8310070291

--8310070295 "Response to NUREG-0737, Suppl 1 & Reg Guide 1.97 Application to Emergency Response Facilities"
BROWN, W E, WASENKO, M Carolina Power & Light Co 83/08/07
77pp 20655 211 24X Fiche 50-324, 83/09/30, 8310070291

8310070241 Ack receipt of 830927 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-24 & 50-325/83-24
O'REILLY, J P Region 2, Office of Director 83/10/05 UTLEY, E E
Carolina Power & Light Co 1p 20657 124 24X
Fiche 50-324, 83/10/05, 8310070241

--8310070246 Responds to NRC 830901 ltr re violations noted in IE Insp Repts 50-324/83-24 & 50-325/83-24 Corrective actions withheld (ref 10CFR73.21 & 10CFR2.770)
UTLEY, E E Carolina Power & Light Co 83/09/27 O'REILLY, J P
Region 2, Office of Director 2pp 20659 125 24X
Fiche 50-324, 83/10/05, 8310070241

8310180427 Provides supplemental response to Generic Ltr 82-33 re emergency response capability Add'l interim milestones & clarification of 830415 response re safety parameter display sys & emergency operating procedures provided
UTLEY, E E Carolina Power & Light Co 83/10/14 VASSALLO, D B
Operating Reactors Branch 2 3pp 20803 300 24X
Fiche 50-324, 83/10/14, 8310180427

8310210064 Forwards IE Safeguards Insp Repts 50-324/83-33 & 50-325/83-33 on 830927-29
VERRELL, I D Division of Project & Resident Programs 83/10/17
UTLEY, E E Carolina Power & Light Co 2pp 20857 268 24X
Fiche 50-324, 83/10/17, 8310210064

--8310210070 IE Safeguards Insp Repts 50-324/83-33 & 50-325/83-33 on 830927-29 No noncompliance noted Major areas inspected review of licensee action to correct prior violations & testing details withheld (ref 10CFR73.21)
TOBIN, W J Region 2, Office of Director 83/10/14 1p
20857 268 24X Fiche 50-324, 83/10/17, 8310210064

8310240080 Summary of 830907 meeting w/util in Bethesda, MD re outstanding items & util progress on alternate shutdown capability assessment & mods required by 10CFR50, App R
MACKAY, S Operating Reactors Branch 2 83/10/17
Operating Reactors Branch 2 4pp 20903 205 24X Fiche 50-324, 83/10/17, 8310240080

8310280129 Notification of 831103 meeting w/util in Bethesda, MD to discuss alternate shutdown sys, associated circuits, add'l analyses, field verification, App R deviations & options & high-low pressure interfaces
MACKAY, S D Operating Reactors Branch 2 83/10/25 VASSALLO, D B
Operating Reactors Branch 2 2pp 20964 026 24X
Fiche 50-324, 83/10/25, 8310280129

P Operating license stage documents & correspondence

8310030161 Advises that organizational changes for QA program & changes to FSARs & mgt capability rept will be forwarded when completed
UTLEY, E E Carolina Power & Light Co 83/09/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 20390 024 24X
Fiche 50-000, 83/09/13, 8310030161

8310040354 Summarizes 830831 meeting w/util re plans for restructuring corporate organization
O'REILLY, J P Region 2, Office of Director 83/09/22 UTLEY, E E
Carolina Power & Light Co 2pp 20620 321 24X
Fiche 50-000, 83/09/22, 8310040354

8310040385 Application for amend to Licenses DPR-62 & DPR-71, changing Tech Spec re feedwater & main turbine trip/bypass sys
HOWE, P W Carolina Power & Light Co 83/09/29 VASSALLO, D B
Operating Reactors Branch 2 3pp 20617 209 24X
Fiche 50-324, 83/09/29, 8310040385

--8310040388 Proposed Tech Spec changes re feedwater/main turbine trip sys actuation instrumentation & main turbine trip sys
* Carolina Power & Light Co 83/09/29 28pp 20617 212 24X
Fiche 50-324, 83/09/29, 8310040385

8310060054 Application for amend to Licenses DPR-71 & DPR-62, changing 18-month interval surveillance requirements & primary containment leakage requirements
HOWE, P W Carolina Power & Light Co 83/10/03 VASSALLO, D B
Operating Reactors Branch 2 3pp 20641 043 24X
Fiche 50-324, 83/10/03, 8310060054

--8310060066 Proposed Tech Spec changes for primary containment leakage testing
* Carolina Power & Light Co 83/10/03 10pp 20641 046 24X
Fiche 50-324, 83/10/03, 8310060054

8310310137 Forwards safety evaluation re review of util submitted addressing NUREG-0737 Item II K 3.17, "Rept on Duties of ECCS" Requirements met
VASSALLO, D B Operating Reactors Branch 2 83/10/14 UTLEY, E E
Carolina Power & Light Co 4pp 20965 250 24X
Fiche 50-324, 83/10/14, 8310310137

--8306160513 "ECCS Repts (F-47) TMI Action Plan Requirements, Brunswick Stream Electric Plant, Units 1 & 2," technical evaluation rept
VOSBURY, F W, OVERDECK, G J Franklin Institute/Franklin Research Center NRC-02-81-130 TCR-C5506-174/175 83/06/13 (HOWE, P W)
NRC - No Detailed Affiliation Given 23pp 20965 254 24X
Fiche 50-324, 83/10/14, 8310310137

8310200058 Clarifies licensee intentions re installation of effluent monitoring instrumentation referenced in 821213 proposed radiological effluent Tech Specs summary of installation schedules encl
ZIMMERMAN, S R Carolina Power & Light Co 83/10/17 VASSALLO, D B
Operating Reactors Branch 2 4pp 20806 005 24X
Fiche 50-324, 83/10/17, 8310200058

8310200206 Requests extension until 831130 to provide response to 830901 request for add'l info re electric distribution sys voltages
HOWE, P W Carolina Power & Light Co 83/10/17 VASSALLO, D B
Operating Reactors Branch 2 1p 20804 127 24X
Fiche 50-324, 83/10/17, 8310200206

8310210264 Application for amend to Licenses DPR-71 & DPR-62, revising radiological effluent Tech Specs justification for proposed changes & summary of revs encl
HOWE, P W Carolina Power & Light Co 83/10/17 VASSALLO, D B
Operating Reactors Branch 2 15pp 20848 282 24X
Fiche 50-324, 83/10/17, 8310210264

--8310210268 Proposed changes to radiological effluent Tech Specs
* Carolina Power & Light Co 83/10/17 200pp 20848 297 24X
Fiche 50-324, 83/10/17, 8310210264

8310250036 Requests approval to perform short duration integrated leak rate test (Type A) Test would meet criteria of Bechtel Topical Rept NH-100P-1, Tech Specs, 10CFR50, App J & ANSI Std N45 4-1972 Approval requested by 840101
HOWE, P W Carolina Power & Light Co 83/10/20 VASSALLO, D B
Operating Reactors Branch 2 2pp 20805 272 24X
Fiche 50-324, 83/10/20, 8310250036

8310260141 Forwards program outlines, "Demonstration of Raychem Cable for Qualified Use in Class 1E Svc" & "Measure of Voltage Withstand Level on Raychem Cable Samples After Exposure to Simulated LOCA" Programs expected to begin by Jan 1984
HOWE, P W Carolina Power & Light Co 83/10/20 VASSALLO, D B
Operating Reactors Branch 2 2pp 20915 197 24X
Fiche 50-324, 83/10/20, 8310260141

--8310260145 Rev 2 to "Demonstration of Raychem Cable For Qualified Use in Class 1E Svc Primary & Secondary Containment for Brunswick Stream Electric Plant, Units 1 & 2"
PARKS, B, WALDORF, J Carolina Power & Light Co 83/08/23 27pp
20915 197 24X Fiche 50-324, 83/10/20, 8310260141

--8310260148 Rev 0 to "Measure of Voltage Withstand Level on Raychem Cable Samples After Exposure to Simulated LOCA"
PARKS, B, WALDORF, J M Carolina Power & Light Co 83/08/24 27pp
20915 226 24X Fiche 50-324, 83/10/20, 8310260141

G Inspection reports, IE Bulletins & correspondence

8310040182 Forwards IE Insp Repts 50-324/83-28 & 50-325/83-28 on 830801-05 No noncompliance noted
VERRELL, I D Division of Project & Resident Programs 83/08/20
UTLEY, E E Carolina Power & Light Co 2pp 20617 241 24X
Fiche 50-324, 83/08/30, 8310040182

DOCKETED ITEMS

177

--B310040203 IE Insp Repts 50-324/83-28 & 50-325/83-28 on B30801-05 No noncompliance noted Major areas inspected licensee action on previous enforcement matters, QA program annual review & audit program implementation
DEBBAGH, A O Region 2, Office of Director UPRIGHT, C M Division of Engineering & Operational Programs 83/08/25 /pp 20617 241
24X Fiche 50-324, 83/08/30, B310040192

B310070273 Forwards IE Safeguards Insp Repts 50-324/83-24 & 50-325/83-24 on B30707 & notice of violation
O'REILLY, J P Region 2, Office of Director 83/09/01 UTLEY, E L
Carolina Power & Light Co 2pp 20656 249 24X
Fiche 50-324, 83/09/01, B310070273

--B310070282 Notice of violation from insp on B30707
* Region 2, Office of Director 83/09/01 1p 20656 251 24X
Fiche 50-324, 83/09/01, B310070273

--B310070294 IE Safeguards Insp Repts 50-324/83-24 & 50-325/83-24 on B30707 Noncompliance noted authorized employee entered protected area w/o badge & w/o being physically searched
Details withheld (ref 10CFR2.71)
HALL, B L Region 2, Office of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 83/08/01 1p
20656 252 24X Fiche 50-324, 83/09/01, B310070273

B310250565 Forwards IE Insp Repts 50-324/83-29 & 50-325/83-29 on B30815-19 No noncompliance noted
O'REILLY, J P Region 2, Office of Director 83/09/21 UTLEY, E L
Carolina Power & Light Co 2pp 20900 059 24X
Fiche 50-324, 83/09/21, B310250565

--B310250578 IE Insp Repts 50-324/83-29 & 50-325/83-29 on B30815-19 No noncompliance noted Major areas inspected emergency preparedness
CLINE, W E Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/09/13 9pp
20902 061 24X Fiche 50-324, 83/09/21, B310250565

B310040298 Ack receipt of B30830 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-26 & 50-325/83-26
VERRELL, D M Division of Project & Resident Programs 83/09/22
UTLEY, E L Carolina Power & Light Co 1p 20621 001 24X
Fiche 50-324, 83/09/22, B310040298

--B310040306 Responds to NRC B30801 ltr re violations noted in IE Insp Repts 50-324/83-26 & 50-325/83-26 Corrective actions fire protection sys walkdown will be performed to verify sys drawings Revised drawings will be prepared as needed
DIEFZ, C R Carolina Power & Light Co 83/08/30 O'REILLY, J P
Region 2, Office of Director 2pp 20621 002 24X
Fiche 50-324, 83/09/22, B310040298

B310040321 Forwards IE Insp Repts 50-324/83-26 & 50-325/83-26 on B30615-0715 & notice of violation
VERRELL, D M Division of Project & Resident Programs 83/08/01
UTLEY, E L Carolina Power & Light Co 2pp 20621 004 24X
Fiche 50-324, 83/09/22, B310040298

--B310040326 Notice of violation from insp on B30615-0715
* Division of Project & Resident Programs 83/08/01 1p
20621 006 24X Fiche 50-324, 83/09/22, B310040298

--B310040332 IE Insp Repts 50-324/83-26 & 50-325/83-26 on B30615 0715 Noncompliance noted Fire Protection Procedure OP-41 inadequately established
MYERS, D O, GARNER, L W, ORRERS, W T Region 2, Office of Director 83/07/29 10pp 20621 007 24X Fiche 50-324, 83/09/22, B310040298

B308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/26 Consolidated Edison Co of New York, Inc 11pp 20794 022 24X Fiche 50-000, 83/09/26, B308300340

B308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intake." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/26 Consolidated Edison Co of New York, Inc 11pp 20777 210 24X Fiche 50-000, 83/09/26, B308300342

B308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/26 Consolidated Edison Co of New York, Inc 11pp 20778 001 24X Fiche 50-000, 83/09/26, B308300345

B308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/29 Consolidated Edison Co of New York, Inc 11pp 20716 224 24X Fiche 50-000, 83/09/29, B308300349

B310070241 Ack receipt of B30927 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-24 & 50-325/83-24
O'REILLY, J P Region 2, Office of Director 83/10/05 UTLEY, E L
Carolina Power & Light Co 1p 20659 124 24X
Fiche 50-324, 83/10/05, B310070241

--B310070246 Responds to NRC B30901 ltr re violations noted in IE Insp Repts 50-324/83-24 & 50-325/83-24 Corrective actions withheld (ref 10CFR73.21 & 10CFR2.770)
UTLEY, E L Carolina Power & Light Co 83/09/27 O'REILLY, J P
Region 2, Office of Director 2pp 20659 125 24X
Fiche 50-324, 83/10/05, B310070241

B308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Dupass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, B308300378

B308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, B308300752

B308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/11 Consolidated Edison Co of New York, Inc 11pp 21043 075 24X Fiche 50-000, 83/10/11, B308300759

B308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, B308300761

B310250474 Ack receipt of B30928 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-23 & 50-325/83-23
O'REILLY, J P Region 2, Office of Director 83/10/11 UTLEY, E L
Carolina Power & Light Co 1p 20900 061 24X
Fiche 50-324, 83/10/11, B310250474

--B310250480 Responds to NRC B30825 ltr re violations noted in IE Insp Repts 50-324/83-23 & 50-325/83-23 Corrective actions procedure will be implemented by B31130 to ensure revs to certificates of compliance will be identified
HOWE, P W Carolina Power & Light Co 83/09/23 O'REILLY, J P
Region 2, Office of Director 3pp 20900 062 24X
Fiche 50-324, 83/10/11, B310250474

--B310250488 Forwards IE Insp Repts 50-324/83-23 & 50-325/83-23 on B30626-30 & notice of violation Requests response to circumstances surrounding radioactive matl shipment to another licensee, per B30727 enforcement conference at site
O'REILLY, J P Region 2, Office of Director 83/08/25 UTLEY, E L
Carolina Power & Light Co 2pp 20900 065 24X
Fiche 50-324, 83/10/11, B310250474

--B310250493 Notice of violation from insp on B30626-30
* Region 2, Office of Director 83/08/25 1p 20900 067 24X
Fiche 50-324, 83/10/11, B310250474

--B310250501 IE Insp Repts 50-324/83-23 & 50-325/83-23 on B30626-30 Noncompliance noted large quantity shipment in CNS-2-55 shipping cask not leak tested prior to delivery of package to carrier for transport
ALBRIGHT, R H, BARR, K P Region 2, Office of Director 83/08/05 7pp 20900 068 24X Fiche 50-324, 83/10/11, B310250474

B310200166 Forwards Rev 13 to Engineering Procedure ENP-16, "Procedure for Administrative Control of Inservice Insp Activities " List providing status of existing relief/exemption requests encl
HOWE, P W Carolina Power & Light Co 83/10/12 VASSALLO, D R
Operating Reactors Branch 2 2pp 20148 001 24X
Fiche 50-324, 83/10/12, B310200166

--B310200168 Rev 13 to Engineering Procedure ENP-16, "Procedure for Administrative Control of Inservice Insp Activities " * Carolina Power & Light Co 83/08/26 280pp 20028 003 24X
Fiche 50-324, 83/10/12, B310200166

DOCKETED ITEMS

8310180551 Notification of 831021 meeting w/BWR licensees in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking
MIRAGLIA, F J Assistant Director for Safety Assessment 83/10/14
EISENHUT, D G Division of Licensing 5pp 20823 358 24X
Fiche 50-000, 83/10/14, 8310180551

8310210064 Forwards IE Safeguards Insp Repts 50-324/83-33 & 50-325/83-33 on 830927-29
VERRELLI, D Division of Project & Resident Programs 83/10/17
UTLEY, E E Carolina Power & Light Co 2pp 20857 266 24X
Fiche 50-324, 83/10/17, 8310210064

--8310210070 IE Safeguards Insp Repts 50-324/83-33 & 50-325/83-33 on 830927-29 No noncompliance noted Major areas inspected review of licensee action in correct prior violations & testing Details withheld (ref IOCR/121)
TOBIN, W J, MCCUIRE, D R Region 2, Office of Director 83/10/14
ip 20857 266 24X Fiche 50-324, 83/10/17, 8310210064

8310250451 Act receipt of 830804 ltr informing NRC of steps taken to correct violations noted in II Insp Repts 50-324/83-18 & 50-325/83-18 Violation re worker whole body count remains
O'REILLY, J P Region 2, Office of Director 83/10/17 UTLEY, E E Carolina Power & Light Co 2pp 20897 081 24X
Fiche 50-324, 83/10/17, 8310250451

--8310250457 Act receipt of 830804 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-18 & 50-325/83-18
LEWIS, R C Division of Project & Resident Programs 83/08/30
UTLEY, E E Carolina Power & Light Co ip 20897 083 24X
Fiche 50-324, 83/10/17, 8310250451

--8310250460 Responds to NRC 830705 ltr re violations noted in II Insp Repts 50-324/83-18 & 50-325/83-18 Corrective actions special ventilation hood installed from HEPA filtration unit in bag cutting/insp station
DIETZ, C R Carolina Power & Light Co 83/08/04 O'REILLY, J P Region 2, Office of Director 4pp 20897 084 24X
Fiche 50-324, 83/10/17, 8310250451

--8310250468 Forwards IE Insp Repts 50-324/83-18 & 50-325/83-18 on 830523-27 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/07/05
UTLEY, E E Carolina Power & Light Co 2pp 20897 088 24X
Fiche 50-324, 83/10/17, 8310250451

--8310250473 Notice of violation from insp on 830523-27
Region 2, Office of Director 83/07/05 ip 20897 090 24X
Fiche 50-324, 83/10/17, 8310250451

--8310250477 IE Insp Repts 50-324/83-18 & 50-325/83-18 on 830523-27 Noncompliance noted failure to perform adequate air sampling
ALBRICHT, R H, BARR, K P Region 2, Office of Director 83/07/01
7pp 20897 091 24X Fiche 50-324, 83/10/17, 8310250451

8310250571 Comments on detection of deficiencies in quality resulting from suppliers fraudulent actions, described in IE info Notices 83-07 & 83-01 & IE Bulletins 83-06 & 83-07 Use of add'l insp & testing during receipt insps investigated
MCDOUFFIE, M A Carolina Power & Light Co 83/10/21 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement ip 20900 347 24X Fiche 50-000, 83/10/21, 8310250571

Periodic operating reports & related correspondence

8310130124 Monthly operating repts for Sept 1983 W/831006 ltr
ARRISON, F J, DIETZ, C R Carolina Power & Light Co 83/10/06
JEYOUNG, R C Director's Office, Office of Inspection and Enforcement 14pp 20726 311 24X Fiche 50-324, 83/10/06, 8310130124

Reportable occurrences, LERs & related correspondence

10210329 Responds to FOIA request for all documents re significantly high rate of equipment failures for SL BWR/4 rated at 2,436 MW Forwards App A documents Documents also available in PDR
FELTON, J H Division of Ruler and Records 83/07/28 HAFNER, D Suffolk Nuclear Study Group 2pp 20892 223 24X
Fiche 50-000, 83/07/28, 8310210129

8303240341 Summarizes evaluation of LERs for 1982 IER submittals usually acceptable Potential mgt weakness indicated by large number of procedural deficiencies, lack of followup repts committed to & possible training problems
BEYFRIT, K V Reactor Operations Analysis Branch 83/03/15
LEWIS, R C Division of Project & Resident Programs 4pp 20882 269 24X Fiche 50-000, 83/07/28, 8310210329

8310040412 IER 83-037/03L-0 on 830831, control rod 18-35 did not have full-out indication while fully withdrawn caused by defective position indication switch Indication will be repaired during future unit outage W/830904 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/09/04
O'REILLY, J P Region 2, Office of Director 2pp 20647 360 24X
Fiche 50-325, 83/09/28, 8310040412

8310040582 IER 83-033/03L-0 on 830829, during power operation, discovered primary containment isolation sys reactor low level 7 instrument 1821-LIM-NO248-1 showing higher level than expected Caused by instrument draft W/830928 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/09/04
O'REILLY, J P Region 2, Office of Director 2pp 20625 375 24X
Fiche 50-325, 83/09/28, 8310040582

8310060218 RD re HP(1) sys, reported on 830904 Condition determined not reportable
DIETZ, C R Carolina Power & Light Co 83/09/30 O'REILLY, J P Region 2, Office of Director ip 20647 093 24X
Fiche 50-325, 83/09/30, 8310060218

8310120300 IER 83-042/03L-0 on 830909, rod full-out position indication did not work when rod fully withdrawn Caused by position indication probe connector or position indication feed switch problem W/831003 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/10/03
O'REILLY, J P Region 2, Office of Director 2pp 20691 014 24X
Fiche 50-325, 83/10/03, 8310120300

8310140011 Updated IER 83-036/03L-1 on 830804, during reactor startup, control power supply fuse on motor operator breaker of sys flow control valve 1-611-F068 blew Caused by broken open position lamp fuse replaced W/831004 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/10/04
O'REILLY, J P Region 2, Office of Director 2pp 20666 360 24X
Fiche 50-325, 83/10/04, 8310140011

8310140053 Updated IER 83-029/03L-1 on 830710, following reactor scram, RCIC sys turbine automatically started on reactor low level, but immediately tripped on high turbine exhaust pressure Caused by calibr discrepancy W/831004 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/10/04
O'REILLY, J P Region 2, Office of Director 3pp 20666 011 24X
Fiche 50-325, 83/10/04, 8310140053

8310170414 IER 83-044/03L-0 on 830917, reactor recirculation pump 1H motor generator set tripped Caused by high motor generator set fluid drive temp Control air to valve isolated W/831005 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/10/05
O'REILLY, J P Region 2, Office of Director 2pp 20779 117 24X
Fiche 50-325, 83/10/05, 8310170414

8310190141 IER 83-045/03L-0 on 830919 & 24, while performing reactor vessel level loop calibr, inbound PCIV steam supply to RCIC sys 831-F007 would not reopen past dual open-close position Cause unknown 100% repaired W/831011 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/10/11
O'REILLY, J P Region 2, Office of Director 2pp 20420 245 24X
Fiche 50-325, 83/10/11, 8310190141

8310190227 IER 83-039/03L-0 on 830923, during equipment & instrument channel checks, PI-0114 revealed drywell & suppression chamber water temp indications differed Caused by miscalibrated point indicator IR-77B Indicator adjusted W/831011 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/10/11
O'REILLY, J P Region 2, Office of Director 2pp 20618 048 24X
Fiche 50-325, 83/10/11, 8310190227

8310250521 Updated IER 83-018/03L-1 on 830503, during refueling outage, average power range monitor 11 discovered inoperable due to failed power supply Caused by defective diode, thyristor & capacitor W/831017 ltr
PASTVA, M J, DEYOUNG, R M, DIETZ, C R Carolina Power & Light Co 83/10/17
O'REILLY, J P Region 2, Office of Director 4pp 20901 293 24X Fiche 50-325, 83/10/17, 8310250521

8310270224 PNO-II-83-085 during ultrasonic exam of 26-inch recirculation sys discharge piping, suspect indications identified in two welds Add'l analysis of data for proper categorization continuing State of NC informed
BLAKE, J, HARDING, A Region 2, Office of Director 83/10/21 ip 20924 044 24X Fiche 50-325, 83/10/21, 8310270224

DOCKETED ITEMS

17

DOCKET 50 327 SFOUDYAH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8310040452 Submits central emergency control ctr meteorological data availability statistics for Apr-June 1983 Data availability reports will be discontinued due to consistently high data availability through previous rpt periods
MILLS, L M Tennessee Valley Authority 83/09/28 ADENSAH, E
Licensing Branch 4 2pp 20623 326 24X Fiche 50-000, 83/09/28, 8310040452

831010076 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20687 327 24X Fiche 50-327, 83/10/05, 831010076

- 8310110100 Public version of Rev 1 to Emergency Plan Implementing Procedure SGN-IP-19, "Radiological Emergency Plan Training"
W/830721 11
CRAWLEY, D L, KAMMER, D S Tennessee Valley Authority 83/09/16
DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 20687 330 24X Fiche 50-327, 83/10/05, 8310110096

8310250563 Forwards IE Insp Repts 50-327/83-21 & 50-328/83-21 on 830913-16 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/10/06
PARRIS, H O Tennessee Valley Authority 2pp 20901 144 24X Fiche 50-327, 83/10/06, 8310250563

- 8310250569 IE Insp Repts 50-327/83-21 & 50-328/83-21 on 830913-16 No noncompliance noted Major areas inspected fire protection/prevention program & implementation
GIBBONS, J D Region 2, Office of Director COMING, T E Division of Engineering & Operational Programs 83/10/04 5pp 20701 146 24X Fiche 50-327, 83/10/06, 8310250569

P Operating license stage documents & correspondence

8310030604 Forwards SER re response to Generic Ltr 81-21, "Natural Circulation Cooldown" Upon acceptable implementation of emergency response guidelines, procedures will be adequate to perform safe natural circulation shutdown
NOVAK, T M Assistant Director for Licensing 83/09/23 PARRIS, H O Tennessee Valley Authority 2pp 20607 288 24X Fiche 50-000, 83/09/23, 8310030604

--8310030607 SER accepting 81201 response to Generic Ltr 81-21, "Natural Circulation Cooldown"
* NRC - No Detailed Affiliation Given 83/09/23 5pp 20607 290 24X Fiche 50-000, 83/09/23, 8310030604

8310120043 Forwards Amends 31 & 32 to Licenses DPR-77 & DPR-79, respectively & safety evaluation Amends revise diesel generator surveillance requirements to reflect actual as-designed logic
ADENSAH, E O Licensing Branch 4 83/09/30 PARRIS, H O Tennessee Valley Authority 3pp 20751 259 24X Fiche 50-327, 83/09/30, 8310120043

--8310120046 Amends 31 & 32 to Licenses DPR-77 & DPR-79, respectively, revising diesel generator surveillance requirements to reflect actual as-designed logic
ADENSAH, E O Licensing Branch 4 83/09/30 5pp 20751 262 24X Fiche 50-327, 83/09/30, 8310120043

--8310120048 Safety evaluation supporting Amends 31 & 32 to Licenses DPR-77 & DPR-79, respectively
* Office of Nuclear Reactor Regulation, Director 83/09/30 2pp 20751 270 24X Fiche 50-327, 83/09/30, 8310120043

--8310120050 Requests FR publication of notice of consideration of issuance of amends to Licenses DPR-77 & DPR-79 & proposed NSHC determination & opportunity for hearing on 830615 & 0729 requests re diesel generator surveillance requirements
ADENSAH, E O Licensing Branch 4 83/10/04 MILLER, J K Operating Reactors Branch 3 1p 20751 272 24X Fiche 50-327, 83/09/30, 8310120043

--8310120056 Requests FR publication of notice of consideration of issuance of amends to Licenses DPR-77 & DPR-79 & proposed NSHC determination & opportunity for hearing on 830615 request re diesel generator surveillance requirements
ADENSAH, E O Licensing Branch 4 83/07/22 CLARK, R A Operating Reactors Branch 3 2pp 20751 273 24X Fiche 50-327, 83/09/30, 8310120043

8310190199 Forwards safety evaluation re util response to Generic Ltr 81-21 "Natural Circulation Cooldown" Upon acceptable implementation of emergency response guidelines, procedures adequate for safe natural circulation shutdown
NOVAK, T M Assistant Director for Licensing 83/09/30 RUCKER, H J Duke Power Co 2pp 20838 098 24X Fiche 50-000, 83/09/30, 8310190199

--8310190208 SER re response to Generic Ltr 81-21 "Natural Circulation Cooldown" Response acceptable
* NRC - No Detailed Affiliation Given 83/09/30 8pp 20838 100 24X Fiche 50-000, 83/09/30, 8310190199

8310170133 Forwards notice of consideration of issuance of amend to Licenses DPR-77 & DPR-79 & proposed NSHC determination & opportunity for hearing Amends change Tech Specs re DNR parameters & hydrogen igniter surveillance test
ADENSAH, E O Licensing Branch 4 83/10/11 PARRIS, H O Tennessee Valley Authority 2pp 20813 044 24X Fiche 50-327, 83/10/11, 8310170133

--8310170254 Notice of consideration of issuance of amend to Licenses DPR-77 & DPR-79 & proposed NSHC determination & opportunity for hearing
ADENSAH, E O Licensing Branch 4 83/10/04 6pp 20813 046 24X Fiche 50-327, 83/10/11, 8310170133

8310170261 Forwards NRC comments on TAYCO igniter spray environ program to be performed by Factory Mutual Response requested prior to test program completion
NOVAK, T M Assistant Director for Licensing 83/10/11 PARRIS, H O Tennessee Valley Authority 4pp 20756 261 24X Fiche 50-327, 83/10/11, 8310170133

8310180443 Requests extension until 840120 to submit final summary technical rpt on results of surveillance capsule in reactor vessel testing & analysis
KAMMER, D S Tennessee Valley Authority 83/10/13 ADENSAH, E O Licensing Branch 4 1p 20802 123 24X Fiche 50-327, 83/10/13, 8310180443

8310280021 Application for amend to Licenses DPR-77 & DPR-79 changing Tech Specs 3/4 7 9 for snubbers, ref to tables & deletion of ref to 51-162
MILLS, L M Tennessee Valley Authority 83/10/24 ADENSAH, E O Licensing Branch 4 2pp 20934 183 24X Fiche 50-327, 83/10/24, 8310280021

--8310280040 Proposed Tech Specs re Tables 3/4 7 9 on snubbers, deletion of Tables 4 7 9a, 4 7 9b & 4 7 9c from Limiting Condition for Operation 3 / 9, ref to tables & deletion of ref to 51-16P
* Tennessee Valley Authority 83/10/24 13pp 20934 185 24X Fiche 50-327, 83/10/24, 8310280021

8310280022 Forwards proposed Tech Specs, revising 830819 amend request re accident monitoring instrumentation
MILLS, L M Tennessee Valley Authority 83/10/24 ADENSAH, E O Licensing Branch 4 1p 20934 179 24X Fiche 50-327, 83/10/24, 8310280022

--8310280027 Proposed Tech Specs, revising 830819 submittal re accident monitoring instrumentation
* Tennessee Valley Authority 83/10/24 3pp 20934 180 24X Fiche 50-327, 83/10/24, 8310280022

8310310429 Application for amend to Licenses DPR-77 & DPR-79, changing allowable value for diesel generator start & load shed timer
MILLS, L M Tennessee Valley Authority 83/10/24 ADENSAH, E O Licensing Branch 4 2pp 20959 187 24X Fiche 50-327, 83/10/24, 8310310429

--8310310438 Proposed Tech Specs, changing allowable value for diesel generator start & load shed timer Significant hazards determination consideration encl
* Tennessee Valley Authority 83/10/24 5pp 20959 189 24X Fiche 50-327, 83/10/24, 8310310429

Q Inspection reports, IE Bulletins & correspondence

8310040442 Discusses WD DeFord discrimination case arising from unlawful actions against employee for participation in Jul 1980 NRC insp described in IL Insp Repts 50-327/80-24 & 50-328/80-15 dtd 800806 & forwards notice of violation
O'REILLY, J P Region 2, Office of Director 83/09/20 PARRIS, H O Tennessee Valley Authority 2pp 20619 048 24X Fiche 50-327, 83/09/20, 8310040442

DOCKETED ITEMS

- 8310040446 Notice of violation arising from WD Deford discrimination case re unlawful actions against employee for participation in Jul 1980 NRC insp
O'REILLY, J P Region 2, Office of Director 83/09/20 2pp
20619 050 24X Fiche 50-327, 83/09/20, 8310040442
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Wilder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345
- 8310250299 Forwards IE Insp Repts 50-327/83-17 & 50-328/83-17 on 830906-09 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/09/28
PARRIS, H G Tennessee Valley Authority 2pp 20895 331 24X Fiche 50-327, 83/09/28, 8310250299
- 8310250300 IE Insp Repts 50-327/83-17 & 50-328/83-17 on 830906-09 No noncompliance noted Major areas inspected inservice testing of pumps & valves & plant water chemistry
ROSS, W J Region 2, Office of Director BLAKE, J J Division of Engineering & Technical Programs 83/09/26 6pp 20895 331 24X Fiche 50-327, 83/09/28, 8310250299
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o IOPR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349
- 8310250475 Ack receipt of 830822 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-12 & 50-328/83-12
LEWIS, R C Division of Project & Resident Programs 83/10/03
PARRIS, H G Tennessee Valley Authority 1p 20902 103 24X Fiche 50-327, 83/10/03, 8310250475
- 8310250484 Responds to NRC 830725 ltr re violations noted in IE Insp Repts 50-327/83-12 & 50-328/83-12 Corrective actions all piping capped or sealed to prevent damage or deterioration & all stainless steel piping in storage shed sealed
MILLS, L M Tennessee Valley Authority 83/09/24 O'REILLY, J P Region 2, Office of Director 3pp 20902 104 24X Fiche 50-327, 83/10/03, 8310250475
- 8310250494 Responds to NRC 830/25 ltr re violation noted in IE Insp Repts 50-327/83-12 & 50-328/83-12 Corrective actions all piping corrected & verified capped or sealed to prevent damage or deterioration
HAMMER, D S Tennessee Valley Authority 83/08/27 O'REILLY, J P Region 2, Office of Director 2pp 20902 107 24X Fiche 50-327, 83/10/03, 8310250475
- 8310250502 Forwards IE Insp Repts 50-327/83-12 & 50-328/83-12 on 830606-0705 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/07/25
PARRIS, H G Tennessee Valley Authority 2pp 20902 110 24X Fiche 50-327, 83/10/03, 8310250475
- 8310250509 Notice of violation from insp on 830606-0705
* Region 2, Office of Director 83/07/25 1p 20902 112 24X Fiche 50-327, 83/10/03, 8310250475
- 8310250517 IE Insp Repts 50-327/83-12 & 50-328/83-12 on 830606-0705 Noncompliance noted failure to properly store QA matl
FORD, E J, BUTLER, S D Region 2, Office of Director QUICK, P R Division of Project & Resident Programs 83/07/22 6pp 20902 113 24X Fiche 50-327, 83/10/03, 8310250475
- 8310250403 Ack receipt of 830924 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-14 & 50-328/83-14
LEWIS, R C Division of Project & Resident Programs 83/10/05
PARRIS, H G Tennessee Valley Authority 1p 20897 199 24X Fiche 50-327, 83/10/05, 8310250403
- 8310250436 Responds to NRC 830824 ltr re violations noted in IE Insp Repts 50-327/83-14 & 50-328/83-14 Corrective actions all late audit repts issued by 8/10/83 & instructions served that deferment of responses unacceptable
MILLS, L M Tennessee Valley Authority 83/09/27 O'REILLY, J P Region 2, Office of Director 3pp 20897 200 24X Fiche 50-327, 83/10/05, 8310250403
- 8310250454 Forwards IE Insp Repts 50-327/83-14 & 50-328/83-14 on 830718-22 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/08/24
PARRIS, H G Tennessee Valley Authority 2pp 20897 201 24X Fiche 50-327, 83/10/05, 8310250403
- 8310250466 Notice of violation from insp on 830718-22
* Region 2, Office of Director 83/08/24 2pp 20897 207 24X Fiche 50-327, 83/10/05, 8310250403
- 8310250492 IE Insp Repts 50-327/83-14 & 50-328/83-14 on 830718-22 Noncompliance noted failure to assure that audit repts issued within 30 working days & failure to assure response to audit findings issued within 30 days
DEBBAG, A G, UPRIGHT, C M Division of Engineering & Operations Programs 83/08/18 7pp 20897 209 24X Fiche 50-327, 83/10/05, 8310250403
- 8310250563 Forwards IE Insp Repts 50-327/83-21 & 50-328/83-21 on 830913-14 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/10/06
PARRIS, H G Tennessee Valley Authority 2pp 20901 144 21X Fiche 50-327, 83/10/06, 8310250563
- 8310250569 IE Insp Repts 50-327/83-21 & 50-328/83-21 on 830913-14 No noncompliance noted Major areas inspected fire protection/prevention program & implementation
GIBBONS, T D Region 2, Office of Director COMUNITI, E Division of Engineering & Operational Programs 83/10/04 5pp 20901 146 24X Fiche 50-327, 83/10/06, 8310250561
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in R1D Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752
- 8308300799 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300799
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761
- 8310250593 Ack receipt of 83100/ ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-14 & 50-328/83-14
VERRELLI, D M Division of Project & Resident Programs 83/10/19
PARRIS, H G Tennessee Valley Authority 1p 20900 139 24X Fiche 50-327, 83/10/19, 8310250593
- 8310250602 Responds to NRC 830913 ltr re violations noted in IE Insp Repts 50-327/83-16 & 50-328/83-16 Corrective actions AB015 fan control switches placed in auto position A upon discovery & outboard bearing disassembled for QC insp
MILLS, L M Tennessee Valley Authority 83/10/07 O'REILLY, J P Region 2, Office of Director 4pp 20900 140 24X Fiche 50-327, 83/10/19, 8310250593
- 8310250611 Forwards IE Insp Repts 50-327/83-16 & 50-328/83-16 on 830706-0805 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/09/13
PARRIS, H G Tennessee Valley Authority 2pp 20900 144 24X Fiche 50-327, 83/10/19, 8310250593
- 8310250617 Notice of violation from insp on 830706-0805
* Region 2, Office of Director 83/09/13 2pp 20900 146 24X Fiche 50-327, 83/10/19, 8310250593

DOCKETED ITEMS

181

--8310250624 IE Insp Repts 50-327/83-16 & 50-328/83-16 on 830706-0009 Noncompliance noted failure to follow SDI-30 & for calibr of main & auxiliary feedwater pumps
FORD, E J., OUTLER, S D Region 2, Office of Director JULIAN, C A
Division of Project & Resident Programs 83/09/13 6pp
20900 14B 24X Fiche 50-327,83/10/19,8310250593

R Periodic operating reports & related correspondence

8310190066 Monthly operating repts for Aug 1983 W/830915 ltr
EDDINGS, M G., DUPREE, D C., MASON, C C Tennessee Valley Authority
83/09/15 Office of Resource Management, Director 19pp
20822 301 24X Fiche 50-327,83/09/15,8310190066

S Reportable occurrences, LERs & related correspondence

8310030218 LER 83-111/03L-O on 830831, while performing 81-102, diesel generator 1A2 found w/oil in glycol expansion tank Caused by oil on top of water from prior lube oil cooler leak & failed cylinder head Coolant replaced W/830928 ltr
BOSCH, G E., HARDING, M R., GREEN, H J Tennessee Valley Authority
83/09/28 O'REILLY, J P Region 2, Office of Director 2pp
20590 147 24X Fiche 50-327,83/09/28,8310030218

8310060083 LER 83-113/03L-O on 830901, steam generator blowdown effluent line radiation monitor (1-RM-90-120/121) declared inoperable Caused by loss of effluent flow during steam generator flushing process W/830923 ltr
ROGERS, H R., HARDING, M R., GREEN, H J Tennessee Valley Authority
83/09/28 O'REILLY, J P Region 2, Office of Director 2pp
20647 178 24X Fiche 50-327,83/09/28,8310060083

8310070301 Potential Part 21 rept re underrange characteristic of Model N-EIOM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X Fiche 50-000,83/09/30,8310070301

8310170276 LER 83-120/03L-O on 830910, all ice condenser doors opened when containment sump isolation valve 1-CV-63-73 stroked Caused by backflowed water causing small pressure surge in lower containment doors closed W/831007 ltr
GREEN, H J Tennessee Valley Authority 83/10/07 O'REILLY, J P Region 2, Office of Director App 20786 205 24X Fiche 50-327,83/10/07,8310170276

8310170592 LER 83-117/01T-O on 830926, monthly power range in-core/ ex-core channel comparison found not performed Caused by personnel error Surveillance performed Personnel restructured W/831007 ltr
GREEN, H J Tennessee Valley Authority 83/10/07 O'REILLY, J P Region 2, Office of Director 3pp 20780 190 24X Fiche 50-327,83/10/07,8310170592

8310170597 LER 83-119/03L-O on 830910, containment internal pressure limit for annulus pressure exceeded Caused by normal air leakage into containment w/o venting Containment pressure returned to within limit W/831007 ltr
GREEN, H J Tennessee Valley Authority 83/10/07 O'REILLY, J P Region 2, Office of Director App 20782 107 24X Fiche 50-327,83/10/07,8310170597

8310190124 Updated LER 83-063/03L-1 on 830912, while in Mode 3, following maint, PORV 1-PCV-6B-340 found leaking Caused by associated block valve not closing Fully PORVs will be replaced during refueling outage W/831011 ltr
KIRK, C., HARDING, M R., GREEN, H J Tennessee Valley Authority
83/10/11 O'REILLY, J P Region 2, Office of Director 3pp
20821 121 24X Fiche 50-327,83/10/11,8310190124

8310250077 LER 83-125/03L-O on 830920 & 22, condenser exhaust flow rate monitor 1-FY-2-257 failed high Caused by sensor lines containing buildup of condensate which caused channels to read high & erratic Lines blown down W/831017 ltr
ROGERS, H R., HARDING, M R., GREEN, H J Tennessee Valley Authority
83/10/17 O'REILLY, J P Region 2, Office of Director 2pp
20896 163 24X Fiche 50-327,83/10/17,8310250077

DOCKET 50-328 SEQUOIA NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8310040452 Submits central emergency control ctr meteorological data availability statistics for Apr-June 1983 Data availability repts will be discontinued due to consistently high data availability through previous rept periods
MILLS, L M Tennessee Valley Authority 83/09/28 ADENSAM, E
Licensing Branch 4 2pp 20623 326 24X Fiche 50-000,83/09/28,8310040452

8310210341 Forwards Amend 23 to License DPR-79 & safety evaluation Amend changes conditions re post-accident sampling (TMI Item 11 B 3), instruments for core cooling, addl accident monitoring instrumentation & upgrades support facilities
ADENSAM, E Q Licensing Branch 4 83/09/30 PARRIS, H O Tennessee Valley Authority 3pp 20883 130 24X Fiche 50-328,83/09/30,8310210341

--8310210344 Amend 23 to License DPR-79, changing post-accident sampling (TMI Item 11 B 3), addl accident monitoring instrumentation, instruments for core cooling & upgrading emergency support facilities
EISENHUT, D O Licensing Branch 4 83/09/30 2pp 20883 156, 24X Fiche 50-328,83/09/30,8310210341

8310110096 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20687 329 24X Fiche 50-327,83/10/05,8310110096

--8310110100 Public version of Rev 1 to Emergency Plan Implementing Procedure SON-IP-19, "Radiological Emergency Plan Training" W/830921 ltr
CRAWLEY, D E., HAMMER, D G Tennessee Valley Authority 83/09/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp
20687 330 24X Fiche 50-327,83/10/05,8310110096

8310250563 Forwards IE Insp Repts 50-327/83-21 & 50-328/83-21 on 830913-16 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/10/06 PARRIS, H O Tennessee Valley Authority 2pp 20901 144 24X Fiche 50-327,83/10/06,8310250563

--8310250569 IE Insp Repts 50-327/83-21 & 50-328/83-21 on 830913-16 No noncompliance noted Major areas inspected fire protection/prevention program & implementation
O'BRIEN, T D Region 2, Office of Director 83/10/04 5pp
20901 146 24X Fiche 50-327,83/10/06,8310250563

P Operating license stage documents & correspondence

8310030604 Forwards BER re response to Generic Ltr 81-21, "Natural Circulation Cutdown" Upon acceptable implementation of emergency response guidelines, procedures will be adequate to perform safe natural circulation cutdown
NOVAK, T M Assistant Director for Licensing 83/09/23 PARRIS, H O Tennessee Valley Authority 2pp 20607 288 24X Fiche 50-000,83/09/23,8310030604

--8310030607 BER accepting 811201 response to Generic Ltr 81-21, "Natural Circulation Cutdown"
* NRC - No Detailed Affiliation Given 83/09/23 8pp
20607 290 24X Fiche 50-000,83/09/23,8310030604

8310130029 Forwards Amend 21 to License DPR-79 & safety evaluation Amend changes Tech Specs to accommodate Cycle 2 reload operations & changes requirement for testing containment protective fuses to visual insp
ADENSAM, E Q Licensing Branch 4 83/09/29 PARRIS, H O Tennessee Valley Authority 3pp 20776 324 24X Fiche 50-328,83/09/29,8310130029

--8310130039 Amend 21 to License DPR-79, changing Tech Specs to accommodate Cycle 2 reload operations & changing requirement for testing containment protective fuses from destructive type testing to visual insp
ADENSAM, E Q Licensing Branch 4 83/09/29 28pp 20776 326 24X Fiche 50-328,83/09/29,8310130029

--8310130043 Safety evaluation supporting Amend 21 to License DPR-79
* Office of Nuclear Reactor Regulation, Director 83/09/29 9pp
20776 335 24X Fiche 50-328,83/09/29,8310130029

8310120043 Forwards Amends 31 & 22 to Licenses DPR-77 & DPR-79, respectively & safety evaluation Amends revise diesel generator surveillance requirements to reflect actual as-designed logic
ADENSAM, E Q Licensing Branch 4 83/09/30 PARRIS, H O Tennessee Valley Authority 3pp 20751 259 24X Fiche 50-327,83/09/30,8310120043

--8310120046 Amends 31 & 22 to Licenses DPR-77 & DPR-79, respectively, revising diesel generator surveillance requirements to reflect actual as-designed logic
ADENSAM, E Q Licensing Branch 4 83/09/30 8pp 20751 262 24X Fiche 50-327,83/09/30,8310120043

--8310120048 Safety evaluation supporting Amends 31 & 22 to Licenses DPR-77 & DPR-79, respectively
* Office of Nuclear Reactor Regulation, Director 83/09/30 2pp
20751 270 24X Fiche 50-327,83/09/30,8310120043

DOCKETED ITEMS

--8310120054 Requests FR publication of notice of consideration of issuance of amends to Licenses DPR-77 & DPR-79 & proposed NSHC determination & opportunity for hearing on 830615 request re diesel generator surveillance requirements
ADENSAH,E O Licensing Branch 4 83/07/22 CLARK,R A Operating Reactors Branch 3 2pp 20751 273 24X Fiche 50-327,83/09/30, 8310120043

8310190199 Forwards safety evaluation re util response to Generic Ltr 81-21 "Natural Circulation Cooldown " Upon acceptable implementation of emergency response guidelines,procedures adequate for safe natural circulation cooldown
NOVAH,T H Assistant Director For Licensing 83/09/30 TUCKER,H B Duke Power Co 2pp 20838 098 24X Fiche 50-000,83/09/30, 8310190199

--8310190208 SER re response to Generic Ltr 81-21 "Natural Circulation Cooldown " Response acceptable
* NRC - No Detailed Affiliation Given 83/09/30 Bpp 20838 100 24X Fiche 50-000,83/09/30, 8310190199

8310210341 Forwards Amend 23 to License DPR-79 & safety evaluation Amend changes conditions re post-accident sampling (THI Item 11 B 3),instruments for core cooling,addl accident monitoring instrumentation & upgrades support facilities
ADENSAH,E O Licensing Branch 4 83/09/30 PARRIS,H O Tennessee Valley Authority 3pp 20883 150 24X Fiche 50-328,83/09/30, 8310210341

--8310210344 Amend 23 to License DPR-79,changing post-accident sampling (THI Item 11 B 3),addl accident monitoring instrumentation, instruments for core cooling & upgrading emergency support facilities
EISENHUT,D O Licensing Branch 4 83/09/30 2pp 20883 152 24X Fiche 50-328,83/09/30, 8310210341

--8310210347 Safety evaluation supporting Amend 23 to License DPR-79 * Office of Nuclear Reactor Regulation, Director 83/09/30 3pp 20883 154 24X Fiche 50-328,83/09/30, 8310210341

8310170133 Forwards notice of consideration of issuance of amend to Licenses DPR-77 & DPR-79 & proposed NSHC determination & opportunity for hearing Amends change Tech Specs re DND parameters & hydrogen igniter surveillance test
ADENSAH,E O Licensing Branch 4 83/10/11 PARRIS,H O Tennessee Valley Authority 2pp 20813 044 24X Fiche 50-327,83/10/11, 8310170133

--8310170254 Notice of consideration of issuance of amend to licenses DPR-77 & DPR-79 & proposed NSHC determination & opportunity for hearing
ADENSAH,E O Licensing Branch 4 83/10/04 6pp 20813 046 24X Fiche 50-327,83/10/11,8310170133

8310170261 Forwards NRC comments on TAYCO igniter spray environ program to be performed by Factory Mutual Response requested prior to test program completion
NOVAH,T H Assistant Director For Licensing 83/10/11 PARRIS,H O Tennessee Valley Authority 4pp 20796 261 24X Fiche 50-327,83/10/11,8310170261

110280021 Application for amend to License DPR-77 & DPR-79 changing Tech Specs 3/4 7 7 for snubbers,ref to tables & deletion of ref to 51-162
MILLS,L M Tennessee Valley Authority 83/10/24 ADENSAH,E Licensing Branch 4 2pp 20934 183 24X Fiche 50-327,83/10/24, 8310280021

--8310280040 Proposed Tech Specs re Tables 3/4, 7 7 on snubbers, deletion of Tables 4 7 9a, 4 7 9b & 4 7 9c from Limiting Condition For Operation 3 7 9,ref to tables & deletion of ref to 51-162
* Tennessee Valley Authority 83/10/24 13pp 20934 185 24X Fiche 50-327,83/10/24,8310280021

310280022 Forwards proposed Tech Specs, revising 830819 amend request re accident monitoring instrumentation
MILLS,L M Tennessee Valley Authority 83/10/24 ADENSAH,E Licensing Branch 4 1p 20934 179 24X Fiche 50-327,83/10/24, 8310280022

-8310280027 Proposed Tech Specs, revising 830819 submittal re accident monitoring instrumentation
* Tennessee Valley Authority 83/10/24 3pp 20934 180 24X Fiche 50-327,83/10/24,8310280022

8310310429 Application for amend to Licenses DPR-77 & DPR-79, changing allowable value for diesel generator start & load shed timer
MILLS,L M Tennessee Valley Authority 83/10/24 ADENSAH,E Licensing Branch 4 2pp 20989 187 24X Fiche 50-327,83/10/24, 8310310429

--8310310438 Proposed Tech Specs,changing allowable value for diesel generator start & load shed timer significant hazards determination consideration encl
* Tennessee Valley Authority 83/10/24 5pp 20959 189 24X Fiche 50-327,83/10/24,8310310429

G Inspection reports, IE Bulletins & correspondence

8310040442 Discusses WD DeFord discrimination case arising from unlawful actions against employee for participation in Jul 1980 NRC insp described in 1L Insp Repts 50-327/80-24 & 50-328/80-15 dtd 800806 & forwards notice of violation
O'REILLY,J P Region 2, Office of Director 83/09/20 PARRIS,H O Tennessee Valley Authority 2pp 20619 048 24X Fiche 50-327,83/09/20,8310040442

--8310040446 Notice of violation arising from WD DeFord discrimination case re unlawful actions against employee for participation in Jul 1980 NRC insp
O'REILLY,J P Region 2, Office of Director 83/09/20 2pp 20619 050 24X Fiche 50-327,83/09/20,8310040442

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Wilder Qualification Tests " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345

8310250299 Forwards IE Insp Repts 50-327/83-17 & 50-328/83-17 on 830906-09 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/09/28 PARRIS,H O Tennessee Valley Authority 2pp 20895 331 24X Fiche 50-327,83/09/28,8310250299

--8310250300 IE Insp Repts 50-327/83-17 & 50-328/83-17 on 830906-09 No noncompliance noted Major areas inspected inservice testing of pumps & valves & plant water chemistry
ROSS,W J Region 2, Office of Director BLAKE,J J Division of Engineering & Technical Programs 83/09/26 6pp 20895 333 24X Fiche 50-327,83/09/28,8310250299

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349

8310130029 Forwards Amend 21 to License DPR-79 & safety evaluation Amend changes Tech Specs to accommodate Cycle 2 reload operations & changes requirement for testing containment protective fuses to visual insp
ADENSAH,E O Licensing Branch 4 83/09/29 PARRIS,H O Tennessee Valley Authority 3pp 20776 324 24X Fiche 50-328,83/09/29, 8310130029

--8310130039 Amend 21 to License DPR-79,changing Tech Specs to accommodate Cycle 2 reload operations & changing requirement for testing containment protective fuses from destructive type testing to visual insp
ADENSAH,E O Licensing Branch 4 83/09/29 28pp 20776 326 24X Fiche 50-328,83/09/29,8310130029

--8310130043 Safety evaluation supporting Amend 21 to License DPR-79 * Office of Nuclear Reactor Regulation, Director 83/09/29 9pp 20776 355 24X Fiche 50-328,83/09/29,8310130029

8310250475 Ack receipt of 830822 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-12 & 50-328/83-12
LEWIS,R C Division of Project & Resident Programs, 83/10/03 PARRIS,H O Tennessee Valley Authority 1p 20902 103 24X Fiche 50-327,83/10/03,8310250475

DOCKETED ITEMS

183

--8310250184 Responds to NRC 830725 ltr re violations noted in IE Insp Repts 50-327/83-12 & 50-328/83-12 Corrective actions all piping capped or sealed to prevent damage or deterioration & all stainless steel piping in storage shed sealed
MILLS, L M Tennessee Valley Authority 83/09/23 O'REILLY, J P
Region 2, Office of Director 3pp 20902 104 24X
Fiche 50-327, 83/10/03, 8310250475

--8310250494 Responds to NRC 830725 ltr re violation noted in IE Insp Repts 50-327/83-12 & 50-328/83-12 Corrective actions all piping corrected & verified capped or sealed to prevent damage or deterioration
KAMMER, D B Tennessee Valley Authority 83/08/22 O'REILLY, J P
Region 2, Office of Director 2pp 20902 107 24X
Fiche 50-327, 83/10/03, 8310250475

--8310250502 Forwards IE Insp Repts 50-327/83-12 & 50-328/83-12 on 830604-0705 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/07/25
PARRIS, H G Tennessee Valley Authority 2pp 20902 110 24X
Fiche 50-327, 83/10/03, 8310250475

--8310250507 Notice of violation from insp on 830604-0705
* Region 2, Office of Director 83/07/23 1p 20902 112 24X
Fiche 50-327, 83/10/03, 8310250475

--8310250517 IE Insp Repts 50-327/83-12 & 50-328/83-12 on 830604-0705
Noncompliance noted failure to properly store OA mail
FORD, E J, BUTLER, S D Region 2, Office of Director QUICK, D R
Division of Project & Resident Programs 83/07/22 8pp
20902 113 24X Fiche 50-327, 83/10/03, 8310250475

8310250403 Ack receipt of 830923 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-14 & 50-328/83-14
LEWIS, R C Division of Project & Resident Programs 83/10/05
PARRIS, H G Tennessee Valley Authority 1p 20897 199 24X
Fiche 50-327, 83/10/05, 8310250403

--8310250436 Responds to NRC 830824 ltr re violations noted in IE Insp Repts 50-327/83-14 & 50-328/83-14 Corrective actions all late audit repts issued by 830630 & instructions issued that deferment of responses unacceptable
MILLS, L M Tennessee Valley Authority 83/09/23 O'REILLY, J P
Region 2, Office of Director 5pp 20897 200 24X
Fiche 50-327, 83/10/05, 8310250403

--8310250454 Forwards IE Insp Repts 50-327/83-14 & 50-328/83-14 on 830718-22 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/08/24
PARRIS, H G Tennessee Valley Authority 2pp 20897 205 24X
Fiche 50-327, 83/10/05, 8310250403

--8310250466 Notice of violation from insp on 830718-22
* Region 2, Office of Director 83/08/24 2pp 20897 207 24X
Fiche 50-327, 83/10/05, 8310250403

--8310250492 IE Insp Repts 50-327/83-14 & 50-328/83-14 on 830718-22
Noncompliance noted failure to assure that audit repts issued within 30 working days & failure to assure responses to audit findings issued within 30 days
BEBBAGE, A G, UPRIGHT, C M Division of Engineering & Operational Programs 83/08/18 7pp 20897 209 24X Fiche 50-327, 83/10/05, 8310250403

8310250563 Forwards IE Insp Repts 50-327/83-21 & 50-328/83-21 on 830913-16 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/10/06
PARRIS, H G Tennessee Valley Authority 2pp 20901 144 24X
Fiche 50-327, 83/10/06, 8310250563

--8310250567 IE Insp Repts 50-327/83-21 & 50-328/83-21 on 830913-16 No noncompliance noted Major areas inspected fire protection/prevention program & implementation
QIBBONS, T D Region 2, Office of Director CONLON, T E Division of Engineering & Operational Programs 83/10/04 5pp 20701 146 24X Fiche 50-327, 83/10/06, 8310250563

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 11pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310250593 Ack receipt of 831007 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-16 & 50-328/83-16
VERRELLI, D M Division of Project & Resident Programs 83/10/19
PARRIS, H G Tennessee Valley Authority 1p 20900 139 24X
Fiche 50-327, 83/10/19, 8310250593

--8310250602 Responds to NRC 830913 ltr re violations noted in IE Insp Repts 50-327/83-16 & 50-328/83-16 Corrective actions ABOTS fan control switches placed in auto position A upon discovery & outboard bearing disassembled for GC insp
MILLS, L M Tennessee Valley Authority 83/10/07 O'REILLY, J P
Region 2, Office of Director 4pp 20900 140 24X
Fiche 50-327, 83/10/19, 8310250593

--8310250611 Forwards IE Insp Repts 50-327/83-16 & 50-328/83-16 on 830706-0805 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/09/13
PARRIS, H G Tennessee Valley Authority 2pp 20900 144 24X
Fiche 50-327, 83/10/19, 8310250593

--8310250617 Notice of violation from insp on 830706-0805
* Region 2, Office of Director 83/09/13 2pp 20900 146 24X
Fiche 50-327, 83/10/19, 8310250593

--8310250624 IE Insp Repts 50-327/83-16 & 50-328/83-16 on 830706-0805
Noncompliance noted failure to follow SDI-30 6 for calibr of main & auxiliary feedwater pumps
FORD, E J, BUTLER, S D Region 2, Office of Director JULIAN, C A
Division of Project & Resident Programs 83/09/13 4pp
20900 148 24X Fiche 50-327, 83/10/19, 8310250593

R Periodic operating reports & related correspondence

8310190066 Monthly operating repts for Aug 1983 W/830915 ltr
EDDINGS, H G, DUPREE, D C, MASON, C C Tennessee Valley Authority
83/09/15 Office of Resource Management, Director 19pp
20822 301 24X Fiche 50-327, 83/09/15, 8310190066

S Reportable occurrences, LERs & related correspondence

8310030240 LER 83-114/03L-0 on 830823, during testing of safety injection sys (SIS) & centrifugal charging pumps (CCP), SIS pump 2A & both CCPs failed to meet min head curve requirements Caused by normal pump operation W/830921 ltr
HARDING, H R, KIRK, G B, GREEN, H J Tennessee Valley Authority
83/09/21 O'REILLY, J P Region 2, Office of Director 4pp
20590 075 24X Fiche 50-328, 83/09/21, 8310030240

8310070301 Potential Part 21 rept re underrange characteristic of Model N-E110M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X
Fiche 50-000, 83/09/30, 8310070301

8310140087 LER 83-118/03L-0 on 830907, 81-214 re uncontrolled boron dilution not performed within required 72 h frequency Caused by personnel error Operations personnel reinstructed W/ 831006 ltr
GREEN, H J Tennessee Valley Authority 83/10/06 O'REILLY, J P
Region 2, Office of Director 2pp 20767 009 24X
Fiche 50-328, 83/10/06, 8310140087

8310170658 LER 83-121/03L-0 on 830911, during Mode 5, lower containment airlock failed overall leakage Test SI-157 1 Caused by leakage through four handwheel packings due to normal wear. Doors overhauled W/831007 ltr
GREEN, H J Tennessee Valley Authority 83/10/07 O'REILLY, J P
Region 2, Office of Director 3pp 20779 282 24X
Fiche 50-328, 83/10/07, 8310170658

DOCKETED ITEMS

DOCKET 50-329 MIDLAND PLANT, UNIT 1

A Application/construction stage documents & correspondence

8310190311 FOIA request for documents re caseload forecast panel B30419 meeting on plant const
GARDE, B P Government Accountability Project 83/07/11 Office
of Administration 2pp 20840 329 24X Fiche 50-329, 83/07/11, 8310190311

8310180618 FOIA request for documents submitted by util for consideration of candidate companies or methodologies to perform const implementation overview of const completion plan
GARDE, B P Government Accountability Project 83/08/05 Office
of Administration 2pp 20839 110 24X Fiche 50-329, 83/08/05, 8310180618

8310130390 FOIA request for all records on re-review of structural adequacy of diesel generator bldg subsequent to May testimony of R Landsman in ASLB proceedings
GARDE, B P Government Accountability Project 83/08/08 Office
of Administration 2pp 20769 352 24X Fiche 50-329, 83/08/08, 8310130390

8310190316 Responds to FOIA request for documents re caseload forecast panel B30419 meeting on plant const info partially withheld
JH Cook draft ltr to TM Novak (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/08/09 GARDE, B P
Government Accountability Project 6pp 21116 001 24X
Fiche 50-329, 83/08/09, 8310190316

8310190300 Appeals denial of FOIA request for documents re caseload forecast panel B30419 meeting on plant const Denial effectively denied bulk of documents requested
GARDE, B P Government Accountability Project 83/08/10
DIRCKS, W J Office of the Executive Director for Operations 2pp
20840 326 24X Fiche 50-329, 83/08/10, 8310190300

8310130394 Responds to FOIA request for all records on re-review of structural adequacy of diesel generator bldg subsequent to May testimony of R Landsman in ASLB proceedings Forwards App A documents Documents also in PDR
FELTON, J M Division of Rules and Records 83/08/25 GARDE, B P
Government Accountability Project 2pp 20769 354 24X
Fiche 50-329, 83/08/25, 8310130394

8308150338 Advises of assignment as member of task group to reevaluate structural design & const adequacy of plant diesel generator bldg
KUD, P T Structural & Geotechnical Engineering Branch 83/08/08
TAN, C P Structural & Geotechnical Engineering Branch 1p
20769 362 24X Fiche 50-329, 83/08/25, 8310130394

8308290029 Requests meeting on 830822 to discuss Landsman concerns that diesel generator bldg inadequate to return to svc based on inability to meet design requirements
VOLLMER, R NRC - No Detailed Affiliation Given, 83/08/15
KNIGHT, J NRC - No Detailed Affiliation Given, 1p 20769 361
24X Fiche 50-329, 83/08/25, 8310130394

8310180625 Responds to FOIA request for records submitted by util & reviewed during consideration of candidate companies or methodologies re const implementation overview Forwards documents Documents also available in PDR
FELTON, J M Division of Rules and Records, 83/09/01, GARDE, B P
Government Accountability Project 3pp 20839 112 24X
Fiche 50-329, 83/09/01, 8310180625

8310280450 Forwards util 821005 three-part independent review program consisting of biennial quality audits, INPD-type const evaluation & independent design verification of auxiliary feedwater sys Meeting scheduled for 831019 to discuss plan
NOVAK, T M Assistant Director for Licensing 82/10/07
VOLLMER, R H Division of Engineering, 1p, 20839 124 24X
Fiche 50-329, 83/09/01, 8310180625

8312300076 Documents conclusions reached at 821207 meeting in Bethesda, MD re QA implementation at facility Region 3 insp of diesel generator bldg & util decision to stop certain safety-related work being performed by Bechtel
HERNAN, R W Licensing Branch 4 82/12/21 NOVAK, T M Assistant
Director for Licensing 3pp 20839 125, 24X
Fiche 50-329, 83/09/01, 8310180625

8310180630 Forwards util revised plan for const completion Program includes measures to be taken as result of work slowdown & elements of QA implementation & third-party assessments requested by NRC w/o encl.
HERNAN, R Division of Licensing, 83/01/12 ADENSAH, E. NRC - No
Detailed Affiliation Given 1p, 20839 128 24X
Fiche 50-329, 83/09/01, 8310180625

8310190034 Rev 1 to Quality Control Instruction 10 01, "Const Implementation Overview Assessment"
THOMPSON, J C Stone & Webster Engineering Corp 83/06/21 bpp
20839 134 24X Fiche 50-329, 83/09/01, 8310180625

8310190036 Rev 0 to Verification Attribute Checklist P-2 20V, "Pipe Supports"
BARANDOW, S W Stone & Webster Engineering Corp 83/07/21 10pp
20839 140 24X Fiche 50-329, 83/09/01, 8310180625

8310190038 Rev 1 to third-party const implementation overview approval
KELLY, R B Stone & Webster Engineering Corp 83/08/05 5pp
20839 150 24X Fiche 50-329, 83/09/01, 8310180625

8310190042 Rev 1 to Quality Control Instruction 15 01, "Nonconformance Identification & Reporting"
BARANDOW, S Stone & Webster Engineering Corp 83/08/05 5pp
20839 155 24X Fiche 50-329, 83/09/01, 8310180625

8310190047 Rev 1 for third-party const implementation overview re QA plan
BARANDOW, S, WALTERS, C, KELLY, R B Stone & Webster Engineering Corp 83/08/05 4pp 20839 160 24X Fiche 50-329, 83/09/01, 8310180625

8310030542 Memorializes 830902 telcon re rescheduling of Sept 1983 followup meeting on const completion dates Meeting will not be held in Sept
HODD, D Licensing Branch 4 83/09/08 ADENSAH, E G Licensing
Branch 4 1p 20602 353 24X Fiche 50-329, 83/09/08, 8310070542

8310190305 Responds to appeal re denial of FOIA request for documents on caseload forecast panel B30419 meeting on plant const All documents identified subj to request Appeal re 1 Novak draft ltr to JH Cook moot
DIRCKS, W J Office of the Executive Director for Operations 83/09/13 GARDE, B P Government Accountability Project 1p
20840 328 24X Fiche 50-329, 83/09/13, 8310190305

8310240029 Confirms transmittal of controlled copies of PQCI &/or changes to SM SM-1 70, Rev 1 to CNA00079, C-2 10, Rev 12 & MW-1 00, Rev 2
PUCCI, J A Consumers Power Co 83/09/15 BARANDOW, S Stone &
Webster Engineering Corp 1p 20881 360 24X Fiche 50-329, 83/09/15, 8310240029

8310240131 Confirms transmittal of listed revs to PQCI
EWERT, G F Consumers Power Co 83/09/19 BARANDOW, S Stone &
Webster, Inc 1p 20881 365 24X Fiche 50-329, 83/09/19, 8310240131

8310240033 Confirms transmittal of computer printout containing info on MPQAD (balance of plant) inspector records Print covers all training, exams, performance demos & certifications
BOTIMER, L A Consumers Power Co 83/09/20 BARANDOW, S Stone &
Webster Engineering Corp 1p 20881 359 24X Fiche 50-329, 83/09/20, 8310240033

8310240033 Confirms transmittal of controlled copies of PQCI &/or changes to SM control log for wk ending 830916, PF-1 10, Rev 4 to CNA00043 & E-1 60, Rev 6 followup to inactive ltr
PUCCI, J A Consumers Power Co 83/09/20 BARANDOW, S Stone &
Webster Engineering Corp 1p 20881 347 24X Fiche 50-329, 83/09/20, 8310240033

8310240050 Confirms transmittal of controlled copies of PQCI &/or changes to SM control log for wk ending 830916, PF-1 10, Rev 4 to CNA00043 & E-1 60, Rev 6 followup to inactive ltr
PUCCI, J A Consumers Power Co 83/09/20 BARANDOW, S Stone &
Webster Engineering Corp 1p 20881 347 24X Fiche 50-329, 83/09/20, 8310240050

8310240063 Confirms transmittal of controlled copies of PQCI &/or changes to SM procedures
PUCCI, J A Consumers Power Co 83/09/22 BARANDOW, S Stone &
Webster, Inc 1p 20881 346 24X Fiche 50-329, 83/09/22, 8310240063

8310040122 Requests authorization for listed remedial soils work activities
MOONEY, J A Consumers Power Co 83/09/26 HARRISON, J J Region 3,
Office of Director 1p 20608 278 24X Fiche 50-329, 83/09/26, 8310040122

8310050296 Requests authorization to perform listed remedial soils work re solid waste processing sys, Soldier Piles 1-30
MOONEY, J A Consumers Power Co 83/09/28 HARRISON, J J Region 3,
Office of Director 1p 20628 351 24X Fiche 50-329, 83/09/28, 8310050296

DOCKETED ITEMS

185

8310050322 Discusses 830927 telcon re moving check valves & pipe supports in svc water bldg Work involves minor change to benchmark installation & can be completed as agreed
MOOREY, J A Consumers Power Co 83/09/28 HARRISON, J J Region 3, Office of Director 1p 20634 001 24X Fiche 50-329, 83/09/28, 8310050322

8310070109 Notification of 831004-06 meetings w/util & Bechtel in Midland, MI to review structural adequacy of as-constructed HVAC sys
MOORE, D B Licensing Branch 4 83/09/28 ADENSAM, E G Licensing Branch 4 5pp 20671 310 24X Fiche 50-329, 83/09/28 8310070109

8310070142 Forwards response to 830526 request for addl info re Question 130 26 for Vol I of seismic margin review rpt entitled "Methodology & Criteria"
COOK, J W Consumers Power Co 83/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 22pp 20654 038 24X Fiche 50-329, 83/09/28, 8310070142

8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway
EISENHUT, D G Division of Licensing 83/09/29 PALLADINO, N J Commissioners 3pp 20632 001 24X Fiche 50-000, 83/09/29, 8308300357

8310050341 Forwards evaluation of util proposal to have S&W perform third-party independent overview of const completion program Proposal approved
KEPPLER, J G Region 3, Office of Director 83/09/29 COOK, J W Consumers Power Co 7pp 20632 357 24X Fiche 50-329, 83/09/29, 8310050341

8310110377 Summarizes 830926 telcon w/M Capicchioni of util re location of safety-related equipment in local break zones Applicant will submit info indicating no subj equipment at location
MILLER, M A Licensing Branch 4 83/09/29 Licensing Branch 4 3pp 20713 228 24X Fiche 50-329, 83/09/29, 8310110377

8310050393 Issues authorization to proceed w/remedial soils work activities scheduled for Oct 1983
HARRISON, J J Region 3, Office of Director 83/09/30 MILLER, D B Consumers Power Co 2pp 20632 163 24X Fiche 50-329, 83/09/30, 8310050393

8310120320 Responds to NRC concerns re equipment qualification & seismic margin review program, as discussed at 830208 meeting w/NRC
COOK, J W Consumers Power Co 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 24pp 20700 2/5 24X Fiche 50-329, 83/09/30, 8310120320

8310170624 Forwards resumes for insertion into QA program, App C for IDVP
LEVIN, H A TERA Corp 83/09/30 KEPPLER, J G Region 3, Office of Director EISENHUT, D G Division of Licensing COOK, J W Consumers Power Co 8pp 20782 072 24X Fiche 50-329, 83/09/30, 8310170624

8310110635 Summary of 830913 meeting w/util & Bechtel re util compliance w/GDC 51 re fracture toughness characterization
MILLER, M Licensing Branch 4 83/10/04 Licensing Branch 4 20pp 20706 329 24X Fiche 50-329, 83/10/04, 8310110635

8310170721 Discusses NRC concerns re delays in establishing firm schedule for plant completion Estimate developed by NRC will be utilized for planning purposes if response not forthcoming
NOVAK, T M Assistant Director for Licensing 83/10/04 COOK, J W Consumers Power Co 5pp 20748 110 24X Fiche 50-329, 83/10/04, 8310170721

8310240136 Confirms transmittal of PQCI &/or changes to PQCI, including control logs for wks ending 830923 & 30
PUCCI, J A Consumers Power Co 83/10/04 BARANOW, S Stone & Webster, Inc 1p 20881 169 24X Fiche 50-329, 83/10/04, 8310240136

8310120179 Provides info re licensee 830928 decision to stop all "Q" soil drilling & pile driving imposed as result of unknowingly drilling into structural concrete Info provided per board notification procedures
HARNICK, R F Region 3, Office of Director 83/10/05 EISENHUT, D G Division of Licensing 2pp 20693 326 24X Fiche 50-329, 83/10/05, 8310120179

8310170068 Advises that Option 1 in H Levin 830815 ltr acceptable re selection of independent design & const verification program associated w/Baction 13 of Public Law 97-415 (Ford Amend)
NOVAK, T M Assistant Director for Licensing 83/10/05 COOK, J W Consumers Power Co LEVIN, H A TERA Corp 4pp 20798 024 24X Fiche 50-329, 83/10/05, 8310170068

8310170714 Documents 830927 telcon re removal of all soil & drift sets above Elevation 600 ft on north side of drift from KC2 to KC3 after drift invert is poured
MILLER, D B Consumers Power Co 83/10/05 HARRISON, J J Region 3, Office of Director 1p 20779 230 24X Fiche 50-329, 83/10/05, 8310170714

8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ABCO solenoid valves
EISENHUT, D G Division of Licensing 83/10/06 PALLADINO, N J Commissioners 3pp 20818 001 24X Fiche 50-000, 83/10/06, 8308300771

8310130045 Notification of 831017-21 meetings w/util, Interlock, Inc & LLL in Midland, MI to audit control room & related documentation prior to implementation of human factors related mods
MILLER, M A Licensing Branch 4 83/10/06 ADENSAM, E G Licensing Branch 4 5pp 20776 237 24X Fiche 50-329, 83/10/06, 8310130045

8310140270 Authorizes critical work activities presently scheduled for Oct 1983, per 831005 request
HARRISON, J J Region 3, Office of Director 83/10/06 MILLER, D B Consumers Power Co 3pp 20761 264 24X Fiche 50-329, 83/10/06, 8310140270

--8310140273 Requests authority to proceed w/work authorization Procedures 752050001 & 752050002 for drilling, replacing & installing anodes
MILLER, D B Consumers Power Co 83/10/05 HARRISON, J J Region 3, Office of Director 1p 20761 266 24X Fiche 50-329, 83/10/06, 8310140270

8310200375 Forwards confirmatory order for mod of CPPR-B1 & CPPR-B2 due to continued problems in implementation of QA program
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/10/06 COOK, J W Consumers Power Co 4pp 20859 069 24X Fiche 50-329, 83/10/06, 8310200375

--8310200380 Confirmatory order for mod of CPPR-B1 & CPPR-B2 due to continued problems in implementation of QA program
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/10/06 Consumers Power Co 5pp 20859 073 24X Fiche 50-329, 83/10/06, 8310200375

--8310200386 Decision DD-83-16 re BP Garde of Govt Accountability Project on behalf of Lone Tree Council 2 206 request that NRC take immediate action w/Midland project due to continued problems in implementation of QA program
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/10/06 23pp 20859 078 24X Fiche 50-329, 83/10/06, 8310200375

--8310200392 Notice of issuance of Director's Decision DD-83-16 re 830610 2 206 petition filed by BP Garde of Govt Accountability Project on behalf of Lone Tree Council re Midland project
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/10/06 1p 20859 101 24X Fiche 50-329, 83/10/06, 8310200375

8310240084 Confirms transmittal of controlled copies of &/or changes to PQCI, as listed
PUCCI, J A Consumers Power Co 83/10/07 BARANOW, S Stone & Webster, Inc 1p 20881 004 24X Fiche 50-329, 83/10/07, 8310240084

8310170257 Requests that encl D&W Site Ofc Manager Ltr 490 re torque wrench for replacement of CBA flow distributor bolts be forwarded to D&W
MILLER, D B Consumers Power Co 83/10/10 HIERZER, O A Bechtel Corp 2pp 20787 087 24X Fiche 50-329, 83/10/10, 8310170257

8310240023 Confirms transmittal of three computer printouts containing info on MPQAD (balance of plant) inspector records Printout covers all training, exams, performance demos & certifications
BOTIMER, L A Consumers Power Co 83/10/10 BARANOW, S Stone & Webster Engineering Corp 1p 20880 341 24X Fiche 50-329, 83/10/10, 8310240023

8308300767 Board Notification 83-153 suppls info re R Landsman concerns on structural adequacy of diesel generator bldg
NOVAK, T M Assistant Director for Licensing 83/10/11 Atomic Safety and Licensing Board Panel 3pp 20717 153 24X Fiche 50-329, 83/10/11, 8308300767

--8310050059 Responds to 830815 memo re R Landsman concerns on inadequate diesel generator bldg Task group rpt scheduled to be completed in Oct 1983
KNIGHT, J P Assistant Director for Comp & Structures Engineering (Post 830201), 83/09/23 VOLLMER, R H Division of Engineering 2pp 20717 156 24X Fiche 50-329, 83/10/11, 8308300767

DOCKETED ITEMS

- 8310130269 Requests identity of any consultant or NRC employee sharing Landsman concern that diesel generator bldg inadequate
Matters to be discussed on 830822
VOLLNER, R NRC - No Detailed Affiliation Given 83/08/15
KNIGHT, J NRC - No Detailed Affiliation Given 1p 20717 158
24X Fiche 50-329, 83/10/11, 8308300767
- 8310170436 Authorizes listed remedial soils work activities scheduled for Oct 1983
HARRISON, J J Region 3, Office of Director 83/10/11 MILLER, D B
Consumers Power Co 2pp 20779 222 24X Fiche 50-329, 83/10/11,
8310170436
- 8310170439 Requests remedial soils work authorization for emergency personnel locks
MILLER, D B Consumers Power Co 83/10/06 HARRISON, J J Region 3, Office of Director 1p 20779 224 24X Fiche 50-329, 83/10/11,
8310170436
- 8310210134 Forwards summary of 830912-13 meetings w/DNL & Bechtel in Ann Arbor, MI re structural adequacy of diesel generator bldg
HOOD, D B Licensing Branch 4 83/10/12 Licensing Branch 4
4pp 20884 096 24X Fiche 50-329, 83/10/12, 8310210134
- 8310070007 Trip rept of 830912-13 visit to Bechtel ofcs in Ann Arbor, MI to conduct audit of structural design calculations of diesel generator bldg Attendance list & chronological list of events before & after NRC order modifying CPs encl
ROMNEY, N D Structural & Geotechnical Engineering Branch
83/09/29 LEAR, O E Structural & Geotechnical Engineering Branch
19pp 20884 100 24X Fiche 50-329, 83/10/12, 8310210134
- 8310210142 "Midland Plants, Units 1 & 2 Diesel Generator Bldg, Executive Summary"
* Bechtel Corp 83/08/24 48pp 20884 119 24X
Fiche 50-329, 83/10/12, 8310210134
- 8310200265 Forwards quality action requests on NIRs 002-003, describing actions taken to resolve deficiencies, per 831007 ltr. Review expected to be completed by 831216
WELLS, R A Consumers Power Co 83/10/13 BARANOW, S W Stone & Webster, Inc 18pp 20830 051 24X Fiche 50-329, 83/10/13,
8310200265
- 8308310050 Board Notification 83-160 provides info re 830812 Failure of main crankshaft on one of three Transamerica Delaval emergency diesel generators at Shoreham
EISENHUT, D O Division of Licensing 83/10/14 PALLADINO, N J Commissioners 15pp 67056 070 24X Fiche 50-000, 83/10/14,
8308310050
- 8310210027 Responds to 830912 request for addl info re comparison of rebar stresses resulting from two 40-yr estimated settlement analyses performed on diesel generator bldg finite-element model
ERHARDT, R J Consumers Power Co 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 20856 012 24X
Fiche 50-329, 83/10/14, 8310210027
- 8310250058 Discusses current const status of project, in lieu of submitting yellowbook update for Third Quarter 1983 On 831006, ABL order to complete project received Completion schedule being developed Update submittal requested
MILLER, D B Consumers Power Co 83/10/14 HARTFIELD, R A NRC - No Detailed Affiliation Given 1p 20879 169 24X
Fiche 50-329, 83/10/14, 8310250058
- 8310270066 Confirms transmittal of control copies of PQCI &/or changes as listed
EWERT, O F, PUCCI, J A Consumers Power Co 83/10/17 BARANOW, S Stone & Webster, Inc 1p 20924 120 24X Fiche 50-329, 83/10/17,
8310270066
- 8310310366 Requests authorization for listed remedial soils work
GUAMME, D L Consumers Power Co 83/10/17 HARRISON, J J Region 3, Office of Director 2pp 20961 112 24X Fiche 50-329, 83/10/17,
8310310366
- 8310240107 Informs that S&W meets independence & competence criteria for third-party reviewers & that proposed const overview adequate for assessment of const completion plan in response to 830925 ltr. NRC orders encl.
KEPFLER, J O, Region 3, Office of Director 83/10/18 ROMO, L R Lone Tree Council 2pp 20081 022 24X Fiche 50-329, 83/10/18,
8310240107
- 8310250499 Authorizes listed remedial soils work activities for Oct 1983
HARRISON, J J Region 3, Office of Director 83/10/19 MILLER, D B Consumers Power Co 2pp 20902 086 24X Fiche 50-329, 83/10/19,
8310250499
- 8310250507 Requests authorization for listed remedial soils work
GUAMME, D L Consumers Power Co 83/10/17 HARRISON, J J Region 3, Office of Director 2pp 20902 088 24X Fiche 50-329,
83/10/19, 8310250499
- 8310260331 Forwards procedures for performing calculations & technical studies, resolution of spatial sys interaction program/seismic postulated interactions & preparation of project technical repts
ERHARDT, R J Consumers Power Co 83/10/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 20909 224 24X
Fiche 50-329, 83/10/19, 8310260331
- 8310260335 Rev 1 to Procedure ATP-13-G, "Procedure for Performing Calculations & Technical Studies"
* Mark Technologies Corp 83/08/26 13pp 20909 231 24X
Fiche 50-329, 83/10/19, 8310260331
- 8310260340 Rev 1 to Procedure 8301 WTP-4-G, "Procedure for Resolution of Spatial Sys Interaction Program/Seismic Postulated Interactions"
DURAND, R J Mark Technologies Corp 83/08/26 7pp 20909 244 24X
Fiche 50-329, 83/10/19, 8310260331
- 8310260344 Rev 1 to Procedure ATP-13-G, "Procedure for Preparation of Project Technical Repts"
* Mark Technologies Corp 83/08/26 10pp 20909 251 24X
Fiche 50-329, 83/10/19, 8310260331
- 8310310369 Confirms transmittal of controlled QA program manual for Vol I, "Policies" & Vol II "Procedure for Design & Const"
EWERT, O F Consumers Power Co 83/10/19 BARANOW, S Stone & Webster, Inc 1p 20959 241 24X Fiche 50-329, 83/10/19, 8310310369
- 8310310489 Summary of 830826 meeting w/B&W Owners Group re implementation of Generic ltr 83-28 concerning defenses against ATWS & proposed ATWS rule for B&W plants List of attendees & viewpoints encl
KADAMBI, P Operating Reactors Branch 4 83/10/20 Operating Reactors Branch 4 13pp 20965 147 24X Fiche 50-000, 83/10/20,
8310310489
- 8308310032 Board Notification 83-155 forwards info re util 830928 stop work order on G-soil drilling & pile driving after drilling into structural concrete
NOVAK, T M Assistant Director for Licensing 83/10/24 Atomic Safety and Licensing Board Panel 3pp 20909 261 24X
Fiche 50-329, 83/10/24, 8308310032
- 8310260285 Submits new info & matl relevant to OH/OL proceeding re license 830928 decision to stop all G-soil drilling & pile driving after unknowingly drilling into structural concrete
Drilling procedures will be revised
WARNICK, R F Region 3, Office of Director 83/10/05
EISENHUT, D O Division of Licensing 2pp 20909 264 24X
Fiche 50-329, 83/10/24, 8308310032
- E NRC Safety Evaluation Report (SER), supplis & correspondence
- 8310190263 Summary of 831003 telcon meeting w/util & Energy Technology Engineering Ctr re resolution of SER Confirmatory Issue 4, "Independent Analysis of Piping Sys"
MILLER, M A Licensing Branch 4 83/10/17 Licensing Branch 4
6pp 20843 257 24X Fiche 50-329, 83/10/17, 8310190263
- F Security, medical, emergency & fire protection plans
- 8310030601 Forwards comments on 830331 detailed control room design review final rept per Suppl 1 to NUREG-0737 Rept acceptable Meeting to discuss comments before 831017 preimplementation audit recommended
ADENBAM, E G Licensing Branch 4 83/09/19 COOK, J W Consumers Power Co 10pp 20607 343 24X Fiche 50-329, 83/09/19, 8310030601
- 8310030606 Advises of compliance w/requirements of Suppl 1, Table 1, to NUREG-0737 re habitability & location of emergency operations Facility Approval of other features will be determined during post-implementation appraisal
ADENBAM, E G Licensing Branch 4 83/09/21 COOK, J W Consumers Power Co 3pp 20607 353 24X Fiche 50-329, 83/09/21, 8310030606
- 8310110019 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20689 357 24X Fiche 50-000, 83/10/05,
8310110019

DOCKETED ITEMS

187

--B310110024 Public version of Rev 6 to Emergency Plan Implementing Procedure EOI-7, "Offsite Dose Worksheet (Protective Actions)" W/B30922 ltr & receipt form
BRADLEY, J Consumers Power Co 83/07/18 Document Management Branch 2pp 20687 358 24X Fiche 50-000,83/10/05,8310110019

B310120464 Notification of B31026 meeting w/util & Engineering Planning & Mgt in Bethesda, MD to discuss proposal to resolve NRC concerns re safe shutdown capability in event of fire
MILLER, M A Licensing Branch 4 83/10/06 ADENSAM, E G Licensing Branch 4 5pp 20751 275 24X Fiche 50-329,83/10/06,8310120464

B310210030 EN-83-069 on B31026, notice of violation & proposed imposition of civil penalty in amount of \$100,000 to be issued Action based on fireline relocation activities performed in "G" soils w/o prior NRC authorization
KLINGLER, G Director's Office, Office of Inspection and Enforcement 83/10/20 1p 20855 344 24X Fiche 50-329,83/10/20,8310210030

B310270491 Releases public version of revised controlled copyholder list of emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20928 337 24X Fiche 50-000,83/10/21,8310270491

--B310270510 Forwards public version of Rev 2 to controlled copyholder list of general ofc ctr/emergency operations facility emergency implementing procedures & list depicting location of proprietary info in procedures
CARLEY, A Consumers Power Co 83/09/15 Office of Nuclear Reactor Regulation, Director 7pp 20928 338 24X Fiche 50 000,83/10/21,8310270491

B310270590 Releases public version of revised general ofc control ctr/emergency operations facility emergency implementing procedures
FELTON, J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20944 322 24X Fiche 50-000,83/10/25,8310270590

--B310270593 Forwards public version of revised general ofc control ctr/emergency operations facility emergency implementing procedures, including Procedure GEN-2 re emergency telephone numbers Receipt form encl
CARLEY, A Consumers Power Co 83/10/13 Document Management Branch 4pp 20944 323 24X Fiche 50-000,83/10/25,8310270590

--B310270597 Public version of revised general ofc control ctr/emergency operations facility emergency implementing procedures, including Procedure GEN-2 re emergency telephone numbers
* Consumers Power Co 83/10/11 42pp 20944 327 24X Fiche 50-000,83/10/25,8310270590

G Adjudicatory correspondence

B310180625 Responds to FOIA request for records submitted by util & reviewed during consideration of candidate companies or methodologies re const implementation overview Forwards documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/09/01 GARRE, R P Government Accountability Project 3pp 20839 112 24X Fiche 50-329,83/09/01,8310180625

--B310180628 Forwards util B20512 response to Interrogatory IV re Contention B on independent design audit
* NRC - No Detailed Affiliation Given 82/10/01 NRC - No Detailed Affiliation Given 1p 20839 115 24X Fiche 50 329,83/09/01,8310180625

--B310180627 Response to Interrogatory IV re Contention B on independent design audit
* Consumers Power Co 82/05/12 Stamiris, B 8pp 20839 116 24X Fiche 50-329,83/09/01,8310180625

B310050418 Forwards Chief Hearing Counsel B30819 memo to Ofc of Investigations requesting release of rept of investigation of alleged violation of ASLB B20430 order & preliminary notes.
PATON, W D Hearing Branch 2 83/09/28 BECHHOEFER, C, COWAN, F P, HARBOUR, J Atomic Safety and Licensing Board Panel 3pp 20629 358 24X Fiche 50-329,83/09/28,8310050418

B310030465 Notice of JL Donnell B31015 deposition in Las Vegas, NV, Certificate of Svc encl
WILLIAMS, F C Consumers Power Co WILLIAMS, F C Isham, Lincoln & Beale 83/09/29 3pp 20601 055 24X Fiche 50-329,83/09/29,8310030465

B310030514 Order delineating schedules for proposed findings of fact & conclusions of law
BECHHOEFER, C Atomic Safety and Licensing Board Panel 83/09/29 3pp 20601 182 24X Fiche 50-329,83/09/29,8310030514

B310040467 Requests reply to encl B30921 ltr & advice as to whether L Clark will be produced for deposition on B31004 Svc list encl Related correspondence
PROCTOR, S D Isham, Lincoln & Beale 83/09/29 KARR, J W Karr & Lyons 3pp 20623 288 24X Fiche 50-329,83/09/29,8310040467

B310060269 Notice of correction to B30930 motion for reconsideration
KARR, J W Government Accountability Project 83/10/03 1p 20646 154 24X Fiche 50-329,83/10/03,8310060269

--B310060291 Errata to B30930 motion for reconsideration Certificate of Svc encl
* Government Accountability Project 83/10/03 Atomic Safety and Licensing Board Panel 4pp 20646 155 24X Fiche 50-329,83/10/03,8310060269

B310110310 Application for deposition subpoena duces tecum to JL Donnell Certificate of Svc encl
WILLIAMS, F C Consumers Power Co WILLIAMS, F C Isham, Lincoln & Beale 83/10/03 Atomic Safety and Licensing Board Panel 9pp 20665 346 24X Fiche 50-329,83/10/03,8310110310

B310120101 Motion to stay depositions of L Clark, T Devine, BP Garde & L Hallberg as directed in ASLB B30831 order Depositions should be stayed pending review of B30930 motion for reconsideration Certificate of Svc encl
KARR, J W Government Accountability Project 83/10/03 Atomic Safety and Licensing Board Panel 6pp 20697 103 24X Fiche 50-329,83/10/03,8310120101

B310110071 Second supplemental memorandum in support of intervenor Stamiris motion to litigate Dow Chemical Co issues against applicant Dow documents & complaints support litigation of issues raised in original motion Certificate of Svc encl
BERNABEI, L Government Accountability Project 83/10/05 Atomic Safety and Licensing Board Panel 104pp 20667 174 24X Fiche 50-329,83/10/05,8310110071

B310130010 Forwards BB Hayes B30912 memo transmitting supplemental OFC of Investigations rept re alleged violation of ASLB order w/o rept
HASSELL, D F Hearing Branch 1 WRIGHT, N A Hearing Branch 2 83/10/05 BECHHOEFER, C, COWAN, F P, HARBOUR, J Atomic Safety and Licensing Board Panel 5pp 20725 209 24X Fiche 50-329,83/10/05,8310130010

B310130233 Forwards one oversize revised settlement plot drawing referred to during Kane B30920 testimony, per ASLB B30921 request Drawing should be marked as Exhibit 25 Aperture card available in PDR
HASSELL, D F Hearing Branch 1 WRIGHT, N A Hearing Branch 2 83/10/05 BECHHOEFER, C, COWAN, F P, HARBOUR, J Atomic Safety and Licensing Board Panel 3pp 20719 150 24X Fiche 50-329,83/10/05,8310130233

B310110210 Memorandum & Order LBP-B3-64, denying Govt Accountability Project deponent motion for reconsideration of ASLB B30831 Order LBP-B3-53 & for stay of depositions, subj to noted conditions
BECHHOEFER, C Atomic Safety and Licensing Board Panel, 83/10/06 Government Accountability Project 11pp 20665 062 24X Fiche 50-329,83/10/06,8310110210

B310110320 Memorandum explaining reasons for denying Govt Accountability Project (GAP) B31003 motion for stay of ASLB B30831 order denying motion to quash subpoenas of GAP employees Stay of motion already pending before ASLB
SHOEMAKER, C J Atomic Safety and Licensing Board Panel 83/10/06 3pp 20665 355 24X Fiche 50-329,83/10/06,8310110320

B310170383 Interrogatories re OFC of Investigations rept Certificate of Svc encl
BERNABEI, L Stamiris, B BERNABEI, L Government Accountability Project 83/10/11 Office of the Executive Legal Director 10pp 20785 019 24X Fiche 50-329,83/10/11,8310170383

B310170393 Request for production of documents Certificate of Svc encl
BERNABEI, L Stamiris, B BERNABEI, L Government Accountability Project 83/10/11 Carolina Power & Light Co 10pp 20785 035 24X Fiche 50-329,83/10/11,8310170393

B310170427 Interrogatories directed to util Certificate of Svc encl
BERNABEI, L Stamiris, B BERNABEI, L Government Accountability Project 83/10/11 Consumers Power Co 15pp 20779 203 24X Fiche 50-329,83/10/11,8310170427

B310170524 Request for production of documents Certificate of Svc encl
BERNABEI, L Stamiris, B BERNABEI, L Government Accountability Project 83/10/11 Office of the Executive Legal Director 7pp 20784 209 24X Fiche 50-329,83/10/11,8310170524

DOCKETED ITEMS

--8310280078 Transcript of JL Donnell 831015 deposition in Las Vegas, NV re alleged violation of ASLB order
DONNELL, J L Consumers Power Co DONNELL, J L Science Applications, Inc 83/10/15 114pp 20733 351 24X
Fiche 50-329, 83/10/25, 8310280078

8310280100 Order directing parties to be prepared to respond, during 831031 hearing session, to applicant 831025 motion for admission into evidence of JL Donnell deposition
BECHHOEFER, C Atomic Safety and Licensing Board Panel 83/10/26
Intervenor Other Than Dow 1p 20935 205 24X
Fiche 50-329, 83/10/26, 8310280100

8310280145 Motion to continue beginning date of hearings scheduled for 831031 to 3 days after date Extended hearing necessary to allow time to receive responses to 831011 discovery requests W/Certificate of Svc
BERNABEI, L Stamiris, B BERNABEI, L Government Accountability Project 83/10/26 Atomic Safety and Licensing Board Panel 6pp
20929 248 24X Fiche 50-329, 83/10/26, 8310280145

8310310390 Motion to stay ASLB 830831 & 1006 orders denying deponent motion for reconsideration of motion to quash subpoenas pending ASLB decision on deponent 831021 appeal Certificate of Svc encl Related correspondence
KARR, J W Government Accountability Project 83/10/26 Atomic Safety and Licensing Appeal Panel 5pp 20960 011 24X
Fiche 50-329, 83/10/26, 8310310390

8310310431 Order denying Govt Accountability Project 831021 motion to stay ASLB 830831 & 1006 orders denying motions to quash subpoenas & for reconsideration, respectively Motion filed late & fails to show stay warranted
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/27 Government Accountability Project 6pp 20939 230 24X
Fiche 50-329, 83/10/27, 8310310431

8310310211 Order granting B Stamiris 831026 motion to continue evidentiary hearings due to nonreceipt of responses to discovery request Three-day continuance granted
BECHHOEFER, C Atomic Safety and Licensing Board Panel 83/10/28 STAMIRIS, B Stamiris, B 2pp 20958 322 24X
Fiche 50-329, 83/10/28, 8310310211

G Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 117pp 20734 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 9A-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310170558 Forwards IE Insp Repts 50-329/83-12 & 50-330/83-13 on 830523-27, 0613-17 & 27-31 & notice of violation
WARNICK, R F Region 3, Office of Director 83/09/29 COWAN, J W Consumers Power Co 2pp 20780 213 24X Fiche 50-329, 83/09/29, 8310170558

on insp on 830523-27, 0613-17 & 27-31 & notice of Director 83/09/29 2pp.
9/29, 8310170558

50-330/83-13 on 830523-27, noted failure to

Region 3, Office of Director 50-329, 83/09/29, 8310170558

8310180456 Expresses concern re discrepancies in const completion schedule Public meeting warranted in light of varying completion dates
GARDE, B P Government Accountability Project 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20801 202 24X Fiche 50-329, 83/10/13, 8310180456

--8310180465 Affidavit of BP Garde re discrepancies in const completion dates Exhibits encl
GARDE, B P Government Accountability Project 83/09/21 Atomic Safety and Licensing Board Panel 2pp 20801 310 24X
Fiche 50-329, 83/10/13, 8310180465

8310190050 Errata to instructions for interrogatories & requests for production filed on 831011 Related correspondence
BERNABEI, L Government Accountability Project 83/10/13 PATON, W D Hearing Branch 2 STEPTOE, P Isham, Lincoln & Beale 1p 20823 223 24X Fiche 50-329, 83/10/13, 8310190050

8310190048 Response to B Stamiris 831005 second supplemental memorandum supporting Dow issues Stamiris fails to show new & significant info justifying reopening record Certificate of Svc encl
STEPTOE, P P Consumers Power Co STEPTOE, P P Isham, Lincoln & Beale 83/10/14 Atomic Safety and Licensing Board Panel 13pp 20823 174 24X Fiche 50-329, 83/10/14, 8310190048

8310200254 Corrects typographical errors found in applicant response to second supplemental memorandum in support of intervenor B Stamiris motion to litigate Dow issues
STEPTOE, P P Isham, Lincoln & Beale STEPTOE, P P Consumers Power Co 83/10/17 BECHHOEFER, C, HARBOUR, J, COWAN, F P Atomic Safety and Licensing Board Panel 1p 20830 102 24X
Fiche 50-329, 83/10/17, 8310200254

8310240172 Forwards documents not served at 830728 & 0721 hearings Certificate of Svc encl Related correspondence
LAUER, R J Isham, Lincoln & Beale LAUER, R J Consumers Power Co 83/10/18 Office of the Executive Legal Director 148pp 20879 240 24X Fiche 50-329, 83/10/18, 8310240172

8310250073 Advises of util intent to complete const despite Dow Chemical Co attempted withdrawal from contract to purchase steam generated by facility Unit 1 could be converted to electric unit Svc list encl
BRUNNER, J E Consumers Power Co 83/10/18 BECHHOEFER, C, HARBOUR, J, COWAN, F P Atomic Safety and Licensing Board Panel 3pp 20874 112 24X Fiche 50-329, 83/10/18, 8310250073

8310250053 Notice of L Clark, L Hallberg, T Devine & BP Garde 83110, 22, 1201 & 15, respectively, depositions in Washington, DC & Midland, MI Certificate of Svc encl
PROCTOR, B D Consumers Power Co 83/10/19 4pp 20094 105 24X
Fiche 50-329, 83/10/19, 8310250053

8310250041 Objections to 831011 interrogatories & document production requests Certificate of Svc encl
BRUNNER, J E Consumers Power Co 83/10/20 STAMIRIS, B Stamiris, B 5pp 20874 190 24X Fiche 50-329, 83/10/20, 8310250041

8310270257 Notice of appeal from ASLB orders granting discovery against Govt Accountability Project Certificate of Svc encl
KARR, J W Government Accountability Project 83/10/21 2pp 20923 268 24X Fiche 50-329, 83/10/21, 8310270257

--8310270266 Memorandum in support of appeal from ASLB orders granting discovery against Govt Accountability Project Subpoenas violate common law of privilege Util showed no compelling need for discovery
KARR, J W Government Accountability Project 83/10/21 Atomic Safety and Licensing Appeal Panel 10pp 20923 270 24X
Fiche 50-329, 83/10/21, 8310270266

8310270345 Motion to compel CPC responses to 831011 interrogatories & request for production re investigation of alleged violation Certificate of Svc encl
BERNABEI, L Stamiris, B BERNABEI, L Government Accountability Project 83/10/25 Atomic Safety and Licensing Board Panel 7pp 20923 345 24X Fiche 50-329, 83/10/25, 8310270345

8310270367 Order extending time until 831130 for Commission to act to review Director's Decision DD-83-16
CHILK, B J Office of the Secretary of the Commission 83/10/25 Commissioners 1p 20923 293 24X Fiche 50-329, 83/10/25, 8310270367

8310280073 Motion for admission into evidence of transcript of JL Donnell 831015 deposition Certificate of Svc encl
WILLIAMS, F C Consumers Power Co WILLIAMS, F C Isham, Lincoln & Beale 83/10/25 Atomic Safety and Licensing Board Panel 7pp 20933 342 24X Fiche 50-329, 83/10/25, 8310280073

DOCKETED ITEMS

189

- 8310170459 Forwards IE Mgt Meeting Repts 50-329/83-16 & 50-330/83-17 on 830825 re B&W Engineering const implementation overview program
WARNICK, R F Region 3, Office of Director 83/09/30 COOK, J W
Consumers Power Co 2pp 20/84 052 24X Fiche 50-329, 83/09/30, 8310170459
- 8310170464 IE Mgt Meeting Repts 50-329/83-16 & 50-330/83-17 on 830825 Major areas discussed until proposed third party overview & B&W Engineering const implementation overview program
GARDNER, R N, HARRISON, J J Region 3, Office of Director 83/09/29 6pp 20784 054 24X Fiche 50-329, 83/09/30, 8310170459
- 8310170466 Confirms commitments made to NRC at 830825 public meeting in Midland, MI re third party const implementation overview program Viewgraphs encl
WILD, P A Stone & Webster, Inc 83/08/30 KEPLER, J G Region 3, Office of Director 20pp 20784 060 24X
Fiche 50-329, 83/09/30, 8310170459
- 8310170513 Forwards IE Insp Repts 50-329/83-19 & 50-330/83-20 on 830821-0920 No noncompliance noted
WARNICK, R F Region 3, Office of Director 83/10/03 COOK, J W
Consumers Power Co 2pp 20/81 080 24X Fiche 50-329, 83/10/03, 8310170513
- 8310170534 IE Insp Repts 50-329/83-19 & 50-330/83-20 on 830821-0920 No noncompliance noted Major areas inspected review of svc water pump structure instrumentation, remedial soils work activities & plant tours
BURGESS, D L, COOK, R J, GARDNER, R N Region 3, Office of Director 83/09/30 4pp 20781 082 24X Fiche 50-329, 83/10/03, 8310170513
- 8310170538 Forwards Weekly Rept 52 of independent assessment of underpinning for period 830911-17
LUCKS, A S Stone & Webster, Inc 83/09/20 COOK, R NRC - No Detailed Affiliation Given 14pp 20781 086 24X
Fiche 50-329, 83/10/03, 8310170513
- 8310170544 Forwards Weekly Rept 51 of independent assessment of underpinning for period 830903-10
LUCKS, A S Stone & Webster, Inc 83/09/14 COOK, R NRC - No Detailed Affiliation Given 11pp 20781 100 24X
Fiche 50-329, 83/10/03, 8310170513
- 8310170549 Forwards Weekly Rept 50 of independent assessment of underpinning for period 830828-0703
LUCKS, A S Stone & Webster, Inc 83/09/08 COOK, R NRC - No Detailed Affiliation Given 13pp 20781 111 24X
Fiche 50-329, 83/10/03, 8310170513
- 8310170553 Forwards Weekly Rept 49 of independent assessment of underpinning for period 830821-27
LUCKS, A S Stone & Webster, Inc 83/08/31 COOK, R NRC - No Detailed Affiliation Given 13pp 20781 126 24X
Fiche 50-329, 83/10/03, 8310170513
- 8310170559 Forwards Weekly Rept 48 of independent assessment of underpinning for period 830814-20
LUCKS, A S Stone & Webster, Inc 83/08/24 COOK, R NRC - No Detailed Affiliation Given 14pp 20781 139 24X
Fiche 50-329, 83/10/03, 8310170513
- 8310170560 Forwards Rept 14 of const implementation overview for period 830912-16
BARANOW, S W Stone & Webster, Inc 83/09/19 KEPLER, J G Region 3, Office of Director 7pp 20781 153 24X
Fiche 50-329, 83/10/03, 8310170513
- 8310170564 Forwards Rept 13 of const implementation overview for period 830905-07
BARANOW, S W Stone & Webster, Inc 83/09/12 KEPLER, J G Region 3, Office of Director 6pp 20781 160, 24X
Fiche 50-329, 83/10/03, 8310170513
- 8310170567 Forwards Rept 12 of const implementation overview for period 830829-0902
BARANOW, S W Stone & Webster, Inc 83/09/06 KEPLER, J G Region 3, Office of Director 10pp 20781 166 24X
Fiche 50-329, 83/10/03, 8310170513
- 8310170571 Forwards Rept 11 of const implementation overview for period 830822-24
BARANOW, S W Stone & Webster, Inc 83/08/29 KEPLER, J G Region 3, Office of Director 5pp 20781 176 24X
Fiche 50-329, 83/10/03, 8310170513
- 8310170575 Forwards Rept 10 of const implementation overview for period 830815-19
BARANOW, S W Stone & Webster, Inc 83/08/22 KEPLER, J G Region 3, Office of Director 7pp 20781 181 24X
Fiche 50-329, 83/10/03, 8310170513
- 8310170583 Forwards IE Insp Repts 50-329/83-15 & 50-330/83-16 on 830721-0820 No noncompliance noted
WARNICK, R F Region 3, Office of Director 83/10/03 COOK, J W
Consumers Power Co 2pp 20/80 237 24X Fiche 50-329, 83/10/03, 8310170583
- 8310170591 IE Insp Repts 50-329/83-15 & 50-330/83-16 on 830721-0820 No noncompliance noted Major areas inspected remedial soils activities, team training, B&W hanger installations & SALP meeting
BURGESS, D L, COOK, R J, GARDNER, R B Region 3, Office of Director 83/09/30 5pp 20780 239 24X Fiche 50-329, 83/10/03, 8310170583
- 8310170598 Forwards Rept 6 of const implementation overview for period 830715-21
BARANOW, S W Stone & Webster, Inc 83/07/25 KEPLER, J G Region 3, Office of Director 5pp 20780 244 24X
Fiche 50-329, 83/10/03, 8310170583
- 8310170602 Forwards Rept 7 of const implementation overview for period 830722-28
BARANOW, S W Stone & Webster, Inc 83/08/01 KEPLER, J G Region 3, Office of Director 5pp 20780 249 24X
Fiche 50-329, 83/10/03, 8310170583
- 8310170606 Forwards Rept 8 of const implementation overview for period 830729-0804
BARANOW, S W Stone & Webster, Inc 83/08/08 KEPLER, J G Region 3, Office of Director 6pp 20780 254 24X
Fiche 50-329, 83/10/03, 8310170583
- 8310170610 Forwards Rept 9 of const implementation overview for period 830805-12
BARANOW, S W Stone & Webster, Inc 83/08/15 KEPLER, J G Region 3, Office of Director 6pp 20780 260 24X
Fiche 50-329, 83/10/03, 8310170583
- 8310170616 Forwards Weekly Rept 44 of independent assessment of underpinning for period 830717-23
LUCKS, A S Stone & Webster, Inc 83/07/28 COOK, R NRC - No Detailed Affiliation Given 16pp 20780 266 24X
Fiche 50-329, 83/10/03, 8310170583
- 8310170622 Forwards Weekly Rept 45 of independent assessment of underpinning for period 830724-30
LUCKS, A S Stone & Webster, Inc 83/08/04 COOK, R NRC - No Detailed Affiliation Given 17pp 20780 282 24X
Fiche 50-329, 83/10/03, 8310170583
- 8310170627 Forwards Weekly Rept 46 of independent assessment of underpinning for period 830731-0806
LUCKS, A S Stone & Webster, Inc 83/08/10 COOK, R NRC - No Detailed Affiliation Given 11pp 20780 299 24X
Fiche 50-329, 83/10/03, 8310170583
- 8310170634 Forwards Weekly Rept 47 of independent assessment of underpinning for period 830807-13
LUCKS, A S Stone & Webster, Inc 83/08/17 COOK, R NRC - No Detailed Affiliation Given 14pp 20780 310 24X
Fiche 50-329, 83/10/03, 8310170583
- 8310240067 Confirms transmittal of computer printout containing info on MPQAD (balance of plant) inspector records
BOTNER, L Commonwealth Edison Co 83/10/03 BARANOW, S Stone & Webster Engineering Corp 1p 20881 344 24X Fiche 50-329, 83/10/03, 8310240067
- 8310120317 Notification of 831011 significant license meeting w/Util in Glen Ellyn, IL to review IC investigation rpt & to discuss alleged violation of ASLB order on remedial soils
Region 3, Office of Director 83/10/05 Region 3, Office of Director, 1p 20700 307 24X Fiche 50-329, 83/10/03, 8310120317
- 8310120325 Confirms 831011 meeting in Region III ofc to discuss alleged violation of ASLB order re remedial soils areas & possible IE enforcement actions
WARNICK, R F Region 3, Office of Director 83/10/05 COOK, J W
Consumers Power Co 1p 20700 273 24X Fiche 50-329, 83/10/03, 8310120325

DOCKETED ITEMS

8310130010 Forwards 80 Hayes 830912 memo transmitting supplemental Ufr of Investigations rept re alleged violation of ASLR order
W/o rept
HASSELL, D F Hearing Branch 1 WRIGHT, N A Hearing Branch 2
83/10/05 BECHHOEFER, C, COHAN, F P, HARBOR, J Atomic Safety and
Licensing Board Panel 5pp 20725 209 24X Fiche 50-329, 83/10/05,
8310130010

8310210314 Forwards IE Audit Repts 50-329/83-20 & 50-330/83-21 on
830914-15
HARNICK, R F Region 3, Office of Director 83/10/05 COOK, J W
Consumers Power Co 2pp 20851 079 24X Fiche 50-329, 83/10/05,
8310210314

--8310210319 IE Audit Repts 50-329/83-20 & 50-330/83-21 on 830914-15
Major areas audited calculations of auxiliary bldg based on
new soil modulus determined from underpinning pier load test
results Related natis encl
LANDSMAN, R D, HARRISON, J J Region 3, Office of Director
83/10/04 50pp 20851 081 24X Fiche 50-329, 83/10/05, 8310210314

8310110191 EN-83-064 on 831006, notice of confirmatory order for mod of
CPS issued Order requires const implementation overview
program to provide reasonable assurance that facility can
be completed in accordance w/regulatory requirements
STONE, J, HEISHMAN, R Director's Office, Office of Inspection and
Enforcement 83/10/06 1p 20665 007 24X Fiche 50-329, 83/10/06,
8310110191

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass
Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 78pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical
Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 79pp 20892 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect
Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective
Self-Contained Breathing Apparatus Air Cylinders " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180265 Clarifies NRC position re procedures for admitting NRC
personnel to Facility List of personnel requiring access to
vital areas encl Updates will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 COOK, J W
Consumers Power Co 7pp 20807 043 24X Fiche 50-329, 83/10/14,
8310180265

8310310411 Forwards IE Insp Repts 50-329/83-17 & 50-330/83-18 on
830711-12 & 0816-19 No noncompliance noted
HARNICK, R F Region 3, Office of Director 83/10/17 COOK, J W
Consumers Power Co 2pp 20959 304 24X Fiche 50-329, 83/10/17,
8310310411

--8310310417 IE Insp Repts 50-329/83-17 & 50-330/83-18 on 830711-12 &
0816-19 No noncompliance noted Major areas inspected review
of B&W QC insp & process for installation at A9ME III
Class 1 pipe
SIMON, J A, SATHER, A, HARRISON, J J Region 3, Office of Director
83/10/17 4pp 20959 306 24X Fiche 50-329, 83/10/17, 8310310417

8310210030 EN-83-069 on 831026, notice of violation & proposed
imposition of civil penalty in amount of \$100,000 to be
issued Action based on fireline relocation activities
performed in "G" soils w/o prior NRC authorization
KLINDLER, G, AXELRAD, J Director's Office, Office of Inspection and
Enforcement 83/10/20 1p 20855 344 24X Fiche 50-329, 83/10/20,
8310210030

8310270165 Authorizes util to proceed w/Phase I activities for const
completion program in response to 831020 request insp
results used as basis for granting authorization documented
in NRC/Midland monthly insp repts
HARRISON, J J Region 3, Office of Director 83/10/21 QUAMME, D L
Consumers Power Co 2pp 20924 154 24X Fiche 50-329, 83/10/21,
8310270165

--8310270171 Advises that status assessment & verification of completed
work (Phase I of const completion program) initiated &
requests NRC release to initiate Phase I Initial activities
will be restricted to five modules
QUAMME, D L Consumers Power Co 83/10/20 HARRISON, J J Region
3, Office of Director 4pp 20924 156 24X Fiche 50-329,
83/10/21, 8310270165

--8310270176 Provides overview of const completion program Modules 340,
102, 120, 410 & 800 requested for release
BARANOW, S W Stone & Webster, Inc 83/10/12 KEPPLER, J Q
Region 3, Office of Director 11pp 20924 160 24X
Fiche 50-329, 83/10/21, 8310270165

8310270341 Advises that review of util 830624 supplemental response to
Item B & of 830208 notice of violation completed Response
unacceptable Schedule for penetrant tests of welds must be
submitted within 25 days of 1tr receipt
HARNICK, R F Region 3, Office of Director 83/10/21 COOK, J W
Consumers Power Co 2pp 20923 352 24X Fiche 50-329, 83/10/21,
8310270341

--8310270352 Forwards supplemental info re Item B of 830208 notice of
violation, in response to NRC 830523 request Const training
procedure revised to establish program assuring appropriate
training in installation procedures
COOK, J W Consumers Power Co 83/06/24 KEPPLER, J Q Region 3,
Office of Director 15pp 20923 354 24X Fiche 50-329, 83/10/21,
8310270341

R Periodic operating reports & related correspondence

8310210272 Forwards fifth monthly status rept for independent design &
const verification program for Sept 1983
LEVIN, H A TERA Corp 83/10/17 EISENHUT, D Q Division of
Licensing KEPPLER, J Q Region 3, Office of Director COOK, J W
Consumers Power Co 3pp 20848 220 24X Fiche 50-329, 83/10/17,
8310210272

--8310210275 Fifth monthly status rept for independent design & const
verification program for Sept 1983
DAUGHERTY, G, LEVIN, H A, DECK, J W TERA Corp 83/10/17 51pp
20848 223 24X Fiche 50-329, 83/10/17, 8310210272

8310310078 Forwards listed documents written or closed during
Sept 1983, per condition of Memorandum & Order ALAB-106 &
Amend 1 to CFPB-B1 & CFPB-B2
COOK, J W Consumers Power Co 83/10/25 DEYOUNG, R C Director's
Office, Office of Inspection and Enforcement 3800pp 20980 001
24X Fiche 50-329, 83/10/25, 8310310078

S Reportable occurrences, ILEs & related correspondence

8309090259 Interim deficiency rept re dc backed power supplies for 1006
interlock relays in auxiliary feedwater sys Schematic
Diagram E-15810) revised & issued as of 830727 to provide
120-volt ac power
COOK, J W Consumers Power Co 83/09/02 KEPPLER, J Q Region 3,
Office of Director 6pp 20310 187 24X Fiche 50-329, 83/09/02,
8309090259

8310120446 PNO-111-83-092 on 831004, marijuana found in truck owned by
carpenter employed by Bechtel Corp Individual fired by
Bechtel & left site No action planned by Region III State of
MI will be notified
HARRISON, J, HARNICK, R Region 3, Office of Director 83/10/04
1p 20698 325 24X Fiche 50-329, 83/10/04, 8310120446

8310140090 PNO-111-83-095 on 831005, B&W issued stop work order on
Class 1 piping hanger installation Stop work applies to both
small bore & large bore piping & is based on deficiencies
identified in hangers during Bechtel insp
HARRISON, J, GARDNER, R Region 3, Office of Director 83/10/04
1p 20767 059 24X Fiche 50-329, 83/10/04, 8310140090

8310170421 Final deficiency rept re underrated terminal strips on
Limiting valve operators Initially reported on 810213 New
valve operators for use inside containment will be purchased
w/o terminal blocks or space heaters
COOK, J W Consumers Power Co 83/10/06 KEPPLER, J Q Region 3,
Office of Director 25pp 20783 323 24X Fiche 50-329, 83/10/06,
8310170421

8310250101 Final rept re deficiencies in electrical components in that
non-Class IE devices wired into Class 1k circuits
Engineering production schedule activities will be revised
by 831021
COOK, J W Consumers Power Co 83/10/14 KEPPLER, J Q Region 3,
Office of Director 14pp 20896 172 24X Fiche 50-329, 83/10/14,
8310250101

DOCKETED ITEMS

191

8310270265 Interim deficiency rpt re reactor bldg spray piping supports initially reported on 7/9/21. Caused by conservative modeling assumptions made in original water hammer analysis. Next rpt by 8310230. CDDK, J W Consumers Power Co 83/10/21 KEPPLER, J G Region 3, Office of Director 6pp 20423 247 24X Fiche 50-329, 83/10/21, 8310270265

T Hearing transcripts on non-antitrust matters

8310280073 Motion for admission into evidence of transcript of JL Donnell 831015 deposition Certificate of Svc encl WILLIAMS, F C Consumers Power Co WILLIAMS, F C Isham, Lincoln & Beale 83/10/25 Atomic Safety and Licensing Board Panel 7pp 20933 342 24X Fiche 50-329, 83/10/25, 8310280073

--8310280078 Transcript of JL Donnell 831015 deposition in Las Vegas, NV re alleged violation of ASLB order DONNELL, J L Consumers Power Co DONNELL, J L Science Applications, Inc 83/10/15 114pp 20933 351 24X Fiche 50-329, 83/10/25, 8310280073

DOCKET 50-330 MIDLAND PLANT, UNIT 2

A Application/construction stage documents & correspondence

8310190311 FOIA request for documents re caseload forecast panel 830419 meeting on plant const GARDE, B P Government Accountability Project 83/0/11 Office of Administration 2pp 20840 329 24X Fiche 50-329, 83/0/11, 8310190311

8310180618 FOIA request for documents submitted by util for consideration of candidate companies or methodologies to perform const implementation overview of const completion plan GARDE, B P Government Accountability Project 83/08/05 Office of Administration 2pp 20839 110 24X Fiche 50-329, 83/08/05, 8310180618

8310130390 FOIA request for all records on re-review of structural adequacy of diesel generator bldg subsequent to May testimony of R Landsman in ASLB proceedings GARDE, B P Government Accountability Project 83/08/08 Office of Administration 2pp 20769 352 24X Fiche 50-329, 83/08/08, 8310130390

8310190316 Responds to FOIA request for documents re caseload forecast panel 830419 meeting on plant const info partially withheld JW Cook draft ltr to TM Novak (ref FOIA Exemption b) FELTON, J M Division of Rules and Records 83/08/09 GARDE, B P Government Accountability Project 6pp 21116 001 24X Fiche 50-329, 83/08/09, 8310190316

8310190300 Appeals denial of FOIA request for documents re caseload forecast panel 830419 meeting on plant const Denial effectively denied bulk of documents requested GARDE, B P Government Accountability Project 83/08/10 DIRCKS, W J Office of the Executive Director for Operations 2pp 20840 326 24X Fiche 50-329, 83/08/10, 8310190300

8310130394 Responds to FOIA request for all records on re-review of structural adequacy of diesel generator bldg subsequent to May testimony of R Landsman in ASLB proceedings Forwards App A documents Documents also in PDR FELTON, J M Division of Rules and Records 83/08/25 GARDE, B P Government Accountability Project 2pp 20769 354 24X Fiche 50-329, 83/08/25, 8310130394

--8308150338 Advises of assignment as member of task group to reevaluate structural design & const adequacy of plant diesel generator bldg KUD, P T Structural & Geotechnical Engineering Branch 83/08/08 TAN, C P Structural & Geotechnical Engineering Branch 1p 20769 362 24X Fiche 50-329, 83/08/25, 8310130394

---8308290029 Requests meeting on 830822 to discuss Landsman concerns that diesel generator bldg inadequate to return to svc based on inability to meet design requirements VOLLMER, R NRC - No Detailed Affiliation Given 83/08/15 KNIGHT, J NRC - No Detailed Affiliation Given 1p 20769 361 24X Fiche 50-329, 83/08/25, 8310130394

8310180625 Responds to FOIA request for records submitted by Util & reviewed during consideration of candidate companies or methodologies re const implementation overview Forwards documents Documents also available in PDR FELTON, J M Division of Rules and Records 83/09/01 GARDE, B P Government Accountability Project 3pp 20839 112 24X Fiche 50-329, 83/09/01, 8310180625

--8310280450 Forwards util 821005 three-part independent review program, consisting of biennial quality audits, INPO-type const evaluation & independent design verification of auxiliary feedwater sys Meeting scheduled for 831019 to discuss plan NOVAK, T M Assistant Director for Licensing 82/10/07 VOLLMER, R H Division of Engineering 1p 20839 124 24X Fiche 50-329, 83/09/01, 8310180625

--8312300076 Documents conclusions reached at 821207 meeting in Bethesda, MD re QA implementation at facility Region 3 insp of diesel generator bldg & util decision to stop certain safety-related work being performed by Bechtel HERNAN, R M Licensing Branch 4 82/12/21 NOVAK, T M Assistant Director for Licensing 3pp 20837 125 24X Fiche 50-329, 83/09/01, 8310180625

--8310180630 Forwards util revised plan for const completion Program includes measures to be taken as result of work slowdown & elements of QA implementation & third-party assessments requested by NRC w/o encl HERNAN, R Division of Licensing 83/01/12 ADENSAH, E NRC - No Detailed Affiliation Given 1p 20839 128 24X Fiche 50-329, 83/09/01, 8310180625

--8310190034 Rev 1 to Quality Control Instruction 10 01, "Const Implementation Overview Assessment " THOMPSON, J C Stone & Webster Engineering Corp 83/06/21 6pp 20839 134 24X Fiche 50-329, 83/09/01, 8310180625

--8310190036 Rev 0 to Verification Attribute Checklist P-2 20V, "Pipe Supports " BARANOW, S W Stone & Webster Engineering Corp 83/07/21 10pp 20839 140 24X Fiche 50-329, 83/09/01, 8310180625

--8310190038 Rev 1 to third-party const implementation overview approval KELLY, R B Stone & Webster Engineering Corp 83/08/05 5pp 20839 150 24X Fiche 50-329, 83/09/01, 8310180625

--8310190042 Rev 1 to Quality Control Instruction 15 01, "Nonconformance Identification & Reporting " BARANOW, S Stone & Webster Engineering Corp 83/08/05 5pp 20839 155 24X Fiche 50-329, 83/09/01, 8310180625

--8310190047 Rev 1 for third-party const implementation overview re QA plan BARANOW, S, WALTERS, C, KELLY, R B Stone & Webster Engineering Corp 83/08/05 4pp 20839 160 24X Fiche 50-329, 83/09/01, 8310180625

8310030542 Memorializes 830902 telcon re rescheduling of Sept 1983 followup meeting on const completion dates Meeting will not be held in Sept HOOD, D Licensing Branch 4 83/09/08 ADENSAH, E G Licensing Branch 4 1p 20602 353 24X Fiche 50-329, 83/09/08, 8310030542

8310190305 Responds to appeal re denial of FOIA request for documents on caseload forecast panel 830419 meeting on plant const All documents identified subj to request Appeal re T Novak draft ltr to JW Cook moot DIRCKS, W J Office of the Executive Director for Operations 83/09/13 GARDE, B P Government Accountability Project 1p 20840 328 24X Fiche 50-329, 83/09/13, 8310190305

8310240029 Confirms transmittal of controlled copies of PQCI &/or changes to S&W SM-1 70, Rev 1 to CNA00079, C-2 10, Rev 12 & MW-1 00, Rev 2 PUCCI, J A Consumers Power Co 83/09/15 BARANOW, S Stone & Webster Engineering Corp 1p 20881 360 24X Fiche 50-329, 83/09/15, 8310240029

8310240131 Confirms transmittal of listed revs to PQCI EWERT, Q F Consumers Power Co 83/09/19 BARANOW, S Stone & Webster, Inc 1p 20881 165 24X Fiche 50-329, 83/09/19, 8310240131

8310240033 Confirms transmittal of computer printout containing info on MPQAD (balance of plant) inspector records Print covers all training, exams, performance demos & certifications BOTIMER, L A Consumers Power Co 83/09/20 BARANOW, S Stone & Webster Engineering Corp 1p 20881 359 24X Fiche 50-329, 83/09/20, 8310240033

8310240050 Confirms transmittal of controlled copies of PQCI &/or changes to S&W control log for wk ending 830916, PF-1 10, Rev 4 to CNA00043 & E-1 60, Rev 6 followup to inactive ltr PUCCI, J A Consumers Power Co 83/09/20 BARANOW, S Stone & Webster Engineering Corp 1p 20881 347 24X Fiche 50-329, 83/09/20, 8310240050

8310240063 Confirms transmittal of controlled copies of PQCI &/or changes to S&W procedures PUCCI, J A Consumers Power Co 83/09/22 BARANOW, S Stone & Webster, Inc 1p 20881 346 24X Fiche 50-329, 83/09/22, 8310240063

DOCKETED ITEMS

- 8310040122 Requests authorization for listed remedial soils work activities
MOONEY, J A Consumers Power Co 83/09/28 HARRISON, J J Region 3, Office of Director 1p 20608 278 24X Fiche 50-329, 83/09/28, 8310040122
- 8310050296 Requests authorization to perform listed remedial soils work re solid waste processing sys. Soldier Hills 1-30
MOONEY, J A Consumers Power Co 83/09/28 HARRISON, J J Region 3, Office of Director 1p 20628 331 24X Fiche 50-329, 83/09/28, 8310050296
- 8310050322 Discusses 830927 telcon re moving check valves & pipe supports in svc water bldg Work involves minor change to benchmark installation & can be completed as agreed
MOONEY, J A Consumers Power Co 83/09/28 HARRISON, J J Region 3, Office of Director 1p 20634 001 24X Fiche 50-329, 83/09/28, 8310050322
- 8310070109 Notification of 831004-06 meetings w/util & Bechtel in Midland, MI to review structural adequacy of as-constructed HVAC sys
HODD, D S Licensing Branch 4 83/09/28 ADENSAH, E G Licensing Branch 4 3pp 20671 310 24X Fiche 50-329, 83/09/28, 8310070109
- 8310070142 Forwards response to 830526 request for addl info re Question 130 2B for Vol I of seismic margin review rept entitled "Methodology & Criteria"
COOK, J W Consumers Power Co 83/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 22pp 20659 038 24X Fiche 50-329, 83/09/28, 8310070142
- 8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway
EISENHUT, D G Division of Licensing 83/09/29 PALLADINO, N J Commissioners 3pp 20632 001 24X Fiche 50-000, 83/09/29, 8308300357
- 8310050341 Forwards evaluation of util proposal to have B&W perform third-party independent overview of consist completion program Proposal approved
KEPPLER, J O Region 3, Office of Director 83/09/29 COOK, J W Consumers Power Co 7pp 20632 337 24X Fiche 50-329, 83/09/29, 8310050341
- 831010377 Summarizes 830926 telcon w/M Capicchioni of util re location of safety-related equipment in local break zones Applicant will submit info indicating no subj equipment at location
MILLER, M A Licensing Branch 4 83/09/29 Licensing Branch 4 3pp 20713 228 24X Fiche 50-329, 83/09/29, 831010377
- 8310050393 Issues authorization to proceed w/remedial soils work activities scheduled for Oct 1983
HARRISON, J J Region 3, Office of Director 83/09/30 MILLER, D B Consumers Power Co 2pp 20632 163 24X Fiche 50-329, 83/09/30, 8310050393
- 831020320 Responds to NRC concerns re equipment qualification & seismic margin review program, as discussed at 830208 meeting w/NRC
COOK, J W Consumers Power Co 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 24pp 20700 275 24X Fiche 50-329, 83/09/30, 831020320
- 8310170624 Forwards resumes for insertion into QA program, App C for IDVP
LEVIN, H A TERA Corp 83/09/30 KEPPLER, J O Region 3, Office of Director EISENHUT, D G Division of Licensing COOK, J W Consumers Power Co 8pp 20782 072 24X Fiche 50-329, 83/09/30, 8310170624
- 831010635 Summary of 830913 meeting w/util & Bechtel re util compliance w/QDC 51 re fracture toughness characterization
MILLER, M A Licensing Branch 4 83/10/04 Licensing Branch 4 20pp 20706 329 24X Fiche 50-329, 83/10/04, 831010635
- 8310170721 Discusses NRC concerns re delays in establishing firm schedule for plant completion Estimate developed by NRC will be utilized for planning purposes if response not forthcoming
NOVAK, T M Assistant Director for Licensing 83/10/04 COOK, J W Consumers Power Co 5pp 20798 110 24X Fiche 50-329, 83/10/04, 8310170721
- 8310240136 Confirms transmittal of PQCI &/or changes to PQCI, including control logs for wks ending 830923 & 30
PUCCI, J A Consumers Power Co 83/10/04 BARANOW, B Stone & Webster, Inc 1p 20881 169 24X Fiche 50-329, 83/10/04, 8310240136
- 8310120179 Provides info re licensee 830928 decision to stop all "Q" soil drilling & pile driving imposed as result of unknowingly drilling into structural concrete Info provided per board notification procedures
HARNICK, R F Region 3, Office of Director 83/10/05 EISENHUT, D G Division of Licensing 2pp 20693 326 24X Fiche 50-329, 83/10/05, 8310120179
- 8310170068 Advises that Option 1 in H Levin 830815 ltr acceptable re selection of independent design & const verification program associated w/Section 13 of Public Law 97-415 (Ford Amend)
NOVAK, T M Assistant Director for Licensing 83/10/05 COOK, J W Consumers Power Co LEVIN, H A TERA Corp 4pp 20798 024 24X Fiche 50-329, 83/10/05, 8310170068
- 8310170714 Documents 830927 telcon re removal of all soil & drift setc above Elevation 600 ft on north side of drift from KC2 to KC3 after draft invert is poured
MILLER, D B Consumers Power Co 83/10/05 HARRISON, J J Region 3, Office of Director 1p 20779 230 24X Fiche 50-329, 83/10/05, 8310170714
- 8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves
EISENHUT, D G Division of Licensing 83/10/06 PALLADINO, N J Commissioners 3pp 20818 001 24X Fiche 50-000, 83/10/06, 8308300771
- 8310130045 Notification of 831017-21 meetings w/util, Interlock, Inc & L.L. in Midland, MI to audit control room & related documentation prior to implementation of human factors related mods
MILLER, M A Licensing Branch 4 83/10/06 ADENSAH, E G Licensing Branch 4 5pp 20776 237 24X Fiche 50-329, 83/10/06, 8310130045
- 8310140270 Authorizes critical work activities presently scheduled for Oct 1983, per 831005 request
HARRISON, J J Region 3, Office of Director 83/10/06 MILLER, D B Consumers Power Co 3pp 20761 264 24X Fiche 50-329, 83/10/06, 8310140270
- 8310140273 Requests authority to proceed w/work authorization Procedures 75P050001 & 752030002 for drilling, replacing & installing anodes
MILLER, D B Consumers Power Co 83/10/05 HARRISON, J J Region 3, Office of Director 1p 20761 266 24X Fiche 50-329, 83/10/05, 8310140270
- 8310200375 Forwards confirmatory order for mod of CPPR-B1 & CPPR-B2 due to continued problems in implementation of QA program
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/10/06 COOK, J W Consumers Power Co 4pp 20859 069 24X Fiche 50-329, 83/10/06, 8310200375
- 8310200380 Confirmatory order for mod of CPPR-B1 & CPPR-B2 due to continued problems in implementation of QA program
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/10/06 Consumers Power Co 5pp 20859 073 24X Fiche 50-329, 83/10/06, 8310200375
- 8310200386 Decision DD-83-16 re BP Garde of Govt Accountability Project on behalf of Lone Tree Council 2 206 request that NRC take immediate action w/Midland project due to continued problems in implementation of QA program
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/10/06 23pp 20859 078 24X Fiche 50-329, 83/10/06, 8310200375
- 8310200392 Notice of issuance of Director's Decision DD-83-16 re 830619 2 206 petition filed by BP Garde of Govt Accountability Project on behalf of Lone Tree Council re Midland project
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/10/06 1p 20859 101 24X Fiche 50-329, 83/10/06, 8310200375
- 8310240084 Confirms transmittal of controlled copies of &/or changes to PQCI, as listed
PUCCI, J A Consumers Power Co 83/10/07 BARANOW, B Stone & Webster, Inc 1p 20881 004 24X Fiche 50-329, 83/10/07, 8310240084
- 8310170257 Requests that encl B&W Site Dfc Manager Ltr 490 re torque wrench for replacement of CSA flow distributor bolts be forwarded to B&W
MILLER, D B Consumers Power Co 83/10/10 HIERZLER, G A Bechtel Corp 2pp 20787 087 24X Fiche 50-329, 83/10/10, 8310170257

DOCKETED ITEMS

193

8310240023 Confirms transmittal of three computer printouts containing info on MFGAD (balance of plant) inspector records Printout covers all training, exams, performance demos & certifications
BOTIMER, L A Consumers Power Co 83/10/10 BARANOW, S Stone & Webster Engineering Corp 1p 20880 541 24X Fiche 50-329, 83/10/10, 8310240023

8308300767 Board Notification 83-153 suppls info re R Landsman concerns on structural adequacy of diesel generator bldg
NOVAK, T M Assistant Director for Licensing 83/10/11 Atomic Safety and Licensing Board Panel 3pp 20717 193 24X Fiche 50-329, 83/10/11, 8308300767

--8310090057 Responds to 830815 memo re R Landsman concerns on inadequate diesel generator bldg task group rept scheduled to be completed in Oct 1983
KNIGHT, J P Assistant Director for Comp & Structures Engineering (Post 830201) 83/09/23 VOLLMER, R H Division of Engineering 2pp 20717 156 24X Fiche 50-329, 83/10/11, 8308300767

--8310130267 Requests identity of any consultant or NRC employee sharing Landsman concern that diesel generator bldg inadequate
Matters to be discussed on 830822
VOLLMER, R NRC - No Detailed Affiliation Given 83/08/15
KNIGHT, J NRC - No Detailed Affiliation Given 1p 20717 150 24X Fiche 50-329, 83/10/11, 8308300767

8310170436 Authorizes listed remedial soils work activities scheduled for Oct 1983
HARRISON, J J Region 3, Office of Director 83/10/11 MILLER, D B Consumers Power Co 2pp 20779 222 24X Fiche 50-329, 83/10/11, 8310170436

--8310170439 Requests remedial soils work authorization for emergency personnel locks
MILLER, D B Consumers Power Co 83/10/06 HARRISON, J J Region 3, Office of Director 1p 20779 224 24X Fiche 50-329, 83/10/11, 8310170436

8310210134 Forwards summary of 830912-13 meetings w/BNL & Bechtel in Ann Arbor, MI re structural adequacy of diesel generator bldg
MOOD, D B Licensing Branch 4 83/10/12 Licensing Branch 4 4pp 20884 096 24X Fiche 50-329, 83/10/12, 8310210134

--8310070007 Trip rept of 830912-13 visit to Bechtel oPcs in Ann Arbor, MI to conduct audit of structural design calculations of diesel generator bldg Attendance list & chronological list of events before & after NRC order modifying CPs encl
ROMNEY, N D Structural & Geotechnical Engineering Branch 83/09/29 LEAR, G E Structural & Geotechnical Engineering Branch 19pp 20884 100 24X Fiche 50-329, 83/10/12, 8310210134

--8310210142 "Midland Plants, Units 1 & 2 Diesel Generator Bldg, Executive Summary"
* Bechtel Corp 83/08/24 48pp 20884 119 24X Fiche 50-329, 83/10/12, 8310210134

8310200265 Forwards quality action requests on NIRs 002-005, describing actions taken to resolve deficiencies, per 831007 ltr Review expected to be completed by 831216
WELLS, R A Consumers Power Co 83/10/13 BARANOW, S W Stone & Webster, Inc 10pp 20830 051 24X Fiche 50-329, 83/10/13, 8310200265

8308310050 Board Notification 83-160 provides info re 830812 failure of main crankshaft on one of three Transamerica Delaval emergency diesel generators at Shoreham
EISENHUT, D G Division of Licensing 83/10/14 PALLADINO, N J Commissioners 15pp 67056, 070 24X Fiche 50-000, 83/10/14, 8308310050

8310210027 Responds to 830912 request for addl info re comparison of rebar stresses resulting from two 40-yr estimated settlement analyses performed on diesel generator bldg finite-element model
ERHARDT, R J Consumers Power Co 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 20856 012 24X Fiche 50-329, 83/10/14, 8310210027

8310250098 Discusses current const status of project, in lieu of submitting yellowbook update for Third Quarter 1983 On 831006, ASLB order to complete project received Completion schedule being developed Update submittal requested
MILLER, D B Consumers Power Co 83/10/14 HARTFIELD, R A NRC - No Detailed Affiliation Given 1p 20894, 169 24X Fiche 50-329, 83/10/14, 8310250098

8310270066 Confirms transmittal of control copies of PQCI &/or changes as listed
EWERT, G F, PUKCI, J A Consumers Power Co 83/10/17 BARANOW, S Stone & Webster, Inc 1p 20924 120 24X Fiche 50-329, 83/10/17, 8310270066

8310310366 Requests authorization for listed remedial soils work
QUAMME, D L Consumers Power Co 83/10/17 HARRISON, J J Region 3, Office of Director 2pp 20961 112 24X Fiche 50-329, 83/10/17, 8310310366

8310240107 Informs that S&W meets independence & competence criteria for third-party reviewers & that proposed const overview adequate for assessment of const completion plan, in response to 830725 ltr NRC orders encl
KEPPLER, J Q Region 3, Office of Director 83/10/18 ROMO, L R Lone Tree Council 2pp 20881 022 24X Fiche 50-329, 83/10/18, 8310240107

8310250499 Authorizes listed remedial soils work activities for Oct 1983
HARRISON, J J Region 3, Office of Director 83/10/19 MILLER, D B Consumers Power Co 2pp 20902 086 24X Fiche 50-329, 83/10/19, 8310250499

--8310250507 Requests authorization for listed remedial soils work
QUAMME, D L Consumers Power Co 83/10/17 HARRISON, J J Region 3, Office of Director 2pp 20902 086 24X Fiche 50-329, 83/10/19, 8310250499

8310260331 Forwards procedures for performing calculations & technical studies, resolution of spatial sys interaction program/seismic postulated interactions & preparation of project technical repts
ERHARDT, R J Consumers Power Co 83/10/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 20909 224 24X Fiche 50-329, 83/10/19, 8310260331

--8310260335 Rev 1 to Procedure ATP-12-Q, "Procedure for Performing Calculations & Technical Studies"
* Mark Technologies Corp 83/08/26 13pp 20909 231 24X Fiche 50-329, 83/10/19, 8310260331

--8310260340 Rev 1 to Procedure 8301 WTP-4-Q, "Procedure for Resolution of Spatial Sys Interaction Program/Seismic Postulated Interactions"
DURAND, R J Mark Technologies Corp 83/08/26 7pp 20909 244 24X Fiche 50-329, 83/10/19, 8310260331

--8310260344 Rev 1 to Procedure ATP-13-Q, "Procedure for Preparation of Project Technical Repts"
* Mark Technologies Corp 83/08/26 10pp 20909 231 24X Fiche 50-329, 83/10/19, 8310260331

8310310369 Confirms transmittal of controlled QA program manual for Vol I, "Policies" & Vol II "Procedure for Design & Const"
EWERT, G F Consumers Power Co 83/10/19 BARANOW, S Stone & Webster, Inc 1p 20959 241 24X Fiche 50-329, 83/10/19, 8310310369

8308310032 Board Notification 83-155 forwards info re util 830928 stop work order on G-soil drilling & pile driving after drilling into structural concrete
NOVAK, T M Assistant Director for Licensing 83/10/24 Atomic Safety and Licensing Board Panel 3pp 20909 261 24X Fiche 50-329, 83/10/24, 8308310032

--8310260285 Submits new info & matl relevant to OM/OL proceeding re licensee 830928 decision to stop all G-soil drilling & pile driving after unknowingly drilling into structural concrete
Drilling procedures will be revised
WARRICK, R F Region 3, Office of Director 83/10/05
EISENHUT, D G Division of Licensing 2pp 20909 264 24X Fiche 50-329, 83/10/24, 8308310032

E NRC Safety Evaluation Report (SER), suppls & correspondence

8310190263 Summary of 831003 telcon meeting w/util & Energy Technology Engineering Ctr re resolution of SER Confirmatory Issue 4, "Independent Analysis of Piping Sys"
MILLER, M A Licensing Branch 4 83/10/17 Licensing Branch 4 6pp 20843, 257 24X Fiche 50-329, 83/10/17, 8310190263

F Security, medical, emergency & fire protection plans

8310030601 Forwards comments on 830331 detailed control room design review final rept per Suppl 1 to NUREG-0737 Rept acceptable
Meeting to discuss comments before 831017 preimplementation audit recommended
ADENSAH, E Q Licensing Branch 4 83/09/19 COOK, J W Consumers Power Co 10pp 20607 343 24X Fiche 50-329, 83/09/19, 8310030601

DOCKETED ITEMS

8310030604 Advises of compliance w/requirements of Suppl 1, Table 1, to NUREG-0737 re habitability & location of emergency operations facility. Approval of other features will be determined during post-implementation appraisal.
ADENSAM, E G Licensing Branch 4 83/09/21 COOK, J W Consumers Power Co 3pp 20607 353 24X Fiche 50-329, 83/09/21, 8310030604

8310110019 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20687 357 24X Fiche 50-000, 83/10/05, 8310110019

--8310110024 Public version of Rev 6 to Emergency Plan Implementing Procedure EDF-7, "Offsite Dose Worksheet (Protective Actions)" W/830922 ltr & receipt form
BRADLEY, J Consumers Power Co 83/07/18 Document Management Branch 2pp 20687 358 24X Fiche 50-000, 83/10/05, 8310110019

8310120464 Notification of 831026 meeting w/util & Engineering Planning & Mgt in Bethesda, MD to discuss proposal to resolve NRC concerns re safe shutdown capability in event of fire
MILLER, M A Licensing Branch 4 83/10/06 ADENSAM, E G Licensing Branch 4 5pp 20751 275 24X Fiche 50-329, 83/10/06, 8310120464

8310210030 EN-83-069 on 831026, notice of violation & proposed imposition of civil penalty in amount of \$100,000 to be issued Action based on fireline relocation activities performed in "Q" soils w/o prior NRC authorization
KLINGLER, G Director's Office, Office of Inspection and Enforcement 83/10/20 1p 20855 344 24X Fiche 50-329, 83/10/20, 8310210030

8310270491 Releases public version of revised controlled copyholder list of emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20928 337 24X Fiche 50-000, 83/10/21, 8310270491

--8310270510 Forwards public version of Rev 2 to controlled copyholder list of general ofc ctr/emergency operations facility emergency implementing procedures & list depicting location of proprietary info in procedures
CARLEY, A Consumers Power Co 83/09/15 Office of Nuclear Reactor Regulation, Director 7pp 20928 338 24X Fiche 50-000, 83/10/21, 8310270491

8310270590 Releases public version of revised general ofc control ctr/emergency operations facility emergency implementing procedures
FELTON, J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20944 322 24X Fiche 50-000, 83/10/25, 8310270590

--8310270593 Forwards public version of revised general ofc control ctr/emergency operations facility emergency implementing procedures, including Procedure GEN-2 re emergency telephone numbers (Receipt form encl)
CARLEY, A Consumers Power Co 83/10/13 Document Management Branch 4pp 20944 323 24X Fiche 50-000, 83/10/25, 8310270590

--8310270597 Public version of revised general ofc control ctr/emergency operations facility emergency implementing procedures, including Procedure GEN-2 re emergency telephone numbers
* Consumers Power Co 83/10/11 42pp 20944 327 24X Fiche 50-000, 83/10/25, 8310270590

0 Adjudicatory correspondence

8310180625 Responds to FOIA request for records submitted by util & reviewed during consideration of candidate companies or methodologies re const implementation overview Forwards documents. Documents also available in PDR
FELTON, J M Division of Rules and Records 83/09/01 GARDE, D P Government Accountability Project 3pp 20839 112 24X Fiche 50-329, 83/09/01, 8310180625

--8310180628 Forwards util 820512 response to Interrogatory IV re Contention B on independent design audit
* NRC - No Detailed Affiliation Given 82/10/01 NRC - No Detailed Affiliation Given 1p 20839 115 24X Fiche 50-329, 83/09/01, 8310180625

8310180629 Response to Interrogatory IV re Contention B on independent design audit
* Consumers Power Co 82/05/12 Stamiris, B 8pp 20839 116 24X Fiche 50-329, 83/09/01, 8310180625

8310050418 Forwards Chief Hearing Counsel 830819 memo to Ofc of Investigations requesting release of rept of investigation of alleged violation of ASLB 820430 order & preliminary notes
PAYON, W D Hearing Branch 2 83/09/28 BECHHOEFER, C, COHAN, F P, HARBOUR, J Atomic Safety and Licensing Board Panel 3pp 20629 358 24X Fiche 50-329, 83/09/28, 8310050418

8310030465 Notice of JL Donnell 831015 deposition in Las Vegas, NV
Certificate of Svc encl
WILLIAMS, F C Consumers Power Co WILLIAMS, F C Isham, Lincoln & Beale 83/09/29 3pp 20601 055 24X Fiche 50-329, 83/09/29, 8310030465

8310030514 Order delineating schedules for proposed findings of fact & conclusions of law
BECHHOEFER, C Atomic Safety and Licensing Board Panel 83/09/29 3pp 20601 182 24X Fiche 50-329, 83/09/29, 8310030514

8310040467 Requests reply to encl 830921 ltr & advice as to whether L Clark will be produced for deposition on 831004 Svc list encl Related correspondence
PROCTOR, S D Isham, Lincoln & Beale 83/09/29 KARR, J W Karr & Lyons 3pp 20623 288 24X Fiche 50-329, 83/09/29, 8310040467

8310060269 Notice of correction to 830930 motion for reconsideration
KARR, J W Government Accountability Project 83/10/03 1p 20646 154 24X Fiche 50-329, 83/10/03, 8310060269

--8310060291 Errata to 830930 motion for reconsideration Certificate of Svc encl
* Government Accountability Project 83/10/03 Atomic Safety and Licensing Board Panel 4pp 20646 155 24X Fiche 50-329, 83/10/03, 8310060269

8310110310 Application for deposition subpoena duces tecum to JL Donnell Certificate of Svc encl
WILLIAMS, F C Consumers Power Co WILLIAMS, F C Isham, Lincoln & Beale 83/10/03 Atomic Safety and Licensing Board Panel 9pp 20665 346 24X Fiche 50-329, 83/10/03, 8310110310

8310120101 Motion to stay depositions of L Clark, T Devine, BP Garde & L Hallberg as directed in ASLB 830831 order. Depositions should be stayed pending review of 830930 motion for reconsideration Certificate of Svc encl
KARR, J W Government Accountability Project 83/10/03 Atomic Safety and Licensing Board Panel 6pp 20697 103 24X Fiche 50-329, 83/10/03, 8310120101

8310110071 Second supplemental memorandum in support of intervenor Stamiris motion to litigate Dow Chemical Co issues against applicant Dow documents & complaints support litigation of issues raised in original motion Certificate of Svc encl
BERNABEIL, L Government Accountability Project 83/10/05 Atomic Safety and Licensing Board Panel 104pp 20667 174 24X Fiche 50-329, 83/10/05, 8310110071

8310130010 Forwards BB Hayes 830912 memo transmitting supplemental Ofc of Investigations rept re alleged violation of ASLB order W/o rept
HASSELL, D F Hearing Branch 1 WRIGHT, N A Hearing Branch 2 83/10/05 BECHHOEFER, C, COHAN, F P, HARBOUR, J Atomic Safety and Licensing Board Panel 3pp 20725 209 24X Fiche 50-329, 83/10/05, 8310130010

8310130233 Forwards one oversize revised settlement plot drawing referred to during Kane 830920 testimony, per ASLB 830921 request Drawing should be marked as Exhibit 25 Aperture card available in PDR
HASSELL, D F Hearing Branch 1 WRIGHT, N A Hearing Branch 2 83/10/05 BECHHOEFER, C, COHAN, F P, HARBOUR, J Atomic Safety and Licensing Board Panel 3pp 20719 150 24X Fiche 50-329, 83/10/05, 8310130233

8310110210 Memorandum & Order LDP-83-64, denying Govt Accountability Project deponent motion for reconsideration of ASLB 830831 Order LDP-83-53 & for stay of depositions, subj to noted conditions
BECHHOEFER, C Atomic Safety and Licensing Board Panel 83/10/06 Government Accountability Project 11pp 20665 062 24X Fiche 50-329, 83/10/06, 8310110210

8310110320 Memorandum explaining reasons for denying Govt Accountability Project (OAP) 831003 motion for stay of ASLB 830831 order denying motion to quash subpoenas of OAP employees Stay of motion already pending before ASLB
SHOENAKER, C J Atomic Safety and Licensing Board Panel 83/10/06 3pp 20665 358, 24X Fiche 50-329, 83/10/06, 8310110320

DOCKETED ITEMS

195

8310170383 Interrogatories re Ofc of Investigations rept Certificate of Svc encl
BERNABEI, L. Stamiris, B. BERNABEI, L. Government Accountability Project 83/10/11 Office of the Executive Legal Director 10pp 20785 019 24X Fiche 50-329, 83/10/11, 8310170383

8310170393 Request for production of documents Certificate of Svc encl
BERNABEI, L. Stamiris, B. BERNABEI, L. Government Accountability Project 83/10/11 Carolina Power & Light Co 10pp 20785 035 24X Fiche 50-329, 83/10/11, 8310170393

8310170427 Interrogatories directed to util Certificate of Svc encl
BERNABEI, L. Stamiris, B. BERNABEI, L. Government Accountability Project 83/10/11 Consumers Power Co 15pp 20779 203 24X Fiche 50-329, 83/10/11, 8310170427

8310170524 Request for production of documents Certificate of Svc encl
BERNABEI, L. Stamiris, B. BERNABEI, L. Government Accountability Project 83/10/11 Office of the Executive Legal Director 7pp 20784 209 24X Fiche 50-329, 83/10/11, 8310170524

8310180456 Expresses concern re discrepancies in const completion schedule Public meeting warranted in light of varying completion dates
GARDE, B. P. Government Accountability Project 83/10/13 DEBTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 20801 202 24X Fiche 50-329, 83/10/13, 8310180456

--8310180465 Affidavit of BP Garde re discrepancies in const completion dates Exhibits encl
GARDE, B. P. Government Accountability Project 83/09/21 Atomic Safety and Licensing Board Panel 23pp 20801 310 24X Fiche 50-329, 83/10/13, 8310180465

8310190050 Errata to instructions for interrogatories & requests for production filed on 831011 Related correspondence
BERNABEI, L. Government Accountability Project 83/10/13 PATON, W. D. Hearing Branch 2 STEPTOE, P. Isham, Lincoln & Beale 1p 20823 223 24X Fiche 50-329, 83/10/13, 8310190050

8310190048 Response to B Stamiris 831005 second supplemental memorandum supporting Dow issues Stamiris fails to show new & significant info justifying reopening record Certificate of Svc encl
STEPTOE, P. P. Consumers Power Co STEPTOE, P. P. Isham, Lincoln & Beale 83/10/14 Atomic Safety and Licensing Board Panel 13pp 20823 174 24X Fiche 50-329, 83/10/14, 8310190048

8310200254 Corrects typographical errors found in applicant response to second supplemental memorandum in support of intervenor B Stamiris motion to litigate Dow issues
STEPTOE, P. P. Isham, Lincoln & Beale STEPTOE, P. P. Consumers Power Co 83/10/17 BECHHOEFER, C. HARBOUR, J. COWAN, F. P. Atomic Safety and Licensing Board Panel 1p 20830 102 24X Fiche 50-329, 83/10/17, 8310200254

8310240172 Forwards documents not served at 830728 & 0921 hearings Certificate of Svc encl Related correspondence
LAUER, R. J. Isham, Lincoln & Beale LAUER, R. J. Consumers Power Co 83/10/18 Office of the Executive Legal Director 148pp 20879 240 24X Fiche 50-329, 83/10/18, 8310240172

8310250073 Advises of util intent to complete const despite Dow Chemical Co attempted withdrawal from contract to purchase steam generated by facility Unit 1 could be converted to electric unit Svc list encl
BRUNNER, J. E. Consumers Power Co. 83/10/18 BECHHOEFER, C. HARBOUR, J. COWAN, F. P. Atomic Safety and Licensing Board Panel 3pp 20894 112 24X Fiche 50-329, 83/10/18, 8310250073

8310250053 Notice of L. Clark, L. Hallberg, T. Devine & BP Garde 83110, 22, 1201 & 15, respectively, depositions in Washington, DC & Midland, MI Certificate of Svc encl
PROCTOR, S. D. Consumers Power Co 83/10/19 App 20894 105 24X Fiche 50-329, 83/10/19, 8310250053

8310250041 Objections to 831011 interrogatories & document production requests Certificate of Svc encl
BRUNNER, J. E. Consumers Power Co 83/10/20 STAMIRIS, B. Stamiris, B. 5pp 20894 190 24X Fiche 50-329, 83/10/20, 8310250041

8310270257 Notice of appeal from ASLB orders granting discovery against Govt Accountability Project Certificate of Svc encl
KARR, J. W. Government Accountability Project 83/10/21, 2pp 20923 268 24X Fiche 50-329, 83/10/21, 8310270257

--8310270266 Memorandum in support of appeal from ASLB orders granting discovery against Govt Accountability Project Subpoenas violate common law of privilege Util showed no compelling need for discovery
KARR, J. W. Government Accountability Project 83/10/21 Atomic Safety and Licensing Appeal Panel 10pp 20923 270 24X Fiche 50-329, 83/10/21, 8310270266

8310270345 Motion to compel CPC responses to 831011 interrogatories & request for production re investigation of alleged violation Certificate of Svc encl
BERNABEI, L. Stamiris, B. BERNABEI, L. Government Accountability Project 83/10/25 Atomic Safety and Licensing Board Panel 7pp 20923 345 24X Fiche 50-329, 83/10/25, 8310270345

8310270367 Order extending time until 831130 for Commission to act to review Director's Decision DD-83-16
CHILK, B. J. Office of the Secretary of the Commission 83/10/25, Commissioners 1p 20923 293 24X Fiche 50-329, 83/10/25, 8310270367

8310280073 Motion for admission into evidence of transcript of J.L. Donnell 831015 deposition Certificate of Svc encl
WILLIAMS, F. C. Consumers Power Co WILLIAMS, F. C. Isham, Lincoln & Beale 83/10/25 Atomic Safety and Licensing Board Panel 7pp 20933 342 24X Fiche 50-329, 83/10/25, 8310280073

--8310280078 Transcript of J.L. Donnell 831015 deposition in Las Vegas, NV re alleged violation of ASLB order
DONNELL, J. L. Consumers Power Co DONNELL, J. L. Science Applications, Inc 83/10/15 114pp 20933 351 24X Fiche 50-329, 83/10/25, 8310280078

8310280100 Order directing parties to be prepared to respond during 831031 hearing session, to applicant 831025 motion for admission into evidence of J.L. Donnell deposition.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel 83/10/26 Intervenor Other Than Dow 1p 20933 205 24X Fiche 50-329, 83/10/26, 8310280100

8310280145 Motion to continue beginning date of hearings scheduled for 831031 to 3 days after date Extended hearing necessary to allow time to receive responses to 831011 discovery requests W/Certificate of Svc
BERNABEI, L. Stamiris, B. BERNABEI, L. Government Accountability Project 83/10/26 Atomic Safety and Licensing Board Panel 6pp 20929 248 24X Fiche 50-329, 83/10/26, 8310280145

8310310390 Motion to stay ASLB 830831 & 1006 orders denying deponent motion for reconsideration of motion to quash subpoenas pending ASLB decision on deponent 831021 appeal Certificate of Svc encl Related correspondence
KARR, J. W. Government Accountability Project 83/10/26 Atomic Safety and Licensing Appeal Panel 5pp 20960 011 24X Fiche 50-329, 83/10/26, 8310310390

8310310431 Order denying Govt Accountability Project 831021 motion to stay ASLB 830831 & 1006 orders denying motions to quash subpoenas & for reconsideration, respectively Motion filed late & fails to show stay warranted
SHENAKER, C. J. Atomic Safety and Licensing Appeal Panel 83/10/27 Government Accountability Project 6pp 20959 230 24X Fiche 50-329, 83/10/27, 8310310431

8310310211 Order granting B Stamiris 831026 motion to continue evidentiary hearings due to nonreceipt of responses to discovery request Three-day continuance granted
BECHHOEFER, C. Atomic Safety and Licensing Board Panel 83/10/28 STAMIRIS, B. Stamiris, B. 2pp 20958 322 24X Fiche 50-329, 83/10/28, 8310310211

G Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

DOCKETED ITEMS

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310170558 Forwards IE Insp Repts 50-329/83-12 & 50-330/83-13 on 830523-27, 0613-17 & 27-30 & 0701 compliance notice of violation
WARNICK, R F Region 3, Office of Director 83/09/29 COOK, J W Consumers Power Co 2pp 20780 213 24X Fiche 50-329, 83/09/29, 8310170558

--8310170562 Notice of violation from insp on 830523-27, 0613-17 & 27-30 & 0701
WARNICK, R F Region 3, Office of Director 83/09/29 2pp 20780 215 24X Fiche 50-329, 83/09/29, 8310170562

--8310170572 IE Insp Repts 50-329/83-12 & 50-330/83-13 on 830523-27, 0613-17 & 27-30 & 0701 Noncompliance noted failure to follow hanger & field weld procedures
SIMON, J A, SATHER, A, HARRISON, J J Region 3, Office of Director 83/09/29 8pp 20780 217 24X Fiche 50-329, 83/09/29, 8310170572

8310170459 Forwards IE Mgt Meeting Repts 50-329/83-16 & 50-330/83-17 on 830825 re S&W Engineering const implementation overview program
WARNICK, R F Region 3, Office of Director 83/09/30 COOK, J W Consumers Power Co 2pp 20784 052 24X Fiche 50-329, 83/09/30, 8310170459

--8310170464 IE Mgt Meeting Repts 50-329/83-16 & 50-330/83-17 on 830825 Major areas discussed until proposed third party overview & S&W Engineering const implementation overview program
GARDNER, R N, HARRISON, J J Region 3, Office of Director 83/09/29 6pp 20784 054 24X Fiche 50-329, 83/09/30, 8310170464

--8310170466 Confirms commitments made to NRC at 830825 public meeting in Midland, MI re third party const implementation overview program Viewgraphs encl
WILD, P A Stone & Webster, Inc 83/08/30 KEPLER, J G Region 3, Office of Director 20pp 20784 060 24X Fiche 50-329, 83/09/30, 8310170466

8310170513 Forwards IE Insp Repts 50-329/83-19 & 50-330/83-20 on 830821-0920 No noncompliance noted
WARNICK, R F Region 3, Office of Director 83/10/03 COOK, J W Consumers Power Co 2pp 20781 080 24X Fiche 50-329, 83/10/03, 8310170513

--8310170534 IE Insp Repts 50-329/83-19 & 50-330/83-20 on 830821-0920 No noncompliance noted Major areas inspected review of svc water pump structure instrumentation, remedial soils work activities & plant tours
BURGESS, B L, COOK, R J, GARDNER, R N Region 3, Office of Director 83/09/30 4pp 20781 082 24X Fiche 50-329, 83/10/03, 8310170534

--8310170538 Forwards Weekly Rept 52 of independent assessment of underpinning for period 830911-17
LUCKS, A B Stone & Webster, Inc 83/09/20 COOK, R NRC - No Detailed Affiliation Given 14pp 20781 086 24X Fiche 50-329, 83/10/03, 8310170538

--8310170544 Forwards Weekly Rept 51 of independent assessment of underpinning for period 830903-10
LUCKS, A B Stone & Webster, Inc 83/09/14 COOK, R NRC - No Detailed Affiliation Given 11pp 20781 100 24X Fiche 50-329, 83/10/03, 8310170544

--8310170549 Forwards Weekly Rept 50 of independent assessment of underpinning for period 830828-0903
LUCKS, A B Stone & Webster, Inc 83/09/08 COOK, R NRC - No Detailed Affiliation Given 15pp 20781 111 24X Fiche 50-329, 83/10/03, 8310170549

--8310170555 Forwards Weekly Rept 49 of independent assessment of underpinning for period 830821-27
LUCKS, A B Stone & Webster, Inc 83/08/31 COOK, R NRC - No Detailed Affiliation Given 13pp 20781 126 24X Fiche 50-329, 83/10/03, 8310170555

--8310170559 Forwards Weekly Rept 48 of independent assessment of underpinning for period 830814-20
LUCKS, A B Stone & Webster, Inc 83/08/24 COOK, R NRC - No Detailed Affiliation Given 14pp 20781 139 24X Fiche 50-329, 83/10/03, 8310170559

--8310170560 Forwards Rept 14 of const implementation overview for period 830912-16
BARANOW, S W Stone & Webster, Inc 83/09/19 KEPLER, J G Region 3, Office of Director 7pp 20781 193 24X Fiche 50-329, 83/10/03, 8310170560

--8310170564 Forwards Rept 13 of const implementation overview for period 830905-09
BARANOW, S W Stone & Webster, Inc 83/09/12 KEPLER, J G Region 3, Office of Director 6pp 20781 160 24X Fiche 50-329, 83/10/03, 8310170564

--8310170567 Forwards Rept 12 of const implementation overview for period 830827-0902
BARANOW, S W Stone & Webster, Inc 83/09/06 KEPLER, J G Region 3, Office of Director 10pp 20781 166 24X Fiche 50-329, 83/10/03, 8310170567

--8310170571 Forwards Rept 11 of const implementation overview for period 830822-26
BARANOW, S W Stone & Webster, Inc 83/08/29 KEPLER, J G Region 3, Office of Director 5pp 20781 176 24X Fiche 50-329, 83/10/03, 8310170571

--8310170575 Forwards Rept 10 of const implementation overview for period 830815-19
BARANOW, S W Stone & Webster, Inc 83/08/22 KEPLER, J G Region 3, Office of Director 7pp 20781 181 24X Fiche 50-329, 83/10/03, 8310170575

8310170583 Forwards IE Insp Repts 50-329/83-15 & 50-330/83-16 on 830721-0820 No noncompliance noted
WARNICK, R F Region 3, Office of Director 83/10/03 COOK, J W Consumers Power Co 2pp 20780 237 24X Fiche 50-329, 83/10/03, 8310170583

--8310170591 IE Insp Repts 50-329/83-15 & 50-330/83-16 on 830721-0820 No noncompliance noted Major areas inspected remedial soils activities, team training, D&W hanger installations & S&W meeting
BURGESS, B L, COOK, R J, GARDNER, R N Region 3, Office of Director 83/09/30 5pp 20780 239 24X Fiche 50-329, 83/10/03, 8310170591

--8310170598 Forwards Rept 6 of const implementation overview for period 830715-21
BARANOW, S W Stone & Webster, Inc 83/07/25 KEPLER, J G Region 3, Office of Director 5pp 20780 244 24X Fiche 50-329, 83/10/03, 8310170598

--8310170602 Forwards Rept 7 of const implementation overview for period 830722-28
BARANOW, S W Stone & Webster, Inc 83/08/01 KEPLER, J G Region 3, Office of Director 5pp 20780 249 24X Fiche 50-329, 83/10/03, 8310170602

--8310170606 Forwards Rept 8 of const implementation overview for period 830729-0804
BARANOW, S W Stone & Webster, Inc 83/08/08 KEPLER, J G Region 3, Office of Director 6pp 20780 254 24X Fiche 50-329, 83/10/03, 8310170606

--8310170610 Forwards Rept 9 of const implementation overview for period 830805-12
BARANOW, S W Stone & Webster, Inc 83/08/15 KEPLER, J G Region 3, Office of Director 6pp 20780 260 24X Fiche 50-329, 83/10/03, 8310170610

--8310170616 Forwards Weekly Rept 44 of independent assessment of underpinning for period 830717-23
LUCKS, A B Stone & Webster, Inc 83/07/28 COOK, R NRC - No Detailed Affiliation Given 16pp 20780 266 24X Fiche 50-329, 83/10/03, 8310170616

--8310170622 Forwards Weekly Rept 45 of independent assessment of underpinning for period 830724-30
LUCKS, A B Stone & Webster, Inc 83/08/04 COOK, R NRC - No Detailed Affiliation Given 17pp 20780 282 24X Fiche 50-329, 83/10/03, 8310170622

--8310170627 Forwards Weekly Rept 46 of independent assessment of underpinning for period 830731-0806
LUCKS, A B Stone & Webster, Inc 83/08/10 COOK, R NRC - No Detailed Affiliation Given 11pp 20780 299 24X Fiche 50-329, 83/10/03, 8310170627

--8310170634 Forwards Weekly Rept 47 of independent assessment of underpinning for period 830807-13
LUCKS, A B Stone & Webster, Inc 83/08/17 COOK, R NRC - No Detailed Affiliation Given 14pp 20780 310 24X Fiche 50-329, 83/10/03, 8310170634

DOCKETED ITEMS

197

8310240067 Confirms transmittal of computer printout containing info on MPDAD (balance of plant) inspector records
BOTINER, L Commonwealth Edison Co 83/10/03 BARANOW, S Stone & Webster Engineering Corp 1p 20881 344 24X Fiche 50-329, 83/10/03, 8310240067

8310120317 Notification of 831011 significant licensee meeting w/util in Glen Ellyn, IL to review IE investigation rept & to discuss alleged violation of ASLB order on remedial soils
* Region 3, Office of Director 83/10/05 Region 3, Office of Director 1p 20700 307 24X Fiche 50-329, 83/10/05, 8310120317

8310120325 Confirms 831011 meeting in Region III ofc to discuss alleged violation of ASLB order re remedial soils areas & possible IE enforcement actions
WARNICK, R F Region 3, Office of Director 83/10/05 COOK, J W Consumers Power Co 1p 20700 273 24X Fiche 50-329, 83/10/05, 8310120325

8310130010 Forwards BB Hayes 830912 memo transmitting supplemental Ofc of Investigations rept re alleged violation of ASLB order w/o rept
HASSELL, D F Hearing Branch 1 83/10/05 BECHHOEFER, C Atomic Safety and Licensing Board Panel 5pp 20725 209 24X Fiche 50-329, 83/10/05, 8310130010

8310210316 Forwards IE Audit Repts 50-329/83-20 & 50-330/83-21 on 830914-15
WARNICK, R F Region 3, Office of Director 83/10/05 COOK, J W Consumers Power Co 2pp 20851 079 24X Fiche 50-329, 83/10/05, 8310210316

--8310210319 IE Audit Repts 50-329/83-20 & 50-330/83-21 on 830914-15
Major areas audited calculations of auxiliary bldg based on new soil modulus determined from underpinning pier load test results Related matls encl
LANDSMAN, R B, HARRISON, J J Region 3, Office of Director 83/10/04 50pp 20851 081 24X Fiche 50-329, 83/10/05, 8310210316

8310110191 EN-83-044 on 831006, notice of confirmatory order for mod of GPs issued Order requires const implementation overview program to provide reasonable assurance that facility can be completed in accordance w/regulatory requirements
STONE, J, HEIGHMAN, R Director's Office, Office of Inspection and Enforcement 83/10/06 1p 20665 007 24X Fiche 50-329, 83/10/06, 8310110191

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180265 Clarifies NRC position re procedures for admitting NRC personnel to Facility List of personnel requiring access to vital areas encl. Updates will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 COOK, J W Consumers Power Co 7pp 20807 043 24X Fiche 50-329, 83/10/14, 8310180265

8310310411 Forwards IE Insp Repts 50-329/83-17 & 50-330/83-18 on 830711-12 & 0816-19 No noncompliance noted
WARNICK, R F Region 3, Office of Director 83/10/17, COOK, J W Consumers Power Co 2pp 20959 304, 24X Fiche 50-329, 83/10/17, 8310310411

--8310310417 IE Insp Repts 50-329/83-17 & 50-330/83-18 on 830711-12 & 0816-19 No noncompliance noted. Major areas inspected: review of B&W GC insp & process for installation at ABME III Class 1 pipe
SIMON, J A, BATHER, A, HARRISON, J J Region 3, Office of Director 83/10/17 4pp 20959 306 24X Fiche 50-329, 83/10/17, 8310310411

8310210030 EN-83-049 on 831026, notice of violation & proposed imposition of civil penalty in amount of \$100,000 to be issued Action based on fireline relocation activities performed in "Q" soils w/o prior NRC authorization
KLINGLER, G, AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/10/20 1p 20855 344 24X Fiche 50-329, 83/10/20, 8310210030

8310270165 Authorizes util to proceed w/Phase I activities for const completion program in response to 831020 request Insp results used as basis for granting authorization documented in NRC/Midland monthly insp repts
HARRISON, J J Region 3, Office of Director 83/10/21 GUAMME, D L Consumers Power Co 2pp 20924 154 24X Fiche 50-329, 83/10/21, 8310270165

--8310270171 Advises that status assessment & verification of completed work (Phase I of const completion program) initiated & requests NRC release to initiate Phase I initial activities will be restricted to five modules
GUAMME, D L Consumers Power Co 83/10/20 HARRISON, J J Region 3, Office of Director 4pp 20924 156 24X Fiche 50-329, 83/10/21, 8310270165

--8310270176 Provides overview of const completion program Modules 340, 102, 120, 410 & 800 requested for release
BARANOW, S W Stone & Webster, Inc 83/10/12 KEPLER, J Q Region 3, Office of Director 11pp 20924 160 24X Fiche 50-329, 83/10/21, 8310270165

8310270341 Advises that review of util 830624 supplemental response to Item B of 830208 notice of violation completed Response unacceptable Schedule for penetrant tests of welds must be submitted within 25 days of ltr receipt
WARNICK, R F Region 3, Office of Director 83/10/21 COOK, J W Consumers Power Co 2pp 20923 352 24X Fiche 50-329, 83/10/21, 8310270341

--8310270352 Forwards supplemental info re Item B of 830208 notice of violation, in response to NRC 830523 request Const training procedure revised to establish program assuring appropriate training in installation procedures
COOK, J W Consumers Power Co 83/06/24 KEPLER, J Q Region 3, Office of Director 15pp 20923 354 24X Fiche 50-329, 83/10/21, 8310270341

R Periodic operating reports & related correspondence

8310210272 Forwards fifth monthly status rept for independent design & const verification program for Sept 1983
LEVIN, H A YERA Corp 83/10/17 EISENHUT, D Q Division of Licensing KEPLER, J Q Region 3, Office of Director, COOK, J W Consumers Power Co 3pp 20848 220 24X Fiche 50-329, 83/10/17, 8310210272

--8310210275 Fifth monthly status rept for independent design & const verification program for Sept 1983
DAUGHERTY, F, LEVIN, H A, BECK, J W YERA Corp 83/10/17 51pp, 20848 223 24X Fiche 50-329, 83/10/17, 8310210272

8310310078 Forwards listed documents written or closed during Sept 1983, per condition of Memorandum & Order ALAB-106 & Amend 1 to CPPR-B1 & CPPR-B2
COOK, J W Consumers Power Co 83/10/25 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3800pp 20980 001, 24X Fiche: 50-329, 83/10/25, 8310310078

B Reportable occurrences, LERs & related correspondence

8309090259 Interim deficiency rept re dc backed power supplies for F000 interlock relays in auxiliary feedwater sys Schematic Diagram E-158(G) revised & issued as of 830727 to provide 120-volt ac power.
COOK, J W Consumers Power Co 83/09/02 KEPLER, J Q Region 3, Office of Director 6pp 20310 187 24X Fiche 50-329, 83/09/02, 8309090259

8310120446 PNO-III-83-092 on 831004, marijuana found in truck owned by carpenter employed by Bechtel Corp Individual fired by Bechtel & left site No action planned by Region III State of MI will be notified
HARRISON, J, WARNICK, R Region 3, Office of Director, 83/10/04, 1p, 20698 325 24X Fiche 50-329, 83/10/04, 8310120446,

8310140090 PNO-III-83-095, on 831005, B&W issued stop work order on Class I piping hanger installation. Stop work applies to both small bore & large bore piping & is based on deficiencies identified in hangers during Bechtel insp
HARRISON, J, QARDNER, R Region 3, Office of Director, 83/10/06, 1p 20767 059, 24X Fiche 50-329, 83/10/06, 8310140090,

DOCKETED ITEMS

8310170421 Final deficiency rept re underrated terminal strips on Limitorque valve operators initially reported on 830213 New valve operators for use inside containment will be purchased w/o terminal blocks or space heaters
COOK, J W Consumers Power Co 83/10/06 KEPLER, J O Region 3, Office of Director 25pp 20783 323 24X Fiche 50-329, 83/10/06, 8310170421

8310250101 Final rept re deficiencies in electrical components in that non-Class IE devices wired into Class IE circuits
Engineering production schedule activities will be revised by 831021
COOK, J W Consumers Power Co 83/10/14 KEPLER, J O Region 3, Office of Director 14pp 20696 172 24X Fiche 50-329, 83/10/14, 8310250101

8310270265 Interim deficiency rept re reactor bldg spray piping supports, initially reported on 791221 Caused by conservative modeling assumptions made in original water hammer analysis
Next rept by 831230
COOK, J W Consumers Power Co 83/10/21 KEPLER, J O Region 3, Office of Director 6pp 20923 247 24X Fiche 50-329, 83/10/21, 8310270265

T Hearing transcripts on non-antitrust matters

8310280073 Motion for admission into evidence of transcript of JL Donnell 831015 deposition Certificate of Svc encl
WILLIAMS, F C Consumers Power Co 83/10/25 Atomic Safety and Licensing Board Panel 9pp 20933 342 24X Fiche 50-329, 83/10/25, 8310280073

--8310280078 Transcript of JL Donnell 831015 deposition in Las Vegas, NV re alleged violation of ASLR order
DONNELL, J L Consumers Power Co 83/10/15 114pp 20933 351 24X Fiche 50-329, 83/10/25, 8310280078

DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

F. Security, medical, emergency & fire protection plans

8310040195 Forwards IE Insp Rept 50-331/83-14 on 830808-12 No notice of violation will be issued for activities not complying w/NRC requirements since 10CFR2, App C, Section IV, A provisions met
PAPERIELLO, C J Region 3, Office of Director 83/09/16 LIU, L Iowa Electric Light & Power Co 2pp 20608 233 24X Fiche: 50-331, 83/09/16, 8310040195

--8310040198 IE Insp Rept 50-331/83-14 on 830808-12 Noncompliance noted lack of timely offsite notification capability & failure to classify unusual event
PATTERSON, J P, GLOERSEN, W B, PHILLIPS, M P Region 3, Office of Director 83/09/16 14pp. 20608 235 24X Fiche 50-331, 83/09/16, 8310040198.

8310110035 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20686 269 24X Fiche 50-331, 83/10/05, 8310110035

--8310110036 Forwards public version of Rev 4 to Emergency Plan Implementing Procedure EPIP 3.3a, "Manual Dose Projections" & Rev 3 to EPIP 3.3b, "Computerized Dose Projections" w/830824 receipt form.
PORTZ, R Iowa Electric Light & Power Co 83/09/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp. 20686 266 24X Fiche: 50-331, 83/10/05, 8310110035

--8310110038 Public version of Rev 4 to Emergency Plan Implementing Procedure EPIP 3.3a, "Manual Dose Projections" & Rev 3 to EPIP 3.3b, "Computerized Dose Projections."
* Iowa Electric Light & Power Co 83/08/24 47pp. 20686 269 24X Fiche: 50-331, 83/10/05, 8310110035

8310110042 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p. 20687-001 24X Fiche: 50-331, 83/10/05, 8310110042.

--8310110055 Forwards public version of revised Emergency Plan Implementing Procedures EPIP 3.3a re initial dose projections, EPIP 3.3b re followup dose projections & EPIP 6.4 re emergency preparedness communications testing
PORTZ, R, Iowa Electric Light & Power Co. 83/05/31. DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp. 20687.002 24X Fiche 50-331, 83/10/05, 8310110042

--8310110060 Public version of revised Emergency Plan Implementing Procedures EPIP 3.3a re initial dose projections, EPIP 3.3b re followup dose projections & EPIP 6.4 re emergency preparedness communications testing
* Iowa Electric Light & Power Co 83/05/25 147pp 20687 005 24X Fiche 50-331, 83/10/05, 8310110042

8310250668 Releases public version of revised corporate plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/27 Document Management Branch 1p 20908 053 24X Fiche 50-331, 83/10/27, 8310250668

--8310250669 Forwards public version of Rev 5 to corporate plan implementing procedures, including Procedures CPIP-1 2 re corporate notification & CPIP-1 3 re activation & operation of emergency operations facility.
PORTZ, R Iowa Electric Light & Power Co 83/10/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20908 054 24X Fiche 50-331, 83/10/27, 8310250668

--8310250670 Public version of Rev 5 to emergency plan implementing procedures, including Procedures CPIP-1 2 re corporate notification & CPIP-1 3 re activation & operation of emergency operations facility
* Iowa Electric Light & Power Co 83/10/07 133pp 20908 056 24X Fiche 50-331, 83/10/27, 8310250668

8310270005 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/27 Document Management Branch 1p 20939 120 24X Fiche 50-331, 83/10/27, 8310270005

--8310270015 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1 re determination of emergency action level & EPIP 1.2 re notifications. Receipt form encl
WILSON, D L Iowa Electric Light & Power Co 83/10/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20939 122 24X Fiche 50-331, 83/10/27, 8310270005

--8310270019 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1 re determination of emergency action level & EPIP 1.2 re notifications
* Iowa Electric Light & Power Co 83/10/03 40pp 20939 124 24X Fiche 50-331, 83/10/27, 8310270005

P Operating license stage documents & correspondence

8310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR
CONNER, L Affiliation Unknown 83/05/02 NRC - No Detailed Affiliation Given 1p 21004 270 24X Fiche 50-000, 83/05/02, 8310310017

8310170119 Forwards safety evaluation of 780301 request for relief from 10CFR50.55a(g) & ASME Boiler & Pressure Vessel Code inservice testing requirements Relief granted in part
VASSALLO, D B Operating Reactors Branch 2 83/09/26 LIU, L, Iowa Electric Light & Power Co 4pp 20813 067 24X Fiche 50-331, 83/09/26, 8310170119

--8310170125 Safety evaluation supporting proposed inservice insp/testing program & granting, in part, 780301 request for relief from testing requirements
* NRC - No Detailed Affiliation Given 83/09/26 8pp 20813 071. 24X Fiche 50-331, 83/09/26, 8310170119

8310140254 Forwards fourth semiannual "Rept on Environ Qualification Program for Duane Arnold Energy Ctr" covering safety-related electrical equipment
MCGAUGHY, R W Iowa Electric Light & Power Co 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20759 300 24X Fiche 50-331, 83/09/30, 8310140254

--8310140258 "Rept on Environ Qualification Program for Duane Arnold Energy Ctr," fourth semiannual rept
* Bechtel Corp 83/09/22 592pp 20759 302 24X Fiche 50-331, 83/09/30, 8310140254

8310180198 Forwards response to request for addl info re single recirculation loop operation. Independent verification of average power range monitor gain adjustment performed daily
MCGAUGHY, R W, Iowa Electric Light & Power Co 83/10/11 DENTON, H R, Office of Nuclear Reactor Regulation, Director 2pp 20808 339 24X Fiche 50-331, 83/10/11, 8310180198

8310180424 Responds to D Vassallo 830823 ltr re automatic closing of containment purge & vent valves on high radiation signal (NUREG-0737, Item II E 4 2(7)) Facility will be modified, as result of evaluation of BWR Owners Group position
MCGAUGHY, R W Iowa Electric Light & Power Co 83/10/13
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p
20803 305 24X Fiche 50-331, 83/10/13, 8310180424

8310200182 Revised application for amend to License DPR-49, consisting of Proposed Change RTS-115D to Tech Specs re noble gas monitoring & annual verification of cumulative air dose Class III fee submitted w/770829 application
MCGAUGHY, R W Iowa Electric Light & Power Co 83/10/17 DENTON, H
Office of Nuclear Reactor Regulation, Director 3pp 20833 055
24X Fiche 50-331, 83/10/17, 8310200182

--8310200186 Proposed Change RTS-115D to Tech Specs Pages 3 2-3, 3 2-4, 3 2-29, 3 2-33, 3 14-11, 3 15-3, 3 15-5, 3 15-7, 3 15-8, 3 15-10, 6 11-4 & 6 11-12 re noble gas & cumulative air dose, per comments in telcons w/NRC during wk of 830926-30
* Iowa Electric Light & Power Co 83/10/17 14pp 20835 058
24X Fiche 50-331, 83/10/17, 8310200186

8310310117 Rejects 830902 request for extension of time to submit Formal, 120-day response to Generic Ltr 83-28 re Salem ATWS events Response due by 831105 Participation in owners group acceptable for long-range planning issues only
VASSALLO, D B Operating Reactors Branch 2 83/10/19 LIU, L Iowa
Electric Light & Power Co 2pp 20965 327 24X
Fiche 50-331, 83/10/19, 8310310117

8310270535 Notification of 831102 meeting w/util in Bethesda, MD to discuss guidance on requirements for application to upgrade power.
THADANI, M C. Operating Reactors Branch 2 83/10/21 VASSALLO, D B
Operating Reactors Branch 2 2pp 20938 032 24X
Fiche 50-331, 83/10/21, 8310270535

Q Inspection reports, IE Bulletins & correspondence

8310040195 Forwards IE Insp Rept 90-331/83-14 on 830808-12 No notice of violation will be issued for activities not complying w/NRC requirements since 10CFR2, App C, Section IV A provisions met
PAPERIELLO, C J Region 3, Office of Director 83/09/16 LIU, L
Iowa Electric Light & Power Co 2pp 20608 233 24X
Fiche 50-331, 83/09/16, 8310040195

--8310040198 IE Insp Rept 90-331/83-14 on 830808-12 Noncompliance noted lack of timely offsite notification capability & failure to classify unusual event
PATTERSON, J P, OLDERSEN, W B, PHILLIPS, M P Region 3, Office of Director 83/09/16 14pp 20608 235 24X Fiche 50-331, 83/09/16, 8310040198

8310060158 Forwards IE Insp Rept 90-331/83-11 on 830627-0830 No noncompliance noted
SHAFER, W D Region 3, Office of Director 83/09/21 LIU, L Iowa
Electric Light & Power Co 2pp 20647 180 24X
Fiche 50-331, 83/09/21, 8310060158

--8310060165 IE Insp Rept 90-331/83-11 on 830627-0830 No noncompliance noted Major areas inspected operational safety, maint, surveillance, LERs, procedures, plant operations, plant trips, IE circulars, audits, TMI items & licensee meetings
CLARDY, L S, WALKER, R D Region 3, Office of Director 83/09/16 14pp 20647 182 24X Fiche 50-331, 83/09/21, 8310060158

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310170117 Forwards safety evaluation of 780301 request for relief from 10CFR50.55a(g) & ASME Boiler & Pressure Vessel Code inservice testing requirements Relief granted in part
VASSALLO, D B Operating Reactors Branch 2 83/09/26 LIU, L Iowa
Electric Light & Power Co 4pp 20813 067 24X
Fiche 50-331, 83/09/26, 8310170117

--8310170125 Safety evaluation supporting proposed inservice insp/testing program & granting, in part, 780301 request for relief from testing requirements
* NRC - No Detailed Affiliation Given 83/09/26 8pp
20813 071 24X Fiche 50-331, 83/09/26, 8310170119

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310140254 Forwards fourth semiannual "Rept on Environ Qualification Program for Duane Arnold Energy Ctr" covering safety-related electrical equipment
MCGAUGHY, R W Iowa Electric Light & Power Co 83/09/30 DENTON, H
Office of Nuclear Reactor Regulation, Director 2pp 20759 300
24X Fiche 50-331, 83/09/30, 8310140254

--8310140258 "Rept on Environ Qualification Program for Duane Arnold Energy Ctr," fourth semiannual rept
* Bechtel Corp 83/09/22 592pp 20759 302 24X
Fiche 50-331, 83/09/30, 8310140254

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Hatl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180206 Clarifies NRC position re procedures for admitting NRC insp personnel to facilities List of NRC personnel requiring access to plant vital areas encl Update will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 LIU, L Iowa
Electric Light & Power Co 7pp 20808 317 24X
Fiche 50-331, 83/10/14, 8310180206

8310180551 Notification of 831021 meeting w/BWR licensees in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking
HRAQLIA, F J Assistant Director for Safety Assessment 83/10/14
EISENHUT, D G Division of Licensing 3pp 20823 338 24X
Fiche 50-000, 83/10/14, 8310180551

8310270457 Discusses scram discharge vol short-term mode in response to IE Bulletin 80-17 Water added to scram discharge vol & vent procedures & drain valve operability & closure time test changed from quarterly to monthly
MCGAUGHY, R W Iowa Electric Light & Power Co 83/10/18
KEPPLER, J O Region 3, Office of Director 1p 20923 133 24X
Fiche 50-331, 83/10/18, 8310270459

R Periodic operating reports & related correspondence

8310170405 Monthly monitoring rept for Aug 1983 w/831006 ltr.
MCGAUGHY, R W Iowa Electric Light & Power Co 83/08/31
KEPPLER, J O Region 3, Office of Director 2pp 20779 156 24X
Fiche 50-331, 83/08/31, 8310170405

8310140254 Forwards fourth semiannual "Rept on Environ Qualification Program for Duane Arnold Energy Ctr" covering safety-related electrical equipment
MCGAUGHY, R W Iowa Electric Light & Power Co 83/09/30 DENTON, H
Office of Nuclear Reactor Regulation, Director 2pp 20759 300
24X Fiche 50-331, 83/09/30, 8310140254

--8310140258 "Rept on Environ Qualification Program for Duane Arnold Energy Ctr," fourth semiannual rept
* Bechtel Corp 83/09/22 592pp 20759 302 24X
Fiche 50-331, 83/09/30, 8310140254

DOCKETED ITEMS

8310170581 "Radiological Analysis of Strontium Samples, Second Quarter 1983"
MINECK, D L Iowa Electric Light & Power Co 83/10/03 KEPLER, J Q
Region 3, Office of Director 2pp 20760 335 24X
Fiche 50-331, 83/10/03, 8310170581

8310190068 Monthly operating rept for Sept 1983 W/831014 ltr
ANDERSEN, M. MINECK, D L Iowa Electric Light & Power Co 83/10/14
Director's Office, Office of Inspection and Enforcement 8pp
20822 293 24X Fiche 50-331, 83/10/14, 8310190068

8 Reportable occurrences, LERs & related correspondence

8310110430 Responds to FOIA request for four different categories of documents described in 830510 ltr Forwards matl listed in App A, responsive to Items 1, 2 & 4 DOE should be contacted for matl requested in Item 3 of ltr
FELTON, J M Division of Rules and Records 83/06/14, HIATT, S L
Ohio Citizens for Responsible Energy 3pp 20706 002 24X
Fiche 50-000, 83/06/14, 8310110430

--8310110467 Daily rept re events at three different facilities IACBHR experienced scram due to low water level PNO-III-83-026
updates use of lubricants on valve seats
* Region 3, Office of Director 83/04/14 1p 20706 062 24X
Fiche 50-000, 83/06/14, 8310110430

8310120380 RO on 830308, radiographic exams conducted on 10 HPCI turbine reversing chambers Seven chambers did not meet augmented acceptance criteria Cracking caused by mfg process & pressure pulsing fatigue
MINECK, D L Iowa Electric Light & Power Co 83/08/23 KEPLER, J Q
Region 3, Office of Director 2pp 20699 198 24X
Fiche: 50-331, 83/08/23, 8310120380

8310120400 LER 83-033/03L-O on 830903, HPCI min flow return to torus line valve HQ-2318 indication intermittently showed valve open HPCI declared inoperable Caused by cracked valve yoke Yoke repaired & tightened W/831003 ltr
KIBLER, D R., MINECK, D L Iowa Electric Light & Power Co 83/10/03
KEPLER, J Q Region 3, Office of Director 2pp 20700 202 24X
Fiche 50-331, 83/10/03, 8310120400

8310170490 LER 83-035/03L-O on 830906, during surveillance testing, L1B 4531 & 4532 for reactor water low-low tripped nonconservatively at 113 2 & 113 4 inches, respectively
Caused by instrument drift Switches recalibr W/831006 ltr
HARRIS, M B., MINECK, D L Iowa Electric Light & Power Co 83/10/06
KEPLER, J Q Region 3, Office of Director 2pp 20784 117 24X
Fiche: 50-331, 83/10/06, 8310170490

8310120421 LER 83-036/03L-O on 830909, during normal operation, visual insp of HFA relays revealed relay A71B-K1B deteriorated
Caused by varnish sticking armature closed Relay replaced W/831009 ltr
HAMEL, D B., MINECK, D L Iowa Electric Light & Power Co 83/10/09
KEPLER, J Q Region 3, Office of Director 2pp 20698 319 24X
Fiche: 50-331, 83/10/09, 8310120421

8310210090 LER 83-040/03L-O on 830913, during surveillance testing, drywell equipment drain line valve CV-3729 did not close on manual closure signal, Caused by air operator piston being stuck Valve lubricated & cycled
ANDERSEN, M W., MINECK, D L Iowa Electric Light & Power Co 83/10/13
KEPLER, J Q Region 3, Office of Director 2pp 20838 195 24X Fiche 50-331, 83/10/13, 8310210090

310250481 LER 83-037/03L-O on 830915, during surveillance test, rod block monitor channel B prevented movement of rod 26-07, causing inoperability of channel Caused by wiring problem Component replaced W/831017 ltr
HARRIS, M B., MINECK, D L Iowa Electric Light & Power Co. 83/10/17
KEPLER, J Q Region 3, Office of Director 4pp 20897 071 24X
Fiche: 50-331, 83/10/17, 8310250481

1 pump IP-233
oil
ed
Co
7p.

DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT

F Security, medical, emergency & fire protection plans

8310170533 Advises that 1983 annual emergency preparedness exercise tentatively scheduled for 831012. Exercise will be small scale & involve only limited participation by Oswego County & State of NY
MCNEILL, C A Power Authority of the State of New York 83/01/04
HAYNES, R C Region 1, Office of Director 2pp 20779 321 24X
Fiche 50-333, 83/01/04, 8310170533

--8310170655 Forwards "Emergency Response Plan Exercise Manual" Withholding of exercise scenario until exercise completed requested
BAYNE, J P Power Authority of the State of New York 83/07/15
MURLEY, T E Region 1, Office of Director 2pp 20779 324 24X
Fiche 50-333, 83/01/04, 8310170533

--8310170659 Rev 1 to Procedure BAP-1, "Emergency Response Plan Exercise Manual"
* Power Authority of the State of New York 83/04/30 213pp
20779 326 24X Fiche 50-333, 83/01/04, 8310170533

8310210126 Forwards "Emergency Response Plan Exercise Manual," for 831012 site preparedness exercise
BAYNE, J P Power Authority of the State of New York 83/10/07
MURLEY, T E Region 1, Office of Director 1p 20853 230 24X
Fiche 50-333, 83/10/07, 8310210126

--8310210127 "Emergency Response Plan Exercise Manual"
* Power Authority of the State of New York 83/10/12 465pp
20853 231 24X Fiche 50-333, 83/10/07, 8310210126

8310280044 Forwards "Detailed Control Room Design Review Program Plan for JA Fitzpatrick Nuclear Power Plant," in response to 831217 Generic Ltrs 82-33 & 83-18, Suppl 1 to NUREG-0737 & TH1 Action Item 1 D 1
BAYNE, J P Power Authority of the State of New York 83/10/24
VASSALLO, D B Operating Reactors Branch 2 2pp 20934 348 24X
Fiche: 50-333, 83/10/24, 8310280044

--8310280054 "Detailed Control Room Design Review Program Plan for JA Fitzpatrick Nuclear Power Plant"
* Power Authority of the State of New York 83/10/19 86pp
20934 350 24X Fiche: 50-333, 83/10/24, 8310280044

0 Adjudicatory correspondence

8310060580 Forwards UCB 830912 petition per 10CFR2 206 requesting immediate action to shut down plant Response by 831012 requested
DENTON, H R. Office of Nuclear Reactor Regulation, Director 83/09/23
BAYNE, J P Power Authority of the State of New York 3pp 20661 212 24X Fiche 50-333, 83/09/23, 8310060580

8310130113 Responds to 830923 request for response to UCB 830912 petition filed under 10CFR2. 206 re pipe support issues Extension of response date to 831116 requested
BAYNE, J P Power Authority of the State of New York 83/10/11
DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20726 308 24X Fiche 50-333, 83/10/11, 8310130113

P. Operating license stage documents & correspondence

8310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR
CONNOR, L Affiliation Unknown, 83/05/02 NRC - No Detailed Affiliation Given 1p 21004 270 24X Fiche: 50-000, 83/05/02, 8310310017

8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which repts are unavailable
FELTON, J M Division of Rules and Records 83/07/06 CONNER, L
Affiliation Unknown 1p 21004 271 24X Fiche: 50-000, 83/07/06, 8310310031

--8310310038 "Integrated Leak Rate Test Computer Program for Primary Containment"
* Power Authority of the State of New York. 74/03/20 100pp
21005 179 24X Fiche 50-000, 83/07/06, 8310310031

8310180531 FOIA request for Target Technology, Ltd documents re pipe supports
WEISS, E R Union of Concerned Scientists, 83/08/11 FELTON, J M
Division of Rules and Records 1p 20825 005 24X
Fiche 50-333, 83/08/11, 8310180531

DOCKETED ITEMS

201

8310180534 Responds to FOIA request for Target Technology, Ltd documents re pipe supports Forwards document encl Document also available in PDR
FELTON, J. M. Division of Rules and Records 83/09/06 WEISS, E. R
Union of Concerned Scientists 1p 20825 006 24X
Fiche 50-333, 83/09/06, 8310180534

--8310180538 Comments on pipe support design noncompliance w/FSAR
Summary of 830627 meeting w/8&W re list of 20 unacceptable supports submitted on 830103 discussed
DAINDORA, J. Target Technology Ltd 83/06/30 GUAGUIL, L. Power Authority of the State of New York 5pp 20825 007 24X
Fiche 50-333, 83/09/06, 8310180534

8310070084 Forwards safety evaluation of util response to NUREG-0737, Item II D 1, "Reliability Engineering" re safety & relief valve testing Requirements met Item resolved
VASSALLO, D. B. Operating Reactors Branch 2 83/09/22 BAYNE, J. P. Power Authority of the State of New York 17pp 20671 317 24X
Fiche 50-333, 83/09/22, 8310070084

831010112 Forwards Phase 1 response for Criteria 1, 2d, 3, 4, 11a & 11b of NUREG-0737, Item II B 3 re post-implementation review of util post-accident sampling sys Remaining responses will be submitted in 6 months
BAYNE, J. P. Power Authority of the State of New York 83/10/05 VASSALLO, D. B. Operating Reactors Branch 2 18pp 20667 278 24X
Fiche 50-333, 83/10/05, 831010112

8310140196 Forwards Rev 0 to "Plant-Unique Analysis Rept of Torus Suppression Chamber," Mark I containment program technical rept, per acceptance criteria in App A to NUREG-0661
BAYNE, J. P. Power Authority of the State of New York 83/10/11 VASSALLO, D. B. Operating Reactors Branch 2 1p 20762 084 24X
Fiche 50-333, 83/10/11, 8310140196

--8310140202 Rev 0 to "Plant-Unique Analysis Rept of Torus Suppression Chamber," Mark I containment program technical rept for James A. Fitzpatrick Nuclear Power Plant
* Teledyne Engineering Services TR-5321-1 R00 83/08/11 144pp 20762 086 24X Fiche 50-333, 83/10/11, 8310140196

8310310043 Forwards revised offsite dose calculation manual Primary changes reflect recalculated XQG/DOQ values & mod to calculation methodology
BAYNE, J. P. Power Authority of the State of New York 83/10/26 VASSALLO, D. B. Operating Reactors Branch 2 1p 20947:280 24X
Fiche 50-333, 83/10/26, 8310310043

--8310310046 Revised offsite dose calculation manual
* Power Authority of the State of New York 83/10/31 232pp 20947 281 24X Fiche 50-333, 83/10/26, 8310310043

Q Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/09/26 Consolidated Edison Co. of New York, Inc 117pp, 20754.022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/09/26 Consolidated Edison Co. of New York, Inc 116pp 20777:210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/09/26 Consolidated Edison Co. of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR30 59 Evaluation " Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716:324 24X Fiche 50-000, 83/09/29, 8308300349

8310190157 Forwards IE Insp Rept 50-333/83-18 on 830801-0905 No noncompliance noted
STAROSTECKI, R. Division of Project & Resident Programs 83/10/05 MCNEILL, C. A. Power Authority of the State of New York 2pp 20820 316 24X Fiche 50-333, 83/10/05, 8310190157

--8310190168 IE Insp Rept 50-333/83-18 on 830801-0905 No noncompliance noted Major areas inspected license action on previous insp findings, LER review, operational safety verification, review of plant operations & surveillance observations
DOERFLEIN, L. T. Region 1, Office of Director KISTER, H. B. Division of Project & Resident Programs 83/10/03 11pp 20820 318 24X Fiche 50-333, 83/10/05, 8310190157

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/10/07 Consolidated Edison Co. of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/10/07 Consolidated Edison Co. of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8310170480 Forwards Change 2 to Rev 3 to inservice insp program for pumps & valves, in accordance w/IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators "
BAYNE, J. P. Power Authority of the State of New York 83/10/07, VASSALLO, D. B. Operating Reactors Branch 2 6pp 20784 085, 24X Fiche 50-333, 83/10/07, 8310170480.

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases," Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/10/11 Consolidated Edison Co. of New York, Inc 117pp 21043.075 24X Fiche 50-000, 83/10/11, 8308300759.

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Bvc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/10/11 Consolidated Edison Co. of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310310364 Submits supplemental response to IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes "
BAYNE, J. P. Power Authority of the State of New York. 83/10/11, MURLEY, T. E. Region 1, Office of Director 2pp 20959:089 24X Fiche 50-333, 83/10/11, 8310310364

8310180551 Notification of 831021 meeting w/BWR licensees in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking.
MIRAGLIA, F. J. Assistant Director for Safety Assessment 83/10/14 EISENHUT, D. O. Division of Licensing 5pp 20823:358 24X _
Fiche 50-000, 83/10/14, 8310180551

R Periodic operating reports & related correspondence

8310120435 Monthly operating rept for Sept 1983 W/831006 ltr.
CODY, J., MCNEILL, C. A. Power Authority of the State of New York 83/09/30 NRC - No Detailed Affiliation Given 12pp, 20698:301 24X Fiche 50-333, 83/09/30, 8310120435

S Reportable occurrences, LERs & related correspondence

8310210329 Responds to FOIA request for all documents re significantly high rate of equipment failures for GE BWR/4 rated at 2,436 MW Forwards App A documents Documents also available in PDR
FELTON, J. M. Division of Rules and Records. 83/07/28 HAFNER, B. Suffolk Nuclear Study Group 2pp 20882 223 24X
Fiche: 50-000, 83/07/28, 8310210329

--8302020202 Summarizes evaluation of LERs for 1982 in support of upcoming BALP review Licensee performance adequate.
SEYFRIT, K. V. Reactor Operations Analysis Branch. 83/01/26 STAROSTECKI, R. Division of Project & Resident Programs 3pp 20882 254 24X Fiche 50-000, 83/07/28, 8310210329.

8310060089 Updated LER 83-023/01X-1 on 830607, water seepage discovered from weld in stainless steel pipe section of control rod hydraulic return line Control rod drive hydraulic return line cut & capped at vessel nozzle W/830908 ltr
FERNANDEZ, W., MCNEILL, C. A. Power Authority of the State of New York. 83/09/01, MURLEY, T. E. Region 1, Office of Director 2pp, 20647: 105 24X Fiche 50-333, 83/09/01, 8310060089

DOCKETED ITEMS

8310190150 LER 83-028/03L-0 on 830823, instrument 02-3-PS-528 setpoint found at 444 psig, below Tech Spec limit of 450 psig Caused by instrument drift Switch setpoint immediately adjusted & testing frequency increased W/830919 ltr
MCNEILL, C A Power Authority of the State of New York 83/09/19.
MURLEY, T E Region 1, Office of Director 2pp 20820 222 24X
Fiche 50-333, 83/09/19, 8310190150

8310190213 LER 83-032/03L-0 on 830903, during post-mod scram test at 30% rod density, two of four scram instrument val drain valves failed to close in specified time frame Caused by contact between handwheels & object W/830919 ltr
BERNSTEIN, B , MCNEILL, C A Power Authority of the State of New York
83/09/19 MURLEY, T E Region 1, Office of Director 3pp
20818 034 24X Fiche 50-333, 83/09/19, 8310190213

8310200134 LER 83-029/03L-0 on 830829, hydraulic snubber H12-94 (12-1-B-20) failed to lockup in compression when tested Caused by poppet spring lodged between compression poppet & seat. Modified valve assembly installed W/830921 ltr
MCNEILL, C A Power Authority of the State of New York 83/09/21
MURLEY, T E Region 1, Office of Director 2pp 20836 341 24X
Fiche 50-333, 83/09/21, 8310200134

8310190082 LER 83-034/03L-0 on 830906, during surveillance on average power range monitor C, downscale trip level setting found low Caused by instrument drift. Monitor adjusted Testing frequency increased W/830923 ltr
LINDSEY, D J , MCNEILL, C A Power Authority of the State of New York
83/09/23 MURLEY, T E Region 1, Office of Director 2pp
20822 268 24X Fiche 50-333, 83/09/23, 8310190082

8310070301 Potential Part 21 rept re underrange characteristic of Model N-E110M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERTAN, H J Foxboro Corp 83/09/30, Director's Office, Office of Inspection and Enforcement 1pp 20651, 064 24X
Fiche 50-000, 83/09/30, 8310070301

8310250412 LER 83-041/04T-0 on 830923, environ radiological monitoring sample revealed mollusks & periphyton exceeded 10 times control sample for Mn-54 & Co-60, respectively Caused by high bioaccumulation factor W/831005 ltr
SOLINI, J A , MCNEILL, C A Power Authority of the State of New York
83/10/05, MURLEY, T E Region 1, Office of Director 7pp
20897 247, 24X Fiche 50-333, 83/10/05, 8310250412

8310250585 LER 83-040/03L-0 on 830921, while performing valve lineup for sampling using post-accident sampling sys, containment hydrogen & oxygen return line & affected sys isolated Caused by failure to open solenoid operated valve W/831005 ltr
HERRMANN, T , MCNEILL, C A Power Authority of the State of New York
83/10/05, MURLEY, T E Region 1, Office of Director 3pp.
20901 253 24X Fiche 50-333, 83/10/05, 8310250585

8310250614 LER 83-037/03L-0 on 830915, while conducting surveillance testing on drywell high pressure switches for reactor protection & auto depressurization sys, setpoint found less conservative than Tech Specs Setpoint adjusted W/831005 ltr
MCNEILL, C A Power Authority of the State of New York 83/10/05.
MURLEY, T E Region 1, Office of Director 3pp 20900 269 24X
Fiche 50-333, 83/10/05, 8310250614.

8310310203 LER 83-033/03L-0 on 830905 & 07, during startup & ascension to power while inerting drywell, torus level fell below Tech Spec requirements Caused by water block in dry leg of level transmitter Dry leg vented W/831005 ltr.
MCNEILL, C A Power Authority of the State of New York. 83/10/05
MURLEY, T E Region 1, Office of Director 3pp 20958 329, 24X
Fiche 50-333, 83/10/05, 8310310203.

10140082 PND-1-83-105 on 831007, seismic event occurred in northeastern US w/magnitude of 5.2 on Richter scale in NY, 4.0 in NH No damage to equipment identified
ALLO, R. M Region 1, Office of Director 83/10/07 1p 20766 116
24X Fiche 50-000, 83/10/07, 8310140082

10250294 LER 83-036/03L-0 on 830914, during testing on high drywell pressure switches, ECCS actuation occurred, resulting in starting of core spray pumps A & B, MCP1, standby gas treatment sys & emergency diesel generators W/831014 ltr.
MCNEILL, C A Power Authority of the State of New York. 83/10/14
MURLEY, T E Region 1, Office of Director. 3pp. 20895 339, 24X
Fiche: 50-333, 83/10/14, 8310250294

DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8310040361 Forwards "Program Plan For Implementation of Control Room Design Review of Beaver Valley Power Station," following guidelines in Suppl 1 to NUREG-0737, per Generic Ltr 82-33
CAREY, J J Duquesne Light Co 83/09/29 EISENHUT, D G Division of Licensing 3pp 20622 165 24X Fiche 50-334, 83/09/27, 8310040361

--8310040569 "Program Plan For Implementation of Control Room Design Review of Beaver Valley Nuclear Power Station "
* Duquesne Light Co 83/09/27 88pp 20622 168 24X
Fiche 50-334, 83/09/27, 8310040561

8310140208 Forwards three-shift schedule for manning control room w/existing control room supervisory complement & list of addl personnel undergoing training Forms for addl personnel will be forwarded during wk of 831003
CAREY, J J Duquesne Light Co 83/09/29 MURLEY, T E Region 1, Office of Director 2pp 20762 338 24X Fiche 50-334, 83/09/29, 8310140208

8310180432 Forwards "Comparison of Beaver Valley Power Station Dose Projection Methodology vs NRC Interactive Rapid Dose Assessment Model," due to NRC reported dose projection results from recent emergency planning exercise
CAREY, J J Duquesne Light Co 83/10/03 VARQA, B A Operating Reactors Branch 1 3pp 20799 050 24X Fiche 50-334, 83/10/03, 8310180432

--8310180434 "Comparison of Beaver Valley Power Station Dose Projection Methodology vs NRC Interactive Rapid Dose Assessment Model "
LA VIE, S F Duquesne Light Co 83/08/31 41pp 20799 033 24X
Fiche 50-334, 83/10/03, 8310180432

8310200007 Forwards 1E Insp Repts 50-334/83-19 & 50-334/83-23 on 830816-0912 & 0922-23, respectively Enforcement conference scheduled for 831011, per 830926 telcon.
STAROSTECKI, R Division of Project & Resident Programs 83/10/03
CAREY, J J Duquesne Light Co 3pp 20837 012 24X
Fiche 50-334, 83/10/03, 8310200007

--8310200010 1E Insp Rept 50-334/83-19 on 830816-0912 Noncompliance noted failure to perform surveillance test within required time period & RHR sys inoperable
TROSKOSKI, W M , TRIPP, L E Region 1, Office of Director
83/09/29 17pp 20837 015 24X Fiche 50-334, 83/10/03, 8310200007

8310240146 Forwards emergency preparedness plan implementing procedures, Issue 7, Rev 2 W/o encl
EISEN, J D Duquesne Light Co 83/10/07 VARQA, B A Operating Reactors Branch 1. 2pp 20881 171 24X Fiche 50-334, 83/10/07, 8310240146

8310280140 Forwards notice of one-time exemption from schedular requirements of 10CFR50, App E, Section IV F, allowing annual emergency preparedness exercise to be conducted no later than 840630
VARQA, B A Operating Reactors Branch 1 83/10/12 CAREY, J J Duquesne Light Co 3pp 20965 077 24X Fiche 50-334, 83/10/12, 8310280140

--8310280142 Exemption from 10CFR50, App E, Section IV, F 1, allowing annual emergency preparedness exercise to be conducted no later than 840630
EISENHUT, D G Division of Licensing 83/10/12 Duquesne Light Co 3pp 20965 080 24X Fiche 50-334, 83/10/12, 8310280140

P Operating license stage documents & correspondence

8310120257 Forwards proposed rev to updated FBAR re reanalysis of LOCA radiological consequence analysis & supporting documentation set
CAREY, J J Duquesne Light Co 83/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director. 258pp 20691 052 24X
Fiche 50-334, 83/09/28, 8310120257

8310130188 Forwards Amend 72 to License DPR-66 & safety evaluation Amend clarifies intent of Amend 49 dtd 820330 adding two footnotes to Sections 3 7 12 & 4 7 12 re snubbers
TAM, P S Operating Reactors Branch 1 83/09/30 CAREY, J J Duquesne Light Co 3pp 20777 158 24X Fiche 50-334, 83/09/30, 8310130188

--8310130191 Amend 72 to License DPR-66, clarifying intent of Amend 49 dtd 820330 by adding two footnotes to Sections 3 7 12 & 4 7 12, Footnote 1 defines sys that require operable snubbers during Modes 5 & 6
VARQA, B A Operating Reactors Branch 1. 83/09/30 5pp
20777 161 24X Fiche 50-334, 83/09/30, 8310130188

DOCKETED ITEMS

203

--8310130195 Safety evaluation supporting Amend 72 to License DPR-66
* Office of Nuclear Reactor Regulation, Director 83/09/30 2pp
20777 166 24X Fiche 50-334,83/09/30,8310130188

8310140171 Forwards interim regulatory position re compliance
w/10CFR55.31(e) re reactor operator or senior reactor
operator requalification Plant manager or designee should
review each operator returning to licensed functions
STAROSTECKI,R Division of Project & Resident Programs 83/09/30
CAREY,J J Duquesne Light Co 4pp 20765 004 24X
Fiche 50-334,83/09/30,8310140171

8310210238 Forwards Rev 1 to "Reload Safety Evaluation,Beaver Valley
Nuclear Plant Unit 1,Cycle 4 "
CAREY,J J Duquesne Light Co 83/10/11 VAR0A,S A Operating
Reactors Branch 1 3pp 20852 017 24X Fiche 50-334,83/10/11,
8310210238

--8310210240 Rev 1 to "Reload Safety Evaluation,Beaver Valley Nuclear
Plant Unit 1,Cycle 4 "
PETRARCA,D J Duquesne Light Co 83/09/30 16pp 20852 020
24X Fiche 50-334,83/10/11,8310210238

8310210351 Requests remittal of addl fees due for 821123 & 830714
requests for Tech Spec change re safety-related hydraulic
snubbers & main feedwater piping, respectively
MILLER,W O License Fee Management Branch 83/10/14 CAREY,J J
Duquesne Light Co 1p 20882 361 24X Fiche 50-334,83/10/14,
8310210351

8310270154 Forwards response to 830828 request for addl info re N-1
loop operation Any asymmetries existing due to N-1 loop
operation have little or no impact on power distribution,DNB
limits & fuel integrity
CAREY,J J Duquesne Light Co 83/10/21 VAR0A,S A Operating
Reactors Branch 1 10pp 20924 142 24X Fiche 50-334,83/10/21,
8310270154

4 Inspection reports, IE Bulletins & correspondence

8310040400 Forwards two revised pages to "Reactor Vessel Inservice Insp
Refueling Outage Core 1-II Rept," submitted on 810205
CAREY,J J Duquesne Light Co 83/09/22 VAR0A,S A Operating
Reactors Branch 1 1p 20619 029 24X Fiche 50-334,83/09/22,
8310040400

--8310040411 Revised pages to "Reactor Vessel Inservice Insp Refueling
Outage Core 1-II Rept "
* Duquesne Light Co 83/09/22 3pp 20619 031 24X
Fiche 50-334,83/09/22,8310040400

8310060341 Forwards IE Enforcement Conference Rept 50-334/83-16
MARTIN,T T Division of Engineering & Technical Programs 83/09/22
CAREY,J J Duquesne Light Co 2pp 20646 131 24X
Fiche 50-334,83/09/22,8310060341

--8310060349 IE Enforcement Conference Rept 50-334/83-16 on 830901 Major
areas discussed actions of radiological controls personnel
during entry,use of untimely survey of radiation hazards &
responsibility of workers to maintain safety practices
MCBRIDE,M ; SHANBAKY,M Region 1, Office of Director 83/09/15
2pp 20646 133 24X Fiche 50-334,83/09/22,8310060341

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder
Qualification Tests " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 117pp 20794 022 24X Fiche 50-000,83/09/26,8308300340.

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
Detectors Positioned at Control Room Ventilation Air
Intakes " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse
Type SA-1 Differential Relays " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345.

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to
Safety-Related Sys W/o 10CFR50.59 Evaluation " Svc list
encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New
York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349.

8310200007 Forwards IE Insp Repts 50-334/83-19 & 50-334/83-23 on
830816-0912 & 0922-23, respectively Enforcement conference
scheduled for 831011,per 830926 telcon
STAROSTECKI,R Division of Project & Resident Programs 83/10/03
CAREY,J J Duquesne Light Co 3pp 20837 012 24X
Fiche 50-334,83/10/03,8310200007

--8310200010 IE Insp Rept 50-334/83-19 on 830816-0912 Noncompliance
noted failure to perform surveillance test within required
time period & RHR sys inoperable
TROSKOSKI,W M , TRIPP,L E Region 1, Office of Director
83/09/29 17pp 20837 015 24X Fiche 50-334,83/10/03,8310200007

--8310200021 IE Insp Rept 50-334/83-23 on 830922-23 Noncompliance noted:
Failure to follow administrative & managerial controls per
Tech Specs re river water sys
TROSKOSKI,W M , TRIPP,L E Region 1, Office of Director
83/09/29 7pp 20837 032 24X Fiche 50-334,83/10/03,8310200007

8310190246 Forwards IE Insp Rept 50-334/83-18 on 830822-26 No
noncompliance noted.
MARTIN,T T Division of Engineering & Technical Programs 83/10/05
CAREY,J J Duquesne Light Co 2pp 20818 121 24X
Fiche 50-334,83/10/05,8310190246

--8310190251 IE Insp Rept 50-334/83-18 on 830822-26 No noncompliance
noted Major areas inspected previous insp findings, personnel
qualifications,organization & administration,QA program
annual review,QA/QC program administration & audits
BISSETT,P H , SHAUB,E T Region 1, Office of Director,
CAPTAN,D L Division of Engineering & Technical Programs
83/09/30 7pp 20818 123 24X Fiche 50-334,83/10/05,8310190246

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass
Loops Used in Westinghouse Plants " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical
Facility " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect
Causes Production of Noxious Gases " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043:075 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective
Self-Contained Breathing Apparatus Air Cylinders " Svc list
encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827:129 24X Fiche 50-000,83/10/11,8308300761.

8310180316 Ack receipt of 830922 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-334/83-14
STAROSTECKI,R Division of Project & Resident Programs 83/10/11
CAREY,J J Duquesne Light Co 1p 20806 234 24X
Fiche 50-334,83/10/11,8310180316

--8310180322 Responds to NRC 830823 ltr re violations noted in IE Insp
Rept 50-334/83-14 Corrective actions river water header
expansion joints clearly tagged utilizing stainless steel
binding type tags
CAREY,J J Duquesne Light Co 83/09/22 STAROSTECKI,R Division
of Project & Resident Programs 2pp 20806:235 24X
Fiche 50-334,83/10/11,8310180316

8310270052 Discusses IE Insp Rept 50-334/83-16 on 830805 & forwards
notice of violation, Violation re occupational radiation
exposure categorized as Severity Level III Due to prompt
reporting, no civil penalty will be issued
MURLEY,T E Region 1, Office of Director 83/10/11 CAREY,J J,
Duquesne Light Co 3pp 20924 115 24X Fiche 50-334,83/10/11,
8310270052

--8310270058 Notice of violation from insp on 830805 Noncompliance noted:
radiation protection policies not properly implemented.
* Region 1, Office of Director. 83/10/11 2pp 20924 118 24X
Fiche 50-334,83/10/11,8310270052

R Periodic operating reports & related correspondence

8310190019 Monthly operating rept for Aug 1983 W/830907 ltr
HOLTZ,J L., CAREY,J J Duquesne Light Co 83/09/07 NRC - No
Detailed Affiliation Given 5pp 20822:034 24X
Fiche 50-334,83/09/07,8310190019

DOCKETED ITEMS

B Reportable occurrences, LERs & related correspondence

8310280010 Requests that LER 83-021/03L-0 be withdrawn based on investigation which revealed that surveillance test complies w/requisite actions for limiting condition for Tech Spec 3.7.9 re core reload
LACEY, W B Duquesne Light Co 83/09/29 ALLAN, J M Region 1, Office of Director 3pp 20934 104 24X Fiche 50-334, 83/09/29, 8310280010

8310060040 PND-1-83-098A strike of Intl Brotherhood of Electrical Workers possible after contract expires Union meeting to vote on licensee proposal set for 831005 Licensee contingencies in event of strike acceptable
TRIPP, L E Region 1, Office of Director 83/09/30 1p 20647 084 24X Fiche 50-334, 83/09/30, 8310060040

8310130395 Notification of Significant Licensee Meeting 83-82 on 831011 in King of Prussia, PA to discuss separate events in which RHR sys & svc water pump inoperable
TRIPP, L E Region 1, Office of Director 83/10/05 Region 1, Office of Director 1p 20770 354 24X Fiche 50-334, 83/10/05, 8310130395

8310250546 LER 83-022/03L-0 on 830907, flow rate of 36,056 cfm measured through train B filter bank caused by plugged prefilter
Prefilter replaced w/831007 ltr
LACEY, W B Duquesne Light Co 83/10/07 ALLAN, J M Region 1, Office of Director 4pp 20901 088 24X Fiche 50-334, 83/10/07, 8310250546

8310250595 LER 83-024/03L-0 on 830918, during core subcooling monitor surveillance test to check channel behavior, monitor found to be reading erroneously caused by loose connector within unit connector repaired w/831007 ltr
DRUGA, R J, LACEY, W B Duquesne Light Co 83/10/07 ALLAN, J M Region 1, Office of Director 4pp 20900 306 24X Fiche 50-334, 83/10/07, 8310250595

DOCKET 50-335 ST LUCIE PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8310060490 Releases public version of revised offnormal & emergency operating procedures
FELTON, J M Division of Rules and Records 83/09/22 Document Management Branch 1p 20650 299 24X Fiche 50-335, 83/09/22, 8310060490

--8310060492 Forwards public version of revised offnormal & emergency operating procedures, including Procedures 1-0910032 re auxiliary transformer offnormal operation & 2-1010030 re loss of instrument air
WETHY, C M Florida Power & Light Co 83/09/12 Director's Office, Office of Inspection and Enforcement 1p 20650 300 24X Fiche 50-335, 83/09/22, 8310060490

--8310060494 Public version of revised offnormal & emergency operating procedures, including Procedures 1-0910032 re auxiliary transformers offnormal operation & 2-1010030 re loss of instrument air
PETRIE, L Florida Power & Light Co 83/09/01 60pp 20650 301 24X Fiche 50-335, 83/09/22, 8310060490

8310250400 Forwards IE Insp Repts 50-335/83-30 & 50-389/83-58 on 830829-0902 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/10/05 UHRIG, R E Florida Power & Light Co 2pp 20897 236 24X Fiche 50-335, 83/10/05, 8310250400

--8310250409 IE Insp Repts 50-335/83-30 & 50-389/83-58 on 830829-0902 No noncompliance noted Major areas inspected: changes to emergency preparedness program, shift staffing & augmentation & dose calculations & assessments
HUFFMAN, O N, STODDART, P O Region 2, Office of Director JENKINS, O R Division of Engineering & Operational Programs 83/09/30 10pp 20897 258 24X Fiche 50-335, 83/10/05, 8310250400

8310170222 Forwards draft emergency operating procedure, "Alternate Shutdown" & indices "App R Cables w/Fire Area Routes" & "App R Equipment & Cables by Fire Area," per 10CFR50, App R, Section III G 3 requirements
UHRIG, R E Florida Power & Light Co 83/10/07 EISENHUT, D O Division of Licensing 9pp 20785 088 24X Fiche 50-335, 83/10/07, 8310170222

--8310170224 Draft emergency operating Procedure 1-0030142, "Alternate Shutdown"
* Florida Power & Light Co. 83/09/27 14pp. 20785 097 24X Fiche 50-335, 83/10/07, 8310170222

--8310170230 "App R Cables w/Fire Area Routes," for Florida Power & Light Co, St Lucie Nuclear Power Station
* Ebasco Services, Inc (subs of Enserch Corp) 83/09/28 104pp 20785 111 24X Fiche 50-335, 83/10/07, 8310170222

--8310170325 "App R Equipment & Cables by Fire Area," for Florida Power & Light Co, St Lucie Nuclear Power Station
* Ebasco Services, Inc (subs of Enserch Corp) 83/09/28 171pp 20785 218 24X Fiche 50-335, 83/10/07, 8310170222

P Operating license stage documents & correspondence

8310070182 Forwards Amend 61 to License DPR-67 & safety evaluation Amend revises limiting conditions for operations & surveillance requirements for 125-volt dc batteries in conjunction w/mods to sys
SELLS, D C Operating Reactors Branch 3 83/09/22 UHRIG, R E Florida Power & Light Co 2pp 20680 256 24X Fiche 50-335, 83/09/22, 8310070182

--8310070183 Amend 61 to License DPR-67, revising limiting conditions for operation & surveillance requirements for 125-volt dc batteries in conjunction w/mods to sys
MILLER, J R Operating Reactors Branch 3 83/09/22 5pp 20680 258 24X Fiche 50-335, 83/09/22, 8310070182

--8310070184 Safety evaluation supporting Amend 61 to License DPR-67
* NRC - No Detailed Affiliation Given 83/09/28 2pp 20680 265 24X Fiche 50-335, 83/09/22, 8310070182

831010483 Forwards safety evaluation re NUREG-0737, Item II B 3, "Post-Accident Sampling Sys (PASS)" Core damage estimate procedure including comparison of PASS data w/other plant parameters, should be provided item complete
MILLER, J R Operating Reactors Branch 3 83/09/28 UHRIG, R E Florida Power & Light Co 13pp 20714 328 24X Fiche 50-335, 83/09/28, 831010483

8310130397 Summary of 830922 meeting w/util, Exxon & C-E re organization & content of final rept being prepared for NRC review prior to restart Meeting to review entire final rept scheduled for mid-Dec Viewgraphs encl
SELLS, D C Operating Reactors Branch 3 83/10/05 Operating Reactors Branch 3 15pp 20771 012 24X Fiche 50-335, 83/10/05, 8310130397

8310310125 Forwards safety evaluation based on review of 820100 submittal adopting C-E Owners Group analysis on TMI Action Item II K 2 17, "Potential for Voiding in RCS During Transients" Analysis acceptable item complete
MILLER, J R Operating Reactors Branch 3 83/10/05 UHRIG, R E Florida Power & Light Co 9pp 20965 332 24X Fiche 50-335, 83/10/05, 8310310125

8310130009 Discusses reactor vessel internals & thermal shield & plant recovery program Outline of final rept of integrity & stability of internals w/o thermal shield, presented at 830922 meeting, encl info submittal dates listed
UHRIG, R E Florida Power & Light Co 83/10/06 MILLER, J R Operating Reactors Branch 3 15pp 20726 274 24X Fiche 50-335, 83/10/06, 8310130009

8310170088 Forwards Franklin Research Ctr "Operating Reactor PORV Repts (F-37) TMI Action Plan Requirements, C-E Owners Group (CEN-145)," technical evaluation rept & safety evaluation supporting responses to TMI Items II K 3 1 & II K 3 2
MILLER, J R Operating Reactors Branch 3 83/10/06 UHRIG, R E Florida Power & Light Co 3pp 20813 135 24X Fiche 50-335, 83/10/06, 8310170088

--8310170092 Safety evaluation supporting C-E licensee responses to NUREG-0737, Item II K 3 2, "Rept on PORVs"
* NRC - No Detailed Affiliation Given 83/10/06 62pp. 20813 138 24X Fiche 50-335, 83/10/06, 8310170088

8310180208 Application for amend to Licenses DPR-67 & NPF-16, revising facility organization chart & modifying definition of shift technical advisor function
WILLIAMS, J M Florida Power & Light Co 83/10/12 EISENHUT, D O Division of Licensing 3pp 20808 217 24X Fiche 50-335, 83/10/12, 8310180208

--8310180211 Proposed Tech Specs, revising facility organization chart & modifying definition of shift technical advisor function
Safety evaluation encl
* Florida Power & Light Co 83/10/12 4pp 20808 220 24X Fiche 50-335, 83/10/12, 8310180208

DOCKETED ITEMS

205

8310180254 Forwards Rev 5 to recovery plan listing post-core support barrel approximate repair flushing time Remaining info submittal dates listed Thermal shield failure analysis will be submitted by 831027
WILLIAMS, J W Florida Power & Light Co 83/10/13 MILLER, J R
Operating Reactors Branch 3 3pp 20802 341 24X
Fiche 50-335, 83/10/13, 8310180254

8310240140 Responds to 830916 telcon request for addl info on Franklin Research Ctr technical evaluation rept. Item 114 re Fisher & Porter pressure transmitter Transmitter inoperability will not affect safety sys if failure occurs
WILLIAMS, J W Florida Power & Light Co 83/10/19 MILLER, J R
Operating Reactors Branch 3 1p 20881 170 24X
Fiche 50-335, 83/10/19, 8310240140

8310270120 Provides amended safety evaluation & determination of no significant hazards in response to concerns re NSHC determination submitted w/830825 proposed license amend re peaking factor & load follow power peaking penalty
WILLIAMS, J W Florida Power & Light Co 83/10/21 EISENHUT, D G
Division of Licensing 3pp 20924 109 24X Fiche 50-335, 83/10/21, 8310270120

8310280082 Provides schedule for submittal of core damage assessment procedure, eleventh criterion of NUREG-0737, Item 11 B 3, "Post-Accident Sampling Sys." Procedure will be submitted prior to startup following Fall 1984 refueling outage
WILLIAMS, J W Florida Power & Light Co 83/10/25 MILLER, J R
Operating Reactors Branch 3 1p 20934 103 24X
Fiche 50-335, 83/10/25, 8310280082

8310280153 Forwards proprietary "Failure Mechanism Analysis Program" Rept withheld (ref 10CFR 9.314)
WILLIAMS, J W Florida Power & Light Co 83/10/25 MILLER, J R
Operating Reactors Branch 3 5pp 20929 276 24X
Fiche 50-335, 83/10/25, 8310280153

8310310015 Forwards Class I & Class II fees for 831012 application to amend Licenses DPR-67 & NPF-16 w/o encl
WILLIAMS, J W Florida Power & Light Co 83/10/26 EISENHUT, D G
Division of Licensing 1p 20947 105 24X Fiche 50-335, 83/10/26, 8310310015

Q Inspection reports, IE Bulletins & correspondence

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310040447 Forwards IE Insp Repts 50-335/83-27 & 50-389/83-52 on 830611-0710 No noncompliance noted.
DANCE, H C Division of Project & Resident Programs 83/09/14.
UHRIG, R E Florida Power & Light Co. 2pp 20625 285 24X
Fiche: 50-335, 83/09/14, 8310040447

--8310040454 IE Insp Repts 50-335/83-27 & 50-389/83-52 on 830611-0710 No noncompliance noted Major areas inspected maint & surveillance observations, plant operations, IE bulletins & circulars, LERs, BCR followup & PAB item followup
ELROD, S A, BIRB, H E Region 2, Office of Director JULIAN, C.
Division of Project & Resident Programs. 83/09/13 17pp
20625 287 24X Fiche 50-335, 83/09/14, 8310040447

8310040405 Confirms telcon re 831021 mgt meeting in Miami, FL to discuss results of first phase of BALP review for period Jul 1982 - June 1983 Proposed agenda encl
LEWIS, R C Division of Project & Resident Programs 83/09/22
UHRIG, R E Florida Power & Light Co 2pp 20619 092 24X
Fiche 50-000, 83/09/22, 8310040405

8310040458 Confirms 830916 decision to cancel NRC training assessment team 830926-30 Insp Util will be informed of reschedule date.
LEWIS, R C Division of Project & Resident Programs. 83/09/23
UHRIG, R E Florida Power & Light Co 1p 20623 324 24X
Fiche: 50-335, 83/09/23, 8310040458

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 117pp 20734 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8310250615 Forwards IE Insp Repts 50-335/83-31 & 50-389/83-59 on 830830-0902 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/27
UHRIG, R E Florida Power & Light Co 2pp 20900 167 24X
Fiche 50-335, 83/09/27, 8310250615

--8310250621 IE Insp Rept 50-335/83-31 & 50-389/83-59 on 830830-0902 No noncompliance noted Major areas inspected health physics instruments & equipment, GC audits, thermal shield disposal practices & actions on previous inspector followup items
WRAY, J R Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/09/23 5pp 20900 169 24X Fiche 50-335, 83/09/27, 8310250615

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR 50.59 Evaluation." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310250400 Forwards IE Insp Repts 50-335/83-30 & 50-389/83-58 on 830829-0902 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/10/05.
UHRIG, R E Florida Power & Light Co 2pp 20897 256 24X
Fiche 50-335, 83/10/05, 8310250400

--8310250409 IE Insp Repts 50-335/83-30 & 50-389/83-58 on 830829-0902 No noncompliance noted Major areas inspected changes to emergency preparedness program, shift staffing & augmentation & dose calculations & assessments
HUFFMAN, G N, STODDART, P O Region 2, Office of Director
JENKINS, O R Division of Engineering & Operational Programs 83/09/30 10pp 20897 258 24X Fiche 50-335, 83/10/05, 8310250400

8310250516 Forwards IE Insp Repts 50-335/83-28 & 50-389/83-55 on 830711-0810 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/10/06
UHRIG, R E Florida Power & Light Co 2pp 20901 310 24X
Fiche 50-335, 83/10/06, 8310250516

--8310250528 IE Insp Repts 50-335/83-28 & 50-389/83-55 on 830711-0810. No noncompliance noted Major areas inspected maint & surveillance observation, plant operations, IE bulletins, circulars & info notices, LERs & startup testing
ELROD, S A, BIRB, H E, LANDIS, K Region 2, Office of Director
83/10/04 11pp 20901 312 24X Fiche 50-335, 83/10/06, 8310250516

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752.

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp. 21043 075 24X Fiche 50-000, 83/10/11, 8308300759.

8308300761 IE Info Notice 83-68, "Respirator User Warning, Defective Self-Contained Breathing Apparatus Air Cylinders." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761.

R Periodic operating reports & related correspondence

8310190023 Monthly operating repts for Aug 1983 W/830915 ltr.
GRANT, N W, WILLIAMS, J W Florida Power & Light Co 83/09/13,
Office of Resource Management, Director. 17pp. 20822 017 24X
Fiche 50-000, 83/09/15, 8310190023

S Reportable occurrences, LERs & related correspondence

8310310458 Requests clarification of info provided in 820831 submittal re loss of all nonemergency ac power facility Response should be provided by 831115
MILLER, J R Operating Reactors Branch 3 83/10/12 UHRIG, R E
Florida Power & Light Co 2pp 20965 179 24X
Fiche: 50-335, 83/10/12, 8310310458

DOCKETED ITEMS

8310270531 Notification of 831108 meeting w/uttl in Bethesda, MD to discuss failure mode analysis associated w/thermal shield & core barrel damage at facility
SELLS, D E Operating Reactors Branch 3 83/10/13 MILLER, J R
Operating Reactors Branch 3 2pp 20738 026 24X
Fiche 50-336, 83/10/13, 8310270531

DOCKET 50-336 HILLSTONE NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8310060035 Forwards matl for 831005 emergency response exercise info needed for obtaining security & radiation protection clearances for NRC personnel requested by 830914. Exercise objectives for licensee encl w/o encl
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/08/08
MURLEY, T E Region 1, Office of Director 3pp 20647 245 24X
Fiche 50-245, 83/08/08, 8310060035

8310060205 Forwards draft exercise controller manual for upcoming 831005 full-scale emergency preparedness exercise info re NRC personnel participation & roles requested to allow inclusion in final manual w/o encl
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/08/22
MURLEY, T E Region 1, Office of Director 2pp 20647 035. 24X
Fiche 50-245, 83/08/22, 8310060205

8310120259 Forwards "Re-Entry & Recovery Scenario" section of emergency preparedness exercise controllers manual. Limited distribution requested, until completion of 831005 exercise.
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/09/27 MURLEY, T E Region 1, Office of Director 25pp 20693 145 24X Fiche 50-245, 83/09/27, 8310120259

J Insurance & indemnity information

8310270461 Forwards Endorsements 89 & 90 to NELIA Policy NF-173 & MAELU Policy NF-52, respectively. Endorsement 4 to NELIA Certificates NF-15 & NF-16 & MAELU Certificates NF-15 & NF-16
SINISI, J H Marsh & McLennan, Inc 83/10/21 SALTZMAN, J D
Assistant Director for State & License Relations 7pp 20923:126
24X Fiche 50-245, 83/10/21, 8310270461

P Operating license stage documents & correspondence

8310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in FDR
CONNER, L Affiliation Unknown 83/05/02 NRC - No Detailed Affiliation Given 1p 21004 270 24X Fiche 50-000, 83/05/02, 8310310017

8310110543 Forwards BER re util 791231, 810621 & 820602 responses to NUREG-0737, Item II.B.1, "RCB Vents" & "Selected Operating Reactor Issues Program II RCB Vents (NUREG-0737, Item II.B.1), " final technical evaluation rept
MILLER, J R Operating Reactors Branch 3 83/09/20 COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 11pp, 20712 180 24X Fiche 50-336, 83/09/20, 8310110543

--8306080065 "Selected Operating Reactor Issues Program II RCB Vents (NUREG-0737, Item II.B.1), " final technical evaluation rept
HELD, J T Energy Incorporated * Lawrence Livermore Laboratory
FIN A-0250 TF-349/0812A 83/03/02 ALBERTHAL, O NRC - No Detailed Affiliation Given 6pp 20712 191 24X
Fiche 50-336, 83/09/20, 8310110543

10110466 Forwards safety evaluation re util responses to NUREG-0737, Item II.K.3.1, "Automatic PORV Isolation," Item II.K.3.2, "Rept on PORVs" & OE Owners Group generic rept Review complete. Responses acceptable
MILLER, J R Operating Reactors Branch 3 83/09/23 COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 14pp 20712 114 24X Fiche 50-336, 83/09/23, 8310110466

8307200260 "Operating Reactor PORV Repts (F-37), TH1 Action Plan Requirements, C-E Owners Group (CEN-145)," technical evaluation rept
OVERBECK, G J, JENKINS, S M, DELGAIZO, T J Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-409
83/07/18 CHOW, E NRC - No Detailed Affiliation Given 52pp 20712:128 24X Fiche 50-336, 83/09/23, 8310110466

8310170656 Requests rev to confirmatory order contained in 830314 ltr for NUREG-0737 Items II.F.1.1 & II.F.1.2 to specify new 840101 completion date Replacement of Deiger-Mueller in detectors will be completed by 840101
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/09/27
MILLER, J R Operating Reactors Branch 3 2pp 20782 070 24X
Fiche 50-245, 83/09/27, 8310170656

8310130137 Approves 830731 request on behalf of C-E Owners Group for withholding from public disclosure App A to "Response to Questions on RCS Asymmetric Loads Evaluation Program," per 10CFR2 790
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/03
LUNDVALL, A E Baltimore Gas & Electric Co 6pp 20777 065 24X
Fiche 50-000, 83/10/03, 8310130137

8310170504 Application to amend License DPR-21 & DPR-65, revising Tech Spec Section 6 re administrative controls to comply w/final rule on licensed operator staffing at nuclear power units per 44FR31611
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/10/04
MILLER, J R Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 20784 137 24X Fiche 50-245, 83/10/04, 8310170504

--8310170508 Proposed Tech Spec Section 6 re administrative controls for licensed operator staffing & qualification of radiation protection manager
* Northeast Nuclear Energy Co (subs of Northeast Utilities)
83/10/04 8pp 20784 140 24X Fiche 50-245, 83/10/04, 8310170504

8310240103 Forwards Amend 88 to License DPR-65, safety evaluation & request for FR publication Amend modifies Tech Spec 3.1.2.2 to be consistent w/Tech Spec 3.5.2 requirements re boric acid tanks
LEECH, P H Operating Reactors Branch 3 83/10/07 COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 20903:176 24X Fiche 50-336, 83/10/07, 8310240103

--8310240108 Amend 88 to License DPR-65, modifying Tech Spec 3.1.2.2 to be consistent w/Tech Spec 3.5.2 requirements that both boric acid tanks & corresponding facility dependent flow paths are operable in modes in which operability required by ECCS
MILLER, J R Operating Reactors Branch 3 83/10/11 9pp 20903 178 24X Fiche 50-336, 83/10/07, 8310240103

--8310240109 Safety evaluation supporting Amend 88 to License DPR-65
* Office of Nuclear Reactor Regulation, Director 83/10/11 2pp, 20903 187 24X Fiche 50-336, 83/10/07, 8310240103

--8310240113 Requests FR publication of notice of consideration of issuance of amend to License DPR-65 & proposed NBHC determination & opportunity for hearing on 820924 request re operability of boric acid tanks
MILLER, J R Operating Reactors Branch 3 83/10/07 KREUTZER, P H Operating Reactors Branch 3 1p 20903 189 24X
Fiche 50-336, 83/10/07, 8310240103

8310180409 Forwards listed revs to "Corporate Organization for Nuclear Incidents (CONI) Procedure Manual," per Section V of App E to 10CFR50 w/o encl
COUNCIL, W O Connecticut Yankee Atomic Power Co COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNCIL, W O Northeast Utilities 83/10/12 EIBENHUT, D O Division of Licensing 1p 20803:173 24X Fiche 50-000, 83/10/12, 8310180409

8310200187 Requests addl time to provide info re 6-inch containment purge & vent valve operability. Info will be provided by 831026
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/10/12
MILLER, J R Operating Reactors Branch 3 1p, 20834 150 24X
Fiche 50-336, 83/10/12, 8310200187

8310200229 Application for amend to License DPR-65, revising Tech Specs re pressurizer level band
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/10/12
MILLER, J R Operating Reactors Branch 3, App. 20833 040 24X
Fiche 50-336, 83/10/12, 8310200229

--8310200233 Proposed Tech Specs re pressurizer level band.
* Northeast Nuclear Energy Co (subs of Northeast Utilities)
83/10/31 3pp 20833 044. 24X Fiche 50-336, 83/10/12, 8310200229

8310280112 Denies 830906 request for 120-day extension to respond to Generic Ltr 83-2B re generic implications of Salem ATWS events NRC review schedule does not permit extension Response due by 831105
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/26 COUNCIL, W O Connecticut Yankee Atomic Power Co COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 20929 261 24X Fiche 50-000, 83/10/26, 8310280112

Q Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

R Periodic operating reports & related correspondence

8310190207 Monthly operating rept for Aug 1983 W/830915 ltr
OIBSON, J, MROCKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCKA, E J Northeast Utilities 83/09/14 Office of Resource Management, Director 7pp 20818 114 24X Fiche 50-336, 83/09/14, 8310190207

8310200167 Monthly operating rept for Sept 1983 W/831014 ltr
OIBSON, J, MROCKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/10/13 Office of Resource Management, Director 7pp 20834 071 24X Fiche 50-336, 83/10/13, 8310200167

S Reportable occurrences, LERs & related correspondence

8310070163 Part 21 rept re potential defects in molded case of 100-amp frame, multi-pole E & HE series circuit breakers Initially reported on 830902
ERHARDT, J V Gavid, Inc 83/09/26 MURLEY, T E Region 1, Office of Director 10pp 20659 095 24X Fiche 50-000, 83/09/26, 8310070163

8310070301 Potential Part 21 rept re underrange characteristic of Model N-5110M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X Fiche 50-000, 83/09/30, 8310070301

8310240269 Responds to 830906 memo re AEOO/T314: "Improper Size of Inlet Piping to Primary Safety Valves at Millstone 2 & Calvert Cliffs 1 & 2 " Flow limiting devices for code safety valves 1 7/8-inch bore diameter discussed
EISENHUT, D C Division of Licensing 83/10/18 THOMPSON, H L Division of Human Factors Safety 1p 20707 338 24X Fiche 50-000, 83/10/18, 8310240269

DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8310040252 Forwards technical support ctr & emergency operations Facility floor plans, route maps to emergency response Facilities & telephone listings Requests update of info & submittal of personnel access documents
DANCE, H C Division of Project & Resident Programs 83/09/12 STEWART, W L Virginia Electric & Power Co 16pp 20613 049 24X Fiche 50-000, 83/09/12, 8310040252

8310070403 Releases public version of revised corporate emergency response plan
FELTON, J M Division of Rules and Records 83/09/30 Document Management Branch 1p 20675 182 24X Fiche 50-000, 83/09/30, 8310070403

--8310070418 Public version of revised corporate emergency response plan.
W/830614 ltr
STEWART, W L Virginia Electric & Power Co 83/05/15 O'REILLY, J P Region 2, Office of Director 114pp 20675 183, 24X Fiche 50-000, 83/09/30, 8310070403

8310110186 Releases public version of radiological emergency response plan
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20701 020 24X Fiche 50-000, 83/10/05, 8310110186

--8310110190 Public version of radiological emergency response plan
W/830621 ltr
* Virginia Electric & Power Co 83/06/30 O'REILLY, J P Region 2, Office of Director 301pp 20701 021, 24X Fiche 50-000, 83/10/05, 8310110186

8310180277 Forwards changes to security program Changes withheld (ref 10CFR73 21).
STEWART, W L Virginia Electric & Power Co 83/10/06 MCQUIRE, D R Division of Emergency Preparedness & Materials Safety 1p 20807 035 24X Fiche 50-338, 83/10/06, 8310180277

8310130103 Application for amend to Licenses NPF-4 & NPF-7 changing Tech Specs to reflect addition of new fire protection sys
STEWART, W L Virginia Electric & Power Co 83/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 3pp 20719 126 24X Fiche 50-338, 83/10/07, 8310130103

--8310130107 Proposed Tech Spec changes to reflect addition of new fire protection sys
* Virginia Electric & Power Co 83/10/07 15pp 20719 130 24X Fiche 50-338, 83/10/07, 8310130103

Q Adjudicatory correspondence

8310190200 Updates status of full core reserve at facility. Full core reserve will be lost during outage scheduled for early 1984 if fuel performs properly during future operating cycles.
MAUPIN, M W Hutton & Williams MAUPIN, M W Virginia Electric & Power Co 83/10/13 WOLFE, S J Atomic Safety and Licensing Board Panel 3pp 20818 135 24X Fiche 50-338, 83/10/13, 8310190200

8310240163 Ack receipt of 831013 ltr updating status of full-core reserve & indicating possible agreement w/DOE re dry cask demonstration program Notification of efforts to expedite case disposition requested by 831104
WOLFE, S J Atomic Safety and Licensing Appeal Panel 83/10/20 MAUPIN, M W Hutton & Williams 1p 20880 038 24X Fiche 50-338, 83/10/20, 8310240163

8310260299 Summarizes 831012 meeting w/NRC, util & Louisa County re Louisa County contentions Mutually agreeable proceeding schedule recommended following publication of environ analysis & EER Related correspondence
MAUPIN, M W Hutton & Williams MAUPIN, M W Virginia Electric & Power Co 83/10/20 WOLFE, S J Atomic Safety and Licensing Board Panel 2pp 20910 322 24X Fiche 50-338, 83/10/20, 8310260299

DOCKETED ITEMS

8310270317 Order extending time for Commission review of ALAB-741 to 831108
CHILK, S J Office of the Secretary of the Commission 83/10/25
Commissioners 1p 20923 188 24X Fiche: 50-338, 83/10/25, 8310270317

8310270326 Order accepting, as amended, recommendations by counsel re stipulated contentions & discovery schedule.
WOLFE, S J Atomic Safety and Licensing Board Panel 83/10/25 2pp
20923, 180 24X Fiche 50-338, 83/10/25, 8310270326

M Antitrust correspondence

8310200289 Suppl to 830310 application to amend Licenses NPF-4 & NPF-7, adding name of Old Dominion Electric Cooperative in appropriate OL sections. Cooperative will be partial owner of facilities Supporting documentation encl
STEWART, W L Virginia Electric & Power Co 83/10/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 524pp. 20831 159 24X
Fiche 50-338, 83/10/17, 8310200289

P Operating license stage documents & correspondence

8310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR
CONNOR, L Affiliation Unknown. 83/05/02 NRC - No Detailed
Affiliation Given 1p 21004 270 24X Fiche 50-000, 83/05/02, 8310310017

8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which repts are unavailable.
FELTON, J M Division of Rules and Records 83/07/06 CONNER, L
Affiliation Unknown 1p 21004 271. 24X Fiche. 50-000, 83/07/06, 8310310031

8310040587 Application for amend to Licenses NPF-4 & NPF-7, changing fractional thermal power multiplier from 0.2 to 0.3 for 587 B F operation
STEWART, W L Virginia Electric & Power Co 83/09/29. DENTON, H R.
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 11pp 20626 262 24X
Fiche: 50-338, 83/09/29, 8310040587

--8310040590 Proposed Tech Specs changing fractional thermal power multiplier from 0.2 to 0.3 for 587 B F operation
* Virginia Electric & Power Co 83/09/29. 12pp 20626 273 24X
Fiche 50-338, 83/09/29, 8310040587

8310120114 Advises that extension until 831007 required to complete review & approval of proposed inservice testing program for pumps & valves
STEWART, W L Virginia Electric & Power Co 83/10/04. DENTON, H R.
Office of Nuclear Reactor Regulation, Director MILLER, J R.
Operating Reactors Branch 3 1p. 20696 150 24X
Fiche. 50-338, 83/10/04, 8310120114

8310130145 Application for amend to Licenses NPF-4 & NPF-7 adding exemption which allows engineering evaluation to be performed if failure occurs on steam generator/reactor coolant pump support snubber. Amend fee encl.
STEWART, W L Virginia Electric & Power Co 83/10/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3. 4pp 20749 040 24X
Fiche 50-338, 83/10/04, 8310130145

--8310130148 Proposed Tech Specs adding exemption to allow performance of engineering evaluation if failure occurs on steam generator/reactor coolant pump support snubber to determine if generic deficiencies exist.
* Virginia Electric & Power Co. 83/10/04 49pp 20749 044. 24X
Fiche: 50-338, 83/10/04, 8310130145.

8310120140 Forwards revised inservice testing program for pumps & valves Revs clarify component listings & relief requests Programs will be fully implemented by 840301 W/o encl
STEWART, W L Virginia Electric & Power Co 83/10/05 DENTON, H R.
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3. 2pp. 20695: 279. 24X
Fiche: 50-338, 83/10/05, 8310120140.

310130103 Application for amend to Licenses NPF-4 & NPF-7 changing Tech Specs to reflect addition of new fire protection sys
STEWART, W L Virginia Electric & Power Co. 83/10/07. DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R.
Operating Reactors Branch 3. 3pp. 20719 126. 24X
Fiche: 50-338, 83/10/07, 8310130103

--8310130107 Proposed Tech Spec changes to reflect addition of new fire protection sys
* Virginia Electric & Power Co 83/10/07 15pp 20719 130 24X
Fiche 50-338, 83/10/07, 8310130103

8310180440 Requests extension to 840601 for submittal of simulator portion of licensed operator requalification program
STEWART, W L Virginia Electric & Power Co 83/10/12 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 2pp 20802 124 24X
Fiche 50-338, 83/10/12, 8310180440

8310190112 Application to amend Licenses NPF-4 & NPF-7, reflecting reorganization in nuclear operations dept, security dept & change in responsibilities & title of executive vice president-power
STEWART, W L Virginia Electric & Power Co 83/10/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 3pp 20821 104 24X
Fiche 50-338, 83/10/13, 8310190112

--8310190130 Proposed Tech Spec changes re reorganization in nuclear operations dept, security dept & responsibilities & title of executive vice president-power
* Virginia Electric & Power Co 83/10/13 15pp 20821 107 24X
Fiche 50-338, 83/10/13, 8310190112

8310180309 Forwards status rept of progress on resolving rotating motor operated valves (MOV) & plan for addl work per ODC 17, committed to in 830607 ltr Preliminary review determined 74 of 130 MOVs will not need to operate when voltage below 90%
STEWART, W L Virginia Electric & Power Co 83/10/14 DENTON, H R
MILLER, J R Operating Reactors Branch 3 4pp 20806 291 24X
Fiche 50-338, 83/10/14, 8310180309

8310190043 Forwards "VEPCO NOMAD Code & Model " Rept is one of series discussing nuclear reload licensing & core follow support capabilities
STEWART, W L Virginia Electric & Power Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 2pp 20822 335 24X Fiche 50-000, 83/10/14, 8310190043

--8310190057 "VEPCO NOMAD Code & Model "
BOHMAN, S M, DZIADOSZ, D, BERRYMAN, R M Virginia Electric & Power Co
VEP-NFE-1 83/09/30 118pp 20822 337 24X
Fiche 50-000, 83/10/14, 8310190043

8310200289 Suppl to 830310 application to amend Licenses NPF-4 & NPF-7, adding name of Old Dominion Electric Cooperative in appropriate OL sections. Cooperative will be partial owner of facilities Supporting documentation encl.
STEWART, W L Virginia Electric & Power Co 83/10/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 524pp 20831 159. 24X
Fiche 50-338, 83/10/17, 8310200289

8310270300 Suppl 830325 response to 830111 request for addl info re NUREG-0737, item 11 B 3, "Post-Accident Sampling " Interim core damage assessment procedure in use until Westinghouse Owners Group methodology completed by end of 1983
STEWART, W L Virginia Electric & Power Co 83/10/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 2pp 20923, 193 24X Fiche 50-000, 83/10/20, 8310270300

G Inspection reports, IE Bulletins & correspondence

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310040550 Responds to IE Bulletin 83-06, "Nonconforming Metals Supplied by Tube Line Corp Facilities " No subj metals in use in safety-related sys
STEWART, W L Virginia Electric & Power Co 83/09/16 O'REILLY, J P
Region 2, Office of Director 1p 20622, 314 24X
Fiche 50-338, 83/09/16, 8310040550.

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 117pp 20754 022. 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/09/26 Consolidated Edison Co. of New York, Inc 116pp. 20777 210 24X Fiche. 50-000, 83/09/26, 8308300342

DOCKETED ITEMS

209

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310250414 Forwards IE Insp Repts 50-338/83-22 & 50-339/83-22 on 830815-19 & 0917-20 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/10/05
STEWART, W L Virginia Electric & Power Co 2pp 20897 227 24X Fiche 50-338, 83/10/05, 8310250414

--8310250428 IE Insp Repts 50-338/83-22 & 50-339/83-22 on 830815-19 & 0917-20 No noncompliance noted Major areas inspected liquid & gaseous effluent releases, effluent control instrumentation, reactor coolant water quality & NUREG-0737
HARRY, J R Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs, 83/09/30 9pp 20897, 229 24X Fiche 50-338, 83/10/05, 8310250414

8310250508 Responds to 830628 ltr requesting deletion of Violation B noted in IE Insp Repts 50-338/83-12 & 50-339/83-12 re radiation area posting of auxiliary bldg Entrance not properly posted Citation stands Present posting adequate
O'REILLY, J P Region 2, Office of Director 83/10/06 STEWART, W L Virginia Electric & Power Co 2pp 20902 071 24X Fiche 50-338, 83/10/06, 8310250508

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-64, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827, 129 24X Fiche 50-000, 83/10/11, 8308300761

R Periodic operating reports & related correspondence

8310190002 Monthly operating repts for Aug 1983 W/830915 ltr
SCHMITTENDORF, G, STEWART, W L Virginia Electric & Power Co 83/09/02 HALLER, N M Office of Resource Management, Director 14pp 20823 095 24X Fiche 50-338, 83/09/02, 8310190002

B. Reportable occurrences, LFRs & related correspondence

8310070328 LER 83-057/03L-0 on 830903 & 12, Fire Door 871-19 between emergency diesel Room 1H & turbine bldg would not latch
Caused by faulty latching mechanism & misalignment Latch repaired & realigned W/830928 ltr
HARRELL, E W Virginia Electric & Power Co 83/09/28 O'REILLY, J P Region 2, Office of Director 2pp, 20652 224 24X Fiche 50-338, 83/09/28, 8310070328

8310070301 Potential Part 21 rept re underrange characteristic of Model N-E11QM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 044 24X Fiche: 50-000, 83/09/30, 8310070301

8310140161 LER 83-058/03L-0 on 830808, incorrect alignment of charging high head safety injection pump breakers & control switches discovered Caused by inadequate procedural guidance
Alignment corrected W/831005 ltr
HARRELL, E W Virginia Electric & Power Co, 83/10/05 O'REILLY, J P Region 2, Office of Director, 3pp 20765 090 24X Fiche: 50-338, 83/10/05, 8310140161

8310170091 Forwards repts on 821205 main generator failure & proprietary & nonproprietary repts on seven main transformer failures occurring between 801129 & 821205 Proprietary rept withheld (ref 10CFR2 790)
STEWART, W L Virginia Electric & Power Co 83/10/05 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 2pp 20789 207 24X Fiche 50-338, 83/10/05, 8310170091

--8310170098 "Generator Rept on VEPCO North Anna Unit 1 Transformer Incident of 821205 "
WEYANT, P A, BALDWIN, M B, WARD, R T Virginia Electric & Power Co 83/10/05 14pp 20789 209 24X Fiche 50-338, 83/10/05, 8310170091

--8310170107 Nonproprietary version of "Transformer Rept on Events at North Anna Power Station "
COSSAART, J, PETRIE, E, SKODOLUND, J Westinghouse Electric Corp 83/06/16 274pp 20789 226 24X Fiche 50-338, 83/10/05, 8310170091

8310140082 PNO-I-83-i05 on 831007, seismic event occurred in northeastern US w/magnitude of 5.2 on Richter scale in NY & 4.0 in NH No damage to equipment identified
GALLO, R H, GREENMAN, E O Region 1, Office of Director 83/10/07 1p 20766 116 24X Fiche 50-000, 83/10/07, 8310140082.

8310210058 LER 83-059/03L-0 on 830918, while at 100% power, inner seal on containment personnel hatch failed to pass periodic test following containment entry Caused by dirt buildup on seal
Seal cleaned, relubricated & tested W/831013 ltr
HARRELL, E W Virginia Electric & Power Co 83/10/13 O'REILLY, J P Region 2, Office of Director, 2pp 20855 266 24X Fiche 50-338, 83/10/13, 8310210058

DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8310040292 Forwards technical support ctr & emergency operations facility floor plans, route maps to emergency response facilities & telephone listings Requests update of info & submittal of personnel access documents
DANCE, H C Division of Project & Resident Programs 83/09/12 STEWART, W L Virginia Electric & Power Co 14pp 20613 049, 24X Fiche 50-000, 83/09/12, 8310040292

8310070403 Releases public version of revised corporate emergency response plan
FELTON, J M Division of Rules and Records 83/09/30 Document Management Branch 1p 20675 182 24X Fiche 50-000, 83/09/30, 8310070403

--8310070418 Public version of revised corporate emergency response plan, W/830614 ltr
STEWART, W L Virginia Electric & Power Co 83/05/15 O'REILLY, J P Region 2, Office of Director 114pp 20675 183, 24X Fiche 50-000, 83/09/30, 8310070403

8310110186 Releases public version of radiological emergency response plan
FELTON, J M Division of Rules and Records 83/10/03 Document Management Branch 1p 20701 020 24X Fiche: 50-000, 83/10/03, 8310110186

--8310110190 Public version of radiological emergency response plan W/830621 ltr
* Virginia Electric & Power Co 83/06/30 O'REILLY, J P Region 2, Office of Director 301pp 20701 021 24X Fiche 50-000, 83/10/03, 8310110186

8310180277 Forwards changes to security program Changes withheld (ref 10CFR73 21)
STEWART, W L Virginia Electric & Power Co 83/10/06 MCQUIRE, D R Division of Emergency Preparedness & Materials Safety, 1p 20807 035 24X Fiche 50-338, 83/10/06, 8310180277

8310130103 Application for amend to Licenses NPF-4 & NPF-7 changing Tech Specs to reflect addition of new fire protection sys
STEWART, W L Virginia Electric & Power Co 83/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director, 3pp, 20719 126 24X Fiche: 50-338, 83/10/07, 8310130103

--8310130107 Proposed Tech Spec changes to reflect addition of new fire protection sys
* Virginia Electric & Power Co 83/10/07 15pp, 20719 130 24X Fiche 50-338, 83/10/07, 8310130103

DOCKETED ITEMS

G Adjudicatory correspondence

8310190200 Updates status of full core reserve at Facility Full core reserve will be lost during outage scheduled for early 1986 if fuel performs properly during future operating cycles MAUPIN, M W Hutton & Williams MAUPIN, M W Virginia Electric & Power Co 83/10/13 WOLFE, S J Atomic Safety and Licensing Board Panel 3pp 20818 135 24X Fiche 50-338, 83/10/13, 8310190200

8310240163 Ack receipt of 831013 ltr updating status of full-core reserve & indicating possible agreement w/DOE re dry cask demonstration program Notification of efforts to expedite case disposition requested by 831104 WOLFE, S J Atomic Safety and Licensing Appeal Panel 83/10/20 MAUPIN, M W Hutton & Williams 1p 20880 038 24X Fiche 50-338, 83/10/20, 8310240163

8310260299 Summarizes 831012 meeting w/NRC, util & Louisa County re Louisa County contentions. Mutually agreeable proceeding schedule recommended following publication of environ analysis & SER. Related correspondence. MAUPIN, M W Hutton & Williams MAUPIN, M W Virginia Electric & Power Co 83/10/20 WOLFE, S J Atomic Safety and Licensing Board Panel 2pp 20910 322 24X Fiche 50-338, 83/10/20, 8310260299

8310270317 Order extending time for Commission review of ALAB-741 to 831108 CHILK, S J Office of the Secretary of the Commission 83/10/25 Commissioners. 1p 20923 188 24X Fiche 50-338, 83/10/25, 8310270317.

8310270326 Order accepting, as amended, recommendations by counsel re stipulated contentions & discovery schedule WOLFE, S J Atomic Safety and Licensing Board Panel 83/10/25 2pp. 20923 180 24X Fiche 50-338, 83/10/25, 8310270326.

H Antitrust correspondence

8310200289 Suppl to 830310 application to amend Licenses NPF-4 & NPF-7, adding name of Old Dominion Electric Cooperative in stipulated conditions & discovery schedule appropriate OL sections Cooperative will be partial owner of facilities. Supporting documentation encl STEWART, W L Virginia Electric & Power Co 83/10/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 524pp 20831 159 24X Fiche 50-338, 83/10/17, 8310200289

P Operating license stage documents & correspondence

8310120016 Addl response to FOIA request for document re problems w/ Tech Specs applying to RCS leakage determinations in PWRs Forwards App A documents FELTON, J M Division of Rules and Records 83/07/07. VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 2pp. 20751 001 24X Fiche 50-000, 83/07/07, 8310120016

--8007290663 Forwards SER suppl. Revision 1, re periodic leak testing of pressure isolation valves Replaces 800702 transmittal HUNGH, J P Assistant Director for Comp & Structures Engineering (Pre 830201). 80/07/16 TEOBECO, R L Assistant Director for Licensing 1p 20751 043, 24X Fiche 50-000, 83/07/07, 8310120016

--8007290676 SER suppl. Revision 1, re periodic leak testing of pressure isolation valves Additions to Tech Specs acceptable. * Assistant Director for Comp & Structures Engineering (Pre 830201) 80/07/16 3pp 20751 044 24X Fiche 50-000, 83/07/07, 8310120016.

8310030625 Advises of refund of fees sent for review of 830418 application for extension to complete License Condition 2.C(21)(i)(iv) Fees refunded since application no longer applicable & will not be received. MILLER, W O License Fee Management Branch 83/09/27. STEWART, W L Virginia Electric & Power Co 1p 20407 360 24X Fiche: 50-339, 83/09/27, 8310030625

8310040587 Application for amend to Licenses NPF-4 & NPF-7, changing fractional thermal power multiplier from 0.2 to 0.3 for 587.8 F operation. STEWART, W L Virginia Electric & Power Co. 83/09/29. DENTON, H R Office of Nuclear Reactor Regulation, Director. MILLER, J R Operating Reactors Branch 3 11pp 20626 262. 24X Fiche. 50-338, 83/09/29, 8310040587.

8310040590 Proposed Tech Specs changing fractional thermal power multiplier from 0.2 to 0.3 for 587.8 F operation * Virginia Electric & Power Co. 83/09/29 12pp 20626 273. 24X Fiche. 50-338, 83/09/29, 8310040587

8310120114 Advises that extension until 831007 required to complete review & approval of proposed inservice testing program for pumps & valves STEWART, W L Virginia Electric & Power Co 83/10/04 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 1p 20696 150 24X Fiche 50-338, 83/10/04, 8310120114

8310130145 Application for amend to Licenses NPF-4 & NPF-7 adding exemption which allows engineering evaluation to be performed if failure occurs on steam generator/reactor coolant pump support snubber Amend Fee encl STEWART, W L Virginia Electric & Power Co 83/10/04 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 4pp 20749 040 24X Fiche 50-338, 83/10/04, 8310130145

--8310130148 Proposed Tech Specs adding exemption to allow performance of engineering evaluation if failure occurs on steam generator/reactor coolant pump support snubber to determine if generic deficiencies exist * Virginia Electric & Power Co 83/10/04 49pp 20749 044 24X Fiche 50-338, 83/10/04, 8310130145

8310120140 Forwards revised inservice testing program for pumps & valves Rev clarify component listings & relief requests Programs will be fully implemented by 840301 W/o encl STEWART, W L Virginia Electric & Power Co 83/10/05 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 2pp 20695 279 24X Fiche 50-338, 83/10/05, 8310120140

8310130103 Application for amend to Licenses NPF-4 & NPF-7 changing Tech Specs to reflect addition of new fire protection sys STEWART, W L Virginia Electric & Power Co 83/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 3pp 20719 126 24X Fiche 50-338, 83/10/07, 8310130103

--8310130107 Proposed Tech Spec changes to reflect addition of new fire protection sys. * Virginia Electric & Power Co 83/10/07 15pp 20719 130 24X Fiche 50-338, 83/10/07, 8310130103

8310180440 Requests extension to 840601 for submittal of simulator portion of licensed operator requalification program STEWART, W L Virginia Electric & Power Co 83/10/12 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 2pp 20802 124 24X Fiche 50-338, 83/10/12, 8310180440

8310190112 Application to amend Licenses NPF-4 & NPF-7, reflecting reorganization in nuclear operations dept, security dept & change in responsibilities & title of executive vice president-power STEWART, W L Virginia Electric & Power Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 3pp 20821 104 24X Fiche 50-338, 83/10/13, 8310190112

--8310190130 Proposed Tech Spec changes re reorganization in nuclear operations dept, security dept & responsibilities & title of executive vice president-power * Virginia Electric & Power Co 83/10/13 15pp 20821 107 24X Fiche 50-338, 83/10/13, 8310190112

8310180309 Forwards status rept of progress on resolving rotating motor operated valves (MOV) & plan for addl work per ODC 17, committed to in 830607 ltr Preliminary review determined 74 of 130 MOVs will not need to operate when voltage below 90% STEWART, W L Virginia Electric & Power Co 83/10/14 DENTON, H R MILLER, J R Operating Reactors Branch 3 4pp 20806 291 24X Fiche 50-338, 83/10/14, 8310180309

8310190043 Forwards "VEPCO NOMAD Code & Model " Rept is one of series discussing nuclear reload licensing & core follow support capabilities STEWART, W L Virginia Electric & Power Co 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20822 335 24X Fiche 50-000, 83/10/14, 8310190043

--8310190057 "VEPCO NOMAD Code & Model " BOWMAN, S M Virginia Electric & Power Co. VEP-NFE-i 83/09/30 118pp 20822 337 24X Fiche 50-000, 83/10/14, 8310190043

8310200289 Suppl to 830310 application to amend Licenses NPF-4 & NPF-7, adding name of Old Dominion Electric Cooperative in appropriate OL sections Cooperative will be partial owner of facilities Supporting documentation encl STEWART, W L Virginia Electric & Power Co 83/10/17 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3. 524pp 20831 159 24X Fiche. 50-338, 83/10/17, 8310200289

DOCKETED ITEMS

211

8310270300 Supplis 830323 response to 830111 request for addl info re NUREG-0737, Item II B 3, "Post-Accident Sampling " Interim core damage assessment procedure in use until Westinghouse Owners Group methodology completed by end of 1983
STEWART, W L Virginia Electric & Power Co 83/10/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20923 193
24X Fiche 50-000, 83/10/20, 8310270300

G Inspection reports, IE Bulletins & correspondence

8310040550 Responds to IE Bulletin 83-06, "Nonconforming Matls Supplied by Tube Line Corp Facilities " No subj matls in use in safety-related sys
STEWART, W L Virginia Electric & Power Co 83/09/16 O'REILLY, J P
Region 2, Office of Director 1p 20622 314 24X
Fiche 50-338, 83/09/16, 8310040550

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20794 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310250414 Forwards IE Insp Repts 50-338/83-22 & 50-339/83-22 on 830815-19 & 0919-20 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/10/05
STEWART, W L Virginia Electric & Power Co 2pp 20897 227 24X
Fiche 50-338, 83/10/05, 8310250414

--8310250428 IE Insp Repts 50-338/83-22 & 50-339/83-22 on 830815-19 & 0919-20 No noncompliance noted Major areas inspected liquid & gaseous effluent releases, effluent control instrumentation, reactor coolant water quality & NUREG-0737
WRAY, J R Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/09/30 9pp 20897 229 24X Fiche 50-338, 83/10/05, 8310250414

8310250508 Responds to 830628 ltr requesting deletion of Violation B noted in IE Insp Repts 50-338/83-12 & 50-339/83-12 re radiation area posting of auxiliary bldg Entrance not properly posted Citation stands Present posting adequate
O'REILLY, J P Region 2, Office of Director 83/10/06 STEWART, W L
Virginia Electric & Power Co 2pp 20902 071 24X
Fiche 50-338, 83/10/06, 8310250508

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 073 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

R Periodic operating reports & related correspondence

8310190002 Monthly operating repts for Aug 1983 W/830915 ltr
SCHMITENDORF, G, STEWART, W L Virginia Electric & Power Co
83/09/02 HALLER, N M Office of Resource Management, Director
14pp 20823 095 24X Fiche 50-338, 83/09/02, 8310190002

S Reportable occurrences, LERs & related correspondence

8310070301 Potential Part 21 rept re underrange characteristic of Model M-E110M transmitter Underrange zero offset may occur when transmitter initially pressurized From atmospheric to suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X
Fiche 50-000, 83/09/30, 8310070301

8310170091 Forwards repts on 821205 main generator failure & proprietary & nonproprietary repts on seven main transformer failures occurring between 801129 & 821205 Proprietary rept withheld (ref 10CFR2 790)
STEWART, W L Virginia Electric & Power Co 83/10/05 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 2pp 20789 207 24X
Fiche 50-338, 83/10/05, 8310170091

--8310170107 Nonproprietary version of "Transformer Rept on Events at North Anna Power Station"
COSSAART, J, PETRIE, E, SKODOLUND, J Westinghouse Electric Corp
83/05/16 276pp 20787 226 24X Fiche 50-338, 83/10/05, 8310170091

8310210047 LER 83-069/03L-0 on 830913, individual rod position indicator for rod K-02 in control bank A exceeded zero step position by 133 steps Caused by personnel error Indicator adjusted W/831012 ltr
HARRELL, E W Virginia Electric & Power Co 83/10/12 O'REILLY, J P
Region 2, Office of Director 2pp 20855 302 24X
Fiche 50-339, 83/10/12, 8310210047

8310250066 Responds to 830615 request for addl info re status of vendor repair or redesign or provisions for obtaining other qualified resistance temp detectors & proposed schedule for installation Installation scheduled for Oct 1984
STEWART, W L Virginia Electric & Power Co 83/10/19 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 2pp 20894 176 24X
Fiche 50-339, 83/10/19, 8310250066

DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8308300357 Board Notification 82-109A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway
EISENHUT, D G Division of Licensing 83/09/29 PALLADINO, N J
Commissioners 3pp 20632 001 24X Fiche 50-000, 83/09/29, 8308300357

8310130229 Forwards Rev 2 to "Inservice Testing Program for Enrico Fermi Unit 2 " Rev to testing program for pumps & valves incorporates necessary mods & clarifications per NRC 830316 ltr & 830517-18 meetings Related info encl
TAUBER, H Detroit Edison Co 83/10/04 YOUNGBLOOD, B J Licensing Branch 1 7pp 20723 287 24X Fiche 50-341, 83/10/04, 8310130229

--8310130232 Rev 2 to Procedure DET-16-0201, "Inservice Testing Program for Enrico Fermi Unit 2 "
KIN, J W, CLAUBB, J M NUTECH Engineers, Inc 83/08/04 160pp 20723 294 24X Fiche 50-341, 83/10/04, 8310130229

8310120098 Requests that NRC defer issuance of proof & review Tech Specs to allow incorporation of current test data & to minimize need to modify specs at later date
JENS, W H Detroit Edison Co 83/10/05 YOUNGBLOOD, B J Licensing Branch 1 1p 20696 184 24X Fiche 50-341, 83/10/05, 8310120098

8310120190 Responds to Generic Ltr 83-24 re TMI Action Item 1 G.1, "Special Low Power Testing & Training " Util will comply w/BWR Owners Group position w/special test incorporated FSAR App H will be revised
JENS, W H Detroit Edison Co 83/10/05 YOUNGBLOOD, B J Licensing Branch 1 2pp 20695 333 24X Fiche 50-341, 83/10/05, 8310120190

8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves
EISENHUT, D G Division of Licensing 83/10/06 PALLADINO, N J
Commissioners 31pp 20818 001 24X Fiche 50-000, 83/10/06, 8308300771

DOCKETED ITEMS

8310180470 Forwards revs to nuclear operations training program description, updating B10603 submittal. Future revs to training plan will be documented in Section 13.2 of FSAR
TAUBER, H Detroit Edison Co 83/10/12 YOUNGBLOOD, B J Licensing Branch 1 10pp 20802 041 24X Fiche 50-341,83/10/12,8310180470

8310210052 Advises that Preoperational Test PRET T4102 001, "Control Ctr HVAC" will be initiated by 831101 Rev 1 to test procedure sent to chief of test programs section
AGOSTI, F E Detroit Edison Co 83/10/13 KONKLIN, J E Region 3, Office of Director 1p 20855 301 24X Fiche 50-341,83/10/13, 8310210052

8310210281 Informs that Preoperational Test PRET T4600 001 re standby gas treatment will be initiated on 831101 Test procedure sent to Chief of Test Programs Section
AGOSTI, F E Detroit Edison Co 83/10/13 KONKLIN, J E Region 3, Office of Director 1p 20848 212 24X Fiche 50-341,83/10/13, 8310210281

8310170589 Forwards Amend 51 to amended & substituted application for license, consisting of Amend 51 to FSAR
LANDGRAF, L C LeBosuf, Lamb, Leiby & MacRae 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20791 009 24X Fiche 50-341,83/10/14,8310170589

--8310170594 Amend 51 to amended & substituted application for license, consisting of Amend 51 to FSAR
HEIDEL, C H Detroit Edison Co 83/10/12 1p 20791 010, 24X Fiche 50-341,83/10/14,8310170589

8310240105 Notification of 831019 meeting w/util in Bethesda, MD to discuss environ qualification of equipment
LYNCH, H D Licensing Branch 1 83/10/18 YOUNGBLOOD, B J Licensing Branch 1 3pp 20891 350 24X Fiche 50-341,83/10/04,8310240105

E NRC Safety Evaluation Report (SER), supp's & correspondence

8310130018 Forwards SORT qualification summary of equipment list update & response to SSER 3 (NUREG-0798) open items
TAUBER, H Detroit Edison Co 83/10/04 YOUNGBLOOD, B J Licensing Branch 1 68pp 20725 123 24X Fiche 50-341,83/10/04,8310130018

F. Security, medical, emergency & fire protection plans

8310170629 Forwards IE Insp Rept 50-341/83-17 on 830701-0831 & notice of violation
KNOP, R C Region 3, Office of Director 83/09/28 WELLS, D A Detroit Edison Co 2pp 20782 080 24X Fiche 50-341,83/09/28, 8310170629

--8310170643 IE Insp Rept 50-341/83-17 on 830701-0831 Noncompliance noted work performed on emergency diesel generator 11 voltage regulator w/illigible & unreadable PNM1 & electrical single line sketch had no refs or description
BYRON, P M, PARKER, M E, LITTLE, B H Region 3, Office of Director 83/09/28 10pp 20782 083 24X Fiche 50-341,83/09/28, 8310170629

8310180029 Releases public version of revised radiological emergency response preparedness plan & revised radiological emergency response preparedness procedures
FELTON, J M Division of Rules and Records 83/10/13, Document Management Branch 1p 20814 304, 24X Fiche 50-341,83/10/13, 8310180029

--8310180034 Forwards public version of Rev 2 to radiological emergency response preparedness plan & revised radiological emergency response preparedness procedures
JENSEN, W H Detroit Edison Co 83/10/04 YOUNGBLOOD, B J Licensing Branch 1 1p 20814 305 24X Fiche 50-341,83/10/13, 8310180029

-8310180037 Public version of Rev 2 to radiological emergency response preparedness plan
Detroit Edison Co 83/09/21 300pp, 20814 306 24X Fiche 50-341,83/10/13,8310180029

-8310180042 Public version of revised emergency plan implementing procedures, including Procedures EP-102 re unusual event, EP-103 re alert & EP-104 re site area emergency,
Detroit Edison Co 83/09/21 797pp, 20815, 252 24X Fiche 50-341,83/10/13,8310180029

8310310342 Forwards IE Preoperational Safeguards Insp Rept 50-341/83-23 on 830926-30 No noncompliance noted
AXELSON, W L Region 3, Office of Director, 83/10/26, WELLS, D A Detroit Edison Co 2pp 20761 317, 24X Fiche 50-341,83/10/26, 8310310342.

--8310310347 IE Preoperational Safeguards Insp Rept 50-341/83-23 on 830926-30 No noncompliance noted Major areas inspected Implementation, installation & operability of security programs Details withheld (ref 10CFR/3.21)
MADEBA, T J, KNICELEY, J R, CRLED, J R Region 3, Office of Director 83/10/25 2pp 20761 319 24X Fiche 50-341,83/10/26, 8310310342

G Adjudicatory correspondence

8310040274 Order extending time until 831001 for Commission to act to review ALAB-730
CHILK, S J Office of the Secretary of the Commission 83/09/10 Commissioners 1p 20612 361 24X Fiche 50-341,83/09/30, 8310040274

8310120405 Order extending time until 831017 for Commission to act to review ALAB-730
CHILK, S J Office of the Secretary of the Commission 83/10/07 Commissioners 1p 20699 024 24X Fiche 50-341,83/10/07, 8310120405

8310280066 Informs that Commission declined to review Decision ALAB-730 Review period expired Decision became final agency action on 831017
CHILK, S J Office of the Secretary of the Commission 83/10/27 MINOCK, J II Affiliation Unknown 1p 20935 060 24X Fiche 50-341,83/10/27,8310280066

H General correspondence

8310200109 Informs that OK Earle became util supervisor of licensing on 831001 L Schuerman, former supervisor of licensing, promoted to supervisor, sys & plant engineering
EARLE, O K Detroit Edison Co 83/10/10 YOUNGBLOOD, B J Licensing Branch 1 1p 20837 102 24X Fiche 50-341,83/10/10,8310200109

K Utility Final Safety Analysis Report (FSAR) & amends

8310170589 Forwards Amend 51 to amended & substituted application for license, consisting of Amend 51 to FSAR
LANDGRAF, L C LeBosuf, Lamb, Leiby & MacRae 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20791 009 24X Fiche 50-341,83/10/14,8310170589

--8310170594 Amend 51 to amended & substituted application for license, consisting of Amend 51 to FSAR
HEIDEL, C H Detroit Edison Co 83/10/12 1p 20791 010 24X Fiche 50-341,83/10/14,8310170589

--8310170600 Amend 51 to FSAR
Detroit Edison Co 83/10/31 488pp 20791 011 24X Fiche 50-341,83/10/14,8310170589

Q Inspection reports, IE Bulletins & correspondence

8310050492 Forwards IE Insp Rept 50-341/83-18 on 830822-26 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/09/24 WELLS, A Detroit Edison Co 2pp 20628 352 24X Fiche 50-341,83/09/24, 8310050492

--8310050497 IE Insp Rept 50-341/83-18 on 830822-26 No noncompliance noted Major areas inspected action taken on 10CFR50.55(e) items, IE bulletins, IE circulars, previous Insp findings & electrical design review
WILLIAMS, C C, AHMED, I H, NAIDU, K R Region 3, Office of Director 83/09/22 8pp 20628 354 24X Fiche 50-341,83/09/23, 8310050492

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345

DOCKETED ITEMS

213

6310170629 Forwards IE Insp Rept 50-341/83-17 on 830701-0831 & notice of violation
KNOP, R C Region 3, Office of Director 83/09/28 WELLS, D A
Detroit Edison Co 2pp 20/82 080 24X Fiche 50-341,83/09/28,
8310170629

--8310170636 Notice of violation from insp on 830701-0831
KNOP, R C Region 3, Office of Director 83/09/28 1p
20782 082 24X Fiche 50-341,83/09/28,8310170629

--8310170643 IE Insp Rept 50-341/83-17 on 830701-0831 Noncompliance
noted work performed on emergency diesel generator 11
voltage regulator w/illisible & unreadable PNM & electrical
single line sketch had no refs or description
BYRON, P M, PARKER, M E, LITTLE, B H Region 3, Office of Director
83/09/28 10pp 20782 083 24X Fiche 50-341,83/09/28,
8310170629

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to
Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New
York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass
Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical
Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752

8310120305 Ack receipt of 830921 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-341/83-07
SPESBARD, R L Division of Engineering 83/10/07 WELLS, D A
Detroit Edison Co 1p 20701 012 24X Fiche 50-341,83/10/07,
8310120305

--8310120311 Supplemental response to NRC 830713 ltr re violations
noted in IE Insp Rept 50-341/83-07 Corrective actions
adequate measures adopted to assure proper control of plant
configuration
WELLS, D A Detroit Edison Co 83/09/21 SPESBARD, R L Division
of Engineering 7pp 20701 013 24X Fiche 50-341,83/10/07,
8310120305

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect
Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective
Self-Contained Breathing Apparatus Air Cylinders " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

8310180289 Clarifies NRC position re procedures for admitting NRC
personnel to facility List of personnel requiring access to
vital areas encl Updates will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 WELLS, D A
Detroit Edison Co 7pp 20806 282 24X Fiche 50-341,83/10/14,
8310180289

8310310342 Forwards IE Preoperational Safeguards Insp Rept 50-341/83-23
on 830926-30 No noncompliance noted
AXELSON, W L Region 3, Office of Director 83/10/26 WELLS, D A
Detroit Edison Co 2pp 20761 317 24X Fiche 50-341,83/10/26,
8310310342

--8310310347 IE Preoperational Safeguards Insp Rept 50-341/83-23 on
830926-30 No noncompliance noted Major areas inspected
implementation, installation & operability of security
programs Details withheld (ref 10CFR73 21)
MAEDA, T J, KNICELEY, J R, CREED, J R Region 3, Office of
Director 83/10/25 2pp 20761 319 24X Fiche 50-341,83/10/26,
8310310342

S Reportable occurrences, LERs & related correspondence

8310070301 Potential Part 21 rept re underrange characteristic of
Model N-E110M transmitter Underrange zero offset may occur
when transmitter initially pressurized from atmospheric to
suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office
of Inspection and Enforcement 11pp 20651 064 24X
Fiche 50-000,83/09/30,8310070301

8310120224 Interim deficiency rept re cracked & broken puffer piston
rods in Brown Boveri 5HK 250/350,1200/2000A circuit
breakers Initially reported on 830317 Insps to be conducted
at maint intervals Cracked assemblies will be replaced
DUVALL, D D Brown Boveri Corp (subs of Brown Boveri & Co, Ltd)
83/10/05 DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 4pp 20693 130 24X Fiche 50-341,83/10/05,8310120224

8310250114 Final deficiency rept, Item B6 re missing Swagelok fittings in
reactor vessel Initially reported on 821229 Missing Swagelok
instrument line plug assemblies replaced All plug keepers
removed & discarded & Swagelok fittings tightened
WELLS, D A Detroit Edison Co 83/10/07 KEPPLER, J Q Region 3,
Office of Director 4pp 20876 268 24X Fiche 50-341,83/10/07,
8310250114

8310210066 Interim deficiency rept re Wismer & Becker inconsistent
implementation of UT procedures for flued head structures
Initially reported on 830909 Investigation continuing
WELLS, D A Detroit Edison Co 83/10/10 KEPPLER, J Q Region 3,
Office of Director 2pp 20858 190 24X Fiche 50-341,83/10/10,
8310210066

8310270447 Final deficiency rept, Item 14 re action taken on RHR HX
relief valves Initially reported on 830503 Listed design
changes to reduce water hammer problem implemented
Commitment satisfied
WELLS, D A Detroit Edison Co 83/10/21 KEPPLER, J Q Region 3,
Office of Director 2pp 20923 080 24X Fiche 50-341,83/10/21,
8310270447

8310270487 PNO-III-83-101 on 831021, licensee employee discovered
suspicious looking package near equipment on third level of
turbine bldg Portion of bldg evacuated & MI State Police
notified Package dismantled & confirmed nonexplosive
CREED, J Region 3, Office of Director 83/10/21 1p 20922 001,
24X Fiche 50-341,83/10/21,8310270487

DOCKET 50-344 TROJAN NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

8310060258 Forwards info re radiological emergency plan 1983 annual
exercise
BROEHL, D J Portland General Electric Co 83/07/18 MARTIN, J B
Region 5, Office of Director 5pp 20645 202 24X
Fiche 50-344,83/07/18,8310060258

--8310060261 Forwards scenario for 831005 radiological emergency plan
exercise
WITHERS, B D Portland General Electric Co 83/08/26 MARTIN, J B
Region 5, Office of Director 55pp 20645 207 24X
Fiche 50-344,83/07/18,8310060258

8310060099 Forwards Rev 1 to 1983 radiological emergency plan exercise
scenario
WITHERS, B D Portland General Electric Co 83/09/15 MARTIN, J B
Region 5, Office of Director 36pp 20647 196 24X
Fiche 50-344,83/09/15,8310060099

8310060491 Forwards info re 1983 radiological emergency plan exercise
WITHERS, B D Portland General Electric Co 83/09/15 MARTIN, J B
Region 5, Office of Director, 166pp 20641 042 24X
Fiche 50-344,83/09/15,8310060491

8310170063 Advises of disapproval of exception to habitability
requirements for emergency operation facility (EOF), per
820503 ltr Plans for establishing EOF per Suppl 1 to
NUREG-0737 (Generic Ltr 82-33) requested by 831128
EISENHUT, D G Division of Licensing 83/09/29, WITHERS, B D
Portland General Electric Co 5pp 20798 035 24X
Fiche 50-344,83/09/29,8310170063

8310130102 Releases public version of revised radiological emergency
plan & procedures manual
FELTON, J M Division of Rules and Records 83/10/06 Document
Management Branch 1p 20751 340, 24X Fiche 50-344,83/10/06,
8310130102

DOCKETED ITEMS

--8310130104 Public version of Rev 3 to Radiological Emergency Plan & Procedures Manual PGE-1008
* Portland General Electric Co 83/09/30 720pp 20751 341
24X Fiche 50-344,83/10/06,8310130102

8310180362 Forwards IE Enforcement Conference Rept 50-344/83-26 on 830909 No noncompliance noted
MARTIN, J B Region 5, Office of Director 83/10/14 WITHERS, B D
Portland General Electric Co 1p 20801 336 24X
Fiche 50-344,83/10/14,8310180362

--8310180367 IE Enforcement Conference Rept 50-344/83-26 on 830909 Major areas discussed violations identified during 830620-24 & 0726-28 Insp of compliance w/10CFR50 App R
Sections 111 C, J, L & O
SCOWEN, K, DODDS, R T Region 5, Office of Director BISHOP, T W
Division of Resident Reactor Project & Engineering Programs
83/10/12 5pp 20801 337 24X Fiche 50-344,83/10/14,8310180362

8310270518 Releases public version of notification that amend to radiological emergency plan forwarded under separate cover
FELTON, J M Division of Rules and Records 83/10/21 Document
Management Branch 1p 20928 361 24X Fiche 50-344,83/10/21,
8310270518

--8310270521 Submits public version of notification that Amend 3 to Radiological Emergency Plan PGE-1008 forwarded under separate cover Amend plan continues to meet stds of 10CFR47(b) & requirements of 10CFR50, App E
WITHERS, B D Portland General Electric Co 83/10/04 MARKIN, J D
Region 5, Office of Director 1p 20928 362 24X
Fiche 50-344,83/10/21,8310270518

J Insurance & indemnity information

8310140257 Forwards Endorsement 62 to NELIA Policy NF-225 & Endorsement 52 to MAELU Policy NF-86
JOHANSEN, E Portland General Electric Co 83/10/06 SALTZMAN, J
Office of State Programs, Director 3pp 20761 336 24X
Fiche 50-344,83/10/06,8310140257

P Operating license stage documents & correspondence

8310250591 Forwards Std Order for DOE Work "Operating Reactors Licensing Actions - Tech Specs for Hydraulic & Mechanical Snubbers for Trojan & Rancho Seco"
ADAMS, C Energy, Dept of FIN B-8559 83/09/16 MARTIN, J B
Region 5, Office of Director 1p 20900 124 24X
Fiche 50-000,83/09/16,8310250591

--8310250600 Std order for DOE Work "Operating Reactors Licensing Action Tech Specs for Hydraulic & Mechanical Snubbers for Trojan & Rancho Seco," issued to LLL
MARTIN, J B Region 5, Office of Director MACRUSKY, J Lawrence Livermore Laboratory FIN B-8559 83/08/31 1p 20900 125 24X
Fiche 50-000,83/09/16,8310250591

--8310250625 Forwards project & budget proposal for NRC work "Operating Reactors Licensing Actions Tech Specs for Hydraulic & Mechanical Snubbers for Trojan & Rancho Seco"
STUART, K J Lawrence Livermore Laboratory FIN B-8562 83/08/18
BISHOP, T W Region 5, Office of Director 1p 20900 126 24X
Fiche 50-000,83/09/16,8310250591

--8310250631 Project & budget proposal for NRC work "Operating Reactors Licensing Actions Tech Specs for Hydraulic & Mechanical Snubbers for Trojan & Rancho Seco"
CLELAND, L L, WHITE, R, JOHNSON, J M Lawrence Livermore Laboratory FIN B-8562 83/08/18 PADOVAN, M L, ZWETZIG, G
Region 5, Office of Director 2pp 20900 127 24X
Fiche 50-312,83/09/16,8310250591

310070133 Forwards, for consideration, project & budget proposal, "Operating Reactors Licensing Actions Tech Specs for Hydraulic & Mechanical Snubbers for Trojan & Rancho Seco Facilities"
TUSZKA, M E, Lawrence Livermore Laboratory FIN B-8562 83/09/20
BISHOP, T W Region 5, Office of Director, 10pp 20659 025 24X
Fiche 50-000,83/09/20,8310070133

10180608 Forwards requests for addl info re spent fuel rack replacement & spent fuel pool storage expansion structural topics to complete review of 830801 application to increase pool capacity Response needed within 45 days of ltr receipt
MILLER, J R Operating Reactors Branch 3, 83/09/30 WITHERS, B D
Portland General Electric Co, 5pp 20817 342 24X
Fiche 50-344,83/09/30,8310180608

8310110189 Forwards License Change Application 96, amending License NPF-1 re offsite & onsite organizations
WITHERS, B D Portland General Electric Co 83/10/04 MILLER, J R
Operating Reactors Branch 3 1p 20665 287 24X
Fiche 50-344,83/10/04,8310110189

--8310110196 License Change Application 96 amending License NPF-1 re offsite & onsite organizations
WITHERS, B D Portland General Electric Co 83/10/04 1p
20665 288 24X Fiche 50-344,83/10/04,8310110189

--8310110201 Proposed changes to Tech Specs re offsite & onsite organizations
* Portland General Electric Co 83/10/04 7pp 20665 289 24X
Fiche 50-344,83/10/04,8310110189

8310200188 Forwards License Change Application 95 requesting amend to License NPF-1, changing Tech Spec 4 & 2.2 d to allow more practical method of verifying available flow from containment spray additive tank
WITHERS, B D Portland General Electric Co 83/10/14 MILLER, J R
Operating Reactors Branch 3 1p 20833 069 24X
Fiche 50-344,83/10/14,8310200188

--8310200192 License Change Application 95 requesting amend to License NPF-1, changing Tech Spec 4 & 2.2 d to allow more practical method of verifying available flow from containment spray additive tank
WITHERS, B D Portland General Electric Co 83/10/14 5pp
20833 070 24X Fiche 50-344,83/10/14,8310200188

--8310200198 Proposed changes to Tech Spec 4 & 2.2 d to allow more practical method of verifying available flow from containment spray additive tank
* Portland General Electric Co 83/10/14 2pp 20833 075 24X
Fiche 50-344,83/10/14,8310200188

8310260237 Forwards "Trojan Nuclear Plant Cycle & Startup & Power Escalation Physics Testing Rept"
WITHERS, B D Portland General Electric Co 83/10/14 MARTIN, J B
Region 5, Office of Director 1p 20912 024 24X
Fiche 50-344,83/10/14,8310260237

--8310260242 Forwards "Trojan Nuclear Plant Cycle & Startup & Power Escalation Physics Testing Rept," & WCAP-10336, "Trojan EDC-5 Onsite Fuel Exam" WCAP-10336 withheld
TODD, A J Portland General Electric Co 83/10/14 MARTIN, J B
Region 5, Office of Director 1p 20912 025 24X
Fiche 50-344,83/10/14,8310260237

--8310260246 "Trojan Nuclear Plant Cycle & Startup & Power Escalation Physics Testing Rept"
* Portland General Electric Co PGE-1040 83/10/31 60pp
20912 026 24X Fiche 50-344,83/10/14,8310260237

8310310299 Forwards "Reactor Containment Bldg Integrated Leak Rate Test, Final Rept 830629-0702"
WITHERS, B D Portland General Electric Co 83/10/17 MILLER, J R
Operating Reactors Branch 3 1p 20957 097 24X
Fiche 50-344,83/10/17,8310310299

--8310310301 "Reactor Containment Bldg Integrated Leak Rate Test, Final Rept 830629-0702"
* Portland General Electric Co PGE-1023-(83) 83/10/31 583pp
20957 099 24X Fiche 50-344,83/10/17,8310310299

Q Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345

DOCKETED ITEMS

215

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Bys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8310120245 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in 830902 rept of insp on 830728-0805
WENSLAWSKI, F A Region 5, Office of Director 83/10/07
WITHERS, B D Portland General Electric Co 1p 20692 161 24X Fiche 50-344, 83/10/07, 8310120245

--8310120247 Responds to NRC 830902 ltr re violations noted in IE insp on 830728-0805 Corrective actions environ contractor instructed to perform specified analyses within 8-day period required by Tech Specs
WITHERS, B D Portland General Electric Co 83/09/30 MARTIN, J B Region 5, Office of Director 2pp 20692 162 24X Fiche 50-344, 83/10/07, 8310120245

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180362 Forwards IE Enforcement Conference Rept 50-344/83-26 on 830909 No noncompliance noted
MARTIN, J B Region 5, Office of Director 83/10/14 WITHERS, B D Portland General Electric Co 1p 20801 336 24X Fiche 50-344, 83/10/14, 8310180362

--8310180367 IE Enforcement Conference Rept 50-344/83-26 on 830909 Major areas discussed violations identified during 830620-24 & 0726-28 insp of compliance w/10CFR50 App R
Sections III O, J, L & O
SCOWEN, K, DODDS, R T Region 5, Office of Director BISHOP, T W Division of Resident, Reactor Project & Engineering Programs
83/10/12 5pp 20801 337 24X Fiche 50-344, 83/10/14, 8310180362

A Periodic operating reports & related correspondence

8310190039 Monthly operating rept for Aug 1983 W/830909 ltr
KENT, G J, YUNDT, C P Portland General Electric Co 83/09/08
Office of Resource Management, Director 5pp 20823 279 24X Fiche 50-344, 83/09/08, 8310190039

8310310299 Forwards "Reactor Containment Bldg Integrated Leak Rate Test, Final Rept 830629-0702, "
WITHERS, B D Portland General Electric Co 83/10/17 MILLER, J R Operating Reactors Branch 3, 1p, 20957, 097 24X Fiche 50-344, 83/10/17, 8310310299

--8310310301 "Reactor Containment Bldg Integrated Leak Rate Test, Final Rept 830629-0702 "
* Portland General Electric Co PGE-1023-(83) 83/10/31 583pp 20957, 097, 24X Fiche 50-344, 83/10/17, 8310310299,

B. Reportable occurrences, LERs & related correspondence

8310280079 Responds to FOIA request for AEDD rept, "Loss of Shutdown Cooling & Subsequent Boron Dilution at San Onofre 2," dtd 830425 & documents re fuel rod degradation problem described in IE Info Notice 82-27 Forwards App A documents
FELTON, J M Division of Rules and Records, 83/07/28, HIATT, S L, Ohio Citizens for Responsible Energy, 2pp 20962 156 24X Fiche 50-000, 83/07/28, 8310280079

--8310280136 Forwards safety evaluations prepared by licensee & Region V re loose fuel pellets & clad pieces in RCS
CRENS, J L Division of Resident, Reactor Project & Engineering Programs 82/07/22 CLARK, R A Operating Reactors Branch 3 6pp 20962 220 24X Fiche 50-000, 83/07/28, 8310280079

--8310280138 Safety evaluation re loose fuel pellets & clad pieces in RCS Strong evidence exists that no more than 20 pellets remain in RCS Licensee performed comprehensive evaluation of proposed operation Related info encl
* Region 5, Office of Director 82/07/21 12pp 20962 226 24X Fiche 50-000, 83/07/28, 8310280079

8310030440 EN-83-060 on or about 830929, notice of violation & proposed imposition of civil penalty in amount of \$100,000 will be issued to licensee Action based on inadequate reassessment of fire protection features, per 10CFR50, App R
CRATO, J, AXELRAD, J, Office of International Programs, Director 83/09/26 1p 20602 089 24X Fiche 50-344, 83/09/26, 8310030440

8310140246 LER 83-013/03L-0 on 830908, train A boric acid transfer pump deenergized & train B boric acid transfer pump mistakenly valved out caused by personnel error in preparation of tag-out procedure Personnel disciplined W/831003 ltr
BAIR, G O, YUNDT, C P Portland General Electric Co 83/10/03 MARTIN, J B Region 5, Office of Director 3pp 20761 342, 24X Fiche 50-344, 83/10/03, 8310140246

8310200165 Part 21 rept re static temp calibr check on transmitters initially reported on 831013 Caused by irregular setpoint for pressurizer pressure safety injection function New 1, 829 psig setpoint recommended
RAHE, E P, Westinghouse Electric Corp 83/10/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 20834 078 24X Fiche 50-000, 83/10/13, 8310200165

8310250444 LER 83-014/03L-0 on 830916, during routine testing, train A emergency diesel generator failed to control voltages as required & failed flash circuit would not deenergize, rendering generator inoperable W/831014 ltr
BAIR, G O, YUNDT, C P Portland General Electric Co 83/10/14 MARTIN, J B Region 5, Office of Director 4pp 20897 160, 24X Fiche 50-344, 83/10/14, 8310250444

8310250543 PNO-V-83-048 on 831013, Region V notified by NRR of temp compensation error w/Barton Model 763 pressure transmitters Same problem exists w/Model 764 steam generator narrow-range water level transmitters Setpoints revised on 831014
HAIBT, D Region 5, Office of Director 83/10/18, 1p 20901:323, 24X Fiche 50-344, 83/10/18, 8310250543

V Operator Examinations

8310030145 Requests schedule, by 831028, for requalification training & exams for 1984 in order to coordinate Region V audit of operator requalification programs
BISHOP, T W, Division of Resident, Reactor Project & Engineering Programs 83/09/26 WITHERS, B D Portland General Electric Co 2pp 20590 036 24X Fiche 50-344, 83/09/26, 8310030145.

DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8310050077 Forwards BER supporting util fire protection corrective action program Acceptable level of fire protection achieved to permit resumption of power pending completion of long-term actions
EISENHUT, D O, Division of Licensing 83/09/23 CRDUSE, R P Toledo Edison Co, 6pp 20650 170 24X Fiche 50-346, 83/09/23, 8310050077.

--8310050082 BER supporting util fire protection corrective action program Acceptable level of fire protection achieved to permit resumption of power pending completion of long-term actions
* NRC - No Detailed Affiliation Given, 83/09/23 11pp, 20650 176 24X Fiche 50-346, 83/09/23, 8310050077

8310060345 Requests exemptions from App R requirements re oil collection sys for reactor coolant pumps, cold shutdown within 72 h w/o use of offsite power & separation of cables & equipment of redundant trains by fire barriers
CRDUSE, R P Toledo Edison Co 83/09/30 EISENHUT, D O Division of Licensing, 12pp, 20646, 139, 24X Fiche 50-346, 83/09/30, 8310060345

8310060590 Releases public version of temporary mod request to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/05, Document Management Branch 1p 20661 193, 24X Fiche 50-346, 83/10/05, 8310060590.

DOCKETED ITEMS

- 8310060595 Public version of Temporary Mod Request T-7400 to Emergency Plan Implementing Procedure EI 1300-08, "Emergency Control Ctr Activation" W/830914 ltr, receipt form & Rev 32 to index
MURRAY, T D, DURDEL, R, DOWNING, G Toledo Edison Co 83/09/06 7pp 20661 194 24X Fiche 50-346, 83/10/05, 8310060590
- 8310110082 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20682 283 24X Fiche: 50-346, 83/10/05, 8310110082
- 8310110085 Forwards public version of revised emergency plan implementing procedures, including Procedure HP 1602 01 re external personnel radiation exposure monitoring Receipt form encl
* Toledo Edison Co. 83/08/25 NRC - No Detailed Affiliation Given 1p 20682 284 24X Fiche 50-346, 83/10/05, 8310110082
- 8310110087 Public version of revised emergency plan implementing procedures, including Procedure HP 1602 01 re external personnel radiation exposure monitoring
MURRAY, T D, BRIDEN, D W Toledo Edison Co. 83/08/15 4pp 20682, 285 24X Fiche 50-346, 83/10/05, 8310110082
- 8310110124 Releases public version of revised administrative procedure
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20686 339 24X Fiche 50-346, 83/10/05, 8310110124
- 8310110131 Public version of Rev 7 to Administrative Procedure AD 1850 04, "Post-Accident Sampling & Counting" W/830921 ltr & receipt form
MURRAY, T D Toledo Edison Co 83/09/13 NRC - No Detailed Affiliation Given 20pp 20686:340 24X Fiche: 50-346, 83/10/05, 8310110124
- 8310210359 Releases public version of temporary mod request to emergency plan supporting procedure.
FELTON, J M Division of Rules and Records 83/10/18 Document Management Branch 1p 20883:146 24X Fiche: 50-346, 83/10/18, 8310210359.
- 8310210363 Public version of Temporary Mod Request T-7480 to Emergency Plan Supporting Procedure AD 1827 07 re earthquake.
W/830930 ltr, receipt form & Rev 191 to index.
MURRAY, T D Toledo Edison Co 83/09/30 3pp. 20883.147 24X Fiche 50-346, 83/10/18, 8310210359
- P Operating license stage documents & correspondence
- 8310120016 Addl response to FOIA request for document re problems w/ Tech Specs applying to RCS leakage determinations in PWRs
Forwards App A documents
FELTON, J M Division of Rules and Records 83/07/07. VOIOT, H H LeBoeuf, Lamb, Leiby & MacRae 2pp. 20751:001. 24X Fiche 50-000, 83/07/07, 8310120016.
- 8310120022 Safety evaluation requiring test of primary coolant sys pressure isolation valves be incorporated into plant Tech Specs
* NRC - No Detailed Affiliation Given 81/04/20 1p 20751 057 24X Fiche: 50-000, 83/07/07, 8310120016
- 8310040648 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept, "ECCS Repts (F-47) Action Plan Requirements, Toledo Edison Co, Davis-Besse Nuclear Power Station, Unit 1" NUREG-0737, Item II K 3 17 requirements met.
STOLZ, J F. Operating Reactors Branch 4 83/09/01. CROUSE, R P Toledo Edison Co 4pp 20627-285. 24X Fiche 50-346, 83/09/01, 8310040648
- 8212010152 "ECCS Repts (F-47), TMI Action Plan Requirements, Davis-Besse Nuclear Power Station, Unit 1," technical evaluation rept
VOISBURY, F W. Franklin Institute/Franklin Research Center NRC-03-B1-130. TER-C5506-273. 82/11/24 CHOW, E. NRC - No Detailed Affiliation Given 14pp. 20627-289. 24X Fiche: 50-346, 83/09/01, 8310040648.
- 8310030598 Forwards exemption extending until 831231 date for installation of reactor vessel head vent. Only interim relief from implementation schedule allowed due to lack of supporting sys data
STOLZ, J F. Operating Reactors Branch 4. 83/09/07. CROUSE, R P. Toledo Edison Co 3pp 20607:279. 24X Fiche: 50-346, 83/09/07, 8310030598.
- 8310030600 Exemption extending until 831231 date for installation of reactor vessel head vent
EISENHUT, D O Division of Licensing 83/09/07 Toledo Edison Co 6pp 20607 282 24X Fiche 50-346, 83/09/07, 8310030598
- 8310180567 Forwards SER re generic mods to reactor trip breakers & for B&W plants to provide automatic actuation of shunt trip attachments, per Generic Ltr 83-28
STOLZ, J F Licensing Branch 4 83/09/22 CROUSE, R P Toledo Edison Co 2pp 20825 012 24X Fiche 50-346, 83/09/22, 8310180567
- 8310180570 SER supporting generic mods to reactor trip breakers for B&W plants to provide automatic actuation of shunt trip attachments
* NRC - No Detailed Affiliation Given 83/09/22 14pp 20825 014 24X Fiche 50-346, 83/09/22, 8310180567
- 8310130382 Forwards Franklin Research Ctr "Operating Reactor PORV Repts (F-37), TMI Action Plan Requirements, Generic Rept - B&W Designed Units," technical evaluation rept & NRR safety evaluation accepting B&W response to TMI Item II K 3 2
STOLZ, J F. Operating Reactors Branch 4 83/09/23 CROUSE, R P Toledo Edison Co 3pp 20770 120 24X Fiche 50-346, 83/09/23, 8310130382
- 8310070080 Forwards documentation which formed basis for exemption granted to util, extending date reactor vessel head vent must be installed, per 830909 request Unit restart began on 830927
DIRCKS, W J Office of the Executive Director for Operations 83/09/28 GLINSKY, V Commissioners 3pp 20671 270 24X Fiche 50-346, 83/09/28, 8310070080.
- 8306090346 Forwards SER re request for exemption from reactor vessel head vent requirement Util not convinced that noncondensable gases that evolve in primary sys can be safely vented by hot leg high point vents alone.
HOUSTON, R W Assistant Director for Reactor Safety 83/05/31. LAINAS, G C Assistant Director for Operating Reactors 9pp 20671 280 24X Fiche 50-346, 83/09/28, 8310070080
- 8310070085 Requests documentation which formed basis of exemption granted to util for installing reactor vessel high point vents Specific date all vents will be in svc also requested by 830923
GLINSKY, V Commissioners 83/09/09 DIRCKS, W J Office of the Executive Director for Operations 1p 20671 299 24X Fiche 50-346, 83/09/28, 8310070080
- 8310110540 Forwards Amend 62 to License NPF-3 & safety evaluation Amend adds Surveillance Requirements 4 4 5, 7 & 4 4 5 8 to Tech Specs based on discovery of dislodged auxiliary feedwater flow distributor
DEAQA210, A W Operating Reactors Branch 4 83/09/30 CROUSE, R P Toledo Edison Co 2pp. 20709 333 24X Fiche 50-346, 83/09/30, 8310110540
- 8310110544 Amend 62 to License NPF-3, adding Surveillance Requirements 4 4 5 7 & 4 4 5 8 to Tech Specs based on discovery of dislodged auxiliary feedwater flow distributor.
STOLZ, J F Operating Reactors Branch 4 83/09/30 6pp 20709 335 24X Fiche: 50-346, 83/09/30, 8310110540
- 8310110548 Safety evaluation supporting Amend 62 to License NPF-3
* Office of Nuclear Reactor Regulation, Director 83/09/30 3pp 20709 341 24X Fiche 50-346, 83/09/30, 8310110540
- 8310060226 Forwards plan & schedule for resolution of NUREG-0737, Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps," (Generic Ltr 83-10), per NRC 830208 request Operating procedures for pumps to be revised
CROUSE, R P Toledo Edison Co 83/10/03 EISENHUT, D O Division of Licensing. 6pp 20647 015 24X Fiche: 50-346, 83/10/03, 8310060226
- 8310200041 Forwards SER re NUREG-0737, Item II B 1, "RCS Vents," based on encl LLL technical evaluation rept & info provided in 800130, 810227, 0323 & 0413 ltrs concerning vent installation Vent sys design acceptable
STOLZ, J F. Operating Reactors Branch 4 83/10/05. CROUSE, R P Toledo Edison Co 7pp 20844.335 24X Fiche 50-346, 83/10/05, 8310200041
- 8306130456 "Selected Operating Reactor Issues Program II, RCS Vents, (NUREG-0737, Item II B 1)," final technical evaluation rept
HELD, J T. Energy Incorporated. * Lawrence Livermore Laboratory FIN A-0250. TF-366/0817A 83/03/14 ALBERTHAL, G. NRC - No Detailed Affiliation Given. 6pp. 20844.342. 24X Fiche 50-346, 83/10/05, 8310200041.

DOCKETED ITEMS

217

8310120103 Responds to NRC 830711 ltr on required actions based on Generic Ltr 83-28 re implication of Salem ATWS event Efforts initiated to ensure satisfactory performance of requested actions & programs Program & schedule expected by 840113 CROUSE, R P Toledo Edison Co 83/10/06 EISENHUT, D G Division of Licensing 1p 20696 240 24X Fiche 50-346, 83/10/06, 8310120103

8310200050 Forwards Franklin Research Ctr draft technical evaluation rept re control of heavy loads, based on 830131, 0502, 06 & 0610 responses to NRC requests for addl info Telcon will be arranged after 831028 to discuss comments STOLZ, J F Operating Reactors Branch 4 83/10/06 CROUSE, R P Toledo Edison Co 3pp 20844 299 24X Fiche 50-346, 83/10/06, 8310200050

--8308180560 "Control of Heavy Loads (C-10), Toledo Edison Co, Davis-Besse Nuclear Power Station Unit 1," draft technical evaluation rept SCHMIDT, C, AHMED, N Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5806-348 DRFT 83/08/09 SINGH, A NRC - No Detailed Affiliation Given 33pp 20844 302 24X Fiche 50-346, 83/10/06, 8310200050

8310170599 Provides schedule for responding to info requested in NRC 830906 ltr re instrumentation to detect inadequate core cooling CROUSE, R P Toledo Edison Co 83/10/07 STOLZ, J F Operating Reactors Branch 4 1p 20782 093 24X Fiche 50-346, 83/10/07, 8310170599

8310170492 Application for amend to License NPF-3, extending temp verification time during & after transport of demineralized water & low boron concentration of liquids of less than 5,000 ppm boron CROUSE, R P Toledo Edison Co 83/10/11 STOLZ, J F Operating Reactors Branch 4 8pp 20783 348 24X Fiche 50-346, 83/10/11, 8310170492

--8310170503 Proposed Tech Specs extending temp verification time during & after transport of demineralized water & low boron concentration of liquids of less than 5,000 ppm boron * Toledo Edison Co 83/10/11 4pp 20783 356 24X Fiche 50-346, 83/10/11, 8310170492

8310250226 Forwards application for amend to License NPF-3, changing Tech Spec Sections 4.1.2.1.4.1.2.3.1.2.8 & 3.1.2.9 to extend time for temp verification during & after transport of demineralized water & liquids w/low boron concentration CROUSE, R P Toledo Edison Co 83/10/11 STOLZ, J F Operating Reactors Branch 4 1p 20899 052 24X Fiche 50-346, 83/10/11, 8310250226

--8310250235 Application for amend to License NPF-3, changing Tech Spec Sections 4.1.2.1.4.1.2.3.1.2.8 & 3.1.2.9 to extend time for temp verification during & after transport of demineralized water & low boron concentration liquid CROUSE, R P Toledo Edison Co 83/10/11 7pp 20899 053 24X Fiche 50-346, 83/10/11, 8310250226

--8310250241 Proposed Tech Spec Sections 4.1.2.1.4.1.2.3.1.2.8 & 3.1.2.9 re time for temp verification during & after transport of demineralized water & low boron concentration liquid * Toledo Edison Co 83/10/11 4pp 20899 060 24X Fiche 50-346, 83/10/11, 8310250226

8310310489 Summary of 830826 meeting w/B&W Owners Group re implementation of Generic Ltr 83-28 concerning defenses against ATWS & proposed ATWS rule for B&W plants, List of attendees & vignettes encl KADAMBI, P Operating Reactors Branch 4 83/10/20 Operating Reactors Branch 4 13pp 20965 147, 24X Fiche 50-000, 83/10/20, 8310310489

G Inspection reports, IE Bulletins & correspondence

8310040176 Forwards IE Insp Rept 50-346/83-17 on 830823-25 No noncompliance noted LITTLE, W. B Region 3, Office of Director 83/09/21 CROUSE, R P Toledo Edison Co 2pp 20608 068 24X Fiche 50-346, 83/09/21, 8310040176

--8310040179 IE Insp Rept 50-346/83-17 on 830823-25 No noncompliance noted Major areas inspected relocation of pressurizer relief valves, followup on previously identified items & snubber & restraint installation VIN, I T, DANIELSON, D H Region 3, Office of Director 83/09/19 6pp 20608 070, 24X Fiche 50-346, 83/09/21, 8310040176

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001, 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/27 Consolidated Edison Co of New York, Inc 115pp, 20716 324 24X Fiche 50-000, 83/09/27, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180202 Clarifies procedures for admitting NRC personnel to Facilities Access lists encl Update will be provided every 6 months AXELSON, W L Region 3, Office of Director 83/10/14 CROUSE, R P Toledo Edison Co 7pp 20808 331 24X Fiche 50-346, 83/10/14, 8310180202

R Periodic operating reports & related correspondence

8310190166 Forwards monthly operating rept for Aug 1983 & Rev 1 to monthly operating rept for Jul 1983 MURRAY, T D Toledo Edison Co 83/09/08 HALLER, N Office of Resource Management, Director 1p 20821 068 24X Fiche 50-346, 83/09/08, 8310190166

--8310190167 Monthly operating rept for Aug 1983 SARSDUR, B Toledo Edison Co 83/09/08 3pp 20821 069, 24X Fiche 50-346, 83/09/08, 8310190166

---8310190170 Rev 1 to monthly operating rept for Jul 1983 SARSDUR, B Toledo Edison Co 83/09/08 2pp 20821 074, 24X Fiche 50-346, 83/09/08, 8310190166

8310180513 "NPDEB Discharge Monitoring Rept, Sept 1983 " W/831013 ltr. CROUSE, R P Toledo Edison Co 83/10/05 Ohio, State of, 10pp 20801 171 24X Fiche 50-346, 83/10/05, 8310180513

8310190020 "Wastewater Rept for Sept 1983." MURRAY, T D, SCOTT, R J Toledo Edison Co 83/10/05 7pp 20822 039 24X Fiche 50-346, 83/10/05, 8310190020

DOCKETED ITEMS

B Reportable occurrences, LERs & related correspondence

8310120239 LER 83-044/03L-0 on 830822, during containment local leak rate test, containment isolation valves CC1407B, SA2101, DR2012A & CC1411B found w/leakage rates in excess of Tech Specs Caused by component failures W/830921 ltr MISSIG, D., LANG, T., MURRAY, T D Toledo Edison Co 83/09/21 KEPLER, J O Region 3, Office of Director 6pp 20691 321 24X Fiche 50-346, 83/09/21, 8310120239

8310120391 Corrected LER 83-044/03L-0 on 830822, during local leak rate test, four containment isolation valves found w/leakage rates in excess of limit Caused by component failures due to dirt & rust on seat Valves repaired & retested W/830921 ltr MISSIG, D., LANG, T., MURRAY, T D Toledo Edison Co 83/09/21 KEPLER, J O Region 3, Office of Director 6pp 20699 107 24X Fiche 50-346, 83/09/21, 8310120391

8310060365 LER 83-046/03L-0 on 830830-0922, during fire protection barrier surveillance test, 15 fire dampers found nonfunctional Caused by const installation error or equipment failure Dampers repaired W/830929 ltr RICHTER, L., MURRAY, T D Toledo Edison Co 83/09/29 KEPLER, J O Region 3, Office of Director 8pp 20646 097 24X Fiche 50-346, 83/09/29, 8310060365

8310070301 Potential Part 21 rept re underrange characteristic of Model N-E110M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X Fiche 50-000, 83/09/30, 8310070301

8310120222 LER 83-047/03L-0 on 830831, during independent offsite ac source bus transfer procedure, automatic unit power supply to each 345 kV transmission line failed Caused by dirt in source selector switch W/830930 ltr UEBBING, R., MURRAY, T D Toledo Edison Co 83/09/30 KEPLER, J O Region 3, Office of Director App 20693 126 24X Fiche 50-346, 83/09/30, 8310120222

8310120322 LER 83-048/03L-0 on 830901, four HPI stop check valves found malfunctioning, in violation of Tech Specs Caused by design deficiency Disk in HP49 replaced w/33 degree seat angle design W/830930 ltr BLANKEMEYER, J., MURRAY, T D Toledo Edison Co 83/09/30 KEPLER, J O Region 3, Office of Director 5pp 20700 300 24X Fiche 50-346, 83/09/30, 8310120322

8310170369 LER 83-049/03L-0 on 830905, Fuel Handling Area Door 306 found open Caused by broken coordinator mechanism Coordinator mechanism replaced W/831005 ltr WOLFE, R., MURRAY, T D Toledo Edison Co 83/10/05 KEPLER, J O Region 3, Office of Director 3pp 20786 182 24X Fiche 50-346, 83/10/05, 8310170369

8310170375 LER 83-051/03L-0 on 830909, snubber BR-4-R-3 in hanger EBB-1-BR4 found w/o oil in reservoir Caused by bad rod seal Snubber replaced Insp interval reduced W/831005 ltr O'NEILL, J., MURRAY, T D Toledo Edison Co 83/10/05 KEPLER, J O Region 3, Office of Director 3pp 20785 016 24X Fiche 50-346, 83/10/05, 8310170375

8310170498 LER 83-050/03L-0 on 830906, during performance of BT 5099 02, miscellaneous instrument daily checks, surveillance requirement 4.4.2 b not performed Caused by lack of administrative controls W/831006 ltr WILLARD, J., MURRAY, T D Toledo Edison Co 83/10/06 KEPLER, J O Region 3, Office of Director App 20784 109 24X Fiche 50-346, 83/10/06, 8310170498

DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8310040436 Resubmits 830725 ltr transmitting Rev 7 to security plan Original ltr contained safeguards info & could not be docketed. CLAYTON, F L Alabama Power Co 83/09/15 O'REILLY, J P Region 2, Office of Director 1p, 20619 053 24X Fiche 50-348, 83/09/15, 8310040436

8310040581 Advises that review of Rev 7 to radiological emergency plan complete Plan continues to meet planning stds of 10CFR50 47(b) & requirements of 10CFR50, App E. VERRELLI, D M Division of Project & Resident Programs, 83/09/20 McDONALD, R P Alabama Power Co 2pp 20622 306, 24X Fiche 50-348, 83/09/20, 8310040581

8310030147 Ack receipt of 830824 ltr documenting results of design description for alternative shutdown capability review re fire protection Description acceptable w/exception that source range monitor be added to hot shutdown panel CLAYTON, F L Alabama Power Co 83/09/28 VARQA, S A Office of Nuclear Reactor Regulation, Director 2pp 20590 034 24X Fiche 50-348, 83/09/28, 8310030147

8310250472 Ack receipt of 830921 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-21 & 50-364/83-19 Request for 60-day extension for response to violations approved VERRELLI, D M Division of Project & Resident Programs 83/10/06 McDONALD, R P Alabama Power Co 2pp 20902 121 24X Fiche 50-348, 83/10/06, 8310250472

--8310250479 Responds to NRC 830909 ltr re violations noted in IE Insp Repts 50-348/83-21 & 50-364/83-19 Corrective actions detailed review of fire protection program underway Extension of 60 days requested for response CLAYTON, F L Alabama Power Co 83/09/21 VERRELLI, D M Division of Project & Resident Programs 2pp 20902 123 24X Fiche 50-348, 83/10/06, 8310250472

--8310250485 Forwards IE Insp Repts 50-348/83-21 & 50-364/83-19 on 830816-19 & notice of violation VERRELLI, D M Division of Project & Resident Programs 83/09/09 McDONALD, R P Alabama Power Co 2pp 20902 125 24X Fiche 50-348, 83/10/06, 8310250472

--8310250490 Notice of violation from insp on 830816-19 * Division of Project & Resident Programs 83/09/09 2pp 20902 127 24X Fiche 50-348, 83/10/06, 8310250472

--8310250498 IE Insp Repts 50-348/83-21 & 50-364/83-19 on 830816-19 Noncompliance noted inadequate surveillance test procedures for fire detection sys, fire protection control valves & carbon dioxide hose reels & no fire stops for cable trays MILLER, W H., GIBBONS, T D., CONLON, T E Region 2, Office of Director 83/09/07 10pp 20902 129 24X Fiche 50-348, 83/10/06, 8310250472

8310280085 Forwards Amends 33 & 26 to Licenses NPF-2 & NPF-B, respectively & safety evaluation Amends consist of administrative changes to Tech Specs re administrative controls for onsite & offsite organization REEVES, E A Operating Reactors Branch 1 83/10/14 CLAYTON, F L Alabama Power Co 2pp 20965 001 24X Fiche 50-348, 83/10/14, 8310280085

--8310280092 Amends 33 & 26 to Licenses NPF-2 & NPF-B, respectively, making administrative changes to Tech Specs re administrative controls for onsite & offsite organization & environ qualification audits VARQA, S A Operating Reactors Branch 1 83/10/14 46pp 20965 003, 24X Fiche 50-348, 83/10/14, 8310280085

--8310280114 Safety evaluation supporting Amends 33 & 26 to Licenses NPF-2 & NPF-B, respectively * Office of Nuclear Reactor Regulation, Director 83/10/14 6pp 20965 049 24X Fiche 50-348, 83/10/14, 8310280085

8310210022 Informs of inaccuracy in design description for alternative shutdown capability transmitted in util 820701 ltr Local mechanical level indication not installed on condensate storage tank but will be added. CLAYTON, F L Alabama Power Co. 83/10/17 VARQA, S A Office of Nuclear Reactor Regulation, Director 2pp 20856 067 24X Fiche 50-348, 83/10/17, 8310210022

F Operating license stage documents & correspondence

8310240320 Addl response to FOIA request for documents re Tech Spec problems applicable to RCB leakage determinations in PWRs. Forwards App A documents Documents also available in PDR FELTON, J M Division of Rules and Records 83/07/14 VOIOT, H H LeBoeuf, Lamb, Leiby & MacRae 2pp 20907 036 24X Fiche 50-348, 83/07/14, 8310240320

--8010010786 Trip rept for site visit re development of portable calculator for RCS leak rates for PWRs Forwards programs for TI 57 & HP 41C calculators used during visit to compute leak rate. WOODRUFF, D C Division of Reactor Operations Inspections 80/08/14 JORDAN, E L Division of Reactor Operations Inspections 27pp 20907 039 24X Fiche 50-348, 83/07/14, 8310240320

DOCKETED ITEMS

219

B310030613 Forwards safety evaluation of shunt trip design for RPS DS 416 reactor trip breakers Design acceptable conditioned on receipt of confirmatory info & completion of action items listed
VARQA, S A Operating Reactors Branch 1 83/09/20 CLAYTON, F L
Alabama Power Co 3pp 20607 314 24X Fiche 50-348, 83/09/20, B310030613

--B310030615 Safety evaluation conditionally accepting shunt trip design for RPS DS 416 reactor trip breakers
* NRC - No Detailed Affiliation Given 83/09/14 18pp
20607 317 24X Fiche 50-348, 83/09/20, B310030613

B310050017 Forwards safety evaluation denying licensee B30304 application for amend to Licenses NPF-2 & NPF-B to allow continued plant operations w/more than one control rod immovable
VARQA, S A Operating Reactors Branch 1 83/09/21 CLAYTON, F L
Alabama Power Co 2pp 20650 268 24X Fiche 50-348, 83/09/21, B310050017

--B310050022 Safety evaluation denying licensee B30304 application for amend to Licenses NPF-2 & NPF-B to allow continued plant operations w/more than one control rod immovable Licensee must resolve potential core-wide mechanical problem
* NRC - No Detailed Affiliation Given 83/09/21 1p 20650 270
24X Fiche 50-348, 83/09/21, B310050017

B310030603 Forwards safety evaluation concurring w/licensee conclusions that NUREG-0737, Item II K 3 2 requirements met w/existing PORV, safety valve & reactor high trip pressure setpoints Automatic PORV isolation sys (Item II K 3 1) not required
VARQA, S A Operating Reactors Branch 1 83/09/23 CLAYTON, F L
Alabama Power Co 14pp 20604 212 24X Fiche 50-348, 83/09/23, B310030603

B310060096 Forwards four oversize drawings, in response to NRC request for addl info re svc water bldg battery sys design, per util B30303 & 0729 proposed Tech Spec changes involving dc distribution sys Aperture cards are available in PDR
CLAYTON, F L Alabama Power Co 83/09/23 VARQA, S A NRC - No Detailed Affiliation Given 2pp 20646 277 24X
Fiche 50-348, 83/09/23, B310060096

B310030414 Identifies specific Reg Guide 1.97 accident monitoring equipment sys for which extension requested, per B30520 & 0824 ltrs Schedules for upgrading equipment provided w/bases for extension request
CLAYTON, F L Alabama Power Co 83/09/27 VARQA, S A Office of Nuclear Reactor Regulation, Director 22pp 20593 087 24X
Fiche 50-348, 83/09/27, B310030414

B310040387 Submits evaluation of existing Westinghouse STB provisions, ASME Code Section XI, Reactor Safety Study (WASH 1400), NUREG-0677 & EG&G rept, "Inservice Leak Testing of Primary Pressure Isolation Valves," as applicable to plant design
CLAYTON, F L Alabama Power Co 83/09/27 VARQA, S A Office of Nuclear Reactor Regulation, Director 16pp 20625 200 24X
Fiche 50-348, 83/09/27, B310040387

B310140194 Application for amend to Licenses NPF-2 & NPF-B, changing Tech Specs to delete turbine valve testing requirements Testing program will be replaced w/insp & maint program for all throttle & governor valves
CLAYTON, F L Alabama Power Co 83/10/06 VARQA, S A Office of Nuclear Reactor Regulation, Director 4pp 20766 077 24X
Fiche 50-348, 83/10/06, B310140194

--B310140199 Proposed Tech Specs re limiting conditions for operation & surveillance requirements of turbine valve testing Turbine overspeed reliability assurance program encl Program withheld (ref 10CFR2.790)
* Alabama Power Co 83/10/06 15pp 20766 081 24X
Fiche 50-348, 83/10/06, B310140194

B310170407 Forwards status of licensing items requiring NRC approval
CLAYTON, F L Alabama Power Co 83/10/10 VARQA, S A Office of Nuclear Reactor Regulation, Director 11pp 20779 161 24X
Fiche 50-348, 83/10/10, B310170407

B310170416 Application to amend Licenses NPF-2 & NPF-B consisting of changes to Tech Spec re movable rod control sys requirements Encl clarifies B30304, 0603 & 0728 submittals in response to NRC B30921 request
CLAYTON, F L Alabama Power Co 83/10/10 VARQA, S A Office of Nuclear Reactor Regulation, Director 3pp 20779 195 24X
Fiche 50-348, 83/10/10, B310170416

--B310170423 Proposed Tech Spec changes re movable rod control sys requirements
* Alabama Power Co 83/10/10 5pp 20779 198 24X
Fiche 50-348, 83/10/10, B310170416

B310180280 Forwards list of application dates, fees paid, fees applicable & NRR fee determination & action on each item Based on NRR fee determinations, total of \$17,500 due Util will be notified of adjustments following final review
MILLER, M O License Fee Management Branch 83/10/11 CLAYTON, F L
Alabama Power Co 3pp 20827 126 24X Fiche 50-348, 83/10/11, B310180280

B310180308 Forwards response to B30916 request for most realistic schedule for inservice insp & testing items requiring NRC approval for fifth refueling outage Approval of proposed changes & SER rev by B40101 requested
CLAYTON, F L Alabama Power Co 83/10/11 VARQA, S A Office of Nuclear Reactor Regulation, Director 3pp 20803 098 24X
Fiche 50-348, 83/10/11, B310180308

B310210259 Application for amend to Licenses NPF-2 & NPF-B, changing Tech Specs to allow operation w/slightly positive moderator temp coefficient at low power levels & increased enthalpy hot channel factor (F Delta H) below full power
CLAYTON, F L Alabama Power Co 83/10/13 VARQA, S A Office of Nuclear Reactor Regulation, Director 50pp 20851 163 24X
Fiche 50-348, 83/10/13, B310210259

--B310210261 Proposed Tech Spec changes to allow operation w/slightly positive moderator temp coefficient at low power levels & increased enthalpy hot channel factor (F Delta H) limit below full power
* Alabama Power Co 83/10/13 13pp 20851 213 24X
Fiche 50-348, 83/10/13, B310210259

B310280085 Forwards Amends 33 & 26 to Licenses NPF-2 & NPF-B, respectively & safety evaluation Amends consist of administrative changes to Tech Specs re administrative controls for onsite & offsite organization
REEVES, E A Operating Reactors Branch 1 83/10/14 CLAYTON, F L
Alabama Power Co 2pp 20965 001 24X Fiche 50-348, 83/10/14, B310280085

--B310280092 Amends 33 & 26 to Licenses NPF-2 & NPF-B, respectively, making administrative changes to Tech Specs re administrative controls for onsite & offsite organization & environ qualification audits
VARQA, S A Operating Reactors Branch 1 83/10/14 46pp
20965 003 24X Fiche 50-348, 83/10/14, B310280085

--B310280114 Safety evaluation supporting Amends 33 & 26 to Licenses NPF-2 & NPF-B, respectively
* Office of Nuclear Reactor Regulation, Director 83/10/14 6pp,
20965 049 24X Fiche 50-348, 83/10/14, B310280085

B310250422 Responds to four items re shunt trip design for DS-416 reactor trip breakers, per NRC B30920 request Environ conditions considered in developing Westinghouse Owners Group generic design
CLAYTON, F L Alabama Power Co 83/10/20 VARQA, S A Office of Nuclear Reactor Regulation, Director 2pp 20897 182 24X
Fiche 50-348, 83/10/20, B310250422

B310270374 Application to amend License NPF-2, permitting one-time Tech Spec change re movable in-core detectors Change does not involve significant hazards consideration
CLAYTON, F L Alabama Power Co 83/10/21 VARQA, S A Office of Nuclear Reactor Regulation, Director 4pp 20924 017 24X
Fiche 50-348, 83/10/21, B310270374

--B310270378 Proposed one-time Tech Spec change re movable in-core detectors
* Alabama Power Co 83/10/21 2pp 20924 023 24X
Fiche 50-348, 83/10/21, B310270374

Q Inspection reports, IE Bulletins & correspondence

B310040374 Ack receipt of B30909 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-20 & 50-364/83-18
VERRELLI, D M Division of Project & Resident Programs 83/09/19
MCDONALD, R P Alabama Power Co 1p 20617 066 24X
Fiche 50-348, 83/09/19, B310040374

--B310040377 Responds to NRC B30819 ltr re violations noted in IE Insp Repts 50-348/83-20 & 50-364/83-18 Corrective actions' containment air cooler fan annunciator links 2A & 2B closed & chemistry control Procedure FNP-B-CCP-12 rewritten
CLAYTON, F L Alabama Power Co 83/09/09 VERRELLI, D M Division of Project & Resident Programs, 3pp 20617 067 24X
Fiche 50-348, 83/09/19, B310040374

--B310040378 Forwards IE Insp Repts 50-348/83-20 & 50-364/83-18 on B30714-0810 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/08/19
MCDONALD, R P Alabama Power Co 2pp, 20617 071 24X
Fiche 50-348, 83/09/19, B310040374

DOCKETED ITEMS

- 8310040379 Notice of violation from insp on 830711-0810
* Region 2, Office of Director 83/08/19 2pp 20417 073 24X
Fiche 50-348, 83/09/19, 8310040374
- 8310040384 IE Insp Repts 50-348/83-20 & 50-364/83-18 on 830711-0810
Noncompliance noted sulfuric acid std used to check
hydrometers not listed on licensee test equipment inventory
& maint schedule & containment air cooler fan links open
BRADFORD, W H, RULAND, W H Region 2, Office of Director
CANTRELL, F B Division of Project & Resident Programs 83/08/18
10pp 20417 075 24X Fiche 50-348, 83/09/19, 8310040374
- 8310250376 Forwards IE Insp Repts 50-348/83-22 & 50-364/83-20 on
830829-31 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/09/19
MCDONALD, R P Alabama Power Co 2pp 20898 130 24X
Fiche 50-348, 83/09/19, 8310250376
- 8310250387 IE Insp Repts 50-348/83-22 & 50-364/83-20 on 830829-31. No
noncompliance noted Major areas inspected, licensee action on
previous insp followup items & two licenses reported events
involving spread of contamination.
DEBB, B T Region 2, Office of Director BARR, K P Division of
Engineering & Operational Programs 83/09/14 4pp 20898 132.
24X Fiche 50-348, 83/09/19, 8310250376
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder
Qualification Tests." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 117pp 20754 022. 24X Fiche 50-000, 83/09/26, 8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
Detectors Positioned at Control Room Ventilation Air
Intakes." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 116pp 20777 210. 24X Fiche 50-000, 83/09/26, 8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse
Type BA-1 Differential Relays." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 118pp 20778:001 24X Fiche 50-000, 83/09/26, 8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to
Safety-Related Sys W/o LOCFR50 59 Evaluation." Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New
York, Inc 115pp 20716, 324. 24X Fiche 50-000, 83/09/29, 8308300349
- 8310140174 Application for amend to Licenses NPF-2 & NPF-8, changing
Tech Specs to delete turbine valve testing requirements.
Testing program will be replaced w/insp & maint program for
all throttle & governor valves.
CLAYTON, F L Alabama Power Co 83/10/06 VARQA, S A Office of
Nuclear Reactor Regulation, Director 4pp 20766 077 24X
Fiche 50-348, 83/10/06, 8310140174
- 8310140199 Proposed Tech Specs re limiting conditions for operation &
surveillance requirements of turbine valve testing Turbine
overspeed reliability assurance program encl Program
withheld (ref 10CFR2 790).
* Alabama Power Co. 83/10/06 15pp 20766, 081 24X
Fiche 50-348, 83/10/06, 8310140174
- 8310250472 Ack receipt of 830921 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-348/83-21 &
50-364/83-19 Request for 60-day extension for response to
violations approved
VERRELLI, D M Division of Project & Resident Programs 83/10/06
MCDONALD, R P Alabama Power Co 2pp 20902 121 24X
Fiche 50-348, 83/10/06, 8310250472
- 8310250479 Responds to NRC 830909 ltr re violations noted in IE Insp
Repts 50-348/83-21 & 50-364/83-19. Corrective actions
detailed review of fire protection program underway
Extension of 60 days requested for response
CLAYTON, F L Alabama Power Co. 83/09/21 VERRELLI, D M Division
of Project & Resident Programs 2pp. 20902 123 24X
Fiche 50-348, 83/10/06, 8310250472.
- 8310250485 Forwards IE Insp Repts 50-348/83-21 & 50-364/83-19 on
830816-19 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/09/09
MCDONALD, R P Alabama Power Co 2pp 20902, 125 24X
Fiche 50-348, 83/10/06, 8310250472.
- 8310250490 Notice of violation from insp on 830816-19
* Division of Project & Resident Programs. 83/09/09. 2pp
20902 127 24X Fiche 50-348, 83/10/06, 8310250472
- 8310250498 IE Insp Repts 50-348/83-21 & 50-364/83-19 on 830816-19
Noncompliance noted inadequate surveillance test procedures
for fire detection sys, fire protection control valves &
carbon dioxide hose reels & no fire stops for cable trays
MILLER, W H, GIBBONS, T D, CONLON, T E Region 2, Office of
Director 83/09/07 10pp 20902 129 24X Fiche 50-348, 83/10/06,
8310250472
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass
Loops Used in Westinghouse Plants." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical
Facility." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect
Causes Production of Noxious Gases." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective
Self-Contained Breathing Apparatus Air Cylinders." Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761
- 8310180308 Forwards response to 830716 request for most realistic
schedule for inservice insp & testing items requiring NRC
approval for fifth refueling outage Approval of proposed
changes & SER rev by 840101 requested
CLAYTON, F L Alabama Power Co 83/10/11 VARQA, S A Office of
Nuclear Reactor Regulation, Director 3pp 20803 098 24X
Fiche 50-348, 83/10/11, 8310180308
- A Periodic operating reports & related correspondence

- 8310180124 Monthly operating rept for Sept 1983 W/831012 ltr
HAIRSTON, W O, CLAYTON, F L Alabama Power Co 83/10/04 NRC - No
Detailed Affiliation Given 9pp 20807 154 24X
Fiche 50-348, 83/10/04, 8310180124
- B Reportable occurrences, LERs & related correspondence

- 8310070138 LER 83-038/03L-0 on 830829, instrumentation channels
associated w/level indicators LI-3594A & LI-3594B declared
inoperable when indicators turned off Caused by procedural
inadequacy Procedure revised W/830927 ltr
HAIRSTON, W O, CLAYTON, F L Alabama Power Co 83/09/27 Region
2, Office of Director 3pp 20659 035 24X Fiche 50-348, 83/09/27,
8310070138
- 8310070296 Forwards LERs 83-057/03L-0 & 83-036/03L-0
CLAYTON, F L Alabama Power Co 83/09/30 Region 2, Office of
Director 1p 20651 075 24X Fiche 50-348, 83/09/30, 8310070296
- 8310070299 LER 83-057/03L-0 on 830831, radiation monitor R-11
containment atmosphere particulate activity indication
decreased off-scale Caused by increase in containment
background radiation Mods made to increase range of R-11
HAIRSTON, W O Alabama Power Co 83/09/30 Region 2, Office of
Director 1p 20651 076 24X Fiche 50-348, 83/09/30, 8310070296
- 8310070302 LER 83-036/03L-0 on 830831, following failure alarm on power
cabinet 2BD, rod control sys declared inoperable Caused by
blown fuse Fuse & blown fuse indicator replaced
HAIRSTON, W O Alabama Power Co 83/09/30 Region 2, Office of
Director 1p 20651 077 24X Fiche 50-348, 83/09/30, 8310070296
- 8310070301 Potential Part 21 rept re underrange characteristic of
Model N-E110M transmitter Underrange zero offset may occur
when transmitter initially pressurized from atmospheric to
suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30, Director's Office, Office
of Inspection and Enforcement 11pp 20651 064 24X
Fiche 50-000, 83/09/30, 8310070301
- 8310120350 Forwards LERs 83-060/03L-0, 83-061/03L-0, 83-037/03L-0 &
83-038/03L-0 W/o LER 83-038/03L-0
CLAYTON, F L Alabama Power Co 83/10/04 Region 2, Office of
Director 1p 20699 317. 24X Fiche 50-348, 83/10/04, 8310120350

DOCKETED ITEMS

221

--B310120356 LER B3-060/03L-0 on B30912, instrumentation channel for flow transmitter FF-415 declared inoperable due to erratic indications Caused by failure of NLP card Card replaced
HAIRSTON, W Q Alabama Power Co 83/10/04 Region 2, Office of Director Ip 20699 318 24X Fiche 50-348, B3/10/04, B310120350

--B310120363 LER B3-061/03L-0 on B30913, instrumentation channel associated w/level transmitter LT-459 declared inoperable when found out of tolerance Caused by failure of NLP card Card replaced & channel declared operable
HAIRSTON, W Q Alabama Power Co 83/10/04 Region 2, Office of Director Ip 20699 319 24X Fiche 50-348, B3/10/04, B310120350

--B310120371 LER B3-037/03L-0 on B30907, battery bank 2A declared inoperable Caused by decrease in voltage on cell 56 below Tech Spec 3 B 2 3 requirements Cell cleaned & charged Sys restored
HAIRSTON, W Q Alabama Power Co 83/10/04 Region 2, Office of Director Ip 20699 320 24X Fiche 50-348, B3/10/04, B310120350

B310140226 Forwards LERs B3-059/03L-0 & B3-062/03L-0
CLAYTON, F L Alabama Power Co 83/10/06 Region 2, Office of Director Ip 20761 250 24X Fiche 50-348, B3/10/06, B310140226

--B310140229 LER B3-059/03L-0 on B30906, train B control room emergency air cleanup sys declared inoperable when train B air conditioner compressor tripped Caused by solenoid valve linkage on pump down line out of adjustment
HAIRSTON, W Q Alabama Power Co 83/10/06 Region 2, Office of Director Ip 20761 251 24X Fiche 50-348, B3/10/06, B310140226

--B310140235 LER B3-062/03L-0 on B30907, during calibr & functional test, train B chlorine detector declared inoperable when zero potentiometer found to be malfunctioning Potentiometer replaced
HAIRSTON, W Q Alabama Power Co 83/10/06 Region 2, Office of Director Ip 20761 252 24X Fiche 50-348, B3/10/06, B310140226

DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1

A Application/construction stage documents & correspondence

B310210315 Responds to FOIA request for documents re decision to conduct Caseload Forecast Panel meetings & only tour facility & any documents re rationale or basis for decision
Forwards documents
FELTON, J M Division of Rules and Records 83/07/29 SUGARMAN, R J Sugarman & Denworth 2pp 20883 170 24X Fiche 50-352, B3/07/29, B310210315

--B303230300 Requests Caseload Forecast Panel site visit to update assessment of const completion status
EISENHUT, D Q Division of Licensing 83/03/16 HARTFIELD, R A Management Information Branch Ip 20883 194 24X Fiche 50-352, B3/07/29, B310210315

B310050360 Notification of B30926 meeting w/util in Bethesda, MD to discuss draft DNL rept on core melt frequency
HARTIN, R E Licensing Branch 2 83/09/21 SCHWENCER, A Licensing Branch 2 App 20650 043 24X Fiche 50-352, B3/09/21, B310050360

B310050455 Notification of Significant Licensee Meeting B3-84 on B31018 w/util at site to discuss status of const & preoperational testing (Module 303018)
CONNER, E L Region 1, Office of Director 83/09/26 Region 1, Office of Director Ip 20690 033, 24X Fiche 50-352, B3/09/26, B310050455

B310040296 Provides addl info re thermal hydraulic stability, per B30624 verbal request Cncl revised FSAR tables will be incorporated into FSAR rev scheduled for Oct 1983
KEMPER, J S Philadelphia Electric Co, 83/09/28 SCHWENCER, A Licensing Branch 2 App 20614 207 24X Fiche 50-352, B3/09/28, B310040296

B310040124 Forwards response to Equipment Qualification Branch B20730 request for addl info re audits by Seismic & Dynamic Qualification & Pump & Valve Operability Review Teams Util will be notified of items selected for B31015 audit
KEMPER, J S Philadelphia Electric Co 83/09/30 SCHWENCER, A Licensing Branch 2 1225pp 20608 202 24X Fiche 50-352, B3/09/30, B310040124

--B310040127 Rev 0 to Procedure B031-0-14, "General Project Requirements for Seismic Design & Analysis of Equipment Supports"
Bechtel Corp 83/08/19 212pp 20609 215 24X Fiche 50-352, B3/09/30, B310040124

--B310040129 Rev 1 to Procedure B031-0-19, "Required Response Spectra (RRS) of Primary Containment for Load Combinations of Seismic & Hydrodynamic Loads"
Bechtel Corp 81/08/02 190pp 20610 067 24X Fiche 50-352, B3/09/30, B310040124

--B310040131 Rev 2 to Procedure B031-0-19, "Required Response Spectra (RRS) of Reactor Bldg & Control Room Structure for Load Combinations of Seismic & Hydrodynamic Loads"
Bechtel Corp 82/01/29 530pp 20610 297 24X Fiche 50-352, B3/09/30, B310040124

B310040431 Forwards response to B20730 ltr re operability qualification of pumps & valves Qualification & installation of active pumps & valves 90% complete, per B30916 telcon
KEMPER, J S Philadelphia Electric Co 83/09/30 SCHWENCER, A Licensing Branch 2 57pp 20617 296 24X Fiche 50-352, B3/09/30, B310040431

B310140093 Forwards analysis of dust loading on first HEPA filter in ESF HVAC filtration train, as discussed in B30926 telcon
Dust loading capabilities not exceeded
KEMPER, J S Philadelphia Electric Co 83/10/03 SCHWENCER, A Licensing Branch 2 7pp 20767 052 24X Fiche 50-352, B3/10/03, B310140093

B310070243 Forwards revised draft FSAR Page 13 4-B adding superintendent, nuclear training section to operating experience assessment committee, per B30929 conference call
Rev will be incorporated in Nov 1983 FSAR rev
BRADLEY, E J Philadelphia Electric Co 83/10/04 SCHWENCER, A Licensing Branch 2 3pp 20658 335 24X Fiche 50-352, B3/10/04, B310070243

B310120062 Advises that operation of facility will not adversely affect significant or archaeological resources, provided investigations performed & negative visual impacts eliminated
WILLIAMS, D Pennsylvania, Commonwealth of, 83/10/05 SCHWENCER, A Licensing Branch 2 Ip 20696 156 24X Fiche 50-352, B3/10/05, B310120062

B310140177 Discusses actions to be taken to revise & expand upon applicant B1104 ltr, in response to NRC B30831 request.
Areas discussed include pipe replacement, matl corrections & additions & nonconforming welds in Class 1 sys
KEMPER, J S Philadelphia Electric Co 83/10/05 EISENHUT, D Q Division of Licensing 16pp 20762 333 24X Fiche 50-352, B3/10/05, B310140177

B310140278 Forwards draft response to B30915 Request for Addl Info RAI 271 2 re qualification of automatic depressurization sys accumulators per TMI Item II K 3 28 Response will be incorporated in Nov 1983 FSAR rev
BRADLEY, E J Philadelphia Electric Co 83/10/05 SCHWENCER, A Licensing Branch 2 9pp 20761 184 24X Fiche 50-352, B3/10/05, B310140278

B310120148 Forwards clarification of requested info on misplaced bundle accident analysis, per B30715 telcon Draft replacement for FSAR Table 15 4-6 encl Info will be incorporated into next FSAR rev
KEMPER, J S Philadelphia Electric Co 83/10/07 SCHWENCER, A Licensing Branch 2 4pp 20696 018 24X Fiche 50-352, B3/10/07, B310120148

B310140097 Forwards Amend 57 to OL application, consisting of "Electrical Equipment Environ Qualification Rept" dtd Oct 1983, replacing earlier version
BRADLEY, E J Philadelphia Electric Co 83/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20755 001, 24X Fiche 50-352, B3/10/07, B310140097

--B310140101 Amend 57 to OL application, consisting of "Electrical Equipment Environ Qualification Rept" dtd Oct 1983, replacing earlier version Certificate of Svc encl
BOYER, V S BRADLEY, E J Philadelphia Electric Co 83/10/06 6pp 20755 003 24X Fiche 50-352, B3/10/07, B310140097

--B310140103 "Electrical Equipment Environ Qualification Rept, Limerick Generating Station Units 1 & 2, Vols 1-3"
NUTECH Engineers, Inc 83/10/31 1,667pp 20755 009 24X Fiche 50-352, B3/10/07, B310140097

C Utility Environmental Report (ER), amends & correspondence

B310180423 Forwards "Limerick Generating Station Request For Addl Info Environ Rept - OL Stage Question E451, B, FSAR Question 451 G, Joint Frequency Distributions of Wind Direction & Speed by Atmospheric Stability Class."
KEMPER, J S Philadelphia Electric Co 83/10/13 SCHWENCER, A Licensing Branch 2 App 20803 318 24X Fiche 50-352, B3/10/13, B310180423

DOCKETED ITEMS

D NRC Draft/Final Environmental Statements, supplis & correspondence

8310180420 Advises that results of review of DES re water supply consistent w/Findings of Delaware River Commission Rept should address low level radwaste storage & disposal
PASTOR, R J Pennsylvania, Commonwealth of, 83/10/04 SCHWENCER, A
Licensing Branch 2 3pp 20803 221 24X Fiche 50-352, 83/10/04, 8310180420

E NRC Safety Evaluation Report (SER), supplis & correspondence

8310070190 Summary of 830615 meeting w/util, Bechtel & OE in Bethesda, MD re open SER issue concerning high radiation signal on containment purge vent valves w/respect to placement of radiation monitors & isolation requirements
MARTIN, R E Licensing Branch 2 83/09/29 Licensing Branch 2
13pp 20680 235 24X Fiche 50-352, 83/09/29, 8310070190

8310110132 Forwards draft revs to FSAR re SER Open Item Issue 19 concerning frequency classification of generator load rejection w/bypass failure & turbine trip w/bypass failure events FSAR revs scheduled for Nov 1983
KEMPER, J S Philadelphia Electric Co 83/10/03 SCHWENCER, A
Licensing Branch 2 9pp 20666, 279 24X Fiche 50-352, 83/10/03, 8310110132

8310120392 Forwards draft revs to FSAR Sections 1, B, 5, 2 & 7 & draft revised response to FSAR Question 410 23, per 831222 meeting re SER Open Issue 8 concerning airborne particulate radioactivity monitoring sys
KEMPER, J S Philadelphia Electric Co 83/10/05 SCHWENCER, A
Licensing Branch 2 25pp 20698, 060 24X Fiche 50-352, 83/10/05, 8310120392

8310260316 Summary of 830707 meeting w/util in Bethesda, MD re overpressurization of standby gas treatment sys ductwork & filters issue resolved. Disposition discussed in SER.
NUREG-0991 issued in Aug 1983
MARTIN, R E Licensing Branch 2 83/10/19 Licensing Branch 2
19pp 20921 220 24X Fiche 50-352, 83/10/19, 8310260316

F Security, medical, emergency & fire protection plans

8310040110 Forwards final schedule for satisfying requirements of Generic Ltr 82-33 re Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability"
SCHWENCER, A Licensing Branch 2 83/09/26 BAUER, E O
Philadelphia Electric Co 4pp 20634 336 24X
Fiche 50-352, 83/09/26, 8310040110

8310180423 Forwards "Limerick Generating Station Request For Addl Info Environ Rept - OL Stage Question E451 B, FSAR Question 451 9, Joint Frequency Distributions of Wind Direction & Speed by Atmospheric Stability Class . . ."
KEMPER, J S Philadelphia Electric Co 83/10/13 SCHWENCER, A
Licensing Branch 2 4pp 20803 318 24X Fiche 50-352, 83/10/13, 8310180423

8310280127 Responds to NRC 830926 ltr re schedule for meeting emergency response capability requirements. Const schedule will permit fuel loading by 840801 Full scale emergency preparedness exercise rescheduled to 840725
BOYER, V B Philadelphia Electric Co 83/10/25 SCHWENCER, A
Licensing Branch 2 3pp 20929 273 24X Fiche 50-352, 83/10/25, 8310280127

G Adjudicatory correspondence

8309130054 Forwards receipts indicating that draft offsite emergency plans received by City of Philadelphia & by J Dorsey on behalf of intervenors
BRADLEY, E J Philadelphia Electric Co 83/09/07 BRENNER, L
MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel
4pp 20356 177 24X Fiche 50-352, 83/09/07, 8309130054

8310030437 Motion to modify wording of Contention V-4 on carburetor icing.
ROMANO, F R Air and Water Pollution Patrol 83/09/26 BRENNER, L
COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 1p
20602, 094, 24X Fiche 50-352, 83/09/26, 8310030437

110030423 Notice of withdrawal of appearance in proceeding Certificate of Svc encl.
CHAM, E I Hearing Branch 2 83/09/27 3pp 20632, 351 24X
Fiche 50-352, 83/09/27, 8310030423

10040491 Motion to reward Contention I-62 re pressurized thermal shock, in response to ASLB 830913 memorandum & order Certificate of Svc encl
LEWIS, M I 83/09/28 Atomic Safety and Licensing Board Panel 3pp 20625 162 24X Fiche 50-352, 83/09/28, 8310040491

8310040498 Respect of Contention I-41 re sys interaction Certificate of Svc encl
DORSEY, J A Limerick Ecology Action DORSEY, J A Dorsey, J A
83/09/28 BRENNER, L, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 8pp 20625 152 24X Fiche 50-352, 83/09/28, 8310040498

8310040187 Memorandum & order re util 830927 motion for summary disposition of Contention V-4 Util directed to file new statement of matl fact w/supporting citations by 831006
BRENNER, L Atomic Safety and Licensing Board Panel 83/09/30
Philadelphia Electric Co 5pp 20608 084 24X
Fiche 50-352, 83/09/30, 8310040187

8310040627 Rept per ASLB 830913 memorandum & order re establishment of hearing schedule & re MI Lewis, Friends of the Earth & Air & Water Pollution Patrol contentions Certificate of Svc encl
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/09/30 6pp 20626 183 24X Fiche 50-352, 83/09/30, 8310040627

8310050429 Response to Limerick Ecology Action 830831 proposed severe accident assessment rept/enviro rept - OL stage (SARA/EROL) Section 7 contentions & City of Philadelphia 830920 SARA concerns
VOGLER, B H Hearing Branch 2 83/09/30 Atomic Safety and Licensing Board Panel 14pp 20633 216 24X Fiche 50-352, 83/09/30, 8310050429

--8310050432 Rept on behalf of applicant, M Lewis, Air & Water Pollution Patrol, Friends of the Earth & Limerick Ecology Action, in response to ASLB 830913 memorandum re hearing schedule proposals Certificate of Svc encl
HODGSON, A P Hearing Branch 2 83/09/30 Atomic Safety and Licensing Board Panel 6pp 20633 230 24X Fiche 50-352, 83/09/30, 8310050432

8310060305 Forwards author notice of appearance in proceeding Author should be substituted for TY Au on svc list Certificate of Svc encl
FERKIN, Z O Pennsylvania, Commonwealth of, 83/09/30 BRENNER, L
MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 5pp 20644 196 24X Fiche 50-352, 83/09/30, 8310060305

8310040183 Memorandum & order shortening schedule for answers to respect of Limerick Ecology Action Contention I-41 re sys interaction Util answer shall be received by NRC by 831007 & by ASLB & Limerick by 831011
BRENNER, L Atomic Safety and Licensing Board Panel 83/10/03 4pp
20608 080 24X Fiche 50-352, 83/10/03, 8310040183

8310050515 Brief opposing Del-Aware Unlimited, Inc exceptions to ASLB 830308 partial initial decision & 830601 memorandum & order denying Del-Aware motion to reopen record Notice of appearance & Certificate of Svc encl
CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn 83/10/03 Atomic Safety and Licensing Appeal Panel 120pp 20630 210 24X Fiche 50-352, 83/10/03, 8310050515

8310110052 Memorandum & order re hearing schedules proposed by parties NRC schedule essentially acceptable
BRENNER, L Atomic Safety and Licensing Board Panel 83/10/04 4pp
20668 265 24X Fiche 50-352, 83/10/04, 8310110052

8310110305 Second interim rept to ASLB re Contention VI-1
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/04 1p 20665 337 24X Fiche 50-352, 83/10/04, 8310110305

--8310110307 Affidavit of VB Boyer re review of welds in 1976 under responsibility of QC inspector Certificate of Svc encl
BOYER, V B Philadelphia Electric Co 83/09/29 4pp 20665 340
24X Fiche 50-352, 83/10/04, 8310110307

8310130037 Advises that hearing schedule & rept to ASLB inadvertently stapled to response to Limerick Ecology Action & City of Philadelphia 830930 severe accident risk assessment contentions Inconvenience regretted
VOGLER, B H Hearing Branch 2 83/10/04 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 1p 20726 289
24X Fiche 50-352, 83/10/04, 8310130037

8310110291 Supplemental affidavit of ME Smith in support of motion for summary disposition of Contention V-4
SMITH, M E Philadelphia Electric Co 83/10/05 3pp 20666, 080
24X Fiche 50-352, 83/10/05, 8310110291

--8310110297 Revised statement of matl facts as to which there is no genuine issue to be heard
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/05 11pp 20666 083 24X
Fiche 50-352, 83/10/05, 8310110297

DOCKETED ITEMS

223

- 8310110300 Affidavit of VS Boyer re Contention V-4 concerning cross-flow natural draft evaporative cooling towers
BOYER, V S Philadelphia Electric Co 83/10/05 1p 20666 094
24X Fiche 50-352, 83/10/05, 8310110291
- 8310110312 Forwards executed signature page of affidavit of ME Smith & D Seymour in support of motion for summary disposition re Contention V-4 Encl page should be substituted for page sent on 830926 Certificate of Svc encl
WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co 83/10/05 Docketing & Services Branch 5pp 20666 095 24X Fiche 50-352, 83/10/05, 8310110291
- 8310110212 Requests assurance that former employment w/NRC does not preclude appearance as counsel for applicant Response by 831019 requested
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/06 LAVERTY, J H Conner & Wetterhahn 1p 20665 061 24X Fiche 50-352, 83/10/06, 8310110212
- 8310110275 Answer to Friends of the Earth 830927 petition for extension of time & scheduling of evidentiary hearings after 840101 & motion to dismiss Contentions V-3a & V-3b, or for other sanctions
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/06 Atomic Safety and Licensing Board Panel 11pp 20666 166 24X Fiche 50-352, 83/10/06, 8310110275
- 8310110277 Answer opposing Air & Water Pollution Control 830926 motion to reword Contentions I-62 & V-4
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/06 Atomic Safety and Licensing Board Panel 3pp 20666 182 24X Fiche 50-352, 83/10/06, 8310110275
- 8310110284 Forwards VS Boyer 831005 affidavit re Contention V-4
WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co 83/10/06 Docketing & Services Branch 2pp. 20666 185 24X Fiche 50-352, 83/10/06, 8310110275
- 8310110287 Notice of transmittal of addl matl re Limerick Ecology Action Contention I-42
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/06 2pp 20666 18/ 24X Fiche 50-352, 83/10/06, 8310110275
- 8310110292 Answer opposing Limerick Ecology Action respect of Contention I-41 re exacerbation of accidents Contention I-62 & specifically Certificate of Svc encl
WETTERHAHN, M J Philadelphia Electric Co 83/10/06 Atomic Safety and Licensing Board Panel 11pp 20666 189 24X Fiche 50-352, 83/10/06, 8310110275
- 8310120364 Motion for summary disposition of Contentions V-3a & V-3b No genuine issue of matl fact exists & util entitled to favorable decision
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/07 Atomic Safety and Licensing Board Panel 1p 20753 041. 24X Fiche 50-352, 83/10/07, 8310120364
- 8310120368 Statement of matl facts as to which there is no genuine issue re Contentions V-3a & V-3b
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/07 Atomic Safety and Licensing Board Panel 10pp 20753 342 24X Fiche 50-352, 83/10/07, 8310120364
- 8310120377 Memorandum supporting util motion for summary disposition of Contentions V-3a & V-3b re postulated failure of two pipelines & effect on plant No substantive answers provided to util discovery requests
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/07 Atomic Safety and Licensing Board Panel 14pp. 20753 392 24X Fiche 50-352, 83/10/07, 8310120364
- 8310120384 Affidavit of JD Walsh supporting motion for summary disposition of Contentions V-3a & V-3b No adverse effects on safety-related structures would occur if natural gas in pipeline detonated One aperture card available in PDR
WALSH, J D Philadelphia Electric Co WALSH, J D Bechtel Corp 83/10/06 11pp 20754 003 24X Fiche 50-352, 83/10/07, 8310120364
- 8310120388 Affidavit of VS Boyer supporting motion for summary disposition ARCO pipeline owner, agreed to prohibit shipping of propane in & through pipelines on plant premises Certificate of Svc encl
BOYER, V S Philadelphia Electric Co 83/10/06 Bpp 20754 014 24X Fiche 50-352, 83/10/07, 8310120364
- 8310180419 Response supporting motions to reword Contention V-4 Applicant objections to rewording deal w/semantics only Effect of steam release not limited to visible plume only Certificate of Svc encl
ROMANO, F R Air and Water Pollution Patrol 83/10/08 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 1p 20803 012 24X Fiche 50-352, 83/10/08, 8310180419
- 8310140071 Reply to util & NRC responses to Limerick Ecology Action severe accident risk assessment Contentions Certificate of Svc encl
ELLIOTT, C W Limerick Ecology Action 83/10/10 Atomic Safety and Licensing Board Panel 69pp 20767 063 24X Fiche 50-352, 83/10/10, 8310140071
- 8310170511 Brief in opposition to Del-Aware Unlimited, Inc exceptions to ASLB Partial Initial Decision LBP-83-11 & to ASLB 830601 order denying motion to reopen record No reversible error committed Certificate of Svc encl
HODGSON, A P Hearing Branch 2 83/10/12 Atomic Safety and Licensing Appeal Panel 41pp 20784 151 24X Fiche 50-352, 83/10/12, 8310170511
- 8310180132 Motion for summary disposition of Contention I-62
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/12 Atomic Safety and Licensing Board Panel 1p 20807 097 24X Fiche 50-352, 83/10/12, 8310180132
- 8310180139 Memorandum in support of motion for summary disposition of Contention I-62 re pressurized thermal shock (PTS) PTS will not be problem due to conservative design, matl selection, const, testing, operation & surveillance
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/12 Atomic Safety and Licensing Board Panel 13pp 20807 098 24X Fiche 50-352, 83/10/12, 8310180132
- 8310180146 Statement of matl facts as to which there is no genuine issue to be heard re Contention I-62
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/12 Atomic Safety and Licensing Board Panel 9pp 20807 113 24X Fiche 50-352, 83/10/12, 8310180132
- 8310180192 Statement of S Ranganath, LB Burns, FE Cooke & SE Carter in support of motion for summary disposition of Contention I-62 Prof qualifications & Certificate of Svc encl
RANGANATH, S, BURNS, L B, COOKE, F E Philadelphia Electric Co 83/10/11 31pp 20807, 122 24X Fiche 50-352, 83/10/12, 8310180132.
- 8310190040 Request for followup to 830927 application to make limited appearance statement before ASLB
ANTHONY, R L Anthony, R L 83/10/12 Atomic Safety and Licensing Board Panel 1p 20823 172 24X Fiche 50-352, 83/10/12, 8310190040
- 8310190044 Response to ASLB 830913 & 1005 memoranda & orders & 831007 & 12 telcons w/NRC. Intervenor has no affidavit from util as to exact ARCO pipeline location
ANTHONY, R L Anthony, R L 83/10/12 1p 20823 173 24X Fiche 50-352, 83/10/12, 8310190040
- 8310190058 Reply to NRC & util filings re severe accident risk assessment/enviro rpt - DL stage, Section 7 issues Assessment grossly deficient Impact on environ cannot be properly assessed Certificate of Svc encl
BUSH, M W Philadelphia, PA 83/10/12 Atomic Safety and Licensing Board Panel 13pp 20823 198 24X Fiche 50-352, 83/10/12, 8310190058
- 8310250100 Response opposing Limerick Ecology Action 830928 respecified Contention I-41 re sys interaction analysis. Contention lacks required specificity & regulatory basis Notice of appearance & Certificate of Svc encl
WRIGHT, N A Hearing Branch 2. 83/10/13 Atomic Safety and Licensing Board Panel 12pp. 20695 279 24X Fiche 50-352, 83/10/13, 8310250100
- 8310180234 Answer opposing Air & Water Pollution Control 831002 motion for production of welder certification & for independent retesting involving reactor Motion unsupported & w/o basis
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/14 Atomic Safety and Licensing Board Panel. 3pp 20806 251. 24X Fiche 50-352, 83/10/14, 8310180234
- 8310180237 Proposed schedule of util, NRC & M Lewis for hearing of Contentions I-62, V-3a, V-3b & V-4 Certificate of Svc encl
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/14 5pp. 20808 254 24X Fiche 50-352, 83/10/14, 8310180234

DOCKETED ITEMS

8310180243 Advises of no conflict of interest between previous NRC employment & current employment w/Conner & Wetterhahn re licensing proceeding
LAVERY, J H Conner & Wetterhahn LAVERY, J H Philadelphia Electric Co 83/10/14 KOHL, C N, DOTCHY, R L, EDLES, G J Atomic Safety and Licensing Appeal Panel 2pp 20808 249 24X Fiche 50-352, 83/10/14, 8310180243

8310250342 Response to Intervenor Air & Water Pollution Patrol 830926 motion to reward Contention V-4 & Intervenor MI Lewis 830928 motion to reward Contention I-62 in response to ASLB 830913 memorandum & order Motions should be denied
VOGLER, D H Hearing Branch 2 83/10/17 Atomic Safety and Licensing Board Panel 3pp 20898 030 24X Fiche 50-352, 83/10/17, 8310250342

--8310250344 Response to Friends of the Earth 830927 petition for extension of time to reward Contentions V-3a & V-3b & scheduling of evidentiary hearing after 840101 & to applicant motion to dismiss Certificate of Svc encl
VOGLER, D H Hearing Branch 2 83/10/17 Atomic Safety and Licensing Board Panel 7pp 20898 033 24X Fiche 50-352, 83/10/17, 8310250342

8310250289 Forwards revised pages to NRC 831012 brief, correcting four inadvertent errors.
RUTBERG, J Hearing Branch 2 83/10/18 KOHL, C N, EDLES, G J, DOTCHY, R L Atomic Safety and Licensing Appeal Panel 4pp 20895 347 24X Fiche 50-352, 83/10/18, 8310250289

--8310250292 Corrected pages to 831012 brief in opposition to Del-Aware Unlimited appeal
* Office of the Executive Legal Director 83/10/18 Atomic Safety and Licensing Appeal Panel 4pp 20895 351 24X Fiche 50-352, 83/10/18, 8310250292

8310240188 Memorandum & order confirming 831017 & 18 prehearing conference rulings on status of certain parties & schedule re Air & Water Pollution Patrol, Friends of the Earth & Lewis contentions Courtesy notification encl
BRENNER, L Atomic Safety and Licensing Board Panel 83/10/20 Air and Water Pollution Patrol 7pp 20878 092 24X Fiche 50-352, 83/10/20, 8310240188

8310260273 Advises of intention to continue as party to litigation on issues re emergency planning w/o svc list Related correspondence
HERSHEY, B P Community Legal Services, Inc HERSHEY, B P CEPA 83/10/21 BRENNER, L Atomic Safety and Licensing Board Panel 1p 20911 308 24X Fiche 50-352, 83/10/21, 8310260273

8310310336 Response to util 830917 statement of matl fact as to which there is no genuine issue to be heard re motion for summary disposition of Contention V-4 Cooling tower plume issue
unaddressed, w/Certificate of Svc
ROMANO, F R Air and Water Pollution Patrol 83/10/21 Atomic Safety and Licensing Board Panel 10pp 20959 071 24X Fiche 50-352, 83/10/21, 8310310336

--8310310353 Statement of matl facts as to which there is genuine issue to be heard re cooling tower plumes.
ROMANO, F R Air and Water Pollution Patrol 83/10/21 Atomic Safety and Licensing Board Panel 5pp 20959 081 24X Fiche 50-352, 83/10/21, 8310310353

--8310310371 Affidavit of FR Romano re summary disposition of Contention V-4
ROMANO, F R Air and Water Pollution Patrol 83/10/21 3pp 20959 086 24X Fiche 50-352, 83/10/21, 8310310371

10270268 Statement of matl facts as to which there is genuine issue as to Contention I-62 Certificate of Svc encl
LEWIS, M I Lewis, M 83/10/24 Atomic Safety and Licensing Board Panel 2pp 20923 327 24X Fiche 50-352, 83/10/24, 8310270268

8310270356 Statement supporting response to applicant motion for summary disposition of Contention I-62
LEWIS, M I Lewis, M 83/10/24 Atomic Safety and Licensing Board Panel 7pp 20923 329 24X Fiche 50-352, 83/10/24, 8310270356

10270362 Rebuttal to applicant 831012 statement of matl facts as to which there is no genuine issue as to Contention I-62
LEWIS, M I Lewis, M 83/10/24 Atomic Safety and Licensing Board Panel 3pp 20923 338 24X Fiche 50-352, 83/10/24, 8310270362

10270368 Response opposing applicant 830927 motion for summary disposition of Contention I-62
* Lewis, M 83/10/24 Atomic Safety and Licensing Board Panel 3pp 20923 341 24X Fiche 50-352, 83/10/24, 8310270368

8310310231 Request for official notice of Federal regulation of ultralight aircraft, 47FR38770 Certificate of Svc encl
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/27 Atomic Safety and Licensing Board Panel 14pp 20947 210 24X Fiche 50-352, 83/10/27, 8310310231

H General correspondence

8310210295 Urges NRC to continue local hearings on plant issue
ADDISON, E T, ADDISON, J C Affiliation Unknown 83/10/17 NRC - No Detailed Affiliation Given 2pp 20851 045 24X Fiche 50-352, 83/10/17, 8310210295

8310250047 Package of seven comments opposing plant licensing
LEWIS, S C, NEVILLE, J T, TRENT, N Affiliation Unknown 83/10/21 BRENNER, L NRC - No Detailed Affiliation Given 15pp 20894 154 24X Fiche 50-352, 83/10/21, 8310250047

8310280083 Package of two comments on plant licensing Plants should not be licensed w/o neighborhood referendum
DEEDY, J L, MILLER, W S Affiliation Unknown 83/10/26 NRC - No Detailed Affiliation Given 2pp 20935 079 24X Fiche 50-352, 83/10/26, 8310280083

K Utility Final Safety Analysis Report (FSAR) & amends

8310050437 Forwards Rev 24 to FSAR
BRADLEY, E J Philadelphia Electric Co 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20631 001 24X Fiche 50-352, 83/09/30, 8310050437

8310250035 Forwards Affidavit of Svc re distribution of Rev 24 to FSAR
BRADLEY, E J Philadelphia Electric Co 83/10/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20895 274 24X Fiche 50-352, 83/10/20, 8310250035

G Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Holder Qualification Tests." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys w/o 10CFR30 59 Evaluation." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310130020 Summary of 830831 meeting w/util in Bethesda, MD re intergranular stress corrosion cracking & preservice insp program
HARRISON, Q Licensing Branch 2 83/09/30 Licensing Branch 2 6pp 20777 003 24X Fiche 50-352, 83/09/30, 8310130020

8310190176 Forwards IE Insp Rept 50-352/83-11 on 830801-0902 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/10/05 KEMPER, J B Philadelphia Electric Co 2pp 20818 083 24X Fiche 50-352, 83/10/05, 8310190176

--8310190185 Notice of violation from insp on 830801-0902
* Region 1, Office of Director 83/10/05 1p 20818 085 24X Fiche 50-352, 83/10/05, 8310190176

--8310190203 IE Insp Rept 50-352/83-11 on 830801-0902 Noncompliance noted, unqualified welders worked on in-core housing guide tube socket fillet welds
CHAUDHARY, S K, REYNOLDS, S D, NICHOLAS, H H Region 1, Office of Director 83/09/20 11p 20818 086 24X Fiche 50-352, 83/10/05, 8310190176

8308300378 IE Info Notice 83-45, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

S Reportable occurrences, LERs & related correspondence

8310280013 Final significant Deficiency Rept 91 re diesel oil storage tank interior coatings Existing coatings will be removed from all eight diesel generator fuel oil storage tanks & recreated w/substitute Amercoat 90 epoxy phenolic coating
KEMPER, J S Philadelphia Electric Co 83/10/05 MURLEY, T E Region I, Office of Director 5pp 20932 273 24X Fiche 50-352, 83/10/05, 8310280013

T Hearing transcripts on non-antitrust matters

8310120176 Transcript of ACRS Subcommittee on Limerick Generating Station Units 1 & 2 831007 meeting in Pottstown, PA Pp 1-252 Viewgraphs encl
* ACRS - Advisory Committee on Reactor Safeguards 83/10/07 272pp 20694 267 24X Fiche 50-352, 83/10/07, 8310120176

8310120168 Transcript of ACRS Subcommittee on Limerick Generating Station Units 1 & 2 831008 meeting in Pottstown, PA Pp 253-330
* ACRS - Advisory Committee on Reactor Safeguards 83/10/08 278pp 20693 349 24X Fiche 50-352, 83/10/08, 8310120168

8310200185 Transcript of 831017 prehearing conference in Phoenixville, PA Pp 4, 530-4, 768 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/10/17 265pp 20834 151 24X Fiche 50-352, 83/10/17, 8310200185

8310210089 Transcript of 831018 prehearing in Phoenixville, PA Pp 4, 749-5, 047
* Atomic Safety and Licensing Board Panel 83/10/18 305pp, 20845 001 24X Fiche 50-352, 83/10/18, 8310210089

8310310171 Transcript of RW Burcik limited appearance statement Urges Commission to grant requested DL
BURCIK, R W Affiliation Unknown 83/10/25 Office of the Secretary of the Commission 2pp 20959 007 24X Fiche 50-352, 83/10/25, 8310310171

V. Operator Examinations

8310070229 Notification of Significant Licensee Meeting 83-85 on 831025 at site to discuss schedule for conducting licensing exams, including qualification & training for licensed operators
JOHNSON, D F Region I, Office of Director 83/09/29 Region I, Office of Director 1p 20664 363 24X Fiche 50-352, 83/09/29, 8310070229

DOCKET 50-353 LINERICK GENERATING STATION, UNIT 2

A Application/Construction stage documents & correspondence

8310050360 Notification of 830926 meeting w/util in Bethesda, MD to discuss draft BNL rept on core melt frequency
MARTIN, R E Licensing Branch 2 83/09/21 SCHWENCER, A Licensing Branch 2 4pp 20650 043 24X Fiche 50-352, 83/09/21, 8310050360

8310040296 Provides addl info re thermal hydraulic stability, per 830624 verbal request Encl revised FSAR tables will be incorporated into FSAR rev scheduled for Oct 1983
KEMPER, J S Philadelphia Electric Co 83/09/28 SCHWENCER, A Licensing Branch 2 6pp 20614 207 24X Fiche 50-352, 83/09/28, 8310040296

8310040124 Forwards response to Equipment Qualification Branch 820730 request for addl info re audits by Seismic & Dynamic Qualification & Pump & Valve Operability Review Teams Util will be notified of items selected for 831015 audit
KEMPER, J S Philadelphia Electric Co 83/09/30 SCHWENCER, A Licensing Branch 2 1225pp 20608 282 24X Fiche 50-352, 83/09/30, 8310040124

--8310040127 Rev 0 to Procedure 8031-Q-14, "General Project Requirements for Seismic Design & Analysis of Equipment Supports "
* Bechtel Corp 83/08/19 212pp 20609 215 24X Fiche 50-352, 83/09/30, 8310040124

--8310040129 Rev 1 to Procedure 8031-Q-19, "Required Response Spectra (RRS) of Primary Containment for Load Combinations of Seismic & Hydrodynamic Loads "
* Bechtel Corp 81/08/02 190pp 20610 067 24X Fiche 50-352, 83/09/30, 8310040124

--8310040131 Rev 2 to Procedure 8031-Q-19, "Required Response Spectra (RRS) of Reactor Bldg & Control Room Structure for Load Combinations of Seismic & Hydrodynamic Loads "
* Bechtel Corp 82/01/29 530pp 20610 257 24X Fiche 50-352, 83/09/30, 8310040124

8310040431 Forwards response to 820730 ltr re operability qualification of pumps & valves Qualification & installation of active pumps & valves 90% complete, per 830916 telcon
KEMPER, J S Philadelphia Electric Co 83/09/30 SCHWENCER, A Licensing Branch 2 57pp 20617 276 24X Fiche 50-352, 83/09/30, 8310040431

8310140093 Forwards analysis of dust loading on first HEPA filter in ESF HVAC filtration train, as discussed in 830926 telcon Dust loading capabilities not exceeded
KEMPER, J S Philadelphia Electric Co 83/10/03 SCHWENCER, A Licensing Branch 2 7pp 20767 052 24X Fiche 50-352, 83/10/03, 8310140093

8310070243 Forwards revised draft FSAR Page 13 4-B adding superintendent, nuclear training section to operating experience assessment committee, per 830929 conference call Rev will be incorporated in Nov 1983 FSAR rev
BRADLEY, E J Philadelphia Electric Co 83/10/04 SCHWENCER, A Licensing Branch 2 3pp 20658 335 24X Fiche 50-352, 83/10/04, 8310070243

8310120062 Advises that operation of facility will not adversely affect significant or archeological resources, provided investigations performed & negative visual impacts eliminated
WILLIAMS, D Pennsylvania, Commonwealth of, 83/10/05 SCHWENCER, A Licensing Branch 2 1p 20696 156 24X Fiche 50-352, 83/10/05, 8310120062

8310140197 Discusses actions to be taken to revise & expand upon applicant 811104 ltr, in response to NRC 830831 request Areas discussed include pipe replacement, matl corrections & additions & nonconforming welds in Class 1 sys
KEMPER, J S Philadelphia Electric Co 83/10/05 EISENHUT, D O Division of Licensing 16pp 20762 333 24X Fiche 50-352, 83/10/05, 8310140197

8310140278 Forwards draft response to 830915 Request for Addl Info RAI 271 2 re qualification of automatic depressurization sys accumulators per TMI Item 11 K 3 28 Response will be incorporated in Nov 1983 FSAR rev
BRADLEY, E J Philadelphia Electric Co 83/10/05 SCHWENCER, A Licensing Branch 2 9pp 20761 186 24X Fiche 50-352, 83/10/05, 8310140278

8310120148 Forwards clarification of requested info on misplaced bundle accident analysis, per 830715 telcon Draft replacement for FSAR Table 15 4-6 encl Info will be incorporated into next FSAR rev
KEMPER, J S Philadelphia Electric Co 83/10/07 SCHWENCER, A Licensing Branch 2 4pp 20696 018 24X Fiche 50-352, 83/10/07, 8310120148

8310140097 Forwards Amend 57 to DL application, consisting of "Electrical Equipment Environ Qualification Rept" dtd Oct 1983, replacing earlier version
BRADLEY, E J Philadelphia Electric Co 83/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20755 001 24X Fiche 50-352, 83/10/07, 8310140097

--8310140101 Amend 57 to DL application, consisting of "Electrical Equipment Environ Qualification Rept" dtd Oct 1983, replacing earlier version Certificate of Svc encl
BOYER, V S, BRADLEY, E J Philadelphia Electric Co 83/10/06 6pp 20755 003 24X Fiche 50-352, 83/10/07, 8310140097

DOCKETED ITEMS

--B310140103 "Electrical Equipment Environ Qualification Rept. Limerick Generating Station Units 1 & 2," Vols 1-3
* NUTECH Engineers, Inc 83/10/31 1.667pp 20755 009 24X
Fiche 50-352,83/10/07,8310140097

C Utility Environmental Report (ER), amends & correspondence

B310180423 Forwards "Limerick Generating Station Request For Addl Info Environ Rept - OL Stage Question E451 B.FSAR Question 451 9, Joint Frequency Distributions of Wind Direction & Speed by Atmospheric Stability Class "
KEMPER, J S Philadelphia Electric Co 83/10/13 SCHWENCER, A
Licensing Branch 2 4pp 20803 318 24X Fiche 50-352,83/10/13, 8310180423

D NRC Draft/Final Environmental Statements, suppl's & correspondence

B310180420 Advises that results of review of DES re water supply consistent w/Findings of Delaware River Commission Rept should address low level radwaste storage & disposal
PASTOR, R J Pennsylvania, Commonwealth of, 83/10/04 SCHWENCER, A
Licensing Branch 2 3pp 20803 221 24X Fiche 50-352,83/10/04, 8310180420

E NRC Safety Evaluation Report (SER), suppl's & correspondence

B310070190 Summary of B30615 meeting w/util, Bechtel & O&E in Bethesda, MD re open BER issue concerning high radiation signal on containment purge vent valves w/respect to placement of radiation monitors & isolation requirements
MARTIN, R E Licensing Branch 2 83/09/29 Licensing Branch 2
13pp 20680 235 24X Fiche 50-352,83/09/29,8310070190

B310110132 Forwards draft revs to FSAR re BER Open Item Issue 19 concerning frequency classification of generator load rejection w/bypass failure & turbine trip w/bypass failure events FSAR revs scheduled for Nov 1983
KEMPER, J S Philadelphia Electric Co 83/10/03 SCHWENCER, A
Licensing Branch 2 9pp 20666 299 24X Fiche 50-352,83/10/03, 8310110132

B310120392 Forwards draft revs to FSAR Sections 1 B.5 2 & 7.7 & draft revised response to FSAR Question 410 23, per 831222 meeting re SER Open Issue 8 concerning airborne particulate radioactivity monitoring sys.
KEMPER, J S Philadelphia Electric Co 83/10/05 SCHWENCER, A
Licensing Branch 2 23pp 20698 060 24X Fiche 50-352,83/10/05, 8310120392

B310260316 Summary of B30707 meeting w/util in Bethesda, MD re overpressurization of standby gas treatment sys ductwork & filters Issue resolved Disposition discussed in SER,
NUREG-0991 issued in Aug 1983
MARTIN, R E Licensing Branch 2 83/10/19 Licensing Branch 2
19pp 20921 220 24X Fiche 50-352,83/10/19,8310260316

F Security, medical, emergency & fire protection plans

B310040110 Forwards final schedule for satisfying requirements of Generic Ltr 82-33 re Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability "
SCHWENCER, A Licensing Branch 2 83/09/26 BAUER, E G
Philadelphia Electric Co 4pp 20634 336 24X
Fiche 50-352,83/09/26,8310040110

B310180423 Forwards "Limerick Generating Station Request For Addl Info Environ Rept - OL Stage Question E451 B.FSAR Question 451 9, Joint Frequency Distributions of Wind Direction & Speed by Atmospheric Stability Class "
KEMPER, J S Philadelphia Electric Co 83/10/13 SCHWENCER, A
Licensing Branch 2 4pp 20803 318 24X Fiche 50-352,83/10/13, 8310180423

B310280127 Responds to NRC 830926 ltr re schedule for meeting emergency response capability requirements Const schedule will permit fuel loading by 840801 Full scale emergency preparedness exercise rescheduled to 840725
BOYER, V S Philadelphia Electric Co 83/10/25 SCHWENCER, A
Licensing Branch 2 3pp 20929 273 24X Fiche 50-352,83/10/25, 8310280127

G Adjudicatory correspondence

B309130054 Forwards receipts indicating that draft offsite emergency plans received by City of Philadelphia & by J Dorsey on behalf of intervenors
BRADLEY, E J Philadelphia Electric Co 83/09/07 BRENNER, L J
MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel
4pp 20356 177 24X Fiche 50-352,83/09/07,8309130054

B310030437 Motion to modify wording of Contention V-4 on carburetor icing
ROMAND, F R Air and Water Pollution Patrol 83/09/26 BRENNER, L J
COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 1p
20602 094 24X Fiche 50-352,83/09/26,8310030437

B310050423 Notice of withdrawal of appearance in proceeding Certificate of Svc encl
CHAN, E J Hearing Branch 2 83/09/27 3pp 20632 351 24X
Fiche 50-352,83/09/27,8310050423

B310040491 Motion to reword Contention I 62 re pressurized thermal shock, in response to ASLB 830913 memorandum & order
Certificate of Svc encl
LEWIS, M I Lewis, M 83/09/28 Atomic Safety and Licensing Board Panel 3pp 20625 162 24X Fiche 50-352,83/09/28,8310040491

B310040498 Respec of Contention I-41 re sys interaction Certificate of Svc encl
DORSEY, J A Limerick Ecology Action DORSEY, J A Dorsey, J A
83/09/28 BRENNER, L J, COLE, R F, MORRIS, P A Atomic Safety and Licensing Board Panel 8pp 20625 151 24X Fiche 50-352,83/09/28, 8310040498

B310040187 Memorandum & order re util 830927 motion for summary disposition of Contention V-4 Util directed to file new statement of matl fact w/supporting citations by B31004
BRENNER, L J Atomic Safety and Licensing Board Panel 83/09/30
Philadelphia Electric Co 5pp 20608 084 24X
Fiche 50-352,83/09/30,8310040187

B310040627 Rept per ASLB 830913 memorandum & order re establishment of hearing schedule & re M I Lewis, Friends of the Earth & Air & Water Pollution Patrol contentions Certificate of Svc encl
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/09/30 4pp 20626 183 24X Fiche 50-352,83/09/30, 8310040627

B310050429 Response to Limerick Ecology Action 830831 proposed severe accident assessment rept/enviroen rept - OL stage (SARA/EROL) Section 7 contentions & City of Philadelphia 830920 SARA concerns
VOGLER, D H Hearing Branch 2 83/09/30 Atomic Safety and Licensing Board Panel 14pp 20633 216 24X Fiche 50-352,83/09/30, 8310050429

--B310050432 Rept on behalf of applicant, M Lewis, Air & Water Pollution Patrol, Friends of the Earth & Limerick Ecology Action, in response to ASLB 830913 memorandum re hearing schedule proposals Certificate of Svc encl
HODGSDON, A P Hearing Branch 2 83/09/30 Atomic Safety and Licensing Board Panel 4pp 20633 230 24X Fiche 50-352, 83/09/30,8310050432

B310060305 Forwards author notice of appearance in proceeding Author should be substituted for TY Au on svc list Certificate of Svc encl
FERKIN, Z G Pennsylvania, Commonwealth of, 83/09/30 BRENNER, L J
MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel
3pp 20646 196 24X Fiche 50-352,83/09/30,8310060305

B310040183 Memorandum & order shortening schedule for answers to respect of Limerick Ecology Action Contention I-41 re sys interaction Util answer shall be received by NRC by 831007 & by ASLB & Limerick by 831011
BRENNER, L J Atomic Safety and Licensing Board Panel 83/10/03 4pp
20608 080 24X Fiche 50-352,83/10/03,8310040183

B310050515 Brief opposing Del-Aware Unlimited, Inc exceptions to ASLB 830308 partial initial decision & 830601 memorandum & order denying Del-Aware motion to reopen record Notice of appearance & Certificate of Svc encl
CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn 83/10/03 Atomic Safety and Licensing Appeal Panel
120pp 20630 210 24X Fiche 50-352,83/10/03,8310050515

B310110052 Memorandum & order re hearing schedules proposed by parties NRC schedule essentially acceptable
BRENNER, L J Atomic Safety and Licensing Board Panel 83/10/04 4pp
20668 265 24X Fiche 50-352,83/10/04,8310110052

B310110305 Second interim rept to ASLB re Contention VI-1
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/04 1p 20665 339 24X Fiche 50-352,83/10/04, 8310110305

--B310110307 Affidavit of VS Boyer re review of welds in 1976 under responsibility of QC Inspector Certificate of Svc encl
BOYER, V S Philadelphia Electric Co 83/09/29 6pp 20665 340
24X Fiche 50-352,83/10/04,8310110305

DOCKETED ITEMS

227

8310130037 Advises that hearing schedule & rept to ASLB inadvertently stapled to response to Limerick Ecology Action & City of Philadelphia 830930 severe accident risk assessment contentions Inconvenience regretted
WOLTER, B H Hearing Branch 2 83/10/04 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 1p 20726 289
24X Fiche 50-352, 83/10/04, 8310130037

831010291 Supplemental affidavit of ME Smith in support of motion for summary disposition of Contention V-4
SMITH, M E Philadelphia Electric Co 83/10/05 3pp 20666 080
24X Fiche 50-352, 83/10/05, 831010291

--831010297 Revised statement of matl facts as to which there is no genuine issue to be heard
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/05 11pp 20666 083 24X
Fiche 50-352, 83/10/05, 831010297

--831010300 Affidavit of VS Boyer re Contention V-4 concerning cross-flow natural draft evaporative cooling towers
BOYER, V S Philadelphia Electric Co 83/10/05 1p 20666 094
24X Fiche 50-352, 83/10/05, 831010291

--831010312 Forwards executed signature page of affidavit of ME Smith & D Seymour in support of motion for summary disposition re Contention V-4 Encl page should be substituted for page sent on 830924 Certificate of Svc encl
WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co 83/10/05 Docketing & Services Branch 3pp 20666 095 24X Fiche 50-352, 83/10/05, 831010291

831010212 Requests assurance that former employment w/NRC does not preclude appearance as counsel for applicant Response by 831019 requested
BHOEFMAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/06 LAVERTY, J H Conner & Wetterhahn 1p 20666 061 24X
Fiche 50-352, 83/10/06, 831010212

831010279 Answer to Friends of the Earth 830927 petition for extension of time & scheduling of evidentiary hearings after 840101 & motion to dismiss Contentions V-3a & V-3b. or for other sanctions
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/06 Atomic Safety and Licensing Board Panel 11pp 20666 166 24X Fiche 50-352, 83/10/06, 831010279

--831010277 Answer opposing Air & Water Pollution Control 830926 motion to reword Contentions I-62 & V-4
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/06 Atomic Safety and Licensing Board Panel 3pp 20666 182 24X Fiche 50-352, 83/10/06, 831010275

--831010284 Forwards VS Boyer 831005 affidavit re Contention V-4
WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co 83/10/06 Docketing & Services Branch 2pp 20666 185 24X Fiche 50-352, 83/10/06, 831010275

--831010287 Notice of transmittal of addl matl re Limerick Ecology Action Contention I-42
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/06 2pp 20666 187 24X
Fiche 50-352, 83/10/06, 831010275

--831010292 Answer opposing Limerick Ecology Action respect of Contention I-41 re exacerbation of accidents Contention lacks basis & specificity Certificate of Svc encl
WETTERHAHN, M J, WETTERHAHN, M J Philadelphia Electric Co 83/10/06 Atomic Safety and Licensing Board Panel 11pp 20666 189 24X Fiche 50-352, 83/10/06, 831010275

8310120364 Motion for summary disposition of Contentions V-3a & V-3b No genuine issue of matl fact exists & util entitled to favorable decision
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/07 Atomic Safety and Licensing Board Panel 1p 20753 341 24X Fiche 50-352, 83/10/07, 8310120364

--8310120368 Statement of matl facts as to which there is no genuine issue re Contentions V-3a & V-3b
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/07 Atomic Safety and Licensing Board Panel 10pp 20753 342 24X Fiche 50-352, 83/10/07, 8310120364

--8310120377 Memorandum supporting util motion for summary disposition of Contentions V-3a & V-3b re postulated failure of two pipelines & effect on plant No substantive answers provided to util discovery requests
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/07 Atomic Safety and Licensing Board Panel 14pp 20753 352 24X Fiche 50-352, 83/10/07, 8310120364

--8310120384 Affidavit of JD Walsh supporting motion for summary disposition of Contentions V-3a & V-3b No adverse effects on safety-related structures would occur if natural gas in pipeline detonated One aperture card available in PDR
WALSH, J D Philadelphia Electric Co WALSH, J D Bechtel Corp 83/10/06 11pp 20754 003 24X Fiche 50-352, 83/10/07, 8310120364

--8310120388 Affidavit of VS Boyer supporting motion for summary disposition ARCO pipeline owner, agreed to prohibit shipping of propane in & through pipelines on plant premises
Certificate of Svc encl
BOYER, V S Philadelphia Electric Co 83/10/06 8pp 20754 014
24X Fiche 50-352, 83/10/07, 8310120364

8310180419 Response supporting motions to reword Contention V-4 Applicant objections to rewording deal w/semantics only Effect of steam release not limited to visible plume only
Certificate of Svc encl
ROMANO, F R Air and Water Pollution Patrol. 83/10/08 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel. 1p 20803 312 24X Fiche 50-352, 83/10/08, 8310180419

8310140071 Reply to util & NRC responses to Limerick Ecology Action severe accident risk assessment contentions Certificate of Svc encl
ELLIS, C W Limerick Ecology Action 83/10/10 Atomic Safety and Licensing Board Panel 6pp 20747 063 24X
Fiche 50-352, 83/10/10, 8310140071

8310170511 Brief in opposition to Del-Aware Unlimited, Inc exceptions to ASLB Partial Initial Decision LBP-83-11 & to ASLB 830601 order denying motion to reopen record No reversible error committed Certificate of Svc encl
HODDODD, A P Hearing Branch 2 83/10/12 Atomic Safety and Licensing Appeal Panel 41pp. 20784 151 24X Fiche 50-352, 83/10/12, 8310170511

8310180132 Motion for summary disposition of Contention I-62
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/12 Atomic Safety and Licensing Board Panel 1p 20807 097 24X Fiche 50-352, 83/10/12, 8310180132

--8310180139 Memorandum in support of motion for summary disposition of Contention I-62 re pressurized thermal shock (PTS), PTS will not be problem due to conservative design, matl selection, const. testing, operation & surveillance
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/12 Atomic Safety and Licensing Board Panel 15pp 20807 098 24X Fiche 50-352, 83/10/12, 8310180132

--8310180146 Statement of matl facts as to which there is no genuine issue to be heard re Contention I-62
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/12 Atomic Safety and Licensing Board Panel 9pp 20807 113 24X Fiche 50-352, 83/10/12, 8310180132

--8310180152 Statement of S Rangnath, LS Burns, FE Cooke & SE Carter in support of motion for summary disposition of Contention I-62 Prof qualifications & Certificate of Svc encl
RANGNATH, S, BURNS, L S, COOKE, F E Philadelphia Electric Co 83/10/11 31pp 20807 122 24X Fiche 50-352, 83/10/12, 8310180132

8310190040 Request for followup to 830927 application to make limited appearance statement before ASLB
ANTHONY, R L Anthony, R L 83/10/12 Atomic Safety and Licensing Board Panel 1p 20823 172 24X Fiche 50-352, 83/10/12, 8310190040

--8310190044 Response to ASLB 830913 & 1005 memoranda & orders & 831007 & 12 telcons w/NRC. Intervenor has no affidavit from util as to exact ARCO pipeline location
ANTHONY, R L Anthony, R L 83/10/12 1p 20823 173 24X
Fiche 50-352, 83/10/12, 8310190040

8310190058 Reply to NRC & util filings re severe accident risk assessment/environ rept - OL stage, Section 7 issues
Assessment grossly deficient Impact on environ cannot be properly assessed. Certificate of Svc encl
BUSH, M W Philadelphia, PA 83/10/12 Atomic Safety and Licensing Board Panel 13pp 20823 196 24X Fiche 50-352, 83/10/12, 8310190058

8310250100 Response opposing Limerick Ecology Action 830928 respecified Contention I-41 re sys interaction analysis Contention lacks required specificity & regulatory basis Notice of appearance & Certificate of Svc encl
WRIGHT, N A Hearing Branch 2 83/10/13 Atomic Safety and Licensing Board Panel 12pp 20895 279 24X Fiche 50-352, 83/10/13, 8310250100

DOCKETED ITEMS

8310180234 Answer opposing Air & Water Pollution Control 831002 motion for production of welder certification & for independent retesting involving reactor Motion unsupported & w/o basis
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/14 Atomic Safety and Licensing Board Panel 3pp 20806 231 24X Fiche 50-352, 83/10/14, 8310180234

--8310180237 Proposed schedule of util. NRC & M Lewis for hearing of Contentions I-62, V-3a, V-3b & V-4 Certificate of Svc encl
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/14 3pp 20808 254 24X
Fiche 50-352, 83/10/14, 8310180234

8310180243 Advises of no conflict of interest between previous NRC employment & current employment w/Conner & Wetterhahn re licensing proceeding
LAVERY, J H Conner & Wetterhahn LAVERY, J H Philadelphia Electric Co 83/10/14 KOHL, C N, QOTCHY, R L, EDLES, G J Atomic Safety and Licensing Appeal Panel 2pp 20808 249 24X
Fiche 50-352, 83/10/14, 8310180243

8310250342 Response to Intervenor Air & Water Pollution Patrol 830926 motion to reward Contention V-4 & Intervenor MI Lewis 830928 motion to reward Contention I-62 in response to ASLB 830913 memorandum & order Motions should be denied
VOGLER, B H Hearing Branch 2 83/10/17 Atomic Safety and Licensing Board Panel 3pp 20898 030 24X Fiche 50-352, 83/10/17, 8310250342

--8310250364 Response to Friends of the Earth 830927 petition for extension of time to reward Contentions V-3a & V-3b & scheduling of evidentiary hearing after 840101 & to applicant motion to dismiss Certificate of Svc encl
VOGLER, B H Hearing Branch 2 83/10/17 Atomic Safety and Licensing Board Panel 7pp 20898 033 24X Fiche 50-352, 83/10/17, 8310250364

8310250289 Forwards revised pages to NRC 831012 brief, correcting four inadvertent errors
RUTBERG, J Hearing Branch 2, 83/10/18 KOHL, C N, EDLES, G J, QOTCHY, R L Atomic Safety and Licensing Appeal Panel 4pp 20895 347 24X Fiche 50-352, 83/10/18, 8310250289

--8310250292 Corrected pages to 831012 brief in opposition to Del-Aware Unlimited appeal
* Office of the Executive Legal Director 83/10/18 Atomic Safety and Licensing Appeal Panel 4pp 20895 351 24X
Fiche 50-352, 83/10/18, 8310250292

8310240188 Memorandum & order confirming 831017 & 18 prehearing conference rulings on status of certain parties & schedule re Air & Water Pollution Patrol, Friends of the Earth & Lewis contentions Courtesy notification encl.
BRENNER, L Atomic Safety and Licensing Board Panel 83/10/20 Air and Water Pollution Patrol, 7pp 20878 092 24X
Fiche 50-352, 83/10/20, 8310240188

1310260273 Advises of intention to continue as party to litigation on issues re emergency planning W/o svc list Related correspondence.
HERSHEY, S P Community Legal Services, Inc HERSHEY, S P CEPA, 83/10/21, BRENNER, L Atomic Safety and Licensing Board Panel, 1p 20911 308 24X Fiche 50-352, 83/10/21, 8310260273

8310310336 Response to util 830917 statement of matl fact as to which there is no genuine issue to be heard re motion for summary disposition of Contention V-4, Cooling tower plume issue
unaddressed W/Certificate of Svc
ROMANO, F R Air and Water Pollution Patrol, 83/10/21 Atomic Safety and Licensing Board Panel 10pp 20959:071 24X
Fiche 50-352, 83/10/21, 8310310336

--8310310333 Statement of matl facts as to which there is genuine issue to be heard re cooling tower plumes
ROMANO, F R Air and Water Pollution Patrol 83/10/21 Atomic Safety and Licensing Board Panel 3pp 20959:081 24X
Fiche 50-352, 83/10/21, 8310310336

-8310310371 Affidavit of FR Romano re summary disposition of Contention V-4
ROMANO, F R Air and Water Pollution Patrol 83/10/21 3pp 20959:086 24X Fiche 50-352, 83/10/21, 8310310336

310270268 Statement of matl facts as to which there is genuine issue as to Contention I-62, Certificate of Svc encl
LEWIS, M I Lewis, M 83/10/24 Atomic Safety and Licensing Board Panel, 2pp, 20923 327 24X Fiche 50-352, 83/10/24, 8310270268

8310270336 Statement supporting response to applicant motion for summary disposition of Contention I-62.
LEWIS, M I Lewis, M 83/10/24 Atomic Safety and Licensing Board Panel 9pp, 20923 329 24X Fiche 50-352, 83/10/24, 8310270268

--8310270362 Rebuttal to applicant 831012 statement of matl facts as to which there is no genuine issue as to Contention I-62
LEWIS, M I Lewis, M 83/10/24 Atomic Safety and Licensing Board Panel 3pp 20923 338 24X Fiche 50-352, 83/10/24, 8310270268

--8310270368 Response opposing applicant 830927 motion for summary disposition of Contention I-62
* Lewis, M 83/10/24 Atomic Safety and Licensing Board Panel 3pp 20923 341 24X Fiche 50-352, 83/10/24, 8310270268

8310310231 Request for official notice of Federal regulation of ultralight aircraft, 47FR38770 Certificate of Svc encl
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/27 Atomic Safety and Licensing Board Panel 14pp 20947 210 24X Fiche 50-352, 83/10/27, 8310310231

H General correspondence

8310210295 Urges NRC to continue local hearings on plant issue
ADDISON, E T, ADDISON, J C Affiliation Unknown 83/10/17 NRC - No Detailed Affiliation Given 2pp 20851 045 24X
Fiche 50-352, 83/10/17, 8310210295

8310250047 Package of seven comments opposing plant licensing
LEWIS, S C, NEVILLE, J T, TRENT, N Affiliation Unknown 83/10/21 BRENNER, L NRC - No Detailed Affiliation Given 15pp 20894 154 24X Fiche 50-352, 83/10/21, 8310250047

8310280083 Package of two comments on plant licensing Plants should not be licensed w/o neighborhood referendum
OZEDZY, J L, MILLER, W S Affiliation Unknown 83/10/26 NRC - No Detailed Affiliation Given 2pp 20935 079 24X
Fiche 50-352, 83/10/26, 8310280083

K Utility Final Safety Analysis Report (FSAR) & amends

8310050437 Forwards Rev 24 to FSAR
BRADLEY, E J Philadelphia Electric Co 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20631 001 24X Fiche 50-352, 83/09/30, 8310050437

8310250035 Forwards Affidavit of Svc re distribution of Rev 24 to FSAR
BRADLEY, E J Philadelphia Electric Co 83/10/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20895 274 24X Fiche 50-352, 83/10/20, 8310250035

G. Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310130020 Summary of 830831 meeting w/util in Bethesda, MD re intergranular stress corrosion cracking & preservice insp program
HARRISON, O Licensing Branch 2 83/09/30 Licensing Branch 2 6pp 20777 003 24X Fiche 50-352, 83/09/30, 8310130020

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants, " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07, Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

DOCKETED ITEMS

229

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

S Reportable occurrences, LERs & related correspondence

8310280013 Final significant Deficiency Rept 91 re diesel oil storage tank interior coatings Existing coatings will be removed from all eight diesel generator fuel oil storage tanks & recoated w/substitute Amercoat 90 epoxy phenolic coating
KEMPER, J S Philadelphia Electric Co 83/10/05 MURLEY, T E Region 1, Office of Director 5pp 20932 273 24X Fiche 50-352, 83/10/05, 8310280013

T Hearing transcripts on non-antitrust matters

8310120176 Transcript of ACRS Subcommittee on Limerick Generating Station Units 1 & 2 831007 meeting in Pottstown, PA
Pp 1-252 Viewgraphs encl
* ACRS - Advisory Committee on Reactor Safeguards 83/10/07 272pp 20694 267 24X Fiche 50-352, 83/10/07, 8310120176

8310120168 Transcript of ACRS Subcommittee on Limerick Generating Station Units 1 & 2 831008 meeting in Pottstown, PA Pp 253-330
* ACRS - Advisory Committee on Reactor Safeguards 83/10/08 276pp 20693 349 24X Fiche 50-352, 83/10/08, 8310120168

8310200185 Transcript of 831017 prehearing conference in Phoenixville, PA Pp 4, 830-4, 748 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/10/17 265pp 20834 151 24X Fiche 50-352, 83/10/17, 8310200185

8310210089 Transcript of 831018 prehearing in Phoenixville, PA Pp 4, 769-5, 047
* Atomic Safety and Licensing Board Panel 83/10/18 305pp 20843 001 24X Fiche 50-352, 83/10/18, 8310210089

8310310171 Transcript of RW Durcik limited appearance statement Urges Commission to grant requested DL
DURCIK, R H Affiliation Unknown 83/10/25 Office of the Secretary of the Commission 2pp 20959 007 24X Fiche 50-352, 83/10/25, 8310310171

DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8310130411 Forwards request for addl info re safety review of OL application Response should be submitted within 60 days of 830930 ltr
SCHWENGER, A Licensing Branch 2 83/09/30 MITTL, R L Public Service Electric & Gas Co of New Jersey 16pp, 20770 001 24X Fiche 50-354, 83/09/30, 8310130411

8310070219 Notification of 831005 meeting w/util in Bethesda, MD to discuss seismological & geotechnical issues for facility
WAGNER, D Licensing Branch 2 83/10/03 SCHWENGER, A Licensing Branch 2 4pp 20676 358 24X Fiche 50-354, 83/10/03, 8310070219

8310070223 Notification of 831005 meeting w/util in Bethesda, MD to discuss structural & geotechnical issues for facility
WAGNER, D Licensing Branch 2 83/10/03 SCHWENGER, A Licensing Branch 2 4pp 20676 344 24X Fiche 50-354, 83/10/03, 8310070223

8310250215 Forwards info re seismic & dynamic qualification test program per FSAR commitment Seismic & environ test schedule for non-NRBB supplied components summarized
MITTL, R L Public Service Electric & Gas Co, of New Jersey 83/10/05 SCHWENGER, A Licensing Branch 2 23pp 20894 037 24X Fiche 50-354, 83/10/05, 8310250215

8310210125 Forwards updated distribution list for environ rept - OL stage, FSAR & general info
SCHWENGER, A Licensing Branch 2 83/10/13 MITTL, R L Public Service Electric & Gas Co of New Jersey 6pp 20883 267 24X Fiche 50-354, 83/10/13, 8310210125

C Utility Environmental Report (ER), amends & correspondence

8310210125 Forwards updated distribution list for environ rept - OL stage, FSAR & general info
SCHWENGER, A Licensing Branch 2 83/10/13 MITTL, R L Public Service Electric & Gas Co of New Jersey 6pp 20883, 267 24X Fiche 50-354, 83/10/13, 8310210125

E NRC Safety Evaluation Report (SER), supp's & correspondence

8310200239 Proposes schedule for balance of safety review questions to support 840221 draft SER date Responses could be transmitted to NRC by 840110 if questions finalized by 831111 Two major FSAR chapters still under NRC review.
MITTL, R L Public Service Electric & Gas Co of New Jersey 83/10/13 SCHWENGER, A Licensing Branch 2 2pp 20833 037 24X Fiche 50-354, 83/10/13, 8310200239

F Security, medical, emergency & fire protection plans

8310240143 Forwards "Control Room Design Review Program Plan, Hope Creek Generating Station," in response to Generic Ltr 82-33, Item 5 Summary rept will be submitted by 840815
MITTL, R L Public Service Electric & Gas Co, of New Jersey 83/10/17 SCHWENGER, A Licensing Branch 2 2pp 20880, 039 24X Fiche 50-354, 83/10/17, 8310240143

--8310240145 "Control Room Design Review Program Plan, Hope Creek Generating Station"
* Essex Corp 83/10/14 52pp 20880 041 24X Fiche 50-354, 83/10/17, 8310240143

G Adjudicatory correspondence

8310030484 Notice of appearance in proceeding Certificate of Svc encl
FRYLING, R Public Service Electric & Gas Co of New Jersey 83/09/29 3pp 20601 074 24X Fiche 50-354, 83/09/29, 8310030484

8310050410 Response to Public Advocate, State of NJ 830909 petition to intervene as party-intervenor in hearing areas re QA & emergency planning Petition not opposed Certificate of Svc encl.
ODDARD, R J Hearing Branch 3 83/09/29 Atomic Safety and Licensing Board Panel 4pp 20633 183 24X Fiche 50-354, 83/09/29, 8310050410

8310200247 Memorandum furnishing qualification & prior prof activities of Judges JH Carpenter, PA Morris & ME Miller in advance of 831122 special prehearing conference Resumes encl.
MILLER, M E Atomic Safety and Licensing Board Panel 83/10/18 6pp 20829 298 24X Fiche 50-354, 83/10/18, 8310200247

8310270381 Informs that updated FSAR will be forwarded as soon as clerical work completed Related correspondence.
CONNER, T B Conner & Wetterhahn 83/10/25 MILLER, M E Atomic Safety and Licensing Board Panel 1p 20923 344 24X Fiche 50-354, 83/10/25, 8310270381

G Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-In for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co, of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co, of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

DOCKETED ITEMS

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8 Reportable occurrences, LERs & related correspondence

8310280101 Potential const deficiency rept re shortened Hilti expansion anchors used in raceway support installations Initially reported on 830816 Exams expected to be completed during wk of 830926 Final rept by 831028
HARTIN, T J Public Service Electric & Gas Co of New Jersey
83/09/14 MURLEY, T E Region 1, Office of Director 2pp 20935 326 24X Fiche 50-354, 83/09/14, 8310280101

8310280075 Significant const deficiency rept re four OE pressure switches containing undetected O-ring that could allow leakage of process fluid into electrical portion of devices Switches will be replaced by 831216
HARTIN, T J Public Service Electric & Gas Co of New Jersey
83/09/28 MURLEY, T E Region 1, Office of Director 2pp 20935 077 24X Fiche 50-354, 83/09/28, 8310280075

8310280093 Potential const deficiency rept re Basler Electric Co resistors installed in emergency diesel generators Initially reported on 830901 & reported by vendor under Part 21 on 830819 Final rept expected by 831130
HARTIN, T J Public Service Electric & Gas Co of New Jersey
83/09/30 MURLEY, T E Region 1, Office of Director 2pp 20935 382 24X Fiche 50-354, 83/09/30, 8310280093

DOCKET 50-358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8310280212 Responds to appeal re denial of FOIA request for OIC of Investigation repts concerning facility Grants appeal in part Forwards document info partially withheld (ref FOIA Exemption 7).
CHILK, B J Office of the Secretary of the Commission 83/08/24.
DEVINE, T Government Accountability Project 2pp 20964, 19B 24X Fiche, 50-358, 83/08/24, 8310280212

--8310280224 Submits revised proposal for providing completion svcs for facility Rev to proposal, originally submitted on 821108, responds to Commission 821122 order to show cause list of independent review team members encl
REINBACH, H D Bechtel Corp. 82/11/23 DICKHONER, W H Cincinnati Gas & Electric Co 7pp 20964 265 24X Fiche 50-358, 83/08/24, 8310280212

--8310280229 Suppl 821123 ltr in response to JO Keppler 821228 request, directed to utilize Bechtel mgt role Boderholm involvement discussed.
AHL, H W Bechtel Corp. 82/12/29 DICKHONER, W H Cincinnati Gas & Electric Co 6pp 20964 296 24X Fiche 50-358, 83/08/24, 8310280212

80231 Forwards description of steps to be taken to identify necessary organizational & procedural action, resumes of case 1 team members, summarizes of Bechtel nuclear experience & contract forms info deleted
REINBACH, H D Bechtel Corp. 82/11/08 DICKHONER, W H Cincinnati Gas & Electric Co 48pp 20964 308 24X Fiche 50-358, 83/08/24, 8310280212.

8310040522 Comments on implementation of recommended independent design review Design verification should be conducted in parallel w/verification of const quality
NEILAN, A J Torrey Pines Technology 83/09/12 WILLIAMS, J
Cincinnati Gas & Electric Co 2pp 20624 235 24X Fiche 50-358, 83/09/12, 8310040522

8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class 1 piping sys Info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway
EISENHUT, D G Division of Licensing 83/09/29 PALLADINO, N J
Commissioners 3pp 20632 001 24X Fiche 50-000, 83/09/29, 8308300357

8310040459 Amend 151 to CL application, consisting of Rev 97 to FSAR
WILLIAMS, J Cincinnati Gas & Electric Co 83/09/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20624 031 24X Fiche 50-358, 83/09/30, 8310040459

8310120304 Forwards agenda & topics of 830929 prebid meeting for independent design review Attendance list, GA matrix, isometrics of RHR sys & responses to questions raised encl
KRAUS, H J Cincinnati Gas & Electric Co 83/09/30 KCPLEH, J G
Region 3, Office of Director 25pp 20690 351 24X Fiche 50-358, 83/09/30, 8310120304

8310170515 Forwards Rev 24 to "Nat'l Board Tasks Rept " Rept assembled for tracking progress on concerns raised by Nat'l Board Interim Repts 1 & 2, Suppls 2, 3, 5, 7 & 13
WILLIAMS, J Cincinnati Gas & Electric Co 83/10/03 YOST, R A
Ohio, State of 1p 20784 253 24X Fiche 50-358, 83/10/03, 8310170515

--8310170515 Rev 24 to "Nat'l Board Tasks Rept "
Cincinnati Gas & Electric Co 83/09/30 61pp 20784 254 24X Fiche 50-358, 83/10/03, 8310170515

8310060497 Declines to approve work requested in 830414 & 0808 & 29 ltr Revised organization should be in place & program to complete const identified & under NRC review prior to approval
KEPPLER, J G Region 3, Office of Director 83/10/04 WILLIAMS, J
Cincinnati Gas & Electric Co 2pp 20641 013 24X Fiche 50-358, 83/10/04, 8310060497

8310110286 Forwards 830930 news release stating that Bechtel Power Corp estimates facility completion in range of 24 to 36 months Final date contingent on orderly & timely resolution of Nov 1982 show cause order Related correspondence
CONNOR, T B Connor & Wetterhahn CONNER, T B Cincinnati Gas & Electric Co 83/10/05 FRYE, J H, HODPCK, F F, LIVINGSTON, M S
Atomic Safety and Licensing Board Panel 2pp 20665 336 24X Fiche 50-358, 83/10/05, 8310110286

8310180035 Staff requirements memo on Torrey Pines, Inc 830928 briefing in Washington, DC re independent review of project mgt
CHILK, B J Office of the Secretary of the Commission. 83/10/05 DIRCKS, W J Office of the Executive Director for Operations 1p 20825 038 24X Fiche 50-358, 83/10/05, 8310180035

8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves.
EISENHUT, D G Division of Licensing 83/10/06 PALLADINO, N J
Commissioners. 31pp 20818 001 24X Fiche 50-000, 83/10/06, 8308300771

8310120252 Forwards response to Phase I of NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants," per BJ Youngblood 830811 request for addl info All cranes & hoists purchased to Sargent & Lundy specs
WILLIAMS, J Cincinnati Gas & Electric Co 83/10/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director. App 20692 102 24X Fiche 50-358, 83/10/06, 8310120252

8310200209 Forwards "Course of Action" responding to 821112 "Order to Show Cause & Order Immediately Suspending Const." (CL-82-22) Section IV B (1)(b) W/o encl
WILLIAMS, J Cincinnati Gas & Electric Co 83/10/06 DIRCKS, W J
Office of the Executive Director for Operations 1p 20832 324 24X Fiche 50-358, 83/10/06, 8310200209

--8310200212 Forwards "Course of Action" responding to 821112 "Order to Show Cause & Order Immediately Suspending Const." (CL-82-33) Section IV D (1)(b) W/o encl
WILLIAMS, J Cincinnati Gas & Electric Co 83/10/06 DEVOUNO, R C
Director's Office, Office of Inspection and Enforcement 1p 20832 325 24X Fiche 50-358, 83/10/06, 8310200209

DOCKETED ITEMS

231

--B310200215 Forwards "Course of Action" responding to B21112 "Order to Show Cause & Order Immediately Suspending Const."
(CLI-82-33) Section IV B (1)(b) W/o encl
WILLIAMS, J Cincinnati Gas & Electric Co 83/10/06 STILLIN, V
Regional Operations & Generic Requirements 1p 20832 326 24X
Fiche 50-358, 83/10/06, B310200209

--B310200222 Forwards "Course of Action" responding to B21112 "Order to Show Cause & Order Immediately Suspending Const."
(CLI-82-33) Section IV B (1)(b) W/o encl
WILLIAMS, J Cincinnati Gas & Electric Co 83/10/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 20832 327
24X Fiche 50-358, 83/10/06, B310200209

--B310200227 Forwards "Course of Action" responding to B21112 "Order to Show Cause & Order Immediately Suspending Const."
(CLI-82-33) Section IV B (1)(b) W/o encl
WILLIAMS, J Cincinnati Gas & Electric Co 83/10/06
EISENHUT, D G Division of Licensing 1p 20832 328 24X
Fiche 50-358, 83/10/06, B310200209

--B310200230 Forwards "Course of Action" responding to B21112 "Order to Show Cause & Order Immediately Suspending Const."
(CLI-82-33) Section IV B (1)(b) W/o encl
WILLIAMS, J Cincinnati Gas & Electric Co 83/10/06
CUNNINGHAM, G H Office of the Executive Legal Director 1p
20832 329 24X Fiche 50-358, 83/10/06, B310200209

--B310200234 Forwards "Course of Action" responding to B21112 "Order to Show Cause & Order Immediately Suspending Const."
(CLI-82-33) Section IV B (1)(b) W/o stated encl Util
external ltrs encl
WILLIAMS, J Cincinnati Gas & Electric Co 83/10/06 LIEBERMAN, J
NRC - No Detailed Affiliation Given 21pp 20832 330 24X
Fiche 50-358, 83/10/06, B310200209

B310130234 Informs that util proposed "Course of Action" rept will be provided to interested persons for comment. Written comments must reach Region III by B31101. Region III will conduct two open meetings on B31101. Distribution list & details encl
KEPPLER, J G Region 3, Office of Director 83/10/07 WILLIAMS, J
Cincinnati Gas & Electric Co 3pp 20720 182 24X
Fiche 50-358, 83/10/07, B310130234

--B310130237 "Course of Action," Vols 1 & 2
Cincinnati Gas & Electric Co 83/10/07 639pp 20720 180
24X Fiche 50-358, 83/10/07, B310130234

B310130242 Forwards Certificate of Svc of Amend 151 to B30930
application for licenses in form of Rev 9/ to FSAR
WILLIAMS, J Cincinnati Gas & Electric Co 83/10/07 DENTON, H
Office of Nuclear Reactor Regulation, Director 3pp 20719 144
24X Fiche 50-358, 83/10/07, B310130242

B310140034 Summary of B30914 meeting w/util in Region III of re actions being taken to strengthen QA program & to outline plan of action.
KEPPLER, J G Region 3, Office of Director 83/10/07 Region 3,
Office of Director 1p 20767 351 24X Fiche 50-358, 83/10/07, B310140034

--B310140055 Summary of B30913 meeting w/util in Washington, DC re plan of action for QA program
MURRAY, J P Office of the Executive Legal Director 83/09/14
Office of the Executive Legal Director 2pp 20767 352 24X
Fiche 50-358, 83/10/07, B310140054

B310240133 Notification of B31013 meeting w/util in Bethesda, MD to discuss proposed course of action to verify quality of facility & complete const as described in B31005 rept
KENTNER, L L Licensing Branch 1 83/10/11 YOUNGBLOOD, B J
Licensing Branch 1 4pp 20891 334, 24X Fiche 50-358, 83/10/11, B310240133

B310210003 Summary of B31011 meeting w/Dayton Power & Light Co in Glen Ellyn, IL re actions required before const can be resumed.
DAVIS, A B Region 3, Office of Director, 83/10/18 Region 3,
Office of Director 1p 20865 166, 24X Fiche 50-358, 83/10/18, B310210003

B310210067 Summary of B31005 meeting w/util at Region III of re actions taken to strengthen QA program
KEPPLER, J G Region 3, Office of Director 83/10/18 Region 3,
Office of Director 1p 20857 269 24X Fiche 50-358, 83/10/18, B310210067

F Security, medical, emergency & fire protection plans

B310040336 Forwards Procedure AD NP 16, "Nuclear Production Directive Emergency Procedure Generation Program," per NUREG-0737, Suppl 1 (Generic Ltr B2-33)
WILLIAMS, J Cincinnati Gas & Electric Co 83/09/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20617 133
24X Fiche 50-358, 83/09/30, B310040336

--B310040341 Procedure AD NP 16, "Nuclear Production Directive Emergency Procedure Generation Program"
WALD, J J Cincinnati Gas & Electric Co 83/09/01 73pp
20617 135 24X Fiche 50-358, 83/09/30, B310040336

B310180197 Clarifies NRC position procedures for admitting NRC personnel to facility Access to vital areas should be afforded to listed Region III personnel. Update will be provided every 6 months.
AXELSON, W L Region 3, Office of Director 83/10/14 WILLIAMS, J
Cincinnati Gas & Electric Co 7pp 20809 046 24X
Fiche 50-358, 83/10/14, B310180197

G Adjudicatory correspondence

B310060245 Petition for reconsideration of ASLB B30915 order denying Miami Valley Power Project motion to reopen record for admission of eight proposed contentions. Add info provided since original decision Certificate of Svc encl
DEVINE, T Miami Valley Power Project DEVINE, T Government
Accountability Project 83/10/03 Atomic Safety and Licensing
Board Panel 81pp 20645 271 24X Fiche 50-358, 83/10/03, B310060245

--B310060252 Affidavit of D Jones for Govt Accountability Project protesting Torrey Pines rept chapter on cases studies. Ref to author interviews incomplete & thus inaccurate. Analysis of whistleblower missed real problem of lack of freedom
JONES, D Affiliation Unknown 83/09/26 9pp 20645 351 24X
Fiche 50-358, 83/10/03, B310060245

--B310060259 Affidavit of T Devine summarizing B30919 discussion w/ C Weaver re summary of interview in Torrey Pines rept. Weaver seriously challenges completeness of interview summary.
DEVINE, T Government Accountability Project 83/09/26 3pp
20646 009 24X Fiche 50-358, 83/10/03, B310060245

--B310060263 Affidavit of R Reiter for Govt Accountability Project expressing dissatisfaction of w/summarized interview in Torrey Pines rept
REITER, R Affiliation Unknown 83/09/24 2pp 20646 012 24X
Fiche 50-358, 83/10/03, B310060245

--B310060266 Motion for extension to file appeal until 10 days after svc of ASLB decision on Miami Valley Power Project petition for reconsideration Certificate of Svc encl
DEVINE, T Miami Valley Power Project DEVINE, T Government
Accountability Project 83/10/03 Atomic Safety and Licensing
Appeal Panel 4pp 20646 014, 24X Fiche 50-358, 83/10/03, B310060245

B310110286 Forwards B30930 news release stating that Bechtel Power Corp estimates facility completion in range of 24 to 36 months. Final date contingent on orderly & timely resolution of Nov 1982 show cause order. Related correspondence
CONNER, T B Conner & Wetterhahn CONNER, T B Cincinnati Gas & Electric Co 83/10/05 FRYE, J H, HOOPER, F F, LIVINGSTON, M B
Atomic Safety and Licensing Board Panel 2pp 20665 336 24X
Fiche 50-358, 83/10/03, B310110286

B310110043 Order granting Miami Valley Power Project B31003 motion for extension to file appeal from ASLB B30915 order. Time extended until 10 days after svc of ASLB decision on Project petition for reconsideration
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/06
Miami Valley Power Project 3pp 20668 277, 24X
Fiche 50-358, 83/10/06, B310110043

B310110208 Notice of JH Lavery employment w/Conner & Wetterhahn, PC. Previous employment w/Commissioner Roberts eliminates any contribution to Zimmer case
LAVERY, J H Conner & Wetterhahn 83/10/06 1p 20665 131, 24X
Fiche 50-358, 83/10/06, B310110208

--B310110216 Notice of JH Lavery employment w/Conner & Wetterhahn, PC. Lavery will not participate in matters leading to DL issuance due to previous employment w/Commissioner Roberts Certificate of Svc encl.
CONNER, T B Conner & Wetterhahn 83/10/06 3pp 20665 132 24X
Fiche 50-358, 83/10/06, B310110208

DOCKETED ITEMS

8310110269 Notification to Commission of Miami Valley Power Project misrepresentation in 831003 motion for reconsideration of ASLB 830915 order No util counsel communicated w/Oavt Accountability Project Certificate of Svc encl CONNER, T B Cincinnati Gas & Electric Co CONNER, T B Conner & Wetterhahn 83/10/06 App 20666 140 24X Fiche 50-358, 83/10/06, 8310110269

8310110214 Requests progress rept on resolution of offsite emergency planning issues, per steps outlined in 830811 ltr FRYE, J H Atomic Safety and Licensing Board Panel 83/10/07 WETTERHAHN, M J Conner & Wetterhahn Ip 20665 060 24X Fiche 50-358, 83/10/07, 8310110214

8310200235 Advises that Ofc of Investigations is conducting ongoing investigation Ofc would present fruits of investigation upon ASLB request in camera ex parte HAYES, B B Office of Investigation 83/10/12 FRYE, J H Atomic Safety and Licensing Board Panel Ip 20832 323 24X Fiche 50-358, 83/10/12, 8310200235

8310190146 Memorandum in support of Miami Valley Power Project (MVPP) petition for reconsideration of ASLB 830915 order MVPP urges ASLB to address stds for reopening record Issues should be included to ensure complete record Certificate of Svc encl WEBB, D F Mentor, KY 83/10/13 Atomic Safety and Licensing Board Panel 6pp 20820 239 24X Fiche 50-358, 83/10/13, 8310190146

8310210153 Answer opposing Miami Valley Power Project 831003 petition for reconsideration of ASLB 830915 memorandum & order denying Project motion to reopen record to admit eight late filed contentions on QA Certificate of Svc encl CONNER, T B Cincinnati Gas & Electric Co CONNER, T B Conner & Wetterhahn 83/10/18 Atomic Safety and Licensing Board Panel 21pp 20855 142 24X Fiche 50-358, 83/10/18, 8310210153

8310260205 Order granting NRC 831021 oral request for extension until 831031 to respond to Miami Valley Power Project petition for reconsideration of ASLB 830915 memorandum & order FRYE, J H Atomic Safety and Licensing Board Panel 83/10/24 Office of the Executive Legal Director Ip 20912 236 24X Fiche 50-358, 83/10/24, 8310260205

8310260230 Responds to 830927 request for actions re mgt structure program, ltr forwarded to JO Kepler for consideration PLATNE, H H Office of the General Counsel 83/10/24 DEVINE, T Miami Valley Power Project Ip 20912 188 24X Fiche 50-358, 83/10/24, 8310260230

H General correspondence

8310120287 Forwards IE Insp Repts 50-358/82-10 & 50-358/83-02 re welder qualifications w/o encls SCHWEIBINZ, E Region 3, Office of Director 83/10/06 STANFIELD, O Cincinnati Gas & Electric Co 20693 001 24X Fiche 50-358, 83/10/06, 8310120287

8310270370 Informs of citizen concern re const defects & QA breakdowns & urges initiation of further action assuring total safety of plant BROWN, J Y Kentucky, Commonwealth of, 83/10/10, PALLADINO, N J Commissioners Ip 20924 008 24X Fiche 50-358, 83/10/10, 8310270370

8310250109 Forwards 831012 Resolution R/195-1983, creating oversight committee. POSEY, W W Cincinnati, OH 83/10/14, DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 20896 230. 24X Fiche 50-358, 83/10/14, 8310250109

K Utility Final Safety Analysis Report (FSAR) & amends

8310040459 Amend 151 to OL application, consisting of Rev 97 to FSAR, WILLIAMS, J Cincinnati Gas & Electric Co, 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20624:031 24X Fiche 50-358, 83/09/30, 8310040459.

--8310040461 Rev 97 to FSAR Grundy Electric Cooperative, Inc. 83/09/30 72pp 20624 034. 24X Fiche 50-358, 83/09/30, 8310040459.

8310130242 Forwards Certificate of Svc of Amend 151 to 830930 application for licenses in form of Rev 97 to FSAR, WILLIAMS, J Cincinnati Gas & Electric Co, 83/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director, 3pp 20719:144 24X Fiche 50-358, 83/10/07, 8310130242.

G Inspection reports, IE Bulletins & correspondence

8310280204 Appeals denial of FOIA request for Ofc of Investigation repts re allegations concerning presence of Bechtel representative at facility prior to Nov 1982 DEVINE, T Government Accountability Project 83/06/16 CHILK, B J Office of the Secretary of the Commission 2pp 20964 192 24X Fiche 50-358, 83/06/16, 8310280204

8310270262 Second response to FOIA request for NRC rept on investigation of charges that Bechtel representatives onsite prior to Bechtel nomination to conduct independent mgt review documents in App A available in PDR FELTON, J M Division of Rules and Records 83/07/14 ANDERSON, P H Shaw, Pittman, Potts & Trowbridge 2pp 20943 067 24X Fiche 50-358, 83/07/14, 8310270262

8310280212 Responds to appeal re denial of FOIA request for Ofc of Investigation repts concerning facility Grants appeal in part Forwards document info partially withheld (ref FOIA Exemption 7) CHILK, B J Office of the Secretary of the Commission 83/08/24 DEVINE, T Government Accountability Project 2pp 20964 190 24X Fiche 50-358, 83/08/24, 8310280212

--8310280220 IE Investigation Rept H-83-001 on 830120-0301 Noncompliance noted Major areas investigated allegations re presence of Bechtel representatives at facility prior to Nov 1982 Affidavit encl Info deleted GILBERT, E C, WARD, W J, HAYES, B B Office of Investigation 83/03/11 60pp 20964 203 24X Fiche 50-358, 83/08/24, 8310280212

8310050538 Forwards IE Insp Rept 50-358/83-12 on 830801-0902 & notice of violation WARNICK, R F Region 3, Office of Director 83/09/22 WILLIAMS, J Cincinnati Gas & Electric Co 2pp 20631 282 24X Fiche 50-358, 83/09/22, 8310050538

--8310050540 Notice of violation from insp on 830801-0902 WARNICK, R F Region 3, Office of Director 83/09/22 2pp 20631 284 24X Fiche 50-358, 83/09/22, 8310050538

--8310050546 IE Insp Rept 50-358/83-12 on 830801-0902 Noncompliance noted failure to follow requirements of Procedure 16-QA-03 in processing Corrective Action Request 81-25 & other documentation GHYNN, T P, NIGHTINGALE, E, FORNEY, W L Region 3, Office of Director 83/09/22 48pp 20631 286 24X Fiche 50-358, 83/09/22, 8310050538

8310050518 Forwards IE Insp Rept 50-358/83-17 on 830428-29 & 0914-16 & notice of violation WARNICK, R F Region 3, Office of Director 83/09/23, WILLIAMS, J Cincinnati Gas & Electric Co 2pp 20634 179 24X Fiche 50-358, 83/09/23, 8310050518

--8310050522 Notice of violation from insp on 830428-29 & 0914-16 WARNICK, R F Region 3, Office of Director, 83/09/23 Ip 20634 181 24X Fiche 50-358, 83/09/23, 8310050518

--8310050530 IE Insp Rept 50-358/83-17 on 830428-29 & 0914-16 Noncompliance noted failure to submit written repts on reportable deficiencies within 30 days of initial notification per 10CFR50.55(e) SCHWEIBINZ, E R, FORNEY, W L Region 3, Office of Director 83/09/23 4pp 20634 182 24X Fiche 50-358, 83/09/23, 8310050518

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp. 20777 210 24X Fiche 50-000, 83/09/26, 8308300342.

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc 113pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310140135 Ack receipt of 830915 interim response informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/B3-07
WARNICK, R F Region 3, Office of Director 83/10/06 WILLIAMS, J
Cincinnati Gas & Electric Co 2pp 20763 044 24X
Fiche 50-358, 83/10/06, 8310140135

--8310140136 Responds to NRC 830628 ltr re violations noted in IE Insp Rept 50-358/B3-07 Corrective actions Chapter 10 of QA manual revised to require that HJ Kaiser perform QC on pumps & motors
WILLIAMS, J Cincinnati Gas & Electric Co 83/09/15 KEPLER, J O
Region 3, Office of Director 6pp 20763 046 24X
Fiche 50-358, 83/10/06, 8310140135

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8310200276 Forwards IE Insp Rept 50-358/B3-11 on 830725-29, 0811, 0830-31 & 0901-02 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/10/07 WILLIAMS, J
Cincinnati Gas & Electric Co 2pp 20830 027 24X
Fiche 50-358, 83/10/07, 8310200276

--8310200280 IE Insp Rept 50-358/B3-11 on 830725-29, 0811, 0830-31 & 0901-02 No noncompliance noted Major areas inspected open items & unresolved items proposed insps plans for cable tray hanger & conduit supports
KEATINGE, D E, DANIELSON, D H Region 3, Office of Director
83/10/07 2pp 20830 027 24X Fiche 50-358, 83/10/07, 8310200276

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310170451 Ack receipt of 830923 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/B2-17.
WARNICK, R F Region 3, Office of Director 83/10/11 WILLIAMS, J
Cincinnati Gas & Electric Co 1p 20784 043 24X
Fiche 50-358, 83/10/11, 8310170451

--8310170454 Responds to NRC 830610 ltr re violations noted in IE Insp Rept 50-358/B2-17 Corrective actions lugs welded by unqualified welders will be reworked & corrective action statement issued re welding control procedure
WILLIAMS, J Cincinnati Gas & Electric Co 83/09/23 KEPLER, J O
Region 3, Office of Director 8pp 20784 044 24X
Fiche 50-358, 83/10/11, 8310170451

8310240161 Summarizes proposed welding reinsp program of Class I structural steel as discussed during 830811 site meeting
Welds found w/major deficiencies will be reworked. Program details encl
WILLIAMS, J Cincinnati Gas & Electric Co 83/10/11 KEPLER, J O
Region 3, Office of Director 5pp 20881 308 24X
Fiche 50-358, 83/10/11, 8310240161

8310180197 Clarifies NRC position procedures for admitting NRC personnel to Facility Access to vital areas should be afforded to listed Region 111 personnel Update will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 WILLIAMS, J
Cincinnati Gas & Electric Co 7pp 20809 046 24X
Fiche 50-358, 83/10/14, 8310180197

8310200157 Submits portions of draft IE info notice & 830915 ltr re NUREG-0969 "Rept of NRC Evaluation Team on Quality of Const at Zimmer Nuclear Power Station," for review & comment
Response requested by 831104
KEPLER, J O Region 3, Office of Director 83/10/17 WILLIAMS, J
Cincinnati Gas & Electric Co 19pp 20834 107 24X
Fiche 50-358, 83/10/17, 8310200157

8310210105 Ack receipt of 830609 ltr & revised 830923 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/B2-10
KEPLER, J O Region 3, Office of Director 83/10/17 WILLIAMS, J
Cincinnati Gas & Electric Co 2pp 20858 207 24X
Fiche 50-358, 83/10/17, 8310210105

--8310210110 Responds to NRC 830325 ltr re violations noted in IE Insp Rept 50-358/B2-10 Corrective actions personnel changes made & procedures revised for update of welder qualification cards Programs for welder qualification will be audited
WILLIAMS, J Cincinnati Gas & Electric Co 83/09/23 KEPLER, J O
Region 3, Office of Director 14pp 20858 208 24X
Fiche 50-358, 83/10/17, 8310210105

--8310210113 Responds to NRC 830325 ltr re violations noted in IE Insp Rept 50-358/B2-10 Corrective actions welder qualification review program being developed Quality records mgt reviewing all welder qualification related documents
WILLIAMS, J Cincinnati Gas & Electric Co 83/06/09 KEPLER, J O
Region 3, Office of Director 10pp 20858 222 24X
Fiche 50-358, 83/10/17, 8310210105

8310260098 Responds to IE Bulletin 83-05 re ASME Nuclear Code pumps & spare parts mfg by Hayward Tyler Pump Co After review of purchasing documentation & investigation of suppliers & subvenders, until determined IE bulletin not applicable
WILLIAMS, J Cincinnati Gas & Electric Co 83/10/18 KEPLER, J O
Region 3, Office of Director 2pp 20912 224 24X
Fiche 50-358, 83/10/18, 8310260098

8310250576 Ack receipt of 830308 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/B1-13 Meeting scheduled 831031 to discuss closeout of Item 5 of insp rept re gap dimensions of socket welds
KEPLER, J O Region 3, Office of Director 83/10/21 WILLIAMS, J
Cincinnati Gas & Electric Co 1p 21182 133 24X
Fiche 50-358, 83/10/21, 8310250576

--8310250586 Responds to NRC 830321 ltr re violations noted in IE Insp Rept 50-358/B1-13 Provides addl info pending changes to ASME Code, Paragraph NX 4427
WILLIAMS, J Cincinnati Gas & Electric Co 83/10/12 KEPLER, J O
Region 3, Office of Director 2pp 20900 357 24X
Fiche 50-358, 83/10/21, 8310250576

R Periodic operating reports & related correspondence

8310170548 Forwards Natl Board Interim Rept 15 dtd 831005 covering audit team activities for Sept 1983
VOST, R A Ohio, State of 83/10/07 WILLIAMS, J Cincinnati Gas & Electric Co 4pp 20780 351 24X Fiche 50-358, 83/10/07, 8310170548

8310210065 Forwards monthly status rept for Sept 1983
DIRCKS, W J Office of the Executive Director for Operations
83/10/13 FALLADINO, N Commissioners 1p 20884 001 24X
Fiche 50-358, 83/10/13, 8310210065

--8310210069 Monthly status rept for Sept 1983
* Region 3, Office of Director 83/09/30, 26pp, 20884 002 24X
Fiche 50-358, 83/10/13, 8310210065

8310180267 Forwards until 831005 written plan re course of action to be taken for audit recommendations in Torrey Pines Technology "Independent Review of Zimmer Project Mgt Final Rept " W/o encl
KEPLER, J O Region 3, Office of Director 83/10/14 NEVLAN, A J
Torrey Pines Technology 4pp 20802 289 24X Fiche 50-358, 83/10/14, 8310180267

S Reportable occurrences, LERs & related correspondence

8310120383 Interim deficiency rept, Item E-30 re electrical cable termination, initially reported on 821027 Approval of procedure rev scheduled for 831015. Failure to incorporate criteria in procedures to be evaluated Next rept by 831231
WILLIAMS, J Cincinnati Gas & Electric Co 83/09/30 KEPLER, J O
Region 3, Office of Director 2pp 20699, 195, 24X
Fiche 50-358, 83/09/30, 8310120383

8310120442 Interim deficiency rept, Item M-76 re indeterminate qualification of supplier per ASME Section III initially reported on 820902 Corrective Action Request 471 initiated by HJ Kaiser Co. requiring audit of facilities & program.
WILLIAMS, J Cincinnati Gas & Electric Co 83/09/30 KEPLER, J O
Region 3, Office of Director 2pp, 20698, 258 24X
Fiche 50-358, 83/09/30, 8310120442

DOCKETED ITEMS

8310120256 PNO-III-83-090 on 830930, licensee notified resident inspector of allegation of improper training & certification of individuals conducting reviews of safety-related records for HJ Kaiser Co. principal site contractor
SCHEIBINZ, E., FORNEY, W. Region 3, Office of Director 83/10/03
1p 20691 330 24X Fiche 50-358, 83/10/03, 8310120256

8310170348 Interim deficiency rept, Item G-11 re failure to implement QA program corrective action reporting sys Initially reported on 830907, QA Dept reorganized & corrective action requests/trending group established Followup rept by 831130
WILLIAMS, J. Cincinnati Gas & Electric Co 83/10/07 KEPLER, J. O
Region 3, Office of Director 2pp 20786 162 24X
Fiche 50-358, 83/10/07, 8310170348

8310170649 Interim deficiency rept, Item G-12 re procedures for insp of rework/repair activities Initially reported on 830909 QA personnel developing program to require verification of repair/rework for closed 7000 series nonconformance repts
WILLIAMS, J. Cincinnati Gas & Electric Co 83/10/07 KEPLER, J. O.
Region 3, Office of Director 2pp 20780 179 24X
Fiche 50-358, 83/10/07, 8310170649

8310170404 Interim deficiency rept, Item E-35 re electrical equipment foundation welding. Initially reported on 830104 Const insp plans developed for surveillance of paint removal & insp of electrical panel mounting welds Next rept by 831201.
WILLIAMS, J. Cincinnati Gas & Electric Co 83/10/10 KEPLER, J. O
Region 3, Office of Director 2pp 20779 154 24X
Fiche 50-358, 83/10/10, 8310170404

8310170448 Interim deficiency rept, Item E-20 re inadequate cable tray hanger insp Initially reported on 820503 Formal submittal of proposed reinsp program, including request for relaxation of NRC 821112 show cause order, will be made by 831108
WILLIAMS, J. Cincinnati Gas & Electric Co. 83/10/10 KEPLER, J. O
Region 3, Office of Director 2pp 20779 228 24X
Fiche 50-358, 83/10/10, 8310170448

8310170485 Interim deficiency rept, Item M-45 re intermediate welder qualifications Initially reported on 830430 Computerized welding info sys scheduled for completion by 840215
Followup rept will be submitted by 840321
WILLIAMS, J. Cincinnati Gas & Electric Co 83/10/10 KEPLER, J. O
Region 3, Office of Director 2pp 20784-091 24X
Fiche 50-358, 83/10/10, 8310170485

8310180296 Interim deficiency rept, Item E-53 re discrepancies in 4 16-kV switchgear wiring diagram Initially reported on 830922 Evaluation continuing Followup rept will be submitted by 840120
WILLIAMS, J. Cincinnati Gas & Electric Co 83/10/10 KEPLER, J. O
Region 3, Office of Director 2pp 20806-352 24X
Fiche 50-358, 83/10/10, 8310180296

8310200098 Interim deficiency rept, Item M-97 re jet pump instrumentation bracket welds not installed to design requirements Initially reported on 830922 DF 30 brackets, 24 not completely welded Next rept expected by 831121.
WILLIAMS, J. Cincinnati Gas & Electric Co 83/10/12 KEPLER, J. O
Region 3, Office of Director 2pp 20835 361 24X
Fiche 50-358, 83/10/12, 8310200098

8310200083 Interim deficiency rept, Item M-56 re inadequate installation of gamma plugs in accessible & embedded piping Initially reported on 820804 HJ Kaiser Co completing investigation Final resolution expected by 840130
WILLIAMS, J. Cincinnati Gas & Electric Co 83/10/14 KEPLER, J. O
Region 3, Office of Director 2pp 20837, 004. 24X
Fiche 50-358, 83/10/14, 8310200083

8310200152 PNO-III-83-097 on 831013, 13 maint & janitorial workers at site resigned due to internal investigation re marijuana & alcohol use during working hours. All safety-related const suspended.
HILL, W., FORNEY, W. Region 3, Office of Director. 83/10/14. 1p 20834, 321. 24X Fiche: 50-358, 83/10/14, 8310200152

8310250487 Interim deficiency rept, Item E-34 re misapplication of control circuit fuses. Initially reported on 830923 Incorrect design documentation will be revised & walkdown program to verify fuses to be developed. Final rept by 840331
WILLIAMS, J. Cincinnati Gas & Electric Co 83/10/17. KEPLER, J. O
Region 3, Office of Director. 2pp 20897-069 24X
Fiche: 50-358, 83/10/17, 8310250487

8310250366 Interim deficiency rept, Item E-46 re lack of Type SIS switchboard wire certification Initially reported on 830713
Bargent & Lundy issued Design Document Change BLE-577 to require Type SIS wire for future use Next rept by 840131
WILLIAMS, J. Cincinnati Gas & Electric Co. 83/10/18 KEPLER, J. O.
Region 3, Office of Director. 3pp. 20898-087. 24X
Fiche, 50-358, 83/10/18, 8310250366

T Hearing transcripts on non-antitrust matters

8310050450 Transcript of 830928 briefing by Torrey Pines, Inc in Washington, DC re independent review of util project
mgt Pp 1-66 Supporting documentation encl
* Commissioners 83/09/28 133pp 20640 001 24X
Fiche 50-358, 83/09/28, 8310050450

DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8310030110 Forwards revs to physical security plan Revs withheld (ref 10CFR73.21).
MEDFORD, M O Southern California Edison Co 83/09/29 Division
of Licensing 2pp 20590 051 24X Fiche 50-206, 83/09/29, 8310030110

8310130012 Forwards two errata pages to Rev 11 to Mar 1981 physical security plan Safeguards contingency plan submitted on 830923 will replace Chapter B of physical security plan by 831215 Pages withheld (ref 10CFR73.21)
MEDFORD, M O Southern California Edison Co 83/10/07 Division
of Licensing 1p 20725 208 24X Fiche 50-206, 83/10/07, 8310130012

8310130424 Requests fee due per 830211 revised physical security plan be remitted within 15 days of receipt of ltr
MILLER, W O License Fee Management Branch 83/10/11 DETCH, R
Southern California Edison Co 2pp 20769 242 24X
Fiche 50-206, 83/10/11, 8310130424

H General correspondence

8310190008 Informs of organizational & personnel changes resulting from Jan 1980 centralization of nuclear engineering & operations dept Revs to Tech Specs being prepared for future submittal
FOGARTY, D J Southern California Edison Co 83/10/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20823 304
24X Fiche 50-206, 83/10/17, 8310190008

P Operating license stage documents & correspondence

8310040009 Informs that evaluation re possible mods to prevent/mitigate inadvertent recirculation actuation signal still in progress Completion of study expected by 840228
MEDFORD, M O Southern California Edison Co 83/09/27
KNIGHTON, O W Licensing Branch 3 1p 20608 112 24X
Fiche 50-361, 83/09/27, 8310040009

8310120278 Forwards response to J Mertens 830805 request for addl info re open items involving damaged snubbers & water hammer Assessment of areas complete
RAY, H B Southern California Edison Co 83/09/29 MARTIN, J B
Region 5, Office of Director 3pp 20693-078 24X
Fiche 50-206, 83/09/29, 8310120278

8310110128 Forwards application for amend to Licenses NPF-10 & NPF-15, changing Tech Specs to revise administration of work hours for min shift crew personnel per Generic Ltr 82-12
BASKIN, K P Southern California Edison Co 83/10/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20666 340
24X Fiche 50-361, 83/10/03, 8310110128

--8310110133 Application for amend to Licenses NPF-10 & NPF-15, changing Tech Specs to revise administration of work hours for min shift crew personnel per Generic Ltr 82-12
BASKIN, K P Southern California Edison Co HOLCOMBE, J C San
Diego Gas & Electric Co, POHLMAN, D L Anaheim, CA 83/10/03
Bpp 20666 342, 24X Fiche 50-361, 83/10/03, 8310110128

--8310110136 Proposed Tech Specs re administration of overtime for min shift crew
* Southern California Edison Co. 83/10/03 53pp 20666 350
24X Fiche 50-361, 83/10/03, 8310110128

8310180173 Forwards notice of consideration of issuance of amend to Licenses NPF-10 & NPF-15, proposed NSHC determination & opportunity for hearing & initial NSHC determination & noticing action re DNBR calculations
RODD, H Licensing Branch 3. 83/10/04 BASKIN, K E Southern
California Edison Co. HOLCOMBE, J C San Diego Gas & Electric Co
3pp 20827 023 24X Fiche 50-361, 83/10/04, 8310180173

--8310180177 Notice of consideration of issuance of amend to Licenses NPF-10 & NPF-15 & proposed NSHC determination & opportunity for hearing re DNBR calculations
KNIGHTON, O W Licensing Branch 3 83/09/26 Bpp 20827 026
24X Fiche 50-361, 83/10/04, 8310180173

DOCKETED ITEMS

235

8310120377 Forwards affidavit attesting to direct distribution of Amend Applications 22 & B
MEDFORD, M D Southern California Edison Co 83/10/07
KNIGHTON, G W Licensing Branch 3 App 20699 093 24X
Fiche 50-361, 83/10/07, 8310120377

8310200177 Forwards response to NRC 83062/ request for addl info to satisfy requirements of NUREG-0737, Item 11 D 1, "Relief & Safety Valve Testing"
MEDFORD, M D Southern California Edison Co 83/10/14
KNIGHTON, G W Licensing Branch 3 17pp 20835 298 24X
Fiche 50-361, 83/10/14, 8310200177

8310250124 Forwards Rev 1 to Calculation SFR-CC-01 i, "Reevaluation of Spent Fuel Storage Racks," in response to NRC 830722 request Racks in fully loaded condition fail to meet seismic criteria
MEDFORD, M D Southern California Edison Co 83/10/17
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 20898 185 24X
Fiche 50-206, 83/10/17, 8310250124

0 Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310120298 Submits comments on 830826 BALP analyses Operator errors primarily result of inadequate procedures or training
Actions taken to improve training & operating experience
feedback in maint program
MCCARTHY, D J Southern California Edison Co 83/09/28 MARTIN, J B
Region 5, Office of Director 2pp 20693 170 24X
Fiche 50-206, 83/09/28, 8310120298

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 118pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310200208 Forwards IE Insp Repts 50-206/83-19, 50-361/83-29 & 50-362/83-27 on 830804-0916 No noncompliance noted
Major areas inspected
operational safety verification, witnessing precriticality, initial criticality & low power physics testing
CHAFFE, A E, D'ANGELO, A, STEWART, J. P Region 5, Office of Director 83/09/30 18pp 20834 130 24X Fiche 50-206, 83/10/04, 8310200208

--8310200214 IE Insp Repts 50-206/83-19, 50-361/83-29 & 50-362/83-27 on 830804-0916 No noncompliance noted
Major areas inspected
operational safety verification, witnessing precriticality, initial criticality & low power physics testing
CHAFFE, A E, D'ANGELO, A, STEWART, J. P Region 5, Office of Director 83/09/30 18pp 20834 130 24X Fiche 50-206, 83/10/04, 8310200208

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310200220 Forwards IE Mgt Meeting Repts 50-206/83-22, 50-361/83-36 & 50-362/83-34 on 830908 re BALP rept for Jul 1982 - May 1983
MARTIN, J B Region 5, Office of Director 83/10/14 MCCARTHY, C B
Southern California Edison Co 2pp 20829 327 24X
Fiche 50-206, 83/10/14, 8310200220

--8310200224 IE Mgt Meeting Repts 50-206/83-22, 50-361/83-36 & 50-362/83-34 on 830908 Major areas discussed BALP rept for Jul 1982 - May 1983
KIRSCH, D F Region 5, Office of Director 83/10/13 2pp, 20829 329 24X Fiche 50-206, 83/10/14, 8310200220

--8310200228 BALP rept for Jul 1982 - May 1983
* Region 5, Office of Director 83/07/15 42pp 20829 331 24X
Fiche 50-206, 83/10/14, 8310200220

--8310200232 Summarizes major investigative activities involving facilities for BALP board review covering Jul 1982 - May 1983
SHACKLETON, D C Office of Investigation 83/06/06 BISHOP, T W
Region 5, Office of Director, 2pp 20830 011 24X
Fiche 50-206, 83/10/14, 8310200220

--8306170106 Forwards observations from evaluation of LERs for 820701-830530, to assist in BALP review Licensee submittals above average in terms of reporting completeness & factual accuracy
SEYFRIT, K V Reactor Operations Analysis Branch 83/06/10
STERNEBERG, D Division of Resident, Reactor Project & Engineering Programs 4pp 20830 015 24X Fiche 50-206, 83/10/14, 8310200220

R Periodic operating reports & related correspondence

8310030102 Monthly operating rept for Mar 1982 W/undated ltr
HANAFORD, I, RAY, H B Southern California Edison Co 82/04/01
Office of Resource Management, Director 7pp 20590 056 24X
Fiche 50-361, 82/04/01, 8310030102

8310190092 Monthly operating repts for Aug 1983 W/830915 ltr
RAY, H B, MAYWEATHER, L Southern California Edison Co 83/09/15
Division of Data Automation & Management Information 13pp, 20822 232 24X Fiche 50-361, 83/09/15, 8310190092

S Reportable occurrences, LERs & related correspondence

8310280071 FOIA request for AEOU rept, "Loss of Shutdown Cooling & Subsequent Boron Dilution at San Onofre 2," dtd 830425 & info re fuel rod degradation problem described in IE Info Notice 82-27
HIATT, S L Ohio Citizens for Responsible Energy 83/06/29
FELTON, J M Division of Rules and Records 1p 20762 155 24X
Fiche 50-361, 83/06/29, 8310280071

8310280079 Responds to FOIA request for AEOU rept, "Loss of Shutdown Cooling & Subsequent Boron Dilution at San Onofre 2," dtd 830425 & documents re fuel rod degradation problem described in IE Info Notice 82-27 Forwards App A documents
FELTON, J M Division of Rules and Records 83/07/28 HIATT, S L
Ohio Citizens for Responsible Energy 2pp 20762 156 24X
Fiche 50-000, 83/07/28, 8310280079

--8305030115 Forwards "Loss of Shutdown Cooling & Subsequent Boron Dilution," engineering evaluation rept
CINTULA, T C Reactor Operations Analysis Branch 83/04/25, SEYFRIT, K V Reactor Operations Analysis Branch 1p, 20762 239, 24X Fiche 50-000, 83/07/28, 8310280079

--8305030120 "Loss of Shutdown Cooling & Subsequent Boron Dilution," engineering evaluation summary
* Director's Office AEOU/EGIO 83/04/25, 13pp 20762 240 24X Fiche 50-000, 83/07/28, 8310280079

--8305160184 Forwards draft IE info notice on possible safety concern to all PHRs re encl engineering evaluation rept on 830314 & 24 loss of shutdown cooling & subsequent boron dilution
HELTENES, C J Docketing & Services Branch 83/05/06 JORDAN, E L
Division of Emergency Preparedness & Engineering Response (Post 830103) 1p 20762 238 24X Fiche 50-000, 83/07/28, 8310280079

DOCKETED ITEMS

8310070304 LER 83-116/03L-0 on 830823, 0702, 04 & 08, calculations indicated DNBR margin not within limits Acceptable margin verified within 15 minutes by restoring core operating limit supervisory sys to svc W/830923 ltr
RAY, H B Southern California Edison Co 83/09/23 MARTIN, J B
Region 5, Office of Director 3pp 20651.086 24X
Fiche 50-361, 83/09/23, 8310070304

8310120152 LER 83-117/01T-0 on 830905, pressurizer level instrument 2L1-0103A on essential plant parameter monitoring sys panel 2L-411 varied from correct reading by approx 15% Level correction applied W/830919 ltr
RAY, H B Southern California Edison Co 83/09/23 MARTIN, J B
Region 5, Office of Director 5pp 20696.011 24X
Fiche 50-361, 83/09/23, 8310120152

8310120116 LER 83-113/03L-0 on 830825, while in Mode 1, shiftily surveillance on control element assembly calculator 2 revealed that three auto restarts occurred within 12 h. Caused by poorly seated disc interface card W/830926 ltr
RAY, H B Southern California Edison Co 83/09/26 MARTIN, J B
Region 5, Office of Director 3pp 20696.147 24X
Fiche 50-361, 83/09/26, 8310120116

8310120130 LER 83-114/03L-0 on 830825, while in Mode 1, containment isolation valve 2HV-0512 gave dual position indication Cause unknown Investigation suspended pending containment entry during next outage W/830926 ltr
RAY, H B Southern California Edison Co 83/09/26 MARTIN, J B
Region 5, Office of Director 3pp 20698.250 24X
Fiche 50-361, 83/09/26, 8310120130

8310120146 LER 83-119/03L-0 on 830828, Group 6 control element assemblies (CEA) inserted to control axial shape index Reactor coolant cold leg temp observed below limits Caused by effects of Xenon build-in & CEA insertion W/830927 ltr
RAY, H B Southern California Edison Co 83/09/27 MARTIN, J B
Region 5, Office of Director 3pp 20696.030 24X
Fiche 50-361, 83/09/27, 8310120146

8310120164 LER 83-115/03L-0 on 830829, toxic gas isolation sys train A ammonia analyzer declared inoperable Failure caused by change in amplifier gain Amplifier board & analyzer recalibr. W/830927 ltr
RAY, H B Southern California Edison Co 83/09/27 MARTIN, J B
Region 5, Office of Director 3pp 20695.358 24X
Fiche 50-361, 83/09/27, 8310120164

8310120070 LER 83-120/03L-0 on 830829 & 31, flow control valve 2FV-031D for iodine removal sys failed to open & declared inoperable Caused by cracked O-ring allowing high pressure oil to leak to low pressure side, W/830928 ltr
RAY, H B Southern California Edison Co 83/09/28 MARTIN, J B
Region 5, Office of Director 3pp 20696.159 24X
Fiche 50-361, 83/09/28, 8310120070

8310120073 LER 83-075/03L-0 on 830828, regulating control element assembly group 6 exceeded time allowed for long-term steady-state insertion limit Caused by use of assemblies to control axial shape index oscillations W/830928 ltr
RAY, H B Southern California Edison Co 83/09/28 MARTIN, J B
Region 5, Office of Director 3pp 20696.191 24X
Fiche 50-361, 83/09/28, 8310120073

8310120342 Forwards updated LERs 83-105/03X-1 & 83-076/03X-1
RAY, H B Southern California Edison Co 83/09/28 MARTIN, J B
Region 5, Office of Director 2pp 20700.253 24X
Fiche 50-361, 83/09/28, 8310120342

--8310120347 Updated LER 83-105/03X-1 on 830801, pilot flames of trains A & B toxic gas isolation sys (TGIS) butane/propane monitors found extinguished Cause of flameout unknown TGIS failure caused by low alarm setpoint for flame detection
RAY, H B Southern California Edison Co 83/09/28 Region 5, Office of Director 1p 20700.255 24X Fiche 50-361, 83/09/28, 8310120347

--8310120351 Updated LER 83-076/03X-1 on 830703, pilot flames of trains A & B of toxic gas isolation sys butane/propane monitors found extinguished Cause of pilot flameout unknown Failure of sys caused by low alarm setpoint, Pilot flames restored
RAY, H B Southern California Edison Co 83/09/28 Region 5, Office of Director 1p 20700.256 24X Fiche 50-361, 83/09/28, 8310120351

8310070301 Potential Part 21 rept re underrange characteristic of Model N-ELIOM transmitter, Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp. 83/09/30 Director's Office, Office of Inspection and Enforcement. 11pp 20651.064 24X
Fiche 50-000, 83/09/30, 8310070301

8310140284 PNO-V-83-045 on 831003, two reactor trip breakers failed 30 day surveillance test Cause of failure under investigation Breakers placed in open position & replaced w/ spares
ECKHARDT, J Region 5, Office of Director 83/10/04 1p 20759.236 24X Fiche 50-361, 83/10/04, 8310140284

8310270454 RO re 1983 land use census, enumerating changes in land use within 5-mile radius of site ref point which have resulted in calculated dose commitments greater than values currently calculated, per Tech Spec 4.11.2.3
BASKIN, K P Southern California Edison Co 83/10/04 MARTIN, J B
Region 5, Office of Director 2pp 20923.004 24X
Fiche 50-361, 83/10/04, 8310270454

8310180477 Requests NRR assume lead responsibility in assessing generic implications of reactor breaker undervoltage trip device failures on 831002 & 03 Previous failures occurred in Mar & Jul 1982 & Mar 1983
BISHOP, T W Division of Resident Reactor Project & Engineering Programs 83/10/07 EISENHUT, D G Division of Licensing 2pp 20803.153 24X Fiche 50-361, 83/10/07, 8310180477

--8310180486 RO 83-125 on 831002, during surveillance testing of reactor trip breakers (RTB), RTB 4 operated out of spec & removed from svc On 831003, RTB 5 removed from svc after failing to open on undervoltage trip Investigation in progress
RAY, H B Southern California Edison Co 83/10/04 MARTIN, J B
Region 5, Office of Director 3pp 20803.155 24X
Fiche 50-361, 83/10/07, 8310180477

8310250145 LER 83-122/03L-0 on 830914, core protection calculator channel D observed to have more than three auto restarts in previous 12 h period Caused by failure of power supply Power supply replaced W/831014 ltr
HAYNES, J O Southern California Edison Co 83/10/14 MARTIN, J B
Region 5, Office of Director 3pp 20896.326 24X
Fiche 50-361, 83/10/14, 8310250145

8310270463 LER 83-124/03L-0 on 830917 & 23, control element assembly calculator declared inoperable due to spurious position from control element assembly 20 Caused by defective board & connector Equipment replaced W/831017 ltr
HAYNES, J O Southern California Edison Co 83/10/17 MARTIN, J B
Region 5, Office of Director 3pp 20923.123 24X
Fiche 50-361, 83/10/17, 8310270463

8310270434 LER 83-125/01T-0 on 831002, during reactor trip breaker testing, breakers 4, 6 & 7 demonstrated anomalous behavior when undervoltage devices tested Cause undetermined Breakers replaced W/831018 ltr
HAYNES, J O Southern California Edison Co 83/10/18 MARTIN, J B
Region 5, Office of Director 6pp 20923.051 24X
Fiche 50-361, 83/10/18, 8310270434

8310270498 LER 83-123/03L-0 on 830913, w/Unit 2 in Mode 1 & Unit 3 in Mode 3, insp of electrical penetrations revealed two holes in penetration seals in auxiliary bldg control area Caused by procedural deficiencies during const W/831018 ltr
HAYNES, J O, RAY, H B Southern California Edison Co 83/10/18 MARTIN, J B
Region 5, Office of Director 3pp 20922.002 24X
Fiche 50-361, 83/10/18, 8310270498

8310310326 RO fire doors listed on encl list found inoperable during Sept routine surveillance Compensatory fire watches established Latching mechanism & closing mechanism failures caused by hardware degradation
HAYNES, J O Southern California Edison Co 83/10/18 MARTIN, J B
Region 5, Office of Director 6pp 20961.142 24X
Fiche 50-361, 83/10/18, 8310310326

8310310284 PNB-V-83-011 on 831024, San Francisco Chronicle published article re use & sale of illegal drugs by current & former facility personnel Drug-related accidents or injuries not cited Repts believed to be untrue or exaggerated
SCHAEFER, D W, NORDERHAUG, L R Region 5, Office of Director 83/10/24, 1p 20961.282 24X Fiche 50-206, 83/10/24, 8310310284

V Operator Examinations

8310030109 Requests, by 831028, schedule for requalification training & exams for 1984 Schedule needed for periodic audits of licensed operator requalification programs
BISHOP, T W Division of Resident Reactor Project & Engineering Programs 83/09/26 FODARTY, D J Southern California Edison Co 2pp 20590.053 24X Fiche 50-206, 83/09/26, 8310030109

DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8310040639 Forwards Amend B to License NPF-15 & notice of issuance & availability Amend authorizes operation at power levels up to 100% of full rated power & revises Tech Spec to reflect changes in fire protection equipment
EISENHUT, D O Division of Licensing 83/09/16 BASKIN, K E
Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co 6pp 20627 324 24X Fiche 50-362, 83/09/16, 8310040639

--8310040642 Amend B to License NPF-15, authorizing operation at power levels up to 100% of full rated power, revising Tech Spec to reflect changes in fire protection equipment & reflecting installation of cooling sys for auxiliary feedwater pump
EISENHUT, D O Division of Licensing 83/09/16 14pp 20627 329 24X Fiche 50-362, 83/09/16, 8310040639

--8310040643 Notice of issuance & availability of Amend B to License NPF-15
KNIGHTON, Q W Licensing Branch 3 83/09/16 4pp 20627 343 24X Fiche 50-362, 83/09/16, 8310040639

8310030110 Forwards revs to physical security plan Revs withheld (ref 10CFR73.21)
MEDFORD, M O Southern California Edison Co 83/09/29 Division of Licensing 2pp 20590 051 24X Fiche 50-206, 83/09/29, 8310030110

8310130012 Forwards two errata pages to Rev 11 to Mar 1981 physical security plan Safeguards contingency plan submitted on 830923 will replace Chapter B of physical security plan by 831215 Pages withheld (ref 10CFR73.21)
MEDFORD, M O Southern California Edison Co 83/10/07 Division of Licensing 1p 20725 208 24X Fiche 50-206, 83/10/07, 8310130012

8310130424 Requests fee due per 830211 revised physical security plan be remitted within 15 days of receipt of ltr
MILLER, W D License Fee Management Branch 83/10/11 DIETCH, R
Southern California Edison Co 2pp 20769 242 24X Fiche 50-206, 83/10/11, 8310130424

H General correspondence

8310190008 Informs of organizational & personnel changes resulting from Jan 1980 centralization of nuclear engineering & operations dept Revs to Tech Specs being prepared for future submittal
FOGARTY, D J Southern California Edison Co 83/10/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20823 304 24X Fiche 50-206, 83/10/17, 8310190008

P Operating license stage documents & correspondence

8310040639 Forwards Amend B to License NPF-15 & notice of issuance & availability Amend authorizes operation at power levels up to 100% of full rated power & revises Tech Spec to reflect changes in fire protection equipment
EISENHUT, D O Division of Licensing 83/09/16 BASKIN, K E
Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co 6pp 20627 324 24X Fiche 50-362, 83/09/16, 8310040639

--8310040642 Amend B to License NPF-15, authorizing operation at power levels up to 100% of full rated power, revising Tech Spec to reflect changes in fire protection equipment & reflecting installation of cooling sys for auxiliary feedwater pump
EISENHUT, D O Division of Licensing 83/09/16 14pp 20627 329 24X Fiche 50-362, 83/09/16, 8310040639

--8310040643 Notice of issuance & availability of Amend B to License NPF-15
KNIGHTON, Q W Licensing Branch 3 83/09/16 4pp 20627 343 24X Fiche 50-362, 83/09/16, 8310040639

8310040009 Informs that evaluation re possible mods to prevent/mitigate inadvertent recirculation actuation signal still in progress Completion of study expected by 840228
MEDFORD, M O Southern California Edison Co 83/09/27
KNIGHTON, Q W Licensing Branch 3 1p 20608 112 24X Fiche 50-361, 83/09/27, 8310040009

8310060508 Approves 830629 request for delay of loss-of-offsite-power test until after 80X testing but prior to 100X testing in order to include test of uninterruptible power supply sys
KNIGHTON, Q W Licensing Branch 3 83/09/28 BASKIN, K
Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co 3pp 20663 253 24X Fiche 50-362, 83/09/28, 8310060508

8308300352 Board Notification 83-144 provides evaluation & recommendations re need for PDRVs on C-E plants Info will be presented to ACRs in Oct 1983
NOVAK, T M Assistant Director for Licensing 83/09/29 Atomic Safety and Licensing Appeal Panel 4pp 20601 230 24X Fiche 50-000, 83/09/29, 8308300352

--8310030407 Informs that "Staff Evaluation of Need for Rapid Depressurization Capability for C-E Plants" & Commission 830916 transcript & slides from San Onofre briefing should be transmitted to boards & parties for C-E plants
EISENHUT, D O Division of Licensing 83/09/27 NOVAK, T M
Assistant Director for Licensing 1p 20601 334 24X Fiche 50-000, 83/09/27, 8308300352

8310120278 Forwards response to J Mertens 830805 request for addl info re open items involving damaged snubbers & water hammer. Assessment of areas complete
RAY, H B Southern California Edison Co 83/09/29 MARTIN, J B
Region 5, Office of Director 3pp 20693 078 24X Fiche 50-206, 83/09/29, 8310120278

8310110128 Forwards application for amend to Licenses NPF-10 & NPF-15, changing Tech Specs to revise administration of work hours for min shift crew personnel per Generic Ltr 82-12
BASKIN, K P Southern California Edison Co 83/10/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20666 340 24X Fiche 50-361, 83/10/03, 8310110128

--8310110133 Application for amend to Licenses NPF-10 & NPF-15, changing Tech Specs to revise administration of work hours for min shift crew personnel per Generic Ltr 82-12
BASKIN, K P Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co POHLMAN, D L Anaheim, CA 83/10/03 8pp 20666 342 24X Fiche 50-361, 83/10/03, 8310110128

--8310110136 Proposed Tech Specs re administration of overtime for min shift crew
Southern California Edison Co 83/10/03 53pp 20666 350 24X Fiche 50-361, 83/10/03, 8310110128

8310180173 Forwards notice of consideration of issuance of amend to Licenses NPF-10 & NPF-15, proposed NSHC determination & opportunity for hearing & initial NSHC determination & noticing action re DNDR calculations
ROOB, H Licensing Branch 3 83/10/04 BASKIN, K E Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co 3pp 20827 023 24X Fiche 50-361, 83/10/04, 8310180173

--8310180177 Notice of consideration of issuance of amend to Licenses NPF-10 & NPF-15 & proposed NSHC determination & opportunity for hearing re DNDR calculations
KNIGHTON, Q W Licensing Branch 3 83/09/26 8pp 20827 026 24X Fiche 50-361, 83/10/04, 8310180173

8310120397 Forwards affidavit attesting to direct distribution of Amend Applications 22 & B.
MEDFORD, M O Southern California Edison Co 83/10/07
KNIGHTON, Q W Licensing Branch 3 4pp 20699 033 24X Fiche 50-361, 83/10/07, 8310120397

8310200177 Forwards response to NRC 830627 request for addl info to satisfy requirements of NUREG-0737, Item II D i, "Relief & Safety Valve Testing"
MEDFORD, M O Southern California Edison Co 83/10/14
KNIGHTON, Q W Licensing Branch 3 17pp 20835 298 24X Fiche 50-361, 83/10/14, 8310200177

8310250124 Forwards Rev 1 to Calculation EFR-CC-01 i, "Reevaluation of Spent Fuel Storage Racks," in response to NRC 830722 request Racks in fully loaded condition fail to meet seismic criteria.
MEDFORD, M O Southern California Edison Co 83/10/17
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 20898 185 24X Fiche 50-206, 83/10/17, 8310250124

8310210260 Requests concurrence re mod to FSAR Table 14.2-2A concerning power ascension testing sequence of 100X power plateau test program, per 830729 ltr, to eliminate need for addl plant trip
MEDFORD, M O Southern California Edison Co 83/10/19
KNIGHTON, Q W Licensing Branch 3 2pp 20855 256 24X Fiche 50-362, 83/10/19, 8310210260

Q Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20734 022 24X Fiche 50-000, 83/09/26, 8308300340

DOCKETED ITEMS

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345

8310120298 Submits comments on 830826 BALP analyses Operator errors primarily result of inadequate procedures or training.
Actions taken to improve training & operating experience
Feedback in maint program
FOGARTY, D J Southern California Edison Co 83/09/28 MARTIN, J B
Region 5, Office of Director 2pp 20693.170 24X
Fiche 50-206,83/09/28,8310120298

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 118pp 20716 324 24X Fiche 50-000,83/09/29,8308300349

8310200208 Forwards IE Insp Repts 50-206/83-19, 50-361/83-29 & 50-362/83-27 on 830804-0916 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 83/10/04 MCCARTHY, C B Southern California Edison Co
2pp 20834 128 24X Fiche 50-206,83/10/04,8310200208

--8310200214 IE Insp Repts 50-206/83-19, 50-361/83-29 & 50-362/83-27 on 830804-0916 No noncompliance noted. Major areas inspected operational safety verification, witnessing precriticality, initial criticality & low power physics testing
CHAFFE, A E., D'ANGELO, A., STEWART, J P Region 5, Office of Director 83/09/30 18pp 20834 130 24X Fiche 50-206,83/10/04,8310200208

708300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378

08300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752.

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043.075 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Ineffective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

200220 Forwards IE Mgt Meeting Repts 50-206/83-22, 50-361/83-36 & -362/83-34 on 830908 re BALP rept for Jul 1982 - May 1983
RYAN, J B Region 5, Office of Director 83/10/14 MCCARTHY, C B Southern California Edison Co 2pp 20829 327 24X
Fiche 50-206,83/10/14,8310200220

10200224 IE Mgt Meeting Repts 50-206/83-22, 50-361/83-36 & 50-362/83-34 on 830908 Major areas discussed: BALP rept for Jul 1982 - May 1983
KIRSCH, D F Region 5, Office of Director. 83/10/13 2pp.
20829 329. 24X Fiche: 50-206,83/10/14,8310200220

10200228 BALP rept for Jul 1982 - May 1983
Region 5, Office of Director. 83/07/13. 42pp. 20829.331 24X
Fiche 50-206,83/10/14,8310200220

0200232 Summarizes major investigative activities involving facilities for BALP board review covering Jul 1982 - May 1983.

HACKLETON, D C Office of Investigation. 83/06/06 BISHOP, T W Region 5, Office of Director. 2pp. 20830.011 24X
Fiche 50-206,83/10/14,8310200220.

--8306170442 Forwards evaluation of LERs for period 820701 to 830530 in support of ongoing BALP review
SEYFRIT, K V Director's Office 83/06/10 STERNBERG, D Division of Resident, Reactor Project & Engineering Programs 4pp
20830 021 24X Fiche 50-206,83/10/14,8310200220

R Periodic operating reports & related correspondence

8310190092 Monthly operating repts for Aug 1983 W/830915 ltr
RAY, H B, MAYHEATHER, L Southern California Edison Co 83/09/15
Division of Data Automation & Management Information 13pp
20822 252 24X Fiche 50-361,83/09/15,8310190092

S Reportable occurrences, LERs & related correspondence

8310120338 LER 83-055/03L-0 on 830826, core protection channel A declared inoperable & bypassed due to failed high reactor coolant cold leg temp input Caused by failed open resistance temp detector 3TE-9179-1 Detector replaced W/830928 ltr
RAY, H B Southern California Edison Co 83/09/28 MARTIN, J B
Region 5, Office of Director 3pp 20700 211 24X
Fiche 50-362,83/09/28,8310120338

8310070333 PNO-V-83-042 on 830929, unusual event declared when unidentified leakage from RCS of 1 ltr gpm discovered Caused by high penalty factor applied in response to 1 h observation Reactor & sys normal after 20% trip test
KIRSCH, D Region 5, Office of Director 83/09/29 1p 20651 002
24X Fiche 50-362,83/09/29,8310070333

8310120172 LER 83-060/03L-0 on 830830, control element assembly calculator 1 & core protection calculator channel B inoperable Caused by failed input amplifier card Card replaced W/830929 ltr
RAY, H B Southern California Edison Co 83/09/29 MARTIN, J B
Region 5, Office of Director 3pp 20695 361 24X
Fiche 50-362,83/09/29,8310120172

8310070301 Potential Part 21 rept re underdrange characteristic of Model N-E110M transmitter Underdrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X
Fiche 50-000,83/09/30,8310070301

8310120075 LER 83-106/01L-0 on 830907, surveillance testing resulted in unsatisfactory float voltage for pilot cells 11 & 13 & unsatisfactory total battery terminal voltage Caused by personnel error W/830930 ltr
RAY, H B Southern California Edison Co 83/09/30 MARTIN, J B
Region 5, Office of Director 3pp 20696 162 24X
Fiche 50-362,83/09/30,8310120075

8310120183 LER 83-066/03L-0 on 830829 & 31, while in Mode 2, control element assembly calculator 2 experienced excessive auto restarts First event caused by faulty central processing unit board Cause for second event unknown W/830930 ltr
RAY, H B Southern California Edison Co 83/09/30 MARTIN, J B
Region 5, Office of Director 3pp 20695 298 24X
Fiche 50-362,83/09/30,8310120183

8310140218 RO 83-073 on 830929, reactor placed in Mode 3 due to excessive unidentified leakage from RCS Cooldown commenced in parallel w/continuing efforts to locate leakage source RCS temp held constant at 480 F to measure leakage
RAY, H B Southern California Edison Co 83/09/30 MARTIN, J B
Region 5, Office of Director 2pp 20761 183 24X
Fiche 50-362,83/09/30,8310140218

8310120065 PNO-V-83-043 on 830929, two manual valves incorrectly closed, isolating all charging pump flow to RCS Plant being shut down due to excessive leakage from RCS On 830930, Tech Spec violation recognized & valves opened
ECKHARDT, J Region 5, Office of Director 83/10/03 1p
20698 296 24X Fiche 50-362,83/10/03,8310120065

8310140023 LER 83-072/03L-0 on 830831, w/unit in Mode 2, containment water level wide range train B instrumentation failed Caused by water trapped in column for level transmitter 3LT-938B-2 Instrument recalibr & declared operable W/831003 ltr
RAY, H B Southern California Edison Co 83/10/03 MARTIN, J B
Region 5, Office of Director 3pp 20768 002 24X
Fiche 50-362,83/10/03,8310140023

8310140125 LER 83-062/03L-0 on 830901 & 05, during low power physics testing in Mode 2, control element assembly B4 dropped more than 19 inches. Caused by improper timing of assembly grippers Timing adjusted W/831004 ltr
RAY, H B Southern California Edison Co 83/10/04 MARTIN, J B
Region 5, Office of Director 3pp 20765 027 24X
Fiche 50-362,83/10/04,8310140125

DOCKETED ITEMS

239

8310140153 PNO-V-83-046 on 831003, while in Mode 3 & attempting to determine why LP turbine stop valve would not fully shut, discovered debris inside moisture separator reheater Turbine not damaged
ECKHARDT, J Region 5, Office of Director 83/10/04 1p
20762 362 24X Fiche 50-362, 83/10/04, 8310140153

8310140167 LER 83-067/03L-0 on 830901, one-phase trip of supply breaker for part-length control element assembly (CEA) 32 rendered CEA incapable of withdrawal Caused by failure of circuitry components Components replaced W/831004 ltr
RAY, H B Southern California Edison Co 83/10/04 MARTIN, J B
Region 5, Office of Director 5pp 20765 073 24X
Fiche 50-362, 83/10/04, 8310140167

8310270454 RO re 1983 land use census, enumerating changes in land use within 5-mile radius of site ref point which have resulted in calculated dose commitments greater than values currently calculated, per Tech Spec 4.11.2.3
BASKIN, K P Southern California Edison Co 83/10/04 MARTIN, J B
Region 5, Office of Director 2pp 20923 004 24X
Fiche 50-361, 83/10/04, 8310270454

8310250495 Corrected LER 83-065/03L-0 on 830905 & 12, high-range in-containment radiation monitor 3RI-7820-1 declared inoperable after discovery in failed low condition Caused by faulty electrical cable penetration path W/831005 ltr
HAYNES, J G Southern California Edison Co 83/10/05 MARTIN, J B
Region 5, Office of Director 4pp 20897 113 24X
Fiche 50-362, 83/10/05, 8310250495

8310270495 LER 83-065/03L-0 on 830905 & 12, w/unit in Mode 2 at zero power, high range in-containment radiation monitor 3RI-7820-1 found in failed low condition & declared inoperable Caused by faulty electrical cable penetration path W/831006 ltr
HAYNES, J G Southern California Edison Co 83/10/06 MARTIN, J B
Region 5, Office of Director 3pp 20922 005 24X
Fiche 50-362, 83/10/06, 8310270495

8310270448 LER 83-076/03L-0 on 830907, during shift surveillance, control element assembly calculator 2 declared inoperable Caused by poorly seated circuit board Circuit boards reseated W/831007 ltr
HAYNES, J G Southern California Edison Co 83/10/07 MARTIN, J B
Region 5, Office of Director 3pp 20923 134 24X
Fiche: 50-362, 83/10/07, 8310270448

8310250465 LER 83-074/03L-0 on 830909, containment airborne radiation monitor 3RI-7804C in continuous alarm state & declared inoperable Caused by alarm setpoint being set too low New setpoint established W/831011 ltr
HAYNES, J G Southern California Edison Co 83/10/11 MARTIN, J B
Region 5, Office of Director 3pp 20897 117 24X
Fiche 50-362, 83/10/11, 8310250465

8310270416 LER 83-069/03L-0 on 830917, w/unit in Mode 3, condenser air ejector wide-range gas monitor 3RI-3870 declared inoperable Caused by loss of communication between RMBO microprocessor & RM23 control room readout Data base reloaded W/831017 ltr
HAYNES, J G Southern California Edison Co 83/10/17 MARTIN, J B
Region 5, Office of Director 3pp 20923 077 24X
Fiche 50-362, 83/10/17, 8310270416

8310270432 RO 83-068 on 830922, w/unit in Mode 3, control room cabinet area emergency air conditioning train A unit 3ME427 removed from svc for routine preventive maint Maint completed on 830924, within limiting condition for operation
HAYNES, J G Southern California Edison Co 83/10/17 MARTIN, J B
Region 5, Office of Director 2pp 20923 042 24X
Fiche 50-362, 83/10/17, 8310270432

8310270439 LER 83-073/01T-0 on 830929, charging & letdown flows isolated by closing manual isolation valves 831208MU084 & 831208MU091 in violation of limiting conditions of operation Caused by personnel error Valves opened on 830930 W/831017 ltr
HAYNES, J G ; RAY, H B Southern California Edison Co 83/10/17 MARTIN, J B
Region 5, Office of Director 4pp 20923 111 24X
Fiche 50-362, 83/10/17, 8310270439

8310270428 Updated LER 83-064/03X-1 on 830829, w/unit in Mode 2, ex-core logarithmic power safety channel C declared inoperable & on 830918, channel B declared inoperable Caused by failed cable connectors Connectors replaced W/831018 ltr
HAYNES, J G Southern California Edison Co 83/10/18 MARTIN, J B
Region 5, Office of Director 3pp 20923 062 24X
Fiche 50-362, 83/10/18, 8310270428

831010326 RO fire doors listed on encl list found inoperable during Sept routine surveillances Compensatory fire watches established Latching mechanism & closing mechanism failures caused by hardware degradation
HAYNES, J G Southern California Edison Co 83/10/18 MARTIN, J B
Region 5, Office of Director 6pp 20961 142 24X
Fiche: 50-361, 83/10/18, 8310310326

8310310284 PNS-V-83-011 on 831024, San Francisco Chronicle published article re use & sale of illegal drugs by current & former facility personnel Drug-related accidents or injuries not cited Repts believed to be untrue or exaggerated
SCHAEFER, D W Region 5, Office of Director 83/10/24 1p
20961 282 24X Fiche 50-206, 83/10/24, 8310310284

V Operator Examinations

8310030109 Requests, by 831028, schedule for requalification training & exams for 1984 Schedule needed for periodic audits of licensed operator requalification programs
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 83/09/26 FOGARTY, D J Southern California Edison Co 2pp 20590 053 24X Fiche 50-206, 83/09/26, 8310030109

DOCKET 50-364 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8310040436 Resubmits 830725 ltr transmitting Rev 7 to security plan Original ltr contained safeguards info & could not be docketed
CLAYTON, F L Alabama Power Co 83/09/15 O'REILLY, J P, Region 2, Office of Director 1p 20619 053 24X Fiche 50-348, 83/09/15, 8310040436

8310040581 Advises that review of Rev 7 to radiological emergency plan complete Plan continues to meet planning stds of 10CFR50 47(b) & requirements of 10CFR50, App E
VERRELLI, D M Division of Project & Resident Programs 83/09/20 McDONALD, R P Alabama Power Co 2pp 20622 306 24X
Fiche 50-348, 83/09/20, 8310040581

8310030147 Ack receipt of 830824 ltr documenting results of design description for alternative shutdown capability review re fire protection Description acceptable w/exception that source range monitor be added to hot shutdown panel
CLAYTON, F L Alabama Power Co 83/09/28 VAROA S A Office of Nuclear Reactor Regulation, Director 2pp 20590 034 24X
Fiche 50-348, 83/09/28, 8310030147

8310250472 Ack receipt of 830921 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-21 & 50-364/83-19 Request for 60-day extension for response to violations approved
VERRELLI, D M Division of Project & Resident Programs 83/10/06 McDONALD, R P Alabama Power Co 2pp 20902 121 24X
Fiche 50-348, 83/10/06, 8310250472

--8310250479 Responds to NRC 830909 ltr re violations noted in IE Insp Repts 50-348/83-21 & 50-364/83-19 Corrective actions detailed review of fire protection program underway Extension of 60 days requested for response
CLAYTON, F L Alabama Power Co 83/09/21 VERRELLI, D M Division of Project & Resident Programs 2pp 20902 123 24X
Fiche 50-348, 83/10/06, 8310250472

--8310250485 Forwards IE Insp Repts 50-348/83-21 & 50-364/83-19 on 830816-19 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/09/09 McDONALD, R P Alabama Power Co 2pp 20902 125 24X
Fiche 50-348, 83/10/06, 8310250472

--8310250490 Notice of violation from insp on 830816-19
* Division of Project & Resident Programs 83/09/09 2pp 20902 127 24X Fiche 50-348, 83/10/06, 8310250472

--8310250498 IE Insp Repts 50-348/83-21 & 50-364/83-19 on 830816-19, Noncompliance noted inadequate surveillance test procedures for fire detection sys, fire protection control valves & carbon dioxide hose reels & no fire stops for cable trays
MILLER, W H Region 2, Office of Director 83/09/07 10pp 20902 129 24X Fiche 50-348, 83/10/06, 8310250472

8310280085 Forwards Amends 33 & 26 to Licenses NPF-2 & NPF-8, respectively & safety evaluation Amends consist of administrative changes to Tech Specs re administrative controls for onsite & offsite organization
REEVES, E A, Operating Reactors Branch 1 83/10/14 CLAYTON, F L Alabama Power Co 2pp 20965 001 24X Fiche 50-348, 83/10/14, 8310280085

--8310280092 Amends 33 & 26 to Licenses NPF-2 & NPF-8, respectively, making administrative changes to Tech Specs re administrative controls for onsite & offsite organization & environ qualification audits
VAROA, S A Operating Reactors Branch 1 83/10/14 46pp 20965 003 24X Fiche 50-348, 83/10/14, 8310280085

DOCKETED ITEMS

--8310280114 Safety evaluation supporting Amends 33 & 26 to Licenses NPF-2 & NPF-B, respectively
 * Office of Nuclear Reactor Regulation, Director 83/10/14 6pp
 20965 049 24X Fiche 50-348, 83/10/14, 8310280085

8310210022 Informs of inaccuracy in design description for alternative shutdown capability transmitted in until 820701 ltr Local mechanical level indication not installed on condensate storage tank but will be added
 CLAYTON, F L Alabama Power Co 83/10/17 VARGA, S A Office of Nuclear Reactor Regulation, Director 2pp 20856-067 24X
 Fiche 50-348, 83/10/17, 8310210022

P Operating license stage documents & correspondence

8310060535 Forwards Rev 1 to 830408 safety evaluation re requests for relief from inservice testing requirements for pumps & valves. Add'l info required for remaining items. Revs requested for Unit 1 will be addressed separately
 VARGA, S A Operating Reactors Branch 1 83/09/16 CLAYTON, F L Alabama Power Co 3pp 20661 322 24X Fiche 50-348, 83/09/16, 8310060535

--8310060540 Rev 1 to 830408 safety evaluation re requests for relief from inservice testing requirements for pumps & valves, based on licensee 830703 submittal Based on review specified alternate testing acceptable.
 * Office of Nuclear Reactor Regulation, Director 83/09/16, 7pp 20661 325 24X Fiche 50-348, 83/09/16, 8310060535

8310030613 Forwards safety evaluation of shunt trip design for RPS DS 416 reactor trip breakers Design acceptable conditioned on receipt of confirmatory info & completion of action items listed
 VARGA, S A Operating Reactors Branch 1 83/09/20 CLAYTON, F L Alabama Power Co 3pp 20607 314 24X Fiche 50-348, 83/09/20, 8310030613

--8310030615 Safety evaluation conditionally accepting shunt trip design for RPS DS 416 reactor trip breakers
 * NRC - No Detailed Affiliation Given 83/09/14 18pp 20607 317 24X Fiche 50-348, 83/09/20, 8310030613

8310050017 Forwards safety evaluation denying licensee 830304 application for amend to Licenses NPF-2 & NPF-B to allow continued plant operations w/more than one control rod immovable
 VARGA, S A Operating Reactors Branch 1, 83/09/21, CLAYTON, F L Alabama Power Co 2pp 20650 268 24X Fiche 50-348, 83/09/21, 8310050017

--8310050022 Safety evaluation denying licensee 830304 application for amend to Licenses NPF-2 & NPF-B to allow continued plant operations w/more than one control rod immovable. Licensee must resolve potential core-wide mechanical problem
 * NRC - No Detailed Affiliation Given, 83/09/21 1p, 20650 270 24X Fiche 50-348, 83/09/21, 8310050017

8310030603 Forwards safety evaluation concurring w/licensee conclusions that NUREG-0737, Item 11 K 3 2 requirements met w/existing PORV, safety valve & reactor high trip pressure setpoints Automatic PORV isolation sys (Item 11 K 3 1) not required
 VARGA, S A Operating Reactors Branch 1 83/09/23 CLAYTON, F L Alabama Power Co 14pp, 20604 212 24X Fiche 50-348, 83/09/23, 8310030603

8310060096 Forwards four oversize drawings, in response to NRC request for add'l info re svc water bldg battery sys design, per util 830503 & 0729 proposed Tech Spec changes involving dc distribution sys. Aperture cards are available in PDR.
 CLAYTON, F L Alabama Power Co, 83/09/23 VARGA, S A NRC - No Detailed Affiliation Given 2pp, 20646; 277, 24X Fiche: 50-348, 83/09/23, 8310060096

8310030414 Identifies specific Reg Guide 1.97 accident monitoring equipment sys for which extension requested, per 830520 & 0824 ltrs Schedules for upgrading equipment provided w/bases for extension request
 CLAYTON, F L Alabama Power Co, 83/09/27, VARGA, S A Office of Nuclear Reactor Regulation, Director 22pp, 20593 087 24X Fiche: 50-348, 83/09/27, 8310030414.

8310040387 Submits evaluation of existing Westinghouse BTS provisions, ASME Code Section XI, Reactor Safety Study (WASH 1400), NUREG-0677 & E060 rept, "Inservice Leak Testing of Primary Pressure Isolation Valves," as applicable to plant design
 CLAYTON, F L Alabama Power Co, 83/09/27 VARGA, S A Office of Nuclear Reactor Regulation, Director, 16pp, 20625, 200 24X Fiche: 50-348, 83/09/27, 8310040387.

8310140194 Application for amend to Licenses NPF-2 & NPF-B, changing Tech Specs to delete turbine valve testing requirements Testing program will be replaced w/insp & maint program for all throttle & governor valves
 CLAYTON, F L Alabama Power Co 83/10/06 VARGA, S A Office of Nuclear Reactor Regulation, Director 4pp 20766 077 24X Fiche 50-348, 83/10/06, 8310140194

--8310140199 Proposed Tech Specs re limiting conditions for operation & surveillance requirements of turbine valve testing Turbine overspeed reliability assurance program encl Program withheld (ref 10CFR2 790)
 * Alabama Power Co 83/10/06 15pp 20766 083 24X Fiche 50-348, 83/10/06, 8310140194

8310170407 Forwards status of licensing items requiring NRC approval
 CLAYTON, F L Alabama Power Co 83/10/10 VARGA, S A Office of Nuclear Reactor Regulation, Director 11pp 20779 161 24X Fiche 50-348, 83/10/10, 8310170407

8310170416 Application to amend Licenses NPF-2 & NPF-B consisting of changes to Tech Spec re movable rod control sys requirements Encl clarifies 830304, 0603 & 0728 submittals in response to NRC 830921 request
 CLAYTON, F L Alabama Power Co 83/10/10 VARGA, S A Office of Nuclear Reactor Regulation, Director 3pp 20779 195 24X Fiche 50-348, 83/10/10, 8310170416

--8310170423 Proposed Tech Spec changes re movable rod control sys requirements
 * Alabama Power Co 83/10/10 5pp 20779 198 24X Fiche 50-348, 83/10/10, 8310170416

8310180280 Forwards list of application dates, fees paid, fees applicable & NRR fee determination & action on each item Based on NRR fee determinations, total of \$17,500 due Util will be notified of adjustments following final review
 MILLER, W O License Fee Management Branch 83/10/11 CLAYTON, F L Alabama Power Co 3pp 20827 126 24X Fiche 50-348, 83/10/11, 8310180280

8310210259 Application for amend to Licenses NPF-2 & NPF-B, changing Tech Specs to allow operation w/slightly positive moderator temp coefficient at low power levels & increased enthalpy hot channel factor (F Delta H) below full power
 CLAYTON, F L Alabama Power Co 83/10/13 VARGA, S A Office of Nuclear Reactor Regulation, Director 50pp 20851 163 24X Fiche 50-348, 83/10/13, 8310210259

--8310210261 Proposed Tech Spec changes to allow operation w/slightly positive moderator temp coefficient at low power levels & increased enthalpy hot channel factor (F Delta H) limit below full power
 * Alabama Power Co 83/10/13 13pp 20851 213 24X Fiche 50-348, 83/10/13, 8310210259

8310280085 Forwards Amends 33 & 26 to Licenses NPF-2 & NPF-B, respectively & safety evaluation Amends consist of administrative changes to Tech Specs re administrative controls for onsite & offsite organization
 REEVES, E A Operating Reactors Branch 1 83/10/14 CLAYTON, F L Alabama Power Co 2pp 20965 001 24X Fiche 50-348, 83/10/14, 8310280085

--8310280092 Amends 33 & 26 to licenses NPF-2 & NPF-B, respectively, making administrative changes to Tech Specs re administrative controls for onsite & offsite organization & environ qualification audits
 VARGA, S A Operating Reactors Branch 1 83/10/14 46pp 20965 003 24X Fiche 50-348, 83/10/14, 8310280085

--8310280114 Safety evaluation supporting Amends 33 & 26 to Licenses NPF-2 & NPF-B, respectively
 * Office of Nuclear Reactor Regulation, Director 83/10/14 6pp 20965 049 24X Fiche 50-348, 83/10/14, 8310280085

8310250422 Responds to four items re shunt trip design for DS-416 reactor trip breakers, per NRC 830920 request Environ conditions considered in developing Westinghouse Owners Group generic design
 CLAYTON, F L Alabama Power Co 83/10/20 VARGA, S A Office of Nuclear Reactor Regulation, Director 2pp 20897 182 24X Fiche: 50-348, 83/10/20, 8310250422

Q Inspection reports, IE Bulletins & correspondence

8310040374 Ack receipt of 830909 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-20 & 50-344/83-18.
 VERRELLI, D M Division of Project & Resident Programs 83/09/19, McDONALD, R F Alabama Power Co 1p 20617-066 24X Fiche 50-348, 83/09/19, 8310040374

--B310042377 Responds to NRC 830819 ltr re violations noted in IE Insp Repts 50-348/83-20 & 50-364/83-18 Corrective actions containment air cooler fan annunciator links 2A & 2B closed & chemistry control Procedure FNP-D-CCP-12 rewritten CLAYTON, F L Alabama Power Co 83/09/09 VERRELLI, D M Division of Project & Resident Programs 3pp 20617 067 24X Fiche 50-348,83/09/19,8310040374

--B310042378 Forwards IE Insp Repts 50-348/83-20 & 50-364/83-18 on 830711-0810 & notice of violation VERRELLI, D M Division of Project & Resident Programs 83/08/19 McDONALD, R P Alabama Power Co 2pp 20617 071 24X Fiche 50-348,83/09/19,8310040374

--B310040379 Notice of violation from insp on 830711-0810 * Region 2, Office of Director 83/08/19 2pp 20617 073 24X Fiche 50-348,83/09/19,8310040374

--B310040384 IE Insp Repts 50-348/83-20 & 50-364/83-18 on 830711-0810 Noncompliance noted sulfuric acid std used to check hydrometers not listed on licensee test equipment inventory & maint schedule & containment air cooler fan links open SPADFORD, W H, RULAND, W H Region 2, Office of Director CANTRELL, F B Division of Project & Resident Programs 83/08/18 10pp 20617 075 24X Fiche 50-348,83/09/19,8310040374

B310250376 Forwards IE Insp Repts 50-348/83-22 & 50-364/83-20 on 830829-31 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 83/09/19 McDONALD, R P Alabama Power Co 2pp 20898 130 24X Fiche 50-348,83/09/19,8310250376

--B310250387 IE Insp Repts 50-348/83-22 & 50-364/83-20 on 830829-31 No noncompliance noted Major areas inspected licensee action on previous insp followup items & two licensee reported events involving spread of contamination IEBB, B T Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/09/14 4pp 20898 132 24X Fiche 50-348,83/09/19,8310250376

B310070049 Forwards SER re util 800725 & 830128 requests for relief from inservice insp requirements of ASME Code, Section XI Requests granted VARGA, S A Operating Reactors Branch 1 83/09/22 CLAYTON, F L Alabama Power Co 3pp 20680 001 24X Fiche 50-364,83/09/22,8310070049

--B310070052 SER re util 800725 & 830128 requests for relief from inservice insp requirements of ASME Code, Section XI Requests granted * Materials Engineering Branch 83/09/20 28pp 20680 004 24X Fiche 50-364,83/09/22,8310070049

--B310070054 Notice of granting of relief from ASME Code requirements VARGA, S A Operating Reactors Branch 1 83/09/22 2pp 20680 032 24X Fiche 50-364,83/09/22,8310070049

B310000340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340

B310000342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342

B310000345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345

B310000349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR30.59 Evaluation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349

B310140194 Application for amend to Licenses NPF-2 & NPF-8, changing Tech Specs to delete turbine valve testing requirements Testing program will be replaced w/insp & maint program for all throttle & governor valves CLAYTON, F L Alabama Power Co 83/10/06 VARGA, S A Office of Nuclear Reactor Regulation, Director 4pp 20766 077 24X Fiche 50-348,83/10/06,8310140194

--B310140199 Proposed Tech Specs re limiting conditions for operation & surveillance requirements of turbine valve testing Turbine over-speed reliability assurance program encl Program withheld (ref 10CFR2.79D) * Alabama Power Co 83/10/06 15pp 20766 081 24X Fiche 50-348,83/10/06,8310140194

B310250472 Ack receipt of 830921 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-21 & 50-364/83-19 Request for 60-day extension for response to violations approved VERRELLI, D M Division of Project & Resident Programs 83/10/06 McDONALD, R P Alabama Power Co 2pp 20902 121 24X Fiche 50-348,83/10/06,8310250472

--B310250479 Responds to NRC 830909 ltr re violations noted in IE Insp Repts 50-348/83-21 & 50-364/83-19 Corrective actions detailed review of fire protection program underway Extension of 60 days requested for response CLAYTON, F L Alabama Power Co 83/09/21 VERRELLI, D M Division of Project & Resident Programs 2pp 20902 123 24X Fiche 50-348,83/10/06,8310250472

--B310250485 Forwards IE Insp Repts 50-348/83-21 & 50-364/83-19 on 830816-19 & notice of violation VERRELLI, D M Division of Project & Resident Programs 83/09/09 McDONALD, R P Alabama Power Co 2pp 20902 125 24X Fiche 50-348,83/10/06,8310250472

--B310250490 Notice of violation from insp on 830816-19 * Division of Project & Resident Programs 83/09/09 2pp 20902 127 24X Fiche 50-348,83/10/06,8310250472

--B310250498 IE Insp Repts 50-348/83-21 & 50-364/83-19 on 830816-19 Noncompliance noted inadequate surveillance test procedures for fire detection sys, fire protection control valves & carbon dioxide hose reels & no fire stops for cable trays MILLER, W H, GIBSON, T D, COMOL, T E Region 2, Office of Director 83/09/07 10pp 20902 129 24X Fiche 50-348,83/10/06,8310250472

B308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378

B308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752

B308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759

B308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

R Periodic operating reports & related correspondence

B310190071 Monthly operating rpt for Aug 1983 W/830912 ltr HAIRSTON, W O, CLAYTON, F L Alabama Power Co 83/09/01 Office of Resource Management, Director 5pp 20822 288 24X Fiche 50-364,83/09/01,8310190071

B310180134 Monthly operating rpt for Sept 1983 W/831012 ltr HAIRSTON, W O, CLAYTON, F L Alabama Power Co 83/10/04 NRC - No Detailed Affiliation Given 9pp 20809 186 24X Fiche 50-364,83/10/04,8310180134

S Reportable occurrences, LERs & related correspondence

B310000439 RO on 830917, while attempting to isolate steam to turbine bldg, three MSIVs failed to close under no-flow conditions Clepper found detached from valve arm Investigation continuing HAIRSTON, W O Alabama Power Co 83/09/19 O'REILLY, J P, Region 2, Office of Director 1p 20602 090 24X Fiche 50-364,83/09/19,8310000439

DOCKETED ITEMS

8310070290 LER 83-039/01T-0 on 830917, MSIVs failed to close under no-flow conditions. MSIV 02N11V002B remained partially open & declared inoperable. Caused by binding in valve packing & separation of valve disc from disc arm W/830930 ltr
HAIRSTON, W O, CLAYTON, F L Alabama Power Co 83/09/30 Region 2, Office of Director App 20655 171 24X Fiche 50-364, 83/09/30, 8310070290

8310070296 Forwards LERs 83-057/03L-0 & 83-036/03L-0
CLAYTON, F L Alabama Power Co 83/09/30 Region 2, Office of Director 1p 20651 075 24X Fiche 50-348, 83/09/30, 8310070296

--8310070302 LER 83-036/03L-0 on 830831, following failure alarm on power cabinet 28D, rod control sys declared inoperable. Caused by blown fuse Fuse & blown fuse indicator replaced.
HAIRSTON, W O Alabama Power Co 83/09/30 Region 2, Office of Director 1p 20651 077 24X Fiche 50-348, 83/09/30, 8310070296

8310070301 Potential Part 21 rept re underdrange characteristic of Model N-E11GM transmitter Underdrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input. End users notified.
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp, 20651 064 24X Fiche 50-000, 83/09/30, 8310070301

8310120350 Forwards LERs 83-060/03L-0, 83-061/03L-0, 83-037/03L-0 & 83-038/03L-0 W/o LER 83-038/03L-0
CLAYTON, F L Alabama Power Co 83/10/04 Region 2, Office of Director 1p 20699 317 24X Fiche 50-348, 83/10/04, 8310120350

--8310120371 LER 83-037/03L-0 on 830907, battery bank 2A declared inoperable. Caused by decrease in voltage on cell 56 below Tech Spec 3 B 2 3 requirements. Cell cleaned & charged. Sys restored.
HAIRSTON, W O Alabama Power Co 83/10/04 Region 2, Office of Director 1p 20699 320 24X Fiche 50-348, 83/10/04, 8310120350

8310270061 Forwards LERs 83-040/03L-0 & 83-041/03L-0
CLAYTON, F L Alabama Power Co 83/10/18 Region 2, Office of Director 1p 20924 194 24X Fiche 50-364, 83/10/18, 8310270061

--8310270108 LER 83-040/03L-0 on 830918, during performance of RCB pressure isolation valve leak test, check valve 02E11V0051A declared inoperable when valve found leaking excessively. Caused by incomplete contact between valve disc & seat.
HAIRSTON, W O Alabama Power Co 83/10/18 Region 2, Office of Director 1p 20924 195 24X Fiche 50-364, 83/10/18, 8310270061

--8310270115 LER 83-041/03L-0 on 830921, instrumentation channel associated w/RCP bus underfrequency relay A declared inoperable due to response time being 1.64 s above Tech Spec time of 0.6 s. Caused by dirty contacts.
HAIRSTON, W O Alabama Power Co 83/10/18 Region 2, Office of Director 1p 20924 196 24X Fiche 50-364, 83/10/18, 8310270061

DOCKET 50-366 EDWIN I HATCH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8310040351 Forwards technical support ctr & emergency operations facility floor plans, route maps to emergency response facilities & telephone listings. Requests update of info & submittal of personnel access documents.
DANCE, H C Division of Project & Resident Programs 83/09/12
KELLY, R J Georgia Power Co App, 20620 323 24X Fiche 50-321, 83/09/12, 8310040351

8310040356 Ack receipt of 830812 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/83-17 & 50-366/83-17
LEWIS, R C Division of Project & Resident Programs 83/09/19
KELLY, R J Georgia Power Co 1p 20625 304 24X Fiche 50-321, 83/09/19, 8310040356

--8310040499 IE Insp Repts 50-321/83-17 & 50-366/83-17 on 830523-27, Noncompliance noted, failure to dispose of radwaste per 10CFR20 301.
KAHLE, J B Region 2, Office of Director 83/06/20, 7pp 20625 312 24X Fiche 50-321, 83/09/19, 8310040356

8310170741 Releases public version of revised emergency plan implementing procedures.
FELTON, J M Division of Rules and Records, 83/10/06 Document Management Branch, 1p 20797 272, 24X Fiche 50-321, 83/10/06, 8310170741

--8310170743 Forwards public version of revised emergency plan implementing procedures, including Procedures HNP-8034 re contaminated tool storage & control & HNP-4861 re emergency notification network.
NIX, H C, SORRELL, E C Georgia Power Co 83/09/16 Office of Nuclear Reactor Regulation, Director App 20797 273 24X Fiche 50-321, 83/10/06, 8310170741

--8310170746 Public version of revised emergency plan implementing procedures, including Procedures HNP-8034 re contaminated tool storage & control & HNP-4861 re emergency notification network.
GREENE, T, ROGERS, W H, NIX, H C Georgia Power Co 83/09/14 26pp 20797 277 24X Fiche 50-321, 83/10/06, 8310170741

8310270012 Forwards IE Safeguards Insp Repts 50-321/83-26 & 50-366/83-28 on 830926-30 No noncompliance noted.
DANCE, H C Division of Project & Resident Programs 83/10/20
KELLY, R J Georgia Power Co 2pp 20924 331 24X Fiche 50-321, 83/10/20, 8310270012

--8310270023 IE Safeguards Insp Repts 50-321/83-26 & 50-366/83-28 on 830926-30 No noncompliance noted. Major areas inspected site orientation, review of security plan & procedures & security organization details withheld (ref 10CFR73 21).
HALL, M L Region 2, Office of Director 83/10/20 1p 20924 333 24X Fiche 50-321, 83/10/20, 8310270012

0 Adjudicatory correspondence

8310180364 Forwards info re util questioning of validity of notice of violation for violating 10CFR20 301 Util requested official interpretation & claimed NRC transferred regulatory authority to State of SC.
LEDERMAN, J Regional Operations & Enforcement Division 83/10/13
OLMSTEAD, B Regulations Division 32pp 20803 044 24X Fiche 50-321, 83/10/13, 8310180364

J Insurance & indemnity information

8310030301 Forwards Endorsements B1 & B2 to NELA Policy NF-215 & Endorsements 66 & 67 to MAELU Policy MF-78.
FIEDLER, J Marsh & McLennan, Inc 83/09/26 BALTZMAN, J Assistant Director For State & License Relations 5pp 20591 008 24X Fiche 50-321, 83/09/26, 8310030301

P Operating license stage documents & correspondence

8310110442 Informs that commitment to add high radiation signal for purge & vent valve isolation meets requirements of NUREG-0737, Item IF E 4 2 7, "Primary Containment High Radiation to Close Vent & Purge Valves".
STOLZ, J F Operating Reactors Branch 4 83/09/29 BECKMAN, J T Georgia Power Co 2pp 20706 319 24X Fiche 50-321, 83/09/29, 8310110442

8310070264 Forwards proprietary "Dresden 2/3 Nuclear Generating Plant Suppression Pool Temp Response," "E1 Hatch Nuclear Power Station Units 1 & 2 Suppression Pool Temp Response" & Mark I 830823 meeting viewgraphs Repts withheld (ref 10CFR2 790).
PFEFFERLEN, H C General Electric Co 83/09/30 VASSALLO, D D Operating Reactors Branch 2 61pp 20611 292 24X Fiche 50-000, 83/09/30, 8310070264

8310070287 Requests that 810226 ltr re proposed Tech Spec changes concerning scram discharge sys be superseded by 830919 submittal.
QUICHA, L T Georgia Power Co 83/10/03 STOLZ, J F Operating Reactors Branch 4 1p 20655 162 24X Fiche 50-321, 83/10/03, 8310070287

8310140241 Provides schedule for plant outages & activities associated w/recirculation piping insp required by IE Bulletins B2-03 & B3-02, as discussed at 830928 meeting w/NRC Replacement of piping planned for Unit 2 Viewgraphs encl.
NIX, H C Georgia Power Co 83/10/05 STOLZ, J F Operating Reactors Branch 4 23pp 20761 345 24X Fiche 50-321, 83/10/05, 8310140241

8310170183 Notifies that plans being developed for replacement/insp of main recirculation stainless steel piping during outage tentatively scheduled to begin Jan 1984. Summary of plans provided. Proposed outline encl.
NIX, H C Georgia Power Co 83/10/05 STOLZ, J F Operating Reactors Branch 4 6pp 20787 105, 24X Fiche 50-366, 83/10/05, 8310170183

DOCKETED ITEMS

243

8310120265 Application for amend to Licenses DPR-57 & NPF-5 revising Tech Specs by transferring radiological effluent Tech Specs from App A to App B, per 781221 submittal Marked-up Tech Specs encl
HEAD, G F Georgia Power Co 83/10/06 STOLZ, J F Operating Reactors Branch 4 158pp 20678 092 24X Fiche 50-321, 83/10/06, 8310120265

8310310439 Responds to 830907 request for mod to NRC 830701 order confirming until commitments to implement certain post-TMI-related items set forth in NUREG-0737 to extend completion date for Item II H 3 to 831201 Request acceptable
STOLZ, J F Operating Reactors Branch 4 83/10/14 DECKHAM, J I Georgia Power Co 2pp 24X Fiche 50-321, 83/10/14, 8310310439

--8310310440 Order granting extension until 831201 to complete Item II B 3, "Post-Accident Sampling" Commitments on applicable NUREG-0737 requirements from Generic Ltr 82-05 encl
EISENHUT, D O Division of Licensing 83/10/14 Georgia Power Co 3pp 20965 164 24X Fiche 50-321, 83/10/14, 8310310439

8310210270 Application for amend to Licenses DPR-57 & NPF-5 transferring radiological effluent Tech Spec from App B to App A
DUCHAU, L T Georgia Power Co 83/10/17 STOLZ, J F Operating Reactors Branch 4 6pp 20846 290 24X Fiche 50-321, 83/10/17, 8310210270

--8310210277 Proposed Tech Spec transferring radiological effluent Tech Spec from App B to App A
* Georgia Power Co 83/10/17 128pp 20846 296 24X Fiche 50-321, 83/10/17, 8310210270

--8310210279 ETS for facilities
* Georgia Power Co 83/10/17 21pp 20847 063 24X Fiche 50-321, 83/10/17, 8310210270

8310270327 Application for amend to License NPF-5, consisting of Tech Spec change request revising applicability of limiting condition for operation of sys & instrumentation associated w/cooling & protection of fuel
CAUSEY, J C Georgia Power Co 83/10/20 STOLZ, J F Operating Reactors Branch 4 2pp 20923 152 24X Fiche 50-366, 83/10/20, 8310270327

--8310270334 Proposed Tech Spec re cooling & protection of fuel in reactor vessel after removal of all fuel
* Georgia Power Co 83/10/20 26pp 20923 154 24X Fiche 50-366, 83/10/20, 8310270327

8310310265 Notifies of possible problem re 10CFR50.49 equipment qualification deadline for electrical components of HPCI control sys Problems first discovered on 830825 Extension of rulemaking deadline may be requested until awaiting data
DUCHAU, L T Georgia Power Co 83/10/24 STOLZ, J F Operating Reactors Branch 4 2pp 20947 123 24X Fiche 50-366, 83/10/24, 8310310265

Q Inspection reports, IE Bulletins & correspondence

8310040012 Forwards IE Insp Repts 50-321/83-24 & 50-366/83-25 on 830817-19 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/08 KELLY, R J Georgia Power Co 2pp 20608 113 24X Fiche 50-321, 83/09/08, 8310040012

--8310040042 IE Insp Repts 50-321/83-24 & 50-366/83-25 on 830817-19 No noncompliance noted Major areas inspected licensee action on previous insp findings, followup on IE Bulletin 80-11 & review of bldg settlement data
LENAHAN, J J Region 2, Office of Director CONLON, T E Division of Engineering & Operational Programs 83/09/06 4pp 20608 113 24X Fiche 50-321, 83/09/08, 8310040012

8310040174 Forwards IE Enforcement Conference Repts 50-321/83-22 & 50-366/83-27 on 830810
O'REILLY, J P Region 2, Office of Director 83/09/15 KELLY, R J, Georgia Power Co 1p 20608 222 24X Fiche 50-321, 83/09/15, 8310040174

--8310040178 IE Enforcement Conference Repts 50-321/83-22 & 50-366/83-27 on 830810 Major areas discussed MSIV leakage sys, HPCI main flow valve & ATWS recirculation pump trip signal,
DANCE, H C Division of Project & Resident Programs 83/09/12 2pp 20608 223 24X Fiche 50-321, 83/09/15, 8310040174

8310040356 Ack receipt of 830812 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/83-17 & 50-366/83-17
LEWIS, R C Division of Project & Resident Programs 83/09/19 KELLY, R J Georgia Power Co 1p 20625 304 24X Fiche 50-321, 83/09/19, 8310040356

--8310040366 Responds to NRC 830713 ltr re violations noted in IE Insp Repts 50-321/83-17 & 50-366/83-17 Corrective actions: boxes prepared for shipment elevated on one end w/drain plug removed for 24 h to allow for liquid drainage
NIX, H C Georgia Power Co 83/08/12 O'REILLY, J P Region 2, Office of Director 4pp 20625 305 24X Fiche 50-321, 83/09/19, 8310040356

--8310040468 Forwards IE Insp Repts 50-321/83-17 & 50-366/83-17 on 830523-27 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/07/13 KELLY, R J Georgia Power Co 2pp 20625 309 24X Fiche 50-321, 83/09/19, 8310040356

--8310040479 Notice of violation from insp on 830523-27
* Region 2, Office of Director 83/07/13 1p 20625 311 24X Fiche 50-321, 83/09/19, 8310040356

--8310040499 IE Insp Repts 50-321/83-17 & 50-366/83-17 on 830523-27 Noncompliance noted failure to dispose of radwaste per 10CFR20.301
KAHLER, J B Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/06/20 7pp 20625 312 24X Fiche 50-321, 83/09/19, 8310040356

8310250519 Forwards IE Training Assessment Repts 50-321/83-23 50-366/83-24 on 830802-05 No noncompliance noted
LEWIS, R C Division of Project & Resident Programs 83/09/19 KELLY, R J Georgia Power Co 2pp 20901 021 24X Fiche 50-321, 83/09/19, 8310250519

--8310250560 IE Training Assessments Repts 50-321/83-23 & 50-366/83-24 on 830802-05 No noncompliance noted Major areas inspected licensed & nonlicensed operator training, requalification programs & onshift/real-time training & mgt training
HEHL, C W, MYERS, D O, SKINNER, P H Region 2, Office of Director 83/09/15 10pp 20901 023 24X Fiche 50-321, 83/09/19, 8310250519

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20734 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310140241 Provides schedule for plant outages & activities associated w/recirculation piping insp required by IE Bulletins 82-03 & 83-02, as discussed at 830928 meeting w/NRC Replacement of piping planned for Unit 2 Viewgraphs encl
NIX, H C Georgia Power Co 83/10/05 STOLZ, J F Operating Reactors Branch 4 23pp 20761 345 24X Fiche 50-321, 83/10/05, 8310140241

8310170183 Notifies that plans being developed for replacement/insp of main recirculation stainless steel piping during outage tentatively scheduled to begin Jan 1984 Summary of plans provided Proposed outline encl
NIX, H C Georgia Power Co 83/10/05 STOLZ, J F Operating Reactors Branch 4 6pp 20767 105 24X Fiche 50-366, 83/10/05, 8310170183

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

DOCKETED ITEMS

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility." Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases." Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043 079 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders." Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180344 Forwards info re util questioning of validity of notice of violation for violating 10CFR20.301 Util requested official interpretation & claimed NRC transferred regulatory authority to State of SC
LIEBERMAN, J. Regional Operations & Enforcement Division 83/10/13
OLMSTEAD, B. Regulations Division 32pp 20803 044 24X
Fiche 50-321, 83/10/13, 8310180344

8310180551 Notification of 831021 meeting w/BWR licenses in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking
MIRALTA, F J. Assistant Director for Safety Assessment 83/10/14
EISENHUT, D O. Division of Licensing 5pp. 20823 358 24X
Fiche 50-000, 83/10/14, 8310180551

8310270012 Forwards IE Safeguards Insp Repts 50-321/83-26 & 50-366/83-28 on 830926-30 No noncompliance noted
DANCE, H C. Division of Project & Resident Programs 83/10/20
KELLY, R J. Georgia Power Co. 2pp. 20924 331 24X
Fiche 50-321, 83/10/20, 8310270012

--8310270023 IE Safeguards Insp Repts 50-321/83-26 & 50-366/83-28 on 830926-30 No noncompliance noted. Major areas inspected site orientation, review of security plan & procedures & security organization details withheld (ref 10CFR73.21)
MALL, B. L., McGuire, D R. Region 2, Office of Director 83/10/20
1p 20924 333 24X Fiche 50-321, 83/10/20, 8310270012

R Periodic operating reports & related correspondence

8310190014 Monthly operating repts for Sept 1983 W/830910 ltr
CURTIS, C M., NIX, H C. Georgia Power Co. 83/10/10. Director's Office, Office of Inspection and Enforcement 14pp. 20823 284 24X
Fiche 50-321, 83/10/10, 8310190014

B Reportable occurrences, LERs & related correspondence

8310210329 Response to FOIA request for all documents re significantly high rate of equipment failures for GE BWR/4 rated at 2,434 MW. Forwards App A documents Documents also available in PDR
FELTON, J M. Division of Rules and Records. 83/07/28 HAFNER, B.
Suffolk Nuclear Study Group 2pp 20882 223 24X
Fiche 50-000, 83/07/28, 8310210329.

8310180246 Submits preliminary account of events associated w/820825 reactor trip Reactor tripped from 99% power due to overpower condition on average power range monitor Caused by closure of one isolation valve on C main steam line
RUBIN, B D. Reactor Operations Analysis Branch 82/09/29
BEYFRIT, K. V. Reactor Operations Analysis Branch 5pp 20882 249
24X Fiche, 50-000, 83/07/28, 8310210329

7301180513 Evaluates LERs for Jul 1981 - Oct 1982 in support of upcoming BALP review LERs minimally adequate in narrative sections. Large number considered mgt deficiency-related
BEYFRIT, K. V. Director's Office. 83/01/12 LEWIS, R. Division of Project & Resident Programs 5pp. 20882 225 24X
Fiche, 50-000, 83/07/28, 8310210329.

83030318 LER 83-081/03L-0 on 830829, during performance of Procedure IP-2-3309, personnel determined HPCI turbine exhaust diaphragm pressure switch out of calibr. Caused by instrument tripout drift. Switch recalibr. W/830922 ltr
TIPPS, S B., NIX, H C. Georgia Power Co. 83/09/22. O'REILLY, J P
Region 2, Office of Director. App 20990 358 24X
Fiche 50-366, 83/09/22, 8310030318

8310030319 LER 83-092/03L-0 on 830831, RHIR svc water pump 2A declared inoperable after motor bearing began to overheat while trying to make up water to circulating water flume caused by partially blocked cooling water line W/830922 ltr
TIPPS, S B., NIX, H C. Georgia Power Co. 83/09/22. O'REILLY, J P
Region 2, Office of Director. App 20990 354 24X
Fiche 50-366, 83/09/22, 8310030319

8310030336 LER 83-057/03L-0 on 830824, while pulling control rods during normal reactor startup, rod block monitor A gave rod out block when certain control rods selected Caused by component failure W/830922 ltr
TIPPS, S B., NIX, H C. Georgia Power Co. 83/09/22. O'REILLY, J P
Region 2, Office of Director. App 20990 207 24X
Fiche 50-366, 83/09/22, 8310030336

8310030359 Updated LER 80-106/03X-1 on 800728, w/reactor in cold shutdown, insp of drywell insulation revealed crystalline deposits around seams on sacrificial shield Cause unknown Investigation inconclusive W/830922 ltr
TIPPS, S B., NIX, H C. Georgia Power Co. 83/09/22. O'REILLY, J P
Region 2, Office of Director. App 20592 134 24X
Fiche 50-366, 83/09/22, 8310030359

8310030382 Updated LER 82-088/03X-1 on 820806, control rod reed switch position indicator found inoperable Caused by failed rod position indication sys probe Probe replaced W/830922 ltr
TIPPS, S B., NIX, H C. Georgia Power Co. 83/09/22. O'REILLY, J P
Region 2, Office of Director. App 20592 172 24X
Fiche 50-366, 83/09/22, 8310030382

8310030415 Updated LER 83-071/03X-1 on 830808, control rod drive low pressure alarm received for HCU 2C11-22-19 Accumulator pressure found low Caused by leaking EP-111 nitrogen changing valve Valve replaced W/830922 ltr
TIPPS, S B., NIX, H C. Georgia Power Co. 83/09/22. O'REILLY, J P
Region 2, Office of Director. App 20593 168 24X
Fiche 50-366, 83/09/22, 8310030415

8310030433 LER 83-093/03L-0 on 830901, remote reactor pressure indicator 2C82-R006 failed to indicate within 40 psig of control reactor pressure indicator 2B21-R004A & declared inoperable Caused by setpoint drift Indicator calibr W/830922 ltr
TIPPS, S B., NIX, H C. Georgia Power Co. 83/09/22. O'REILLY, J P
Region 2, Office of Director. App 20602 079 24X
Fiche 50-366, 83/09/22, 8310030433

8310030442 LER 83-095/03L-0 on 830902, control rod drive hydraulic control unit 2C11-34-03 declared inoperable upon discovery of low accumulator pressure while investigating alarm Accumulator recharged & alarm cleared W/830922 ltr
TIPPS, S B., NIX, H C. Georgia Power Co. 83/09/22. O'REILLY, J P
Region 2, Office of Director. App 20602 065 24X
Fiche 50-366, 83/09/22, 8310030442

8310030486 LER 83-060/03L-0 on 830823, RHIR loop B min flow valve 2E11-F007B found to have no position indication Caused by blown fuse in control circuit of valve, due to loose fuse holder Holder tightened & fuse replaced W/830922 ltr
TIPPS, S B., NIX, H C. Georgia Power Co. 83/09/22. O'REILLY, J P
Region 2, Office of Director. App 20601 079 24X
Fiche 50-366, 83/09/22, 8310030486.

8310030510 LER 83-079/03L-0 on 830830, during performance of HPCI pump operability procedure, HPCI bearing temp recorder indicated higher temp than allowed Caused by broken wire on HPCI outboard bearing temp element, wire repaired W/830922 ltr
TIPPS, S B., NIX, H C. Georgia Power Co. 83/09/22. O'REILLY, J P
Region 2, Office of Director. App 20601 178 24X
Fiche 50-366, 83/09/22, 8310030510.

8310040409 LER 83-052/03L-0 on 830831, drywell particulate fission products monitor 2D11-K631 declared inoperable when counts per minute continually increased Caused by filter paper drive motor failure Motor replaced W/830927 ltr
TIPPS, S B., NIX, H C. Georgia Power Co. 83/09/27. O'REILLY, J P
Region 2, Office of Director. App 20619 088 24X
Fiche 50-366, 83/09/27, 8310040409

8310060011 LER 83-094/03L-0 on 830901, during performance of Procedure HNP-2-3882, hydrogen/oxygen analyzer A (2P33-F001A) found out of calibr Caused by setpoint drift Analyzer recalibr W/830927 ltr
TIPPS, S B., NIX, H C. Georgia Power Co. 83/09/27. O'REILLY, J P
Region 2, Office of Director. App 20649 295 24X
Fiche 50-366, 83/09/27, 8310060011

8310120408 Revised LER 83-045/03X-1 on 830816, during diesel generator manual start procedure, diesel generator 2R43-S001A failed to start per Tech Specs Caused by bent engine governor shutdown solenoid & plunger, bent parts replaced W/830930 ltr
TIPPS, S B., NIX, H C. Georgia Power Co. 83/09/30. O'REILLY, J P
Region 2, Office of Director. App 20699 033 24X
Fiche 50-366, 83/09/30, 8310120408

DOCKETED ITEMS

245

8310170509 LER 83-096/030-0 on 830906, plant personnel determined valve 2E32-F001P would not open when key lock control switch placed in test position Caused by burned up motor Motor replaced W/831005 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/10/05 O'REILLY, J P
Region 2, Office of Director App 20784 113 24X
Fiche 50-366, 83/10/05, 8310170509

8310170531 LER 83-097/03L-0 on 830913, plant personnel determined link CC-30 in panel 2H11-P627 open Cause unknown Standing order issued to prevent recurrence W/831006 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/10/06 O'REILLY, J P
Region 2, Office of Director App 20784 199 24X
Fiche 50-366, 83/10/06, 8310170531

8310170584 Updated LER 82-068/03X-1 on 820707 & 24, volumetric weighted average drywell air temp exceeded Tech Spec limit of 135 F Caused by high ambient temp & failure of alternate chiller fans 85 & 90 New chilling units installed W/831006 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/10/26 O'REILLY, J P
Region 2, Office of Director App 20780 233 24X
Fiche 50-366, 83/10/06, 8310170584

8310250343 LER 83-086/03L-0 on 830919, during performances of Procedure HNP-2-3101, reactor vessel water low-low level instruments 2B21-N0258, Switch 2 & 2B21-N025A, Switch 1, failed to actuate properly Caused by setpoint drift W/831014 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/10/14 O'REILLY, J P
Region 2, Office of Director App 20898 071 24X
Fiche 50-366, 83/10/14, 8310250343

8310250212 LER 83-100/03L-0 on 830926, during control panel walkdown, discovered that reactor vessel water level recorder not recording properly Caused by failed chart drive gear Recorder repaired W/831017 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/10/17 O'REILLY, J P
Region 2, Office of Director App 20693 319 24X
Fiche 50-366, 83/10/17, 8310250212

8310250285 LER 83-099/03L-0 on 830925, while performing Procedure HNP-2-3101, hydrogen analyzer A would not calibr Analyzer panel & drywell & torus recorder declared inoperable Caused by worn sample pump diaphragms W/831017 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/10/17 O'REILLY, J P
Region 2, Office of Director App 20896 001 24X
Fiche 50-366, 83/10/17, 8310250285

8310250291 LER 83-082/03L-0 on 830922, operations personnel determined RCIC percent demand indication off On 830925, RCIC failed to reach rated flow & pressure Caused by setpoint drift High current limiter adjusted W/831017 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/10/17 O'REILLY, J P
Region 2, Office of Director App 20895 343 24X
Fiche 50-366, 83/10/17, 8310250291

8310250311 LER 83-088/03L-0 on 830922, during control locked valve Procedure HNP-514, noninterruptible instrument air supply valves 2P52 F457 & F460 found unlocked Caused by personnel error Valves locked in position W/831017 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/10/17 O'REILLY, J P
Region 2, Office of Director App 20894 360 24X
Fiche 50-366, 83/10/17, 8310250311

8310250312 LER 83-061/03L-0 on 830921, during RCIC turbine exhaust diaphragm pressure instrument Procedure HNP-2-3414, connection line inadvertently broke off RCIC turbine D exhaust diaphragm pressure switch W/831017 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/10/17 O'REILLY, J P
Region 2, Office of Director App 20898 020 24X
Fiche 50-366, 83/10/17, 8310250312

8310250506 LER 83-098/03L-0 on 830924, 2C11-02-27 & 2C11-14-27 accumulators declared inoperable following control rod low pressure or high level alarm Caused by leaking nitrogen charge valve Valve replaced W/831017 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/10/17 O'REILLY, J P
Region 2, Office of Director App 20702, 073, 24X
Fiche 50-366, 83/10/17, 8310250506

8310250061 RD on 831018, drywell equipment drain sump pump 2011-C006B became inoperable w/redundant pump also inoperable Cause not stated Increase of 1.9 gpm unidentified leakage into sump drain requested for 30-day period
NIX, H C Georgia Power Co, 83/10/19 STOLZ, J F Operating Reactors Branch 4 2pp 20896 072 24X Fiche 50-366, 83/10/19, 8310250061

8310310236 LER 83-101/03L-0 on 830927, reactor bldg exhaust vent radiation monitor D 2D11-K609A indicated decreased sensitivity of OM tube W/831020 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/10/20 O'REILLY, J P
Region 2, Office of Director App 20947 203 24X
Fiche 50-366, 83/10/20, 8310310236

8310310259 LER 83-059/03L-0 on 830928, during scram recovery procedure, primary containment isolation valve for traversing in-tore probe B would not close Caused by failed ball valve Ball valve replaced, tested & returned to svc W/831020 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/10/20 O'REILLY, J P
Region 2, Office of Director App 20947 163 24X
Fiche 50-366, 83/10/20, 8310310259

8310310280 LER 83-106/03L-0 on 831001, after personnel backfilled torus water level transmitters 2T48-N021A & B, water level determined to be below Tech Spec requirement Caused by normal evaporation Ref legs backfilled W/831020 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/10/20 O'REILLY, J P
Region 2, Office of Director App 20961 286 24X
Fiche 50-366, 83/10/20, 8310310280

8310310363 LER 83-083/03L-0 on 830928, both recirculation pumps tripped Caused by packing binding inside reactor level instrument 2B21-N031B low pressure side manifold isolation valve Valve operated open-to-close then close-to-open W/831020 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/10/20 O'REILLY, J P
Region 2, Office of Director App 20961 117 24X
Fiche 50-366, 83/10/20, 8310310363

V Operator Examinations

8310250519 Forwards IE Training Assessment Repts 50-321/83-23 & 50-366/83-24 on 830802-05 No noncompliance noted
LEWIS, R C Division of Project & Resident Programs 83/09/19
KELLY, R J Georgia Power Co 2pp 20901 021 24X
Fiche 50-321, 83/09/19, 8310250519

--8310250560 IE Training Assessments Repts 50-321/83-23 & 50-366/83-24 on 830802-05 No noncompliance noted. Major areas inspected
Licensed & nonlicensed operator training, requalification programs & onshift/real-time training & mgt training
HEHL, C W , WATSON, L J Region 2, Office of Director
PANCICRA, V W Division of Project & Resident Programs 83/09/15, 10pp 20901 023 24X Fiche 50-321, 83/09/19, 8310250519.

DOCKET 50-367 DAILY GENERATING STATION

Q Adjudicatory correspondence

8310110278 Requests status rept on author fee petition
WHICHER, J M Businessmen for the Public Interest WHICHER, J M
Whicher, J M 83/10/05 PLAINE, H E Office of the General Counsel.
2pp 20665 327 24X Fiche 50-367, 83/10/05, 8310110278

DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2

F Security, medical, emergency & fire protection plans

8310060520 Forwards clarification of NRC positions on certain requirements of App R to 10CFR50.4B
STOLZ, J F , MILLER, J R Operating Reactors Branch 4 83/09/14,
GRIFFIN, J M Arkansas Power & Light Co 8pp 20663, 139, 24X
Fiche 50-313, 83/09/14, 8310060520

8310030416 Submits addl info re mods to Fire Zones 2100-Z & 2101-AA, per 830713 request for App R scheduled exemption. Delivery of pump switchgear expected in late Jan 1984
MARSHALL, J R Arkansas Power & Light Co 83/09/27, STOLZ, J F
Operating Reactors Branch 4, MILLER, J R Operating Reactors Branch 3 2pp 20593 166, 24X Fiche 50-313, 83/09/27, 8310030416

8310060243 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records, 83/09/30 Document Management Branch, 1p 20660-276 24X Fiche 50-313, 83/09/30, 8310060243

--8310060250 Public version of Rev 4 to Emergency Plan Implementing Procedure 1903.01, "Organization & Use of Emergency Plan Implementing Procedures" & Rev 10 to Procedure 1903.10, "Emergency Action Level Response"
LEVINE, J M Arkansas Power & Light Co 83/09/19, 32pp, 20660, 277, 24X Fiche 50-313, 83/09/30, 8310060243.

8310060597 Releases public version of revised emergency plan
FELTON, J M Division of Rules and Records, 83/10/05, Document Management Branch, 1p, 20661, 092, 24X Fiche 50-313, 83/10/05, 8310060597.

--8310060601 Public version of Rev 8 to emergency plan W/830922 ltr.
MARSHALL, J R Arkansas Power & Light Co 83/09/14 COLLINS, J T
Region 4, Office of Director, 56pp 20661-093 24X
Fiche 50-313, 83/10/05, 8310060597.

DOCKETED ITEMS

8310250559 Withdraws request for scheduler exemption until 830501 to complete installation of certain 1 h rated fire barriers
 Mods completed by 830422
 MARSHALL, J R Arkansas Power & Light Co 83/10/07 STOLZ, J F
 Operating Reactors Branch 4 MILLER, J R Operating Reactors Branch
 3 1p 20900 346 24X Fiche 50-313, 83/10/07, 8310250559

8310140096 Forwards corrected Attachments 24 1 & 27 1 to IAEA design info questionnaire for safeguards program submitted in 830822 ltr
 MARSHALL, J R Arkansas Power & Light Co 83/10/10 EISENHUT, D G
 Division of Licensing 2pp 20766 096 24X Fiche 50-368, 83/10/10, 8310140096

8310190291 Releases public version of amend to emergency plan
 FELTON, J M Division of Rules and Records 83/10/14 Document
 Management Branch 1p 20840 143 24X Fiche 50-313, 83/10/14, 8310190291

--8310190292 Public version of Amend 8 to emergency plan
 * Arkansas Power & Light Co 83/09/14 60pp 20840 144 24X
 Fiche 50-313, 83/10/14, 8310190291

8310190294 Releases public version of revised emergency plan implementing procedure
 FELTON, J M Division of Rules and Records 83/10/14 Document
 Management Branch 1p 20841 341 24X Fiche 50-313, 83/10/14, 8310190294

--8310190295 Public version of Rev 11 to Emergency Plan Implementing Procedure 1903 10, "Emergency Action Level Response"
 4/831002 ltr & receipt form
 LEVINE, J M Arkansas Power & Light Co 83/10/01 70pp
 20841 342 24X Fiche 50-313, 83/10/14, 8310190294

8310250274 Updates present status & describes tasks performed over previous 6 months per requirements of Generic Ltr 82-33 & Suppl 1 to NUREG-0737 re control room design review Figure 2-2 encl
 MARSHALL, J R Arkansas Power & Light Co 83/10/20 EISENHUT, D G
 Division of Licensing 4pp 20902 340 24X Fiche 50-313, 83/10/20, 8310250274

J Insurance & indemnity information

8310240035 Forwards Endorsements 53, 54 & 55 to NELIA Policy NF-210 & Endorsements 46 & 47 to MAELU Policy MF-74
 MARSHALL, J R Arkansas Power & Light Co 83/10/12 DINITZ, I
 Assistant Director for State & License Relations 6pp 20881 353
 24X Fiche 50-313, 83/10/12, 8310240035

P Operating license stage documents & correspondence

8310060402 Forwards NPDES Permit AR0001392, effective 830606 - 840705, per NRC 830311 ltr & util 830520 confirmation.
 MARSHALL, J R Arkansas Power & Light Co 83/06/10 COLLINS, J T
 Region 4, Office of Director 3pp 20641 229 24X
 Fiche 50-313, 83/06/10, 8310060402

--8310060406 NPDES Permit AR0001392, issued to Arkansas Power & Light Co
 KNUDSON, M D Environmental Protection Agency 83/05/04 28pp
 20641.232 24X Fiche 50-313, 83/06/10, 8310060402

8310030337 Application to amend License NPF-6, changing Tech Spec 4 & 4.1 b & Table 3 3-9 re hydrogen analyzer calibr & remote shutdown panel instrumentation, respectively
 GRIFFIN, J M Arkansas Power & Light Co 83/09/27 MILLER, J R
 Operating Reactors Branch 3 4pp 20590 211 24X
 Fiche 50-368, 83/09/27, 8310030337

--8310030340 Proposed Tech Spec 4 & 4.1 b & Table 3 3-9 re hydrogen analyzer calibr & remote shutdown panel instrumentation, respectively
 * Arkansas Power & Light Co 83/09/27 4pp 20590 215 24X
 Fiche 50-368, 83/09/27, 8310030337

8310030332 Updates 830520 request for extension of deadline for environ qualification of equipment Status of specific items enumerated.
 MARSHALL, J R Arkansas Power & Light Co 83/09/28 STOLZ, J F
 Operating Reactors Branch 4 MILLER, J R Operating Reactors Branch
 3 4pp 20592 311 24X Fiche 50-313, 83/09/28, 8310030332

831010618 Summary of 830923 meeting w/util in Bethesda, MD re Tech Specs for mechanical & hydraulic snubbers Agenda & marked-up Tech Specs encl
 VIBBINO, O S Operating Reactors Branch 4 83/09/30 Operating
 Reactors Branch 4 13pp 20715.160 24X Fiche 50-313, 83/09/30, 831010618

8310120079 Forwards updated radiological effluent Tech Specs & offsite dose calculation manual, per 830510 request Implementation date of 830101 established
 GRIFFIN, J M Arkansas Power & Light Co 83/09/30 STOLZ, J F
 Operating Reactors Branch 4 MILLER, J R Operating Reactors Branch
 3 3pp 20696 241 24X Fiche 50-313, 83/09/30, 8310120079

--8310120081 Revs to radiological effluent Tech Specs
 * Arkansas Power & Light Co 83/09/30 116pp 20696 244 24X
 Fiche 50-313, 83/09/30, 8310120079

--8310120083 Revs to offsite dose calculation manual
 * Arkansas Power & Light Co 83/09/30 99pp 20696 360 24X
 Fiche 50-313, 83/09/30, 8310120079

8310130097 Forwards nonproprietary & proprietary responses to 830802 telcon request for addl info re proposed Tech Spec change concerning in-core detectors Affidavit encl Proprietary rept withheld (ref 10CFR2 790)
 GRIFFIN, J M Arkansas Power & Light Co 83/09/30 MILLER, J R
 Operating Reactors Branch 3 10pp 20725 277 24X
 Fiche 50-368, 83/09/30, 8310130097

--8310130109 Nonproprietary "Responses to NRC Questions re Arkansas Nuclear Unit 2 Cycle 3 Tech Spec Change" Proprietary info deleted (ref 10CFR2 790)
 * Combustion Engineering, Inc CEN-250(A)-NP 83/08/31 3pp.
 20725 287 24X Fiche 50-368, 83/09/30, 8310130097

8310210080 Requests remittance of fee due for 830215 application re deletion of terrestrial monitoring programs within 15 days
 MILLER, W O License Fee Management Branch 83/10/17 GRIFFIN, J M
 Arkansas Power & Light Co 1p 20883 251 24X
 Fiche 50-313, 83/10/17, 8310210080

8310250281 Advises of delay in providing addl info re NUREG-0737, Item 11 B 3 concerning post-accident sampling sys, per 830714 request, due to outage beginning ahead of schedule Info expected by 831025
 MARSHALL, J R Arkansas Power & Light Co 83/10/17 STOLZ, J F
 Operating Reactors Branch 4 MILLER, J R Operating Reactors Branch
 3 1p. 20898 362 24X Fiche 50-368, 83/10/17, 8310250281

8310250533 Advises of correction of CPC software discrepancy, per 831011 telcon Mod will be performed prior to initial reactor criticality for Cycle 5 & will not be contingent on schedule for other software changes
 MARSHALL, J R Arkansas Power & Light Co 83/10/18 MILLER, J R
 Operating Reactors Branch 3 1p 20902 142 24X
 Fiche 50-368, 83/10/18, 8310250533

Q Inspection reports, IE Bulletins & correspondence

8310060020 Forwards IE Insp Repts 50-313/83-13 & 50-368/83-13 on 830606-10 No noncompliance noted
 SEIDLE, W C Region 4, Office of Director 83/08/01 GRIFFIN, J M
 Arkansas Power & Light Co 2pp 20647 156 24X
 Fiche 50-313, 83/08/01, 8310060020

--8310060026 IE Insp Repts 50-313/83-13 & 50-368/83-13 on 830606-10 No noncompliance noted Major areas inspected action on previous violations, onsite radiation protection organization, staff qualifications & training, exposure control & ALARA program
 CHANEY, H D, HOLLEY, W L, MURRAY, D Region 4, Office of Director
 83/07/20 19pp 20647 138 24X Fiche 50-313, 83/08/01, 8310060020

8310250153 Provides status of work accomplished in response to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts," & IC Bulletin 79-14 "Seismic Analyses for As-Built Safety Related Piping Sys"
 MARSHALL, J R Arkansas Power & Light Co 83/08/05 COLLINS, J T
 Region 4, Office of Director 1p 20896 343 24X
 Fiche 50-313, 83/08/05, 8310250153

8310130220 Forwards IE Insp Repts 50-313/83-15 & 50-368/83-15 on 830701-31 No noncompliance noted
 SEIDLE, W C Region 4, Office of Director 83/08/10 GRIFFIN, J M
 Arkansas Power & Light Co 2pp 20724 105 24X
 Fiche 50-313, 83/08/10, 8310130220

--8310130226 IE Insp Repts 50-313/83-15 & 50-368/83-15 on 830701-31 No noncompliance noted Major areas inspected operational safety verification, surveillance, maint & followup on previously identified items
 CALLAN, L J, CUMMINS, J E, JOHNSON, W D Region 4, Office of
 Director 83/08/05 12pp 20724 107 24X Fiche 50-313, 83/08/10, 8310130220

DOCKETED ITEMS

24

8310130330 Forwards IE Insp Repts 50-313/83-21 & 50-368/83-21 on 830801-31 & notice of violation
SEIDLE, W C Region 4, Office of Director 83/09/16 GRIFFIN, J M
Arkansas Power & Light Co 2pp 20719 343 24X
Fiche 50-313, 83/09/16, 8310130330 *

--8310130323 Notice of violation from insp on 830801-31
* Region 4, Office of Director 83/09/16 4pp 20719 345 24X
Fiche 50-313, 83/09/16, 8310130330

--8310130335 IE Insp Repts 50-313/83-21 & 50-368/83-21 on 830801-31
Noncompliance noted failure to properly identify calculation
& design change, to perform maint activities w/written
procedure & to install electrical cables per procedures
CALLAN, L J, CUMMINS, J E, JOHNSON, W D Region 4, Office of
Director 83/09/15 11pp 20719 349 24X Fiche 50-313, 83/09/16,
8310130330

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder
Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
Detectors Positioned at Control Room Ventilation Air
Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse
Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to
Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New
York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass
Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical
Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect
Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective
Self-Contained Breathing Apparatus Air Cylinders " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

R Periodic operating reports & related correspondence

8310190045 Monthly operating rept for Aug 1983 W/830915 1tr
BRAHLETT, L S, MARSHALL, J R Arkansas Power & Light Co 83/09/15
BASSETT, H S Division of Data Automation & Management Information
7pp 20823 224 24X Fiche 50-368, 83/09/15, 8310190045

S Reportable occurrences, LERs & related correspondence

8310040398 LER 83-038/03L-0 on 830818, core protection calculator
Channel A placed in bypass & Channel D tripped Caused by
point identification Number 064 for channels reading less
than min W/830919 1tr
ROGERS, P, MARSHALL, J R Arkansas Power & Light Co 83/09/19
SEIDLE, W C Region 4, Office of Director 3pp 20617 275 24X
Fiche 50-368, 83/09/19, 8310040398

8310040149 LER 83-040/03L-0 on 830831, control element assembly 47
dropped to lower electrical limit Caused by blown fuse
Opened Fuse replaced, current traces taken & tightness of
connections checked W/830920 1tr
ROGERS, P, MARSHALL, J R Arkansas Power & Light Co 83/09/20
SEIDLE, W C Region 4, Office of Director 2pp 20608 026 24X
Fiche 50-368, 83/09/20, 8310040149

8310040206 Corrected LER 83-033/03X-1 on 830828, during Full power, Fire
Door 274 to cable spreading room had gap of greater than
3/4 inch at bottom Caused by improper installation
guidance New threshold plate installed W/830922 1tr
ROGERS, P, MARSHALL, J R Arkansas Power & Light Co 83/09/22
SEIDLE, W C Region 4, Office of Director 2pp 20614 324 24X
Fiche 50-368, 83/09/22, 8310040206

8310030476 PNO-IV-83-029 on 830926, unit shut down due to inability to
comply w/Tech Spec action statement following discovery
that station battery 2D11 failed quarterly surveillance test
on 830922 Condition not recognized by mgt until 830926,
JOHNSON, W D, CALLAN, L J Region 4, Office of Director 83/09/27,
1p 20601 066 24X Fiche 50-368, 83/09/27, 8310030476

8310130180 LER 83-044/01T-0 on 830922, battery 2D11 failed surveillance
Reactor shut down Corrective actions on physical battery
impairment & administrative failure under evaluation
W/830927 1tr
LEVINE, J M Arkansas Power & Light Co 83/09/27 COLLINS, J
Region 4, Office of Director 1p 20724 325 24X
Fiche 50-368, 83/09/27, 8310130180

8310130283 LER 83-043/03L-0 on 830907, contract person posted for
fire watch duty discovered asleep Individual awakened &
relieved Disciplinary actions taken Fire watch policy
expanded W/830930 1tr
ROGERS, P, MARSHALL, J R Arkansas Power & Light Co 83/09/30
SEIDLE, W C Region 4, Office of Director 3pp 20723 144 24X
Fiche 50-368, 83/09/30, 8310130283

8310180489 Updated LER 82-007/03X-2 on 820216, leak discovered in weld
for drain line of suction bladder of charging pump 2P-36C
Caused by vibration-induced cracking Check of pulse
inflation added to preventative maint cycle W/830930 1tr
ROGERS, P, MARSHALL, J R Arkansas Power & Light Co 83/09/30
SEIDLE, W C Region 4, Office of Director 3pp 20800 155 24X
Fiche 50-368, 83/09/30, 8310180489

8310180457 LER 83-041/03L-0 on 830831, core protection channel D point
identification 008 read conservatively high Cause
undetermined Evaluation will be performed to determine cause
& corrective action W/831003 1tr
ROGERS, P, MARSHALL, J R Arkansas Power & Light Co 83/10/03
SEIDLE, W C Region 4, Office of Director 3pp 20801 344 24X
Fiche 50-368, 83/10/03, 8310180457

8310180529 Updated LER 83-008/03X-1 on 830207, during walkdown, fire
barrier deficiencies discovered On 831006, inadequate fire
barrier penetration seals identified Caused by inadequate
work controls Fire watch posted W/831006 1tr
ROGERS, P, MARSHALL, J R Arkansas Power & Light Co 83/10/06
SEIDLE, W C Region 4, Office of Director 4pp 20801 181 24X
Fiche 50-368, 83/10/06, 8310180529

8310180189 LER 83-044/01T-0 on 830926, battery 2D11 failed quarterly
surveillance test Caused by normal aging coupled w/
insufficient equalizing charges Surveillance procedure
limits will be treated as Tech Spec limits W/831010 1tr,
MOEDENBERG, D, MARSHALL, J R Arkansas Power & Light Co 83/10/10
SEIDLE, W C Region 4, Office of Director 3pp 20808 349 24X
Fiche 50-368, 83/10/10, 8310180189

8310310368 LER 83-042/03L-0 on 830913 & 15, junction box for conduits in
Fire Zone 2150 discovered open & gap between floor & Fire
Doors 340 & 267 exceeded acceptance criteria Caused by
exclusion of zones from installation specs W/831012 1tr,
ROGERS, P, MARSHALL, J R Arkansas Power & Light Co 83/10/12
GAGLIARDI, J E Region 4, Office of Director 3pp 20959 180 24X
Fiche 50-368, 83/10/12, 8310310368

DDCKET 50-369 WILLIAM B MCQUIRE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8310040511 Summarizes 830916 mgt meeting in Atlanta, GA re security
barrier problems at facility
O'REILLY, J P Region 2, Office of Director 83/09/21 TUCKER, H B
Duke Power Co 1p 20623 096 24X Fiche 50-369, 83/09/21,
8310040511

8310060265 Releases public version of revised station directive
FELTON, J M Division of Rules and Records, 83/09/30 Document
Management Branch 1p 20660 226 24X Fiche 50-369, 83/09/30,
8310060265

DOCKETED ITEMS

- 8310060268 Public version of Rev 5 to Station Directive 3 B 2, "Technical Support Ctr." W/830706 ltr
MCINTOSH, M. D., TUCKER, H. B. Duke Power Co. 83/06/24 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENBAM, E. G. Licensing Branch 4 6pp 20660 227 24X Fiche 50-369, 83/09/30, 8310060265
- 8310070134 Releases public version of revised crisis mgt plan implementing procedures
FELTON, J. M. Division of Rules and Records 83/10/04 Document Management Branch 1p 20670 001 24X Fiche 50-000, 83/10/04, 8310070134
- 8310070143 Forwards public version of revised crisis mgt plan implementing procedures, including Procedures 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group
TUCKER, H. B. Duke Power Co. 83/07/06 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp 20670 002 24X Fiche 50-000, 83/10/04, 8310070134
- 8310070152 Public version of revised crisis mgt plan implementing procedures, including Procedure 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group
* Duke Power Co. 83/07/01 457pp 20670 005 24X Fiche 50-000, 83/10/04, 8310070134
- 831010413 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records 83/10/05 Document Management Branch 1p 20714 001 24X Fiche 50-369, 83/10/05, 831010413
- 831010418 Forwards public version of revised Emergency Plan Implementing Procedure GP/1/A/6200/48 re operation of post-accident liquid sample sys & Station Directive 2 0 5 re news releases
TUCKER, H. B. Duke Power Co. 83/06/14 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENBAM, E. G. Licensing Branch 4 1p 20714 002 24X Fiche 50-369, 83/10/05, 831010413
- 831010421 Public version of revised Emergency Plan Implementing Procedure GP/1/A/6200/48 re operation of post-accident liquid sample sys & Station Directive 2 0 5 re news releases
MCCONNELL, T. L., BEAVER, B. Duke Power Co. 83/05/16 21pp 20714 003 24X Fiche 50-369, 83/10/05, 831010413
- 831010072 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records 83/10/07 Document Management Branch 1p 20709 086 24X Fiche 50-369, 83/10/07, 831010072
- 831010077 Forwards public version of revised emergency plan implementing procedures, including Procedures HP/0/B/1009/02 re alternate method for determining dose rate within reactor bldg & PT/O/A/4600/06 re exercises & drills.
TUCKER, H. B. Duke Power Co. 83/08/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENBAM, E. G. Licensing Branch 4 2pp 20709 087 24X Fiche 50-369, 83/10/07, 831010072
- 831010079 Public version of revised emergency plan implementing procedures, including Procedures HP/0/B/1009/02 re alternate method for determining dose rate within reactor bldg & PT/O/A/4600/06 re exercises & drills
GLOVER, M. B., MCCONNELL, T. L. Duke Power Co. 83/08/03 71pp 20709 089 24X Fiche 50-369, 83/10/07, 831010072
- 831010444 Responds to request for crisis mgt ctr staff to participate emergency exercises at same frequency as technical support ctr staff. Crisis mgt team will be activated in 1-scale exercise involving full state participation
GER, H. B. Duke Power Co. 83/10/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 20802 121 24X Fiche 50-000, 83/10/10, 831010444
- 831010416 Forwards Rev 5 to security training & qualification plan withheld (ref 10CFR73 21) Plans will be updated to include changes
MER, H. B. Duke Power Co. 83/10/10 O'REILLY, J. P. Region 2, Office of Director 1p 20759 303 24X Fiche 50-369, 83/10/10, 831010416
- 831010435 Informs that periodic evaluation of GALP complete Rept roved.
EILLY, J. P. Region 2, Office of Director. 83/10/17 TUCKER, H. B. Duke Power Co. 3pp 20900 205 24X Fiche 50-000, 83/10/17, 831010435
- 8310250652 GALP Repts 50-269/83-17, 50-270/83-17, 50-281/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83 13 for June 1982 - Apr 1983
* Region 2, Office of Director 83/08/02 46pp 20900 211 24X Fiche 50-000, 83/10/17, 8310250652
- 8310270026 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records 83/10/20 Document Management Branch 1p 20942 018 24X Fiche 50-369, 83/10/20, 8310270026
- 8310270136 Forwards public version of revised station directives & Change 2 to Emergency Plan Implementing Procedure GP/1/A/6200/48 re post-accident liquid sample sys
TUCKER, H. B. Duke Power Co. 83/10/06 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENBAM, E. G. Licensing Branch 4 1p 20942 019 24X Fiche 50-369, 83/10/20, 8310270026
- 8310270146 Public version of revised station directives & Change 2 to Emergency Plan Implementing Procedure GP/1/A/6200/48 re post-accident liquid sample sys
MCCONNELL, T. L., BEAVER, B. Duke Power Co. 83/09/29 39pp 20942 020 24X Fiche 50-369, 83/10/20, 8310270026
- J Insurance & indemnity information
- 8310210312 Forwards Endorsement 2B to NELIA Policy NF-24B & Endorsement 23 to MAELU Policy MF-101
LAWSON, L. T. Duke Power Co. 83/10/17 SALTZMAN, J. H. C. - Na Detailed Affiliation Given 3pp 20851 016 24X Fiche 50-369, 83/10/17, 8310210312
- P Operating license stage documents & correspondence
- 8310040368 Forwards proprietary "McQuire Post-Mod Steam Generator Tube Vibration Monitoring Program," preliminary rept, summarizing results of May-June 1983 steam generator tests Rept withheld (ref 10CFR2 790)
TUCKER, H. B. Duke Power Co. 83/08/02 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENBAM, E. G. Licensing Branch 4 2pp 20620 333 24X Fiche 50-369, 83/08/02, 8310040368
- 8310040474 Application to amend Licenses NPF-9 & NPF-17, changing tech Specs to increase upper limit for containment lower compartment to 125 F for up to 90 cumulative days provided lower compartment temp less than 120 F
TUCKER, H. B. Duke Power Co. 83/09/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENBAM, E. G. Licensing Branch 4 3pp 20622 308 24X Fiche 50-369, 83/09/22, 8310040474
- 8310040482 Proposed Tech Specs increasing upper limit for containment lower compartment to 125 F for up to 90 cumulative days per calendar yr provided lower compartment temp averaged over previous 365 days less than 120 F
* Duke Power Co. 83/09/22 3pp 20622 311 24X Fiche 50-369, 83/09/22, 8310040474
- 8310030604 Forwards SER re response to Generic Ltr B1-21, "Natural Circulation Cooldown." Upon acceptable implementation of emergency response guidelines, procedures will be adequate to perform safe natural circulation cooldown
NOVAK, T. M. Assistant Director for Licensing 83/09/23 PARRIS, H. O. Tennessee Valley Authority 2pp 20607 288 24X Fiche 50-000, 83/09/23, 8310030604
- 8310030607 SER accepting B1201 response to Generic Ltr B1-21, "Natural Circulation Cooldown"
* NRC - No Detailed Affiliation Given 83/09/23 8pp 20607 290 24X Fiche 50-000, 83/09/23, 8310030604
- 8310050076 Concurs w/dissolution of Model D2/D3 Steam Generator Unit Design Review Panel Panel work complete
NOVAK, T. M. Assistant Director for Licensing 83/09/23 BLACKLEY, B. K. Design Review Panel 5pp 20650 165 24X Fiche 50-000, 83/09/23, 8310050076
- 8310190199 Forwards safety evaluation re util response to Generic Ltr B1-21 "Natural Circulation Cooldown" Upon acceptable implementation of emergency response guidelines, procedures adequate for safe natural circulation cooldown
NOVAK, T. M. Assistant Director for Licensing 83/09/30 TUCKER, H. B. Duke Power Co. 2pp 20838 098 24X Fiche 50-000, 83/09/30, 8310190199
- 8310190208 SER re response to Generic Ltr B1-21 "Natural Circulation Cooldown" Response acceptable.
* NRC - No Detailed Affiliation Given 83/09/30 8pp 20838 100 24X Fiche 50-000, 83/09/30, 8310190199

DOCKETED ITEMS

249

8310170710 Forwards Amends 24 & 25 to Licenses NPF-9 & NPF-17, respectively & safety evaluation Amends authorize maintaining hot standby conditions w/o preceeding to cold shutdown for Unit 1
ADENSAM, E G Licensing Branch 4 83/10/06 TUCKER, H B Duke Power Co 2pp 20798 134 24X Fiche 50-369, 83/10/06, 8310170710

--8310170719 Amends 24 & 5 to Licenses NPF-9 & NPF-17, respectively, authorizing maintaining hot standby conditions w/o preceeding to cold shutdown for Unit 1
ADENSAM, E G Licensing Branch 4 83/10/06 7pp 20798 136 24X Fiche 50-369, 83/10/06, 8310170710

--8310170726 Safety evaluation supporting Amends 24 & 5 to Licenses NPF-9 & NPF-17, respectively
* Office of Nuclear Reactor Regulation, Director 83/10/06 2pp 20798 143 24X Fiche 50-369, 83/10/06, 8310170710

8310140205 Forwards offsite dose calculation manual, Rev 2 Rev corrects typographical errors & updates meteorological info
TUCKER, H B Duke Power Co 83/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 1p 20762 349 24X Fiche 50-369, 83/10/07, 8310140205

--8310140207 Offsite dose calculation manual, Rev 2
STEWART, J M Duke Power Co 83/09/30 6pp 20762 350 24X Fiche 50-369, 83/10/07, 8310140205

8310210131 Responds to 830901 request that rod control sys interim operating restrictions be removed based on acceptable results from recent unit & cycle specific analysis Agrees that restrictions no longer apply for first cycle
NOVAK, F M Assistant Director for Licensing 83/10/18 TUCKER, H B Duke Power Co 2pp 20863 327 24X Fiche 50-369, 83/10/18, 8310210131

8310280037 Forwards Amends 6 & 25 to Licenses NPF-9 & NPF-17, respectively, safety evaluation & request for FR publication Amends authorize transfer of spent fuel between Units 1 & 2
ADENSAM, E G Licensing Branch 4 83/10/19 TUCKER, H B Duke Power Co 3pp 20964 120 24X Fiche 50-369, 83/10/19, 8310280037

0 Inspection reports, IE Bulletins & correspondence

8310250580 Ack receipt of 830810 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-26 & 50-370/83-33 Acceptability of response under review
LEWIS, R C Division of Project & Resident Programs 83/08/29 TUCKER, H B Duke Power Co 1p 20900 352 24X Fiche 50-369, 83/08/29, 8310250580

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 77pp 20892 026 24X Fiche 50-000, 83/10/07, 8308300752

8310250514 Ack receipt of 830810 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-26 & 50-370/83-33 Evaluation of radiation hazard associated w/ transfer of neutron source adequate Violation withdrawn
O'REILLY, J P Region 2, Office of Director 83/10/07 TUCKER, H B Duke Power Co 2pp 20901 279 24X Fiche 50-369, 83/10/07, 8310250514

--8310250524 Responds to NRC 830711 ltr re violations noted in IE Insp Repts 50-369/83-26 & 50-370/83-33 Violation re failure to perform adequate neutron radiation survey denied Sound health physics judgment used
TUCKER, H B Duke Power Co 83/08/10 O'REILLY, J P Region 2, Office of Director 3pp 20901 281 24X Fiche 50-369, 83/10/07, 8310250514

--8310250530 Forwards IE Insp Repts 50-369/83-26 & 50-370/83-33 on 830606-10 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/07/11 TUCKER, H B Duke Power Co 2pp 20901 284 24X Fiche 50-369, 83/10/07, 8310250514

--8310250534 Notice of violation from insp on 830606-10
* Region 2, Office of Director 83/07/11 1p 20901 286 24X Fiche 50-369, 83/10/07, 8310250514

--8310250540 IE Insp Repts 50-369/83-26 & 50-370/83-33 on 830606-10 Noncompliance noted failure to perform adequate neutron radiation survey to evaluate extent of radiation hazards present prior to permitting worker entry.
COLLINS, T R, BARR, K P Region 2, Office of Director 83/06/28 6pp 20901 287 24X Fiche 50-369, 83/10/07, 8310250514

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310250635 Informs that periodic evaluation of SALP complete Rept approved
O'REILLY, J P Region 2, Office of Director 83/10/17 TUCKER, H B Duke Power Co 3pp 20900 205 24X Fiche 50-000, 83/10/17, 8310250635

--8310250646 Forwards SALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983
LEWIS, R C Division of Project & Resident Programs 83/08/02 TUCKER, H B Duke Power Co 3pp 20900 208 24X Fiche 50-000, 83/10/17, 8310250635

--8310250652 SALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983
* Region 2, Office of Director 83/08/02 56pp 20900 211 24X Fiche 50-000, 83/10/17, 8310250635

--8310250665 Responds to 830802 ltr re SALP board rept Rept incomplete & premature in certain areas in general, until endorses observations re facility performance.
TUCKER, H B Duke Power Co 83/08/29 O'REILLY, J P Region 2, Office of Director 2pp 20900 267 24X Fiche 50-000, 83/10/17, 8310250635

R Periodic operating reports & related correspondence

8310180100 Monthly operating repts for Sept 1983 w/831014 ltr
REAVIS, J A, TUCKER, H B Duke Power Co 83/10/14 Director's Office, Office of Inspection and Enforcement 10pp 20807 163 24X Fiche 50-369, 83/10/14, 8310180100

B Reportable occurrences, LERs & related correspondence

8310060058 Forwards LERs 83-072/03L-0 & 83-044/03L-0, Detailed event analysis encl
TUCKER, H B Duke Power Co 83/09/28 O'REILLY, J P Region 2, Office of Director 3pp 20648 328 24X Fiche 50-369, 83/09/28, 8310060058

DOCKETED ITEMS

--B310060063 LER 83-072/03L-0 on 830914, while in Mode 1, review determined that inadequate fire barrier provided between electrical penetration rooms located in auxiliary bldg. Caused by error during identification of fire barrier penetrations
NARDDCI, P B Duke Power Co 83/09/28 Region 2, Office of Director 1p 20648 331 24X Fiche 50-369, 83/09/28, 8310060058

--B310060068 LER 83-044/03L-0 on 830915, review revealed inadequate fire barrier provided between electrical penetration rooms located in auxiliary bldg. Caused by error during identification of fire barrier penetrations
NARDDCI, P B Duke Power Co 83/09/28 Region 2, Office of Director 1p 20648 332 24X Fiche 50-369, 83/09/28, 8310060058

8310060384 LER 83-073/03L-0 on 830829, surveillance test review determined that monthly test on RCS cold leg accumulator pressure not performed by required date of 830906. Caused by personnel error W/830928 ltr
NARDDCI, P B, TUCKER, H B Duke Power Co 83/09/28 O'REILLY, J P Region 2, Office of Director 2pp 20646 052 24X Fiche 50-369, 83/09/28, 8310060384

8310120413 LER 83-074/03L-0 on 830830, while in Mode 1, invalid fire alarm on Fire Detection Zone EFA-80 received in control room & alarm would not reset. EFA-80 declared inoperable. Caused by dust accumulation in detector W/830929 ltr
NARDDCI, P B, TUCKER, H B Duke Power Co 83/09/29 O'REILLY, J P Region 2, Office of Director 2pp 20698 330 24X Fiche 50-369, 83/09/29, 8310120413

8310170248 LER 83-076/03L-0 on 830901, Fire Door 819A found propped up against wall w/screws removed from door hinges. Caused by door deliberately removed from frame due to dragging problem. Door repaired W/830930 ltr
NARDDCI, P B, TUCKER, H B Duke Power Co 83/09/30 O'REILLY, J P Region 2, Office of Director 2pp 20787 069 24X Fiche 50-369, 83/09/30, 8310170248

8310170384 LER 83-075/03L-0 on 830831, while attempting to open valve 1N1-200B for stroke timing during nuclear sampling valve stroke timing quarterly test, valve failed to open. Caused by burned up actuator. Actuator will be replaced W/830930 ltr
NARDDCI, P B, TUCKER, H B Duke Power Co 83/09/30 O'REILLY, J P Region 2, Office of Director 2pp 20785 029 24X Fiche 50-369, 83/09/30, 8310170384

8310170430 LER 83-077/03L-0 on 830907, while in Mode 1, Channel 4 of loose parts monitor declared inoperable because of circuit noise & continuous alarm. Probably caused by short in accelerometer or flexible cable W/831005 ltr
NARDDCI, P B, TUCKER, H B Duke Power Co 83/10/05 O'REILLY, J P Region 2, Office of Director 4pp 20779 218 24X Fiche 50-369, 83/10/05, 8310170430

8310210308 LER 83-078/03L-0 on 830906, while in Mode 3, invalid fire alarm on fire detection zone EFA 152 received. Fire alarm would not reset & EFA 152 declared inoperable. Cause unknown. Alarm reset w/unit at power W/831006 ltr
NARDDCI, P B, TUCKER, H B Duke Power Co 83/10/06 O'REILLY, J P Region 2, Office of Director 2pp 20691 152 24X Fiche 50-369, 83/10/06, 8310210308

8310210005 LER 83-079/03L-0 on 830908 & 26, steam line IC radiation monitor 1EMF-26 declared inoperable due to sporadic operation of light & checksource function. Caused by OM tube load resistor below limit. Resistor replaced W/831007 ltr
NARDDCI, P B, TUCKER, H B Duke Power Co 83/10/07 O'REILLY, J P Region 2, Office of Director 2pp 20855 164 24X Fiche 50-369, 83/10/07, 8310210005

8310210309 LER 83-080/03L-0 on 830909, during performance of periodic ice condenser intermediate deck door & monitoring sys insp, two intermediate deck doors discovered frozen shut. Caused by unusual svc conditions W/831007 ltr
NARDDCI, P B, TUCKER, H B Duke Power Co 83/10/07 O'REILLY, J P Region 2, Office of Director 2pp 20851 072 24X Fiche 50-369, 83/10/07, 8310210309

10210028 RD 369/83-81 on 830910, fire detection instrumentation found degraded. Investigation & rept preparation incomplete. Rept will be submitted by 831028
TUCKER, H B Duke Power Co 83/10/10 O'REILLY, J P Region 2, Office of Director 1p 20856 011 24X Fiche 50-369, 83/10/10, 8310210028

10270173 LER 83-082/03L-0 on 830911, pressurizer heater group 1B declared inoperable when operation did not aid in RCS pressure control. Caused by blown 500 amp line fuse in vacuum contractor cabinet. Fuse replaced W/831011 ltr
NARDDCI, P B, TUCKER, H B Duke Power Co 83/10/11 O'REILLY, J P Region 2, Office of Director 2pp 20924 173 24X Fiche 50-369, 83/10/11, 8310270173

8310250071 LER 83-084/01T-0 on 830929, nuclear svc water train A declared inoperable after containment spray sys train B declared inoperable on 830928, constituting degraded mode. Caused by water in oil reservoir for pump 1A W/831014 ltr
NARDDCI, P B, TUCKER, H B Duke Power Co 83/10/14 O'REILLY, J P Region 2, Office of Director 3pp 20696 078 24X Fiche 50-369, 83/10/14, 8310250071

8310250074 Forwards LERs 83-085/01T-0 & 83-090/01T-0 Detailed event analysis encl
TUCKER, H B Duke Power Co 83/10/14 O'REILLY, J P Region 2, Office of Director 4pp 20894 133 24X Fiche 50-369, 83/10/14, 8310250074

--8310250076 LER 83-085/01T-0 on 830930, discovered that equipment/cable interfaces using Crouse-Hinds conduit coupling as sealing method may be susceptible to moisture seepage. Caused by design oversight in failure to test connections
NARDDCI, P B Duke Power Co 83/10/14 Region 2, Office of Director 1p 20894 137 24X Fiche 50-369, 83/10/14, 8310250074

--8310250080 LER 83-090/01T-0 on 830930, discovered that equipment/cable interfaces using Crouse-Hinds conduit coupling as sealing method may be susceptible to moisture seepage. Caused by design oversight in failure to test connections
NARDDCI, P B Duke Power Co 83/10/14 Region 2, Office of Director 1p 20894 138 24X Fiche 50-369, 83/10/14, 8310250074

DOCKET 50-370 WILLIAM B MCQUIRE NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8310040511 Summarizes 830916 mgt meeting in Atlanta, GA re security barrier problems at facility
O'REILLY, J P Region 2, Office of Director 83/09/21 TUCKER, H B Duke Power Co 1p 20623 096 24X Fiche 50-369, 83/09/21, 8310040511

8310070128 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/09/26 Document Management Branch 1p 20671 102 24X Fiche 50-370, 83/09/26, 8310070128

--8310070131 Public version of revised Emergency Plan Implementing Procedure QP/2/A/6200/4B, "Operating Procedure for Operation of Post-Accident Liquid Sampling Sys" W/830915 ltr
MCINNELL, T, TUCKER, H B Duke Power Co 83/08/19 DENISON, H R Office of Nuclear Reactor Regulation, Director 19pp 20671 103 24X Fiche 50-370, 83/09/26, 8310070128

8310060265 Releases public version of revised station directive
FELTON, J M Division of Rules and Records 83/09/30 Document Management Branch 1p 20660 226 24X Fiche 50-369, 83/09/30, 8310060265

--8310060268 Public version of Rev 5 to Station Directive 3 B 2, "Technical Support Ctr" W/830706 ltr
MCINTOSH, M D, TUCKER, H B Duke Power Co 83/06/24 DENISON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E G Licensing Branch 4 6pp 20660 227 24X Fiche 50-369, 83/09/30, 8310060265

8310070134 Releases public version of revised crisis mgt plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/04 Document Management Branch 1p 20670 001 24X Fiche 50-000, 83/10/04, 8310070134

--8310070143 Forwards public version of revised crisis mgt plan implementing procedures, including Procedures 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group
TUCKER, H B Duke Power Co 83/07/04 DENISON, H R Office of Nuclear Reactor Regulation, Director 3pp 20670 002 24X Fiche 50-000, 83/10/04, 8310070134

--8310070152 Public version of revised crisis mgt plan implementing procedures, including Procedure 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group
* Duke Power Co 83/07/01 457pp 20670 005 24X Fiche 50-000, 83/10/04, 8310070134

8310110413 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20714 001 24X Fiche 50-369, 83/10/05, 8310110413

--B310110418 Forwards public version of revised Emergency Plan implementing Procedure OP/1/A/6200/48 re operation of post-accident liquid sample sys & Station Directive 2.0.5 re news releases
TUCKER, H. B. Duke Power Co 83/06/14 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENSAM, E. O. Licensing Branch 4 1p 20714 002 24X Fiche 50-369, 83/10/05, 8310110413

--B310110421 Public version of revised Emergency Plan implementing Procedure OP/1/A/6200/48 re operation of post-accident liquid sample sys & Station Directive 2.0.5 re news releases
MCCONNELL, T. L., DEEVER, B. Duke Power Co 83/05/16 21pp 20714 003 24X Fiche 50-369, 83/10/05, 8310110413

B310110072 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records 83/10/07 Document Management Branch 1p 20709 086 24X Fiche 50-369, 83/10/07, 8310110072

--B310110077 Forwards public version of revised emergency plan implementing procedures, including Procedures HP/D/B/1009/02 re alternate method for determining dose rate within reactor bldg & PT/D/A/4600/06 re exercises & drills
TUCKER, H. B. Duke Power Co 83/08/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENSAM, E. O. Licensing Branch 4 2pp 20709 087 24X Fiche 50-369, 83/10/07, 8310110072.

--B310110079 Public version of revised emergency plan implementing procedures, including Procedures HP/D/B/1009/02 re alternate method for determining dose rate within reactor bldg & PT/D/A/4600/06 re exercises & drills
GLOVER, H. B., MCCONNELL, T. L. Duke Power Co 83/08/05 71pp 20709 089 24X Fiche 50-369, 83/10/07, 8310110072

B310180444 Responds to request for crisis mgt ctr staff to participate in emergency exercises at same frequency as technical support ctr staff. Crisis mgt team will be activated in full-scale exercise involving full state participation
TUCKER, H. B. Duke Power Co 83/10/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 20802 121 24X Fiche 50-000, 83/10/10, 8310180444

B310310416 Forwards Rev 5 to security training & qualification plan Rev withheld (ref 10CFR73.21). Plans will be updated to include changes
TUCKER, H. B. Duke Power Co 83/10/10 O'REILLY, J. P. Region 2, Office of Director 1p 20959 303 24X Fiche 50-369, 83/10/10, 8310310416

B310250635 Informs that periodic evaluation of SAMP complete Rept approved
O'REILLY, J. P. Region 2, Office of Director 83/10/17 TUCKER, H. B. Duke Power Co 3pp 20900 205 24X Fiche 50-000, 83/10/17, 8310250635

--B310250652 SAMP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983
J. Region 2, Office of Director 83/08/02 56pp 20900 211 24X Fiche 50-000, 83/10/17, 8310250635

B310270026 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records 83/10/20 Document Management Branch 1p 20942 018 24X Fiche 50-369, 83/10/20, 8310270026

--B310270136 Forwards public version of revised station directives & Change 2 to Emergency Plan implementing Procedure OP/1/A/6200/48 re post-accident liquid sample sys
TUCKER, H. B. Duke Power Co 83/10/06 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENSAM, E. O. Licensing Branch 4 1p 20742 019 24X Fiche 50-369, 83/10/20, 8310270026.

--B310270146 Public version of revised station directives & Change 2 to Emergency Plan implementing Procedure OP/1/A/6200/48 re post-accident liquid sample sys
MCCONNELL, T. L., DEEVER, B. Duke Power Co 83/09/29, 39pp, 20742 020 24X Fiche 50-369, 83/10/20, 8310270026

J Insurance & indemnity information

B310210312 Forwards Endorsement 28 to NELA Policy NF-248 & Endorsement 23 to MAELU Policy MF-101
LAWSON, L. T. Duke Power Co 83/10/17 SALTZMAN, J. NRC - No Detailed Affiliation Given 2pp, 20851 076 24X Fiche 50-369, 83/10/17, 8310210312

P Operating license stage documents & correspondence

B310040474 Application to amend Licenses NPF-9 & NPF-17, changing Tech Specs to increase upper limit for containment lower compartment to 125 F for up to 90 cumulative days provided lower compartment temp less than 120 F.
TUCKER, H. B. Duke Power Co 83/09/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENSAM, E. O. Licensing Branch 4 3pp 20622 308 24X Fiche 50-369, 83/09/22, 8310040474

--B310040482 Proposed Tech Specs increasing upper limit for containment lower compartment to 125 F for up to 90 cumulative days per calendar yr provided lower compartment temp averaged over previous 365 days less than 120 F
* Duke Power Co 83/09/22 3pp, 20622 311 24X Fiche 50-369, 83/09/22, 8310040474

B310030604 Forwards SER re response to Generic Ltr B1-21, "Natural Circulation Cooldown." Upon acceptable implementation of emergency response guidelines, procedures will be adequate to perform safe natural circulation cooldown
NOVAK, T. M. Assistant Director for Licensing 83/09/24 PARRIS, H. O. Tennessee Valley Authority 2pp 20607 288 24X Fiche 50-000, 83/09/23, 8310030604

--B310030607 SER accepting B1201 response to Generic Ltr B1-21, "Natural Circulation Cooldown."
* NRC - No Detailed Affiliation Given, 83/09/23 8pp 20607 290, 24X Fiche 50-000, 83/09/23, 8310030604

B310050076 Concurs w/dissolution of Model D2/D3 Steam Generator Util Design Review Panel Panel work complete
NOVAK, T. M. Assistant Director for Licensing 83/09/23 BLACKLEY, B. K. Design Review Panel 3pp 20650 165 24X Fiche 50-000, 83/09/23, 8310050076

B310190199 Forwards safety evaluation re util response to Generic Ltr B1-21 "Natural Circulation Cooldown." Upon acceptable implementation of emergency response guidelines, procedures adequate for safe natural circulation cooldown
NOVAK, T. M. Assistant Director for Licensing 83/09/30 TUCKER, H. B. Duke Power Co 2pp 20838 098 24X Fiche 50-000, 83/09/30, 8310190199

B310170710 Forwards Amends 24 & 25 to Licenses NPF-9 & NPF-17, respectively & safety evaluation. Amends authorize maintaining hot standby conditions w/o proceeding to cold shutdown for Unit 1
ADENSAM, E. O. Licensing Branch 4 83/10/06 TUCKER, H. B. Duke Power Co 2pp 20798 134 24X Fiche 50-369, 83/10/06, 8310170710

--B310170719 Amends 24 & 5 to Licenses NPF-9 & NPF-17, respectively, authorizing maintaining hot standby conditions w/o proceeding to cold shutdown for Unit 1
ADENSAM, E. O. Licensing Branch 4 83/10/06 7pp, 20798 136 24X Fiche 50-369, 83/10/06, 8310170710

--B310170736 Safety evaluation supporting Amends 24 & 5 to Licenses NPF-9 & NPF-17, respectively
* Office of Nuclear Reactor Regulation, Director 83/10/06 2pp 20798 143 24X Fiche 50-369, 83/10/06, 8310170710.

B310140205 Forwards offsite dose calculation manual, Rev 2 Rev corrects typographical errors & updates meteorological info
TUCKER, H. B. Duke Power Co 83/10/07 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENSAM, E. O. Licensing Branch 4 1p 20762 349, 24X Fiche 50-369, 83/10/07, 8310140205.

--B310140207 Offsite dose calculation manual, Rev 2
STEWART, J. M. Duke Power Co. 83/09/30 6pp 20762:350, 24X Fiche 50-369, 83/10/07, 8310140205

B310210131 Responds to B30901 request that rod control sys interim operating restrictions be removed based on acceptable results from recent unit & cycle specific analysis. Agrees that restrictions no longer apply for first cycle.
NOVAK, T. M. Assistant Director for Licensing 83/10/18, TUCKER, H. B. Duke Power Co 2pp 20883 327, 24X Fiche: 50-369, 83/10/18, 8310210131.

B310280037 Forwards Amends 6 & 25 to Licenses NPF-9 & NPF-17, respectively, safety evaluation & request for FR publication. Amends authorize transfer of spent fuel between Units 1 & 2.
ADENSAM, E. O. Licensing Branch 4, 83/10/19 TUCKER, H. B. Duke Power Co 3pp 20964 120 24X Fiche 50-369, 83/10/19, 8310280037.

DOCKETED ITEMS

D Inspection reports, IE Bulletins & correspondence

8310250580 Act receipt of 830810 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-26 & 50-370/83-33 Acceptability of response under review
LEWIS, R C Division of Project & Resident Programs 83/08/29
TUCKER, H B Duke Power Co Jp 20900 352 24X
Fiche 50-369, 83/08/29, 8310250580

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8310250514 Act receipt of 830810 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-26 & 50-370/83-33 Evaluation of radiation hazard associated w/ transfer of neutron source adequate Violation withdrawn
O'REILLY, J P Region 2, Office of Director 83/10/07 TUCKER, H B Duke Power Co 2pp 20901 279 24X Fiche 50-369, 83/10/07, 8310250514

--8310250524 Responds to NRC 830711 ltr re violations noted in IE Insp Repts 50-369/83-26 & 50-370/83-33 Violation re failure to perform adequate neutron radiation survey denied Sound health physics judgment used
TUCKER, H B Duke Power Co 83/08/10 O'REILLY, J P Region 2, Office of Director 3pp 20901 281 24X Fiche 50-369, 83/10/07, 8310250514

--8310250530 Forwards IE Insp Repts 50-369/83-26 & 50-370/83-33 on 830606-10 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/07/11
TUCKER, H B Duke Power Co 2pp 20901 284 24X
Fiche 50-369, 83/10/07, 8310250534

--8310250534 Notice of violation from insp on 830606-10
* Region 2, Office of Director 83/07/11 1p 20901 286 24X
Fiche 50-369, 83/10/07, 8310250534

--8310250540 IE Insp Repts 50-369/83-26 & 50-370/83-33 on 830606-10 Noncompliance noted failure to perform adequate neutron radiation survey to evaluate extent of radiation hazards present prior to permitting worker entry
COLLINS, T R, BARR, K P Region 2, Office of Director 83/06/28 4pp 20901 287 24X Fiche 50-369, 83/10/07, 8310250514

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning: Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310250635 Informs that periodic evaluation of BALP complete Rept approved

O'REILLY, J P Region 2, Office of Director 83/10/17 TUCKER, H B Duke Power Co 3pp 20900 205 24X Fiche 50-000, 83/10/17, 8310250635

--8310250646 Forwards BALP Repts 50-269/83-17, 50-270/83-17, 50-271/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983
LEWIS, R C Division of Project & Resident Programs 83/08/02
TUCKER, H B Duke Power Co 3pp 20900 208 24X
Fiche 50-000, 83/10/17, 8310250635

--8310250652 BALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983
* Region 2, Office of Director 83/08/02 56pp 20900 211 24X
Fiche 50-000, 83/10/17, 8310250635

--8310250665 Responds to 830802 ltr re BALP board rept Rept incomplete & premature in certain areas In general, until endorses observations re facility performance
TUCKER, H B Duke Power Co 83/08/29 O'REILLY, J P Region 2, Office of Director 2pp 20900 267 24X Fiche 50-000, 83/10/17, 8310250635

R Periodic operating reports & related correspondence

8310180100 Monthly operating repts for Sept 1983 W/831014 ltr
REAVIS, J A, TUCKER, H B Duke Power Co 83/10/14 Director's Office, Office of Inspection and Enforcement 10pp 20807 161 24X
Fiche 50-369, 83/10/14, 8310180100

B Reportable occurrences, LERs & related correspondence

8310040403 Updated LER 83-035/03X-1 on 830726, during routine surveillance, two of four upper head injection level switch setpoints found out of tolerance Caused by design deficiency, Switch recalibr Mod implemented, W/830921 ltr
NARDOCI, P B, TUCKER, H B Duke Power Co 83/09/21 O'REILLY, J P Region 2, Office of Director 3pp 20647 354 24X
Fiche 50-370, 83/09/21, 8310040403

8310060255 LER 83-043/03L-0 from 830627-0707, during isolation valve leak rate test, penetrations M259, M322, M327, M330 & M385 failed to meet Tech Specs. Caused by authorized mods & component malfunction, respectively W/830923 ltr
NARDOCI, P B, TUCKER, H B Duke Power Co 83/09/23 O'REILLY, J P Region 2, Office of Director 4pp 20647 029 24X
Fiche 50-370, 83/09/23, 8310060255

8310060058 Forwards LERs 83-072/03L-0 & 83-044/03L-0 Detailed event analysis encl
TUCKER, H B Duke Power Co 83/09/28 O'REILLY, J P Region 2, Office of Director, 3pp 20648 328 24X Fiche 50-369, 83/09/28, 8310060058

--8310060068 LER 83-044/03L-0 on 830915, review revealed inadequate fire barrier provided between electrical penetration rooms located in auxiliary bldg Caused by error during identification of fire barrier penetrations
NARDOCI, P B Duke Power Co 83/09/28 Region 2, Office of Director 1p 20648 332 24X Fiche 50-369, 83/09/28, 8310060058

8310210077 LER 83-045/03L-0 on 830907, containment sump level wide-range channel B incorrectly indicated 2 ft of water in containment sump Channel B declared inoperable Caused by low side housing bellows installed w/incorrect matl
NARDOCI, P B, TUCKER, H B Duke Power Co 83/10/07 O'REILLY, J P Region 2, Office of Director 2pp 20898 202 24X
Fiche 50-370, 83/10/07, 8310210077

8310270048 LER 83-046/03L-0 on 830912, during removal of tachometer for calibr, turbine-driven auxiliary feedwater pump started & could not be stopped from either local panel or control room Caused by blown fuse Fuse replaced W/831012 ltr
NARDOCI, P B, TUCKER, H B Duke Power Co 83/10/12 O'REILLY, J P Region 2, Office of Director 3pp 20924 112 24X
Fiche 50-370, 83/10/12, 8310270048

8310250074 Forwards LERs 83-085/01T-0 & 83-030/01T-0 Detailed event analysis encl
TUCKER, H B Duke Power Co 83/10/14, O'REILLY, J P, Region 2, Office of Director 4pp 20894 133, 24X Fiche: 50-369, 83/10/14, 8310250074

--8310250080 LER 83-030/01T-0 on 830930, discovered that equipment/cable interfaces using Crouse-Hinds conduit coupling as sealing method may be susceptible to moisture seepage Caused by design oversight in failure to test connections
NARDOCI, P B Duke Power Co 83/10/14, Region 2, Office of Director 1p 20894 138 24X Fiche 50-369, 83/10/14, 8310250074

DOCKETED ITEMS

253

8310270209 LER 83-048/03L-0 on 830914, 15 & 16, average lower containment temp exceeded Tech Spec requirements. Caused by const & design deficiencies. Bus air handling units realigned to cooler source & cooling flow increased W/831014 ltr NARDOCCI, P B, TUCKER, H B Duke Power Co 83/10/14 O'REILLY, J P Region 2, Office of Director 4pp 20924 097 24X Fiche 50-370, 83/10/14, 8310270209

8310270310 LER 83-049/03L-0 on 830916, investigation of cabinet trouble alarm revealed "operate" light for steam line 2A radiation monitor ZEMP-10 failed & could not be restored. Caused by component failure. OH tube replaced W/831014 ltr NARDOCCI, P B, TUCKER, H B Duke Power Co 83/10/14 O'REILLY, J P Region 2, Office of Director 2pp 20923 190 24X Fiche 50-370, 83/10/14, 8310270310

DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8310030227 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/09/28 Document Management Branch 1p 20603 057 24X Fiche 50-373, 83/09/28, 8310030227

--8310030236 Public version of Rev 4 to Emergency Plan Implementing Procedure LTP-1700-2, "Station Employee List" * Commonwealth Edison Co 83/06/09 20pp 20603 038 24X Fiche 50-373, 83/09/28, 8310030236

8310040444 Forwards Rev 15 to security plan Rev withheld (ref 10CFR73.21) FARRAR, D L Commonwealth Edison Co 83/09/30 Office of Nuclear Reactor Regulation, Director 1p 20619 052 24X Fiche 50-373, 83/09/30, 8310040444

8310180250 Forwards IE Insp Repts 50-373/83-36 & 50-374/83-35 on 830914-16 No noncompliance noted PAPERIELLO, C J Region 3, Office of Director 83/10/04 REED, C Commonwealth Edison Co 2pp 20802 332 24X Fiche 50-373, 83/10/04, 8310180250

--8310180257 IE Insp Repts 50-373/83-36 & 50-374/83-35 on 830914-16 No noncompliance noted. Major areas inspected emergency preparedness program including licensee action on previously identified items & licensee audits. PLESKI, T, PHILLIPS, M P Region 3, Office of Director 83/10/03 6pp 20802 334 24X Fiche 50-373, 83/10/04, 8310180250

8310110118 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20686 315 24X Fiche 50-373, 83/10/05, 8310110118

--8310110123 Public version of Rev 4 to Emergency Plan Implementing Procedure LTP-1700-3, "Station Phone List" W/830825 ltr & revised index HOLYOAK, R H Commonwealth Edison Co 83/07/01 Office of Nuclear Reactor Regulation, Director 23pp 20686 316 24X Fiche 50-373, 83/10/05, 8310110118

8310170664 Responds to 830722 ltr re Rev 14 to security plan Portions of plan acceptable. Items from previously approved plan should be followed. For portions inconsistent w/10CFR50.54 Enc1 withheld (ref 10CFR73.21) SCHWENGER, A Licensing Branch 2 83/10/12 FARRAR, D L Commonwealth Edison Co 2pp 20779 293 24X Fiche 50-373, 83/10/12, 8310170664

8310170707 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/10/13 Document Management Branch 1p 20813 242 24X Fiche 50-373, 83/10/13, 8310170707

--8310170711 Public version of Rev 3 to Emergency Plan Implementing Procedure LTP-1330-24, "Determination of Reactor Coolant Hydrogen Offgas Concentrations at High Radiation Sampling Sys" W/830928 ltr & receipt form HOLYOAK, R H Commonwealth Edison Co 83/09/16 38pp 20813 243 24X Fiche 50-373, 83/10/13, 8310170707

8310200416 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/10/17 Document Management Branch 1p 20859 233 24X Fiche 50-373, 83/10/17, 8310200416

--8310200424 Public version of Rev 5 to Emergency Plan Implementing Procedure LTP-1110-1, "Station Director (Acting Station Director)" W/831003 ltr, receipt form & 10CFR50.59 format for safety evaluation HOLYOAK, R H Commonwealth Edison Co 83/10/03 27pp 20859 234 24X Fiche 50-373, 83/10/17, 8310200416

8310270526 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 2093/ 216 24X Fiche 50-000, 83/10/21, 8310270526

--8310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure EDF-6, "Administration & Logistics Manager" W/831017 ltr & receipt form NELLIS, C A Commonwealth Edison Co 83/02/18 DENTON, H R NRC - No Detailed Affiliation Given 7pp 20937 217 24X Fiche 50-000, 83/10/21, 8310270536

8310280206 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20964 148 24X Fiche 50-373, 83/10/25, 8310280206

--8310280215 Public version of revised Emergency Plan Implementing Procedures LTP-1320-1 re augmentation of plant staffing, LTP-1550-11 re post-accident sampling equipment inventory & LTP-1700-2 re station employee list * Commonwealth Edison Co 83/07/25 43pp 20964 149 24X Fiche 50-373, 83/10/25, 8310280206

8310280307 Releases public version of revised generating stations emergency plan telephone directory FELTON, J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20963 126 24X Fiche 50-000, 83/10/25, 8310280307

--8310280314 Public version of revised generating stations emergency plan telephone directory OALLC, D P Commonwealth Edison Co 83/08/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 64pp 20963 127 24X Fiche 50-000, 83/10/25, 8310280307

8310280191 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/10/26 Document Management Branch 1p 20962 266 24X Fiche 50-000, 83/10/26, 8310280191

--8310280209 Public version of Rev 1 to Emergency Plan Implementing Procedure EDF-15, "Emergency Operations Facility Activation" MOORE, R D Commonwealth Edison Co 83/08/02 80pp 20962 267 24X Fiche 50-000, 83/10/26, 8310280191

K Utility Final Safety Analysis Report (FSAR) & amendments

8310180249 Forwards affidavit of distribution of Amend 63 to FSAR SCHROEDER, C W Commonwealth Edison Co 83/10/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20807 081 24X Fiche 50-373, 83/10/10, 8310180249

P Operating license stage documents & correspondence

8310200273 Forwards schedules for equipment qualification test programs for facilities per 810528 ltr. Dates given for current qualification activities should be viewed as "target-dates" & not as firm dates. BARNES, P L Commonwealth Edison Co 83/10/05 KEPLER, J O, Region 3, Office of Director 10pp 20830 034 24X Fiche 50-000, 83/10/05, 8310200273

8310120433 Discusses proposed rev to primary containment vent & purge valve closure times. Util will replace &/or modify eight 26-inch valves & two 8-inch valves per unit to permit 15 s or less closure time. Marked-up Tech Spec enc1 SCHROEDER, C W Commonwealth Edison Co 83/10/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20698 298 24X Fiche 50-373, 83/10/06, 8310120433

8310180281 Forwards marked-up changes to Amend 63 to FSAR Tables 14.2-130, 14.2-124, 14.2-114 & Figure 14.2-2 re startup test program. Summary of changes listed SCHROEDER, C W Commonwealth Edison Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 20807 028 24X Fiche 50-373, 83/10/13, 8310180281

DOCKETED ITEMS

- 8310180377 Confirms 831003 telcon re util decision to perform feedwater pump trip vibration monitoring at two snubber locations in Unit 2 based on Unit 1 test results
SCHROEDER, C W Commonwealth Edison Co 83/10/13 DENTON, H R 24X
Office of Nuclear Reactor Regulation, Director 1p 20803 317
Fiche 50-373, 83/10/13, 8310180377
- 8310180425 Describes results of main turbine bypass sys testing performed to determine position vs flow relationship for main turbine bypass valves, per Tech Spec 3/4 7 10
SCHROEDER, C W Commonwealth Edison Co 83/10/13 DENTON, H R 24X
Office of Nuclear Reactor Regulation, Director 2pp 20803 303
Fiche 50-373, 83/10/13, 8310180425
- 8310190258 Forwards proprietary "In-Plant Safety Relief Valve Test, LaSalle County Station Unit 1," final evaluation rept Rept withheld (ref 10CFR2 790)
SCHROEDER, C W Commonwealth Edison Co 83/10/14 DENTON, H R 24X
Office of Nuclear Reactor Regulation, Director 4pp 20820 120
Fiche 50-373, 83/10/14, 8310190258
- 8310240275 Documents NRC position re elements that must be considered in computation of acceptable closure time for containment purge & vent valves, in response to 831006 ltr justification for interim operation requested
SCHWENGER, A Licensing Branch 2 83/10/18 FARRAR, D L Commonwealth Edison Co 2pp 20907 320 24X
Fiche 50-373, 83/10/18, 8310240275
- 8310250684 Denies request for extension re submittal on Generic Ltr 83-28, "Clarification of Required Actions on Generic Implications of Salem ATWS Events." Required info should be submitted to extent practical, by 831103
SCHWENGER, A Licensing Branch 2 83/10/18 FARRAR, D L Commonwealth Edison Co 2pp 20908 349 24X
Fiche 50-373, 83/10/18, 8310250684
- 8310250293 Forwards Rev 10 to Offsite Dose Calculation Manual for LaSalle & Quad Cities & Rev 9 to Offsite Dose Calculation Manual for Braidwood, consisting of Chapters 7 2 & 8
BENNETT, C J Commonwealth Edison Co 83/10/21 CASE, E G Office of Nuclear Reactor Regulation, Director 1p 20894 259 24X
Fiche 50-000, 83/10/21, 8310250293
- 8310250298 Rev 10 to Offsite Dose Calculation Manual for LaSalle & Quad Cities
* Commonwealth Edison Co 83/09/30 44pp 20894 260. 24X
Fiche 50-000, 83/10/21, 8310250293
- G Inspection reports, IE Bulletins & correspondence
- 8310050493 Forwards IE Insp Repts 50-373/83-30 & 50-374/83-29 on 830725-0909 & notice of violation
STREETEER, J F Region 3, Office of Director 83/09/22 REED, C Commonwealth Edison Co 2pp 20631 350 24X
Fiche 50-373, 83/09/22, 8310050493
- 8310050498 Notice of violation from insp on 830725-0909.
STREETEER, J F Region 3, Office of Director 83/09/22. 1p 20631 352 24X
Fiche 50-373, 83/09/22, 8310050493
- 8310050502 IE Insp Repts 50-373/83-30 & 50-374/83-29 on 830725-0909
Noncompliance noted diesel generator 2A not lined up for startup operation during performance of Preoperational Test PT-AP-203
LANKSBURY, R D, DUPONT, S G, REYES, L A Region 3, Office of Director 83/09/22 5pp 20631 353 24X
Fiche 50-373, 83/09/22, 8310050493
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins For Welder Qualification Tests." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X
Fiche 50-000, 83/09/26, 8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X
Fiche 50-000, 83/09/26, 8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001. 24X
Fiche 50-000, 83/09/26, 8308300345
- 8310040352 Confirms plans for 830930 enforcement conference in Glen Ellyn, IL to discuss inadvertent heatup event on 830824, which caused unplanned mode change & resulted in procedural violations
NORELIUS, C E Division of Project & Resident Programs 83/09/26 REED, C Commonwealth Edison Co 1p 20620 215 24X
Fiche 50-373, 83/09/26, 8310040352
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X
Fiche 50-000, 83/09/29, 8308300349
- 8310140213 Forwards IE Insp Repts 50-373/83-35 & 50-374/83-34 on 830804, 05, 08-11 & 13 No noncompliance noted
STREETEER, J F Region 3, Office of Director 83/09/29 REED, C Commonwealth Edison Co 2pp 20762 307 24X
Fiche 50-373, 83/09/29, 8310140213
- 8310140215 IE Insp Repts 50-373/83-35 & 50-374/83-34 on 830804, 05, 08 11 & 13 No noncompliance noted Major areas inspected review of previous open & unresolved items & followup on previous items of noncompliance
CHOULES, N C, HASSE, R A, RINTER, D R Region 3, Office of Director 83/09/28 6pp 20762 309 24X
Fiche 50-373, 83/09/29, 8310140213
- 8310120290 Provides supplemental response to IE Bulletin 80-16 re misapplication of Rosemount transmitters All changeouts in NSSS sys for Unit 2 complete
BARNES, P L Commonwealth Edison Co 83/10/04 KIEPLER, J G Region 3, Office of Director 2pp 20692 339 24X
Fiche 50-373, 83/10/04, 8310120290
- 8310180250 Forwards IE Insp Repts 50-373/83-36 & 50-374/83-35 on 830914-16 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 83/10/04 REED, C Commonwealth Edison Co 2pp 20802 334 24X
Fiche 50-373, 83/10/04, 8310180250
- 8310180257 IE Insp Repts 50-373/83-36 & 50-374/83-35 on 830914-16 No noncompliance noted Major areas inspected emergency preparedness program including licensee action on previously identified items & licensee audits
FLOSKI, T, PHILLIPS, M P Region 3, Office of Director 83/10/03 4pp 20802 334 24X
Fiche 50-373, 83/10/04, 8310180250
- 8310200124 Forwards IE Mgt Meeting Repts 50-010/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIUS, C E Division of Project & Resident Programs 83/10/04 REED, C Commonwealth Edison Co 2pp 20834 098 24X
Fiche 50-000, 83/10/04, 8310200124
- 8310200148 IE Mgt Meeting Repts 50-020/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIUS, C E Division of Project & Resident Programs 83/10/03 4pp 20834 100 24X
Fiche 50-000, 83/10/04, 8310200124
- 8310200159 Forwards IE Insp Repts 50-373/83-39 & 50-374/83-40 on 830915 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/10/05 REED, C Commonwealth Edison Co 2pp 20834 094 24X
Fiche 50-373, 83/10/05, 8310200159
- 8310200164 IE Insp Repts 50-373/83-39 & 50-374/83-40 on 830915 No noncompliance noted Major areas inspected fatigue usage factors & stress calculations for main steam drain piping
DANIELSON, D H, MUFFETT, J W Region 3, Office of Director 83/10/05 2pp 20834 096 24X
Fiche 50-373, 83/10/05, 8310200159
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X
Fiche 50-000, 83/10/07, 8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X
Fiche 50-000, 83/10/07, 8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X
Fiche 50-000, 83/10/11, 8308300759

DOCKETED ITEMS

251

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svr list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180187 Clarifies NRC position on procedures for admitting NRC personnel Certified access list encl Update will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 REED, C Commonwealth Edison Co 7pp 20809 086 24X Fiche 50-373, 83/10/14, 8310180187

8310180551 Notification of 831021 meeting w/BWR licensees in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking
HIRAGLIA, F J Assistant Director for Safety Assessment 83/10/14 EISENHUT, D G Division of Licensing 5pp 20823 358 24X Fiche 50-000, 83/10/14, 8310180551

8310250356 Ack receipt of 831018 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-30 & 50-374/83-29
STREETER, J F Region 3, Office of Director 83/10/20 REED, C Commonwealth Edison Co 1p 20898 117 24X Fiche 50-373, 83/10/20, 8310250356

--8310250361 Responds to NRC 830922 ltr re violations noted in IE Insp Repts 50-373/83-30 & 50-374/83-29 Corrective actions
Procedure LDP-DG-01 being clarified & step will be added to verify that ESF status panel checked after lineup completed
FARRAR, D L Commonwealth Edison Co 83/10/18 KEPLER, J Q Region 3, Office of Director 2pp 20898 120 24X Fiche 50-373, 83/10/20, 8310250361

S. Reportable occurrences, LERs & related correspondence

8310110430 Responds to FOIA request for four different categories of documents described in 830510 ltr Forwards matl listed in App A, responsive to Items 1,2 & 4 DOE should be contacted for matl requested in Item 3 of ltr
FELTON, J M Division of Rules and Records 83/06/14 HIATT, S L Ohio Citizens for Responsible Energy 3pp 20706 002 24X Fiche 50-000, 83/06/14, 8310110430

--8310110478 Responds to 830413 ltr requesting info re use of foreign mats on valve seating surfaces Lubricants & cleaning solvents used on valve component surfaces per vendor recommendations & maint practices
FARRAR, D L Commonwealth Edison Co 83/04/22 KEPLER, J Q Region 3, Office of Director App 20706 063 24X Fiche 50-000, 83/06/14, 8310110478

8310180273 LER 83-100/03L-0 on 830819, suppression pool nitrogen makeup downstream isolation valve 1V0050 would not close Caused by dirty torque switch contacts, preventing closing direction circuit from completing Contacts cleaned W/830913 ltr
DUS, R, DIEDERICH, G J Commonwealth Edison Co 83/09/13 KEPLER, J Q Region 3, Office of Director App 20802 292 24X Fiche 50-373, 83/09/13, 8310180273

8310120109 LER 83-105/01T-0 on 830914, reactor water level rapidly decreased from 50 inches to 0 inches causing Group VI PCIS initiation at 12 4 inches during valve lineup Caused by injection check valve being stuck open W/830927 ltr
WESTPHAL, B S, DIEDERICH, G J Commonwealth Edison Co 83/09/27 KEPLER, J Q Region 3, Office of Director App 20696 173, 24X Fiche 50-373, 83/09/27, 8310120109

8310060271 LER 83-106/03L-0 on 830830, blowdown flow recorder found reading low Caused by entrapped air in transmitter sensing lines Air removed & lines vented W/830928 ltr
MASTERSON, V, DIEDERICH, G J Commonwealth Edison Co 83/09/28 KEPLER, J Q Region 3, Office of Director App 20641 009 24X Fiche 50-373, 83/09/28, 8310060271

8310060186 LER 83-107/03L-0 on 830901, w/unit shutdown for planned outage, determined that valve leakage rate limits exceeded in all cases at least one isolation valve in piping line w/acceptable leakage rate W/830929 ltr
WITTENBURG, K C, DIEDERICH, G J Commonwealth Edison Co 83/09/29 KEPLER, J Q Region 3, Office of Director App 20647 152, 24X Fiche 50-373, 83/09/29, 8310060186

8310060198 LER 83-108/03L-0 on 830901, during LOS-RH-Q3, RHR A min flow bypass valve 1E12-F064A failed to close, Caused by broken trigger fingers holding motor operator in handwheel operation New fingers installed W/830929 ltr
HOUSTON, R W, DIEDERICH, G J Commonwealth Edison Co 83/09/29 KEPLER, J Q Region 3, Office of Director App 20647 146 24X Fiche 50-373, 83/09/29, 8310060198

8310140045 Updated LER 83-026/03X-1 on 830321, radwaste discharge process radiation monitor declared inoperable Caused by high fixed level of background radiation Equipment design changes investigated W/831003 ltr
ARAND, J J, DIEDERICH, G J Commonwealth Edison Co 83/10/03 KEPLER, J Q Region 3, Office of Director 3pp 20768 275 24X Fiche 50-373, 83/10/03, 8310140045

8310140069 LER 83-109/03L-0 on 830903, radwaste discharge line hi-hi radiation isolation valve OWL067 failed to fully close Caused by faulty valve piston Internal valve piston replaced W/831003 ltr
ARAND, J J, DIEDERICH, G J Commonwealth Edison Co 83/10/03 KEPLER, J Q Region 3, Office of Director 3pp 20768 012 24X Fiche 50-373, 83/10/03, 8310140069

8310140263 Updated LER 83-052/03X-1 on 830516, during valve calibr Procedure LES-MB-01, HSIV 1B21-F028C RPS trip channel, limit switch A2, failed to operate properly Caused by misalignment of limit switch actuating arm Arm readjusted W/831003 ltr
HOUSTON, R W, DIEDERICH, G J Commonwealth Edison Co 83/10/03 KEPLER, J Q Region 3, Office of Director 3pp 20761 267 24X Fiche 50-373, 83/10/03, 8310140263

8310140057 LER 83-110/03L-0 on 830908, while performing LES-QM-119, undervoltage relay 1427-AP037B failed to trip consistently within allowable time limits Caused by defective undervoltage relay ITE-27 Relay replaced W/831005 ltr
HIETALA, J J, DIEDERICH, G J Commonwealth Edison Co 83/10/05 KEPLER, J Q Region 3, Office of Director 3pp 20767 014 24X Fiche 50-373, 83/10/05, 8310140057

8310140073 LER 83-111/03L-0 on 830821, RHR pump A suction valve 1E12-F004A would not operate properly from control room panel 1H13-P601 Caused by broken torque switch in valve motor Motor & torque switch replaced W/831006 ltr
HOUSTON, R W, DIEDERICH, G J Commonwealth Edison Co 83/10/06 KEPLER, J Q Region 3, Office of Director 3pp 20768 015 24X Fiche 50-373, 83/10/06, 8310140073

8310210222 LER 83-112/03L-0 on 830914, bypass damper DVC13YA of Train A odor eater failed in shut position causing temporary loss of control room ventilation Cause unknown Bypass damper wired shut Investigation underway W/831014 ltr
LINTAKAS, A, DIEDERICH, G J Commonwealth Edison Co 83/10/14 KEPLER, J Q Region 3, Office of Director 3pp 20852 076 24X Fiche 50-373, 83/10/14, 8310210222

8310270274 LER 83-114/03L-0 on 830921, DPIS 1B21-N024B reactor water level switch setpoint exceeded Tech Spec by 2.5 inches Cause undetermined Switch found in proper order Switch recalibr & returned to svc on 830921 W/831014 ltr
HOUSTON, R W, DIEDERICH, G J Commonwealth Edison Co 83/10/14 KEPLER, J Q Region 3, Office of Director 3pp 20923 261 24X Fiche 50-373, 83/10/14, 8310270274

8310270276 LER 83-115/03L-0 on 830927, Barton Model 288A switches, DPIS 1B21-N037B & DPIS 1B21-N037D, setpoints found to slightly exceed Tech Spec 3 3 5 values, Cause undetermined. Setpoints recalibr W/831014 ltr
HOUSTON, R W, DIEDERICH, G J Commonwealth Edison Co 83/10/14 KEPLER, J Q Region 3, Office of Director 3pp 20923 264 24X Fiche 50-373, 83/10/14, 8310270276

8310270490 LER 83-116/03L-0 on 830926, control rod drive (CRD) at core location 30-19 indicated overtravel when withdrawn to full out position Caused by inner filter retainer spring damage due to excessive crud buildup W/831017 ltr
WINTERHOF, D R, DIEDERICH, G J Commonwealth Edison Co 83/10/17 KEPLER, J Q Region 3, Office of Director 3pp 20922 008 24X Fiche 50-373, 83/10/17, 8310270490

8310270267 LER 83-117/03L-0 on 830930, RHR HX outlet valve failed to open manually or via motor operator, Cause unknown Task force committee assigned to resolve problem W/831019 ltr
PETERS, M A, DIEDERICH, G J Commonwealth Edison Co 83/10/19 KEPLER, J Q Region 3, Office of Director 3pp 20923 259 24X Fiche 50-373, 83/10/19, 8310270267

DOCKET 50-374 LABALLE COUNTY STATION, UNIT 2

A. Application/construction stage documents & correspondence

8310040105 Confirms 830921 telcon denying 830909 request to delete feedwater pump trip vibration monitoring test Unit 1 results do not ensure correct snubber installation in Unit 2
SCHWENGER, A Licensing Branch 2 83/09/27 FARRAR, D L Commonwealth Edison Co 2pp 20634 355 24X Fiche 50-374, 83/09/27, 8310040105

DOCKETED ITEMS

8310130196 Notification of 831007 site visit w/util in LaSalle County, IL to discuss mgt precicensing review
BOURNIA, A Licensing Branch 2 83/10/04 SCHWENCER, A Licensing Branch 2 4pp 20777 154 24X Fiche 50-374, 83/10/04, 8310130196

8310120007 Comments on util 830907 ltr re emergency power redundancy Preoperational Test PT-A103 Concurs w/conclusion that single set voltage readings for verification of transformer taps acceptable
SCHWENCER, A Licensing Branch 2 83/10/05 FARRAR, D L Commonwealth Edison Co 3pp 20750 297 24X Fiche 50-374, 83/10/05, 8310120007

8310130132 Forwards list of preoperational test deficiencies & time frame for completion Justification for deferral of resolution of items beyond fuel load date provided
SCHROEDER, C W Commonwealth Edison Co 83/10/05 SCHWENCER, A Licensing Branch 2 5pp 20726 345 24X Fiche 50-374, 83/10/05, 8310130132

8310200273 Forwards schedules for equipment qualification test programs for facilities, per 810328 ltr Dates given for current qualification activities should be viewed as "target-dates" & not as firm dates
BARNES, P L Commonwealth Edison Co 83/10/05 KEPPLER, J G Region 3, Office of Director 10pp 20830 034 24X Fiche 50-000, 83/10/05, 8310200273

8310120433 Discusses proposed rev to primary containment vent & purge valve closure times Util will replace &/or modify eight 26-inch valves & two 8-inch valves per unit to permit 15 s or less closure time Marked-up Tech Spec encl
SCHROEDER, C W Commonwealth Edison Co 83/10/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20698 298 24X Fiche 50-373, 83/10/06, 8310120433

8310170426 Forwards status of util request for approval to defer completion of certain preoperational tests, listed in encl to 830721 ltr, beyond fuel load
SCHROEDER, C W Commonwealth Edison Co 83/10/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20783 318 24X Fiche 50-374, 83/10/06, 8310170426

8310180281 Forwards marked-up changes to Amend 63 to FSAR Tables 14 2-130, 14 2-124, 14 2-114 & Figure 14 2-2 re startup test program Summary of changes listed
SCHROEDER, C W Commonwealth Edison Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 20807 025 24X Fiche 50-373, 83/10/13, 8310180281

8310180397 Confirms 831003 telcon re util decision to perform feedwater pump trip vibration monitoring at two snubber locations in Unit 2 based on Unit 1 test results
SCHROEDER, C W Commonwealth Edison Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20803 317 24X Fiche 50-373, 83/10/13, 8310180397

8310240275 Documents NRC position re elements that must be considered in computation of acceptable closure time for containment purge & vent valves in response to 831006 ltr Justification for interim operation requested
SCHWENCER, A Licensing Branch 2 83/10/18 FARRAR, D L Commonwealth Edison Co 2pp 20907 330 24X Fiche 50-373, 83/10/18, 8310240275

8310250684 Denies request for extension re submittal on Generic Ltr 83-28, "Clarification of Required Actions on Generic Implications of Balem ATWS Events." Required info should be submitted, to extent practical, by 831105
SCHWENCER, A Licensing Branch 2 83/10/18 FARRAR, D L Commonwealth Edison Co 2pp 20908 349 24X Fiche 50-373, 83/10/18, 8310250684

8310250293 Forwards Rev 10 to Offsite Dose Calculation Manual for LaSalle & Quad Cities & Rev 9 to Offsite Dose Calculation Manual for Braidwood, consisting of Chapters 7 2 & 8 O
BENNETT, C J Commonwealth Edison Co 83/10/21, CABRE, E G Office of Nuclear Reactor Regulation, Director 1p 20894 259 24X Fiche 50-000, 83/10/21, 8310250293

--8310250298 Rev 10 to Offsite Dose Calculation Manual for LaSalle & Quad Cities
Commonwealth Edison Co 83/09/30 44pp 20894 260 24X Fiche 50-000, 83/10/21, 8310250298

F Security, medical, emergency & fire protection plans

8310030229 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/09/28 Document Management Branch 1p 20603 037 24X Fiche 50-373, 83/09/28, 8310030229

--8310030236 Public version of Rev 4 to Emergency Plan Implementing Procedure L2P-1700-2, "Station Employee List"
Commonwealth Edison Co 83/06/09 20pp 20603 058 24X Fiche 50-373, 83/09/28, 8310030236

8310040444 Forwards Rev 15 to security plan Rev withheld (ref 10CFR73 21)
FARRAR, D L Commonwealth Edison Co 83/09/30 Office of Nuclear Reactor Regulation, Director 1p 20619 052 24X Fiche 50-373, 83/09/30, 8310040444

8310180250 Forwards IE Insp Repts 50-373/83-36 & 50-374/83-35 on 830914-16 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 83/10/04 REED, C Commonwealth Edison Co 2pp 20802 332 24X Fiche 50-373, 83/10/04, 8310180250

--8310180257 IE Insp Repts 50-373/83-36 & 50-374/83-35 on 830914-16 No noncompliance noted Major areas inspected emergency preparedness program including licensee action on previously identified items & licensee audits
PLOSKE, T Region 3, Office of Director 83/10/03 6pp 20802 334 24X Fiche 50-373, 83/10/04, 8310180250

8310110118 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20684 315 24X Fiche 50-373, 83/10/05, 8310110118

--8310110123 Public version of Rev 4 to Emergency Plan Implementing Procedure L2P-1700-3, "Station Phone List" w/830825 ltr & revised index
HOLYOAK, R H Commonwealth Edison Co 83/07/01 Office of Nuclear Reactor Regulation, Director 23pp 20684 316 24X Fiche 50-373, 83/10/05, 8310110118

8310170664 Responds to 830722 ltr re Rev 14 to security plan Portions of plan acceptable Items from previously approved plan should be followed for portions inconsistent w/10CFR50 54 Encl withheld (ref 10CFR73 21)
SCHWENCER, A Licensing Branch 2 83/10/12 FARRAR, D L Commonwealth Edison Co 2pp 20779 293 24X Fiche 50-373, 83/10/12, 8310170664

8310170707 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/13 Document Management Branch 1p 20813 242 24X Fiche 50-373, 83/10/13, 8310170707

--8310170711 Public version of Rev 3 to Emergency Plan Implementing Procedure L2P-1330-24, "Determination of Reactor Coolant Hydrogen Offgas Concentrations at High Radiation Sampling Sys" w/830928 ltr & receipt form
HOLYOAK, R H Commonwealth Edison Co 83/09/16 38pp 20813 243 24X Fiche 50-373, 83/10/13, 8310170707

8310200416 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/17 Document Management Branch 1p 20859 233 24X Fiche 50-373, 83/10/17, 8310200416

--8310200424 Public version of Rev 5 to Emergency Plan Implementing Procedure L2P-1110-1, "Station Director (Acting Station Director)" w/831003 ltr, receipt form & 10CFR50 59 format for safety evaluation
HOLYOAK, R H Commonwealth Edison Co 83/10/03 27pp 20859 234 24X Fiche 50-373, 83/10/17, 8310200416

8310270526 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20937 216 24X Fiche 50-000, 83/10/21, 8310270526

--8310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure EOF-6, "Administration & Logistics Manager" w/831017 ltr & receipt form
NELLIS, C A Commonwealth Edison Co 83/02/18 DENTON, H R NRC - No Detailed Affiliation Given 7pp 20937 217 24X Fiche 50-000, 83/10/21, 8310270526

8310280206 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20964 148 24X Fiche 50-373, 83/10/25, 8310280206

--8310280215 Public version of revised Emergency Plan Implementing Procedures 12P-1320-1 re augmentation of plant staffing, 12P-1330-1 re post-accident sampling equipment inventory & 12P-1700-2 re station employee list
Commonwealth Edison Co 83/07/25 43pp 20964 149 24X
Fiche 50-373, 83/10/25, 8310280206

8310280307 Releases public version of revised generating stations emergency plan telephone directory
FELTON, J H Division of Rules and Records 83/10/25 Document
Management Branch 1p 20963 126 24X Fiche 50-000, 83/10/25,
8310280307

--8310280314 Public version of revised generating stations emergency plan telephone directory
GALLE, D P Commonwealth Edison Co 83/08/11 DENTON, H R Office
of Nuclear Reactor Regulation, Director 64pp 20963 127 24X
Fiche 50-000, 83/10/25, 8310280307

8310280191 Releases public version of revised emergency plan implementing procedure
FELTON, J H Division of Rules and Records 83/10/26 Document
Management Branch 1p 20962 266 24X Fiche 50-000, 83/10/26,
8310280191

--8310280209 Public version of Rev 1 to Emergency Plan Implementing Procedure EQF-1B, "Emergency Operations Facility Activation"
MOORE, R D Commonwealth Edison Co 83/08/02 50pp 20962, 267
24X Fiche 50-000, 83/10/26, 8310280191

K Utility Final Safety Analysis Report (FSAR) & amends

8310180249 Forwards affidavit of distribution of Amend 63 to FSAR
SCHROEDER, C W Commonwealth Edison Co 83/10/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20807, 081
24X Fiche 50-373, 83/10/10, 8310180249

Q Inspection reports, IE Bulletins & correspondence

8310050493 Forwards IE Insp Repts 50-373/83-30 & 50-374/83-29 on 830725-0909 & notice of violation
STREETER, J F Region 3, Office of Director 83/09/22 REED, C
Commonwealth Edison Co 2pp 20631 350 24X Fiche 50-373, 83/09/22,
8310050493

--8310050498 Notice of violation from insp on 830725-0909
STREETER, J F Region 3, Office of Director 83/09/22 1p
20631 352 24X Fiche 50-373, 83/09/22, 8310050493

--8310050502 IE Insp Repts 50-373/83-30 & 50-374/83-29 on 830725-0909
Noncompliance noted diesel generator 2A not lined up for
startup operation during performance of Preoperational Test
PT-AP-203
LANKSBERY, R D, DUPONT, S O, REYES, L A Region 3, Office of
Director 83/09/22 5pp 20631 353 24X Fiche 50-373, 83/09/22,
8310050493

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Bys W/o 10CFR50.59 Evaluation." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New
York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310140213 Forwards IE Insp Repts 50-373/83-35 & 50-374/83-34 on 830804, 05, 08-11 & 15 No noncompliance noted
STREETER, J F Region 3, Office of Director 83/09/29 REED, C,
Commonwealth Edison Co 2pp 20762, 307 24X Fiche 50-373, 83/09/29,
8310140213

--8310140215 IE Insp Repts 50-373/83-35 & 50-374/83-34 on 830804, 05, 08-11 & 15 No noncompliance noted Major areas inspected review of previous open & unresolved items & followup on previous items of noncompliance
CHOULES, N C, HASSE, R A, HUNTER, D R Region 3, Office of
Director 83/09/28 6pp 20762 309 24X Fiche 50-373, 83/09/29,
8310140213

8310120290 Provides supplemental response to IE Bulletin 80-16 re misapplication of Rosemount transmitters All changeouts in NSSS sys for Unit 2 complete
BARNES, P L Commonwealth Edison Co 83/10/04 KEPLER, J Q Region
3, Office of Director 2pp 20692 339 24X Fiche 50-373, 83/10/04,
8310120290

8310180250 Forwards IE Insp Repts 50-373/83-36 & 50-374/83-35 on 830914-16 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 83/10/04 REED, C
Commonwealth Edison Co 2pp 20802 332 24X Fiche 50-373, 83/10/04,
8310180250

--8310180257 IE Insp Repts 50-373/83-36 & 50-374/83-35 on 830914-16 No noncompliance noted Major areas inspected emergency preparedness program including licensee action on previously identified items & licensee audits
PLOSKE, T, PHILLIPS, M P Region 3, Office of Director 83/10/03
6pp 20802 334 24X Fiche 50-373, 83/10/04, 8310180250

8310200124 Forwards IE Mgt Meeting Repts 50-010/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-293/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIUS, C E Division of Project & Resident Programs 83/10/04
REED, C Commonwealth Edison Co 2pp 20834 098 24X
Fiche 50-000, 83/10/04, 8310200124

--8310200148 IE Mgt Meeting Repts 50-020/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIUS, C E Division of Project & Resident Programs 83/10/03
4pp 20834 100 24X Fiche 50-000, 83/10/04, 8310200124

8310200159 Forwards IE Insp Repts 50-373/83-39 & 50-374/83-40 on 830915 No noncompliance noted
LITTLE, W B Region 3, Office of Director 83/10/05 REED, C,
Commonwealth Edison Co 2pp 20834 094 24X Fiche 50-373, 83/10/05,
8310200159

--8310200164 IE Insp Repts 50-373/83-39 & 50-374/83-40 on 830915 No noncompliance noted Major areas inspected fatigue usage factors & stress calculations for main steam drain piping.
DANIELSON, D H, MUFFETT, J H Region 3, Office of Director
83/10/05 2pp 20834 094 24X Fiche 50-373, 83/10/05, 8310200159

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Laps Used in Westinghouse Plants" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning, Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180187 Clarifies NRC position on procedures for admitting NRC personnel. Certified access list encl Update will be provided every 6 months.
AXELSON, W L Region 3, Office of Director 83/10/14 REED, C,
Commonwealth Edison Co 7pp 20809 086 24X Fiche 50-373, 83/10/14,
8310180187

8310250356 Ack receipt of 831018 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-30 & 50-374/83-29
STREETER, J F Region 3, Office of Director 83/10/20 REED, C,
Commonwealth Edison Co 1p 20898 119 24X Fiche 50-373, 83/10/20,
8310250356

DOCKETED ITEMS

--8310250361 Responds to NRC 830922 ltr re violations noted in IF Insp Repts 50-373/83-30 & 50-374/83-29 Corrective actions Procedure LCP-DQ-01 being clarified & step will be added to verify that ESF status panel checked after lineup completed FARRAR, D L. Commonwealth Edison Co. 83/10/18 KEPLER, J O Region 3, Office of Director 2pp 20898 120 24X Fiche 50-373, 83/10/20, 8310250356

S Reportable occurrences, LERs & related correspondence

8310110430 Responds to FOIA request for four different categories of documents described in 830910 ltr Forwards matl listed in App A, responsive to Items 1, 2 & 4 DOE should be contacted for matl requested in Item 3 of ltr FELTON, J M Division of Rules and Records 83/06/14. HIATT, B L Ohio Citizens for Responsible Energy 3pp 20706 002 24X Fiche 50-000, 83/06/14, 8310110430

--8310110478 Responds to 830413 ltr requesting info re use of foreign matls on valve seating surfaces Lubricants & cleaning solvents used on valve component surfaces per vendor recommendations & maint practices FARRAR, D L Commonwealth Edison Co 83/04/22 KEPLER, J O Region 3, Office of Director 4pp 20706 063 24X Fiche 50-000, 83/04/14, 8310110430

8310210056 Final Deficiency Rept 83-06 re ASCO solenoid valves in control rod drive sys Initially reported on 830912 Valves w/defective solenoid plunger housings replaced & spare parts in inventory examined Plant operable SCHROEDER, C W Commonwealth Edison Co 83/10/12 KEPLER, J O Region 3, Office of Director 2pp 20855 284 24X Fiche 50-374, 83/10/12, 8310210056

DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

A Application/construction stage documents & correspondence

8310310063 FOIA request for documents re const & operation of C-E plants List of info required submitted BELL, N Coalition for Safe Power 83/03/31 Office of Administration 1p 20998 173 24X Fiche 50-000, 83/03/31, 8310310063

8310070140 Discusses util deferral of plant-referenced simulator in training program NRC may reconsider position on training program due to deferral Proposed rule under consideration requiring use of simulator EISENHUT, D G Division of Licensing 83/09/22 COLLINS, J T Region 4, Office of Director 3pp 20680 344 24X Fiche 50-382, 83/09/22, 8310070140

--8310070144 Advises that util must provide plant-specific simulator on more timely basis than presently called for Simulator will improve training program COLLINS, J T Region 4, Office of Director 83/07/11, EISENHUT, D G Division of Licensing 2pp 20680 348 24X Fiche 50-382, 83/09/22, 8310070140

8310030060 Forwards Amend 33 to OL application, consisting of Amend 33 to FSAR. LEDDICK, R S Louisiana Power & Light Co 83/09/28 Office of Nuclear Reactor Regulation, Director 2pp 20594 345 24X Fiche 50-382, 83/09/28, 8310030060

--8310030063 Amend 33 to OL application. LEDDICK, R S Louisiana Power & Light Co 83/09/28 1p 20594 347 24X Fiche 50-382, 83/09/28, 8310030060

8310200171 Forwards, for comment, documentation supporting no adverse effect determination for two archeological sites eligible for Natl Register of Historic Places KNIGHTON, O W Licensing Branch 3 83/09/28 WALL, L S Advisory Council on Historic Preservation 6pp 20844, 172 24X Fiche 50-382, 83/09/28, 8310200171

8310270254 Submits documentation of no adverse effect determination re two archeological sites eligible for Natl Register of Historic Places. Concurred in by Advisory Council on Historic Preservation on 831018 KNIGHTON, O W Licensing Branch 3 83/09/28 WALL, L S Advisory Council on Historic Preservation 2pp 20923:280. 24X Fiche 50-382, 83/09/28, 8310270254

8308300352 Board Notification 83-144 provides evaluation & recommendations re need for PORVs on C-E plants. Info will be presented to ACRs in Oct 1983 NOVAK, T M Assistant Director for Licensing 83/09/29 Atomic Safety and Licensing Appeal Panel 4pp 20601:230 24X Fiche 50-000, 83/09/29, 8308300352

--8310030407 Informs that "Staff Evaluation of Need for Rapid Depressurization Capability for C-E Plants" & Commission 830916 transcript & slides from San Onofre briefing should be transmitted to boards & parties for C-E plants EISENHUT, D G Division of Licensing 83/09/27 NOVAK, T M Assistant Director for Licensing 1p 20601 334 24X Fiche 50-000, 83/09/29, 8308300352

8310040372 Forwards response to NRC 830826 request for addl info Argus Chemical Corp will be contacted re effective date of ltr New GAST Terminal Corp ltr will be submitted by 831231 DRUMMOND, F J Louisiana Power & Light Co 83/09/29 KNIGHTON, O W Licensing Branch 3 4pp 20622 344 24X Fiche 50-382, 83/09/29, 8310040372

8310040559 Forwards "Independent Safety Engineering Group Review of NRC Concerns" & Harstead Engineering Assoc rept, "Analysis of Cracks & Water Seepage in Foundation Mat," in response to NRC 830804 ltr CAIN, J M Louisiana Power & Light Co 83/09/29 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 20621 311 24X Fiche 50-382, 83/09/29, 8310040559

--8310040565 "Independent Safety Engineering Group Review of NRC Concerns." DRUMMOND, F J, ALSWORTH, M, CARVER, A M Louisiana Power & Light Co 83/09/29 51pp 20621 313 24X Fiche 50-382, 83/09/29, 8310040559

--8310040573 "Analysis of Cracks & Water Seepage in Foundation Mat" DU BOUCHET, A V, UNSAL, A J, HARSTEAD, O A Harstead Engineering Associates, Inc 8304-1 83/09/19 119pp 20622 002 24X Fiche 50-382, 83/09/29, 8310040559

8310070247 Application to amend CPPR-103, extending const completion date to 840930 Delay due to exhaustive prerequisite testing, preoperational testing, troubleshooting & retesting to meet acceptance criteria LEDDICK, R S Louisiana Power & Light Co 83/09/29 EISENHUT, D G Division of Licensing 4pp 20658 331 24X Fiche 50-382, 83/09/29, 8310070247

8310070235 Advises of installation of removable section of 3BS diesel generator room in south wall Installation of wall will be documented in Amend 34 to FSAR DRUMMOND, F J Louisiana Power & Light Co 83/10/03 KNIGHTON, O W Licensing Branch 3 12pp 20657 070 24X Fiche 50-382, 83/10/03, 8310070235

831010280 Forwards util application for amend to CP to extend latest const completion date from 831030 to 840930 Target date for fuel load date is 840331 BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, E L Louisiana Power & Light Co 83/10/04 KOHL, C Atomic Safety and Licensing Board Panel JOHNSTON, W R, WILBER, H A Atomic Safety and Licensing Appeal Panel 7pp 20665 327 24X Fiche 50-382, 83/10/04, 831010280

8310200070 Forwards INEL technical evaluation repts summarizing activities of SORT during 810914-18 & 830830-0903 seismic & dynamic qualification program audit w/o repts KNIGHTON, O W Licensing Branch 3 83/10/04 LEDDICK, R S Louisiana Power & Light Co 2pp 20844 274 24X Fiche 50-382, 83/10/04, 8310200070

--8309300064 Forwards INEL technical evaluation repts summarizing activities of seismic & dynamic qualification program for mechanical & electrical equipment during facility audit NOONAN, V S Equipment Qualification Branch 83/09/20 KNIGHTON, O Licensing Branch 3 1p 20844 276 24X Fiche 50-382, 83/10/04, 8310200070

8310120226 Advises that util will participate w/INPO & C-E Owners Group in addressing certain requirements of Generic Ltr 83-28, "Required Actions Based on Generic Implication of Salem ATHB Events." Initial response expected by 840115 COOK, K W Louisiana Power & Light Co 83/10/05 EISENHUT, D G Division of Licensing 1p 20693, 134 24X Fiche 50-382, 83/10/05, 8310120226

8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves EISENHUT, D G Division of Licensing 83/10/06 PALLADINO, N J Commissioners 31pp 20818 001 24X Fiche 50-000, 83/10/06, 8308300771

8310170569 Forwards revised App A notes to Harstead Engineering Assoc rept, distributed on 830920 Svc list encl CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge CHURCHILL, B W Louisiana Power & Light Co 83/10/12 KOHL, C N, JOHNSTON, W R, WILBER, H A Atomic Safety and Licensing Appeal Panel 5pp 20780 324 24X Fiche 50-382, 83/10/12, 8310170569

DOCKETED ITEMS

259

8310280002 Forwards, for review, "Analysis of Cracks & Water Seepage in Foundation Mat," covering design adequacy of basemat Design of mat extremely conservative Addl analysis not required
CAIN, J M Louisiana Power & Light Co 03/10/20 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 2pp
20935 085 24X Fiche 50-382, 83/10/20, 8310280002

--8310200006 "Analysis of Cracks & Water Seepage in Foundation Mat"
DU BOUCHET, UNSAL, A I, HARSTEAD, G A Harstead Engineering
Associates, Inc 8304-2 07/10/12 104pp 20935 087 24X
Fiche 50-382, 83/10/20, 8310200006

8310310091 Forwards approved nuclear operations organization charts
Charts provide means for onsite & offsite mgt & describe
technical personnel resources necessary to complete const &
conduct preoperational/startup testing
DRUMMOND, F J Louisiana Power & Light Co 83/10/24 KNIGHTON, G W
Licensing Branch 3 1p 20950 344 24X Fiche 50-382, 83/10/24,
8310310091

E NRC Safety Evaluation Report (SER), supp's & correspondence

8310120072 Discusses actions to be taken to resolve turbine missile
issue identified in SER 4, Section 1 V, including development
of turbine & valve maint programs described in NUREG-0800
for main turbine throttle & governing valves
DRUMMOND, F J Louisiana Power & Light Co 83/10/05 KNIGHTON, G W
Licensing Branch 3 2pp 20697 161 24X Fiche 50-382, 83/10/05,
8310120072

8310250496 Advises that deficiency re failure of CPC software to apply
failed CEAC penalty factor to local power density corrected,
per NRC request item should be closed out in next suppl to
SER
COOK, K H Louisiana Power & Light Co 83/10/20 KNIGHTON, G W
Licensing Branch 3 2pp 20097 125 24X Fiche 50-382, 83/10/20,
8310250496

F Security, medical, emergency & fire protection plans

8310310367 Responds to NRC 830527 ltr re IE Emergency Preparedness
Appraisal Rept 50-382/83-08 Emergency plan & implementing
procedures will be revised to reflect flow of authority &
responsibility
DRUMMOND, F J Louisiana Power & Light Co 83/07/29 MADSEN, G L
Region 4, Office of Director 76pp 20959 091 24X
Fiche 50-382, 83/07/29, 8310310367

8310310315 Responds to NRC 830527 ltr re IC Emergency Preparedness
Appraisal Rept 50-382/83-08 Corrective actions two dedicated
vehicles will be provided for field monitoring teams &
two-way radios will be installed in vehicles
DRUMMOND, F J Louisiana Power & Light Co 83/08/30 MADSEN, G L
Region 4, Office of Director 4pp 20959 066 24X
Fiche 50-382, 83/08/30, 8310310315

831060357 Submits amended implementation schedule for Suppl 1 to
NUREG-073/ requirements for safety parameter display sys &
Reg Guide 1.47 Listing of parameters available for display
encl
DRUMMOND, F J Louisiana Power & Light Co 83/09/29 KNIGHTON, G W
Licensing Branch 3 3pp 20646 107 24X Fiche 50-382, 83/09/29,
831060357

G Adjudicatory correspondence

8310040233 Answer opposing Joint Intervenor 830722 motion to reopen
record re Contention 22 on safety-related concrete Heavy
burden in seeking to reopen record not met
CHURCHILL, B W Louisiana Power & Light Co CHURCHILL, B W Shaw,
Pittman, Potts & Trowbridge 03/09/30 Atomic Safety and
Licensing Appeal Panel 32pp 20613 224 24X Fiche 50-382,
83/09/30, 8310040233

--8310040239 Affidavit of JL Ebasco supporting util opposition to Joint
Intervenor motion to reopen on safety-related concrete
Cracks expected to form in concrete mat, enabling transfer of
tensile load from concrete to embedded steel.
EHASZ, J L Louisiana Power & Light Co EHASZ, J L Ebasco
Services, Inc (subs of Enserch Corp) 83/09/27 14pp
20613 256 24X Fiche 50-382, 83/09/30, 8310040233

--8310040245 Affidavit of WF Qundaker supporting util opposition to Joint
Intervenor motion to reopen record on safety-related
concrete. Corrosion of reinforcing steel in concrete mat will
not occur to significant degree Certificate of Svc encl
QUNDAKER, W F Louisiana Power & Light Co QUNDAKER, W F Ebasco
Services, Inc (subs of Enserch Corp) 83/09/27 150pp
20613 271 24X Fiche 50-382, 83/09/30, 8310040233

831010280 Forwards util application for amend to CP to extend latest
const completion date from 831030 to 840930 Target date for
fuel load date is 840331
BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, E L Louisiana
Power & Light Co 83/10/04 KOHL, C Atomic Safety and Licensing
Appeal Panel 7pp 20665 329 24X Fiche 50-382, 83/10/04,
831010280

8310170478 Motion for further extension until 831121 to respond to
Joint Intervenor 830725 motion to reopen Contention 22 in
light of cracking & water seepage in concrete basemat
Certificate of Svc encl
TURK, B E Hearing Branch 1 83/10/07 Atomic Safety and
Licensing Appeal Panel 8pp 20783 287 24X Fiche 50-382, 83/10/07,
8310170478

--8310170484 Affidavit of J Ma & R Pichumani re cracking & water seepage
in concrete basemat
MA, J, PICHUMANI, R Structural & Geotechnical Engineering Branch.
83/10/07 5pp 20783 295 24X Fiche 50-382, 83/10/07, 8310170478.

8310170398 Response to NRC 831007 motion for further extension to
831121 to file response to Joint Intervenor motion to
reopen contention Motion not opposed Certificate of Svc
encl
BLAKE, E L Louisiana Power & Light Co BLAKE, E L Shaw, Pittman,
Potts & Trowbridge 83/10/12 Atomic Safety and Licensing Appeal
Panel 5pp 20785 075 24X Fiche 50-382, 83/10/12, 8310170398

8310170569 Forwards revised App A notes to Harstead Engineering Assoc
rept, distributed on 830920 Svc list encl
CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge CHURCHILL, B W
Louisiana Power & Light Co 83/10/12 KOHL, C N, JOHNSON, W R,
WILBER, H A Atomic Safety and Licensing Appeal Panel 5pp
20780 324 24X Fiche 50-382, 83/10/12, 8310170569

8310190212 Forwards Harstead Engineering Assoc, Inc rept re design
adequacy of foundation basemat Applicant has not yet
reviewed rept Design of foundation mat conservative Cracking
insignificant W/o rept Svc list encl Related correspondence
CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge CHURCHILL, B W
Louisiana Power & Light Co 83/10/14 KOHL, C N, JOHNSON, W R,
WILBER, H A Atomic Safety and Licensing Appeal Panel 4pp
20818 071 24X Fiche 50-382, 83/10/14, 8310190212

8310310195 Informs that DR Lewis, formerly ASLB participant in OL
proceeding, began working for author on 831024. DR Lewis
will not participate in OL proceeding Certificate of Svc
encl
BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, E L Louisiana
Power & Light Co 83/10/26 Commissioners 4pp 20958 356, 24X
Fiche 50-382, 83/10/26, 8310310195

H General correspondence

8310070001 Informs that, effective immediately, FJ Drummond, nuclear svcs
manager & KW Cook, nuclear support & licensing manager,
authorized to sign correspondence to NRC re facility, except
under 10CFR50.30(b) requiring corporate officer signature
LEDDICK, R S Louisiana Power & Light Co 83/09/30 KNIGHTON, G W
Licensing Branch 3 1p 20651:001 24X Fiche 50-382, 83/09/30,
8310070001

K. Utility Final Safety Analysis Report (FSAR) & amends

8310030060 Forwards Amend 33 to OL application, consisting of Amend 33
to FSAR.
LEDDICK, R S Louisiana Power & Light Co 83/09/28 Office of
Nuclear Reactor Regulation, Director 2pp 20594 345 24X
Fiche 50-382, 83/09/28, 8310030060

--8310030063 Amend 33 to OL application.
LEDDICK, R S Louisiana Power & Light Co 83/09/28 1p
20594 347 24X Fiche 50-382, 83/09/28, 8310030060

--8310030067 Amend 33 to FSAR
* Louisiana Power & Light Co 83/09/30 2191pp 20594 351 24X
Fiche 50-382, 83/09/28, 8310030060

8310060233 Certifies svc of FSAR Amend 33 on 830930.
* Louisiana Power & Light Co 83/10/03 1p 20647:098 24X
Fiche 50-382, 83/10/03, 8310060233

DOCKETED ITEMS

Q Inspection reports, IE Bulletins & correspondence

8310110040 FOIA request for SALP documents, written or routed since 1979, which mention or refer to facility & describe or provide info on SALP insp findings or conclusions based on SALP reviews
RIDENHOUR, R Ombit 83/05/04 GRIMSLEY, D C NRC - No Detailed Affiliation Given 2pp 20713 306 24X Fiche 50-382, 83/05/04, 8310110040

8310110044 Responds to FOIA request for SALP documents, written or routed since 1979, which mention or refer to facility & describe or provide info on SALP insp findings or conclusions re SALP reviews Forwards App A documents
FELTON, J M Division of Rules and Records 83/07/20 RIDENHOUR, R Ombit 2pp 20713 308 24X Fiche 50-000, 83/07/20, 8310110044

--8112170188 Advises that Cycle 2 of systematic evaluation of licensee performance will cover Jul 1980-June 1981 Regional board meetings will be conducted Jul-Dec 1981 All Cycle 2 NRR performance evaluation encl
EISENHUT, D O Division of Licensing 81/06/04 Division of Engineering 4pp 20713 310 24X Fiche 50-382, 83/07/20, 8310110044

--8208230434 Requests input & appropriate comments, re systematic assessment of licensee performance, (SALP) for Aug 1981-Jul 1982 Response required by 820806 SALP criteria encl
BLACK, B Licensing Branch 3 82/08/03 Licensing Branch 3 13pp 20713 324 24X Fiche 50-382, 83/07/20, 8310110044

--8209010314 Forwards draft NRR input for systematic assessment of licensee performance Draft based partly on input solicited from selected staff personnel having contact & involvement w/ util licensing activities
BLACK, B Licensing Branch 3 82/08/11 EISENHUT, D O Division of Licensing 5pp 20713 331 24X Fiche 50-382, 83/07/20, 8310110044

--8210050447 Forwards final NRR input for Cycle 3 systematic assessment of licensee performance Performance is rated Category 2 Licensee resources adequate although staffing could be improved
BLACK, B Operating Reactors Branch 3 82/09/23 EISENHUT, D O Division of Licensing 5pp 20713 336 24X Fiche 50-382, 83/07/20, 8310110044

--8310110051 SALP rept for Jul 1980 - June 1981. Const allegations reviewed
SEYFRIT, K V Region 4, Office of Director 83/07/20. 10pp 20713 314 24X Fiche 50-382, 83/07/20, 8310110044

8310310367 Responds to NRC 830527 ltr re IE Emergency Preparedness Appraisal Rept 50-382/83-08 Emergency plan & implementing procedures will be revised to reflect flow of authority & responsibility
DRUMMOND, F J Louisiana Power & Light Co. 83/07/29 MADSEN, G L Region 4, Office of Director 76pp 20959 091 24X Fiche 50-382, 83/07/29, 8310310367

8310060379 Forwards IE Insp Rept 50-382/83-22 on 830627-0701 No noncompliance noted
MADSEN, G L Region 4, Office of Director 83/08/19 MAURIN, L V Louisiana Power & Light Co 2pp 20646 038 24X Fiche 50-382, 83/08/19, 8310060379

--8310060391 IE Insp Rept 50-382/83-22 on 830627-0701 No noncompliance noted Major areas inspected radiowave program & transportation activities; air cleaning sys, instrumentation Tech Specs, procedures & controls for effluent releases
BAER, R E, MURRAY, B, CROSSMAN, W A Region 4, Office of Director 83/08/10 12pp 20646 040. 24X Fiche 50-382, 83/08/19, 8310060379,

8310060459 Forwards IE Insp Rept 50-382/83-23 on 830711-15 No noncompliance noted
MADSEN, G L Region 4, Office of Director 83/08/22 MAURIN, L V Louisiana Power & Light Co 2pp 20641 019 24X Fiche 50-382, 83/08/22, 8310060459

--8310060464 IE Insp Rept 50-382/83-23 on 830711-15 No noncompliance noted Major areas inspected: preoperational insp of radiation protection program & actions taken on 12 open items in IE Insp Repts 50-382/82-04 & 50-382/83-04.
CHANEY, H D, MURRAY, B, CROSSMAN, W A Region 4, Office of Director 83/08/09 11pp 20641 021 24X Fiche 50-382, 83/08/22, 8310060459,

8310040153 Forwards IE Insp Rept 50-382/83-27 on 830802-05 No noncompliance noted
MADSEN, G L Region 4, Office of Director 83/08/29. LEDDICK, R B Louisiana Power & Light Co 2pp. 20608, 028 24X Fiche 50-382, 83/08/29, 8310040153.

--8310040157 IE Insp Rept 50-382/83-27 on 830802-05 No noncompliance noted Major areas inspected 10CFR50 55(e) reporting program & repts
DBERG, C R, CROSSMAN, W A Region 4, Office of Director 83/08/26 7pp 20608 030 24X Fiche 50-382, 83/08/29, 8310040153

8310310315 Responds to NRC 830527 ltr re IE Emergency Preparedness Appraisal Rept 50-382/83-08 Corrective actions two dedicated vehicles will be provided for field monitoring teams & two-way radios will be installed in vehicles
DRUMMOND, F J Louisiana Power & Light Co 83/08/30 MADSEN, G L Region 4, Office of Director 4pp 20959 066 24X Fiche 50-382, 83/08/30, 8310310315

8310060591 Forwards response to 830727 questions re NRC inquiry team 830628 meeting in New Orleans, LA Inquiry team 830714 rept on GA allegations & IE 830804 status rept encl
PALLADINO, N J Commissioners 83/09/08 MARKEY, E J House of Rep., Interior & Insular Affairs 7pp 20661 160 24X Fiche 50-382, 83/09/08, 8310060591

--8310060593 Forwards inquiry team rept re GA allegations Meeting to discuss followup requested
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/08/04 CAIN, J M Louisiana Power & Light Co 1p 20661 183 24X Fiche 50-382, 83/09/08, 8310060591

--8310060594 Requests info re circumstances of June 1983 interviews w/ NRC investigation team
MARKEY, E J House of Rep., Interior & Insular Affairs 83/07/27 PALLADINO, N J Commissioners 1p 20661 192 24X Fiche 50-382, 83/09/08, 8310060591

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300347 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300347

8310310402 Forwards IE Insp Rept 50-382/83-26 on 830701-0831 No noncompliance noted
MADSEN, G L Region 4, Office of Director 83/10/05 LEDDICK, R B Louisiana Power & Light Co 2pp 20759 287 24X Fiche 50-382, 83/10/05, 8310310402

--8310310408 IE Insp Rept 50-382/83-26 on 830701-0831 No noncompliance noted Major areas inspected allegations, preoperational test witnessing & structural steel erected by American Bridge Div, US Steel
CONSTABLE, G L, FLIPPO, T A, CROSSMAN, W A Region 4, Office of Director 83/09/30 8pp 20959 289 24X Fiche 50-382, 83/10/03, 8310310402

8310130262 Ack receipt of 830824 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-382/83-21
MADSEN, G L Region 4, Office of Director 83/10/06 MAURIN, R B Louisiana Power & Light Co 1p 20723 221 24X Fiche 50-382, 83/10/06, 8310130262

--8310130266 Responds to NRC 830725 ltr re violations noted in IE Insp Rept 50-382/83-21 Corrective actions, change to Procedure MM-8-014 implemented to address new stud installation/removal tool. Maint supervisors instructed
DRUMMOND, F J Louisiana Power & Light Co 83/08/24. MADSEN, G L Region 4, Office of Director 2pp 20723 222 24X Fiche 50-382, 83/10/06, 8310130262,

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

DOCKETED ITEMS

26

8308300732 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 77pp 20882 026 24X Fiche 50-000,83/10/07,8308300732

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

S Reportable occurrences, LERs & related correspondence

8310030259 Fifth interim const Deficiency Rept 66 re GE-type AKR breakers & C-clips possibly falling off Completion of corrective action & review of supporting documentation scheduled for 831014 Final rept by 831102
DRUMMOND, F J Louisiana Power & Light Co 83/09/15 COLLINS, J T
Region 4, Office of Director 2pp 20591 098 24X
Fiche 50-382,83/09/15,8310030259

8310030363 Third interim significant const Deficiency Rept 74 re damage to pressurizer heaters during hot functional testing All 30 pressurizer heaters replaced Welding & NDE testing performed per ASME code Next rept by 831014
DRUMMOND, F J Louisiana Power & Light Co 83/09/15 COLLINS, J T
Region 4, Office of Director 1p 20591 282 24X
Fiche 50-382,83/09/15,8310030363

8310030365 Fourth interim significant const Deficiency Rept 79 re unqualified components in hydrogen analyzers Completion of corrective action delayed until 831014 due to design changes Final rept will be submitted by 831110
DRUMMOND, F J Louisiana Power & Light Co 83/09/15 COLLINS, J T
Region 4, Office of Director 1p 20593 039 24X
Fiche 50-382,83/09/15,8310030365

8310030468 Second interim significant const Deficiency Rept 86 re burned 3A-8 safety inverter output capacitor wiring Supporting documentation under review w/expected completion by 831007 Final rept expected by 831019
DRUMMOND, F J Louisiana Power & Light Co 83/09/15 COLLINS, J T
Region 4, Office of Director 1p 20601 058 24X
Fiche 50-382,83/09/15,8310030468

8310030482 Final significant const Deficiency Rept 93 re chilled water piping supports Caused by overstressed welds & structures & seismic span criteria being exceeded Designs modified
DRUMMOND, F J Arkansas Power & Light Co 83/09/15 COLLINS, J T
Region 4, Office of Director 3pp 20601 071 24X
Fiche 50-382,83/09/15,8310030482

8310030507 Final significant const Deficiency Rept 60 re turnover documentation & inadequate hanger weld problems T-B Completion & documentation review scheduled for 831214 Final rept will be submitted by 840116
DRUMMOND, F J Louisiana Power & Light Co 83/09/15 COLLINS, J T
Region 4, Office of Director 1p 20601 169 24X
Fiche 50-382,83/09/15,8310030507

8310030540 Final Deficiency Rept 123 re fusion of conductor insulation, rendering insulation values indeterminate Initially reported on 830818 Deficiency not reportable per 10CFR50.55(e)
DRUMMOND, F J Louisiana Power & Light Co 83/09/15 COLLINS, J T
Region 4, Office of Director 2pp 20601 192 24X
Fiche 50-382,83/09/15,8310030540

8310040512 Final deficiency rept re Potentially Reportable Deficiency 121 concerning Anchor Darling Valve 281-V3248 circular indication Initially reported on 830818 Radiographic exam revealed no nonconformances Item determined not reportable
DRUMMOND, F J Louisiana Power & Light Co 83/09/15 COLLINS, J T
Region 4, Office of Director 2pp 20623 094 24X
Fiche 50-382,83/09/15,8310040512

8310040134 Interim rept re significant const Deficiency 42-R1 on HMA auxiliary relays Review & verification of supporting documentation scheduled for completion by 831006 Final rept will be submitted by 831020
GERRETS, T F Louisiana Power & Light Co 83/09/26 COLLINS, J T
Region 4, Office of Director 2pp 20608 006 24X
Fiche 50-382,83/09/26,8310040134

8310190151 Final rept re Significant Const Deficiency 53 concerning possible failure of GE-type HFA relays Initially reported on 830725 Lexan coil spools in HFA relays replaced by coils made of Tefzel
GERRETS, T F Louisiana Power & Light Co 83/09/30 COLLINS, J T
Region 4, Office of Director 3pp 20820 224 24X
Fiche 50-382,83/09/30,8310190151

8310210258 First interim significant const Deficiency Rept 88 re refueling water storage pool liner/nozzle overstressed condition Restraints will be added to deficient nozzles to reduce nozzle load on pool liners Next rept by 831215
GERRETS, T F Louisiana Power & Light Co 83/10/07 COLLINS, J T
Region 4, Office of Director 4pp 20848 277 24X
Fiche 50-382,83/10/07,8310210258

8310210290 First interim significant const Deficiency Rept 89 re GE AK50/AK30 switchgear breakers cam shaft bearing retaining ring Interim corrective action taken to prevent bearing movement until repair developed by GE Next rept by 840120
GERRETS, T F Louisiana Power & Light Co 83/10/07 COLLINS, J T
Region 4, Office of Director 3pp 20855 245 24X
Fiche 50-382,83/10/07,8310210290

8310210293 Fifth interim significant const Deficiency Rept 70 re GE 480-volt trip coils not dropping out after tripping Two of 86 breakers remain to have design change installed & verified Final rept will be submitted by 831221
GERRETS, T F Louisiana Power & Light Co 83/10/07 COLLINS, J T
Region 4, Office of Director 2pp 20855 210 24X
Fiche 50-382,83/10/07,8310210293

8310280012 Sixth interim deficiency rept of Significant Const Deficiency 57 re inadequate instrumentation & control installations & turnover documentation Initially reported on 830729 Final rept will be submitted by 840215
GERRETS, T F Louisiana Power & Light Co 83/10/13 COLLINS, J T
Region 4, Office of Director 2pp 20934 107 24X
Fiche 50-382,83/10/13,8310280012

8310280069 Fifth interim significant const Deficiency Rept 77 re inadequate containment purge valve closure time & flow rate Review of supporting documentation will be completed by 831128 Final rept will be submitted by 831215
GERRETS, T F Louisiana Power & Light Co 83/10/13 COLLINS, J T
Region 4, Office of Director 2pp 20933 340 24X
Fiche 50-382,83/10/13,8310280069

8310310292 Third interim rept re Significant Const Deficiency 82 concerning bent control element assembly rods Initially reported on 830816 Rods evaluated & reworked by C-E & returned to facility Final rept will be submitted by 840115
GERRETS, T F Louisiana Power & Light Co 83/10/14 COLLINS, J T
Region 4, Office of Director 2pp 20961 232 24X
Fiche 50-382,83/10/14,8310310292

8310310300 First interim rept re Significant Const Deficiency 90, "Electrical Conduct Overstressed " Initially reported on 830916 All conduit installations will be physically verified Next rept by 840215
GERRETS, T F Louisiana Power & Light Co 83/10/14 COLLINS, J T
Region 4, Office of Director 3pp 20960 359 24X
Fiche: 50-382,83/10/14,8310310300

U Congressional/Executive Correspondence

8310060591 Forwards response to 830727 questions re NRC inquiry team 830628 meeting in New Orleans, LA. Inquiry team 830714 rept on GA allegations & IE 830804 status rept encl
PALLADINO, N J Commissioners 83/09/08, MARKEY, E. J. House of Rep., Interior & Insular Affairs. 7pp 20661 160 24X
Fiche 50-382,83/09/08,8310060591.

--8310060593 Forwards inquiry team rept re GA allegations Meeting to discuss followup requested
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/08/04, CAIN, J M. Louisiana Power & Light Co. 1p 20661 183 24X Fiche: 50-382,83/09/08,8310060591.

--8310060594 Requests info re circumstances of June 1983 interviews w/NRC investigation team
MARKEY, E J House of Rep., Interior & Insular Affairs. 83/07/27, PALLADINO, N J. Commissioners 1p 20661 192 24X
Fiche 50-382,83/09/08,8310060591.

DOCKETED ITEMS

DOCKET 50-387 BUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1
F Security, medical, emergency & fire protection plans

8310060481 Releases public version of revised emergency plan
implementation procedure
FELTON, J M Division of Rules and Records 83/09/22 Document
Management Branch 1p 20660 086 24X Fiche 50-387, 83/09/22,
8310060481

--8310060486 Public version of Rev 2 to Emergency Plan Implementation
Procedure EP-IP-002, "Emergency Mgt Notifications" W/830915
ltr & Rev 24 to table of contents
KAISER, H Pennsylvania Power & Light Co 83/09/15 SCHWENCER, A
NRC - No Detailed Affiliation Given 75pp 20660 087 24X
Fiche 50-387, 83/09/22, 8310060481

8310120037 Forwards Amend 16 to License NPF-14 & safety evaluation
Amend incorporates Rev 2 to fire protection review rept &
corrects typographical errors in Tech Spec 4 11 2.1 2-1
SCHWENCER, A Licensing Branch 2 83/09/28 CURTIS, N W
Pennsylvania Power & Light Co 3pp 20749 183 24X
Fiche 50-387, 83/09/28, 8310120037

--8310120041 Amend 16 to License NPF-14, incorporating Rev 2 to fire
protection review rept & correcting typographical errors in
Tech Spec 4 11 2.1 2-1, "Radioactive Gaseous Waste Sampling
& Analysis Program."
EISENHUT, D Q Division of Licensing 83/09/28 21pp 20749 186
24X Fiche 50-387, 83/09/28, 8310120037

8310170046 Requests publication of FR notice of consideration of
issuance of amend to License NPF-14 & proposed NSHC
determination & opportunity for hearing re fire protection
review rept, NSHC determination available in Central Files
SCHWENCER, A Licensing Branch 2 83/09/28 MILLER, J R Operating
Reactors Branch 3 4pp 20798 060 24X Fiche 50-387, 83/09/28,
8310170046

8310060211 Forwards BAR for safety parameter display sys. in response
to Generic Ltr 82-33, per NUREG-0737, Suppl 1 & Util 830415
ltr Implementation schedule for safety parameter display
sys encl
CURTIS, N W Pennsylvania Power & Light Co 83/09/30 SCHWENCER, A
Licensing Branch 2 98pp 20646:279 24X Fiche 50-387, 83/09/30,
8310060211

8310060333 Releases public version of revised emergency plan
implementation procedure
FELTON, J M Division of Rules and Records 83/09/30 Document
Management Branch 1p 20661 334 24X Fiche 50-387, 83/09/30,
8310060333

--8310060338 Public version of Rev 2 to Emergency Plan Implementation
Procedure EP-IP-007, "Personnel Assembly & Accountability"
W/830720 ltr & Rev 20 to table of contents
KEISER, H Pennsylvania Power & Light Co 83/07/18 SCHWENCER, A.
NRC - No Detailed Affiliation Given 20pp 20661 335 24X
Fiche 50-387, 83/09/30, 8310060333

8310110091 Releases public version of revised emergency plan
implementing procedure
FELTON, J M Division of Rules and Records 83/10/05 Document
Management Branch 1p 20687, 337. 24X Fiche 50-387, 83/10/05,
8310110091

--8310110094 Public version of Rev 1 to Emergency Plan Implementing
Procedure EP-IP-018, "Emergency Call-in & Communication"
W/830831 ltr & receipt form
* Pennsylvania Power & Light Co 83/08/31. SCHWENCER, A. NRC -
No Detailed Affiliation Given 13pp. 20687 338 24X
Fiche 50-387, 83/10/05, 8310110091

H. General correspondence

8310270214 Requests that JW Millard, project manager, be deleted from svc
list & ND Helms be added as new project manager.
CURTIS, N W, Pennsylvania Power & Light Co 83/10/24 SCHWENCER, A
Licensing Branch 2 1p 20924-096. 24X Fiche 50-387, 83/10/24,
8310270214.

F. Operating license stage documents & correspondence

8310050125 Discusses util response to Condition 4 associated w/THI
Action Plan Item 11 K 3 18 re automatic depressurization sys
timer setting Proposed bypass timer setting of 480 s
acceptable. Safety evaluation encl.
SCHWENCER, A Licensing Branch 2 83/09/20. CURTIS, N W
Pennsylvania Power & Light Co. 3pp. 20650:193. 24X
Fiche 50-387, 83/09/20, 8310050125

8310110462 Advises that diesel generator starting times up to 25 s or
less acceptable per 820924 Tech Spec change request
SCHWENCER, A Licensing Branch 2 83/09/28 CURTIS, N W
Pennsylvania Power & Light Co 3pp 20706 314 24X
Fiche 50-387, 83/09/28, 8310110462

8310120037 Forwards Amend 16 to License NPF-14 & safety evaluation
Amend incorporates Rev 2 to fire protection review rept &
corrects typographical errors in Tech Spec 4 11 2.1 2-1
SCHWENCER, A Licensing Branch 2 83/09/28 CURTIS, N W
Pennsylvania Power & Light Co 3pp 20749 183 24X
Fiche 50-387, 83/09/28, 8310120037

--8310120041 Amend 16 to License NPF-14, incorporating Rev 2 to fire
protection review rept & correcting typographical errors in
Tech Spec 4 11 2.1 2-1, "Radioactive Gaseous Waste Sampling
& Analysis Program"
EISENHUT, D Q Division of Licensing 83/09/28 21pp 20749 186
24X Fiche 50-387, 83/09/28, 8310120037

--8310120045 Safety evaluation supporting Amend 16 to License NPF-14
* NRC - No Detailed Affiliation Given 83/09/28 5pp
20749 207 24X Fiche 50-387, 83/09/28, 8310120037

8310170046 Requests publication of FR notice of consideration of
issuance of amend to License NPF-14 & proposed NSHC
determination & opportunity for hearing re fire protection
review rept NSHC determination available in Central Files
SCHWENCER, A Licensing Branch 2 83/09/28 MILLER, J R Operating
Reactors Branch 3 4pp 20798 060 24X Fiche 50-387, 83/09/28,
8310170046

8310170048 Requests publication of FR notice of consideration of
issuance of amend to License NPF-14 & proposed NSHC
determination & opportunity for hearing re deletion of grab
samples NSHC determination available in Central Files
SCHWENCER, A Licensing Branch 2 83/09/28 MILLER, J R Operating
Reactors Branch 3 4pp 20814 142 24X Fiche 50-387, 83/09/28,
8310170048

8310180131 Advises that continued operation until completion of mods re
NUREG-0737, Item 11 E 4.2 concerning gang opening of two sys.
justified licensee committed to modifying logic at first
refueling outage
SCHWENCER, A Licensing Branch 2 83/09/29 CURTIS, N W
Pennsylvania Power & Light Co 3pp 20827 077 24X
Fiche 50-387, 83/09/29, 8310180131

8310130207 Forwards application for amend to License NPF-14, correcting
typographical error in design of reactor water Level 2
& revising isolation signal for valves required for reactor
water Level 3 only
CURTIS, N W Pennsylvania Power & Light Co 83/10/07 SCHWENCER, A
Licensing Branch 2 3pp 20725 018 24X Fiche 50-387, 83/10/07,
8310130207

--8310130213 Application for proposed Amend 30 to License NPF-14,
correcting typographical error in design of reactor water
Level 2 & revising isolation signal for valves required for
reactor water Level 3 only W/marked-up Tech Spec
CURTIS, N W Pennsylvania Power & Light Co 83/10/07 2pp
20725:021 24X Fiche 50-387, 83/10/07, 8310130207

8310140114 Expresses concern re wording of new 10CFR50.72(b)(2)(VI)
effective 840101 Paragraph stated was not included in
proposed rule Rev stating that licensee notify NRC as soon
as practical should be included
CURTIS, N W Pennsylvania Power & Light Co 83/10/10 DENFON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20764 009
24X Fiche 50-387, 83/10/10, 8310140114

8310170495 Request that NUREG-0123, "Std BWR Tech Specs," be revised to
previous format, based on need to provide adequate time frame
for completion of WPPSS-2 power ascension testing program
Susquehanna test duration data encl
SORENSEN, Q C Washington Public Power Supply System 83/10/10
SCHWENCER, A Licensing Branch 2 3pp 20784 015 24X
Fiche 50-000, 83/10/10, 8310170495

8310140155 Application for Amend 29 to License NPF-14, revising
inservice visual insp of snubbers
CURTIS, N W Pennsylvania Power & Light Co 83/10/11 SCHWENCER, A
Licensing Branch 2 4pp 20763 014 24X Fiche 50-387, 83/10/11,
8310140155

--8310140156 Proposed rev to Tech Specs re surveillance requirements for
snubbers
* Pennsylvania Power & Light Co. 83/10/11 2pp 20763 018 24X
Fiche 50-387, 83/10/11, 8310140155

DOCKETED ITEMS

263

- 8310180426 Forwards rev to Section 14.2 of FSAR re proposed startup test program for Unit 2 & clarification of Unit 1 startup test program Revs will be incorporated into next FSAR amend
CURTIS, N W Pennsylvania Power & Light Co 83/10/13 SCHWENGER, A
Licensing Branch 2 70pp 20803 224 24X Fiche 50-387, 83/10/13, 8310180426
- 8310180480 Forwards Rev 1 to "Control Sys Power Supply & Sensor Malfunction Study" Existing sys adequately controls
Facility
CURTIS, N W Pennsylvania Power & Light Co 83/10/14 SCHWENGER, A
Licensing Branch 2 2pp 20800 167 24X Fiche 50-387, 83/10/14, 8310180480
- 8310180481 Rev 1 to "Control Sys Power Supply & Sensor Malfunction Study"
* EDS Nuclear, Inc 02-0160-1102 R01 82/03/31 29pp
20800 169 24X Fiche 50-387, 83/10/14, 8310180480
- 8310180485 App A to Rev 1 to "Control Sys Power Supply & Sensor Malfunction Study," "Technical Procedure for Performance of Analysis"
* EDS Nuclear, Inc 82/03/31 30pp 20800 194 24X
Fiche 50-387, 83/10/14, 8310180480
- 8310180493 App B to Rev 1 to "Control Sys Power Supply & Sensor Malfunction Study," "Control Sys & Safety Functions"
* EDS Nuclear, Inc 02-0160-1102 R1 APPB 82/03/31 10pp
20800 224 24X Fiche 50-387, 83/10/14, 8310180480
- 8310180497 App C to Rev 1 to "Control Sys Power Supply & Sensor Malfunction Study," "Control Sys Identification Diagrams"
W/ five oversize diagrams Aperture cards are available in PDR
* EDS Nuclear, Inc 02-0160-1102 R1 APPC 82/03/31 1p
20800 233 24X Fiche 50-387, 83/10/14, 8310180480
- 8310180498 App D to Rev 1 to "Control Sys Power Supply & Sensor Malfunction Study," "Commonality Diagrams"
* EDS Nuclear, Inc 02-0160-1102 R1 APPD 82/03/31 11pp
20800 235 24X Fiche 50-387, 83/10/14, 8310180480
- 8310180501 App E to Rev 1 to "Control Sys Power Supply & Sensor Malfunction Study," "Failure Modes & Effects Analysis"
* EDS Nuclear, Inc 02-0160-1102 R1 APPE 82/03/31 51pp
20800 246 24X Fiche 50-387, 83/10/14, 8310180480
- 8310180504 App F to Rev 1 to "Control Sys Power Supply & Sensor Malfunction Study," "Malfunction Analysis Tables"
* EDS Nuclear, Inc 02-0160-1102 R1 APPF 82/03/31 43pp
20800 297 24X Fiche 50-387, 83/10/14, 8310180480
- 8310180507 Forwards Rev 0 to "Evaluation of Effects of High Energy Line Breaks on Control Sys"
CURTIS, N W Pennsylvania Power & Light Co 83/10/14 SCHWENGER, A
Licensing Branch 2 1p 20800 340 24X Fiche 50-387, 83/10/14, 8310180507
- 8310180509 Rev 0 to "Evaluation of Effects of High Energy Line Breaks on Control Sys"
* EDS Nuclear, Inc 02-0160-1131 R00 83/05/31 36pp
20800 341 24X Fiche 50-387, 83/10/14, 8310180507
- 8310180510 App A to Rev 0 to "Evaluation of Effects of High Energy Line Breaks on Control Sys," "Technical Procedure for Performance of Analysis"
* EDS Nuclear, Inc 83/05/31 29pp 20801 015 24X
Fiche 50-387, 83/10/14, 8310180507
- 8310180514 App B to Rev 0 to "Evaluation of Effects of High Energy Line Breaks on Control Sys," "Control Sys & Safety Functions"
* EDS Nuclear, Inc 02-0160-1131 R0 APPB 83/05/31 11pp
20801 044 24X Fiche 50-387, 83/10/14, 8310180507
- 8310180518 App C to Rev 0 to "Evaluation of Effects of High Energy Line Breaks on Control Sys," "Control Sys Identification Diagrams & Control System Component Tables" W/ four oversize diagrams Aperture cards are available in PDR
* EDS Nuclear, Inc 02-0160-1131 R0 APPC 83/05/31 13pp
20801 055 24X Fiche 50-387, 83/10/14, 8310180507
- 8310180520 App D to Rev 0 to "Evaluation of Effects of High Energy Line Breaks on Control Sys," "Commonality Diagrams"
* EDS Nuclear, Inc 02-0160-1131 R0 APPD 83/05/31 4pp
20801 067 24X Fiche 50-387, 83/10/14, 8310180507
- 8310180523 App E to Rev 0 to "Evaluation of Effects of High Energy Line Breaks on Control Sys," "Failure Modes & Effects Analysis"
* EDS Nuclear, Inc 02-0160-1131 R0 APPE 83/05/31 19pp
20801 073 24X Fiche 50-387, 83/10/14, 8310180507
- 8310180525 App F to Rev 0 to "Evaluation of Effects of High Energy Line Breaks on Control Sys," "Figures & Tables"
* EDS Nuclear, Inc 02-0160-1131 R0 APPF 83/05/31 22pp
20801 092 24X Fiche 50-387, 83/10/14, 8310180507
- 8310250106 Opposes NRC 830928 position on Tech Spec requiring second diesel start to occur in 10 s or less Opportunity for detailed discussion requested
CURTIS, N W Pennsylvania Power & Light Co 83/10/20 SCHWENGER, A
Licensing Branch 2 1p 20896 248 24X Fiche 50-387, 83/10/20, 8310250106
- 8310250246 Forwards application for Proposed Amend 31 to License NPF-14, changing Tech Spec Table 4 B 1 1 2-2 re settings for emergency svc water pump timers
KENYON, B D Pennsylvania Power & Light Co 83/10/20 SCHWENGER, A
Licensing Branch 2 3pp 20899 030 24X Fiche 50-387, 83/10/20, 8310250246
- 8310250252 Application for Proposed Amend 31 to License NPF-14, changing Tech Spec Table 4 B 1 1 2-2 re settings for emergency svc water pump timers
KENYON, B D Pennsylvania Power & Light Co 83/10/20 1p
20899 033 24X Fiche 50-387, 83/10/20, 8310250246
- 8310250258 Proposed changes to Tech Spec Table 4 B 1 1 2-2 re settings for emergency svc water pump timers
* Pennsylvania Power & Light Co 83/10/20 2pp 20899 034 24X
Fiche 50-387, 83/10/20, 8310250246
- 8310270449 Forwards application for amend to License NPF-14, consisting of Proposed Amend 32, changing Tech Specs to limit spray pond operating temp to 81 F & to maintain inventory at min of 23 million gallons
KENYON, B D Pennsylvania Power & Light Co 83/10/24 SCHWENGER, A
Licensing Branch 2 2pp 20923 027 24X Fiche 50-387, 83/10/24, 8310270449
- 8310270453 Application for amend to License NPF-14, consisting of Proposed Amend 32, changing Tech Specs to limit spray pond operating temp to 81 F & to maintain inventory at min of 23 million gallons
KENYON, B D Pennsylvania Power & Light Co 83/10/24 1p
20923 029 24X Fiche 50-387, 83/10/24, 8310270449
- 8310270457 Proposed Tech Specs re limiting condition for operation & surveillance requirements for spray pond operating temp
* Pennsylvania Power & Light Co 83/10/24 1p 20923 030 24X
Fiche 50-387, 83/10/24, 8310270449
- 9 Inspection reports, IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

DOCKETED ITEMS

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8310180349 Ack receipt of 830928 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-387/83-18
MARTIN, T. T. Division of Engineering & Technical Programs 83/10/07
KENYON, B. D. Pennsylvania Power & Light Co ip 20803 011. 24X Fiche 50-387, 83/10/07, 8310180349

--8310180356 Responds to NRC 830829 ltr re violations noted in IE Insp Rept 50-387/83-18 Corrective actions importance of complying w/plant procedures & radiation work permit requirements stressed & incorporated into training course
KENYON, B. D. Pennsylvania Power & Light Co 83/09/28 MARTIN, T. T. Division of Engineering & Technical Programs 4pp 20803 012 24X Fiche 50-387, 83/10/07, 8310180349

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11. Consolidated Edison Co. of New York, Inc. 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning/Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310140155 Application for Amend 29 to License NPF-14, revising inservice visual insp of snubbers
CURTIS, N. W. Pennsylvania Power & Light Co 83/10/11 SCHWENCER, A. Licensing Branch 2 4pp 20763 014 24X Fiche 50-387, 83/10/11, 8310140155

--8310140156 Proposed rev to Tech Specs re surveillance requirements for snubbers.
* Pennsylvania Power & Light Co 83/10/11. 2pp 20763 018 24X Fiche: 50-387, 83/10/11, 8310140155.

8310180531 Notification of 831021 meeting w/BWR licensees in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking
MIRALOLA, F. J. Assistant Director for Safety Assessment 83/10/14
EISENHUT, D. Q. Division of Licensing. 5pp 20823 358 24X Fiche. 50-000, 83/10/14, 8310180531

8310250476 Advises of plans to revise PSI commitments outlined in Relief Request 4 to delete further efforts w/proposed automated ultrasonic equipment MINAC will be used to radiographically inspect inservice welds during refueling.
CURTIS, N. W. Pennsylvania Power & Light Co 83/10/19. SCHWENCER, A. Licensing Branch 2 2pp 20897 143 24X Fiche 50-387, 83/10/19, 8310250476

R. Periodic operating reports & related correspondence

8310190080 Monthly operating rept for Aug 1983 W/830912 ltr
KUCZYNSKI, L. A., KENYON, B. D. Pennsylvania Power & Light Co 83/09/08 BEEBE, M. R. Management Information Branch 5pp 20822 273. 24X Fiche 50-387, 83/09/08, 8310190080

8310110197 NPDES discharge monitoring rept for Aug 1983 W/830929 ltr
KAUFFMAN, J. T. Pennsylvania Power & Light Co 83/09/26
Pennsylvania, Commonwealth of. 10pp. 20665 296 24X Fiche. 50-387, 83/09/26, 8310110197.

B Reportable occurrences, LERs & related correspondence

8310270541 Responds to FOIA request for three categories of documents re 830606 gas leak at facility Forwards App A documents
FELTON, J. M. Division of Rules and Records. 83/07/22. ARQVROS, D. L. Chamlin, Schettland, Rosen, Cavanagh & Uliano 2pp 20937 225 24X Fiche: 50-000, 83/07/22, 8310270541

--8310270547 Submits morning rept for Region I, listing 830606 & 07 events.
ALLAN, J. M. Region I, Office of Director 83/06/07 BLAHA, J. Program Support Branch ip. 20937 228. 24X Fiche 50-000, 83/07/22, 8310270541

8310210329 Responds to FOIA request for all documents re significantly high rate of equipment failures for GE BWR/4 rated at 2.436 MW. Forwards App A documents Documents also available in PDR
FELTON, J. M. Division of Rules and Records 83/07/28 HAFNER, B. Suffolk Nuclear Study Group 2pp 20882 223 24X Fiche: 50-000, 83/07/28, 8310210329.

--8303030103 Comments of LERs submitted from Feb 1982 - Jan 1983, in support of SALP review LERs generally prepared adequately w/occasional exceptions Licensee performance typical of average BWR facility in initial phase of plant startup
SEYFRIT, K. V. Reactor Operations Analysis Branch 83/02/22
STAROSTECKI, R. Division of Project & Resident Programs 2pp 20882 263 24X Fiche 50-000, 83/07/28, 8310210329

8310250219 LER 83-117/03L-0 on 830815 & 0902, reactor bldg Zone I HVAC supply fans tripped, causing Zone I pressure to exceed Tech Specs Caused by opening reactor bldg Zone I supply plenum access door for approx 30 s or longer W/830915 ltr
PIEMONTESE, A. P., KEISER, H. W. Pennsylvania Power & Light Co 83/09/15 MURLEY, T. E. Region I, Office of Director 2pp 20893 305 24X Fiche 50-387, 83/09/15, 8310250219

8310310305 RD on 830811, trouble alarm for Fire Detection Zone B9 announced in plant control room Investigation revealed open resistance exists in circuit for Zone B9 End-of-life relay replaced
KEISER, H. W. Pennsylvania Power & Light Co 83/09/15 MURLEY, T. E. Region I, Office of Director ip 20941 223 24X Fiche 50-387, 83/09/15, 8310310305

8310200271 LER 83-116/03L-0 on 830823, check valve in RHM pump A discharge line would not seat properly & suction valve closed resulting in limiting condition of operation Caused by need to seat discharge line check valve W/830922 ltr
KUCZYNSKI, L. A., KEISER, H. W. Pennsylvania Power & Light Co 83/09/22 MURLEY, T. E. Region I, Office of Director 3pp 20830 044 24X Fiche 50-387, 83/09/22, 8310200271

8310280130 Final deficiency rept re water hammer in essential svr water sys Initially reported on 830505 Vacuum breakers will be installed during first refueling outage Also reported per Part 21
CURTIS, N. W. Pennsylvania Power & Light Co 83/09/22 MURLEY, T. E. Region I, Office of Director 7pp 20929 254 24X Fiche 50-387, 83/09/22, 8310280130

8310190120 LER 83-120/03L-0 on 830828, during post-scrum vessel level fluctuation, RCIC sys turbine automatically initiated & tripped on electrical overspeed Caused by slow response of governor valve linkage travel reduced W/830927 ltr
GRAHAM, J. J., KEISER, H. W. Pennsylvania Power & Light Co 83/09/27 MURLEY, T. E. Region I, Office of Director 3pp 20821 049 24X Fiche 50-387, 83/09/27, 8310190120

8310190145 LER 83-119/03L-0 on 830828, during drywell vacuum 2 h post-initiation surveillance, anomalous position indication noted for two vacuum breakers Caused by loose cam coupling set screws Solenoid valve cleaned Screws tightened W/830927 ltr.
KUCZYNSKI, L. A., KEISER, H. W. Pennsylvania Power & Light Co 83/09/27 MURLEY, T. E. Region I, Office of Director 3pp 20820 313 24X Fiche 50-387, 83/09/27, 8310190145

8310190230 LER 83-118/03L-0 on 830829, during calibr of main steam line A low pressure switch PSL-B21-IN015A setpoint found below Tech Spec allowable value Setpoint failed acceptance criteria Switch replaced W/830927 ltr
PIEMONTESE, A. P., KEISER, H. W. Pennsylvania Power & Light Co 83/09/27 MURLEY, T. E. Region I, Office of Director 2pp 20818 050 24X Fiche 50-387, 83/09/27, 8310190230

8310250594 LER 83-078/03L-0 on 830829, excess flow check valve XV-B21-F009 could not be tested to verify operability Caused by present configuration of instrument line not allowing access to valve w/o removing vessel head W/830927 ltr
PIEMONTESE, A. P., KEISER, H. W. Pennsylvania Power & Light Co 83/09/27 MURLEY, T. E. Region I, Office of Director 2pp 20901 056 24X Fiche 50-387, 83/09/27, 8310250594

8310250228 LER 83-122/03L-0 on 830901, reactor bldg Zone III ventilation sys isolated & would not restart after radiation detector power supply switched to alternate source Caused by blown fuse on Zone III isolation damper HD17502A W/830930 ltr.
PIEMONTESE, A. P., KEISER, H. W. Pennsylvania Power & Light Co 83/09/30 MURLEY, T. E. Region I, Office of Director 3pp 20899 118 24X Fiche 50-387, 83/09/30, 8310250228

8310250245 LER 83-123/03L-0 on 830901, reactor bldg Zone III ventilation tripped, causing short-duration loss of 0.25 inches Caused by momentary, spurious signal Investigation revealed absence of Zone III isolation signal W/830930 ltr.
KUCZYNSKI, L. A., KEISER, H. W. Pennsylvania Power & Light Co 83/09/30 MURLEY, T. E. Region I, Office of Director 2pp 20899 072 24X Fiche 50-387, 83/09/30, 8310250245

8310250386 LER 83-121/03L-0 on 830902, average power range monitor flow biased simulated thermal power - upscale scram & neutron flux - upscale control rod block trip setpoints higher than Tech Spec limit Caused by power peaking W/830930 ltr
KUCZYNSKI, L. A., KEISER, H. W. Pennsylvania Power & Light Co 83/09/30 MURLEY, T. E. Region I, Office of Director 2pp 20898 143 24X Fiche 50-387, 83/09/30, 8310250386

DOCKETED ITEMS

265

8310250555 LER 83-1P4/03L-0 on 830901, solenoid valve controlling reactor bldg Zone I exhaust fan damper failed Caused by ratl wear in solenoid valve Valve rebuilt & reinstalled W/830930 ltr
KUCZYNSKI, L A , KEISER, H W Pennsylvania Power & Light Co
83/09/30 MURLEY, T E Region 1, Office of Director 2pp
20701 010 24X Fiche 50-387, 83/09/30, 8310250555

8310130187 Advises that AEDD engineering evaluation rept re events involving RHR sys in shutdown cooling mode distributed to appropriate NRR branches & project manager
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/10/04 HELTENES, C J Director's Office 2pp 20754 340 24X
Fiche 50-387, 83/10/04, 8310130187

--8308150385 Forwards AEDD engineering evaluation rept, "Misuse of Valve Resulting in Vibration & Damage to Valve Assembly & Pipe Supports"
BROWN, E J Reactor Operations Analysis Branch 83/07/07
SEVFRIT, K V Reactor Operations Analysis Branch 1p 20754 343
24X Fiche 50-387, 83/10/04, 8310130187

8310250402 LER 83-126/03L-0 on 830905, following receipt of fault alarm, control rod scram accumulator 46-07 pressure found below Tech Spec limit Caused by water leak past piston Accumulator repressurized W/831005 ltr
PIEMONTESE, A P , KEISER, H W Pennsylvania Power & Light Co
83/10/05 MURLEY, T E Region 1, Office of Director 2pp
20897 296 24X Fiche 50-387, 83/10/05, 8310250402

8310250204 LER 83-129/01P-0 on 830927, torque switch spring pack failed to open at specified torque, causing valve operating motor to burn up on over-torque w/locked rotor Engineering evaluation of thermal overload bypass circuit design under review
KEISER, H W Pennsylvania Power & Light Co 83/10/07 MURLEY, T E
Region 1, Office of Director 2pp 20893 362 24X
Fiche 50-387, 83/10/07, 8310250204

8310250242 LER 83-132/03L-0 on 830910, during weekly preventive maint activity, analyzer B exhibited erratic oxygen concentration readings & declared inoperable Caused by malfunctioning hydrogen sample cell flow regulator W/831010 ltr
KUCZYNSKI, L A , KEISER, H W Pennsylvania Power & Light Co
83/10/10 MURLEY, T E Region 1, Office of Director 2pp
20899 070 24X Fiche 50-387, 83/10/10, 8310250242

8310250622 LER 83-131/03L-0 on 830910, diesel generator B tripped prior to achieving 600 rpm Three low priority alarms received concurrently w/trip Caused by water & corrosion products in instrument air sys Air dryers to be installed W/831010 ltr
KUCZYNSKI, L A , KEISER, H W Pennsylvania Power & Light Co
83/10/10 MURLEY, T E Region 1, Office of Director 2pp
20900 285 24X Fiche 50-387, 83/10/10, 8310250622

8310280125 LER 83-130/01P-0 discrepancies discovered in initiating signals for 10 containment isolation valves Caused by personnel omission to make proper FSAR & Tech Spec changes Followup rept will be provided in 14 days
KEISER, H W Pennsylvania Power & Light Co 83/10/10 MURLEY, T E
Region 1, Office of Director 1p 20929 220 24X
Fiche 50-387, 83/10/10, 8310280125

8310250266 LER 83-134/03L-0 on 830912, during diesel generator monthly operability test, diesel generator C tripped on overexcitation Probably caused by voltage perturbation on off-site grid interfacing Investigation ongoing W/831012 ltr
KUCZYNSKI, L A , KEISER, H W Pennsylvania Power & Light Co
83/10/12 MURLEY, T E Region 1, Office of Director 3pp
20899 020 24X Fiche 50-387, 83/10/12, 8310250266

8310200221 NPDES noncompliance notification beginning 830918, drinking water turbidity level ranged from 1.7 to 3.2 turbidity units Free available chlorine level indicated maint of disinfection in sys Safe drinking water requirements met
FIELDG, J S Pennsylvania Power & Light Co 83/10/13
WHITCRAFT, P K Environmental Protection Agency 1p 20833 044
24X Fiche 50-387, 83/10/13, 8310200221

8310250345 LER 83-128/03L-0 on 830913, reactor bldg Zone III ventilation sys tripped & automatically restarted Caused by spurious activation of differential PSDH 17501B switch Pneumatic instruments replaced W/831013 ltr
PIEMONTESE, A P , KEISER, H W Pennsylvania Power & Light Co
83/10/13 MURLEY, T E Region 1, Office of Director 2pp
20898 040 24X Fiche 50-387, 83/10/13, 8310250345

DOCKET 50-388 SUBQUEHANNA STEAM ELECTRIC STATION, UNIT 2
A Application/construction stage documents & correspondence

8310050125 Discusses util response to Condition 4 associated w/TMI Action Plan Item II K 3 18 re automatic depressurization sys timer setting Proposed bypass timer setting of 480 s acceptable Safety evaluation encl
SCHWENCER, A Licensing Branch 2 83/09/20 CURTIS, N W
Pennsylvania Power & Light Co 3pp 20650 195 24X
Fiche 50-387, 83/09/20, 8310050125

8310210292 Forwards summary of 830907 meeting in Allentown, PA re power, voltage & relay study covering cable length deficiency, T-10 & ECCS transformer project
CURTIS, N W Pennsylvania Power & Light Co 83/09/21 MURLEY, T E
Region 1, Office of Director 23pp 20895 222 24X
Fiche 50-388, 83/09/21, 8310210292

8310040052 Forwards 9-month response for NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants" Electrical interlocks prevent main hoist of reactor bldg crane from being used over reactor well or spent fuel pool
CURTIS, N W Pennsylvania Power & Light Co 83/09/29 SCHWENCER, A
Licensing Branch 2 63pp 20608 143 24X Fiche 50-388, 83/09/29, 8310040052

8310040421 Forwards revs to FSAR Section 53 re stainless steel weld cladding & fracture toughness Revs show conformance w/10CFR50 Apps G & H & will be incorporated in next FSAR amend
CURTIS, N W Pennsylvania Power & Light Co 83/09/29 SCHWENCER, A
Licensing Branch 2 10pp 20619 175 24X Fiche 50-388, 83/09/29, 8310040421

8310040640 Forwards revised Section 11.3 of FSAR to be incorporated into next amend Rev refs gaseous waste mgt sys diagrams
CURTIS, N W Pennsylvania Power & Light Co 83/09/30 SCHWENCER, A
Licensing Branch 2 2pp 20625 350 24X Fiche 50-388, 83/09/30, 8310040640

8310120175 Forwards revised Section 3.13 to FSAR Rev references until previously submitted position on Reg Guide 1.97 Rev will be incorporated in next FSAR amend.
CURTIS, N W Pennsylvania Power & Light Co 83/09/30 SCHWENCER, A
Licensing Branch 2 2pp 20695 290 24X Fiche 50-388, 83/09/30, 8310120175

8310070160 Submits rev to FSAR Section 7.5 re neutron flux monitoring sys & plant computer sys Revs will be incorporated in next FSAR amend
CURTIS, N W Pennsylvania Power & Light Co 83/10/03 SCHWENCER, A
Licensing Branch 2 8pp 20659 087 24X Fiche 50-388, 83/10/03, 8310070160

8310120067 Forwards revised Section 7.4 to FSAR, clarifying pressure indicator monitoring, adding discussion of non-Class 1E temp sensors & including info average power range monitor upscale thermal trip Revs will be incorporated into next FSAR rev
CURTIS, N W Pennsylvania Power & Light Co 83/10/06 SCHWENCER, A
Licensing Branch 2 4pp 20697 165 24X Fiche 50-388, 83/10/06, 8310120067

8310120080 Informs that FSAR Section 12.2 revised to reflect that layout of equipment in Unit 2 not significantly different than Unit 1 layout Shielding & zoning requirements apply to both units Info will be incorporated into next FSAR amend
CURTIS, N W Pennsylvania Power & Light Co 83/10/06 SCHWENCER, A
Licensing Branch 2 2pp 20697 155 24X Fiche 50-388, 83/10/06, 8310120080

8310120105 Forwards revised FSAR Section 10.4 re regeneration sys, Revs clarify acid strength & verify ultrasonic resin cleaner added to sys Revs will be incorporated in next FSAR amend
CURTIS, N W Pennsylvania Power & Light Co 83/10/06 SCHWENCER, A
Licensing Branch 2 3pp 20696 225 24X Fiche 50-388, 83/10/06, 8310120105

8310120144 Forwards revised Section 3.4A of FSAR re analysis for HPCI & RCIC pump rooms Info will be incorporated into next FSAR amend
CURTIS, N W Pennsylvania Power & Light Co 83/10/06 SCHWENCER, A
Licensing Branch 2 9pp 20696 033 24X Fiche 50-388, 83/10/06, 8310120144

8310140077 Forwards revised FSAR Section 7.7 clarifying scram discharge high level vol & computer sys block diagram Revs will be incorporated in next FSAR amend
CURTIS, N W Pennsylvania Power & Light Co 83/10/07 SCHWENCER, A
Licensing Branch 2 6pp 20767 134 24X Fiche 50-388, 83/10/07, 8310140077

DOCKETED ITEMS

8310170145 Forwards "UHS Test Interim Rept." conducted to demonstrate that measured performance of spray pond equals or exceeds performance predicted by analysis for two-unit operations
CURTIS, N.W. Pennsylvania Power & Light Co 83/10/12 SCHWENCER, A
Licensing Branch 2 1p 20787 007 24X Fiche 50-388, 83/10/12,
8310170145

--8310170148 "UHS Test Interim Rept."
* Pennsylvania Power & Light Co 83/10/12 5pp 20787 008 24X
Fiche 50-388, 83/10/12, 8310170145

8310180166 Forwards FSAR Section 9.1 re reactor bldg crane, revised in response to NUREG-0612 Changes will be incorporated into next FSAR amend
CURTIS, N.W. Pennsylvania Power & Light Co 83/10/13 SCHWENCER, A
Licensing Branch 2 28pp 20809 001 24X Fiche 50-388, 83/10/13,
8310180166

8310180426 Forwards rev to Section 14.2 of FSAR re proposed startup test program for Unit 2 & clarification of Unit 1 startup test program Revs will be incorporated into next FSAR amend
CURTIS, N.W. Pennsylvania Power & Light Co 83/10/13 SCHWENCER, A
Licensing Branch 2 70pp 20803 224 24X Fiche 50-387, 83/10/13,
8310180426

8310180437 Forwards revised FSAR Sections 14.2.12.4 & 14.2.12.5 covering preoperational test program Revs will be incorporated in next FSAR amend
CURTIS, N.W. Pennsylvania Power & Light Co 83/10/13 SCHWENCER, A
Licensing Branch 2 95pp 20802 163 24X Fiche 50-388, 83/10/13,
8310180437

8310180454 Forwards revs to Section 9.3 of FSAR covering process sampling sys & design bases Revs will be incorporated in next FSAR amend
CURTIS, N.W. Pennsylvania Power & Light Co 83/10/14 SCHWENCER, A
Licensing Branch 2 5pp 20802 107 24X Fiche 50-388, 83/10/14,
8310180454

8310280155 Informs that util completed installation of modified drywell to wetwell vacuum breakers
CURTIS, N.W. Pennsylvania Power & Light Co 83/10/24 SCHWENCER, A
Licensing Branch 2 1p 20929:019 24X Fiche 50-388, 83/10/24,
8310280155

E. NRC Safety Evaluation Report (SER), supp's & correspondence

8310070336 Forwards info re reactor pressure vessel beltline plates & welds, closing out SER Issue 112 FSAR changes generated will be submitted under separate cover
CURTIS, N.W. Pennsylvania Power & Light Co 83/10/03 SCHWENCER, A
Licensing Branch 2 55pp 20651 003 24X Fiche 50-388, 83/10/03,
8310070336

8310140056 Forwards response to 8SER 5, Section 1.9 Item 115 & IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation"
CURTIS, N.W. Pennsylvania Power & Light Co 83/10/10 SCHWENCER, A
Licensing Branch 2 9pp 20767 354, 24X Fiche 50-388, 83/10/10,
8310140056

F. Security, medical, emergency & fire protection plans

8310060481 Releases public version of revised emergency plan implementation procedure
FELTON, J.M. Division of Rules and Records 83/09/22 Document
Management Branch 1p 20660 086 24X Fiche 50-387, 83/09/22,
8310060481

--8310060486 Public version of Rev 2 to Emergency Plan Implementation Procedure EP-IP-002, "Emergency Mgt Notifications" W/830915 ltr & Rev 24 to table of contents
KAISER, H. Pennsylvania Power & Light Co 83/09/15 SCHWENCER, A
NRC - No Detailed Affiliation Given 79pp, 20660 087 24X
Fiche 50-387, 83/09/22, 8310060481

8310060211 Forwards SAR for safety parameter display sys, in response to Generic Ltr 82-33, per NUREG-0737, Suppl 1 & util 830415 ltr implementation schedule for safety parameter display sys encl
CURTIS, N.W. Pennsylvania Power & Light Co. 83/09/30 SCHWENCER, A
Licensing Branch 2 98pp 20646-279 24X Fiche 50-387, 83/09/30,
8310060211

8310060533 Releases public version of revised emergency plan implementation procedure
FELTON, J.M. Division of Rules and Records 83/09/30, Document
Management Branch 1p 20661 334 24X Fiche 50-387, 83/09/30,
8310060533,

--8310060538 Public version of Rev 2 to Emergency Plan Implementation Procedure EP-IP-007, "Personnel Assembly & Accountability" W/830720 ltr & Rev 20 to table of contents
KAISER, H. Pennsylvania Power & Light Co 83/07/18 SCHWENCER, A
NRC - No Detailed Affiliation Given 20pp 20661 335 24X
Fiche 50-387, 83/09/30, 8310060533

8310110091 Releases public version of revised emergency plan implementing procedure
FELTON, J.M. Division of Rules and Records 83/10/05 Document
Management Branch 1p 20687 337 24X Fiche 50-387, 83/10/05,
8310110091

--8310110094 Public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-018, "Emergency Call-in & Communication" W/830831 ltr & receipt form
* Pennsylvania Power & Light Co 83/08/31 SCHWENCER, A (NRC - No Detailed Affiliation Given 13pp 20687 338 24X
Fiche 50-387, 83/10/05, 8310110091

H. General correspondence

8310270214 Requests that JW Millard, project manager, be deleted from svc list & ND Weiss be added as new project manager
CURTIS, N.W. Pennsylvania Power & Light Co 83/10/24 SCHWENCER, A
Licensing Branch 2 1p 20724 076 24X Fiche 50-387, 83/10/24,
8310270214

G. Inspection reports, IE Bulletins & correspondence

8310060041 Forwards IE Insp Rept 50-388/83-13 on 830816-18 No noncompliance noted
MARTIN, T. Division of Engineering & Technical Programs 83/09/22
KENYON, B.D. Pennsylvania Power & Light Co 2pp 20647 232 24X
Fiche 50-388, 83/09/22, 8310060041

--8310060046 IE Insp Rept 50-388/83-13 on 830816-18 No noncompliance noted Major areas inspected preoperational test program, interface of shared sys & QA/QC interface w/test program
NICHOLAS, H.H., BETTENHAUSEN, L. Region 1, Office of Director 83/08/31 7pp, 20647 234 24X Fiche 50-388, 83/09/22, 8310060041

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays" Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation" Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/27 Consolidated Edison Co. of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in R1D Bypass Loops Used in Westinghouse Plants" Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility," Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 77pp, 20882 024 24X Fiche 50-000, 83/10/07, 8308300752

8310140056 Forwards response to 8SER 5, Section 1.9 Item 115 & IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation"
CURTIS, N.W. Pennsylvania Power & Light Co 83/10/10 SCHWENCER, A
Licensing Branch 2 9pp 20767 354 24X Fiche 50-388, 83/10/10,
8310140056

DOCKETED ITEMS

267

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 (Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 (Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

R Periodic operating reports & related correspondence

831010197 NPDES discharge monitoring rept for Aug 1983 W/830927 ltr
KAUFFMAN, J T Pennsylvania Power & Light Co 83/09/26
Pennsylvania, Commonwealth of, 10pp 20665 296 24X
Fiche 50-387, 83/09/26, 831010197

S Reportable occurrences, LERs & related correspondence

8310310305 RO on 830811, trouble alarm for Fire Detection Zone 87 annunciated in plant control room Investigation revealed open resistance exists in circuit for Zone 87 End-of-life relay replaced
KEISEN, H W Pennsylvania Power & Light Co 83/09/15 MURLEY, T L Region 1, Office of Director 1p 20961 223 24X
Fiche 50-387, 83/09/15, 8310310305

8310210292 Forwards summary of 830907 meeting in Allentown, PA re power, voltage & relay study covering cable length deficiency, T-10 & LCCS transformer project
CURTIS, N W Pennsylvania Power & Light Co 83/09/21 MURLEY, T L Region 1, Office of Director 23pp 20855 222 24X
Fiche 50-388, 83/09/21, 8310210292

8310280130 Final deficiency rept re water hammer in essential svc water sys Initially reported on 030505 Vacuum breakers will be installed during first refueling outage Also reported per Part 21
CURTIS, N W Pennsylvania Power & Light Co 83/09/22 MURLEY, T L Region 1, Office of Director 7pp 20929 254 24X
Fiche 50-387, 83/09/22, 8310280130

8310280065 Second interim deficiency rept re GE reactor mode switch Initially reported on 830407 Mode switch redesigned sample will be independently tested Also reported per Part 21 Final rept will be submitted by Dec 1983
CURTIS, N W Pennsylvania Power & Light Co 83/09/30 MURLEY, T L Region 1, Office of Director 6pp 20929 020 24X
Fiche 50-388, 83/09/30, 8310280065

8310280137 Interim deficiency rept re isolation of nitrogen makeup sys Also reportable per Part 21 Initially reported on 830912 Permanent design mod will be implemented Final rept will be submitted in Dec 1983
CURTIS, N W Pennsylvania Power & Light Co 83/10/10 MURLEY, T L Region 1, Office of Director 5pp 20929 009 24X
Fiche 50-388, 83/10/10, 8310280137

DOCKET 50-389 ST LUCIE PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8310060490 Releases public version of revised offnormal & emergency operating procedures
FELTON, J M Division of Rules and Records 83/09/22 Document Management Branch 1p 20650 297 24X Fiche 50-335, 83/09/22, 8310060490

--8310060492 Forwards public version of revised offnormal & emergency operating procedures, including Procedures 1-0910032 re auxiliary transformer offnormal operation & 2-1010030 re loss of instrument air
WEITH, C M Florida Power & Light Co 83/09/12 Director's Office, Office of Inspection and Enforcement 1p 20650 300 24X
Fiche 50-335, 83/09/12, 8310060490

--8310060494 Public version of revised offnormal & emergency operating procedures, including Procedures 1-0910032 re auxiliary transformers offnormal operation & 2-1010030 re loss of instrument air
WEITH, C M Florida Power & Light Co 83/09/01 60pp 20650 301 24X Fiche 50-335, 83/09/22, 8310060490

8310070250 Forwards "Detailed Control Room Design Review of Plant, St Lucie Unit 2 Nuclear Power Station (NUREG-0737, Suppl 1)," per 830415 commitment
UHRIG, R E Florida Power & Light Co 83/09/30 EISENHUT, D O Division of Licensing 1p 20659 128 24X Fiche 50-389, 83/09/30, 8310070250

--8310070253 "Detailed Control Room Design Review of Plant, St Lucie Unit 2 Nuclear Power Station," summary rept
UHRIG, R E Florida Power & Light Co 83/09/30 315pp 20659 129 24X Fiche 50-389, 83/09/30, 8310070250

8310250400 Forwards IE Insp Repts 50-335/83-30 & 50-389/83-58 on 830829-0902 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/10/05 UHRIG, R E Florida Power & Light Co 2pp 20897 256 24X
Fiche 50-335, 83/10/05, 8310250400

--8310250409 IE Insp Repts 50-335/83-30 & 50-389/83-58 on 830829-0902 No noncompliance noted Major areas inspected changes to emergency preparedness program, shift staffing & augmentation & dose calculations & assessments
KAUFFMAN, J N Region 2, Office of Director 83/09/30 10pp, 20897 258 24X Fiche 50-335, 83/10/05, 8310250400

8310270049 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/27 Document Management Branch 1p 20940 286 24X Fiche 50-389, 83/10/27, 8310270049

--8310270053 Forwards public version of Rev 5 to Offnormal Emergency Operating Procedure 2-0030140, "Blackout Operation" & Rev 0 to Procedure 2-0970031, "Loss of SUPS - Nonsafety Vital AC or Fire & Security Inverters"
WEITH, C M Florida Power & Light Co 83/10/10 Director's Office, Office of Inspection and Enforcement 1p 20940 287 24X
Fiche 50-389, 83/10/27, 8310270049

--8310270067 Public version of Rev 5 to Offnormal Emergency Operating Procedure 2-0030140, "Blackout Operation" & Rev 0 to Procedure 2-0970031, "Loss of SUPS - Nonsafety Vital AC or Fire & Security Inverters"
M Florida Power & Light Co 83/10/06 21pp 20940 288 24X
Fiche 50-389, 83/10/27, 8310270049

P Operating license stage documents & correspondence

8310060534 Forwards notice of consideration of issuance of amend to License NPF-16 & proposed NSMC determination & opportunity for hearing on 830617 request re Tech Spec administrative & editorial changes
HERSES, V Licensing Branch 3 83/09/16 UHRIG, R E Florida Power & Light Co 2pp 20663 279 24X Fiche 50-389, 83/09/16, 8310060534

--8310060537 Notice of consideration of issuance of amend to License NPF-16 & proposed NSMC determination & opportunity for hearing on 830617 request re Tech Spec administrative & editorial changes
KNIGHTON, O W Licensing Branch 3 83/09/15 8pp 20663 281 24X Fiche 50-389, 83/09/16, 8310060534

8310101497 Advises that project mgt responsibility transferred from Licensing Branch 3 to Operating Reactor Branch 3, effective 830919 Personnel changes listed
MILLER, J R Operating Reactors Branch 3 83/09/26 UHRIG, R E Florida Power & Light Co 2pp 20714 317 24X
Fiche 50-389, 83/09/26, 8310101497

8310130423 Advises that, effective 830919, mgt responsibility transferred from Licensing Branch 3 to Operating Reactors Branch 3, Div of Licensing
MILLER, J R Operating Reactors Branch 3 83/09/28 O'REILLY, J P Region 2, Office of Director 2pp 20769 240 24X
Fiche 50-389, 83/09/28, 8310130423

8310130153 Forwards "Inservice Test Program for Pumps & Valves" & Rev 0 to PMS-CIG Document 002-10, "Inservice Insp, First 10-Yr Plan," Vols 1 & 2
UHRIG, R E Florida Power & Light Co 83/10/06 EISENHUT, D O Division of Licensing 1p 20717 139 24X Fiche 50-389, 83/10/06, 8310130153

--8310130154 "Inservice Test Program for Pumps & Valves, St Lucie Unit 2"
M Florida Power & Light Co 83/10/06, 129pp 20717 140 24X
Fiche 50-389, 83/10/06, 8310130153

DOCKETED ITEMS

8310180208 Application for amend to Licenses DPR-67 & NPF-16, revising facility organization chart & modifying definition of shift technical advisor function
 WILLIAMS, J W Florida Power & Light Co 83/10/12 EISENHUT, D O
 Division of Licensing 3pp 20808 217 24X Fiche 50-335, 83/10/12, 8310180208

--8310180211 Proposed Tech Specs, revising facility organization chart & modifying definition of shift technical advisor function
 Safety evaluation encl
 * Florida Power & Light Co 83/10/12 6pp 20808 220 24X
 Fiche 50-335, 83/10/12, 8310180208

8310270211 Forwards list of addl ESF actuation sys relays not identified in 830926 submittal or FSAN to be contestable w/o jeopardizing plant safety. Sufficient justification provided for not testing relays
 WILLIAMS, J W Florida Power & Light Co 83/10/21 EISENHUT, D O
 Division of Licensing 3pp 20924 041 24X Fiche 50-389, 83/10/21, 8310270211

8310310015 Forwards Class I & Class II fees for 831012 application to amend Licenses DPR-67 & NPF-16 w/o encl
 WILLIAMS, J W Florida Power & Light Co 83/10/26 EISENHUT, D O
 Division of Licensing 1p 20947 105 24X Fiche 50-335, 83/10/26, 8310310015

G Inspection reports, IE Bulletins & correspondence

8310040447 Forwards IE Insp Repts 50-335/83-27 & 50-389/83-52 on 830611-0710 No noncompliance noted
 DANCE, H C Division of Project & Resident Programs 83/09/14
 UHRIG, R E Florida Power & Light Co 2pp 20625 285 24X
 Fiche 50-335, 83/09/14, 8310040447

--8310040454 IE Insp Repts 50-335/83-27 & 50-389/83-52 on 830611-0710 No noncompliance noted. Major areas inspected maint & surveillance observations, plant operations, IE bulletins & circulars, LERs, BER followup & PAB item followup
 ELROD, S A, BIBB, H E Region 2, Office of Director JULIAN C
 Division of Project & Resident Programs 83/09/13 17pp
 20625 287 24X Fiche 50-335, 83/09/14, 8310040447

8310040405 Confirms telcon re 831021 mgt meeting in Miami, FL to discuss results of first phase of SALP review for period Jul 1982 - June 1983 Proposed agenda encl
 LEWIS, R C Division of Project & Resident Programs 83/09/22
 UHRIG, R E Florida Power & Light Co 2pp 20619 092 24X
 Fiche 50-000, 83/09/22, 8310040405

8310040458 Confirms 830916 decision to cancel NRC training assessment team 830926-30 Insp Util will be informed of reschedule date
 LEWIS, R C Division of Project & Resident Programs 83/09/23
 UHRIG, R E Florida Power & Light Co 1p 20623 324 24X
 Fiche 50-335, 83/09/23, 8310040458

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests." Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/09/26 Consolidated Edison Co of New
 York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes." Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/09/26 Consolidated Edison Co of New
 York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays." Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/09/26 Consolidated Edison Co of New
 York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310250615 Forwards IE Insp Repts 50-335/83-31 & 50-389/83-59 on 830830-0902 No noncompliance noted
 DANCE, H C Division of Project & Resident Programs 83/09/27
 UHRIG, R E Florida Power & Light Co 2pp 20900 167 24X
 Fiche 50-335, 83/09/27, 8310250615

--8310250621 IE Insp Rept 50-335/83-31 & 50-389/83-59 on 830830-0902 No noncompliance noted. Major areas inspected health physics instruments & equipment, QC audits, thermal shield disposal practices & actions on previous inspector followup items
 WRAY, J R Region 2, Office of Director BARR, K P, Division of
 Engineering & Operational Programs, 83/09/23 5pp 20900 169
 24X Fiche 50-335, 83/09/27, 8310250615

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o ICFR50 59 Evaluation." Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/09/29 Consolidated Edison Co of New
 York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310250400 Forwards IE Insp Repts 50-335/83-30 & 50-389/83-58 on 830829-0902 No noncompliance noted
 DANCE, H C Division of Project & Resident Programs 83/10/05
 UHRIG, R E Florida Power & Light Co 2pp 20897 256 24X
 Fiche 50-335, 83/10/05, 8310250400

--8310250409 IE Insp Repts 50-335/83-30 & 50-389/83-58 on 830829-0902 No noncompliance noted. Major areas inspected changed to emergency preparedness program, shift staffing & augmentation & dose calculations & assessments
 HUFFMAN, O N, STODDART, P G Region 2, Office of Director
 JENKINS, G R Division of Engineering & Operational Programs
 83/09/30 10pp 20897 258 24X Fiche 50-335, 83/10/05, 8310250400

8310130153 Forwards "Inservice Test Program for Pumps & Valves" & Rev D to PNS-C10 Document 002-10, "Inservice Insp, First 10-Yr Plan." Vols 1 & 2
 UHRIG, R E Florida Power & Light Co 83/10/06 EISENHUT, D O
 Division of Licensing 1p 20717 159 24X Fiche 50-389, 83/10/06, 8310130153

--8310130154 "Inservice Test Program for Pumps & Valves, St Lucie Unit." *
 * Florida Power & Light Co 83/10/06 129pp 20717 160 24X
 Fiche 50-389, 83/10/06, 8310130153

--8310130157 Rev D to PNS-C10 Document 002-10, "Inservice Insp, First 10-Yr Plan." Vols 1 & 2
 HEYCOCK, P W, GUTCH, G, PADUANO, H N Florida Power & Light Co
 83/10/03 550pp 20717 288 24X Fiche 50-389, 83/10/06, 8310130153

8310250516 Forwards IE Insp Repts 50-335/83-28 & 50-389/83-55 on 830711-0810 No noncompliance noted
 DANCE, H C Division of Project & Resident Programs 83/10/06
 UHRIG, R E Florida Power & Light Co 2pp 20901 310 24X
 Fiche 50-335, 83/10/06, 8310250516

--8310250528 IE Insp Repts 50-335/83-28 & 50-389/83-55 on 830711-0810 No noncompliance noted. Major areas inspected maint & surveillance observation, plant operations, IE bulletins, circulars & info notices, LERs & startup testing
 ELROD, S A, BIBB, H E, LANDIS, K Region 2, Office of Director
 83/10/04 11pp 20901 312 24X Fiche 50-335, 83/10/06, 8310250516

8308300378 IE Info Notice 83-65, "Surveillance of Flow in R10 Bypass Loops Used in Westinghouse Plants." Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/10/07 Consolidated Edison Co of New
 York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility." Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/10/07 Consolidated Edison Co of New
 York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Mntl Defect Causes Production of Noxious Gases." Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/10/11 Consolidated Edison Co of New
 York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders." Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/10/11 Consolidated Edison Co of New
 York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

R Periodic operating reports & related correspondence

8310190023 Monthly operating repts for Aug 1983 W/830915 ltr
 GRANT, N W Florida Power & Light Co 83/09/15 Office of
 Resource Management, Director 17pp 20822 017 24X
 Fiche 50-000, 83/09/15, 8310190023

DOCKETED ITEMS

269

S Reportable occurrences, LERs & related correspondence

8310030398 LER 83-050/03L-0 on 830822, during power operation, train A & B containment particulate iodine & gaseous monitors inoperable. Caused by filter paper stuck on instrument sensor. Papers freed from sensors & realigned W/830920 ltr. ROTELLA, T S, WILLIAMS, J W Florida Power & Light Co 83/09/20
O'REILLY, J P Region 2, Office of Director 2pp 20592 350 24X
Fiche 50-389, 83/09/20, 8310030398

8310030448 LER 83-051/03L-0 on 830822, instrument FT 3306 train A shutdown cooling flow failed. Cause unknown. Calibr checks made of associated sigma & controller FT-3306 valved out & back into svc W/830921 ltr. ROTELLA, T S, WILLIAMS, J W Florida Power & Light Co 83/09/21
O'REILLY, J P Region 2, Office of Director 2pp 20602 032 24X
Fiche 50-389, 83/09/21, 8310030448

8310030254 LER 83-049/01T-0 on 830911, while performing valve lineup checks for startup, svc air containment isolation valves V28794 & V18796 found open. Caused by personnel error. Valves shut W/830926 ltr. WILLIAMS, J W, PARKS, B Florida Power & Light Co 83/09/26
O'REILLY, J P Region 2, Office of Director 2pp 20591 062 24X
Fiche 50-389, 83/09/26, 8310030254

8310140217 Suppl to Final Deficiency Rept 82-014 re malfunctioning shutdown cooling sys HX bypass valves. Valves will be replaced w/conventional limit torque operators prior to startup from first refueling. UHRIOR, R E Florida Power & Light Co 83/10/06
O'REILLY, J P Region 2, Office of Director 1p 20761 189 24X
Fiche 50-389, 83/10/06, 8310140217

8310250060 LER 83-056/03L-0 on 830907, w/shutdown cooling (SDC) train 2H in operation, SDC train 2A in injection mode & loop B reactor coolant pumps inoperable, loop A pumps made inoperable. Caused by erroneously racking out pumps W/831007 ltr. BRAWNIN, J P, WILLIAMS, J W Florida Power & Light Co 83/10/07
O'REILLY, J P Region 2, Office of Director 2pp 20894 174 24X
Fiche 50-389, 83/10/07, 8310250060

8310250039 LER 83-055/03L-0 on 830910, wide range nuclear instrumentation C failed. On 830912, channel D failed. Caused by failure of decade dividers in log counter cards. Parts replaced W/831010 ltr. PARKS, B M, WILLIAMS, J M Florida Power & Light Co 83/10/10
O'REILLY, J P Region 2, Office of Director 2pp 20894 087 24X
Fiche 50-389, 83/10/10, 8310250039

8310250337 LER 83-053/03L-0 on 830909, while in hot shutdown, containment pressure exceeded 0.4 psig limit. Caused by heat & high pressure. Pressure released by purge after obtaining waste gas release permit. PARKS, B M, WILLIAMS, J W Florida Power & Light Co 83/10/10
O'REILLY, J P Region 2, Office of Director 2pp 20898 024 24X
Fiche 50-389, 83/10/10, 8310250337

8310190104 LER 83-058/03L-0 on 830914, during 100% power, fire doors found open. Caused by const activities. Continuous fire patrol watch observed since startup W/831013 ltr. MCCLAUGHLIN, L, WILLIAMS, J W Florida Power & Light Co 83/10/13
O'REILLY, J P Region 2, Office of Director 2pp 20822 110 24X
Fiche 50-389, 83/10/13, 8310190104

DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8310030076 Concurs w/dissolution of Model D2/D3 Steam Generator Util Design Review Panel. Panel work complete. NOVAK, T M Assistant Director for Licensing 83/09/23
BLACKLEY, S K Design Review Panel 5pp 20650 165 24X
Fiche 50-000, 83/09/23, 8310030076

8310170031 Forwards procedures & protocol to be followed by util, Black & Veatch & NRC re completion of review & evaluation of independent review of facility auxiliary feedwater sys. NOVAK, T M Assistant Director for Licensing 83/09/30
PARRIS, H Q Tennessee Valley Authority 5pp 20798 337 24X
Fiche 50-390, 83/09/30, 8310170031

8310170725 Forwards request for addl info re environ equipment qualification program, based on util 830819 environ qualification rept. Response requested by 831017. ADENSAH, E Q Licensing Branch 4 83/10/04
PARRIS, H Q Tennessee Valley Authority 9pp 20798 074 24X
Fiche 50-390, 83/10/04, 8310170725

8310140224 Provides info supporting util decision not to install safety-grade manual switches in main control room for closure of isolation valves in upper head injection sys. MILLS, L M Tennessee Valley Authority 83/10/11
ADENSAH, E Licensing Branch 4 4pp 20761 175 24X
Fiche 50-390, 83/10/11, 8310140224

8310180388 Requests that latest fuel load dates specified in CPR-91 & CPR-92 be extended to Jan & Jul 1985, respectively. Addl work required prior to projected fuel load dates listed. MILLS, L M Tennessee Valley Authority 83/10/11
ADENSAH, E Licensing Branch 4 2pp 20803 213 24X
Fiche 50-390, 83/10/11, 8310180388

8310210023 Forwards util 831003 ltr to J Robinson of Black & Veatch re independent review program personal svcs contract ltr forwarded in keeping w/protocol for handling program, per TM Novak 830930 ltr. KAMMER, D S Tennessee Valley Authority 83/10/14
ADENSAH, E Licensing Branch 4 5pp 20853 338 24X
Fiche 50-390, 83/10/14, 8310210023

8310250034 Notifies of 831025 meeting in Knoxville, TN to discuss TVA procedures for controlling & implementing corrective action on Black & Veatch findings re auxiliary feedwater sys independent review. MILLS, L M Tennessee Valley Authority 83/10/18
ADENSAH, E Q Licensing Branch 4 1p 20897 271 24X
Fiche 50-390, 83/10/18, 8310250034

8310280173 Forwards latest response to NUREG-0737, Item II D 3: "Direct Indication of Relief & Safety Valve Position," reflecting as-installed location of acoustic monitoring sys accelerometer. MILLS, L M Tennessee Valley Authority 83/10/24
ADENSAH, E Licensing Branch 4 2pp 20929 006 24X
Fiche 50-390, 83/10/24, 8310280173

E NRC Safety Evaluation Report (SER), suppls & correspondence

8310210301 Forwards Drawings 47W600-26 & 47W600-27, depicting addl two sensor location changes per SER Confirmatory Item P3. MILLS, L M Tennessee Valley Authority 83/10/18
ADENSAH, E Licensing Branch 4 4pp 20831 057 24X
Fiche 50-390, 83/10/18, 8310210301

F Security, medical, emergency & fire protection plans

8310250367 Supple response to NRC 820827 ltr re deviations noted in IE Insp Repts 50-390/82-29 & 50-391/82-26. Guidance defining fire protection GA boundaries delayed, delaying completion of drawing rev effort & GA verification. KAMMER, D S Tennessee Valley Authority 83/07/25
O'REILLY, J P Region 2, Office of Director 1p 20898 086 24X
Fiche 50-390, 83/07/25, 8310250367

8310040452 Submits central emergency control ctr meteorological data availability statistics for Apr-June 1983. Data availability repts will be discontinued due to consistently high data availability through previous rent periods. MILLS, L M Tennessee Valley Authority 83/09/28
ADENSAH, E Licensing Branch 4 2pp 20623 326 24X
Fiche 50-000, 83/09/28, 8310040452

8310040402 Forwards results of preliminary lighting survey for main control room, per 830727 request & NUREG-0700. MILLS, L M Tennessee Valley Authority 83/09/29
ADENSAH, E Licensing Branch 4 2pp 20617 352 24X
Fiche 50-390, 83/09/29, 8310040402

8310250303 Forwards IE Insp Repts 50-390/83-34 & 50-391/83-23 on 830906-09. No noncompliance noted. VERRELLI, D M Division of Project & Resident Programs 83/09/29.
PARRIS, H Q Tennessee Valley Authority 2pp 20895 322 24X
Fiche 50-390, 83/09/29, 8310250303

--8310250304 IE Insp Repts 50-390/83-34 & 50-391/83-23 on 830906-09. No noncompliance noted. Major areas inspected licensee readiness for emergency preparedness appraisal. CLINE, W E, KREH, J L Region 2, Office of Director JENKINS, O R Division of Emergency Preparedness & Materials Safety 83/09/28
7pp 20895 324 24X
Fiche 50-390, 83/09/29, 8310250303

8310180315 Forwards response to 830325 request for addl info re 10CFR50 App R info includes color-coded line drawings demonstrating compliance w/Section 111 Q & L & degree of separation for equipment inside containment. KAMMER, D S Tennessee Valley Authority 83/10/12
ADENSAH, E Licensing Branch 4 22pp 20806 244 24X
Fiche 50-390, 83/10/12, 8310180315

DOCKETED ITEMS

J Insurance & indemnity information

8310140130 Forwards secondary financial protection certificates to NELIA Policy M-80 & MAELU Policy M-80
 DUCK, J R Marsh & McLennan, Inc 83/10/03 SALTZMAN, J Assistant Director for State & License Relations 13pp 20763 343 24X
 Fiche 50-390, 83/10/03, 8310140130

G Inspection reports, IE Bulletins & correspondence

8310250367 Suppls response to NRC 820827 ltr re deviations noted in II Insp Repts 50-390/82-29 & 50-391/82-26 Guidance defining fire protection QA boundaries delayed, delaying completion of drawing rev effort & QA verification
 KAMMER, D S Tennessee Valley Authority 83/07/25 O'REILLY, J P Region 2, Office of Director 1p 20898 086 24X
 Fiche 50-390, 83/07/25, 8310250367

8310040140 Forwards IE Insp Rept 50-390/83-31 on 830817-19 No noncompliance noted
 VERRELLI, D M Division of Project & Resident Programs 83/09/09
 PARRIS, H Q Tennessee Valley Authority 2pp 20608 013 24X
 Fiche 50-390, 83/09/09, 8310040140

--8310040147 IE Insp Rept 50-390/83-31 on 830817-19 No noncompliance noted Major areas inspected exam of installed supports & restraints, piping vibration program & followup on outstanding items
 WHITENER, H L, JAFE, F Region 2, Office of Director 83/09/07 3pp 20608 015 24X Fiche 50-390, 83/09/09, 8310040140

8310040423 Forwards IE Insp Repts 50-390/83-29 & 50-391/83-20 on 830815-19 No noncompliance noted
 VERRELLI, D M Division of Project & Resident Programs 83/09/12
 PARRIS, H Q Tennessee Valley Authority 10pp 20619 127 24X
 Fiche 50-390, 83/09/12, 8310040423

--8310040427 IE Insp Repts 50-390/83-29 & 50-391/83-20 on 830815-19 No noncompliance noted Major areas inspected licensee action on previous enforcement matters, independent insp effort, IE Bulletin 79-14 & inspector followup items
 YORK, M Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/09/08 10pp 20619 129 24X Fiche 50-390, 83/09/12, 8310040423

8310040555 Forwards IE Insp Repts 50-390/83-33 & 50-391/83-22 on 830822-0826 No noncompliance noted
 VERRELLI, D M Division of Project & Resident Programs 83/09/12
 PARRIS, H Q Tennessee Valley Authority 5pp 20622, 160 24X
 Fiche 50-390, 83/09/12, 8310040555

--8310040563 IE Insp Repts 50-390/83-33 & 50-391/83-22 on 830822-26 No noncompliance noted Major areas inspected preoperational test procedure review & results & review & followup on previously identified insp findings
 THOMAS, M Region 2, Office of Director JAFE, F Division of Engineering & Operational Programs 83/09/07 5pp 20622, 162 24X Fiche 50-390, 83/09/12, 8310040555

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340.

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342.

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays." Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310250303 Forwards IE Insp Repts 50-390/83-34 & 50-391/83-23 on 830906-09 No noncompliance noted.
 VERRELLI, D M Division of Project & Resident Programs 83/09/29
 PARRIS, H Q Tennessee Valley Authority 2pp 20895 322 24X
 Fiche 50-390, 83/09/29, 8310250303

--8310250304 IE Insp Repts 50-390/83-34 & 50-391/83-23 on 830906-09 No noncompliance noted Major areas inspected licensee readiness for emergency preparedness appraisal
 CLINE, W E, KREH, J L Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/09/28 7pp 20895 324 24X Fiche 50-390, 83/09/29, 8310250303

8310250397 Forwards IE Insp Repts 50-390/83-36 & 50-391/83-25 on 830912-16 No noncompliance noted
 VERRELLI, D M Division of Project & Resident Programs 83/10/04
 PARRIS, H Q Tennessee Valley Authority 2pp 20897 191 24X
 Fiche 50-390, 83/10/04, 8310250397

--8310250406 IE Insp Repts 50-390/83-36 & 50-391/83-25 on 830912-16 No noncompliance noted Major areas inspected licensee action on previous enforcement matters & 10CFR21 reportability
 MCFARLAND, C R Region 2, Office of Director UPRIGHT, C M Division of Engineering & Operational Programs 83/09/29 4pp 20897 193 24X Fiche 50-390, 83/10/04, 8310250397

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

S Reportable occurrences, LERs & related correspondence

8310030214 Second interim deficiency rept re seismic analysis of north steam valve room initially reported on 830502 Natural frequencies not used resulting in clipping peaks of response spectra Reanalysis performed incorporating deficiencies
 MILLS, L M Tennessee Valley Authority 83/09/21 O'REILLY, J P Region 2, Office of Director 2pp 20592 321 24X
 Fiche 50-390, 83/09/21, 8310030214

8310030233 Third interim deficiency rept re QA program on Tubeline matl supplied by Capitol Pipe initially reported on 830329 Stop work order issued T-L fittings/flanges not installed in safety-related sys Next rept by 831108
 MILLS, L M Tennessee Valley Authority 83/09/21 O'REILLY, J P Region 2, Office of Director 5pp 20590 343 24X
 Fiche 50-000, 83/09/21, 8310030233

8310030244 Final deficiency rept re offset lead-in guides on Wachter spent fuel cells initially reported on 830318 Engineering Change Notice 4043 issued revising Wachter Assoc. Inc drawings Also reportable per Part 21
 MILLS, L M Tennessee Valley Authority 83/09/21 O'REILLY, J P Region 2, Office of Director 2pp 20591 069 24X
 Fiche 50-390, 83/09/21, 8310030244

8310030252 Supplemental final deficiency rept re main control room habitability Initially reported on 830305 Corrective action in 830906 ltr applicable to Watts Bar only
 MILLS, L M Tennessee Valley Authority 83/09/21 O'REILLY, J P Region 2, Office of Director 1p 20592 310 24X
 Fiche 50-390, 83/09/21, 8310030252

8310030257 First interim deficiency rept re broken pin carrier plate on ERCW motors mfg by Siemens-Alis initially reported on 830824 Vendor in process of determining max loading applied to bushings Also reportable per Part 21
 MILLS, L M Tennessee Valley Authority 83/09/21 O'REILLY, J P Region 2, Office of Director 2pp 20591 060 24X
 Fiche 50-390, 83/09/21, 8310030257

8310030338 Second interim deficiency rept re inaccurate results from ANCHORS computer program initially reported on 830329 Problems reanalyzed using Version 2 issued 830506 Users manual revised Next rept expected by 831231
 MILLS, L M Tennessee Valley Authority 83/09/21 O'REILLY, J P Region 2, Office of Director 2pp 20590 303 24X
 Fiche 50-390, 83/09/21, 8310030338

DOCKETED ITEMS

271

- 8310030388 Second interim deficiency rept re QA program for personal svc contract Initially reported on 830406 Controlled copies of engineering procedures sent to Gilbert Assoc Next rept expected by 831014
MILLS,L M Tennessee Valley Authority 83/09/21 O'REILLY,J P
Region 2, Office of Director 2pp 20592 139 24X
Fiche 50-000,83/09/21,8310030388
- 8310030399 Third interim deficiency rept re incorrect use of Category I(L) supports on pipes near water chillers Initially reported on 830117 Shielding structures being designed to protect chillers Next rept expected by 831017
MILLS,L M Tennessee Valley Authority 83/09/21 O'REILLY,J P
Region 2, Office of Director 2pp 20593 075 24X
Fiche 50-390,83/09/21,8310030399
- 8310030404 First interim deficiency rept re fire dampers not adequately shown on design typical drawings Initially reported on 830824 Clearances between fire damper & embedded sleeve will be inspected Next rept expected by 831006
MILLS,L M Tennessee Valley Authority 83/09/21 O'REILLY,J P
Region 2, Office of Director 2pp 20602 217 24X
Fiche 50-390,83/09/21,8310030404
- 8310030424 Third interim deficiency rept re failure to provide bolt tightening requirements Initially reported on 830120 Requirements provided in general note drawings, structural drawings & manufacturers installation procedures
MILLS,L M Tennessee Valley Authority 83/09/22 O'REILLY,J P
Region 2, Office of Director 2pp 20593 178 24X
Fiche 50-390,83/09/22,8310030424
- 8310030473 Final deficiency rept for Unit 1 & fourth interim deficiency rept for Unit 2 re use of digitized response spectra data Initially reported on 820422 Engineering Change Notice 3491 issued to revise drawings Next rept expected by 840630
MILLS,L M Tennessee Valley Authority 83/09/22 O'REILLY,J P
Region 2, Office of Director 3pp 20601 061 24X
Fiche 50-390,83/09/22,8310030473
- 8310030506 Revised final deficiency rept re sheared motor pinion keys in Limitorque motor operators Initially reported on 820830 Condition only applies to Watts Bar Keys will be replaced by 840201 Also reportable per Part 21
MILLS,L M Tennessee Valley Authority 83/09/22 O'REILLY,J P
Region 2, Office of Director 3pp 20601 194 24X
Fiche 50-000,83/09/22,8310030506
- 8310030519 Final deficiency rept re failure to evaluate operator actions to realign ERCW train A Initially reported on 820510 Analysis revealed that sys able to deliver design flow to all loads during 10 minutes following DGA
MILLS,L M Tennessee Valley Authority 83/09/22 O'REILLY,J P
Region 2, Office of Director 2pp 20601 201 24X
Fiche 50-390,83/09/22,8310030519
- 8310030538 Final deficiency rept re incorrect max pipe movements contained in TPIPE program Initially reported on 830504 Response spectrum utilized in analyzing earthquake effect results in conservative displacements
MILLS,L M Tennessee Valley Authority 83/09/22 O'REILLY,J P
Region 2, Office of Director 3pp 20601 207 24X
Fiche 50-000,83/09/22,8310030538
- 8310030365 Final deficiency rept re Meriam Instruments orifice plates described in QA program Initially reported on 830510 No safety-related plates mfg for util since subj audit Util will verify implementation of QA
MILLS,L M Tennessee Valley Authority 83/09/23 O'REILLY,J P
Region 2, Office of Director 3pp 20592 327 24X
Fiche 50-390,83/09/23,8310030365
- 8310030370 Final interim deficiency rept re diesel generator electrical equipment temp rating Initially reported on 820601 Engineering change notice issued Ventilation sys can maintain acceptable temp in electrical equipment
MILLS,L M Tennessee Valley Authority 83/09/23 O'REILLY,J P
Region 2, Office of Director 2pp 20592 195 24X
Fiche 50-390,83/09/23,8310030370
- 8310030436 First interim deficiency rept re calculation of support design loads in TPIPE Initially reported on 830714 Procedure developed allowing recomputation of design loads near localized phenomena by hand Next rept by 831220
MILLS,L M Tennessee Valley Authority 83/09/23 O'REILLY,J P
Region 2, Office of Director 2pp 20602 095 24X
Fiche 50-000,83/09/23,8310030436
- 8310030462 Final deficiency rept re heat loss from Power Sys diesels Initially reported on 820729 Heat loss tests performed on 821120 & 830223 confirmed temps near safety-related equipment exceeded limits Also reportable per Part 21
MILLS,L M Tennessee Valley Authority 83/09/23 O'REILLY,J P
Region 2, Office of Director 3pp 20601 049 24X
Fiche 50-390,83/09/23,8310030462
- 8310040180 Final deficiency rept re lack of evidence that auxiliary feedwater pump components meet ASME Class 3 or TVA Class C code requirements Initially reported on 820330 Drawings revised to identify piping & components properly
MILLS,L M Tennessee Valley Authority 83/09/27 O'REILLY,J P
Region 2, Office of Director 2pp 20608 265 24X
Fiche 50-390,83/09/27,8310040180
- 8310040544 Final deficiency rept re transfer switches to auxiliary feedwater sys having nondivisional power Initially reported on 830202 Caused by design oversight Engineering change notices issued & design mods made.
MILLS,L M Tennessee Valley Authority 83/09/27 O'REILLY,J P
Region 2, Office of Director 3pp 20623 251 24X
Fiche 50-390,83/09/27,8310040544
- 8310040138 Final deficiency rept re improper classification of ERCW sys piping & components Initially reported on 810324 Components & drawings will be revised to show correct classification of HVAC equipment by 831115
MILLS,L M Tennessee Valley Authority 83/09/28 O'REILLY,J P
Region 2, Office of Director 3pp 20608 008 24X
Fiche 50-390,83/09/28,8310040138
- 8310040193 Final & second interim deficiency repts for Units 1 & 2, respectively re high pressure fire protection sys piping water danger to shutdown board transformers after postulated earthquake Initially reported on 830616
MILLS,L M Tennessee Valley Authority 83/09/28 O'REILLY,J P
Region 2, Office of Director 3pp 20608 103 24X
Fiche 50-390,83/09/28,8310040193
- 8310040549 First interim Deficiency Rept NRC W-138-P re failure of pressurizer level transmitters to cover process range. Initially reported on 830829 Expected disposition will be new caliber span Next rept will be submitted by 840106
MILLS,L M Tennessee Valley Authority 83/09/28 O'REILLY,J P
Region 2, Office of Director 2pp 20623 249 24X
Fiche 50-390,83/09/28,8310040549
- 8310060009 Final deficiency rept re support welds not inspected or documented Initially reported on 830711 List developed of supports requiring weld insp Welds will be inspected & reworked if necessary by 831130
MILLS,L M Tennessee Valley Authority 83/09/29 O'REILLY,J P
Region 2, Office of Director 2pp 20647 243 24X
Fiche 50-390,83/09/29,8310060009
- 8310060016 Final deficiency rept re valve position indication problems w/END gate valves Initially reported on 830203 Westinghouse equipment engineers provided w/instructions re valve function Also reportable under Part 21
MILLS,L M Tennessee Valley Authority 83/09/29 O'REILLY,J P
Region 2, Office of Director 2pp 20648 354 24X
Fiche 50-390,83/09/29,8310060016
- 8310060027 Final deficiency rept re containment spray miniflow valve design error Initially reported on 820305 Westinghouse internal design assurance & verification procedures revised Also reportable under Part 21
MILLS,L M Tennessee Valley Authority 83/09/29 O'REILLY,J P
Region 2, Office of Director 2pp 20647 091 24X
Fiche 50-390,83/09/29,8310060027
- 8310060008 Second interim deficiency rept re diesel generator rear bearing problem Initially reported on 830627 Generator repaired Bearing assembly dimensions will be examined to determine presence of out-of-tolerance parts
MILLS,L M Tennessee Valley Authority 83/09/30 O'REILLY,J P
Region 2, Office of Director 2pp 20647 241 24X
Fiche 50-390,83/09/30,8310060008
- 8310060087 Final deficiency rept re review & updating of piping drawings. Initially reported on 820621 Design Criteria Document WS-DC-40-31 3 revised to add Section 4 3 requiring mod to assure piping has been updated
MILLS,L M Tennessee Valley Authority 83/09/30 O'REILLY,J P
Region 2, Office of Director 3pp 20648 335 24X
Fiche 50-390,83/09/30,8310060087
- 8310060095 Final deficiency rept for Unit 1 & fifth interim deficiency rept for Unit 2 re discrepancies in support details Initially reported on 820302 & 830311, respectively Revs to support drawings will be issued by 840103
MILLS,L M Tennessee Valley Authority 83/09/30 O'REILLY,J P
Region 2, Office of Director 4pp 20648 338 24X
Fiche 50-390,83/09/30,8310060095
- 8310060331 Final & eighth interim deficiency repts for Watts Bar & Bellefonte, respectively re inconsistent establishment of insp program Initially reported on 810324 Requirements, control & use of const requirements manual developed
MILLS,L M Tennessee Valley Authority 83/09/30 O'REILLY,J P
Region 2, Office of Director 4pp 20641 001 24X
Fiche 50-000,83/09/30,8310060331

DOCKETED ITEMS

8310060342 Final deficiency rept re steam generator lower support bolts Initially reported on B20610 Rehrat treatments provide adequate strength at operating temp, sufficient fracture toughness & crack resistance Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 83/09/30 O'REILLY, J P
Region 2, Office of Director 3pp 20646-077 24X
Fiche 50-390, 83/09/30, 8310060342

8310060436 Final deficiency rept re failure of safety-related Westinghouse gate valves Initially reported on B01031 All affected valves modified & applicable drawings revised
MILLS, L M Tennessee Valley Authority 83/09/30 O'REILLY, J P
Region 2, Office of Director 2pp 20641 227 24X
Fiche 50-390, 83/09/30, 8310060436

8310060476 Fifth interim deficiency rept re setpoint program for overpressure mitigation sys Initially reported on B20521 Util conducted PORV response time tests Next rept expected by B40103 Also reportable under Part 21
MILLS, L M Tennessee Valley Authority 83/09/30 O'REILLY, J P
Region 2, Office of Director 2pp 20641 017 24X
Fiche 50-390, 83/09/30, 8310060476

8310060488 Final & third interim deficiency repts for Units 1 & 2, respectively re postulated accident blowdown of more than one steam generator Initially reported on B21015 Power supply to steam generator PORV rearranged
MILLS, L M Tennessee Valley Authority 83/09/30 O'REILLY, J P
Region 2, Office of Director 2pp 20641-015 24X
Fiche 50-390, 83/09/30, 8310060488

8310070301 Potential Part 21 rept re underrange characteristic of Model N-E110M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN, M. J. Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 1pp 20651 064 24X
Fiche 50-000, 83/09/30, 8310070301

8310120236 Final deficiency rept re incorrectly installed pressurizer instrument line Initially reported on B30727 Engineering Change Notice 4249 issued to correct Control Diagram 47W610-6B-5 R9 Hardware corrections completed by B31130
MILLS, L M Tennessee Valley Authority 83/10/03 O'REILLY, J P
Region 2, Office of Director 2pp 20692 170 24X
Fiche 50-390, 83/10/03, 8310120236

8310120237 Final deficiency rept re ambiguous outputs from Barton pressure transmitters in RCB Initially reported on B30409 Addl RCB transmitters installed outside containment. Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 83/10/03 O'REILLY, J P
Region 2, Office of Director 3pp 20692 172 24X
Fiche 50-390, 83/10/03, 8310120237

8310120332 Final deficiency rept re excessive movement of containment penetration bellows Initially reported on B11204 Analysis determined that bellow movement may exceed 0.224-inch lateral displacement. Engineering change notice initiated
MILLS, L M Tennessee Valley Authority 83/10/03 O'REILLY, J P
Region 2, Office of Director 3pp 20699 272 24X
Fiche 50-390, 83/10/03, 8310120332

8310120396 Final & fourth interim deficiency rept for Units 1 & 2, respectively re control of civil engineering support branch analysis calculations Initially reported on B20823 Flange qualification requirements incorporated into checklist
MILLS, L M Tennessee Valley Authority 83/10/03 O'REILLY, J P
Region 2, Office of Director 2pp 20700 197 24X
Fiche 50-390, 83/10/03, 8310120396

8310120100 Final & seventh interim deficiency repts for Units 1 & 2, respectively re piping sys analysis & pipe support design efforts for Class 1, 2 & 3 sys Initially reported on B01217 All Unit 1 supports designed for current loads
MILLS, L M Tennessee Valley Authority 83/10/04 O'REILLY, J P
Region 2, Office of Director 2pp 20694 180 24X
Fiche 50-390, 83/10/04, 8310120100

8310120336 Final deficiency rept re questionable patches of plastic cement mortar Initially reported on B20429 Sampling of expansion anchored supports proved adequacy of supports item not reportable per 10CFR50.55(e)
MILLS, L M Tennessee Valley Authority 83/10/04 O'REILLY, J P
Region 2, Office of Director 3pp 20699 279 24X
Fiche 50-390, 83/10/04, 8310120336

8310120389 Final & sixth interim deficiency repts for Units 1 & 2, respectively re discrepancies in as-built vs as-analyzed piping sys Initially reported on B10226 Support locations evaluated All Unit 1 rework will be completed by B31201
MILLS, L M Tennessee Valley Authority 83/10/04 O'REILLY, J P
Region 2, Office of Director 4pp 20699 128 24X
Fiche 50-390, 83/10/04, 8310120389

8310140048 Final deficiency rept re mass of HVAC supports not included in frequency calculations Initially reported on B30809 Designs revised Field rework & support work will be completed by B40101
MILLS, L M Tennessee Valley Authority 83/10/05 O'REILLY, J P
Region 2, Office of Director 2pp 20768 272 24X
Fiche 50-390, 83/10/05, 8310140048

8310140017 Second interim rept re pump motors supplied w/o seismic analysis or operability demonstration Initially reported on B30428 Addl info received from Westinghouse but analysis not completed Next rept expected by B31230
MILLS, L M Tennessee Valley Authority 83/10/06 O'REILLY, J P
Region 2, Office of Director 2pp 20767 027 24X
Fiche 50-390, 83/10/06, 8310140017

8310170264 Second interim deficiency rept re routing of radioactive & nonradioactive sys instrument lines Initially reported on B30729 Engineering Change Notice 4287 initiated to remove instrument lines Next rept expected by B31221
MILLS, L M Tennessee Valley Authority 83/10/06 O'REILLY, J P
Region 2, Office of Director 1p 20787 100 24X
Fiche 50-390, 83/10/06, 8310170264

8310210096 Final rept re QA program deficiencies in Gilbert Assoc personal svcs contract Initially reported on B30406 Specific problems not identified by audit items not reportable per 10CFR50.55(e)
MILLS, L M Tennessee Valley Authority 83/10/12 O'REILLY, J P
Region 2, Office of Director 4pp 20858 197 24X
Fiche 50-000, 83/10/12, 8310210096

8310250378 Final deficiency rept re supports not designed or modified as required by Engineering Change Notice 2576 Initially reported on B30118 Support designs reviewed Design mods will be completed by B31230
MILLS, L M Tennessee Valley Authority 83/10/12 O'REILLY, J P
Region 2, Office of Director 2pp 20898 137 24X
Fiche 50-390, 83/10/12, 8310250378

8310190089 Final deficiency rept re discrepancy in interface coordination of design review process Initially reported on B10717 Finding of coordination problem not significant & should not have been reported to NRC per 10CFR50.55(e)
MILLS, L M Tennessee Valley Authority 83/10/13 O'REILLY, J P
Region 2, Office of Director 3pp 20818 132 24X
Fiche 50-000, 83/10/13, 8310190089

8310190224 Final deficiency rept re design review failure to verify accuracy & adequacy of design documents Initially reported on B12115 Listed changes to design review process will be implemented by B40101
MILLS, L M Tennessee Valley Authority 83/10/13 O'REILLY, J P
Region 2, Office of Director 3pp 20818 045 24X
Fiche 50-000, 83/10/13, 8310190224

8310210011 Final deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on B50120 New requirements for assessing piping vibration problems during preoperational testing requirements issued
MILLS, L M Tennessee Valley Authority 83/10/13 O'REILLY, J P
Region 2, Office of Director 3pp 20855 345 24X
Fiche 50-000, 83/10/13, 8310210011

8310210015 First interim deficiency rept re support for test lines by alternate analysis Initially reported on B30919 Existing support structure being analyzed to determine if mods necessary for DBA loadings Next rept by B31205
MILLS, L M Tennessee Valley Authority 83/10/13 O'REILLY, J P
Region 2, Office of Director 2pp 20858 261 24X
Fiche 50-390, 83/10/13, 8310210015

8310210042 Supplemental deficiency rept re sensing of pipe breaks in component cooling sys. Initially reported on B30624 Typographical error identified in B30709 final rept Engineering change notice number should be 4253, not 4235
MILLS, L M Tennessee Valley Authority 83/10/13 O'REILLY, J P
Region 2, Office of Director 1p 20858 317 24X
Fiche 50-390, 83/10/13, 8310210042

DOCKETED ITEMS

273

8310210049 Revised final deficiency rept re voiding of engineering change notices (ECNs) w/o proper review Initially reported on 820816 Sections in EN DES-EP 4 02 addressing voiding of ECNs changed in Rev 12, issued on 830203
MILLS, L M Tennessee Valley Authority 83/10/13 O'REILLY, J P
Region 2, Office of Director 2pp 20055 304 24X
Fiche 50-390, 83/10/13, 8310210049

8310210068 Final deficiency rept for Unit 1 & third interim deficiency rept for Unit 2 re loose matl in steam generator Initially reported on 830325 Caused by lack of work controls Also reportable per Part 21 Next rept due by 840706
MILLS, L M Tennessee Valley Authority 83/10/13 O'REILLY, J P
Region 2, Office of Director 4pp 20857 270 24X
Fiche 50-390, 83/10/13, 8310210068

8310190127 First interim deficiency rept re shorted indicating lights in Westinghouse panels Initially reported on 830915 Westinghouse provided trained wiring separation procedure & wiring sketch Next rept expected by 831215
MILLS, L M Tennessee Valley Authority 83/10/14 O'REILLY, J P
Region 2, Office of Director 2pp 20821 128 24X
Fiche 50-390, 83/10/14, 8310190127

8310250371 Final deficiency rept for Unit 1 & interim rept for Unit 2 re alternately analyzed piping Verification of all Unit 1 piping carried out by personal svcs contractor & util div of engineering design
MILLS, L M Tennessee Valley Authority 83/10/14 O'REILLY, J P
Region 2, Office of Director 10pp 20898 044 24X
Fiche 50-390, 83/10/14, 8310250371

8310250012 Supplemental final deficiency rept re corrosion in high pressure fire protection sys Corrective action will be completed by 831230, per 830930 telcon Vendor matl for const rework will not arrive onsite to support original schedule
MILLS, L M Tennessee Valley Authority 83/10/17 O'REILLY, J P
Region 2, Office of Director 1p 20894 183 24X
Fiche 50-390, 83/10/17, 8310250012

8310250142 Second revised final deficiency rept re cross-trained diesel generator HX inlet valves Initially reported on 830531 Applicable drawings revised to apply diesel start signal to correct valve Corrections completed
MILLS, L M Tennessee Valley Authority 83/10/17 O'REILLY, J P
Region 2, Office of Director 3pp 20896 293 24X
Fiche 50-390, 83/10/17, 8310250142

8310250165 Third interim deficiency rept re spacing & clearance of sprinkler heads in high pressure fire protection sys Initially reported on 830331 Caused by lack of understanding necessity for maintaining adequate spray patterns
MILLS, L M Tennessee Valley Authority 83/10/17 O'REILLY, J P
Region 2, Office of Director 3pp 21094 062 24X
Fiche 50-390, 83/10/17, 8310250165

8310250173 Final & fourth interim deficiency repts for Units 1 & 2, respectively, re incorrect use of Category (IL) supports on pipes near water chillers Initially reported on 830117 New spray shields designed to be installed above water chillers
MILLS, L M Tennessee Valley Authority 83/10/17 O'REILLY, J P
Region 2, Office of Director 4pp 20893 278 24X
Fiche 50-390, 83/10/17, 8310250173

8310250233 Revised final deficiency rept re drawings issued under Engineering Change Notice 2104 w/o adding flexible hose Initially reported on 830314 Procedures revised adding checklist for design review
MILLS, L M Tennessee Valley Authority 83/10/17 O'REILLY, J P
Region 2, Office of Director 2pp 20899 049 24X
Fiche 50-390, 83/10/17, 8310250233

8310270150 Final rept re cable bend radius deficiencies due to use of nonstd fittings Initially reported on 830720 Caused by misinterpretation of specs Task team appointed to identify, evaluate & resolve problems Rework completed
MILLS, L M Tennessee Valley Authority 83/10/18 O'REILLY, J P
Region 2, Office of Director, 3pp, 20925-020 24X
Fiche 50-390, 83/10/18, 8310270150

8310270183 Final deficiency rept re welds on structural steel in main steam valve rooms Initially reported on 830921, Util in process of visually reinspecting 100% of all structural steel welds Corrective action will be completed by 841025
MILLS, L M Tennessee Valley Authority 83/10/18 O'REILLY, J P
Region 2, Office of Director 2pp, 20925 031, 24X
Fiche 50-390, 83/10/18, 8310270183,

8310310148 Revised final deficiency rept for Unit 1 & first interim deficiency rept for Unit 2 re installation of flow switches & sensing lines Initially reported on 830810 Actual rev to drawings will be accomplished by 831028 for Unit 1.
MILLS, L M Tennessee Valley Authority 83/10/19 O'REILLY, J P
Region 2, Office of Director 5pp 20959 014 24X
Fiche 50-390, 83/10/19, 8310310148

8310310320 Final deficiency rept for Unit 1 & fourth interim rept for Unit 2 re improper overlapping analysis techniques Initially reported on 830111 Twenty-nine problems judged unacceptable & reanalyzed to comply w/proper techniques
MILLS, L M Tennessee Valley Authority 83/10/21 O'REILLY, J P
Region 2, Office of Director 3pp 20961 210 24X
Fiche 50-390, 83/10/21, 8310310320

8310310348 Final deficiency rept re Target Rock pressurizer PORVs failure to open Initially reported on 830922 Analyses could not identify cause for compressed rings Valves modified by vendor Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 83/10/21 O'REILLY, J P
Region 2, Office of Director 3pp 20957 074 24X
Fiche 50-390, 83/10/21, 8310310348

DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8310050076 Concurs w/dissolution of Model D2/D3 Steam Generator Util Design Review Panel Panel work complete
NOVAK, T M Assistant Director for Licensing 83/09/23
BLACKLEY, S K Design Review Panel 5pp 20650 165 24X
Fiche 50-000, 83/09/23, 8310050076

8310170725 Forwards request for addl info re environ equipment qualification program based on util 830817 environ qualification rept Response requested by 831017
ADENSAH, E G Licensing Branch 4 83/10/04 PARRIS, H G Tennessee Valley Authority 9pp 20798 074, 24X Fiche 50-390, 83/10/04, 8310170725

8310140224 Provides info supporting util decision not to install safety-grade manual switches in main control room for closure of isolation valves in upper head injection sys
MILLS, L M Tennessee Valley Authority 83/10/11 ADENSAH, E, Licensing Branch 4 4pp 20761 175 24X Fiche 50-390, 83/10/11, 8310140224

8310180388 Requests that latest fuel load dates specified in CPFR-91 & CPFR-92 be extended to Jan & Jul 1985, respectively Adtl work required prior to projected fuel load dates listed
MILLS, L M Tennessee Valley Authority 83/10/11 ADENSAH, E, Licensing Branch 4 2pp 20803 213 24X Fiche 50-390, 83/10/11, 8310180388

8310210023 Forwards util 831003 ltr to J Robinson of Black & Veatch re independent review program personal svcs contract ltr forwarded in keeping w/protocol for handling program, per TH Novak 830930 ltr
KAMMER, D S Tennessee Valley Authority, 83/10/14 ADENSAH, E, Licensing Branch 4 5pp 20895 338 24X Fiche 50-390, 83/10/14, 8310210023

8310250034 Notifies of 831025 meeting in Knoxville, TN to discuss TVA procedures for controlling & implementing corrective action on Black & Veatch findings re auxiliary feedwater sys independent review
MILLS, L M Tennessee Valley Authority, 83/10/18 ADENSAH, E, G, Licensing Branch 4 1p 20897 271 24X Fiche 50-390, 83/10/18, 8310250034

8310280173 Forwards latest response to NUREG-0737, Item II D 3, "Direct Indication of Relief & Safety Valve Position," reflecting as-installed location of acoustic monitoring sys accelerometer
MILLS, L M Tennessee Valley Authority 83/10/24, ADENSAH, E, Licensing Branch 4 2pp, 20929, 006 24X Fiche 50-390, 83/10/24, 8310280173

E NRC Safety Evaluation Report (SER), supp & correspondence

8310210301 Forwards Drawings 47W600-26 & 47W600-27, depicting addl two sensor location changes per SER Confirmatory Item 23
MILLS, L M Tennessee Valley Authority, 83/10/18 ADENSAH, E, Licensing Branch 4 4pp 20851, 057 24X Fiche 50-390, 83/10/18, 8310210301

F. Security, medical, emergency & fire protection plans

8310250367 Suppls response to NRC 820827 ltr re deviations noted in IE Insp Repts 50-390/82-29 & 50-391/82-26 Guidance defining fire protection QA boundaries delayed, delaying completion of drawing rev effort & QA verification
KAMMER, D S Tennessee Valley Authority 83/07/25, O'REILLY, J P
Region 2, Office of Director, 1p, 20898, 086 24X
Fiche 50-390, 83/07/25, 8310250367.

DOCKETED ITEMS

8310040452 Submits central emergency control ctr meteorological data availability statistics for Apr-June 1983 Data availability repts will be discontinued due to consistently high data availability through previous rept periods
MILLS, L M Tennessee Valley Authority 83/09/28 ADENSAM, E
Licensing Branch 4 2pp 20623 326 24X Fiche 50-000, 83/09/28, 8310040452

8310040402 Forwards results of preliminary lighting survey for main control room, per 830727 request & NUREG-0700
MILLS, L M Tennessee Valley Authority 83/09/29 ADENSAM, E
Licensing Branch 4 2pp 20617 352 24X Fiche 50-390, 83/09/29, 8310040402

8310250303 Forwards IE Insp Repts 50-390/83-34 & 50-391/83-23 on 830906-09 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/09/29
PARRIS, H O Tennessee Valley Authority 2pp 20895 322 24X
Fiche 50-390, 83/09/29, 8310250303

--8310250304 IE Insp Repts 50-390/83-34 & 50-391/83-23 on 830906-09 No noncompliance noted Major areas inspected licensee readiness for emergency preparedness appraisal
CLINE, W E Region 2, Office of Director 83/09/28 7pp
20895 324 24X Fiche 50-390, 83/09/29, 8310250303

8310180315 Forwards response to 830325 request for addl info re 10CFR50 App R Info includes color-coded line drawings demonstrating compliance w/Section III G & L & degree of separation for equipment inside containment
KAMMER, D S Tennessee Valley Authority 83/10/12 ADENSAM, E
Licensing Branch 4 2pp 20806 244 24X Fiche 50-390, 83/10/12, 8310180315

J Insurance & indemnity information

8310140130 Forwards secondary financial protection certificates to NELA Policy N-80 & MAELU Policy M-80
DUCK, J R Marsh & McLennan, Inc 83/10/03 SALTZMAN, J Assistant
Director for State & License Relations 13pp 20763 343 24X
Fiche 50-390, 83/10/03, 8310140130

G Inspection reports, IE Bulletins & correspondence

8310280367 Suppls response to NRC 820827 ltr re deviations noted in IT Insp Repts 50-390/82-29 & 50-391/82-26 Guidance defining fire protection QA boundaries delayed, delaying completion of drawing rev effort & QA verification
KAMMER, D S Tennessee Valley Authority 83/07/25 O'REILLY, J P
Region 2, Office of Director 1p 20898 084 24X
Fiche 50-390, 83/07/25, 8310280367

8310040423 Forwards IE Insp Repts 50-390/83-29 & 50-391/83-20 on 830815-19 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/09/12
PARRIS, H O Tennessee Valley Authority 10pp 20619 127 24X
Fiche 50-390, 83/09/12, 8310040423

--8310040427 IE Insp Repts 50-390/83-29 & 50-391/83-20 on 830815-19 No noncompliance noted Major areas inspected licensee action on previous enforcement matters, independent insp effort, IE Bulletin 79-14 & inspector followup items
YORK, W Region 2, Office of Director, BLAKE, J J Division of Engineering & Operational Programs 83/09/08 10pp 20619:127
24X Fiche 50-390, 83/09/12, 8310040423

8310040555 Forwards IE Insp Repts 50-390/83-33 & 50-391/83-22 on 830822-0826 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/09/12
PARRIS, H O Tennessee Valley Authority 5pp 20622 160 24X
Fiche 50-390, 83/09/12, 8310040555

--8310040563 IE Insp Repts 50-390/83-33 & 50-391/83-22 on 830822-26 No noncompliance noted Major areas inspected preoperational test procedure review & results & review & followup on previously identified insp findings
THOMAS, M Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs 83/09/07 5pp 20622:162
24X Fiche 50-390, 83/09/12, 8310040555

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20776 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310250303 Forwards IE Insp Repts 50-390/83-34 & 50-391/83-23 on 830906-09 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/09/29
PARRIS, H O Tennessee Valley Authority 2pp 20895 322 24X
Fiche 50-390, 83/09/29, 8310250303

--8310250304 IE Insp Repts 50-390/83-34 & 50-391/83-23 on 830906-09 No noncompliance noted Major areas inspected licensee readiness for emergency preparedness appraisal
CLINE, W E, KREN, J L Region 2, Office of Director JENKINS, C R
Division of Emergency Preparedness & Materials Safety 83/09/28
7pp 20895 324 24X Fiche 50-390, 83/09/29, 8310250303

8310250397 Forwards IE Insp Repts 50-390/83-34 & 50-391/83-25 on 830912-16 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/10/04
PARRIS, H O Tennessee Valley Authority 2pp 20897 191 24X
Fiche 50-390, 83/10/04, 8310250397

--8310250406 IE Insp Repts 50-390/83-36 & 50-391/83-25 on 830912-16 No noncompliance noted Major areas inspected licensee action on previous enforcement matters & 10CFR21 reportability
MCFARLAND, C R Region 2, Office of Director UPRIGHT, C M
Division of Engineering & Operational Programs 83/09/29 4pp
20897 193 24X Fiche 50-390, 83/10/04, 8310250397

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

S Reportable occurrences, LERs & related correspondence

8310030214 Second interim deficiency rept re seismic analysis of north steam valve room Initially reported on 830502 Natural frequencies not used resulting in clipping peaks of response spectra Reanalysis performed incorporating deficiencies
MILLS, L M Tennessee Valley Authority 83/09/21 O'REILLY, J P
Region 2, Office of Director 2pp 20592 321 24X
Fiche 50-390, 83/09/21, 8310030214

8310030233 Third interim deficiency rept re QA program on Tubeline matl supplied by Capitol Pipe Initially reported on 830329 Stop work order issued T-L fittings/flanges not installed in safety-related sys Next rept by 831108
MILLS, L M Tennessee Valley Authority 83/09/21 O'REILLY, J P
Region 2, Office of Director 3pp 20590, 343 24X
Fiche 50-000, 83/09/21, 8310030233

8310030244 Final deficiency rept re offset lead-in guides on Wacher spent fuel cells Initially reported on 830318 Engineering Change Notice 4043 issued revising Wacher Assoc Inc drawings Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 83/09/21 O'REILLY, J P
Region 2, Office of Director 2pp 20591 069 24X
Fiche 50-390, 83/09/21, 8310030244

DOCKETED ITEMS

276

8310030252 Supplemental final deficiency rept re main control room habitability Initially reported on 800305 Corrective action in 830906 ltr applicable to Watts Bar only
MILLS,L M Tennessee Valley Authority 83/09/21 O'REILLY,J P
Region 2, Office of Director 1p 20592 310 24X
Fiche 50-390,83/09/21,8310030252

8310030257 First interim deficiency rept re broken pin carrier plates on ERCW motors mfg by Siemens-Allis Initially reported on 830824 Vendor in process of determining max loading applied to bushings Also reportable per Part 21
MILLS,L M Tennessee Valley Authority 83/09/21 O'REILLY,J P
Region 2, Office of Director 2pp 20591 060 24X
Fiche 50-390,83/09/21,8310030257

8310030338 Second interim deficiency rept re inaccurate results from ANCHORS computer program Initially reported on 830329 Problems reanalyzed using Version 2 issued 830506 Users manual revised Next rept expected by 831231
MILLS,L M Tennessee Valley Authority 83/09/21 O'REILLY,J P
Region 2, Office of Director 2pp 20390 303 24X
Fiche 50-390,83/09/21,8310030338

8310030388 Second interim deficiency rept re QA program for personal svc contract Initially reported on 830406 Controlled copies of engineering procedures sent to Gilbert Assoc Next rept expected by 831014
MILLS,L M Tennessee Valley Authority 83/09/21 O'REILLY,J P
Region 2, Office of Director 2pp 20592 139 24X
Fiche 50-000,83/09/21,8310030388

8310030399 Third interim deficiency rept re incorrect use of Category I(L) supports on pipes near water chillers Initially reported on 830117 Shielding structures being designed to protect chillers Next rept expected by 831017
MILLS,L M Tennessee Valley Authority 83/09/21 O'REILLY,J P
Region 2, Office of Director 2pp 20593 075 24X
Fiche 50-390,83/09/21,8310030399

8310030404 First interim deficiency rept re fire dampers not adequately shown on design typical drawings Initially reported on 830824 Clearances between fire damper & embedded sleeve will be inspected Next rept expected by 831206
MILLS,L M Tennessee Valley Authority 83/09/21 O'REILLY,J P
Region 2, Office of Director 2pp 20602 217 24X
Fiche 50-390,83/09/21,8310030404

8310030424 Third interim deficiency rept re failure to provide bolt tightening requirements Initially reported on 830120, Requirements provided in general note drawings, structural drawings & manufacturers installation procedures.
MILLS,L M Tennessee Valley Authority 83/09/22 O'REILLY,J P
Region 2, Office of Director 2pp 20593 178 24X
Fiche 50-390,83/09/22,8310030424

8310030473 Final deficiency rept for Unit 1 & fourth interim deficiency rept for Unit 2 re use of digitized response spectra data Initially reported on 820422,Engineering Change Notice 3491 issued to revise drawings Next rept expected by 840630
MILLS,L M Tennessee Valley Authority 83/09/22 O'REILLY,J P
Region 2, Office of Director 3pp 20601 061 24X
Fiche 50-390,83/09/22,8310030473

8310030506 Revised final deficiency rept re sheared motor pinion keys in Limitorque motor operators Initially reported on 820830 Condition only applies to Watts Bar Keys will be replaced by 840201 Also reportable per Part 21
MILLS,L M Tennessee Valley Authority 83/09/22 O'REILLY,J P
Region 2, Office of Director 3pp 20601 194 24X
Fiche 50-000,83/09/22,8310030506

8310030519 Final deficiency rept re failure to evaluate operator actions to realign ERCW train A Initially reported on 820510 Analysis revealed that sys able to deliver design flow to all loads during 10 minutes following DBA
MILLS,L M Tennessee Valley Authority 83/09/22 O'REILLY,J P
Region 2, Office of Director 2pp 20601 201 24X
Fiche 50-390,83/09/22,8310030519

8310030538 Final deficiency rept re incorrect max pipe movements contained in TPIPE program Initially reported on 830304 Response spectrum utilized in analyzing earthquake effect results in conservative displacements
MILLS,L M Tennessee Valley Authority 83/09/22 O'REILLY,J P
Region 2, Office of Director 3pp 20601 207 24X
Fiche 50-000,83/09/22,8310030538

8310030665 Final deficiency rept re Meriam Instruments orifice plates described in QA program Initially reported on 830510, No safety-related plates mfg for util since sub audit Util will verify implementation of QA
MILLS,L M Tennessee Valley Authority 83/09/23 O'REILLY,J P
Region 2, Office of Director 3pp 20592 327 24X
Fiche 50-390,83/09/23,8310030665

8310030370 Final interim deficiency rept re diesel generator electrical equipment temp rating Initially reported on 820601 Engineering change notice issued Ventilation sys can maintain acceptable temp in electrical equipment
MILLS,L M Tennessee Valley Authority 83/09/23 O'REILLY,J P
Region 2, Office of Director 2pp 20392 175 24X
Fiche 50-390,83/09/23,8310030370

8310030436 First interim deficiency rept re calculation of support design loads in TPIPE Initially reported on 830714,Procedure developed allowing recomputation of design loads near localized phenomena by hand Next rept by 831220.
MILLS,L M Tennessee Valley Authority 83/09/23 O'REILLY,J P
Region 2, Office of Director 2pp 20602 075 24X
Fiche 50-000,83/09/23,8310030436

8310030462 Final deficiency rept re heat loss from Power Bys diesels. Initially reported on 820729 Heat loss tests performed on 821120 & 830223 confirmed temps near safety-related equipment exceeded limits Also reportable per Part 21.
MILLS,L M Tennessee Valley Authority 83/09/23 O'REILLY,J P
Region 2, Office of Director 3pp 20601 049 24X
Fiche 50-390,83/09/23,8310030462

8310040180 Final deficiency rept re lack of evidence that auxiliary feedwater pump components meet ASME Class 3 or TVA Class C code requirements Initially reported on 820330 Drawings revised to identify piping & components properly
MILLS,L M Tennessee Valley Authority 83/09/27 O'REILLY,J P
Region 2, Office of Director 2pp 20608 265 24X
Fiche 50-390,83/09/27,8310040180

8310040544 Final deficiency rept re transfer switches to auxiliary feedwater sys having nondivisional power Initially reported on 830202 Caused by design oversight Engineering change notices issued & design mods made
MILLS,L M Tennessee Valley Authority 83/09/27 O'REILLY,J P
Region 2, Office of Director 3pp 20623 231 24X
Fiche 50-390,83/09/27,8310040544

8310040138 Final deficiency rept re improper classification of ERCW sys piping & components Initially reported on 810324, Components & drawings will be revised to show correct classification of HVAC equipment by 831115
MILLS,L M Tennessee Valley Authority 83/09/28 O'REILLY,J P
Region 2, Office of Director 3pp 20608 008 24X
Fiche 50-390,83/09/28,8310040138

8310040193 Final & second interim deficiency repts for Units 1 & 2, respectively re high pressure fire protection sys piping water danger to shutdown board transformers after postulated earthquake Initially reported on 830616
MILLS,L M Tennessee Valley Authority 83/09/28 O'REILLY,J P
Region 2, Office of Director 3pp 20608 103 24X
Fiche 50-390,83/09/28,8310040193

8310060009 Final deficiency rept re support welds not inspected or documented Initially reported on 830711 List developed of supports requiring weld insp Welds will be inspected & reworked if necessary by 831130
MILLS,L M Tennessee Valley Authority 83/09/29 O'REILLY,J P
Region 2, Office of Director 2pp 20647 243 24X
Fiche 50-390,83/09/29,8310060009

8310060016 Final deficiency rept re valve position indication problems w/EMD gate valves. Initially reported on 830203,Westinghouse equipment engineers provided w/instructions re valve function Also reportable under Part 21
MILLS,L M Tennessee Valley Authority 83/09/29 O'REILLY,J P
Region 2, Office of Director 2pp 20648 354 24X
Fiche 50-390,83/09/29,8310060016

8310060027 Final deficiency rept re containment spray miniflow valve design error Initially reported on 820305 Westinghouse internal design assurance & verification procedures revised. Also reportable under Part 21
MILLS,L M Tennessee Valley Authority 83/09/29 O'REILLY,J P
Region 2, Office of Director 2pp 20647 091 24X
Fiche 50-390,83/09/29,8310060027

8310060008 Second interim deficiency rept re diesel generator rear bearing problem Initially reported on 830627,Generator repaired Bearing assembly dimensions will be examined to determine presence of out-of-tolerance parts.
MILLS,L M Tennessee Valley Authority 83/09/30 O'REILLY,J P
Region 2, Office of Director 2pp 20647 241 24X
Fiche 50-390,83/09/30,8310060008

8310060087 Final deficiency rept re review & updating of piping drawings. Initially reported on 820621 Design Criteria Document WD-DC-40-31 3 revised to add Section 4.3 requiring mod to assure piping has been updated
MILLS,L M Tennessee Valley Authority 83/09/30 O'REILLY,J P
Region 2, Office of Director 3pp 20648 335 24X
Fiche 50-390,83/09/30,8310060087

DOCKETED ITEMS

- 8310060095 Final deficiency rept for Unit 1 & fifth interim deficiency rept for Unit 2 re discrepancies in support details Initially reported on 820302 & 830311, respectively Revs to support drawings will be issued by 840103
MILLS,L.M Tennessee Valley Authority 83/09/30 O'REILLY,J.P
Region 2, Office of Director App 20648 338 24X
Fiche 50-390,83/09/30,8310060095
- 8310060331 Final & eighth interim deficiency repts for Watts Bar & Bellefonte, respectively re inconsistent establishment of insp program Initially reported on 810324 Requirements, control & use of const requirements manual developed
MILLS,L.M Tennessee Valley Authority 83/09/30 O'REILLY,J.P
Region 2, Office of Director App 20641 001 24X
Fiche 50-000,83/09/30,8310060331
- 8310060342 Final deficiency rept re steam generator lower support bolts Initially reported on 820610 Reheat treatments provide adequate strength at operating temp, sufficient fracture toughness & crack resistance Also reportable per Part 21
MILLS,L.M Tennessee Valley Authority 83/09/30 O'REILLY,J.P
Region 2, Office of Director App 20646 077 24X
Fiche 50-390,83/09/30,8310060342
- 8310060436 Final deficiency rept re failure of safety-related Westinghouse gate valves Initially reported on 801031 All affected valves modified & applicable drawings revised
MILLS,L.M Tennessee Valley Authority 83/09/30 O'REILLY,J.P
Region 2, Office of Director App 20641 227 24X
Fiche 50-390,83/09/30,8310060436
- 8310060488 Final & third interim deficiency repts for Units 1 & 2, respectively re postulated accident blowdown of more than one steam generator. Initially reported on 821015 Power supply to steam generator PORV rearranged
MILLS,L.M Tennessee Valley Authority 83/09/30 O'REILLY,J.P
Region 2, Office of Director App 20641 015 24X
Fiche 50-390,83/09/30,8310060488
- 8310070301 Potential Part 21 rept re underrange characteristic of Model N-E110M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN,H.J Forsboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X
Fiche 50-000,83/09/30,8310070301
- 8310120237 Final deficiency rept re ambiguous outputs from Barton pressure transmitters in RCS Initially reported on 830409 Addl RCS transmitters installed outside containment Also reportable per Part 21.
MILLS,L.M Tennessee Valley Authority 83/10/03 O'REILLY,J.P
Region 2, Office of Director App 20692 172 24X
Fiche 50-390,83/10/03,8310120237
- 8310120322 Final deficiency rept re excessive movement of containment penetration bellows Initially reported on 811204 Analysis determined that bellow movement may exceed 0.226-inch lateral displacement Engineering change notice initiated.
MILLS,L.M Tennessee Valley Authority 83/10/03 O'REILLY,J.P
Region 2, Office of Director App 20699 272 24X
Fiche 50-390,83/10/03,8310120322
- 8310120396 Final & fourth interim deficiency rept for Units 1 & 2, respectively, re control of civil engineering support branch analysis calculations Initially reported on 820823 Flange qualification requirements incorporated into checklist.
MILLS,L.M Tennessee Valley Authority 83/10/03 O'REILLY,J.P
Region 2, Office of Director App 20700 197 24X
Fiche 50-390,83/10/03,8310120396
- 8310120100 Final & seventh interim deficiency repts, for Units 1 & 2, respectively, re piping sys analysis & pipe support design efforts for Class 1,2 & 3 sys Initially reported on 801217 All Unit 1 supports designed for current loads.
MILLS,L.M Tennessee Valley Authority 83/10/04 O'REILLY,J.P
Region 2, Office of Director App 20696 180 24X
Fiche 50-390,83/10/04,8310120100
- 8310120169 Fourth interim (Unit 2) & final (Unit 1) deficiency repts re incomplete/undocumented checking of pipe stress analysis problems Initially reported on 830513, Next rept for Unit 2 expected by 850119.
MILLS,L.M Tennessee Valley Authority 83/10/04 O'REILLY,J.P
Region 2, Office of Director App 20698 089 24X
Fiche 50-390,83/10/04,8310120169
- 8310120210 Final & third interim deficiency repts for Units 1 & 2, respectively, re thick walled instrument piping not accounted for in analysis of process piping Initially reported on 820909, Next rept by 840702
MILLS,L.M Tennessee Valley Authority 83/10/04 O'REILLY,J.P
Region 2, Office of Director App 20696 123 24X
Fiche 50-390,83/10/04,8310120210
- 8310120336 Final deficiency rept re questionable patches of plastic cement mortar Initially reported on 820429 Sampling of expansion anchored supports proved adequacy of supports Item not reportable per 10CFR50.55(e)
MILLS,L.M Tennessee Valley Authority 83/10/04 O'REILLY,J.P
Region 2, Office of Director App 20699 279 24X
Fiche 50-390,83/10/04,8310120336
- 8310120389 Final & sixth interim deficiency repts for Units 1 & 2, respectively, re discrepancies in as-built vs as-analyzed piping sys Initially reported on 810226 Support locations evaluated All Unit 1 rework will be completed by 831201
MILLS,L.M Tennessee Valley Authority 83/10/04 O'REILLY,J.P
Region 2, Office of Director App 20699 128 24X
Fiche 50-390,83/10/04,8310120389
- 8310140048 Final deficiency rept re mass of HVAC supports not included in frequency calculations Initially reported on 830807 Designs revised Field rework & support work will be completed by 840101
MILLS,L.M Tennessee Valley Authority 83/10/05 O'REILLY,J.P
Region 2, Office of Director App 20768 272 24X
Fiche 50-390,83/10/05,8310140048
- 8310140017 Second interim rept re pump motors supplied w/o seismic analysis or operability demonstration Initially reported on 830428 Addl info received from Westinghouse but analysis not completed Next rept expected by 831230
MILLS,L.M Tennessee Valley Authority 83/10/06 O'REILLY,J.P
Region 2, Office of Director App 20767 027 24X
Fiche 50-390,83/10/06,8310140017
- 8310170264 Second interim deficiency rept re routing of radioactive & nonradioactive sys instrument lines Initially reported on 830729 Engineering Change Notice 4287 initiated to remove instrument lines Next rept expected by 831221
MILLS,L.M Tennessee Valley Authority 83/10/06 O'REILLY,J.P
Region 2, Office of Director App 20787 100 24X
Fiche 50-390,83/10/06,8310170264
- 8310210096 Final rept re QA program deficiencies in Gilbert Assoc personal svcs contract Initially reported on 830406 Specific problems not identified by audit Items not reportable per 10CFR50.55(e)
MILLS,L.M Tennessee Valley Authority 83/10/12 O'REILLY,J.P
Region 2, Office of Director App 20858 197 24X
Fiche 50-000,83/10/12,8310210096
- 8310190089 Final deficiency rept re discrepancy in interface coordination of design review process Initially reported on 830717 Finding of coordination problem not significant & should not have been reported to NRC per 10CFR50.55(e)
MILLS,L.M Tennessee Valley Authority 83/10/13 O'REILLY,J.P
Region 2, Office of Director App 20818 132 24X
Fiche 50-000,83/10/13,8310190089
- 8310190224 Final deficiency rept re design review failure to verify accuracy & adequacy of design documents Initially reported on 811215 Listed changes to design review process will be implemented by 840101
MILLS,L.M Tennessee Valley Authority 83/10/13 O'REILLY,J.P
Region 2, Office of Director App 20818 045 24X
Fiche 50-000,83/10/13,8310190224
- 8310210011 Final deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on 830120 New requirements for assessing piping vibration problems during preoperational testing requirements issued
MILLS,L.M Tennessee Valley Authority 83/10/13 O'REILLY,J.P
Region 2, Office of Director App 20855 345 24X
Fiche 50-000,83/10/13,8310210011
- 8310210015 First interim deficiency rept re support for test lines by alternate analysis Initially reported on 830917 Existing support structure being analyzed to determine if mods necessary for DBA loadings Next rept by 831205
MILLS,L.M Tennessee Valley Authority 83/10/13 O'REILLY,J.P
Region 2, Office of Director App 20858 261 24X
Fiche 50-390,83/10/13,8310210015
- 8310210042 Supplemental deficiency rept re sensing of pipe breaks in component cooling sys Initially reported on 830624 Typographical error identified in 830909 final rept Engineering change notice number should be 4253, not 4235
MILLS,L.M Tennessee Valley Authority 83/10/13 O'REILLY,J.P
Region 2, Office of Director App 20855 317 24X
Fiche 50-390,83/10/13,8310210042
- 8310210049 Revised final deficiency rept re voiding of engineering change notices (ECNs) w/o proper review Initially reported on 820816 Sections in EN DES-EP 4 02 addressing voiding of ECNs changed in Rev 12, issued on 830203
MILLS,L.M Tennessee Valley Authority 83/10/13 O'REILLY,J.P
Region 2, Office of Director App 20855 304 24X
Fiche 50-000,83/10/13,8310210049

DOCKETED ITEMS

277

8310210068 Final deficiency rept for Unit 1 & third interim deficiency rept for Unit 2 re loose matl in steam generator Initially reported on 830325 Caused by lack of work controls Also reportable per Part 21 Next rept due by 840706
MILLS,L M Tennessee Valley Authority 83/10/13 O'REILLY,J P
Region 2, Office of Director 4pp 20897 270 24X
Fiche 50-395,83/10/13,8310210068

8310190127 First interim deficiency rept re shorted indicating lights in Westinghouse panels Initially reported on 830915 Westinghouse provided trained wiring separation procedure & wiring sketch Next rept expected by 831215
MILLS,L M Tennessee Valley Authority 83/10/14 O'REILLY,J P
Region 2, Office of Director 2pp 20821 128 24X
Fiche 50-395,83/10/14,8310190127

8310250371 Final deficiency rept for Unit 1 & interim rept for Unit 2 re alternately analyzed piping Verification of all Unit 1 piping carried out by personal svcs contractor & util div of engineering design
MILLS,L M Tennessee Valley Authority 83/10/14 O'REILLY,J P
Region 2, Office of Director 10pp 20898 044 24X
Fiche 50-395,83/10/14,8310250371

8310250012 Supplemental final deficiency rept re corrosion in high pressure fire protection sys Corrective action will be completed by 831230, per 830930 telcon Vendor matl for const raword will not arrive onsite to support original schedule
MILLS,L M Tennessee Valley Authority 83/10/17 O'REILLY,J P
Region 2, Office of Director 1p 20894 183 24X
Fiche 50-395,83/10/17,8310250012

8310250162 Second revised final deficiency rept re cross-trained diesel generator HX inlet valves Initially reported on 830531 Applicable drawings revised to apply diesel start signal to correct valve Corrections completed
MILLS,L M Tennessee Valley Authority 83/10/17 O'REILLY,J P
Region 2, Office of Director 3pp 20896 293 24X
Fiche 50-395,83/10/17,8310250162

8310250165 Third interim deficiency rept re spacing & clearance of sprinkler heads in high pressure fire protection sys Initially reported on 830331 Caused by lack of understanding necessity for maintaining adequate spray patterns
MILLS,L M Tennessee Valley Authority 83/10/17 O'REILLY,J P
Region 2, Office of Director 3pp 20894 062 24X
Fiche 50-395,83/10/17,8310250165

8310250173 Final & fourth interim deficiency repts for Units 1 & 2, respectively, re incorrect use of Category 1(L) supports on pipes near water chillers Initially reported on 830117 New spray shields designed to be installed above water chillers.
MILLS,L M Tennessee Valley Authority 83/10/17 O'REILLY,J P
Region 2, Office of Director 4pp 20893 278 24X
Fiche 50-395,83/10/17,8310250173

8310270150 Final rept re cable bend radius deficiencies due to use of nonstd fittings Initially reported on 830720 Caused by misinterpretation of specs Task team appointed to identify, evaluate & resolve problems Rework completed.
MILLS,L M Tennessee Valley Authority 83/10/18 O'REILLY,J P
Region 2, Office of Director 3pp 20925 020 24X
Fiche 50-395,83/10/18,8310270150

8310270183 Final deficiency rept re welds on structural steel in main steam valve rooms Initially reported on 830921 Util in process of visually reinspecting 100% of all structural steel welds Corrective action will be completed by 841025
MILLS,L M Tennessee Valley Authority 83/10/18 O'REILLY,J P
Region 2, Office of Director 2pp 20925 031 24X
Fiche 50-395,83/10/18,8310270183

8310310148 Revised final deficiency rept for Unit 1 & first interim deficiency rept for Unit 2 re installation of flow switches & sensing lines Initially reported on 830810 Actual rev to drawings will be accomplished by 831028 for Unit 1.
MILLS,L M Tennessee Valley Authority 83/10/19 O'REILLY,J P
Region 2, Office of Director 3pp 20959 014 24X
Fiche 50-395,83/10/19,8310310148

8310310320 Final deficiency rept for Unit 1 & fourth interim rept for Unit 2 re improper overlapping analysis techniques Initially reported on 830111 Twenty-nine problems judged unacceptable & reanalyzed to comply w/proper techniques
MILLS,L M Tennessee Valley Authority 83/10/21 O'REILLY,J P
Region 2, Office of Director 3pp 20961 210 24X
Fiche 50-395,83/10/21,8310310320

DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1

D NRC Draft/Final Environmental Statements, suppl's & correspondence

8310280005 Forwards 831006 comments submitted to SC Dept of Health & Environ Control clarifying points of thermal effects study plan as contained in FES
DIXON,D W South Carolina Electric & Gas Co 83/10/24 DENTON,H R
Office of Nuclear Reactor Regulation, Director 4pp 20934 289
24X Fiche 50-395,83/10/24,8310280005

E NRC Safety Evaluation Report (SER), suppl's & correspondence

8310260109 Suppl's response to SER Items 9 & 10 "Generic Design Package for Incorporation of Automatic Shunt Trip Feature into Westinghouse Reactor Protection Sys," as requested on 831003
DIXON,D W South Carolina Electric & Gas Co 83/10/20 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 20915 234
24X Fiche 50-395,83/10/20,8310260109

F Security, medical, emergency & fire protection plans

8310030573 Releases public version of revised emergency plan implementing procedures
FELTON,J M Division of Rules and Records 83/09/28 Document
Management Branch 1p 20604 328 24X Fiche:50-395,83/09/28,8310030573

--8310030582 Forwards public version of revised emergency plan implementing procedures, including Procedures EPP-002 re communication & notification, EPP-003 re in-plant radiological surveying & EPP-013 re fire emergency
DIXON,D W South Carolina Electric & Gas Co 83/08/12 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 20604 329 24X Fiche 50-395,83/09/28,8310030573

--8310030587 Public version of revised emergency plan implementing procedures, including Procedures EPP-002 re communication & notification, EPP-003 re in-plant radiological surveying & EPP-013 re fire emergency
South Carolina Electric & Gas Co. 83/08/10 367pp 20604:331
24X Fiche 50-395,83/09/28,8310030573

8310170289 Forwards Amend 17 to License NPF-12 & safety evaluation Amend changes wording of license condition re fire suppression to accurately reflect plant design
ADENSAH,E O Licensing Branch 4. 83/10/12 DIXON,D W South
Carolina Electric & Gas Co 20796 245 24X
Fiche:50-395,83/10/12,8310170289

--8310170296 Amend 17 to License NPF-12, changing wording of license condition re fire suppression to accurately reflect plant design
EISENKUT,D O Division of Licensing 83/10/12 2pp. 20796*248
24X Fiche 50-395,83/10/12,8310170289.

--8310170301 Safety evaluation supporting Amend 17 to License NPF-12 * Office of Nuclear Reactor Regulation, Director 83/10/12. 3pp.
20796 250 24X Fiche. 50-395,83/10/12,8310170289.

P Operating license stage documents & correspondence

8310040120 Forwards "Control of Heavy Loads at Nuclear Power Plants, VC Summer Nuclear Station, Unit 1 (PHASE I)," EQ&O technical evaluation rept Synopsis re NRC interpretation of NUREG-0612 guidelines for resolution of open items encl
NOVAK,T.M. Assistant Director for Licensing 83/09/16. DIXON,D.W.
South Carolina Electric & Gas Co 2pp 20640*274. 24X
Fiche 50-395,83/09/16,8310040120

--8310040123 "Control of Heavy Loads at Nuclear Power Plants, VC Summer Nuclear Station, Unit 1 (PHASE I)," technical evaluation rept
FRIEDERICH,B. EQ&O, Inc FIN A-6457. EQ&O-HB-6371. 83/08/31
NRC - No Detailed Affiliation Given 47pp 20640:276 24X
Fiche 50-395,83/09/16,8310040120

8310050076 Concurs w/dissolution of Model B2/D3 Steam Generator Util Design Review Panel Panel work complete.
NOVAK,T.M. Assistant Director for Licensing. 83/09/23
BLACKLEY,S K Design Review Panel 5pp 20630:165. 24X
Fiche 50-000,83/09/23,8310050076

8310170289 Forwards Amend 17 to License NPF-12 & safety evaluation Amend changes wording of license condition re fire suppression to accurately reflect plant design.
ADENSAH,E O. Licensing Branch 4. 83/10/12. DIXON,D W South
Carolina Electric & Gas Co. 3pp. 20796 245. 24X
Fiche. 50-395,83/10/12,8310170289

DOCKETED ITEMS

--8310170296 Amend 17 to License NPF-12, changing wording of license condition re fire suppression to accurately reflect plant design
EISENHUT, D O Division of Licensing 83/10/12 2pp 20796 248.
24X Fiche 50-395, 83/10/12, 8310170289

--8310170301 Safety evaluation supporting Amend 17 to License NPF-12
* Office of Nuclear Reactor Regulation, Director. 83/10/12 3pp
20796-250 24X Fiche 50-395, 83/10/12, 8310170289

8310260232 Application for amend to License NPF-12 changing Tech Specs re svc water intake structure monitoring/insp Revised License Condition 2 C(5) encl
DIXON, O W South Carolina Electric & Gas Co 83/10/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 20912 169
24X Fiche 50-395, 83/10/21, 8310260232

8310260255 Application for amend to License NPF-12 revising Tech Specs re cold overpressure protection sys Marked-up proposed Tech Specs encl
DIXON, O W South Carolina Electric & Gas Co 83/10/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director 10pp 20909 267
24X Fiche 50-395, 83/10/21, 8310260255

8310270135 Notification of 83101 meeting w/util in Reading, PA to discuss equipment qualification analyses performed for seismic confirmatory program.
HOPKINS, J B Licensing Branch 4 83/10/21 ABENSAM, E O Licensing Branch 4 4pp 20942 190 24X Fiche 50-395, 83/10/21, 8310270135

G Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 116pp 20777-210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc 115pp 20716-324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 79pp 20882-026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Metl Defect Causes Production of Noxious Gases." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761.

8310200252 Forwards SC Dept of Health & Environ Control 830830 ltr & util 830912 response to noncompliances noted during 830711-13 insp of NPDES Permit 800030856. Corrective action will be completed by 831015
DIXON, O W South Carolina Electric & Gas Co. 83/10/18 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 20830 118
24X Fiche 50-395, 83/10/18, 8310200252.

8310260232 Application for amend to License NPF-12 changing Tech Specs re svc water intake structure monitoring/insp Revised License Condition 2 C(5) encl
DIXON, O W South Carolina Electric & Gas Co 83/10/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 20912 169
24X Fiche 50-395, 83/10/21, 8310260232

R Periodic operating reports & related correspondence

8310190028 Monthly operating rept for Aug 1983 W/830913 ltr
TAYLOR, G J, DIXON, O W South Carolina Electric & Gas Co 83/07/12
BARRY, L W Office of Resource Management, Director 3pp
20523 236 24X Fiche 50-395, 83/09/12, 8310190028

S Reportable occurrences, LERs & related correspondence

8310030475 RO on 830822, while in Mode 1, fireproofing for Control Bldg Room CB-36-02 declared degraded when section removed from structural steel for const mod fire watch established. Fire proofing repaired & detectors declared operable on 830831
DIXON, O W South Carolina Electric & Gas Co 83/09/17
O'REILLY, J P Region 2, Office of Director 2pp 20601 064 24X
Fiche 50-395, 83/09/19, 8310030475

8310030343 LER 83-102/03L-0 on 830823 & 26, while in Mode 1, turbine room sump liquid radiation monitor RM-LB had insufficient sample flow caused by clogged solenoid valve on 830823 & closed suction line on 830826 W/830920 ltr
KOLB, L E, DIXON, O W South Carolina Electric & Gas Co 83/09/20
O'REILLY, J P Region 2, Office of Director 3pp 20590 337 24X
Fiche 50-395, 83/09/20, 8310030343

8310040416 Confirms 830916 mgt meeting in Region II ofc to discuss 830912 event where apparent load rejection at 75% power did not result in proper functioning of related sys, per 830913 telcon. Proposed meeting agenda encl
O'REILLY, J P Region 2, Office of Director 83/09/24 DIXON, O W
South Carolina Electric & Gas Co 3pp 20619 169 24X
Fiche 50-395, 83/09/24, 8310040416

8310040465 LER 83-103/03L-0 on 830910, w/unit in Mode 1, plant went from 97% power to 79% within 1 h Required isotopic iodine analysis not performed within 2 to 6 h Caused by personnel error Procedure mods implemented W/830926 ltr
BOUMKNIGHT, R J, DIXON, O W South Carolina Electric & Gas Co 83/09/26 O'REILLY, J P Region 2, Office of Director 3pp
20623 143 24X Fiche 50-395, 83/09/26, 8310040465

8310070002 LER 83-105/03L-0 on 830902, w/unit in Mode 1, refueling water storage tank level transmitter LT-791 failed high, declared inoperable & placed in bypassed condition. Caused by water in conduit resulting in electrical short W/830926 ltr
MCKINNEY, C J, DIXON, O W South Carolina Electric & Gas Co 83/09/26 O'REILLY, J P Region 2, Office of Director 2pp
20638 246 24X Fiche 50-395, 83/09/26, 8310070002

8310070278 LER 83-104/01T-0 on 830914, discovered that hourly fire watch patrol not established on 830909 when fire barrier surrounding HVAC ducts in HVAC chiller rooms removed for QA insp. Caused by personnel error W/830927 ltr
BOUMKNIGHT, R J, DIXON, O W South Carolina Electric & Gas Co 83/09/27 O'REILLY, J P Region 2, Office of Director 4pp
20637 021 24X Fiche 50-395, 83/09/27, 8310070278

8310070126 LER 83-107/03L-0 on 830914, reactor bldg internal pressure dropped below Tech Spec min Caused by change of ambient temp Reactor bldg minipurge supply activated to return pressure to within limits W/830929 ltr
KOLB, L E, DIXON, O W South Carolina Electric & Gas Co 83/09/29
O'REILLY, J P Region 2, Office of Director 2pp 20659 062 24X
Fiche 50-395, 83/09/29, 8310070126

8310070338 LER 83-106/03L-0 on 830904, post-accident hydrogen analyzer panel A (XPN-7215A) declared inoperable when calibr rotometer ball bearing indicator lodged in pressure regulator Caused by personnel error W/830930 ltr
KOLB, L E, DIXON, O W South Carolina Electric & Gas Co 83/09/30
O'REILLY, J P Region 2, Office of Director 3pp 20652 165 24X
Fiche 50-395, 83/09/30, 8310070338

8310170568 LER 83-108/03L-0 on 830902, while in Mode 1, diesel generator A output breaker failed to close during performance of surveillance test Cause not determined Test performed & unit returned to operable status W/830930 ltr
MCKINNEY, C J, DIXON, O W South Carolina Electric & Gas Co 83/09/30 O'REILLY, J P Region 2, Office of Director 4pp
20780-339 24X Fiche 50-395, 83/09/30, 8310170568

8310170443 LER 83-111/03L-0 on 830911, while in Mode 1, reactor trip occurred following power interruption on 115 kV offsite power source. Cause of trip from transient to onsite power source under investigation W/831010 ltr
MCKINNEY, C J, DIXON, D W South Carolina Electric & Gas Co 83/10/10
O'REILLY, J P Region 2, Office of Director 3pp
20779 225 24X Fiche 50-395, 83/10/10, 8310170443

8310210128 LER 83-110/03L-0 on 830912, during Mode 1, RCS Tavg exceeded power distribution limits by 2-1/2 degrees. Caused by failure of permanent magnet generator 22-volt power supply condenser & atmospheric dump valves W/831010 ltr
KOON, A R, DIXON, D W South Carolina Electric & Gas Co 83/10/10
O'REILLY, J P Region 2, Office of Director 7pp 20838 241 24X
Fiche 50-395, 83/10/10, 8310210128

8310310234 LER 83-112/03L-0 on 830923, signal comparator IPT-953B1 associated w/containment pressure transmitter IPT-953 declared inoperable when bistable tripped & would not reset. Caused by defective bistable electronic card W/831020 ltr.
MOLB, C E, DIXON, D W South Carolina Electric & Gas Co 83/10/20
O'REILLY, J P Region 2, Office of Director 3pp 20947 207 24X
Fiche 50-395, 83/10/20, 8310310234

8310310392 LER 83-114/03L-0 on 831004, steam generator C pressure indicator 494 declared inoperable due to spiking causing various alarms & bistable to activate. Caused by faulty electronic loop power supply card W/831020 ltr
BOWMAN, R J, DIXON, D W South Carolina Electric & Gas Co 83/10/20
O'REILLY, J P Region 2, Office of Director 2pp
20959 325 24X Fiche 50-395, 83/10/20, 8310310392

8310310394 LER 83-113/03L-0 on 830924, operator found personnel escape door hatch outer door hard to operate & unsecured. Caused by sheared right angle gear drive pin. Both doors locked & seal leak tested satisfactorily W/831020 ltr
BOWMAN, R J, DIXON, D W South Carolina Electric & Gas Co 83/10/20
O'REILLY, J P Region 2, Office of Director 2pp
20959 282 24X Fiche 50-395, 83/10/20, 8310310394

8310260117 Forwards clarification of why operator did not manually initiate reactor trip when reactor trip window illuminated on first-out annunciator panel on 830912, per NRC request at 830915 meeting
DIXON, D W South Carolina Electric & Gas Co 83/10/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 20915:231
24X Fiche 50-395, 83/10/21, 8310260117

DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2

A Application/construction stage documents & correspondence

8310030357 Forwards response to 830907 request for addl info re setpoint methodology. Resolution of issue generically w/NRC-recognized util group presently addressing issue requested
SORENSEN, O C Washington Public Power Supply System 83/09/23
SCHWENCER, A Licensing Branch 2 3pp 20392:337 24X
Fiche 50-397, 83/09/23, 8310030357

8310040440 Forwards addl info re containment "Out-of-Roundness" per NRC 830722 meeting
SORENSEN, O C Washington Public Power Supply System 83/09/26
SCHWENCER, A Licensing Branch 2 29pp 20619 059, 24X
Fiche 50-397, 83/09/26, 8310040440

8310070342 Forwards "Design Reverification Program," Vols 1 & 2, final assessment rpt. Results of program will be presented to NRC in late Oct 1983
SORENSEN, O C Washington Public Power Supply System 83/09/27
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
20651 100 24X Fiche 50-397, 83/09/27, 8310070342

--8310070346 "Design Reverification Program," Vols 1 & 2, final assessment rpt
* Washington Public Power Supply System 83/09/30 415pp
20651 102 24X Fiche 50-397, 83/09/27, 8310070342

8310110332 Forwards draft Tech Specs to require use of shorting links during initial source range monitors/intermediate range monitors overlap demonstration or post-mod, per NUREG-0123
SORENSEN, O C Washington Public Power Supply System 83/10/03
SCHWENCER, A Licensing Branch 2 7pp 20666:068 24X
Fiche 50-397, 83/10/03, 8310110332

8310120267 Requests that spent fuel storage pool monitors not be made requirement in Tech Specs, based on recent exemption granted for License SNM-1890 Storage in spent fuel storage area exemption predicated on design of storage facility
SORENSEN, O C Washington Public Power Supply System 83/10/03
SCHWENCER, A Licensing Branch 2 2pp 20693 135, 24X
Fiche 50-397, 83/10/03, 8310120267

8310120261 Forwards response to FSAR Question 110 43 in NRC 830803 ltr. Increased damping & seismic spectra resulting from finite element model utilized to produce Phase II refined loads for each of five sample anchor groups
SORENSEN, O C Washington Public Power Supply System 83/10/04
SCHWENCER, A Licensing Branch 2 5pp 20693 114 24X
Fiche 50-397, 83/10/04, 8310120261

8310170131 Forwards request for addl info re Outstanding Issue 13 "Control Sys Failures" Response requested by 831028
SCHWENCER, A Licensing Branch 2 83/10/05 MAZUR, D W Washington
Public Power Supply System 8pp 20811 352 24X
Fiche 50-397, 83/10/05, 8310170131

8310130212 Notification of 831018 meeting w/util in Bethesda, MD to discuss seismic & dynamic qualification of electrical & mechanical equipment
AULUCK, R Licensing Branch 2 83/10/06 SCHWENCER, A Licensing
Branch 2 3pp 20777 192 24X Fiche 50-397, 83/10/06, 8310130212

8310170495 Request that NUREG-0123, "Std BWR Tech Specs," be revised to previous format, based on need to provide adequate time frame for completion of WPPSS-2 power ascension testing program. Susquehanna test duration data encl
SORENSEN, O C Washington Public Power Supply System 83/10/10
SCHWENCER, A Licensing Branch 2 3pp 20784 018, 24X
Fiche: 50-000, 83/10/10, 8310170495

--8310170499 Tech Spec Page 3/4 10-5 re oxygen concentration limiting condition for operation
* Washington Public Power Supply System 82/02/01 1p
20784 018 24X Fiche 50-000, 83/10/10, 8310170495

8310170313 Forwards draft Amend 33 to FSAR consisting of solid waste mgmt sys re utilization of interim portable solid radwaste solidification sys. Submittal will be incorporated in FSAR Amend 33. W/two oversize drawings. Aperture cards in PDR
SORENSEN, O C Washington Public Power Supply System 83/10/11
SCHWENCER, A Licensing Branch 2 1p 20784 346 24X
Fiche 50-397, 83/10/11, 8310170313

8310200031 Forwards request for addl info re design adequacy for Anchor Group 37 identified in 830914 submittal
SCHWENCER, A Licensing Branch 2 83/10/12 MAZUR, D W Washington
Public Power Supply System 3pp 20844 233 24X
Fiche 50-397, 83/10/12, 8310200031

8310180449 Forwards Rev 0 to "Dissolved Gas Analysis" Implementation of post-accident sampling sys & final dissolved gas sampling procedure contingent upon receipt of mod equipment from OE to be delivered by 831130
SORENSEN, O C Washington Public Power Supply System 83/10/13
SCHWENCER, A Licensing Branch 2 2pp 20802:068 24X
Fiche: 50-397, 83/10/13, 8310180449

--8310180453 Rev 0 to Procedure 12 10 B, "Dissolved Gas Analysis"
* Washington Public Power Supply System 83/09/27, 19pp
20802 070 24X Fiche 50-397, 83/10/13, 8310180449

8310210168 Forwards "Response to NRC Human Factors Engineering Preliminary Design Assessment Audit Rpt of 830826"
SORENSEN, O C Washington Public Power Supply System 83/10/14
SCHWENCER, A Licensing Branch 2 1p 20843:306, 24X
Fiche: 50-397, 83/10/14, 8310210168

--8310210173 "Response to NRC Human Factors Engineering Preliminary Design Assessment Audit Rpt of 830826"
DAVALLE, R O, FREEMAN, G J, MCILTON, C H Washington Public Power
Supply System 83/10/07 200pp, 20843 307 24X
Fiche: 50-397, 83/10/14, 8310210168

8310210305 Provides documentation of util position re reactor pressure vessel surveillance program & recently amended 10CFR50 App H. Coupon removal sys consistent w/1973 version of ASTM-E185
SORENSEN, O C Washington Public Power Supply System 83/10/14
SCHWENCER, A Licensing Branch 2 2pp 20831:074 24X
Fiche 50-397, 83/10/14, 8310210305

8310240150 Provides status info on Branch Technical Position PBB-1 commitments per 8 Rhow 830905 request. OE field dispositions re final Div 3 second level undervoltage protection design & two oversize drawings encl Aperture cards available in PDR
SORENSEN, O C Washington Public Power Supply System 83/10/14
SCHWENCER, A Licensing Branch 2 2pp 20878:054 24X
Fiche: 50-397, 83/10/14, 8310240150

8310260113 Forwards Offsite Dose Calculation Manual
SORENSEN, O C Washington Public Power Supply System 83/10/17
SCHWENCER, A Licensing Branch 2 1pp 20912:283, 24X
Fiche 50-397, 83/10/17, 8310260113

DOCKETED ITEMS

--8310260122 "Offsite Dose Calculation Manual"
 * Washington Public Power Supply System 83/10/17 110pp
 20912 284 24X Fiche 50-397, 83/10/17, 8310260113

8310270444 Advises that quality processes group functions can be assumed by sys completion group in const mgt organization. Quality processes group will be disestablished.
 CARLISLE, C S Washington Public Power Supply System 83/10/18
 MARTIN, J B Region 5, Office of Director 2pp 20923 115 24X
 Fiche 50-397, 83/10/18, 8310270444

8310250088 Forwards Vols I & III of "Independent Evaluation of Plant Verification Program at WPPSS-2"
 CARLISLE, C S Washington Public Power Supply System 83/10/19
 MARTIN, J B Region 5, Office of Director 3pp 20892 001 24X
 Fiche 50-397, 83/10/19, 8310250088

--8310250093 "Independent Evaluation of Plant Verification Program at WPPSS-2 Vol I Quality Verification"
 LANEY, R V, RODDIS, L H, SHEETS, H E Technical Audit Associates, Inc 1126-F1 V01 83/09/30 100pp 20892 004 24X
 Fiche 50-397, 83/10/19, 8310250088

--8310250097 "Independent Evaluation of Plant Verification Program at WPPSS-2 Vol 3 - Technical Audit Assoc. Inc Audit Repts"
 LANEY, R V, RODDIS, L H, SHEETS, H E Technical Audit Associates, Inc 1126-F3 V03 83/09/30 240pp 20892 114 24X
 Fiche 50-397, 83/10/19, 8310250088

E NRC Safety Evaluation Report (SER), suppls & correspondence

8310030361 Discusses agreement w/NRC affecting surveillance requirements in NUREG-0892, SER Suppl 2 re TMI Action Item II K 3.28 on automatic depressurization sys Bottle pressure verification changed to 31 days
 SORENSEN, O C Washington Public Power Supply System 83/09/23
 SCHWENGER, A Licensing Branch 2 3pp 20592 131 24X
 Fiche 50-397, 83/09/23, 8310030361

8310110276 Forwards four oversize drawings, closing out NUREG-0892, SER Outstanding Issue 29 re vacuum breaker valves Valve response meets containment design bases for response time & flow capacity. Aperture cards are available in PDR
 SORENSEN, O C Washington Public Power Supply System 83/09/28
 SCHWENGER, A Licensing Branch 2 2pp 20665 325 24X
 Fiche 50-397, 83/09/28, 8310110276

8310170298 Forwards loose parts detection sys conformance evaluation, including action requested in NUREG-0892, SER Section 4.4.6
 SORENSEN, O C Washington Public Power Supply System 83/09/29
 SCHWENGER, A Licensing Branch 2 8pp 20786 186 24X
 Fiche 50-397, 83/09/29, 8310170298

8310180387 Forwards proprietary FSAR Table 3.9-2b re SER Confirmatory Issues 9 & 10 Table contains OE proprietary info Table withheld (ref 10CFR2 790) Affidavit requesting info be withheld & OE 830923 ltr also encl
 SORENSEN, O C Washington Public Power Supply System 83/09/29
 SCHWENGER, A Licensing Branch 2 4pp 20804 098 24X
 Fiche 50-397, 83/09/29, 8310180387

8310120155 Forwards response to FSAR Question 110.41 re requirements for equipment nozzle loads, per SER Confirmatory Issue 7 on component supports
 SORENSEN, O C Washington Public Power Supply System 83/10/04
 SCHWENGER, A Licensing Branch 2 3pp 20696 005 24X
 Fiche 50-397, 83/10/04, 8310120155

8310120059 Forwards marked-up Tech Spec re ECCB in response to 830923 request for proposed change to surveillance requirements on automatic depressurization sys backup air supply, per SER, NUREG-0892 & Item II K 3.28
 SORENSEN, O C Washington Public Power Supply System 83/10/06
 SCHWENGER, A Licensing Branch 2 2pp 20697 101 24X
 Fiche 50-397, 83/10/06, 8310120059

8310170212 Forwards marked-up FSAR changes in response to SER Confirmatory Issue 1 re break locations. Info based on "status as-built" configuration. Final "as-built" analysis not expected to result in significant differences
 SORENSEN, O C Washington Public Power Supply System 83/10/11
 SCHWENGER, A Licensing Branch 2 135pp 20786 223 24X
 Fiche 50-397, 83/10/11, 8310170212

8310170235 Forwards response to telcon request for addl clarification of response to Question 440.01 a & b re emergency operating procedures generation package. SER (NUREG-0892) Confirmatory Issue 15 re emergency procedures review closed.
 SORENSEN, O C Washington Public Power Supply System 83/10/11
 SCHWENGER, A Licensing Branch 2 6pp 20787 013 24X
 Fiche 50-397, 83/10/11, 8310170235

F Security, medical, emergency & fire protection plans

8310040397 Forwards IE Safeguards Insp Repts 50-397/83-33 & 70-2950/83-02 on 830815-18 & notice of violation Encls withheld (ref 10CFR2 790)
 NORDERHAUO, L R Region 5, Office of Director 83/09/28
 CARLISLE, C S Washington Public Power Supply System 2pp 20620 042 24X Fiche 50-397, 83/09/28, 8310040397

8310040232 Part 21 rept re plant mod implementing fire protection, including blocking vent paths from reactor bldg rooms containing high energy lines initially reported on 830928. Six rooms require reanalysis
 CONN, W O Burns & Roe Co 83/09/29 Director's Office, Office of Inspection and Enforcement 2pp 20613 201 24X
 Fiche 50-397, 83/09/29, 8310040232

8310170446 Discusses history & background of use of fire dampers not fire rated or tested in const of facility, due to state-of-the-art const at time of installation FSAR will be revised via Amend 33 to document const Marked-up drawings encl
 SORENSEN, O C Washington Public Power Supply System 83/09/24
 SCHWENGER, A Licensing Branch 2 27pp 20790 282 24X
 Fiche 50-397, 83/09/29, 8310170446

8310120335 Discusses proposed implementation of emergency preparedness training plan first phase, per NUREG-0654, will be completed prior to fuel load Detailed schedules will be completed & made available for review upon concurrence
 SORENSEN, O C Washington Public Power Supply System 83/10/04
 SCHWENGER, A Licensing Branch 2 2pp 20699 277 24X
 Fiche 50-397, 83/10/04, 8310120335

8310120027 Forwards request for addl info re emergency classification scheme in emergency planning program Response requested by 831028
 SCHWENGER, A Licensing Branch 2 83/10/05 MAZUR, D W Washington Public Power Supply System 7pp 20749 345 24X
 Fiche 50-397, 83/10/05, 8310120027

8310170266 Advises that util position re establishing primary emergency operations facility approx 0.75 miles from site & alternate location at util headquarters 9.5 miles from site acceptable
 EISENHUT, D O Division of Licensing 83/10/07 MAZUR, D W Washington Public Power Supply System 2pp 20776 259 24X
 Fiche 50-397, 83/10/07, 8310170266

8310180503 Clarifies util 820617 ltr describing emergency operations facility ventilation, per NUREG-0696 Charcoal will not be provided in ventilation sys
 SORENSEN, O C Washington Public Power Supply System 83/10/12
 SCHWENGER, A Licensing Branch 2 1p 20801 180 24X
 Fiche 50-397, 83/10/12, 8310180503

G Adjudicatory correspondence

8310050216 Notice of withdrawal of appearance in proceeding Certificate of Bvc encl
 CHAN, E I Hearing Branch 2 83/09/27 2pp 20628 286 24X
 Fiche 50-397, 83/09/27, 8310050216

K Utility Final Safety Analysis Report (FSAR) & amends

8310070277 Amend 32 to FSAR W/830902 ltr
 SORENSEN, O C Washington Public Power Supply System 83/09/30
 SCHWENGER, A Licensing Branch 2 823pp 20652 226 24X
 Fiche 50-397, 83/09/30, 8310070277

Q Inspection reports, IE Bulletins & correspondence

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Bvc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310170428 Forwards IE Insp Rept 50-397/83-42 on 830815-18 & 19-0902 No noncompliance noted
 BISHOP, T W Region 5, Office of Director 83/09/21 MATLOCK, R O Washington Public Power Supply System 2pp 20783 268 24X
 Fiche 50-397, 83/09/21, 8310170428

--8310170432 IE Insp Rept 50-397/83-42 on 830815-18 & 19-0902 No noncompliance noted Major areas inspected, previously identified const deficiencies (10CFR50 55(e) repts)
 BURDGIN, J F., SCOWEN, K H, RODDIS, R T Region 5, Office of Director 83/09/19 12pp 20783 260 24X Fiche 50-397, 83/09/21, 8310170428

DOCKETED ITEMS

281

- 83100340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340
- 83100342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342
- 8310040397 Forwards IE Safeguards Insp Repts 50-397/83-33 & 70-2950/83-02 on 830819-18 & notice of violation Encls withheld (ref 10CFR2 790)
KORDEHAUO, L R Region 5, Office of Director 83/09/28
CARLISLE, C S Washington Public Power Supply System 2pp 20620 042 24X Fiche 50-397, 83/09/28, 8310040397
- 8310120192 Ack receipt of 830919 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-397/83-38
BISHOP, T W Division of Resident, Reactor Project & Engineering
Programs 83/09/28 CARLISLE, C S Washington Public Power Supply System 1p 20692 227 24X Fiche 50-397, 83/09/28, 8310120192
- 8310120196 Responds to NRC 830830 ltr re violations noted in IE Insp Rept 50-397/83-38 Corrective actions all welds on six separate tree risers inspected & found fully welded out No deficiencies encountered
CARLISLE, C S Washington Public Power Supply System 83/09/19
MARTIN, J B Region 5, Office of Director 8pp 20692 228 24X Fiche 50-397, 83/09/28, 8310120192
- 8310120248 Ack receipt of 830916 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-397/83-38
BISHOP, T W Division of Resident, Reactor Project & Engineering
Programs 83/09/28 CARLISLE, C S Washington Public Power Supply System 1p 20691 331 24X Fiche 50-397, 83/09/28, 8310120248
- 8310120250 Responds to NRC 830830 ltr re violations noted in IE Insp Rept 50-397/83-38 Corrective actions honeycombed areas in beams 2B11 & 2D25 excavated to sound concrete & will be repaired Destructive exam & documentation review conducted
CARLISLE, C S Washington Public Power Supply System 83/09/16
MARTIN, J B Region 5, Office of Director 133pp 20691 332 24X Fiche 50-397, 83/09/28, 8310120248
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 57 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349
- 8310170612 Forwards IE Insp Rept 50-397/83-44 during Aug 1983 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering
Programs 83/09/29 MAZUR, D W Washington Public Power Supply System 2pp 20782 172 24X Fiche 50-397, 83/09/29, 8310170612
- 8310170621 IE Insp Rept 50-397/83-44 during Aug 1983 No noncompliance noted Major areas inspected preoperational test procedure review & independent insp effort, including testing of pipe support & restraint sys
FEIL, R A , DODDS, R T Region 5, Office of Director 83/09/27 6pp 20782 174 24X Fiche 50-397, 83/09/29, 8310170612
- 8310180331 Ack receipt of 830912 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-397/83-14
BISHOP, T W Division of Resident, Reactor Project & Engineering
Programs 83/10/03 CARLISLE, C S Washington Public Power Supply System 1p 20802 344 24X Fiche 50-397, 83/10/03, 8310180331
- 8310180341 Submits interim response to NRC 830603 ltr re violations noted in IE Insp Rept 50-397/83-14 Corrective actions Quality Class I & II PEDs undergoing reevaluation Sample program expected to be completed by 830930.
CARLISLE, C S Washington Public Power Supply System 83/09/12
STERNBERG, D M Region 5, Office of Director 2pp 20802 345 24X Fiche 50-397, 83/10/03, 8310180331
- 8310200194 Ack receipt of 830926 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-397/83-38
BISHOP, T W Division of Resident, Reactor Project & Engineering
Programs 83/10/04 CARLISLE, C S Washington Public Power Supply System 1p 20833-346 24X Fiche 50-397, 83/10/04, 8310200194
- 8310200200 Responds to NRC 830830 ltr re violations noted in IE Insp Rept 50-397/83-38 Corrective actions deficiencies reviewed against required hanger function Hangers determined adequate
CARLISLE, C S Washington Public Power Supply System 83/09/26, MARTIN, J B Region 5, Office of Director 35pp 20833 347 24X Fiche 50-397, 83/10/04, 8310200194
- 8310200203 "Engineering Insp & Evaluation of Quality Class II/Seismic Category I Pipe Supports "
VARANE, L S , COOK, J L , PURVIS, F Stone & Webster Engineering Corp 83/09/22 34pp 20834 020 24X Fiche 50-397, 83/10/04, 8310200194
- 8310210055 Forwards IE Insp Rept 50-397/83-34 on 830701-31 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering
Programs 83/10/04 MAZUR, D W Washington Public Power Supply System 2pp 20855 275 24X Fiche 50-397, 83/10/04, 8310210055
- 8310210060 IE Insp Rept 50-397/83-34 on 830701-31 No noncompliance noted Major areas inspected preoperational test procedure review, preoperational test witnessing, unresolved items & independent insp effort
FEIL, R A , DODDS, R T Region 5, Office of Director 83/09/30 7pp 20855 277 24X Fiche 50-397, 83/10/04, 8310210055
- 8310130426 Notification of 831014 meeting w/util in Bethesda, MD to discuss const appraisal team findings in civil & structural const area
AULUCK, R Licensing Branch 2 83/10/06 SCHWENGER, A Licensing Branch 2, 3pp 20769 244 24X Fiche 50-397, 83/10/06, 8310130426
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752
- 8310170481 Ack receipt of 830929 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-397/83-38
BISHOP, T W Division of Resident, Reactor Project & Engineering
Programs 83/10/07 CARLISLE, C S Washington Public Power Supply System 1p 20783 300. 24X Fiche 50-397, 83/10/07, 8310170481.
- 8310170507 Responds to NRC 830830 ltr re violations noted in IE Insp Rept 50-397/83-38 Corrective actions specific deficiency noted in item D of notice of violation placed in project tracking sys Deficiency will be corrected by 83101
CARLISLE, C S Washington Public Power Supply System 83/09/29, MARTIN, J B Region 5, Office of Director 4pp 20783 301 24X Fiche 50-397, 83/10/07, 8310170481
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Hatl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761
- 8310210043 Forwards IE Insp Rept 50-397/83-48 in Sept 1983 No noncompliance noted
BISHOP, T W Region 5, Office of Director. 83/10/13 MAZUR, D W Washington Public Power Supply System. 2pp 20855 268 24X Fiche 50-397, 83/10/13, 8310210043.
- 8310210045 IE Insp Rept 50-397/83-48 during Sept 1983 No noncompliance noted Major areas inspected preoperational test witnessing & independent insp effort
FEIL, R A , DODDS, R T Region 5, Office of Director. 83/10/11, 5pp 20855:270. 24X Fiche 50-397, 83/10/13, 8310210043
- 8310270420 Notification of 831025 significant licensee meeting w/util in Walnut Creek, CA to discuss NRC regional evaluation of licensee performance for Aug 1982 - Jul 1983
* Region 5, Office of Director 83/10/25 Region 5, Office of Director 1p 20923.107 24X Fiche 50-397, 83/10/25, 8310270420

DOCKETED ITEMS

B Reportable occurrences, LERs & related correspondence

8309300331 Final deficiency rept, Condition 258 re failure to comply w/OE specs for installation of RHR HX Initially reported on 830609 Deficiencies corrected Final review practices developed by completion contractor
CARLISLE, C B Washington Public Power Supply System 83/09/22
MARTIN, J B Region 5, Office of Director 6pp 20548 266 24X
Fiche 50-397, 83/09/22, 8309300331

8310040331 Part 21 rept re control circuits for safety-related valves
CAC-FCV-1A & 1B powered from non-Class IE power supply
Caused by failure to recognize valves have two safety-related functions: isolation & oxygen/hydrogen recombination
CONN, W O Burns & Roe Co 83/09/29 Director's Office, Office of Inspection and Enforcement 2pp 20617, 118 24X
Fiche 50-397, 83/09/29, 8310040331

8310250505 Part 21 rept re safety-related control circuits for CAC-FCV-1A & 1B, being powered from non-Class IE power supply Initially reported on 830928 PED 218-E-C105 issued to provide Class IE power supplies to two valves
CONN, W O Burns & Roe Co 83/09/29 Director's Office, Office of Inspection and Enforcement 2pp. 20902 078 24X
Fiche: 50-397, 83/09/29, 8310250505

8310250290 Final deficiency rept, Condition 49 re operation of standby gas treatment sys damper Initially reported on 820817 Caused by AE failure to adequately apply single failure criterion PED-218-E-8137 issued to reroute circuits
CARLISLE, C B Washington Public Power Supply System 83/10/11
MARTIN, J B Region 5, Office of Director 4pp. 20899 013 24X
Fiche 50-397, 83/10/11, 8310250290

8310250425 Final Deficiency Rept 270 re indeterminate grade matl on ECCB pumps HP-1, LPCS-P-1, RHR-P-28 & 2C Initially reported on 830707 Operations maint surveillance program implemented to check breakaway torque
CARLISLE, C B Washington Public Power Supply System 83/10/13
MARTIN, J B Region 5, Office of Director 3pp 20897 001 24X
Fiche 50-397, 83/10/13, 8310250425

8310250453 Final deficiency rept, Condition 252 re power piping M-146 near brackets substituted for previously approved & unavailable M-142 brackets Burns & Roe revised Spec 215, Section 1B, App D
CARLISLE, C B Washington Public Power Supply System 83/10/13
MARTIN, J B Region 5, Office of Director 3pp 20897 155 24X
Fiche 50-397, 83/10/13, 8310250453

8310250092 Interim deficiency rept, Reportable Condition 286 re linear indications in containment weld pads Cause unknown All 19 weld pads providing support for radial beams being reinspected & repaired Next rept due by 831111
CARLISLE, C B Washington Public Power Supply System 83/10/14
MARTIN, J B Region 5, Office of Director 3pp 20894 109 24X
Fiche 50-397, 83/10/14, 8310250092

8310250144 Final Deficiency Rept 290 re diesel generator exciter control cabinet overheating Design Change SPED 8218-M-C247 issued to provide addl ventilation for Div 1 & 2 diesel generator excitation control cabinets.
CARLISLE, C B Washington Public Power Supply System 83/10/14
MARTIN, J B Region 5, Office of Director 2pp. 20894 324 24X
Fiche 50-397, 83/10/14, 8310250144

V Operator Examinations

8310030142 Requests schedule, by 831028, for requalification training & exams for 1984 in order to coordinate Region V audit of operator requalification programs
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs, 83/09/26 ODDFREY, O Washington Public Power Supply System 2pp 20590 040 24X Fiche 50-397, 83/09/26, 8310030142

DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

8310280174 FOIA request for all internal nonpublic documentation re const flaws & improper conduct by inspectors, util contractors or subcontractors
MCINNIS, D News & Observer 83/07/19, FELTON, J Division of Rules and Records 1p 20963 287 24X Fiche 50-400, 83/07/19, 8310280174

8310030161 Advises that organizational changes for QA program & changes to FSARs & mgt capability rept will be forwarded when completed.
UTLEY, E E Carolina Power & Light Co. 83/09/13, DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20590 028 24X
Fiche 50-000, 83/09/13, 8310030161

8310040354 Summarizes 830831 meeting w/util re plans for restructuring corporate organization
O'REILLY, J P Region 2, Office of Director 83/09/22 UTLEY, E E Carolina Power & Light Co 2pp 20620 331 24X
Fiche 50-000, 83/09/22, 8310040354

8310280176 Responds to FOIA request for internal nonpublic documentation re const flaws & improper conduct of NRC inspectors & util contractors or subcontractors Forwards documents listed in App A
FELTON, J M Division of Rules and Records 83/09/23 VADEN, T News & Observer 3pp 20963 288 24X Fiche 50-400, 83/09/23, 8310280176

--8310280197 Forwards draft Ofc of Inspector & Auditor 78109 rept on inquiry into alleged omission of line inspector views from CP hearing, for perusal W/O encl
MURRAY, J P Deputy Executive Legal Director 78/12/18 CUMMINGS, J J Office of Inspector & Auditor 3pp 20963 297 24X Fiche 50-400, 83/09/23, 8310280176

--8310280202 Documents telcon w/ C Cantrell re insp file in preparation for testimony Instructions not received to review file Cantrell relied solely on personal notes & records to prepare testimony
FOSTER, W H Office of Inspector & Auditor 78/11/01 Office of Inspector & Auditor 1p 20963 295 24X Fiche 50-400, 83/09/23, 8310280176

--8310280207 Advises that ASLAB Chairman, AS Rosenthal will decline interview, claiming purposelessness
FOSTER, W H Office of Inspector & Auditor 78/10/26 Office of Inspector & Auditor 1p 20963 296 24X Fiche 50-400, 83/09/23, 8310280176

--8310280211 Advises that IE Manual Chapter 94010-B only written policy for preparing testimony for licensing hearings, per 781025 telcon w/RC Paulus
FOSTER, W H Office of Inspector & Auditor 78/10/26 Office of Inspector & Auditor 1p 20963 297 24X Fiche 50-400, 83/09/23, 8310280176

--8310280214 Forwards AS Rosenthal 781024 memo to OO Abston, for perusal
ABSTON, O O Office of Inspector & Auditor 78/10/25 HENDRIE, J M Commissioners 1p 20963 298 24X
Fiche 50-400, 83/09/23, 8310280176

--8310280218 Advises that ASLAB members not willing to be interviewed due to possible future involvement in case
ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel 78/10/24 ABSTON, O O Office of Inspector & Auditor 1p 20963 299 24X Fiche 50-400, 83/09/23, 8310280176

--8310280222 Requests interview w/ASLAB members to discuss impact of omission of line inspector views from written & oral testimony
ABSTON, O O Office of Inspector & Auditor 78/10/24 ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel 1p 20963 300 24X Fiche 50-400, 83/09/23, 8310280176

--8310280225 Forwards info re Ofc of Inspector & Auditor interview of ASLAB (ref Yore 781019 memo to Commissioners)
FRYE, J H Atomic Safety and Licensing Board Panel 78/10/20 ROSENTHAL, A, KELLEY, J L, ABSTON, O O NRC - No Detailed Affiliation Given 1p 20963 301 24X Fiche 50-400, 83/09/23, 8310280176

--8310280236 Forwards DH Gamble 781019 memo, for interest
ABSTON, O O Office of Inspector & Auditor 78/10/20 HENDRIE, J M Commissioners 1p 20963 312 24X
Fiche 50-400, 83/09/23, 8310280176

--8310280238 Summarizes A Rosenthal 781019 telcon opposing potential interview w/ASLAB members, citing unpleasantness of ASLAB interview Ofc of Inspector & Auditor must assure different line of questioning before interview is granted
GAMBLE, D H Office of Inspector & Auditor 78/10/19 Office of Inspector & Auditor 2pp 20963 313 24X Fiche 50-400, 83/09/23, 8310280176

--8310280242 Forwards documentation of 781017 conversation w/JM Vaisla, former AEC employee re V Brownlee Conversation connected w/ current investigation
DAVIS, J O Director's Office, Office of Inspection and Enforcement 78/10/19 ABSTON, O O Office of Inspector & Auditor 1p 20963 315 24X Fiche 50-400, 83/09/23, 8310280176

DOCKETED ITEMS

283

- 8310280244 Documents 781017 conversation w/J Varela, former Region II employee Brownlee directed Varela to change info in insp rept, causing dispute
DAVIS, J O Director's Office, Office of Inspection and Enforcement 78/10/19 Director's Office, Office of Inspection and Enforcement 1p 20963 316 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280246 Documents 781017 conversation w/C Barth (OELD) re testimony forwarded to ASLB before 771004 hearing ASLB should be required to read testimony before hearing
FOSTER, W H Office of Inspector & Auditor 78/10/18 Office of Inspector & Auditor 1p 20963 317 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280248 Advises of Ofc of Inspector & Auditor inability to procure useful info during interview w/ASLB due to ASLB unresponsiveness
ABSTON, D G Office of Inspector & Auditor 78/10/17 HENDRIE, J M, GILINSKY, V, KENNEDY, R T Commissioners 2pp 20963 324 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280250 Advises that HA Wilbur perusal of Dance testimony disclosed no ref to GA problems listed in subj insp repts
FOSTER, W H Office of Inspector & Auditor 78/10/10 Office of Inspector & Auditor 1p 20963 326 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280254 Forwards case assignments for ASLB members OD Bright, JV Leeds & IW Smith, per request
FITZ, C J Atomic Safety and Licensing Board Panel 78/10/06 GAMBLE, D H Office of Inspector & Auditor 6pp 20963 327 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280256 Forwards Acting General Counsel opinion indicating no ex parte problem w/Ofc of Inspector & Auditor interview of ASLB members
ABSTON, D G Office of Inspector & Auditor 78/10/03 YORE, J R, POSENTHAL, A S Atomic Safety and Licensing Board Panel 1p 20963 333 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280259 Informs of 781003 conversation w/I Smith of ASLB re Ofc of Inspector & Auditor interview w/ASLB members, to fulfill Commission order interview will probably not be granted due to ex parte rule
FOSTER, W H Office of Inspector & Auditor 78/10/03 Office of Inspector & Auditor 1p 20963 335 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280263 Summarizes continued attempts to gain ASLB interview through 780927 conversation w/JV Leeds Leeds will not cooperate, citing ex parte rule
FOSTER, W H Office of Inspector & Auditor, 78/09/27 Office of Inspector & Auditor 2pp 20963 336 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280265 Informs of alleged improprieties re deficiency discrepancy repts & corresponding logbook entries
VORSE, J Y Office of Investigation 83/03/04 ALBERSON, C Y NRC - No Detailed Affiliation Given 1p 20963 338 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280270 Discusses alleged improprieties re deficiency discrepancy repts & corresponding logbook entries
BURCH, R H Office of Investigation 83/03/03 Office of Investigation 1p 20963 339 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280299 Advises that no new info revealed after inquiry of alleged improprieties re deficiency discrepancy repts & corresponding logbook entries
VORSE, J Y Office of Investigation 83/03/06 TODD, G NRC - No Detailed Affiliation Given 1p 20963 340 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280303 Advises that inquiry into alleged improprieties re deficiency discrepancy repts & corresponding logbook entries closed Util cited for violation
BURCH, R H Office of Investigation 83/03/04 Office of Investigation 1p 20963 341 24X Fiche 50-400, 83/09/23, 8310280176
- 8310070120 Forwards response to requests for addl info, including response to Rev 1 to "Basis for Auxiliary Feedwater Sys Flow Requirements," in support of safety review Response includes info re main steam turbine valve testing issue
MCDOUFFIE, M A Carolina Power & Light Co, 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 41pp 20658 341 24X Fiche 50-400, 83/09/30, 8310070120
- 8310310172 Forwards NRC 830921 ltr to util advising of acceptance of design, analyses, matls & const aspects of containment vessel weld deficiencies, in response to Resolution 1443-83
NOVAK, T M Assistant Director for Licensing 83/10/18 EULERT, O A Perry, OH 3pp 20965 288 24X Fiche 50-400, 83/10/18, 8310310172
- E NRC Safety Evaluation Report (SER), suppl's & correspondence

- 8310310240 Forwards addl info in response to draft SER Open Item 354, including Mechanical Engineering Branch questions in 830819 & 25 ltrs
MCDOUFFIE, M A Carolina Power & Light Co 83/09/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 20722 236 24X Fiche 50-400, 83/09/19, 8310310240
- 8310310248 GC Procedure 120, "Hydrostatic Testing (Critical Bvr) "
* Goulds Pumps, Inc 80/07/01 3pp 20722 242 24X Fiche 50-400, 83/09/19, 8310310240
- 8310310254 Rev 3 to GA Instruction 0A1-212, "Training & Qualification of GA Personnel "
* Goulds Pumps, Inc 80/06/18 11pp 20722 245 24X Fiche 50-400, 83/09/19, 8310310240
- 8310310261 "Seismic Qualification Envelope Limitorque Valve Actuators "
DRAB, J D, DENKOWSKI, W J, FORMICA, C D, Limitorque Corp 80037 80/01/11 24pp 20722 236 24X Fiche 50-400, 83/09/19, 8310310240
- 8310310267 Rev 1 to "Rept of Test on Seismic Vibration Testing of One Limitorque SHM-000/HOBC Actuator for Limitorque Corp."
ESPPOSITO, B., CASABON, M., TOLF, M L Acton Environ Testing Corp 14331-2 R01 79/03/13 16pp 20722 280 24X Fiche 50-400, 83/09/19, 8310310240
- 8310310271 Rev 1 to "Rept of Test on Seismic Vibration Testing One Limitorque SHM-000/HOBC Actuator W/Seismic Adapter for Limitorque Corp "
ESPPOSITO, B., CASABON, M., TOLF, M L Acton Environ Testing Corp 14331-3 R01 79/03/13 12pp 20722 296 24X Fiche 50-400, 83/09/19, 8310310240
- 8310310273 "Seismic Test SHM-000/HOBC "
YOUNG, P T Limitorque Corp 80045 83/09/19 6pp 20722 308 24X Fiche 50-400, 83/09/19, 8310310240
- 8310310277 Rev 1 to "Rept of Test on Seismic Vibration Testing of Limitorque SHM-1/HOBC Actuators for Limitorque Corp "
ESPPOSITO, B., OILFOY, R., TOLF, M L Acton Environ Testing Corp 14801-1 R01 79/06/11 41pp 20722 314 24X Fiche 50-400, 83/09/19, 8310310240
- 8310310280 "Rept of Fragility Test on SHM-1-25/H4BC W/Btd Cast Adapter for Limitorque Corp "
* Aero Nav Laboratories, Inc 5-6167-5 75/12/17, 36pp 20722 355 24X Fiche 50-400, 83/09/19, 8310310240
- 8310310282 Rev 0 to Engineering Spec JSN-T35, "Seat Testing & Disc Hydrostatic Testing - 5 Minute Duration "
* Jamesbury Corp 78/01/24 11pp 20723 029 24X Fiche 50-400, 83/09/19, 8310310240
- 8310310285 Rev 0 to Procedure 4-106, "Cold Bending of Carbon Steel & Ferritic Alloy "
* Southwest Fabricating & Welding Co (subs. of IU International Corp) 73/05/04 3pp 20723 040 24X Fiche 50-400, 83/09/19, 8310310240
- 8310310287 Rev 0 to Procedure 4-107, "Cold Bending of Austenitic Stainless Steel Piping "
* Southwest Fabricating & Welding Co (subs. of IU International Corp) 73/05/04 3pp 20723 043 24X Fiche 50-400, 83/09/19, 8310310240
- 8310310289 Rev 0 to Procedure 4-108, "Hot Bending of Carbon Steel & Ferritic Alloys "
* Southwest Fabricating & Welding Co (subs. of IU International Corp) 73/05/04 5pp 20723 046 24X Fiche 50-400, 83/09/19, 8310310240
- 8310310290 Rev 0 to Procedure 4-109, "Hot Bending of Austenitic Stainless Steel Piping "
* Southwest Fabricating & Welding Co. (subs. of IU International Corp) 73/05/04 11pp 20723 051 24X Fiche 50-400, 83/09/19, 8310310240
- 8310310291 Procedure MNE-65, "Pipe Line Sizing Guide "
* Ebasco Services, Inc (subs. of Enserch Corp) 70/06/20 7pp 20723 062 24X Fiche 50-400, 83/09/19, 8310310240

DOCKETED ITEMS

--8310130293 Rev B to Site Spec 030, "Field Fabrication & Erection of Power Pipe"
* Carolina Power & Light Co 83/03/29 23pp 20723 069 24X
Fiche 50-400, 83/09/19, 8310130240

--8310130294 Engineering Procedure 3.2, "Design Change Control"
* Carolina Power & Light Co 83/08/19 32pp 20723 092 24X
Fiche 50-400, 83/09/19, 8310130240

8310170124 Summary of 830825 meeting w/util & Ebasco in Bethesda, MD re Meteorological & Effluents Treatment Sys Branch draft SER open items
BUCKLEY, B C, HOLDNICH, J Licensing Branch 3 83/09/29
Office of Nuclear Reactor Regulation, Director 20813 059 24X Fiche 50-400, 83/09/29, 8310170124

8310110119 Forwards amended response to request for addl info re draft SER Open Item 38 concerning technical basis for QDC-31 compliance Responses to other requests will be provided shortly
MCDUFFIE, M A Carolina Power & Light Co 83/09/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 150pp 20667 038 24X Fiche 50-400, 83/09/30, 8310110119

8310120180 Forwards response to request for addl info re draft SER open items on reevaluation of PHP, plant area water accumulation & adequacy of electric distribution sys voltages
MCDUFFIE, M A Carolina Power & Light Co 83/10/05 DENTON, H R
Office of Nuclear Reactor Regulation, Director 8pp 20695 301 24X Fiche 50-400, 83/10/05, 8310120180

8310140126 Forwards response to NRC Question 210 59 re piping spec, loading combinations & stress limits completing response to 32 Mechanical Engineering Branch questions in 830819 & 25 ltrs for SER Open Item 354
MCDUFFIE, M A Carolina Power & Light Co 83/10/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director 21pp 20765 045 24X Fiche 50-400, 83/10/10, 8310140126

8310180474 Forwards responses to draft SER Open Items 355-383, discussed at 830921 meeting w/Auxiliary Sys Branch in Bethesda, MD
MCDUFFIE, M A Carolina Power & Light Co 83/10/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director 37pp 20801 351 24X Fiche 50-400, 83/10/11, 8310180474

8310180311 Forwards addl info re draft SER open items, in response to Mechanical Engineering, Power Sys & Reactor Sys Branch concerns Westinghouse Owners Group Jul 1977 rept & Sept 1977 suppl will be used in derivation of setpoints
MCDUFFIE, M A Carolina Power & Light Co 83/10/12 DENTON, H R
Office of Nuclear Reactor Regulation, Director 22pp 20803 076 24X Fiche 50-400, 83/10/12, 8310180311

8310210024 Forwards responses to requests for addl info re draft SER open items
MCDUFFIE, M A Carolina Power & Light Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 53pp 20856 017 24X Fiche 50-400, 83/10/14, 8310210024

8310250638 Forwards supplemental info in response to Biting Analysis Branch concerns re SER Item 7 Seaboard Sys Railroad provided assistance in preparation of supplemental info. Encl withheld (ref 10CFR2 790)
MCDUFFIE, M A Carolina Power & Light Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20899 314 24X Fiche 50-400, 83/10/14, 8310250638

8310260259 Forwards proprietary & nonproprietary versions of "Table of Control Rod Drive Mechanism (CRDM) 400 Series Stainless Steel Items," in response to Matls Engineering Branch draft SER open items Proprietary table withheld (ref 10CFR2 790)
MCDUFFIE, M A Carolina Power & Light Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20909 209 24X Fiche 50-400, 83/10/14, 8310260259

--8310260267 Application for withholding proprietary "Table of Control Rod Drive Mechanism (CRDM) 400 Series Stainless Steel Items," per 10CFR2 790 W/affidavit
WIESEMANN, R A Westinghouse Electric Corp 83/10/11 LIAW, B D
Materials Engineering Branch 10pp 20909 211 24X
Fiche 50-400, 83/10/14, 8310260259

--8310260283 Nonproprietary "Table of Control Rod Drive Mechanism (CRDM) 400 Series Stainless Steel Items"
* Westinghouse Electric Corp. 83/10/14 1p 20909 221 24X
Fiche: 50-400, 83/10/14, 8310260259

8310260147 Forwards responses to requests for addl info re draft SER Open Items 63 & 67 Responses verify containment pressure & justify operation of normal containment purge sys
MCDUFFIE, M A Carolina Power & Light Co 83/10/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 20912 236 24X Fiche 50-400, 83/10/20, 8310260147

8310260152 Forwards response to NRC request for addl info re emergency diesel generator load sequence reliability (draft SLR Option Item 310) Applicant in process of performing PRA on sequencer
MCDUFFIE, M A Carolina Power & Light Co 83/10/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20912 232 24X Fiche 50-400, 83/10/20, 8310260152

8310260134 Forwards response to request for addl info re draft SER Open Item 77 Shunt trip attachment mod will be implemented, per Generic Ltr 83-28
MCDUFFIE, M A Carolina Power & Light Co 83/10/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20912 236 24X Fiche 50-400, 83/10/21, 8310260134

8310280014 Forwards nonproprietary & proprietary responses to request for addl info re criticality analyses for spent fuel racks
Draft SER Open Item 360 completed Proprietary response withheld (ref 10CFR2 790)
MCDUFFIE, M A Carolina Power & Light Co 83/10/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 20929 026 24X Fiche 50-400, 83/10/21, 8310280014

--8310280019 Application for withholding proprietary response to request for addl info re criticality analyses for spent fuel racks
Nonproprietary version of response encl
WIESEMANN, R A Westinghouse Electric Corp 83/10/11
BERLINGER, C H Core Performance Branch 32pp 20929 030 24X
Fiche 50-400, 83/10/21, 8310280014

F Security, medical, emergency & fire protection plans

8310170070 Summary of 830825 meeting w/util & Ebasco re fire protection program & safe shutdown analysis
HOLDNICH, J Licensing Branch 1 BUCKLEY, B C Licensing Branch 3
83/09/30 Licensing Branch 1 3pp 20798 019 24X
Fiche 50-400, 83/09/30, 8310170070

8310180185 Summary of 830926 & 27 meetings w/util & Ebasco re fire protection open items, drawing review & Auxiliary Sys Branch discussion of safe shutdown analysis
BUCKLEY, B C Licensing Branch 3 HOLDNICH, J J Licensing Branch 1
83/09/30 Licensing Branch 3 9pp 20827 014 24X
Fiche 50-400, 83/09/30, 8310180185

8310210264 Forwards Rev 1 to emergency plan Evacuation time study scheduled for completion by 8/1/23
UTLEY, E E Carolina Power & Light Co 83/10/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20688 001 24X Fiche 50-400, 83/10/04, 8310210264

--8310120268 Rev 1 to emergency plan
* Carolina Power & Light Co 83/09/30 63pp 20688 003 24X
Fiche 50-400, 83/10/04, 8310120264

8310210136 Forwards addl info re fire protection, including response to Safety Review Question 280 1, revised safe shutdown analysis w/exemptions & mods, info requested in 830926-27 meetings w/NRC & response to Enforcement Action 83-41
MCDUFFIE, M A Carolina Power & Light Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 475pp 20856 151 24X Fiche 50-400, 83/10/14, 8310210136

G Adjudicatory correspondence

8310030441 Response to general interrogatories & interrogatories on Contention BF(1) Related correspondence
CARROW, H Carolina Power & Light Co 83/09/23 EDDLEMAN, W
Edelman, W 16pp 20602 069 24X Fiche 50-400, 83/09/23, 8310030441

--8310030478 Response to request for production of documents on Contention BF(1) Certificate of Svc encl
CARROW, H Carolina Power & Light Co 83/09/23 EDDLEMAN, W
Edelman, W 4pp 20602 085 24X Fiche 50-400, 83/09/23, 8310030441

8310030367 Response opposing util motion for summary disposition of Edleman Contention 80 re mixing & dispersion models
Statement of facts as to which there are issues to be heard encl
EDDLEMAN, W Edleman, W 83/09/27 Atomic Safety and Licensing Board Panel 6pp 20593 009 24X Fiche 50-400, 83/09/27, 8310030367

DOCKETED ITEMS

285

- 8310030369 Response opposing util motion for summary disposition of Eddleman Contention 75 on clams Statement of facts as to which there are issues to be heard encl
EDDLEMAN, W Eddleman, W 83/09/27 Atomic Safety and Licensing Board Panel 8pp 20593 015 24X Fiche 50-400,83/09/27, 8310030367
- 8310030372 Response opposing util motion for summary disposition of Eddleman Contention 83/84 re carcinogenic discharges
Statement of facts as to which there are issues to be heard encl
EDDLEMAN, W Eddleman, W 83/09/27 Atomic Safety and Licensing Board Panel 6pp 20593 024 24X Fiche 50-400,83/09/27, 8310030367
- 8310030375 Response to util motion for summary disposition of Eddleman Contention 84F
EDDLEMAN, W Eddleman, W 83/09/27 Atomic Safety and Licensing Board Panel 2pp 20593 030 24X Fiche 50-400,83/09/27, 8310030367
- 8310030377 Motion for license condition on spent fuel shortage if Contention 84F withdrawn
EDDLEMAN, W Eddleman, W 83/09/27 Atomic Safety and Licensing Board Panel 5pp 20593 032 24X Fiche 50-400,83/09/27, 8310030367
- 8310030380 Response partly opposing util proposed schedule rev Certificate of Svc encl
EDDLEMAN, W Eddleman, W 83/09/27 Atomic Safety and Licensing Board Panel 2pp 20593 037 24X Fiche 50-400,83/09/27, 8310030367
- 8310040523 Notifies that util counsel & author agreed to negotiate next Lt on util responses to Eddleman Interrogatories 15AA & 8F1
Notice tolls time for filing motion to compel
EDDLEMAN, W Eddleman, W 83/09/28 KELLEY, J Atomic Safety and Licensing Board Panel 1p 20624 234 24X Fiche 50-400,83/09/28, 8310040523
- 8310030508 Response to ASLB 830922 inquiry re W Eddleman proffered Contention 24 Opposes contention re terrorist acts directed against irradiated fuel in transit Regulations do not require security plan for shipment Certificates of Svc encl
BARTH, C A Hearing Branch 1 83/09/29 Atomic Safety and Licensing Board Panel 8pp 20601 170 24X Fiche 50-400,83/09/29, 8310030508
- 8310040518 Response re 10CFR2 75B petition of 830630 on need for power & alternatives Certificate of Svc encl
EDDLEMAN, W Eddleman, W 83/09/30 Atomic Safety and Licensing Board Panel 8pp 20623 001 24X Fiche 50-400,83/09/30, 8310040518
- 8310040538 Forwards Page 10, inadvertently omitted from util 830929 reply to W Eddleman response to ASLB 830824 order
O'NEILL, J H Shaw, Pittman, Potts & Trowbridge O'NEILL, J H Carolina Power & Light Co 83/09/30 KELLEY, J L, BRIGHT, O D, CARPENTER, J H Atomic Safety and Licensing Board Panel 1p 20623 297 24X Fiche 50-400,83/09/30,8310040538
- 8310040541 Page 10, inadvertently omitted from util 830929 reply to W Eddleman response to ASLB 830824 order Svc list encl
Carolina Power & Light Co 83/09/30 Atomic Safety and Licensing Board Panel 3pp 20623 298 24X Fiche 50-400, 83/09/30, 8310040538
- 8310050555 Response supporting util 830912 motion to modify schedule on environ contentions Issuance of FES by 831031 should be factored into scheduler mods Certificate of Svc encl
BARTH, C A Hearing Branch 1 83/10/03 Atomic Safety and Licensing Board Panel 3pp 20629 037 24X Fiche 50-400,83/10/03, 8310050555
- 8310060188 Forwards motion for summary disposition of Joint Intervenor's Contention II & W Eddleman Contention 37B on health effects Related correspondence
O'NEILL, J H Shaw, Pittman, Potts & Trowbridge O'NEILL, J H Carolina Power & Light Co 83/10/03 KELLEY, J L, BRIGHT, O D, CARPENTER, J H Atomic Safety and Licensing Board Panel 2pp 20649 001 24X Fiche 50-400,83/10/03,8310060188
- 8310060193 Motion for summary disposition of Joint Intervenor's Contention II & W Eddleman Contention 37B re health effects
No genuine issue of matl fact exists & util entitled to favorable decision Related correspondence
AULICK, D D Carolina Power & Light Co AULICK, D D Shaw, Pittman, Potts & Trowbridge 83/10/03 Atomic Safety and Licensing Board Panel 62pp 20647 003 24X Fiche 50-400,83/10/03,8310060188
- 8310060203 Statement of matl facts as to which there is no genuine issue re Joint Intervenor's Contention II & W Eddleman Contention 37B Related correspondence
AULICK, D D Carolina Power & Light Co AULICK, D D Shaw, Pittman, Potts & Trowbridge 83/10/03 Atomic Safety and Licensing Board Panel 13pp 20649 071 24X Fiche 50-400,83/10/03,8310060188
- 8310060212 Affidavit of JI Fabrikant re health effects estimates in DES Somatic & genetic health effect estimates in DES are not underestimated Prof qualifications encl Related correspondence
FABRIKANT, J I Carolina Power & Light Co FABRIKANT, J I Lawrence Livermore Laboratory 83/10/01 120pp 20649 084 24X Fiche 50-400,83/10/03,8310060188
- 8310060222 Affidavit of GH Whipple supporting util motion for summary disposition of Joint Intervenor's Contention II NRC models use concentrations, doses & health effects unaffected by incomplete mixing or dispersion Related correspondence
WHIPPLE, G H Carolina Power & Light Co 83/09/30 16pp 20649 209 24X Fiche 50-400,83/10/03,8310060188
- 8310060238 Affidavit of JJ Mauro supporting util motion for summary disposition of Joint Intervenor's Contention II & Eddleman Contention 37B DES determined max ratio of health effects from plant operation Related correspondence
MAURO, J J Carolina Power & Light Co MAURO, J J Ebasco Services, Inc (subs of Enserch Corp) 83/10/03 18pp 20649 225 24X Fiche 50-400,83/10/03,8310060188
- 8310060323 Notice of appearance in proceeding Certificate of Svc encl
AULICK, D D Carolina Power & Light Co AULICK, D D Shaw, Pittman, Potts & Trowbridge 83/10/03 5pp 20646 227 24X Fiche 50-400,83/10/03,8310060323
- 8310110150 Motion for summary disposition of Eddleman Contention 29/30 (App I compliance) No genuine issue of matl fact exists & applicant entitled to favorable decision Related correspondence
O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/10/05 Atomic Safety and Licensing Board Panel 50pp 20665 135 24X Fiche 50-400,83/10/05, 8310110150
- 8310110155 Statement of matl facts as to which there is no genuine issue re Eddleman Contention 29/30
O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/10/05 Atomic Safety and Licensing Board Panel 10pp 20665 186 24X Fiche 50-400,83/10/05,8310110150
- 8310110407 Affidavit of JJ Mauro & G Martin in support of applicant motion for summary disposition of W Eddleman Contention 29/30
MAURO, J J, MARTIN, G Carolina Power & Light Co 83/10/03 58pp 20665 196 24X Fiche 50-400,83/10/05,8310110150
- 8310110409 Affidavit of RL Shearin in support of applicant motion for summary disposition of W Eddleman Contention 29/30
SHEARIN, R L Carolina Power & Light Co 83/09/30 8pp 20665 254 24X Fiche 50-400,83/10/05,8310110150
- 8310110412 Affidavit of TJ Grant in support of applicant motion for summary disposition of W Eddleman Contention 29/30 Certificate of Svc encl
GRANT, T J Carolina Power & Light Co 83/09/30 16pp 20665 262 24X Fiche 50-400,83/10/05,8310110150
- 8310110209 Memorandum & order ruling on discovery disputes Motions to compel & for protective order granted/denied as noted.
KELLEY, J L Atomic Safety and Licensing Board Panel 83/10/06 Eddleman, W 16pp 20665 073 24X Fiche 50-400,83/10/06, 8310110209
- 8310110218 Memorandum & order admitting some of W Eddleman late-filed contentions on detailed control room design review R Wilson
830921 & Conservation Council of North Carolina 830924 motions to withdraw contentions granted
BRIGHT, O D, CARPENTER, J H, KELLEY, J L Atomic Safety and Licensing Board Panel 83/10/06 Conservation Council of North Carolina 14pp 20665 042 24X Fiche 50-400,83/10/06,8310110218
- 8310120370 Response to interrogatories on Contentions 15AA & 8F1 Certificate of negotiations & Certificate of Svc encl
EDDLEMAN, W Eddleman, W 83/10/06 Carolina Power & Light Co 18pp 20699 254 24X Fiche 50-400,83/10/06,8310120370
- 8310140072 Revised Contention 16! re safety shutdown sys failure Certificate of Svc encl
EDDLEMAN, W Eddleman, W 83/10/11 Atomic Safety and Licensing Board Panel 2pp 20766 357 24X Fiche 50-400,83/10/11,8310140072

DOCKETED ITEMS

8310140065 Erratum to ASLB 831006 memorandum & order ruling on W Eddleman proposed contentions re detailed control room design review & R Wilson & Conservation Council of North Carolina motions to withdraw contentions
KELLEY, J L Atomic Safety and Licensing Board Panel 83/10/12
EDDLEMAN, W Eddleman, W WILSON, R Wilson, R 2pp 20768 007
24X Fiche 50-400, 83/10/12, 8310140065

8310170543 Forwards corrected version of util motion for summary disposition of Joint Intervenor's Contention II & W Eddleman Contention 37B on health effects
AULICK, D D Shaw, Pittman, Potts & Trowbridge AULICK, D D Carolina Power & Light Co 83/10/12 KELLEY, J L, BRIGHT, G O, CARPENTER, J H Atomic Safety and Licensing Board Panel 1p 20780 355 24X Fiche 50-400, 83/10/12, 8310170543

--8310170608 Corrected copy of motion for summary disposition of Joint Intervenor's Contention II & W Eddleman Contention 37B on health effects Errata sheet encl
AULICK, D D Carolina Power & Light Co AULICK, D D Shaw, Pittman, Potts & Trowbridge 83/10/03 Atomic Safety and Licensing Board Panel 4pp 20780 356 24X Fiche 50-400, 83/10/12, 8310170543

--8310170620 Fourth set of interrogatories & request for production of documents
O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/10/12 Joint Intervenor's-Shearon Harris 15pp 20781 055 24X Fiche 50-400, 83/10/12, 8310170543

--8310170630 Reply opposing W Eddleman 830927 motion for license condition on spent fuel storage, ASLB lacks jurisdiction over issues of health & safety re spent fuel transportation Certificate of Svc encl
O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/10/12 Atomic Safety and Licensing Board Panel 10pp 20781 070 24X Fiche 50-400, 83/10/12, 8310170543

8310170626 Response to 830831 interrogatories re Contention 37B concerning health impacts from exposure to radioactive materials
BRANAQAN, E F Radiological Assessment Branch BARTH, C Hearing Branch 1 83/10/12 EDDLEMAN, W Eddleman, W 3pp 20782 113 24X Fiche 50-400, 83/10/12, 8310170626

--8310170632 Response to 830831 second set of interrogatories Statement of prof qualifications & Certificate of Svc encl
SCHWENK, G A Radiological Assessment Branch BARTH, C A Hearing Branch 1 83/10/12 EDDLEMAN, W Eddleman, W 54pp 20782 116 24X Fiche 50-400, 83/10/12, 8310170626

8310250467 Response opposing W Eddleman 830927 motion for license condition on spent fuel storage Motion premature & not in conformity w/Commission regulations Certificate of Svc encl
BARTH, C A Hearing Branch 1 83/10/17 Atomic Safety and Licensing Board Panel 4pp 20897 145 24X Fiche 50-400, 83/10/17, 8310250467

8310250125 Followup response to Interrogatory 4 on Contention B(1)(1) Listed document will be placed in PDR
BARTH, C A Hearing Branch 1 83/10/19 EDDLEMAN, W Eddleman, W 1p 20896 344 24X Fiche 50-400, 83/10/19, 8310250125

8310270351 Notifies that negotiations re adequacy & accuracy of NRC response to 830831 discovery on Contentions 37B, 15AA, BF1 & BF2 continuing Motions to compel will be filed within 10 days of breakdown of negotiations, if required
EDDLEMAN, W Eddleman, W 83/10/19 KELLEY, J Atomic Safety and Licensing Board Panel 1p 20924 009 24X Fiche 50-400, 83/10/19, 8310270351

8310240183 Third supplemental responses to W Eddleman 831006 general interrogatories & interrogatories on Contentions 29 & 37B Certificate of Svc encl
QIBBS, J J Carolina Power & Light Co QIBBS, J J Shaw, Pittman, Potts & Trowbridge 83/10/20 Eddleman, W 11pp 20878 104 24X Fiche 50-400, 83/10/20, 8310240183

8310250167 Forwards Pages 26-32 of ALAD-653 re security plan contentions, per 831005 telcon request Pages withheld (ref 10CFR73.21)
BARTH, C A Hearing Branch 1 83/10/20 RUNKLE, J North Carolina, State of 1p 20894 061 24X Fiche 50-400, 83/10/20, 8310250167

8310250037 General interrogatories & interrogatories on Contentions BF1, BF2 & 15AA (sixth set) Related correspondence
EDDLEMAN, W Eddleman, W 83/10/21 Carolina Power & Light Co 18pp. 20894 115 24X Fiche 50-400, 83/10/21, 8310250037

8310250040 Interrogatories re Contentions BF1, BF2 & 15AA (second round, third set) Related correspondence
EDDLEMAN, W Eddleman, W 83/10/21 Office of the Executive Leg./ Director 6pp 20896 166 24X Fiche 50-400, 83/10/21, 8310250040

8310250086 Response to applicant interrogatories on Eddleman Contention 65 (sixth set) Certificate of Svc encl Related correspondence
EDDLEMAN, W Eddleman, W 83/10/21 Carolina Power & Light Co 8pp 20894 143 24X Fiche 50-400, 83/10/21, 8310250086

8310260202 Interrogatories & request for production of documents on Eddleman Contention BF(1) Related correspondence
CARROW, H Consumers Power Co 83/10/21 EDDLEMAN, W Eddleman, W 6pp 20912 237 24X Fiche 50-400, 83/10/21, 8310260202

--8310260209 Second set of interrogatories & request for production of documents re Eddleman Contention 15AA Certificate of Svc encl Related correspondence
CARROW, H Consumers Power Co 83/10/21 EDDLEMAN, W Eddleman, W 7pp 20912 243 24X Fiche 50-400, 83/10/21, 8310260202

8310270319 Memorandum & order modifying schedule on environ contentions
KELLEY, J L Atomic Safety and Licensing Board Panel 83/10/25 5pp 20923 183 24X Fiche 50-400, 83/10/25, 8310270319

8310280051 Response opposing W Eddleman 831010 proposed rev to Contention 161 re safety shutdown sys failure Rev fails to specify defects in original circuit breaker design Certificate of Svc encl
O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/10/25 Atomic Safety and Licensing Board Panel 14pp 20934 333 24X Fiche 50-400, 83/10/25, 8310280051

8310280164 Fifth set of interrogatories on Joint Contention VI re radiation detection & monitoring & request for production of documents
ANDERSON, P H Carolina Power & Light Co ANDERSON, P H Shaw, Pittman, Potts & Trowbridge 83/10/25 Joint Intervenor-Shearon Harris 16pp 20929 226 24X Fiche 50-400, 83/10/25, 8310280164

8310310146 Informs that DR Lewis, formerly ASLB participant in UL proceeding, began working for author on 831024 DR Lewis will not participate in UL proceeding
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A Carolina Power & Light Co 83/10/26 Commissioners 4pp 20939 056 24X Fiche 50-400, 83/10/26, 8310310146

0 Inspection reports, IE Bulletins & correspondence

8310040220 Ack receipt of 830831 ltr requesting 3-month extension to complete corrective actions in response to violations noted in IE Insp Rept 50-400/82-37 Request acceptable.
LEWIS, R C Division of Project & Resident Programs 83/09/13 UTLEY, E E Carolina Power & Light Co 1p 20614 264 24X Fiche 50-400, 83/09/13, 8310040220

--8310040224 Requests extension until 831201 to complete replacement of unidentified bolts on all Seismic 1 pumps, in response to violations noted in IE Insp Rept 50-400/82-37
PARSONS, R M Carolina Power & Light Co 83/08/31 O'REILLY, J P Region 2, Office of Director 1p 20614 265 24X Fiche 50-400, 83/09/13, 8310040220

8310040595 Ack receipt of 830831 & 0902 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/83-22 & 50-401/83-22
LEWIS, R C Division of Project & Resident Programs 83/09/13 UTLEY, E E Carolina Power & Light Co 1p 20626 240 24X Fiche 50-400, 83/09/13, 8310040595

--8310040600 Responds to NRC 830803 ltr re violations noted in IE Insp Repts 50-400/83-22 & 50-401/83-22 Corrective actions all shop welded joints requiring inservice insp will be identified & reworked to meet surface finish requirements
PARSONS, R M Carolina Power & Light Co 83/09/02 O'REILLY, J P Region 2, Office of Director 3pp 20626 241 24X Fiche 50-400, 83/09/13, 8310040595

--8310040603 Responds to NRC 830803 ltr re violations noted in IE Insp Repts 50-400/83-22 & 50-401/83-22 Corrective actions approx 150 deficiency & disposition repts reviewed by superintendent & QC for closure by QC/QA specialist
PARSONS, R M Carolina Power & Light Co 83/09/02 O'REILLY, J P Region 2, Office of Director, 5pp 20626 244 24X Fiche 50-400, 83/09/13, 8310040595

DOCKETED ITEMS

287

--B310040606 Responds to NRC 830803 ltr re violations noted in IE Insp Repts 50-400/83-22 & 50-401/83-22 Corrective actions Phase I
insps of hanger SA-H-123 declared preliminary & Phase II
insps considered insp of record
PARSONS, R M Carolina Power & Light Co 83/08/31 D'REILLY, J P
Region 2, Office of Director 2pp 20626 249 24X
Fiche 50-400, 83/09/13, 8310040595

--B310040608 Forwards IE Insp Repts 50-400/83-22 & 50-401/83-22 on 830620-0720 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/08/03
UTLEY, E E Carolina Power & Light Co 2pp 20626 251 24X
Fiche 50-400, 83/09/13, 8310040595

--B310040610 Notice of violation from insp on 830620-0720
* Region 2, Office of Director 83/08/03 2pp 20626 253 24X
Fiche 50-400, 83/09/13, 8310040595

--B310040613 IE Insp Repts 50-400/83-22 & 50-401/83-22 on 830620-0720
Noncompliance noted failure to comply w/procurement
requirements, control nonconformance repts & to follow
procedure for hanger insp
MAXWELL, G F, PREVATTE, R L Region 2, Office of Director
BEMIS, P R Division of Project & Resident Programs 83/08/02
7pp 20626 255 24X Fiche 50-400, 83/09/13, 8310040595

B310280176 Responds to FOIA request re const flaws & improper conduct
of NRC inspectors & util contractors or subcontractors
Forwards documents listed in App A Review of addl
documentation continuing
FELTON, J M Division of Rules and Records 83/09/23 VAUGHN, T.
News & Observer 3pp 20963 288 24X Fiche 50-400, 83/09/23, 8310280176

--B310280193 Documents O Zacher 790212 request for current status of
remand hearing & NRC actions re recommendations in Ofc of
Inspector & Auditor repts Recommendations will be adopted
FOSTER, W H Office of Inspector & Auditor 79/02/13 Office of
Inspector & Auditor 1p 20963 291 24X Fiche 50-400, 83/09/23, 8310280176

--B310280250 Advises that HA Wilbur perusal of Dance testimony disclosed
no ref to GA problems listed in subj insp repts
FOSTER, W H Office of Inspector & Auditor 78/10/10. Office of
Inspector & Auditor 1p 20963 326 24X Fiche 50-400, 83/09/23, 8310280176

B308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder
Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

B308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
Detectors Positioned at Control Room Ventilation Air
Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

B308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse
Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 118pp 20778 001, 24X Fiche 50-000, 83/09/26, 8308300345

B308300349 IE Info Notice 83-64, "Lead Shielding Attached to
Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New
York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

B310250628 Forwards IE Insp Repts 50-400/83-28 & 50-401/83-28 on
830820-0920 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/10/05
UTLEY, E E Carolina Power & Light Co 2pp. 20900 158 24X
Fiche 50-400, 83/10/05, 8310250628

--B310250632 IE Insp Repts 50-400/83-28 & 50-401/83-28 on 830820-0920
No noncompliance noted Major areas inspected concrete,
storage, welding & steam generator mods
MAXWELL, G F, PREVATTE, R L, BEMIS, P R Region 2, Office of
Director 83/10/05 5pp 20900 160 24X Fiche 50-400, 83/10/05, 8310250628

B308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass
Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 76pp 20827 213, 24X Fiche 50-000, 83/10/07, 8308300378

B308300752 IE Info Notice 83-66, "Fatality at Argentine Critical
Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

B308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect
Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

B308300761 IE Info Notice 83-68, "Respirator User Warning Defective
Self-Contained Breathing Apparatus Air Cylinders " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761.

B310250208 Ack receipt of B30923 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-400/83-16
LEWIS, R C Division of Project & Resident Programs 83/10/13
UTLEY, E E Carolina Power & Light Co 1p 20893 323 24X
Fiche 50-400, 83/10/13, 8310250208

--B310250211 Responds to NRC 830517 ltr re violations noted in IE Insp
Rept 50-400/83-16 Corrective actions surveillance teams,
consisting of QC welding inspector & discipline engineer,
will survey cable tray supports & identify problem areas.
PARSONS, R M Carolina Power & Light Co 83/09/23 D'REILLY, J P
Region 2, Office of Director 3pp 20893 324 24X
Fiche 50-400, 83/10/13, 8310250208

B310210136 Forwards addl info re fire protection, including response to
Safety Review Question 280 1, revised safe shutdown analysis
w/exemptions & mods, info requested in 830926-27 meetings w/
NRC & response to Enforcement Action 83-41
MCDOUFFIE, M A Carolina Power & Light Co 83/10/14 BENTON, H R
Office of Nuclear Reactor Regulation, Director. 479pp 20856 151
24X Fiche 50-400, 83/10/14, 8310210136

B310250571 Comments on detection of deficiencies in quality resulting
from suppliers fraudulent actions, described in IE Info
Notices 83-07 & 83-01 & IE Bulletin 83-06 & 83-07, Use of
addl insp & testing during receipt insps investigated
MCDOUFFIE, M A Carolina Power & Light Co 83/10/21. DEYOUNG, R. C.
Director's Office, Office of Inspection and Enforcement 1p.
20900 347 24X Fiche 50-000, 83/10/21, 8310250571

R Periodic operating reports & related correspondence

B310250450 "Seismic Monitoring Program Quarterly Data Rept, Jul-Sept
1983 " W/831019 ltr
ZIMMERMAN, S R Carolina Power & Light Co 83/09/30. DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 2pp. 20897 158
24X Fiche 50-400, 83/09/30, 8310250450

S Reportable occurrences, LERs & related correspondence

B310030526 Final deficiency rept, item 105 re auxiliary relay cabinets
supplied by Sys Control Corp Vendor supplied revised
drawings w/critical welds identified & has completed seismic
analysis to determine structural integrity
PARSONS, R M Carolina Power & Light Co. 83/09/21 D'REILLY, J P.
Region 2, Office of Director 4ppp 20601 186 24X
Fiche 50-400, 83/09/21, 8310030526

B310070163 Part 21 rept re potential defects in molded case of 100-
amp frame, multi-pole E & HE series circuit breakers
Initially reported on 830902
ERHARDT, J V Gould, Inc 83/09/26 MURLEY, T E Region 1, Office
of Director 10pp 20659 095 24X Fiche 50-000, 83/09/26, 8310070163

B310060036 Third interim Deficiency Rept 77 re shop welding defects in
seismic Class I cable tray, conduit & HVAC hangers, Initially
reported on 820802 Final rept expected by 840301. Also
reportable per 10CFR21
PARSONS, R M Carolina Power & Light Co. 83/09/29 D'REILLY, J P
Region 2, Office of Director. 4pp 20647.087. 24X
Fiche 50-400, 83/09/29, 8310060036

B310060336 Interim deficiency rept, item 143 re weld deficiencies in
sections of ducts CC-1 & CC-2 & transformers 1D1, 1D2, 1E1 &
1E2 from Gould & Brown-Boveri Util awaiting vendor
response. Also reportable per Part 21.
PARSONS, R M Carolina Power & Light Co. 83/09/29 D'REILLY, J P
Region 2, Office of Director. 1p 20646.092 24X
Fiche 50-400, 83/09/29, 8310060336

DOCKETED ITEMS

8310120246 Second interim deficiency rept, item 94 re seismic pipe hangers previously accepted by GC inspector & item 72 re undersize skewed tee fillet welds on seismic pipe hangers initially reported on 820813 & 1103, respectively
PARSONS, R M Carolina Power & Light Co 83/10/03 O'REILLY, J P
Region 2, Office of Director 5pp 20692 108 24X
Fiche 50-400, 83/10/03, 8310120246

8310120367 Second interim deficiency rept, items 95 & 72 & Part 21 rept re shop welding deficiencies in seismic 1 pipe hangers supplied by Bergen-Paterson Initially reported on 820813 & 1103 All active hangers corrected
PARSONS, R M Carolina Power & Light Co 83/10/03 O'REILLY, J P
Region 3, Office of Director 5pp 20699 299 24X
Fiche 50-400, 83/10/03, 8310120367

8310190171 Second interim deficiency rept, item 103 re main control board supplied by Westinghouse Initially reported on 821014 Deficient welding identified & repaired by vendor New scheduled completion date is 831230 Final rept by 840131
PARSONS, R M Carolina Power & Light Co 83/10/12 O'REILLY, J P
Region 2, Office of Director App 20821 076 24X
Fiche 50-400, 83/10/12, 8310190171

8310270206 Part 21 rept re engine mounted electrical cables Defective cable not installed as 830927 ltr states Parts shipped & installed on Gulf States River Bend Site (Engine Serial 74037/40 DSR 48) Instruction for cable changeout due in Nov.
BOYER, R E Transamerica Delaval, Inc 83/10/20 Director's Office, Office of Inspection and Enforcement 1p 20924 108 24X
Fiche 50-000, 83/10/20, 8310270206

DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8310280174 FOIA request for all internal nonpublic documentation re const flaws & improper conduct by inspectors, util contractors or subcontractors
MCINNIS, D News & Observer 83/07/19 FELTON, J Division of Rules and Records 1p 20963 287 24X Fiche 50-400, 83/07/19, 8310280174

8310030161 Advises that organizational changes for QA program & changes to FBARS & mgt capability rept will be forwarded when completed
UTLEY, E E Carolina Power & Light Co 83/09/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 20590 028 24X
Fiche 50-000, 83/09/13, 8310030161

8310040354 Summarizes 830831 meeting w/util re plans for restructuring corporate organization
O'REILLY, J P Region 2, Office of Director 83/09/22 UTLEY, E E
Carolina Power & Light Co 2pp 20620 331 24X
Fiche 50-000, 83/09/22, 8310040354

8310280176 Responds to FOIA request for internal nonpublic documentation re const flaws & improper conduct of NRC inspectors & util contractors or subcontractors Forwards documents listed in App A
FELTON, J M Division of Rules and Records 83/09/23 VALEN, T
News & Observer 3pp 20963 288 24X Fiche 50-400, 83/09/23, 8310280176

--8310280197 Forwards draft Ofc of Inspector & Auditor 781109 rept on inquiry into alleged omission of line inspector views from CP hearing, for perusal w/o encl
MURRAY, J P Deputy Executive Legal Director 78/12/18
CUMMINGS, J J Office of Inspector & Auditor 3pp 20963 292 24X Fiche 50-400, 83/09/23, 8310280176

--8310280202 Documents telcon w/FC Cantrell re insp file in preparation for testimony instructions not received to review file Cantrell relied solely on personal notes & records to prepare testimony
FOSTER, W H Office of Inspector & Auditor 78/11/01 Office of Inspector & Auditor 1p 20963 295 24X Fiche 50-400, 83/09/23, 8310280176

--8310280207 Advises that ASLAB Chairman, AS Rosenthal will decline interview, claiming purposelessness
FOSTER, W H Office of Inspector & Auditor 78/10/26 Office of Inspector & Auditor 1p 20963 296 24X Fiche 50-400, 83/09/23, 8310280176

--8310280211 Advises that IE Manual Chapter 94010-B only written policy for preparing testimony for licensing hearings, per 781025 telcon w/RC Paulus
FOSTER, W H Office of Inspector & Auditor 78/10/26 Office of Inspector & Auditor 1p 20963 297 24X Fiche 50-400, 83/09/23, 8310280176

--8310280214 Forwards AS Rosenthal 781024 memo to DG Abston, for perusal
ABSTON, D G Office of Inspector & Auditor 78/10/25
HENDRIE, J M Commissioners 1p 20963 298 24X
Fiche 50-400, 83/09/23, 8310280176

--8310280218 Advises that ASLAB members not willing to be interviewed due to possible future involvement in case
ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel 78/10/24
ABSTON, D G Office of Inspector & Auditor 1p 20963 299 24X Fiche 50-400, 83/09/23, 8310280176

--8310280222 Requests interview w/ASLAB members to discuss impact of omission of line inspector views from written & oral testimony
ABSTON, D G Office of Inspector & Auditor 78/10/24
ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel 1p 20963 300 24X Fiche 50-400, 83/09/23, 8310280176

--8310280225 Forwards info re Ofc of Inspector & Auditor interview of ASLAB (ref Yore 781019 memo to Commissioners)
FRYE, J H Atomic Safety and Licensing Board Panel 78/10/20
ROSENTHAL, A S, KELLEY, J L, ABSTON, D G NRC - No Detailed Affiliation Given 1p 20963 301 24X Fiche 50-400, 83/09/23, 8310280176

--8310280236 Forwards DH Gamble 781019 memo, for interest
ABSTON, D G Office of Inspector & Auditor 78/10/20
HENDRIE, J M Commissioners 1p 20963 312 24X
Fiche 50-400, 83/09/23, 8310280176

--8310280238 Summarizes A Rosenthal 781019 telcon opposing potential interview w/ASLAB members, citing unpleasantness of ASLB interview Ofc of Inspector & Auditor must assure different line of questioning before interview is granted
GAMBLE, D H Office of Inspector & Auditor 78/10/19 Office of Inspector & Auditor 2pp 20963 313 24X Fiche 50-400, 83/09/23, 8310280176

--8310280242 Forwards documentation of 781017 conversation w/JM Varela, former AEC employee re V Brownlee Conversation connected w/ current investigation
DAVIS, J O Director's Office, Office of Inspection and Enforcement 78/10/19 ABSTON, D G Office of Inspector & Auditor 1p 20963 315 24X Fiche 50-400, 83/09/23, 8310280176

--8310280244 Documents 781017 conversation w/J Varela, former Region 11 employee Brownlee directed Varela to change info in insp rept, causing dispute
DAVIS, J O Director's Office, Office of Inspection and Enforcement 78/10/19 Director's Office, Office of Inspection and Enforcement 1p 20963 316 24X Fiche 50-400, 83/09/23, 8310280176

--8310280246 Documents 781017 conversation w/C Barth (DELD) re testimony forwarded to ASLB before 771004 hearing ASLB should be required to read testimony before hearing
FOSTER, W H Office of Inspector & Auditor 78/10/18 Office of Inspector & Auditor 1p 20963 317 24X Fiche 50-400, 83/09/23, 8310280176

--8310280248 Advises of Ofc of Inspector & Auditor inability to procure useful info during interview w/ASLB due to ASLB unresponsiveness
ABSTON, D G Office of Inspector & Auditor 78/10/17
HENDRIE, J M, GILINSKY, V, KENNEDY, R T Commissioners 2pp 20963 324 24X Fiche 50-400, 83/09/23, 8310280176

--8310280250 Advises that HA Wilbur perusal of Dance testimony disclosed no ref to QA problems listed in subj insp repts
FOSTER, W H Office of Inspector & Auditor 78/10/10 Office of Inspector & Auditor 1p 20963 326 24X Fiche 50-400, 83/09/23, 8310280176

--8310280254 Forwards case assignments for ASLB members GD Bright, JV Leeds & IW Smith, per request
FITZ, C J Atomic Safety and Licensing Board Panel 78/10/06
GAMBLE, D H Office of Inspector & Auditor 6pp 20963 327 24X Fiche 50-400, 83/09/23, 8310280176

--8310280256 Forwards Acting General Counsel opinion indicating no ex parte problem w/Ofc of Inspector & Auditor interview of ASLB members
ABSTON, D G Office of Inspector & Auditor 78/10/03 YORE, J R, ROSENTHAL, A S Atomic Safety and Licensing Board Panel 1p 20963 333 24X Fiche 50-400, 83/09/23, 8310280176

--8310280259 Informs of 781003 conversation w/I Smith of ASLB re Ofc of Inspector & Auditor interview w/ASLB members, to fulfill Commission order Interview will probably not be granted due to ex parte rule
FOSTER, W H Office of Inspector & Auditor 78/10/03 Office of Inspector & Auditor 1p 20963 335 24X Fiche 50-400, 83/09/23, 8310280176

DOCKETED ITEMS

289

- 8310280263 Summarizes continued attempts to gain ASLB interview through 780927 conversation w/JV Leeds Leeds will not cooperate, citing as par te rule
FOSTER, W H Office of Inspector & Auditor 78/09/27 Office of Inspector & Auditor 2pp 20963 336 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280265 Informs of alleged improprieties re deficiency discrepancy repts & corresponding logbook entries
VORSE, J Y Office of Investigation 83/03/04 ALBERSON, C V NRC - No Detailed Affiliation Given 1p 20963 338 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280270 Discusses alleged improprieties re deficiency discrepancy repts & corresponding logbook entries
BURCH, R H Office of Investigation 83/03/03 Office of Investigation 1p 20963 339 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280299 Advises that no new info revealed after inquiry of alleged improprieties re deficiency discrepancy repts & corresponding logbook entries
VORSE, J Y Office of Investigation 83/05/06 TODD, G NRC - No Detailed Affiliation Given 1p 20963 340 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280303 Advises that inquiry into alleged improprieties re deficiency discrepancy repts & corresponding logbook entries (closed Util) cited for violation
BURCH, R H Office of Investigation 87/05/04 Office of Investigation 1p 20963 341 24X Fiche 50-400, 83/09/23, 8310280176
- 8310070120 Forwards response to requests for addl info, including response to Rev 1 to "Basis for Auxiliary Feedwater Sys Flow Requirements," in support of safety review Response includes info re main steam turbine valve testing issue
MCUFFIE, M A Carolina Power & Light Co 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 41pp 2065B 341 24X Fiche 50-400, 83/09/30, 8310070120
- 8310310172 Forwards NRC 830921 ltr to util advising of acceptance of design, analyses, matls & const aspects of containment vessel w/d deficiencies, in response to Resolution 1443-83
MCVAX, T M Assistant Director for Licensing 83/10/18 EULER, G A Perry, DH 3pp 20965 288 24X Fiche 50-400, 83/10/18, 8310310172
- E NRC Safety Evaluation Report (SER), supplis & correspondence
- 8310130240 Forwards addl info in response to draft SER Open Item 354, including Mechanical Engineering Branch questions in 830819 & 25 ltrs
MCUFFIE, M A Carolina Power & Light Co 83/09/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 20722 236 24X Fiche 50-400, 83/09/19, 8310130240
- 8310130248 QC Procedure 120, "Hydrostatic Testing (Critical Svc) "
* Goulds Pumps, Inc 80/07/01 3pp 20722 242 24X Fiche 50-400, 83/09/19, 8310130240
- 8310130254 Rev 3 to QA Instruction QAI-212, "Training & Qualification of QA Personnel "
* Goulds Pumps, Inc 80/06/18 11pp 20722 245 24X Fiche 50-400, 83/09/19, 8310130240
- 8310130261 "Seismic Qualification Envelope Limitorque Valve Actuators
DRAB, J B, DENKOWSKI, W J, FORNICA, C D Limitorque Corp 10037 80/01/11 24pp 20722 256 24X Fiche 50-400, 83/09/19, 8310130240
- 8310130267 Rev 1 to "Rept of Test on Seismic Vibration Testing of One Limitorque SMB-000/HQBC Actuator for Limitorque Corp "
ESP08110, B, CABAUBON, M, TOLF, M L Acton Environ Testing Corp 14331-2 R01 79/03/13 16pp 20722 280 24X Fiche 50-400, 83/09/19, 8310130240
- 8310130271 Rev 1 to "Rept of Test on Seismic Vibration Testing One Limitorque SMB-000/HQBC Actuator W/Seismic Adaptor for Limitorque Corp "
ESP08110, B, CABAUBON, M, TOLF, M L Acton Environ Testing Corp 14331-3 R01 79/03/13 12pp 20722 296 24X Fiche 50-400, 83/09/19, 8310130240
- 8310130273 "Seismic Test SMB-000/HQBC "
YOUNG, P T Limitorque Corp 80045 83/09/19 6pp 20722 308 24X Fiche 50-400, 83/09/19, 8310130240
- 8310130277 Rev 1 to "Rept of Test on Seismic Vibration Testing of Limitorque SMB-1/HQBC Actuators for Limitorque Corp "
ESP08110, B, CILFOY, R, TOLF, M L Acton Environ Testing Corp 14801-1 R01 79/06/11 41pp 20722 314 24X Fiche 50-400, 83/09/19, 8310130240
- 8310130280 "Rept of Fragility Test on SMB-1-25/H4BC W/Std Cast Adapter for Limitorque Corp "
* Aero Nav Laboratories, Inc 5-6167-5 75/12/17 36pp 20722 355 24X Fiche 50-400, 83/09/19, 8310130240
- 8310130282 Rev 0 to Engineering Spec JSN-TJ35, "Seat Testing & Disc Hydrostatic Testing - 5 Minute Duration "
* Jamesbury Corp 78/01/24 11pp 20723 029 24X Fiche 50-400, 83/09/19, 8310130240
- 8310130285 Rev 0 to Procedure 4-106, "Cold Bending of Carbon Steel & Ferritic Alloy "
* Southwest Fabricating & Welding Co (subs of IU International Corp) 73/05/04 3pp 20723 040 24X Fiche 50-400, 83/09/19, 8310130240
- 8310130287 Rev 0 to Procedure 4-107, "Cold Bending of Austenitic Stainless Steel Piping "
* Southwest Fabricating & Welding Co (subs of IU International Corp) 73/05/04 3pp 20723 043 24X Fiche 50-400, 83/09/19, 8310130240
- 8310130289 Rev 0 to Procedure 4-108, "Hot Bending of Carbon Steel & Ferritic Alloys "
* Southwest Fabricating & Welding Co (subs of IU International Corp) 73/05/04 3pp 20723 046 24X Fiche 50-400, 83/09/19, 8310130240
- 8310130290 Rev 0 to Procedure 4-109, "Hot Bending of Austenitic Stainless Steel Piping "
* Southwest Fabricating & Welding Co (subs of IU International Corp) 73/05/04 11pp 20723 051 24X Fiche 50-400, 83/09/19, 8310130240
- 8310130291 Procedure MNE-65, "Pipe Line Sizing Guide "
* Ebasco Services, Inc (subs of Enserch Corp) 70/06/20, 7pp 20723 062 24X Fiche 50-400, 83/09/19, 8310130240
- 8310130293 Rev B to Site Spec 030, "Field Fabrication & Erection of Power Pipe "
* Carolina Power & Light Co 83/03/29 23pp 20723 049 24X Fiche 50-400, 83/09/19, 8310130240
- 8310130294 Engineering Procedure 3 2, "Design Change Control "
* Carolina Power & Light Co 83/08/19 52pp 20723 092 24X Fiche 50-400, 83/09/19, 8310130240
- 8310170124 Summary of 830825 meeting w/util & Ebasco in Bethesda, MD re Meteorological & Effluents Treatment Sys Branch draft SER open items
BUCKLEY, B C, HOLONICH, J Licensing Branch 3 83/09/29 Licensing Branch 3 8pp 20813 037 24X Fiche 50-400, 83/09/29, 8310170124
- 8310110119 Forwards amended response to request for addl info re draft SER Open Item 38 concerning technical basis for QDC-51 compliance Responses to other requests will be provided shortly
MCUFFIE, M A Carolina Power & Light Co 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 150pp 20867 038 24X Fiche 50-400, 83/09/30, 8310110119
- 8310120180 Forwards response to request for addl info re draft SER open items on reevaluation of PMP, plant area water accumulation & adequacy of electric distribution sys voltages
MCUFFIE, M A Carolina Power & Light Co 83/10/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 20895 301 24X Fiche 50-400, 83/10/05, 8310120180
- 8310140126 Forwards response to NRC Question 210 59 re piping spec, loading combinations & stress limits completing response to 32 Mechanical Engineering Branch questions in 830819 & 25 ltrs for SER Open Item 354
MCUFFIE, M A Carolina Power & Light Co 83/10/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 21pp 20765 045 24X Fiche 50-400, 83/10/10, 8310140126
- 8310180474 Forwards responses to draft SER Open Items 355-383, discussed at 830921 meeting w/Auxiliary Sys Branch in Bethesda, MD
MCUFFIE, M A Carolina Power & Light Co 83/10/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 37pp 20801 331 24X Fiche 50-400, 83/10/11, 8310180474
- 8310180311 Forwards addl info re draft SER open items, in response to Mechanical Engineering, Power Sys & Reactor Sys Branch concerns Westinghouse Owners Group Jul 1977 rept & Sept 1977 suppl will be used in derivation of setpoints
MCUFFIE, M A Carolina Power & Light Co 83/10/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 27pp 20803 076 24X Fiche 50-400, 83/10/12, 8310180311

DOCKETED ITEMS

8310210024 Forwards responses to requests for addl info re draft SER open items
MCDUFFIE, M A Carolina Power & Light Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 55pp 20856 017
24X Fiche 50-400, 83/10/14, 8310210024

8310250638 Forwards supplemental info in response to Siting Analysis Branch concerns re SER Item 7 Seaboard Sys Railroad provided assistance in preparation of supplemental info Encl withheld (ref 10CFR2 790)
MCDUFFIE, M A Carolina Power & Light Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20899 314
24X Fiche 50-400, 83/10/14, 8310250638

8310260259 Forwards proprietary & nonproprietary versions of "Table of Control Rod Drive Mechanism (CRDM) 400 Series Stainless Steel Items," in response to Matls Engineering Branch draft SER open items Proprietary table withheld (ref 10CFR2 790)
MCDUFFIE, M A Carolina Power & Light Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20909 209
24X Fiche 50-400, 83/10/14, 8310260259

--8310260267 Application for withholding proprietary "Table of Control Rod Drive Mechanism (CRDM) 400 Series Stainless Steel Items," per 10CFR2 790 W/affidavit
WIEBEMANN, R A Westinghouse Electric Corp 83/10/11 LIAM, B D
Materials Engineering Branch 10pp 20909 211 24X
Fiche 50-400, 83/10/14, 8310260259

--8310260283 Nonproprietary "Table of Control Rod Drive Mechanism (CRDM) 400 Series Stainless Steel Items"
* Westinghouse Electric Corp 83/10/14 1p 20909 221 24X
Fiche 50-400, 83/10/14, 8310260259

8310260147 Forwards responses to requests for addl info re draft SER Open Items 63 & 67 Responses verify containment pressure & justify operation of normal containment purge sys
MCDUFFIE, M A Carolina Power & Light Co 83/10/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 20912 220
24X Fiche 50-400, 83/10/20, 8310260147

8310260152 Forwards response to NRC request for addl info re emergency diesel generator load sequence reliability (draft SER Open Item 310) Applicant in process of performing PRA on sequencer
MCDUFFIE, M A Carolina Power & Light Co 83/10/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20912 232
24X Fiche 50-400, 83/10/20, 8310260152

8310260134 Forwards response to request for addl info re draft SER Open Item 77 Shunt trip attachment mod will be implemented, per Generic Ltr 83-28
MCDUFFIE, M A Carolina Power & Light Co 83/10/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20912 226
24X Fiche 50-400, 83/10/21, 8310260134

8310280014 Forwards nonproprietary & proprietary responses to request for addl info re criticality analyses for spent fuel racks Draft SER Open Item 360 completed Proprietary response withheld (ref 10CFR2 790)
MCDUFFIE, M A Carolina Power & Light Co 83/10/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 20929 026
24X Fiche 50-400, 83/10/21, 8310280014

F Security, medical, emergency & fire protection plans

8310170070 Summary of 830825 meeting w/util & Ebasco re fire protection program & safe shutdown analysis
HOLNICH, J J Licensing Branch 1 BUCKLEY, B C Licensing Branch 3
83/09/30 Licensing Branch 1 3pp 20798 019 24X
Fiche 50-400, 83/09/30, 8310170070

--8310180183 Summary of 830926 & 27 meetings w/util & Ebasco re fire protection open items, drawing review & Auxiliary Sys Branch inclusion of safe shutdown analysis
HOLNICH, J J Licensing Branch 3 HOLNICH, J J Licensing Branch 1
83/09/30 Licensing Branch 2 9pp 20827 014 24X
Fiche 50-400, 83/09/30, 8310180183

1020266 Forwards Rev 1 to emergency plan Evacuation time study scheduled for completion by 831231
LEY, E E Carolina Power & Light Co 83/10/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20688 001
X Fiche 50-400, 83/10/04, 8310120266

10120268 Rev 1 to emergency plan
* Carolina Power & Light Co 83/09/30 63pp 20688 001 24X
Fiche 50-400, 83/10/04, 8310120266

8310210136 Forwards addl info re fire protection, including response to Safety Review Question 280 i, revised safe shutdown analysis, w/exemptions & mods, info requested in 830926-27 meetings w/NRC & response to Enforcement Action 83-41
MCDUFFIE, M A Carolina Power & Light Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 475pp 20896 131
24X Fiche 50-400, 83/10/14, 8310210136

G Adjudicatory correspondence

8310030441 Response to general interrogatories & interrogatories on Contention 8F(1) Related correspondence
CARROW, H Carolina Power & Light Co 83/09/23 EDDLEMAN, W
Eddleman, W 16pp 20602 049 24X Fiche 50-400, 83/09/23, 8310030441

--8310030478 Response to request for production of documents on Contention 8F(1) Certificate of Svc encl
CARROW, H Carolina Power & Light Co 83/09/23 EDDLEMAN, W
Eddleman, W 4pp 20602 085 24X Fiche 50-400, 83/09/23, 8310030441

8310030367 Response opposing util motion for summary disposition of Eddleman Contention 8D re mixing & dispersion models Statement of facts as to which there are issues to be heard encl
EDDLEMAN, W Eddleman, W 83/09/27 Atomic Safety and Licensing Board Panel 6pp 20593 009 24X Fiche 50-400, 83/09/27, 8310030367

--8310030369 Response opposing util motion for summary disposition of Eddleman Contention 75 on claims Statement of facts as to which there are issues to be heard encl
EDDLEMAN, W Eddleman, W 83/09/27 Atomic Safety and Licensing Board Panel 8pp 20593 015 24X Fiche 50-400, 83/09/27, 8310030367

--8310030372 Response opposing util motion for summary disposition of Eddleman Contention 83/84 re carcinogenic discharges Statement of facts as to which there are issues to be heard encl
EDDLEMAN, W Eddleman, W 83/09/27 Atomic Safety and Licensing Board Panel 4pp 20593 024 24X Fiche 50-400, 83/09/27, 8310030367

--8310030375 Response to util motion for summary disposition of Eddleman Contention 64F
EDDLEMAN, W Eddleman, W 83/09/27 Atomic Safety and Licensing Board Panel 2pp 20593 030 24X Fiche 50-400, 83/09/27, 8310030367

--8310030377 Motion for license condition on spent fuel shortage if Contention 64F withdrawn
EDDLEMAN, W Eddleman, W 83/09/27 Atomic Safety and Licensing Board Panel 5pp 20593 032 24X Fiche 50-400, 83/09/27, 8310030367

--8310030380 Response partly opposing util proposed schedule rev Certificate of Svc encl
EDDLEMAN, W Eddleman, W 83/09/27 Atomic Safety and Licensing Board Panel 2pp 20593 037 24X Fiche 50-400, 83/09/27, 8310030367

8310040523 Notifies that util counsel & author agreed to negotiate next wk on util responses to Eddleman Interrogatories 15AA & 8F1 Notice tolls time for filing motion to compel
EDDLEMAN, W Eddleman, W 83/09/28 KELLEY, J Atomic Safety and Licensing Board Panel 1p 20624 234 24X Fiche 50-400, 83/09/28, 8310040523

8310040518 Response re 10CFR2 75B petition of 830630 on need for power & alternatives Certificate of Svc encl
EDDLEMAN, W Eddleman, W 83/09/30 Atomic Safety and Licensing Board Panel 89pp 20623 001 24X Fiche 50-400, 83/09/30, 8310040518

8310040538 Forwards Page 10, inadvertently omitted from util 830926 reply to W Eddleman response to ASLB 830824 order
O'NEILL, J H Shaw, Pittman, Potts & Trowbridge O'NEILL, J H
Carolina Power & Light Co 83/09/30 KELLEY, J L, BRIGHIT, C I, CARPENTER, J H Atomic Safety and Licensing Board Panel 1p 20623 297 24X Fiche 50-400, 83/09/30, 8310040538

--8310040541 Page 10, inadvertently omitted from util 830929 reply to W Eddleman response to ASLB 830824 order, Svc list encl
* Carolina Power & Light Co 83/09/30 Atomic Safety and Licensing Board Panel 3pp 20623 498 24X Fiche 50-400, 83/09/30, 8310040538

- 8310050565 Response supporting util 830912 motion to modify schedule on environ contentions Issuance of FES by 831031 should be factored into scheduler mods Certificate of Svc encl
BARTH, C A Hearing Branch 1 83/10/03 Atomic Safety and Licensing Board Panel 3pp 20629 03/ 24X Fiche 50-400, 83/10/03, 8310050565
- 8310060188 Forwards motion for summary disposition of Joint intervenors Contention II & W Eddleman Contention 37B on health effects Related correspondence
O'NEILL, J H Shaw, Pittman, Potts & Trowbridge O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/10/03 Atomic Safety and Licensing Board Panel 2pp 20649 001 24X Fiche 50-400, 83/10/03, 8310060188
- 8310060193 Motion for summary disposition of Joint intervenors Contention II & W Eddleman Contention 37B re health effects No genuine issue of matl fact exists & util entitled to favorable decision Related correspondence
AULICK, D D Carolina Power & Light Co AULICK, D D Shaw, Pittman, Potts & Trowbridge 83/10/03 Atomic Safety and Licensing Board Panel 62pp 20649 003 24X Fiche 50-400, 83/10/03, 8310060188
- 8310060203 Statement of matl facts as to which there is no genuine issue re Joint intervenors Contention II & W Eddleman Contention 37B Related correspondence
AULICK, D D Carolina Power & Light Co AULICK, D D Shaw, Pittman, Potts & Trowbridge 83/10/03 Atomic Safety and Licensing Board Panel 13pp 20649 071 24X Fiche 50-400, 83/10/03, 8310060188
- 8310060212 Affidavit of JI Fabrikant re health effects estimates in DES Somatic & genetic health effect estimates in DES are not underestimated Prof qualifications encl Related correspondence
FABRIKANT, J I Carolina Power & Light Co FABRIKANT, J I Lawrence Livermore Laboratory 83/10/01 120pp 20649 084 24X Fiche 50-400, 83/10/03, 8310060188
- 8310060222 Affidavit of OH Whipple supporting util motion for summary disposition of Joint intervenors Contention II NRC models use concentrations, doses & health effects unaffected by incomplete mixing or dispersion Related correspondence
WHIPPLE, O H Carolina Power & Light Co 83/09/30 16pp 20649 209, 24X Fiche 50-400, 83/10/03, 8310060188
- 8310060238 Affidavit of JJ Mauro supporting util motion for summary disposition of Joint intervenors Contention II & Eddleman Contention 37B DES determined max ratio of health effects from plant operation Related correspondence
MAURO, J J Carolina Power & Light Co MAURO, J J Ebasco Services, Inc (subs of Enserch Corp) 83/10/03 18pp 20649 225 24X Fiche 50-400, 83/10/03, 8310060188
- 8310060323 Notice of appearance in proceeding Certificate of Svc encl
AULICK, D D Carolina Power & Light Co AULICK, D D Shaw, Pittman, Potts & Trowbridge 83/10/03 5pp 20646 227 24X Fiche 50-400, 83/10/03, 8310060323
- 8310101050 Motion for summary disposition of Eddleman Contention 29/30 (App I compliance) No genuine issue of matl fact exists & applicant entitled to favorable decision Related correspondence
O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/10/05 Atomic Safety and Licensing Board Panel 50pp 20665 135 24X Fiche 50-400, 83/10/05, 8310101050
- 8310101055 Statement of matl facts as to which there is no genuine issue re Eddleman Contention 29/30
O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/10/05 Atomic Safety and Licensing Board Panel 10pp 20665 186 24X Fiche 50-400, 83/10/05, 8310101050
- 831010407 Affidavit of JJ Mauro & G Martin in support of applicant motion for summary disposition of W Eddleman Contention 29/30
MAURO, J J, MARTIN, G Carolina Power & Light Co. 83/10/03, 58pp 20665 196 24X Fiche 50-400, 83/10/05, 8310101050
- 831010409 Affidavit of RL Shearin in support of applicant motion for summary disposition of W Eddleman Contention 29/30
SHEARIN, R L Carolina Power & Light Co. 83/09/30 8pp 20665 254 24X Fiche 50-400, 83/10/05, 8310101050
- 831010412 Affidavit of TJ Grant in support of applicant motion for summary disposition of W Eddleman Contention 29/30 Certificate of Svc encl
GRANT, T J Carolina Power & Light Co 83/09/30 16pp 20665 262 24X Fiche 50-400, 83/10/05, 8310101050
- 831010209 Memorandum & order ruling on discovery disputes Motions to compel & for protective order granted/denied as noted
KELLEY, J L Atomic Safety and Licensing Board Panel 83/10/06 Eddleman, W 16pp 20665 073 24X Fiche 50-400, 83/10/06, 831010209.
- 831010218 Memorandum & order admitting some of W Eddleman late-filed contentions on detailed control room design review R Wilson
830921 & Conservation Council of North Carolina 830824 motions to withdraw contentions granted
BRIGHT, O D, CARPENTER, J H, KELLEY, J L Atomic Safety and Licensing Board Panel 83/10/06 Conservation Council of North Carolina, 14pp 20665 042 24X Fiche 50-400, 83/10/06, 831010218
- 8310120370 Response to interrogatories on Contentions 19AA & BF1 Certificate of negotiations & Certificate of Svc encl
EDDLEMAN, W Eddleman, W 83/10/06 Carolina Power & Light Co 18pp 20699 254 24X Fiche 50-400, 83/10/06, 8310120370
- 8310140072 Revised Contention 161 re safety shutdown sys failure. Certificate of Svc encl
EDDLEMAN, W Eddleman, W 83/10/11 Atomic Safety and Licensing Board Panel 2pp 20766 357 24X Fiche 50-400, 83/10/11, 8310140072
- 8310140065 Erratum to ASLB 831006 memorandum & order ruling on W Eddleman proposed contentions re detailed control room design review & R Wilson & Conservation Council of North Carolina motions to withdraw contentions.
KELLEY, J L Atomic Safety and Licensing Board Panel. 83/10/12 EDDLEMAN, W Eddleman, W WILSON, R Wilson, R 2pp. 20768 007 24X Fiche 50-400, 83/10/12, 8310140065
- 8310170543 Forwards corrected version of util motion for summary disposition of Joint intervenors Contention II & W Eddleman Contention 37B on health effects
AULICK, D D Shaw, Pittman, Potts & Trowbridge AULICK, D D Carolina Power & Light Co 83/10/12 KELLEY, J L, BRIGHT, O D, CARPENTER, J H Atomic Safety and Licensing Board Panel 1p 20780 355 24X Fiche 50-400, 83/10/12, 8310170543
- 8310170608 Corrected copy of motion for summary disposition of Joint intervenors Contention II & W Eddleman Contention 37B on health effects Errata sheet encl
AULICK, D D Carolina Power & Light Co. AULICK, D D Shaw, Pittman, Potts & Trowbridge 83/10/03 Atomic Safety and Licensing Board Panel 61pp 20780 356 24X Fiche 50-400, 83/10/12, 8310170608.
- 8310170620 Fourth set of interrogatories & request for production of documents
O'NEILL, J H Carolina Power & Light Co. O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/10/12 Joint intervenors-Shearon Harris 15pp 20781 035 24X Fiche 50-400, 83/10/12, 8310170620
- 8310170630 Reply opposing W Eddleman 830927 motion for license condition on spent fuel storage. ASLB lacks jurisdiction over issues of health & safety re spent fuel transportation. Certificate of Svc encl
O'NEILL, J H Carolina Power & Light Co. O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/10/12, Atomic Safety and Licensing Board Panel 10pp, 20781 070 24X Fiche 50-400, 83/10/12, 8310170630.
- 8310170626 Response to 830831 interrogatories re Contention 37B concerning health impacts from exposure to radioactive matls
BRANAGAN, E F Radiological Assessment Branch, BARTH, C. Hearing Branch 1 83/10/12 EDDLEMAN, W Eddleman, W 3pp 20782 113 24X Fiche 50-400, 83/10/12, 8310170626
- 8310170632 Response to 830831 second set of interrogatories. Statement of prof qualifications & Certificate of Svc encl
SCHENK, O. A. Radiological Assessment Branch BARTH, C. A Hearing Branch 1. 83/10/12 EDDLEMAN, W Eddleman, W 54pp 20782 116 24X Fiche 50-400, 83/10/12, 8310170626
- 8310250469 Response opposing W Eddleman 830927 motion for license condition on spent fuel storage. Motion premature & not in conformity w/Commission regulations Certificate of Svc encl
BARTH, C. A Hearing Branch 1 83/10/17 Atomic Safety and Licensing Board Panel 4pp 20897 145 24X Fiche 50-400, 83/10/17, 8310250469
- 8310250125 Followup response to Interrogatory 4 on Contention 8(F)(1). Listed document will be placed in PDR
BARTH, C. A Hearing Branch 1 83/10/19, EDDLEMAN, W Eddleman, W, 1p. 20896 344 24X Fiche 50-400, 83/10/19, 8310250125

DOCKETED ITEMS

8310240183 Third supplemental responses to W Eddleman 831006 general interrogatories & interrogatories on Contentions 29 & 37H Certificate of Svc encl
O'BESS, J J Carolina Power & Light Co O'BESS, J J Shaw, Pittman, Potts & Trowbridge 83/10/20 Eddleman, W 11pp 20878 104 24X Fiche 50-400, 83/10/20, 8310240183

8310250167 Forwards Pages 26-32 of ALAB-653 re security plan contentions, per 831005 telcon request Pages withheld (ref 10CFR73 21)
BARTH, C A Hearing Branch 1 83/10/20 RUNKLE, J North Carolina, State of 1p 20894 061 24X Fiche 50-400, 83/10/20, 8310250167

8310250037 General interrogatories & interrogatories on Contentions 8F1, 8F2 & 15AA (sixth set) Related correspondence
EDDLEMAN, W Eddleman, W 83/10/21 Carolina Power & Light Co. 18pp 20894 115 24X Fiche 50-400, 83/10/21, 8310250037

8310250040 Interrogatories re Contentions 8F1, 8F2 & 15AA (second round, third set) Related correspondence
EDDLEMAN, W Eddleman, W 83/10/21 Office of the Executive Legal Director 6pp 20896 166 24X Fiche 50-400, 83/10/21, 8310250040

8310250086 Response to applicant interrogatories on Eddleman Contention 65 (sixth set) Certificate of Svc encl Related correspondence
EDDLEMAN, W Eddleman, W 83/10/21 Carolina Power & Light Co 8pp 20894 143 24X Fiche 50-400, 83/10/21, 8310250086

8310260202 Interrogatories & request for production of documents on Eddleman Contention 8F(1) Related correspondence
CARROW, H Consumers Power Co 83/10/21 EDDLEMAN, W Eddleman, W 4pp 20912 237 24X Fiche 50-400, 83/10/21, 8310260202

--8310260209 Second set of interrogatories & request for production of documents re Eddleman Contention 15AA Certificate of Svc encl Related correspondence
CARROW, H Consumers Power Co 83/10/21 EDDLEMAN, W Eddleman, W 9pp 20912 243 24X Fiche 50-400, 83/10/21, 8310260209

8310270319 Memorandum & order modifying schedule on environ contentions
KELLEY, J L Atomic Safety and Licensing Board Panel 83/10/25 5pp 20923 183 24X Fiche 50-400, 83/10/25, 8310270319

8310280051 Response opposing W Eddleman 831010 proposed rev to Contention 161 re safety shutdown sys Failure Rev fails to specify defects in original circuit breaker design Certificate of Svc encl
O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/10/25 Atomic Safety and Licensing Board Panel 14pp 20934 333 24X Fiche 50-400, 83/10/25, 8310280051

8310280164 Fifth set of interrogatories on Joint Contention VI re radiation detection & monitoring & request for production of documents
ANDERSON, P H Carolina Power & Light Co ANDERSON, P H Shaw, Pittman, Potts & Trowbridge 83/10/25 Joint Intervenor-Shearon Harris 16pp 20929 226 24X Fiche 50-400, 83/10/25, 8310280164

8310310146 Informs that DR Lewis, formerly ASLB participant in OL proceeding, began working for author on 831024 DR Lewis will not participate in OL proceeding
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A Carolina Power & Light Co 83/10/26 Commissioners 4pp 20959, 056 24X Fiche 50-400, 83/10/26, 8310310146

G. Inspection reports, IE Bulletins & correspondence

8310040595 Ack receipt of 830831 & 0902 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/83-22 & 50-401/83-22
LEWIS, R C Division of Project & Resident Programs 83/09/13, UTLEY, E E Carolina Power & Light Co. 1p 20626 240 24X Fiche 50-400, 83/09/13, 8310040595

--8310040600 Responds to NRC 830803 ltr re violations noted in IE Insp Repts 50-400/83-22 & 50-401/83-22 Corrective actions, all shop welded joints requiring inservice insp will be identified & reworked to meet surface finish requirements
PARSONS, R M Carolina Power & Light Co 83/09/02 O'REILLY, J P Region 2, Office of Director 3pp 20626 241 24X Fiche 50-400, 83/09/13, 8310040595

--8310040603 Responds to NRC 830803 ltr re violations noted in IF Insp Repts 50-400/83-22 & 50-401/83-22 Corrective actions approx 150 deficiency & disposition repts reviewed by superintendent & QC for closure by QC/QA specialist
PARSONS, R M Carolina Power & Light Co 83/09/02 O'REILLY, J P Region 2, Office of Director 5pp 20626 244 24X Fiche 50-400, 83/09/13, 8310040595

--8310040606 Responds to NRC 830803 ltr re violations noted in IE Insp Repts 50-400/83-22 & 50-401/83-22 Corrective actions Phase I insps of hanger SA-H-123 declared preliminary & Phase II insps considered insps of record
PARSONS, R M Carolina Power & Light Co 83/09/03 O'REILLY, J P Region 2, Office of Director 2pp 20626 249 24X Fiche 50-400, 83/09/13, 8310040595

--8310040608 Forwards IE Insp Repts 50-400/83-22 & 50-401/83-22 on 830620-0720 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/08/05 UTLEY, E E Carolina Power & Light Co 2pp 20626 251 24X Fiche 50-400, 83/09/13, 8310040595

--8310040613 IE Insp Repts 50-400/83-22 & 50-401/83-22 on 830620-0720 Noncompliance noted failure to comply w/procurement requirements, control nonconformance repts & to follow procedure for hanger insp
MAXWELL, G F, PREVATTE, R L Region 2, Office of Director BENIS, P R Division of Project & Resident Programs 83/08/02 7pp 20626 255 24X Fiche 50-400, 83/09/13, 8310040595

8310280176 Responds to FOIA request re const flaws & improper conduct of NRC inspectors & util contractors or subcontractors Forwards documents listed in App A Review of addl documentation continuing
FELTON, J M Division of Rules and Records 83/09/23 VADEN, T News & Observer 3pp 20963 288 24X Fiche 50-400, 83/09/23, 8310280176

--8310280173 Documents Q Zacher 790212 request for current status of noncompliance hearing & NRC actions re recommendations in Dfc of Inspector & Auditor reft Recommendations will be adopted
FOSTER, W H Office of Inspector & Auditor 79/02/13 Office of Inspector & Auditor 1p 20963 291 24X Fiche 50-400, 83/09/23, 8310280176

--8310280250 Advises that HA Wilbur perusal of Dance testimony disclosed no ref to QA problems listed in subj insp repts
FOSTER, W H Office of Inspector & Auditor 78/10/10 Office of Inspector & Auditor 1p 20963 326 24X Fiche 50-400, 83/09/23, 8310280176

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310250628 Forwards IE Insp Repts 50-400/83-28 & 50-401/83-28 on 830820-0920 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/10/05 UTLEY, E E Carolina Power & Light Co 2pp 20900 158 24X Fiche 50-400, 83/10/05, 8310250628

--8310250632 IE Insp Repts 50-400/83-28 & 50-401/83-28 on 830820-0920 No noncompliance noted Major areas inspected concrete, storage, welding & steam generator mds
MAXWELL, G F, PREVATTE, R L, BENIS, P R Region 2, Office of Director 83/10/05 5pp 20900 160 24X Fiche 50-400, 83/10/05, 8310250628

DOCKETED ITEMS

293

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

8310210136 Forwards addl info re fire protection, including response to Safety Review Question 280 1, revised safe shutdown analysis w/exceptions & mods, info requested in 830926-27 meetings w/ NRC & response to Enforcement Action 83-41
MC DUFFIE, M A Carolina Power & Light Co 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 475pp 20856 151 24X Fiche 50-400,83/10/14,8310210136

8310250571 Comments on detection of deficiencies in quality resulting from suppliers fraudulent actions, described in IE Info Notices 83-07 & 83-01 & IE Bulletins 83-06 & 83-07 Use of addl Insp & testing during receipt insps investigated
MC DUFFIE, M A Carolina Power & Light Co 83/10/21 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 20900 347 24X Fiche 50-000,83/10/21,8310250571

P Periodic operating reports & related correspondence

8310250450 "Seismic Monitoring Program Quarterly Data Rept, Jul-Sept 1983 " W/831019 ltr
ZIMMERMAN, B R Carolina Power & Light Co 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20897 158 24X Fiche 50-400,83/09/30,8310250450

S Reportable occurrences, LERs & related correspondence

8310070163 Part 21 rept re potential defects in molded case of 100-amp frame, multi-pole E & HE series circuit breakers
Initially reported on 830902
ERHARDT, J V Gould, Inc 83/09/26 MURLEY, T E Region 1, Office of Director 10pp 20659 095 24X Fiche 50-000,83/09/26,8310070163

8310060036 Third interim Deficiency Rept 77 re shop welding defects in seismic Class 1 cable tray, conduit & HVAC hangers initially reported on 820802 Final rept expected by 840301 Also reportable per 10CFR21
PARSONS, R M Carolina Power & Light Co 83/09/29 O'REILLY, J P Region 2, Office of Director 4pp 20647 087 24X Fiche 50-400,83/09/29,8310060036

8310060036 Interim deficiency rept, item 143 re weld deficiencies in sections of ducts CC-1 & CC-2 & transformers ID1, 102, 1E1 & 1E2 from Gould & Brown-Boveri Util awaiting vendor response Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co 83/09/29 O'REILLY, J P Region 2, Office of Director 1p 20646 092, 24X Fiche 50-400,83/09/29,8310060036

8310120367 Second interim deficiency rept, items 95 & 72 & Part 21 rept re shop welding deficiencies in seismic 1 pipe hangers supplied by Bergen-Paterson Initially reported on 820813 & 1103 All active hangers corrected
PARSONS, R M Carolina Power & Light Co, 83/10/03, O'REILLY, J P Region 3, Office of Director 5pp 20699 295, 24X Fiche 50-400,83/10/03,8310120367

8310270206 Part 21 rept re engine mounted electrical cables, defective cable not installed as 830927 ltr states Parts shipped & installed on Gulf States River Bend Site (Engine Serial 74039740 DSR 48) Instruction for cable changeout due in Nov
BOYER, R E Transamerica Delaval, Inc 83/10/20, Director's Office, Office of Inspection and Enforcement, 1p 20924 108, 24X Fiche 50-000,83/10/20,8310270206

DOCKET 50-406 TUSKEGEE INST RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

8310110426 Requests closeout insp of facility to verify residual radiological conditions, per 830809 request to terminate License R-122
THOMAS, C D Standardization & Special Projects Branch 83/10/03
VERRELLI, D M Division of Project & Resident Programs 1p 20714 342 24X Fiche 50-406,83/10/03,8310110426

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

F Security, medical, emergency & fire protection plans

8310130310 Releases public version of rev to emergency plan implementing procedure
FELTON, J M Division of Rules and Records, 83/10/06 Document Management Branch 1p 20769 014 24X Fiche 50-409,83/10/06,8310130310

--8310130311 Public version of issue 2 to Emergency Plan Implementing Procedure EPP-6, "Sample Collection & Analysis During Emergencies " W/830928 ltr
SHAFFER, P W, LINDER, F, Dairyland Power Cooperative 83/08/31
CRUTCHFIELD, D Operating Reactors Branch 5 38pp 20769:015 24X Fiche 50-409,83/10/06,8310130310

8310130203 Forwards summary of 830810 meeting & site tour re changes to physical security program
CRUTCHFIELD, D Operating Reactors Branch 5, 83/10/11 LINDER, F, Dairyland Power Cooperative 3pp 20725 009 24X Fiche 50-409,83/10/11,8310130203

8310200003 Forwards Amend 34 to License DPR-45 & safety evaluation Amend modifies Tech Specs incorporating addl limitations to protect against degraded grid voltage & pipe cracking & new requirements to facilitate fire protection
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/14 LINDER, F, Dairyland Power Cooperative 3pp 20837 042 24X Fiche 50-409,83/10/14,8310200003

--8310200005 Amend 34 to License DPR-45, modifying Tech Specs to incorporate addl limitations to protect against degraded grid voltage & pipe cracking & new requirements to facilitate fire protection & inservice insp
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/14 45pp 20837 046 24X Fiche 50-409,83/10/14,8310200005

--8310200006 Safety evaluation supporting Amend 34 to License DPR-45, * Office of Nuclear Reactor Regulation, Director 83/10/14 7pp 20837 091 24X Fiche 50-409,83/10/14,8310200006

8310190131 Forwards comments on detailed control room design review program plan if implemented properly, review will probably produce results that fulfill requirements of Suppl 1 to NUREG-0737 Response not required
CRUTCHFIELD, D Operating Reactors Branch 5, 83/10/17 LINDER, F, Dairyland Power Cooperative 10pp 20820,287 24X Fiche 50-409,83/10/17,8310190131

8310310158 Ack receipt of 831005 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-409/83-09, Severity Level IV violation remains, Violation based on App E to 10CFR50 Emergency plan review underway
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/10/25 LINDER, F W Dairyland Power Cooperative, 2pp 20959 038 24X Fiche 50-409,83/10/25,8310310158

--8310310163 Responds to NRC 830906 ltr re violations noted in IE Insp Rept 50-409/83-09 Corrective actions emergency plan procedure revised to notify local authorities within 15 minutes Protective action guidelines will be incorporated
LINDER, F Dairyland Power Cooperative, 83/10/03 PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 8pp, 20959 040 24X Fiche 50-409,83/10/25,8310310158

P Operating license stage documents & correspondence

8310050101 Forwards summary of proposed integrated plant safety assessment (NUREG-0827) & SEP Topics III-3.A, III-4.B & VIII-1.A, Printing error in NUREG-0485 corrected to read 01/01/84
LINDER, F, Dairyland Power Cooperative 83/09/29 CRUTCHFIELD, D, Operating Reactors Branch 5 21pp, 20628,289 24X Fiche 50-409,83/09/29,8310050101

DOCKETED ITEMS

8310120104 Requests formal update to completion schedules in integrated plant safety assessment rept intermediate milestones should be established enabling NRC to review evaluation methods & acceptance criteria
CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/06 LINDER, F
Dairyland Power Cooperative 2pp 20696 182 24X
Fiche 50-409, 83/10/06, 8310120104

8310170159 Forwards clarification of evaluation of pipe whip, jet impingement & breaks within pipe tunnel (SEP Topic III 5 B), per 830720 request transmitting integrated plant safety assessment program (NUREG-0827)
LINDER, F. Dairyland Power Cooperative 83/10/06 CRUTCHFIELD, D
Operating Reactors Branch 5 4pp 20788 347 24X
Fiche 50-409, 83/10/06, 8310170159

8310120272 Advises that FR, containing Commission monthly notices which afford public opportunities for hearing on requests for action, will be transmitted w/o forwarding ltr in future
CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/07 LINDER, F
Dairyland Power Cooperative 2pp 20690 347 24X
Fiche 50-409, 83/10/07, 8310120272

8310130276 Forwards evaluation of util 830831 plant design submittal in response to integrated plant SAR (NUREG-0827) Section 4.24.1, App K, "Electrical Instrumentation & Control Reviews for LACBWR" Issue resolved.
CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/07 LINDER, F
Dairyland Power Cooperative 7pp 20723 198 24X
Fiche 50-409, 83/10/07, 8310130276

8310200003 Forwards Amend 34 to License DPR-45 & safety evaluation Amend modifies Tech Specs incorporating addl limitations to protect against degraded grid voltage & pipe cracking & new requirements to facilitate fire protection
CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/14 LINDER, F
Dairyland Power Cooperative 3pp 20837 042 24X
Fiche 50-409, 83/10/14, 8310200003

--8310200005 Amend 34 to License DPR-45, modifying Tech Specs to incorporate addl limitations to protect against degraded grid voltage & pipe cracking & new requirements to facilitate fire protection & inservice insp
CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/14 45pp
20837 046 24X Fiche 50-409, 83/10/14, 8310200003

--8310200006 Safety evaluation supporting Amend 34 to License DPR-45
* Office of Nuclear Reactor Regulation, Director 83/10/14 7pp
20837 091 24X Fiche 50-409, 83/10/14, 8310200003

8310290566 Forwards "LACBWR Containment Bldg Independent Seismic Analysis" Models & assumptions must reflect actual plant configuration before floor response spectra used
CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/18 LINDER, F
Dairyland Power Cooperative 2pp 20901 151 24X
Fiche 50-409, 83/10/18, 8310290566

--8310290570 "LACBWR Containment Bldg Independent Seismic Analysis"
BRIDGES, T. L., HARRIS, B. L. EQ&O, Inc. 83/10/18 NRC - No
Detailed Affiliation Given. 7pp 20901 153 24X
Fiche 50-409, 83/10/18, 8310290566

8310210303 Responds to 830311 request for extension of deadline for final environ qualification of certain electrical equipment
Items Extension to no later than 850331 granted.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director
83/10/19 LINDER, F. Dairyland Power Cooperative 7pp 20851 064
24X Fiche 50-409, 83/10/19, 8310210303

10280128 Forwards safety evaluation re util 830929 response to NUREG-0827 re integrated safety assessment rept. Sections 4.26 & 4.26.3 Commitments & justification for not modifying certain Foxboro & Honeywell recorders acceptable.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/10/27 LINDER, F
Dairyland Power Cooperative 2pp 20929 038 24X
Fiche 50-409, 83/10/27, 8310280128

8310280134 Safety evaluation re util 830929 response to NUREG-0827 integrated plant safety assessment rept. Sections 4.26 & 4.26.3 Commitments & justification acceptable.
* Operating Reactors Branch 5 83/10/27 2pp 20929 040 24X
Fiche 50-409, 83/10/27, 8310280128

8310280161 Discusses 831006 response to request for addl info re integrated plant safety assessment rept (NUREG-0827), Section 4.12, "Pipe Break Outside Containment." Criteria for jet impingement provided Section complete Evaluation encl.
CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/27 LINDER, F
Dairyland Power Cooperative. 2pp 20929 221. 24X
Fiche 50-409, 83/10/27, 8310280161

--8310280163 Safety evaluation supporting integrated plant safety assessment rept (NUREG-0827), Section 4.12, "Pipe Break Outside Containment"
* NRC - No Detailed Affiliation Given 83/10/27 1p 20729 223
24X Fiche 50-409, 83/10/27, 8310280161

G Inspection reports, IE Bulletins & Correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 118pp 20778 001. 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New
York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180274 Clarifies NRC position re procedures for admitting NRC personnel to facilities Access should be afforded to Region III personnel listed in encl Update will be provided every 6 months
AXELSON, W. L. Region 3, Office of Director 83/10/14 LINDER, F. W
Dairyland Power Cooperative 7pp 20802 295 24X
Fiche 50-409, 83/10/14, 8310180274

8310200003 Forwards Amend 34 to License DPR-45 & safety evaluation Amend modifies Tech Specs incorporating addl limitations to protect against degraded grid voltage & pipe cracking & new requirements to facilitate fire protection
CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/14 LINDER, F
Dairyland Power Cooperative 3pp 20837 042 24X
Fiche 50-409, 83/10/14, 8310200003

--8310200005 Amend 34 to License DPR-45, modifying Tech Specs to incorporate addl limitations to protect against degraded grid voltage & pipe cracking & new requirements to facilitate fire protection & inservice insp
CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/14 45pp
20837 046 24X Fiche 50-409, 83/10/14, 8310200003

--8310200006 Safety evaluation supporting Amend 34 to License DPR-45
* Office of Nuclear Reactor Regulation, Director 83/10/14 7pp
20837 091. 24X Fiche 50-409, 83/10/14, 8310200003

8310310397 Forwards IE Insp Rept 50-409/83-13 on 830808-12 & notice of violation Written response detailing plans & schedules for addl QA training required
SPESSARD, R. L. Division of Engineering 83/10/17 LINDER, F
Dairyland Power Cooperative 2pp 20959 310 24X
Fiche 50-409, 83/10/17, 8310310397

DOCKETED ITEMS

295

8310310400 Notice of violation from insp on 830808-12
SPASSARD, R L Division of Engineering 83/10/17 4pp
20959 312 24X Fiche 50-409, 83/10/17, 8310310397

8310310407 IE Insp Rept 50-409/83-13 on 830808-12 Noncompliance noted
reproper recording of surveillance & calibr data
Instrumentation calibr performed w/o adequate guidelines to
technicians re prerequisites for performing calibr
FARRELL, R E, KISH, J N, HUNTER, D R Region 3, Office of Director
83/10/17 6pp 20959 316 24X Fiche 50-409, 83/10/17, 8310310397

8310310158 Ack receipt of 831005 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-409/83-09
Severity Level IV violation remains Violation based on App
E to 10CFR50 Emergency plan review underway
PAPERIELLO, C J Division of Emergency Preparedness & Operational
Support 83/10/25 LINDER, F W Dairyland Power Cooperative 2pp
20959 438 24X Fiche 50-409, 83/10/25, 8310310158

8310310163 Responds to NRC 830906 ltr re violations noted in IE Insp
Rept 50-409/83-09 Corrective actions emergency plan
procedure revised to notify local authorities within 15
minutes Protective action guidelines will be incorporated
LINDER, F Dairyland Power Cooperative 83/10/05 PAPERIELLO, C J
Division of Emergency Preparedness & Operational Support 6pp
20959 040 24X Fiche 50-409, 83/10/25, 8310310158

Periodic operating reports & related correspondence

831090027 Monthly operating rept for Aug 1983 W/830909 ltr
WODMAN, L B, LINDER, F Dairyland Power Cooperative 83/09/07
KFC - No Detailed Affiliation Given 12pp 20823 155 24X
Fiche 50-409, 83/09/07, 8310190027

Reportable occurrences, LERs & related correspondence

831010430 Responds to FOIA request for four different categories of
documents described in 830510 ltr Forwards matl listed in
App A, responsive to Items 1, 2 & 4 DOE should be contacted
for matl requested in Item 3 of ltr
ELTON, J M Division of Rules and Records 83/06/14 HIAIT, S L
Ohio Citizens for Responsible Energy 3pp 20706 002 24X
Fiche 50-000, 83/06/14, 8310110430

831010467 Daily rept re events at three different facilities LACBWH
experienced scram due to low water level PND-III-83-026
updates use of lubricants on valve seats
Region 3, Office of Director 83/04/14 1p 20706 062 24X
Fiche 50-000, 83/06/14, 8310110430

83070301 Potential Part 21 rept re underrange characteristic of
Model M-E110M transmitter Underrange zero offset may occur
when transmitter initially pressurized from atmospheric to
suppressed zero input End users notified
EPPERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of
Inspection and Enforcement 11pp 20691 064 24X
Fiche 50-000, 83/09/30, 8310070301

831070364 Updated LER 83-00/01X-1 on 830716, seal injection (SI) sys
pressure transient caused gasket in forced circulation pump
IA supply line orifice to fail Caused by personnel error SI
sys control changes planned W/831003 ltr
WODMAN, L B, LINDER, F Dairyland Power Cooperative 83/10/03
KEPPLER, J O Region 3, Office of Director 3pp 20786 174 24X
Fiche 50-409, 83/10/03, 8310170364

8310210002 RO on 830906, high pressure svc water alternate core spray
pump 1B removed from svc more than 7 days to install addl
pump Caused by delay in providing replacement pump
Equivalent pump obtained & installed
LINDER, F Dairyland Power Cooperative 83/10/11 KEPPLER, J O
Region 3, Office of Director 2pp 20098 258 24X
Fiche 50-409, 83/10/11, 8310210002

NET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2

Application/construction stage documents & correspondence

8310050131 Forwards request for addl info re operating & maint
procedures & ATWS, FSAR Sections 13.5.2 & 15.8 & Items 1 C.7
& 1 C.8 from Section 1.10 Responses should be submitted as
changes to FSAR by 831027
SCHWENCER, A Licensing Branch 2 83/09/20 RHODE, G K Niagara
Mohawk Power Corp 6pp 20650 198 24X Fiche 50-410, 83/09/20,
8310050131

8310050087 Forwards request for addl info needed for FSAR review
Responses should be submitted as changes to FSAR by 831215
SCHWENCER, A Licensing Branch 2 83/09/27 RHODE, G K Niagara
Mohawk Power Corp 4pp 20650 191 24X Fiche 50-410, 83/09/27,
8310050087

8310110411 Forwards request for addl info re NUREG-0737 items &
safety-related structures, sys & components controlled by QA
program (FSAR Table 3.2-1) Responses should be submitted as
changes to FSAR by 831027
SCHWENCER, A Licensing Branch 2 83/09/27 RHODE, G K Niagara
Mohawk Power Corp 7pp 20713 344 24X Fiche 50-410, 83/09/27,
8310110411

8310070194 Notification of 831013 meeting w/util in Bethesda, MD to
discuss geoscience issues for facility
HAUGHEV, M F Licensing Branch 2 83/09/29 SCHWENCER, A Licensing
Branch 2 3pp 20679 360 24X Fiche 50-410, 83/09/29, 8310070194

8310170045 Forwards request for addl info re safety review of power sys
area Schedule for response should be provided within 14 days
of date of ltr
SCHWENCER, A Licensing Branch 2 83/10/03 RHODE, G K Niagara
Mohawk Power Corp 33pp 20812 276 24X Fiche 50-410, 83/10/03,
8310170045

8310170716 Forwards updated distribution list for environ rept, FSAR &
general info portion of OL application
SCHWENCER, A Licensing Branch 2 83/10/04 RHODE, G K Niagara
Mohawk Power Corp 5pp 20798 117 24X Fiche 50-410, 83/10/04,
8310170716

8310170745 Advises that instrument tubing & supports program acceptable
for plant safety-related sys, based on review of util 830418
proposal & FSAR Table 3.9A-15 Acceptance subj to listed
conditions
SCHWENCER, A Licensing Branch 2 83/10/05 RHODE, G K Niagara
Mohawk Power Corp 3pp 20796 352 24X Fiche 50-410, 83/10/05,
8310170745

8310310228 Application for Amend 5 to OL application (filed in PDR
Category A), consisting of Amend 5 to FSAR (filed in PDR
Category K) & Suppl 4 to environ rept - OL stage (filed in
PDR Category C) Affidavit encl
MANGAN, C V Niagara Mohawk Power Corp 83/10/24 EISENHUT, D O
Division of Licensing 2pp 20952 134 24X Fiche 50-410, 83/10/24,
8310310228

C Utility Environmental Report (ER), amends & correspondence

8310310228 Forwards Suppl 4 to environ rept - OL stage
MANGAN, C V Niagara Mohawk Power Corp 83/10/24 EISENHUT, D O
Division of Licensing 2pp 20952 134 24X Fiche 50-410, 83/10/24,
8310310228

--8310310238 Suppl 4 to environ rept - OL stage
MANGAN, C V Niagara Mohawk Power Corp 83/10/31 63pp 20952 136 24X
Fiche 50-410, 83/10/24, 8310310228

F Security, medical, emergency & fire protection plans

8310050131 Forwards request for addl info re operating & maint
procedures & ATWS, FSAR Sections 13.5.2 & 15.8 & Items 1 C.7
& 1 C.8 from Section 1.10 Responses should be submitted as
changes to FSAR by 831027
SCHWENCER, A Licensing Branch 2 83/09/20 RHODE, G K Niagara
Mohawk Power Corp 6pp 20650 198 24X Fiche 50-410, 83/09/20,
8310050131

K Utility Final Safety Analysis Report (FSAR) & amends

8310310228 Forwards Amend 5 to FSAR including proprietary info
MANGAN, C V Niagara Mohawk Power Corp, 83/10/24, EISENHUT, D O
Division of Licensing 2pp 20952 134 24X Fiche 50-410, 83/10/24,
8310310228

--8310310243 Amend 5 to FSAR, Vol 2, incorporating certain responses to
FSAR & environ rept
MANGAN, C V Niagara Mohawk Power Corp 83/10/31 1316pp 20952 199 24X
Fiche 50-410, 83/10/24, 8310310228

Q Inspection reports, IE Bulletins & correspondence

8310060004 Forwards IE Insp Rept 50-410/83-11 on 830802-04 No
noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/09/22
RHODE, G K Niagara Mohawk Power Corp 2pp 20649 283 24X
Fiche 50-410, 83/09/22, 8310060004

--8310060012 IE Insp Rept 50-410/83-11 on 830802-04, No noncompliance
noted Major areas inspected installation of electrical
cables, raceway, motor control ctrs, quality records &
inspector Followup on previously identified items
FINKEL, A, ANDERSON, C Region 3, Office of Director 83/09/09
7pp 20649 287 24X Fiche 50-410, 83/09/22, 8310060004

DOCKETED ITEMS

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 110pp 20778 001 24X Fiche 50-000,83/09/26,8308300345

8310040389 Forwards IE Enforcement Conference Rept 50-410/83-14 on 830830
STAROSTECKI, R Division of Project & Resident Programs 83/09/28
RHODE, G K, SEIBERT, C R Niagara Mohawk Power Corp 2pp 20620 044 24X Fiche 50-410,83/09/28,8310040389

--8310040393 IE Enforcement Conference Rept 50-410/83-14 on 830830 Major areas discussed implementation efforts to improve performance of piping contractor, ITT Grinnell & results of NRC investigation of contractor
GRANT, J, GALLO, R Region 1, Office of Director 83/09/26 3pp 20620 046 24X Fiche 50-410,83/09/28,8310040389

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o IOCFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349

8310130146 Act receipt of 830922 ltr forwarding payment of civil penalty imposed by 830824 ltr
AXELRAD, J A Director's Office, Office of Inspection and Enforcement 83/09/29 RHODE, G K Niagara Mohawk Power Corp 2pp 20777 152 24X Fiche 50-410,83/09/29,8310130146

8310190128 Forwards IE Insp Rept 50-410/83-12 on 830808-0921 & notices of violation & deviation w/o notices
STAROSTECKI, R Division of Project & Resident Programs 83/10/04
RHODE, G K Niagara Mohawk Power Corp 2pp 20820 297 24X Fiche 50-410,83/10/04,8310190128

--8310190135 IE Insp Rept 50-410/83-12 on 830808-0921 Noncompliance noted failure to properly inspect cable rework activities & to comply w/FSAR commitments to hold point usage
GRAMM, R A, GRANT, J, GALLO, R M Region 1, Office of Director 83/09/30 14pp 20820 299 24X Fiche 50-410,83/10/04,8310190128

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

8310310338 Discusses IE Investigation Rept 50-410/1-83-005 on 830222-24,28 & 0301-04 & forwards notice of violation
Violation re mgt of QC personnel classified Severity Level IV.
STAROSTECKI, R Division of Project & Resident Programs 83/10/13
RHODE, G K Niagara Mohawk Power Corp. 2pp 20961 325 24X Fiche 50-410,83/10/13,8310310338

--8310310343 Notice of violation from investigation on 830222-24,28 & 0301-04 Noncompliance noted until personnel did not have sufficient control of QA program to permit ITT Grinnell organizational freedom
Region 1, Office of Director 83/10/13 2pp 20961 327 24X Fiche 50-410,83/10/13,8310310338

5 Reportable occurrences, LERs & related correspondence

8310170153 Interim deficiency rept re Rockwell Intl microswitch in post-LOCA hydrogen recombiners Initially reported on 830811
Final rept will be submitted by 830909 Also reported per Part 21
HANNO, S F Niagara Mohawk Power Corp 83/09/01 STAROSTECKI, R
Division of Project & Resident Programs 2pp 20787 114 24X Fiche 50-410,83/09/01,8310170153

8310280052 Interim deficiency rept re 40-mil, 1,000-volt fire-resistant control cable supplied by Kerite Co Initially reported on 830829 Cause under investigation Final rept to be submitted by 831215
HANNO, S F Niagara Mohawk Power Corp 83/09/23 STAROSTECKI, R
Division of Project & Resident Programs 2pp 20934 331 24X Fiche 50-410,83/09/23,8310280052

8310070301 Potential Part 21 rept re underrange characteristic of Model N-E11QM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X Fiche 50-000,83/09/30,8310070301

DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

8310050352 Notification of 830428-29 meetings w/util in Shippingport, PA to discuss public concerns of environ interest & to conduct site visits
LAZD, L Licensing Branch 3 83/09/19 KNIGHTON, G W Licensing Branch 3 8pp 20635 001 24X Fiche 50-412,83/09/19,8310050352

8310060514 Forwards request for addl environ qualification info, based on review of FSAR submitted w/830518 OL application Response due by 831123
KNIGHTON, G W Licensing Branch 3 83/09/22 WOOLEVER, E J
Duquesne Light Co 7pp 20663 169 24X Fiche 50-412,83/09/22,8310060514

8310060524 Forwards request for addl seismic & dynamic load info, based on review of FSAR submitted w/830518 OL application Response due by 831118
KNIGHTON, G W Licensing Branch 3 83/09/22 WOOLEVER, E J
Duquesne Light Co 5pp 20662 305 24X Fiche 50-412,83/09/22,8310060524

8310060530 Forwards comments on FSAR Section 1 9, "BRP Conformance Evaluation " Comments should be considered in responding to 830919 request for addl structural & geotechnical engineering info
KNIGHTON, G W Licensing Branch 3 83/09/22 WOOLEVER, E J
Duquesne Light Co 10pp 20662 295 24X Fiche 50-412,83/09/22,8310060530

8310060510 Forwards request for addl plant personnel training info, based on review of FSAR submitted w/830518 OL application Response due by 831125
KNIGHTON, G W Licensing Branch 3 83/09/28 WOOLEVER, E J
Duquesne Light Co 11pp 20663 176 24X Fiche 50-412,83/09/28,8310060510

8310180121 Notification of Significant Licensee Meeting 83-39 on 831021 in King of Prussia, PA to discuss engineering design control program & compliance w/Reg Guide 1.75, Rev 2 re electrical separation criteria
TRIPP, L E Region 1, Office of Director 83/10/12 Region 1, Office of Director 1p 20824 040 24X Fiche 50-412,83/10/12,8310180121

8310310089 Summarizes 830823 meeting w/NRC in Bethesda, MD re development of Tech Specs for plant, Concern raised re human factors aspect of attempting to operate two essentially identical units from common control room
WOOLEVER, E J Duquesne Light Co 83/10/26 DENION, H R Office of Nuclear Reactor Regulation, Director 3pp 20950 341 24X Fiche 50-412,83/10/26,8310310089

DOCKETED ITEMS

297

Security, medical, emergency & fire protection plans

831030309 Forwards Amend 1 to fire protection evaluation rept Amend consists of mods to text resulting from responses to NRC request for addl info questions contained in Encl 1 of G.W. Knighton 830831 ltr to EJ Woolever
WOOLEVER, E J Duquesne Light Co 83/10/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20961 172 24X
Fiche 50-412, 83/10/27, 8310310309

8310310312 Amend 1 to fire protection evaluation rept
* Stone & Webster Engineering Corp 83/10/31 34pp 20961 174
24X Fiche 50-412, 83/10/27, 8310310309

Adjudicatory correspondence

10050533 Response opposing Ohio Citizens for Responsible Energy 830906 amended petition for leave to intervene Petition to waive regulations to admit need for power contention is meritless Certificate of Svc encl
FERLIS, R G Hearing Branch 3 83/09/26 Atomic Safety and Licensing Board Panel 11pp 20631 334 24X Fiche 50-412, 83/09/26, 8310050533

10050402 Response to 830909 suppl to request of Environ Coalition on Nuclear Power (ECNP) for DL hearing & petition for leave to intervene ECNP fails to provide admissible contentions Petition should be denied Certificate of Svc encl
FERLIS, R G Hearing Branch 3 83/09/24 Atomic Safety and Licensing Board Panel 15pp 20633 348 24X Fiche 50-412, 83/09/29, 8310050402

10140019 Forwards ZG Ferkin notice of appearance, substituting for D Rees & M.L. Woolfing W/o encl Related correspondence
FERKIN, Z G Pennsylvania, Commonwealth of, 83/10/11
MARGULIES, M B Atomic Safety and Licensing Board Panel 1p
20767 029 24X Fiche 50-412, 83/10/11, 8310140019

10140091 Notice of appearance in proceeding Certificate of Svc encl
FERKIN, Z G Pennsylvania, Commonwealth of, 83/10/11 3pp
20767 023 24X Fiche 50-412, 83/10/11, 8310140091

10180343 Notice of withdrawal as party from proceeding Certificate of Svc encl
HITE, Q S Affiliation Unknown 83/10/11 3pp 20802 360 24X
Fiche 50-412, 83/10/11, 8310180343

0180140 Forwards substitution of appearance of ZG Ferkin for D Rees & M.L. Woolfing for Commonwealth of PA Certificate of Svc encl
FERKIN, Z G Pennsylvania, Commonwealth of, 83/10/13
MARGULIES, M B Atomic Safety and Licensing Board Panel 3pp
20809 182 24X Fiche 50-412, 83/10/13, 8310180140

0250297 Clarifies cite to Seabrook decision adverted to at 831012 rehearing conference re consideration of sunk costs Full citation for decision is CLJ-77-0
ERLIS, R G Hearing Branch 3 83/10/14 MARGULIES, M B, HILL, E E, URBON, P W Atomic Safety and Licensing Board Panel 1p
0898 361 24X Fiche 50-412, 83/10/14, 8310250297

Utility Final Safety Analysis Report (FSAR) & amends

0310062 Forwards Amend 3 to FSAR, consisting of responses to 830831 request for addl info
WOOLEVER, E J Duquesne Light Co 83/10/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20967 032 24X
Fiche 50-412, 83/10/26, 8310310062

310310065 Amend 3 to FSAR, consisting of responses to 830831 request for addl info
* Stone & Webster Engineering Corp 83/10/31 1,300pp
20967 034 24X Fiche 50-412, 83/10/26, 8310310062

Antitrust correspondence

02000038 Forwards notice of receipt of antitrust info re DL application, per Reg Guide 9.3
NIGHTON, Q W Licensing Branch 3 83/10/06 WOOLEVER, E J Duquesne Light Co 3pp 20844 228 24X Fiche 50-412, 83/10/06, 3102000038

310200042 Notice of receipt of antitrust info re DL application, per Reg Guide 9.3
NIGHTON, Q W Licensing Branch 3 83/10/06 2pp 20844, 231
24X Fiche 50-412, 83/10/06, 8310200038

G Inspection reports, IE Bulletins & correspondence

8310030345 Ack receipt of 830825 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-412/83-08
MARTIN, T T Division of Engineering & Technical Programs 83/09/12
WOOLEVER, E J Duquesne Light Co 1p 20592 333 24X
Fiche 50-412, 83/09/12, 8310030345

--8310030360 Responds to NRC 830725 ltr re violations noted in IE Insp Rept 50-412/83-08 Corrective actions Schneider Power Corp assigned special block of numbers applicable to nonconformance & deficiency repts for ASME III Program
WOOLEVER, E J Duquesne Light Co 83/08/25 STAROSTECKI, R Division of Project & Resident Programs 3pp 20592 334 24X
Fiche 50-412, 83/09/12, 8310030345

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340.

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752.

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Malfunction Causes Production of Noxious Gases." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310270323 Confirms 831021 meeting w/util at Region I ofc to discuss util role in control, review & independent assessment of ongoing engineering efforts in response to previous NRC insp finding & SALP evaluations.
STAROSTECKI, R Division of Project & Resident Programs 83/10/12.
WOOLEVER, E J Duquesne Light Co 1p 20923 182, 24X
Fiche 50-412, 83/10/12, 8310270323

T Hearing transcripts on non-antitrust matters

8310170442 Transcript of 831012 special prehearing conference in Pittsburgh, PA, pp 1-146
* Atomic Safety and Licensing Board Panel 83/10/12 147pp
20778 130 24X Fiche 50-412, 83/10/12, 8310170442

DOCKETED ITEMS

DOCKET 50-413 CATAWBA NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8310050076 Concurs w/dissolution of Model D2/D3 Steam Generator Util Design Review Panel Panel work complete.
NOVAK, T M Assistant Director for Licensing 83/09/23
BLACKLEY, B K Design Review Panel 3pp 20630 165 24X
Fiche 50-000, 83/09/23, 8310050076

8308300395 Board Notification 83-66A: advises that position re rod drop issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycle
EISENHUT, D G Division of Licensing 83/09/29 PALLADINO, N J Commissioners, 10pp 20632 106 24X Fiche 50-000, 83/09/29, 8308300395

8308300397 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway
EISENHUT, D G Division of Licensing 83/09/29 PALLADINO, N J Commissioners, 3pp 20632 001 24X Fiche 50-000, 83/09/29, 8308300397

8310030412 Trip rept of 830920 site visit including plant tour & meeting w/util mgt
JOOSTER, J K Commissioners 83/09/29 Commissioners 18pp 20993 109 24X Fiche 50-413, 83/09/29, 8310030412

8308300763 Board Notification 83-151 provides info re desirability of current ECCB actuation logic for Westinghouse plants, in light of recent info concerning steam generator tube rupture procedure for Borssele Nuclear Power Station
EISENHUT, D G Division of Licensing 83/10/04 PALLADINO, N J Commissioners 2pp, 20698 033 24X Fiche 50-000, 83/10/04, 8308300763

8310110636 Summary of 830913 site meeting w/util re mods to steam generators
JABBOUR, K N Licensing Branch 4 83/10/04 Licensing Branch 4 3pp, 20706 326 24X Fiche 50-413, 83/10/04, 8310110636

8310210179 Comments on incorrect statements noted in 830929 trip rept correct milestone date for Unit 1 hot functional testing is Nov 1983 & May 1984 for fuel loading
TUCKER, H B Duke Power Co 83/10/13 DILINSKY, V Commissioners 2pp 20856 125 24X Fiche 50-413, 83/10/13, 8310210179

8308310050 Board Notification 83-160 provides info re 830812 failure of main crankshaft on one of three Transamerica Delaval emergency diesel generators at Shoreham
EISENHUT, D G Division of Licensing 83/10/14 PALLADINO, N J Commissioners 15pp 67036 070 24X Fiche 50-000, 83/10/14, 8308310050

8310240245 Forwards notice of receipt of request for action under 10CFR2.206 for 830914 petition submitted on behalf of Palmetto Alliance, requesting mgt audit of util & independent review of as-built condition of plant
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/10/14 GARDE, B P Government Accountability Project 3pp 20907 280 24X Fiche 50-413, 83/10/14, 8310240245.

--8310240249 Notice of receipt of request for action under 10CFR2.206 for 830914 petition submitted on behalf of Palmetto Alliance, requesting mgt audit of util & independent review of as-built condition of plant
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/10/14 1p 20907 283 24X Fiche 50-413, 83/10/14, 8310240249

E NRC Safety Evaluation Report (SER), suppis & correspondence

8310070150 Notification of 830930 meeting w/util in Bethesda, MD to discuss internal corrosion protection for fuel oil storage tanks (SER License Condition 18) & emergency lighting (SER Open Item 150).
JABBOUR, K N Licensing Branch 4 83/09/27 ADENSAH, E G Licensing Branch 4 2pp 20680 306 24X Fiche 50-413, 83/09/27, 8310070150

8310040016 Forwards one oversize revised flow diagram to comply w/Section 10.4.9 of SER re License Condition 20, loss of primary source of condensate storage water Aperture card is available in PDR
TUCKER, H B Duke Power Co 83/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 2pp, 20619 034 24X Fiche 50-413, 83/09/28, 8310040016

8310190264 Notification of 831027 meeting w/util in Bethesda, MD to discuss technical issues re SLR Confirmatory Item 1, "PPNP & Effects on Safety-Related Structures & Components"
JABBOUR, K N Licensing Branch 4 83/10/12 ADENSAH, E G Licensing Branch 4 3pp 20843 162 24X Fiche 50-413, 83/10/12, 8310190264

8310190165 Advises that design max temp of standby nuclear svc water pond raised from 95 F to 100 F, in response to SSER 1, Open Item 2 Info will be incorporated in FSAR, Rev B
TUCKER, H B Duke Power Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 3pp 20821 065 24X Fiche 50-413, 83/10/13, 8310190165

8310190195 Advises that installation of voltmeters to determine reactor trip status by measuring P-4 signal in reactor trip breaker cabinets completed, in response to SER Confirmatory Item 27
TUCKER, H B Duke Power Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 1p 20820 203 24X Fiche 50-413, 83/10/13, 8310190195

8310190262 Forwards description of analysis & results to confirm that sufficient time exists to reestablish DLR if RHR sys inadvertently isolated as result of loss of instrument bus, in response to SSER 1, Open Item 12
TUCKER, H B Duke Power Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 3pp 20818 061 24X Fiche 50-413, 83/10/13, 8310190262

8308300779 Board Notification 83-140A forwards Board Notification 83-128 re draft test rept on qualification test program of Class 1E solenoid valves Resolution will be handled under Outstanding Issue 4 in SER
NOVAK, T M Assistant Director for Licensing 83/10/17 Atomic Safety and Licensing Board Panel 3pp 20855 167 24X Fiche 50-413, 83/10/17, 8308300779

8310280096 Responds to SER Open Item 4 re NUREG-0737, Item II F 2, "Instrumentation for Detection of Inadequate Core Cooling," providing updated FSAR pages concerning core exit thermocouples & reactor vessel level measurement
TUCKER, H B Duke Power Co 83/10/19 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 13pp 20935 191 24X Fiche 50-413, 83/10/19, 8310280096

F Security, medical, emergency & fire protection plans

8310040406 Forwards IE Insp Repts 50-413/83-23 & 50-414/83-20 on 830801-05 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/13 TUCKER, H B Duke Power Co 2pp 20619 094 24X Fiche 50-413, 83/09/13, 8310040406

--8310040413 IE Insp Repts 50-413/83-23 & 50-414/83-20 on 830801-05 No noncompliance noted Major areas inspected preoperational emergency preparedness, including Procedure TI 2515/55 re readiness for emergency plan implementation appraisal
HUFFMAN, O N Region 2, Office of Director JENKINS, O R Division of Emergency Preparedness & Materials Safety 83/09/08 10pp 20619 094 24X Fiche 50-413, 83/09/13, 8310040406

8310040287 Forwards Rev 2 to 830414 response to Suppl 1 to NUREG-0737, including rept on review of Reg Guide 1.97
TUCKER, H B Duke Power Co 83/09/26 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 71pp 20614 077 24X Fiche 50-413, 83/09/26, 8310040287

8310070150 Notification of 830930 meeting w/util in Bethesda, MD to discuss internal corrosion protection for fuel oil storage tanks (SER License Condition 18) & emergency lighting (SER Open Item 150)
JABBOUR, K N Licensing Branch 4 83/09/27 ADENSAH, E G Licensing Branch 4 2pp 20680 306 24X Fiche 50-413, 83/09/27, 8310070150

8310250383 Forwards IE Insp Repts 50-413/83-29 & 50-414/83-25 on 830914 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/30 TUCKER, H B Duke Power Co 2pp 20898 139 24X Fiche 50-413, 83/09/30, 8310250383

--8310250392 IE Insp Repts 50-413/83-29 & 50-414/83-25 on 830914 No noncompliance noted Mgt meeting held to discuss NRC insp program for emergency planning
HUFFMAN, O N Region 2, Office of Director JENKINS, O R Division of Emergency Preparedness & Materials Safety 83/09/28 2pp 20898 141 24X Fiche 50-413, 83/09/30, 8310250383

8310070134 Releases public version of revised crisis mgt plan implementing procedures
FELTON, J H Division of Rules and Records 83/10/04 Document Management Branch 1p 20670 001 24X Fiche 50-000, 83/10/04, 8310070134

DOCKETED ITEMS

299

--8310070143 Forwards public version of revised crisis mgt plan implementing procedures, including Procedures 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group
TUCKER, H B Duke Power Co 83/07/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20670 002 24X
Fiche 50-000, 83/10/04, 8310070134

--8310070152 Public version of revised crisis mgt plan implementing procedures, including Procedure 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group
* Duke Power Co 83/07/01 457pp 20670 005 24X
Fiche 50-000, 83/10/04, 8310070134

8310110607 Notification of 831001-04 site meetings w/util to audit fire protection program
JABBOUR, K N Licensing Branch 4 83/10/04 ADENSAH, E Q Licensing Branch 4 3pp 20701 357 24X Fiche 50-413, 83/10/04, 8310110607

8310250635 Informs that periodic evaluation of SALP complete Rept approved
O'REILLY, J P Region 2, Office of Director 83/10/17 TUCKER, H B Duke Power Co 3pp 20900 205 24X Fiche 50-000, 83/10/17, 8310250635

--8310250652 SALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-349/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983
+ Region 2, Office of Director 83/08/02 56pp 20900 211 24X
Fiche 50-000, 83/10/17, 8310250635

Adjudicatory correspondence

8308300480 Forwards answer to util & NRC motions for summary disposition of Contentions 11, 17 & 27 Proposed schedule for emergency planning proceeding encl
GUILD, R Guild, R Palmetto Alliance 83/08/26
KELLEY, J L, FOSTER, R F, CALLIHAN, D Atomic Safety and Licensing Board Panel 3pp 20210 327 24X Fiche 50-413, 83/08/26, 8308300480

--8308300486 Answer opposing util & NRC motions for summary disposition of Contentions 11, 17 & 27 Many substantial & matl issues of fact exist affecting public health & safety & environ
Certificate of Svc encl
GUILD, R Palmetto Alliance GUILD, R Guild, R 83/08/26
Atomic Safety and Licensing Board Panel 25pp 20210 330 24X
Fiche 50-413, 83/08/26, 8308300480

8310050406 Submits list of NRC witnesses to appear at hearing on Palmetto Alliance Contention 16 & Carolina Environ Study Group Contention 18/Palmetto Alliance Contention 44 W/o encl
JOHNSON, O E Hearing Branch 4 83/09/23 KELLEY, J L, FOSTER, R F, CALLIHAN, D Atomic Safety and Licensing Board Panel 3pp 20630 123 24X Fiche 50-413, 83/09/23, 8310050406

8310030406 Forwards signed & corrected PA Evans affidavit Related correspondence
MCGARRY, J M Debevoise & Liberman MCGARRY, J M Duke Power Co 83/09/27 KELLEY, J L, CALLIHAN, A D, FOSTER, R F Atomic Safety and Licensing Board Panel 1p 20593 132 24X Fiche 50-413, 83/09/27, 8310030406

--8308303409 Affidavit of PA Evans in response to Palmetto Alliance allegations that self-initiated evaluation identified problems which are symptomatic of systematic deficiencies in plant const
EVANS, P A Duke Power Co 83/09/27 12pp 20593 133 24X
Fiche 50-413, 83/09/27, 8310030406

8310030412 Trip rept of 830920 site visit including plant tour & meeting w/util mgt
JOUSTEN, J K Commissioners 83/09/29 Commissioners 18pp 20593 109 24X Fiche 50-413, 83/09/29, 8310030412

8310060295 Ack receipt of 830816 ltr requesting info on util spent fuel mgt plans Area is ever changing so precise mix of options util will adopt is difficult to predict Flexibility must exist in future Related correspondence
GRIFFITH, S C Duke Power Co 83/09/29, WILSON, R P South Carolina, State of 3pp 20641 005 24X Fiche 50-413, 83/09/29, 8310060295

8310040177 Memorandum & order ruling on objections to ASLB 830914 prehearing conference order Hearing will commence on 831004
KELLEY, J L Atomic Safety and Licensing Board Panel 83/09/30, Palmetto Alliance 11pp 20608 254 24X Fiche 50-413, 83/09/30, 8310040177

8310050362 Objection to Palmetto Alliance 830924 request for issuance of ASLB subpoena to JP O'Reilly, Region 11 administrator, based on ASLB 830912 denial of identical request Partial transcript of 830831 telcon & Certificate of Svc encl
JOHNSON, O E Hearing Branch 4 83/10/03 Atomic Safety and Licensing Board Panel 36pp 20629 001 24X Fiche 50-413, 83/10/03, 8310050362

8310110294 Requests 831017 meeting in Charlotte, NC to discuss discovery needs re emergency planning contentions & projected schedule for completing discovery for all parties before 840201
Related correspondence
CARR, A V Duke Power Co 83/10/04 GUILD, R Palmetto Alliance
RILEY, J L Carolina Environmental Study Group 1p 20665 338 24X
Fiche 50-413, 83/10/04, 8310110294

0 Inspection reports, IE Bulletins & correspondence

8310110044 Responds to FOIA request for SALP documents, written or routed since 1979, which mention or refer to facility & describe or provide info on SALP insp findings or conclusions re SALP reviews Forwards App A documents
FELTON, J M Division of Rules and Records 83/07/20 RIDENHOUR, R Gambit 2pp 20713 308 24X Fiche 50-000, 83/07/20, 8310110044

--8310110059 Forwards case chronology re allegations concerning welding issues at facilities W/o encl
ALDERSON, C E Region 2, Office of Director 83/02/23
JOHNSON, O E Office of the Executive Legal Director 1p 20713 341 24X Fiche 50-413, 83/07/20, 8310110044

8310040329 Forwards IE Insp Repts 50-413/83-24 & 50-414/83-21 on 830816-19 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/02
TUCKER, H B Duke Power Co 2pp 20617 085 24X
Fiche 50-413, 83/09/02, 8310040329

--8310040345 IE Insp Repts 50-413/83-24 & 50-414/83-21 on 830816-19 No noncompliance noted Major areas inspected verification of as-built & insp of 10CFR21 regulations
MC FARLAND, C R, WRIGHT, R W Region 2, Office of Director
UPRIGHT, C M Division of Engineering & Operational Programs 83/09/01 7pp 20617 087 24X Fiche 50-413, 83/09/02, 8310040329

8310040146 Forwards IE Insp Rept 50-413/83-25 on 830822-26 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/08
TUCKER, H B Duke Power Co 2pp 20608 018 24X
Fiche 50-413, 83/09/08, 8310040146

--8310040150 IE Insp Rept 50-413/83-25 on 830822-26 No noncompliance noted Major areas inspected preoperational test program/procedure verification & plant tour
TAYLOR, P A, JAFFE, F Region 2, Office of Director 83/09/06 3pp 20608 020 24X Fiche 50-413, 83/09/08, 8310040146

8310040406 Forwards IE Insp Repts 50-413/83-23 & 50-414/83-20 on 830801-05 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/13
TUCKER, H B Duke Power Co 2pp 20619 094 24X
Fiche 50-413, 83/09/13, 8310040406

--8310040413 IE Insp Repts 50-413/83-23 & 50-414/83-20 on 830801-05 No noncompliance noted Major areas inspected preoperational emergency preparedness, including Procedure T1 2515/55 re readiness for emergency plan implementation appraisal
HUFFMAN, O N Region 2, Office of Director JENKINS, O R Division of Emergency Preparedness & Materials Safety 83/09/08 10pp 20619 096 24X Fiche 50-413, 83/09/13, 8310040406

8310040599 Forwards supplemental response to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Components by Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel) " Final rept re infestation to be available by 831101
TUCKER, H B Duke Power Co 83/09/16 O'REILLY, J P Region 2, Office of Director 2pp 20626 174 24X Fiche 50-413, 83/09/16, 8310040599

8310040313 Ack receipt of 830908 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/83-17 & 50-414/83-16
LEWIS, R C Division of Project & Resident Programs 83/09/22
TUCKER, H B Duke Power Co 1p, 20649 299 24X
Fiche 50-413, 83/09/22, 8310040313

--8310040319 Responds to NRC 830811 ltr re violations noted in IE Insp Repts 50-413/83-17 & 50-414/83-16, Corrective actions signoff for const engineer-civil restricted to eight experienced personnel
TUCKER, H B Duke Power Co 83/09/08 O'REILLY, J P Region 2, Office of Director 4pp 20649 300 24X Fiche 50-413, 83/09/22, 8310040313

DOCKETED ITEMS

--B310040323 Forwards IE Insp Repts 50-413/83-17 & 50-414/83-16 on 830711-15 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/08/11
TUCKER, H B Duke Power Co 2pp 20649 304 24X
Fiche 50-413, 83/09/22, B310040313

--B310040327 Notice of violation from Insp on 830711-15
* Region 2, Office of Director. 83/08/11 2pp 20649 306 24X
Fiche 50-413, 83/09/22, B310040313

--B310040335 IE Insp Repts 50-413/83-17 & 50-414/83-16 on 830711-15
Noncompliance noted improper concrete mix placed &
checklists for certification of structural inspector,
concrete, Level I, improperly labeled as Level II
WRIGHT, R W, JACKSON, L H Region 2, Office of Director
UPRIGHT, C M Division of Emergency Preparedness & Materials
Safety 83/08/08 10pp 20649 308 24X Fiche 50-413, 83/09/22,
B310040313

B308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder
Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26, Consolidated Edison Co of New
York, Inc 117pp. 20754 022 24X Fiche 50-000, 83/09/26, B308300340

B308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
Detectors Positioned at Control Room Ventilation Air
Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26, Consolidated Edison Co of New
York, Inc 116pp 20777 210, 24X Fiche 50-000, 83/09/26, B308300342

B308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse
Type 8A-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26, Consolidated Edison Co of New
York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, B308300345

B310250398 Forwards IE Insp Repts 50-413/83-27 & 50-414/83-24 on
830906-09 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/26,
TUCKER, H B Duke Power Co 2pp 20897 284 24X
Fiche: 50-413, 83/09/26, B310250398.

--B310250404 IE Insp Repts 50-413/83-27 & 50-414/83-24 on B30906-09 No
noncompliance noted Major areas inspected: const progress,
licensee action on previous enforcement matters, steam
generator mod & review of QA implementing procedures,
KLEINBORGER, W P Region 2, Office of Director BLAKE, J J
Division of Engineering & Operational Programs 83/09/21 7pp
20897 286 24X Fiche: 50-413, 83/09/26, B310250398

B308300349 IE Info Notice 83-64, "Lead Shielding Attached to
Safety-Related Sys W/o 10CFR50.59 Evaluation." Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29, Consolidated Edison Co of New
York, Inc 115pp 20716 324, 24X Fiche 50-000, 83/09/29, B308300349

B310250383 Forwards IE Insp Repts 50-413/83-27 & 50-414/83-25 on
830914 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/30,
TUCKER, H B Duke Power Co 2pp. 20898 139, 24X
Fiche: 50-413, 83/09/30, B310250383

--B310250392 IE Insp Repts 50-413/83-29 & 50-414/83-25 on 830914. No
noncompliance noted Mgt meeting held to discuss NRC insp
program for emergency planning.
HUFFMAN, O M Region 2, Office of Director, JENKINS, O R Division
of Emergency Preparedness & Materials Safety. 83/09/28 2pp
20898 141 24X Fiche: 50-413, 83/09/30, B310250383

B310250225 Forwards IE Insp Rept 50-413/83-30 on 830912-16 No
noncompliance noted.
DANCE, H C Division of Project & Resident Programs 83/10/04
TUCKER, H B Duke Power Co. 2pp 20899: 113, 24X
Fiche 50-413, 83/10/06, B310250225

--B310250230 IE Insp Rept 50-413/83-30 on 830912-16 No noncompliance
noted. Major areas inspected: preoperational test witnessing
& test procedure review (integrated hot functional
sequencing document)
TAYLOR, P A Region 2, Office of Director, JAPE, F. Division of
Engineering & Operational Programs 83/10/04, 3pp. 20899: 115
24X Fiche: 50-413, 83/10/06, B310250225.

B308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass
Loops Used in Westinghouse Plants." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07, Consolidated Edison Co of New
York, Inc 76pp 20827: 213 24X Fiche: 50-000, 83/10/07, B308300378.

B308300752 IE Info Notice 83-66, "Fatality at Argentine Critical
Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07, Consolidated Edison Co of New
York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, B308300752

B308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect
Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11, Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, B308300759

B308300761 IE Info Notice 83-68, "Respirator User Warning Defective
Self-Contained Breathing Apparatus Air Cylinders " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11, Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, B308300761

B310250635 Informs that periodic evaluation of SALP complete Rept
approved.
O'REILLY, J P Region 2, Office of Director 83/10/17 TUCKER, H B
Duke Power Co 3pp 20900 205 24X Fiche 50-000, 83/10/17,
B310250635

--B310250646 Forwards SALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17,
50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for
June 1982 - Apr 1983
LEWIS, R C Division of Project & Resident Programs 83/08/02
TUCKER, H B Duke Power Co 3pp 20900 208 24X
Fiche 50-000, 83/10/17, B310250635

--B310250652 SALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17,
50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for
June 1982 - Apr 1983
* Region 2, Office of Director 83/08/02 66pp 20900 211 24X
Fiche 50-000, 83/10/17, B310250635

--B310250665 Responds to B30802 ltr re SALP board rept Rept incomplete &
premature in certain areas in general, until endorses
observations re facility performance
TUCKER, H B Duke Power Co 83/08/29 O'REILLY, J P Region 2,
Office of Director 2pp 20900 267 24X Fiche 50-000, 83/10/17,
B310250635

9 Reportable occurrences, LERs & related correspondence

B310060038 Interim significant Deficiency Rept SD 413-414/83-10 re
failure of power supply printed circuit card adhesive bond
of heat sink assembly for inverter transistors Initially
reported on B30615 Assemblies will be replaced by B31201
TUCKER, H B Duke Power Co 83/09/27 O'REILLY, J P Region 2,
Office of Director 2pp 20647 085 24X Fiche 50-413, 83/09/27,
B310060038

B310060052 Significant Deficiency Rept SD 83-11 re faulty Westinghouse
N558 process instrumentation & control sys temp channel test
card mercury relays Initially reported on B30829 Replacement
relay testing underway
TUCKER, H B Duke Power Co 83/09/27 O'REILLY, J P Region 2,
Office of Director 2pp 20648 326 24X Fiche 50-413, 83/09/27,
B310060052

B310210111 Significant Deficiency Rept SD 413-414/83-12 re metal filr
found in diesel generators 1B & 2A Initially reported on
B30913 File found in air gap between rotor & stator during
preliminary checkout
TUCKER, H B Duke Power Co 83/10/13 O'REILLY, J P Region 2,
Office of Director 3pp 20898 255 24X Fiche 50-413, 83/10/13,
B310210111

B310270482 Revised interim Significant Deficiency Rept SD 413-414/83-06
re socket welds dtd B20415 Required work on Unit 1
completed Unit 2 incomplete due to incomplete list of
affected socket welds Completion expected by B30201
TUCKER, H B Duke Power Co 83/10/17 O'REILLY, J P Region 2,
Office of Director 1p 20922 011 24X Fiche 50-413, 83/10/17,
B310270482

B308310045 Board Notification 83-147 supplies new info re apparent
diesel generator deficiency On 830914, metal file found in
diesel generators investigation underway to determine
circumstances surrounding incidences
NOVAK, T M Assistant Director for Licensing 83/10/25 Atomic
Safety & Licensing Board Panel 5pp 20929 014 24X
Fiche: 50-413, 83/10/25, B308310045

DOCKETED ITEMS

301

Hearing transcripts on non-antitrust matters

8310240012 Partial response to FUIA request for transcripts of deposition testimony prepared in discovery in OL proceeding for facilities Forwards App A documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/08/10 AHLERS, D M Palmetto Alliance 3pp 20885 001 24X Fiche 50-413, 83/08/10, 8310240012

8310240014 Transcript of M Birch deposition in Charlotte, NC re Contention 27
BIRCH, M Duke Power Co 83/05/11 126pp 20885 008 24X Fiche 50-413, 83/08/10, 8310240012

8310240017 Transcript of CW Graves deposition in Charlotte, NC re Contention 6
GRAVES, C W Duke Power Co 83/05/12 44pp 20885 134 24X Fiche 50-413, 83/08/10, 8310240012

8310240018 Transcript of PK Vandoorn deposition in Charlotte, NC re Contention 6
VANDOORN, P K Duke Power Co 83/05/19 150pp 20885 178 24X Fiche 50-413, 83/08/10, 8310240012

8310240021 Transcript of WR McFee deposition in Charlotte, NC re Contention 6
MCFEE, W R Palmetto Alliance 83/05/19 128pp 20885 328 24X Fiche 50-413, 83/08/10, 8310240012

8310240022 Transcript of NL Hoopengardner deposition in Charlotte, NC re Contention 6
HOOPENGARDNER, N Palmetto Alliance 83/05/19 47pp 20886 074 24X Fiche 50-413, 83/08/10, 8310240012

8310240024 Transcript of NR Hoopingartner deposition in Charlotte, NC re Contention 6
HOOPINGARTNER, N Palmetto Alliance 83/05/20 109pp 20886 142 24X Fiche 50-413, 83/08/10, 8310240012

8310240030 Transcript of GE Vaughn deposition in Charlotte, NC re Contention 7
VAUGHN, G E Duke Power Co 83/05/20 41pp 20886 251 24X Fiche 50-413, 83/08/10, 8310240012

8310240032 Transcript of JC Bryant deposition in Charlotte, NC re Contentions 6 & 7
BRYANT, J C NRC - No Detailed Affiliation Given 83/05/20 80pp 20886 292 24X Fiche 50-413, 83/08/10, 8310240012

8310240038 Transcript of PK Vandoorn deposition in Charlotte, NC re Contention 6, Vol II
VANDOORN, P K Duke Power Co 83/05/20 137pp 20887 011 24X Fiche 50-413, 83/08/10, 8310240012

8310240040 Transcript of BQ Addis deposition in Charlotte, NC re Contention 6
ADDIS, B Q Duke Power Co 83/06/27 129pp 20887 139 24X Fiche 50-413, 83/08/10, 8310240012

8310240043 Transcript of GH Bell deposition in Charlotte, NC re Contention 6
BELL, G H Duke Power Co 83/06/27 75pp 20887 269 24X Fiche 50-413, 83/08/10, 8310240012

8310240047 Transcript of JC Rogers deposition in Charlotte, NC re Contention 6
ROGERS, J C Duke Power Co 83/06/27 32pp 20887 346 24X Fiche 50-413, 83/08/10, 8310240012

8310240049 Transcript of WD Henry deposition in Charlotte, NC re Contention 6
HENRY, W D Duke Power Co 83/06/28 133pp 20888 017 24X Fiche 50-413, 83/08/10, 8310240012

8310240053 Transcript of DQ Beam deposition in Charlotte, NC re Contention 6
BEAM, D Q Duke Power Co 83/06/28 81pp 20888 152 24X Fiche 50-413, 83/08/10, 8310240012

8310240055 Transcript of WD Henry deposition in Charlotte, NC re Contention 6
HENRY, W D Duke Power Co 83/06/29 65pp 20888 235 24X Fiche 50-413, 83/08/10, 8310240012

8310240056 Transcript of AE Allum 830629 deposition in Charlotte, NC re Contention 6
ALLUM, A E Duke Power Co 83/06/29 114pp 20888 300 24X Fiche 50-413, 83/08/10, 8310240012

--8310240057 Transcript of CR Baldwin 830629 deposition in Charlotte, NC re Contention 6
BALDWIN, C R Duke Power Co 83/06/29 191pp 20889 032 24X Fiche 50-413, 83/08/10, 8310240012

--8310240058 Transcript of JE Grogan deposition in Charlotte, NC Related info encl
GROGAN, J E Duke Power Co 83/07/01 27pp 20889 241 24X Fiche 50-413, 83/08/10, 8310240012

--8310240059 Transcript of WH Bradley deposition in Charlotte, NC re Contention 6
BRADLEY, W H Duke Power Co 83/07/07 56pp 20889 270 24X Fiche 50-413, 83/08/10, 8310240012

--8310240060 Transcript of CN Alexander deposition in Charlotte, NC re Contention 6 Related info encl
ALEXANDER, C N Duke Power Co 83/07/07 110pp 20889 327 24X Fiche 50-413, 83/08/10, 8310240012

--8310240061 Transcript of WS Lee deposition in Charlotte, NC Related info encl
LEE, W S Duke Power Co 83/07/12 78pp 20890 074 24X Fiche 50-413, 83/08/10, 8310240012

--8310240062 Transcript of RA Morgan deposition in Charlotte, NC re Contention 6
MORGAN, R A Duke Power Co 83/07/13 120pp 20890 153 24X Fiche 50-413, 83/08/10, 8310240012

--8310240065 Transcript of BH Deaton deposition in Charlotte, NC re Contention 6
DEATON, B H Duke Power Co 83/07/14 49pp 20890 274 24X Fiche 50-413, 83/08/10, 8310240012

--8310240068 Transcript of S Ledford deposition in Charlotte, NC re Contention 6
LEDFORD, S Duke Power Co 83/07/14 26pp 20890 325 24X Fiche 50-413, 83/08/10, 8310240012

--8310240073 Transcript of JC Shropshire deposition in Charlotte, NC re Contention 6 Related info encl
SHROPSHIRE, J C Duke Power Co 83/07/14 89pp 20890 353 24X Fiche 50-413, 83/08/10, 8310240012

--8310240076 Transcript of L Sifford deposition in Charlotte, NC re Contention 6
SIFFORD, W L Duke Power Co 83/07/14 38pp 20891 083 24X Fiche 50-413, 83/08/10, 8310240012

8310050386 Forwards testimony of BJ Elliot, WL Brooks, A Singh, F Clemenson, RJ Serbu & F Japs on Palmetto Alliance Contention 16 & Carolina Environ Study Group Contention 18/ Palmetto Alliance 44
JOHNSON, Q E Operations & Administrative Division 83/09/30
KELLEY, J L, FOSTER, R F, CALLIHAN, D Atomic Safety and Licensing Board Panel 1p 20630 140 24X Fiche 50-413, 83/09/30, 8310050386

--8310050392 Testimony of BJ Elliot on Carolina Environ Study Group Contention 18/Palmetto Alliance Contention 44 re reactor embrittlement.
ELLIOT, B J Materials Engineering Branch 83/09/30 22pp 20630 141 24X Fiche 50-413, 83/09/30, 8310050386

--8310050401 Testimony of WL Brooks on Palmetto Alliance Contention 16 re criticality
BROOKS, W L Core Performance Branch 83/09/30 12pp 20630 163 24X Fiche 50-413, 83/09/30, 8310050386

--8310050415 Joint testimony of A Singh & F Clemenson on Palmetto Alliance Contention 16 re spent fuel pool cooling sys.
SINGH, A, CLEMENSON, F Auxiliary Systems Branch 83/09/30 18pp 20630 175 24X Fiche 50-413, 83/09/30, 8310050386

--8310050419 Joint testimony of RJ Serbu & F Japs on Palmetto Alliance Contention 16 re spent fuel handling.
SERBU, R J Radiological Assessment Systems Branch JAPS, F. Division of Engineering & Operational Programs 83/09/30 17pp 20630 193 24X Fiche 50-413, 83/09/30, 8310050386

831010270 Testimony of JL Riley re Contention 18 concerning unanticipated rapid embrittlement Affirmation of Svc encl Related correspondence
RILEY, J L Carolina Environmental Study Group 83/10/03 14pp 20666 144 24X Fiche 50-413, 83/10/03, 831010270

DOCKETED ITEMS

8310060310 Testimony of TR Mager & TA Meyer re Carolina Environ Study Group & Palmetto Alliance Contention 18/44 Ref temp will not exhibit more rapid increase than calculations show due to radiation effects on vessel W/Certificate of Svc MAGER, T R, MEYER, T A Duke Power Co MAGER, T R Westinghouse Electric Corp 83/10/04 26pp 20646 201 24X Fiche 50-413, 83/10/04, 8310060310

831010098 Transcript of 831004 hearing in Rock Hill, SC Pp 1,535-1,734
* Atomic Safety and Licensing Board Panel 83/10/04 202pp
20667 312 24X Fiche 50-413, 83/10/04, 831010098

8310120352 Transcript of 831005 hearing in Rockhill, SC Pp 1,735-1,962
* Atomic Safety and Licensing Board Panel 83/10/05 228pp
20699 323 24X Fiche 50-413, 83/10/05, 8310120352

8310130013 Transcript of 831006 hearing in Rockhill, SC Pp 1,963-2,207
* Atomic Safety and Licensing Board Panel 83/10/06 245pp
20725 292 24X Fiche 50-413, 83/10/06, 8310130013

8310120295 Transcript of 831007 hearing in Rockhill, SC Pp 2,208-2,379
* Atomic Safety and Licensing Board Panel 83/10/07 172pp
20693 172 24X Fiche 50-413, 83/10/07, 8310120295

8310170137 Transcript of 831011 hearing in Rockhill, SC Pp 2,380-2,592
* Atomic Safety and Licensing Board Panel 83/10/11 213pp
20788 354 24X Fiche 50-413, 83/10/11, 8310170137

8310170456 Transcript of 831012 hearing in Rockhill, SC Pp 2,593-2,832
* Atomic Safety and Licensing Board Panel 83/10/12 241pp
20778 279 24X Fiche 50-413, 83/10/12, 8310170456

8310190115 Transcript of 831013 hearing in Rockhill, SC Pp 2,833-3,060
* Atomic Safety and Licensing Board Panel 83/10/13 228pp
20818 232 24X Fiche 50-413, 83/10/13, 8310190115

8310190119 Transcript of 831013 hearing in Rockhill, SC Pp 1-67
* Atomic Safety and Licensing Board Panel 83/10/13 68pp
20620 340 24X Fiche 50-413, 83/10/13, 8310190119

8310190122 Transcript of 831014 hearing in Rockhill, SC Pp 3,061-3,297
* Atomic Safety and Licensing Board Panel 83/10/14 237pp
20819 244 24X Fiche 50-413, 83/10/14, 8310190122

8310210050 Transcript of 831017 hearing in Rockhill, SC Pp 3,298-3,495
* Atomic Safety and Licensing Board Panel 83/10/17 198pp
20874 281 24X Fiche 50-413, 83/10/17, 8310210050

8310210186 Testimony of WM Bradley re quality or safety concerns expressed by welding inspectors Related correspondence
BRADLEY, W H Duke Power Co 83/10/17 5pp 20856 107 24X Fiche 50-413, 83/10/17, 8310210186

--8310210192 Testimony of WD Henry re quality or safety concerns expressed by welding inspectors Certificate of Svc encl Related correspondence
HENRY, W D Duke Power Co 83/10/17 9pp 20856 112 24X Fiche 50-413, 83/10/17, 8310210186

8310240013 Transcript of 831018 hearing in Rockhill, SC Pp 3,496-3,740
* Atomic Safety and Licensing Board Panel 83/10/18 245pp
20880 093 24X Fiche 50-413, 83/10/18, 8310240013

8310250003 Transcript of 831019 hearing in Rock Hill, SC Pp 3,741-3,999
* Atomic Safety and Licensing Board Panel 83/10/19 254pp
20895 001 24X Fiche 50-413, 83/10/19, 8310250003

8310250001 Transcript of 831020 hearing in Rock Hill, SC Pp 4,000-4,240
* Atomic Safety and Licensing Board Panel 83/10/20 248pp
20893 001 24X Fiche 50-413, 83/10/20, 8310250001

8310280031 Transcript of 831021 hearing in Rock Hill, SC Pp 4,249-4,361
* Atomic Safety and Licensing Board Panel 83/10/21 112pp
20933 209 24X Fiche 50-413, 83/10/21, 8310280031

8310310358 Transcript of 831025 hearing in Rock Hill, SC Pp 4,362-4,620
* Atomic Safety and Licensing Board Panel 83/10/25 267pp
20960 016 24X Fiche 50-413, 83/10/25, 8310310358

DOCKET 50-414 CATAWBA NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8308300355 Board Notification 83-66A advises that position re red drop issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycle
EISENHUT, D G Division of Licensing 83/09/29 PALLADINO, N J Commissioners 10pp 20632 106 24X Fiche 50-000, 83/09/29, 8308300355

8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Canyon 1 & 2 Fermi 2 & Callaway
EISENHUT, D G Division of Licensing 83/09/29 PALLADINO, N J Commissioners 3pp 20632 001 24X Fiche 50-000, 83/09/29, 8308300357

8310030412 Trip rept of 830920 site visit including plant tour & meeting w/util mgt
JDOSTEN, J K Commissioners 83/09/29 Commissioners 10pp 20593 109 24X Fiche 50-413, 83/09/29, 8310030412

8308300763 Board Notification 83-151 provides info re desirability of current ECCS actuation logic for Westinghouse plants, in light of recent info concerning steam generator tube rupture procedure for Darasels Nuclear Power Station
EISENHUT, D G Division of Licensing 83/10/04 PALLADINO, N J Commissioners 2pp 20678 033 24X Fiche 50-000, 83/10/04, 8308300763

8310210179 Comments on incorrect statements noted in 830929 trip rept Correct milestone date for Unit 1 hot functional testing is Nov 1983 & May 1984 for fuel loading
TUCKER, H B Duke Power Co 83/10/13 GILINSKY, V Commissioners 2pp 20856 125 24X Fiche 50-413, 83/10/13, 8310210179

8308310050 Board Notification 82-160 provides info re 830812 failure of main crankshaft on one of three Transamerica Delaval emergency diesel generators at Shoreham
EISENHUT, D G Division of Licensing 83/10/14 PALLADINO, N J Commissioners 11pp 67056 070 24X Fiche 50-000, 83/10/14, 8308310050

8310240245 Forwards notice of receipt of request for action under 10CFR2 206 for 830914 petition submitted on behalf of Palmetto Alliance, requesting mgt audit of util & independent review of as-built condition of plant
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/10/14 GARBE, D P Government Accountability Project 3pp 20907 280 24X Fiche 50-413, 83/10/14, 8310240245

--8310240249 Notice of receipt of request for action under 10CFR2 206 for 830914 petition submitted on behalf of Palmetto Alliance, requesting mgt audit of util & independent review of as-built condition of plant
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/10/14 1p 20907 283 24X Fiche 50-413, 83/10/14, 8310240245

E NRC Safety Evaluation Report (SLR), suppl & correspondence

8310070150 Notification of 830930 meeting w/util in Bethesda, MD to discuss internal corrosion protection for fuel oil storage tanks (SER License Condition 18) & emergency lighting (SER Open Item 150)
JABBOUR, K N Licensing Branch 4 83/09/27 ADENSAM, E G Licensing Branch 4 2pp 20680 306 24X Fiche 50-413, 83/09/27, 8310070150

8310040016 Forwards one oversize revised flow diagram to comply w/Section 10 4 9 of SER re License Condition 20, loss of primary source of condensate storage water Aperture card is available in PDR
TUCKER, H B Duke Power Co 83/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 20615 034 24X Fiche 50-413, 83/09/28, 8310040016

8310190264 Notification of 831027 meeting w/util in Bethesda, MD to discuss technical issues re SER Confirmatory Item 1, "RMP & Effects on Safety-Related Structures & Components"
JABBOUR, K N Licensing Branch 4 83/10/12 ADENSAM, E G Licensing Branch 4 3pp 20843 162 24X Fiche 50-413, 83/10/12, 8310190264

8310190165 Advises that design max temp of standby nuclear svc water pond raised from 95 F to 100 F, in response to SER 1, Open Item 2 Info will be incorporated in FSAR, Rev B
TUCKER, H B Duke Power Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 3pp 20821 065 24X Fiche 50-413, 83/10/13, 8310190165

DOCKETED ITEMS

303

8310190195 Advises that installation of voltmeters to determine reactor trip status by measuring P-4 signal in reactor trip breaker cabinets completed, in response to SER Confirmatory Item 27
TUCKER, H B Duke Power Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSA, E O Licensing Branch 4 1p 20820 203 24X Fiche 50-413, 83/10/13, 8310190195

8310190262 Forwards description of analysis & results to confirm that sufficient time exists to reestablish LHR if RHR says inadvertently isolated as result of loss of instrument bus, in response to SER 1, Open Item 12
TUCKER, H B Duke Power Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSA, E O Licensing Branch 4 3pp 20818 061 24X Fiche 50-413, 83/10/13, 8310190262

8308300779 Board Notification 83-140A forwards Board Notification 83-128 re draft test rept on qualification test program of Class 1E solenoid valves Resolution will be handled under Outstanding Issue 4 in SER
MCVAK, T M Assistant Director for Licensing 83/10/17 Atomic Safety and Licensing Board Panel 3pp 20855 167 24X Fiche 50-413, 83/10/17, 8308300779

8310280096 Responds to SER Open Item 6 re NUREG-0737, Item 11 i 2, "Instrumentation for Detection of Inadequate Core Cooling," providing updated FSAR pages concerning core exit thermocouples & reactor vessel level measurement
TUCKER, H B Duke Power Co 83/10/19 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSA, E O Licensing Branch 4 13pp 20935 191 24X Fiche 50-413, 83/10/19, 8310280096

Security, medical, emergency & fire protection plans

8310040406 Forwards IE Insp Repts 50-413/83-23 & 50-414/83-20 on 830801-05 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/13 TUCKER, H B Duke Power Co 2pp 20619 094 24X Fiche 50-413, 83/09/13, 8310040406

8310040413 IE Insp Repts 50-413/83-23 & 50-414/83-20 on 830801-05 No noncompliance noted Major areas inspected preoperational emergency preparedness, including Procedure TI 2515/55 re readiness for emergency plan implementation appraisal
HUFFMAN, O N Region 2, Office of Director 83/09/08 10pp 20619 096 24X Fiche 50-413, 83/09/13, 8310040406

8310040287 Forwards Rev 2 to 830414 response to Suppl 1 to NUREG-0737, including rept on review of Reg Guide 1.9
TUCKER, H B Duke Power Co 83/09/26 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSA, E O Licensing Branch 4 91pp 20614 077 24X Fiche 50-413, 83/09/26, 8310040287

8310070150 Notification of 830920 meeting w/util in Bethesda, MD to discuss internal corrosion protection for fuel oil storage tanks (SER License Condition 18) & emergency lighting (SER Open Item 130)
JABBOUR, K N Licensing Branch 4 83/09/27 ADENSA, E O Licensing Branch 4 2pp 20680 306 24X Fiche 50-413, 83/09/27, 8310070150

8310250383 Forwards IE Insp Repts 50-413/83-29 & 50-414/83-25 on 830914 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/30 TUCKER, H B Duke Power Co 2pp 20898 139 24X Fiche 50-413, 83/09/30, 8310250383

8310250392 IE Insp Repts 50-413/83-29 & 50-414/83-25 on 830914 No noncompliance noted Mgt meeting held to discuss NRC insp program for emergency planning
HUFFMAN, O N Region 2, Office of Director 83/09/28 2pp 20698 141 24X Fiche 50-413, 83/09/30, 8310250383

8310070134 Releases public version of revised crisis mgt plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/04 Document Management Branch 1p 20670 001 24X Fiche 50-000, 83/10/04, 8310070134

8310070143 Forwards public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.1 re recovery manager & immediate staff group plan & 5.3.4 re scheduling/planning support group
TUCKER, H B Duke Power Co 83/07/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20670 002, 24X Fiche 50-000, 83/10/04, 8310070134

8310070152 Public version of revised crisis mgt plan implementing procedures, including Procedure 5.3.1 re recovery manager & immediate staff group plan & 5.3.4 re scheduling/planning support group
Duke Power Co 83/07/01 457pp, 20670.005 24X Fiche 50-000, 83/10/04, 8310070134

8310110607 Notification of 831001-04 site meetings w/util to audit fire protection program
JABBOUR, K N Licensing Branch 4 83/10/04 ADENSA, E O Licensing Branch 4 5pp 20701 357 24X Fiche 50-413, 83/10/04, 8310110607

8310250635 Informs that periodic evaluation of SALP complete Rept approved
O'REILLY, J P Region 2, Office of Director 83/10/17 TUCKER, H B Duke Power Co 3pp 20900 205 24X Fiche 50-000, 83/10/17, 8310250635

--8310250652 SALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983
* Region 2, Office of Director 83/08/02 56pp 20900 211 24X Fiche 50-000, 83/10/17, 8310250635

G Adjudicatory correspondence

8308300480 Forwards answer to util & NRC motions for summary disposition of Contentions 11, 17 & 27 Proposed schedule for emergency planning proceeding encl
GUILD, R GUILD, R Palmetto Alliance 83/08/26 KELLEY, J L, FOSTER, R F, CALLIHAN, D Atomic Safety and Licensing Board Panel 3pp 20210 327 24X Fiche 50-413, 83/08/26, 8308300480

--8308300486 Answer opposing util & NRC motions for summary disposition of Contentions 11, 17 & 27 Many substantial & matl issues of fact exist affecting public health & safety & environ. Certificate of Evc encl
GUILD, R Palmetto Alliance GUILD, R GUILD, R 83/08/26 Atomic Safety and Licensing Board Panel 25pp 20210:330. 24X Fiche 50-413, 83/08/26, 8308300480

8310050406 Submits list of NRC witnesses to appear at hearing on Palmetto Alliance Contention 16 & Carolina Environ Study Group Contention 18/Palmetto Alliance Contention 44. W/o encl
JOHNSON, G E Hearing Branch 4 83/09/23 KELLEY, J L, FOSTER, R F, CALLIHAN, D Atomic Safety and Licensing Board Panel 3pp 20630 123 24X Fiche 50-413, 83/09/23, 8310050406

8310030406 Forwards signed & corrected PA Evans affidavit. Related correspondence
MCARRY, J M Debovoise & Liberman MCARRY, J M Duke Power Co 83/09/27 KELLEY, J L, CALLIHAN, A D, FOSTER, R F, Atomic Safety and Licensing Board Panel 1p 20593 132 24X Fiche 50-413, 83/09/27, 8310030406

--8310030409 Affidavit of PA Evans in response to Palmetto Alliance allegations that self-initiated evaluation identified problems which are symptomatic of systematic deficiencies in plant const
EVANS, P A Duke Power Co 83/09/27, 12pp 20593 133 24X Fiche 50-413, 83/09/27, 8310030406

8310030412 Trig rept of 830920 site visit including plant tour & meeting w/util mgt
JOHNSON, J K Commissioners 83/09/29, Commissioners, 18pp 20593 109 24X Fiche 50-413, 83/09/29, 8310030412

8310060295 Ack receipt of 830816 ltr requesting info on util spent fuel mgt plans Area is ever changing so precise mix of options util will adopt is difficult to predict. Flexibility must exist in future Related correspondence.
GRIFFITH, B C Duke Power Co 83/09/29 WILSON, R P, South Carolina, State of 3pp 20641 005 24X Fiche 50-413, 83/09/29, 8310060295

8310040177 Memorandum & order ruling on objections to ASLB 830914 prehearing conference order Hearing will commence on 831004
KELLEY, J L Atomic Safety and Licensing Board Panel, 83/09/30 Palmetto Alliance 11pp 20608 254 24X Fiche 50-413, 83/09/30, 8310040177.

8310050562 Objection to Palmetto Alliance 830924 request for issuance of ASLB subpoena to JP O'Reilly, Region 11 administrator, based on ASLB 830912 denial of identical request. Partial transcript of 830831 telcon & Certificate of Evc encl.
JOHNSON, G E Hearing Branch 4, 83/10/03 Atomic Safety and Licensing Board Panel 36pp 20629 001 24X Fiche 50-413, 83/10/03, 8310050562

831010294 Requests 831017 meeting in Charlotte, NC to discuss discovery needs re emergency planning contentions & projected schedule for completing discovery for all parties before 840201. Related correspondence.
CARR, A V Duke Power Co 83/10/04 GUILD, R Palmetto Alliance, RILEY, J L Carolina Environmental Study Group 1p, 20665 338 24X Fiche 50-413, 83/10/04, 831010294

DOCKETED ITEMS

Q Inspection reports, IE Bulletins & correspondence

8310110044 Responds to FOIA request for SALP documents, written or routed since 1979, which mention or refer to Facility & describe or provide info on SALP insp findings or conclusions re SALP reviews Forwards App A documents
FELTON, J M Division of Rules and Records 83/07/20 RIDENHOUR, R
Gambit 2pp 20713 308 24X Fiche 50-000, 83/07/20, 8310110044

--8310110059 Forwards case chronology re allegations concerning welding issues at facilities w/o encl
ALDERSON, C E Region 2, Office of Director 83/02/23
JOHNSON, G E Office of the Executive Legal Director 1p
20713 341 24X Fiche 50-413, 83/07/20, 8310110044

8310040329 Forwards IE Insp Repts 50-413/83-24 & 50-414/83-21 on 830816-19 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/02
TUCKER, H B Duke Power Co 2pp 20617 085 24X
Fiche 50-413, 83/09/02, 8310040329

--8310040345 IE Insp Repts 50-413/83-24 & 50-414/83-21 on 830816-19 No noncompliance noted Major areas inspected const progress, as-built & insp of 10CFR21 regulations
MCFARLAND, C R, WRIGHT, R W Region 2, Office of Director
UPRIGHT, C M Division of Engineering & Operational Programs 83/09/01 7pp 20617 087 24X Fiche 50-413, 83/09/02, 8310040329.

8310040406 Forwards IE Insp Repts 50-413/83-23 & 50-414/83-20 on 830801-05 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/13
TUCKER, H B Duke Power Co 2pp 20619 094 24X
Fiche 50-413, 83/09/13, 8310040406

--8310040413 IE Insp Repts 50-413/83-23 & 50-414/83-20 on 830801-05 No noncompliance noted Major areas inspected preoperational emergency preparedness, including Procedure TI 2515/55 re readiness for emergency plan implementation appraisal
HUFFMAN, G N Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/09/08 10pp
20619 096 24X Fiche 50-413, 83/09/13, 8310040406

8310040599 Forwards supplemental response to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Components by Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel) " Final rept re infestation to be available by 831101
TUCKER, H B Duke Power Co 83/09/16 O'REILLY, J P Region 2, Office of Director 2pp 20626 174 24X Fiche 50-413, 83/09/16, 8310040599

8310040313 Ack receipt of 830908 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/83-17 & 50-414/83-16
LEWIS, R C Division of Project & Resident Programs 83/09/22
TUCKER, H B Duke Power Co 1p 20649 299 24X
Fiche 50-413, 83/09/22, 8310040313

--8310040319 Responds to NRC 830811 ltr re violations noted in IE Insp Repts 50-413/83-17 & 50-414/83-16 Corrective actions signoff for const engineer-civil restricted to eight experienced personnel
TUCKER, H B Duke Power Co 83/09/08 O'REILLY, J P Region 2, Office of Director 4pp 20649 300 24X Fiche 50-413, 83/09/22, 8310040313

--8310040323 Forwards IE Insp Repts 50-413/83-17 & 50-414/83-16 on 830711-15 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/08/11
TUCKER, H B Duke Power Co 2pp 20649 304 24X
Fiche 50-413, 83/09/22, 8310040313

--8310040327 Notice of violation from insp on 830711-15
* Region 2, Office of Director 83/08/11 2pp 20649 306 24X
Fiche: 50-413, 83/09/22, 8310040313

--8310040335 IE Insp Repts 50-413/83-17 & 50-414/83-16 on 830711-15 Noncompliance noted improper concrete mix placed & checklists for certification of structural inspector, concrete, Level I, improperly labeled as Level II.
WRIGHT, R W, JACKSON, L H Region 2, Office of Director
UPRIGHT, C M Division of Emergency Preparedness & Materials Safety, 83/08/08 10pp 20649 308 24X Fiche 50-413, 83/09/22, 8310040313

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20734 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 110pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310250398 Forwards IE Insp Repts 50-413/83-27 & 50-414/83-24 on 830906-09 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/26
TUCKER, H B Duke Power Co 2pp 20097 284 24X
Fiche 50-413, 83/09/26, 8310250398

--8310250404 IE Insp Repts 50-413/83-27 & 50-414/83-24 on 830906-09 No noncompliance noted Major areas inspected const progress, licensee action on previous enforcement matters, steam generator mod & review of QA implementing procedures
KLEINSORGE, W P Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/09/21 7pp
20897 286 24X Fiche 50-413, 83/09/26, 8310250398

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 SV Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310250383 Forwards IE Insp Repts 50-413/83-29 & 50-414/83-25 on 830914 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/30
TUCKER, H B Duke Power Co 4pp 20848 139 24X
Fiche 50-413, 83/09/30, 8310250383

--8310250392 IE Insp Repts 50-413/83-29 & 50-414/83-25 on 830914 No noncompliance noted Mgt meeting held to discuss NRC insp program for emergency planning
HUFFMAN, G N Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/09/28 2pp
20898 141 24X Fiche 50-413, 83/09/30, 8310250383

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310250635 Informs that periodic evaluation of SALP complete Rept approved
O'REILLY, J P Region 2, Office of Director 83/10/17 TUCKER, H B Duke Power Co 3pp 20900 205 24X Fiche 50-000, 83/10/17, 8310250635

--8310250646 Forwards SALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983
LEWIS, R C Division of Project & Resident Programs 83/08/02
TUCKER, H B Duke Power Co 3pp 20900 208 24X
Fiche 50-000, 83/10/17, 8310250635

--8310250652 SALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983
* Region 2, Office of Director 83/08/02 56pp 20900 211 24X
Fiche 50-000, 83/10/17, 8310250635

DOCKETED ITEMS

305

--8310250665 Responds to 830802 ltr re SALP board rept Rept incomplete & premature in certain areas in general, until endorses observations re facility performance
TUCKER, H B Duke Power Co 83/08/29 O'REILLY, J P Region 2, Office of Director 2pp 20900 267 24X Fiche 50-000, 83/10/17, 8310250635

Reportable occurrences, LERs & related correspondence

8310060038 Interim significant Deficiency Rept SD 413-414/83-10 re failure of power supply printed circuit card adhesive bond of heat sink assembly for inverter transistors Initially reported on 830615 Assemblies will be replaced by 831201
TUCKER, H B Duke Power Co 83/09/27 O'REILLY, J P Region 2, Office of Director 2pp 20647 085 24X Fiche 50-413, 83/09/27, 8310060038

8310060052 Significant Deficiency Rept SD 83-11 re faulty Westinghouse KSSS process instrumentation & control sys temp channel test card mercury relays Initially reported on 830829 Replacement relay testing underway
TUCKER, H B Duke Power Co 83/09/27 O'REILLY, J P Region 2, Office of Director 2pp 20648 326 24X Fiche 50-413, 83/09/27, 8310060052

8310210111 Significant Deficiency Rept SD 413-414/83-12 re metal file found in diesel generators 1B & 2A Initially reported on 830913 File found in air gap between rotor & stator during preliminary checkout
TUCKER, H B Duke Power Co 83/10/13 O'REILLY, J P Region 2, Office of Director 3pp 20858 255 24X Fiche 50-413, 83/10/13, 8310210111

8310270482 Revised interim Significant Deficiency Rept SD 413-414/82-06 re socket welds dtd 820415 Required work on Unit 1 completed Unit 2 incomplete due to incomplete list of affected socket welds Completion expected by 830201
TUCKER, H B Duke Power Co 83/10/17 O'REILLY, J P Region 2, Office of Director 1p 20922 011 24X Fiche 50-413, 83/10/17, 8310270482

8308310045 Board Notification 83-14/ supplies new info re apparent diesel generator deficiency On 830914, metal file found in diesel generators Investigation underway to determine circumstances surrounding incidences
NOVAK, F M Assistant Director for Licensing 83/10/25 Atomic Safety and Licensing Board Panel 5pp 20929 014 24X Fiche 50-413, 83/10/25, 8308310045

Hearing transcripts on non-antitrust matters

8310240012 Partial response to FOIA request for transcripts of deposition testimony prepared in discovery in DL proceeding for facilities Forwards App A documents Documents also available in FDR
FELTON, J M Division of Rules and Records 83/08/10 AHLERS, D M Palmetto Alliance 3pp 20885 001 24X Fiche 50-413, 83/08/10, 8310240012

--8310240014 Transcript of M Birch deposition in Charlotte, NC re Contention 27.
BIRCH, M Duke Power Co 83/05/11 126pp 20885 008 24X Fiche 50-413, 83/08/10, 8310240012

--8310240017 Transcript of CW Graves deposition in Charlotte, NC re Contention 8
GRAVES, C W Duke Power Co 83/05/12 44pp 20885 134 24X Fiche 50-413, 83/08/10, 8310240012

8310240018 Transcript of PK Vandoorn deposition in Charlotte, NC re Contention 6
VANDDOORN, P K Duke Power Co 83/05/19 150pp 20885 178 24X Fiche 50-413, 83/08/10, 8310240012

8310240021 Transcript of WR McAfee deposition in Charlotte, NC re Contention 6
MCAFEE, W R Palmetto Alliance 83/05/19 128pp 20885 328 24X Fiche 50-413, 83/08/10, 8310240012

8310240022 Transcript of NL Hoopengardner deposition in Charlotte, NC re Contention 6
HOOPENGARDNER Palmetto Alliance 83/05/19 47pp, 20886 074 24X Fiche 50-413, 83/08/10, 8310240012

8310240024 Transcript of NR Hoopengardner deposition in Charlotte, NC re Contention 6
HOOPENGARDNER, N. Palmetto Alliance, 83/05/20 107pp 20886 142, 24X Fiche 50-413, 83/08/10, 8310240012

--8310240030 Transcript of OE Vaughn deposition in Charlotte, NC re Contention 7
VAUGHN, O E Duke Power Co 83/05/20 41pp 20886 231 24X Fiche 50-413, 83/08/10, 8310240012

--8310240032 Transcript of JC Bryant deposition in Charlotte, NC re Contentions 6 & 7
BRYANT, J C NRC - No Detailed Affiliation Given 83/05/20 80pp 20886 292 24X Fiche 50-413, 83/08/10, 8310240012

--8310240038 Transcript of PK Vandoorn deposition in Charlotte, NC re Contention 6, Vol 11
VANDDOORN, P K Duke Power Co 83/05/20 137pp 20887 011 24X Fiche 50-413, 83/08/10, 8310240012

--8310240040 Transcript of DG Addis deposition in Charlotte, NC re Contention 6
ADDIS, D G Duke Power Co 83/06/27 129pp 20887 139 24X Fiche 50-413, 83/08/10, 8310240012

--8310240043 Transcript of GH Bell deposition in Charlotte, NC re Contention 6
BELL, G H Duke Power Co 83/06/27 75pp 20887 269 24X Fiche 50-413, 83/08/10, 8310240012

--8310240047 Transcript of JC Rogers deposition in Charlotte, NC re Contention 6
ROGERS, J C Duke Power Co 83/06/27 32pp 20887 346 24X Fiche 50-413, 83/08/10, 8310240012

--8310240049 Transcript of WD Henry deposition in Charlotte, NC re Contention 6
HENRY, W D Duke Power Co 83/06/28 133pp 20888 017 24X Fiche 50-413, 83/08/10, 8310240012

--8310240053 Transcript of DO Beam deposition in Charlotte, NC re Contention 6
BEAM, D O Duke Power Co 83/06/28 81pp 20888 152, 24X Fiche 50-413, 83/08/10, 8310240012

--8310240055 Transcript of WD Henry deposition in Charlotte, NC re Contention 6
HENRY, W D Duke Power Co 83/06/29 63pp 20888 235 24X Fiche 50-413, 83/08/10, 8310240012

--8310240056 Transcript of AE Allum 830629 deposition in Charlotte, NC re Contention 6
ALLUM, A E Duke Power Co 83/06/29 114pp, 20888 300 24X Fiche 50-413, 83/08/10, 8310240012

--8310240057 Transcript of GR Baldwin 830629 deposition in Charlotte, NC re Contention 6
BALDWIN, C R Duke Power Co 83/06/29 191pp 20889 092 24X Fiche 50-413, 83/08/10, 8310240012

--8310240058 Transcript of JE Orogan deposition in Charlotte, NC Related info encl
GROGAN, J E Duke Power Co 83/07/01 27pp 20889 241 24X Fiche 50-413, 83/08/10, 8310240012

--8310240059 Transcript of WH Bradley deposition in Charlotte, NC re Contention 6
BRADLEY, W H Duke Power Co 83/07/07 56pp 20889 270 24X Fiche 50-413, 83/08/10, 8310240012

--8310240060 Transcript of CN Alexander deposition in Charlotte, NC re Contention 6 Related info encl
ALEXANDER, C N Duke Power Co 83/07/07, 110pp, 20889 327 24X Fiche 50-413, 83/08/10, 8310240012

--8310240061 Transcript of WS Lee deposition in Charlotte, NC Related info encl
LEE, W S Duke Power Co 83/07/12 78pp 20890 074, 24X Fiche 50-413, 83/08/10, 8310240012

--8310240062 Transcript of RA Morgan deposition in Charlotte, NC re Contention 6
MORGAN, R A Duke Power Co 83/07/13 120pp, 20890 153 24X Fiche 50-413, 83/08/10, 8310240012

--8310240065 Transcript of BW Deaton deposition in Charlotte, NC re Contention 6
DEATON, B W Duke Power Co 83/07/14 47pp, 20890 274 24X Fiche 50-413, 83/08/10, 8310240012

--8310240068 Transcript of S Ledford deposition in Charlotte, NC re Contention 6
LEDFOORD, S Duke Power Co 83/07/14, 24pp 20890 325 24X Fiche 50-413, 83/08/10, 8310240012

DOCKETED ITEMS

--8310240073 Transcript of JC Shropshire deposition in Charlotte, NC re Contention 6 Related info encl
SHROPSHIRE, J C Duke Power Co 83/07/14 89pp 20890 353 24X
Fiche 50-413, 83/08/10, 8310240012

--8310240076 Transcript of L Sifford deposition in Charlotte, NC re Contention 6
SIFORD, W L Duke Power Co 83/07/14 38pp 20891 083 24X
Fiche 50-413, 83/08/10, 8310240012

8310050386 Forwards testimony of BJ Elliot, WL Brooks, A Singh, F Clemenson, RJ Serbu & F Jape on Palmetto Alliance Contention 14 & Carolina Environ Study Group Contention 18/ Palmetto Alliance 44
JOHNSON, O E Operations & Administrative Division 83/09/30
KELLEY, J L, FOSTER, R F, CALLIHAM, D Atomic Safety and Licensing Board Panel 1p 20630 140 24X Fiche 50-413, 83/09/30, 8310050386

--8310050392 Testimony of BJ Elliot on Carolina Environ Study Group Contention 18/Palmetto Alliance Contention 44 re reactor embrittlement
ELLIOT, B J Materials Engineering Branch 83/09/30 22pp 20630 141 24X Fiche 50-413, 83/09/30, 8310050386

--8310050401 Testimony of WL Brooks on Palmetto Alliance Contention 14 re criticality
BROOKS, W L Core Performance Branch 83/09/30 12pp 20630 163 24X Fiche 50-413, 83/09/30, 8310050386

--8310050415 Joint testimony of A Singh & F Clemenson on Palmetto Alliance Contention 14 re spent fuel pool cooling sys
SINGH, A, CLEMENSON, F Auxiliary Systems Branch 83/09/30 18pp 20630 175 24X Fiche 50-413, 83/09/30, 8310050386

--8310050419 Joint testimony of RJ Serbu & F Jape on Palmetto Alliance Contention 14 re spent fuel handling
SERBU, R J Radiological Assessment Branch JAPE, F Division of Engineering & Operational Programs 83/09/30 17pp 20630 173 24X Fiche 50-413, 83/09/30, 8310050386

831010270 Testimony of JL Riley re Contention 18 concerning unanticipated rapid embrittlement Affirmation of Svc encl
Related correspondence
RILEY, J L Carolina Environmental Study Group 83/10/03 14pp 20666 144 24X Fiche 50-413, 83/10/03, 831010270

8310060310 Testimony of TR Mager & TA Meyer re Carolina Environ Study Group & Palmetto Alliance Contention 18/44 Ref temp will not exhibit more rapid increase than calculations show due to radiation effects on vessel W/Certificate of Svc
MAGER, T R, MEYER, T A Duke Power Co MAGER, T R Westinghouse Electric Corp 83/10/04 26pp, 20646-201 24X
Fiche 50-413, 83/10/04, 8310060310

8310110098 Transcript of 831004 hearing in Rock Hill, SC Pp 1,535-1,734
* Atomic Safety and Licensing Board Panel 83/10/04 202pp, 20667 312 24X Fiche 50-413, 83/10/04, 8310110098

8310120352 Transcript of 831005 hearing in Rockhill, SC Pp 1,735-1,962
* Atomic Safety and Licensing Board Panel 83/10/05 228pp 20699 323 24X Fiche 50-413, 83/10/05, 8310120352

8310130013 Transcript of 831006 hearing in Rockhill, SC Pp 1,963-2,207
* Atomic Safety and Licensing Board Panel 83/10/06 245pp 20725 292 24X Fiche 50-413, 83/10/06, 8310130013

8310120295 Transcript of 831007 hearing in Rockhill, SC Pp 2,208-2,379
* Atomic Safety and Licensing Board Panel 83/10/07 172pp 20693 172 24X Fiche 50-413, 83/10/07, 8310120295

8310170137 Transcript of 831011 hearing in Rockhill, SC Pp 2,380-2,592
* Atomic Safety and Licensing Board Panel 83/10/11 213pp 20788 354 24X Fiche 50-413, 83/10/11, 8310170137

8310170456 Transcript of 831012 hearing in Rockhill, SC Pp 2,593-2,832
* Atomic Safety and Licensing Board Panel 83/10/12 241pp, 20778 279 24X Fiche 50-413, 83/10/12, 8310170456

8310190115 Transcript of 831013 hearing in Rockhill, SC Pp 2,833-3,060
* Atomic Safety and Licensing Board Panel 83/10/13 228pp 20818 232 24X Fiche 50-413, 83/10/13, 8310190115

8310190119 Transcript of 831013 hearing in Rockhill, SC Pp 1-67
* Atomic Safety and Licensing Board Panel 83/10/13 68pp 20820 340 24X Fiche 50-413, 83/10/13, 8310190119

8310190122 Transcript of 831014 hearing in Rockhill, SC Pp 3,061-3,297
* Atomic Safety and Licensing Board Panel 83/10/14 237pp 20819 244 24X Fiche 50-413, 83/10/14, 8310190122

8310210050 Transcript of 831017 hearing in Rockhill, SC Pp 3,298-3,495
* Atomic Safety and Licensing Board Panel 83/10/17 198pp 20874 281 24X Fiche 50-413, 83/10/17, 8310210050

8310210186 Testimony of WH Bradley re quality or safety concerns expressed by welding inspectors Related correspondence
BRADLEY, W H Duke Power Co 83/10/17 5pp 20856 107 24X
Fiche 50-413, 83/10/17, 8310210186

--8310210192 Testimony of WD Henry re quality or safety concerns expressed by welding inspectors Certificate of Svc encl
Related correspondence
HENRY, W D Duke Power Co 83/10/17 9pp 20856 112 24X
Fiche 50-413, 83/10/17, 8310210186

8310240013 Transcript of 831018 hearing in Rockhill, SC Pp 3,496-3,740
* Atomic Safety and Licensing Board Panel 83/10/18 245pp, 20890 073 24X Fiche 50-413, 83/10/18, 8310240013

8310250003 Transcript of 831019 hearing in Rock Hill, SC Pp 3,741-3,999
* Atomic Safety and Licensing Board Panel 83/10/19 254pp 20895 001 24X Fiche 50-413, 83/10/19, 8310250003

8310250001 Transcript of 831020 hearing in Rock Hill, SC Pp 4,000-4,240
* Atomic Safety and Licensing Board Panel 83/10/20 248pp 20893 001 24X Fiche 50-413, 83/10/20, 8310250001

8310280031 Transcript of 831021 hearing in Rock Hill, SC Pp 4,249 4,361
* Atomic Safety and Licensing Board Panel 83/10/21 112pp 20933 209 24X Fiche 50-413, 83/10/21, 8310280031

8310310358 Transcript of 831025 hearing in Rock Hill, SC Pp 4,362-4,689
* Atomic Safety and Licensing Board Panel 83/10/25 267pp 20960 016 24X Fiche 50-413, 83/10/25, 8310310358

DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1

E MRC Safety Evaluation Report (SER), supp's & correspondence

8310180330 Provides addl info on SER Confirmatory Item 1 10(4) re soil structure interaction, in fulfillment of commitments made in response to NRC 830112 ltr Util committed to utilizing elastic half-space methodology
DALE, L F Mississippi Power & Light Co 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 2080P 348 24X Fiche 50-416, 83/10/14, 8310180330

F Security, medical, emergency & fire protection plans

8310040394 Forwards summary of 830909 meeting in Region 11 of re proposed physical security plan mods
LEWIS, R C Division of Project & Resident Programs 83/09/26
RICHARD, J B Mississippi Power & Light Co 3pp 20619 041 24X
Fiche 50-416, 83/09/26, 8310040394

8310180430 Forwards Rev 9 to physical security plan Rev withheld (ref 10CFR2 790 & 10CFR9 5)
DALE, L F Mississippi Power & Light Co 83/09/30 D'REILLY, J P Region 2, Office of Director 2pp 20803 297 24X
Fiche 50-416, 83/09/30, 8310180430

8310120349 Advises that due to uncertainty in instrumentation availability & manpower resources, instrumentation necessary to meet Reg Guide 1.97 requirements will be implemented by third refueling outage per Suppl 1 to NUREG-0737
DALE, L F Mississippi Power & Light Co 83/10/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20700 231 24X Fiche 50-416, 83/10/10, 8310120349

8310170141 Forwards IE Safeguards Insp Rept 50-416/83-40 on 830912-16 No noncompliance noted
VERRELLI, D Division of Project & Resident Programs 83/10/11, RICHARD, J B Mississippi Power & Light Co 2pp 20788 351 24X
Fiche 50-416, 83/10/11, 8310170141

--8310170149 IE Safeguards Insp Rept 50-416/83-40 on 830912-16 No noncompliance noted Major areas inspected: review of security organization-response, security program audit, records & repts Details withheld (ref 10CFR73 21)
ENNIS, J D Region 2, Office of Director MCQUIRE, D R Division of Emergency Preparedness & Materials Safety 83/10/06 1p 20788 353 24X Fiche 50-416, 83/10/11, 8310170141

DOCKETED ITEMS

307

H General correspondence

8310190222 Responds to 830906 telephoned comments re NRC proposed NSHC determination on amend requests NRC made final NSHC determination on 830923 Opportunity for hearing will be afforded after FR notice published
SCHWENCER, A Licensing Branch 2 83/10/07 LAWRENCE, K
Affiliation Unknown 5pp 20838 164 24X Fiche 50-416, 83/10/07, 8310190222

F Operating license stage documents & correspondence

8310030081 Forwards Amend 9 to License NPF-13, safety evaluation & notice of issuance & availability Amend corrects editorial & nomenclature errors to achieve consistency w/as-built condition of plant
SCHWENCER, A Licensing Branch 2 83/07/15 MCGAUGHY, J P
Mississippi Power & Light Co 5pp 20603 258 24X
Fiche 50-416, 83/07/15, 8310030081

--8310030085 Amend 9 to License NPF-13, correcting editorial & nomenclature errors to achieve consistency w/as-built condition of plant
SCHWENCER, A Licensing Branch 2 83/07/15 122pp 20603 262
24X Fiche 50-416, 83/07/15, 8310030085

--8310030089 Safety evaluation supporting Amend 9 to License NPF-13
* Office of Nuclear Reactor Regulation, Director 83/07/15 6pp.
20604 023 24X Fiche 50-416, 83/07/15, 8310030089

--8310030104 Notice of issuance & availability of Amend 9 to License NPF-13
SCHWENCER, A Licensing Branch 2 83/07/15 4pp 20604 029 24X
Fiche 50-416, 83/07/15, 8310030104

8310040046 Forwards request for addl info re 830610 GA program update
LEWIS, R C Division of Project & Resident Programs 83/07/23
RICHARD, J B Mississippi Power & Light Co 5pp 20608 138 24X
Fiche 50-416, 83/07/23, 8310040046

8310050067 Agrees that pneumatic testing of containment isolation valves more conservative than hydrostatic testing & represents acceptable alternative per 830926 ltr
SCHWENCER, A Licensing Branch 2 83/07/23 MCGAUGHY, J P
Mississippi Power & Light Co 2pp 20650 135 24X
Fiche 50-416, 83/07/23, 8310050067

8310050073 Advises that 830721 & 0823 revs to startup test program acceptable
SCHWENCER, A Licensing Branch 2 83/07/23 MCGAUGHY, J P
Mississippi Power & Light Co 2pp 20649 361 24X
Fiche 50-416, 83/07/23, 8310050073

8310060033 Forwards Amend 10 to License NPF-13 & safety evaluation Amend changes Tech Specs & grants one-time exceptions to Tech Specs for relief needed for restart
SCHWENCER, A Licensing Branch 2 83/07/23 MCGAUGHY, J P
Mississippi Power & Light Co 6pp 20664 073 24X
Fiche 50-416, 83/07/23, 8310060033

--8310060037 Amend 10 to License NPF-13, changing Tech Specs & granting one-time exceptions to Tech Specs for restart
SCHWENCER, A Licensing Branch 2 83/07/23 12pp 20664 078
24X Fiche 50-416, 83/07/23, 8310060037

--8310060050 Safety evaluation supporting Amend 10 to License NPF-13
* NRC - No Detailed Affiliation Given 83/07/23 11p
20664 070 24X Fiche 50-416, 83/07/23, 8310060050

8310060057 Forwards Amend 11 to License NPF-13 & safety evaluation. Amend grants change to license condition re completion of control room envelope leak tightness test
SCHWENCER, A Licensing Branch 2 83/07/23 MCGAUGHY, J P
Mississippi Power & Light Co 3pp 20664 064 24X
Fiche 50-416, 83/07/23, 8310060057

--8310060064 Amend 11 to License NPF-13 changing Tech Specs re completion of control room envelope leak tightness test
EISENHUT, D G Division of Licensing 83/07/23 3pp 20664:067
24X Fiche 50-416, 83/07/23, 8310060064

--8310060071 Safety evaluation supporting Amend 11 to License NPF-13
* NRC - No Detailed Affiliation Given 83/07/23 3pp
20664 070 24X Fiche 50-416, 83/07/23, 8310060071

8310130343 Requests publication of FR notice of consideration of issuance of amend to License NPF-13 & proposed NSHC determination & opportunity for hearing re restart changes to Tech Specs NSHC determination available in Central Files
SCHWENCER, A Licensing Branch 2 83/07/23 MILLER, J R Operating Reactors Branch 3 5pp 20754 327 24X Fiche 50-416, 83/07/23, 8310130343

8310170167 Requests publication of FR notice of consideration of issuance of amend to License NPF-13 & proposed NSHC determination & opportunity for hearing re control room leak test NSHC determination available in Central Files
SCHWENCER, A Licensing Branch 2 83/07/23 MILLER, J R Operating Reactors Branch 3 3pp 20811 360 24X Fiche 50-416, 83/07/23, 8310170167

8310060227 Responds to 830828 request re reasons for length of extended outage Substantial mods to drywell cooling capability indicated during non-nuclear heatup. Mods included extensive design & installation work
MCGAUGHY, J P Mississippi Power & Light Co 83/07/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 20647 094
24X Fiche 50-416, 83/07/30, 8310060227

8310120444 Responds to NRC 830819 concerns over isolation of instrument air sys & response of certain components Isolation of instrument air will not prevent accident mitigation under present design
DALE, L F Mississippi Power & Light Co 83/10/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 20698 254
24X Fiche 50-416, 83/10/04, 8310120444

8310120281 Confirms installation of mechanical pressure gauge on automatic depressurization sys air makeup line & performance of associated surveillance
DALE, L F Mississippi Power & Light Co 83/10/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20693 347, 24X Fiche 50-416, 83/10/07, 8310120281

8310120436 Application to amend License NPF-13, revising changes to proposed Tech Specs to update Table 3 7 4-2 re safety-related mechanical snubbers Change involves NSHC
DALE, L F Mississippi Power & Light Co 83/10/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20698 260
24X Fiche 50-416, 83/10/07, 8310120436

--8310120438 Revised changes to proposed Tech Specs updating Table 3 7 4-2 re safety-related mechanical snubbers
* Mississippi Power & Light Co 83/10/07 15pp 20698 262 24X
Fiche 50-416, 83/10/07, 8310120438

8310130117 Application for amend to License NPF-13, revising Tech Specs to change Action 50 of RCIC sys actuation instrumentation to reflect only one trip sys
MCGAUGHY, J P Mississippi Power & Light Co 83/10/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 20725 053
24X Fiche 50-416, 83/10/11, 8310130117

--8310130121 Proposed Tech Spec Table 3 3 5-1 re RCIC sys actuation instrumentation
* Mississippi Power & Light Co. 83/10/11 2pp 20725 057 24X
Fiche 50-416, 83/10/11, 8310130121

8308310050 Board Notification 83-160, provides info re 830812 failure of main crankshaft on one of three Transamerica Delaval emergency diesel generators at Boreham
EISENHUT, D G Division of Licensing 83/10/14 PALLADINO, N J, GILINSKY, V, ROBERTS, T Commissioners 15pp 20966 312 24X
Fiche 50-000, 83/10/14, 8308310050

8310180306 Forwards responses to informal NRC concerns on containment structural integrity test per 830706 conference w/Bechtel & NRC Test performed in compliance w/provisions of Reg Guide 1.1B, Rev 1
DALE, L F Mississippi Power & Light Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 30pp 20806 295
24X Fiche 50-416, 83/10/14, 8310180306

8310180352 Forwards addl info re fuel assembly liftoff, schedule for implementing mitigating measures for intergranular stress corrosion cracking & dynamic qualification of equipment; per 831004 request, info will be incorporated into FSAR update
DALE, L F Mississippi Power & Light Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 6pp 20803 147
24X Fiche 50-416, 83/10/14, 8310180352

8310190037 Forwards response to 830912 request for info re min number of operable channel requirements for isolation actuation instrumentation. Due to review to provide info, until identified need to modify procedures, Tech Specs & FSAR
DALE, L F Mississippi Power & Light Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 20823 167
24X Fiche 50-416, 83/10/14, 8310190037

DOCKETED ITEMS

8310260276 Forwards info to assist in NRC evaluation of adequacy of hydrogen control sys to support full-power operation info provided includes scaling of convective heat fluxes & addl CLASIX-3 & NARCH analyses.
DALE, L. F. Mississippi Power & Light Co 83/10/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director 162pp 20911 140
24X Fiche 50-416, 83/10/17, 8310260276

8310260220 Provides addl info re qualification of automatic depressurization sys (ADS) accumulator & related air sys, in response to 830811 ltr ADS leak test frequency of 18 months anticipated.
DALE, L. F. Mississippi Power & Light Co 83/10/24 DENTON, H R
Office of Nuclear Reactor Regulation, Director 7pp 20912 113
24X Fiche 50-416, 83/10/24, 8310260220

8310310044 Forwards revised FSAR App 13A, incorporating staff changes involving key personnel info will be incorporated into next FSAR amend.
DALE, L. F. Mississippi Power & Light Co 83/10/26 DENTON, H R
Office of Nuclear Reactor Regulation, Director 32pp 20951 049
24X Fiche 50-416, 83/10/26, 8310310044

Q Inspection reports, IE Bulletins & correspondence

8310250389 Provides supplemental final response to violation noted in IE Insp Rept 50-416/83-12 Bechtel GA evaluated & verified that corrective actions respond to concerns raised All corrective actions completed on 830607
MCQUAGHY, J P. Mississippi Power & Light Co 83/06/15
O'REILLY, J P Region 2, Office of Director 2pp 20898 145 24X
Fiche 50-416, 83/06/15, 8310250389

8310250262 Responds to NRC 830727 ltr re violations noted in IE Insp Rept 50-416/83-30 Corrective actions surveillance testing activity completed on Div 1 load shedding & sequencing panels & M&IE removed
DALE, L. F. Mississippi Power & Light Co 83/08/26 O'REILLY, J P
Region 2, Office of Director 2pp 20898 235 24X
Fiche 50-416, 83/08/26, 8310250262

--8310250268 Forwards IE Insp Rept 50-416/83-30 on 830616-0714 & notice of violation
LEWIS, R C. Division of Project & Resident Programs 83/07/27
RICHARD, J B Mississippi Power & Light Co 2pp 20898 237 24X
Fiche 50-416, 83/08/26, 8310250262

--8310250269 Notice of violation from insp on 830616-0714
Division of Project & Resident Programs 83/07/27 1p
20898 239 24X Fiche 50-416, 83/08/26, 8310250262

--8310250271 IE Insp Rept 50-416/83-30 on 830616-0714 Noncompliance noted failure to perform 10CFR50.59 review.
WAGNER, A G Region 2, Office of Director QUICK, D R. Division of Project & Resident Programs 83/07/26 7pp 20898 240 24X
Fiche 50-416, 83/08/26, 8310250262

8310040163 Forwards IE Insp Rept 50-416/83-37 on 830822-26 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/09/08
RICHARD, J B Mississippi Power & Light Co 2pp 20608 206 24X
Fiche 50-416, 83/09/08, 8310040163

--8310040167 IE Insp Rept 50-416/83-37 on 830822-26 No noncompliance noted Major areas inspected completed preoperational & sys acceptance tests, proposed startup test & local leak rate test procedures
BURNETT, P. T., JAPE, F. Region 2, Office of Director 83/09/06
6pp 20608 208 24X Fiche 50-416, 83/09/08, 8310040163

8310040502 Confirms 830923 mgt meeting at Region II to discuss results of util investigation of Agastat relay failures, proposed corrective action & other topics Proposed meeting agenda encl.
LEWIS, R. C. Division of Project & Resident Programs 83/09/21
RICHARD, J. B. Mississippi Power & Light Co 2pp 20622 360 24X
Fiche 50-416, 83/09/21, 8310040502

8310250439 Forwards IE Insp Rept 50-416/83-39 on 830830-0902 No noncompliance noted
VERRELLI, D. M. Division of Project & Resident Programs 83/09/21
RICHARD, J. B. Mississippi Power & Light Co 2pp 20897 046 24X
Fiche 50-416, 83/09/21, 8310250439

--8310250452 IE Insp Rept 50-416/83-39 on 830830-0902 No noncompliance noted Major areas inspected: diesel generator engine, relays, relay bases, hydraulic control unit, solenoid valves & TMI Item II, D. 3, "Coolant Sys Valve Test Requirements"
JANT, M. D. Region 2, Office of Director CONLON, T. E. Division of Engineering & Operational Programs 83/09/20 3pp 20897 048
24X Fiche 50-416, 83/09/21, 8310250439

8310040263 Concurs in planned schedule for attaining recriticality outlined in util 830829 & 0913 ltrs Items contained in NRC 821020 confirmation of action ltr verified as completed Conditions to satisfy concurrence listed
O'REILLY, J P Region 2, Office of Director 83/09/23 RICHARD, J B
Mississippi Power & Light Co 2pp 20613 003 24X
Fiche 50-416, 83/09/23, 8310040263

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310040528 Confirms 831004 mgt meeting at Region II ofc to discuss util investigation of failure to conduct maint activities & other topics of current interest, per 830926 telcon Proposed meeting agenda encl
O'REILLY, J P Region 2, Office of Director 83/09/28 RICHARD, J B
Mississippi Power & Light Co 2pp 20624 029 24X
Fiche 50-416, 83/09/28, 8310040528

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310250214 Forwards IE Insp Rept 50-416/83-42 on 830912-16 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/10/04
RICHARD, J B Mississippi Power & Light Co 2pp 20893 310 24X
Fiche 50-416, 83/10/04, 8310250214

--8310250216 IE Insp Rept 50-416/83-42 on 830912-16 No noncompliance noted Major areas inspected emergency procedures, operating procedures & surveillance testing
KRUG, H E Region 2, Office of Director JAPE, F. Division of Engineering & Operational Programs 83/09/29 7pp 20893 312
24X Fiche 50-416, 83/10/04, 8310250214

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310170141 Forwards IE Safeguards Insp Rept 50-416/83-40 on 830912-16 No noncompliance noted
VERRELLI, D Division of Project & Resident Programs 83/10/11
RICHARD, J B Mississippi Power & Light Co 2pp 20788 351 24X
Fiche 50-416, 83/10/11, 8310170141

--8310170149 IE Safeguards Insp Rept 50-416/83-40 on 830912-16 No noncompliance noted Major areas inspected, review of security organization-response, security program audit, records & reports Details withheld (ref 10CFR73.21).
LEWIS, J D Region 2, Office of Director MCQUAGHY, D R Division of Emergency Preparedness & Materials Safety 83/10/06 1p
20788 353 24X Fiche 50-416, 83/10/11, 8310170141

DOCKETED ITEMS

309

8310210314 Forwards "Applicability of Shoreham Delaval Diesel/ Generator Crankshaft Failure to Grand Gulf Nuclear Station," in response to IE info Notice 83-98 Rept concludes that failure will not occur at Facility
DALE, L F Mississippi Power & Light Co 83/10/19 DENTON, H R
Office of Nuclear Reactor Regulation, Director 7pp 20851 154
24X Fiche 50-416, 83/10/19, 8310210314

8310310126 Forwards "Rept on Div I, II & III Diesel Generators," in response to NRC request & generic problems identified in IE info Notice 83-31
DALE, L F Mississippi Power & Light Co 83/10/26 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20949 110
24X Fiche 50-416, 83/10/26, 8310310126

--8310310130 "Rept on Div I, II & III Diesel Generators"
STALSBURG, D, HARDESTY, D, TAYLOR, J Mississippi Power & Light Co
83-024 83/10/22 5pp 20949 112 24X Fiche 50-416, 83/10/26,
8310310126

R Periodic operating reports & related correspondence

8310190006 Monthly operating rept for Sept 1983 W/831014 ltr
CESARE, J G, DALE, L F Mississippi Power & Light Co 83/10/15
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 8pp 20823 110 24X Fiche 50-416, 83/10/15, 8310190006

S Reportable occurrences, LERs & related correspondence

8309060068 LER 83-107/03L-0 on 830727, Div I diesel generator
turbocharger mounting bolts found loose, broken & missing
during 24 h test run Caused by cracked welds on intercooler
adapter between intercooler & turbocharger W/830826 ltr
CATHEY, D E, DALE, L F Mississippi Power & Light Co 83/08/26
O'REILLY, J P Region 2, Office of Director 3pp 20862 105 24X
Fiche 50-416, 83/08/26, 8309060068

8309090416 RO 83-072/0 on 830729, 30 & 0814-16, control room air temp
exceeded Tech Spec limit Caused by lack of operating control
room HVAC subsystems & low Freon in subsystem B,
respectively No corrective action stated
DALE, L F Mississippi Power & Light Co 83/08/29 O'REILLY, J P
Region 2, Office of Director 2pp 20314 348 24X
Fiche 50-416, 83/08/29, 8309090416

8310030296 LER 83-123/01T-0 on 830906, inadequate design flow paths
identified from drywell cooler drip pans to leak detection
monitor Caused by inadequate sys design Mods completed,
W/830920 ltr
BYRD, R, DALE, L F Mississippi Power & Light Co 83/09/20
O'REILLY, J P Region 2, Office of Director 4pp 20591 031 24X
Fiche 50-416, 83/09/20, 8310030296

8310030438 Updated LER 83-113/03X-1 on 830729, standby fresh air unit B
to control room intentionally lost w/simulated loss of
power Caused by performance of ECCB loss of power
surveillance test Unit restarted W/830920 ltr
CATHEY, D E, DALE, L F Mississippi Power & Light Co 83/09/20
O'REILLY, J P Region 2, Office of Director 3p 20602 091 24X
Fiche 50-416, 83/09/20, 8310030438

8310030472 Updated RO 83-066/1 on 830709 & 13, triaxial peak recording
accelerograph used for seismic monitoring of auxiliary bldg
foundation & reactor vessel support failed surveillance New
instruments installed
DALE, L F Mississippi Power & Light Co 83/09/20 O'REILLY, J P
Region 2, Office of Director 2pp 20601 059 24X
Fiche 50-416, 83/09/20, 8310030472

8310030490 LER 83-122/01T-0 on 830908, discovered valve P64F461, which
supplies operating pressure to carbon dioxide protection
master selector valve, closed Caused by personnel error
Valve locked open & procedure revised W/830920 ltr
BYRD, R, DALE, L F Mississippi Power & Light Co 83/09/20
O'REILLY, J P Region 2, Office of Director, 3pp 20601 083, 24X
Fiche 50-416, 83/09/20, 8310030490

8310030317 LER 83-127/03L-0 on 830822, during surveillance testing,
control room ventilation radiation monitor channel B
& channel C hi-hi setpoints exceeded allowable values Caused
by instrument drift W/830921 ltr
CATHEY, D E, DALE, L F Mississippi Power & Light Co 83/09/21
O'REILLY, J P Region 2, Office of Director 2pp 20591 001, 24X
Fiche 50-416, 83/09/21, 8310030317

8310030325 RO 83-083/0 on 830817, penetration AP-126C at southwest
corner of auxiliary bldg on Elevation 139 ft, discovered
open Fire watches maintained until penetration restored on
830827
DALE, L F Mississippi Power & Light Co 83/09/21 O'REILLY, J P
Region 2, Office of Director 2pp 20590 352 24X
Fiche 50-416, 83/09/21, 8310030325

8310030373 Final & interim deficiency rept for Units I & 2, respectively
re incorrect operation of Div I & II diesel generator load
shedding & sequencing sys panels w/automatic test feature on
line Initially reported 830921 Also reportable per Part 21
MCQUAGHY, J P Mississippi Power & Light Co 83/09/21
O'REILLY, J P Region 2, Office of Director 4pp 20593 083 24X
Fiche 50-416, 83/09/21, 8310030373

8310030430 RO 83-084/0 on 830819, during performance of fire protection
surveillance procedure, 16 of 20 G-rated fire dampers
discovered, w/"B" shaped hooks connecting fusible links
w/damper instead of required vice-crimped straps
DALE, L F Mississippi Power & Light Co 83/09/21 O'REILLY, J P
Region 2, Office of Director 2pp 20593 174 24X
Fiche 50-416, 83/09/21, 8310030430

8310040502 Confirms 830923 mtg meeting at Region II to discuss results
of util investigation of Agastat relay failures, proposed
corrective action & other topics Proposed meeting agenda
encl
LEWIS, R C Division of Project & Resident Programs 83/09/21,
RICHARD, J B Mississippi Power & Light Co 2pp 20622 360 24X
Fiche 50-416, 83/09/21, 8310040502

8310030374 Second interim deficiency rept re failure of Agastat GP
series relays to change state when called to operate Caused
by svc aging in mild environ in combination w/mechanical
configurations & tolerances of internal parts
MCQUAGHY, J P Mississippi Power & Light Co 83/09/22
O'REILLY, J P Region 2, Office of Director 3pp 20592 190 24X
Fiche 50-416, 83/09/22, 8310030374

8310030461 PNO-II-83-078 on 830925, recriticality achieved after 1-yr
shutdown to modify drywell cooling sys & other areas Low
power physics testing will be conducted during next 3-wk
period
WATSON, J, JULIAN, C A Region 2, Office of Director 83/09/26 1p
20601 048 24X Fiche 50-416, 83/09/26, 8310030461

8310070169 RO 83-085/0 on 830823, latch to Fire Door ID302 of Div I
diesel generator room damaged Fire watches established, per
Tech Spec 3 7 7 until door restored on 830910
DALE, L F Mississippi Power & Light Co 83/09/26 O'REILLY, J P
Region 2, Office of Director 1p 20659 110 24X
Fiche 50-416, 83/09/26, 8310070169

8310070170 LER 83-128/01T-0 on 830912, during routine maint, control bldg
fire rated penetrations CE428B & CE77E found unsealed, Cause
unknown Penetrations revealed, Investigation continuing
W/830926 ltr
BYRD, R, DALE, L F Mississippi Power & Light Co 83/09/26
O'REILLY, J P Region 2, Office of Director, 3pp 20659 111, 24X
Fiche 50-416, 83/09/26, 8310070170

8310070192 LER 83-132/03L-0 on 830827, component cooling water radiation
monitor failed to meet calibr procedure, Caused by out-of-
tolerance count rate meter readings due to faulty diodes &
capacitors in circuit W/830926 ltr
BYRD, R, DALE, L F Mississippi Power & Light Co 83/09/26
O'REILLY, J P Region 2, Office of Director, 2pp 20659 115 24X
Fiche 50-416, 83/09/26, 8310070192

8310070239 LER 83-129/03L-0 on 830827, HPCB diesel generator tripped due
to high jacket water temp Caused by personnel error Standby
svc water valves reopened W/830926 ltr
CATHEY, D E, DALE, L F Mississippi Power & Light Co 83/09/26
O'REILLY, J P Region 2, Office of Director, 3pp 20658 338, 24X
Fiche 50-416, 83/09/26, 8310070239

8310070305 Updated LER 83-084/03X-1 on 830718, Unanticipated activation
of Div II LOCA logic occurred All automatic actions occurred
except for RHR pump C. Caused by malfunctioning inverter for
LOCA signal Inverter replaced W/830926 ltr
BYRD, R, DALE, L F Mississippi Power & Light Co 83/09/26
O'REILLY, J P Region 2, Office of Director 4pp 20651 089, 24X
Fiche 50-416, 83/09/26, 8310070305

8310040364 LER 83-130/03L-0 on 830829, shutdown cooling sys isolated
twice when suction valve received erroneous isolation
signals Caused by personnel error Update rept expected by
831215 W/830928 ltr
BYRD, R, DALE, L F Mississippi Power & Light Co 83/09/28,
O'REILLY, J P Region 2, Office of Director 3pp 20620 277, 24X
Fiche 50-416, 83/09/28, 8310040364

8310040417 LER 83-131/01T-0 on 830913, w/radioactivity monitors
inoperable, Action 110 of Tech Spec 3 3 7 11 not fully met
Caused by personnel error Chemist reinstructed on
requirements W/830928 ltr
BYRD, R, DALE, L F Mississippi Power & Light Co 83/09/28
O'REILLY, J P Region 2, Office of Director, 3pp 20619 172, 24X
Fiche 50-416, 83/09/28, 8310040417

DOCKETED ITEMS

- 8310060001 LER 83-135/03L-0 on 830913, temporary connection from discharge of Div 2 diesel generator starting air storage tank D to Div 1 diesel generator made w/o proper review. Caused by personnel error W/830928 ltr
BYRD, R., DALE, L. F. Mississippi Power & Light Co 83/09/28
O'REILLY, J. P. Region 2, Office of Director App 20648 359 24X
Fiche 50-416, 83/09/28, 8310060001
- 8310060002 Updated LER 83-094/03X-1 on 830711, RHR pump A breaker tripped during first test start after maint to clean rack to breaker auxiliary contacts. Caused by misaligned breaker worm gear rod. Rod realigned W/830928 ltr
BYRD, R., DALE, L. F. Mississippi Power & Light Co 83/09/28
O'REILLY, J. P. Region 2, Office of Director App 20649 277 24X
Fiche 50-416, 83/09/28, 8310060002
- 8310060112 LER 83-134/03L-0 on 830829, output of RPS reactor water level channel 8 loop discovered out of tolerance. Caused by instrument drift. Instrument loop recalibr W/830928 ltr
CATHEY, D. E., DALE, L. F. Mississippi Power & Light Co 83/09/28
O'REILLY, J. P. Region 2, Office of Director App 20648 342 24X
Fiche 50-416, 83/09/28, 8310060112
- 8310060401 LER 83-133/03L-0 on 830829 & 31, diesel generator declared inoperable when air receiver C pressure dropped below Tech Spec psig limit. Caused by setpoint drift & sticking check valve. Relief valve replaced W/830928 ltr
BYRD, R., DALE, L. F. Mississippi Power & Light Co 83/09/28
O'REILLY, J. P. Region 2, Office of Director App 20646 121 24X
Fiche 50-416, 83/09/28, 8310060401
- 8310060025 LER 83-136/03L-0 on 830830, Div 1 diesel generator shutdown when right bank 1 & left bank 5 cylinder exhaust gaskets failed. Crack & two broken welds discovered on intercoolers. Caused by normal deterioration of gaskets W/830929 ltr
CATHEY, D. E., DALE, L. F. Mississippi Power & Light Co 83/09/29
O'REILLY, J. P. Region 2, Office of Director App 20648 356 24X
Fiche 50-416, 83/09/29, 8310060025
- 8310190257 LER 83-138/03L-0 on 830831, Div 1 diesel generator failed to automatically trip following unexpected high bearing temp alarm & was shutdown. Caused by leaky pneumatic temp sensor afg by California Controls Device replaced W/830930 ltr
CATHEY, D. E., DALE, L. F. Mississippi Power & Light Co 83/09/30
O'REILLY, J. P. Region 2, Office of Director App 20818 075 24X
Fiche 50-416, 83/09/30, 8310190257
- 8310120419 LER 83-140/03L-0 on 830902, power to Div 1 ESF bus intentionally removed to perform loss of power test on diesel generator. Diesel generator auto started, but did not regulate bus voltage during load shedding W/831003 ltr
CATHEY, D. E., DALE, L. F. Mississippi Power & Light Co 83/10/03
O'REILLY, J. P. Region 2, Office of Director App 20698 292 24X
Fiche 50-416, 83/10/03, 8310120419
- 8310140061 LER 83-142/03L-0 on 830903, RHR low pressure alarm trip unit A setpoint discovered less than Tech Spec limits. Cause unknown. Instrument recalibr W/831003 ltr
CATHEY, D. E., DALE, L. F. Mississippi Power & Light Co 83/10/03
O'REILLY, J. P. Region 2, Office of Director App 20768 005 24X
Fiche 50-416, 83/10/03, 8310140061
- 8310140122 LER 83-141/01T-0 on 830919, determined containment spray timers could operate less conservatively than Tech Spec limit. Caused by containment spray & core cooling modes functioning w/less conservative limits W/831003 ltr
BYRD, R., DALE, L. F. Mississippi Power & Light Co 83/10/03
O'REILLY, J. P. Region 2, Office of Director App 20763 082 24X
Fiche 50-416, 83/10/03, 8310140122
- 8310170474 LER 83-137/03L-0 on 830901, after shifting reactor protective sys power supply to alternate source for surveillance testing, supply breaker tripped, causing isolation of shutdown cooling, reactor half-scream & control room SFAU W/831003 ltr
BYRD, R., DALE, L. F. Mississippi Power & Light Co 83/10/03
O'REILLY, J. P. Region 2, Office of Director App 20783 284 24X
Fiche 50-416, 83/10/03, 8310170474
- 0170408 RD 83-088/0, on 830904, control room temp exceeded 77 F limit. Upper cabinet area on elevation 189 ft of control room 1dg also exceeded limit. Excessive temps sporadic from 830904-10. Cause under investigation
DALE, L. F. Mississippi Power & Light Co 83/10/04
O'REILLY, J. P. Region 2, Office of Director App 20779 159 24X
Fiche 50-416, 83/10/04, 8310170408
- 140051 Updated LER 83-136/03X-1, on 830830, Div 1 diesel generator shutdown when right bank 1 & left bank 5 cylinder exhaust gaskets failed & cracked. Two broken welds discovered on intercoolers. Caused by loose manifold bolts W/831005 ltr
CATHEY, D. E., DALE, L. F. Mississippi Power & Light Co 83/10/05
O'REILLY, J. P. Region 2, Office of Director App 20768 269 24X
Fiche 50-416, 83/10/05, 8310140051
- 8310140075 Final deficiency rept for Unit 1 & interim deficiency rept for Unit 2 re potential rupture of high pressure fuel injection lines on Div I & II diesel generators during engine operation. Also reportable under Part 21 for Unit 1
MCGAUGHY, J. P. Mississippi Power & Light Co 83/10/05
O'REILLY, J. P. Region 2, Office of Director App 20763 011 24X
Fiche 50-416, 83/10/05, 8310140075
- 8310140160 RD 83-087/0 on 830831, Fire Door 1A204 blocked open to support planned maint activities. Fire watches established per Tech Specs until door restored on 830910
DALE, L. F. Mississippi Power & Light Co 83/10/05
O'REILLY, J. P. Region 2, Office of Director App 20765 070 24X
Fiche 50-416, 83/10/05, 8310140160
- 8310140169 RD 83-086/0 on 830829, listed fire barriers opened to support planned maint activities. Fire watches established & barriers restored
DALE, L. F. Mississippi Power & Light Co 83/10/05
O'REILLY, J. P. Region 2, Office of Director App 20763 071 24X
Fiche 50-416, 83/10/05, 8310140169
- 8310170458 Updated LER 83-089/03X-1 on 830703, discovered carbon dioxide heat detector surveillance test did not exist. Caused by delays w/ongoing surveillance review program. Procedure issued on 830720 & completed on 830912 W/831005 ltr
CATHEY, D. E., DALE, L. F. Mississippi Power & Light Co 83/10/05
O'REILLY, J. P. Region 2, Office of Director App 20763 247 24X
Fiche 50-416, 83/10/05, 8310170458
- 8310170512 Updated LER 83-078/03X-1 on 830701, diesel generator 13 air receiver pressure could not be maintained greater than Tech Spec limit. Caused by relief valve setpoint drift. Valves to be replaced by 831231 W/831005 ltr
BYRD, R., DALE, L. F. Mississippi Power & Light Co 83/10/05
O'REILLY, J. P. Region 2, Office of Director App 20763 236 24X
Fiche 50-416, 83/10/05, 8310170512
- 8310170400 Final Deficiency Rept PRD-83/15 re defective Sprague Type 40B capacitor on Brown Boveri Electric low voltage circuit breakers equipped w/solid state trip devices. Initially reported on 831002. Also reportable per Part 21
MCGAUGHY, J. P. Mississippi Power & Light Co 83/10/10
O'REILLY, J. P. Region 2, Office of Director App 20763 080 24X
Fiche 50-416, 83/10/10, 8310170400
- 8310190109 LER 83-144/03L-0 on 830911, loop A of RHR sys placed in shutdown cooling mode while standby svc water loop A radiation monitor inoperable. Cause under investigation. Radiation monitor reworked & returned to svc W/831011 ltr
BYRD, R., DALE, L. F. Mississippi Power & Light Co 83/10/11
O'REILLY, J. P. Region 2, Office of Director App 20822 105 24X
Fiche 50-416, 83/10/11, 8310190109
- 8310210019 LER 83-143/01T-0 on 830928, component cooling water process radiation monitor sample pump found not operating properly. Cause of pump being secured not yet identified. Pump restarted. Pumps added to daily surveillance W/831011 ltr
BYRD, R., DALE, L. F. Mississippi Power & Light Co 83/10/11
O'REILLY, J. P. Region 2, Office of Director App 20835 313 24X
Fiche 50-416, 83/10/11, 8310210019
- 8310270397 Updated LER 83-080/03X-1 on 830626, due to problems w/11VAL system in control room exceeded required limit several times. Caused by malfunctioning condenser cooling water flow control valve limit switch adjusted W/831011 ltr
BYRD, R., DALE, L. F. Mississippi Power & Light Co 83/10/11
O'REILLY, J. P. Region 2, Office of Director App 20924 025 24X
Fiche 50-416, 83/10/11, 8310270397
- 8310190098 Updated LER 83-092/03X-1 on 830709, discovered inappropriate maint retest performed on 830708 for both control room chlorine detectors. Sys released for work at same time on 830707. Caused by personnel error W/831012 ltr
CATHEY, D. E., DALE, L. F. Mississippi Power & Light Co 83/10/12
O'REILLY, J. P. Region 2, Office of Director App 20822 113 24X
Fiche 50-416, 83/10/12, 8310190098
- 8310190111 Updated LER 83-095/03X-1 on 830713, during Div 1 standby diesel generator functional test, diesel generator tripped on high jacket water temp. Caused by temp switch out of calibr due to loose set screw. Switch adjusted W/831012 ltr
BYRD, R., DALE, L. F. Mississippi Power & Light Co 83/10/12
O'REILLY, J. P. Region 2, Office of Director App 20821 101 24X
Fiche 50-416, 83/10/12, 8310190111
- 8310190234 Updated LER 83-136/03X-2 on 830830, during 24 h surveillance test run, Div 1 diesel generator shutdown when right bank 1 & left bank 5 cylinder exhaust gaskets failed & crack & two broken welds discovered on intercoolers. Caused by loose manifold bolts W/831012 ltr
CATHEY, D. E., DALE, L. F. Mississippi Power & Light Co 83/10/12
O'REILLY, J. P. Region 2, Office of Director App 20818 056 24X
Fiche 50-416, 83/10/12, 8310190234

DOCKETED ITEMS

311

E310190232 RD 83-098/0 on 830915, fire-rated Door 1A203 blocked open to support planned maint activities Fire watches established per Tech Spec 3 7 7 until 831006
DALE, L F Mississippi Power & Light Co 83/10/13 O'REILLY, J P
Region 3, Office of Director 1p 20818 055 24X
Fiche 50-416, 83/10/13, 8310190232

E310240247 Forwards request for addl info re inoperable Agostat relays identified during recent surveillance testing
SCHRENCER, A Licensing Branch 2 83/10/13 MCOAUGHY, J P
Mississippi Power & Light Co 4pp 20907 399 24X
Fiche 50-416, 83/10/13, 8310240247

E310270167 RD 83-093/0 on 830914 & 15, control room upper cable spreading room ambient air temp exceeded area temp limit of 77 F in Tech Spec 3 7 8-1 c during 36 h period Max qualification temp not exceeded
DALE, L F Mississippi Power & Light Co 83/10/14 O'REILLY, J P
Region 2, Office of Director 2pp 20924 171 24X
Fiche 50-416, 83/10/14, 8310270167

E310270229 RD 83-090/0 on 830910, during surveillance testing, fire Doors 1A320 & DC211 found inoperable & Fire Door 1A320 in auxiliary bldg could not be locked Locking mechanism & hinges replaced Hourly fire watch established for duration
DALE, L F Mississippi Power & Light Co 83/10/14 O'REILLY, J P
Region 2, Office of Director 2pp 20924 068 24X
Fiche 50-416, 83/10/14, 8310270229

E310270037 RD 83-09210 on 830910, listed control room fire-rated penetrations opened to implement design change package Fire watch established Penetrations revealed on 831007
DALE, L F Mississippi Power & Light Co 83/10/17 O'REILLY, J P
Region 2, Office of Director 2pp 20924 336 24X
Fiche 50-416, 83/10/17, 8310270037

E310270160 RD 83-091/0 on 830910, during surveillance testing, Fire Door DC713 on elevation 189 ft in control bldg found w/o lock
Fire Door DC713 not designed to lock Door deleted from Procedure 06-0P-EP64-W-0049, Rev 20 Fire watch established
DALE, L F Mississippi Power & Light Co 83/10/17 O'REILLY, J P
Region 2, Office of Director 2pp 20924 192 24X
Fiche 50-416, 83/10/17, 8310270160

E310270336 LER 83-145/03L-0 on 830915, Div II diesel generator starting air pressure dropped below 160 psig Windings in electric motor overheated & shorted Caused by incorrect pressure signal tag location Motor replaced W/831017 ltr
CATHRYN, D E DALE, L F Mississippi Power & Light Co 83/10/17 O'REILLY, J P
Region 2, Office of Director 2pp 20923 143 24X
Fiche 50-416, 83/10/17, 8310270336

E310270433 Final Deficiency Rept PRD-83/12 for Unit 1 & interim rept for Unit 2 re failure of Agostat OP series relays to switch Initially reported on 830902 Deficiency reportable per Part 21 for Unit 1 Investigation ongoing for Unit 2
MCOAUGHY, J P Mississippi Power & Light Co 83/10/17 O'REILLY, J P
Region 2, Office of Director 3pp 20923 044 24X
Fiche 50-416, 83/10/17, 8310270433

E310210182 LER 83-139/03L-0 on 830912, Div I reactor protective sys motor generator set tripped, causing half scram signal & loss of shutdown cooling Caused by motor winding short Motor replaced W/831011 ltr
BYRD, R. DALE, L F Mississippi Power & Light Co 83/10/18 O'REILLY, J P
Region 2, Office of Director 2pp 20856 122 24X
Fiche 50-416, 83/10/18, 8310210182

E310270233 LER 83-146/03L-0 on 830918, alarms failed to annunciate following shutdown cooling loop pump B trip due to isolated suction valve Caused by open circuit breaker Investigation continuing Updated rept expected by 831130 W/831018 ltr
BYRD, R. DALE, L F Mississippi Power & Light Co 83/10/18 O'REILLY, J P
Region 2, Office of Director 2pp 20924 045 24X
Fiche 50-416, 83/10/18, 8310270233

E310260186 Part 21 rept re potentially defective Presray airlock seal in drywell personnel airlock supplied by WJ Woolley Initially reported by vendor on 830919 New seal being designed by Presray Corp will be installed when available
DALE, L F Mississippi Power & Light Co 83/10/24 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 20915 250 24X
Fiche 50-416, 83/10/24, 8310260186

Operator Examinations

E310040494 Discusses operator & senior operator requalification exams on 830729, 0816 & 17 Summary of exam results encl W/o encl
VERRELLI, D M Division of Project & Resident Programs 83/08/29, RICHARD, J B Mississippi Power & Light Co 2pp 20625 160 24X
Fiche 50-416, 83/08/29, 8310040494

DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

E310040046 Forwards request for addl info re 830610 0A program update
LEWIS, R C Division of Project & Resident Programs 83/09/23 RICHARD, J B Mississippi Power & Light Co 3pp 20608 138 24X
Fiche 50-416, 83/09/23, 8310040046

E310120444 Response to NRC 830819 concerns over isolation of instrument air sys & response of certain components Isolation of instrument air will not prevent accident mitigation under present design
DALE, L F Mississippi Power & Light Co 83/10/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 20698 254 24X
Fiche 50-416, 83/10/04, 8310120444

E308310050 Board Notification 83-140 provides info re 830812 failure of main crankshaft on one of three Transamerica Delaval emergency diesel generators at Shoreham
EIBENHUT, D G Division of Licensing 83/10/14 PALLADINO, N J, GILINSKY, V., ROBERTS, T Commissioners 15pp 20766 312 24X
Fiche 50-000, 83/10/14, 8308310050

E310180352 Forwards addl info re fuel assembly liftoff, schedule for implementing mitigating measures for intergranular stress corrosion cracking & dynamic qualification of equipment, per 831004 request Info will be incorporated into FSAR update
DALE, L F Mississippi Power & Light Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 6pp 20803 147 24X
Fiche 50-416, 83/10/14, 8310180352

E310260220 Provides addl info re qualification of automatic depressurization sys (ADS) accumulator & related air sys, in response to 830811 ltr ADS leak test frequency of 18 months anticipated
DALE, L F Mississippi Power & Light Co 83/10/24 DENTON, H R
Office of Nuclear Reactor Regulation, Director 7pp 20912 113 24X
Fiche 50-416, 83/10/24, 8310260220

E310310044 Forwards revised FSAR App 13A, incorporating staff changes involving key personnel Info will be incorporated into next FSAR amend
DALE, L F Mississippi Power & Light Co 83/10/26 DENTON, H R
Office of Nuclear Reactor Regulation, Director 32pp 20951 049 24X
Fiche 50-416, 83/10/26, 8310310044

E NRC Safety Evaluation Report (SER), suppls & correspondence

E310180330 Provides addl info on SER Confirmatory Item 1 10(4) re soil structure interaction, in fulfillment of commitments made in response to NRC 830112 ltr Util committed to utilizing elastic half-space methodology
DALE, L F Mississippi Power & Light Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 20802 348 24X
Fiche 50-416, 83/10/14, 8310180330

F Security, medical, emergency & fire protection plans

E310040394 Forwards summary of 830909 meeting in Region II o/c re proposed physical security plan mods
LEWIS, R C Division of Project & Resident Programs 83/09/26 RICHARD, J B Mississippi Power & Light Co 3pp 20619 041 24X
Fiche 50-416, 83/09/26, 8310040394

E310180430 Forwards Rev 9 to physical security plan, Rev withheld (ref 10CFR2.790 & 10CFR9.5)
DALE, L F Mississippi Power & Light Co 83/09/30 O'REILLY, J P
Region 2, Office of Director 2pp 20803 297 24X
Fiche 50-416, 83/09/30, 8310180430

E310120349 Advises that due to uncertainty in instrumentation availability & manpower resources, instrumentation necessary to meet Reg Guide 1.97 requirements will be implemented by third refueling outage per Suppl 1 to NUREG-0737
DALE, L F Mississippi Power & Light Co 83/10/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20700 231 24X
Fiche 50-416, 83/10/10, 8310120349

G Inspection reports, IE Bulletins & correspondence

E308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 117pp 20734 022 24X
Fiche 50-000, 83/09/26, 8308300340

DOCKETED ITEMS

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 9A-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20862 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310210314 Forwards "Applicability of Shoreham Delaval Diesel/Generator Crankshaft Failure to Grand Gulf Nuclear Station," in response to IE Info Notice 83-58 Rept concludes that failure will not occur at facility
DALE, L F Mississippi Power & Light Co 83/10/19, DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 20851 154 24X Fiche 50-416, 83/10/19, 8310210314

B Reportable occurrences, LERs & related correspondence

8310030373 Final & interim deficiency rept for Units 1 & 2, respectively re incorrect operation of Div 1 & II diesel generator load shedding & sequencing sys panels w/automatic test feature on line Initially reported 830921. Also reportable per Part 21
MCBAUGH, J P Mississippi Power & Light Co 83/09/21
O'REILLY, J P Region 2, Office of Director 4pp 20593 083 24X Fiche 50-416, 83/09/21, 8310030373

8310140075 Final deficiency rept for Unit 1 & interim deficiency rept for Unit 2 re potential rupture of high pressure fuel injection lines on Div 1 & II diesel generators during engine operation Also reportable under Part 21 for Unit 1
MCBAUGH, J P Mississippi Power & Light Co 83/10/05
O'REILLY, J P Region 2, Office of Director 5pp 20768 018 24X Fiche 50-416, 83/10/05, 8310140075

8310140007 Supplemental Interim Deficiency Rept PRD-81/29, Rept 2 re Temp Flex penetration bellows assemblies exhibiting cracked & broken welds between shroud support spokes & bellows and sleeves Initially reported on 810529 Final rept by 840815
MCBAUGH, J P Mississippi Power & Light Co 83/10/07
O'REILLY, J P Region 2, Office of Director 4pp 20768:056 24X Fiche 50-417, 83/10/07, 8310140007

8310270433 Final Deficiency Rept PRD-83/12 for Unit 1 & interim rept for Unit 2 re failure of Agastat OP series relays to switch. Initially reported on 830902, Deficiency reportable per Part 21 for Unit 1 Investigation ongoing for Unit 2
MCBAUGH, J P Mississippi Power & Light Co 83/10/17
O'REILLY, J P Region 2, Office of Director 5pp 20723.044 24X Fiche 50-416, 83/10/17, 8310270433

8310260186 Part 21 rept re potentially defective Presray airlock seal in drywell personnel airlock supplied by WJ Woolley Initially reported by vendor on 830919 New seal being designed by Presray Corp will be installed when available
DALE, L F Mississippi Power & Light Co 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20915 250 24X Fiche 50-416, 83/10/24, 8310260186

V Operator Examinations

8310040494 Discusses operator & senior operator requalification exam on 830729, 0816 & 17 Summary of exam results encl W/o encl
VERRELLI, U M Division of Project & Resident Programs 83/08/29
RICHARD, J B Mississippi Power & Light Co 2pp 20625 160 24X Fiche 50-416, 83/08/29, 8310040494

DOCKET 50-423 MILL STONE NUCLEAR POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

8310030335 Forwards remaining responses & corresponding FSAR changes to 640 series questions not forwarded by util 830829 ltr Responses will be formally submitted along w/Amend 5 by 831101
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/09/27
YOUNGBLOOD, B J Licensing Branch 1 84pp 20590 219 24X Fiche 50-423, 83/09/27, 8310030335

8310050453 Notification of 831011 & 12 meetings in Waterford, CT to support NRC review of probabilistic safety study & to conduct site tour
DOLITTLE, E L Licensing Branch 1 83/09/28 YOUNGBLOOD, B J Licensing Branch 1 3pp 20650 034 24X Fiche 50-423, 83/09/28, 8310050453

8310170069 Authorizes use of ASME Code Case N-310-1 in const of component support bolting under Section III, Div 1, Class 1 of code
YOUNGBLOOD, B J Licensing Branch 1 83/09/30 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 20798 022 24X Fiche 50-423, 83/09/30, 8310170069

8310170190 Forwards Rev F to QA program manual Historical document containing all changes to QA manual since first edition issued in Aug 1973 encl
COUNSIL, W G Northeast Utilities Service Co COUNSIL, W G Northeast Utilities 83/09/30 MURLEY, T E Region 1, Office of Director 2pp 20787 116 24X Fiche 50-423, 83/09/30, 8310170190

--8310170198 Rev F to QA program manual
KELLY, R B, ALLEN, W F, SMITH, L B Stone & Webster Engineering Corp 81/04/06 589pp 20787 118 24X Fiche 50-423, 83/09/30, 8310170190

8310170193 Forwards request for addl info re application for DL resulting from review of FSAR & design basis response to Reg Guide 1.97, Rev 2 Response to Questions 230.6 & 420.6 required within 30 days of receipt of ltr
YOUNGBLOOD, B J Licensing Branch 1 83/10/03 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 8pp 20813 004 24X Fiche 50-423, 83/10/03, 8310170193

8310170726 Forwards request for addl info required to complete evaluation of environ & safety portions of application for DL Response requested within 30 days
YOUNGBLOOD, B J Licensing Branch 1 83/10/07 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 10pp 20798 044 24X Fiche 50-423, 83/10/07, 8310170726

8310170563 Deters responses to three acceptance review questions & Encl 4, Item 7 as committed to in 830331 & 0630 ltrs Rev to responses to Questions 311.1, 311.4 & 220.6 will be forwarded w/Amend 5 to FSAR in Nov 1983
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/10/11
YOUNGBLOOD, B J Division of Licensing 1p 20780 227 24X Fiche 50-423, 83/10/11, 8310170563

8310240044 Summary of 830602 meeting w/util, S&W & Westinghouse in Bethesda, MD to discuss objectives of Instrumentation & Control Sys Branch review process for DL application
DOLITTLE, E L Licensing Branch 1 83/10/11 Licensing Branch 1 4pp 20903 234 24X Fiche 50-423, 83/10/11, 8310240044

8310310170 Notifies that NRC will conduct site visit on 831025-27 to obtain info re const status Agenda encl
YOUNGBLOOD, B J Licensing Branch 1 83/10/18 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 20965 304 24X Fiche 50-423, 83/10/18, 8310310170

DOCKETED ITEMS

313

8310280112 Denies 830906 request for 120-day extension to respond to Generic Ltr 83-28 re generic implications of Salem ATWS events NRC review schedule does not permit extension
Response due by 831105
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/26 COUNCIL, W O
Connecticut Yankee Atomic Power Co 2pp 20929 261 24X
Fiche 50-000, 83/10/26, 8310280112

C Utility Environmental Report (ER), amends & correspondence

8310040521 Forwards Amend 4 to environ rept - OL stage
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/09/27
YOUNGBLOOD, D J Licensing Branch 1 2pp 20621 229 24X
Fiche 50-423, 83/09/27, 8310040521

--8310040521 Amend 4 to environ rept - OL stage
Northeast Utilities Service Co 83/09/23 79pp 20621 231
24X Fiche 50-423, 83/09/27, 8310040521

E NRC Safety Evaluation Report (SER), supplis & correspondence

8310110602 Requests technical editing assistance in preparing draft SER Draft SER inputs from technical review branches scheduled for submittal by 831101 w/draft SER to be issued on 831201
YOUNGBLOOD, D J Licensing Branch 1 83/09/29 BINGHAM, M H Policy & Publications Management Branch 1p 20714 348 24X
Fiche: 50-423, 83/09/29, 8310110602

K Utility Final Safety Analysis Report (FSAR) & amends

8310040161 Forwards Amend 4 to FSAR, consisting of responses to selected requests for addl info
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/09/30
YOUNGBLOOD, D J Licensing Branch 1 2pp 20619 284 24X
Fiche 50-423, 83/09/30, 8310040161

--8310040161 Amend 4 to FSAR
Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/09/30 437pp 20619 286 24X Fiche 50-423, 83/09/30, 8310040161

3 Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 118pp 20716 024 24X Fiche 50-000, 83/09/29, 8308300349

8310190182 Forwards IE Insp Rept 50-423/83-10 on 830613-0731 No noncompliance noted.
STAROSTECKI, R Division of Project & Resident Programs 83/10/03
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 20820 211 24X Fiche 50-423, 83/10/03, 8310190182

--8310190182 IE Insp Rept 50-423/83-10 on 830613-0731 No noncompliance noted Major areas inspected EBF as-built comparison, severance of control cables, battery discharge & containment liner stud spacing requirements
REBELOWSKI, T, FORD, E J Region 1, Office of Director ELIASSEN, T Division of Project & Resident Programs 83/09/29, 7pp 20820 213, 24X Fiche 50-423, 83/10/03, 8310190182

8310180077 Forwards draft NRR BALP input for Sept 1982 - Aug 1983 Comments received by 831006 will be considered in final rept Category 2 assigned in area of licensing activities
DOOLITTLE, E L Licensing Branch 1 83/10/04 EISENHUT, D G, Division of Licensing MATTHEW, R J Division of Systems Integration (Post 831005) VOLLMER, R H Division of Engineering App 20827 036 24X Fiche 50-423, 83/10/04, 8310180077

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043:075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827:129 24X Fiche 50-000, 83/10/11, 8308300761

S Reportable occurrences, LERs & related correspondence

8310070163 Part 21 rept re potential defects in molded case of 100-amp frame, multi-pole E & HE series circuit breakers.
Initially reported on 830902
ERHARDT, J V Coupl, Inc 83/09/26 MURLEY, T E Region 1, Office of Director 10pp 20659 095 24X Fiche 50-000, 83/09/26, 8310070163

8310070301 Potential Part 21 rept re underrange characteristic of Model N-E110M transmitter. Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
DERBERIAN, M J Foyboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X Fiche 50-000, 83/09/30, 8310070301

DOCKET 50-424 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8310110374 Clarifies question contained in 830906 ltr which indicated FSAR sections referenced in FSAR Table 1 8-1 did not provide adequate evaluation of differences w/BRP. Format containing specific subsection devoted to GRP differences preferred.
NOVAK, T M Assistant Director for Licensing, 83/09/26, FOSTER, D O, Georgia Power Co. 3pp 20713 222 24X Fiche 50-424, 83/09/26, 8310110374

8310180604 Forwards notice of receipt of 830913 OL application for CPPR-10B & CPPR-109 Notice sent for publication in FR
ADENBAM, E G Licensing Branch 4 83/10/11, FOSTER, D Georgia Power Co. 2pp 20817:347 24X Fiche 50-424, 83/10/11, 8310180604

--8310180604 Notice of receipt of 830913 OL application for CPPR-10B & CPPR-109, authorizing applicants to possess, use & operate two PWRs onsite at 3.411 MWT reactor core power
ADENBAM, E G Licensing Branch 4 83/10/06 3pp, 20817:349 24X Fiche 50-424, 83/10/11, 8310180604

8308300775 Board Notification 83-135A forwards 830919 revised draft of "QA Case Study Working Paper - Case C," & cover & transmittal memos re Diablo Canyon.
EISENHUT, D G Division of Licensing 83/10/14 PALLADINO, N J, OLINSKY, V, ROBERTS, T Commissioners. 3pp, 20799:001 24X Fiche 50-000, 83/10/14, 8308300775

--8310180505 Informs that working papers for three QA case studies complete, per 830923 memo. Case C re Diablo Canyon; dtd 830919, is rev to 830719 draft transmitted in Board Notification 83-135 on 830902. Papers & transmittal ltrs forwarded.
TAYLOR, J M QA Branch, 83/09/26, EISENHUT, D G Division of Licensing, 2pp 20799:004 24X Fiche 50-000, 83/10/14, 8308300775

DOCKETED ITEMS

8310190125 Forwards application for amend to CPPR-108 & CPPR-109, authorizing sale of addl 5% undivided interest to Municipal Electric Authority of Georgia
FOSTER, D O Georgia Power Co 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20821 124 24X
Fiche 50-424, 83/10/14, 8310190125

--8310190126 Application for amend to CPPR-108 & CPPR-109, authorizing sale of addl 5% undivided interest to Municipal Electric Authority of Georgia
FOSTER, D O Georgia Power Co 83/10/14 3pp 20821 125 24X
Fiche 50-424, 83/10/14, 8310190125

M Antitrust correspondence

8310210106 Forwards FR notice of receipt of antitrust info associated w/application for OLS
ADENBAM, E O Licensing Branch 4 83/10/13 FOSTER, D Georgia Power Co 2pp 20883 323 24X Fiche 50-424, 83/10/13, 8310210106

--8310210109 Notice of receipt of antitrust info associated w/application for OLS
ADENBAM, E O, Licensing Branch 4 83/10/07 2pp 20883 325 24X
Fiche 50-424, 83/10/13, 8310210106

Q Inspection reports, IE Bulletins & correspondence

8310040215 Forwards IE Insp Repts 50-424/83-17 & 50-425/83-17 on 830711-0815 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/01.
KELLY, R J Georgia Power Co 2pp 20614 266 24X
Fiche: 50-424, 83/09/01, 8310040215

--8310040222 IE Insp Repts 50-424/83-17 & 50-425/83-17 on 830711-0815 No noncompliance noted. Major areas inspected observation of work in progress re fitting & welding NSSB primary coolant piping & storage of critical equipment
SANDERB, W F Region 2, Office of Director PANCIERA, V Division of Project & Resident Programs, 83/09/01 3pp 20614 269, 24X
Fiche 50-424, 83/09/01, 8310040215

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26, Consolidated Edison Co of New York, Inc. 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp, 20777:210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 118pp 20778:001 24X Fiche 50-000, 83/09/26, 8308300345

8310040588 Forwards summary of 830822 mgt meeting at util headquarters of re findings concerning investigation of subcontractor QA performance at plant list of attendees also encl
O'REILLY, J P, Region 2, Office of Director, 83/09/28 KELLY, R J, Georgia Power Co, 4pp 20626 236, 24X Fiche 50-424, 83/09/28, 8310040588

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29, Consolidated Edison Co of New York, Inc. 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 76pp, 20827:213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/10/07, Consolidated Edison Co of New York, Inc. 79pp 20882, 026, 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/10/11, Consolidated Edison Co of New York, Inc. 117pp, 21043, 073, 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

S Reportable occurrences, LERs & related correspondence

8310120296 Interim deficiency rept re Brown Boveri reactor coolant pump switchgear reported in QN-247 Resolution rescheduled from 830923 to 1014 due to delay in engineering evaluation
FOSTER, D O Georgia Power Co 83/09/28 O'REILLY, J P Region 2, Office of Director 1p 20692 338 24X Fiche 50-424, 83/09/28, 8310120296

8310170566 Deficiency & Part 21 repts re GE SFF-30 relays Evaluation concluded deficiency & substantial safety hazards do not exist
FOSTER, D O Georgia Power Co 83/10/06 O'REILLY, J P Region 2, Office of Director 1p 20780 189 24X Fiche 50-424, 83/10/06, 8310170566

8310270315 Interim deficiency rept re defective weld wire Engineering evaluation will be completed & conclusions re reportability will be submitted by 831028
FOSTER, D O Georgia Power Co 83/10/17 O'REILLY, J P Director's Office, Office of Inspection and Enforcement 1p 20923 189 24X Fiche: 50-424, 83/10/17, 8310270315

U Congressional/Executive Correspondence

8310200442 Responds to 830922 ltr re NRC handling of several working papers for case studies being conducted to support NRC rept to Congress per Section 13 of NRC Authorization Act Three working papers encl
PALLADINO, N J Commissioners 83/10/07 FORD, W H Senate 3pp 20871 295 24X Fiche 50-000, 83/10/07, 8310200442

--8310200455 Expresses appreciation for cooperation w/IC activities to comply w/Congressional directive to NRC to perform QA studies Draft working paper for study encl
TAYLOR, J M Division of QA, Safeguards & Inspection Programs (Post 830103) 83/08/02 KELLY, R J Georgia Power Co 1p 20871 307 24X Fiche 50-000, 83/10/07, 8310200442

DOCKET 50-425 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8310110374 Clarifies question contained in 830906 ltr which indicated FSAR sections referenced in FSAR Table 1 8-1 did not provide adequate evaluation of differences w/GHP Format containing specific subsection devoted to SRP differences preferred
NOVAK, T M Assistant Director for Licensing 83/09/28 FOSTER, D O Georgia Power Co 3pp 20713 222 24X Fiche 50-424, 83/09/28, 8310110374

8310180604 Forwards notice of receipt of 830913 OL application for CPPR-108 & CPPR-109 Notice sent for publication in FR
ADENBAM, E O Licensing Branch 4 83/10/11 FOSTER, D Georgia Power Co 2pp 20817 347 24X Fiche 50-424, 83/10/11, 8310180604

--8310180606 Notice of receipt of 830913 OL application for CPPR-108 & CPPR-109, authorizing applicants to possess, use & operate two PHRs onsite at 3,411 MWt reactor core power
ADENBAM, E O, Licensing Branch 4 83/10/06 3pp 20817 349 24X Fiche 50-424, 83/10/11, 8310180604

8308300775 Board Notification 83-135A forwards 830919 revised draft of "QA Case Study Working Paper - Case C," & cover & transmittal memos re Diablo Canyon
EISENHUT, D O Division of Licensing 83/10/14 PALLADINO, N J Commissioners 3pp 20799 001 24X Fiche 50-000, 83/10/14, 8308300775

--8310180505 Informs that working papers for three QA case studies complete per 830923 memo Case C re Diablo Canyon, dtd 830919, is rev to 830719 draft transmitted in Board Notification 83-135 on 830902 Papers & transmittal ltrs forwarded
TAYLOR, J M QA Branch 83/09/28 EISENHUT, D O Division of Licensing 2pp 20799 004 24X Fiche 50-000, 83/10/14, 8308300775

8310190125 Forwards application for amend to CPPR-108 & CPPR-109, authorizing sale of addl 5% undivided interest to Municipal Electric Authority of Georgia
FOSTER, D O Georgia Power Co 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20821 124 24X Fiche 50-424, 83/10/14, 8310190125

DOCKETED ITEMS

315

--8310190126 Application for amend to CPPR-108 & CPPR-109, authorizing sale of addl 5% undivided interest to Municipal Electric Authority of Georgia
FOSTER, D O Georgia Power Co 83/10/14 3pp 20821 125 24X
Fiche 50-424, 83/10/14, 8310190125

M Antitrust correspondence

8310210106 Forwards FR notice of receipt of antitrust info associated w/application for DLs
ADENSAH, E O Licensing Branch 4 83/10/13 FOSTER, D Georgia Power Co 2pp 20883 323 24X Fiche 50-424, 83/10/13, 8310210106

--8310210107 Notice of receipt of antitrust info associated w/application for DLs
ADENSAH, E O Licensing Branch 4 83/10/07 2pp 20883 325 24X
Fiche 50-424, 83/10/13, 8310210106

Q Inspection reports, IE Bulletins & correspondence

8310040215 Forwards IE Insp Repts 50-424/83-17 & 50-425/83-17 on 830711-0815 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/01 KELLY, R J Georgia Power Co 2pp 20614 266 24X
Fiche 50-424, 83/09/01, 8310040215

--8310040222 IE Insp Repts 50-424/83-17 & 50-425/83-17 on 830711-0815 No noncompliance noted Major areas inspected observation of work in progress re fitting & welding NSSS primary coolant piping & storage of critical equipment
SANDERS, W F Region 2, Office of Director PANCIERA, V Division of Project & Resident Programs 83/09/01, 5pp 20614 268 24X
Fiche 50-424, 83/09/01, 8310040215

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310040588 Forwards summary of 830822 mgt meeting at util headquarters of re findings concerning investigation of subcontractor QA performance at plant List of attendees also encl
O'REILLY, J P Region 2, Office of Director 83/09/28 KELLY, R J Georgia Power Co 4pp 20626, 236 24X Fiche 50-424, 83/09/28, 8310040588

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716, 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213, 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 77pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning, Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

S Reportable occurrences, LERs & related correspondence

8310120296 Interim deficiency rept re Brown Boveri reactor coolant pump switchgear reported in GN-247 Resolution rescheduled from 830923 to 1014 due to delay in engineering evaluation
FOSTER, D O Georgia Power Co 83/09/28 O'REILLY, J P Region 2, Office of Director 1p 20692 338, 24X Fiche 50-424, 83/09/28, 8310120296

8310170566 Deficiency & Part 21 repts re OE BFF-30 relays. Evaluation concluded deficiency & substantial safety hazards do not exist
FOSTER, D O Georgia Power Co 83/10/06 O'REILLY, J P Region 2, Office of Director 1p 20780 189 24X Fiche 50-424, 83/10/06, 8310170566

8310270315 Interim deficiency rept re defective weld wire Engineering evaluation will be completed & conclusions re reportability will be submitted by 831028
FOSTER, D O Georgia Power Co 83/10/17 O'REILLY, J P Director's Office, Office of Inspection and Enforcement 1p 20923 189, 24X Fiche 50-424, 83/10/17, 8310270315

U Congressional/Executive Correspondence

8310200442 Responds to 830922 ltr re NRC handling of several working papers for case studies being conducted to support NRC rept to Congress per Section 13 of NRC Authorization Act Three working papers encl
PALLADINO, N J Commissioners 83/10/07 FORD, W H Senate, 3pp, 20871 295 24X Fiche 50-000, 83/10/07, 8310200442

--8310200455 Expresses appreciation for cooperation w/IE activities to comply w/Congressional directive to NRC to perform QA studies Draft working paper for study encl
TAYLOR, J M Division of QA, Safeguards & Inspection Programs (Post 830103) 83/08/02 KELLY, R J Georgia Power Co 1p 20871 307, 24X Fiche 50-000, 83/10/07, 8310200442

DOCKET 50-433 UC-SANTA BARBARA RESEARCH REACTOR

A Application/construction stage documents & correspondence

8308300357 Board Notification B2-105A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway
EISENHUT, D O Division of Licensing 83/09/29 PALLADINO, N J Commissioners 3pp 20632 001 24X Fiche 50-000, 83/09/29, 8308300357

DOCKET 50-434 SURRY POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

8308300357 Board Notification B2-105A forwards evaluation of allegations re design deficiencies in Class I piping sys. Info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway
EISENHUT, D O Division of Licensing 83/09/29 PALLADINO, N J Commissioners 3pp 20632 001 24X Fiche 50-000, 83/09/29, 8308300357

DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8310210178 Advises that scheduled fuel load date remains May 1985 for Unit 1 per NRC 810803 request. Any changes will be reported in next quarterly update
MILLS, L M Tennessee Valley Authority 83/10/17 EISENHUT, D O Division of Licensing 1p, 20856 124 24X Fiche 50-438, 83/10/17, 8310210178

8310310443 Requests info to determine if operation of plant may affect cultural resources listed or eligible for listing in Natl Register of Historic Places
ADENSAH, E O Licensing Branch 4 83/10/18 OAKS, L Alabama, State of, 1p 20965 169 24X Fiche 50-438, 83/10/18, 8310310443

8310310489 Summary of 830826 meeting w/B&W Owners Group re implementation of Generic Ltr 83-28 concerning defenses against ATWS & proposed ATWS rule for B&W plants. List of attendees & viewpoints encl
KADAMBI, P Operating Reactors Branch 4 83/10/20, Operating Reactors Branch 4 13pp 20965 147, 24X Fiche 50-000, 83/10/20, 8310310489

DOCKETED ITEMS

F Security, medical, emergency & fire protection plans

8310250301 Ack receipt of 830518 & 0928 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-08 & 50-439/83-08 Records revised to delete Item B of violation re maint of cleanliness control
VERRELLI, D M Division of Project & Resident Programs 83/10/19
PARRIS, H Q Tennessee Valley Authority 2pp 20897 301 24X
Fiche 50-438, 83/10/19, 8310250301

--8310250306 Forwards revised response to NRC 830414 ltr re violations noted in IE Insp Repts 50-438/83-08 & 50-439/83-08
Corrective actions individuals counseled in QA program requirements W/one oversize drawing Aperture card in PDR
MILLS, L M Tennessee Valley Authority 83/09/28 O'REILLY, J P
Region 2, Office of Director App 20897 303 24X
Fiche 50-438, 83/10/19, 8310250301

--8310250313 Responds to NRC 830414 ltr re violations noted in IE Insp Repts 50-438/83-08 & 50-439/83-08 Corrective actions failure to perform holiday test on fire protection piping documented Violation re const flush configuration denied
MILLS, L M Tennessee Valley Authority 83/05/18 O'REILLY, J P
Region 2, Office of Director App 20897 308 24X
Fiche 50-438, 83/10/19, 8310250301

--8310250318 Forwards IE Insp Repts 50-438/83-08 & 50-439/83-08 on 830201-28 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/04/14
PARRIS, H Q Tennessee Valley Authority 2pp 20897 314 24X
Fiche 50-438, 83/10/19, 8310250301

--8310250324 Notice of violation from insp on 830201-28
* Division of Project & Resident Programs 83/04/14 2pp
20897 316 24X Fiche 50-438, 83/10/19, 8310250301

--8310250333 IE Insp Repts 50-438/83-08 & 50-439/83-08 on 830201-28
Noncompliance noted inadequate holiday test of fire protection, const flush configuration control & valve lineup
WILCOX, J D Region 2, Office of Director QUICK, D R Division of Project & Resident Programs 83/04/14 14pp 20897 318 24X
Fiche 50-438, 83/10/19, 8310250301

G Inspection reports, IE Bulletins & correspondence

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8310110365 FOIA request for NRC rept re violations at facility over misplaced & misfiled documents during 1981-82
FOLEY, J R Foley, Hoag & Elliot 83/08/09 QUILLAND, J Office of Public Affairs 1p 20712 351 24X Fiche 50-438, 83/08/09, 8310110365

8310110361 Responds to FOIA request for NRC rept re violations at facility over misplaced & misfiled documents during 1981-82
Lists repts identified by Region II of prepared in 1981-82 Repts available in PDR
FELTON, J M Division of Rules and Records 83/08/18 FOLEY, J R
Foley, Hoag & Elliot 1p 20712 350 24X Fiche 50-438, 83/08/18, 8310110361

8310040211 Forwards IE Insp Repts 50-438/-83-18 & 50-439/83-18 on 830601-05 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/09/02
PARRIS, H Q Tennessee Valley Authority 2pp 20615 007 24X
Fiche 50-438, 83/09/02, 8310040211

8310040244 IE Insp Repts 50-438/83-18 & 50-439/83-18 on 830801-05 No noncompliance noted Major areas inspected QA insp of civil (anchor bolts) & mechanical/piping installation work activities & licensee identified 10CFR50 55(e) items
WRIGHT, R W, MCFARLAND, C R Region 2, Office of Director
UPRIGHT, C M Division of Engineering & Operational Programs, 83/08/31 10pp 20615 009 24X Fiche 50-438, 83/09/02, 8310040211

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20714 324 24X Fiche 50-000, 83/09/29, 8308300349

8310250373 Forwards IE Insp Repts 50-438/83-25 & 50-439/83-25 on 830913-16 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/10/01
PARRIS, H Q Tennessee Valley Authority 2pp 20897 178 24X
Fiche 50-438, 83/10/03, 8310250373

--8310250380 IE Insp Repts 50-438/83-25 & 50-439/83-25 on 830913-16 No noncompliance noted Major areas inspected licensee action on previous enforcement matters, inspector Followup items, licensee identified items, electrical cables & terminations
RUFF, A B Region 2, Office of Director CONLON, T J Division of Engineering & Operational Programs 83/09/29 5pp 20898 100 24X Fiche 50-438, 83/10/03, 8310250373

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Mntl Defect Causes Production of Noxious Gases" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 127 24X Fiche 50-000, 83/10/11, 8308300761

8310250301 Ack receipt of 830518 & 0928 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-08 & 50-439/83-08 Records revised to delete Item B of violation re maint of cleanliness control
VERRELLI, D M Division of Project & Resident Programs 83/10/19
PARRIS, H Q Tennessee Valley Authority 2pp 20897 301 24X
Fiche 50-438, 83/10/19, 8310250301

--8310250306 Forwards revised response to NRC 830414 ltr re violations noted in IE Insp Repts 50-438/83-08 & 50-439/83-08
Corrective actions individuals counseled in QA program requirements W/one oversize drawing Aperture card in PDR
MILLS, L M Tennessee Valley Authority 83/09/28 O'REILLY, J P
Region 2, Office of Director App 20897 303 24X
Fiche 50-438, 83/10/19, 8310250301

--8310250313 Responds to NRC 830414 ltr re violations noted in IE Insp Repts 50-438/83-08 & 50-439/83-08 Corrective actions failure to perform holiday test on fire protection piping documented Violation re const flush configuration denied
MILLS, L M Tennessee Valley Authority 83/09/18 O'REILLY, J P
Region 2, Office of Director App 20897 308 24X
Fiche 50-438, 83/10/19, 8310250301

--8310250318 Forwards IE Insp Repts 50-438/83-08 & 50-439/83-08 on 830201-28 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/04/14
PARRIS, H Q Tennessee Valley Authority 2pp 20897 314 24X
Fiche 50-438, 83/10/19, 8310250301

--8310250324 Notice of violation from insp on 830201-28
* Division of Project & Resident Programs 83/04/14 2pp
20897 316 24X Fiche 50-438, 83/10/19, 8310250301

--8310250333 IE Insp Repts 50-438/83-08 & 50-439/83-08 on 830201-28
Noncompliance noted inadequate holiday test of fire protection, const flush configuration control & valve lineup
WILCOX, J D Region 2, Office of Director QUICK, D R Division of Project & Resident Programs 83/04/14 14pp 20897 318 24X
Fiche 50-438, 83/10/19, 8310250301

DOCKETED ITEMS

317

S Reportable occurrences, LERs & related correspondence

8310030233 Third interim deficiency rept re QA program on Tubeline matl supplied by Capitol Pipe Initially reported on 830329 Stop work order issued T-L Fittings/Flanges not installed in safety-related sys Next rept by 831108
MILLS, L M Tennessee Valley Authority 83/09/21 O'REILLY, J P
Region 2, Office of Director 3pp 20590 343 24X
Fiche 50-000, 83/09/21, 8310030233

8310030388 Second interim deficiency rept re QA program for personal svc contract Initially reported on 830406 Controlled copies of engineering procedures sent to Gilbert Assoc Next rept expected by 831014
MILLS, L M Tennessee Valley Authority 83/09/21 O'REILLY, J P
Region 2, Office of Director 3pp 20592 139 24X
Fiche 50-000, 83/09/21, 8310030388

8310030506 Revised final deficiency rept re sheared motor pinion keys in Limitorque motor operators Initially reported on 820830 Condition only applies to Watts Bar Keys will be replaced by 840201 Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 83/09/22 O'REILLY, J P
Region 2, Office of Director 3pp 20601 194 24X
Fiche 50-000, 83/09/22, 8310030506

8310030938 Final deficiency rept re incorrect max pipe movements contained in TPIPE program Initially reported on 830304 Response spectrum utilized in analyzing earthquake effect results in conservative displacements
MILLS, L M Tennessee Valley Authority 83/09/22 O'REILLY, J P
Region 2, Office of Director 3pp 20601 207 24X
Fiche 50-000, 83/09/22, 8310030938

8310030436 First interim deficiency rept re calculation of support design loads in TPIPE Initially reported on 830714 Procedure developed allowing recomputation of design loads near localized phenomena by hand Next rept by 831220
MILLS, L M Tennessee Valley Authority 83/09/23 O'REILLY, J P
Region 2, Office of Director 3pp 20602 095 24X
Fiche 50-000, 83/09/23, 8310030436

8310040172 First interim Deficiency Rept 2 re QA on valve purchase orders Initially reported on 830901 Hold on valve shipment initiated on 830902 & contractor reviewing deviation Next rept will be submitted by 831221
MILLS, L M Tennessee Valley Authority 83/09/26 O'REILLY, J P
Region 2, Office of Director 3pp 20608 055 24X
Fiche 50-438, 83/09/26, 8310040172

8310060331 Final & eighth interim deficiency repts for Watts Bar & Bellefonte, respectively re inconsistent establishment of insp program Initially reported on 810324 Requirements, control & use of const requirements manual developed
MILLS, L M Tennessee Valley Authority 83/09/30 O'REILLY, J P
Region 2, Office of Director 4pp 20641 001 24X
Fiche 50-000, 83/09/30, 8310060331

8310120228 First interim deficiency rept re flexible conduit requiring O-ring installed in various areas of plant w/o O-rings Initially reported on 830906 Procedures will include compliance w/manufacture instructions Next rept by 840208
MILLS, L M Tennessee Valley Authority 83/10/04 O'REILLY, J P
Region 2, Office of Director 3pp 20692 176 24X
Fiche 50-438, 83/10/04, 8310120228

8310140277 Second interim deficiency rept re welds on baffle plates in core support assembly mgt by B&W Initially reported on 830302 Baffle plates on former bolt locking pin welds repaired Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 83/10/05 O'REILLY, J P
Region 2, Office of Director 19pp 20761 195 24X
Fiche 50-438, 83/10/05, 8310140277

8310210096 Final rept re QA program deficiencies in Gilbert Assoc personal svcs contract Initially reported on 830406 Specific problems not identified by audit Items not reportable per 10CFR50.55(e)
MILLS, L M Tennessee Valley Authority 83/10/12 O'REILLY, J P
Region 2, Office of Director 4pp. 20858 197. 24X
Fiche 50 000, 83/10/12, 8310210096

8310190089 Final deficiency rept re discrepancy in interface coordination of design review process Initially reported on 810717 Finding of coordination problem not significant & should not have been reported to NRC per 10CFR50.55(e)
MILLS, L M Tennessee Valley Authority 83/10/13 O'REILLY, J P
Region 2, Office of Director 3pp 20818 132 24X
Fiche 50-000, 83/10/13, 8310190089

8310190224 Final deficiency rept re design review failure to verify accuracy & adequacy of design documents Initially reported on 811215 Listed changes to design review process will be implemented by 840101
MILLS, L M Tennessee Valley Authority 83/10/13 O'REILLY, J P
Region 2, Office of Director 3pp 20818 045 24X
Fiche 50-000, 83/10/13, 8310190224

8310210011 Final deficiency rept re resolution of unanticipated vibratory loading concerns. Initially reported on 830120 New requirements for assessing piping vibration problems during preoperational testing requirements issued
MILLS, L M Tennessee Valley Authority 83/10/13 O'REILLY, J P
Region 2, Office of Director 3pp 20855 345 24X
Fiche 50-000, 83/10/13, 8310210011

8310210049 Revised final deficiency rept re voiding of engineering change notices (ECNs) w/o proper review Initially reported on 820816 Sections in EN DES-EP 4 02 addressing voiding of ECNs changed in Rev 12, issued on 830203
MILLS, L M Tennessee Valley Authority 83/10/13 O'REILLY, J P
Region 2, Office of Director 3pp 20855 304 24X
Fiche 50-000, 83/10/13, 8310210049

8310190220 Final deficiency rept re generic implications of failure to implement design criteria in design drawings Initially reported on 810401 Eight addl nonconformances identified Functional control logic diagrams will be revised by 840301
MILLS, L M Tennessee Valley Authority 83/10/14 O'REILLY, J P
Region 2, Office of Director 3pp 20818 069 24X
Fiche 50-438, 83/10/14, 8310190220

8310250110 Second revised final deficiency rept re overpressurization of makeup & purification piping & valves Initially reported on 820528 Site personnel restrained to Div of Const test procedure for hydrostatic sys
MILLS, L M Tennessee Valley Authority 83/10/17 O'REILLY, J P
Region 2, Office of Director 3pp. 20896 255 24X
Fiche 50-438, 83/10/17, 8310250110

8310250149 Final deficiency rept re power for emergency air cleanup units after loss of offsite power Initially reported on 830103 Control logic corrected to allow cleanup units to be automatically loaded as part of loading sequence
MILLS, L M Tennessee Valley Authority 83/10/17 O'REILLY, J P
Region 2, Office of Director 3pp 20896 341 24X
Fiche 50-438, 83/10/17, 8310250149

8310270248 Final deficiency rept re cable bend radius going from vertical to horizontal trays Initially reported on 830422 Cable acceptable as-is, per Okonite Co evaluation Condition not reportable per 10CFR50.55(e)
MILLS, L M Tennessee Valley Authority 83/10/18 O'REILLY, J P
Region 2, Office of Director 3pp 20924 049 24X
Fiche 50-438, 83/10/18, 8310270248

8310310157 Final deficiency rept re inadequate expansion anchor spacing criteria Initially reported on 820607 Item not reportable under 10CFR50.55(e) Sampling programs indicated low probability of defects
MILLS, L M Tennessee Valley Authority 83/10/19 O'REILLY, J P
Region 2, Office of Director 3pp 20959 048. 24X
Fiche 50-438, 83/10/19, 8310310157

DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8310210178 Advises that scheduled fuel load date remains May 1985 for Unit 1, per NRC 810803 request Any changes will be reported in next quarterly update
MILLS, L M Tennessee Valley Authority 83/10/17. EISENHUT, D O
Division of Licensing 1p 20856 124 24X Fiche 50-438, 83/10/17, 8310210178

8310310443 Requests info to determine if operation of plant may affect cultural resources listed or eligible for listing in Natl Register of Historic Places.
ADENSAH, E O Licensing Branch 4 83/10/18 OAKS, L Alabama, State of 1p 20965 169 24X Fiche 50-438, 83/10/18, 8310310443

F Security, medical, emergency & fire protection plans

8310250301 Ack receipt of 830518 & 0928 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-08 & 50-439/83-08, Records revised to delete item B of violation re maint of cleanliness control
VERRELLI, D M Division of Project & Resident Programs 83/10/19
PARRISH, H O Tennessee Valley Authority 3pp 20897, 301 24X
Fiche 50-438, 83/10/19, 8310250301

DOCKETED ITEMS

--8310250306 Forwards revised response to NRC 830414 ltr re violations noted in IE Insp Repts 50-438/83-08 & 50-439/83-08
Corrective actions individuals counseled in QA program
requirements w/one oversize drawing Aperture card in PDR
MILLB, L M Tennessee Valley Authority 83/09/28 O'REILLY, J P
Region 2, Office of Director 4pp 20897 303 24X
Fiche 50-438, 83/10/19, 8310250301

--8310250313 Responds to NRC 830414 ltr re violations noted in IE Insp Repts 50-438/83-08 & 50-439/83-08 Corrective actions failure to perform holiday test on fire protection piping
documented Violation re const flush configuration denied
MILLB, L M Tennessee Valley Authority 83/05/18 O'REILLY, J P
Region 2, Office of Director 6pp 20897 308 24X
Fiche 50-438, 83/10/19, 8310250301

--8310250318 Forwards IE Insp Repts 50-438/83-08 & 50-439/83-08 on 830201-28 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/04/14
PARRIS, H G Tennessee Valley Authority 2pp 20897 314 24X
Fiche 50-438, 83/10/19, 8310250301

--8310250324 Notice of violation from insp on 830201-28
* Division of Project & Resident Programs 83/04/14 2pp
20897 316 24X Fiche 50-438, 83/10/19, 8310250301

--8310250333 IE Insp Repts 50-438/83-08 & 50-439/83-08 on 830201-28
Noncompliance noted: inadequate holiday test of fire
protection, const flush configuration control & valve lineup
WILCOX, J D Region 2, Office of Director 83/04/14 14pp
20897 318 24X Fiche 50-438, 83/10/19, 8310250301

G Inspection reports, IE Bulletins & correspondence

8310110365 FOIA request for NRC rept re violations at facility over
misplaced & misfiled documents during 1981-82
FOLEY, J R Foley, Hoag & Elliot 83/08/09 GILLILAND, J Office of
Public Affairs 1p 20712 351 24X Fiche 50-438, 83/08/09,
8310110365

8310110361 Responds to FOIA request for NRC rept re violations at
facility over misplaced & misfiled documents during 1981-82
Lists repts identified by Region II ofc prepared in
1981-82 Repts available in PDR
FELTON, J M Division of Rules and Records 83/08/18 FOLEY, J R
Foley, Hoag & Elliot 1p 20712 350 24X Fiche 50-438, 83/08/18,
8310110361

8310040211 Forwards IE Insp Repts 50-438/-83-18 & 50-439/83-18 on
830801-05 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/09/02
PARRIS, H G Tennessee Valley Authority 2pp 20615 007 24X
Fiche 50-438, 83/09/02, 8310040211

--8310040244 IE Insp Repts 50-438/83-18 & 50-439/83-18 on 830801-05 No
noncompliance noted Major areas inspected QA Insp of civil
(anchor bolts) & mechanical/piping installation work
activities & licensee identified 10CFR50.55(a) items
WRIGHT, R W, McFARLAND, C R Region 2, Office of Director
UPRIGHT, C M Division of Engineering & Operational Programs
83/08/31 10pp 20615:009 24X Fiche 50-438, 83/09/02, 8310040211

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder
Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New
York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
Detectors Positioned at Control Room Ventilation Air
Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New
York, Inc 116pp 20777-210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse
Type BA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New
York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345.

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to
Safety-Related Sys W/o 10CFR50.59 Evaluation " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co. of New
York, Inc 115pp 20716-324 24X Fiche 50-000, 83/09/29, 8308300349

8310250373 Forwards IE Insp Repts 50-438/83-25 & 50-439/83-25 on
830913-16 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/10/03
PARRIS, H G Tennessee Valley Authority 2pp 20898 178 24X
Fiche 50-438, 83/10/03, 8310250373

--8310250380 IE Insp Repts 50-438/83-25 & 50-439/83-25 on 830913-16 No
noncompliance noted Major areas inspected licensee action on
previous enforcement matters, inspector followup items,
licensee identified items, electrical cables & terminations
RUFF, A B Region 2, Office of Director CONLON, T E Division of
Engineering & Operational Programs 83/09/29 5pp 20898 180
24X Fiche 50-438, 83/10/03, 8310250373

8308300378 IE Info Notice 83-65, "Surveillance of Flow in R1D Bypass
Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New
York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical
Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New
York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect
Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective
Self-Contained Breathing Apparatus Air Cylinders " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New
York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310250301 Ack receipt of 830518 & 0928 ltrs informing NRC of steps
taken to correct violations noted in IE Insp Repts
50-438/83-08 & 50-439/83-08 Records revised to delete
Item 8 of violation re maint of cleanliness control
VERRELLI, D M Division of Project & Resident Programs 83/10/19
PARRIS, H G Tennessee Valley Authority 2pp 20897 301 24X
Fiche 50-438, 83/10/19, 8310250301

--8310250306 Forwards revised response to NRC 830414 ltr re violations
noted in IE Insp Repts 50-438/83-08 & 50-439/83-08
Corrective actions individuals counseled in QA program
requirements w/one oversize drawing Aperture card in PDR
MILLB, L M Tennessee Valley Authority 83/09/28 O'REILLY, J P
Region 2, Office of Director 4pp 20897 303 24X
Fiche 50-438, 83/10/19, 8310250301

--8310250313 Responds to NRC 830414 ltr re violations noted in IE Insp Repts
50-438/83-08 & 50-439/83-08 Corrective actions failure
to perform holiday test on fire protection piping
documented Violation re const flush configuration denied
MILLB, L M Tennessee Valley Authority 83/05/18 O'REILLY, J P
Region 2, Office of Director 6pp 20897 308 24X
Fiche 50-438, 83/10/19, 8310250301

--8310250318 Forwards IE Insp Repts 50-438/83-08 & 50-439/83-08 on
830201-28 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/04/14
PARRIS, H G Tennessee Valley Authority 2pp 20897 314 24X
Fiche 50-438, 83/10/19, 8310250301

--8310250324 Notice of violation from insp on 830201-28
* Division of Project & Resident Programs 83/04/14 2pp
20897 316 24X Fiche 50-438, 83/10/19, 8310250301

--8310250333 IE Insp Repts 50-438/83-08 & 50-439/83-08 on 830201-28
Noncompliance noted inadequate holiday test of fire
protection, const flush configuration control & valve lineup
WILCOX, J D Region 2, Office of Director QUICK, D K Division of
Project & Resident Programs 83/04/14 14pp 20897 318 24X
Fiche 50-438, 83/10/19, 8310250301

B Reportable occurrences, LERs & related correspondence

8310030233 Third interim deficiency rept re QA program on Tubeline matl
supplied by Capitol Pipe Initially reported on 830329 Stop
work order issued. T-L fittings/flanges not installed in
safety-related sys Next rept by 831108.
MILLB, L M Tennessee Valley Authority 83/09/21 O'REILLY, J P
Region 2, Office of Director 5pp 20590 343 24X
Fiche 50-000, 83/09/21, 8310030233

DOCKETED ITEMS

319

8310030388 Second interim deficiency rept re QA program for personal svc contract Initially reported on 830406 Controlled copies of engineering procedures sent to Gilbert Assoc Next rept expected by 831014
MILLS,L M Tennessee Valley Authority 83/09/21 O'REILLY,J P
Region 2, Office of Director 2pp 20592 139 24X
Fiche 50-000,83/09/21,8310030388

8310030506 Revised final deficiency rept re sheared motor pinion keys in Limitorque motor operators Initially reported on 820830 Condition only applies to Watts Bar Keys will be replaced by 840201 Also reportable per Part 21
MILLS,L M Tennessee Valley Authority 83/09/22 O'REILLY,J P
Region 2, Office of Director 3pp 20601 194 24X
Fiche 50-000,83/09/22,8310030506

8310030538 Final deficiency rept re incorrect max pipe movements contained in TPIPE program Initially reported on 830504 Response spectrum utilized in analyzing earthquake effect results in conservative displacements
MILLS,L M Tennessee Valley Authority 83/09/22 O'REILLY,J P
Region 2, Office of Director 3pp 20601 207 24X
Fiche 50-000,83/09/22,8310030538

8310030436 First interim deficiency rept re calculation of support design loads in TPIPE Initially reported on 830714 Procedure developed allowing recomputation of design loads near localized phenomena by hand Next rept by 831220
MILLS,L M Tennessee Valley Authority 83/09/23 O'REILLY,J P
Region 2, Office of Director 2pp 20602 093 24X
Fiche 50-000,83/09/23,8310030436

8310040172 First interim Deficiency Rept 2 re QA on valve purchase orders Initially reported on 830701 Hold on valve shipment initiated on 830902 & contractor reviewing deviation Next rept will be submitted by 831221
MILLS,L M Tennessee Valley Authority 83/09/26 O'REILLY,J P
Region 2, Office of Director 2pp 20608 055 24X
Fiche 50-438,83/09/26,8310040172

8310060331 Final & eighth interim deficiency repts for Watts Bar & Bellefonte, respectively re inconsistent establishment of insp program Initially reported on 810324 Requirements, control & use of const requirements manual developed
MILLS,L M Tennessee Valley Authority 83/09/30 O'REILLY,J P
Region 2, Office of Director App 20641 001 24X
Fiche 50-000,83/09/30,8310060331

8310120228 First interim deficiency rept re flexible conduit requiring O-ring installed in various areas of plant w/o O-rings Initially reported on 830906 Procedures will include compliance w/manufacture instructions Next rept by 840208
MILLS,L M Tennessee Valley Authority 83/10/04 O'REILLY,J P
Region 2, Office of Director 2pp 20692 176 24X
Fiche 50-438,83/10/04,8310120228

8310210096 Final rept re QA program deficiencies in Gilbert Assoc personal svcs contract Initially reported on 830406 Specific problems not identified by audit Items not reportable per 10CFR50.55(e)
MILLS,L M Tennessee Valley Authority 83/10/12 O'REILLY,J P
Region 2, Office of Director App 20858 197 24X
Fiche 50-000,83/10/12,8310210096

8310190089 Final deficiency rept re discrepancy in interface coordination of design review process. Initially reported on 810717 Finding of coordination problem not significant & should not have been reported to NRC per 10CFR50.55(e)
MILLS,L M Tennessee Valley Authority 83/10/13 O'REILLY,J P
Region 2, Office of Director 3pp 20818 132 24X
Fiche 50-000,83/10/13,8310190089

8310190224 Final deficiency rept re design review failure to verify accuracy & adequacy of design documents. Initially reported on 811215 Listed changes to design review process will be implemented by 840101
MILLS,L M Tennessee Valley Authority 83/10/13 O'REILLY,J P
Region 2, Office of Director 3pp 20818.045 24X
Fiche 50-000,83/10/13,8310190224

8310210011 Final deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on 820120 New requirements for assessing piping vibration problems during preoperational testing requirements issued
MILLS,L M Tennessee Valley Authority 83/10/13 O'REILLY,J P
Region 2, Office of Director 3pp 20855 345 24X
Fiche 50-000,83/10/13,8310210011

8310210049 Revised final deficiency rept re voiding of engineering change notices (ECNs) w/o proper review Initially reported on 820816 Sections in EN DES-EP 4.02 addressing voiding of ECNs changed in Rev 12, issued on 830203
MILLS,L M Tennessee Valley Authority 83/10/13 O'REILLY,J P
Region 2, Office of Director 2pp 20855 304 24X
Fiche 50-000,83/10/13,8310210049

8310190220 Final deficiency rept re generic implications of failure to implement design criteria in design drawings Initially reported on 810401 Eight addl nonconformances identified Functional control logic diagrams will be revised by 840301
MILLS,L M Tennessee Valley Authority 83/10/14 O'REILLY,J P
Region 2, Office of Director 2pp 20818 067 24X
Fiche 50-438,83/10/14,8310190220

8310250149 Final deficiency rept re power for emergency air cleanup units after loss of offsite power Initially reported on 830103 Control logic corrected to allow cleanup units to be automatically loaded as part of loading sequence
MILLS,L M Tennessee Valley Authority 83/10/17 O'REILLY,J P
Region 2, Office of Director 2pp 20896 341 24X
Fiche 50-438,83/10/17,8310250149

8310270248 Final deficiency rept re cable bend radius going from vertical to horizontal trays Initially reported on 830422 Cable acceptable as-is, per Dynite Co evaluation Condition not reportable per 10CFR50.55(e)
MILLS,L M Tennessee Valley Authority 83/10/18 O'REILLY,J P
Region 2, Office of Director 2pp 20924 049 24X
Fiche 50-438,83/10/18,8310270248

8310310157 Final deficiency rept re inadequate expansion anchor spacing criteria Initially reported on 820407 Item not reportable under 10CFR50.55(e) Sampling programs indicated low probability of defects
MILLS,L M Tennessee Valley Authority 83/10/19 O'REILLY,J P
Region 2, Office of Director 2pp 20959 048 24X
Fiche 50-438,83/10/19,8310310157

DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys. Info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway
EISENHUT,D O Division of Licensing 83/09/29 PALLADINO,N J
Commissioners 3pp 20632 001 24X Fiche 50-000,83/09/29,8308300357

8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves
EISENHUT,D O Division of Licensing 83/10/06 PALLADINO,N J
Commissioners 3pp 20818 001 24X Fiche 50-000,83/10/06,8308300771

8310200395 Forwards TM Novak 821112 memo to DO Eisenhut & J Stefano 821115 informal note to TM Novak re caseload panel review of facility, per R Ganulin FOIA-83-583 request Caseload Forecast Panel rept dtd 830317 also available
STEFANO,J Licensing Branch 1 83/10/07, WILSON,V Management Analysis Branch 1p 20874 272 24X Fiche 50-440,83/10/07,8310200395

--8310200397 Advises of Caseload Forecast Panel review scheduled for wk of 830110.
STEFANO,J NRC - No Detailed Affiliation Given 82/11/15
NOVAK,T M NRC - No Detailed Affiliation Given 1p 20874 275 24X Fiche 50-440,83/10/07,8310200395

--8310200400 Advises that site review by Caseload Forecast Panel scheduled for wk of 830110
BASSETT,H S Division of Data Automation & Management Information 82/11/12
BRESSARD,R L Director's Office, Office of Inspection and Enforcement 1p 20874 276 24X Fiche 50-440,83/10/07,8310200395

--8310200404 Discusses need for Caseload Forecast Panel review of facility
STEFANO,J NRC - No Detailed Affiliation Given 82/10/20,
NOVAK,T M NRC - No Detailed Affiliation Given 2pp 20874 277 24X Fiche 50-440,83/10/07,8310200395

--8310200407 Forwards R Ganulin FOIA-83-583 request for all documents re Caseload Forecast Panel meetings held during 1982-83 concerning plant const
WILSON,V H Management Analysis Branch 83/10/05
YOUNGBLOOD,B J Licensing Branch 1 2pp 20874 279 24X
Fiche 50-440,83/10/07,8310200395

8308310050 Board Notification 83-160, provides info re 830812 failure of main crankshaft on one of three Transamerica Delaval emergency diesel generators at Shoreham
EISENHUT,D O Division of Licensing 83/10/14 PALLADINO,N J
Commissioners 15pp 67056-070 24X Fiche 50-000,83/10/14,8308310050

DOCKETED ITEMS

8310240163 Clarifies Criteria 1, 2 & 10 of 830916 submittal re TMI Action Plan Item 11 B 3. "Post-Accident Sampling Sys " Chemistry technicians requalified biannually Offsite boron analysis performed only on undiluted sample
EDELMAN, M R Cleveland Electric Illuminating Co 83/10/14
YOUNGBLOOD, B J Licensing Branch 1 2pp 20661 313 24X
Fiche 50-440, 83/10/14, 8310240163

8310310378 Provides clarification on quencher tie-down loads Design dynamic stress from bending moment on quencher arm greater than 5,000 psi Facility design meets acceptance criteria
EDELMAN, M R Cleveland Electric Illuminating Co 83/10/21
YOUNGBLOOD, B J Licensing Branch 1 1p 20939 362 24X
Fiche 50-440, 83/10/21, 8310310378

8310310050 Forwards response to 830805 request for addl info re changes to diesel generator air starting sys Info will be incorporated into future FSAR amend
EDELMAN, M R Cleveland Electric Illuminating Co 83/10/24
YOUNGBLOOD, B J Licensing Branch 1 40pp 20947 240 24X
Fiche 50-440, 83/10/24, 8310310050

E NRC Safety Evaluation Report (SER), suppl's & correspondence

8310040227 Forwards info to resolve SER License Condition 7 per TMI Action Plan Item 11 B 3. "Post-Accident Sampling Sys " W/ two oversize drawings Aperture cards are available in PDR Proprietary info withheld (ref 10CFR2 7903)
EDELMAN, M R Cleveland Electric Illuminating Co 83/09/16
YOUNGBLOOD, B J Licensing Branch 1 1p 20612 067 24X
Fiche 50-440, 83/09/16, 8310040227

--8310040229 "Evaluation of Post-Accident Sampling Sys for Perry Nuclear Power Plant " * Cleveland Electric Illuminating Co 83/07/31 31pp 20612 071 24X Fiche 50-440, 83/09/16, 8310040227

--8310040231 Preliminary Rev 0 to Procedure CHI-22, Chemistry Equipment Instruction, "Single Channel Analyzer Canberra " WESTBROOK, W W Cleveland Electric Illuminating Co 83/09/16 17pp 20612 102 24X Fiche 50-440, 83/09/16, 8310040227

--8310040234 Preliminary Rev 0 to Procedure CHI-12, Chemistry Equipment Instruction, "Multi-Channel Analyzer, Canberra, Series 85 " WESTBROOK, W W Cleveland Electric Illuminating Co 83/09/16 18pp 20612 119 24X Fiche 50-440, 83/09/16, 8310040227

310110499 Requests input for SSER 4 by 831021 for Nov 1983 scheduled issuance Listing of info & responsible review branch encl SSER 4 will be basis for addressing steam erosion issue
YOUNGBLOOD, B J Licensing Branch 1 83/09/27, NODMAN, V Equipment Qualification Branch BOSNAK, R Mechanical Engineering Branch LIAW, B Materials Engineering Branch 4pp 20714 313 24X
Fiche 50-440, 83/09/27, 8310110499

110200238 Responds to SER Outstanding Issue 10 re containment purge, documenting design mod & sys operation limits, per 830526 meeting Containment purge sys provides for filtered purging for personnel entry & maint access
EDELMAN, M R Cleveland Electric Illuminating Co 83/10/07
YOUNGBLOOD, B J Licensing Branch 1 5pp 20833 052 24X
Fiche 50-440, 83/10/07, 8310200238

Adjudicatory correspondence

10050375 Forwards JE Konklin affidavit & JL Streeter & TE Vendel joint affidavit re inspector certification & QA advisory committee
GOLDBERG, S C Hearing Branch 4 83/09/29, BLOCH, P B, BRIDHT, O O, CLINE, J R Atomic Safety and Licensing Board Panel 1p 20634 002 24X Fiche 50-440, 83/09/29, 8310050375

1310050382 Affidavit of JE Konklin re inspector certifications & QA advisory committee meetings
KONKLIN, J E Region 3, Office of Director 83/09/27 6pp 20634 003 24X Fiche 50-440, 83/09/29, 8310050375

310050389 Affidavit of JF Streeter & TE Vendel supporting NRC position on QA advisory committee, Prop qualifications encl
STREETER, J F, VENDEL, T E Region 3, Office of Director 83/09/27 7pp 20634 009 24X Fiche 50-440, 83/09/29, 8310050375

3050520 Answer opposing Ohio Citizens for Responsible Energy 830916 motion to resubmit Contention 2 re diesel generator reliability Motion fails to meet criteria of adequate basis specificity Certificate of Svc encl
IGER, M A Cleveland Electric Illuminating Co SHIOER, M A Shaw, Pittman, Potts & Trowbridge 83/10/03 Atomic Safety and Licensing Board Panel 53pp 20634 126 24X Fiche 50-440, 83/10/03, 110050520

8310110061 Order extending time until 831007 for Commission to act to review ALAB-736
CHILK, S J Office of the Secretary of the Commission 83/10/03
Commissioners 1p 20668 238 24X Fiche 50-440, 83/10/03, 8310110061

8310130144 Response opposing Ohio Citizens for Responsible Energy 830916 motion to resubmit original proposed Contention 2 re diesel generator reliability Requirements for late-filed contentions not met Certificate of Svc encl
GOLDBERG, S C Hearing Branch 4 83/10/06 Atomic Safety and Licensing Board Panel 46pp 20749 092 24X Fiche 50-440, 83/10/06, 8310130144

8310120099 Reply to applicant & NRC affidavits re motion to reopen OA record FOIA request made in Nov 1982 produced negative results Formal discovery closed 3 months prior to ASLB issue Identification W/Certificate of Svc Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 83/10/07 Atomic Safety and Licensing Board Panel 11pp 20697 109 24X
Fiche 50-440, 83/10/07, 8310120099

8310130224 Advises that time for Commission to review ALAB-736 expired Commission declined review Decision became final agency action on 831007
CHILK, S J Office of the Secretary of the Commission 83/10/12
Office of the Executive Legal Director 1p 20724 094 24X
Fiche 50-440, 83/10/12, 8310130224

8310180337 Motion for reconsideration of ASLB 830809 Memorandum & Order LBP-83-46 granting summary disposition of Issue 13 Motion based on addl evidence Certificate of Svc encl Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 83/10/14 Atomic Safety and Licensing Board Panel 4pp 20803 002 24X
Fiche 50-440, 83/10/14, 8310180337

8310190061 Response to util & NRC 831003 & 06 answers, respectively, to Ohio Citizens for Responsible Energy 830916 motion to resubmit Contention 2 NRC misunderstood thrust of motion Contention should be admitted W/Certificate of Svc
HIATT, S L Ohio Citizens for Responsible Energy 83/10/14 Atomic Safety and Licensing Board Panel 11pp 20823 211 24X
Fiche 50-440, 83/10/14, 8310190061

8310270252 Answer opposing Ohio Citizens for Responsible Energy (OCRE) 831007 request to hold open Issue 3 record until fuel load Request reiterates previously denied OCRE motion Certificate of Svc encl
CLASSIEGEL, H Cleveland Electric Illuminating Co 83/10/24 Atomic Safety and Licensing Board Panel 6pp 20923 240 24X
Fiche 50-440, 83/10/24, 8310270252

8310270330 Response opposing Ohio Citizens for Responsible Energy (OCRE) 831014 response to NRC & util answers to OCRE motion to resubmit Contention 2 re diesel generator OCRE competence remains unproven Certificate of Svc encl
SILBERG, J E Cleveland Electric Illuminating Co SILBERG, J E Shaw, Pittman, Potts & Trowbridge 83/10/25 Atomic Safety and Licensing Board Panel 7pp 20923 145 24X Fiche 50-440, 83/10/25, 8310270330

G Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20734 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310170662 Forwards IE Insp Repts 50-440/83-27 & 50-441/83-26 on 830701-0831 & notice of violation
KNOPF, R C Region 3, Office of Director 83/09/28 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 20779 286 24X
Fiche 50-440, 83/09/28, 8310170662

--8310170667 Notice of violation from insp on 830701-0831
KNOPF, R C Region 3, Office of Director 83/09/28 1p 20779 288 24X Fiche 50-440, 83/09/28, 8310170662

DOCKETED ITEMS

32

--8310170670 IE Insp Repts 50-440/83-27 & 50-441/83-26 on 830701-08.11
Noncompliance noted failure to follow problem evaluation for
10CFR50.55(e) reportability procedures
GILDER, M L, KONKLIN, J E Region 3, Office of Director
83/09/27 4pp 20779 289 24X Fiche 50-440, 83/09/28, 8310170662

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to
Safety-Related Sys W/a 10CFR50.59 Evaluation " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New
York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310240121 Forwards IE Insp Repts 50-440/83-28 & 50-441/83-27 on
830922-23 No noncompliance noted
KNOP, R C Region 3, Office of Director 83/10/04 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 20881 145 24X
Fiche 50-440, 83/10/04, 8310240121

--8310240137 IE Insp Repts 50-440/83-28 & 50-441/83-27 on 830921-23 No
noncompliance noted Major areas inspected licensee actions
on previous insp findings, 10CFR50.55(e) reportable
items & IE bulletin
PELKE, P R, DAVIS, A D, KONKLIN, J E Region 3, Office of Director
83/10/03 3pp 20881 147 24X Fiche 50-440, 83/10/04, 8310240121

8310200045 forwards IE Insp Repts 50-440/83-26 & 50-441/83-25 on
830816-19 & notices of violation & deviation
LITTLE, W S Region 3, Office of Director 83/10/05 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 20836 009 24X
Fiche 50-440, 83/10/05, 8310200045

--8310200049 Notice of violation from insp on 830816-19
LITTLE, W S Region 3, Office of Director 83/10/05 1p
20836 011 24X Fiche 50-440, 83/10/05, 8310200045

--8310200053 Notice of deviation from insp on 830816-19
LITTLE, W S Region 3, Office of Director 83/10/05 1p
20836 012 24X Fiche 50-440, 83/10/05, 8310200045

--8310200057 IE Insp Repts 50-440/83-26 & 50-441/83-25 on 830816-19
Noncompliance noted bus bar support between 4, 160-volt
switchgear cubicles modified w/o approval & QA records
corrected improperly
MERRIWEATHER, N Region 3, Office of Director CONLON, T E
Division of Engineering 83/10/05 7pp 20836 013 24X
Fiche 50-440, 83/10/05, 8310200045

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass
Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 76pp 20627 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical
Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect
Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective
Self-Contained Breathing Apparatus Air Cylinders " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180215 Clarifies NRC position re procedures for admitting NRC
personnel to facility List of personnel requiring access to
vital areas encl Updates will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 EDELMAN, M R
Cleveland Electric Illuminating Co 7pp 20808 309 24X
Fiche 50-440, 83/10/14, 8310180215

8310270422 Forwards IE Insp Repts 50-440/83-29 & 50-441/83-28 on
830927-30 & notice of violation
SPESSARD, R L Division of Engineering 83/10/14 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 20923 065 24X
Fiche 50-440, 83/10/14, 8310270422

--8310270423 Notice of violation from insp on 830927-30
SPESSARD, R L Division of Engineering 83/10/14 1p 20923 067
24X Fiche 50-440, 83/10/14, 8310270422

--8310270426 IE Insp Repts 50-440/83-29 & 50-441/83-28 on 830927-30
Noncompliance noted licensee QA program did not provide for
developing, approving & distributing relay setting sheets
MERRIWEATHER, N Region 3, Office of Director CONLON, T E
Division of Engineering 83/10/11 App 20923 068 24X
Fiche 50-440, 83/10/14, 8310270422

S Reportable occurrences, LLRs & related correspondence

831010425 FOIA request for info re PND-111-83-027 concerning faulty
valve radiographs, PND-111-83-026 concerning use of lubricant
on valve seats & info on DOE/NRC 830417-20 meetings
concerning geologic repository in salt program
HIATT, S L Ohio Citizens for Responsible Energy 83/05/10
FELTON, J M Division of Rules and Records 1p 20706 001 24X
Fiche 50-000, 83/05/10, 831010425

831010430 Responds to FOIA request for four different categories of
documents described in 830510 ltr Forwards matl listed in
App A, responsive to Items 1, 2 & 4 DOE should be contacted
for matl requested in Item 3 of ltr
FELTON, J M Division of Rules and Records 83/06/14 HIATT, S L
Ohio Citizens for Responsible Energy 3pp 20706 002 24X
Fiche 50-000, 83/06/14, 831010430

--831010443 Forwards PND & morning rept re faulty Borg-Warner valve
radiographs Problem may be generic Related info encl
LITTLE, W S Region 3, Office of Director 83/04/13 POTAPOV, V
Region 4, Office of Director 15pp 20706 005 24X
Fiche 50-000, 83/06/14, 831010430

--831010461 Excerpt from notification of events at two different
facilities re deficiency concerning control complex chilled
water sys & info received that grease incorrectly used on
MSIVs, respectively Related info encl
* Region 3, Office of Director 83/04/08 11pp 20706 044 24X
Fiche 50-000, 83/06/14, 831010430

8310040404 Final deficiency rept re NAMCO Controls limit switches mfg
to inadequately implemented QA program Initially reported on
810210 Bill of matl spec (87793-05-4549-00) developed,
reviewed & approved for procurement of NAMCO switches
EDELMAN, M R Cleveland Electric Illuminating Co 83/09/27
KEPPLER, J G Region 3, Office of Director 3pp 20617 357 24X
Fiche 50-440, 83/09/27, 8310040404

8310102086 Interim deficiency rept re failure of panel circuit wiring
in Transamerica Delaval standby diesel generators to meet
IEEE 383 insulation flame test Vendor info under review
Final rept scheduled for submittal by 831230
EDELMAN, M R Cleveland Electric Illuminating Co 83/09/27
KEPPLER, J G Region 3, Office of Director 1p 20693 346 24X
Fiche 50-440, 83/09/27, 8310102086

8310060340 Final deficiency rept re violations of spec requirements
during installation of adjacent Hilti Xwik bolts Initially
reported on 830207 One-inch bolts will no longer be used
Insp program will be implemented
EDELMAN, M R Cleveland Electric Illuminating Co 83/09/30
KEPPLER, J G Region 3, Office of Director 2pp 20646 125 24X
Fiche 50-440, 83/09/30, 8310060340

8310060392 Final deficiency rept re rejection of previously accepted
radiographs on containment vessel shell plate welds
Initially reported on 820405 Accessible rejectable welds
excavated, repaired & reradiographed
EDELMAN, M R Cleveland Electric Illuminating Co 83/09/30
KEPPLER, J G Region 3, Office of Director 2pp 20646 105 24X
Fiche 50-440, 83/09/30, 8310060392

8310170469 Second interim Deficiency Rept RDC 78(83) re exhaust line
back pressures exceeding manufacturer recommendations on
standby diesel generators for HFCB Initially reported on
830805 Further mods required Also reported per Part 21
EDELMAN, M R Cleveland Electric Illuminating Co 83/10/06
KEPPLER, J G Region 3, Office of Director 2pp 20784 101 24X
Fiche 50-440, 83/10/06, 8310170469

8310210112 Interim deficiency rept re damage during removal of shroud
head/separator from reactor pressure vessel by use of
strongback & polar crane Initially reported on 830916
Further evaluation required Next rept by 840131
EDELMAN, M R Cleveland Electric Illuminating Co 83/10/12
KEPPLER, J G Region 3, Office of Director 2pp 20858 232 24X
Fiche 50-440, 83/10/12, 8310210112

8310270030 Interim deficiency rept re pipe support shop welds supplied
by Power Piping Co Initially reported on 830921 Engineer
support evaluation will be completed in Dec 1983 Final rept
will be submitted by 831215
EDELMAN, M R Cleveland Electric Illuminating Co 83/10/18
KEPPLER, J G Region 3, Office of Director 2pp 20924 334 24X
Fiche 50-440, 83/10/18, 8310270030

DOCKETED ITEMS

8310270206 Part 21 rept re engine mounted electrical cables Defective cable not installed as 830927 ltr states Parts shipped & installed on Gulf States River Bend Site (Engine Serial 74037/40 DSR 48) Instruction for cable changeout due in Nov BOYER, R E Transamerica Delaval, Inc 83/10/20 Director's Office, Office of Inspection and Enforcement 1p 20924 10R 24X Fiche 50-000, 83/10/20, 8310270206

DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class 1 piping sys Info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway EISENHUT, D G Division of Licensing 83/09/29 PALLADINO, N J Commissioners 3pp 20632 001 24X Fiche 50-000, 83/09/29, 8308300357

8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves EISENHUT, D G Division of Licensing 83/10/06 PALLADINO, N J Commissioners 31pp 20818 001 24X Fiche 50-000, 83/10/06, 8308300771

8310200395 Forwards TM Novak 821112 memo to DG Eisenhut & J Stefano 821115 informal note to TM Novak re caseload panel review of facility, per R Ganulin FOIA-83-583 request Caseload Forecast Panel rept dtd 830317 also available STEFANO, J Licensing Branch 1 83/10/07 WILSON, V Management Analysis Branch 1p 20874 272 24X Fiche 50-440, 83/10/07, 8310200395

--8310200400 Advises that site review by Caseload Forecast Panel scheduled for wk of 830110 BASSETT, H S Division of Data Automation & Management Information 82/11/12 SPESBARD, R L Director's Office, Office of Inspection and Enforcement 1p 20874 276 24X Fiche 50-440, 83/10/07, 8310200395

--8310200407 Forwards R Ganulin FOIA-83-583 request for all documents re Caseload Forecast Panel meetings held during 1982-83 concerning plant const WILSON, V H Management Analysis Branch 83/10/05 YOUNGBLOOD, B J Licensing Branch 1 2pp 20874 279 24X Fiche 50-440, 83/10/07, 8310200395

8308310050 Board Notification 83-160 provides info re 830812 failure of main crankshaft on one of three Transamerica Delaval emergency diesel generators at Shoreham EISENHUT, D G Division of Licensing 83/10/14 PALLADINO, N J Commissioners 19pp 67056 070 24X Fiche 50-000, 83/10/14, 8308310050

8310240165 Clarifies Criteria 1, 2 & 10 of 830916 submittal re TMI Action Plan Item II B 3, "Post-Accident Sampling Sys" Chemistry technicians requalified biannually Offsite boron analysis performed only on undiluted sample EDELMAN, M R Cleveland Electric Illuminating Co. 83/10/14 YOUNGBLOOD, B J Licensing Branch 1 2pp 20881 313 24X Fiche 50-440, 83/10/14, 8310240165

8310310378 Provides clarification on quencher tie-down loads Design dynamic stress from bending moment on quencher arm greater than 5,000 psi Facility design meets acceptance criteria EDELMAN, M R Cleveland Electric Illuminating Co. 83/10/21 YOUNGBLOOD, B J Licensing Branch 1 1p 20959 352 24X Fiche 50-440, 83/10/21, 8310310378

8310310050 Forwards response to 830805 request for addl info re changes to diesel generator air starting sys info will be incorporated into future FSAR amend EDELMAN, M R Cleveland Electric Illuminating Co. 83/10/24 YOUNGBLOOD, B J Licensing Branch 1 40pp 20947 240 24X Fiche 50-440, 83/10/24, 8310310050

NRC Safety Evaluation Report (SER), suppl's & correspondence

831040227 Forwards info to resolve SER License Condition 7 per TMI Action Plan Item II B 3, "Post-Accident Sampling Sys" w/two oversite drawings Aperture cards are available in PDR Proprietary info withheld (ref 10CFR2.790) EDELMAN, M R Cleveland Electric Illuminating Co. 83/09/16 YOUNGBLOOD, B J Licensing Branch 1 4pp 20612 067 24X Fiche 50-440, 83/09/16, 831040227

8310040229 "Evaluation of Post-Accident Sampling Sys for Perry Nuclear Power Plant" * Cleveland Electric Illuminating Co. 83/07/31 31pp 20612, 071 24X Fiche 50-440, 83/07/16, 8310040229

--8310040231 Preliminary Rev 0 to Procedure CHI-22, Chemistry Equipment Instruction, "Single Channel Analyzer, Canberra" WESTBROOK, W W Cleveland Electric Illuminating Co. 83/09/16 17pp 20612 102 24X Fiche 50-440, 83/09/16, 8310040227

--8310040234 Preliminary Rev 0 to Procedure CHI-12, Chemistry Equipment Instruction, "Multi-Channel Analyzer, Canberra, Series 85" WESTBROOK, W W Cleveland Electric Illuminating Co. 83/09/16 18pp 20612 119 24X Fiche 50-440, 83/09/16, 8310040227

8310110495 Requests input for SER 4 by 831021 for Nov 1983 scheduled issuance Listing of info 2 responsible review branch encl SER 4 will be basis for addressing steam erosion issue YOUNGBLOOD, B J Licensing Branch 1 83/09/27 NUOMAN, V Equipment Qualification Branch BOSNAK, R Mechanical Engineering Branch LIAM, B Materials Engineering Branch 4pp 20714 317 24X Fiche 50-440, 83/09/27, 8310110495

8310200238 Responds to SER Outstanding Issue 10 re containment purge, documenting design mod & sys operation limits, per 830516 meeting Containment purge sys provides for filtered purging for personnel entry & maint access EDELMAN, M R Cleveland Electric Illuminating Co. 83/10/07 YOUNGBLOOD, B J Licensing Branch 1 1pp 20833 052 24X Fiche 50-440, 83/10/07, 8310200238

G Adjudicatory correspondence

8310050375 Forwards JE Konklin affidavit & JL Streeter & TE Vandel joint affidavit re inspector certification & QA advisory committee GOLDBERG, S C Hearing Branch 4 83/09/29 BLOCH, P B, BRIGHI, G D, KLINE, J R Atomic Safety and Licensing Board Panel 1p 20634 001 24X Fiche 50-440, 83/09/29, 8310050375

--8310050382 Affidavit of JE Konklin re inspector certification & QA advisory committee meetings KONKLIN, J E Region 3, Office of Director 83/09/27 4pp 20634 003 24X Fiche 50-440, 83/09/29, 8310050375

--8310050389 Affidavit of JF Streeter & TE Vandel supporting NRC position on QA advisory committee Prof qualifications encl STREETER, J F, VENDEL, T E Region 3, Office of Director 83/09/29 7pp 20634 009 24X Fiche 50-440, 83/09/29, 8310050375

8310050520 Answer opposing Ohio Citizens for Responsible Energy 830916 motion to resubmit Contention 2 re diesel generator reliability Motion fails to meet criteria of adequate basis & specificity Certificate of Svc encl SWIGER, M A Cleveland Electric Illuminating Co. SWIGER, M A Shaw, Pittman, Potts & Trowbridge 83/10/03 Atomic Safety and Licensing Board Panel 53pp 20634 126 24X Fiche 50-440, 83/10/03, 8310050520

8310110061 Order extending time until 831001 for Commission to act to review ALAB-734 CHILK, S J Office of the Secretary of the Commission 83/10/05 Commissioners 1p 20668 238 24X Fiche 50-440, 83/10/03, 8310110061

8310130144 Response opposing Ohio Citizens for Responsible Energy 830916 motion to resubmit original proposed Contention 4 re diesel generator reliability Requirements for late-filed contentions not met Certificate of Svc encl GOLDBERG, S C Hearing Branch 4 83/10/06 Atomic Safety and Licensing Board Panel 46pp 20749 092 24X Fiche 50-440, 83/10/06, 8310130144

831020079 Reply to applicant & NRC affidavits re motion to reopen QA record FOIA request made in Nov 1982 produced negative results Formal discovery closed 3 months prior to AGH issue identification w/Certificate of Svc Related correspondence HIATT, S L Ohio Citizens for Responsible Energy 83/10/07 Atomic Safety and Licensing Board Panel 11pp 20697 109 24X Fiche 50-440, 83/10/07, 831020079

8310130224 Advises that time for Commission to review ALAB-734 expired Commission declined review Decision became final agency action on 831007 CHILK, S J Office of the Secretary of the Commission 83/10/12 Office of the Executive Legal Director 1p 20724 094 24X Fiche 50-440, 83/10/12, 8310130224

8310180337 Motion for reconsideration of ASLB 830809 Memorandum & Order LBP-83-44 granting summary disposition of Issue 13 Motion based on addl evidence Certificate of Svc encl Related correspondence HIATT, S L Ohio Citizens for Responsible Energy 83/10/14 Atomic Safety and Licensing Board Panel 4pp 20803 002 24X Fiche 50-440, 83/10/14, 8310180337

DOCKETED ITEMS

32

8310190061 Response to util & NRC 831003 & 06 answers, respectively, to Ohio Citizens for Responsible Energy 831016 motion to resubmit Contention 2 NRC misunderstood thrust of motion Contention should be admitted w/ certificate of Svc
HIATT, S L Ohio Citizens for Responsible Energy 83/10/14
Atomic Safety and Licensing Board Panel 11pp 20823 211 24X
Fiche 50-440, 83/10/14, 8310190061

8310270252 Answer opposing Ohio Citizens for Responsible Energy (OCRE) 831007 request to hold open Issue 3 record until fuel load Request reiterates previously denied OCRE motion Certificate of Svc encl
GLASSPIEGEL, M Cleveland Electric Illuminating Co 83/10/24
Atomic Safety and Licensing Board Panel 6pp 20923 240 24X
Fiche 50-440, 83/10/24, 8310270252

8310270330 Response opposing Ohio Citizens for Responsible Energy (OCRE) 831014 response to NRC & util answers to OCRE motion to resubmit Contention 2 re diesel generator OCRE competence remains unproven Certificate of Svc encl
SILBERG, J E Cleveland Electric Illuminating Co SILBERG, J F Shaw, Pittman, Potts & Trowbridge 83/10/25 Atomic Safety and Licensing Board Panel 7pp 20923 145 24X Fiche 50-440, 83/10/25, 8310270330

G Inspection reports, IE Bulletins, & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 6A-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310170662 Forwards IE Insp Repts 50-440/83-27 & 50-441/83-26 on 830701-0831 & notice of violation
KNOP, R C Region 3, Office of Director 83/09/28 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 20779 246 24X
Fiche 50-440, 83/09/28, 8310170662

--8310170667 Notice of violation from insp on 830701-0831
KNOP, R C Region 3, Office of Director 83/09/28 1p 20779 288 24X Fiche 50-440, 83/09/28, 8310170667

--8310170670 IE Insp Repts 50-440/83-27 & 50-441/83-26 on 830701-0831 Noncompliance noted failure to follow problem evaluation for 10CFR50.55(e) reportability procedures
OILDNER, M L, KONKLIN, J E Region 3, Office of Director 83/09/27 4pp 20779 289 24X Fiche 50-440, 83/09/28, 8310170662

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310240121 Forwards IE Insp Repts 50-440/83-28 & 50-441/83-27 on 830922-23 No noncompliance noted
KNOP, R C Region 3, Office of Director 83/10/04 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 20881 145 24X
Fiche 50-440, 83/10/04, 8310240121

--8310240137 IE Insp Repts 50-440/83-28 & 50-441/83-27 on 830921-23 No noncompliance noted Major areas inspected licensee actions on previous insp findings, 10CFR50.55(e) reportable items & IE bulletin
PELKE, P R, DAVIS, A B, KONKLIN, J E Region 3, Office of Director 83/10/03 3pp 20881 147 24X Fiche 50-440, 83/10/04, 8310240121

8310200045 Forwards IE Insp Repts 50-440/83-26 & 50-441/83-25 on 830816-19 & notices of violation & deviation
LITTLE, W B Region 3, Office of Director 83/10/05 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 20836 004 24X
Fiche 50-440, 83/10/05, 8310200045

--8310200057 IE Insp Repts 50-440/83-26 & 50-441/83-25 on 830816-19 Noncompliance noted bus bar support between 4,160-volt switchgear cubicles modified w/o approval & QA records corrected improperly
MERRIWEATHER, N Region 3, Office of Director CONLON, T E Division of Engineering 83/10/05 7pp 20836 013 24X
Fiche 50-440, 83/10/05, 8310200045

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180215 Clarifies NRC position re procedures for admitting NRC personnel to facility List of personnel requiring access to vital areas encl Updates will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 EDELMAN, M R Cleveland Electric Illuminating Co 7pp 20808 309 24X
Fiche 50-440, 83/10/14, 8310180215

8310270422 Forwards IE Insp Repts 50-440/83-29 & 50-441/83-28 on 830927-30 & notice of violation
SPESSARD, R L Division of Engineering 83/10/14 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 20923 065 24X
Fiche 50-440, 83/10/14, 8310270422

--8310270423 Notice of violation from insp on 830927-30
SPESSARD, R L Division of Engineering 83/10/14 1p 20923 067 24X Fiche 50-440, 83/10/14, 8310270422

--8310270426 IE Insp Repts 50-440/83-29 & 50-441/83-28 on 830927-30 Noncompliance noted licensee QA program did not provide for developing, approving & distributing relay setting sheets
MERRIWEATHER, N Region 3, Office of Director CONLON, T E Division of Engineering 83/10/11 6pp 20923 068 24X
Fiche 50-440, 83/10/14, 8310270422

S Reportable occurrences, LERs & related correspondence

8310110425 FOIA request for info re PNO-III-83-027 concerning faulty valve radiographs, PNO-III-83-026 concerning use of lubricant on valve seats & info on DOE/NRC 830419-20 meetings concerning geologic repository in salt program
HIATT, S L Ohio Citizens for Responsible Energy 83/05/10 FELTON, J M Division of Rules and Records 1p 20706 001 24X
Fiche 50-000, 83/05/10, 8310110425

8310110430 Responds to FOIA request for four different categories of documents described in 830510 ltr Forwards matl listed in App A responsive to Items 1, 2 & 4. DOE should be contacted for matl requested in Item 3 of ltr
FELTON, J M Division of Rules and Records 83/06/14 HIATT, S L Ohio Citizens for Responsible Energy 3pp 20706 002 24X
Fiche 50-000, 83/06/14, 8310110430

--8310110443 Forwards PNO & morning rept re faulty Borg-Warner valve radiographs. Problem may be generic Related info encl
LITTLE, W B Region 3, Office of Director 83/04/13 POFAPQVB, U Region 4, Office of Director 15pp 20706 005 24X
Fiche 50-000, 83/06/14, 8310110430

--8310110461 Excerpt from notification of events at two different facilities re deficiency concerning control complex chilled water sys & info received that grease incorrectly used on MSIVs, respectively Related info encl
Region 3, Office of Director 83/04/08 11pp 20706 044 24X
Fiche 50-000, 83/06/14, 8310110430

DOCKETED ITEMS

8310040404 Final deficiency rept re NAMCO Controls limit switches mfg to inadequately implemented QA program Initially reported on 810210 Bill of matl spec (SP793-03-4549-00) developed, reviewed & approved for procurement of NAMCO switches
EDELMAN, M R Cleveland Electric Illuminating Co 83/09/27
KEPPLER, J Q Region 3, Office of Director 3pp 20617 357 24X
Fiche 50-440, 83/09/27, 8310040404

8310120286 Interim deficiency rept re failure of panel circuit wiring in Transamerica Delaval standby diesel generators to meet IEEE 383 insulation flame test Vendor info under review
Final rept scheduled for submittal by 831230
EDELMAN, M R Cleveland Electric Illuminating Co 83/09/27
KEPPLER, J Q Region 3, Office of Director 1p 20693 346 24X
Fiche 50-440, 83/09/27, 8310120286

8310060340 Final deficiency rept re violations of spec requirements during installation of adjacent Hilti Fwtk bolts Initially reported on 830207 One-inch bolts will no longer be used Insp program will be implemented
EDELMAN, M R Cleveland Electric Illuminating Co 83/09/30
KEPPLER, J Q Region 3, Office of Director 2pp 20646 125 24X
Fiche 50-440, 83/09/30, 8310060340

8310060392 Final deficiency rept re rejection of previously accepted radiographs on containment vessel shell plate welds Initially reported on 820405 Accessible rejectable welds excavated, repaired & reradiographed
EDELMAN, M R Cleveland Electric Illuminating Co 83/09/30
KEPPLER, J Q Region 3, Office of Director 2pp 20646 105 24X
Fiche 50-440, 83/09/30, 8310060392

8310170469 Second interim Deficiency Rept RDC 78(83) re exhaust line back pressures exceeding manufacturer recommendations on standby diesel generators for HFCS Initially reported on 830805 Further Mods required Also reported per Part 21
EDELMAN, M R Cleveland Electric Illuminating Co 83/10/06
KEPPLER, J Q Region 3, Office of Director 2pp 20784 101 24X
Fiche 50-440, 83/10/06, 8310170469

8310250483 Final deficiency rept re contact leads on OE HMA relays Initially reported on 820818 Evaluation revealed no instances of insufficient lead to terminal spacing Potential deficiency not applicable to Unit 2 HMA relays
EDELMAN, M R Cleveland Electric Illuminating Co 83/10/18
KEPPLER, J Q Region 3, Office of Director 1p 20897 142 24X
Fiche 50-441, 83/10/18, 8310250483

8310270030 Interim deficiency rept re pipe support shop welds supplied by Power Piping Co Initially reported on 830921 Engineer support evaluation will be completed in Dec 1983 Final rept will be submitted by 831215
EDELMAN, M R Cleveland Electric Illuminating Co 83/10/18
KEPPLER, J Q Region 3, Office of Director 2pp 20924 334 24X
Fiche 50-440, 83/10/18, 8310270030

8310270206 Part 21 rept re engine mounted electrical cables Defective cable not installed as 830927 ltr states Parts shipped & installed on Gulf States River Bend Site (Engine Serial 74039/40 DSR 48) Instruction for cable changeout due in Nov
BOYER, R E Transamerica Delaval, Inc 83/10/20 Director's Office, Office of Inspection and Enforcement 1p 20924 108 24X
Fiche 50-000, 83/10/20, 8310270206

DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8310070232 Notification of Significant Licensee Meeting 83-86 on 831005 at site to discuss open electrical items, issues & commitments
CERNE, A Region 1, Office of Director 83/09/28 Region 1, Office of Director 1p 20664 362 24X Fiche 50-443, 83/09/28, 8310070232

8308300355 Board Notification 83-66A advises that position re rod drop issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycle
EISENHUT, D Q Division of Licensing 83/09/29 PALLADINO, N J Commissioners 10pp 20632 106 24X Fiche 50-000, 83/09/29, 8308300355

8308300763 Board Notification 83-151 provides info re desirability of current ECCS actuation logic for Westinghouse plants, in light of recent info concerning steam generator tube rupture procedure for Borssele Nuclear Power Station
EISENHUT, D Q Division of Licensing 83/10/04 PALLADINO, N J Commissioners 2pp 20698 033 24X Fiche 50-000, 83/10/04, 8308300763

8310120263 Forwards resolution & press release re reduced expenditure level & const activity on Unit 2 Reduced expenditure level will be continued until fuel loading for Unit 1 completed, unless Unit 2 canceled
DEVINCENYIS, J Yankee Atomic Electric Co DEVINCENYIS, J Public Service Co of New Hampshire 83/10/05 KNIGHTON, O W Licensing Branch 3 5pp 20693 073 24X Fiche 50-443, 83/10/05, 8310120263

8308300771 Board Notification 83-128A Forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves
EISENHUT, D Q Division of Licensing 83/10/06 PALLADINO, N J Commissioners 31pp 20818 001 24X Fiche 50-000, 83/10/06, 8308300771

8310260187 Forwards Amend 51 to application for DL transferring 0 412597 ownership share from Vermont Electric Cooperative, Inc to Vermont Electric Generation & Transmission Cooperative, Inc Certificate of Svc encl
RITSHER, J A Ropes & Gray 83/10/17 Division of Licensing 1p 20912 252 24X Fiche 50-443, 83/10/17, 8310260187

--8310260201 Amend 51 to application for DL transferring 0 412597 ownership share from Vermont Electric Cooperative, Inc to Vermont Electric Generation & Transmission Cooperative, Inc JOHNSTON, V P Public Service Co of New Hampshire 83/10/03 Division of Licensing 5pp 20912 253 24X Fiche 50-443, 83/10/17, 8310260187

--8310260208 Info furnished per 10CFR50.33 of Commission rules & regulations as part of request for partial transfer of ownership of CP Financial statements encl
GALLAGHER, J W Vermont Electric Cooperative, Inc 83/09/26 24pp 20912 259 24X Fiche 50-443, 83/10/17, 8310260187

F Security, medical, emergency & fire protection plans

8310170394 Forwards draft App D to radiological emergency response plans for Towns of Newfields, New Castle, North Hampton & Brentwood, NH, entitled "Cross-Reference to NUREG-0654"
LESSY, R P Hearing Branch 3 83/10/12 HOYT, H, LUEDKE, L A, HARBOUR, J Atomic Safety and Licensing Board Panel 26pp 20785 045 24X Fiche 50-443, 83/10/12, 8310170394

G Adjudicatory correspondence

8310030355 Motion to dismiss DL application for Unit 2 Further civil efforts deferred until Unit 1 complete Jul 1987 estimated const completion date for Unit 2 abandoned w/Certificate of Svc
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/09/26 Atomic Safety and Licensing Board Panel 7pp 20593 063 24X Fiche 50-443, 83/09/26, 8310030355

8310030397 Comments on scheduling of offsite emergency planning contentions All offsite planning contentions should be litigated together Issues similar & some witnesses will testify on both plans Certificate of Svc encl
BISBEE, O D New Hampshire, State of 83/09/26 7pp 20592 343 24X Fiche 50-443, 83/09/26, 8310030397

8310040533 Objects to conduct at 830031 hearing re continued participation of Town of Rye, NH representative G Chichester Earlier telcon did not advise Town that Chichester dismissed from further participation
NADEAU, J P, YOUNG, M L, HOLWAY, F I Rye, NH 83/09/26 HOYT, H Atomic Safety and Licensing Board Panel 2pp 20623 279 24X Fiche 50-443, 83/09/26, 8310040533

8310050366 Response to State of MA Atty General 830909 contention re offsite emergency planning for Towns of Seabrook, Hampton, North Hampton & Rye Present wording of contention w/o regulatory basis Certificate of Svc encl
PATTERSON, W F LESSY, R P Hearing Branch 3 83/09/26 Atomic Safety and Licensing Board Panel 7pp 20630 345 24X Fiche 50-443, 83/09/26, 8310050366

8310050472 Response to Town of Hampton Falls, NH 830906 offsite emergency planning contention Contention not opposed
LESSY, R P, PATTERSON, W F Hearing Branch 3 83/09/26 Atomic Safety and Licensing Board Panel 3pp 20633 190 24X Fiche 50-443, 83/09/26, 8310050472

--8310050474 Response to Commonwealth of MA 830909 motion for clarification of ASLB 830830 order admitting contentions & motion for reconsideration of ASLB 830630 order on evacuation time estimates Motions not opposed
LESSY, R P, PATTERSON, W F Hearing Branch 3, 83/09/26 Atomic Safety and Licensing Board Panel 3pp 20633, 193 24X Fiche 50-443, 83/09/26, 8310050472

DOCKETED ITEMS

32

--B310050477 Response opposing JF Doherty B30906 petition to intervene No good cause shown for petition late by 22 months Other factors for untimely intervention not met
PATTERSON, W F , LESSY, R P Hearing Branch 3 83/09/26 Atomic
Safety and Licensing Board Panel 7pp 20633 196 24X
Fiche 50-443,83/09/26, B310050472

--B310050480 Response to Hampton Beach Area Chamber of Commerce B30906 contentions on offsite emergency planning for Town of Hampton, NH Objects to admission of Contentions I, II, III & IV(a, b, c, f & g) Certificate of Svc encl
PATTERSON, W F , LESSY, R P Hearing Branch 3 83/09/26 Atomic
Safety and Licensing Board Panel 13pp 20633 203 24X
Fiche 50-443,83/09/26, B310050472

B310040510 Position on schedule of offsite emergency planning issues Hearings on New Hampshire radiological emergency response plans & local plans should be postponed until Mar 1984
Certificate of Svc encl
CASSIDY, D P Federal Emergency Management Agency 83/09/27 29pp
20625 216 24X Fiche 50-443,83/09/27, B310040510

B310050551 Response to Town of Kensington contentions re emergency planning Town of Kensington resolution of concerns & inadequacies expected prior to litigation of Contentions I(a-d) & II Certificate of Svc encl
PATTERSON, W F , LESSY, R P Hearing Branch 3 83/09/27 Atomic
Safety and Licensing Board Panel 8pp 20629 346 24X
Fiche 50-443,83/09/27, B310050551

B310040256 Interrogatories & requests for documents re emergency planning for State of NH
BELLOTTI, F X Massachusetts, Commonwealth of 83/09/27 Federal
Emergency Management Agency 12pp 20613 005 24X
Fiche 50-443,83/09/27, B310040256

--B310040262 Interrogatories & requests for documents re emergency planning for State of NH
BELLOTTI, F X Massachusetts, Commonwealth of 83/09/27 New
Hampshire, State of 12pp 20613 017 24X Fiche 50-443,83/09/27, B310040256

--B310040272 Notice of B31017 deposition in Boston, MA of all util. NRC, State of NH or FEMA witnesses re admitted contentions on draft New Hampshire radiological emergency response plans
SHOTWELL, J A Massachusetts, Commonwealth of 83/09/29 2pp
20613 029 24X Fiche 50-443,83/09/29, B310040256

--B310040277 Interrogatories & requests for documents re emergency planning for State of NH Certificate of Svc encl
BELLOTTI, F X Massachusetts, Commonwealth of 83/09/29 Public
Service Co of New Hampshire 11pp 20613 031 24X
Fiche 50-443,83/09/29, B310040256

B310050373 Response to Seacoast Anti-Pollution League B30909 supplemental petition for leave to intervene & contentions re offsite emergency planning Objects to Contentions 11, 14, 15, 17, 18, 19, 20, 22 & 23 Certificate of Svc encl
PATTERSON, W F , LESSY, R P Hearing Branch 3 83/09/29 Atomic
Safety and Licensing Board Panel 25pp 20632 268 24X
Fiche 50-443,83/09/29, B310050373

--B310050381 Response to New England Coalition on Nuclear Pollution B30909 contentions on State of NH offsite radiological emergency response planning Objects to listed contentions Certificate of Svc encl
PATTERSON, W F , LESSY, R F Hearing Branch 3 83/09/29 Atomic
Safety and Licensing Board Panel 21pp 20632, 273 24X
Fiche 50-443,83/09/29, B310050373

--B310050388 Response to Town of Seabrook, NH B30909 contentions re offsite emergency planning Objects to Contentions 1, 5, 6, 9, 12 & 10 Certificate of Svc encl
PERLIS, R Q , PATTERSON, W F , LESSY, R F Hearing Branch 3 83/09/29 Atomic
Safety and Licensing Board Panel 14pp
20632 314 24X Fiche 50-443,83/09/29, B310050373

B310050398 Opposes presently worded proposed contention on local emergency planning Std of providing complete protection under all circumstances not dictated by law
PATTERSON, W F Hearing Branch 3 83/10/03 SHOTWELL, J
Massachusetts, Commonwealth of 2pp 20629 337 24X
Fiche 50-443,83/10/03, B310050398

B31010152 Motion for leave to file response to NRC & applicant answers to Atty General FX Bellotti motion for reconsideration of ASLB ruling on evacuation time estimate preparation time Certificate of Svc encl
SHOTWELL, J A Massachusetts, Commonwealth of 83/10/03 Atomic
Safety and Licensing Board Panel 5pp 20666 287 24X
Fiche 50-443,83/10/03, B31010152

B310120178 Requests to be advised of steps necessary to appeal ASLB dismissal of Q Chichester from proceeding & advises that contentions will be resubmitted
NADEAU, J P , YOUNG, M L , HOLWAY, F I Rye, NH 83/10/03 HOYT, H F
Atomic Safety and Licensing Board Panel 3pp 20695 292 24X
Fiche 50-443,83/10/03, B310120178

B310110202 Amended petition for leave to intervene Svc of Process encl
DOHERTY, J F Doherty, J F 83/10/04 Atomic Safety and Licensing
Board Panel 7pp 20665:024 24X Fiche 50-443,83/10/04, B310110202

B310110316 Requests leave to amend petition for leave to intervene Amended petition based on applicant & NRC urging for uncountenanced expansion of NRC rulings & misrepresentation of petitioner arguments in one case
DOHERTY, J F Doherty, J F 83/10/04 Atomic Safety and Licensing
Board Panel 1p 20665 006 24X Fiche 50-443,83/10/04, B310110316

B310110049 Order extending time until B31013 for Commission to act to review ALAD-737
CHILK, S J Office of the Secretary of the Commission 83/10/05
Commissioners 1p 20668 272 24X Fiche 50-443,83/10/05, B310110049

B310110083 Forwards proposed findings of fact & conclusions of law
GAD, R K Ropes & Gray GAD, R K Public Service Co of New
Hampshire 83/10/05 Office of the Secretary of the Commission
1p 20668 157 24X Fiche 50-443,83/10/05, B310110083

--B310110092 Proposed Findings of fact & conclusions of law, Certificate of Svc encl
DIGNAN, T Q , GAD, R K Public Service Co of New Hampshire
DIGNAN, T Q Ropes & Gray 83/10/05 54pp 20668 158 24X
Fiche 50-443,83/10/05, B310110083

B310110158 First set of interrogatories on State of NH radiological emergency response plan
CURRAN, D , JORDAN, W S New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/10/05 Federal Emergency Management
Agency 4pp 20666 241 24X Fiche 50-443,83/10/05, B310110158

--B310110165 First set of interrogatories on State of NH radiological emergency response plan
CURRAN, D , JORDAN, W S New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/10/05 Public Service Co of New
Hampshire 3pp 20666 245 24X Fiche 50-443,83/10/05, B310110158

--B310110170 Objection to improper ASLB conduct, response to util position as to scheduling of emergency planning issues & request for hearing on licensing schedule
CURRAN, D , JORDAN, W S New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/10/05 10pp 20666 248 24X
Fiche 50-443,83/10/05, B310110158

--B310110175 First set of interrogatories on State of NH radiological emergency response plan Certificate of Svc encl.
CURRAN, D , JORDAN, W S New England Coalition on Nuclear Pollution.
CURRAN, D Harmon & Weiss 83/10/05 New Hampshire, State of
15pp 20666 258, 24X Fiche 50-443,83/10/05, B310110158

B310110227 Interrogatories & requests for documents on emergency planning for State of NH Related correspondence
BACKUS, R A Seacoast Anti-Pollution League. BACKUS, R A Backus,
Bhea & Meyer 83/10/05 Public Service Co of New Hampshire
7pp 20665 316 24X Fiche 50-443,83/10/05, B310110227

B310120133 Answer opposing Seacoast Anti-Pollution League B30926 motion to dismiss OL application for Unit 2 Wrong regulation cited
NRR, not ASLB, issues OLs League argument previously rejected by ASLB Certificate of Svc encl
DIGNAN, T Q , GAD, R K Public Service Co of New Hampshire
DIGNAN, T Q Ropes & Gray 83/10/06 Atomic Safety and Licensing
Board Panel 7pp 20695 270, 24X Fiche 50-443,83/10/06, B310120133

B310120428 Response opposing Town of Hampton B30919 contentions on town radiological emergency response plan. No justification offered for late filing Towns should not be allowed to attack own plans Certificate of Svc encl
DIGNAN, T Q , GAD, R K Public Service Co of New Hampshire
DIGNAN, T Q Ropes & Gray 83/10/06 Atomic Safety and Licensing
Board Panel 4pp 20698 326 24X Fiche 50-443,83/10/06, B310120428

B310130255 Discusses rev to NRC B30926 response to State of MA contentions on offsite emergency planning for Towns of Seabrook, Hampton, North Hampton & Rye. Rev limited to local plans & provisions re Town sheltering responsibilities
PATTERSON, W F Hearing Branch 3 83/10/06, SHOTWELL, J A
Massachusetts, Commonwealth of 3pp 20723 234 24X
Fiche 50-443,83/10/06, B310130255

DOCKETED ITEMS

- 8310140015 Lists QA procedures approved for implementation & available for insp at station Svc list encl
QAD, R K Ropes & Gray 83/10/06 CURRAN, D Harmon & Weiss 5pp
20767 041 24X Fiche 50-443, 83/10/06, 8310140015
- 8310140021 Response to applicant 83092; motion for denial of Towns of Kensington & South Hampton contentions re emergency planning Plans formulated by private consulting firm & not endorsed by towns Certificate of Svc encl
GAVUTIS, S Kensington, NH VERGE, A W South Hampton, NH 83/10/06 Atomic Safety and Licensing Board Panel 9pp
20767 032 24X Fiche 50-443, 83/10/06, 8310140021
- 8310120107 Motion for disqualification of Judge Hoyt Hostility toward intervenor & state counsel, as well as municipal representatives apparent & ever-increasing Appearance of partiality established
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/10/07 Atomic Safety and Licensing Board Panel 68pp
20695 178 24X Fiche 50-443, 83/10/07, 8310120107
- 8310120111 Reply opposing applicant objection to Seacoast Anti-Pollution League supplemental petition for leave to intervene Applicant objections w/o merit Contentions should be admitted
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/10/07 Atomic Safety and Licensing Board Panel 7pp
20695 247 24X Fiche 50-443, 83/10/07, 8310120107
- 8310120115 Affidavit in support of 831007 motion for recusal of Judge Hoyt
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/10/07 2pp
20695 254 24X Fiche 50-443, 83/10/07, 8310120107
- 8310120122 Answer supporting New England Coalition on Nuclear Pollution (NECNP) reply to Applicant & NRC responses to NECNP contentions on State of NH radiological emergency response plan
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/10/07 Atomic Safety and Licensing Board Panel 1p
20695 256 24X Fiche 50-443, 83/10/07, 8310120107
- 8310120126 Errata to 830926 motion to dismiss DL application for Unit 2 City on Page 1 should read 10CFR57(a)(1)
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/10/07 Atomic Safety and Licensing Board Panel 1p
20695 257 24X Fiche 50-443, 83/10/07, 8310120107
- 8310120135 Motion to stay further ASLB rulings pending review & appeal of Seacoast Anti-Pollution League motion for recusal of Judge Hoyt
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/10/07 Atomic Safety and Licensing Board Panel 1p
20695 258 24X Fiche 50-443, 83/10/07, 8310120107
- 8310120141 Reply to NRC response to Seacoast Anti-Pollution League supplemental petition for leave to intervene concerning emergency planning contentions Certificate of Svc encl
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/10/07 Atomic Safety and Licensing Board Panel 9pp
20695 259 24X Fiche 50-443, 83/10/07, 8310120107
- 8310120147 Motion for summary disposition of Commonwealth of MA Contentions I, II, III, IV A & IV B, Seacoast Anti-Pollution League Contention 5 & New England Coalition on Nuclear Pollution Contentions 3, 4, 5, 7, 12 & 13
SHOTWELL, J A Massachusetts, Commonwealth of 83/10/07 Atomic Safety and Licensing Board Panel 46pp
20696 042 24X Fiche 50-443, 83/10/07, 8310120147
- 8310120151 Answer to NRC & util 830926 & 20, respectively, responses to Commonwealth of MA 830909 emergency planning contentions Evacuation within times estimated will suby beachgoers to fatal radiation doses Certificate of Svc encl
SHOTWELL, J A Massachusetts, Commonwealth of 83/10/07 Atomic Safety and Licensing Board Panel 10pp
20696 088 24X Fiche 50-443, 83/10/07, 8310120147
- 8310120046 Response opposing Town of Rye contentions re emergency planning for State of NH & Town of Rye Contention 1 vague & raises issues outside hearing scope Contention 2 already litigated Certificate of Svc encl
PATTERSON, M F LESSY, R P Hearing Branch 3 83/10/11 Atomic Safety and Licensing Board Panel 10pp
20725 065 24X Fiche 50-443, 83/10/11, 8310120046
- 8310140191 Reply to util & NRC responses to New England Coalition on Nuclear Pollution contention on State of NH local emergency response plans Coalition has specifically alleged unreliability of info in plans W/Certificate of Svc
CURRAN, D, JORDAN, W S New England Coalition on Nuclear Pollution CURRAN, D Harmon & Weiss 83/10/11 Atomic Safety and Licensing Board Panel 16pp
20762 315 24X Fiche 50-443, 83/10/11, 8310140191
- 8310170394 Forwards draft App D to radiological emergency response plans for Towns of Newfields, New Castle, North Hampton & Brentwood, NH, entitled "Cross-Reference to NUREG-0654"
LESSY, R P Hearing Branch 3 83/10/12 HOYT, H LUEBKE, L A HARBOUR, J Atomic Safety and Licensing Board Panel 26pp
20785 045 24X Fiche 50-443, 83/10/12, 8310170394
- 8310180150 Forwards applicant 831012 response to FX Bellotti motion for leave to file responses to NRC & util answers to State of MA motion for reconsideration of ASLB ruling on evacuation time estimates preparation time
QAD, R K Ropes & Gray QAD, R K Public Service Co of New Hampshire 83/10/12 Office of the Secretary of the Commission 1p
20809 154 24X Fiche 50-443, 83/10/12, 8310180150
- 8310180153 Response to FX Bellotti 831003 motion for leave to file response to NRC & util answers to motion for reconsideration of ASLB ruling on evacuation time estimates preparation time Certificate of Svc encl
DIGNAN, T O, QAD, R K Public Service Co of New Hampshire DIGNAN, T O Ropes & Gray 83/10/12 Atomic Safety and Licensing Board Panel 16pp
20809 155 24X Fiche 50-443, 83/10/12, 8310180150
- 8310180368 Notice of continuance of depositions of witnesses on State of NH radiological emergency response plan scheduled for wk of 831017
SHOTWELL, J A Massachusetts, Commonwealth of 83/10/12 2pp
20803 175 24X Fiche 50-443, 83/10/12, 8310180368
- 8310180373 Motion for leave to file response to NRC 831006 ltr which constituted supplemental answer to Commonwealth of MA contention on emergency planning Contention is not untimely Certificate of Svc encl
SHOTWELL, J A Massachusetts, Commonwealth of 83/10/12 Atomic Safety and Licensing Board Panel 5pp
20803 177 24X Fiche 50-443, 83/10/12, 8310180368
- 8310170424 Order extending time until 831025 for Commission to act to review ALAB-737
CHILK, S J Office of the Secretary of the Commission 83/10/13 Commissioners 1p
20784 037 24X Fiche 50-443, 83/10/13, 8310170424
- 8310180165 Forwards answer to Atty General Bellotti interrogatories & requests for documents on emergency planning for State of NH
QAD, R K Ropes & Gray QAD, R K Public Service Co of New Hampshire 83/10/13 Docketing & Services Branch 1p
20809 114 24X Fiche 50-443, 83/10/13, 8310180165
- 8310180170 Answers to interrogatories & requests for documents on emergency planning for State of NH Certificate of Svc encl
DIGNAN, T O, QAD, R K Public Service Co of New Hampshire DIGNAN, T O Ropes & Gray 83/10/13 Massachusetts, Commonwealth of 22pp
20809 115 24X Fiche 50-443, 83/10/13, 8310180165
- 8310180329 Contentions on State of NH evacuation time study, Certificate of Svc encl
CURRAN, D, JORDAN, W S New England Coalition on Nuclear Pollution CURRAN, D Harmon & Weiss 83/10/13 Atomic Safety and Licensing Board Panel 10pp
20801 134 24X Fiche 50-443, 83/10/13, 8310180329
- 8310200267 Answer supporting JF Doherty 831004 request for leave to amend petition to intervene Petition for leave to intervene, as amended, should be denied Certificate of Svc encl
DIGNAN, T O, QAD, R K Public Service Co of New Hampshire DIGNAN, T O Ropes & Gray 83/10/17 Atomic Safety and Licensing Board Panel 4pp
20830 047 24X Fiche 50-443, 83/10/17, 8310200267
- 8310200277 Response to New England Coalition on Nuclear Pollution 831005 objection to improper ASLB conduct, response to applicant position as to scheduling of emergency planning issues & request for hearing Certificate of Svc encl
DIGNAN, T O, QAD, R K Public Service Co of New Hampshire DIGNAN, T O Ropes & Gray 83/10/17 Atomic Safety and Licensing Board Panel 7pp
20829 311 24X Fiche 50-443, 83/10/17, 8310200277

DOCKETED ITEMS

327

8310250319 Response opposing Seacoast Anti-Pollution League 830926 motion to dismiss application for Seabrook Unit 2 Subj not properly before ASLB but NRR Certificate of Svc encl LESSY, R P , PATTERSON, W F Hearing Branch 3 83/10/17 Atomic Fiche 50-443, 83/10/17, 8310250319

8310260262 Inquires if ASLB issued order re author 830906 petition for leave to intervene & 831004 request for leave to amend petition for leave to intervene Related correspondence DOHERTY, J F Doherty, J F 83/10/20 HOYT, H , HARBOUR, J LUEBKE, E A Atomic Safety and Licensing Board Panel 1p 20911 328 24X Fiche 50-443, 83/10/20, 8310260262

8310250044 Order denying Seacoast Anti-Pollution League 831007 motion to stay further ASLB rulings pending review & appeal of motion for disqualification of Judge Hoyt Grounds for stay insufficient Delay would disrupt proceeding HOYT, H F Atomic Safety and Licensing Board Panel 83/10/21 Seacoast Anti-Pollution League 2pp 20894 195 24X Fiche 50-443, 83/10/21, 8310250044

8310250056 Motion to compel answers to Atty General Bellotti interrogatories & requests for documents to applicants on emergency planning for State of NH Subj matter of witness testimony not described Certificate of Svc encl SNEIDER, C B Massachusetts, Commonwealth of 83/10/21 Atomic Safety and Licensing Board Panel 12pp 20896 086 24X Fiche 50-443, 83/10/21, 8310250056

8310260254 Answer opposing Seacoast Anti-Pollution League (SAPL) 831007 motion to stay further ASLB rulings pending review & appeal of SAPL motion for disqualification Motion frivolous, absurd & allows judge-shopping Certificate of Svc encl DIGMAN, T G , GAD, R K Public Service Co of New Hampshire DIGMAN, T G Ropes & Gray 83/10/24 Atomic Safety and Licensing Board Panel 5pp 20912 124 24X Fiche 50-443, 83/10/24, 8310260254

--8310260261 Answers to 831005 interrogatories & requests for documents on emergency planning Certificate of Svc encl JOHNSON, W P , DIGMAN, T G , GAD, R K Public Service Co of New Hampshire 83/10/24 Seacoast Anti-Pollution League 11pp 20912 129 24X Fiche 50-443, 83/10/24, 8310260254

--8310260266 Answer to 831005 first set of interrogatories on State of NH radiological emergency response plan Certificate of Svc encl JOHNSON, W P , DIGMAN, T G , GAD, R K Public Service Co of New Hampshire 83/10/24 New England Coalition on Nuclear Pollution 9pp 20912 140 24X Fiche 50-443, 83/10/24, 8310260254

--8310260272 Answer opposing Seacoast Anti-Pollution League (SAPL) 831007 motion for disqualification of Judge Hoyt SAPL spoiling for fight, disrespectful & contemptuous of ASLB & guilty of judge-baiting Certificate of Svc encl DIGMAN, T G , GAD, R K Public Service Co of New Hampshire, DIGMAN, T G Ropes & Gray 83/10/24 Atomic Safety and Licensing Board Panel 39pp 20912 149 24X Fiche 50-443, 83/10/24, 8310260254

8310270218 Order extending time until 831101 for Commission to act to review ALAB-737 CHILK, S J Office of the Secretary of the Commission 83/10/25 Commissioners 1p 20924 040 24X Fiche 50-443, 83/10/25, 8310270218

8310280109 Order granting Atty General Bellotti 831012 motion for leave to file response to NRC 831006 ltr & NRC 831024 motion for leave to file supplemental response to proposed contention re offsite emergency planning HOYT, H F Atomic Safety and Licensing Board Panel 83/10/26 Massachusetts, Commonwealth of 2pp 20929 215 24X Fiche 50-443, 83/10/26, 8310280109

8310310202 Proposed findings of fact & conclusions of law on Contentions I B 2, III 1, III 3 & 21 Certificate of Svc encl CURRAN, D , JORDAN, W S New England Coalition on Nuclear Pollution CURRAN, D Harmon & Weiss, 83/10/27 24pp 20928 332, 24X Fiche 50-443, 83/10/27, 8310310202

H General correspondence

8310050508 Requests assistance in obtaining financial repts & other info from Yankee Atomic Electric Co by being included on svc list CHICHESTER, G Rye, NH CHICHESTER, G Rye Nuclear Intervention Committee, 83/09/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20634 016 24X Fiche 50-443, 83/09/07, 8310050508

I Financial information

8310260187 Forwards Amend 51 to application for OL transferring 0 41259% ownership share from Vermont Electric Cooperative, Inc to Vermont Electric Generation & Transmission Cooperative, Inc Certificate of Svc encl RITSHER, J A Ropes & Gray 83/10/17 Division of Licensing, 1p 20912 252 24X Fiche 50-443, 83/10/17, 8310260187

--8310260208 Info furnished per 10CFR50 33 of Commission rules & regulations as part of request for partial transfer of ownership of CP Financial statements encl GALLAGHER, J W Vermont Electric Cooperative, Inc 83/09/30 24pp 20912 259 24X Fiche 50-443, 83/10/17, 8310260187

G Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310190133 Forwards IE Insp Rept 50-443/83-12 on 830808-12 & notice of violation MARTIN, T T Division of Engineering & Technical Programs 83/10/05 HARRISON, R J Public Service Co of New Hampshire 2pp 20820 276 24X Fiche 50-443, 83/10/05, 8310190133

--8310190136 Notice of violation from insp on 830808-12 * Region 1, Office of Director 83/10/05 1p 20820 278 24X Fiche 50-443, 83/10/05, 8310190133

--8310190142 IE Insp Rept 50-443/83-12 on 830808-12. Noncompliance noted ultrasonic exam for acceptance of safety-related components (fillet welds) performed w/o qualified ultrasonic test procedure MCBREARTY, R A , NARROW, L , GRAY, E H Region 1, Office of Director 83/09/28 8pp 20820 279, 24X Fiche 50-443, 83/10/05, 8310190133

8310190172 Forwards IE Insp Repts 50-443/83-14 & 50-444/83-11 on 830815-19 & notice of violation MARTIN, T T Division of Engineering & Technical Programs 83/10/05, HARRISON, R J Public Service Co of New Hampshire 2pp 20821 080 24X Fiche 50-443, 83/10/05, 8310190172

--8310190175 Notice of violation from insp on 830815-19 * Region 1, Office of Director 83/10/05 1p 20821 082 24X Fiche: 50-443, 83/10/05, 8310190172

--8310190180 IE Insp Repts 50-443/83-14 & 50-444/83-11 on 830815-19, Noncompliance noted failure to properly inspect electrical terminations of small gauge conductors RICHARDS, B., ANDERSON, C. Region 1, Office of Director, 83/10/05, 8pp 20821 083, 24X Fiche: 50-443, 83/10/05, 8310190172

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp, 20827, 213 24X Fiche: 50-000, 83/10/07, 8308300378.

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp, 20882 026, 24X Fiche: 50-000, 83/10/07, 8308300752.

DOCKETED ITEMS

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310270445 Forwards IE Investigation Repts 50-443/1-83-001 & 50-444/1-83-001 on 821228, 830110-14 & 18-21 & 50-443/1-83-007 & 50-444/1-83-007 on 830411-0603 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/10/13
HARRISON, R J Public Service Co of New Hampshire 2pp 20922 016 24X Fiche 50-443, 83/10/13, 8310270445

--8310270462 IE Investigation Repts 50-443/1-83-001 & 50-444/1-83-001 on 821228, 830110-14 & 18-21 No noncompliance noted Major areas investigated allegations re intimidation & harassment of GC inspector & hanger weld deficiencies
SHEPHERD, R E, CHRISTOPHER, R, WARD, W Office of Investigation 83/08/02 3pp. 20922 018 24X Fiche 50-443, 83/10/13, 8310270445

--8310270474 IE Investigation Repts 50-443/1-83-007 & 50-444/1-83-007 on 830411-0603 No noncompliance noted Major areas investigated alleged employee discrimination by licensee contractor Perini Power Constructors, Inc
SHEPHERD, R E, CHRISTOPHER, R, WARD, W Office of Investigation. 83/08/19 4pp 20922 021 24X Fiche 50-443, 83/10/13, 8310270445

8310210243 Ack receipt of 830907 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-443/83-08
MARTIN, T T Division of Engineering & Technical Programs 83/10/17
HARRISON, R J Public Service Co of New Hampshire 1p 20852 012 24X Fiche 50-443, 83/10/17, 8310210243

--8310210250 Responds to NRC 830809 ltr re violations noted in IE Insp Rept 50-443/83-08 Corrective actions engineers reinductrated re in-place storage requirement & need for preventative maint Rules on cleanliness established
DEVINCENTIS, J Yankee Atomic Electric Co, DEVINCENTIS, J Public Service Co of New Hampshire 83/09/07 MARTIN, T T Division of Engineering & Technical Programs 4pp 20852 013 24X Fiche 50-443, 83/10/17, 8310210243

B Reportable occurrences, LERs & related correspondence

8310070163 Part 21 rept re potential defects in molded case of 100-amp frame, multi-pole E & HE series circuit breakers
Initially reported on 830902
ERHARDT, J V Gould, Inc 83/09/26 MURLEY, Y E Region 1, Office of Director. 10pp 20659 095 24X Fiche 50-000, 83/09/26, 8310070163

8310060343 Part 21 rept re Gould unitized starters supplied as spare parts Initially reported on 830923 Final rept expected 831130
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/09/28 Region 1, Office of Director 4pp 20646 135 24X Fiche 50-443, 83/09/28, 8310060343

8310140082 PNO-I-83-105 on 831007, seismic event occurred in northeastern US w/magnitude of 5.2 on Richter scale in NY & 4.0 in NH No damage to equipment identified
GALL, R M Region 1, Office of Director 83/10/07 1p 20766 116 24X Fiche 50-000, 83/10/07, 8310140082

U. Congressional/Executive Correspondence

8310060363 Forwards ASLB 830927 ltr to C Nord re accidental oversight in skipping C Nord at recent limited appearance session. ASLB allowed Nord to submit written statement
LEWIS, D R Atomic Safety and Licensing Board Panel 83/10/04
HILDT, B Massachusetts, Commonwealth of 1p 20646 072 24X Fiche 50-443, 83/10/04, 8310060363

--8310060364 Requests assistance in determining reason for ASLB not allowing constituent C Nord to testify at 830831 hearing
HILDT, B Massachusetts, Commonwealth of 83/09/27 LEWIS, D R Atomic Safety and Licensing Board Panel 1p. 20646 074 24X Fiche 50-443, 83/10/04, 8310060363

8310280088 Requests public notification of hearings, that hearings be held in State of MA or near site & that C Nord be scheduled to present public oral comments
COSTELLO, N J Massachusetts, Commonwealth of 83/10/04 HOYT, H LUEBKE, E A, HARBOUR, J Atomic Safety and Licensing Board Panel 4pp 20935 081 24X Fiche 50-443, 83/10/04, 8310280088

DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8310070232 Notification of Significant Licensee Meeting 83-86 on 831001, at site to discuss open electrical items, issues & comments
GERNE, A Region 1, Office of Director 83/09/28 Region 1, Office of Director 1p 20664 362 24X Fiche 50-443, 83/09/28, 8310070232

8308300355 Board Notification 83-66A advises that position re rod drop issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycle
EISENHUT, D O Division of Licensing 83/09/29 PALLADINO, N J Commissioners 10pp 20632 106 24X Fiche 50-000, 83/09/24, 8308300355

8308300763 Board Notification 83-151 provides info re desirability of current ECCB actuation logic for Westinghouse plants, in light of recent info concerning steam generator tube rupture procedure for Borssele Nuclear Power Station
EISENHUT, D O Division of Licensing 83/10/04 PALLADINO, N J Commissioners 2pp 20698 033 24X Fiche 50-000, 83/10/04, 8308300763

8310120263 Forwards resolution & press release re reduced expenditure level & const activity on Unit 2 Reduced expenditure level will be continued until fuel loading for Unit 1 completed, unless Unit 2 canceled
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/10/05 KNIGHTON, Q W Licensing Branch 3 5pp 20693 073 24X Fiche 50-443, 83/10/05, 8310120263

8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves
EISENHUT, D O Division of Licensing 83/10/04 PALLADINO, N J Commissioners 31pp 20818 001 24X Fiche 50-000, 83/10/04, 8308300771

8310260187 Forwards Amend 51 to application for OL transferring 0.4125% ownership share from Vermont Electric Cooperative, Inc to Vermont Electric Generation & Transmission Cooperative, Inc Certificate of Svc encl
RITTSER, J A Ropes & Gray 83/10/17 Division of Licensing 1p 20912 252 24X Fiche 50-443, 83/10/17, 8310260187

--8310260201 Amend 51 to application for OL transferring 0.4125% ownership share from Vermont Electric Cooperative, Inc to Vermont Electric Generation & Transmission Cooperative, Inc
JOHNSON, V P Public Service Co of New Hampshire 83/10/03 Division of Licensing 4pp 20912 253 24X Fiche 50-443, 83/10/17, 8310260187

--8310260208 Info furnished per 10CFR50.33 of Commission rules & regulations as part of request for partial transfer of ownership of CP Financial statements encl
GALLAGHER, J W Vermont Electric Cooperative, Inc 83/09/30 24pp 20912 259 24X Fiche 50-443, 83/10/17, 8310260187

F Security, medical, emergency & fire protection plans

8310170394 Forwards draft App D to radiological emergency response plans for Towns of Newfields, New Castle, North Hampton & Brentwood, NH, entitled "Cross-Reference to NUREG-0654"
LESSY, R P Hearing Branch 3 83/10/12 HOYT, H Atomic Safety and Licensing Board Panel 26pp 20785 045 24X Fiche 50-443, 83/10/12, 8310170394

G Adjudicatory correspondence

8310030355 Motion to dismiss OL application for Unit 2 Further const efforts deferred until Unit 1 complete Jul 1987 estimated const completion date for Unit 2 abandoned w/Certificate of Svc.
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/09/26 Atomic Safety and Licensing Board Panel 7pp. 20593 063 24X Fiche 50-443, 83/09/26, 8310030355

DOCKETED ITEMS

8310030397 Comments on scheduling of offsite emergency planning
contentions All offsite planning contentions should be
litigated together Issues similar & some witnesses will
testify on both plans Certificate of Svc encl
BISBEE, O D New Hampshire, State of 83/09/26 7pp 20992 34X
24X Fiche 50-443, 83/09/26, 8310030397

8310040533 Objects to conduct at 830831 hearing re continued
participation of Town of Rye, NH representative G Chichester
Earlier telcon did not advise town that Chichester dismissed
from further participation
NADEAU, J P, YOUNG, M L, HOLWAY, F I Rye, NH 83/09/26 HOYT, H
Atomic Safety and Licensing Board Panel 2pp 20623 279 24X
Fiche 50-443, 83/09/26, 8310040533

8310050366 Response to State of MA Atty General 830909 contention re
offsite emergency planning for Towns of Seabrook, Hampton,
North Hampton & Rye Present wording of contention w/n
regulatory basis Certificate of Svc encl
PATTERSON, W F, LESSY, R P Hearing Branch 3 83/09/26 Atomic
Safety and Licensing Board Panel 9pp 20630 345 24X
Fiche 50-443, 83/09/26, 8310050366

8310050472 Response to Town of Hampton Falls, NH 830906 offsite
emergency planning contention Contention not opposed
LESSY, R P, PATTERSON, W F Hearing Branch 3 83/09/26 Atomic
Safety and Licensing Board Panel 3pp 20633 190 24X
Fiche 50-443, 83/09/26, 8310050472

--8310050474 Response to Commonwealth of MA 830909 motion for
clarification of ASLB 830830 order admitting contentions &
motion for reconsideration of ASLB 830630 order on
evacuation time estimates Motions not opposed
LESSY, R P, PATTERSON, W F Hearing Branch 3 83/09/26 Atomic
Safety and Licensing Board Panel 3pp 20633 193 24X
Fiche 50-443, 83/09/26, 8310050472

--8310050477 Response opposing JF Doherty 830906 petition to intervene No
good cause shown for petition late by 22 months Other
factors for untimely intervention not met
PATTERSON, W F, LESSY, R P Hearing Branch 3 83/09/26 Atomic
Safety and Licensing Board Panel 7pp 20633 196 24X
Fiche 50-443, 83/09/26, 8310050472

--8310050480 Response to Hampton Beach Area Chamber of Commerce 830908
contentions on offsite emergency planning for Town of
Hampton, NH Objects to admission of Contentions I, II, III &
IV(a,b,c,f & g) Certificate of Svc encl
PATTERSON, W F, LESSY, R P Hearing Branch 3 83/09/26 Atomic
Safety and Licensing Board Panel 13pp. 20633 203 24X
Fiche 50-443, 83/09/26, 8310050472

8310040510 Position on schedule of offsite emergency planning issues
Hearings on New Hampshire radiological emergency response
plans & local plans should be postponed until Mar 1984
Certificate of Svc encl
CASSIDY, B P Federal Emergency Management Agency 83/09/27 29pp
20625 214 24X Fiche 50-443, 83/09/27, 8310040510

8310050551 Response to Town of Kensington contentions re emergency
planning Town of Kensington resolution of concerns &
inadequacies expected prior to litigation of Contentions
I(a-d) & II Certificate of Svc encl
PATTERSON, W F, LESSY, R P Hearing Branch 3 83/09/27 Atomic
Safety and Licensing Board Panel 8pp 20629 346. 24X
Fiche 50-443, 83/09/27, 8310050551

8310040256 Interrogatories & requests for documents re emergency
planning for State of NH
BELLOTTI, F X Massachusetts, Commonwealth of 83/09/29 Federal
Emergency Management Agency 12pp 20613 009 24X
Fiche 50-443, 83/09/29, 8310040256

--8310040262 Interrogatories & requests for documents re emergency
planning for State of NH
BELLOTTI, F X Massachusetts, Commonwealth of. 83/09/29 New
Hampshire, State of 12pp 20613 017. 24X Fiche 50-443, 83/09/29,
8310040256

--8310040272 Notice of 831017 deposition in Boston, MA of all util, NRC,
State of NH or FEMA witnesses re admitted contentions on
draft New Hampshire radiological emergency response plans
SHOTWELL, J A Massachusetts, Commonwealth of 83/09/29 2pp.
20613 029 24X Fiche 50-443, 83/09/29, 8310040256.

--8310040277 Interrogatories & requests for documents re emergency
planning for State of NH. Certificate of Svc encl
BELLOTTI, F X Massachusetts, Commonwealth of 83/09/29 Public
Service Co. of New Hampshire. 11pp 20613 031 24X
Fiche 50-443, 83/09/29, 8310040256

8310050373 Response to Seacoast Anti-Pollution League 830909
supplemental petition for leave to intervene & contentions
re offsite emergency planning Objects to Contentions 11, 14,
15, 17, 18, 19, 20, 22 & 23 Certificate of Svc encl
PATTERSON, W F, LESSY, R P Hearing Branch 3 83/09/29 Atomic
Safety and Licensing Board Panel 25pp 20632 268 24X
Fiche 50-443, 83/09/29, 8310050373

--8310050381 Response to New England Coalition on Nuclear Pollution
830909 contentions on State of NH offsite radiological
emergency response planning Objects to listed contentions
Certificate of Svc encl
PATTERSON, W F, LESSY, R P Hearing Branch 3 83/09/29 Atomic
Safety and Licensing Board Panel 21pp 20632 293 24X
Fiche 50-443, 83/09/29, 8310050373

--8310050388 Response to Town of Seabrook, NH 830909 contentions re
offsite emergency planning Objects to Contentions 1, 5, 6, 7,
12 & 10 Certificate of Svc encl
PERLIS, R O, PATTERSON, W F, LESSY, R P Hearing Branch 3
83/09/29 Atomic Safety and Licensing Board Panel 14pp
20632 314 24X Fiche 50-443, 83/09/29, 8310050373

8310050398 Opposes presently worded proposed contention on local
emergency planning Std of providing complete protection
under all circumstances not dictated by law
PATTERSON, W F Hearing Branch 3 83/10/03. SHOTWELL, J
Massachusetts, Commonwealth of. 2pp. 20629: 337 24X
Fiche 50-443, 83/10/03, 8310050398

8310110152 Motion for leave to file response to NRC & applicant answers
to Atty General FX Bellotti motion for reconsideration of
ASLB ruling on evacuation time estimate preparation time
Certificate of Svc encl
SHOTWELL, J A Massachusetts, Commonwealth of 83/10/03 Atomic
Safety and Licensing Board Panel 3pp 20666 287 24X
Fiche 50-443, 83/10/03, 8310110152

8310120178 Requests to be advised of steps necessary to appeal ASLB
dismissal of G Chichester from proceeding & advises that
contentions will be resubmitted
NADEAU, J P, YOUNG, M L, HOLWAY, F I Rye, NH 83/10/03 HOYT, H F
Atomic Safety and Licensing Board Panel 3pp 20695 292 24X
Fiche 50-443, 83/10/03, 8310120178

8310110202 Amended petition for leave to intervene Svc of Process encl
DOHERTY, J F Doherty, J F 83/10/04. Atomic Safety and Licensing
Board Panel 7pp 20665 024 24X Fiche 50-443, 83/10/04, 8310110202

8310110316 Requests leave to amend petition for leave to intervene
Amended petition based on applicant & NRC urging for
uncontested expansion of NRC rulings & misrepresentation
of petitioner arguments in one case
DOHERTY, J F Doherty, J F 83/10/04 Atomic Safety and Licensing
Board Panel 1p 20665 006 24X Fiche 50-443, 83/10/04, 8310110316

8310110049 Order extending time until 831013 for Commission to act to
review ALAB-737
CHILK, B J Office of the Secretary of the Commission 83/10/05.
Commissioners 1p 20668 272 24X Fiche 50-443, 83/10/05,
8310110049

8310110083 Forwards proposed findings of fact & conclusions of law
QAD, R K Ropes & Gray QAD, R K Public Service Co of New Hampshire
83/10/05 Office of the Secretary of the Commission.
1p 20668. 197 24X Fiche 50-443, 83/10/05, 8310110083

--8310110092 Proposed findings of fact & conclusions of law Certificate
of Svc encl
DIGNAN, T O, QAD, R K Public Service Co of New Hampshire
DIGNAN, T O Ropes & Gray 83/10/05 54pp. 20668 158 24X
Fiche 50-443, 83/10/05, 8310110083

8310110158 First set of interrogatories on State of NH radiological
emergency response plan
CURRAN, D, JORDAN, W B New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss. 83/10/05. Federal Emergency Management
Agency 4pp 20666 241 24X Fiche 50-443, 83/10/05, 8310110158

--8310110165 First set of interrogatories on State of NH radiological
emergency response plan.
CURRAN, D, JORDAN, W B New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/10/05. Public Service Co of Na
Hampshire 3pp. 20666 245 24X Fiche 50-443, 83/10/05, 8310110158

--8310110170 Objection to improper ASLB conduct, response to util posit
as to scheduling of emergency planning issues & request for
hearing on licensing schedule
CURRAN, D, JORDAN, W B New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/10/05 10pp. 20666 248. 24X
Fiche 50-443, 83/10/05, 8310110158

DOCKETED ITEMS

- B310110175 First set of interrogatories on State of NH radiological emergency response plan Certificate of Svc encl
CURRAN, D. JORDAN, W S New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/10/05 New Hampshire, State of
15pp 20666 238 24X Fiche 50-443, 83/10/05, B310110158
- B310110227 Interrogatories & requests for documents on emergency planning for State of NH Related correspondence
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus,
Shea & Meyer 83/10/05 Public Service Co of New Hampshire
7pp 20665 316 24X Fiche 50-443, 83/10/05, B310110227
- B310120133 Answer opposing Seacoast Anti-Pollution League 830926 motion to dismiss OL application for Unit 2 Wrong regulation cited
NRR, not ASLB, issues OLs League argument previously rejected
by ASLB Certificate of Svc encl
DIGNAN, T O, QAD, R K Public Service Co of New Hampshire
DIGNAN, T O Ropes & Gray 83/10/06 Atomic Safety and Licensing Board Panel 7pp 20695 270 24X Fiche 50-443, 83/10/06, B310120133
- B310120428 Response opposing Town of Hampton 830919 contentions on town radiological emergency response plan No justification offered for late filing Towns should not be allowed to attack own plans Certificate of Svc encl
DIGNAN, T O, QAD, R K Public Service Co of New Hampshire.
DIGNAN, T O Ropes & Gray 83/10/06 Atomic Safety and Licensing Board Panel 4pp 20698 326 24X Fiche 50-443, 83/10/06, B310120428
- B310130255 Discusses rev to NRC 830926 response to State of MA contentions on offsite emergency planning for Towns of Seabrook, Hampton, North Hampton & Rye Rev limited to local plans & provisions re Town sheltering responsibilities
PATTERSON, W F Hearing Branch 3 83/10/06 SHOTWELL, J A Massachusetts, Commonwealth of 3pp 20723 234 24X Fiche 50-443, 83/10/06, B310130255
- B310140015 Lists GA procedures approved for implementation & available for insp at station, Svc list encl
QAD, R K Ropes & Gray 83/10/06 CURRAN, D Harmon & Weiss 5pp 20767 041 24X Fiche 50-443, 83/10/06, B310140015
- B310140021 Response to applicant 830921 motion for denial of Towns of Kensington & South Hampton contentions re emergency planning Plans formulated by private consulting firm & not endorsed by town's Certificate of Svc encl
QAD, T B Kensington, NH VERDE, A W South Hampton, NH
83/10/06 Atomic Safety and Licensing Board Panel 7pp 20767 032 24X Fiche 50-443, 83/10/06, B310140021
- B310120107 Motion for disqualification of Judge Hoyt Hostility toward intervenor & state counsel, as well as municipal representatives apparent & ever-increasing Appearance of partiality established
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus,
Shea & Meyer 83/10/07 Atomic Safety and Licensing Board Panel 68pp 20695 178 24X Fiche 50-443, 83/10/07, B310120107
- B310120111 Reply opposing applicant objection to Seacoast Anti-Pollution League supplemental petition for leave to intervene Applicant objections w/o merit Contentions should be admitted
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus,
Shea & Meyer 83/10/07 Atomic Safety and Licensing Board Panel 7pp 20695 247 24X Fiche 50-443, 83/10/07, B310120107
- B310120115 Affidavit in support of B31007 motion for recusal of Judge Hoyt
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus,
Shea & Meyer 83/10/07 2pp 20695 254 24X Fiche 50-443, 83/10/07, B310120107.
- B310120122 Answer supporting New England Coalition on Nuclear Pollution (NECNP) reply to applicant & NRC responses to NECNP contentions on State of NH radiological emergency response plan
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus,
Shea & Meyer 83/10/07 Atomic Safety and Licensing Board Panel 1p 20695 256 24X Fiche 50-443, 83/10/07, B310120107
- B310120126 Errata to 830926 motion to dismiss OL application for Unit 2 Cite on Page 1 should read 10CFR57(a)(1)
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus,
Shea & Meyer 83/10/07 Atomic Safety and Licensing Board Panel 1p 20695 257 24X Fiche 50-443, 83/10/07, B310120107.
- B310120135 Motion to stay further ASLB rulings pending review & appeal of Seacoast Anti-Pollution League motion for recusal of Judge Hoyt
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus,
Shea & Meyer 83/10/07 Atomic Safety and Licensing Board Panel 1p 20695 258 24X Fiche 50-443, 83/10/07, B310120107.
- B310120141 Reply to NRC response to Seacoast Anti-Pollution League supplemental petition for leave to intervene concerning emergency planning contentions Certificate of Svc encl
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus,
Shea & Meyer 83/10/07 Atomic Safety and Licensing Board Panel 7pp 20695 259 24X Fiche 50-443, 83/10/07, B310120107
- B310120147 Motion for summary disposition of Commonwealth of MA Contentions 1, 11, 111, IV A & IV G, Seacoast Anti-Pollution League Contention 5 & New England Coalition on Nuclear Pollution Contentions 3, 4, 5, 7, 12 & 13
SHOTWELL, J A Massachusetts, Commonwealth of 83/10/07 Atomic Safety and Licensing Board Panel 46pp 20696 042 24X Fiche 50-443, 83/10/07, B310120147
- B310120151 Answer to NRC & util 830926 & 20, respectively, responses to Commonwealth of MA 830909 emergency planning contentions Evacuation within times estimated will subj beachgoers to fatal radiation doses Certificate of Svc encl
SHOTWELL, J A Massachusetts, Commonwealth of 83/10/07 Atomic Safety and Licensing Board Panel 10pp 20696 088 24X Fiche 50-443, 83/10/07, B310120147
- B310130046 Response opposing Town of Rye contentions re emergency planning for State of NH & Town of Rye Contention 1 vague & raises issues outside hearing scope Contention 2 already litigated Certificate of Svc encl
PATTERSON, W F, LESSY, R P Hearing Branch 3 83/10/11 Atomic Safety and Licensing Board Panel 10pp 20725 065 24X Fiche 50-443, 83/10/11, B310130046
- B310140191 Reply to util & NRC responses to New England Coalition on Nuclear Pollution contention on State of NH local emergency response plans Coalition has specifically alleged unreliability of info in plans W/Certificate of Svc
CURRAN, D JORDAN, W S New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/10/11 Atomic Safety and Licensing Board Panel 16pp 20762 315 24X Fiche 50-443, 83/10/11, B310140191
- B310170394 Forwards draft App D to radiological emergency response plans for Towns of Newfields, New Castle, North Hampton & Brentwood, NH, entitled "Cross-Reference to NUREG-0654"
LESSY, R P Hearing Branch 3 83/10/12 HOYT, H, LUEBKE, E A, HARBOR, J Atomic Safety and Licensing Board Panel 26pp 20785 045 24X Fiche 50-443, 83/10/12, B310170394
- B310180150 Forwards applicant B31012 response to FX Bellotti motion for leave to file responses to NRC & util answers to State of MA motion for reconsideration of ASLB ruling on evacuation time estimates preparation time
QAD, R K Ropes & Gray QAD, R K Public Service Co of New Hampshire 83/10/12 Office of the Secretary of the Commission 1p 20809 154 24X Fiche 50-443, 83/10/12, B310180150
- B310180153 Response to FX Bellotti B31003 motion for leave to file response to NRC & util answers to motion for reconsideration of ASLB ruling on evacuation time estimates preparation time Certificate of Svc encl
DIGNAN, T O, QAD, R K Public Service Co of New Hampshire
DIGNAN, T O Ropes & Gray 83/10/12 Atomic Safety and Licensing Board Panel 14pp 20809 155 24X Fiche 50-443, 83/10/12, B310180150
- B310180368 Notice of continuance of depositions of witnesses on State of NH radiological emergency response plan scheduled for wk of B31017
SHOTWELL, J A Massachusetts, Commonwealth of 83/10/12 2pp 20803 175 24X Fiche 50-443, 83/10/12, B310180368
- B310180373 Motion for leave to file response to NRC B31006 ltr which constituted supplemental answer to Commonwealth of MA contention on emergency planning Contention is not untimely Certificate of Svc encl
SHOTWELL, J A Massachusetts, Commonwealth of 83/10/12 Atomic Safety and Licensing Board Panel 5pp 20803 177 24X Fiche 50-443, 83/10/12, B310180368
- B310170424 Order extending time until B31025 for Commission to act to review ALAB-737
CHILK, S J Office of the Secretary of the Commission 83/10/13 Commissioners 1p 20784 037 24X Fiche 50-443, 83/10/13, B310170424
- B310180165 Forwards answer to Atty General Bellotti interrogatories & requests for documents on emergency planning for State of NH
QAD, R K Ropes & Gray QAD, R K Public Service Co of New Hampshire 83/10/13 Docketing & Services Branch 1p 20809 114 24X Fiche 50-443, 83/10/13, B310180165

DOCKETED ITEMS

--B310180170 Answers to interrogatories & requests for documents on emergency planning for State of NH Certificate of Svc encl
DIGNAN, T G , QAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/10/13 Massachusetts,
Commonwealth of 22pp 20809 115 24X Fiche 50-443, 83/10/13,
8310180165

B310180329 Contentions on State of NH evacuation time study Certificate of Svc encl
CURRAN, D , JORDAN, W S New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/10/13 Atomic Safety and Licensing
Board Panel 10pp 20801 154 24X Fiche 50-443, 83/10/13,
8310180329

B310200267 Answer supporting JF Doherty B31004 request for leave to amend petition to intervene Petition for leave to intervene, as amended, should be denied Certificate of Svc encl.
DIGNAN, T G , QAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/10/17 Atomic Safety and Licensing
Board Panel 4pp 20830 047 24X Fiche 50-443, 83/10/17, 8310200267

B310200277 Response to New England Coalition on Nuclear Pollution B31005 objection to improper ASLB conduct, response to applicant position as to scheduling of emergency planning issues & request for hearing Certificate of Svc encl
DIGNAN, T G , QAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray, 83/10/17 Atomic Safety and Licensing
Board Panel 7pp 20829 311 24X Fiche 50-443, 83/10/17, 8310200277

B310250319 Response opposing Seacoast Anti-Pollution League B30926 motion to dismiss application for Seabrook Unit 2 Subj not properly before ASLB but NRR Certificate of Svc encl
LESSY, R P , PATTERSON, W F Hearing Branch 3 83/10/17 Atomic
Safety and Licensing Board Panel 6pp 20898 003 24X
Fiche 50-443, 83/10/17, 8310250319

B310260262 Inquires if ASLB issued order re author B30906 petition for leave to intervene & B31004 request for leave to amend petition for leave to intervene Related correspondence
DOHERTY, J F Doherty, J F 83/10/20 HOYT, H , HARBOUR, J ,
LUEBKE, E A Atomic Safety and Licensing Board Panel 1p
20911 328 24X Fiche 50-443, 83/10/20, 8310260262

B310290044 Order denying Seacoast Anti-Pollution League B31007 motion to stay further ASLB rulings pending review & appeal of motion for disqualification of Judge Hoyt Grounds for stay insufficient Delay would disrupt proceeding.
HOYT, H F Atomic Safety and Licensing Board Panel 83/10/21
Seacoast Anti-Pollution League 2pp 20894 193 24X
Fiche 50-443, 83/10/21, 8310290044

B310250054 Motion to compel answers to Atty General Bellotti interrogatories & requests for documents to applicants on emergency planning for State of NH Subj matter of witness testimony not described Certificate of Svc encl
SNEIDER, C B Massachusetts, Commonwealth of 83/10/21 Atomic
Safety and Licensing Board Panel 12pp 20896 086 24X
Fiche 50-443, 83/10/21, 8310250054

B310260254 Answer opposing Seacoast Anti-Pollution League (SAPL) B31007 motion to stay further ASLB rulings pending review & appeal of SAPL motion for disqualification Motion frivolous, absurd & allows judge-shopping Certificate of Svc encl
DIGNAN, T G , QAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/10/24 Atomic Safety and Licensing
Board Panel 5pp 20912 124 24X Fiche 50-443, 83/10/24, 8310260254

--B310260261 Answers to B31005 interrogatories & requests for documents on emergency planning Certificate of Svc encl
JOHNSON, W P , DIGNAN, T G , QAD, R K Public Service Co. of New
Hampshire 83/10/24 Seacoast Anti-Pollution League 11pp,
20912 129 24X Fiche 50-443, 83/10/24, 8310260254

--B310260266 Answer to B31005 first set of interrogatories on State of NH radiological emergency response plan Certificate of Svc encl
JOHNSON, W P , DIGNAN, T G , QAD, R K Public Service Co. of New
Hampshire 83/10/24 New England Coalition on Nuclear
Pollution 9pp 20912 140 24X Fiche 50-443, 83/10/24, 8310260254

--B310260272 Answer opposing Seacoast Anti-Pollution League (SAPL) B31007 motion for disqualification of Judge Hoyt SAPL spelling for fight, disrespectful & contemptuous of ASLB & guilty of judge-baiting Certificate of Svc encl
DIGNAN, T G , QAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/10/24 Atomic Safety and
Licensing Board Panel 37pp 20912 149 24X
Fiche 50-443, 83/10/24, 8310260254

B310270218 Order extending time until 831101 for Commission to act to review ALAD-73/
CHILK, S J Office of the Secretary of the Commission. 83/10/25
Commissioners 1p 20924 040 24X Fiche 50-443, 83/10/25,
8310270218

B310280109 Order granting Atty General Bellotti B31012 motion for leave to file response to NRC B31006 ltr & NRC B31024 motion for leave to file supplemental response to proposed contention re offsite emergency planning
HOYT, H F Atomic Safety and Licensing Board Panel. 83/10/26
Massachusetts, Commonwealth of 2pp 20929 215 24X
Fiche 50-443, 83/10/26, 8310280109

B310310202 Proposed findings of fact & conclusions of law on Contentions I D 2, III 1, III 3 & 21 Certificate of Svc encl,
CURRAN, D , JORDAN, W S New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/10/27. 24pp 20958 332 24X
Fiche 50-443, 83/10/27, 8310310202

H General correspondence

B310050508 Requests assistance in obtaining financial repts & other info from Yankee Atomic Electric Co by being included on svc list
CHICHESTER, O Rye, NH CHICHESTER, O Rye Nuclear Intervention
Committee 83/09/07 DENTON, H R Office of Nuclear Reactor
Regulation, Director 1p 20634 016 24X Fiche: 50-443, 83/09/07,
8310050508.

I Financial information

B310260187 Forwards Amend 51 to application for OL transferring 0 A125% ownership share from Vermont Electric Cooperative, Inc to Vermont Electric Generation & Transmission Cooperative, Inc Certificate of Svc encl
RITSHER, J A Ropes & Gray 83/10/17 Division of Licensing 1p,
20912 252 24X Fiche 50-443, 83/10/17, 8310260187.

--B310260208 Info furnished per 10CFR50 33 of Commission rules & regulations as part of request for partial transfer of ownership of CP Financial statements encl
GALLAGHER, J W Vermont Electric Cooperative, Inc 83/09/30
24pp 20912 239 24X Fiche 50-443, 83/10/17, 8310260187

P Operating license stage documents & correspondence

B308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New
York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340.

Q Inspection reports, IE Bulletins & correspondence

B308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New
York, Inc 116pp, 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

B308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New
York, Inc 118pp, 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

B308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co. of New
York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349.

B310190172 Forwards 1E Insp Repts 50-443/83-14 & 50-444/83-11 on B30815-19 & notice of violation
MARTIN, T T. Division of Engineering & Technical Programs. 83/10/05
HARRISON, R J Public Service Co of New Hampshire 2pp
20821 080 24X Fiche 50-443, 83/10/05, 8310190172.

--B310190180 IE Insp Repts 50-443/83-14 & 50-444/83-11 on B30815-19. Noncompliance noted failure to properly inspect electrical terminations of small gauge conductors.
RICHARDS, S , ANDERSON, C Region 1, Office of Director. 83/10/05
6pp, 20621 083 24X Fiche. 50-443, 83/10/05, 8310190172.

DOCKETED ITEMS

308300378 IE Info Notice 83-65, "Surveillance of Flow in RID Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc 117pp. 21043-075 24X Fiche 50-000, 83/10/11, 8308300759

08300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc 120pp. 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

10270445 Forwards IE Investigation Repts 50-443/1-83-001 & 50-444/1-83-001 on 821228, 830110-14 & 18-21 & 50-443/1-83-007 & 50-444/1-83-007 on 830411-0603 No noncompliance noted
STARGOSTECKI, R. Division of Project & Resident Programs 83/10/13
HARRISON, R. J. Public Service Co. of New Hampshire 2pp 20922 016 24X Fiche: 50-443, 83/10/13, 8310270445

8310270442 IE Investigation Repts 50-443/1-83-001 & 50-444/1-83-001 on 821228, 830110-14 & 18-21 No noncompliance noted. Major areas investigated, allegations re intimidation & harassment of QC inspector & hanger weld deficiencies.
SHEPHERD, R. E., CHRISTOPHER, R., WARD, W. Office of Investigation 83/08/02. 3pp 20922: 018 24X Fiche 50-443, 83/10/13, 8310270445.

8310270474 IE Investigation Repts 50-443/1-83-007 & 50-444/1-83-007 on 830411-0603. No noncompliance noted. Major areas investigated alleged employee discrimination by licensee contractor Perini Power Constructors, Inc.
SHEPHERD, R. E., CHRISTOPHER, R., WARD, W. Office of Investigation 83/08/19 4pp. 20922 021 24X Fiche 50-443, 83/10/13, 8310270445

Reportable occurrences, LERs & related correspondence

0070163 Part 21 rept re potential defects in molded case of 100-amp frame, multi-pole E & HE series circuit breakers initially reported on 830902.
RHARDT, J. V. Gould, Inc 83/09/26 MURLEY, T. E. Region 1, Office of Director. 10pp 20659 095 24X Fiche 50-000, 83/09/26, 8310070163

0060343 Part 21 rept re Gould unitized starters supplied as spare parts initially reported on 830923. Final rept expected 31130
EVINGENTIS, J. Yankee Atomic Electric Co DEVINCENTIS, J. Public Service Co. of New Hampshire 83/09/28. Region 1, Office of Director 4pp. 20646 135 24X Fiche 50-443, 83/09/28, 8310060343

0140082 PND-I-83-105 on 831007, seismic event occurred in northeastern US w/magnitude of 5.2 on Richter scale in NY 4.0 in NH. No damage to equipment identified.
ALLO, R. M. Region 1, Office of Director 83/10/07 1p. 20766 116 24X Fiche: 50-000, 83/10/07, 8310140082

Congressional/Executive Correspondence

0060363 Forwards ABLB 830927 ltr to C Nord re accidental oversight in skipping C Nord at recent limited appearance session ABLB allowed Nord to submit written statement
LEWIS, D. R. Atomic Safety and Licensing Board Panel 83/10/04
LEWIS, D. R. Massachusetts, Commonwealth of. 1p. 20646: 072. 24X Fiche: 50-443, 83/10/04, 8310060363

310060364 Requests assistance in determining reason for ASLB not allowing constituent C Nord to testify at 830831 hearing.
LEWIS, D. R. Massachusetts, Commonwealth of. 83/09/27. LEWIS, D. R. Atomic Safety and Licensing Board Panel. 1p. 20646: 074. 24X Fiche: 50-443, 83/10/04, 8310060363.

1280088 Requests public notification of hearings, that hearings be held in State of MA or near site & that C Nord be scheduled present public oral comments.
STELLLO, N. J. Massachusetts, Commonwealth of. 83/10/04. HOYT, H., EBKE, E. A., HARRISON, J. Atomic Safety and Licensing Board Panel p. 20935: 081. 24X Fiche 50-443, 83/10/04, 8310280088.

DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA , UNIT 1

A Application/construction stage documents & correspondence

8310110007 Responds to FOIA request for SECY-82-279, SECY-82-330 & SECY-83-120 Forwards documents Documents also available in PDR
FELTON, J. M. Division of Rules and Records 83/07/15 PEDRO, J. NUS Corp 1p 20712 280 24X Fiche 50-445, 83/07/15, 8310110007

--8310110022 Recommends issuance of encl proposed order directing ASLB to resume hearings as soon as possible on issue not involving informant identities
PLAINE, H. H. Office of the General Counsel SECY-83-120 83/04/01 4pp 20712 319 24X Fiche 50-445, 83/07/15, 8310110007

8310180582 FOIA request for VS Noonan 830426 memo to BJ Youngblood re addl info needed by Equipment Qualification Branch to complete review of environ qualification of mechanical equipment
PEDRO, J. NUS Corp 83/08/17 Division of Rules and Records 1p 20817 329 24X Fiche 50-445, 83/08/17, 8310180582

8310260279 Forwards nonproprietary & proprietary versions of "Counterflow Preheat Steam Generator Tube Expansion Rept" & "Counterflow Preheat Steam Generator Tube Vibration Summary Rept." Proprietary version withheld (ref 10CFR2 790)
RAHE, E. P. Westinghouse Electric Corp 83/08/26 EISENHUT, D. G. Division of Licensing. 2pp 20909 354 24X Fiche 50-445, 83/08/26, 8310260279

--8310260281 Application for withholding proprietary versions of "Counterflow Preheat Steam Generator Tube Expansion Rept" & "Counterflow Preheat Steam Generator Tube Vibration Summary Rept." per 10CFR2 790 Affidavit encl
MIESEMANN, R. A. Westinghouse Electric Corp 83/08/26 EISENHUT, D. G. Division of Licensing 7pp 20909 358 24X Fiche 50-445, 83/08/26, 8310260279

--8310260284 Nonproprietary version of "Counterflow Preheat Steam Generator Tube Expansion Rept" *
Westinghouse Electric Corp 83/08/30 140pp 20910 005 24X Fiche: 50-445, 83/08/26, 8310260279

--8310260286 Nonproprietary version of "Counterflow Preheat Steam Generator Tube Vibration Summary Rept" *
Westinghouse Electric Corp 83/08/30 180pp 20910 144 24X Fiche 50-445, 83/08/26, 8310260279

8310180588 Responds to FOIA request for VS Noonan 830426 memo re addl info needed by Equipment Qualification Branch to complete review of environ qualification of mechanical equipment Forwards document
FELTON, J. M. Division of Rules and Records 83/09/06 PEDRO, J. NUS Corp 1p 20817 330 24X Fiche 50-445, 83/09/06, 8310180588

--8303060124 Forwards request for addl info necessary to complete review of licensee 830330 info re environ qualification of safety-related mechanical equipment located in harsh environ
NOONAN, V. B. Equipment Qualification Branch 83/04/26 YOUNGBLOOD, B. J. Licensing Branch 1 2pp 20817 331 24X Fiche 50-445, 83/09/06, 8310180588

8308300355 Board Notification 83-66A advises that position re rod drop issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycle
EISENHUT, D. G. Division of Licensing 83/09/29 PALLADINO, N. J. Commissioners. 10pp 20632 106 24X Fiche 50-000, 83/09/29, 8308300355

8308300357 Board Notification 82-105A Forwards evaluation of allegations re design deficiencies in Class I piping sys. Info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway
EISENHUT, D. G. Division of Licensing 83/09/29 PALLADINO, N. J. Commissioners. 3pp 20632 001 24X Fiche 50-000, 83/09/29, 8308300357

8310040604 Informs that instrument accuracy study for TMI Action Item I K 3 B, "Automatic Trip of Reactor Coolant Pumps," will not be available on 830930 as stated in response to Generic Ltr 83-10C
SCHMIDT, M. C. Texas Utilities Services, Inc. 83/09/30 YOUNGBLOOD, B. J. Licensing Branch 1 1p. 20625 336 24X Fiche: 50-445, 83/09/30, 8310040604

8310040604 Informs that instrument accuracy study for TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps," will not be available on 830930 as stated in response to Generic Ltr 83-10C
SCHMIDT, H C Texas Utilities Services, Inc 83/09/30
YOUNGBL000, B J Licensing Branch 1 1p 20625 336 24X
Fiche 50-445, 83/09/30, 8310040604

8308300763 Board Notification 83-151 provides info re desirability of current ECCS actuation logic for Westinghouse plants, in light of recent info concerning steam generator tube rupture procedure for Borssele Nuclear Power Station
EISENHUT, D G Division of Licensing 83/10/04 PALLADINO, N J Commissioners 2pp 20698 033 24X Fiche 50-000, 83/10/04, 8308300763

8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves
EISENHUT, D G Division of Licensing 83/10/06 PALLADINO, N J Commissioners 31pp 20818 001 24X Fiche 50-000, 83/10/06, 8308300771

8310170715 Forwards safety evaluation of FSAR Amend 3B re NUREG-0737, Item II F 2, "Detection of Inadequate Core Cooling " Amend unacceptable Justification for proposed late implementation of in-core thermocouples requested
YOUNGBL000, B J Licensing Branch 1 83/10/07 GRAY, R J Texas Utilities Generating Co 4pp 20798 122 24X Fiche 50-445, 83/10/07, 8310170715

8310280041 Forwards new heatup & cooldown curves for draft Tech Specs Curves not impacted by new 10CFR50, App G & H which address metal temp of closure head Flange Temp graphs encl
SCHMIDT, H C Texas Utilities Services, Inc 83/10/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 20933 326 24X Fiche 50-445, 83/10/11, 8310280041

8308310050 Board Notification 83-160 provides info re 830812 failure of main crankshaft on one of three Transamerica Delaval emergency diesel generators at Shoreham
EISENHUT, D G Division of Licensing 83/10/14 PALLADINO, N J Commissioners 19pp 67056 070 24X Fiche 50-000, 83/10/14, 8308310050

8310210081 Informs that util response to TMI Item II.F 2 will be submitted by 83117
MARSHALL, J S Texas Utilities Generating Co 83/10/18 BURWELL, S B Licensing Branch 1 1p 20835 332 24X
Fiche 50-445, 83/10/18, 8310210081

F Security, medical, emergency & fire protection plans

8310040156 Forwards IE Insp Rept 50-445/83-29 on 830712-14 No noncompliance noted
MADSEN, O L Region 4, Office of Director 83/09/02 GARY, R J Texas Utilities Generating Co 3pp 20608 218 24X
Fiche 50-445, 83/09/02, 8310040156

--8310040160 IE Insp Rept 50-445/83-29 on 830712-14 No noncompliance noted Major areas inspected approved guard training & qualification plan (App B to 10CFR73) Details withheld (ref 10CFR73 21)
EVANS, C A KELLY, J Region 4, Office of Director, 83/08/11 1p 20608 221 24X Fiche 50-445, 83/09/02, 8310040156

8310050424 Forwards DM Rohrer 830923 memo re 830909 conversation w/ Judge Bloch on schedule for NRC emergency preparedness implementation audit Audit should not be confused w/annual emergency preparedness exercise & will be held 830926-1007
ROTHSCHILD, M U Hearing Branch 1 83/09/29 BLOCH, P B, JORDAN, W H, MCCOLLOM, K A Atomic Safety and Licensing Board Panel 3pp 20632 354 24X Fiche 50-445, 83/09/29, 8310050424

8310101073 Forwards position paper "Engineering Basis for Structural Integrity of Raceway Supports Associated w/1 H Rated Cable Protective Envelope Sys Upon Exposure to Fire "
SCHMIDT, H C Texas Utilities Services, Inc 83/10/04 YOUNGBL000, B J Office of Nuclear Reactor Regulation, Director 1p 20666-227 24X Fiche 50-445, 83/10/04, 8310101073,

--8310101077 "Engineering Basis for Structural Integrity of Raceway Supports Associated w/1 H Rated Cable Protective Envelope Sys Upon Exposure to Fire."
* Texas Utilities Services, Inc 83/09/27 8pp, 20666 228 24X Fiche 50-445, 83/10/04, 8310101073,

8310101009 Releases public version of applicant ltr forwarding revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/05, Document Management Branch 1p 20687 318 24X Fiche 50-445, 83/10/05, 8310101009

--8310101016 Forwards public version of revised emergency plan implementing procedures, including Procedures EPP-101 re preparation of emergency plan procedures & EPP-201 re assessment of emergency action levels w/o encl
SCHMIDT, H C Texas Utilities Services, Inc 83/08/18, COLLINS, J T Region 4, Office of Director 2pp 20687 319 24X
Fiche 50-445, 83/10/05, 8310101016

8310310256 Forwards IE Mgt Meeting Repts 50-445/83-37 & 50-446/83-19 on 830908 No noncompliance noted
MADSEN, O L Region 4, Office of Director 83/10/07 GARY, R J Texas Utilities Generating Co 2pp 20947 171 24X
Fiche 50-445, 83/10/07, 8310310256

--8310310264 IE Mgt Meeting Repts 50-445/83-37 & 50-446/83-19 on 830908 No noncompliance noted Major areas discussed & inspected emergency preparedness appraisal & emergency response facilities equipment
BAIRD, J B, HUNNICUTT, D M Region 4, Office of Director 83/10/05 2pp 20947 173 24X Fiche 50-445, 83/10/07, 8310310256

8310270175 Forwards test results re fire rating of watertight doors, verifying acceptability of std industrial watertight doors utilized at facility as 3 h fire barriers
SCHMIDT, H C Texas Utilities Services, Inc 83/10/24 YOUNGBL000, B J Office of Nuclear Reactor Regulation, Director 4pp 20925 033 24X Fiche 50-445, 83/10/24, 8310270175

8310270185 Requests withdrawal of 831004 "Engineering Basis for Structural Integrity of Raceway Supports Associated w/1 H Rated Cable Protective Envelope Sys Upon Exposure to Fire " Supports capable of withstanding 1 h fire
SCHMIDT, H C Texas Utilities Services, Inc 83/10/24 YOUNGBL000, B J Licensing Branch 1 1p 20924 184 24X
Fiche 50-445, 83/10/24, 8310270185

G Adjudicatory correspondence

8310050430 Forwards IE Insp Repts 50-445/83-34 & 50-446/83-18 on allegations concerning Atchison dismissal & reactor vessel outer wall Caseload Forecast Panel meeting & site visit scheduled for 830927-29 w/o encl
ROTHSCHILD, M U Hearing Branch 1 83/09/26 BLOCH, P B, MCCOLLOM, K A, JORDAN, W H Atomic Safety and Licensing Board Panel 1p 20633 319 24X Fiche 50-445, 83/09/26, 8310050430

8310050435 Forwards NUREG-1000, Vol 2, "Generic Implications of ATWS Events at Salem Nuclear Power Plant" & BECV-83-24B, "Generic Actions for Licensees & Staff in Response to ATWS Events at Salem " w/o encls
ROTHSCHILD, M U Hearing Branch 1 83/09/27 BLOCH, P B, JORDAN, W H, MCCOLLOM, K A Atomic Safety and Licensing Board Panel, 1p 20628 362 24X Fiche 50-445, 83/09/27, 8310050435

8310030528 Advises that time for Commission to review Director's Decision DD-83-11 expired Commission declined review Decision became final agency action on 830923
CHILK, S J Office of the Secretary of the Commission 83/09/29 ELLIS, J Citizens Association for Sound Energy 1p 20602-031 24X Fiche 50-445, 83/09/29, 8310030528

8310040230 Answer opposing util 830922 motions to cancel evidentiary hearings & for expedited consideration Hearing set for wk of 831017 on NRC insp of fuel bldg must go forward & J Gagliardo of NRC must testify Certificate of Evc encl
ELLIS, J Citizens Association for Sound Energy 83/09/29, Atomic Safety and Licensing Board Panel 14pp 20613 074 24X
Fiche 50-445, 83/09/29, 8310040230

8310050424 Forwards DM Rohrer 830923 memo re 830909 conversation w/ Judge Bloch on schedule for NRC emergency preparedness implementation audit Audit should not be confused w/annual emergency preparedness exercise & will be held 830926-1007.
ROTHSCHILD, M U Hearing Branch 1 83/09/29 BLOCH, P B, JORDAN, W H, MCCOLLOM, K A Atomic Safety and Licensing Board Panel 3pp 20632 354 24X Fiche 50-445, 83/09/29, 8310050424

8310050525 Answer to util 830922 motions to cancel evidentiary hearings & for expedited consideration ASLB must determine significance of matters raised in IE Insp Rept 83-23 Certificate of Evc encl
ROTHSCHILD, M U Hearing Branch 1 83/09/29, Atomic Safety and Licensing Board Panel, 7pp 20632 328, 24X Fiche 50-445, 83/09/29, 8310050525

8310050433 Forwards ASLB proposed initial decision requesting that ACRB be informed of matters re deletion of boron injection tank w/o encl.
TREY, B A, Hearing Branch 1 83/09/30 FRALEY, R F, ACRB - Advisory Committee on Reactor Safeguards 1p, 20629 040 24X
Fiche 50-445, 83/09/30, 8310050433

DOCKETED ITEMS

8310120414 Forwards revised list of some of Citizens Assoc for Sound Energy exhibits, matching exhibit numbers to transcript page where document accepted into evidence
ELLIS, J Citizens Association For Sound Energy 83/10/01
BLOCH, P B., JORDAN, W H., MCCOLLUM, K A Atomic Safety and Licensing Board Panel 39pp 20698 332 24X Fiche 50-445, 83/10/01, 8310120414

8310060316 Confirms 831003 oral motion for extension until 831011 to respond to ASLB 830920 memorandum on computerization of nonconformances Related correspondence
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Texas Utilities Generating Co 83/10/03 BLOCH, P B Atomic Safety and Licensing Board Panel 1p 20646 276 24X Fiche 50-445, 83/10/03, 8310060316

8310110266 Partial Initial Decision LBP-83-63 re change in matl properties for A500 steel Util ordered to file analyses demonstrating pipe supports mfg w/A500 steel have adequate safety margins Replier due 15 days after analyses filed
BLOCH, P B., JORDAN, W H., MCCOLLUM, K A Atomic Safety and Licensing Board Panel 83/10/06 Texas Utilities Generating Co 7pp 20666-131 24X Fiche 50-445, 83/10/06, 8310110266

8310110322 Motion for reconsideration of ASLB 830923 memorandum & order affirming declaration of intervenor default of contentions re emergency planning, GA/OC & Board issues Certificate of Svc encl
REYNOLDS, N S HORIN, W A Texas Utilities Generating Co REYNOLDS, N S Debevoise & Liberman 83/10/06 Atomic Safety and Licensing Board Panel 49pp 20666-002 24X Fiche 50-445, 83/10/06, 8310110322

8310130031 Motion for reconsideration of 830923 memorandum & order re emergency planning, GA & Board issues ASLB erred in retaining jurisdiction over emergency planning Record should be cited Certificate of Svc encl
ROTTSCHILD, M U Hearing Branch 1 83/10/06 Atomic Safety and Licensing Board Panel 15pp 20726 259 24X Fiche 50-445, 83/10/06, 8310130031

8310130167 Memorandum cautioning parties not to place great weight on ASLB characterization of LBP-83-63 as partial initial decision in determining appealability of LBP-83-63 as matter of right
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/11 4pp. 20724 293 24X Fiche 50-445, 83/10/11, 8310130167

8310170412 Forwards telecopy facsimile of RO Tolson affidavit responding to ASLB questions re computerization of nonconformances Original forthcoming
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Texas Utilities Generating Co 83/10/11 BLOCH, P B., JORDAN, W H., MCCOLLUM, K A Atomic Safety and Licensing Board Panel 5pp 20764 103 24X Fiche 50-445, 83/10/11, 8310170412

8310170417 Supports NRC opposition to Citizens Assoc for Sound Energy 830929 motion to require presence of NRC Region IV Director, Div of Resident Reactor Project & Engineering Programs, J Gagliardo at 831017 hearings
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Texas Utilities Generating Co 83/10/11 BLOCH, P B., JORDAN, W H., MCCOLLUM, K A Atomic Safety and Licensing Board Panel 1p 20764 108 24X Fiche 50-445, 83/10/11, 8310170417

8310170488 Answer to Citizens Assoc for Sound Energy 830929 motion to require testimony of JE Gagliardo Testimony may not be required since exceptional circumstances not shown Certificate of Svc encl
ROTTSCHILD, M U Hearing Branch 1 83/10/11 Atomic Safety and Licensing Board Panel. 8pp. 20784:093 24X Fiche 50-445, 83/10/11, 8310170488

8310140018 Memorandum inviting parties to file briefs by 831014 on relationship to OL proceeding of Board Notification 82-105A re NRC evaluation of allegations of potential design deficiencies in Class I piping
BLOCH, P B Atomic Safety and Licensing Board Panel 83/10/12 1p 20768-065 24X Fiche 50-445, 83/10/12, 8310140018

8310140083 Memorandum re Citizens Assoc for Sound Energy 830926 request for info re potential conflict of interest of Judge McCollum Indirect interest in funds contributed by Brown & Root inconsequential
BLOCH, P B., JORDAN, W H Atomic Safety and Licensing Board Panel. 83/10/12. 4pp 20767:046. 24X Fiche 50-445, 83/10/12, 8310140083.

8310140085 Advises that Halliburton Foundation grant monies do not constitute conflict of interest for author as member of ASLB. Contribution is small & author does not receive any funds for personal use from foundation
MCCOLLUM, K A Oklahoma State Univ. 83/10/03 BLOCH, P B Atomic Safety and Licensing Board Panel. 2pp 20767 050 24X Fiche: 50-445, 83/10/12, 8310140085.

8310170577 Advises that Ofc of Investigations is conducting several ongoing investigations involving plant Ofc will provide oral presentation of investigations in camera ex parte when ASLB meets in Arlington, TX for 831017 hearings
HAYES, B B Office of Investigation 83/10/13 BLOCH, P B Atomic Safety and Licensing Board Panel 1p 20780 188 24X Fiche 50-445, 83/10/13, 8310170577

8310180339 Requests stipulations/admissions to authenticity of documents attached as offer of proof to Citizens Assoc for Sound Energy motion to add new contention & motion for discovery
ELLIS, J Citizens Association for Sound Energy 83/10/13 REYNOLDS, N S Lowenstein, Neuman, Reis, Axelrad & Toll 3pp 20805 019 24X Fiche 50-445, 83/10/13, 8310180339

--8310180342 Motion to add proposed Contention 26 re hot functional test, motion for discovery & offer of proof Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 83/10/13 Atomic Safety and Licensing Board Panel 497pp 20809 022 24X Fiche 50-445, 83/10/13, 8310180339

8310180158 Forwards stipulation re allegations of discouraging identification of nonconforming conditions, per ASLB request
HORIN, W A Debevoise & Liberman HORIN, W A Texas Utilities Generating Co 83/10/14 BLOCH, P B., JORDAN, W H., MCCOLLUM, K A Atomic Safety and Licensing Board Panel 1p 20809 029 24X Fiche 50-445, 83/10/14, 8310180158

--8310180163 Stipulation on results of util employee interviews re allegations of discouragement of reporting nonconforming conditions
TRESBY, S A Hearing Branch 1 PREISTER, D J Texas, State of HORIN, W A Texas Utilities Generating Co 83/10/11 4pp 20809 030 24X Fiche 50-445, 83/10/14, 8310180158

8310250260 Forwards unexecuted affidavits of WP Chen & JI Tapia on open items re Walsh/Doyle concerns
MIZUND, G S Hearing Branch 1 83/10/14 BLOCH, P B., JORDAN, W H., MCCOLLUM, K A Atomic Safety and Licensing Board Panel 89pp 20898 269 24X Fiche 50-445, 83/10/14, 8310250260

8310250295 Forwards calculations for support (CC-1-028-039-533R) & b11 checklist utilized in independent design verification of 100 pipe supports W/o encl
MIZUND, G S Hearing Branch 1 83/10/14 ELLIS, J Citizens Association for Sound Energy 1p 20895 342 24X Fiche 50-445, 83/10/14, 8310250295

8310250489 Forwards IE Insp Rpts 50-445/83-27, 50-445/83-28 & 50-445/83-14 re RL Messerley allegations of improper const practices W/o encl
ROTTSCHILD, M U Hearing Branch 1 83/10/14. BLOCH, P B., JORDAN, W H., MCCOLLUM, K A Atomic Safety and Licensing Board Panel 1p 20902 070 24X Fiche 50-445, 83/10/14, 8310250489

8310210184 Forwards original signature page of RO Tolson 831011 affidavit re computerization of nonconformances
HORIN, W A Debevoise & Liberman HORIN, W A Texas Utilities Generating Co 83/10/19 STUCKY, S W Docketing & Services Branch 1p 20855 115 24X Fiche 50-445, 83/10/19, 8310210184

--8310210195 Original signature page of RO Tolson of 831011 affidavit re computerization of nonconformances
TOLSON, R O Texas Utilities Generating Co 83/10/11 1p 20855 116 24X Fiche 50-445, 83/10/19, 8310210184

8310280059 Forwards 831022 & 0923 news articles re illegal firing of QC inspector & adequacy of emergency plans, respectively
ELLIS, J Citizens Association for Sound Energy 83/10/24 BLOCH, P B., JORDAN, W H., MCCOLLUM, K A Atomic Safety and Licensing Board Panel. 7pp 20933 332 24X Fiche 50-445, 83/10/24, 8310280059

8310270228 Memorandum on adopted procedure re GA hearings to be conducted for finished safety sys, Cygna rept & applicant followup insp of protective coatings Citizens Assoc for Sound Energy will file allegations on GA deficiencies
BLOCH, P B., JORDAN, W H., MCCOLLUM, K A Atomic Safety and Licensing Board Panel 83/10/25 3pp, 20924 071 24X Fiche. 50-445, 83/10/25, 8310270228

8310270293 Memorandum & order LBP-83-69, instructing util to inspect sample of Westinghouse coatings & to submit further evidence re plug welds & further testimony or proposals responding to other adverse findings in ASLB 830923 memorandum & order
BLOCH, P B., JORDAN, W H., MCCOLLUM, K A Atomic Safety and Licensing Board Panel 83/10/25 Texas Utilities Generating Co 14pp. 20923 207. 24X Fiche 50-445, 83/10/25, 8310270293

DOCKETED ITEMS

335

8310280070 Memorandum informing that directed certification of ASLB
831006 partial initial decision may still be sought ASLB
will continue to treat order as totally interlocutory
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/27
Atomic Safety and Licensing Appeal Panel 3pp 20935 061 24X
Fiche 50-445, 83/10/27, 8310280070

K Utility Final Safety Analysis Report (FSAR) & amends

8310180179 Forwards revised pages to FSAR Amend 41, Chapter 17 1 re
Westinghouse QA organization Revs reflect changes to
QA program description
GARY, R J Texas Utilities Generating Co 83/08/12 COLLINS, J T
Region 4, Office of Director 1p 20808 352 24X
Fiche 50-445, 83/08/12, 8310180179

--8310180183 Errata to FSAR Amend 41, Chapter 17 1 re Westinghouse
QA organization
* Texas Utilities Generating Co 83/07/11 3pp 20808 353 24X
Fiche 50-445, 83/08/12, 8310180179

8310140180 Amend 44 to FSAR W/831010 1tr
GARY, R J Texas Utilities Generating Co 83/10/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director 332pp 20765 095
24X Fiche 50-445, 83/10/10, 8310140180

8310200149 Forwards affidavit of svc of Amend 44 to FSAR
SCHMIDT, H C Texas Utilities Services, Inc 83/10/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 20836 322
24X Fiche 50-445, 83/10/11, 8310200149

G Inspection reports, IE Bulletins & correspondence

8310040181 Forwards IE Insp Rept 50-445/83-32 on 830701-31 No
noncompliance noted
MADSEN, G L Region 4, Office of Director 83/08/24 GARY, R J
Texas Utilities Generating Co 2pp 20608 057 24X
Fiche 50-445, 83/08/24, 8310040181

--8310040186 IE Insp Rept 50-445/83-32 on 830701-31 No noncompliance
noted Major areas inspected initial startup test procedure
review, Tech Spec review, sys walkdown, plant tours & plant
status
KELLEY, D L, JONES, W B, HUNNICUTT, D M Region 4, Office of
Director 83/08/23 7pp 20608 057 24X Fiche 50-445, 83/08/24,
8310040181

8310040223 Forwards IE Insp Repts 50-445/83-24 & 50-446/83-15 on
830301-0731
MADSEN, G L Region 4, Office of Director 83/08/24 GARY, R J
Texas Utilities Generating Co 2pp 20614 239 24X
Fiche 50-445, 83/08/24, 8310040223

--8310040240 IE Insp Repts 50-445/83-24 & 50-446/83-15 on 830301-0731. No
noncompliance noted Insp confirmed need to issue violations
re HVAC, equipment installation, document control & equipment
in storage
TAYLOR, R G, HUNNICUTT, D M Region 4, Office of Director
83/08/19 23pp 20614 241 24X Fiche 50-445, 83/08/24, 8310040223

8310030395 Forwards notice of violation & proposed imposition of
civil penalty in amount of \$40,000 based on violation of
employee protection provisions of Energy Reorganization
Act of 1974
COLLINS, J T Region 4, Office of Director 83/08/29 GARY, R J
Texas Utilities Generating Co 3pp 20593 078 24X
Fiche 50-445, 83/08/29, 8310030395

--8310030411 Notice of violation & proposed imposition of civil penalty
based on Dept of Labor 830610 determination that Brown &
Root QA program failed to provide sufficient organizational
freedom to QA inspectors
COLLINS, J T Region 4, Office of Director 83/08/29 2pp
20593 081 24X Fiche 50-445, 83/08/29, 8310030395

8310040156 Forwards IE Insp Rept 50-445/83-29 on 830712-14 No
noncompliance noted
MADSEN, G L Region 4, Office of Director 83/09/02 GARY, R J
Texas Utilities Generating Co 3pp 20608 218 24X
Fiche 50-445, 83/09/02, 8310040156

--8310040160 IE Insp Rept 50-445/83-29 on 830712-14 No noncompliance
noted Major areas inspected approved guard training &
qualification plan (App B to 10CFR73) Details withheld
(ref 10CFR73 21)
EVANS, C A, KELLY, J Region 4, Office of Director 83/08/11 1p
20608 221 24X Fiche 50-445, 83/09/02, 8310040156

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder
Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340.

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
Detectors Positioned at Control Room Ventilation Air
Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse
Type 9A-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 116pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345,

8310180466 Forwards IE Insp Rept 50-445/83-36 on 830801-31 No
noncompliance noted
MADSEN, G L Region 4, Office of Director 83/09/27 GARY, R J
Texas Utilities Generating Co 2pp 20802 032 24X
Fiche 50-445, 83/09/27, 8310180466

--8310180472 IE Insp Rept 50-445/83-36 on 830801-31 No noncompliance
noted Major areas inspected initial startup test procedure
review, penetration seal installation, sys walkdown, plant
tours & plant status
KELLEY, D L, JONES, W B, HUNNICUTT, D M Region 4, Office of
Director 83/09/27 7pp 20802 034 24X Fiche 50-445, 83/09/27,
8310180466

8310050403 Responds to 830829 notice of violation & proposed imposition
of civil penalty in amount of \$40,000 (EA-83-64) re alleged
violation of 10CFR50, App B, Criterion 1 Answer protesting
civil penalty encl
GARY, R J Texas Utilities Generating Co 83/09/28 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 26pp
20873 057 24X Fiche 50-445, 83/09/28, 8310050403

--8310090412 Response opposing imposition of civil penalty in amount of
\$40,000 for alleged violation of 10CFR50, App B, Criterion 1
Requests proposed civil penalty be withdrawn or mitigated in
full
* Texas Utilities Generating Co 83/09/28 Commissioners
10pp 20630 130 24X Fiche 50-445, 83/09/28, 8310090403.

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to
Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New
York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310180214 Forwards IE Insp Rept 50-445/83-27 on 830510-0701 & 0909-22
No noncompliance noted
MADSEN, G L Region 4, Office of Director 83/09/29 GARY, R J
Texas Utilities Generating Co 2pp 20808 189 24X
Fiche 50-445, 83/09/29, 8310180214

--8310180219 IE Insp Rept 50-445/83-27 on 830510-0701 & 0909-22 No
noncompliance noted Major areas inspected alleged improper
const practices expressed by RL Messerly in affidavit dtd
830203 Allegation re improper documentation substantiated
STEWART, R C, HUNNICUTT, D M Region 4, Office of Director
83/09/28 22pp 20808 191 24X Fiche 50-445, 83/09/29, 8310180214

--8310180223 "Comanche Peak Alleged Improper Const Practices "
GRIFFIN, H B, HERR, R K Region 4, Office of Director 83/05/20
3pp 20808 213 24X Fiche 50-445, 83/09/29, 8310180214

--8310180229 "Comanche Peak Steam Electric Station Alleged Improper Const
Practices "
GRIFFIN, H B, HERR, R K Region 4, Office of Director 83/09/07
1p 20808 216 24X Fiche 50-445, 83/09/29, 8310180214

8310180218 Forwards IE Insp Repts 50-445/83-28 & 50-446/83-14 on
830627-0916 No noncompliance noted.
MADSEN, G L Region 4, Office of Director 83/10/03 GARY, R J
Texas Utilities Generating Co 2pp 20808 270 24X
Fiche 50-445, 83/10/03, 8310180218

--8310180227 IE Insp Repts 50-445/83-28 & 50-446/83-14 on 830627-0916. No
noncompliance noted Major areas inspected, followup on Const
Appraisal Team Insp Repts 50-445/83-18 & 50-446/83-12
MARTIN, L E, HUNNICUTT, D M Region 4, Office of Director
83/09/23 35pp 20808 272 24X Fiche 50-445, 83/10/03, 8310180218

DOCKETED ITEMS

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8310310256 Forwards IE Mgt Meeting Repts 50-445/83-37 & 50-446/83-19 on 830908 No noncompliance noted.
MADSEN, O L Region 4, Office of Director 83/10/07 GARY, R J Texas Utilities Generating Co 2pp 20947 171 24X Fiche 50-445, 83/10/07, 8310310256

--8310310264 IE Mgt Meeting Repts 50-445/83-37 & 50-446/83-19 on 830908 No noncompliance noted Major areas discussed & inspected emergency preparedness appraisal & emergency response facilities equipment
BAIRD, J B, HUNNICUTT, D H Region 4, Office of Director 83/10/05 2pp 20947 173 24X Fiche 50-445, 83/10/07, 8310310256

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180478 Ack receipt of 830824 & 31 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-445/83-23
JOHNSON, E H Region 4, Office of Director 83/10/13 GARY, R J Texas Utilities Generating Co 1p 20800 158 24X Fiche 50-445, 83/10/13, 8310180478

--8310180484 Responds to NRC 830727 ltr re violations noted in IE Insp Rept 50-445/83-23 Corrective actions. Five loose jam nuts on large bore ASME pipe supports reworked & verified snug tight Extension of due date until 830901 granted by NRC
GARY, R J Texas Utilities Generating Co 83/08/24 MADSEN, O L Region 4, Office of Director 2pp 20800 159 24X Fiche 50-445, 83/10/13, 8310180478

--8310180488 Responds to NRC 830727 ltr re violations noted in IE Insp Rept 50-445/83-23 Corrective actions engineering evaluation concluded that plant safety would not have been affected
Mads made to insp procedures.
GARY, R J Texas Utilities Generating Co 83/08/31 MADSEN, O L Region 4, Office of Director 3pp 20800 161 24X Fiche 50-445, 83/10/13, 8310180478

B Reportable occurrences, LERs & related correspondence

8310130278 Final deficiency rept re pipe wall thickness of reactor coolant pressurizer surge line initially reported on 821101 Deficiency not reportable per 10CFR50.55(e)
GARY, R J Texas Utilities Generating Co 82/11/23 MADSEN, O L Region 4, Office of Director 1p 20723 197 24X Fiche 50-445, 82/11/23, 8310130278

8310130268 Interim deficiency rept re temp in excess of FSAR parameters experienced in annulus between reactor vessel insulation & shield wall Cooling increased by reducing chilled water temp & installing addl cooling coil
GARY, O L Texas Utilities Generating Co 83/09/26 MADSEN, O L Region 4, Office of Director 2pp 20723 215 24X Fiche 50-445, 83/09/26, 8310130268

8310030516 Advises of meeting tentatively scheduled for 831013 w/util, Westinghouse & NRR to discuss Pacific Pump multi-vane diffuser linear indications.
GARY, R J Texas Utilities Generating Co 83/10/01 MADSEN, O L Region 4, Office of Director 1p 20601 200 24X Fiche 50-445, 83/10/01, 8310030516

8310280003 Final deficiency rept re premature corrosion of valves in svc water sys. Initially reported on 830919 Investigation complete. Item not reportable under 10CFR50.55(e).
GARY, R J Texas Utilities Generating Co 83/10/17 JOHNSON, E Region 4, Office of Director 1p 20933 330 24X Fiche 50-445, 83/10/17, 8310280003.

T Hearing transcripts on non-antitrust matters

8310140022 Forwards testimony of RO Tolson & OR Purdy re NRC insp of fuel bldg & design change verification
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Texas Utilities Generating Co 83/10/12 BLOCH, P B, JORDAN, W H, MCCLIM, K A Atomic Safety and Licensing Board Panel 1p 2076B 066 24X Fiche 50-445, 83/10/12, 8310140022

--8310140024 Testimony of RO Tolson & OR Purdy re NRC insp of fuel bldg & design change verification
TOLSON, R O, PURDY, O R Texas Utilities Generating Co PURDY, O R Brown & Root Corp (subs of Halliburton Corp) 83/10/12 10pp 2076B 067 24X Fiche 50-445, 83/10/12, 8310140022

8310170683 Testimony of TF Westerman, CR Oberg, JE Bess, CE Johnson, JI Tapia, KA Whittlesey & RO Taylor re findings of 830523-0610 special insp of fuel bldg Prof qualifications encl
WESTERMAN, T F, OBERG, C R Region 4, Office of Director BESS, J E Division of Resident, Reactor Project & Engineering Programs 83/10/12 14pp 20779 232 24X Fiche 50-445, 83/10/12, 8310170683

--8310170688 Testimony of RO Taylor re relationship between as-built certified design & vendor certified design Certificate of Svc encl
TAYLOR, R O Region 4, Office of Director 83/10/12 10pp 20779 246 24X Fiche 50-445, 83/10/12, 8310170683

8310210057 Transcript of 831017 hearing in Fort Worth, TX Pp 8, 751-8, 927 Supporting documentation encl
* Commissioners 83/10/17 273pp 20857 276 24X Fiche 50-445, 83/10/17, 8310210057.

8310210059 Transcript of 831018 hearing in Fort Worth, TX Pp 8, 428-9, 075 Supporting documentation encl
* Commissioners 83/10/18 78pp 20858 265 24X Fiche 50-445, 83/10/18, 8310210059

8310250103 Transcript of 831021 telcon in Bethesda, MD Pp 9, 076-9, 134 * Atomic Safety and Licensing Board Panel 83/10/21 60pp 20876 186 24X Fiche 50-445, 83/10/21, 8310250103

U Congressional/Executive Correspondence

8310200062 Responds to 830713 ltr re investigation of QA/QC program at facility
PALLADINO, N J Commissioners 83/10/07 UDALL, M K House of Rep, Interior & Insular Affairs 3pp 20872 280 24X Fiche 50-445, 83/10/07, 8310200062

--8310200073 Requests copies of listed documents re QA/QC program problems at facility
UDALL, M K House of Rep, Interior & Insular Affairs 83/09/13 PALLADINO, N J Commissioners 2pp 20873 093 24X Fiche 50-445, 83/10/07, 8310200062

DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA, UNIT 2

A Application/construction stage documents & correspondence

8310110007 Responds to FOIA request for SECY-82-279, SECY-82-330 & SECY-83-120 Forwards documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/07/15 PEDRO, J NUB Corp 1p 20712 280 24X Fiche 50-445, 83/07/15, 8310110007

--8310110022 Recommends issuance of encl proposed order directing ASLB to resume hearings as soon as possible on issue not involving informant identities
PLAINE, H H Office of the General Counsel SECY-83-120 83/04/01 4pp 20712 319 24X Fiche 50-445, 83/07/15, 8310110007

8310180982 FOIA request for VS Noonan 830426 memo to BJ Youngblood re addl info needed by Equipment Qualification Branch to complete review of environ qualification of mechanical equipment
PEDRO, J, NUB Corp, 83/08/17 Division of Rules and Records 1p 20817 329 24X Fiche 50-445, 83/08/17, 8310180982

8310260279 Forwards nonproprietary & proprietary versions of "Counterflow Preheat Steam Generator Tube Expansion Rept" & "Counterflow Preheat Steam Generator Tube Vibration Summary Rept " Proprietary version withheld (ref 10CFR2 790)
RAHE, E P Westinghouse Electric Corp 83/08/26 EIBENHUT, D O Division of Licensing 2pp 20909 394 24X Fiche 50-445, 83/08/26, 8310260279

DOCKETED ITEMS

337

--8310260281 Application for withholding proprietary versions of "Counterflow Preheat Steam Generator Tube Expansion Rept" & "Counterflow Preheat Steam Generator Tube Vibration Summary Rept," per 10CFR2 790 Affidavit encl WIEBEMANN, R A Westinghouse Electric Corp 83/08/26 EISENHUT, D O Division of Licensing 9pp 20909 358 24X Fiche 50-445, 83/08/26, 8310260279

--8310260284 Nonproprietary version of "Counterflow Preheat Steam Generator Tube Expansion Rept" * Westinghouse Electric Corp SOPR-8301 83/06/30 140pp 20910 005 24X Fiche 50-445, 83/08/26, 8310260279

--8310260286 Nonproprietary version of "Counterflow Preheat Steam Generator Tube Vibration Summary Rept" * Westinghouse Electric Corp SOPR-8302 83/06/30 180pp 20910 144 24X Fiche 50-445, 83/08/26, 8310260279

8310180588 Responds to FOIA request for VS Noonan 830426 memo re addl info needed by Equipment Qualification Branch to complete review of environ qualification of mechanical equipment Forwards document FELTON, J M Division of Rules and Records 83/09/06 PEDRO, J NUB Corp 1p 20817 330 24X Fiche 50-445, 83/09/06, 8310180588

--8305060124 Forwards request for addl info necessary to complete review of licensee 830330 info re environ qualification of safety-related mechanical equipment located in harsh environ NOONAN, V S Equipment Qualification Branch 83/04/26 YOUNGBLOOD, B J Licensing Branch 1 2pp 20817 331 24X Fiche 50-445, 83/09/06, 8310180588

8308300355 Board Notification 83-66A advises that position re rod drop issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycle EISENHUT, D O Division of Licensing 83/09/29 PALLADINO, N J Commissioners 10pp 20632 106 24X Fiche 50-000, 83/09/29, 8308300355

8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway EISENHUT, D O Division of Licensing 83/09/29 PALLADINO, N J Commissioners 3pp 20632 001 24X Fiche 50-000, 83/09/29, 8308300357

8310040604 Informs that instrument accuracy study for TMI Action Item 1F K 3 B, "Automatic Trip of Reactor Coolant Pumps," will not be available on 830930 as stated in response to Generic Ltr 83-10C SCHMIDT, H C Texas Utilities Services, Inc 83/09/30 YOUNGBLOOD, B J Licensing Branch 1 1p 20625 336 24X Fiche 50-445, 83/09/30, 8310040604

8308300763 Board Notification 83-151 provides info re desirability of current ECCB actuation logic for Westinghouse plants, in light of recent info concerning steam generator tube rupture procedure for Borssele Nuclear Power Station EISENHUT, D O Division of Licensing 83/10/04 PALLADINO, N J Commissioners 2pp 20698 033 24X Fiche 50-000, 83/10/04, 8308300763

8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves EISENHUT, D O Division of Licensing 83/10/06 PALLADINO, N J Commissioners 31pp 20818 001 24X Fiche 50-000, 83/10/06, 8308300771

8310170715 Forwards safety evaluation of FSAR Amend 3B re NUREG-0737, Item 11 F 2, "Detection of Inadequate Core Cooling" Amend unacceptable Justification for proposed late implementation of in-core thermocouples requested YOUNGBLOOD, B J Licensing Branch 1 83/10/07, GRAY, R J, Texas Utilities Generating Co 4pp 20798 122 24X Fiche 50-445, 83/10/07, 8310170715

8310280041 Forwards new heatup & cooldown curves for draft Tech Specs. Curves not impacted by new 10CFR50, Apps Q & H which address metal temp of closure head flange Temp graphs encl SCHMIDT, H C Texas Utilities Services, Inc 83/10/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp. 20933 326 24X Fiche 50-445, 83/10/11, 8310280041

8308310050 Board Notification 83-160 provides info re 830812 failure of main crankshaft on one of three Transamerica Delaval emergency diesel generators at Shoreham EISENHUT, D O Division of Licensing 83/10/14 PALLADINO, N J Commissioners 15pp 67056 070 24X Fiche 50-000, 83/10/14, 8308310050

8310210081 Informs that util response to TMI Item 11 F 2 will be submitted by 831117 MARSHALL, J S Texas Utilities Generating Co 83/10/18 BURWELL, B D Licensing Branch 1 1p 20855 332 24X Fiche 50-445, 83/10/18, 8310210081

F Security, medical, emergency & fire protection plans

8310050424 Forwards DM Rohrer 830923 memo re 830909 conversation w/ Judge Bloch on schedule for NRC emergency preparedness implementation audit Audit should not be confused w/annual emergency preparedness exercise & will be held 830926-1007 ROTHCHILD, M U Hearing Branch 1 83/09/29 BLOCH, P B Atomic Safety and Licensing Board Panel 3pp. 20632 354 24X Fiche 50-445, 83/09/29, 8310050424

8310110173 Forwards position paper "Engineering Basis for Structural Integrity of Raceway Supports Associated W/1 H Rated Cable Protective Envelope Sys Upon Exposure to Fire" SCHMIDT, H C Texas Utilities Services, Inc 83/10/04 YOUNGBLOOD, B J Office of Nuclear Reactor Regulation, Director 1p 20666 227 24X Fiche 50-445, 83/10/04, 8310110173

--8310110177 "Engineering Basis for Structural Integrity of Raceway Supports Associated W/1 H Rated Cable Protective Envelope Sys Upon Exposure to Fire" * Texas Utilities Services, Inc 83/09/27 8pp 20666 228 24X Fiche 50-445, 83/10/04, 8310110173

8310110109 Releases public version of applicant ltr forwarding revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20687:318 24X Fiche 50-445, 83/10/05, 8310110109

--8310110116 Forwards public version of revised emergency plan implementing procedures, including Procedures EPP-101 re preparation of emergency plan procedures & EPP-201 re assessment of emergency action levels W/o encl SCHMIDT, H C Texas Utilities Services, Inc 83/08/18 COLLINS, J T Region 4, Office of Director. 2pp 20687 319 24X Fiche: 50-445, 83/10/05, 8310110109

8310310256 Forwards 1E Mgt Meeting Repts 50-445/83-37 & 50-446/83-19 on 830908 No noncompliance noted MADSEN, Q L Region 4, Office of Director 83/10/07, GARY, R J, Texas Utilities Generating Co 2pp 20947 171 24X Fiche 50-445, 83/10/07, 8310310256

--8310310264 1E Mgt Meeting Repts 50-445/83-37 & 50-446/83-19 on 830908 No noncompliance noted Major areas discussed & inspected emergency preparedness appraisal & emergency response facilities equipment BAIRD, J B Region 4, Office of Director. 83/10/05 2pp. 20947 173 24X Fiche 50-445, 83/10/07, 8310310256

8310270175 Forwards test results re fire rating of watertight doors, verifying acceptability of std industrial watertight doors utilized at facility as 3 h fire barriers SCHMIDT, H C Texas Utilities Services, Inc 83/10/24, YOUNGBLOOD, B J Office of Nuclear Reactor Regulation, Director 4pp 20925 033 24X Fiche 50-445, 83/10/24, 8310270175

8310270183 Requests withdrawal of 831004 "Engineering Basis for Structural Integrity of Raceway Supports Associated W/1 H Rated Cable Protective Envelope Sys Upon Exposure to Fire" Supports capable of withstanding 1 h fire SCHMIDT, H C Texas Utilities Services, Inc. 83/10/24 YOUNGBLOOD, B J Licensing Branch 1 1p. 20924:184. 24X Fiche 50-445, 83/10/24, 8310270183

G Adjudicatory correspondence

8310050430 Forwards 1E Insp Repts 50-445/83-34 & 50-446/83-1B on allegations concerning Atchison dismissal & reactor vessel outer wall Caseload Forecast Panel meeting & site visit scheduled for 830927-29 W/o encl. ROTHCHILD, M U Hearing Branch 1. 83/09/26 BLOCH, P B, MCCOLLOM, K A, JORDAN, W H Atomic Safety and Licensing Board Panel 1p. 20633 319. 24X Fiche 50-445, 83/09/26, 8310050430.

8310050435 Forwards NUREG-1000, Vol 2, "Generic Implications of ATWS Events at Salem Nuclear Power Plant" & BECY-83-248, "Generic Actions for Licensees & Staff in Response to ATWS Events at Salem" W/o encls ROTHCHILD, M U Hearing Branch 1 83/09/27 BLOCH, P B, JORDAN, W H, MCCOLLOM, K A Atomic Safety and Licensing Board Panel. 1p 20628 362 24X Fiche 50-445, 83/09/27, 8310050435

DOCKETED ITEMS

- 8310030528 Advises that time for Commission to review Director's Decision DD-83-11 expired Commission declined review Decision became final agency action on 830923
CHILK, S J Office of the Secretary of the Commission 83/09/29
ELLIS, J Citizens Association for Sound Energy 1p 20602 031
24X Fiche 50-445, 83/09/29, 8310030528
- 8310040230 Answer opposing until 830922 motions to cancel evidentiary hearings & for expedited consideration Hearing set for wk of 831017 on NRC insp of fuel bldg must go forward & J Gagliardo of NRC must testify Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 83/09/29 Atomic Safety and Licensing Board Panel 14pp 20613 074 24X Fiche 50-445, 83/09/29, 8310040230
- 8310050424 Forwards OM Rohrer 830923 memo re 830907 conversation w/ Judge Bloch on schedule for NRC emergency preparedness implementation audit Audit should not be confused w/annual emergency preparedness exercise & will be held 830926-1007
ROTHSCHILD, M U Hearing Branch 1 83/09/29 BLOCH, P B, JORDAN, W H, MCCOLLOM, K A Atomic Safety and Licensing Board Panel 3pp 20632 334 24X Fiche 50-445, 83/09/29, 8310050424
- 8310050523 Answer to util 830922 motions to cancel evidentiary hearings & for expedited consideration ASLB must determine significance of matters raised in IE Insp Rept 83-23 Certificate of Svc encl
ROTHSCHILD, M U Hearing Branch 1 83/09/29 Atomic Safety and Licensing Board Panel 7pp 20632 328 24X Fiche 50-445, 83/09/29, 8310050523
- 8310050433 Forwards ASLB proposed initial decision requesting that ACRS be informed of matters re deletion of boron injection tank w/o encl
TREBY, S A Hearing Branch 1 83/09/30 FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards 1p 20629 040 24X Fiche 50-445, 83/09/30, 8310050433
- 8310120414 Forwards revised list of some of Citizens Assoc for Sound Energy exhibits, matching exhibit numbers to transcript page where document accepted into evidence
ELLIS, J Citizens Association for Sound Energy 83/10/01
BLOCH, P B, JORDAN, W H, MCCOLLOM, K A Atomic Safety and Licensing Board Panel 39pp 20698 332 24X Fiche 50-445, 83/10/01, 8310120414
- 8310060316 Confirms 831003 oral motion for extension until 831011 to respond to ASLB 830920 memorandum on computerization of nonconformances Related correspondence
REYNOLDS, N S Debevoise & Liberman, REYNOLDS, N S, Texas Utilities Generating Co 83/10/03 BLOCH, P B Atomic Safety and Licensing Board Panel 1p 20646: 276 24X Fiche 50-445, 83/10/03, 8310060316
- 8310110266 Partial Initial Decision LBP-83-63 re change in matl properties for A500 steel Util ordered to file analyses demonstrating pipe supports mfg w/A500 steel have adequate safety margins Replies due 15 days after analyses filed
BLOCH, P B, JORDAN, W H, MCCOLLOM, K A Atomic Safety and Licensing Board Panel 83/10/06 Texas Utilities Generating Co. 9pp 20666 131 24X Fiche 50-445, 83/10/06, 8310110266
- 8310110322 Motion for reconsideration of ASLB 830923 memorandum & order affirming declaration of intervenor default of contentions re emergency planning, QA/QC & Board issues Certificate of Svc encl
REYNOLDS, N S, HORIN, W A Texas Utilities Generating Co
REYNOLDS, N S Debevoise & Liberman, 83/10/06 Atomic Safety and Licensing Board Panel 49pp 20666 002 24X Fiche 50-445, 83/10/06, 8310110322
- 8310130031 Motion for reconsideration of 830923 memorandum & order re emergency planning, QA & Board issues ASLB erred in retaining jurisdiction over emergency planning. Record should be closed Certificate of Svc encl
ROTHSCHILD, M U Hearing Branch 1 83/10/06 Atomic Safety and Licensing Board Panel 15pp 20726: 259 24X Fiche 50-445, 83/10/06, 8310130031
- 8310130167 Memorandum cautioning parties not to place great weight on ASLB characterization of LBP-83-63 as partial initial decision, in determining appealability of LBP-83-63 as matter of right
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel, 83/10/11 4pp 20724 293 24X Fiche 50-445, 83/10/11, 8310130167
- 8310170412 Forwards telecopy facsimile of RO Tolson affidavit responding to ASLB questions re computerization of nonconformances Original forthcoming
REYNOLDS, N S Debevoise & Liberman, REYNOLDS, N S, Texas Utilities Generating Co 83/10/11 BLOCH, P B, JORDAN, W H, MCCOLLOM, K A Atomic Safety and Licensing Board Panel 5pp 20784: 103, 24X Fiche 50-445, 83/10/11, 8310170412
- 8310170417 Supports NRC opposition to Citizens Assoc for Sound Energy 830929 motion to require presence of NRC Region IV Director, Div of Resident Reactor Project & Engineering Programs, J Gagliardo at 831017 hearings
REYNOLDS, N S Debevoise & Liberman, REYNOLDS, N S, Texas Utilities Generating Co 83/10/11 BLOCH, P B, JORDAN, W H, MCCOLLOM, K A Atomic Safety and Licensing Board Panel 1p 20784 108 24X Fiche 50-445, 83/10/11, 8310170412
- 8310170488 Answer to Citizens Assoc for Sound Energy 830929 motion to require testimony of JE Gagliardo Testimony may not be required since exceptional circumstances not shown Certificate of Svc encl
ROTHSCHILD, M U Hearing Branch 1 83/10/11 Atomic Safety and Licensing Board Panel 8pp 20784 093 24X Fiche 50-445, 83/10/11, 8310170488
- 8310140018 Memorandum inviting parties to file briefs by 831104 on relationship to DL proceeding of Board Notification 82-103A re NRC evaluation of allegations of potential design deficiencies in Class I piping
BLOCH, P B Atomic Safety and Licensing Board Panel 83/10/12 1p 20768 065 24X Fiche 50-445, 83/10/12, 8310140018
- 8310140083 Memorandum re Citizens Assoc for Sound Energy 830926 request for info re potential conflict of interest of Judge McCollom indirect interest in funds contributed by Brown & Root inconsequential
BLOCH, P B, JORDAN, W H Atomic Safety and Licensing Board Panel 83/10/12 4pp 20767 046 24X Fiche 50-445, 83/10/12, 8310140083
- 8310140085 Advises that Halliburton Foundation grant monies do not constitute conflict of interest for author as member of ASLB Contribution is small & author does not receive any funds for personal use from Foundation
MCCOLLOM, K A Oklahoma State Univ 83/10/03 BLOCH, P B Atomic Safety and Licensing Board Panel 2pp 20767 050 24X Fiche 50-445, 83/10/12, 8310140083
- 8310170577 Advises that Ofc of Investigations is conducting several ongoing investigations involving plant Ofc will provide oral presentation of investigations in camera ex parte when ASLB meets in Arlington, TX for 831017 hearings
HAYES, B B Office of Investigation 83/10/13 BLOCH, P B Atomic Safety and Licensing Board Panel 1p 20780 188 24X Fiche 50-445, 83/10/13, 8310170577
- 8310180339 Requests stipulations/admissions to authenticity of documents attached as offer of proof to Citizens Assoc for Sound Energy motion to add new contention & motion for discovery
ELLIS, J Citizens Association for Sound Energy 83/10/13 REYNOLDS, N S Lowenstein, Neuman, Reis, Axelrad & Toll 3pp 20805 019 24X Fiche 50-445, 83/10/13, 8310180339
- 8310180342 Motion to add proposed Contention 26 re hot functional test, motion for discovery & offer of proof Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 83/10/13 Atomic Safety and Licensing Board Panel 497pp 20805 022 24X Fiche 50-445, 83/10/13, 8310180339
- 8310180158 Forwards stipulation re allegations of discouraging identification of nonconforming conditions, per ASLB request
HORIN, W A Debevoise & Liberman, HORIN, W A Texas Utilities Generating Co 83/10/14 BLOCH, P B, JORDAN, W H, MCCOLLOM, K A Atomic Safety and Licensing Board Panel 1p 20809 029 24X Fiche 50-445, 83/10/14, 8310180158
- 8310180163 Stipulation on results of util employee interviews re allegations of discouragement of reporting nonconforming conditions
TREBY, S A Hearing Branch 1 PREISTER, D J Texas, State of HORIN, W A Texas Utilities Generating Co 83/10/11 6pp 20809 030 24X Fiche 50-445, 83/10/14, 8310180158
- 8310250260 Forwards unexecuted affidavits of WP Chen & JI Tapia on open items re Walsh/Doyle concerns
MIZUNO, G S Hearing Branch 1 83/10/14 BLOCH, P B, JORDAN, W H, MCCOLLOM, K A Atomic Safety and Licensing Board Panel 89pp 20898 269 24X Fiche 50-445, 83/10/14, 8310250260
- 8310250295 Forwards calculations for support (CC-1-028-039-533R) & SIT checklist utilized in independent design verification of 100 pipe supports w/o encl
MIZUNO, G S Hearing Branch 1 83/10/14 ELLIS, J Citizens Association for Sound Energy 1p 20895 342 24X Fiche 50-445, 83/10/14, 8310250295

DOCKETED ITEMS

8310250489 Forwards IE Insp Repts 50-445/83-27, 50-445/83-28 & 50-446/83-14 re RL Messerley allegations of improper const practices w/o encls
ROTHSCHILD, M U Hearing Branch 1 83/10/14 BLOCH, P B
JORDAN, W H, MCCOLLUM, K A Atomic Safety and Licensing Board Panel
1p 20902 070 24X Fiche 50-445, 83/10/14, 8310250489

8310210184 Forwards original signature page of RG Tolson 831011 affidavit re computerization of nonconformances
HORIN, W A Debevoise & Liberman HORIN, W A Texas Utilities Generating Co 83/10/19 STUCKY, S W Docketing & Services Branch
1p 20855 115 24X Fiche 50-445, 83/10/19, 8310210184

--8310210196 Original signature page of RG Tolson of 831011 affidavit re computerization of nonconformances
TOLSON, R G Texas Utilities Generating Co 83/10/11 1p
20855 116 24X Fiche 50-445, 83/10/19, 8310210184

8310280059 Forwards 831022 & 0923 news articles re illegal firing of GC inspector & adequacy of emergency sirens, respectively
ELLIS, J Citizens Association for Sound Energy 83/10/24
BLOCH, P B JORDAN, W H, MCCOLLUM, K A Atomic Safety and Licensing Board Panel 7pp 20933 332 24X Fiche 50-445, 83/10/24, 8310280059

8310270228 Memorandum on adopted procedure re QA hearings to be conducted for finished safety sys. Cigna rept & applicant followup insp of protective coatings Citizens Assoc for Sound Energy will file allegations on QA deficiencies
BLOCH, P B JORDAN, W H, MCCOLLUM, K A Atomic Safety and Licensing Board Panel 83/10/25 3pp 20924 071 24X Fiche 50-445, 83/10/25, 8310270228

8310270293 Memorandum & order LRP-83-67, instructing util to inspect sample of Westinghouse coatings & to submit further evidence re plug welds & further testimony or proposals responding to other adverse findings in ASLB 830923 memorandum & order
BLOCH, P B JORDAN, W H, MCCOLLUM, K A Atomic Safety and Licensing Board Panel 83/10/25 Texas Utilities Generating Co 14pp
20923 207 24X Fiche 50-445, 83/10/25, 8310270293

8310280070 Memorandum informing that directed certification of ASLB 831006 partial initial decision may still be sought ASLB will continue to treat order as totally interlocutory
SHOMAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/27 Atomic Safety and Licensing Appeal Panel 3pp 20935 061 24X Fiche 50-445, 83/10/27, 8310280070

K Utility Final Safety Analysis Report (FSAR) & amends

8310180179 Forwards revised pages to FSAR Amend 41, Chapter 17 re Westinghouse QA organization Revs reflect changes to QA program description
GARY, R J Texas Utilities Generating Co 83/08/12 COLLINS, J T Region 4, Office of Director 1p 20808 352 24X Fiche 50-445, 83/08/12, 8310180179

--8310180183 Errata to FSAR Amend 41, Chapter 17 re Westinghouse QA organization
* Texas Utilities Generating Co 83/07/11 5pp 20808 353 24X Fiche 50-445, 83/08/12, 8310180179

8310140180 Amend 44 to FSAR W/831010 ltr
GARY, R J Texas Utilities Generating Co 83/10/10 DENION, H R Office of Nuclear Reactor Regulation, Director 332pp 20765 095 24X Fiche 50-445, 83/10/10, 8310140180

8310200149 Forwards affidavit of svc of Amend 44 to FSAR
SCHMIDT, H C Texas Utilities Services, Inc 83/10/11 DENION, H R Office of Nuclear Reactor Regulation, Director 4pp 20836 322 24X Fiche 50-445, 83/10/11, 8310200149

G Inspection reports, IE Bulletins & correspondence

8310040223 Forwards IE Insp Repts 50-445/83-24 & 50-446/83-15 on 830301-0731
MADSEN, G L Region 4, Office of Director 83/08/24 GARY, R J Texas Utilities Generating Co 2pp 20614 239 24X Fiche 50-445, 83/08/24, 8310040223

--8310040240 IE Insp Repts 50-445/83-24 & 50-446/83-15 on 830301-0731 No noncompliance noted Insp confirmed need to issue violations re HVAC equipment installation, document control & equipment in storage
TAYLOR, R G, HUNNICUTT, D M Region 4, Office of Director 83/08/19 23pp 20614, 241, 24X Fiche 50-445, 83/08/24, 8310040223

8310030395 Forwards notice of violation & proposed imposition of civil penalty in amount of \$40,000 based on violation of employee protection provisions of Energy Reorganization Act of 1974
COLLINS, J T Region 4, Office of Director 83/08/29 GARY, R J Texas Utilities Generating Co 3pp 20593 078 24X Fiche 50-445, 83/08/29, 8310030395

--8310030411 Notice of violation & proposed imposition of civil penalty based on Dept of Labor 830610 determination that Brown & Root QA program failed to provide sufficient organizational freedom to QA inspectors
COLLINS, J T Region 4, Office of Director 83/08/29 2pp 20593 081 24X Fiche 50-445, 83/08/29, 8310030395

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310050403 Responds to 830829 notice of violation & proposed imposition of civil penalty in amount of \$40,000 (EA-83-64) re alleged violation of 10CFR50, App B, Criterion 1 Answer protesting civil penalty encl
GARY, R J Texas Utilities Generating Co 83/09/28 DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement. 26pp 20873 037 24X Fiche 50-445, 83/09/28, 8310050403

--8310050412 Response opposing imposition of civil penalty in amount of \$40,000 for alleged violation of 10CFR50, App B, Criterion 1 Requests proposed civil penalty be withdrawn or mitigated in full
* Texas Utilities Generating Co 83/09/28 Commissioners 10pp 20630 130 24X Fiche 50-445, 83/09/28, 8310050403

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc 115pp. 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310180218 Forwards IE Insp Repts 50-445/83-28 & 50-446/83-14 on 830627-0916 No noncompliance noted
MADSEN, G L Region 4, Office of Director. 83/10/03. GARY, R J Texas Utilities Generating Co 2pp 20808 270 24X Fiche 50-445, 83/10/03, 8310180218

--8310180227 IE Insp Repts 50-445/83-28 & 50-446/83-14 on 830627-0916. No noncompliance noted Major areas inspected followup on Const Appraisal Team Insp Repts 50-445/83-18 & 50-446/83-12
MARTIN, L. E., HUNNICUTT, D M Region 4, Office of Director 83/09/23 35pp 20808 272 24X Fiche 50-445, 83/10/03, 8310180218

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378.

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8310310256 Forwards IE Mgt Meeting Repts 50-445/83-37 & 50-446/83-19 on 830908 No noncompliance noted
MADSEN, G L Region 4, Office of Director 83/10/07. GARY, R J Texas Utilities Generating Co 2pp 20947 171 24X Fiche 50-445, 83/10/07, 8310310256

--8310310264 IE Mgt Meeting Repts 50-445/83-37 & 50-446/83-19 on 830908 No noncompliance noted Major areas discussed & inspected: emergency preparedness appraisal & emergency response facilities equipment
BAIRD, J B, HUNNICUTT, D M Region 4, Office of Director 83/10/05 2pp 20947 173 24X Fiche 50-445, 83/10/07, 8310310256

DOCKETED ITEMS

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Past 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Past 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

S Reportable occurrences, LERs & related correspondence

8310130278 Final deficiency rept re pipe wall thickness of reactor coolant pressurizer surge line Initially reported on 821101
Deficiency not reportable per IOCFR50.55(e)
GARY, R J Texas Utilities Generating Co 82/11/23 MADSEN, O L
Region 4, Office of Director 1p 20723 197 24X
Fiche 50-445, 82/11/23, 8310130278

8310130268 Interim deficiency rept re temp in excess of FSAR parameters experienced in annulus between reactor vessel insulation & shield wall Cooling increased by reducing chilled water temp & installing addl cooling coil
GARY, O L Texas Utilities Generating Co 83/09/26 MADSEN, O L
Region 4, Office of Director 2pp 20723 215 24X
Fiche 50-445, 83/09/26, 8310130268

8310030516 Advises of meeting tentatively scheduled for 831013 w/util, Westinghouse & NRC to discuss Pacific Pump multi-vane diffuser linear indications
GARY, R J Texas Utilities Generating Co 83/10/01 MADSEN, O L
Region 4, Office of Director 1p 20401 200 24X
Fiche 50-445, 83/10/01, 8310030516

8310280003 Final deficiency rept re premature corrosion of valves in svc water sys Initially reported on 820919 Investigation complete Item not reportable under IOCFR50.55(e)
GARY, R J Texas Utilities Generating Co 83/10/17 JOHNSON, F
Region 4, Office of Director 1p 20933 330 24X
Fiche 50-445, 83/10/17, 8310280003

T. Hearing transcripts on non-antitrust matters

8310140022 Forwards testimony of RO Tolson & OR Purdy re NRC insp of fuel bldg & design change verification
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Texas Utilities
Generating Co 83/10/12 BLOCH, P B, JORDAN, W H, MCCOLLUM, K A
Atomic Safety and Licensing Board Panel 1p 20768 066 24X
Fiche 50-445, 83/10/12, 8310140022

--8310140024 Testimony of RO Tolson & OR Purdy re NRC insp of fuel bldg & design change verification
TOLSON, R O, PURDY, O R Texas Utilities Generating Co PURDY, O R
Brown & Root Corp (subs of Halliburton Corp.) 83/10/12 10pp
20768 067 24X Fiche 50-445, 83/10/12, 8310140022

8310170683 Testimony of TF Westerman, CR Oberg, JE Bess, CC Johnson, JI Tapia, KA Whittlesby & RO Taylor re findings of 830523-0610 special insp of fuel bldg Prof qualifications encl.
WESTERMAN, T F, OBERG, C R Region 4, Office of Director BESS, J E
Division of Resident, Reactor Project & Engineering Programs
83/10/12 14pp 20779 232 24X Fiche 50-445, 83/10/12, 8310170683

--8310170688 Testimony of RO Taylor re relationship between as-built certified design & vendor certified design Certificate of Svc encl
TAYLOR, R O Region 4, Office of Director 83/10/12 10pp
20779 246 24X Fiche 50-445, 83/10/12, 8310170688

8310210057 Transcript of 831017 hearing in Fort Worth, TX. Pp B. 751-8, 925, Supporting documentation encl.
* Commissioners. 83/10/17 273pp 20857, 276 24X
Fiche 50-445, 83/10/17, 8310210057

8310210059 Transcript of 831018 hearing in Fort Worth, TX Pp B. 928-9, 075, Supporting documentation encl
* Commissioners. 83/10/18 78pp 20858 265 24X
Fiche 50-445, 83/10/18, 8310210059

8310250103 Transcript of 831021 telcon in Bethesda, MD Pp 9, 076-9, 134
* Atomic Safety and Licensing Board Panel. 83/10/21 60pp
20896 186 24X Fiche 50-445, 83/10/21, 8310250103

U Congressional/Executive Correspondence

8310200062 Responds to 830913 ltr re investigation of QA/QC program at facility
PALLADINO, N J Commissioners 83/10/07 UDALL, M K House of Rep ,
Interior & Insular Affairs 3pp 20872 280 24X
Fiche 50-445, 83/10/07, 8310200062

--8310200073 Requests copies of listed documents re QA/QC program problems at facility
UDALL, M K House of Rep , Interior & Insular Affairs 83/09/17
PALLADINO, N J Commissioners 2pp 20873 093 24X
Fiche 50-445, 83/10/07, 8310200062

DOCKET STN-50-447 GESSAR-23B

A Application/construction stage documents & correspondence

8310210342 Notification of 831017 meeting w/vendor & BNL in Bethesda, MD to discuss vendor response to NRC question re GESSAR-II PRA & recent seismic events analysis submittal
SCALET, D C Standardization & Special Projects Branch 83/10/12
THOMAS, C D Standardization & Special Projects Branch 2pp
20883 143 24X Fiche 50-447, 83/10/12, 8310210342

E NRC Safety Evaluation Report (SER), suppls & correspondence

8310260206 Forwards Amend 20 to GESSAR-II, responding to Confirmatory Issue 18 of SER, Suppl 1 to NUREG-0979, revised responses to NRC 820825 ltr re communication & lighting sys & updating interface tables of Subsection 1.9.1
SHERWOOD, O G General Electric Co 83/10/04 EISENHUT, D O
Division of Licensing 3pp 20909 001 24X Fiche 50-447, 83/10/04, 8310260206

--8310260211 Amend 20 to GESSAR-II
* General Electric Co 83/10/04 205pp 20909 004 24X
Fiche 50-447, 83/10/04, 8310260206

K Utility Final Safety Analysis Report (FSAR) & amends

8310260106 Forwards proprietary Rev 20 to GESSAR-II re environ qualification of safety-related equipment Rev should be withheld (ref IOCFR2.790) Affidavit encl
SHERWOOD, O G General Electric Co 83/10/04 EISENHUT, D O
Division of Licensing 6pp 20912 097 24X Fiche 50-447, 83/10/04, 8310260106

8310260206 Forwards Amend 20 to GESSAR-II, responding to Confirmatory Issue 18 of SER, Suppl 1 to NUREG-0979, revised responses to NRC 820825 ltr re communication & lighting sys & updating interface tables of Subsection 1.9.1
SHERWOOD, O G General Electric Co 83/10/04 EISENHUT, D O
Division of Licensing 3pp 20909 001 24X Fiche 50-447, 83/10/04, 8310260206

--8310260211 Amend 20 to GESSAR-II
* General Electric Co 83/10/04 205pp 20909 004 24X
Fiche 50-447, 83/10/04, 8310260206

DOCKET STN-50-454 BYRON STATION, UNIT 1

A Application/construction stage documents & correspondence

8308300355 Board Notification 83-66A advises that position re rod drop issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycle
EISENHUT, D O Division of Licensing 83/09/29 PALLADINO, N J,
GILINSKY, V, ROBERTS, T M Commissioners 10pp 20632 106 24X
Fiche 50-000, 83/09/29, 8308300355

8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway
EISENHUT, D O Division of Licensing 83/09/29 PALLADINO, N J
Commissioners 3pp 20632 001 24X Fiche 50-000, 83/09/29, 8308300357

8310110605 Notification of 831013 meeting w/util in Bethesda, MD to discuss control room human factors review
OLSHAN, L N Licensing Branch 1. 83/09/29 YOUNGBLOOD, D J
Licensing Branch 1 3pp 20714 349 24X Fiche 50-454, 83/09/29, 8310110605

DOCKETED ITEMS

8308300763 Board Notification 83-151 provides info re desirability of current ECCS actuation logic for Westinghouse plants, in light of recent info concerning steam generator tube rupture procedure for Borssele Nuclear Power Station
EISENHUT, D G Division of Licensing 83/10/04 PALLADINO, N J Commissioners 2pp 20676 03J 24X Fiche 50-000, 83/10/04, 8308300763

8310130049 Notification of date change from 831013 to 831026 for meeting w/utl to discuss control room factors review
OLSHAN, L N Licensing Branch 1 83/10/04 YOUNGBLOOD, B J Licensing Branch 1 3pp 20776 231 24X Fiche 50-454, 83/10/04, 8310130049

8310200273 Forwards schedules for equipment qualification test program for facilities, per 810528 ltr Dates given for current qualification activities should be viewed as "target dates" & not as firm dates
BARNES, P L Commonwealth Edison Co 83/10/05 KFFPLER, J C Region 3, Office of Director 10pp 20830 034 24X Fiche 50-000, 83/10/05, 8310200273

8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves
EISENHUT, D G Division of Licensing 83/10/06 PALLADINO, N J Commissioners 31pp 20818 001 24X Fiche 50-000, 83/10/06, 8308300771

8310240031 Notification of 831117 meeting w/utl in Bethesda, MD to discuss turbine maint program for turbine missile issue
OLSHAN, L N Licensing Branch 1 83/10/14 YOUNGBLOOD, B J Licensing Branch 1 3pp 20903 242 24X Fiche 50-454, 83/10/14, 8310240031

8310310060 Submits info re Edison rod swap analysis method for review & approval Methods employed in support of control rod worth measurements using rod swap technique during reload physics testing Criteria tables encl
LENTINE, F G Commonwealth Edison Co 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 20951 024 24X Fiche 50-000, 83/10/24, 8310310060

E NRC Safety Evaluation Report (SER), suppls & correspondence

8310120427 Requests review of Westinghouse rept, "Use of Process Noise Measurements to Determine Response Characteristics in US Plant" & approval of use of process noise sensor response time Noise measurement acceptable per EFR, Section 7.2.2.5
TRAMM, T R Commonwealth Edison Co 83/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20699 043 24X Fiche 50-000, 83/09/28, 8310120427

F Security, medical, emergency & fire protection plans

8310210234 Forwards Amend 2 to fire protection rept Amend incorporates info re instrumentation, communications & suppression sys & addl info & commitments responding to NRC concerns from fire protection audit
TRAMM, T R Commonwealth Edison Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 20853 015 24X Fiche 50-000, 83/10/13, 8310210234

--8310210236 Amend 2 to fire protection rept, incorporating info re instrumentation, communications & suppression sys & addl info & commitments responding to NRC concerns from fire protection audit
* Commonwealth Edison Co 83/10/31, 200pp 20853 023 24X Fiche 50-000, 83/10/31, 8310210236

8310270526 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20937 216 24X Fiche 50-000, 83/10/21, 8310270526

--8310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure EDF-6, "Administration & Logistics Manager" W/831017 ltr & receipt form
NELLIS, C A Commonwealth Edison Co 83/02/18 DENTON, H R NRC - No Detailed Affiliation Given 7pp 20937, 217 24X Fiche 50-000, 83/10/21, 8310270526

8310280307 Releases public version of revised generating stations emergency plan telephone directory.
FELTON, J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20963 126 24X Fiche 50-000, 83/10/25, 8310280307

--8310280314 Public version of revised generating stations emergency plan telephone directory
GALLE, D P Commonwealth Edison Co 83/08/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 64pp 20963 127 24X Fiche 50-000, 83/10/25, 8310280307

8310280191 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/26 Document Management Branch 1p 20962 266 24X Fiche 50-000, 83/10/26, 8310280191

--8310280209 Public version of Rev 1 to Emergency Plan Implementing Procedure EDF-15, "Emergency Operations Facility Activation"
MOORE, R D Commonwealth Edison Co 83/08/02 50pp 20962 267 24X Fiche 50-000, 83/10/26, 8310280191

G Adjudicatory correspondence

8310040205 Partial proposed findings of fact & conclusions of law on Contention 1A Certificate of Evc encl
WHICHER, J M League of Women Voters of Rockford, IL WHICHER, J M DeKalb Area Alliance for Responsible Energy WHICHER, J M Mississippi Alliance for the Environment (SAFE) 83/09/30, 44pp 20614 280 24X Fiche 50-454, 83/09/30, 8310040205

8310050452 Forwards NRC proposed supplemental findings of fact & conclusions of law on GA/GC issues & list of proposed transcript corrections
YOUNG, M A Hearing Branch 4 83/09/30 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 20630 001 24X Fiche 50-454, 83/09/30, 8310050452

--8310050468 Proposed supplemental findings of fact & conclusions of law on GA/GC issues
YOUNG, M A Hearing Branch 4 83/09/30 34pp 20630 002 24X Fiche 50-454, 83/09/30, 8310050452

--8310050475 Proposed transcript corrections for 830810-12 hearings, Certificate of Evc encl
YOUNG, M A Hearing Branch 4 83/09/30 4pp 20630 036 24X Fiche 50-454, 83/09/30, 8310050452

8310060319 Forwards util addl proposed findings of fact & conclusions of law re GA & GC
FURSE, M C Isham, Lincoln & Beale, FURSE, M C Commonwealth Edison Co 83/09/30 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 20646 232 24X Fiche 50-454, 83/09/30, 8310060319

--8310060321 Addl proposed findings of fact & conclusions of law re GA/GC Certificate of Evc encl
MILLER, M J, BECKER, B D, FURSE, M C Commonwealth Edison Co, 83/09/30 31pp 20646 233, 24X Fiche 50-454, 83/09/30, 8310060319

8310050440 Forwards IE Insp Repts 50-454/83-41 & 50-455/83-31 on 830701-0831 Insp investigated allegations re Hatfield Electric Co
YOUNG, M A Hearing Branch 4, 83/10/03 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 8pp, 20633 340 24X Fiche 50-454, 83/10/03, 8310050440

8310050488 Memorandum taking official notice of publications of Illinois State Geological Survey
SMITH, I W Atomic Safety and Licensing Board Panel 83/10/03 47pp 20632 116 24X Fiche 50-454, 83/10/03, 8310050488,

8310060314 Advises of revised initial fuel load date, from 831201 to 840215 Rev attributable to unanticipated addl work required to complete piping supports & mods to ventilation duct work
MILLER, M J Isham, Lincoln & Beale MILLER, M J Commonwealth Edison Co 83/10/03 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 20641 008, 24X Fiche 50-454, 83/10/03, 8310060314

8310170346 Advises that util does not object to ABLB taking official notice of EPA rept, "Protective Action Evaluation Part 11, Evacuation & Sheltering as Protective Actions Against Nuclear Accidents Involving Gaseous Releases" Part 1 encl
COPELAND, V G Isham, Lincoln & Beale COPELAND, V G Commonwealth Edison Co, 83/10/10 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel, 2pp 20786:030 24X Fiche 50-454, 83/10/10, 8310170346.

--8310170356 Affidavit of DD Ed, clarifying testimony re EPA rept, "Protective Action Evaluation Part 11, Evacuation & Sheltering as Protective Actions Against Nuclear Accidents Involving Gaseous Releases."
ED, D D Commonwealth Edison Co ED, D D Illinois, State of, 83/10/10 119pp 20786, 032, 24X Fiche, 50-454, 83/10/10, 8310170346

DOCKETED ITEMS

B310130014 Response to ASLB B30920 memorandum advising of intent to take official notice of emergency planning witness testimony NRC has no objection to notice Certificate of Svc encl
YOUNG, M A Hearing Branch 4 B3/10/11 Atomic Safety and Licensing Board Panel App 20725 204 24X Fiche 50-454, B3/10/11, B310130014

B310140067 Response to DC Thomas motion to strike proposed findings of fact & conclusions of law & to withdraw as Rockford League of Women Voters counsel Rockford objects to motion to strike but not to withdrawal Related correspondence
LEWIS, E League of Women Voters of Rockford, IL B3/10/13 Atomic Safety and Licensing Board Panel 2pp 20768 009 24X Fiche 50-454, B3/10/13, B310140067

--B310140070 Motion to strike Rockford League of Women Voters proposed findings of fact & conclusions of law & for leave to withdraw as Rockford counsel Rockford told counsel of dissatisfaction w/ findings Related correspondence
THOMAS, D C League of Women Voters of Rockford, IL THOMAS, D C Thomas, D C B3/10/13 1p 20768 011 24X Fiche 50-454, B3/10/13, B310140067

B310180275 Forwards applicant reply to Joint intervenors partial proposed findings of fact & conclusions of law on Contention 1A
FURSE, M C Isham, Lincoln & Beale FURSE, M C Commonwealth Edison Co B3/10/14 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 20807 003 24X Fiche 50-454, B3/10/14, B310180275

--B310180279 Reply to Joint intervenors partial proposed findings of fact & conclusions of law on Contention 1A intervenors findings misleading & inaccurate & should not be adopted Certificate of Svc encl
FURSE, M C, BECKER, B D Commonwealth Edison Co FURSE, M C Isham, Lincoln & Beale B3/10/14 2pp 20807 004 24X Fiche 50-454, B3/10/14, B310180275

B310200077 Reply to util supplemental findings of fact & conclusions of law on OA/GC Certificate of Svc encl
WHICHER, J M DeKalb Area Alliance for Responsible Energy WHICHER, J M WhicHER, J M WHICHER, J M Sinmissippi Alliance for the Environment (SAFE) B3/10/17 12pp 20836 048 24X Fiche 50-454, B3/10/17, B310200077

B310250486 Forwards reply to Joint intervenors partial proposed findings of fact & conclusions of law re OA/GC
YOUNG, M A Hearing Branch 4 B3/10/17 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 20902 090 24X Fiche 50-454, B3/10/17, B310250486

--B310250504 Response to Joint intervenors B30930 partial proposed findings of fact & conclusions of law re OA/GC Findings should be rejected Certificate of Svc encl
YOUNG, M A Hearing Branch 4 B3/10/17 Atomic Safety and Licensing Board Panel 12pp 20902 091 24X Fiche 50-454, B3/10/17, B310250486

B310210204 Advises of author absence on B31109 D Cassel will be contact for intervenor group
WHICHER, J M Businessmen for the Public Interest B3/10/18 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 20852 102 24X Fiche 50-454, B3/10/18, B310210204

--B310210219 Motion for limited discovery against NRC & util re B40215 projected fuel load date Date critical to proceeding at present stage
WHICHER, J M DeKalb Area Alliance for Responsible Energy WHICHER, J M Sinmissippi Alliance for the Environment (SAFE) WHICHER, J M WhicHER, J M B3/10/18 Atomic Safety and Licensing Board Panel 8pp 20852 103 24X Fiche 50-454, B3/10/18, B310210204

10250513 Forwards corrected Page 2 of reply to Joint intervenors partial proposed findings of fact & conclusions of law on OA/GC
YOUNG, M A Hearing Branch 4 B3/10/18 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 0901 258 24X Fiche 50-454, B3/10/18, B310250513

B310250520 Corrected Page 2 of reply to Joint intervenors proposed findings of fact & conclusions of law on OA/GC.
* Office of the Executive Legal Director B3/10/18 1p 20901 259 24X Fiche 50-454, B3/10/18, B310250513

0250117 Forwards IE Insp Repts 50-454/B3-38 & 50-455/B3-28 addressing Hughes allegations re welding of cable support by & B30804 mgt meeting on reinsp program
YOUNG, M A Hearing Branch 4 B3/10/21 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 0899 240 24X Fiche 50-454, B3/10/21, B310250117

B310310127 Withdrawal of previous response to own counsel motion to strike proposed findings of fact & conclusions of law Motion to strike never filed but mailed to svc list to intimidate intervenor into paying disputed fee Related correspondence
LEWIS, E League of Women Voters of Rockford, IL B3/10/27 Atomic Safety and Licensing Board Panel 3pp 20949 107 24X Fiche 50-454, B3/10/27, B310310127

H General correspondence

B310030347 Package of four public comments opposing plant const & licensing
CAMPBELL, B E, BEARLE, L K Sinmissippi Alliance for the Environment (SAFE) B3/09/29 SMITH, J W Atomic Safety and Licensing Board Panel 8pp 20590 156 24X Fiche 50-454, B3/09/29, B310030347

K Utility Final Safety Analysis Report (FSAR) & amends

B310040554 Forwards affidavit certifying distribution of FSAR, Amend 4/2 per NRC 781020 ltr
TRAMM, T R Commonwealth Edison Co B3/09/28 DENFON, H R Office of Nuclear Reactor Regulation, Director 2pp 20623 210 24X Fiche 50-000, B3/09/28, B310040554

G Inspection reports, IE Bulletins & correspondence

B310170525 Forwards IE Insp Repts 50-454/B3-38 & 50-455/B3-28 on B30803-04 & 08 No noncompliance noted
KNOP, R C Region 3, Office of Director B3/09/01 REED, C Commonwealth Edison Co 2pp 20784 192 24X Fiche 50-454, B3/09/01, B310170525

--B310170529 IE Insp Repts 50-454/B3-38 & 50-455/B3-28 on B30803-04 & 08 No noncompliance noted Major areas inspected followup on allegations re station electrical contractor, including exam of procedures & records, observations & interviews
HAYES, D W, KNOP, R C Region 3, Office of Director B3/09/01 5pp 20784 194 24X Fiche 50-454, B3/09/01, B310170525

B310040424 Forwards IE Insp Repts 50-454/B3-41 & 50-455/B3-31 on B30701-0831 No noncompliance noted
KNOP, R C Region 3, Office of Director B3/09/23 REED, C Commonwealth Edison Co 2pp 20619 117 24X Fiche 50-454, B3/09/23, B310040424

--B310040430 IE Insp Repts 50-454/B3-41 & 50-455/B3-31 on B30701-0831 No noncompliance noted Major areas inspected preoperational testing operations & procedures, IE circular file responses & licensee actions on previously identified items
CONNOR, HAYES, D W Region 3, Office of Director B3/09/23 5pp 20619 119 24X Fiche 50-454, B3/09/23, B310040430

B308300340 IE Info Notice B3-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, B3/09/26, B308300340

B308300342 IE Info Notice B3-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, B3/09/26, B308300342

B308300345 IE Info Notice B3-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, B3/09/26, B308300345

B310040257 Ack receipt of B30926 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-454/B3-33
Concurs w/ util opinion that violations should be categorized as Severity Level V
LITTLE, W S Region 3, Office of Director B3/09/28 REED, C Commonwealth Edison Co 1p 20614 064 24X Fiche 50-454, B3/09/28, B310040257

--B310040260 Responds to NRC B30822 ltr re violations noted in IE Insp Rept 50-454/B3-33 Corrective actions number number corrected in rev to test procedure Violation should be categorized as Severity Level V
FARRAR, D L Commonwealth Edison Co B3/09/26 KEPLER, J Q Region 3, Office of Director 3pp 20614 065 24X Fiche 50-454, B3/09/28, B310040257

DOCKETED ITEMS

34

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o LOCFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349

8310140179 Forwards IE Insp Rept 50-454/83-39 on 830808-12,16-17 & 0907-09 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/09/29 REED, C
Commonwealth Edison Co 2pp 20765 070 24X Fiche 50-454,83/09/29,8310140179

--8310140192 IE Insp Rept 50-454/83-37 on 830808-12,16-17 & 0907 07
No noncompliance noted Major areas inspected licensee action on previously identified items re reinsp program for Powers-Airco-Pope & Hatfield Electric Co
LOVE, R S, WILLIAMS, C C Region 3, Office of Director 83/09/28 13pp 20765 032 24X Fiche 50-454,83/09/29,8310140179

8310190266 Forwards IE Integrated Design Insp Rept 50-454/83-32 on 830523-0610 & 20-30 Findings re errors, procedural violations & inconsistencies identified in rept
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/09/30 REED, C Commonwealth Edison Co 6pp 20842 054 24X Fiche 50-454,83/09/30,8310190266

--8310190270 IE Integrated Design Insp Rept 50-454/83-32 on 830523-0610 & 20-30 Major areas inspected mechanical sys & components, electrical power, instrumentation & control & civil & structural engineering
ALLISON, D P Director's Office, Office of Inspection and Enforcement MILMOAN, J L GA Branch 83/09/29 228pp 20842 060 24X Fiche 50-454,83/09/30,8310190266

8310050440 Forwards IE Insp Repts 50-454/83-41 & 50-455/83-31 on 830701-0831 Insp investigated allegations re Hatfield Electric Co
YOUNG, M A Hearing Branch 4 83/10/03 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 8pp 20633 340 24X Fiche 50-454,83/10/03,8310050440

8310200124 Forwards IE Mgt Meeting Repts 50-010/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-275/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIUS, C E Division of Project & Resident Programs 83/10/04 REED, C Commonwealth Edison Co 2pp 20834 098 24X Fiche 50-000,83/10/04,8310200124

--8310200148 IE Mgt Meeting Repts 50-020/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-275/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIUS, C E Division of Project & Resident Programs 83/10/03 4pp 20834 100 24X Fiche 50-000,83/10/04,8310200124

8310120302 Ack receipt of 830926 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/83-18 & 50-455/83-15
NORELIUS, C E Division of Project & Resident Programs 83/10/05 REED, C Commonwealth Edison Co 1p 20699 009 24X Fiche 50-454,83/10/05,8310120302

--8310120401 Supplis response to NRC 830526 ltr re violations noted in IE Insp Repts 50-454/83-18 & 50-455/83-15 Corrective actions nonconformance repts reviewed to determine whether FSAR change required & whether change actually made
FARRAR, D L Commonwealth Edison Co 83/09/26 KEPLER, J Q Region 3, Office of Director 2pp 20699 010 24X Fiche 50-454,83/10/05,8310120302

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

8310270128 Forwards IE Insp Repts 50-454/83-40 & 50-455/83-30 on 830811-0919 & notice of violation
STREETER, J F Region 3, Office of Director 83/10/11 REED, C Commonwealth Edison Co 2pp 20924 124 24X Fiche 50-454,83/10/11,8310270128

--8310270134 Notice of violation from insp on 830811-0919
STREETER, J F Region 3, Office of Director 83/10/11 2pp 20924 126 24X Fiche 50-454,83/10/11,8310270128

--8310270140 IE Insp Repts 50-454/83-40 & 50-455/83-30 on 830811-0919
Noncompliance noted failure to follow out-of-svc procedures for valve lineup of chemical & vol control sys
RING, M, VANDENBURGH, C, REYES, L A Region 3, Office of Director 83/10/11 10pp 20924 128 24X Fiche 50-454,83/10/11,8310270128

8310310134 Requests that util response to generic implications of audits of design implementation address program for all plants Util position may be included in response to integrated design insp rept
EISENHUT, D Q Division of Licensing 83/10/12 REED, C Commonwealth Edison Co 6pp 20965 318 24X Fiche 50-000,83/10/12,8310310134

8310180295 Clarifies NRC position re procedures for admitting NRC personnel to facilities List of personnel requiring access to vital areas encl Updates will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 REED, C Commonwealth Edison Co 7pp 20806 354 24X Fiche 50-454,83/10/14,8310180295

8308300777 Board Notification 83-157 forwards 831003 & 1012 memos re GA integrated design insp
NOVAK, T M Assistant Director for Licensing 83/10/17 Atomic Safety and Licensing Board Panel 2pp 20830 236 24X Fiche 50-454,83/10/17,8308300777

--8310200244 Responds to 830811 request for concurrence w/proposed ltr i util concluding programs re integrated design insp sufficient to assure design per FSAR & recommended addl design GA efforts Requirements for GA efforts listed
TAYLOR, J M Division of GA, Safeguards & Inspection Programs (Post 830103) 83/10/03 NOVAK, T M Division of Licensing 2pp 20830 238 24X Fiche 50-454,83/10/17,8308300777

--8310200248 Summarizes 830504 meeting w/util to determine if GA & design verification program sufficient to ensure design in accordance w/FSAR Response, including position re generic aspects of program requested
EISENHUT, D Q Division of Licensing 83/10/12 REED, C Commonwealth Edison Co 4pp 20830 240 24X Fiche 50-454,83/10/17,8308300777

B Reportable occurrences, LERs & related correspondence

8310170411 Interim deficiency rept re Westinghouse A-200 motor control ctrs Initially reported on 830909 All affected overload blocks identified by personnel will be replaced w/properly calibr overload blocks
SWARTZ, E D Commonwealth Edison Co 83/10/06 KEPLER, J Q Region 3, Office of Director 2pp 20784 019 24X Fiche 50-000,83/10/06,8310170411

8310170573 Final deficiency rept re Anaconda flexible conduit splitting Initially reported on 830909 Caused by exceeding specified bending radius & exposure to high temps during installation Conduit jackets covered by Okonite T-33 tape.
SWARTZ, E D Commonwealth Edison Co 83/10/06 KEPLER, J Q Region 3, Office of Director 2pp 20780 337 24X Fiche 50-000,83/10/06,8310170573

T Hearing transcripts on non-antitrust matters

8310050452 Forwards NRC proposed supplemental findings of fact & conclusions of law on GA/GC issues & list of proposed transcript corrections
YOUNG, M A Hearing Branch 4 83/09/30 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 20630 001 24X Fiche 50-454,83/09/30,8310050452

--8310050475 Proposed transcript corrections for 830810-12 hearings Certificate of Svc encl
YOUNG, M Hearing Branch 4 83/09/30 4pp 20630 036 24X Fiche 50-454,83/09/30,8310050452

DOCKETED ITEMS

DOCKET STN-50-455 BYRON STATION, UNIT 2

A Application/construction stage documents, & correspondence

8308300355 Board Notification 83-66A advises that position re rod drop issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycle
EISENHUT, D O Division of Licensing 83/09/29 PALLADINO, N J Commissioners 10pp 20632:106 24X Fiche 50-000, 83/09/29, 8308300355

8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class 1 piping sys info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway
EISENHUT, D O Division of Licensing 83/09/29 PALLADINO, N J Commissioners 3pp 20632 001 24X Fiche 50-000, 83/09/29, 8308300357.

8310110605 Notification of 831013 meeting w/util in Bethesda, MD to discuss control room human factors review
OLSHAN, L N Licensing Branch 1 83/09/29 YOUNGBLOOD, B J Licensing Branch 1 3pp 20714 349 24X Fiche 50-454, 83/09/29, 8310110605

8308300763 Board Notification 83-151 provides info re desirability of current ECCS actuation logic for Westinghouse plants, in light of recent info concerning steam generator tube rupture procedure for Borssele Nuclear Power Station
EISENHUT, D O Division of Licensing 83/10/04 PALLADINO, N J Commissioners 2pp 20698 033 24X Fiche 50-000, 83/10/04, 8308300763

8310130049 Notification of date change from 831013 to 831026 for meeting w/util to discuss control room factors review
OLSHAN, L N Licensing Branch 1 83/10/04 YOUNGBLOOD, B J Licensing Branch 1 3pp 20776 231 24X Fiche 50-454, 83/10/04, 8310130049

8310200273 Forwards schedules for equipment qualification test programs for facilities, per 810328 ltr Dates given for current qualification activities should be viewed as "target-dates" & not as firm dates
BARNES, P. L. Commonwealth Edison Co 83/10/05 KEPPLER, J O Region 3, Office of Director 10pp 20830-034 24X Fiche 50-000, 83/10/05, 8310200273

8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ABCO solenoid valves.
EISENHUT, D O Division of Licensing 83/10/06 PALLADINO, N J Commissioners 31pp 20818 001 24X Fiche 50-000, 83/10/06, 8308300771

8310240031 Notification of 831117 meeting w/util in Bethesda, MD to discuss turbine maint program for turbine missile issue
OLSHAN, L N Licensing Branch 1 83/10/14 YOUNGBLOOD, B J Licensing Branch 1 3pp 20903 242 24X Fiche: 50-454, 83/10/14, 8310240031

8310310060 Submits info re Edison rod swap analysis method for review & approval. Methods employed in support of control rod worth measurements using rod swap technique during reload physics testing. Criteria tables encl.
LENTINE, F O. Commonwealth Edison Co 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 20951-024 24X Fiche 50-000, 83/10/24, 8310310060

E. NRC Safety Evaluation Report (BER), suppl's & correspondence

831020427 Requests review of Westinghouse rept, "Use of Process Noise Measurements to Determine Response Characteristics in US Plant" & approval of use of process noise sensor response time noise measurement acceptable per BER, Section 7.2.2.3
TRAMM, T. R. Commonwealth Edison Co. 83/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20699 043 24X Fiche: 50-000, 83/09/28, 831020427

Security, medical, emergency & fire protection plans

10210234 Forwards Amend 2 to fire protection rept. Amend incorporates info re instrumentation, communications & suppression sys & addl info & commitments responding to NRC concerns from fire protection audit.
TRAMM, T. R. Commonwealth Edison Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 20853:015 24X Fiche 50-000, 83/10/13, 8310210234.

--8310210236 Amend 2 to fire protection rept, incorporating info re instrumentation, communications & suppression sys & addl info & commitments responding to NRC concerns from fire protection audit
* Commonwealth Edison Co 83/10/31 200pp 20853 023 24X Fiche 50-000, 83/10/13, 8310210234

8310270526 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20937 216 24X Fiche 50-000, 83/10/21, 8310270526

--8310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure EOP-6, "Administration & Logistics Manager"
W/831017 ltr & receipt form
NELLIS, C A Commonwealth Edison Co 83/02/18 DENTON, H R NRC -- No Detailed Affiliation Given 7pp 20937 217 24X Fiche 50-000, 83/10/21, 8310270536

8310280307 Releases public version of revised generating stations emergency plan telephone directory
FELTON, J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20963 126 24X Fiche 50-000, 83/10/25, 8310280307

--8310280314 Public version of revised generating stations emergency plan telephone directory
GALLE, D P Commonwealth Edison Co 83/08/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 64pp 20963 127 24X Fiche 50-000, 83/10/25, 8310280307

8310280191 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/26 Document Management Branch 1p 20962 266 24X Fiche 50-000, 83/10/26, 8310280191

--8310280209 Public version of Rev 1 to Emergency Plan Implementing Procedure EOP-15, "Emergency Operations Facility Activation"
MOORE, R D Commonwealth Edison Co 83/08/02 50pp 20962 267 24X Fiche 50-000, 83/10/26, 8310280191

G Adjudicatory correspondence

8310040205 Partial proposed findings of fact & conclusions of law on Contention 1A Certificate of SVC encl
WHICHER, J M League of Women Voters of Rockford, IL WHICHER, J M DeKalb Area Alliance for Responsible Energy WHICHER, J M Mississippi Alliance for the Environment (SAFE) 83/09/30 44pp 20614 280 24X Fiche 50-454, 83/09/30, 8310040205

8310050452 Forwards NRC proposed supplemental findings of fact & conclusions of law on GA/GC issues & list of proposed transcript corrections
YOUNG, M A Hearing Branch 4 83/09/30 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 20630 001 24X Fiche 50-454, 83/09/30, 8310050452

--8310050468 Proposed supplemental findings of fact & conclusions of law on GA/GC issues
YOUNG, M A Hearing Branch 4 83/09/30 34pp 20630 002 24X Fiche 50-454, 83/09/30, 8310050452

8310060317 Forwards util addl proposed findings of fact & conclusions of law re GA & GC
FURBE, M C. Isham, Lincoln & Beale FURBE, M C Commonwealth Edison Co 83/09/30 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 20646 232 24X Fiche 50-454, 83/09/30, 8310060317

--8310060321 Addl proposed findings of fact & conclusions of law re GA & GC Certificate of SVC encl.
MILLER, M I, BECHER, B D, FURBE, M C Commonwealth Edison Co 83/09/30 31pp 20646 233 24X Fiche 50-454, 83/09/30, 8310060317

8310050440 Forwards IE Insp Repts 50-454/83-41 & 50-455/83-31 on 830701-0831 Insp investigated allegations re Hatfield Electric Co.
YOUNG, M A Hearing Branch 4 83/10/03 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 8pp 20633 340, 24X Fiche 50-454, 83/10/03, 8310050440

8310050488 Memorandum taking official notice of publications of Illinois State Geological Survey.
SMITH, I W, Atomic Safety and Licensing Board Panel, 83/10/03 47pp 20632 116 24X Fiche 50-454, 83/10/03, 8310050488

DOCKETED ITEMS

345

B310060314 Advises of revised initial fuel load date, from B31201 to B40215 Rev attributable to unanticipated addl work required to complete piping supports & mods to ventilation duct work MILLER, M I Isham, Lincoln & Beale MILLER, M I Commonwealth Edison Co B3/10/03 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 20641 000 24X Fiche 50-454, B3/10/03, B310060314

B310170346 Advises that util does not object to ASLD taking official notice of EPA rept, "Protective Action Evaluation Part II, Evacuation & Sheltering as Protective Actions Against Nuclear Accidents Involving Gaseous Release " Part I encl COPELAND, V O Isham, Lincoln & Beale COPELAND, V O Commonwealth Edison Co B3/10/10 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 20786 030 24X Fiche 50-454, B3/10/10, B310170346

--B310170356 Affidavit of DD Ed, clarifying testimony re EPA rept, "Protective Action Evaluation Part II, Evacuation & Sheltering as Protective Actions Against Nuclear Accidents Involving Gaseous Releases " ED, D D Commonwealth Edison Co ED, D D Illinois, State of B3/10/10 11pp 20786 031 24X Fiche 50-454, B3/10/10, B310170356

B310130014 Response to ASLD B30920 memorandum advising of intent to take official notice of emergency planning witness testimony NRC has no objection to notice Certificate of Svc encl YOUNG, M A Hearing Branch 4 B3/10/11 Atomic Safety and Licensing Board Panel 4pp 20725 204 24X Fiche 50-454, B3/10/11, B310130014

B310140067 Response to DC Thomas motion to strike proposed findings of fact & conclusions of law & to withdraw as Rockford League of Women Voters counsel Rockford objects to motion to strike but not to withdrawal Related correspondence LEWIS, E League of Women Voters of Rockford, IL B3/10/13 Atomic Safety and Licensing Board Panel 2pp 20768 009 24X Fiche 50-454, B3/10/13, B310140067

--B310140070 Motion to strike Rockford League of Women Voters proposed findings of fact & conclusions of law & for leave to withdraw as Rockford counsel Rockford told counsel of dissatisfaction w/ findings Related correspondence THOMAS, D C League of Women Voters of Rockford, IL THOMAS, D C Thomas, D C B3/10/13 1p 20768 011 24X Fiche 50-454, B3/10/13, B310140067

B310180275 Forwards applicant reply to Joint Intervenor's partial proposed findings of fact & conclusions of law on Contention 1A FURSE, M C Isham, Lincoln & Beale FURSE, M C Commonwealth Edison Co B3/10/14 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 20807 003 24X Fiche 50-454, B3/10/14, B310180275

--B310180279 Reply to Joint Intervenor's partial proposed findings of fact & conclusions of law on Contention 1A Intervenor's findings misleading & inaccurate & should not be adopted Certificate of Svc encl FURSE, M C, BECKER, B D Commonwealth Edison Co FURSE, M C Isham, Lincoln & Beale B3/10/14 21pp 20807 004 24X Fiche 50-454, B3/10/14, B310180275

B310200077 Reply to util supplemental findings of Fact & conclusions of law on GA/GC Certificate of Svc encl WHICHER, J M DeKalb Area Alliance for Responsible Energy WHICHER, J M Whicher, J M WHICHER, J M Sinissippi Alliance for the Environment (SAFE) B3/10/17 12pp, 20836 048 24X Fiche 50-454, B3/10/17, B310200077

B310250486 Forwards reply to Joint Intervenor's partial proposed findings of fact & conclusions of law re GA/GC YOUNG, M A Hearing Branch 4 B3/10/17 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 20902 090 24X Fiche 50-454, B3/10/17, B310250486

--B310250504 Response to Joint Intervenor's B30930 partial proposed findings of fact & conclusions of law re GA/GC Findings should be rejected, Certificate of Svc encl YOUNG, M A Hearing Branch 4 B3/10/17 Atomic Safety and Licensing Board Panel 12pp 20902 091 24X Fiche 50-454, B3/10/17, B310250486

B310210204 Advises of author absence on B31109 D Cassel will be contact for intervenor group WHICHER, J M Businessmen for the Public Interest B3/10/18 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 20852 102 24X Fiche 50-454, B3/10/18, B310210204

--B310210219 Motion for limited discovery against NRC & util re B40215 projected fuel load date Date critical to proceeding at present stage WHICHER, J M DeKalb Area Alliance for Responsible Energy WHICHER, J M Sinissippi Alliance for the Environment (SAFE) WHICHER, J M Whicher, J M B3/10/18 Atomic Safety and Licensing Board Panel Bpp 20852 103 24X Fiche 50-454, B3/10/18, B310210204

B310250513 Forwards corrected Page 2 of reply to Joint Intervenor's partial proposed findings of fact & conclusions of law on GA/GC YOUNG, M A Hearing Branch 4 B3/10/18 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 20901 258 24X Fiche 50-454, B3/10/18, B310250513

--B310250520 Corrected Page 2 of reply to Joint Intervenor's proposed findings of fact & conclusions of law on GA/GC * Office of the Executive Legal Director B3/10/18 1p 20901 259 24X Fiche 50-454, B3/10/18, B310250513

B310250117 Forwards IE Insp Repts 50-454/B3-38 & 50-455/B3-28 addressing Hughes allegations re welding of cable support tray & B30804 mgt meeting on reinsp program YOUNG, M A Hearing Branch 4 B3/10/21 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 20877 240 24X Fiche 50-454, B3/10/21, B310250117

B310310127 Withdrawal of previous response to own counsel motion to strike proposed findings of fact & conclusions of law Motion to strike never filed but mailed to svc list to intimidate intervenor into paying disputed fee Related correspondence LEWIS, E League of Women Voters of Rockford, IL B3/10/27 Atomic Safety and Licensing Board Panel 3pp 20949 107 24X Fiche 50-454, B3/10/27, B310310127

H General correspondence

B310030349 Package of four public comments opposing plant const & licensing CAMPBELL, S E, SEARLS, L K Sinissippi Alliance for the Environment (SAFE) B3/09/29 SMITH, J W Atomic Safety and Licensing Board Panel Bpp 20590 156 24X Fiche 50-454, B3/09/29, B310030349

K Utility Final Safety Analysis Report (FSAR) & amends

B310040554 Forwards affidavit certifying distribution of FSAR, Amend 43 per NRC 7B1020 ltr TRAMM, T R Commonwealth Edison Co B3/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20623 210 24X Fiche 50-000, B3/09/28, B310040554

Q Inspection reports, IE Bulletins & correspondence

B310170525 Forwards IE Insp Repts 50-454/B3-38 & 50-455/B3-28 on B30803-04 & 08 No noncompliance noted KNOP, R C Region 3, Office of Director B3/09/01 REED, C Commonwealth Edison Co 2pp 20784 192 24X Fiche 50-454, B3/09/01, B310170525

--B310170529 IE Insp Repts 50-454/B3-38 & 50-455/B3-28 on B30803-04 & 08 No noncompliance noted Major areas inspected followup on allegations re station electrical contractor, including exam of procedures & records, observations & interviews HAYES, D W, KNOP, R C Region 3, Office of Director B3/09/01 5pp 20784 194 24X Fiche 50-454, B3/09/01, B310170525

B310040424 Forwards IE Insp Repts 50-454/B3-41 & 50-455/B3-31 on B30701-0831 No noncompliance noted KNOP, R C Region 3, Office of Director B3/09/23 REED, C Commonwealth Edison Co 2pp 20619 117 24X Fiche 50-454, B3/09/23, B310040424

--B310040430 IE Insp Repts 50-454/B3-41 & 50-455/B3-31 on B30701-0831 No noncompliance noted Major areas inspected preoperational testing operations & procedures, IE circular file responses & licensee actions on previously identified items CONNAUGHTON, M, HAYES, D W Region 3, Office of Director B3/09/23 5pp 20619 119 24X Fiche 50-454, B3/09/23, B310040424

B308300340 IE Info Notice B3-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, B3/09/26, B308300340

DOCKETED ITEMS

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Bys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310050440 Forwards IE Insp Repts 50-454/83-41 & 50-455/83-31 on 830701-0831 Insp investigated allegations re Hatfield Electric Co
YOUNG, M A Hearing Branch 4 83/10/03 SMITH, I W Atomic Safety and Licensing Board Panel 8pp 20633 340 24X Fiche 50-454, 83/10/03, 8310050440

8310200124 Forwards IE Mgt Meeting Repts 50-010/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIUS, C E Division of Project & Resident Programs 83/10/04
REED, C Commonwealth Edison Co 2pp 20834 098 24X Fiche 50-000, 83/10/04, 8310200124

--8310200148 IE Mgt Meeting Repts 50-020/83-18, 50-237/83-27, 50-249/83-26, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIUS, C E Division of Project & Resident Programs 83/10/03
4pp 20834 100 24X Fiche 50-000, 83/10/04, 8310200124

8310120302 Act receipt of 830926 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/83-18 & 50-455/83-15
NORELIUS, C E Division of Project & Resident Programs 83/10/05
REED, C Commonwealth Edison Co 1p 20699 009 24X Fiche 50-454, 83/10/05, 8310120302

--8310120401 Suppls response to NRC 830526 ltr re violations noted in IE Insp Repts 50-454/83-18 & 50-455/83-15 Corrective actions nonconformance repts reviewed to determine whether FSAR change required & whether change actually made
FARRAR, D L Commonwealth Edison Co 83/09/26 KEPLER, J G Region 3, Office of Director 2pp 20699 010 24X Fiche 50-454, 83/10/05, 8310120302

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310270128 Forwards IE Insp Repts 50-454/83-40 & 50-455/83-30 on 830811-0919 & notice of violation
STREETER, J F Region 3, Office of Director 83/10/11 REED, C Commonwealth Edison Co 2pp 20924 124 24X Fiche 50-454, 83/10/11, 8310270128

8310270134 Notice of Violation from Insp on 830811-0919
STREETER, J F Region 3, Office of Director 83/10/11 2pp 20924 126 24X Fiche 50-454, 83/10/11, 8310270128

--8310270140 IE Insp Repts 50-454/83-40 & 50-455/83-30 on 830811-0919 Noncompliance noted failure to follow out-of-svc procedures for valve lineup of chemical & vol control sys
RING, M, VANDENBURGH, C, REYES, L A Region 3, Office of Director 83/10/11 10pp 20924 128 24X Fiche 50-454, 83/10/11, 8310270128

8310310134 Requests that util response to generic implications of audits of design implementation address program for all plants Util position may be included in response to integrated design insp rept
EISENHUT, D G Division of Licensing 83/10/12 REED, C Commonwealth Edison Co 6pp 20965 318 24X Fiche 50-000, 83/10/12, 8310310134

8310180295 Clarifies NRC position re procedures for admitting NRC personnel to Facilities List of personnel requiring access to vital areas encl Updates will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 REED, C Commonwealth Edison Co 7pp 20806 354 24X Fiche 50-454, 83/10/14, 8310180295

S Reportable occurrences, LERs & related correspondence

8310170411 Interim deficiency rept re Westinghouse A-200 motor control ctrs Initially reported on 830909 All affected overload blocks identified by personnel will be replaced w/properly calibr overload blocks
SWARTZ, E D Commonwealth Edison Co 83/10/06 KEPLER, J G Region 3, Office of Director 2pp 20784 019 24X Fiche 50-000, 83/10/06, 8310170411

8310170573 Final deficiency rept re Anaconda flexible conduit splitting Initially reported on 830909 Caused by exceeding specified bending radius & exposure to high temps during installation Conduit jackets covered by Okonite T-33 tape
SWARTZ, E D Commonwealth Edison Co 83/10/06 KEPLER, J G Region 3, Office of Director 2pp 20780 337 24X Fiche 50-000, 83/10/06, 8310170573

T Hearing transcripts on non-antitrust matters

8310050452 Forwards NRC proposed supplemental findings of fact & conclusions of law on OAR/QC issues & list of proposed transcript corrections
YOUNG, M A Hearing Branch 4 83/09/30 SMITH, I W Atomic Safety and Licensing Board Panel 1p 20630 001 24X Fiche 50-454, 83/09/30, 8310050452

--8310050475 Proposed transcript corrections for 830810-12 hearings Certificate of Svc encl
YOUNG, M A Hearing Branch 4 83/09/30 4pp 20630 026 24X Fiche 50-454, 83/09/30, 8310050452

DOCKET STN-50-456 BRAIDWOOD STATION, UNIT 1

A Application/construction stage documents & correspondence

8310200273 Forwards schedules for equipment qualification test programs for facilities, per 810528 ltr Dates given for current qualification activities should be viewed as "target-dates" & not as firm dates
BARNES, P L Commonwealth Edison Co 83/10/05 KEPLER, J G Region 3, Office of Director 10pp 20830 034 24X Fiche 50-000, 83/10/05, 8310200273

8310310168 Requests info necessary to initiate determination of eligibility per request to keeper of Natl Register of Historic Places re Area 1 Ka 179 identified in archeological survey Repts by Illinois State Museum Soc
YOUNGBLOOD, B J Licensing Branch 1 83/10/12 FARRAR, D L Commonwealth Edison Co 8pp 20965 308 24X Fiche 50-456, 83/10/12, 8310310168

8310250293 Forwards Rev 10 to Offsite Dose Calculation Manual for LaSalle & Quad Cities & Rev 9 to Offsite Dose Calculation Manual for Braidwood, consisting of Chapters 7 2 & 8 O
BENNETT, C J Commonwealth Edison Co 83/10/21 CASE, E G Office of Nuclear Reactor Regulation, Director 1p 20894 259 24X Fiche 50-000, 83/10/21, 8310250293

--8310250302 Rev 9 to Offsite Dose Calculation Manual for Braidwood, consisting of Chapters 7 2 & 8 O
* Commonwealth Edison Co 83/08/31 56pp 20894 304 24X Fiche 50-000, 83/10/21, 8310250293

DOCKETED ITEMS

8310310060 Submits info re Edison rod swap analysis method for review & approval Methods employed in support of control rod worth measurements using rod swap technique during reload physics testing Criteria tables encl
CENTINE, F G Commonwealth Edison Co 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 20951 024 24X
Fiche 50-000, 83/10/24, 8310310060

C Utility Environmental Report (ER), amends & correspondence

8310110302 Forwards majority of Amend 4 to environ rept - DL stage, containing responses to NRC 830907 & 14 requests for addl info Amended response to Question ER470 3 encl W/six oversize drawings Aperture cards are available in PDR
MCDONOUGH, C L Commonwealth Edison Co 83/10/06 STEVENS, J A Licensing Branch 1 4pp 20669 085 24X Fiche 50-456, 83/10/06, 8310110302

--8310110304 Advance copy of Amend 4 to environ rept - DL stage
* Commonwealth Edison Co 83/10/31 47pp 20669 089 24X
Fiche 50-456, 83/10/06, 8310110302

8310180252 Forwards Amend 2 to environ rept - DL stage, containing responses to 830907 & 14 requests for addl info & info on site/environ interfaces & effluent & environ measurements/monitoring programs
SWARTZ, E D Commonwealth Edison Co 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20804 337 24X
Fiche 50-456, 83/10/14, 8310180252

--8310180351 Amend 4 to environ rept - DL stage
* Commonwealth Edison Co 83/10/31 40pp 20804 339 24X
Fiche 50-456, 83/10/14, 8310180252

E NRC Safety Evaluation Report (SER), supls & correspondence

8310120427 Requests review of Westinghouse rept, "Use of Process Noise Measurements to Determine Response Characteristics in US Plant" & approval of use of process noise sensor response time Noise measurement acceptable per SER, Section 7 2 2 5
TRAMM, T R Commonwealth Edison Co 83/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20699 043 24X
Fiche 50-000, 83/09/28, 8310120427

8310120219 Responds to unresolved issues contained in draft SER, NUREG-1002 dtd 830715 Some items re NRC site audits unresolved
SWARTZ, E D Commonwealth Edison Co 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 20692 179 24X
Fiche 50-456, 83/09/30, 8310120219

F Security, medical, emergency & fire protection plans

8310210234 Forwards Amend 2 to fire protection rept Amend incorporates info re instrumentation, communications & suppression sys & addl info & commitments responding to NRC concerns from fire protection audit
TRAMM, T R Commonwealth Edison Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 20853 015 24X
Fiche 50-000, 83/10/13, 8310210234

--8310210236 Amend 2 to fire protection rept, incorporating info re instrumentation, communications & suppression sys & addl info & commitments responding to NRC concerns from fire protection audit
* Commonwealth Edison Co 83/10/31 200pp 20853 023 24X
Fiche 50-000, 83/10/13, 8310210234

8310270526 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20937 216 24X Fiche 50-000, 83/10/21, 8310270526

--8310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure EDF-6, "Administration & Logistics Manager"
W/831017 ltr & receipt form
NELLIS, C A Commonwealth Edison Co 83/02/18 DENTON, H R NRC - No Detailed Affiliation Given 7pp 20937 217 24X
Fiche 50-000, 83/10/21, 8310270526

8310280307 Releases public version of revised generating stations emergency plan telephone directory
FELTON, J M Division of Rules and Records, 83/10/25 Document Management Branch 1p 20943 126 24X Fiche: 50-000, 83/10/25, 8310280307

--8310280314 Public version of revised generating stations emergency plan telephone directory
GALLE, D P Commonwealth Edison Co 83/08/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 64pp 20963 127 24X
Fiche 50-000, 83/10/25, 8310280307

8310280191 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/26 Document Management Branch 1p 20962 266 24X Fiche 50-000, 83/10/26, 8310280191

--8310280209 Public version of Rev 1 to Emergency Plan Implementing Procedure EDF-15, "Emergency Operations Facility Activation"
MODRE, R D Commonwealth Edison Co 83/08/02 50pp 20962 267 24X Fiche 50-000, 83/10/26, 8310280191

K Utility Final Safety Analysis Report (FSAR) & amends

8310040554 Forwards affidavit certifying distribution of FSAR, Amend 43 per NRC 781020 ltr
TRAMM, T R Commonwealth Edison Co 83/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20623 210 24X
Fiche 50-000, 83/09/28, 8310040554

Q Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310040158 Ack receipt of 830922 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/83-08 & 50-457/83-08
KNOP, R C Region 3, Office of Director 83/09/29 REED, C Commonwealth Edison Co 1p 20608 039 24X Fiche 50-456, 83/09/29, 8310040158

--8310040162 Responds to NRC 830823 ltr re violations noted in IE Insp Repts 50-456/83-08 & 50-457/83-08 Corrective actions motor control ctr cleaned, injector pump covers tightened & mud drained bottom of accumulator tanks & support skirt removed.
FARRAR, D L Commonwealth Edison Co 83/09/22 KEPLER, J O Region 3, Office of Director 4pp 20608 040 24X
Fiche 50-456, 83/09/29, 8310040158

8310200124 Forwards IE Mgt Meeting Repts 50-010/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIUS, C E Division of Project & Resident Programs 83/10/04 REED, C Commonwealth Edison Co 2pp 20834 098 24X
Fiche 50-000, 83/10/04, 8310200124

--8310200148 IE Mgt Meeting Repts 50-020/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIUS, C E Division of Project & Resident Programs 83/10/03 4pp 20834 100 24X Fiche 50-000, 83/10/04, 8310200124

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

DOCKETED ITEMS

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

8310310134 Requests that util response to generic implications of audits of design implementation address program for all plants Util position may be included in response to integrated design insp rept
EISENHUT, D O Division of Licensing 83/10/12 REED, C
Commonwealth Edison Co 6pp 20965 318 24X Fiche 50-000,83/10/12,8310310134

8310170666 Ack receipt of 830909 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/83-07 & 50-457/83-07 Violation re inadequate drawing control restated.
NORELIUS, C E Division of Project & Resident Programs. 83/10/13
REED, C Commonwealth Edison Co 2pp 20779 307 24X
Fiche 50-456,83/10/13,8310170666

--8310170671 Responds to NRC 830808 ltr re violations noted in IE Insp Repts 50-456/83-07 & 50-457/83-07 Corrective actions: drawings exhibiting discrepancies reviewed & review results listed Log established to improve drawing traceability
FARRAR, D L Commonwealth Edison Co 83/09/09 KEPLER, J G.
Region 3, Office of Director 12pp 20779 309 24X
Fiche 50-456,83/10/13,8310170666

8310180116 Forwards access lists for NRC personnel requiring access to vital areas on announced or unannounced basis Encls effective upon receipt Updates will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14, REED, C
Commonwealth Edison Co. 7pp. 20807 208 24X Fiche 50-456,83/10/14,8310180116

8310240069 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-456/83-13.
LITTLE, W B Region 3, Office of Director. 83/10/19 REED, C
Commonwealth Edison Co. 1p. 20881 340 24X Fiche: 50-456,83/10/19,8310240069

8310240077 Responds to NRC 830902 ltr re violations noted in IE Insp Rept 50-456/83-13 Corrective actions Phillips, Qerschow Co issued Field Change Order IAF563 to correct reversed instrument sensing lines
FARRAR, D L Commonwealth Edison Co. 83/09/30 KEPLER, J G
Region 3, Office of Director. 3pp 20881 341, 24X
Fiche 50-456,83/10/19,8310240069

3 Reportable occurrences, LERs & related correspondence

8310170411 Interim deficiency rept re Westinghouse A-200 motor control ctrs Initially reported on 830909 All affected overload blocks identified by personnel will be replaced w/properly calibr overload blocks
SWARTZ, E D Commonwealth Edison Co 83/10/06, KEPLER, J G Region 3, Office of Director 2pp 20784 019 24X Fiche: 50-000,83/10/06,8310170411

8310170573 Final deficiency rept re Anaconda flexible conduit splitting. Initially reported on 830909 Caused by exceeding specified bending radius & exposure to high temps during installation. Conduit jackets covered by Okonite T-33 tape
SWARTZ, E D, Commonwealth Edison Co 83/10/06 KEPLER, J G Region 3, Office of Director 2pp 20780 337 24X Fiche: 50-000,83/10/06,8310170573.

8310270188 Interim Deficiency Rept 83-08 re fabrication of duct fittings w/o approved design documentation. Initially reported on 830701. Pullman Sheet Metal submitted Rev A to duct brochure. Final approval by Sargent & Lundy pending
SWARTZ, E D, Commonwealth Edison Co. 83/10/20 KEPLER, J G Region 3, Office of Director. 2pp 20924 356. 24X Fiche-50-456,83/10/20,8310270188

DOCKET STN-50-457 BRAIDWOOD STATION, UNIT 2

A Application/construction stage documents & correspondence

8310200273 Forwards schedules for equipment qualification test programs for facilities, per 810528 ltr Dates given for current qualification activities should be viewed as "target-dates" & not as firm dates
BARNES, P L Commonwealth Edison Co 83/10/05 KEPLER, J G Region 3, Office of Director 10pp 20830 034 24X Fiche 50-000,83/10/05,8310200273

8310310168 Requests info necessary to initiate determination of eligibility per request to keeper of Natl Register of Historic Places re Area 11 Ka 179 identified in archeological survey repts by Illinois State Museum Soc
YOUNGBLOOD, B J Licensing Branch 1 83/10/12 FARRAR, D L Commonwealth Edison Co 8pp 20965 308 24X Fiche 50-456,83/10/12,8310310168

8310250293 Forwards Rev 10 to Offsite Dose Calculation Manual for LaSalle & Quad Cities & Rev 9 to Offsite Dose Calculation Manual for Braidwood, consisting of Chapters 7 2 & 8 0
BENNETT, C J Commonwealth Edison Co 83/10/21 CASE, E G Office of Nuclear Reactor Regulation, Director 1p 20894 259 24X Fiche 50-000,83/10/21,8310250293

--8310250302 Rev 9 to Offsite Dose Calculation Manual for Braidwood, consisting of Chapters 7 2 & 8 0
* Commonwealth Edison Co 83/08/31 56pp 20894 304 24X Fiche 50-000,83/10/21,8310250293

8310310060 Submits info re Edison rod swap analysis method for review & approval Methods employed in support of control rod worth measurements using rod swap technique during reload physics testing Criteria tables encl
LENTINE, F G Commonwealth Edison Co 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 20951 024 24X Fiche. 50-000,83/10/24,8310310060

C Utility Environmental Report (ER), amends & correspondence

8310110302 Forwards majority of Amend 4 to environ rept - DL stage, containing responses to NRC 830907 & 14 requests for addl info. Amended response to Question ER470 3 encl W/six oversize drawings Aperture cards are available in PDR
MCDONOUGH, C L Commonwealth Edison Co 83/10/06 STEVENS, J A Licensing Branch 1 4pp 20669 085 24X Fiche 50-456,83/10/06,8310110302

--8310110304 Advance copy of Amend 4 to environ rept - DL stage
* Commonwealth Edison Co 83/10/31 47pp 20669 089 24X Fiche 50-456,83/10/06,8310110302

8310180252 Forwards Amend 2 to environ rept - DL stage, containing responses to 830907 & 14 requests for addl info & info on site/enviro interfaces & effluent & environ measurements/monitoring programs
SWARTZ, E D Commonwealth Edison Co 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20804 337 24X Fiche. 50-456,83/10/14,8310180252

--8310180351 Amend 4 to environ rept - DL stage
* Commonwealth Edison Co 83/10/31 40pp 20804 339 24X Fiche 50-456,83/10/14,8310180252

E NRC Safety Evaluation Report (SER), supls & correspondence

8310120427 Requests review of Westinghouse rept: "Use of Process Noise Measurements to Determine Response Characteristics in US Plant" & approval of use of process noise sensor response time Noise measurement acceptable per SER, Section 7 2 2 3
TRAMM, T R Commonwealth Edison Co 83/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20699 043 24X Fiche. 50-000,83/09/28,8310120427

8310120219 Responds to unresolved issues contained in draft SER, NUREG-1002 dtd 830715 Some items re NRC site audits unresolved
SWARTZ, E D Commonwealth Edison Co 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 44pp 20692 179 24X Fiche 50-456,83/09/30,8310120219

DOCKETED ITEMS

34

F Security, medical, emergency & fire protection plans

8310210234 Forwards Amend 2 to fire protection rept Amend incorporates info re instrumentation, communications & suppression sys & addl info & commitments responding to NRC concerns from fire protection audit
TRAMM, T R Commonwealth Edison Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 20853 015 24X
Fiche 50-000, 83/10/13, 8310210234

--8310210236 Amend 2 to fire protection rept, incorporating info re instrumentation, communications & suppression sys & addl info & commitments responding to NRC concerns from fire protection audit
* Commonwealth Edison Co 83/10/31 200pp 20853 023 24X
Fiche 50-000, 83/10/13, 8310210234

8310270526 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20937 216 24X Fiche 50-000, 83/10/21, 8310270526

--8310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure EDF-6, "Administration & Logistics Manager"
W/831017 ltr & receipt form
NELLIS, C A Commonwealth Edison Co 83/02/18 DENTON, H R NRC - No Detailed Affiliation Given 7pp 20937 217 24X
Fiche 50-000, 83/10/21, 8310270526

8310280307 Releases public version of revised generating stations emergency plan telephone directory
FELTON, J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20963 126 24X Fiche 50-000, 83/10/25, 8310280307

--8310280314 Public version of revised generating stations emergency plan telephone directory
GALLE, D P Commonwealth Edison Co 83/08/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 64pp 20963 127 24X
Fiche 50-000, 83/10/25, 8310280307

8310280191 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/10/26 Document Management Branch 1p 20962 266 24X Fiche 50-000, 83/10/26, 8310280191

--8310280209 Public version of Rev 1 to Emergency Plan Implementing Procedure EDF-15, "Emergency Operations Facility Activation"
MOORE, R D Commonwealth Edison Co 83/08/02 50pp 20962 267 24X Fiche 50-000, 83/10/26, 8310280191

K Utility Final Safety Analysis Report (FSAR) & amends

8310040554 Forwards affidavit certifying distribution of FSAR, Amend 43 per NRC 781020 ltr
TRAMM, T R Commonwealth Edison Co 83/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20623 210 24X
Fiche 50-000, 83/09/28, 8310040554

G Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8310040158 Ack receipt of 830922 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/83-08 & 50-457/83-08
KNOP, R C Region 3, Office of Director 83/09/29 REED, C Commonwealth Edison Co 1p 20608 039 24X Fiche 50-456, 83/09/29, 8310040158

--8310040162 Responds to NRC 830823 ltr re violations noted in IE Insp Repts 50-456/83-08 & 50-457/83-08 Corrective actions motor control ctr cleaned, injector pump covers tightened & mud between bottom of accumulator tanks & support skirt removed
FARRAR, D L Commonwealth Edison Co 83/09/22 KEPLER, J G Region 3, Office of Director 4pp 20608 040 24X
Fiche 50-456, 83/09/29, 8310040158

8310200124 Forwards IE Mgt Meeting Repts 50-010/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIUS, C E Division of Project & Resident Programs 83/10/04 REED, C Commonwealth Edison Co 2pp 20834 098 24X
Fiche 50-000, 83/10/04, 8310200124

--8310200148 IE Mgt Meeting Repts 80-020/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
NORELIUS, C E Division of Project & Resident Programs 83/10/03 4pp 20834 100 24X Fiche 50-000, 83/10/04, 8310200124

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning, Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310310134 Requests that util response to generic implications of audits of design implementation address program for all plants Util position may be included in response to integrated design insp rept
EISENHUT, D G Division of Licensing 83/10/12 REED, C Commonwealth Edison Co 6pp 20965 318 24X Fiche 50-000, 83/10/12, 8310310134

8310170666 Ack receipt of 830909 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/83-07 & 50-457/83-07 Violation re inadequate drawing control retested.
NORELIUS, C E Division of Project & Resident Programs 83/10/13 REED, C Commonwealth Edison Co 2pp 20779 307 24X
Fiche 50-456, 83/10/13, 8310170666

--8310170671 Responds to NRC 830808 ltr re violations noted in IE Insp Repts 50-456/83-07 & 50-457/83-07 Corrective actions drawings exhibiting discrepancies reviewed & review results listed, Log established to improve drawing traceability.
FARRAR, D L Commonwealth Edison Co 83/09/09 KEPLER, J G Region 3, Office of Director 12pp 20779 309 24X
Fiche 50-456, 83/10/13, 8310170666

8310180116 Forwards access lists for NRC personnel requiring access to vital areas on announced or unannounced basis Encls effective upon receipt Updates will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 REED, C Commonwealth Edison Co 7pp 20807 208 24X Fiche 50-456, 83/10/14, 8310180116

DOCKETED ITEMS

B Reportable occurrences, LERs & related correspondence

B310170411 Interim deficiency rept re Westinghouse A-200 motor control cts Initially reported on 830909 All affected overload blocks identified by personnel will be replaced w/properly calibr overload blocks
SWARTZ, E D Commonwealth Edison Co 83/10/04 KEPLER, J G Region 3, Office of Director 2pp 20784 019 24X Fiche 50-000, 83/10/06, 8310170411

B310170573 Final deficiency rept re Anaconda flexible conduit splitting Initially reported on 830907 Caused by exceeding specified bending radius & exposure to high temps during installation Conduit jackets covered by Okonite T-33 tape
SWARTZ, E D Commonwealth Edison Co 83/10/06 KEPLER, J G Region 3, Office of Director 2pp 20780 337 24X Fiche 50-000, 83/10/06, 8310170573

B310270188 Interim Deficiency Rept 83-08 re fabrication of duct fittings w/o approved design documentation Initially reported on 830701 Pullman Sheet Metal submitted Rev A to duct brochure Final approval by Sargent & Lundy pending
SWARTZ, E D Commonwealth Edison Co 83/10/20 KEPLER, J G Region 3, Office of Director 2pp 20924 356 24X Fiche 50-458, 83/10/20, 8310270188

DOCKET 50-458 RIVER BEND STATION, UNIT 1

A Application/construction stage documents & correspondence

B307260003 Forwards const QA program identifying changes to program since issuance of CP W/o encl
BOOKER, J E Gulf States Utilities Co 83/06/10 COLLINS, J T Region 4, Office of Director 1p 20626 082 24X Fiche 50-458, 83/06/10, 8307260003

--B310040615 Const QA program for River Bend Station.
* Gulf States Utilities Co 83/03/31 91pp 20626 083 24X Fiche 50-458, 83/06/10, 8307260003

B310280183 Appeals partial denial of FOIA request for four categories of info re Caseload Forecast Panel 830330-31 meeting & site visit
FALKENHEIMER, D Louisiana Consumer's League, Inc FALKENHEIMER, D Falkenheimer, D. 83/09/01 Office of the Executive Director for Operations 2pp 20963 342 24X Fiche 50-458, 83/09/01, 8310280183

B310070319 Responds to 810330 ltr re ultimate capacity analysis of Mark III containments Ultimate capacities of containment equipment hatch & personnel airlock determined to be 56 psi & 72 psi, respectively.
BOOKER, J E Gulf States Utilities Co 83/09/30 NOVAK, T M Assistant Director for Licensing 7pp, 20652 177 24X Fiche 50-458, 83/09/30, 8310070319

B310210221 Summarizes analysis of inclusion of redundant chlorine & ammonia detectors in control bldg ventilation sys design NRC reconsideration of requirement requested Meeting in Bethesda, MD in Nov proposed
BOOKER, J E Gulf States Utilities Co 83/10/17 SCHWENCER, A Licensing Branch 2 5pp 20852 084 24X Fiche 50-458, 83/10/17, 8310210221

B310260014 Forwards request for addl info re mechanical engineering to proceed w/review of OL application
SCHWENCER, A Licensing Branch 2 83/10/18 CAHILL, W J Gulf States Utilities Co 3pp 20928 043 24X Fiche: 50-458, 83/10/18, 8310260014

B310280189 Responds to Appeal re partial denial of FOIA request for four categories of info re Caseload Forecast Panel 830330-31 meeting & site visit Forwards complete version of requested documents
DIRCKS, W J Office of the Executive Director for Operations. 83/10/18, FALKENHEIMER, D Falkenheimer, D 1p, 20963 344, 24X Fiche, 50-458, 83/10/18, 8310280189.

-B310280199 Calculations re facility components. Supporting documentation encl
* Gulf States Utilities Co 83/03/30, 11pp 20963 350, 24X Fiche: 50-458, 83/10/18, 8310280189

10260442 Notification of 831117 meeting w/util in Bethesda, MD to discuss equipment qualification programs
WEINKAM, E J Licensing Branch 2 83/10/19, SCHWENCER, A Licensing Branch 2 3pp 20926 354 24X Fiche: 50-458, 83/10/19, 8310260442

C Utility Environmental Report (ER), amends & correspondence

B310030232 Forwards Suppl 6 to environ rept - OL stage Review questions attached to NRC 830/08 ltr renumbered Affidavit of Svc encl
CAHILL, W J Gulf States Utilities Co 83/09/27 EISENHUT, D O Division of Licensing 7pp 20590 074 24X Fiche 50-458, 83/09/27, 8310030232

--B310030238 Suppl 6 to environ rept - OL stage
* Stone & Webster, Inc 83/09/30 62pp 20590 086 24X Fiche 50-458, 83/09/27, 8310030232

E NRC Safety Evaluation Report (SER), supple & correspondence

B310240272 Requests estimated dates for submitting addl info associated w/SER open & confirmatory issues Response requested within 7 days
SCHWENCER, A Licensing Branch 2 83/10/18 CAHILL, W J Gulf States Utilities Co 2pp 20907 332 24X Fiche 50-458, 83/10/18, 8310240272

B310270181 Revises schedule for providing responses to draft SER issues & clarifications to FSAR Responses previously committed for 831015 will be provided between 831101 & 1231
BOOKER, J E Gulf States Utilities Co 83/10/25 SCHWENCER, A Licensing Branch 2 1p 20924 175 24X Fiche 50-458, 83/10/25, 8310270181

F Security, medical, emergency & fire protection plans

B310130084 Notification of 831012-13 meetings w/util in St Francisville, LA to discuss onsite emergency preparedness topics
WEINKAM, E J Licensing Branch 2 83/10/03 SCHWENCER, A Licensing Branch 2 3pp 20777 022 24X Fiche 50-458, 83/10/03, 8310130084

B310240135 Notification of 831017-21 meetings w/util & SNURPS in Fulton, MD to audit fire protection design
EDISON, O E Licensing Branch 1 83/10/11 YOUNGBLOOD, B J Licensing Branch 1 3pp 20884 358 24X Fiche 50-458, 83/10/11, 8310240135

G Adjudicatory correspondence

B310120398 Order rewarding Contention 2 re probability of failure of old river control structure
COTTER, D P, COLE, R F, LINENBERGER, O Atomic Safety and Licensing Board Panel 83/10/07 2pp 20700 204 24X Fiche 50-458, 83/10/07, 8310120398

H Utility Final Safety Analysis Report (FSAR) & amends

B310030226 Certifies svc of Amend 10 to FSAR on 830913 Distribution list encl
LIBERTOWICZ, F Gulf States Utilities Co LIBERTOWICZ, F Stone & Webster, Inc 83/09/27 2pp 20590 147 24X Fiche 50-458, 83/09/27, 8310030226

M Antitrust correspondence

B310250171 Forwards NRC updated OL antitrust inquiry transmitted to util on 830816
VOLGER, B H Hearing Branch 2 83/10/13 SPIEGEL, O Spiegel & McDiarmid 23pp 20893 282 24X Fiche 50-458, 83/10/13, 8310250171

Q Inspection reports, IE Bulletins & correspondence

B310030402 Forwards IE Insp Rept 50-458/83-12 on 830603-0728 No noncompliance noted
MADSEN, O L Region 4, Office of Director 83/08/17 CAHILL, W J Gulf States Utilities Co 2pp 20593 148 24X Fiche 50-458, 83/08/17, 8310030402

--B310030420 IE Insp Rept 50-458/83-12 on 830603-0728 No noncompliance noted Major areas inspected followup of licensee identified const deficiencies, IE bulletins, Action Item H07003078 & allegations, training & weld matl control
BROWN, R L, CROSSMAN, W A Region 4, Office of Director 83/08/15 12pp 20593 150 24X Fiche 50-458, 83/08/17, 8310030420

B310130247 Forwards IE Insp Rept 50-458/83-14 on 830718-22 No noncompliance noted
MADSEN, O L Region 4, Office of Director 83/08/19, CAHILL, W J Gulf States Utilities Co 2pp 20723 237 24X Fiche 50-458, 83/08/19, 8310130247

DOCKETED ITEMS

--8310130252 IE Insp Rept 50-458/83-14 on 830718-22 No noncompliance noted Major areas inspected const activities, including site tour, review of procedures re electrical & instrumentation cable pulling & termination
BESS, J E , JOHNSON, L E , HULL, R E Region 4, Office of Director
83/08/19 8pp 20723 239 24X Fiche 50-458, 83/08/19, 8310130247

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8310180144 Forwards IE Insp Rept 50-458/83-16 on 830729-0909 No noncompliance noted
MADSEN, O L Region 4, Office of Director 83/09/27 CAHILL, W J Gulf States Utilities Co 2pp 20809 170 24X
Fiche 50-458, 83/09/27, 8310180144

--8310180149 IE Insp Rept 50-458/83-16 on 830729-0909 No noncompliance noted Major areas inspected followup of licensee identified const deficiencies & IE bulletins, preoperational test procedures review & safety-related component installation
BROWN, R L , GARCIA, H L , CROSSMAN, W A Region 4, Office of Director 83/09/27 8pp 20809 172 24X Fiche 50-458, 83/09/27, 8310180144

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310260017 Forwards request for addl info re preservice/in-service insp programs to proceed w/review of DL application
SCHWENGER, A Licensing Branch 2 83/10/18 CAHILL, W J Gulf States Utilities Co 4pp 20926 359 24X Fiche 50-458, 83/10/18, 8310260017

S Reportable occurrences, LERs & related correspondence

8310030549 Interim Deficiency Rept DR-127 Investigation incomplete Next rept will be provided by 831110
BOOKER, J E Gulf States Utilities Co 83/09/19 COLLINS, J T Region 4, Office of Director. Ip 20601 210 24X
Fiche 50-458, 83/09/19, 8310030549.

8310040318 Interim Deficiency Rept DR-61 Investigation ongoing Interim or final status rept will be submitted by 831020.
BOOKER, J E Gulf States Utilities Co, 83/09/23 COLLINS, J T Region 4, Office of Director. Ip 20620 322 24X
Fiche 50-458, 83/09/23, 8310040318

8310040126 Interim Deficiency Rept DR-129 Investigation ongoing Interim or final status rept will be provided by 831215
BOOKER, J E Gulf States Utilities Co 83/09/26 COLLINS, J T Region 4, Office of Director Ip 20608 004 24X
Fiche 50-458, 83/09/26, 8310040126

8310040130 Interim Deficiency Rept DR-128 Investigation ongoing Interim or final status rept will be submitted by 831108
BOOKER, J E Gulf States Utilities Co 83/09/26 COLLINS, J T Region 4, Office of Director Ip 20608 005 24X
Fiche 50-458, 83/09/26, 8310040130

8310040496 Interim Deficiency Rept DR-108 Investigation incomplete Next rept will be provided by 831111
BOOKER, J E Gulf States Utilities Co 83/09/26 COLLINS, J T Region 4, Office of Director Ip 20622 362 24X
Fiche 50-458, 83/09/26, 8310040496

8310060074 Interim Deficiency Rept DR-125 Investigation not completed Interim or final status rept will be provided by 831109
BOOKER, J E Gulf States Utilities Co 83/09/27 COLLINS, J T Region 4, Office of Director. Ip 20647 151, 24X
Fiche 50-458, 83/09/27, 8310060074

8310130210 Interim Deficiency Rept DR-72 Investigation ongoing Interim or final rept will be provided by 831117
BOOKER, J E Gulf States Utilities Co 83/09/28 COLLINS, J T Region 4, Office of Director Ip 20725 023 24X
Fiche 50-458, 83/09/28, 8310130210.

8310130256 Interim Deficiency Rept DR-74 Investigation incomplete Next rept will be submitted by 831117
BOOKER, J E Gulf States Utilities Co 83/09/28 COLLINS, J T Region 4, Office of Director. Ip 20723 233 24X
Fiche 50-458, 83/09/28, 8310130256

8310130183 Interim Deficiency Rept DR-97 Investigation ongoing Next rept will be provided by 831110
BOOKER, J E Gulf States Utilities Co 83/09/29 COLLINS, J T Region 4, Office of Director. Ip 20724 326, 24X
Fiche 50-458, 83/09/29, 8310130183

8310130322 Interim Deficiency Rept DR-130 Investigation incomplete. Interim or final rept expected by 831122
BOOKER, J E Gulf States Utilities Co 83/09/29 COLLINS, J T Region 4, Office of Director Ip 20719 360 24X
Fiche 50-458, 83/09/29, 8310130322

8310130215 Interim Deficiency Rept DR-107 Util investigation incomplete Next rept will be submitted by 831025
BOOKER, J E Gulf States Utilities Co 83/09/30 COLLINS, J T Region 4, Office of Director. Ip 20725 048 24X
Fiche 50-458, 83/09/30, 8310130215

8310130258 Final Deficiency Rept DR-117 re previously unanalyzed containment negative pressure scenario Condition does not meet criteria for reportability under 10CFR50 55(a).
BOOKER, J E Gulf States Utilities Co 83/09/30 COLLINS, J T Region 4, Office of Director Ip 20723 224 24X
Fiche 50-458, 83/09/30, 8310130258

8310180303 Interim Deficiency Rept DR-126 Investigation not completed Next rept will be submitted by 831114
BOOKER, J E Gulf States Utilities Co 83/10/03 COLLINS, J T Region 4, Office of Director Ip 20806 325 24X
Fiche 50-458, 83/10/03, 8310180303

8310180461 Interim Deficiency Rept DR-131 Investigation ongoing Interim or final status rept will be provided by 831104
BOOKER, J E Gulf States Utilities Co 83/10/03 COLLINS, J T Region 4, Office of Director Ip 20802 064 24X
Fiche 50-458, 83/10/03, 8310180461.

8310180305 Final Deficiency Rept DR-80 re defective piston skirt castings installed in emergency diesel generator engines supplied by Transamerica Delaval. Initially reported on 821124 Piston skirts replaced Also reported per Part 21.
BOOKER, J E Gulf States Utilities Co 83/10/06 COLLINS, J T Region 4, Office of Director 2pp 20803 096, 24X
Fiche 50-458, 83/10/06, 8310180305

8310180269 Interim Deficiency Rept DR-132 Investigation incomplete. Next rept will be provided by 831128
BOOKER, J E Gulf States Utilities Co 83/10/07 COLLINS, J T Region 4, Office of Director. Ip 20801 114 24X
Fiche 50-458, 83/10/07, 8310180269

8310180460 Interim Deficiency Rept DR-124 Investigation ongoing Interim or final status rept will be provided by 831124
BOOKER, J E Gulf States Utilities Co 83/10/11 COLLINS, J T Region 4, Office of Director. Ip 20802 065 24X
Fiche 50-458, 83/10/11, 8310180460

DOCKETED ITEMS

8310210149 Interim Deficiency Rept DR-94 Investigation ongoing Interim or final status rept will be provided by 831123
BOOKER, J E Gulf States Utilities Co 83/10/12 COLLINS, J T
Region 4, Office of Director 1p 20856 097 24X
Fiche 50-458, 83/10/12, 8310210149

8310210262 Interim Deficiency Rept DR-103 Investigation ongoing Interim or final status rept will be provided by 831129
BOOKER, J E Gulf States Utilities Co 83/10/13 COLLINS, J T
Region 4, Office of Director 1p 20849 139 24X
Fiche 50-458, 83/10/13, 8310210262.

8310210175 Interim Deficiency Rept DR-104 Investigation incomplete. Next rept will be submitted by 831123
BOOKER, J E Gulf States Utilities Co 83/10/14 COLLINS, J T
Region 4, Office of Director 1p 20856 150 24X
Fiche 50-458, 83/10/14, 8310210175

8310210201 Interim Deficiency Rept DR-105 Investigation incomplete. Next rept will be submitted by 831130
BOOKER, J E Gulf States Utilities Co 83/10/14 COLLINS, J T
Region 4, Office of Director 1p 20856 081 24X
Fiche 50-458, 83/10/14, 8310210201

8310210255 Part 21 rept re potential defects in molded case, 100 ampere frame, multi-pole E & HE series circuit breakers Encl: suppl 830926 ltr.
FENNETEAU, M M Gould, Inc 83/10/14 MURLEY, T E Region 1, Office of Director 2pp 20851 047 24X Fiche: 50-458, 83/10/14, 8310210255

8310280030 Interim Deficiency Rept DR-136 Investigation incomplete. Interim or final status rept will be provided by 831209
BOOKER, J E Gulf States Utilities Co 83/10/17 COLLINS, J T
Region 4, Office of Director 1p 20933 208 24X
Fiche 50-458, 83/10/17, 8310280030

8310280084 Interim Deficiency Rept DR-112 Investigation ongoing. Interim or final status rept will be provided by 831130.
BOOKER, J E Gulf States Utilities Co 83/10/17 COLLINS, J T
Region 4, Office of Director 1p 20935 064 24X
Fiche 50-458, 83/10/17, 8310280084.

8310280117 Interim Deficiency Rept DR-78 Investigation incomplete. Next rept will be submitted by 840116.
BOOKER, J E Gulf States Utilities Co 83/10/17 COLLINS, J T
Region 4, Office of Director 1p 20929 263 24X
Fiche 50-458, 83/10/17, 8310280117

8310280011 Final Deficiency Rept DR-61 re length of capscrew which holds starting air valve assembly in cylinder head of standby diesel generators Condition not reportable under 10CFR50 55(f)
BOOKER, J E Gulf States Utilities Co 83/10/18 COLLINS, J T
Region 4, Office of Director 1p 20932 278 24X
Fiche 50-458, 83/10/18, 8310280011

10280053 Interim Deficiency Rept DR-119 Investigation incomplete. Final or interim rept expected by 831111
BOOKER, J E Gulf States Utilities Co 83/10/18 COLLINS, J T
Region 4, Office of Director 1p 20933 331 24X
Fiche 50-458, 83/10/18, 8310280053

8310270206 Part 21 rept re engine mounted electrical cables. Defective cable not installed as 830927 ltr states Parts shipped & installed on Gulf States River Bend Site (Engine Serial 74039/40 DSR 48) Instruction for cable changeout due in Nov
BOYER, R E Transamerica Delaval, Inc 83/10/20 Director's Office, Office of Inspection and Enforcement 1p 20924 108 24X
Fiche: 50-000, 83/10/20, 8310270206

8310270206 RIVER BEND STATION, UNIT 2

Application/construction stage documents & correspondence

0280183 Appeals partial denial of FOIA request for four categories of info re Caseload Forecast Panel 830330-31 meeting & site visit
ALKENHEINER, D. Louisiana Consumer's League, Inc. 83/09/01
Office of the Executive Director for Operations 2pp. 20963 342.
4X Fiche 50-459, 83/09/01, 8310280183

0070319 Responds to 810330 ltr re Ultimate capacity analysis of art III containments Ultimate capacities of containment equipment hatch & personnel airlock determined to be 56 psi 72 psi, respectively
BOOKER, J E Gulf States Utilities Co 83/09/30 NOVAK, T M.
Assistant Director for Licensing 7pp 20652 177 24X
Fiche: 50-458, 83/09/30, 8310070319.

8310210221 Summarizes analysis of inclusion of redundant chlorine & ammonia detectors in control bldg ventilation sys design
NRC reconsideration of requirement Requested Meeting in Bethesda, MD in Nov proposed
BOOKER, J E Gulf States Utilities Co 83/10/17 SCHWENCER, A
Licensing Branch 2 3pp 20852 084 24X Fiche 50-458, 83/10/17, 8310210221

8310260014 Forwards request for addl info re mechanical engineering to proceed w/review of DL application
SCHWENCER, A Licensing Branch 2 83/10/18 CAHILL, W J Gulf States Utilities Co 3pp 20928 043 24X Fiche 50-458, 83/10/18, 8310260014

8310280189 Responds to appeal re partial denial of FOIA request for four categories of info re Caseload Forecast Panel 830330-31 meeting & site visit Forwards complete version of requested documents
DIRCKS, W J Office of the Executive Director for Operations
83/10/18 FALKENHEINER, D Falkenheiner, D 1p 20963 344 24X
Fiche 50-458, 83/10/18, 8310280189

--8310280199 Calculations re facility components Supporting documentation encl.
* Gulf States Utilities Co 83/03/30 11pp 20963 350 24X
Fiche 50-458, 83/10/18, 8310280189

8310260442 Notification of 831117 meeting w/util in Bethesda, MD to discuss equipment qualification programs
WEINKAM, E J Licensing Branch 2 83/10/19 SCHWENCER, A Licensing Branch 2 3pp 20926 354 24X Fiche 50-458, 83/10/19, 8310260442

C Utility Environmental Report (ER), amends & correspondence

8310030232 Forwards Suppl 6 to environ rept - DL stage Review questions Attached to NRC 830708 ltr renumbered Affidavit of Svc encl
CAHILL, W J Gulf States Utilities Co 83/09/27 EISENHUT, D G Division of Licensing 7pp 20590 074 24X Fiche 50-458, 83/09/27, 8310030232

--8310030238 Suppl 6 to environ rept - DL stage
* Stone & Webster, Inc 83/09/30 62pp 20590 086 24X
Fiche 50-458, 83/09/27, 8310030232

E NRC Safety Evaluation Report (SER), supple & correspondence

8310240272 Requests estimated dates for submitting addl info associated w/SER open & confirmatory issues Response requested within 7 days
SCHWENCER, A Licensing Branch 2 83/10/18 CAHILL, W J Gulf States Utilities Co 2pp 20907 332 24X Fiche 50-458, 83/10/18, 8310240272

8310270181 Revises schedule for providing responses to draft SER issues & clarifications to FSAR Responses previously committed for 831015 will be provided between 831101 & 1231
BOOKER, J E Gulf States Utilities Co 83/10/25 SCHWENCER, A Licensing Branch 2 1p 20924 175 24X Fiche 50-458, 83/10/25, 8310270181

F Security, medical, emergency & fire protection plans

8310130084 Notification of 831012-13 meetings w/util in St Francisville, LA to discuss onsite emergency preparedness topics
WEINKAM, E J Licensing Branch 2 83/10/03 SCHWENCER, A Licensing Branch 2 3pp 20777 022 24X Fiche 50-458, 83/10/03, 8310130084

G Adjudicatory correspondence

8310120398 Order rewording Contention 2 re probability of failure of old river control structure
COTTER, B P, COLE, R F, LINENBERGER, G Atomic Safety and Licensing Board Panel 83/10/07 2pp 20700 204 24X Fiche 50-458, 83/10/07, 8310120398

K Utility Final Safety Analysis Report (FSAR) & amends

8310030226 Certifies svc of Amend 10 to FSAR on 830913 Distribution list encl
LIBERTOWICZ, F. Gulf States Utilities Co LIBERTOWICZ, F Stone & Webster, Inc 83/09/27 2pp 20590 147 24X Fiche 50-458, 83/09/27, 8310030226

DOCKETED ITEMS

353

M Antitrust correspondence

8310250171 Forwards NRC updated OL antitrust inquiry transmitted to
util on 830816
VOLGER, B H Hearing Branch 2 83/10/13 SPIEGEL, G Spiegel &
McDiarmid 23pp 20893 282 24X Fiche 50-458, 83/10/13, 8310250171

G Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins For Welder
Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New
York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
Detectors Positioned at Control Room Ventilation Air
Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New
York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse
Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New
York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to
Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co. of New
York, Inc 115pp 20716 324, 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass
Loops Used in Westinghouse Plants." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New
York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical
Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New
York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect
Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New
York, Inc 117pp 21043:075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective
Self-Contained Breathing Apparatus Air Cylinders." Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New
York, Inc 120pp 20827 129, 24X Fiche 50-000, 83/10/11, 8308300761

8310260017 Forwards request for addl info re preservice/in-service insp
programs to proceed w/review of DL application
SCHWENCER, A Licensing Branch 2 83/10/18 CAHILL, W J Gulf
States Utilities Co 4pp. 20926 359 24X Fiche 50-458, 83/10/18,
8310260017

S Reportable occurrences, LERs & related correspondence

8310270206 Part 21 rept re engine mounted electrical cables Defective
cable not installed as 830927 ltr states Parts shipped &
installed on Gulf States River Bend Site (Engine Serial
74039740 DSR 48) Instruction for cable changeout due in Nov
BOYER, R E Transamerica Delaval, Inc. 83/10/20 Director's
Office, Office of Inspection and Enforcement, 1p 20924:108 24X
Fiche 50-000, 83/10/20, 8310270206

DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

A Application/Construction stage documents & correspondence

8310030303 Forwards Rev 1 to BAW-1762, "Auxiliary Feedwater Sys
Reliability Study for WPPSS Unit 1," in response to
NUREG-0737, Item II, E 1
BORESEN, Q C Washington Public Power Supply System 83/09/23
ADENBAM, E O, Licensing Branch 4 1p 20593.181 24X
Fiche 50-460, 83/09/23, 8310030303.

--8310030306 Rev 1 to "Auxiliary Feedwater Sys Reliability Study of WPPSS
Unit 1 "
* Babcock & Wilcox Co BAW-1762 R01 83/06/30 41pp
20593 183 24X Fiche 50-460, 83/09/23, 8310030303

8310210224 Forwards "Rept on Containment Structural Integrity Test for
WPPSS Unit 1 " Containment responded satisfactorily to test
pressure loads & acceptance criteria of ASME III, Div 2.
SORENSEN, Q C Washington Public Power Supply System 83/09/28
ADENBAM, E O Licensing Branch 4 1p 20847 084 24X
Fiche 50-460, 83/09/28, 8310210224

--8310210225 "Rept on Containment Structural Integrity Test for WPPSS
Unit 1 " W/seven oversize figures Aperture cards are
available in PDR
* United Engineers & Constructors, Inc (subs of Raytheon Co)
83/06/03 482pp 20847 085 24X Fiche 50-460, 83/09/28,
8310210224

8310310489 Summary of 830826 meeting w/B&W Owners Group re
implementation of Generic Ltr 83-28 concerning defenses
against ATWS & proposed ATWS rule for B&W plants. List of
attendees & vignettes encl
KADAMBIF, P Operating Reactors Branch 4 83/10/20, Operating
Reactors Branch 4 13pp 20965 147 24X Fiche 50-000, 83/10/20,
8310310489

F Security, medical, emergency & fire protection plans

8309300239 Forwards Amend 4 to "Fire Protection Evaluation,"
Vols 1 & 2, in response to 820103 request & 10CFR50, App R.
SORENSEN, Q C Washington Public Power Supply System 83/09/22
ADENBAM, E O Licensing Branch 4 1p, 20544 199, 24X
Fiche 50-460, 83/09/22, 8309300239

--8309300246 "Fire Protection Evaluation," Vols 1 & 2
W/oversized drawings Aperture cards available in PDR
* Washington Public Power Supply System 83/09/22 650pp
20544, 200 24X Fiche 50-460, 83/09/22, 8309300239

G Adjudicatory correspondence

8310040200 Updated response to 830812 second set of interrogatories &
request to produce Certificate of Svc encl
ROSE, J E Coalition for Safe Power 83/09/27 Washington Public
Power Supply System 5pp 20615:028 24X Fiche 50-460, 83/09/27,
8310040200

8310040175 Memorandum & order granting until 830906 motion to strike
Coalition for Safe Power 830822 motion to compel until
responses to Coalition 830713 third set of interrogatories.
Coalition alternate request to suspend hearing denied
GROSSMAN, H Atomic Safety and Licensing Board Panel 83/09/30,
Washington Public Power Supply System 4pp 20608 076 24X
Fiche 50-460, 83/09/30, 8310040175.

8310180320 Memorandum & Order LBP-83-66, admitting Coalition for Safe
Power as intervenor, ruling on contentions & holding
proceeding in abeyance Until ordered to file quarterly repts
on const activities
GROSSMAN, H Atomic Safety and Licensing Board Panel 83/10/14,
Coalition for Safe Power 40pp 20806, 188 24X
Fiche 50-460, 83/10/14, 8310180320

8310200240 Memorandum & order denying until 830912 motion to compel
Coalition for Safe Power to produce documents referenced in
response to util interrogatories Requests denied as moot or
for other reasons as noted
GROSSMAN, H Atomic Safety and Licensing Board Panel 83/10/18
Washington Public Power Supply System 5pp. 20833 059, 24X
Fiche. 50-460, 83/10/18, 8310200240.

8310210203 Order scheduling 831027 telephone conference re 840110
hearing.
GROSSMAN, H Atomic Safety and Licensing Board Panel 83/10/19,
2pp 20855:113 24X Fiche 50-460, 83/10/19, 8310210203.

8310310226 Memorandum & order confirming 831027 telcon w/all parties to
ensure resolution of discovery matters & adherence to
previously adopted schedule.
GROSSMAN, H Atomic Safety and Licensing Board Panel. 83/10/28
2pp 20947, 125 24X Fiche 50-460, 83/10/28, 8310310226

G. Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins For Welder
Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New
York, Inc 117pp 20754:022 24X Fiche 50-000, 83/09/26, 8308300340

DOCKETED ITEMS

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 119pp 20716 324 24X Fiche 50-000,83/09/29,8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043 075. 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761.

B Reportable occurrences, LERs & related correspondence

8310270206 Part 21 rept re engine mounted electrical cables Defective cable not installed as 830927 ltr states Parts shipped & installed on Gulf States River Bend Site (Engine Serial 740397/40 DER 48) Instruction for cable changeout due in Nov 80VER, R E Transamerica Delaval, Inc 83/10/20 Director's Office, Office of Inspection and Enforcement 1p 20924 108 24X Fiche 50-000,83/10/20,8310270206

V. Operator Examinations

8310030142 Requests schedule, by 831028, for requalification training & exams for 1984 in order to coordinate Region V audit of operator requalification programs.
BISHOP, T. M. Division of Resident Reactor Project & Engineering Programs 83/09/26. GODFREY, G Washington Public Power Supply System 2pp 20390 040 24X Fiche 50-397,83/09/26,8310030142

DOCKET 50-461 CLINTON POWER STATION, UNIT 1

A Application/construction stage documents & correspondence

8310120181 Informs that final corrective action item re recovery Verification team assessment of QA program & implementation as applied to mechanical equipment, piping, pipe supports/restraints & HVAC complete on 830718, per 820421 ltr.
HALL, D. P. Illinois Power Co. 83/08/04 KEPLER, J. Q. Region 3, Office of Director 1p 20695-295 24X Fiche 50-461,83/08/04,8310120181

8310050085 Advises of conditional acceptance of use of ASME Code Case N-315, "Repair of Bellows, Section III, Div 1," to repair 10 guard pipe expansion bellows Description & justification of repair not replacement, must be submitted
SCHWENCER, A Licensing Branch 2 83/09/27 NELSON, R. M. Illinois Power Co 2pp 20650 189 24X Fiche 50-461,83/09/27,8310050085.

8310210009 Informs that HPCS diesel generator preoperational testing program complying w/Reg Guides 1.108 & 1.9 & IEEE Std 387-1977 will be implemented Program description provided.
NELSON, R. M. Illinois Power Co 83/10/14 SCHWENCER, A Licensing Branch 2, 2pp 20856 049. 24X Fiche 50-461,83/10/14,8310210009.

8310260346 Summary of Caseload forecast Panel 830810-12 meetings w/uti/ in Clinton, IL re const status of facility Viewgraphs encl
ABELSON, H Licensing Branch 2 83/10/17 Licensing Branch 2 164pp 20918 084 24X Fiche 50-461,83/10/17,8310260346

8310240254 Submits daily highlights Unit 2 canceled on 831014 Const on Unit 1 continuing & not affected by cancellation
HARRISON, G Licensing Branch 2 83/10/18 DENTON, H R, CASE, E O, CARTER, J Office of Nuclear Reactor Regulation, Director 1p 20907 277 24X Fiche 50-461,83/10/18,8310240254

E NRC Safety Evaluation Report (SER), supp's & correspondence

8309120437 Provides proposed responses to questions re SER (NUREG-0853) Confirmatory Issue 1 concerning degraded core hydrogen control & emergency plan dose assessment reporting sys
NELSON, R. M. Illinois Power Co 83/09/06 SCHWENCER, A Licensing Branch 2 6pp 20335 248 24X Fiche 50-461,83/09/06,8309120437

8310120359 Advises that util has incorporated three LRO-II position papers into DL application Position Paper 3-CRB, "Periodic Low Pressure Leakage Testing of Drywell," constituting response to Confirmatory Issue 66 of SER (NUREG-0853)
NELSON, R. M. Illinois Power Co 83/09/30 SCHWENCER, A Licensing Branch 2 3pp 20700 206 24X Fiche 50-461,83/09/30,8310120359

8310140228 Forwards draft FSAR page changes on SER Confirmatory Issues 45 & 46 re TMI Action Plan Items 11 K 3 13, "HPCI & RCIC Initiation Levels" & 11 K 3 15, "Isolation of HPCI & RCIC " Engineering design completed
NELSON, R. M. Illinois Power Co 83/10/06 SCHWENCER, A Licensing Branch 2 11pp 20761 253 24X Fiche 50-461,83/10/06,8310140228

8310270552 Releases public version of revised emergency plan
FELTON, J. M. Division of Rules and Records 83/10/21 Document Management Branch 1p 20944 017 24X Fiche 50-461,83/10/21,8310270552

--8310270569 Forwards public version of draft Amend 28 to FSAR, App 13 B, consisting of Rev 2 to Emergency Plan CAP1890 008 Rev should resolve SER Outstanding Issue 18 (NUREG-0853)
NELSON, R. M. Illinois Power Co 83/10/14 SCHWENCER, A Licensing Branch 2 1p 20944 018 24X Fiche 50-461,83/10/21,8310270552

F Security, medical, emergency & fire protection plans

8309120437 Provides proposed responses to questions re SER (NUREG-0853) Confirmatory Issue 1 concerning degraded core hydrogen control & emergency plan dose assessment reporting sys
NELSON, R. M. Illinois Power Co 83/09/06 SCHWENCER, A Licensing Branch 2 6pp 20335 248 24X Fiche 50-461,83/09/06,8309120437

8310200201 Forwards Amend 27 to FSAR, consisting of safety relief valve monitoring description, Chapter 14 updating & responses to NRC questions on emergency preparedness meteorological program
HALL, D. P. Illinois Power Co 83/10/11, DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20828 292 24X Fiche 50-461,83/10/11,8310200201

8310270552 Releases public version of revised emergency plan
FELTON, J. M. Division of Rules and Records 83/10/21 Document Management Branch. 1p 20944 017 24X Fiche 50-461,83/10/21,8310270552

--8310270569 Forwards public version of draft Amend 28 to FSAR, App 13 B, consisting of Rev 2 to Emergency Plan CAP1890 008 Rev should resolve SER Outstanding Issue 18 (NUREG-0853)
NELSON, R. M. Illinois Power Co 83/10/14 SCHWENCER, A Licensing Branch 2 1p 20944 018 24X Fiche 50-461,83/10/21,8310270552

--8310270574 Public version of draft Amend 28 to FSAR, App 13 B, consisting of Rev 2 to emergency plan
* Illinois Power Co 83/10/10 303pp 20944 019 24X Fiche: 50-461,83/10/21,8310270552

G Adjudicatory correspondence

8310120403 Notice of appearance in proceeding Certificate of Svc encl
ABELSON, A Illinois, State of 83/10/06 3pp 20699 017 24X Fiche 50-461,83/10/06,8310120403

H General correspondence

8310110105 Advises that R Nelson appointed Director of Nuclear Licensing & Configuration
HALL, D. P. Illinois Power Co 83/09/30 SCHWENCER, A. Licensing Branch 2 1p 20668 136 24X Fiche 50-461,83/09/30,8310110105

DOCKETED ITEMS

K Utility Final Safety Analysis Report (FSAR) & amends

8310200201 Forwards Amend 27 to FSAR, consisting of safety relief valve monitoring description, Chapter 14 updating & responses to NRC questions on emergency preparedness meteorological program
HALL, D P Illinois Power Co 83/10/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20828 292 24X
Fiche 50-461,83/10/11,8310200201

--8310200205 Amend 27 to FSAR
* Illinois Power Co 83/10/31 365pp 20828 293 24X
Fiche 50-461,83/10/11,8310200201

Q Inspection reports, IE Bulletins & correspondence

8310060282 Forwards IE Insp Rept 50-461/83-14 on 830824-26 No noncompliance noted
KNOP, R C Region 3, Office of Director. 83/09/14 GERSTNER, W C Illinois Power Co 2pp 20646 159 24X Fiche 50-461,83/09/14, 8310060282

--8310060309 IE Insp Rept 50-461/83-14 on 830824-26 No noncompliance noted Major areas inspected licensee action on open items, results of study on nonconformance repts & design verification of electrical raceway support sys
JABLONSKI, F. J., HAYES, D W Region 3, Office of Director 83/09/14 20pp 20646 161 24X Fiche 50-461,83/09/14,8310060282

8310140147 Forwards IE Insp Rept 50-461/83-15 on 830824-26 & 31-0901 & notice of violation
STREETEER, J F Region 3, Office of Director 83/09/29 GERSTNER, W C Illinois Power Co 2pp 20763 025 24X
Fiche 50-461,83/09/29,8310140147

--8310140148 Notice of violation from insp on 830824-26 & 31-0901
STREETEER, J F Region 3, Office of Director 83/09/29 2pp 20763 027 24X Fiche 50-461,83/09/29,8310140147

--8310140150 IE Insp Rept 50-461/83-15 on 830824-26 & 31-0901
Noncompliance noted failure to specify that 10CFR21 provisions applied to five welding matl procurement documents & to assure bore bent piping compliance
SCHULZ, R D, HUNTER, D R Region 3, Office of Director 83/09/29 10pp 20763 029 24X Fiche 50-461,83/09/29,8310140147

8310250636 Forwards IE Insp Rept 50-461/83-13 on 830727-0915, No noncompliance noted
KNOP, R C Region 3, Office of Director 83/09/30 GERSTNER, W C Illinois Power Co 2pp 20900 296 24X Fiche 50-461,83/09/30, 8310250636

--8310250642 IE Insp Rept 50-461/83-13 on 830727-0915 No noncompliance noted Major areas inspected const activities, including matl laydown & storage areas, program control, licensee action on previous insp findings & welding activities
LIVERMORE, H H, CHRISTIANSON, F, HAYNES, D W Region 3, Office of Director 83/09/29 5pp 20900 298 24X Fiche 50-461,83/09/30, 8310250636

8310060395 Ack receipt of 830728 ltr requesting concurrence in plans for proceeding w/Phase III insp activities delineated in HVAC recovery plan outline Phase III reinsp & plans to remove galvanox from welds acceptable
KEPPLER, J Q Region 3, Office of Director. 83/10/03 GERSTNER, W C Illinois Power Co 1p 20641, 218 24X Fiche 50-461,83/10/03, 8310060395

--8310060409 Requests review & concurrence to proceed w/Phase III of HVAC recovery plan Also requests concurrence to remove galvanox on all accessible first attachment, hanger structural & hanger-to-duct welds
HALL, D P Illinois Power Co 83/07/28 KEPPLER, J Q Region 3, Office of Director 2pp. 20641:219 24X Fiche 50-461,83/10/03, 8310060395

8310310289 Forwards IE Insp Rept 50-461/83-16 on 830913-16, No noncompliance noted
KNOP, R C Region 3, Office of Director 83/10/12 GERSTNER, W C Illinois Power Co 2pp 20937:087 24X Fiche 50-461,83/10/12, 8310310289

---8310310293 IE Insp Rept 50-461/83-16 on 830913-16 No noncompliance noted Major areas inspected assessment & progress w/record & field verification & open item action (ref confirmation of 820901 & 1006 action ltrs)
JABLONSKI, F. J., HAYES, D W Region 3, Office of Director 83/10/12 8pp 20937:089 24X Fiche 50-461,83/10/12,8310310289

8310180271 Clarifies NRC position re procedures for admitting NRC personnel to facilities List of personnel requiring access to vital areas encl Updates will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 GERSTNER, W C Illinois Power Co 7pp 20807 036 24X Fiche 50-461,83/10/14, 8310180271

8310250619 Describes significant improvements in corrective action program, eliminating need for checklist trending, in response to notices of violation & 820901 confirmation of action ltr
HALL, D P Illinois Power Co 83/10/17, KEPPLER, J Q, Region 3, Office of Director 2pp 20900 287 24X Fiche 50-461,83/10/17, 8310250619

S Reportable occurrences, LERs & related correspondence

8310040204 Final Deficiency Rept 55-83-05 re failure of certain 1/4-inch 20-hex head cap screws during installation of conduit strap attachments to supports Initially reported on 830412 Item not reportable per 10CFR30 55(a)
HALL, D P Illinois Power Co 83/09/26 KEPPLER, J Q, Region 3, Office of Director 4pp 20614 276 24X Fiche 50-461,83/09/26, 8310040204

8310040238 Final deficiency rept re wall thickness for safety-related piping Initially reported on 821007 Lines 1LP21A4 & 1LP21B4 will be used as-installed & penetration sleeve will be modified to shield pipe from external loads
HALL, D P Illinois Power Co 83/09/26 KEPPLER, J Q Region 3, Office of Director 4pp 20613 220 24X Fiche 50-461,83/09/26, 8310040238

8310120077 Final Deficiency Rept 83-04 re control of design change documents Initially reported on 830215 Procedures revised re methods of posting & handling design change documents.
HALL, D P Illinois Power Co 83/09/30 KEPPLER, J Q, Region 3, Office of Director 4pp 20697 157 24X Fiche 50-461,83/09/30, 8310120077

8310120441 Potential Deficiency 55-82-09 re small bore/instrumentation piping & conduit support design calculations Initially reported on 820902 Personnel reviewing small bore/instrumentation piping support calculations retained
HALL, D P Illinois Power Co. 83/09/30 KEPPLER, J Q Region 3, Office of Director 6pp 20698 313 24X Fiche 50-461,83/09/30, 8310120441

DOCKET 50-462 CLINTON POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

8310240254 Submits daily highlights Unit 2 canceled on 831014 Const on Unit 1 continuing & not affected by cancellation
HARRISON, G Licensing Branch 2 83/10/18 DENTON, H. R., CASE, E O, CARTER, J. Office of Nuclear Reactor Regulation, Director 1p 20907 277 24X Fiche 50-461,83/10/18, 8310240254

Q Inspection reports, IE Bulletins & correspondence

8310180271 Clarifies NRC position re procedures for admitting NRC personnel to facilities List of personnel requiring access to vital areas encl Updates will be provided every 6 months.
AXELSON, W L Region 3, Office of Director 83/10/14 GERSTNER, W C Illinois Power Co 7pp 20807 036 24X Fiche 50-461,83/10/14, 8310180271

DOCKET STN-50-470 CESSAR SYSTEM 80

A Application/construction stage documents & correspondence

8310070274 Discusses referenceability of CESSAR-F final design approval NRC support for standardization as abstract concept for future plants w/o resolving present issues inconsistent.
SCHERER, A E Combustion Engineering, Inc 83/09/30, EISENHUT, D. G Division of Licensing 2pp. 20657:026 24X Fiche 50-470,83/09/30, 8310070274

8310270006 Notification of 831026 meeting w/C-E in Bethesda, MD to discuss use of pipe whip restraints in C-E atd BAR design.
MEYER, G C Standardization & Special Projects Branch 83/10/19, THOMAS, C. O. Standardization & Special Projects Branch. 2pp 20940 165 24X Fiche 50-470,83/10/19,8310270006

8310280306 Discusses confirmatory issues impinging on C-E exceptions to limitations placed on CESSAR final design approval (FDA) & possible similar limitations on CESSAR FDA
MEYER, G C. Standardization & Special Projects Branch 83/10/21, EISENHUT, D G. Division of Licensing. 5pp 20964 356 24X Fiche 50-470,83/10/21,8310280306

DOCKETED ITEMS

E NRC Safety Evaluation Report (SER), supp's & correspondence

8310050232 SAFETY EVALUATION REPORT RELATED TO THE FINAL DESIGN OF THE STANDARD NUCLEAR STEAM SUPPLY REFERENCE SYSTEM, CESSAR SYSTEM
80 Docket No 50-470 (Combustion Engineering, Incorporated)
* Office of Nuclear Reactor Regulation, Director NUREG-0852 802
83/09/30 163pp 20635 151 24X Fiche 50-470, 83/09/30, 8310050232

8310170204 Forwards SSER 2 (NUREG-0852) re CESSAR & application for final design approval w/o encl.
THOMAS, C O Standardization & Special Projects Branch 83/09/30
SCHERER, A E Combustion Engineering, Inc 2pp 20798 092 24X
Fiche 50-470, 83/09/30, 8310170204

DOCKET 50-471 PILGRIM NUCLEAR POWER STATION, UNIT 2

S Reportable occurrences, LERs & related correspondence

8310140082 PND-1-83-105 on 831007, seismic event occurred in northeastern US w/magnitude of 5.2 on Richter scale in NY & 4.0 in NH no damage to equipment identified.
GALLO, R M Region 1, Office of Director. 83/10/07 1p 20786 116
24X Fiche 50-000, 83/10/07, 8310140082

DOCKET STN-50-482 WOLF CREEK GENERATING STATION

A Application/construction stage documents & correspondence

8310250054 Provides supplemental info on Item 6, "Final Acceptance Criteria," of util 830729 ltr re sys turnover quality action plan info addresses means by which util will conduct final sys walkdown surveillance verification program
KOESTER, O L Kansas Gas & Electric Co 83/08/25 SEIDLE, W C
Region 4, Office of Director 1p 20894 199 24X
Fiche 50-482, 83/08/25, 8310250054

8310110600 Requests that encl 830830 memo re postulated primary reactor coolant loop breaks be reviewed to determine whether change in radiation shielding constitutes agreement that double-ended guillotine pipebreak need not be postulated.
NOVAK, T M Assistant Director for Licensing 83/09/28 KNIIGHT, J P
Assistant Director for Comp & Structures Engineering (Post 830201)
HOUSTON, R W Assistant Director for Reactor Safety MULLER, D R
Assistant Director for Radiation Protection 2pp 20714 344 24X
Fiche 50-000, 83/09/28, 8310110600

8310240039 Notification of 831023 meeting w/util in Rockville, MD to discuss NRC comments on detailed control room design review
HOLONICH, J. J., EDISON, O E. Licensing Branch 1 83/10/12
YOUNGBLOOD, B J Licensing Branch 1 4pp 20903 298 24X
Fiche 50-000, 83/10/12, 8310240039

8310240075 Notification of 831026 meeting w/util & Bechtel in Bethesda, MD to discuss outstanding issues associated w/qualification of electrical equipment
HOLONICH, J. J., EDISON, O E. Licensing Branch 1 83/10/13
YOUNGBLOOD, B J Licensing Branch 1 4pp 20903 210 24X
Fiche 50-000, 83/10/13, 8310240075

8310250133 Forwards marked-up Tech Spec Section 4.0, "Administrative Controls," for review & approval
KOESTER, O L Kansas Gas & Electric Co 83/10/21, DENTON, H R
Office of Nuclear Reactor Regulation, Director. 52pp 20899 187
24X Fiche 50-482, 83/10/21, 8310250133

E NRC Safety Evaluation Report (SER), supp's & correspondence

8310180317 Forwards Rev 1 to "Emergency Procedure Generation Package," & Rev 1 to "Writers Guide For Emergency Operating Procedures," per Generic Ltr 82-33 (NUREG-0737, Suppl 1). Listed SER items resolved
KOESTER, O L Kansas Gas & Electric Co. 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director. 2pp. 20803 101.
24X Fiche 50-482, 83/10/14, 8310180317

--8310180321 Rev 1 to Procedure ADM 01-052 "Emergency Procedure Generation Package."
ARMSTRONG, S Kansas Gas & Electric Co. 83/10/11 14pp
20803 103 24X Fiche 50-482, 83/10/14, 8310180317

--8310180325 Rev 1 to Procedure ADM 02-022 "Writers Guide for Emergency Operating Procedures."
ARMSTRONG, S. Kansas Gas & Electric Co. 83/10/03 30pp
20803 117 24X Fiche 50-482, 83/10/14, 8310180317.

F Security, medical, emergency & fire protection plans

8310110376 Forwards request for addl info for review of emergency plan info requested within 2 wks
YOUNGBLOOD, B J Licensing Branch 1 83/09/23 KOESTER, O L Kansas
Gas & Electric Co 3pp 20713 225, 24X Fiche 50-482, 83/09/24,
8310110376

8310170713 Forwards request for addl info re instrumentation & control sys - remote safe shutdown info needed within 2 wks of receipt of ltr
YOUNGBLOOD, B J Licensing Branch 1 83/10/05 KOESTER, O L Kansas
Gas & Electric Co SCHNEL, D F Union Electric Co 8pp
20798 126 24X Fiche 50-000, 83/10/05, 8310170713

8310170722 Forwards comments on util detailed control room design review submitted in response to Generic Ltr 82-33, "Suppl 1 to NUREG-0737 Requirements for Emergency Response Capability." Info mgt sys discussion needs more detail
YOUNGBLOOD, B J Licensing Branch 1 83/10/05 KOESTER, O L Kansas
Gas & Electric Co 10pp 20798 100 24X Fiche 50-000, 83/10/05,
8310170722

8310180317 Forwards Rev 1 to "Emergency Procedure Generation Package," & Rev 1 to "Writers Guide For Emergency Operating Procedures," per Generic Ltr 82-33 (NUREG-0737, Suppl 1). Listed SER items resolved
KOESTER, O L Kansas Gas & Electric Co 83/10/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20803 101
24X Fiche 50-482, 83/10/14, 8310180317

--8310180321 Rev 1 to Procedure ADM 01-052 "Emergency Procedure Generation Package."
ARMSTRONG, S Kansas Gas & Electric Co 83/10/11 14pp
20803 103 24X Fiche 50-482, 83/10/14, 8310180317

--8310180325 Rev 1 to Procedure ADM 02-022 "Writers Guide for Emergency Operating Procedures."
ARMSTRONG, S Kansas Gas & Electric Co 83/10/03 30pp
20803 117 24X Fiche 50-482, 83/10/14, 8310180317

8310210414 Releases public version of licensee responses to questions re emergency plan
FELTON, J M Division of Rules and Records 83/10/17 Document
Management Branch 1p 20882 327 24X Fiche 50-482, 83/10/17,
8310210414

--8310210415 Forwards public version of responses to questions re emergency plan Responses will be incorporated in Rev 12 to FSAR
KOESTER, O L Kansas Gas & Electric Co 83/10/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director 12pp 20882 378
24X Fiche 50-482, 83/10/17, 8310210414

G Adjudicatory correspondence

8310140020 Informs that D Garner will tour plant on 831021 DL proceeding issues will not be discussed Trip rept will be served Certificate of Svc encl
REARER, C W Commissioners 83/10/13 LAURENBERG, J A,
ANDERSON, O C, PAXTON, H C Atomic Safety and Licensing Board Panel
2pp. 20767 030 24X Fiche 50-482, 83/10/13, 8310140020

Q Inspection reports, IE Bulletins & correspondence

8310250084 Describes addl mgt initiatives implemented to change QA plans Joint final insp of sys & components released prior to start proposed
KOESTER, O L Kansas Gas & Electric Co 83/07/29 SEIDLE, W C
Region 4, Office of Director 5pp 20894 072, 24X
Fiche 50-482, 83/07/29, 8310250084

8310130172 Forwards IE Insp Rept 50-482/83-19 on 830701-31 No noncompliance noted
SEIDLE, W C Region 4, Office of Director 83/08/22 KOESTER, O L
Kansas Gas & Electric Co 2pp 20724 298 24X
Fiche 50-482, 83/08/22, 8310130172

--8310130178 IE Insp Rept 50-482/83-19 on 830701-31. No noncompliance noted Major areas inspected: observation of startup activities & secondary hydrostatic testing, procedure review & followup on previous violations
JOHNSON, W D, SCHUM, W S, WHITLEY, K A Region 4, Office of
Director 83/08/19 3pp 20724 300 24X Fiche 50-482, 83/08/22,
8310130172

8310130241 Forwards IE Insp Rept 50-482/83-21 on 830616-0815 & notice of violation
SEIDLE, W C Region 4, Office of Director. 83/09/06 KOESTER, O L
Kansas Gas & Electric Co 2pp 20723 272 24X
Fiche 50-482, 83/09/06, 8310130241.

DOCKETED ITEMS

357

--B310130246 Notice of violation, from insp on B30616-0815
* Region 4, Office of Director 83/09/06 1p 20723 274 24X
Fiche 50-482, 83/09/06, B310130241

--B310130251 IE Insp Rept 50-482/83-21 on B30616-0815 Noncompliance
noted Failure to follow &/or implement quality requirements
for work operations on traveler G-SAP-WC-030
ROBERDB, H W, JOHNSON, W D Region 4, Office of Director
83/09/01 6pp 20723 275 24X Fiche 50-482, 83/09/06, B310130241

B310130257 Forwards IE Insp Rept 50-482/83-22 on B30822-26 No
noncompliance noted
SEIDLE, W C Region 4, Office of Director 83/09/13 KOESTER, G L
Kansas Gas & Electric Co 2pp 20723 225 24X
Fiche 50-482, 83/09/13, B310130257

--B310130259 IE Insp Rept 50-482/83-22 on B30822-26 No noncompliance
noted Major areas inspected const GA & turnover of sys
for preoperational testing
JAUDON, J P, JOHNSON, W D Region 4, Office of Director 83/09/12
6pp 20723 227 24X Fiche 50-482, 83/09/13, B310130257

B308300340 IE Info Notice B3-61, "Alleged Use of Stand-Ins for Welder
Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/09/26 Consolidated Edison Co. of New
York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, B308300340

B308300342 IE Info Notice B3-62, "Failure of Redundant Toxic Gas
Detectors Positioned at Control Room Ventilation Air
Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/09/26 Consolidated Edison Co. of New
York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, B308300342

B308300345 IE Info Notice B3-63, "Potential Failures of Westinghouse
Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/09/26 Consolidated Edison Co. of New
York, Inc 118pp 20778 001. 24X Fiche 50-000, 83/09/26, B308300345

B308300349 IE Info Notice B3-64, "Lead Shielding Attached to
Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/09/29 Consolidated Edison Co. of New
York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, B308300349

B308300378 IE Info Notice B3-65, "Surveillance of Flow in RTD Bypass
Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/10/07 Consolidated Edison Co. of New
York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, B308300378

B308300752 IE Info Notice B3-66, "Fatality at Argentine Critical
Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/10/07 Consolidated Edison Co. of New
York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, B308300752

B308300759 IE Info Notice B3-67, "Emergency Use Respirator Matl Defect
Causes Production of Noxious Gases," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/10/11 Consolidated Edison Co. of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, B308300759

B308300761 IE Info Notice B3-68, "Respirator User Warning Defective
Self-Contained Breathing Apparatus Air Cylinders " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/10/11 Consolidated Edison Co. of New
York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, B308300761

B310280121 Forwards NRR SALP rept based partly on input solicited from
selected reviewers & NRR SALP input for Aug 1982 - Jul 1983
Staffing & training attributes contained in rept removed,
based on B30913 meeting in Region IV.
HOLONICH, J J Licensing Branch 1 83/10/12 EISENHUT, D O
Division of Licensing 6pp 20765 083, 24X Fiche 50-482, 83/10/12,
B310280121

B Reportable occurrences, L&Rs & related correspondence

B310120092 Part 21 rept re snubber failure during shock arrester test
Caused by broken capstan spring Vendor effecting corrective
action w/J Evans Co to inspect shock arrestors containing
Evans springs
HADNAGY, P A Pacific Scientific 83/09/14 Region 5, Office of
Director 4pp 20696 167 24X Fiche 50-482, 83/09/14, B310120092

B310040386 Interim deficiency rept re Gould-Rundel Type 88-3
handswitches w/binding cams Initially reported on B30824 AE
evaluating concern Next rept will be submitted by B40120
Switches subj of IE Info Notice B3-42
KOESTER, G L Kansas Gas & Electric Co 83/09/23 SEIDLE, W C
Region 4, Office of Director 1p 20617 295. 24X
Fiche 50-482, 83/09/23, B310040386

B310130192 Fourth interim deficiency rept re documentation & hardware
discrepancies in b-rated refueling water sys Initially
reported on B30121 Evaluation of safety significance of away
strut washer ongoing Final rept will be submitted by B31209.
KOESTER, G L Kansas Gas & Electric Co 83/09/28 SEIDLE, W C
Region 4, Office of Director 2pp 20724 330 24X
Fiche 50-482, 83/09/28, B310130192

B310130223 Interim deficiency rept re Vulkens Supreme cable
terminations Initially reported on B30620 AE evaluation
results expected within 2 wks Next rept will be submitted
by B31123
KOESTER, G L Kansas Gas & Electric Co 83/09/28 SEIDLE, W C
Region 4, Office of Director 1p 20724 095 24X
Fiche 50-482, 83/09/28, B310130223

B310130231 Interim deficiency rept re Culter-Hammer push button
switches Initially reported on B30609 Condition still under
evaluation Next rept will be submitted by B31209
KOESTER, G L Kansas Gas & Electric Co 83/09/28 SEIDLE, W C.
Region 4, Office of Director 1p 20723 286 24X
Fiche 50-482, 83/09/28, B310130231

B310180389 Interim deficiency rept re miscellaneous component failures
in safety-related Power Conversion Products battery
charger Initially reported on B30309 Battery charger testing
near completion Next rept by B40120
KOESTER, G L Kansas Gas & Electric Co 83/10/03 SEIDLE, W C.
Region 4, Office of Director 1p 20803 174 24X
Fiche 50-482, 83/10/03, B310180389

B310180171 Final deficiency rept re changes to hanger notes & symbol
drawings Initially reported on B30221 Matter not reportable
per 10CFR50 55(e)
KOESTER, G L Kansas Gas & Electric Co 83/10/07 SEIDLE, W C
Region 4, Office of Director 1p 20808 360 24X
Fiche 50-482, 83/10/07, B310180171

B310180256 Final deficiency rept re cracked insulated couplings in OE
AKR breakers. Initially reported on B30620 Item determined
not to be reportable per 10CFR50 55(e)
KOESTER, G L Kansas Gas & Electric Co 83/10/07 SEIDLE, W C
Region 4, Office of Director 1p 20802 340 24X
Fiche: 50-482, 83/10/07, B310180256.

B310210244 Interim deficiency rept re Pacific Scientific Co snubbers
Initially reported on B30913 Preliminary investigation
results revealed suspect springs restricted to one
subvendor Final rept will be submitted by B31130.
KOESTER, G L Kansas Gas & Electric Co 83/10/13 OAGLIARDO, J E.
Division of Resident, Reactor Project & Engineering Programs. 2pp
20851-269 24X Fiche 50-482, 83/10/13, B310210244

B310210188 Final deficiency rept re Guyon 1/2-inch socket couplings.
Initially reported on B30617 Item not reportable per
10CFR50 55(e)
KOESTER, G L Kansas Gas & Electric Co 83/10/14, OAGLIARDO, J E.
Division of Resident, Reactor Project & Engineering Programs 1p.
20856 080 24X Fiche: 50-482, 83/10/14, B310210188

B310310074 Part 21 rept re design deficiency involving combination
supports for Class IE cable trays & HVAC ducts. Initially
reported on B31025 Due to misclassification, supports
specified w/less than full safety-related QA program
MEYERS, D L Bechtel Corp 83/10/27 DEYOUNG, R Director's Office,
Office of Inspection and Enforcement. 3pp 20951 040 24X
Fiche 50-000, 83/10/27, B310310074

DOCKET STN-50-483 CALLAWAY PLANT, UNIT 1

A Application/construction stage documents & correspondence

B310110600 Requests that encl B30830 memo re postulated primary reactor
coolant loop breaks be reviewed to determine whether change
in radiation shielding constitutes agreement that
double-ended guillotine pipebreak need not be postulated
NOVAK, T M Assistant Director for Licensing. 83/09/28, KNIGHT, J P
Assistant Director for Comp & Structures Engineering (Post B30201)
HOUSTON, R W Assistant Director for Reactor Safety. MULLER, D R.
Assistant Director for Radiation Protection 2pp. 20714 344. 24X
Fiche 50-000, 83/09/28, B310110600

DOCKETED ITEMS

8308300355 Board Notification B3-46A advises that position re rod drop issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycle
EISENHUT, D G Division of Licensing 83/09/29 PALLADINO, N J
Commissioners 10pp 20632 104 24X Fiche 50-000, 83/09/29, 8308300355

8308300357 Board Notification B2-105A forwards evaluation of allegations re design deficiencies in Class I piping sys info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway
EISENHUT, D G Division of Licensing 83/09/29 PALLADINO, N J
Commissioners 3pp 20632 001 24X Fiche 50-000, 83/09/29, 8308300357

8308300763 Board Notification B3-191 provides info re desirability of current ECCS actuation logic for Westinghouse plants, in light of recent info concerning steam generator tube rupture procedure for Borssele Nuclear Power Station
EISENHUT, D G Division of Licensing 83/10/04 PALLADINO, N J
Commissioners 2pp 20698 033 24X Fiche 50-000, 83/10/04, 8308300763

8308300771 Board Notification B3-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves
EISENHUT, D G Division of Licensing 83/10/06 PALLADINO, N J
Commissioners 3pp 20818 001 24X Fiche 50-000, 83/10/06, 8308300771

8310240039 Notification of 831025 meeting w/util in Rockville, MD to discuss NRC comments on detailed control room design review
HOLONICH, J J, EDISON, O E Licensing Branch 1 83/10/12
YOUNGBLOOD, B J Licensing Branch 1 App 20903 238 24X
Fiche 50-000, 83/10/12, 8310240039

8310240075 Notification of 831026 meeting w/utills & Bechtel in Bethesda, MD to discuss outstanding issues associated w/qualification of electrical equipment
HOLONICH, J J, EDISON, O E Licensing Branch 1 83/10/13
YOUNGBLOOD, B J Licensing Branch 1 App 20903 210 24X
Fiche 50-000, 83/10/13, 8310240075

E NRC Safety Evaluation Report (SER), supply & correspondence

8310270443 Forwards comments on Rev 5A to emergency plan Comments will be categorized as improvement items since SER states plan meets 10CFR50 47(b) stds & 10CFR50 App E requirements, per NUREG-0830
PAPERIELLO, C J Region 3, Office of Director 83/10/25
MATTHEWS, D B Emergency Preparedness Branch 6pp 20923 091 24X
Fiche 50-483, 83/10/25, 8310270443

F Security, medical, emergency & fire protection plans

8310170713 Forwards request for addl info re instrumentation & control sys - remote safe shutdown info needed within 2 wks of receipt of ltr
YOUNGBLOOD, B J Licensing Branch 1 83/10/05 KOESTER, O L Kansas Gas & Electric Co SCHNELL, D F Union Electric Co 6pp 20798 126 24X Fiche 50-000, 83/10/05, 8310170713

8310170722 Forwards comments on util detailed control room design review submitted in response to Generic Ltr B2-33, "Suppl 1 to NUREG-0737 Requirements for Emergency Response Capability" Info mgt sys discussion needs more detail
YOUNGBLOOD, B J Licensing Branch 1, 83/10/05 KOESTER, O L Kansas Gas & Electric Co 10pp 20798 100 24X Fiche 50-000, 83/10/05, 8310170722

8310250656 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/10/20 Document Management Branch 1p 20916 260 24X Fiche 50-483, 83/10/20, 8310250656

8310250661 Forwards public version of revised emergency plan implementing procedures, including Procedures EIP-ZZ-00101 re classification of emergencies, EIP-ZZ-00102 re emergency implementing actions & EIP-ZZ-00201 re notifications
SCHNELL, D F Union Electric Co 83/10/05 KEPLER, J G Region 3, Office of Director 3pp 20916 261 24X Fiche 50-483, 83/10/20, 8310250661

8310250664 Public version of revised emergency plan implementing procedures, including Procedures EIP-ZZ-00101 re classification of emergencies, EIP-ZZ-00102 re emergency implementing actions & EIP-ZZ-00201 re notifications
* Union Electric Co 83/07/18, 540pp 20916 264 24X
Fiche 50-483, 83/10/20, 8310250664

8310270443 forwards comments on Rev 5A to emergency plan Comments will be categorized as improvement items since SER states plan meets 10CFR50 47(b) stds & 10CFR50 App E requirements, per NUREG-0830
PAPERIELLO, C J Region 3, Office of Director 83/10/25
MATTHEWS, D B Emergency Preparedness Branch 6pp 20923 091 24X
Fiche 50-483, 83/10/25, 8310270443

G Adjudicatory correspondence

8310050457 Motion to withdraw portion of DM Rohrer testimony re use of source terms in policy development on redistribution of potassium iodide to general public Certificate of Svc encl
PERLIS, R O Hearing Branch 3 83/09/27 Atomic Safety and Licensing Board Panel 7pp 20632 161 24X Fiche 50-483, 83/09/27, 8310050457

8310040225 Motion for extension to file w/Commission petition for review of ASLB 830914 Decision ALAB-740 Extension should be granted until 15 days after ASLB rules on Joint Intervenor
830923 reconsideration petition Certificate of Svc encl
CHACKES, K M Joint Intervenor-Callaway CHACKES, K M Chackes & Hoare 83/09/24 Commissioners 3pp 20614 236 24X
Fiche 50-483, 83/09/29, 8310040225

8310040217 Order advising that time within which Commission may review ALAB-740 on Commission motion or time within which parties may file petitions for review of ALAB-740 will not commence until date ASLB rules on reconsideration petition
CHILK, S J Office of the Secretary of the Commission 83/10/03
Commissioners 1p 20614 235 24X Fiche 50-483, 83/10/03, 8310040217

8310050509 Memorandum & order approving NRC motion for leave to withdraw testimony of witness DM Rohrer Agreement of parties approved re schedule of filing proposed findings of fact & conclusions of law
OLEASON, J P Atomic Safety and Licensing Board Panel 83/10/04
Office of the Executive Legal Director 1p 20634 018 24X
Fiche 50-483, 83/10/04, 8310050509

8310120420 Findings of fact & conclusions of law Certificate of Svc encl
REED, J O Reed, J O 83/10/06 10pp 20698 282 24X
Fiche 50-483, 83/10/06, 8310120420

8310140063 Response to Joint Intervenor 830823 petition for reconsideration of ASLB 830914 Decision ALAB-740 Insufficient showing made to justify reopening record Certificate of Svc encl
GALEN, R E Union Electric Co GALEN, R E Shaw, Pittman, Potts & Trowbridge 83/10/12 Atomic Safety and Licensing Appeal Panel 201pp 20767 140 24X Fiche 50-483, 83/10/12, 8310140063

8310170419 Response opposing Joint Intervenor 830923 petition for reconsideration of ALAB-740 & to reopen record Integrated design insp program rept not presented in timely fashion Notice of appearance & Certificate of Svc encl
REPKA, D A, PERLIS, R O Hearing Branch 3 83/10/12 Atomic Safety and Licensing Appeal Panel 21pp 20779 174 24X
Fiche 50-483, 83/10/12, 8310170419

8310240180 Memorandum & order directing applicant & NRC to disclose sufficient addl info & views re intervenor 830923 petition for reconsideration of ALAB-740 by 831004 & 15, respectively Disposition of petition awaits receipt of info
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/20
Union Electric Co 4pp 20880 034 24X Fiche 50-483, 83/10/20, 8310240180

8310250163 Proposed findings of fact & conclusions of law on J Reed contentions re emergency planning Final decision to issue license should be ordered Certificate of Svc encl
PERLIS, R O Hearing Branch 3 83/10/21 28pp 20696 296 24X
Fiche 50-483, 83/10/21, 8310250163

8310310200 Reply to Reed 831006 proposed findings of fact & conclusions of law re Contention 6 Findings mischaracterized FDA recommendation & position of applicant & State of MO Certificate of Svc encl
BAXTER, T A Union Electric Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge 83/10/27 13pp 20959 167 24X Fiche 50-483, 83/10/27, 8310310200

M Antitrust correspondence

8310280166 Forwards most recent correspondence re Union Electric Co transmission svc & arrangements for interconnecting svc Unconvinced that umbrella-type transmission svc is proper approach
BARNETT, B J Missouri Joint Municipal Electric Utility Commission 83/09/06 LAMBE, W NRC - No Detailed Affiliation Given 5pp 20929 001 24X Fiche 50-483, 83/09/06, 8310280166

DOCKETED ITEMS

359

A Inspection reports, IE Bulletins & correspondence

8310060449 Forwards IE Insp Rept 50-483/BJ-15 on 830701-0831 & notice of violation
KNOP, R C Region 3, Office of Director 83/09/23 SCHNELL, D F
Union Electric Co 2pp 20641 032 24X Fiche 50-483, 83/09/23,
8310060449

--8310060453 Notice of Violation from Insp on 830701-0831
KNOP, R C Region 3, Office of Director 83/09/23 1p
20641 034 24X Fiche 50-483, 83/09/23, 8310060449

--8310060462 IE Insp Rept 50-483/BJ-15 on 830701-0831 Noncompliance
noted procedural controls inadequate to prevent unauthorized
temporary alterations of plant components from being
accomplished by startup personnel
NEISLER, J H, KONKLIN, J C Region 3, Office of Director
83/09/23 7pp 20641 035 24X Fiche 50-483, 83/09/23, 8310060449

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder
Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
Detectors Positioned at Control Room Ventilation Air
Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse
Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300347 IE Info Notice 83-64, "Load Shielding Attached to
Safety-Related Sys W/o 10CFR40 57 Evaluation " Svc list
encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New
York, Inc 119pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300347

8310040268 Ack receipt of 830920 ltr clarifying status of turbine
driven auxiliary feedwater pump turbine control panels in
response to IL Insp Rept 50-483/BJ-14
KNOP, R C Region 3, Office of Director 83/09/30 SCHNELL, D F
Union Electric Co 1p 20613 001 24X Fiche 50-483, 83/09/30,
8310040268

--8310040273 Responds to NRC 830728 & 0902 ltrs re IE Insp Rept
50-483/BJ-14 Turbine driven auxiliary feedwater pump turbine
control panel procured, received & installed
SCHNELL, D F Union Electric Co 83/09/20 KNOP, R C Region 3,
Office of Director 1p 20613 002 24X Fiche 50-483, 83/09/30,
8310040268

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass
Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical
Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 77pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect
Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective
Self-Contained Breathing Apparatus Air Cylinders " Svc list
encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180260 Clarifies NRC position re procedures for admitting NRC
personnel to facilities List of personnel requiring access
to vital areas until Updates will be provided every 6
months
AXELSON, W L Region 3, Office of Director 83/10/14 SCHNELL, D F
Union Electric Co 7pp 20802 268 24X Fiche 50-483, 83/10/14,
8310180260.

8310310285 Ack receipt of 831010 transmittal of 1982 annual rept for
facility radiological environ monitoring program Open item
identified in IE Insp Rept 50-483/BJ-07-02 closed out
PAPERIELLO, C J Region 3, Office of Director 83/10/26
SCHNELL, D F Union Electric Co 1p 20961 283 24X
Fiche 50-483, 83/10/26, 8310310285

R Periodic operating reports & related correspondence

8310120069 Provides quarterly status rept in response to 810527 ltr
Schedule unchanged Fuel load scheduled for Apr 1984 w/
commercial operation scheduled for late 1984 or early 1985
SCHNELL, D F Union Electric Co 83/10/03 DENTON, H R Office of
Nuclear Reactor Regulation, Director 1p 20697 163 24X
Fiche 50-483, 83/10/03, 8310120069

8310310285 Ack receipt of 831010 transmittal of 1982 annual rept for
facility radiological environ monitoring program Open item
identified in IE Insp Rept 50-483/BJ-07-02 closed out
PAPERIELLO, C J Region 3, Office of Director 83/10/26
SCHNELL, D F Union Electric Co 1p 20961 283 24X
Fiche 50-483, 83/10/26, 8310310285

S Reportable occurrences, LERs & related correspondence

8310210098 Interim Deficiency Rept U-63 re broken or cracked capstan
spring tangs on Pacific Scientific mechanical snubbers
Initially reported on 830916 Caused by age hardening snubber
springs prior to plating Final rept by 831111
SCHNELL, D F Union Electric Co 83/10/14 KEFFLER, J O Region 3,
Office of Director 1p 20858 260 24X Fiche 50-483, 83/10/14,
8310210098

8310310074 Part 21 rept re design deficiency involving combination
supports for Class IE cable trays & HVAC ducts Initially
reported on 831025 Due to misclassification, supports
specified w/less than full safety-related QA program
MEYER, B L Bechtel Corp 83/10/27 DEYOUNG, R Director's Office,
Office of Inspection and Enforcement 3pp 20951 040 24X
Fiche 50-000, 83/10/27, 8310310074

DOCKET STN-50-486 CALLAWAY PLANT, UNIT 2

A Application/construction stage documents & correspondence

8308300355 Board Notification 83-66A advises that position re rod drop
issue revised to require each Westinghouse plant owner
provide statement that required plant-specific calculations
have been performed for first cycle
EISENHUT, D G Division of Licensing 83/09/29 PALLADINO, N J
Commissioners 10pp 20632 106 24X Fiche 50-000, 83/09/29,
8308300355

8308300357 Board Notification 82-105A forwards evaluation of
allegations re design deficiencies in Class I piping sys
Info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway
EISENHUT, D G Division of Licensing 83/09/29 PALLADINO, N J,
Commissioners 3pp 20632 001 24X Fiche 50-000, 83/09/29,
8308300357

8308300763 Board Notification 83-131 provides info re desirability of
current ECCS actuation logic for Westinghouse plants, in
light of recent info concerning steam generator tube rupture
procedure for Borssele Nuclear Power Station
EISENHUT, D G Division of Licensing 83/10/04 PALLADINO, N J,
Commissioners 2pp 20698 033 24X Fiche 50-000, 83/10/04,
8308300763

8308300771 Board Notification 83-128A forwards Equipment Qualification
Branch conclusions re potential problems w/ASCO solenoid
valves
EISENHUT, D G Division of Licensing 83/10/06 PALLADINO, N J
Commissioners 31pp 20818 001 24X Fiche 50-000, 83/10/06,
8308300771

G Adjudicatory correspondence

8310270307 Errata correcting Pages 3 & 435 of ASLB 831024
recommendations to Commission
GLEASON, J P Atomic Safety and Licensing Board Panel 83/10/25
1p 20923 192 24X Fiche 50-247, 83/10/25, 8310270307

DOCKETED ITEMS

G Inspection reports, IE Bulletins & correspondence

8310180260 Clarifies NRC position re procedures for admitting NRC personnel to Facilities List of personnel requiring access to vital areas encl Updates will be provided every 6 months
AXELSON, W L. Region 3, Office of Director 83/10/14 SCINELL, D F
Union Electric Co 7pp 20802 268 24X Fiche 50-483, 83/10/14, 8310180260

B Reportable occurrences, LERs & related correspondence

8310310074 Part 21 rept re design deficiency involving combination supports for Class IE cable trays & HVAC ducts Initially reported on 831025 Due to misclassification, supports specified w/less than full safety-related QA program
MEYER, B L. Bechtel Corp 83/10/27 DEYOUNG, R. Director's Office, Office of Inspection and Enforcement 3pp 20951 040 24X Fiche 50-000, 83/10/27, 8310310074

DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1

G Adjudicatory correspondence

8310110068 Motion to terminate appellate jurisdiction retained in ALAB-482 & ALAB-540 re environ effects of radon releases from U mining & milling for fuel Issue now moot Certificate of Svc encl
CARR, A V. Duke Power Co CARR, A V. Debevoise & Liberman 83/10/04 Atomic Safety and Licensing Appeal Panel 26pp 20668 212 24X Fiche 50-491, 83/10/04, 8310110068

8310130197 Memorandum & Order ALAB-745, granting until request to terminate appellate jurisdiction retained in ALAB-482 re issue of environ effects associated w/radon gas release Plants canceled & CPs surrendered
SHOENAKER, C J. Atomic Safety and Licensing Appeal Panel 83/10/12 Duke Power Co 3pp 20725 006 24X Fiche 50-491, 83/10/12, 8310130197

DOCKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

G Adjudicatory correspondence

8310110068 Motion to terminate appellate jurisdiction retained in ALAB-482 & ALAB-540 re environ effects of radon releases from U mining & milling for fuel Issue now moot Certificate of Svc encl
CARR, A V. Duke Power Co CARR, A V. Debevoise & Liberman, 83/10/04 Atomic Safety and Licensing Appeal Panel 26pp 20668 212 24X Fiche 50-491, 83/10/04, 8310110068

8310130197 Memorandum & Order ALAB-745, granting until request to terminate appellate jurisdiction retained in ALAB-482 re issue of environ effects associated w/radon gas release Plants canceled & CPs surrendered
SHOENAKER, C J. Atomic Safety and Licensing Appeal Panel 83/10/12 Duke Power Co 3pp 20725 006 24X Fiche 50-491, 83/10/12, 8310130197

DOCKET STN-50-493 CHEROKEE NUCLEAR STATION, UNIT 3

G Adjudicatory correspondence

8310110068 Motion to terminate appellate jurisdiction retained in ALAB-482 & ALAB-540 re environ effects of radon releases from U mining & milling for fuel Issue now moot Certificate of Svc encl
CARR, A V. Duke Power Co CARR, A V. Debevoise & Liberman, 83/10/04 Atomic Safety and Licensing Appeal Panel 26pp 20668 212 24X Fiche 50-491, 83/10/04, 8310110068

8310130197 Memorandum & Order ALAB-745, granting until request to terminate appellate jurisdiction retained in ALAB-482 re issue of environ effects associated w/radon gas release Plants canceled & CPs surrendered
SHOENAKER, C J. Atomic Safety and Licensing Appeal Panel 83/10/12 Duke Power Co 3pp 20725 006 24X Fiche 50-491, 83/10/12, 8310130197

DOCKET 50-496 MONTAGUE NUCLEAR POWER STATION, UNIT 1

G Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

DOCKET 50-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2

G Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

DOCKETED ITEMS

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1

A Application/construction stage documents & correspondence

8310070184 Notification of contract execution "Review of Tornado Missile PRA-South Texas Project," awarded to NBS
WIOGINS, E Technical Assistance Contracts Branch FIN B-845/
83/09/29 MATISON, R J Division of Systems Integration (post
811005). SINGH, B K NRC - No Detailed Affiliation Given 1p
20680 248 24X Fiche 50-498, 83/09/29, 8310070184

--8310070188 Ltr Contract NRC-03-83-114 "Review of Tornado Missile PRA-South Texas Project," awarded to NBS
MORTON, K V Division of Contracts FIN B-8457 83/09/21
SIMIU, E Commerce, Dept of, National Bureau of Standards 7pp
20680 249 24X Fiche 50-498, 83/09/29, 8310070184

G Adjudicatory correspondence

831010220 Motion for order limiting scope of Citizens Concerned About Nuclear Power participation in Phase II of OL proceeding
Request based on intervenor failure to meet obligations
Certificate of Svc encl
GUTTERMAN, A H Joint Applicants-South Texas Project GUTTERMAN, A H
Lowenstein, Newman, Reis, Axelrad & Toll 83/10/06 Atomic
Safety and Licensing Board Panel 17pp 20666 051 24X
Fiche 50-498, 83/10/06, 831010220

8310170556 Notices of Commissioner Palladino 831102 site visit One representative of each party may accompany Commissioner on visit Parties must make arrangements w/util Svc list encl
REAMER, C W Commissioners 83/10/14 BECHHOEFER, C, LAMB, J C, HILL, E E Atomic Safety and Licensing Board Panel 2pp 20780 345
24X Fiche 50-498, 83/10/14, 8310170556

8310250545 Forwards response to State of TX interrogatories on Contention 4 & Quadrex & documents in response to Quadrex Interrogatories 7, 11, 18, 20, 30, 31, 36, 42, 45, 46, 47, 49 & 50 Documents re Interrogatories 23, 33 & 34 forthcoming
PERLIS, R G Hearing Branch 3 83/10/18 BERNARD, B E Texas, State of 1p 20701 062 24X Fiche 50-498, 83/10/18, 8310250545

--8310250551 Response to first set of interrogatories & request for production of documents on Quadrex
* Office of the Executive Legal Director 83/10/18 Texas, State of 35pp 20701 063 24X Fiche 50-498, 83/10/18, 8310250545

--8310250558 Response to first set of interrogatories & request for production of documents on Contention 4 re wind speeds
* Office of the Executive Legal Director 83/10/18 Texas, State of 46pp 20701 078 24X Fiche 50-498, 83/10/18, 8310250545

8310260249 Informs of extension for reply to applicant 831006 motion for sanctions Reply date extended to 831031
SINKIN, L Citizens Concerned About Nuclear Power, Inc SINKIN, L
Sinkin, L A 83/10/19 BECHHOEFER, C, LAMB, J C, HILL, E E Atomic Safety and Licensing Board Panel 1p 20712 123 24X
Fiche 50-498, 83/10/19, 8310260249

8310260269 Motion for new contention re instability of soil beneath facility Recently submitted deficiency rept provides sufficient evidence to warrant inquiry. Certificate of Svc encl
SINKIN, L Citizens Concerned About Nuclear Power, Inc SINKIN, L
Sinkin, L A 83/10/20 Atomic Safety and Licensing Board Panel 17pp 20711 311 24X Fiche 50-498, 83/10/20, 8310260269

H General correspondence

8310130142 Responds to 830617 ltr re constituents concerns re environ impact of const & operation of 400 kV dc power line from Walker to Matagorda County, TX No NRC approval required Texas Public Util Commission to hold hearings on application
DIRCKS, W J Office of the Executive Director for Operations
83/09/20 TOWER, J Senate 10pp 20777 032 24X
Fiche 50-498, 83/09/20, 8310130142

K Utility Final Safety Analysis Report (FSAR) & amends

8310030167 Forwards Amend 33 to FSAR Amend revises responses to NUREG-0737, II K items & NRC questions & updates Sections 2 5 1, 3 1-3, 3 11-12 & 5 2 Affidavit encl
GOLDBERG, J H Houston Lighting & Power Co 83/09/27. DENTON, H
Office of Nuclear Reactor Regulation, Director 5pp 20593 323
24X Fiche 50-498, 83/09/27, 8310030167

--8310030168 Amend 33 to FSAR, revising responses to NUREG-0737, II K item & NRC questions & updating Sections 2 5 1, 3 1-3, 3 11-12 & 5 2
* Houston Lighting & Power Co 83/09/27 377pp 20593 328 24X
Fiche 50-498, 83/09/27, 8310030167

Q Inspection reports, IE Bulletins & correspondence

8310140030 FOIA request for IE Insp Rept 79-19, associated notice of proposed imposition of civil penalties, notice of violation & order to show cause
HAMLIN, J B Shaw, Pittman, Potts & Trowbridge 83/05/31. Office of Administration 6pp 20794 110 24X Fiche 50-498, 83/05/31, 8310140030

8310130176 Forwards IE Insp Repts 50-498/83-14 & 50-499/83-14 on 830725-29 No noncompliance noted
MADSEN, O L Region 4, Office of Director. 83/08/22 OPREA, G W.
Houston Lighting & Power Co 2pp 20724 315 24X
Fiche 50-498, 83/08/22, 8310130176

--8310130170 IE Insp Repts 50-498/83-14 & 50-499/83-14 on 830725-29 No noncompliance noted Major areas inspected radiographs, weld-related nonconformance repts, control of weld filler metals, Ebasco audits & structural steel matl control
CROSSMAN, W A, HALL, R E Region 4, Office of Director 83/08/17.
8pp 20724 317 24X Fiche 50-498, 83/08/22, 8310130176

8310140031 Partial response to FOIA request for documents re IE Insp Rept 79-19 & associated notice of proposed imposition of civil penalties, notice of violation & order to show cause
Forwards App A documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/08/23 HAMLIN, J B
Shaw, Pittman, Potts & Trowbridge 1p 20794 116 24X
Fiche 50-498, 83/08/23, 8310140031

--8008270592 Forwards Region 5 rept of investigation re alleged falsification of QA records by Brown & Root inspector
W/O encl
WARD, W J Office of Inspection & Enforcement, Office of the Director 80/08/01 FORTUNA, R Office of Inspector & Auditor.
1p 20795 186 24X Fiche 50-498, 83/08/23, 8310140031

--8310140032 "South Texas Project - History "
* NRC - No Detailed Affiliation Given 83/05/31 4pp
20794 117 24X Fiche 50-498, 83/08/23, 8310140031.

--8310140037 Notification of 800819 meeting w/util & Brown & Root in B City, TX to clarify util response to 800430 show cause order.
* NRC - No Detailed Affiliation Given 83/10/13. NRC - No Detailed Affiliation Given. 4pp 20794 129 24X
Fiche 50-498, 83/08/23, 8310140031

--8310140041 Requests formal public hearing, w/full disclosure, re NRC 79110 investigation of South Texas Project
* Affiliation Unknown 80/02/07 NRC - No Detailed Affiliation Given 1p. 20794 133 24X Fiche 50-498, 83/08/23, 8310140031.

--8310140044 NRC proposal to fine Texas Util for alleged noncompliance w/NRC requirements re Brown & Root QA program & violation of piping weld tests
* NRC - No Detailed Affiliation Given 83/10/13 2pp.
20794 134 24X Fiche 50-498, 83/08/23, 8310140031

--8310140047 Enforcement history, South Texas Project, Oct 1976 - Mar 19
* NRC - No Detailed Affiliation Given 83/10/13. 3pp.
20794 136 24X Fiche 50-498, 83/08/23, 8310140031

DOCKETED ITEMS

- 8310140050 Discusses notice of violation issued as result of 791110-820207 insps Noncompliance noted GC insp by Brown & Root not sufficiently independent Marked-up copy
* NRC - No Detailed Affiliation Given 83/05/31 NRC - No Detailed Affiliation Given 35pp 20794 139 24X
Fiche 50-498,83/08/23,8310140031
- 8310140052 Forwards draft investigation rept & proposed enforcement action for comment Commission briefing on investigation & enforcement planned for wk of 800414 Draft rept also sent to pertinent NRC personnel
SHEWMAKER, R E Director's Office, Office of Inspection and Enforcement 80/04/01 THORNBURG, H D Director's Office, Office of Inspection and Enforcement 140pp 20794 175 24X
Fiche 50-498,83/08/23,8310140031
- 8310140062 Requisition for payment to Continental Airlines for PDX svl of pkg to Houston, TX
* NRC - No Detailed Affiliation Given 80/05/01 2pp 20795 071 24X Fiche 50-498,83/08/23, 8310140031
- 8310140088 Advises that, due to seriousness of violations by Brown & Root & util at South Texas Project, full-scale public hearing in Matagorda County, TX mandatory
VAN HOY, G Affiliation Unknown 80/05/20 STELLD, V Director's Office, Office of Inspection and Enforcement 1p 20795 079 24X
Fiche 50-498,83/08/23,8310140031
- 8310140095 Submits draft generic ltr for use w/incoming correspondence as result of 800430 IE enforcement pkg
STELLD, V Director's Office, Office of Inspection and Enforcement 83/10/13 Affiliation Unknown 3pp 20795 167 24X
Fiche 50-498,83/08/23,8310140031
- 8310040536 Forwards IE Insp Repts 50-498/83-12 & 50-499/83-12 on 830711-21 No noncompliance noted
MADSEN, O L Region 4, Office of Director 83/08/29 OPREA, G W Houston Lighting & Power Co 2pp 20623 254 24X
Fiche 50-498,83/08/29,8310040536
- 8310040546 IE Insp Repts 50-498/83-12 & 50-499/83-12 on 830711-21 No noncompliance noted Major areas inspected licensee mgt of QA activities & QA insp of performance
DBERG, C R, CROSSMAN, W A Region 4, Office of Director 83/08/12 12pp 20623 256 24X Fiche 50-498,83/08/29,8310040536
- 8310030385 Forwards IE Insp Repts 50-498/83-15 & 50-499/83-15 on 830701-0814 No noncompliance noted
MADSEN, O L Region 4, Office of Director 83/09/07 OPREA, G W Houston Lighting & Power Co 2pp 20572 143 24X
Fiche 50-498,83/09/07,8310030385
- 8310030392 IE Insp Repts 50-498/83-15 & 50-499/83-15 on 830701-0814 No noncompliance noted Major areas inspected previous insp findings, storage & maint of equipment, nonperformance repts, structural concrete & matl control & identification
HILL, W M, CROSSMAN, W A Region 4, Office of Director 83/09/02 8pp 20572 145 24X Fiche 50-498,83/09/07,8310030385
- 8310130221 Forwards IE Insp Repts 50-498/83-17 & 50-499/83-17 on 830815-17 & notice of violation
MADSEN, O L Region 4, Office of Director 83/09/07 OPREA, G W Houston Lighting & Power Co 2pp 20724 096 24X
Fiche 50-498,83/09/07,8310130221
- 8310130227 Notice of violation from insp on 830815-17
* Region 4, Office of Director 83/09/07 2pp 20724 098 24X
Fiche 50-498,83/09/07,8310130221
- 8310130230 IE Insp Repts 50-498/83-17 & 50-499/83-17 on 830815-17 Noncompliance noted failure to maintain identification & control of mats
TOMLINSON, D P, CROSSMAN, W A, HALL, R E Region 4, Office of Director 83/09/02 3pp 20724 100, 24X Fiche 50-498,83/09/07,8310130221
- 83100412 Forwards IE Insp Repts 50-498/83-16 & 50-499/83-16 on 830906-08 No noncompliance noted
MADSEN, O L Region 4, Office of Director 83/09/22 OPREA, G W Houston Lighting & Power Co 2pp 20803 165 24X
Fiche 50-498,83/09/22,83100412
- 8310180414 IE Insp Repts 50-498/83-16 & 50-499/83-16 on 830906-08, No noncompliance noted Major areas inspected const activities, including licensee actions on 10CFR50 55(e) rept of breakdown in QA program for procurement cycle
BOARDMAN, J R, CROSSMAN, W A Region 4, Office of Director 83/09/21 6pp 20803 167 24X Fiche 50-498,83/09/22,8310180412
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340
- 8308300342 IC Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in R1D Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761
- S Reportable occurrences, L&Rs & related correspondence

- 8310040410 Final deficiency rept re auxiliary feedwater sys containment isolation valves Initially reported on 830822 Sys design modified to require performance sys function of safety-grade active valves Also reported per Part 21
OPREA, G W Houston Lighting & Power Co 83/09/21 COLLINS, J T Region 4, Office of Director 5pp 20619 035 24X
Fiche 50-498,83/09/21,8310040410
- 8310040289 First interim deficiency rept re corrosion on reactor containment bldg post-tensioning sys tendons Initially reported on 830826 Evaluation underway to determine if condition impairs tendon strength Next rept by 840229
OPREA, G W Houston Lighting & Power Co 83/09/22 COLLINS, J T Region 4, Office of Director 3pp 20614 213 24X
Fiche 50-498,83/09/22,8310040289
- 8310130187 Revised final deficiency rept re essential cooling water intake structure gantry crane Initially reported on 790516 Crane design revised for severe & extreme environ loadings to retain structural integrity
OPREA, G W Houston Lighting & Power Co 83/09/28 COLLINS, J T Region 4, Office of Director 3pp 20724 327 24X
Fiche 50-498,83/09/28,8310130187
- 8310130265 First interim deficiency rept re design basis flood calculations not considering erosion effects of postulated embankment breach Initially reported on 830830 Next rept expected by 840120
OPREA, G W Houston Lighting & Power Co 83/09/28 COLLINS, J T Region 4, Office of Director 4pp 20723 217 24X
Fiche 50-498,83/09/28,8310130265
- 8310130319 Supplemental final deficiency rept re Westinghouse supplied pressure & level transmitters Transmitters will be provided for applications described in 830804 ltr, per Westinghouse Group B & WCAP-B5B7 generic qualifications
OPREA, G W Houston Lighting & Power Co 83/09/28 COLLINS, J T Region 4, Office of Director 2pp 20719 361 24X
Fiche 50-498,83/09/28,8310130319

DOCKETED ITEMS

8310180290 Seventh interim deficiency rept re nonconformances of welds in Vendor-fabricated Category I structural steel Initially reported on 810108 Review continuing Final rept will be submitted by 831230
OPREA, Q W Houston Lighting & Power Co 83/09/30 COLLINS, J T Region 4, Office of Director 2pp 20006 289 24X Fiche 50-498, 83/09/30, 8310180290

8310210193 Final deficiency rept re computer program verification Initially reported on 810308 Verification program for review & acceptance of Brown & Root computer calculations implemented
OPREA, Q W Houston Lighting & Power Co 83/10/14 COLLINS, J T Region 4, Office of Director 2pp 20056 071 24X Fiche 50-498, 83/10/14, 8310210193

V Operator Examinations

8310140110 Revises 830228 response to Generic Ltr 83-01 "Operator Licensing Exam Site Visit" Applications will be submitted in Feb 1984 for 10 persons scheduled for Sept 1984 instructor certification exam
GOLDBERG, J H Houston Lighting & Power Co 83/09/28 EISENHU, D C Division of Licensing 2pp 20766 108 24X Fiche 50-498, 83/09/28, 8310140110

DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2

A Application/construction stage documents & correspondence

8310070184 Notification of contract execution "Review of Tornado Missile PRA-South Texas Project," awarded to NBS
WIGGINS, E Technical Assistance Contracts Branch FIN B-8657 83/09/29 MATTSO, R J Division of Systems Integration (post 811005) SINGH, B K NRC - No Detailed Affiliation Given 1p 20680 248 24X Fiche 50-498, 83/09/29, 8310070184

--8310070188 Ltr Contract NRC-03-83-114 "Review of Tornado Missile PRA-South Texas Project," awarded to NBS
MORTON, K V Division of Contracts FIN B-8657 83/09/21 SIMIUE, Commerce, Dept of, National Bureau of Standards 7pp 20680 249 24X Fiche 50-498, 83/09/29, 8310070184

G Adjudicatory correspondence

8310110220 Motion for order limiting scope of Citizens Concerned About Nuclear Power participation in Phase II of OL proceeding Request based on intervenor failure to meet obligations Certificate of Svc encl
OUTTERMAN, A H Joint Applicants-South Texas Project OUTTERMAN, A H Lowenstein, Newman, Reis, Axelrad & Toll 83/10/06 Atomic Safety and Licensing Board Panel 17pp 20666 051 24X Fiche 50-498, 83/10/06, 8310110220

8310170556 Notifies of Commissioner Palladino 831102 site visit One representative of each party may accompany Commissioner on visit Parties must make arrangements w/util Svc list encl
REARER, C W Commissioners 83/10/14 DECHHOEFER, C, LAM, J C, HILL, E E Atomic Safety and Licensing Board Panel 2pp 20780 345 24X Fiche 50-498, 83/10/14, 8310170556

8310250545 Forwards response to State of TX interrogatories on Contention 4 & Quadrex & documents in response to Quadrex Interrogatories 7, 11, 18, 20, 30, 31, 36, 42, 43, 46, 47, 49 & 50 Documents re Interrogatories 23, 33 & 34 forthcoming
PERLIS, R G Hearing Branch 3 83/10/18 BERWICK, B F Texas, State of 1p 20901 062 24X Fiche 50-498, 83/10/18, 8310250545

--8310250551 Response to first set of interrogatories & request for production of documents on Quadrex
* Office of the Executive Legal Director 83/10/18 Texas, State of 35pp 20901 063 24X Fiche 50-498, 83/10/18, 8310250545

--8310250558 Response to first set of interrogatories & request for production of documents on Contention 4 re wind speeds
* Office of the Executive Legal Director 83/10/18 Texas, State of 46pp 20901 098 24X Fiche 50-498, 83/10/18, 8310250545

8310260249 Informs of extension for reply to applicant 831006 motion for sanctions Reply date extended to 831031
SINKIN, L Citizens Concerned About Nuclear Power, Inc SINKIN, L Sinkin, L A 83/10/19 DECHHOEFER, C, LAM, J C, HILL, E E Atomic Safety and Licensing Board Panel 1p 20912 123 24X Fiche 50-498, 83/10/19, 8310260249

8310260269 Motion for new contention re instability of soil beneath facility Recently submitted deficiency rept provides sufficient evidence to warrant inquiry Certificate of Svc encl
SINKIN, L Citizens Concerned About Nuclear Power, Inc SINKIN, L Sinkin, L A 83/10/20 Atomic Safety and Licensing Board Panel 17pp 20911 311 24X Fiche 50-498, 83/10/20, 8310260269

H General correspondence

8310130142 Responds to 830617 ltr re constituents concerns re environ impact of const & operation of 400 kV dc power line from Walker to Matagorda County, TX No NRC approval required Texas Public Util Commission to hold hearings on application
DIRCKS, W J Office of the Executive Director for Operations 83/09/20 TOWNE, J Senate 10pp 20777 052 24X Fiche 50-498, 83/09/20, 8310130142

K Utility Final Safety Analysis Report (FSAR) & amends

8310030167 Forwards Amend 33 to FSAR Amend revises responses to NUREG-0737, II K items & NRC questions & updates Sections 2 5 1, 3 1-3, 3 11-12 & 5 2 Affidavit encl.
GOLDBERG, J H Houston Lighting & Power Co 83/09/27. DENTON, H Office of Nuclear Reactor Regulation, Director 5pp 20593 323 24X Fiche 50-498, 83/09/27, 8310030167

--8310030168 Amend 33 to FSAR, revising responses to NUREG-0737, II K items & NRC questions & updating Sections 2 5 1, 3 1-3, 3 11-12 & 5 2
* Houston Lighting & Power Co 83/09/27 377pp 20593 328 24X Fiche 50-498, 83/09/27, 8310030167

G Inspection reports, IE Bulletins & correspondence

8310140030 FOIA request for IE Insp Rept 79-19, associated notice of proposed imposition of civil penalties, notice of violation & order to show cause
HAMLIN, J B Shaw, Pittman, Potts & Trowbridge 83/05/31. Office of Administration 6pp 20794 110 24X Fiche 50-498, 83/05/31, 8310140030

8310130176 Forwards IE Insp Repts 50-498/83-14 & 50-499/83-14 on 830725-29 No noncompliance noted
MADSEN, G L Region 4, Office of Director 83/08/22 OPREA, Q W Houston Lighting & Power Co 2pp 20724 315 24X Fiche 50-498, 83/08/22, 8310130176

--8310130170 IE Insp Repts 50-498/83-14 & 50-499/83-14 on 830725-29 No noncompliance noted Major areas inspected radiographs, weld-related nonconformance repts, control of weld filler mats, Ebasco audits & structural steel matl control
CROSSMAN, W A, HALL, R E Region 4, Office of Director 83/08/17 8pp 20724 317 24X Fiche 50-498, 83/08/22, 8310130176

8310140031 Partial response to FOIA request for documents re IE Insp Rept 79-19 & associated notice of proposed imposition of civil penalties, notice of violation & order to show cause
Forwards App A documents Documents also available in PDR
FELTON, J M Division of Rules and Records, 83/08/23 HAMLIN, J B Shaw, Pittman, Potts & Trowbridge 1p 20794.116 24X Fiche 50-498, 83/08/23, 8310140031

--8308270592 Forwards Region 5 rept of investigation re alleged falsification of QA records by Brown & Root inspector.
W/o encl
WARD, W J Office of Inspection & Enforcement, Office of the Director 80/08/01 FORTUNA, R Office of Inspector & Auditor 1p 20795 186 24X Fiche 50-498, 83/08/23, 8310140031

--8310140032 "South Texas Project - History"
* NRC - No Detailed Affiliation Given 83/05/31 4pp 20794 117 24X Fiche 50-498, 83/08/23, 8310140031.

--8310140037 Notification of 800819 meeting w/util & Brown & Root in B City, TX to clarify util response to 800430 show cause order.
* NRC - No Detailed Affiliation Given 83/10/13 NRC - No Detailed Affiliation Given 4pp 20794 129 24X Fiche 50-498, 83/08/23, 8310140031

--8310140041 Requests formal public hearing, w/full disclosure, re NRC 791110 investigation of South Texas Project
* Affiliation Unknown 80/02/07 NRC - No Detailed Affiliation Given 1p 20794 133 24X Fiche 50-498, 83/08/23, 8310140031.

--8310140044 NRC proposal to fine Texas Utils for alleged noncompliance w/NRC requirements re Brown & Root QA program & violation of piping weld tests
* NRC - No Detailed Affiliation Given 83/10/13 2pp 20794 134 24X Fiche 50-498, 83/08/23, 8310140031

DOCKETED ITEMS

- 8310140047 Enforcement history, South Texas Project, Oct 1976 - Mar 1980
* NRC - No Detailed Affiliation Given 83/10/13 3pp
20794 136 24X Fiche 50-498, 83/08/23, 8310140031
- 8310140050 Discusses notice of violation issued as result of 791110
830207 insps Noncompliance noted GC insp by Brown & Root not
sufficiently independent Marked-up copy
* NRC - No Detailed Affiliation Given 83/05/31 NRC - No
Detailed Affiliation Given 35pp 20794 139 24X
Fiche 50-498, 83/08/23, 8310140031
- 8310140052 Forwards draft investigation rept & proposed enforcement
action for comment Commission briefing on investigation &
enforcement planned for wk of 800414 Draft rept also sent
to pertinent NRC personnel
BHEWMAKER, R E Director's Office, Office of Inspection and
Enforcement 80/04/01 THORNBURG, H D Director's Office, Office
of Inspection and Enforcement 140pp 20794 175 24X
Fiche 50-498, 83/08/23, 8310140031
- 8310140062 Requisition for payment to Continental Airlines for PBX hvy
of pkg to Houston, TX
* NRC - No Detailed Affiliation Given 80/05/01 2pp.
20795 071 24X Fiche 50-498, 83/08/23, 8310140031
- 8310140088 Advises that, due to seriousness of violations by Brown &
Root & util at South Texas Project, full-scale public
hearing in Matagorda County, TX mandatory
VAN HDY, G Affiliation Unknown 80/05/20 STELLQ, V Director's
Office, Office of Inspection and Enforcement 1p 20795 079 24X
Fiche 50-498, 83/08/23, 8310140031
- 8310140095 Submits draft generic ltr for use w/incoming correspondence
as result of 800430 IE enforcement pkg
STELLQ, V, Director's Office, Office of Inspection and Enforcement
83/10/13 Affiliation Unknown 3pp 20795 167 24X
Fiche 50-498, 83/08/23, 8310140031
- 8310040536 Forwards IE Insp Repts 50-498/83-12 & 50-499/83-12 on
830711-21 No noncompliance noted
MADSEN, Q L Region 4, Office of Director. 83/08/29 OPREA, Q W
Houston Lighting & Power Co. 2pp 20623 254 24X
Fiche 50-498, 83/08/29, 8310040536
- 8310040546 IE Insp Repts 50-498/83-12 & 50-499/83-12 on 830711-21 No
noncompliance noted Major areas inspected licensee mgt of QA
activities & QA insp of performance
OBERQ, C R, CROSSMAN, W A Region 4, Office of Director 83/08/12
12pp. 20623 256 24X Fiche 50-498, 83/08/29, 8310040536
- 8310030385 Forwards IE Insp Repts 50-498/83-15 & 50-499/83-15 on
830701-0814 No noncompliance noted
MADSEN, Q L Region 4, Office of Director 83/09/07 OPREA, Q W
Houston Lighting & Power Co. 2pp 20592 143 24X
Fiche 50-498, 83/09/07, 8310030385
- 8310030392 IE Insp Repts 50-498/83-15 & 50-499/83-15 on 830701-0814 No
noncompliance noted Major areas inspected previous insp
findings, storage & maint of equipment, nonconformance repts,
structural concrete & matl control & identification
HILL, W. M., CROSSMAN, W A Region 4, Office of Director 83/09/02
8pp 20592 145 24X Fiche: 50-498, 83/09/07, 8310030385.
- 810130221 Forwards IE Insp Repts 50-498/83-17 & 50-499/83-17 on
830815-17 & notice of violation
MADSEN, Q L Region 4, Office of Director 83/09/07. OPREA, Q W
Houston Lighting & Power Co. 3pp. 20724 096 24X
Fiche 50-498, 83/09/07, 8310130221
- 8310130227 Notice of violation from insp on 830815-17
* Region 4, Office of Director 83/09/07 2pp 20724 098 24X
Fiche: 50-498, 83/09/07, 8310130221.
- 8310130230 IE Insp Repts 50-498/83-17 & 50-499/83-17 on 830815-17
Noncompliance noted failure to maintain identification &
control of Matls
TOMLINSON, D P., CROSSMAN, W A., HALL, R E Region 4, Office of
Director. 83/09/02 5pp 20724 100. 24X Fiche 50-498, 83/09/07,
8310130221.
- 8180412 Forwards IE Insp Repts 50-498/83-16 & 50-499/83-16 on
80906-08 No noncompliance noted
IDSEN, Q L Region 4, Office of Director 83/09/22 OPREA, Q W
Houston Lighting & Power Co. 2pp 20803 165 24X
Fiche: 50-498, 83/09/22, 8310180412
- 810180414 IE Insp Repts 50-498/83-16 & 50-499/83-16 on 830906-08 No
noncompliance noted Major areas inspected const activities,
including licensee actions on 10CFR50 55(a) rept of
breakdown in QA program for procurement cycle
DARDMAN, J R, CROSSMAN, W A. Region 4, Office of Director
83/09/21 4pp. 20803 167. 24X Fiche 50-498, 83/09/22, 8310180412
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder
Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 11pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
Detectors Positioned at Control Room Ventilation Air
Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342
- 8308300345 IE Info Notice 83-63 "Potential Failures of Westinghouse
Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New
York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to
Safety-Related Sys W/o 10CFR50 39 Evaluation " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New
York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass
Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical
Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New
York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect
Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective
Self-Contained Breathing Apparatus Air Cylinders " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New
York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761
- 8 Reportable occurrences, IERs & related correspondence

- 8310040410 Final deficiency rept re auxiliary feedwater sys containment
isolation valves Initially reported on 830822 Sys design
modified to require performance sys function of safety-grade
active valves Also reported per Part 21
OPREA, Q W Houston Lighting & Power Co 83/09/21 COLLINS, J T
Region 4, Office of Director 3pp 20619 035 24X
Fiche 50-498, 83/09/21, 8310040410
- 8310040289 First interim deficiency rept re corrosion on reactor
containment bldg post-tensioning sys tendons Initially
reported on 830826 Evaluation underway to determine if
condition impairs tendon strength Next rept by 840229
OPREA, Q W Houston Lighting & Power Co 83/09/22 COLLINS, J T
Region 4, Office of Director 3pp 20614 213 24X
Fiche 50-498, 83/09/22, 8310040289
- 8310130187 Revised final deficiency rept re essential cooling water
intake structure gantry crane Initially reported on 790516
Crane design revised for severe & extreme environ loadings
to retain structural integrity
OPREA, Q W Houston Lighting & Power Co 83/09/28 COLLINS, J T
Region 4, Office of Director 3pp 20724 327 24X
Fiche 50-498, 83/09/28, 8310130187
- 8310130265 First interim deficiency rept re design basis flood
calculations not considering erosion effects of postulated
embankment breach Initially reported on 830830 Next rept
expected by 840120
OPREA, Q W Houston Lighting & Power Co 83/09/28 COLLINS, J T
Region 4, Office of Director 4pp. 20723 217 24X
Fiche 50-498, 83/09/28, 8310130265
- 8310130319 Supplemental final deficiency rept re Westinghouse supplied
pressure & level transmitters Transmitters will be provided
for applications described in 830804 ltr, per Westinghouse
Group 8 & WCAP-8587 generic qualifications.
OPREA, Q W Houston Lighting & Power Co 83/09/28 COLLINS, J T
Region 4, Office of Director 2pp 2019 361. 24X
Fiche 50-498, 83/09/28, 8310130319

DOCKETED ITEMS

36

8310180290 Seventh interim deficiency rept re nonconformances of welds in vendor-fabricated Category 1 structural steel
Initially reported on 831008 Review continuing Final rept will be submitted by 831230
OPREA, G W Houston Lighting & Power Co 83/09/30 COLLINS, J T
Region 4, Office of Director 2pp 20606 289 24X
Fiche 50-498, 83/09/30, 8310180290

8310210193 Final deficiency rept re computer program verifications
Initially reported on 810508 Verification program for review & acceptance of Brown & Root computer calculations implemented
OPREA, G W Houston Lighting & Power Co 83/10/14 COLLINS, J T
Region 4, Office of Director 2pp 20856 071 24X
Fiche 50-498, 83/10/14, 8310210193

V Operator Examinations

8310140110 Revises 830228 response to Generic Ltr 83-01 "Operator Licensing Exam Site Visit" Applications will be submitted in Feb 1984 for 10 persons scheduled for Sept 1984 instructor certification exam
GOLDBERG, J H Houston Lighting & Power Co 83/09/28 EISENHUT, D G
Division of Licensing 2pp 20766 108 24X Fiche 50-498, 83/09/28, 8310140110

DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

A Application/construction stage documents & correspondence

8310140176 Forwards "Mgt Plan for Extended Const Delay of WNP-3 (Level II)," per GC Sorensen 830712 ltr Util executive board expected to approve budget rather than approve plan details
SORENSEN, G C Washington Public Power Supply System 83/09/15
KNIGHTON, G W Licensing Branch 3 1p 20764 324 24X
Fiche 50-508, 83/09/15, 8310140176

--8310140182 "Mgt Plan for Extended Const Delay of WNP-3 (Level II)"
* Washington Public Power Supply System 83/08/04 37pp
20764 325 24X Fiche 50-508, 83/09/15, 8310140176

8310030339 Responds to 830809 ltr re concerns to prevent further erosion impacts in vicinity of Ranney intake structures & Elizabeth Creek during const delay Dressing & seeding of Ranney Well area near Elizabeth Creek completed
SORENSEN, G C Washington Public Power Supply System 83/09/28
KNIGHTON, G W Licensing Branch 3 2pp 20590 305 24X
Fiche 50-508, 83/09/28, 8310030339

8310040344 Concludes that proposed project will have no effect on known cultural resources included in or eligible for inclusion in Natl Register of Historic Places
WHITLAM, R O Washington, State of 83/09/29 KNIGHTON, G W
Licensing Branch 3 1p 20617 279 24X Fiche 50-508, 83/09/29, 8310040344

8310190152 Forwards Amend 2 & suppl to application for DL clarifying & explicitly stating intent that once issued, DL is to run for 40 yrs commencing w/date of issuance & provides updated info re const & status & membership of Boards of Directors
SORENSEN, G C Washington Public Power Supply System 83/10/11
KNIGHTON, G W Licensing Branch 3 3pp 20820 124 24X
Fiche 50-508, 83/10/11, 8310190152

--8310190154 Amend 2 & suppl to application for DL clarifying & explicitly stating intent that license run for 40 yrs commencing w/date of issuance Updated const status & membership of Boards of Directors also provided
SORENSEN, G C Washington Public Power Supply System 83/10/11
36pp 20820 127 24X Fiche 50-508, 83/10/11, 8310190152

8310310149 Forwards draft "Ecological Monitoring Preoperational/Operational Program" & draft "Rept on Fish Bioassays Toxicity of Copper, Zinc & Chemical Forms to Coho Salmon & Steelhead Trout in Chehalis River, WA"
SORENSEN, G C Washington Public Power Supply System 83/10/21
KNIGHTON, G W Licensing Branch 3 2pp 20950 042 24X
Fiche 50-508, 83/10/21, 8310310149

--8310310151 Draft "Ecological Monitoring Preoperational/Operational Program"
* Washington Public Power Supply System 83/10/21 5pp
20950 044 24X Fiche 50-508, 83/10/21, 8310310149

--8310310154 Draft "Rept on Fish Bioassays Toxicity of Copper, Zinc & Chemical Forms to Coho Salmon & Steelhead Trout in Chehalis River, WA"
DAVIS, W, NORTHSTROM, T E, JEANE, G S. Washington Public Power Supply System 83/09/30 290pp 20750 049 24X
Fiche 50-508, 83/10/21, 8310310149

E NRC Safety Evaluation Report (SER), suppl & correspondence

8310310063 FOIA request for documents re const & operation of C-E plants List of info required submitted
BELL, N Coalition for Safe Power 83/03/31 Office of Administration 1p 20998 173 24X Fiche 50-000, 83/03/31, 8310310063

F Security, medical, emergency & fire protection plans

8310260189 Forwards WPPS-3/5 physical security plan, Rev 2 & WPPS-3/5 safeguards contingency plan, Rev 1 Revs withheld (ref 10CFR73.21)
SORENSEN, G C Washington Public Power Supply System 83/10/17
KNIGHTON, G W Licensing Branch 3 2pp 20912 234 24X
Fiche 50-508, 83/10/17, 8310260189

G Adjudicatory correspondence

8310140066 Brief supporting util 830915 notice of appeal from ASLB 830421 & 0927 memoranda & orders admitting Coalition for Safe Power as party ASLB abused discretion by granting untimely petition Certificate of Svc encl
REYNOLDS, N S Washington Public Power Supply System REYNOLDS, N S Debevoise & Liberman 83/10/12 Atomic Safety and Licensing Appeal Panel 54pp 20766 241 24X Fiche 50-508, 83/10/12, 8310140066

8310140086 Notice of appeal of ASLB 830421 & 0927 memoranda & orders admitting Coalition for Safe Power as intervenor Order of 830421 should be reversed, 830927 order vacated & proceeding dismissed Certificate of Svc encl
REYNOLDS, N S Washington Public Power Supply System REYNOLDS, N S Debevoise & Liberman 83/10/12 3pp 20767 060 24X
Fiche 50-508, 83/10/12, 8310140086

8310180333 Notice of ASLB constitution AB Rosenthal, chairman & GJ Edles & HA Wilber, members
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/14 1p 20802 347 24X Fiche 50-508, 83/10/14, 8310180333

8310280126 Comments on impact of ALAB-743 denying untimely petition to intervene Portions of analysis directly applicable to applicant 831012 appeal of ASLB grant of untimely petition to intervene
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Washington Public Power Supply System 83/10/26 ROSENTHAL, A S, EDLES, G J, WILBER, H A Atomic Safety and Licensing Appeal Panel 5pp 20929 248 24X Fiche 50-508, 83/10/26, 8310280126

8310310175 Addresses impact of ALAB-743 on proceeding in accordance w/obligation to identify & address recent developments in law affecting pending cases
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Washington Public Power Supply System 83/10/26 ROSENTHAL, A S, WILBER, H A, EDLES, G J Atomic Safety and Licensing Appeal Panel 5pp 20959 002 24X Fiche 50-508, 83/10/26, 8310310175

H General correspondence

8310180586 FOIA request for util corporate chart in PBAR
CONSTAS, J Pro-Tech Support Services, Inc 83/08/17 Office of Administration 1p 20825 323 24X Fiche 50-508, 83/08/17, 8310180586

8310180590 Responds to FOIA request for util corporate chart in PBAR
Forwards chart
FELTON, J M Division of Rules and Records 83/09/06 CONSTAS, J
Pro-Tech Support Services, Inc 1p 20825 324 24X
Fiche 50-508, 83/09/06, 8310180590

G Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 83103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 83103), 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

DOCKETED ITEMS

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345

8310170653 Forwards IE Insp Rept 50-508/83-06 on 830516-20 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 83/09/28 KOHLER, A D Washington Public Power Supply System 2pp 20760 181 24X Fiche 50-508,83/09/28,8310170653

--8310170663 IE Insp Rept 50-508/83-06 on 830516-20 No noncompliance noted Major areas inspected design control, followup on design of rigid strut bracket & review of heat treatment procedures & records for ASME III work by 251 contractor
HAIST, D P, DODDS, R T Region 5, Office of Director 83/09/27 5pp 20760 183 24X Fiche 50-508,83/09/28,8310170663

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

V Operator Examinations

8310030142 Requests schedule, by 831028, for requalification training & exams for 1984 in order to coordinate Region V audit of operator requalification programs
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 83/09/26 GODFREY, Q Washington Public Power Supply System 2pp 20590 040 24X Fiche 50-397,83/09/26,8310030142

DOCKET 50-513 WPPSS NUCLEAR PROJECT, UNIT 4

B. Reportable occurrences, LERs & related correspondence

8310270206 Part 21 rept re engine mounted electrical cables Defective cable not installed as 830927 ltr states Parts shipped & installed on Gulf States River Bend Site (Engine Serial 740397/40 DBR 4B) Instruction for cable changeout due in Nov
BOYER, R E Transamerica Delaval, Inc 83/10/20 Director's Office, Office of Inspection and Enforcement 1p 20924 108 24X Fiche 50-000,83/10/20,8310270206

DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

Application/construction stage documents & correspondence

10180417 Requests info re NRC costs for withdrawing CP application, per 830909 ltr. Extension of due date for payment of 830913 invoice requested
WITHERS, B. D. Portland General Electric Co 83/10/11 MILLER, W D. License Fee Management Branch 1p 20803 310 24X Fiche 50-514,83/10/11,8310180417

G Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827-129 24X Fiche 50-000,83/10/11,8308300761

DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8310180417 Requests info re NRC costs for withdrawing CP application, per 830909 ltr. Extension of due date for payment of 830913 invoice requested
WITHERS, B D Portland General Electric Co 83/10/11 MILLER, W D License Fee Management Branch 1p 20803 310 24X Fiche 50-514,83/10/11,8310180417

G Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345

DOCKETED ITEMS

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

DOCKET 50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1

G Adjudicatory correspondence

8310030390 Second request for addl extension until 840115 to answer intervenor motion for summary disposition of Contention 1
Portland General Electric Co expects to decide on plant termination by end of 1983 Certificate of Svc encl
THOMSEN, F T Puget Sound Power & Light Co THOMSEN, F T Perkins, Coie, Stone, Olsen & Williams 83/09/28 Atomic Safety and Licensing Board Panel 7pp 20593 040 24X Fiche 50-522,83/09/28,8310030390

8310140089 Memorandum & order granting until 830928 request for extension until 840115 to file response to intervenor motion for summary disposition of Contention 1
WOLF, J F Atomic Safety and Licensing Board Panel 83/10/12 Puget Sound Power & Light Co 2pp 20767 021 24X Fiche 50-522,83/10/12,8310140089

G Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

DOCKET 50-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 2

G Adjudicatory correspondence

8310030390 Second request for addl extension until 840115 to answer intervenor motion for summary disposition of Contention 1
Portland General Electric Co expects to decide on plant termination by end of 1983 Certificate of Svc encl
THOMSEN, F T Puget Sound Power & Light Co THOMSEN, F T Perkins, Coie, Stone, Olsen & Williams 83/09/28 Atomic Safety and Licensing Board Panel 7pp 20593 040 24X Fiche 50-522,83/09/28,8310030390

8310140089 Memorandum & order granting until 830928 request for extension until 840115 to file response to intervenor motion for summary disposition of Contention 1
WOLF, J F Atomic Safety and Licensing Board Panel 83/10/12 Puget Sound Power & Light Co 2pp 20767 021 24X Fiche 50-522,83/10/12,8310140089

G Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

DOCKETED ITEMS

DOCKET STN-50-52B PALO VERDE NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8310240197 Partial response to L Bernabei 830805 FOIA request for agency records relevant to &/or generated in connection w/ NRC investigations, insps or repts on allegations made by R Gunderson & W Royce Forwards App A documents
FELTON, J M Division of Rules and Records 83/09/08 GARDE, B
Government Accountability Project App 20903 231 24X
Fiche 50-52B, 83/09/08, 8310240197

--8206080487 Comments on 820511 ltr re allegations of improper electrical work inquiry being made
DIRCKS, W J Office of the Executive Director for Operations
82/05/26 WOODS, T G Arizona Public Service Co 1p 20904 12B
24X Fiche 50-52B, 83/09/08, 8310240197

--8310240201 Submits list of plant electrician allegations that author considers readily documented w/o further investigation Some items listed already documented in rough form
ECKHARDT, J H NRC - No Detailed Affiliation Given 82/12/17
SHACKLETON, D NRC - No Detailed Affiliation Given 1p.
20903 335 24X Fiche 50-52B, 83/09/08, 8310240197

--8310240203 Submits results from informal 830323 meeting re unreviewed affidavits from Govt Accountability Project Shackleton analyzed Gunderson Affidavit & will identify any new areas to Region V
NARBUT, P Region 5, Office of Director 83/03/23
STERNBERG, D H, YOUNG, T, FIORELLI, C. NRC - No Detailed Affiliation Given 1p 20903 336 24X Fiche 50-52B, 83/09/08, 8310240197

--8310240219 Forwards M Young & L Bernabei FOIA request for documents re allegations of R Gunderson & senior Bechtel manager FOIA time record form should be completed & returned
GRIMSLEY, D H NRC - No Detailed Affiliation Given 83/03/31.
WILSON, V Office of Nuclear Reactor Regulation, Director
SWEENEY, M Office of the General Counsel 2pp 20904 049 24X
Fiche 50-52B, 83/09/08, 8310240197

--8310240220 Requests that documents be provided in attached FOIA Request 83-450 Documents required to be delivered to I Alexander by 830817 Forwards FOIA Request 83-450 & list of documents on sub. Documents need not be duplicated
NARBUT, P Region 5, Office of Director 83/08/16 MARTIN, J.,
STERNBERG, D, YOUNG, T NRC - No Detailed Affiliation Given 4pp
20904 051 24X Fiche 50-52B, 83/09/08, 8310240197

--8310240236 Notifies that author had no involvement in investigation into allegations at facility, per NARBUT 830816 memo No relevant documents re FOIA Request 83-450 in author possession
JOHNSON, P NRC - No Detailed Affiliation Given 83/08/18
ALEXANDER, I, NRC - No Detailed Affiliation Given 1p 20904 111
24X Fiche 50-52B, 83/09/08, 8310240197

8310050247 Notification of 831012 meeting w/util & C-E in Bethesda, MD to discuss updated status re reactor internals, evaluation of reactor coolant pumps, thermal sleeves & thermowells
LICITRA, E A Licensing Branch 3 83/09/19 KNIGHTON, G W
Licensing Branch 3 3pp 20680 051 24X Fiche 50-52B, 83/09/19, 8310050347

8310050010 Submits updated status on RCB pumps, thermal sleeves & C-E shroud assemblies per 830913 & 14 telcons Design of pumps will be modified Followup status meeting scheduled for 831012
LICITRA, E A Licensing Branch 3 83/09/28 NOVAK, T M Assistant Director for Licensing 3pp 20650 855 24X Fiche 50-52B, 83/09/28, 8310050010

8310130126 Forwards Rev 3 to "Salt Deposition & Impact Monitoring Plan"
VAN BRUNT, E E Arizona Public Service Co 83/09/29 KNIGHTON, G
Licensing Branch 3 2pp 20726 325 24X Fiche: 50-52B, 83/09/29, 8310130126

--8310130129 Rev 3 to "Salt Deposition & Impact Monitoring Plan"
* NUS Corp 83/07/31 18pp 20726, 327, 24X
Fiche 50-52B, 83/09/29, 8310130126

8310260156 Forwards Rev 1 to Suppl 3 of "Probabilistic Risk Assessment of Effects of PORVs on Depressurization & DHR" Changes are result of detailed treatment of automatic PORV cases & complete analysis of auxiliary feedwater restoration
VAN BRUNT, E E Arizona Public Service Co 83/10/13 KNIGHTON, G
Licensing Branch 3 3pp 20914 178 24X Fiche: 50-52B, 83/10/13, 8310260156

--8310260160 Rev 1 to Suppl 3 of "Probabilistic Risk Assessment of Effects of PORVs on Depressurization & DHR"
* Combustion Engineering, Inc CEN-239 S03 R01 83/09/30
373pp 20914 181 24X Fiche 50-52B, 83/10/13, 8310260156

8310210252 Forwards revised responses to NRC 830727 request for addl info re util proposed rev to FSAR Section 1 B concerning exceptions to Reg Guide 1.89 to permit use of records storage facility w/level concrete floor & roof
VAN BRUNT, E E Arizona Public Service Co 83/10/17 KNIGHTON, G
Licensing Branch 3 6pp 20851 263 24X Fiche 50-52B, 83/10/17, 8310210252

8310250146 Forwards documents re recent reactor coolant pump problems per FOIA Request 83-448 Documents contain no proprietary info
VAN BRUNT, E E Arizona Public Service Co 83/10/19 BISHOP, T W
Division of Resident/Reactor Project & Engineering Programs 11pp
20896 329 24X Fiche 50-52B, 83/10/19, 8310250146

8310310372 Informs that info requested in 830920 ltr re impact of high energy line breaks on control sys & exceptions taken in FSAR Section 3.8.1 & 6.1 will be submitted by 831117
VAN BRUNT, E E Arizona Public Service Co 83/10/21 KNIGHTON, G
Licensing Branch 3 1p 20960 001 24X Fiche 50-52B, 83/10/21, 8310310372

E NRC Safety Evaluation Report (SER), suppls & correspondence

8310030425 Forwards proprietary "Final Assessment of Palo Verde Nuclear Generation Station Fuel Assembly Spacer Grid Impact Loads Under Faulted Conditions," per SER (NUREG-0857) Section 4.2.1 Affidavit encl Rept withheld (ref 10LFR2 790)
VAN BRUNT, E E Arizona Public Service Co 83/09/26 KNIGHTON, G
Licensing Branch 3 7pp 20602 219 24X Fiche 50-52B, 83/09/26, 8310030425

F Security, medical, emergency & fire protection plans

8310040375 Forwards revised response to outstanding fire protection Open Items 2, 4, 8, 10, 16, 21 & 23 identified at 830803 meeting in Bethesda, MD Revised response to Items 1, 3, 5 & 25 will be provided by 831130
VAN BRUNT, E E Arizona Public Service Co 83/09/29 KNIGHTON, G
Licensing Branch 3 34pp 20620 288 24X Fiche 50-52B, 83/09/29, 8310040375

G Adjudicatory correspondence

8310240197 Partial response to L Bernabei 830805 FOIA request for agency records relevant to &/or generated in connection w/ NRC investigations, insps or repts on allegations made by R Gunderson & W Royce Forwards App A documents
FELTON, J M Division of Rules and Records 83/09/08 GARDE, B
Government Accountability Project App 20903 231 24X
Fiche 50-52B, 83/09/08, 8310240197

--8310240212 Forwards Dept of Labor 830324 Recommended Decision & Order of Administrative Law Judge in W Royce vs Bechtel Corp case
BUTLER, G D Bechtel Corp 83/03/30 Bechtel Corp 12pp
20904 001 24X Fiche 50-52B, 83/09/08, 8310240197

G Inspection reports, IE Bulletins & correspondence

8310240196 FOIA request for agency records relevant to &/or generated in connection w/NRC investigations, insp or repts on allegations made by R Gunderson & W Royce re facilities
BERNABEI, L Government Accountability Project 83/08/05 Office of Administration, 2pp 20903 249 24X Fiche 50-52B, 83/08/05, 8310240196

8310240197 Partial response to L Bernabei 830805 FOIA request for agency records relevant to &/or generated in connection w/ NRC investigations, insps or repts on allegations made by R Gunderson & W Royce Forwards App A documents
FELTON, J M Division of Rules and Records 83/09/08 GARDE, B
Government Accountability Project App 20903 231 24X
Fiche 50-52B, 83/09/08, 8310240197

--8310240199 Requests assistance in disclosing worker allegations re problems at facility Various allegations by workers re const, QA & QC problems existing at plant discussed
MORRISON, J R Palo Verde Intervention Fund 82/12/07 GARDE, B
Government Accountability Project 3pp 20903 332 24X
Fiche 50-52B, 83/09/08, 8310240197

DOCKETED ITEMS

369

- 8310240215 Requests review of NRC serious mishandling of investigation of worker allegations re deficiencies in electrical work & startup testing program at facilities on behalf of R Gunderson & W Royce Related matl encl
BERNABEI, L. Government Accountability Project 83/07/14
PALLADINO, N. GILINSKY, V. AHCARNE, J. Commissioners 17pp
20904 013 24X Fiche 50-528, 83/09/08, 8310240197
- 8310240218 Submits list of documents in Region V files which apply to Young & Bernabei FOIA-83-161 request for documents re allegations of electrical problems Related matl encl
ALEXANDER, I. Region 5, Office of Director 83/03/06 TOMS, V
NRC - No Detailed Affiliation Given 5pp 20904 045 24X
Fiche 50-528, 83/09/08, 8310240197
- 8310240221 Forwards L Bernabei FOIA request for documents in connection w/NRC investigations, insp repts or repts on allegations made by R Gunderson & W Royce re facilities List of questions for response to NL Toms requested by BJOHNS
GRIMSLEY, D H. NRC - No Detailed Affiliation Given 83/08/07
BROWN, W. Office of the Secretary of the Commission SWEENEY, M
Office of the General Counsel 2pp 20904 055 24X
Fiche 50-528, 83/09/08, 8310240197
- 8310240222 Notifies that special, unannounced insp scheduled at facility on 830404-08 Team consisting of author, A Johnson, J Burdoin, G Fiorelli & L Vorderbruggen will examine facts surrounding as many allegations as possible during insp
YOUNG, T. Region 5, Office of Director 83/03/31 STERNBERG, D
NRC - No Detailed Affiliation Given 1p 20904 059 24X
Fiche 50-528, 83/09/08, 8310240197
- 8310240223 Discusses NRC insp entrance interview conducted on 83061b, to describe NRC planned insp activities Lists NRC inspectors & areas of investigation NRC will be primarily investigating allegations during visit Related matl encl
IDE, W C. Arizona Public Service Co 82/06/15 ROEDEL, J A
Arizona Public Service Co 4pp 20904 102 24X
Fiche 50-528, 83/09/08, 8310240197
- 8310240227 Discusses status of special insp re allegations, in response to 830411 memo Lists items not addressed Efforts will be concluded & pertinent repts issued on listed items prior to 830601 Relevant documents issued & received encl
MARTIN, J D. Region 5, Office of Director 83/05/02
CUNNINGHAM, G H. Office of the Executive Legal Director 2pp
20904 106 24X Fiche 50-528, 83/09/08, 8310240197
- 8310240239 Forwards documents re FOIA request for NRC investigation, insps or repts on allegations made by R Gunderson & W Royce concerning facilities Excerpt of installation spec for cable splicing encl
ALEXANDER, I. Region 5, Office of Director 83/08/19 TOMS, N
NRC - No Detailed Affiliation Given 9pp 20904 112 24X
Fiche 50-528, 83/09/08, 8310240197
- 8310240251 Discusses immediate effectiveness review of facilities re analysis of pending insp/investigation items identified in O/C of Insp & LDO repts of 830325 & 27 Presumes BECY will extend review time to accommodate Commission consideration
ASSELSTINE, J K. Commissioners 83/04/01 PALLADINO
Commissioners 1p 20904 131 24X Fiche 50-528, 83/09/08, 8310240197
- 8310040532 Forwards IE Insp Rept 50-528/83-38 on 830801-31 No noncompliance noted
BISHOP, T W. Division of Resident, Reactor Project & Engineering Programs 83/09/19 ANDOGNINI, G O. Arizona Public Service Co 2pp 20624 010 24X Fiche 50-528, 83/09/19, 8310040532
- 8310040537 IE Insp Rept 50-528/83-38 on 830801-31 No noncompliance noted Major areas inspected equipment qualification, startup testing, TMI Followup items, NSSS problems & plant mod
FIORILLI, G. JOHNSTON, G. YOUNG, T. Region 5, Office of Director 83/09/15 7pp 20624 012 24X Fiche 50-528, 83/09/19, 8310040532
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp. 20777 210 24X Fiche 50-000, 83/09/26, 8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345
- 8310170468 Forwards IE Insp Rept 50-528/83-26 on 830705-08 & 19-22 No noncompliance noted
BISHOP, T W. Division of Resident, Reactor Project & Engineering Programs 83/09/28 ANDOGNINI, G O. Arizona Public Service Co 2pp 20783 252 24X Fiche 50-528, 83/09/28, 8310170468
- 8310170470 IE Insp Rept 50-528/83-26 on 830705-08 & 19-22 No noncompliance noted Major areas inspected plant procedures, surveillance testing & independent insp effort
JOHNSON, P H. YOUNG, T. Region 5, Office of Director 83/09/26 4pp 20783 254 24X Fiche 50-528, 83/09/28, 8310170468
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761
- 8310310396 Forwards IE Insp Rept 50-528/82-35 on 821216-23 No noncompliance noted
BISHOP, T W. Division of Resident, Reactor Project & Engineering Programs 83/10/13 ANDOGNINI, G O. Arizona Public Service Co 2pp 20959 355 24X Fiche 50-528, 83/10/13, 8310310396
- 8310310398 IE Insp Rept 50-528/82-35 on 821216-23 No noncompliance noted Major areas inspected preoperational containment leak rate test, procedure review, interviews w/personnel & witnessing portions of structural integrity test
D'ANGELO, A J. YOUNG, T. Region 5, Office of Director 83/10/13 5pp 20959 357 24X Fiche 50-528, 83/10/13, 8310310396
- S Reportable occurrences, LERs & related correspondence
- 8310070286 Final Deficiency Rept DER 82-68 re underground cables to startup transformers which may not carry full load current at max site soil temp Initially reported on 821126 Condition not reportable per 10CFR50 55(e)
VAN BRUNT, E E. Arizona Public Service Co 83/09/16 STERNBERG, D H. Region 5, Office of Director 5pp 20657 028 24X
Fiche 50-528, 83/09/16, 8310070286
- 8310070289 "Soil Thermal Property Measurements for Palo Verde Nuclear Plant "
MARTIN, M A. M&E Technology, Inc. 83/02/09 32pp 20657 033
24X Fiche 50-528, 83/09/16, 8310070286
- 8310070006 Final Deficiency Rept DER 83-41 re flooding in control bldg train Room B Pipe penetrations between circulating water intake canal & pump pit will be sealed to limit leakage rate into pump pit to within pit drainage sys capacity
VAN BRUNT, E E. Arizona Public Service Co 83/09/21 STERNBERG, D H. Region 5, Office of Director 5pp 20657 084 24X
Fiche 50-528, 83/09/21, 8310070006
- 8310070147 Final Deficiency Rept DER 83-25 re instrumentation tubing w/o required boundary class break Initially reported on 830421 Deficiency determined not reportable under 10CFR50 55(e)
VAN BRUNT, E E. Arizona Public Service Co 83/09/21 STERNBERG, D H. Region 5, Office of Director 13pp 20659 068 24X
Fiche 50-528, 83/09/21, 8310070147

DOCKETED ITEMS

8310070352 Interim Deficiency Rept DER 83-42 re thermowells in RCS Initially reported on 830729 Final rept extension requested due to extensive investigation & evaluation Final rept will be submitted by 831201
VAN BRUNT, E E Arizona Public Service Co 83/09/21 STERNBERG, D M
Region 5, Office of Director 2pp 20651 095 24X
Fiche 50-528, 83/09/21, 8310070352

8310140269 Final Deficiency Rept DER 83-15 re Marathon Steel A354 anchor bolt breaking under installation torque after test acceptance Initially reported on 830318 Analysis concluded bolt torsional failure caused by ductile shear overload
VAN BRUNT, E E Arizona Public Service Co 83/09/23 STERNBERG, D M
Region 5, Office of Director 5pp 20761 270 24X
Fiche 50-528, 83/09/23, 8310140269

--8310140274 "Failure Analysis of ASTM A-354 Bolt "
GONZALES, J C , SCHMIDT, O R , HACKNEY, D D Bechtel Corp 0383-03
FA 83/03/31 20pp 20761 275 24X Fiche 50-529, 83/09/23,
8310140269

8310140259 Final Deficiency Rept DER 83-45 re cable separations in control room panels Initially reported on 830707 Procedures revised to ref Const Spec 13-EM-306 for separation criteria requirements Also reportable per Part 21
VAN BRUNT, E E Arizona Public Service Co 83/09/26 STERNBERG, D M
Region 5, Office of Director 15pp 20762 069 24X
Fiche 50-528, 83/09/26, 8310140259

8310140012 Final Deficiency Rept DER 83-14 re failure of Westinghouse diesel generator protective relays due to leaking capacitors Initially reported on 830316 Relays will be returned to supplier Capacitors will be replaced
VAN BRUNT, E E Arizona Public Service Co 83/09/27 STERNBERG, D M
Region 5, Office of Director 3pp 20767 006 24X
Fiche 50-528, 83/09/27, 8310140012

8310270430 Final Deficiency Rept DER 83-43 re improper crimp terminations in 12 cabinets furnished by Harlo Corp Initially reported on 830708 Harlo cabinets for all units will be inspected & reworked Also reportable per Part 21
VAN BRUNT, E E Arizona Public Service Co 83/09/27 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 6pp
20923 085 24X Fiche 50-528, 83/09/27, 8310270430

8310140238 Interim Deficiency Rept DER 83-46 re Borg Warner valve manually overtorqued during hydrostatic testing Initially reported on 830715 Time extension until 831214 requested for final rept, due to extensive investigation required
VAN BRUNT, E E Arizona Public Service Co 83/09/28 STERNBERG, D M
Region 5, Office of Director 2pp 20761 321 24X
Fiche 50-528, 83/09/28, 8310140238

8310250099 Interim Deficiency Rept DER 83-40 re low pressure safety injection & CB pump motors leaking oil & w/defective welds Initially reported on 830729 Due to extensive investigation, rept will not be submitted until 831206
VAN BRUNT, E E Arizona Public Service Co 83/10/05 BISHOP, T W
Region 5, Office of Director 2pp 20895 277 24X
Fiche 50-528, 83/10/05, 8310250099

8310250415 Interim Deficiency Repts DER 82-57, DER 82-64 & DER 83-32 re conditions & circumstances surrounding design processes involved w/dissimilar metal socket welds
VAN BRUNT, E E Arizona Public Service Co 83/10/06 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 2pp
20897 245 24X Fiche 50-528, 83/10/06, 8310250415

8310250568 Final Deficiency Rept DER 83-38 re Steiler Steel clip angles used for HVAC supports that do not meet ASTM A-36 requirements Initially reported on 830628 Deficiency determined not reportable per 10CFR90.55(c)
VAN BRUNT, E E Arizona Public Service Co 83/10/06 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 9pp
20901 324 24X Fiche 50-528, 83/10/06, 8310250568

8310250079 Interim Deficiency Rept 83-10 re main steam relief valve tests exceeding specified 5% blowdown limit. Initially reported 830228 Due to extensive investigation & evaluation required, rept will not be submitted until 831118.
VAN BRUNT, E E Arizona Public Service Co 83/10/07 BISHOP, T W
Region 5, Office of Director 2pp 20894 139 24X
Fiche 50-528, 83/10/07, 8310250079.

8310310138 Interim Deficiency Rept DER 83-54 re washers in steam generators 1 & 2 Initially reported on 830802 Due to extensive evaluation required, next rept will be submitted by 831215
VAN BRUNT, E E Arizona Public Service Co 83/10/13 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 2pp
20959 035 24X Fiche 50-528, 83/10/13, 8310310138

8310310316 Interim Deficiency Rept DER 83-61 re low pressure safety injection pumps failing to start & to produce required head Initially reported on 830914 Due to extensive investigation & evaluation, final rept will be submitted by 840126
VAN BRUNT, E E Arizona Public Service Co 83/10/13 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 3pp
20961 164 24X Fiche 50-528, 83/10/13, 8310310316

U Congressional/Executive Correspondence

8310240197 Partial response to L Bernabei 830805 FOIA request for agency records relevant to &/or generated in connection w/ NRC investigations, insps or repts on allegations made by R Gunderson & W Royce Forwards App A documents
FELTON, J M Division of Rules and Records 83/09/08 GARDI, D
Government Accountability Project 4pp 20903 251 24X
Fiche 50-528, 83/09/08, 8310240197

--8310240217 Requests response to issues raised by J Morrison 830703 ltr expressing concerns w/manner in which Regional V & Ofc of Investigation handled allegations of violations at plant
J Morrison 830703 ltr encl
UDALL, H K House of Rep , Interior & Insular Affairs 83/09/17
PALLADINO, N Commissioners 4pp 20904 040 24X
Fiche 50-528, 83/09/08, 8310240197

--8310240241 Notices of receipt of T Woods 820511 ltr to NRC re allegations about safety at facilities Requests to be addressed of any action taken by NRC in subj matter
RUDD, E House of Rep 82/05/17 PALLADINO, N J Commissioners
1p 20904 129 24X Fiche 50-528, 83/09/08, 8310240197

--8310240246 Ack receipt of 820519 ltr to Chairman Palladino expressing concern re allegations of improper electrical work at facilities Region V initiated independent inquiry into matter w/legal assistance
KAMMERER, C Office of Congressional Affairs 82/06/01 RUDD, E
House of Rep 1p 20904 130 24X Fiche 50-528, 83/09/08,
8310240197

V Operator Examinations

8310030154 Requests schedule, by 830928, for requalification training & exams for 1984 in order to coordinate Region V audit of operator requalification programs
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 83/09/26 ANDONINI, G C Arizona Public Service Co
2pp 20590 030 24X Fiche 50-528, 83/09/26, 8310030154

DOCKET 83N-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8206080487 Comments on 820511 ltr re allegations of improper electrical work Inquiry being made
DIRCKS, W J Office of the Executive Director for Operations
82/05/26 WOODS, T G Arizona Public Service Co 1p 20904 120
24X Fiche 50-528, 83/09/08, 8310240197

--8310240201 Submits list of plant electrician allegations that author considers readily documented w/o further investigation Some items listed already documented in rough form
ECKHARDT, J H NRC - No Detailed Affiliation Given 82/12/17
SHACKLETON, O NRC - No Detailed Affiliation Given 1p
20903 335 24X Fiche 50-528, 83/09/08, 8310240197

--8310240203 Submits results from informal 830323 meeting re unreviewed affidavits from Govt Accountability Project Shackleton analyzed Gunderson affidavit & will identify any new areas to Region V
NARBUT, P P Region 5, Office of Director 83/03/23
STERNBERG, D M , YOUNG, T , FIORELLI, G NRC - No Detailed Affiliation Given 1p 20903 336 24X Fiche 50-528, 83/09/08,
8310240197

--8310240217 Forwards M Young & L Bernabei FOIA request for documents re allegations of R Gunderson & senior Bechtel manager FOIA time record form should be completed & returned
ORINSLEY, D H NRC - No Detailed Affiliation Given 83/03/31
WILSON, V Office of Nuclear Reactor Regulation, Director
SWEENEY, M Office of the General Counsel 2pp 20904 047 24X
Fiche 50-528, 83/09/08, 8310240197

--8310240220 Requests that documents be provided in attached FOIA Request 83-450 Documents required to be delivered to I Alexander by 830817, Forwards FOIA Request 83-450 & list of documents on subj Documents need not be duplicated
NARBUT, P Region 5, Office of Director 83/08/16 MARTIN, J,
STERNBERG, D , YOUNG, T NRC - No Detailed Affiliation Given 4pp
20904 051 24X Fiche 50-528, 83/09/08, 8310240197

DOCKETED ITEMS

--B310240236 Notifies that author had no involvement in investigation into allegations at facility, per Narbut B30816 memo No relevant documents re FOIA Request B3-450 in author possession
JOHNSON, P NRC - No Detailed Affiliation Given B3/08/18
ALEXANDER, I NRC - No Detailed Affiliation Given 1p 20704 111
24X Fiche 50-528, B3/09/08, B310240197

B310050347 Notification of B31012 meeting w/uttl & C-E in Bethesda, MD to discuss updated status re reactor internals, evaluation of reactor coolant pumps, thermal sleeves & thermowells
LICITRA, E A Licensing Branch 3 B3/09/19 KNIGHTON, G W
Licensing Branch 3 3pp 20670 051 24X Fiche 50-528, B3/09/19, B310050347

B310050010 Submits updated status on RCS pumps, thermal sleeves & C-E shroud assemblies per B30913 & 14 telcons Design of pumps will be modified followup status meeting scheduled for B31012
LICITRA, E A Licensing Branch 3 B3/09/28 NOVAK, T M Assistant Director for Licensing 3pp 20650 255 24X Fiche 50-528, B3/09/28, B310050010

B310130126 Forwards Rev 3 to "Salt Deposition & Impact Monitoring Plan"
VAN BRUNT, E E Arizona Public Service Co B3/09/29 KNIGHTON, G
Licensing Branch 3 2pp 20726 325 24X Fiche 50-528, B3/09/29, B310130126

--B310130129 Rev 3 to "Salt Deposition & Impact Monitoring Plan"
* NUS Corp B3/07/31 10pp 20726 327 24X
Fiche 50-528, B3/09/29, B310130126

B310260156 Forwards Rev 1 to Suppl 3 of "Probabilistic Risk Assessment of Effects of PORVs on Depressurization & DHR" Changes are result of detailed treatment of automatic PORV cases & complete analysis of auxiliary feedwater restoration
VAN BRUNT, E E Arizona Public Service Co B3/10/13 KNIGHTON, G
Licensing Branch 3 3pp 20914 178 24X Fiche 50-528, B3/10/13, B310260156

--B310260160 Rev 1 to Suppl 3 of "Probabilistic Risk Assessment of Effects of PORVs on Depressurization & DHR"
* Combustion Engineering, Inc CEN-239 803 R01 B3/09/30
373pp 20914 181 24X Fiche 50-528, B3/10/13, B310260156

B310210252 Forwards revised responses to NRC B30727 request for addl info re util proposed rev to FSAR Section 1 B concerning exceptions to Reg Guide 1.8B to permit use of records storage facility w/level concrete floor & roof
VAN BRUNT, E E Arizona Public Service Co B3/10/17 KNIGHTON, G
Licensing Branch 3 6pp 20851 263 24X Fiche 50-528, B3/10/17, B310210252

B310310372 Informs that info requested in B30920 ltr re impact of high energy line breaks on control sys & exceptions taken in FSAR Section 3.8.1.6 & 1 will be submitted by B31117
VAN BRUNT, E E Arizona Public Service Co B3/10/21 KNIGHTON, G
Licensing Branch 3 1p 20960 001 24X Fiche 50-528, B3/10/21, B310310372

E NRC Safety Evaluation Report (SER), supp's & correspondence

B310030425 Forwards proprietary "Final Assessment of Palo Verde Nuclear Generation Station Fuel Assembly Spacer Grid Impact Loads Under Faulted Conditions," per SER (NUREG-0897) Section 4.2.1 Affidavit encl Rept withheld (ref 10CFR2.790)
VAN BRUNT, E E Arizona Public Service Co B3/09/26 KNIGHTON, G
Licensing Branch 3 7pp 20602 219 24X Fiche 50-528, B3/09/26, B310030425

F Security, medical, emergency & fire protection plans

B310040375 Forwards revised response to outstanding fire protection Open Items 2, 4, 8, 10, 16, 21 & 23 identified at B30803 meeting in Bethesda, MD Revised response to Items 1, 3, 5 & 25 will be provided by B31130
VAN BRUNT, E E Arizona Public Service Co B3/09/29 KNIGHTON, G
Licensing Branch 3 34pp 20620 288 24X Fiche 50-528, B3/09/29, B310040375

G Adjudicatory correspondence

B310240197 Partial response to L Bernabei B30805 FOIA request for agency records relevant to &/or generated in connection w/ NRC investigations, insps or repts on allegations made by R Gunderson & W Royce Forwards App A documents
FELTON, J M Division of Rules and Records B3/09/08 GARDE, B
Government Accountability Project App 20903 251 24X
Fiche 50-528, B3/09/08, B310240197

--B310240212 Forwards Dept of Labor B30324 Recommended Decision & Order of Administrative Law Judge in W Royce vs Bechtel Corp case
BUTLER, S D Bechtel Corp B3/03/30 Bechtel Corp 12pp
20904 001 24X Fiche 50-528, B3/09/08, B310240197

B310250264 Forwards several insp repts re investigations of allegations by former const workers
DEWEY, L S NRC - No Detailed Affiliation Given B3/10/21
LAZO, R M, COLE, R F, CALLIHAN, D Atomic Safety and Licensing Board Panel 5pp 20899 088 24X Fiche 50-529, B3/10/21, B310250264

B310270234 Order extending time until B3110B for Commission to act to review ALAB-742
CHILK, S J Office of the Secretary of the Commission B3/10/26
Commissioners 1p 20924 070 24X Fiche 50-529, B3/10/26, B310270234

G Inspection reports, IE Bulletins & correspondence

B310240196 FOIA request for agency records relevant to &/or generated in connection w/NRC investigations, insp or repts on allegations made by R Gunderson & W Royce re facilities
BERNABEI, L Government Accountability Project B3/08/05 Office of Administration 2pp 20903 249 24X Fiche 50-528, B3/08/05, B310240196

B310240197 Partial response to L Bernabei B30805 FOIA request for agency records relevant to &/or generated in connection w/ NRC investigations, insps or repts on allegations made by R Gunderson & W Royce Forwards App A documents
FELTON, J M Division of Rules and Records B3/09/08 GARDE, B
Government Accountability Project App 20903 251 24X
Fiche 50-528, B3/09/08, B310240197

--B310240199 Requests assistance in disclosing worker allegations re problems at facility Various allegations by workers re const, QA & QC problems existing at plant discussed
MORRISON, J R Palo Verde Intervention Fund B2/12/07 GARDE, B
Government Accountability Project 3pp 20903 332 24X
Fiche 50-528, B3/09/08, B310240197

--B310240215 Requests review of NRC serious mishandling of investigation of worker allegations re deficiencies in electrical work & startup testing program at facilities, on behalf of R Gunderson & W Royce Related matl encl
BERNABEI, L Government Accountability Project B3/07/14
PALLADINO, N, OILINSKY, V, AHEARNE, J Commissioners 17pp
20904 013 24X Fiche 50-528, B3/09/08, B310240197

--B310240218 Submits list of documents in Region V files which apply to Young & Bernabei FOIA-B3-161 request for documents re allegations of electrical problems Related matl encl
ALEXANDER, I Region 5, Office of the Director B3/05/06 TOMS, V
NRC - No Detailed Affiliation Given 5pp 20904 045 24X
Fiche 50-528, B3/09/08, B310240197

--B310240221 Forwards L Bernabei FOIA request for documents in connection w/NRC investigations, insp repts or repts on allegations made by R Gunderson & W Royce re facilities List of questions for response to ML Toms requested by B30816
GRIMSLEY, D H NRC - No Detailed Affiliation Given B3/08/09
BROWN, N Office of the Secretary of the Commission SWEENEY, M
Office of the General Counsel 2pp 20904 055 24X
Fiche 50-528, B3/09/08, B310240197

--B310240222 Notifies that special, unannounced insp scheduled at facility on B30404-08 Team consisting of author, A Johnson, J Burdoin, Q Fiorelli & L Vanderbruggen will examine facts surrounding as many allegations as possible during insp
YOUNG, T Region 5, Office of the Director B3/03/31 STERNBERG, D
NRC - No Detailed Affiliation Given 1p 20904 059 24X
Fiche 50-528, B3/09/08, B310240197

--B310240223 Discusses NRC insp entrance interview conducted on B30 describe NRC planned insp activities Lists NRC inspectors & areas of investigation NRC will be primarily investigating allegations during visit Related matl encl
IDE, W E Arizona Public Service Co B2/06/15, ROEDEL, J A
Arizona Public Service Co App 20904 102 24X
Fiche 50-528, B3/09/08, B310240197

--B310240227 Discusses status of special insp re allegations, in response to B30411 memo Lists items not addressed Efforts will be concluded & pertinent repts issued on listed items prior to B30401 Relevant documents issued & received encl
MARTIN, J B Region 5, Office of the Director B3/05/02
CUNNINGHAM, Q H Office of the Executive Legal Director 2pp
20904 106 24X Fiche 50-528, B3/09/08, B310240197

DOCKETED ITEMS

--8310240239 Forwards documents re FOIA request for NRC investigation. insps or repts on allegations made by R Gunderson & W Royce concerning facilities Excerpt of installation spec for cable splicing encl
ALEXANDER, I Region 5, Office of Director 83/08/19 TOMS, W
NRC - No Detailed Affiliation Given 7pp 20904 112 24X
Fiche 50-528, 83/09/08, 8310240197

--8310240251 Discusses immediate effectiveness review of facilities re analysis of pending insp/investigation items identified in Ofc of Insp & EDO repts of 830325 & 29 Presumes SECY will extend review time to accommodate Commission consideration
ASSELSTINE, J K Commissioners 83/04/01 PALLADIO
Commissioners 1p 20904 131 24X Fiche 50-528, 83/09/08, 8310240197

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins For Wilder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 EUTPSNH Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310250264 Forwards several insp repts re investigations of allegations by former const workers
DENEY, L S NRC - No Detailed Affiliation Given 83/10/21
LAZOR, R M, COLE, R F, CALLIHAN, D Atomic Safety and Licensing Board Panel 5pp 20899 088 24X Fiche 50-529, 83/10/21, 8310250264

S Reportable occurrences, LERs & related correspondence

8310070286 Final Deficiency Rept DER 82-68 re underground cables to startup transformers which may not carry full load current at max site soil temp Initially reported on 821126 Condition not reportable per 10CFR50 55(e)
VAN BRUNT, E E Arizona Public Service Co 83/09/16 STERNBERG, D H
Region 5, Office of Director 5pp 20657 028 24X
Fiche 50-528, 83/09/16, 8310070286

--8310070289 "Soil Thermal Property Measurements for Palo Verde Nuclear Plant"
MARTIN, M A M&E Technology, Inc 83/02/09 32pp 20657 033
24X Fiche 50-528, 83/09/16, 8310070286

8310070339 Final Deficiency Rept DER 83-34 re instrument racks in containment w/surface cracks on various welds to embed plates Initially reported on 830927 Item not reportable under 10CFR50 55(e)
VAN BRUNT, E E Arizona Public Service Co 83/09/19 STERNBERG, D H
Region 5, Office of Director 4pp 20651 060 24X
Fiche 50-529, 83/09/19, 8310070339

8310070147 Final Deficiency Rept DER 83-25 re instrumentation tubing w/o required boundary class break Initially reported on 830421 Deficiency determined not reportable under 10CFR50 55(e)
VAN BRUNT, E E Arizona Public Service Co 83/09/21 STERNBERG, D H
Region 5, Office of Director 13pp 20659 068 24X
Fiche 50-528, 83/09/21, 8310070147

8310070352 Interim Deficiency Rept DER 83-42 re thermowells in RCS Initially reported on 830729 Final rept extension requested due to extensive investigation & evaluation Final rept will be submitted by 831201
VAN BRUNT, E E Arizona Public Service Co 83/09/21 STERNBERG, D H
Region 5, Office of Director 2pp 20651 095 24X
Fiche 50-528, 83/09/21, 8310070352

8310140269 Final Deficiency Rept DER 83-15 re Marathon Steel A354 anchor bolt breaking under installation torque after test acceptance Initially reported on 830318 Analysis concluded bolt torsional failure caused by ductile shear overload
VAN BRUNT, E E Arizona Public Service Co 83/09/23 STERNBERG, D H
Region 5, Office of Director 5pp 20761 270 24X
Fiche 50-529, 83/09/23, 8310140269

--8310140274 "Failure Analysis of ASME A-384 Bolt "
GONZALES, J C, SCHMIDT, G R, HACKNEY, B D Bechtel Corp 83/03 03
FA 83/03/31 20pp 20761 275 24X Fiche 50-529, 83/09/23, 8310140269

8310140012 Final Deficiency Rept DER 83-14 re failure of Westinghouse diesel generator protective relays due to leaking capacitors Initially reported on 830316 Relays will be returned to supplier Capacitors will be replaced
VAN BRUNT, E E Arizona Public Service Co 83/09/27 STERNBERG, D H
Region 5, Office of Director 3pp 20767 006 24X
Fiche 50-528, 83/09/27, 8310140012

8310140238 Interim Deficiency Rept DER 83-46 re Borg Warner valve manually overtorqued during hydrostatic testing Initially reported on 830715 Time extension until 831214 requested for final rept due to extensive investigation required
VAN BRUNT, E E Arizona Public Service Co 83/09/28 STERNBERG, D H
Region 5, Office of Director 2pp 20761 321 24X
Fiche 50-528, 83/09/28, 8310140238

8310270413 Interim Deficiency Rept DER 83-59 re IEEE-384 separation criteria violated by wiring in post-accident control room & safety radiation monitoring cabinets Initially reported on 830830 Final rept to be submitted by 831129
VAN BRUNT, E E Arizona Public Service Co 83/10/03 STERNBERG, D H
Region 5, Office of Director 3pp 20924 028 24X
Fiche 50-529, 83/10/03, 8310270413

8310270460 Interim Deficiency Rept DER 83-60 re failure of wiring in main steam & feedwater actuation sys supplied by Vitro Labs Div to meet IEEE-384 separation criteria Initially reported on 830830 Completion of evaluation & final rept by 831130
VAN BRUNT, E E Arizona Public Service Co 83/10/03 STERNBERG, D H
Region 5, Office of Director 3pp 20922 025 24X
Fiche 50-529, 83/10/03, 8310270460

8310250415 Interim Deficiency Repts DER 82-57, DER 82-64 & DER 83-32 re conditions & circumstances surrounding design processes involved w/dissimilar metal socket welds
VAN BRUNT, E E Arizona Public Service Co 83/10/06 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 7pp 20897 245 24X Fiche 50-528, 83/10/06, 8310250415

8310250568 Final Deficiency Rept DER 83-38 re Steeler Steel clip angle used for HVAC supports that do not meet ASTM A-36 requirements Initially reported on 830620 Deficiency determined not reportable per 10CFR50 55(e)
VAN BRUNT, E E Arizona Public Service Co 83/10/06 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 93pp 20901 324 24X Fiche 50-528, 83/10/06, 8310250568

U Congressional/Executive Correspondence

8310240217 Requests response to issues raised by J Morrison 830703 ltr expressing concerns w/manner in which Regional V & Ofc of Investigation handled allegations of violations at plant
J Morrison 830703 ltr encl
UDALL, M K House of Rep, Interior & Insular Affairs 83/07/17
PALLADIO, N Commissioners 4pp 20904 040 24X
Fiche 50-528, 83/09/08, 8310240197

DOCKETED ITEMS

373

--B310240241 Notifies of receipt of T Woods B20511 ltr to NRC re allegations about safety at facilities Requests to be advised of any action taken by NRC in subj matter
RUDD, E House of Rep 82/05/19 PALLADINO, N J Commissioners
1p 20904 129 24X Fiche 50-528, 83/09/08, 8310240177

--B310240246 Ack receipt of B20519 ltr to Chairman Palladino expressing concern re allegations of improper electrical work at facilities Region V initiated independent inquiry into matter w/legal assistance
KAMMERER, C Office of Congressional Affairs 82/06/01 RUDD, E House of Rep 1p 20904 130 24X Fiche 50-528, 83/09/08, 8310240197

V Operator Examinations

B310030154 Requests schedule, by B30928, for requalification training & exams for 1984 in order to coordinate Region V audit of operator requalification programs
BISHOP, T W Division of Resident Reactor Project & Engineering Programs 83/09/26 ANDOGNINI, O C Arizona Public Service Co
2pp 20590 030 24X Fiche 50-528, 83/09/26, 8310030154

DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

B206080487 Comments on B20511 ltr re allegations of improper electrical work Inquiry made
DIRCKS, W J Office of the Executive Director for Operations 82/05/26 WOODS, T O Arizona Public Service Co 1p 20904 128 24X Fiche 50-528, 83/09/08, 8310240197

--B310240201 Submits list of plant electrician allegations that author considers readily documented w/o further investigation Some items listed already documented in rough form
ECKHARDT, J H NRC - No Detailed Affiliation Given 82/12/17
SHACKLETON, O NRC - No Detailed Affiliation Given 1p 20903 335 24X Fiche 50-528, 83/09/08, 8310240197

--B310240203 Submits results from informal B30323 meeting re unreviewed affidavits from Govt Accountability Project Shackleton analyzed Gunderson affidavit & will identify any new areas to Region V
NARBUT, P P Region 5, Office of Director 83/03/23
STERNBERG, D M NRC - No Detailed Affiliation Given 1p 20903 336 24X Fiche 50-528, 83/09/08, 8310240197

--B310240219 Forwards M Young & L Bernabei FOIA request for documents re allegations of R Gunderson & senior Bechtel manager FOIA time record form should be completed & returned
GRIMBLEY, D H NRC - No Detailed Affiliation Given 83/03/31
WILSON, V Office of Nuclear Reactor Regulation, Director 2pp 20904 049 24X Fiche 50-528, 83/09/08, 8310240197

--B310240220 Requests that documents be provided in attached FOIA Request B3-450 Documents required to be delivered to I Alexander by B30817 Forwards FOIA Request B3-450 & list of documents on subj Documents need not be duplicated
NARBUT, P Region 5, Office of Director 83/08/16 MARLIN, J NRC - No Detailed Affiliation Given 4pp 20904 051 24X Fiche 50-528, 83/09/08, 8310240197

--B310240236 Notifies that author had no involvement in investigation into allegations at facility, per Narbut B30816 memo No relevant documents re FOIA Request B3-450 in author possession
JOHNSON, P NRC - No Detailed Affiliation Given 83/08/18
ALEXANDER, I NRC - No Detailed Affiliation Given 1p 20904 111 24X Fiche 50-528, 83/09/08, 8310240197

B310050347 Notification of B31012 meeting w/util & C-E in Bethesda, MD to discuss updated status re reactor internals, evaluation of reactor coolant pumps, thermal sleeves & thermowells
LICITRA, E A Licensing Branch 3 83/09/19 KNIGHTON, Q W Licensing Branch 3 3pp 20650 051 24X Fiche 50-528, 83/09/19, 8310050347

B310050010 Submits updated status on RCB pumps, thermal sleeves & C-E shroud assemblies per B30913 & 14 telcons Design of pumps will be modified Followup status meeting scheduled for B31012
LICITRA, E A Licensing Branch 3 83/09/28 NOVAK, T M Assistant Director for Licensing 3pp 20650 255 24X Fiche 50-528, 83/09/28, 8310050010

B310130126 Forwards Rev 3 to "Salt Deposition & Impact Monitoring Plan"
VAN BRUNT, E E Arizona Public Service Co 83/09/29 KNIGHTON, Q Licensing Branch 3 2pp 20726 325 24X Fiche 50-528, 83/09/29, 8310130126

--B310130129 Rev 3 to "Salt Deposition & Impact Monitoring Plan"
* NUS Corp 83/07/31 18pp 20726 327 24X
Fiche 50-528, 83/09/29, 8310130126

B310260156 Forwards Rev 1 to Suppl 3 of "Probabilistic Risk Assessment of Effects of PORVs on Depressurization & DHR." Changes are result of detailed treatment of automatic PORV cases & complete analysis of auxiliary feedwater restoration
VAN BRUNT, E E Arizona Public Service Co 83/10/13 KNIGHTON, Q Licensing Branch 3 3pp 20914 178 24X Fiche 50-528, 83/10/13, 8310260156

--B310260160 Rev 1 to Suppl 3 of "Probabilistic Risk Assessment of Effects of PORVs on Depressurization & DHR."
* Combustion Engineering, Inc CEN-239 803 R01 83/09/30 373pp 20914 181 24X Fiche 50-528, 83/10/13, 8310260160

B310210252 Forwards revised responses to NRC B30727 request for addl info re util proposed rev to FAR Section 1 B concerning exceptions to Reg Guide 1.8B to permit use of records storage facility w/level concrete floor & roof
VAN BRUNT, E E Arizona Public Service Co 83/10/17 KNIGHTON, Q Licensing Branch 3 6pp 20851 263 24X Fiche 50-528, 83/10/17, 8310210252

B310310372 Informs that info requested in B30920 ltr re impact of high energy line breaks on control sys & exceptions taken in FAR Section 3.8.1.6 & 1 will be submitted by B31117
VAN BRUNT, E E Arizona Public Service Co 83/10/21 KNIGHTON, Q Licensing Branch 3 1p 20960 001 24X Fiche 50-528, 83/10/21, 8310310372

E NRC Safety Evaluation Report (SER), supplis & correspondence

B310030425 Forwards proprietary "Final Assessment of Palo Verde Nuclear Generation Station Fuel Assembly Spacer Grid Impact Loads Under Faulted Conditions," per SER (NUREG-0897) Section 4.2.1 Affidavit encl Rept withheld (ref 10CFR2.790)
VAN BRUNT, E E Arizona Public Service Co 83/09/26 KNIGHTON, Q Licensing Branch 3 7pp 20602 219 24X Fiche 50-528, 83/09/26, 8310030425

F Security, medical, emergency & fire protection plans

B310040375 Forwards revised response to outstanding fire protection Open Items 2, 4, 8, 10, 16, 21 & 23 identified at B30803 meeting in Bethesda, MD Revised response to Items 1, 3, 5 & 25 will be provided by B31130
VAN BRUNT, E E Arizona Public Service Co 83/09/29 KNIGHTON, Q Licensing Branch 3 34pp 20620 288 24X Fiche 50-528, 83/09/29, 8310040375

G Adjudicatory correspondence

B310240197 Partial response to L Bernabei B30805 FOIA request for agency records relevant to &/or generated in connection w/ NRC investigations, insps or repts on allegations made by R Gunderson & W Royce Forwards App A documents, FELTON, J M Division of Rules and Records, 83/09/08 GARDE, B Government Accountability Project 4pp 20903 251 24X Fiche 50-528, 83/09/08, 8310240197

--B310240212 Forwards Dept of Labor B30324 Recommended Decision & Order of Administrative Law Judge in W Royce vs Bechtel Corp case
BUTLER, S D Bechtel Corp 83/03/30 Bechtel Corp. 12pp 20904 001 24X Fiche 50-528, 83/09/08, 8310240197

B310250264 Forwards several insp repts re investigations of allegations by former const workers
DEWEY, L B NRC - No Detailed Affiliation Given 83/10/21
LAZO, R M, COLE, R F, CALLIHAN, D Atomic Safety and Licensing Board Panel 5pp 20899 088 24X Fiche 50-529, 83/10/21, 8310250264

B310270234 Order extending time until B31108 for Commission to act to review ALAB-742
CHILK, B J Office of the Secretary of the Commission 83/10/26 Commissioners 1p 20924 070 24X Fiche 50-529, 83/10/26, 8310270234

G Inspection reports, IE Bulletins & correspondence

B310240196 FOIA request for agency records relevant to &/or generated in connection w/NRC investigations, insp or repts on allegations made by R Gunderson & W Royce re facilities, BERNABEI, L Government Accountability Project 83/08/05 Office of Administration 2pp 20903 249 24X Fiche 50-528, 83/08/05, 8310240196

DOCKETED ITEMS

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/p 10CFR50 59 Evaluation." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 EUTPSNH Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310250264 Forwards several insp repts re investigations of allegations by former const workers
DEWEY, L. S. NRC - No Detailed Affiliation Given 83/10/21
LAZD, R. H. Atomic Safety and Licensing Board Panel 5pp 20899 088 24X Fiche 50-528, 83/10/21, 8310250264

8 Reportable occurrences, IERs & related correspondence

8310070286 Final Deficiency Rept DER 82-48 re underground cables to startup transformers which may not carry full load current at max site soil temp. Initially reported on 821126 Condition not reportable per 10CFR50.55(e).
VAN BRUNT, E. E. Arizona Public Service Co 83/09/16. STERNBERG, D. M. Region 5, Office of Director 5pp 20457. 028 24X Fiche 50-528, 83/09/16, 8310070286

8310070289 "Boil Thermal Property Measurements for Palo Verde Nuclear Plant."
MARTIN, M. A. M&E Technology, Inc 83/02/09 32pp 20457-033 24X Fiche 50-528, 83/09/16, 8310070289

8310070147 Final Deficiency Rept DER 83-25 re instrumentation tubing w/o required boundary class break. Initially reported on 830421. Deficiency determined not reportable under 10CFR50.55(e).
VAN BRUNT, E. E. Arizona Public Service Co. 83/09/21 STERNBERG, D. M. Region 5, Office of Director. 13pp 20459 048 24X Fiche 50-528, 83/09/21, 8310070147

8310070352 Interim Deficiency Rept DER 83-42 re thermowells in RCS Initially reported on 830729 Final rept extension requested due to extensive investigation & evaluation Final rept will be submitted by 831201.
VAN BRUNT, E. E. Arizona Public Service Co 83/09/21 STERNBERG, D. M. Region 5, Office of Director. 2pp 20451. 095 24X Fiche 50-528, 83/09/21, 8310070352

831040269 Final Deficiency Rept DER 83-15 re Marathon Steel A354 anchor bolt breaking under installation torque after test acceptance. Initially reported on 830318 Analysis concluded bolt torsional failure caused by ductile shear overload.
VAN BRUNT, E. E. Arizona Public Service Co 83/09/23 STERNBERG, D. M. Region 5, Office of Director. 5pp 20761-270 24X Fiche 50-529, 83/09/23, 831040269

0140274 "Failure Analysis of ASTM A-354 Bolt."
ONZALEZ, J. C., SCHMIDT, G. R., HACKNEY, B. D. Bechtel Corp 0383-03 A. 83/03/31. 20pp 20761-275. 24X Fiche 50-529, 83/09/23, 831040269

8310240197 Partial response to L Bernabei 830805 FOIA request for agency records relevant to &/or generated in connection w/ NRC investigations, insps or repts on allegations made by R Gunderson & W Royce Forwards App A documents
FELTON, J. M. Division of Rules and Records 83/09/08 GARDE, B. Government Accountability Project 4pp 20903 251 24X Fiche 50-528, 83/09/08, 8310240197

--8310240199 Requests assistance in disclosing worker allegations re problems at facility Various allegations by workers re const, OA & GC problems existing at plant discussed
MORRISON, J. R. Palo Verde Intervention Fund 82/12/07 GARDE, B. Government Accountability Project 3pp 20903 032 24X Fiche 50-528, 83/09/08, 8310240197

--8310240215 Requests review of NRC serious mishandling of investigation of worker allegations re deficiencies in electrical work & startup testing program at facilities, on behalf of
R Gunderson & W Royce Related matl encl
BERNABEI, L. Government Accountability Project 83/07/14
PALLADINO, N. Commissioners 17pp 20904 013 24X Fiche 50-528, 83/09/08, 8310240197

--8310240218 Submits list of documents in Region V files which apply to Young & Bernabei FOIA-83-161 request for documents re allegations of electrical problems Related matl encl
ALEXANDER, I. Region 5, Office of Director 83/05/06 TOMS, V. NRC - No Detailed Affiliation Given 5pp 20904 045 24X Fiche 50-528, 83/09/08, 8310240197

--8310240221 Forwards L Bernabei FOIA request for documents in connection w/NRC investigations, insps or repts on allegations made by R Gunderson & W Royce re facilities List of questions for response to NL Toms requested by 830816
GRIMSLEY, D. H. NRC - No Detailed Affiliation Given 83/08/09
BROWN, N. Office of the Secretary of the Commission 2pp 20904 055 24X Fiche 50-528, 83/09/08, 8310240197

--8310240222 Notifies that special, unannounced insp scheduled at facility on 830404-08 Team consisting of author, A Johnson, J Burdoin, G Fiorelli & L Vorderbruggen will examine facts surrounding as many allegations as possible during insp
YOUNG, T. Region 5, Office of Director 83/03/31 STERNBERG, D. NRC - No Detailed Affiliation Given 1p 20904 059 24X Fiche 50-528, 83/09/08, 8310240197

--8310240223 Discusses NRC insp entrance interview conducted on 830615 to describe NRC planned insp activities Lists NRC inspectors & areas of investigation NRC will be primarily investigating allegations during visit Related matl encl
IDE, W. E. Arizona Public Service Co 82/06/15 ROEDEL, J. A. Arizona Public Service Co 4pp 20904 102 24X Fiche 50-528, 83/09/08, 8310240197

--8310240227 Discusses status of special insp re allegations, in response to 830411 memo Lists items not addressed Efforts will be concluded & pertinent repts issued on listed items prior to 830601 Relevant documents issued & received encl
MARTIN, J. B. Region 5, Office of Director 83/05/02
CUNNINGHAM, G. H. Office of the Executive Legal Director 8pp 20904 104 24X Fiche 50-528, 83/09/08, 8310240197

--8310240239 Forwards documents re FOIA request for NRC investigation, insps or repts on allegations made by R Gunderson & W Royce concerning facilities Excerpt of installation spec for cable splicing encl
ALEXANDER, I. Region 5, Office of Director 83/08/19 TOMS, V. NRC - No Detailed Affiliation Given 9pp 20904 112 24X Fiche 50-528, 83/09/08, 8310240197

--8310240251 Discusses immediate effectiveness review of facilities re analysis of pending insp/investigation items identified in Ofc of Insp & EDQ repts of 830325 & 29 Presumes SECY will extend review time to accommodate Commission consideration
ASSELSTINE, J. K. Commissioners 83/04/01 PALLADINO, Commissioners 1p 20904 131 24X Fiche 50-528, 83/09/08, 8310240197

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intake." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

DOCKETED ITEMS

376

8310140238 Interim Deficiency Rept DER 83-46 re Borg Warner valve manually overtorqued during hydrostatic testing Initially reported on 830715 Time extension until 831214 requested for final rept,due to extensive investigation required
VAN BRUNT,E E Arizona Public Service Co 83/09/28 STERNBERG,D M Region 5, Office of Director 2pp 20761 321 24X
Fiche 50-528,83/09/28,8310140238

8310250415 Interim Deficiency Repts DER 82-57,DER 82-64 & DER 83-32 re conditions & circumstances surrounding design processes involved w/dissimilar metal socket welds
VAN BRUNT,E E Arizona Public Service Co 83/10/06 BISHOP,T W Division of Resident, Reactor Project & Engineering Programs 2pp 20897 245 24X Fiche 50-528,83/10/06,8310250415

8310250568 Final Deficiency Rept DER 83-38 re Steiler Steel clip angles used for HVAC supports that do not meet ASTM A-36 requirements Initially reported on 830620 Deficiency determined not reportable per 10CFR50.55(e)
VAN BRUNT,E E Arizona Public Service Co 83/10/06 BISHOP,T W Division of Resident,Reactor Project & Engineering Programs 43pp 20901 324 24X Fiche 50-528,83/10/06,8310250568

8310270409 Interim Deficiency Rept DER 83-36 re excessive recycling of ITT hydramotor actuators Initially reported on 830629 Due to extensive investigation & evaluation,final rept expected by 831208
VAN BRUNT,E E Arizona Public Service Co 83/10/12 BISHOP,T W Division of Resident,Reactor Project & Engineering Programs 2pp 20924 031 24X Fiche 50-530,83/10/12,8310270409

U Congressional/Executive Correspondence

8310240217 Requests response to issues raised by J Morrison 830703 ltr expressing concerns w/manner in which Regional V & Ofc of Investigation handled allegations of violations at plant
J Morrison 830703 ltr encl
UDALL,M K House of Rep , Interior & Insular Affairs 83/07/17
PALLADINO,N Commissioners 4pp 20904 040 24X
Fiche 50-528,83/09/08,8310240197

--8310240241 Notifies of receipt of T Woods 820511 ltr to NRC re allegations about safety at facilities Requests to be advised of any action taken by NRC in subj matter
RUDD,E House of Rep 82/05/19 PALLADINO,N J Commissioners 1p 20904 129 24X Fiche 50-528,83/09/08,8310240197

--8310240246 Ack receipt of 820519 ltr to Chairman Palladino expressing concern re allegations of improper electrical work at facilities Region V initiated independent inquiry into matter w/legal assistance
KAMMERER,C Office of Congressional Affairs 82/06/01 RUDD,E House of Rep 1p 20904 130 24X Fiche 50-528,83/09/08,8310240197

V Operator Examinations

8310030154 Requests schedule,by 830928,for requalification training & exams for 1984 in order to coordinate Region V audit of operator requalification programs
BISHOP,T W Division of Resident,Reactor Project & Engineering Programs 83/09/26 ANDOGNINI,G C Arizona Public Service Co 2pp 20590 030 24X Fiche 50-528,83/09/26,8310030154

DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

A Application/Construction stage documents & correspondence

8310260309 Summarizes 830808 informal meeting on contract re PRA review of CRBR (Task 4) & NRC concerns associated w/Technology for Energy Corp deliverables schedule
JOHNSON,B Science Applications, Inc NRC-03-82-096 83/08/11
SPANO,A NRC - No Detailed Affiliation Given 10pp 20911 343
24X Fiche 50-537,83/08/11,8310260309

8310050405 Notification of 831004 meeting w/util,DOE & Project Mgt Corp in Bethesda,MD to discuss applicants probabilistic risk assessment
STARK,R M Clinch River Breeder Reactor Program Office 83/09/26
GRACE,J N Clinch River Breeder Reactor Program Office 4pp 20650 006 24X Fiche 50-537,83/09/26,8310050405

8308300357 Board Notification 82-105A Forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Canyon 1 & 2,Fermi 2 & Callaway
EISENHUT,D G Division of Licensing 83/09/29 PALLADINO,N J Commissioners 3pp 20632 001 24X Fiche 50-000,83/09/29,8308300357

8310130159 Notification of 831025 meeting w/DOE,Project Mgt Corp & util in Oak Ridge,TN to discuss applicants equipment storage requirements
STARK,R M Clinch River Breeder Reactor Program Office 83/10/05
GRACE,J N Clinch River Breeder Reactor Program Office 3pp 20777 175 24X Fiche 50-537,83/10/05,8310130159

8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves
EISENHUT,D G Division of Licensing 83/10/06 PALLADINO,N J Commissioners 31pp 20818 001 24X Fiche 50-000,83/10/06,8308300771

8308310050 Board Notification 83-160 provides info re 830812 failure of main crankshaft on one of three Transamerica Delaval emergency diesel generators at Shoreham
EISENHUT,D G Division of Licensing 83/10/14 PALLADINO,N J Commissioners 13pp 67056 070 24X Fiche 50-000,83/10/14,8308310050

8310310059 Summarizes 831004 meeting w/NRC,ACRS & LNR Assoc re mgt of CRBR PRA program Viewgraphs & list of meeting attendees encl
QAYIGAN,F X Energy, Dept of Clinch River Breeder Reactor Plant 83/10/24 GRACE,J N Clinch River Breeder Reactor Program Office 19pp 20951 005 24X Fiche 50-537,83/10/24,8310310059

G Adjudicatory correspondence

8310130150 Response to ASLB 830915 order,applicant 830921 motion to close record & motion for leave to file NRC affidavit & supplemental proposed findings of fact Supports motion to close record
TURK,S E Hearing Branch 1 83/10/06 Atomic Safety and Licensing Board Panel 6pp 20724:231 24X Fiche 50-537,83/10/06,8310130150

--8310130152 Affidavit of BJ Brocoun,RL Rothman & RB McMullen providing NRC evaluation of recent discovery of faults at site Faults not capable & do not represent hazardous site condition
BROCOUN,B J, ROTHMAN,R L, MCMULLEN,R B Geosciences Branch 83/10/06 18pp 20724 257 24X Fiche 50-537,83/10/06,8310130150

--8310130156 Supplemental proposed findings of fact re site faults. Certificate of Svc encl
TURK,S E Hearing Branch 1 83/10/06 5pp 20724.275 24X Fiche 50-537,83/10/06,8310130150

8310260292 Supplemental citations supporting thesis that following hydrodynamic core disruptive accident,reactor vessel closure head is more susceptible to failure than reactor vessel head Certificate of Svc encl
EDGAR,G L Project Management Corp EDGAR,G L Edgar, G L LUCK,W D Energy, Dept of 83/10/25 7pp 20912 001 24X Fiche 50-537,83/10/25,8310260292

8310260301 Order accepting into evidence,applicant 830921 & NRC 831004 written responses to ASLB 830915 request for seismic info Ruling on applicant motion to close record deferred,NRDC response to Hulman affidavit will be reviewed by ASLB
MILLER,M E Atomic Safety and Licensing Board Panel 83/10/25 4pp 20911 035 24X Fiche 50-537,83/10/25,8310260301

G Inspection reports, IE Bulletins & correspondence

8310250231 Forwards IE Insp Rept 50-537/83-10 on 830901-02 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/09/22 BREHINGTON,P Tennessee Valley Authority 2pp 20899 047 24X Fiche 50-537,83/09/22,8310250231

--8310250236 IE Insp Rept 50-537/83-10 on 830901-02.No noncompliance noted Major areas inspected site preparation & structural concrete
HARRIS,J R Region 2, Office of Director, CONLON,T E Division of Engineering & Operational Programs 83/09/20 3pp 20899:049 24X Fiche 50-537,83/09/22,8310250231

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 116pp 20777-210 24X Fiche 50-000,83/09/26,8308300342

DOCKETED ITEMS

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Mtl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

DOCKET 83N-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8310040428 Forward's status of outstanding Third Quarter 1983 commitments in amends to FSAR Description of containment hydrogen monitoring sys will be submitted during First Quarter 1984
SHIELDS, S W Public Service Co of Indiana, Inc 83/09/30
DENTON, H R Office of Nuclear Reactor Regulation, Director. 2pp 20619 106 24X Fiche 50-546, 83/09/30, 8310040428

110240178 "Independent Const Review of Marble Hill Units 1 & 2," Vol 1, "Executive Summary "
* Torrey Pines Technology QA-C17258 V01 83/09/30 25pp 20878 115 24X Fiche 50-546, 83/09/30, 8310240178

8310240179 "Independent Const Review of Marble Hill Units 1 & 2," Vol 2, "Program Results "
* Torrey Pines Technology QA-C17258 V02 83/09/30 129pp 20878 144 24X Fiche 50-546, 83/09/30, 8310240179

8310240182 "Independent Const Review of Marble Hill Units 1 & 2," Vol 3, "Potential Finding Repts & Corrective Action Plans "
* Torrey Pines Technology QA-C17258 V03 83/09/30 327pp 20878 273 24X Fiche 50-546, 83/09/30, 8310240182

8310130047 Notification of 831013 meeting w/utl in Bethesda, MD to discuss Occurrences Branch request for addl info
O'DONNOR, P W Licensing Branch 1 83/10/03 YOUNGBLOOD, B J Licensing Branch 1 3pp 20776 234 24X Fiche 50-546, 83/10/03, 8310130047

8300775 Board Notification 83-135A forwards 830919 revised draft of QA Case Study Working Paper - Case C, - & cover & transmittal memos re Diablo Canyon
EISENHUT, D O Division of Licensing 83/10/14 PALLADINO, N J Commissioners 3pp 20799 001 24X Fiche 50-000, 83/10/14, 8300775

8310180505 Informs that working papers for three QA case studies complete, per 830923 memo. Case C re Diablo Canyon, dtd 830919, is rev to 830719 draft transmitted in Board Notification 83-135 on 830902. Papers & transmittal ltrs forwarded
TAYLOR, J M QA Branch 83/09/28 EISENHUT, D O Division of Licensing 2pp 20799 004 24X Fiche 50-000, 83/10/14, 8308300775

8310153 Ack receipt of 830902 request for extension to submit 20-day response to Generic Ltr 83-28 re Salem ATWS events request granted Submittal by 840401 requested
YOUNGBLOOD, B J Licensing Branch 1 83/10/19 SHIELDS, S W Public Service Co of Indiana, Inc. 2pp 20665 316 24X Fiche 50-546, 83/10/19, 8310153

C Utility Environmental Report (ER), amends & correspondence

8310110383 Forwards request for addl info re environ review requested to complete evaluation of application for OLS Requests results of review of environ rept
YOUNGBLOOD, B J Licensing Branch 1 83/09/28 SHIELDS, S W Public Service Co of Indiana, Inc 7pp 20713 297 24X Fiche 50-546, 83/09/28, 8310110383

8310110901 Forwards request for addl info required to complete evaluation of environ rept Response requested by 831011
YOUNGBLOOD, B J Licensing Branch 1 83/09/29 SHIELDS, S W Public Service Co of Indiana, Inc 4pp 20714 360 24X Fiche 50-546, 83/09/29, 8310110901

G Adjudicatory correspondence

8310260291 Petition of Save the Valley for leave to intervene, listing 15 contentions re integrity of concrete in safety-related structures, electrical work, evacuation plans & common mode failures Certificate of Svc encl
CASSIDY, H G Save the Valley - Save Marble Hill 83/10/21 Office of the Secretary of the Commission 6pp 20711 137 24X Fiche 50-546, 83/10/21, 8310260291

8310310177 Informs that recent filings by intervenors received by ATWS w/only one copy for all three members Procedures require each party & ASLD member to be served individually ASLD requires all parties comply w/proper filing procedures
MORAN, D M Atomic Safety and Licensing Board Panel 83/10/20 1p 20759 001 24X Fiche 50-546, 83/10/20, 8310310177

Q Inspection reports, IE Bulletins & correspondence

8310040390 Expresses appreciation for cooperation w/LL activities to comply w/Congressional direction to NRC to perform QA studies & pilot program Draft QA case study working paper encl
TAYLOR, J M Division of QA, Safeguards & Inspection Programs (Post 830103) 83/08/02 SHIELDS, S W Public Service Co of Indiana, Inc 76pp 20620 049 24X Fiche 50-546, 83/08/02, 8310040390

8310040526 Forwards IE Insp Repts 50-546/83-15 & 50-547/83-15 on 830701-0831 & notice of violation
KONF, R C Region 3, Office of Director 83/09/13 SHIELDS, S W Public Service Co of Indiana, Inc 2pp 20623 268 24X Fiche 50-546, 83/09/13, 8310040526

8310040531 Notice of violation from insp on 830701-0831
* Region 3, Office of Director 83/09/13 1p 20623 270 24X Fiche 50-546, 83/09/13, 8310040531

8310040540 IE Insp Repts 50-546/83-15 & 50-547/83-15 on 830701-0831 Noncompliance noted failure to document nonconforming condition re 1 beam column linear indication
SCHAFER, J F, KONKLIN, J E Region 3, Office of Director 83/09/12 8pp 20623 271 24X Fiche 50-546, 83/09/13, 8310040540

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50.59 Evaluation." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

DOCKETED ITEMS

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 77pp 20882 026 24X Fiche 50-000,83/10/07,8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

8310180233 Clarifies NRC position re procedures for admitting NRC personnel to facility List of personnel requiring access to vital areas encl Updates will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 SHIELDS, S W Public Service Co of Indiana, Inc 7pp 20808 174 24X Fiche 50-546,83/10/14,8310180233

8310240066 Ack receipt of 831011 ltr informing NRC of steps taken to correct violations noted in 1h Insp Repts 50-546/83-15 & 50-547/83-15
KHOP, R C Region 3, Office of Director 83/10/19 SHIELDS, S W Public Service Co of Indiana, Inc 1p 20878 099 24X Fiche 50-546,83/10/19,8310240066

--8310240081 Responds to NRC 830913 ltr re violations noted in 1h Insp Repts 50-546/83-15 & 50-547/83-15 Corrective actions directive will be issued to Pullman Const Industries emphasizing responsibility for reporting nonconformances
SHIELDS, S W Public Service Co of Indiana, Inc 83/10/11 KEPLER, J G Region 3, Office of Director 2pp 20878 100 24X Fiche 50-546,83/10/19,8310240066

8310280195 Forwards ltrs to Comm Ed & Byron integrated design insp rept identifying QA & design verification issues for Byron & Braidwood stations Response required within 90 days
YOUNGBLOOD, B J Licensing Branch 1 83/10/19 SHIELDS, S W Public Service Co of Indiana, Inc 2pp 20764 144 24X Fiche 50-546,83/10/19,8310280195

S Reportable occurrences, LfRs & related correspondence

8310040337 Interim deficiency rept re potential for spec/design changes to remain unincorporated in as-built configuration of safety-related equipment or structures Initially reported on 81120B Procedure changes in progress Next rept by 840217
SHIELDS, S W Public Service Co of Indiana, Inc 83/09/30 KEPLER, J G Region 3, Office of Director 2pp 20646 129 24X Fiche 50-546,83/09/30,8310040337

8310210025 Interim deficiency rept re indications that Pullman Const Industries, Inc failed to adequately implement QA program Initially reported on 83022B Reinsp continuing Next rept will be submitted by 840210
SHIELDS, S W Public Service Co of Indiana, Inc 83/10/13 KEPLER, J G Region 3, Office of Director 2pp 20858 204 24X Fiche 50-546,83/10/13,8310210025

8310270395 Interim deficiency rept re Westinghouse centrifugal charging pumps at min allowable flow rate when kCS reaches value below pressurizer safety valve setpoint pressure Initially reported on 800509 Also reported per Part 21
SHIELDS, S W Public Service Co of Indiana, Inc 83/10/20 KEPLER, J G Region 3, Office of Director 2pp 20924 034 24X Fiche 50-546,83/10/20,8310270395

8310270458 Interim deficiency rept re welding techniques not covered by QA program used in fabrication of safety-related switchgear Initially reported on 820525 QA manual rewritten & procedures revised to include controls on welding
SHIELDS, S W Public Service Co of Indiana, Inc 83/10/20 KEPLER, J G Region 3, Office of Director 2pp 20923 105 24X Fiche 50-546,83/10/20,8310270458

DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8310040428 Forwards status of outstanding Third Quarter 1983 commitments in amends to FSAR Description of containment hydrogen monitoring sys will be submitted during First Quarter 1984
SHIELDS, S W Public Service Co of Indiana, Inc 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp. 20619 106 24X Fiche 50-546,83/09/30,8310040428

8310240178 "Independent Const Review of Marble Hill Units 1 & 2," Vol 1, "Executive Summary"
* Torrey Pines Technology QA-C17258 V01 83/09/30 25pp 20878 115 24X Fiche 50-546,83/09/30,8310240178

--8310240179 "Independent Const Review of Marble Hill Units 1 & 2," Vol 2, "Program Results"
* Torrey Pines Technology QA-C17258 V02 83/09/30 129pp 20878 144 24X Fiche 50-546,83/09/30,8310240178

--8310240182 "Independent Const Review of Marble Hill Units 1 & 2," Vol 3, "Potential Finding Repts & Corrective Action Plans"
* Torrey Pines Technology QA-C17258 V03 83/09/30 327pp. 20878 273 24X Fiche 50-546,83/09/30,8310240178

8310130047 Notification of 831013 meeting w/util in Bethesda, MD to discuss Geosciences Branch request for addl info
O'CONNOR, P W Licensing Branch 1 83/10/03 YOUNGBLOOD, B J Licensing Branch 1 3pp 20776 234 24X Fiche 50-546,83/10/03,8310130047

8308300775 Board Notification 83-135A forwards 830919 revised draft of "QA Case Study Working Paper - Case C," & cover & transmittal memos re Diablo Canyon
EISENHUT, D G Division of Licensing 83/10/14 PALLADINO, N J Commissioners 3pp 20799 001 24X Fiche 50-000,83/10/14,8308300775

--8310180505 Informs that working papers for three QA case studies complete per 830923 memo Case C re Diablo Canyon, dtd 830919, is rev to 830719 draft transmittal in Board Notification 83-135 on 830902 Papers & transmittal ltrs forwarded
TAYLOR, J M QA Branch 83/09/28 EISENHUT, D G Division of Licensing 2pp 20799 004 24X Fiche 50-000,83/10/14,8308300775

8310310153 Ack receipt of 830902 request for extension to submit 120-day response to Generic Ltr 83-28 re Salem ATWS events Request granted Submittal by 840401 requested
YOUNGBLOOD, B J Licensing Branch 1 83/10/19 SHIELDS, S W Public Service Co of Indiana, Inc 2pp 20965 316 24X Fiche 50-546,83/10/19,8310310153

C Utility Environmental Report (ER), amends & correspondence

8310110383 Forwards request for addl info re environ review required to complete evaluation of application for OLS Requests results of review of environ rept
YOUNGBLOOD, B J Licensing Branch 1 83/09/28 SHIELDS, S W Public Service Co of Indiana, Inc 9pp 20713 297 24X Fiche 50-546,83/09/28,8310110383

8310110501 Forwards request for addl info required to complete evaluation of environ rept Response requested by 831101
YOUNGBLOOD, B J Licensing Branch 1 83/09/29 SHIELDS, S W Public Service Co of Indiana, Inc 4pp 20714 360 24X Fiche 50-546,83/09/29,8310110501

D Adjudicatory correspondence

8310260291 Petition of Save the Valley for leave to intervene, listing 15 contentions re integrity of concrete in safety-related structures, electrical work, evacuation plans & common mode failures Certificates of Svc encl
CASSIDY, H G Save the Valley - Save Marble Hill 83/10/21 Office of the Secretary of the Commission 6pp 20711-357 24X Fiche 50-546,83/10/21,8310260291

8310310179 Informs that recent filings by intervenors received by ASLB w/only one copy for all three members Procedures require each party & ASLB member to be served individually ASLB requires all parties comply w/proper filing procedures
MORAN, D M Atomic Safety and Licensing Board Panel 83/10/28 1p. 20959 001 24X Fiche 50-546,83/10/28,8310310179

DOCKETED ITEMS

G Inspection reports, IE Bulletins & correspondence

8310040390 Expresses appreciation for cooperation w/IE activities to comply w/Congressional direction to NRC to perform QA studies & pilot program Draft QA case study working paper encl
TAYLOR, J M Division of QA, Safeguards & Inspection Programs (Post 830103) 83/08/02 SHIELDS, S W Public Service Co of Indiana, Inc 7pp 20620 049 24X Fiche 50-546, 83/08/02, 8310040390

8310040526 Forwards IE Insp Repts 50-546/83-15 & 50-547/83-15 on 830701-0831 & notice of violation
KNOP, R C Region 3, Office of Director 83/09/13 SHIELDS, S W Public Service Co of Indiana, Inc 2pp 20623 268 24X Fiche 50-546, 83/09/13, 8310040526

--8310040531 Notice of violation from insp on 830701-0831
* Region 3, Office of Director 83/09/13 1p 20623 270 24X Fiche 50-546, 83/09/13, 8310040531

--8310040540 IE Insp Repts 50-546/83-15 & 50-547/83-15 on 830701-0831 Noncompliance noted failure to document nonconforming condition re I beam column linear indication
SCHAPKE, J F, KONKLIN, J E Region 3, Office of Director 83/09/12 8pp 20623 271 24X Fiche 50-546, 83/09/13, 8310040526

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180233 Clarifies NRC position re procedures for admitting NRC personnel to Facility List of personnel requiring access to vital areas encl Updates will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 SHIELDS, S W Public Service Co of Indiana, Inc 7pp 20808 174 24X Fiche 50-546, 83/10/14, 8310180233

8310240066 Ack receipt of 831011 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/83-15 & 50-547/83-15
KNOP, R C Region 3, Office of Director 83/10/19 SHIELDS, S W Public Service Co of Indiana, Inc 1p 20878 099 24X Fiche 50-546, 83/10/19, 8310240066

--8310240081 Responds to NRC 830913 ltr re violations noted in IE Insp Repts 50-546/83-15 & 50-547/83-15 Corrective actions directive will be issued to Pullman Const Industries emphasizing responsibility for reporting nonconformances
SHIELDS, S W Public Service Co of Indiana, Inc 83/10/11 KEPLER, J G Region 3, Office of Director 2pp 20878 100 24X Fiche 50-546, 83/10/19, 8310240066

8310280195 Forwards ltrs to Comm Ed & Buion integrated design insp report identifying QA & design verification issues for Buion & Braidwood Stations Response required within 90 days
YOUNGBLOOD, J J Licensing Branch 1 83/10/19 SHIELDS, S W Public Service Co of Indiana, Inc 2pp 20664 144 24X Fiche 50-546, 83/10/19, 8310280195

S Reportable occurrences, LHRs & related correspondence

8310060337 Interim deficiency rpt re potential for spec/design change to remain unincorporated in as-built configuration of safety-related equipment or structures Initially reported on 811208 Procedure changes in progress Next rpt by 840217
SHIELDS, S W Public Service Co of Indiana, Inc 83/09/30 KEPLER, J G Region 3, Office of Director 2pp 20646 129 24X Fiche 50-546, 83/09/30, 8310060337

8310170530 Final rpt re cracks in welds at stiffeners to box beams Initially reported on 830715 Welding method modified Cracked areas ground out & repaired using approved procedures
SHIELDS, S W Public Service Co of Indiana, Inc 83/10/07 KEPLER, J G Region 3, Office of Director 2pp 20784 234 24X Fiche 50-547, 83/10/07, 8310170530

8310210025 Interim deficiency rpt re indications that Pullman Const Industries, Inc failed to adequately implement QA program Initially reported on 830228 Reinsp continuing Next rpt will be submitted by 840210
SHIELDS, S W Public Service Co of Indiana, Inc 83/10/13 KEPLER, J G Region 3, Office of Director 2pp 20858 204 24X Fiche 50-546, 83/10/13, 8310210025

8310270395 Interim deficiency rpt re Westinghouse centrifugal charging pumps at min allowable flow rate when RCS reaches value below pressurizer safety valve setpoint pressure Initially reported on 800509 Also reported per Part 21
SHIELDS, S W Public Service Co of Indiana, Inc 83/10/20 KEPLER, J G Region 3, Office of Director 2pp 20724 034 24X Fiche 50-546, 83/10/20, 8310270395

8310270458 Interim deficiency rpt re welding techniques not covered by QA program used in fabrication of safety-related switchgear Initially reported on 820525 QA manual rewritten & procedures revised to include controls on welding
SHIELDS, S W Public Service Co of Indiana, Inc 83/10/20 KEPLER, J G Region 3, Office of Director 2pp 20723 105 24X Fiche 50-546, 83/10/20, 8310270458

DOCKET STN-50-553 PHIPPS BEND NUCLEAR STATION, UNIT 1

G Adjudicatory correspondence

8310210177 Forwards Memorandum & Order A1 AD-745, suggesting TVA file motion to terminate proceedings for canceled units
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/19 BURGER, J F Tennessee Valley Authority 1p 20856 127 24X Fiche 50-553, 83/10/19, 8310210177

DOCKET STN-50-554 PHIPPS BEND NUCLEAR STATION, UNIT 2

G Adjudicatory correspondence

8310210177 Forwards Memorandum & Order A1 AD-745, suggesting TVA file motion to terminate proceedings for canceled units
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/19 BURGER, J F Tennessee Valley Authority 1p 20856 127 24X Fiche 50-553, 83/10/19, 8310210177

DOCKET STN-50-556 BLACK FOX STATION, UNIT 1

G Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

#

DOCKETED ITEMS

Q Inspection reports, IE Bulletins & correspondence

8310040390 Expresses appreciation for cooperation w/IE activities to comply w/Congressional direction to NRC to perform QA studies & pilot program Draft QA case study working paper encl
TAYLOR, J M Division of QA, Safeguards & Inspection Programs (Post 830103) 83/08/02 SHIELDS, S W Public Service Co of Indiana, Inc 76pp 20620 049 24X Fiche 50-546, 83/08/02, 8310040390

8310040526 Forwards IE Insp Repts 50-546/83-15 & 50-547/83-15 on 830701-0831 & notice of violation
KNOP, R C Region 3, Office of Director 83/09/13 SHIELDS, S W Public Service Co of Indiana, Inc 2pp 20623 268 24X Fiche 50-546, 83/09/13, 8310040526

--8310040531 Notice of violation from insp on 830701-0831
* Region 3, Office of Director 83/09/13 1p 20623 270 24X Fiche 50-546, 83/09/13, 8310040531

--8310040540 IE Insp Repts 50-546/83-15 & 50-547/83-15 on 830701-0831 Noncompliance noted failure to document nonconforming condition re I beam column linear indication
SCHAPKER, J F, KONKLIN, J E Region 3, Office of Director 83/09/12 8pp 20623 271 24X Fiche 50-546, 83/09/12, 8310040540

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20862 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761

8310180233 Clarifies NRC position re procedures for admitting NRC personnel to facility list of personnel requiring access to vital areas encl Updates will be provided every 6 months
AXELSON, W L Region 3, Office of Director 83/10/14 SHIELDS, S W Public Service Co of Indiana, Inc 7pp 20808 174 24X Fiche 50-546, 83/10/14, 8310180233

8310240066 Ack receipt of 831011 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/83-15 & 50-547/83-15
KNOP, R C Region 3, Office of Director 83/10/19 SHIELDS, S W Public Service Co of Indiana, Inc 1p 20878 099 24X Fiche 50-546, 83/10/19, 8310240066

--8310240081 Responds to NRC 830913 ltr re violations noted in IE Insp Repts 50-546/83-15 & 50-547/83-15 Corrective actions directive will be issued to Pullman Const Industries emphasizing responsibility for reporting nonconformances.
SHIELDS, S W Public Service Co of Indiana, Inc 83/10/11, KEPLER, J G, Region 3, Office of Director 2pp 20878 100 24X Fiche 50-546, 83/10/19, 8310240081

8310280195 Forwards ltr to Comm Ed & Byron integrated design insp repl identifying QA & design verification issues for Byron & Bradwood stations Response required within 90 days
YOUNGBLOOD, B J Licensing Branch 1 83/10/19 SHIELDS, S W Public Service Co of Indiana, Inc 2pp 20964 144 24X Fiche 50-546, 83/10/19, 8310280195

S Reportable occurrences, LHRs & related correspondence

8310060337 Interim deficiency rpt re potential for spec/design change to remain unincorporated in as-built configuration of safety-related equipment or structures Initially reported on 811208 Procedure changes in progress Next rpt by 840217
SHIELDS, S W Public Service Co of Indiana, Inc 83/09/30 KEPLER, J G Region 3, Office of Director 2pp 20646 124 24X Fiche 50-546, 83/09/30, 8310060337

8310170530 Final rpt re cracks in welds at stiffeners to box beams Initially reported on 830715 Welding method modified Cracked areas ground out & repaired using approved procedures
SHIELDS, S W Public Service Co of Indiana, Inc 83/10/07 KEPLER, J G Region 3, Office of Director 2pp 20784 234 24X Fiche 50-547, 83/10/07, 8310170530

8310210025 Interim deficiency rpt re indications that Pullman Const Industries, Inc failed to adequately implement QA program Initially reported on 830228 Reinsp continuing Next rpt will be submitted by 840210
SHIELDS, S W Public Service Co of Indiana, Inc 83/10/13 KEPLER, J G Region 3, Office of Director 2pp 20858 204 24X Fiche 50-546, 83/10/13, 8310210025

8310270395 Interim deficiency rpt re Westinghouse centrifugal charging pumps at min allowable flow rate when KLS reaches value below pressurizer safety valve setpoint pressure Initially reported on 800509 Also reported per Part 21
SHIELDS, S W Public Service Co of Indiana, Inc 83/10/20 KEPLER, J G Region 3, Office of Director 2pp 20924 034 24X Fiche 50-546, 83/10/20, 8310270395

8310270458 Interim deficiency rpt re welding techniques not covered by QA program used in fabrication of safety-related switchgear Initially reported on 820525 QA manual rewritten & procedures revised to include controls on welding
SHIELDS, S W Public Service Co of Indiana, Inc 83/10/20 KEPLER, J G Region 3, Office of Director 2pp 20923 109 24X Fiche 50-546, 83/10/20, 8310270458

DOCKET STN-50-553 PHIPPS BEND NUCLEAR STATION, UNIT 1

Q Adjudicatory correspondence

8310210177 Forwards Memorandum & Order ALAB-745, suggesting TVA file motion to terminate proceedings for canceled units
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/19 BURGER, J F Tennessee Valley Authority 1p 20856 127 24X Fiche 50-553, 83/10/19, 8310210177

DOCKET STN-50-554 PHIPPS BEND NUCLEAR STATION, UNIT 2

Q Adjudicatory correspondence

8310210177 Forwards Memorandum & Order ALAB-745, suggesting TVA file motion to terminate proceedings for canceled units
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/10/19 BURGER, J F Tennessee Valley Authority 1p 20856 127 24X Fiche 50-553, 83/10/19, 8310210177

DOCKET STN-50-556 BLACK FOX STATION, UNIT 1

Q Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

DOCKETED ITEMS

375

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

DOCKET STN-50-55/ BLACK FOX STATION, UNIT 2

G Inspection reports, IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Wulder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 57 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warnings:Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP , CANOGA PARK, CA

8310240225 Advises that Suppl 5 to AI-74-44, "SNM Control Program for EBR-II Blanket Fuel Decladding," acceptable sub; to listed confirmation All decladding operations conducted within Cells 3 & 4 will be performed under inert atmosphere.
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/08/25
REMLEY, M E Rockwell International Corp 2pp 20907 311.

8310170071 Forwards app to Suppl 5 of "SNM Control Program for EBR-II Blanket Fuel Decladding," per 830825 request App clarifies orally presented info W/o encl
* Rockwell International Corp 83/09/20 BROWN, W B Fuel Facility Safeguards Licensing Branch 1p 20798 018

8310120390 Memorandum & order terminating proceeding No responses to Commission 830602 order meet intervention requirements
NRC authorized to renew License SNM-21 when all regulatory requirements met
LAZD, R M Atomic Safety and Licensing Board Panel 83/10/07 App. 20699 113

DOCKET 70-0027 BABCOCK & WILCOX CO , LYNCHBURG, VA

8310240101 Revises License Condition 2 1 to Amend MPP-1 to License SNM-42 per 830429,0310,0608 & 0723 ltrs transmitting revised pages to fundamental nuclear matl control plan
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/07/28
REGAN, N A Babcock & Wilcox Co 1p 20891 355

8310170034 Application for amend to License SNM-42, Section IV re fundamental nuclear matls control plan. Encl restricted data withheld
* Babcock & Wilcox Co 83/08/03 BROWN, W B Fuel Facility Safeguards Licensing Branch 1p 20798 333

8310240088 Responds to 830721 ltr requesting time extension to complete requirements of 10CFR70 50(a)(4)(i) for May-June 1983 matl balance period License SNM-42 revised by adding new unnumbered license condition
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/08/04
REGAN, N A Babcock & Wilcox Co 1p 20891 362

8310240210 Grants 10-day extension to meet NRC requirements for preparation & distribution of Form DOE/NRC 741 New unnumbered license condition added to Safeguards Amend MPP-1 to License SNM-42 to reflect extension
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/08/18
REGAN, N A Babcock & Wilcox Co 1p 20907 319

8310270556 Advises that Safeguards Amend MPP-1 to License SNM-42 revised, adding new License Condition 2 1 1, effective immediately Amend incorporates new pages to fundamental nuclear matl control plan proposed in 830803 & 23 ltrs
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/08/24
REGAN, N A Babcock & Wilcox Co 1p 20943 352

8310170229 Advises that certain changes to physical security plan submitted on 830601 Changes do not decrease effectiveness of plan & were implemented per 10CFR70 32(e)
REGAN, N A Babcock & Wilcox Co 83/08/25 O'REILLY, J P Region 2, Office of Director 2pp 20796 284

8310170315 Advises that revised pages to safeguards contingency plan submitted on 830629 Changes do not decrease effectiveness of plan & were implemented per 10CFR70 32(e)
REGAN, N A Babcock & Wilcox Co 83/08/25 O'REILLY, J P Region 2, Office of Director 2pp 20795 278

8310040503 Forwards IE Safeguards Insp Rept 70-0027/83-15 on 830726-29. No noncompliance noted Rept withheld (ref 10CFR2 790)
STOHR, J P Division of Emergency Preparedness & Materials Safety 83/09/01 ECKERT, J P Babcock & Wilcox Co 2pp 20622 351.

8310170081 Forwards revised pages to License SNM-42 fundamental nuclear matls control plan, per 830824 approval of amend request
Encls withheld
* Babcock & Wilcox Co 83/09/02 BROWN, W B Fuel Facility Safeguards Licensing Branch 1p 21241.067

8310170727 Forwards Drawing LP-3239-88, inadvertently omitted from attachment to 830601 ltr re changes to security plan. Photo of site facility details also transmitted, W/o encls
REGAN, N A Babcock & Wilcox Co 83/09/08 Region 2, Office of Director 1p 20797 358

DOCKETED ITEMS

8310040487 Forwards IE Safeguards Insp Rept 70-0027/83-18 on 830823-26 No noncompliance noted
STOHR, J P Division of Emergency Preparedness & Materials Safety
83/09/14 ECKERT, J P Babcock & Wilcox Co 2pp 20622 348

--8310040493 IE Safeguards Insp Rept 70-0027/83-18 on 830823-26 No noncompliance noted Major areas inspected licensee action on previous findings & inventory differences & associated limit of error Details withheld (ref 10CFR2 790)
JONES, D W, MCALPINE, E J Region 2, Office of Director 83/09/14 1p 20622 350

8309200181 Ack receipt of 830401 ltr transmitting 830401 rev to physical security plan Rev transferred to Fuel Facility Safeguards Licensing Branch of NMSS
STOHR, J P Division of Emergency Preparedness & Materials Safety
83/09/16 ECKERT, J P Babcock & Wilcox Co 1p 20430 356

8310170065 Forwards revised pages of 830803 application for safeguards amend to License SNM-42, per request Rev replaces info submitted on 830902 Pages withheld (ref 10CFR2 790)
* Babcock & Wilcox Co 83/09/22 BROWN, W B Fuel Facility Safeguards Licensing Branch 1p 20748 028

8310170206 Forwards officer certificates for Licenses SNM-42, 145, 414, 778 & 1168 financially assuring payment for decommissioning costs of nuclear facilities, per GO Zipf 780313 commitment
JORDAN, L V Babcock & Wilcox Co 83/09/23 PAGE, R G Uranium Fuel Licensing Branch 5pp 20798 087

8310040464 Ack receipt of 830908 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0027/83-09
STOHR, J P Division of Emergency Preparedness & Materials Safety
83/09/26 ECKERT, J P Babcock & Wilcox Co 1p 20623 127

--8310040470 Responds to NRC 830811 ltr re violations noted in IE Insp Rept 70-0027/83-09 Corrective actions previous repts containing data from cellulose filter paper will be corrected & completed by 831030
ECKERT, J P Babcock & Wilcox Co 83/09/08 O'REILLY, J P Region 2, Office of Director 3pp 20623 128

--8310040486 Forwards IE Insp Rept 70-0027/83-09 on 830613-17 & notice of violation
STOHR, J P Division of Emergency Preparedness & Materials Safety
83/08/11 ECKERT, J P Babcock & Wilcox Co 2pp 20623 131

--8310040501 Notice of violation from insp on 830613-17
* Region 2, Office of Director 83/08/11 1p 20623 133

--8310040508 IE Insp Rept 70-0027/83-09 on 830613-17 Noncompliance noted failure to determine surface collection efficiency of recovery bldg stack air sampler filter media
KAME, J B Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/07/18 9pp 20623 134

8310200418 Application to amend License SNM-42, installing second phase of U fuel powder processing Rev 0 to Section V of license
encl
REGAN, N A Babcock & Wilcox Co 83/09/27, PAGE, R G Uranium Fuel Licensing Branch 23pp 20859 261

8310260433 Responds to 830822 ltr Authorization to deviate from certain provisions of approved physical protection plan granted allowing employees w/o DOE clearances to work within particular matl access area for limited time.
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/09/30
REGAN, N A Babcock & Wilcox Co 1p 20926 336

8310170239 Forwards IE Safeguards Insp Rept 70-0027/83-21 on 830920-23 No noncompliance noted
STOHR, J P Division of Emergency Preparedness & Materials Safety
83/10/11 ECKERT, J P Babcock & Wilcox Co 2pp 20787 102

--8310170246 IE Safeguards Insp Rept 70-0027/83-21 on 830920-23 No noncompliance noted Major areas inspected, site orientation, security plan & implementing procedures review & records & repts Details withheld (ref 10CFR2 790)
TILLMAN, A, MCQUIRE, D R Region 2, Office of Director 83/10/11 1p 20787 104

810260154 Ack receipt of 830802 & 31 ltrs informing NRC of steps taken to correct deviation noted in IE Safeguards Insp Rept 70-0027/83-11.
STOHR, J P Division of Emergency Preparedness & Materials Safety
1/10/12 ECKERT, J P Babcock & Wilcox Co 1p 20912 086

--8310260166 Clarifies 830802 response re audit performed during wk of 830613 All working stds used in calibr of well counters stored in tamper safe condition Direct cognizance means accountability personnel never lose sight of stds.
REGAN, N A Babcock & Wilcox Co 83/08/31 MCALPINE, E Region 2, Office of Director 2pp 20912 087

--8310260179 Responds to NRC 830713 ltr re deviation noted in IF Safeguards Insp Rept 70-0027/83-11 Corrective actions Std Operating Procedures E41-70 & E46-39 will be revised
ECKERT, J P Babcock & Wilcox Co 83/08/02 O'REILLY, J P Region 2, Office of Director 3pp 20912 089

DOCKET 70-0036 COMBUSTION ENGINEERING, INC, WINDSOR, CT

8310040359 Forwards IE Insp Rept 70-0036/83-03 on 830816-19 No noncompliance noted
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/09/16 LICHTENBERGER Combustion Engineering, Inc 2pp 20620 224

--8310040360 IE Insp Rept 70-0036/83-03 on 830816-19 No noncompliance noted Major areas inspected radiation protection, radwaste mgt, organization, criticality safety, audits, facility mods & emergency planning
GRANT, W B, SMITH, B W, GREGER, L R Region 3, Office of Director 83/09/15 7pp 20620 226

8310140181 Forwards addendum to IE Insp Rept 70-0036/83-01 re comparative results for samples collected & split during insp Results of analyses in Table I compared w/ 10CFR20 App B, Table II limits for natural U
PAPERIELLO, C J Region 3, Office of Director 83/10/11 LICHTENBERGER Combustion Engineering, Inc 2pp 20761 242

--8310140188 Addendum I to IE Insp Rept 70-0036/83-01 re confirmatory measurements program
* Region 3, Office of Director 83/04/15 1p 20761 243

DOCKET 70-0135 BABCOCK & WILCOX CO, APOLLO, PA

8310270989 Responds to 830310 ltr transmitting fundamental nuclear matl control plan for low enriched U decontamination activities & seven exemptions Sections J, D through B O of Safeguards Amend MPP-1 to License SNM-145 revised
BURNETT, R F Division of Safeguards 83/08/11 AUSTIN, M A Babcock & Wilcox Co 5pp 20946 262

8310270538 Responds to 830808 ltr transmitting fundamental nuclear matl control plan for low enriched U scrap recovery License Condition 2 1 3 of Safeguards Amend MPP-1 to License SNM-145 revised Plan withheld (ref 10CFR2 790)
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/08/26
AUSTIN, M A Babcock & Wilcox Co 1p 20938 034

8310120195 Forwards IE Safeguards Insp Rept 70-0135/83-06 on 830815-19 No noncompliance noted
HARTIN, T T Division of Engineering & Technical Programs 83/09/14 COLEMAN, W L Babcock & Wilcox Co 2pp 20692 223

--8310120201 IE Safeguards Insp Rept 70-0135/83-06 on 830815-19 No noncompliance noted Major areas inspected shipper/receiver & inventory verification
WOLTER, E, GUDY, A T Region 1, Office of Director 83/09/14 2pp 20692 225

8310170206 Forwards officer certificates for Licenses SNM-42, 145, 414, 778 & 1168 financially assuring payment for decommissioning costs of nuclear facilities, per GO Zipf 780313 commitment
JORDAN, L V Babcock & Wilcox Co 83/09/23 PAGE, R G Uranium Fuel Licensing Branch 5pp 20798 087

DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC, ERWIN, TN

8310240074 Responds to 830624 request re extension for submittal of physical inventory reft required under License Condition 3 4 of Safeguards Amend MPP-1 Request granted New license condition issued
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/07/11
HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co) 1p 20903 214

8310240089 Responds to 830719 request for 31-day extension for completing 10CFR70 51(e)(4) requirements for 830623 high enriched U physical inventory Request granted
BURNETT, R F Fuel Facility Safeguards Licensing Branch 83/07/26
HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co) 3pp 20891 359

DOCKETED ITEMS

381

8310240214 Advises that Rev 13 to physical safeguards plan dtd 830805 approved & incorporated
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/08/08
HENSLEY, K Nuclear Fuel Services, Inc (subs of Getty Oil Co)
lp 20707 318

8310070254 Forwards IE Safeguards Insp Rept 70-0143/83-30 on 830712-15 & notice of violation Notice of violation & insp rept details withheld (ref 10CFR73 21)
STOHR, J P Division of Emergency Preparedness & Materials Safety
83/08/12 QUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 20656 360

--8310070259 IE Safeguards Insp Rept 70-0143/83-30 on 830712-15 Noncompliance noted inadequate Procedure 83-30-010 Details withheld (ref 10CFR73 21)
TOBIN, W J Region 2, Office of Director MCQUIRE, D R Division of Emergency Preparedness & Materials Safety 83/08/12 lp 20656 362

8310240231 Approves 830805 request for rev to Safeguards License Condition 2 7(4) increasing allowed amount of combustible waste on 830623 physical inventory to 2 5 kg U
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/08/12
HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co)
lp 20707 305

8310170036 Forwards Rev 7 to interim security measures implemented 820731 Attachments III & IV revised to extend completion date of uninterruptable power supply sys & to update upgrade items Incorporation requested Encl withheld
HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co)
83/08/26 BROWN, W B Division of Safeguards lp 20798 332

8310170299 Application for amend to License BNM-124 deleting Conditions 61 & 67 Ventilation upgrade project complete & monthly status rept required by Condition 6/ unnecessary Amend Fee encl
DEKER, R L Nuclear Fuel Services, Inc (subs of Getty Oil Co)
83/08/29 PAGE, R G Uranium Fuel Licensing Branch 3pp 20796 239

8310040190 Forwards IE Insp Rept 70-0143/83-34 on 830816-19 No noncompliance noted
STOHR, J P Division of Emergency Preparedness & Materials Safety
83/09/08 QUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) lp 20608 272

--8310040197 IE Insp Rept 70-0143/83-34 on 830816-19 No noncompliance noted Major areas inspected facility changes & mods, safety committees, procedure control, operations, nuclear criticality safety & LER Followup
CORVELL, G P Region 2, Office of Director MCALPINE, E J Division of Emergency Preparedness & Materials Safety 83/09/07 5pp 20608 273

8310110164 Ack receipt of 830629 ltr forwarding Rev 5 to site security training plan Changes inconsistent w/provisions of 10CFR70 32(c) encl Encl withheld (ref 10CFR73 21)
STOHR, J P Division of Emergency Preparedness & Materials Safety
83/09/14 QUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 20666 236

8310110181 Ack receipt of 830630 ltr forwarding Rev 12 to physical safeguards plan One portion inconsistent w/10CFR70 32(e) Comments provided for mod of plan W/o encl
STOHR, J P Division of Emergency Preparedness & Materials Safety
83/09/14 QUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) lp 20665 014

8310040346 Ack receipt of 830809 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-0143/83-23
STOHR, J P Division of Emergency Preparedness & Materials Safety
83/09/20 QUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) lp 20617 291

--8310040350 Responds to NRC 830713 ltr re violation noted in IE Insp Rept 70-0143/83-23 Corrective actions incoming make-up air reduced on 830517 & differential pressure gauges installed
QUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co)
83/08/09 STOHR, J P Division of Emergency Preparedness & Materials Safety 3pp 20617 292

8310040303 Ack receipt of 830624 & 0729 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/83-17
STOHR, J P Division of Emergency Preparedness & Materials Safety
83/09/21 QUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) lp 20620 338

--8310040309 Notifies that corrective actions stated in 830624 & 0729 ltrs re violation noted in IE Insp Rept 70-0143/83-17 re training of hourly personnel Inaccurate Training will begin on 830912
QUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co)
83/09/09 STOHR, J P Division of Emergency Preparedness & Materials Safety lp 20620 339

--8310040312 Forwards IE Insp Rept 70-0143/83-17 on 830418-22 & notice of violation
STOHR, J P Division of Emergency Preparedness & Materials Safety
83/05/25 MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 20620 349

--8310040314 Notice of violation from insp on 830418-22
* Region 2, Office of Director 83/05/25 2pp 20620 351

--8310040340 IE Insp Rept 70-0143/83-17 on 830418-22 Noncompliance noted contrary to licenser procedure, personnel crossed yellow barricade lines into control areas & out again, w/o donning white shoe covers
KAHLE, J B Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/05/19 10pp. 20620 353

8310050471 Ack receipt of 830727 & 0831 ltrs informing NRC of steps taken to correct violation noted in IE Safeguards Insp Rept 70-0143/83-22
STOHR, J P Division of Emergency Preparedness & Materials Safety
83/09/21 QUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) lp 20632 346

--8310050473 Forwards proprietary supplemental response to NRC 830630 ltr re violation noted in IE Safeguards Insp Rept 70-0143/83-22 Encl withheld (ref 10CFR2 790)
QUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co)
83/08/31 STOHR, J P Division of Emergency Preparedness & Materials Safety lp 20632 347

8310170737 Application for Amend MPP-1 to License BNM-124 Amend withheld (ref 10CFR2 790)
HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co)
83/09/22 BROWN, W R Division of Safeguards lp 20796 361

8310170680 Confirms 830908 telcon re liquid found in Bldg 303 furnace pit Drain line unplugged & coolant water spill cleaned up by production personnel Pitch of trough changed to divert future water overflows
QUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co)
83/09/26 O'REILLY, J P Region 2, Office of Director 3pp 20798 221

8310270571 Grants 830922 request for 19-day extension for completing certain requirements of 10CFR70 31(e)(4) for 830826 high enriched U physical inventory New unnumbered license condition to Amend MPP-1 issued effective immediately
BURNETT, R F Division of Safeguards 83/09/26 HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co) lp 20946 255

8310190290 Ack receipt of IE Insp Rept 70-0143/83-22 dtd 830831 No proprietary info
QUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co).
83/09/27 STOHR, J P Division of Emergency Preparedness & Materials Safety lp 20842 032

8310250500 Ack receipt of 830908 ltr forwarding IE Insp Rept 70-0143/83-34 No proprietary info
QUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co)
83/09/27 STOHR, J P Division of Engineering & Operational Programs lp 20902 085

8310050527 Ack receipt of 830805 & 0909 ltrs informing NRC of steps taken to correct violation noted in IE Safeguards Insp Rept 70-0143/83-23
STOHR, J P Division of Emergency Preparedness & Materials Safety.
83/09/29 QUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) lp 20632-266

--8310050535 Forwards proprietary supplemental response to NRC 830713 ltr re violation noted in IE Safeguards Insp Rept 70-0143/83-23 Encl withheld (ref 10CFR2 790)
QUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co)
83/09/09 STOHR, J P Division of Emergency Preparedness & Materials Safety lp 20632-267

8310170724 Forwards Rev 8 to interim security measures implemented on 820731 Implementation revised to extend completion dates of uninterruptable power supply sys & controlled access areas Incorporation of pages requested W/o encl
HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co)
83/09/29 BROWN, W B Fuel Facility Safeguards Licensing Branch lp 20798 094

DOCKETED ITEMS

8310060079 RADIOLOGICAL SURVEY OF THE NUCLEAR FUEL SERVICES, INC ERWIN
PLANT BURIAL SITE
BQTH, L F , NYERGES, P L , GROFF, D W Radiation Management Corp FIN
8-6901 NUREG/CR-3486 83/09/30 Division of Fuel Cycle &
Material Safety 54pp 20664 001

8310070139 Ack receipt of 830914 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 70-0143/83-30
STOHR, J P Division of Emergency Preparedness & Materials Safety
83/10/04 GUINN, F K Nuclear Fuel Services, Inc (subs of Getty
Oil Co) 1p 20657 082

--8310070145 Responds to NRC 830812 ltr re violations noted in IE Insp
Rept 70-0143/83-30 Corrective actions withheld
GUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co)
83/09/14, STOHR, J P Division of Emergency Preparedness &
Materials Safety 1p 20657.083

8310260097 Forwards proprietary IE Safeguards Insp Rept 70-0143/83-35
on 830815-26 No noncompliance noted Rept withheld (ref
10CFR2 790)
STOHR, J P Division of Emergency Preparedness & Materials Safety
83/10/04 GUINN, F K Nuclear Fuel Services, Inc. (subs of Getty
Oil Co) 2pp 20912 095

8310180011 Advises of issuance of Amend 22 to License SNM-124, revising
groundwater monitoring program, per 821015 & 830603
applications SER approving amend encl
PAGE, R G Uranium Fuel Licensing Branch 83/10/05 IDEKER, R.
Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp
20825 068

--8310180015 Safety evaluation supporting licensee 821015 & 830603
applications for amend to License SNM-124 to implement
proposed groundwater monitoring program
WYNARDEN, S D , CROW, W T Uranium Fuel Licensing Branch
83/10/05 4pp 20825 070

8310170691 Advises of issuance of Amend 23 to License SNM-124,
incorporating changes in organizational structures
PAGE, R G Uranium Fuel Licensing Branch 83/10/06 IDEKER, R
Nuclear Fuel Services, Inc (subs of Getty Oil Co) 1p.
20798 163

--8310170693 Safety evaluation supporting issuance of Amend 23 to
License SNM-124
SDONO, A L , CROW, W T Uranium Fuel Licensing Branch 83/10/06
2pp. 20798 164

8310250336 Ack receipt of 830914 ltr informing NRC of steps taken to
correct violation noted in IE Insp Rept 70-0143/83-28
O'REILLY, J P Region 2, Office of Director 83/10/06 GUINN, F K
Nuclear Fuel Services, Inc (subs of Getty Oil Co) 1p
20898 054

--8310250340 Responds to NRC 830817 ltr re violation noted in IE Insp
Rept 70-0143/83-28 Corrective actions procedures involved
in packaging & loading waste shipment reviewed Procedure
NFB-HB-A-23 issued
GUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co)
83/09/14 O'REILLY, J P Region 2, Office of Director 3pp
20898 055

--8310250344 Forwards IE Insp Rept 70-0143/83-28 on 830627-30 & notice of
violation
O'REILLY, J P Region 2, Office of Director 83/08/17 GUINN, F K
Nuclear Fuel Services, Inc. (subs of Getty Oil Co) 2pp
20898 058.

--8310250347 Notice of violation from insp on 830627-30
* Region 2, Office of Director 83/08/17 2pp. 20898 060

--8310250352 IE Insp Rept 70-0143/83-28 on 830627-30 Noncompliance noted
failure to provide reviewed & approved procedure for air
particle site measurements & waste shipment in violation of
DOT regulations
CUNNINGHAM, A L , TROUP, O L Region 2, Office of Director
MONTGOMERY, D M Division of Engineering & Operational Programs
83/08/09. 8pp 20898.062

1310260029 Approves Rev B to interim security measures submitted in
830929 ltr Physical security plan scheduled revs acceptable.
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/09/30
HENSLEY, K Nuclear Fuel Services, Inc. (subs of Getty Oil Co).
1p 20921 357.

DOCKET 70-0364 BABCOCK & WILCOX CO , APOLLO, PA

8310270564 Advises of rev to Amend MPP-1 to License SNM-414, deleting
Section 7, physical protection requirements, in entirety,
effective immediately (ref 830307 ltr)
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/08/31
AUSTIN, M A Babcock & Wilcox Co 1p 20943 354

8310070016 Forwards Amend 20 to License SNM-414, revising Spec 1-1 to
reflect reduction in quantity of SNM held at facility &
changing Condition 10 to authorize use of U-235 as calibr or
ref sources
GREENMAN, E G Division of Project & Resident Programs 83/09/27
AUSTIN, M A Babcock & Wilcox Co 2pp 20674 344

--8310070024 Safety evaluation supporting Amend 20 to License SNM-414
List of effective pages to Section 1 of BAW application
encl
* NRC - No Detailed Affiliation Given 83/09/23 4pp
20674 346

--8310070027 Amend 20 to License SNM-414, revising Spec 1-1 to reflect
reduction in quantity of SNM held at facility & changing
Condition 10 to authorize use of U-235 as calibr or ref
sources
GREENMAN, E G Division of Project & Resident Programs 83/09/06
3pp 20674 350

--8310070028 Forwards revised Page 1 B 1 0 to License SNM-414 to replace
page submitted in 830630 transmittal, per 830712 telcon Encl
page more accurately reflects matl possession limits at
facility
AUSTIN, M A Babcock & Wilcox Co 83/07/13 ROTH, J Region 1,
Office of Director 1p 20674 353

--8310070032 Proposed Page 1 B 1 0 to License SNM-414, reflecting matl
possession limits
* Babcock & Wilcox Co 83/06/30 1p 20674 354

--8310070035 Requests Condition 10 of License SNM-414 be changed to
authorize use of Items R & S at Pu plant & Items Q, R & S at
metals & hafnium complex Request should be included w/830409
application Revised pages of Spec 1 to license encl
AUSTIN, M A Babcock & Wilcox Co 83/06/30 Region 1, Office of
Director 1p 20674 355

--8310070038 Proposed Pages 1 B 1 0 & 1 B 1 0(a) to Spec 1 of License
SNM-414, permitting use of Items R & S at Pu plant & Items Q,
R & S at metals & hafnium complex
* Babcock & Wilcox Co 83/06/30 2pp 20674 356

--8310070040 Requests reduction in possession limits of matls authorized
under License SNM-414 Reduction will permit disconnection of
criticality monitoring sys at Pu & Type II facilities
Affected Page 1 B 1 0 of Spec 1-1 encl
AUSTIN, M A Babcock & Wilcox Co 83/04/08 ROUSE, L C Advanced
Fuel & Spent Fuel Licensing Branch 1p 20674 358

--8310070042 Proposed Page 1 B 1 0 of Spec 1-1 to License SNM-414,
reducing possession limits for Pu & U-235
* Babcock & Wilcox Co 83/04/08 1p 20674 359

8310170206 Forwards officer certificates for Licenses SNM-42, 145, 414,
778 & 1168 financially assuring payment for decommissioning
costs of nuclear facilities, per 80 Zlpf 780313 commitment
JORDAN, L V Babcock & Wilcox Co 83/09/23 PAGE, R G Uranium Fuel
Licensing Branch 5pp 20798 087

DOCKET 70-0371 UNC NAVAL PRODUCTS, INC , UNCASVILLE, CT

8310270515 Responds to 830808 request for 1-wk extension to complete
U & isotopic content assay & rept Amend MPP-1 to License
SNM-36B issued, extending rept due date until 830812
BURNETT, R F Division of Safeguards 83/08/19 KIRK, W F United
Nuclear Corp 1p 20928 360

8310170083 Forwards status rept for Aug 1983 re progress of final const
item listed in Chapter 13 of physical protection plan Rept
withheld
GUSTAFSON, R B United Nuclear Corp 83/09/01 BROWN, W B Fuel
Facility Safeguards Licensing Branch 1p 20798 005

831010599 Forwards comments on & request for addl info re application
for renewal of License SNM-36B License conditions in current
license & amends should be incorporated into license renewal
application Info due in 60 days
BIDINGER, O H Uranium Fuel Licensing Branch 83/10/03 KIRK, W F
United Nuclear Corp 12pp 20704 318

DOCKETED ITEMS

38

8310270164 Forwards IE Safeguards Insp Rept 70-0371/83-10 on 830913-16 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/10/13
AMY, G D United Nuclear Corp 2pp 20925 005

--8310270169 Notice of violation from insp on 830913-16
* Region 1, Office of Director 83/10/13 1p 20925 007

--8310270178 IE Safeguards Insp Rept 70-0371/83-10 on 830913-16
Noncompliance noted failure of security personnel to take annual requalification exam
SMITH, G C, DUNLAP, J M Region 1, Office of Director GDDY, A T
Division of Engineering & Technical Programs 83/10/11 5pp
20925 008

DOCKET 70-0474 UPSALA COLLEGE, EAST ORANGE, NJ

8310310337 Discusses IE Insp Rept 70-0474/83-01 conducted on 830922 No noncompliance noted Major areas inspected selective exams of procedures & representative records, interviews w/personnel, measurement & observations by inspector
MARTIN, T T Division of Engineering & Technical Programs 83/10/24
FELDER, R Upsala College 2pp 20961 323

DOCKET 70-0572 MONSANTO RESEARCH CORP, DAYTON, OH

8310120279 Forwards IE Insp Rept 70-0572/03-01 on 830815-19 & notice of violation
SRENIANSKI, D J Region 3, Office of Director 83/10/07
SCHIMMEL, R L Monsanto Research Corp 2pp 20691 016

--8310120283 Notice of violation from insp on 830815-19
SRENIANSKI, D J Region 3, Office of Director 83/10/06 2pp
20691 018

--8310120288 IE Insp Rept 70-0572/83-01 on 830815-19 Noncompliance noted failure to perform adequate personnel surveys & failure to provide fire extinguisher in each glove box
SLAWINSKI, W J, CANIANO, R, SRENIANSKI, D J Region 3, Office of Director 83/10/06 20pp 20691 020

--8310120292 Forwards rept of 830425 contamination event, in compliance w/10CFR20 404(a)(5)
HODDLEY, S D Monsanto Research Corp 83/05/06 Region 3,
Office of Director 3pp 20691 040

DOCKET 70-0698 WESTINGHOUSE ELECTRIC CORP, PITTSBURGH, PA

8310170197 Forwards "Groundwater Monitoring Samples at Waltz Mill Site," Quarterly Rept 3
QALM, D T Westinghouse Electric Corp 83/09/23 MURLEY, I Region 1, Office of Director 2pp 20812 340

--8310170203 "Groundwater Monitoring Samples at Waltz Mill Site," Quarterly Rept 3
* Westinghouse Electric Corp 83/08/23 24pp 20812 342

DOCKET 70-0734 QA TECHNOLOGIES, INC, SAN DIEGO, CA

8310180217 Forwards IE Safeguards Insp Rept 70-0734/83-10 on 830825-26, 0919-23 & 26-30 No noncompliance noted Rept withheld (ref 10CFR73 21)
NORDERHAUG, L R Region 5, Office of Director 83/10/11
PARKER, J W QA Technologies, Inc /General Atomic Co 2pp 20808 307

8310180120 Forwards IE Safeguards Insp Rept 70-0734/83-12 on 830829-0901 No noncompliance noted
NORDERHAUG, L R Region 5, Office of Director 83/10/12
PARKER, J W QA Technologies, Inc /General Atomic Co 2pp 20808 171

--8310180123 IE Safeguards Insp Rept 70-0734/83-12 on 830829-0901 No noncompliance noted Major areas inspected measurement controls, shipper-receiver verification & inventory difference Details withheld (ref 10CFR2 790)
NELSON, G B, NORDERHAUG, L R Region 5, Office of Director 83/10/11 1p 20808 173

8310310258 PNB-V-83-010 on 830912, latest bimonthly physical inventory indicated difference (ID gain) occurred in high enriched U HTOR fuel mfg area Past IDs did not exceed limit of error Current gain reduces cumulative ID by one half
WIEDER, A V, NELSON, G B Region 5, Office of Director 83/10/20
2pp 20947 160

DOCKET 70 0754 GENERAL ELECTRIC CO, PLEASANTON, CA

8310120372 Memorandum & order granting J Turk 830915 request for 60-day extension of deadline for filing appeals to contentions & petition
FRYE, J H Atomic Safety and Licensing Board Panel 83/10/07
TURK, J Turk, J 1p 20697 253 24X Fiche 50-070, 83/10/07, 8310120372

DOCKET 70-0820 UNITED NUCLEAR CORP, WOOD RIVER JUNCTION, RI

8310170030 Quarterly progress rept for Contract NRC-02-B0-076 re calibr of flow & containment transport model
WARNER, D L Don L Warner, Inc NRC-02-B0-076 83/09/21
WYNGARDEN, S D Office of Nuclear Material Safety & Safeguards, Director 2pp 20798 342

8310200163 Forwards IE Insp Rept 70-0820/83-07 on 830822-26 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/09/30
AMY, G D United Nuclear Corp 2pp 20834 080

--8310200169 IE Insp Rept 70-0820/83-07 on 830822-26 No noncompliance noted Major areas inspected in-ofc insp to follow confirmatory survey of licensee decommissioned facility.
ROTH, J J Region 1, Office of Director ELBASSER, T C Division of Project & Resident Programs 83/09/28 5pp. 20834.082

8310250440 Ack receipt of 830913 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0820/83-04.
MARTIN, T T Division of Engineering & Technical Programs 83/10/18
AMY, G D United Nuclear Corp 1p 20897 105

--8310250445 Forwards response to NRC 830822 ltr re violations noted in IE Insp Rept 70-0820/83-04 Corrective actions entries for documents made in general ledger Matl status repts submitted
OREGO, R J United Nuclear Corp 83/09/13 MARTIN, T T Division of Engineering & Technical Programs 2pp 20897 106

DOCKET 70-0824 BABCOCK & WILCOX CO, LYNCHBURG, VA

8310240228 Documents branch position re investigation & corrective action necessary to reconcile shipper/receiver differences involving U element weight investigation & corrective action must consider weight, U & isotopic assay
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/08/16
OLSEN, A F Babcock & Wilcox Co 1p 20907 308

8310270562 Advises that Safeguards Amend MPP-1 to License SNM-778 amended by deleting Sections 1 through 8, effective 830811 Amend due to reduction of possession limit of U & Pu to less than 1 effective kg
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/08/19
OLSEN, A F Babcock & Wilcox Co 1p 20943 353

8310170730 Forwards 10CFR70 32(e) rev to Bldg C security plan, reflecting administrative changes Rev withheld (ref 10CFR2 790)
OLSEN, A F Babcock & Wilcox Co 83/09/19 Division of Safeguards 1p 20797 335

8310170206 Forwards officer certificates for Licenses SNM-42, 145, 414, 778 & 1168 financially assuring payment for decommissioning costs of nuclear facilities, per QQ Zipf 780313 commitment
JORDAN, L V Babcock & Wilcox Co 83/09/23 PAGE, R G Uranium Fuel Licensing Branch 5pp 20798 087

8310040337 Forwards IE Safeguards Insp Rept 70-0824/83-05 on 830824-26 No noncompliance noted
STOHR, J P Division of Emergency Preparedness & Materials Safety 83/09/29, ENGELDER, T C Babcock & Wilcox Co 2pp. 20620-335

--8310040342 IE Safeguards Insp Rept 70-0824/83-05 on 830824-26 No noncompliance noted Major areas inspected facility organization & operation, measurements & statistical controls Details withheld (ref 10CFR2 790)
BATES, J W, SABADOS, J W Region 2, Office of Director MCALPINE, E J Division of Emergency Preparedness & Materials Safety 83/09/27 1p 20620 337

DOCKETED ITEMS

DOCKET 70-0984 BATTELLE MEMORIAL INSTITUTE, RICHLAND, WA

8310170649 Forwards revised pages to Manual PNL-MA-11, "Emergency Preparedness," for insertion
Koyama, E Battelle Memorial Institute, Pacific Northwest Laboratory
83/08/29 Battelle Memorial Institute, Pacific Northwest Laboratory 2pp 20798 223

--8310170675 Manual PNL-MA-11, "Emergency Preparedness"
ASHUND, V C Battelle Memorial Institute, Pacific Northwest Laboratory 83/08/22 104pp 20798 224

DOCKET 70-1100 COMBUSTION ENGINEERING, INC, WINDSOR, CT

8310270494 Confirms verbal consent to use of CE-Windsor license paper format in preparing design info questionnaire License Condition 2.4 added to Amend MPP-4 to License SNM-1067, granting exemption from 10CFR25 11(d)
BURNETT, R F Division of Safeguards 83/08/31 LICHTENBERGER Combustion Engineering, Inc 1p 20938 101

8310190215 Application for amend to License SNM-1067 to renew license for 5 yrs & to make administrative changes
LICHTENBERGER Combustion Engineering, Inc 83/09/16 PAGE, R G Uranium Fuel Licensing Branch 96pp 20838 108

8310120082 Forwards IE Insp Repts 70-1100/83-03 & 30-03754/83-01 on 830718-21 & notice of deviation
STAROSTECKI, R Division of Project & Resident Programs 83/09/19 LICHTENBERGER Combustion Engineering, Inc 2pp 20697 142

--8310120085 Notice of deviation from insp on 830718-21
* Region 1, Office of Director 83/09/19 1p 20697 144

--8310120088 IE Insp Repts 70-1100/83-03 & 30-03754/83-01 on 830718-21 Noncompliance noted failure to properly handle breathing zone sampler head filter paper w/clean gloves
ROTH, J Region 1, Office of Director, ELSSASSER, T C Division of Project & Resident Programs 83/08/12 10pp 20697.145

8310070211 Discusses items of interest Meeting held on 830921 w/C-E in Windsor, CT re C-E proposed license amend application to modify air sampling sys On 830915, NRC concurred in DDE remedial action plan for Canonsburg, PA site
PAGE, R G Uranium Fuel Licensing Branch 83/09/22 DAVIS, J Q Office of Nuclear Material Safety & Safeguards, Director 1p 20679 353

8310110441 Summary of 830915 & 21 meetings w/DOE & C-E re remedial action plan & proposed license amend application concerning mod of air sampling sys in Windsor plant, respectively
PAGE, R G Uranium Fuel Licensing Branch, 83/09/22 DAVIS, J Q Office of Nuclear Material Safety & Safeguards, Director 1p 20714 341

8310190192 Forwards MA Elmaghribi resume to be included in 830916 application for amend to License SNM-1067
LICHTENBERGER Combustion Engineering, Inc 83/10/03 PAGE, R G Uranium Fuel Licensing Branch 3pp 20838 094

8310180027 Forwards page changes to 830916 application for amend to License SNM-1067
LICHTENBERGER Combustion Engineering, Inc 83/10/05 PAGE, R G Uranium Fuel Licensing Branch 1p 20825 049

--8310180031 Page changes to 830916 application for amend to License SNM-1067
* Combustion Engineering, Inc 83/10/05 3pp. 20825 050

8310240082 Forwards IE Safeguards Insp Rept 70-1100/83-04 on 830906-09 No noncompliance noted
MARTIN, T T, Division of Engineering & Technical Programs 83/10/07 LICHTENBERGER Combustion Engineering, Inc 2pp 20881 017

--8310240085 IE Safeguards Insp Rept 70-1100/83-04 on 830906-09 No noncompliance noted Major areas inspected: measurement control program & inventory difference & associated limit of error verification.
ZIBULSKY, H, SANBORN, J, GODY, A T. Region 1, Office of Director 83/10/07 3pp 20881-019.

8310310282 Ack receipt of ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-1100/83-03 & 30-03754/83-01.
STAROSTECKI, R Division of Project & Resident Programs 83/10/20 LICHTENBERGER Combustion Engineering, Inc 1p 20957 084

--8310310287 Responds to NRC 830919 ltr re violations noted in IE Insp Repts 70-1100/83-03 & 30-03754/83-01 Corrective actions applicable personnel re-instructed in proper use of breathing zone air sampler devices
LICHTENBERGER Combustion Engineering, Inc 83/10/31 STAROSTECKI, R Division of Project & Resident Programs 2pp 20957 085

DOCKET 70-1113 GENERAL ELECTRIC CO, WILMINGTON, NC

8310170249 Application for amend to License SNM-1097 to include storage of waste boxes prepared for shipment in site warehouse
Details encl
VAUGHAN, C M General Electric Co 83/08/17 CROW, W T Uranium Fuel Licensing Branch 4pp 20796 267

--8310170253 Ack receipt of 830817 payment re rev to License Condition 10 to License SNM-1097
WEISS, D J Uranium Fuel Licensing Branch 83/09/13 VAUGHAN, C M General Electric Co 2pp 20796 271

8310170051 Request for amend to License SNM-1097 authorizing receipt of SNM under special conditions on one-time basis Encl withheld (ref 10CFR2 790)
VAUGHAN, C M General Electric Co 83/09/23 BROWN, W D Fuel Facility Safeguards Licensing Branch 1p 20798 040

8310250547 Forwards IE Insp Rept 70-1113/83-24 on 830822-26 No noncompliance noted
STOHR, J P Division of Emergency Preparedness & Materials Safety 83/09/26 LONG, J A General Electric Co 2pp 20901 001

--8310250554 IE Insp Rept 70-1113/83-24 on 830822-26 No noncompliance noted Major areas inspected: calibr & use of instruments, external exposure control, posting, labeling & control of radiological areas
HOSEY, C M Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/09/14 7pp 20901 007

8310130225 Forwards Chapters 15 & 16 to license renewal application document dtd 830725
VAUGHAN, C M General Electric Co 83/09/30 CROW, W T Office of Nuclear Material Safety & Safeguards, Director 11pp 20754 191

--8310130228 Chapters 15 & 16 to 830725 license renewal application
* General Electric Co 83/09/30 122pp 20754 203

8310240226 Grants 830923 request to receive low enriched U under special conditions, on one time basis Two unnumbered license conditions added to Amend MPP-3 to License SNM-1097, effective immediately
BURNETT, R F Division of Safeguards 83/09/30 VAUGHAN, C M General Electric Co 2pp 20907 309

8310170155 Forwards Rev 1 to Chapter 6 of 830725 application for amend to License SNM-1097
VAUGHAN, C M General Electric Co 83/10/03 CROW, W T Office of Nuclear Material Safety & Safeguards, Director 1p 20813 037

--8310170158 Rev 1 to Chapter 6 of 830725 application for amend to License SNM-1097
* General Electric Co 83/10/03 6pp 20813 053

8310250427 Ack receipt of IE Insp Rept 70-1113/83-24 on 830822-26 No proprietary info
VAUGHAN, C M General Electric Co 83/10/03 STOHR, J P Division of Emergency Preparedness & Materials Safety 1p 20897.181

8310260190 Forwards IE Safeguards Insp Rept 70-1113/83-27 on 830913-16 No noncompliance noted
STOHR, J P Division of Emergency Preparedness & Materials Safety 83/10/05 LONG, J A General Electric Co 2pp 20912 103

--8310260194 IE Safeguards Insp Rept 70-1113/83-27 on 830913-16 No noncompliance noted Major areas inspected: measurement & statistical control & followup on previous insp findings
Details withheld (ref 10CFR2 790)
SABADOS, J W Region 2, Office of Director MCALPINE, E J Division of Emergency Preparedness & Materials Safety 83/10/05 1p 20912-105.

8310260215 Forwards IE Safeguards Insp Rept 70-1113/83-23 on 830906-00 No noncompliance noted
STOHR, J P Division of Emergency Preparedness & Materials Safety 83/10/05 LONG, J A General Electric Co 2pp 20912 077

DOCKETED ITEMS

385

--8310260221 IE Safeguards Insp Rept 70-1113/83-23 on 830906-08 No noncompliance noted Major areas inspected review of licensee approved physical security plan for LNM of low strategic significance Details withheld (ref 10CFR2 790)
ENNIS, J D , McGuire, D R Division of Emergency Preparedness & Materials Safety 83/10/04 1p 20912 094

8310260297 Ack receipt of 830907 ltr informing NRC of steps taken to correct violations noted in IL Safeguards Insp Rept 70-1113/83-21
STOHR, J P Division of Engineering & Operational Programs 83/10/05 LONG, J A General Electric Co 1p 20909 222

--8310260307 Responds to NRC 830816 ltr re violations noted in IE Safeguards Insp Rept 70-1113/83-21 Corrective actions withheld (ref 10CFR2 790)
VAUGHAN, C M General Electric Co 83/09/09 STOHR, J P Division of Engineering & Operational Programs 1p 20909 223

DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA

8310260045 Forwards Rev 1 to "Final Survey Results from Decommissioning Bldg 7 Westinghouse-NFD U Oxide Lab," per requirements of License Condition 20
NARDI, A J Westinghouse Electric Corp 83/09/22 MURLEY, T I Region 1, Office of Director 1p 20928 053

--8310260054 Rev 1 to "Final Survey Results from Decommissioning Bldg 7 Westinghouse-NFD U Oxide Lab "
* Westinghouse Electric Corp 83/09/30 19pp 20928 054

8310240248 Forwards "Final Survey Results of Decontamination of Pu Fuels Development Lab "
NARDI, A J Westinghouse Electric Corp 83/10/04. MURLEY, T E Region 1, Office of Director 1p 20905 001

--8310240250 "Final Survey Results of Decontamination of Pu Fuels Development Lab "
* Westinghouse Electric Corp 83/10/31 749pp 20905 002

DOCKET 70-1144 OHMART CORP , CINCINNATI, OH

8310260019 Responds to FOIA request for matl re Ohmart Corp on & offsite radiation-related incidents Forwards App A documents App B documents partially withheld (ref FOIA Exemptions 6 & 7)
FELTON, J M Division of Rules and Records 83/07/15 CARPENTER, T Cincinnati Alliance for Responsible Energy 10pp 20927 002

--8310260119 Submits matter to be reviewed re high film badge exposure reported in Ohmart 750122 ltr
NDRELIUS, C E Region 3, Chicago, Office of the Director, 75/01/27 Region 3, Chicago, Office of the Director 1p 20927 095

--8310260128 Submits matter to be reviewed during next insp re high film badge exposure per Ohmart Corp 750430 ltr
* Region 3, Chicago, Office of the Director 75/02/26 Region 3, Chicago, Office of the Director 1p 20927 093

--8310260146 Responds to 770811 ltr re calculated dose received by personnel from Oct 1976 - Mar 1977, training program & source handling procedures Trainees will be suby to verbal exam
COOK, H L Ohmart Corp 77/05/26 THOMPSON, D Office of Inspection & Enforcement, Office of the Director 3pp 20927.114

--8310260149 Suppls 770414, 0512 & 26 ltrs re noncompliance concerning handling unshielded sources & exposure of individuals to radiation Info deleted
COOK, H L Ohmart Corp 77/06/17 THOMPSON, D Office of Inspection & Enforcement, Office of the Director 24pp 20927 117

--8310260165 Ack receipt of 721023 ltr informing AEC of steps taken to correct items of noncompliance noted in insp of Licenses 34-00639-01, 34-00639-030 & SNM-1091
GRIER, B H Region 3, Chicago, Office of the Director 72/11/02, KELLY, G A Ohmart Corp 1p 20927 181

--8310260250 IE Insp Repts 70-1144/77-01, 30-05634/77-01 & 30-05635/77-01 on 770330-0401 & 11-12 Noncompliance noted individual received overexposure while handling licensed matl & no evaluation made of extremity exposure
SCHULTZ, W H, PHILLIP, G A, LONERGAN, O. T. Region 3, Chicago, Office of the Director 77/05/04 17pp 20927 273.

--8310260265 Discusses IE Insp Repts 70-1144/77-01, 30-05634/77-01 & 30-05635/77-01 on 770330-0401 & 11-12 Ltr & insp rept will be placed in PDR unless licensee believes portions are proprietary & should be withheld
KEPLER, J G Region 3, Chicago, Office of the Director 77/05/17 COOK, H L Ohmart Corp 2pp 20927 292

--8310260287 Discusses insp of Licenses SNM-1091, 34-00639-01 & 34-00639-030 on 770330-0401 & 11-12 & forwards notice of violation
THOMPSON, D Office of Inspection & Enforcement, Office of the Director 77/05/11 COOK, P L Ohmart Corp 3pp 20927 318

DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA

8310240224 Discusses concerns re nondestructive assay of solid waste contained in large wooden boxes, reliability of LEID values & SNM procedures contained in MC&A safeguards program
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/08/26 SANDERS, C F Westinghouse Electric Corp 2pp 20907 313

8310040143 Forwards IE Safeguards Insp Rept 70-1151/83-16 on 830808-12 No noncompliance noted
STOHR, J P Division of Emergency Preparedness & Operational Support, 83/09/01 BRITTON, W H Westinghouse Electric Corp 2pp 2060B 279

--8310040148 IE Safeguards Insp Rept 70-1151/83-16 on 830808-12 No noncompliance noted Major areas inspected Facility operation & statistical controls associated w/SNM accountability measurements Details withheld (ref 10CFR2 790)
JONES, D W Region 2, Office of Director MCALPINE, E J Division of Emergency Preparedness & Materials Safety 83/08/31 1p 2060B 281

8310170330 Requests exemption from provisions of 10CFR70 53(b) for License SNM-1107, to permit 10-day extension for reporting LEID calculation results & 20-day extension for reporting overall matl balance for inventory period
NARDI, A J Westinghouse Electric Corp 83/09/06 BROWN, W B Fuel Facility Safeguards Licensing Branch 3pp 20795 272

8310170219 Forwards info re const & use of new bldg to be constructed within control access area & to be used by contractor during installation of equipment for new IDR MAP project Const to begin in early Sept
REITLER, E K Westinghouse Electric Corp 83/09/13 CROW, W T Uranium Fuel Licensing Branch 3pp 20794 296

8310240230 Advises that proposed change in methodology for determining U element content of solid waste represents upgrade Rev to Fundamental nuclear matl control plan should describe how average enrichment factor will be calculated
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/09/20 SANDERS, C F Westinghouse Electric Corp 1p. 2090B 002

8310240229 Approves 830906 request for exceptions from 10CFR70 53(b) requirements to calculate U element & U-235 LEID values for each physical inventory & to submit rpt within 50 calendar days
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/09/21 SANDERS, C F Westinghouse Electric Corp 2pp. 20907 306.

8310040144 Responds to 830913 ltr re preengineered IDR const bldg NRC has no objection to const & use by contractor, however, use of bldg for licensed matl will require license amend
BIDINGER, G H Uranium Fuel Licensing Branch 83/09/22 REITLER, E K Westinghouse Electric Corp 1p 20634.340

8310040422 Ack receipt of 830823 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1151/83-11.
O'REILLY, J P Region 2, Office of Director 83/09/23, BRITTON, W H Westinghouse Electric Corp 1p 20626 045

--8310040628 Responds to NRC 830725 ltr re violation noted in IE Insp Rept 70-1151/83-11 Corrective actions: all drummed waste packaged & shipped in DDT spec steel drums Insp checklists rewritten to clarify acceptance criteria
BRITTON, W H Westinghouse Electric Corp 83/08/23 O'REILLY, J P, Region 2, Office of Director 2pp. 20626.046

--8310040632 Forwards IE Insp Rept 70-1151/83-11 on 830606-10 & notice of violation Since civil penalty issued by State of SC, no NRC civil penalty action will be taken.
O'REILLY, J P Region 2, Office of Director 83/07/25 BRITTON, W H Westinghouse Electric Corp 2pp 20626 048

--8310040635 Notice of violation from insp on 830606-10
* Region 2, Office of Director 83/07/25 1p 20626.050.

DOCKETED ITEMS

--8310040637 IE Insp Rept 70-1151/83-11 on 830606-10 Noncompliance noted holes existed in six steel drums containing low specific radwaste shipped to Barnwell, SC on 830921 & 23
PEERY, W W Region 2, Office of Director DARR, K P Division of Engineering & Operational Programs 83/07/08 App 20626 051

8310050013 Summarizes 830912-16 safety insp of fuel fabrication facility in Columbia, SC Noncompliances noted handling of radwaste, hood air velocity & unidentified change in radiation protection organization
COOL, D A Uranium Fuel Licensing Branch 83/09/26 Uranium Fuel Licensing Branch App 20650 258

8310250310 Ack receipt of 830901 ltr re IE Safeguards Insp Rept 70-1151/83-16 on 830808-12
SANDERS, C F Westinghouse Electric Corp 83/09/27 O'REILLY, J P Region 2, Office of Director 1p 20895 291

8310260104 Forwards IE Safeguards Insp Rept 70-1151/83-19 on 830912-15 No noncompliance noted
STOHR, J P Division of Emergency Preparedness & Materials Safety, 83/10/12 BRITTON, W H Westinghouse Electric Corp App 20912 106

--8310260114 IE Safeguards Insp Rept 70-1151/83-19 on 830912-15 No noncompliance noted Major areas inspected measurements & statistical controls Details withheld (ref 10CFR2 790).
RICHARDS, B L, MCALPINE, E J Division of Emergency Preparedness & Materials Safety 83/10/11 1p 20912 108

8310240078 Trip rept of 831005-07 visit to Westinghouse in Columbia, SC to review inventory of scrapped cladding, combustible contaminated waste & contaminated mats from plant maint & mtd
BIDINGER, C H Uranium Fuel Licensing Branch 83/10/18 CRUM, W T Uranium Fuel Licensing Branch 1p 20903 209

DOCKET 70-1201 BABCOCK & WILCOX CO , LYNCHBURG, VA

8310240070 Responds to 830715 request for use of estimated weights for 12 fuel rods loaded w/low enriched U pellets Amend MPP-2 to License SNM-116B revised to include new unnumbered license condition to use extended U & U-235 values
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/07/22 FORD, J T Babcock & Wilcox Co 1p 20903 215

8310170076 Forwards revised fundamental nuclear mats control plan for License SNM-116B Rev deletes requirements for pellet mfg & incorporates changes for pellet receipt Plan withheld (ref 10CFR2 790)
FORD, J T Babcock & Wilcox Co 83/08/26 BROWN, W B Fuel Facility Safeguards Licensing Branch 1p 20798 017

8310170740 Forwards page-date index, table of contents & fundamental nuclear matl control plan Plan withheld (ref 10CFR2 790).
FORD, J T Babcock & Wilcox Co 83/09/21 BROWN, W B Division of Safeguards 1p 20796 362

8310170204 Forwards officer certificates for License SNM-42, 145, 414, 778 & 116B financially assuring payment for decommissioning costs of nuclear facilities, per QQ Zipf 780313 commitment
JORDAN, L V Babcock & Wilcox Co 83/09/23 PAGE, R C Uranium Fuel Licensing Branch 5pp 20798 087

DOCKET 70-1257 EXXON NUCLEAR CO., INC , RICHLAND, WA

8310260046 Grants approval for rev to License SNM-1227 adding Condition 4.7 to Amend MPP-2, per 830706 request re performance of contractor lab data audits at interval not to exceed 24 months
BURNETT, R F Division of Safeguards 83/07/31 SCHNEIDER, R A Exxon Nuclear Co, Inc (subs of Exxon Corp) 1p. 20921 334

8310270426 Informs that Rev 5 to physical protection plan for matl of low strategic significance, submitted on 830630, acceptable.
Rev withheld (ref 10CFR2 790)
BROWN, W B Fuel Facility Safeguards Licensing Branch, 83/08/05 MALODY, C W Exxon Nuclear Co, Inc (subs. of Exxon Corp.) 1p 20946 261

8310130208 Application for amend to License SNM-1227 providing for storage warehouse for fuel assemblies
MALODY, C W Exxon Nuclear Co., Inc. (subs of Exxon Corp.) 83/08/30 CROW, W T Uranium Fuel Licensing Branch. 6pp 20751 331

8310240240 Grants 830815 request for 1-month extension for scheduled start of SNM inventory Unnumbered license condition added to Amend MPP-2 to License SNM-1227 to require next physical inventory on or before 831110
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/09/02 SCHNEIDER, R A Exxon Nuclear Co, Inc (subs of Exxon Corp) 1p 20908 001

8310050110 Advises that 820428 & 830218 submittals re changes in radiological contingency plan reviewed & incorporated into plan No license amend necessary Changer do not decrease plan effectiveness
CARDARELLI, R D Uranium Fuel Licensing Branch 83/09/21 MALODY, C W Exxon Nuclear Co, Inc (subs of Exxon Corp) 1p 20650 238

8310170233 Forwards revised Page 3 to application for Amend 11 to License SNM-1227 re enrichment levels
MALODY, C W Exxon Nuclear Co, Inc (subs of Exxon Corp) 83/09/29 CROW, W T Uranium Fuel Licensing Branch 1p 20913 039

--8310170236 Revised Page 3 to application for Amend 11 to License SNM-1227 Amend covers criticality safety & environ impacts
MALODY, C W Exxon Nuclear Co, Inc (subs of Exxon Corp) 83/07/18 1p 20813 040

8310120348 Ack receipt of 830919 ltr informing NRC of steps taken to correct violations noted in IE insp rept
HENSLEWSKI, F A Region 3, Office of Director 83/10/06 MALODY, C W Exxon Nuclear Co, Inc (subs of Exxon Corp) 1p 20698 053

--8310120357 Responds to NRC 830831 ltr re violations noted in IE insp rept Corrective actions detailed list of requirements of amends to license will be transmitted to personnel responsible for operation covered by amend
MALODY, C W Exxon Nuclear Co, Inc (subs of Exxon Corp) 83/09/17 THOMAS, R D Region 3, Office of Director App 20698 054

DOCKET 70-1308 GENERAL ELECTRIC CO , SAN JOSE, CA

8310140212 Forwards IE Insp Rept 72-0001/83-03 on 830729-0922 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 83/09/29 VAN HORNISSEN General Electric Co App 20762 296

--8310140216 IE Insp Rept 72-0001/83-03 on 830729-0922 No noncompliance noted Major areas inspected spent reactor fuel shipping & general plant maint activities, radwaste mgt, 10CFR21 reporting & periodic maint of packaging
LOVENDALE, P C, GREGER, L R, FIRTLE, D L Region 3, Office of Director 83/09/29 9pp 20762 290

DOCKET 70-1426 TRANSNUCLEAR, INC , FALLS CHURCH, VA

8310060598 Forwards modified 830922 primary spent fuel route from West Valley, NY to Morris, IL
SHERR, T B Material Transfer Safeguards Licensing Branch 83/09/27 MANGUBI, J Transnuclear, Inc 9pp 20661 275

DOCKET 70-1462 HARPER HOSP , DEIRIDIT, MI

8310180048 Forwards sanitized version of 831003 modified alternate spent fuel route from West Valley, NY to Dresden facility Remaining provisions of NRC 830914 ltr unchanged
SHERR, T B Material Transfer Safeguards Licensing Branch 83/10/05 MANGUBI, J Transnuclear, Inc 9pp 20824 292

DOCKET 70-1487 DOW CHEMICAL USA, MIDLAND, MI

8310110065 Further response to FOIA request for records re incineration of radioactive mats by Dow Chemical Co Midland, MI plant Forwards App B documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/06/20 GARDE, B P Government Accountability Project App 20704 001

--8310110139 Discusses insp of License SNM-1451, 21-00265-04 & 21-00265-06 on 761006 & forwards description of noncompliance
ALLAN, J M Region 3, Chicago, Office of the Director 76/10/20 LANGNER, R R Dow Chemical Co App 20704 087

DOCKETED ITEMS

DOCKET 70-1795 GEORGE WASHINGTON UNIV , WASHINGTON, DC

8310270635 Responds to 830927 memo re civil penalties imposed on George Washington Univ Medical Ctr & Nuclear Metals, Inc Ltrs to licensees, notices of violation & inep repts encl
DIRCKS, W J Office of the Executive Director for Operations
83/10/03 GILINSKY, V Commissioners 1p 20946 041

--8310270639 Discusses IE insp on 830601-02 & forwards notice of violation & proposed imposition of civil penalty
MURLEY, L E Region 1, Office of Director 83/09/01 (LEONARD), F
George Washington Univ Medical Center Wash DC 3pp 20946 041

--8310270644 Notice of violation & proposed imposition of civil penalty in amount of \$2,500 Noncompliance noted adequate survey not performed to assure compliance w/10CFR20.106(a) re radioactive releases
MURLEY, L E Region 1, Office of Director 83/09/01 5pp
20946 045

--8310270656 Requests description of noncompliances identified at George Washington Univ Medical Ctr & Nuclear Metals, Inc which resulted in proposed fines of \$2,500 & \$9,000 respectively
GILINSKY, V Commissioners 83/09/01 AXELRAD, J Director's Office, Office of Inspection and Enforcement, 1p 20946 078

DOCKET 70-2067 UNION CARBIDE CORP , MARIETTA, OH

8310170262 Forwards ORNL 830914 ltr re analytical data on epoxy floor covering samples from process bldg info establishes thorium/U ratio in contaminants on floors to develop appropriate guidelines for decontamination
EVANS, L O Union Carbide Corp 83/10/05 PAPERIELLO, C J Region 3, Office of Director 4pp 20784 315

DOCKET 70-2319 OUR LADY OF LOURDES HOSP , CAMDEN, NJ

8310310419 Ack receipt of 830912 ltr informing NRC of steps taken to correct violations noted in IF Insp Rept 70-2319/83-01
MARTIN, T T Division of Engineering & Technical Programs 83/10/25
PETERS, A Our Lady of Lourdes Hosp , Camden, NJ 1p 20959 234

--8310310425 Responds to NRC 830719 ltr re violations noted in IE Insp Rept 70-2319/83-01 Corrective actions all original NRC licenses, including SNM license, will be kept on file in administration ofc
PETERS, A Our Lady of Lourdes Hosp , Camden, NJ 83/09/12
Region 1, Office of Director 1p 20959 240

DOCKET 70-2430 MERCER MEDICAL CENTER, TRENTON, NJ

8310310414 Ack receipt of 830916 ltr informing NRC of steps taken to correct violations noted in IF Insp Repts 70-2430/83-01, 30-02411/83-01 & 30-00341/83-01 on 830630
MARTIN, T T Division of Engineering & Technical Programs 83/10/25
STEWART, C C Mercer Medical Center Trenton, NJ 1p 20959 285

--8310310418 Responds to NRC 830818 ltr re violations noted in IE Insp Repts 70-2430/83-01, 30-02411/83-01 & 30-00341/83-01 on 830630 Corrective actions, disposable gloves will be utilized by all personnel when handling radioactive matl
STEWART, C C Mercer Medical Center Trenton, NJ 83/09/16
MARTIN, T T Division of Engineering & Technical Programs 1p
20959 286

DOCKET 70-2808 WESTMORELAND HOSP , GREENSBURG, PA

8310180137 Discusses IE Insp Repts 70-2808/83-01 & 30-09731/83-01 on 830826 No noncompliance noted Major areas inspected, procedures & records & interviews w/personnel Pu powered pacemakers never received under License SNM-1815
MARTIN, T T Division of Engineering & Technical Programs 83/09/29
WILCOX, H K Westmoreland Hosp Greensburg, PA 2pp 20800 165

DOCKET 70-2941 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN

8310170733 Suppl to application to amend 810106 physical security plan, reflecting section & div changes Amend withheld (ref 10CFR2 790)
MILLS, L M Tennessee Valley Authority 83/08/24 O'REILLY, J P
Region 2, Office of Director 1p 20797 352

DOCKET 70-2945 UNION ELECTRIC CO , ST LOUIS, MO

8310040133 Issues Amend 3 to License SNM-1901 increasing possession limit to 27.0 g U-235 Safety evaluation encl
PAGE, R G Uranium Fuel Licensing Branch 83/09/23 SCHNELL, D F
Union Electric Co 1p 20627 356

--8310040137 Safety evaluation supporting Amend 3 to License SNM-1901
SERINI, B L , CROW, W T Uranium Fuel Licensing Branch 83/09/23
3pp 20627 357

DOCKET 70-2946 LOUISIANA POWER & LIGHT CO , NEW ORLEANS, LA

8310180622 Unexecuted Amend 1 to Indemnity Agreement 8-92, revising Item 4 on location of land, bldgs & structures
SALTZMAN, J Assistant Director for State & Licensee Relations
83/10/11 3pp 20817 333

DOCKET 70-2949 ARIZONA PUBLIC SERVICE CO , PHOENIX, AZ

8310060176 IE Insp Findings & Licensee Ack dtd 830713 of License SNM-1887 Insp findings no violations observed
SKOV, D D Region 5, Office of Director 83/07/26 1p 20648 353

DOCKET 70-2950 WASHINGTON PUBLIC POWER SUPPLY SYSTEM, RICHLAND, WA

8310040397 Forwards IE Safeguards Insp Repts 50-397/83-33 & 70-2950/83-02 on 830815-18 & notice of violation Encls withheld (ref 10CFR2 790)
NORDERHAUD, L R Region 5, Office of Director 83/09/28
CARLISLE, C S Washington Public Power Supply System 2pp
20620 042 24X Fiche 50-397, 83/09/28, 8310040397

DOCKET 70-2960 KANSAS GAS & ELECTRIC CO , WICHITA, KS

8310170644 Forwards Rev 2 to SNM license application updating technical info re crane usage, fire protection & security for SNM & dosimetry for fuel handling activities Six fission chambers & 10 detector foils also added to application
KEESTER, O L Kansas Gas & Electric Co 83/09/23 DAVIS, J O
Office of Nuclear Material Safety & Safeguards, Director 2pp
20798 205

--8310170654 Rev 2 to SNM license application updating technical info re crane usage, fire protection & security for SNM & dosimetry for fuel handling activities
* Kansas Gas & Electric Co 83/09/30 12pp 20798 207

8310210095 Forwards Rev 2 to SNM license application, providing technical info updates re crane usage, fire protection & security for SNM
KEESTER, O L Kansas Gas & Electric Co 83/09/23 DAVIS, J O
Office of Nuclear Material Safety & Safeguards, Director 3pp
20883 252

--8310210100 Rev 2 to application for SNM license for receipt & possession of reactor fuel & associated matl from Wolf Creek
* Kansas Gas & Electric Co 83/09/23 11pp, 20883 255

DOCKET 70-2968 CLEVELAND ELECTRIC ILLUMINATING CO , CLEVELAND, OH

8310170613 Forwards response to 830329 request for addl info re license application for storage only of unirradiated reactor fuel & associated radioactive matl at Perry Unit 1
EDELMAN, M R Cleveland Electric Illuminating Co 83/05/27
KILLINGER, M H Uranium Fuel Licensing Branch 5pp 20814.149

DOCKET 70-2973 COMMONWEALTH EDISON CO , CHICAGO, IL

8310170718 Forwards Rev 1 to security plan for SNM security per 10CFR70.32(e) Rev withheld (ref 10CFR73 21)
FARRAR, D L Commonwealth Edison Co 83/09/13 BROWN, W Fuel Facility Safeguards Licensing Branch 1p 20798 115

DOCKETED ITEMS

DOCKET 70-2977 DETROIT EDISON CO., DETROIT, MI

8310250575 Forwards IE Safeguards Insp Repts 70-2977/83-01 & 70-2977/83-02 on 830926-27 & 30 No noncompliance noted
AXELSON, W L Region 3, Office of Director 83/10/21 WELLS, D A
Detroit Edison Co 2pp 20900 303

--8310250582 IE Safeguards Insp Repts 70-2977/83-01 & 70-2977/83-02 on 830926-27 & 30 No noncompliance noted Major areas inspected
SNM controls & accountability & new fuel security Details withheld (ref 10CFR2 790)
MAEDA, T J, KNICELEY, J R, CREED, J R Region 3, Office of Director 83/10/21 1p 20900 305

DOCKET 70-2983 PENNSYLVANIA POWER & LIGHT CO., ALLENTOWN, PA

8310240099 Determines that 830505 physical security plan for protection of SNM of low strategic significance meets requirements of 10CFR73 47 7 Plan must be fully implemented by fuel receipt date
BROWN, W D Fuel Facility Safeguards Licensing Branch 83/07/14
CURTIS, N W Pennsylvania Power & Light Co 1p 20891 356

DOCKET 70-2988 PHILADELPHIA ELECTRIC CO., PHILADELPHIA, PA

8310170225 Responds to 830915 telcon request for addl info re SNM license application for Limerick Unit 1
KEMPER, J B Philadelphia Electric Co 83/09/20 PAGE, R G Uranium Fuel Licensing Branch 4pp 20796 288

8310060543 Forwards License SNM-1926 authorizing receipt, possession, storage & use of U enriched in U-235 contained in fission chambers
PAGE, R G Uranium Fuel Licensing Branch 83/09/23 BAUER, E G Philadelphia Electric Co 2pp 20661 287

--8310060548 License SNM-1926 for Philadelphia Electric Co authorizing use of U enriched in U-235 contained in sealed sources
PAGE, R G Division of Fuel Cycle & Material Safety 83/09/23 2pp 20661 289

--8310060553 Safety evaluation supporting License SNM-1926 re receipt, possession & use of fission chambers
SERINI, B L Uranium Fuel Licensing Branch 83/09/23 31pp 20661 291

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0037 NAVY, DEPT OF

8310050124 Forwards QA program approval for Radioactive Matl Package 0037, Rev 2
MACDONALD, C E Transportation Branch 83/09/23 Navy, Dept of 1p 20650 055

--8310050133 QA program approval for Radioactive Matl Package 0077, Rev 2
MACDONALD, C E Transportation Branch 83/09/23 1p 20650 056

DOCKET 71-0059 GENERAL ELECTRIC CO

8310050014 Informs that QA program approval for Radioactive Matl Package 0059 terminated after 830923, per 830909 request
MACDONALD, C E Transportation Branch 83/09/26 JOLLY, J General Electric Co 1p 20650 260

DOCKET 71-0137 METALS TESTING CO., INC.

8310170322 Advises that on Jul 1980 ownership changed & radiographic insp svcs discontinued Future FR changes or certificates of compliance for radioactive matl not needed.
CAYEN, C F Metals Testing Co, Inc 83/09/13 MACDONALD, C E Transportation Branch 2pp 20793 276

DOCKET 71-0148 UNITED ENGINEERS & CONSTRUCTORS, INC

8310190269 Ack receipt of Rev 1 to QA program approval for Radioactive Matl Package 0148 submitted in support of Matls/Byproduct License 37-01546-04 QA program inactive since 800630, per encl Amend 5 to license
POLIQUIN, T E United Engineers & Constructors, Inc (subs of Raytheon Co) 83/09/23 MACDONALD, C E Transportation Branch 1p 20843 197

DOCKET 71-0466 MINNESOTA MINING & MANUFACTURING CO (3M CO)

8310040094 Forwards QA program approval for Radioactive Matl Package 0466, Rev 3
MACDONALD, C E Transportation Branch 83/09/23 HEILAND, R 3M Co Minnesota Mining & Mfg Co 1p 20634 357

--8310040099 QA program approval for Radioactive Matl Package 0466, Rev 3
MACDONALD, C E Transportation Branch 83/09/23 1p 20634 358

DOCKET 71-0503 PENN INSPECTION CO

8310130253 Forwards response to 830824 request re organization, QA/QC program & implementing procedures
PATTERSON, H Big State X-Ray 83/09/26 MACDONALD, C E Transportation Branch 6pp 20754 351

8310240305 Forwards QA program approval for Radioactive Matl Package 0503, Rev 0
MACDONALD, C E Transportation Branch 83/10/18 PATTERSON, H Penn Inspection Co 1p 20904 358

--8310240307 QA program approval for Radioactive Matl Package 0503, Rev 0
MACDONALD, C E Transportation Branch 83/10/18 1p 20904 359

DOCKET 71-0504 TEXAS UTILITY GENERATING CO

8310180399 Notifies of intention to apply 10CFR50, App B QA program to packaging & transportation of radioactive matls as required by 10CFR71 81 & 10CFR71 101(b)
KUYKENDALL, J C Texas Utilities Generating Co 83/09/13 Office of Nuclear Material Safety & Safeguards, Director 1p 20825 359

8310240317 Forwards QA program approval for Radioactive Matl Package 0504, Rev 0
MACDONALD, C E Transportation Branch 83/10/18 JONES, R A Texas Utilities Generating Co 1p 20907 163

--8310240319 QA program approval for Radioactive Matl Package 0504, Rev 0
MACDONALD, C E Transportation Branch 83/10/18 1p 20907 164

DOCKET 71-0505 SOUTHWEST RESEARCH INSTITUTE

8310190343 Provides matrix showing applicability of QA program manual to Reg Guide 7 10 for shipment of reactor pressure vessel surveillance capsules, per 830920 telcon
MORRIS, E B, MADRITO, B Southwest Research Institute 83/09/21 GORDON, L Transportation Branch 3pp 20842 303

8310110402 Forwards QA program approval for Radioactive Matl Package 0505, Rev 0
MACDONALD, C E Transportation Branch 83/09/29 MADRITO, B Southwest Research Institute 1p 20713 342

--8310110410 QA program approval for Radioactive Matl Package 0505, Rev 0
MACDONALD, C E Transportation Branch 83/09/29 1p 20713 343

DOCKET 71-0506 BABCOCK & WILCOX CO

8310110416 Forwards QA program approval for Radioactive Matl Package 0506, Rev 0
MACDONALD, C E Transportation Branch 83/09/29 FERREE, D V. Babcock & Wilcox Co 1p 20713 352

--8310110423 QA program approval for Radioactive Matl Package 0506, Rev 0
MACDONALD, C E Transportation Branch 83/09/29 1p 20713 353

DOCKETED ITEMS

389

DOCKET 71-4909 MODEL GE-21PF-1, GENERAL ELECTRIC CO

8310050019 Informs that drawings submitted w/830720 application re Model W-21PF-1 packaging will be placed in PDR unless withholding requested within 15 days of ltr
MACDONALD, C E Transportation Branch 83/09/26 NARDI, A J
Westinghouse Electric Corp Ip 20650 271

8310170342 Requests registration as user of Models GE-21PF-1 & W-21PF-1
WEINTRAUB, A A Energy, Dept of 83/10/03 MACDONALD, C E
Transportation Branch Ip 20795 239

DOCKET 71-5059 MODEL NFS-URANYL NIT, NUCLEAR FUEL SERVICES, INC

8310050114 Notification of registration as user of Model NFS-URANYL-NIT in response to 830901 request
MACDONALD, C E Transportation Branch 83/09/26 MAIER, J B Allied
General Nuclear Services Ip 20650 237

DOCKET 71-5088 MODEL D34710-1, D34710-2, ROCKWELL INTERNATIONAL CORP

8310050097 Notification of registration as user of Models D 34710-1 & D 34710-2 in response to 830928 request
MACDONALD, C E Transportation Branch 83/09/26 COOK, G M
Michigan, Univ of, Ann Arbor, MI Ip 20650 054

DOCKET 71-5450 MODEL RCC, -1, -2, -3, -4, WESTINGHOUSE ELECTRIC CORP

8310200451 Application to amend Certificate of Compliance 5450 for RCC shipping package, increasing fuel enrichment by limiting shipment to one fuel assembly per shipping container
NARDI, A J Westinghouse Electric Corp 83/10/04 MACDONALD, C E
Transportation Branch 4pp 20844 352

8310240257 Forwards Rev 17 to Certificate of Compliance 5450 for Models RCC, RCC-1, RCC-2, RCC-3 & RCC-4
MACDONALD, C E Transportation Branch 83/10/13 NARDI, A J
Westinghouse Electric Corp 2pp 20907 268

--8310240259 Certificate of Compliance 5450, Rev 17, for Models RCC, RCC-1, RCC-2, RCC-3 & RCC-4
MACDONALD, C E Transportation Branch 83/10/13 6pp 20907 270

DOCKET 71-5595 MODEL L&M ORNL URANIUM SHIELDED CASK, ENERGY, DEPT OF

8310190335 Forwards Certificate of Compliance 5595, Rev 5 for Models L & M Changes include deletion of decomposition temp for special form, corrections to print ref & changes re rev to DOT regulations
TRAVIS, W H Energy, Dept of 83/09/30 MACDONALD, C E
Transportation Branch Ip 20843 147

8310170170 Forwards Rev 5 to Certificate of Compliance 5595 for Models L & M ORNL U shielded cask
WEINTRAUB, A A Energy, Dept of 83/10/04, MACDONALD, C E
Transportation Branch 3pp 20798 202

--8310170175 Certificate of Compliance 5595, Rev 5, for Models L & M ORNL U shielded cask
TRAVIS, W H Energy, Dept of 83/09/20 2pp 20798 204

8310190237 Forwards Rev O to Certificate of Compliance 5595 for Model L&M
MACDONALD, C E Transportation Branch 83/10/13 WEINTRAUB, A A
Energy, Dept of Ip 20838 087

--8310190240 Certificate of Compliance 5595, Rev O, for Model L&M
MACDONALD, C E Transportation Branch 83/10/13, 4pp 20838 080,

DOCKET 71-5797 MODEL INNER & OUTER HFIR UN, ENERGY, DEPT OF

8310200333 Requests registration as user of Models HFIR, UN & TREAT,
REGAN, N A Babcock & Wilcox Co 83/10/10 MACDONALD, C E
Transportation Branch 3pp 20844 266

DOCKET 71-5805 MODEL CNS 3-55, CHEM-NUCLEAR SYSTEMS, INC

8310190332 Application for rev to Certificate of Compliance 5805 for CNS 3-55 cask allowing 15 shipments of activated stainless steel in thermal shield sections for transport to Barnwell site by 831231 Fee encl
POPPE, L K Chem-Nuclear Systems, Inc 83/08/10 MACDONALD, C E
Transportation Branch 3pp 20842 298

DOCKET 71-5828 MODEL TREAT, ENERGY, DEPT OF

8310200333 Requests registration as user of Models HFIR, UN & TREAT
REGAN, N A Babcock & Wilcox Co 83/10/10 MACDONALD, C E
Transportation Branch 3pp 20844 266

DOCKET 71-5908 MODEL DOT-6M TYPE B, BABCOCK & WILCOX CO

8310130249 Requests registration as user of Model DOT-6M
BOATRIGT, P A OI Corp 83/09/28 MACDONALD, C E Transportation
Branch 2pp 20754 357

DOCKET 71-5939 MODEL GE-1500, GENERAL ELECTRIC CO

8310170744 Requests registration as user of Model GE 1500
WEINTRAUB, A A Energy, Dept of 83/09/28, MACDONALD, C E
Transportation Branch 2pp 20796 355

8310190272 Summary of 831007 meeting w/GE in Silver Spring, MD re proposed amends to package design concerning Models
GE-200, 1500, 1600 & 8500
ODEGAARDEN, R H Transportation Branch 83/10/13 Transportation
Branch 2pp 20843 165

DOCKET 71-5957 MODEL BMI-1, BATTTELLE COLUMBUS LABORATORY

8310070005 Forwards request for addl info needed to complete review of request for amend to Model BMI-1 packaging. Info should be submitted in form of revised pages within 30 days of ltr date
MACDONALD, C E Transportation Branch 83/09/22 BURIAN, R J
Battelle Memorial Institute, Columbus Laboratories 3pp 20674 360

8310050097 Notification of registration as user of Models D 34710-1 & D 34710-2 in response to 830922 request
MACDONALD, C E Transportation Branch 83/09/26 COOK, G M
Michigan, Univ of, Ann Arbor, MI Ip 20650 054

DOCKET 71-5971 MODEL GE-200, GENERAL ELECTRIC CO

8310190272 Summary of 831007 meeting w/GE in Silver Spring, MD re proposed amends to package design concerning Models
GE-200, 1500, 1600 & 8500
ODEGAARDEN, R H Transportation Branch 83/10/13 Transportation
Branch 2pp 20843 165

DOCKET 71-6003 MODEL M-130, ENERGY, DEPT OF

8310050016 Forwards Rev 6 to Certificate of Compliance 6003 for Model M-130
MACDONALD, C E Transportation Branch 83/09/26 ENGEL, W P
Energy, Dept of 1pp 20650 261

--8310050041 Certificate of Compliance 6003, Rev 6, for Model M-130,
MACDONALD, C E Transportation Branch 83/09/26, 6pp 20650 262

DOCKET 71-6144 MODEL B-2, U S ECOLOGY, INC

8310200422 Forwards summary of radioactive matls inventory scheduled for delivery to Monterrey, Mexico to reestablish business operations
WALKER, E L Ead Metallurgical, Inc 83/09/28, RAWL, R R
Transportation, Dept. of 10pp 20859 283

8310130095 Summary of 830928 meeting w/EAD Metallurgical, Inc in Silver Spring, MD re shipment of radioactive matl stored in Richer Warehouse, Laredo, TX to Monterrey, Mexico for reestablishment of smoke detector business
ODEGAARDEN, R H Transportation Branch 83/10/06, Transportation
Branch 2pp, 20777 025

DOCKETED ITEMS

8310200012 Amends Certificate of Compliance 6144 to authorize certain radioactive matls described in 830923 ltr as addl contents for Model B-2
MACDONALD, C E Transportation Branch 83/10/13 WALKER, E L Ed
Metallurgical, Inc 2pp 20844 243

DOCKET 71-6166 MODEL O 5T, ENERGY, DEPT OF

8310110619 Forwards Rev 2 to Certificate of Compliance 6166 for Model O 5T
MACDONALD, C E Transportation Branch 83/10/06 JACKSON, C D
Energy, Dept of 1p 20701 353

--8310110622 Certificate of Compliance 6166, Rev 2 for Model O 5T
MACDONALD, C E Transportation Branch 83/10/06 3pp 20701 354

DOCKET 71-6346 MODEL FSV-1, OA TECHNOLOGIES, INC

8310130270 Application for amend to Certificate of Compliance 6346, allowing use of 2x4-inch bar of steel fashioned into 13-inch ID ring as added shielding for contents of burial liner
MOWRY, W R OA Technologies, Inc /General Atomic Co 83/09/19
MACDONALD, C Transportation Branch 2pp 20751 284

--8310130274 "Consolidated Design Rept for Fort St Vrain Fuel Shipping Cask"
* OA Technologies, Inc /General Atomic Co. QADR-55 ADD04
83/09/30 60pp 20751 286

8310170064 Forwards section of Chapter 2 from "Theory of Flow & Fracture of Solids," Vol 2 by A Nadai, in response to criticisms of safety analysis, QADR, Addendum IV, Rev 1 for waste canister for small highly irradiated hardware
MOWRY, W R OA Technologies, Inc /General Atomic Co 83/09/30
MACDONALD, C Transportation Branch 6pp 20798 029

DOCKET 71-6400 MODEL 6400, WESTINGHOUSE ELECTRIC CORP

8310170739 Forwards addl info supporting Naval Reactors 830422 statement re reactivity effect of replacing all or part of polyurethane foam w/water Reactivity level would decrease slightly due to importance of neutron absorption
ENGEL, W P Energy, Dept of 83/09/26 MACDONALD, C E
Transportation Branch. 5pp 20796 357

8310060332 Summary of 830922 meeting w/Sandia Natl Labs in Silver Spring, MD re shipments of transuranic waste matls in TRUPAC packaging.
ODEGAARDEN, R H Transportation Branch 83/09/29 Transportation Branch 2pp 20660 212

DOCKET 71-6478 MODEL 4T, ENERGY, DEPT OF

8310120001 Forwards Rev 2 to Certificate of Compliance 6478 for Model 4T
MACDONALD, C E Transportation Branch 83/10/06 JACKSON, C D
Energy, Dept of 2pp 20749 356

--8310120002 Certificate of Compliance 6478, Rev 2, for Model 4T
MACDONALD, C E Transportation Branch 83/10/06 3pp 20749 358

DOCKET 71-6550 MODEL 6-GS-1, ENERGY, DEPT OF

8310170306 Application for rev to Certificate of Compliance 6550 to approve use of shielded shipping cask sys for shipment of 1 Ci Ra-226 in form of RaBr(2) in spherical beryllium container
WEINTRAUB, A A Energy, Dept. of. 83/10/04. MACDONALD, C E
Transportation Branch. 11pp 20796 134

DOCKET 71-6574 MODEL HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP.

8310200014 Requests registration as user of Hittman Nuclear & Development Corp Model HN-200.
ZUPKO, J H Public Service Electric & Gas Co of New Jersey
83/07/29 MACDONALD, C E Transportation Branch 2pp. 20844 261

8310240289 Notification of registration as user of Model HN-200 in response to 830729 request.
MACDONALD, C E Transportation Branch 83/10/18 MIDURA, H J.
Public Service Electric & Gas Co of New Jersey. 1p 20907-327

DOCKET 71-6601 MODEL CNS B-120, CHEM-NUCLEAR SYSTEMS, INC

8310170748 Application for renewal of Certificate of Compliance 6601 for Model CNS B-120 SAR encl
CORBETT, J S Chem-Nuclear Systems, Inc 79/11/19 MACDONALD, C E
Transportation Branch 1p 20812 001

--8310170750 "SAR for Shipment of Radioactive Matl in (NS B-120 (LL-50-100) Cask"
* Chem-Nuclear Systems, Inc 79/10/31 152pp 20812 002

DOCKET 71-6679 MODEL 6679, U S ECOLOGY, INC

8310200330 Advises that response to 830914 request for addl info re 821223, 830410 & 0630 applications for renewal of Certificate of Compliance 6679 will be provided by 831104
WALLER, W K US Ecology, Inc (formerly Nuclear Engineering)
83/10/12 MACDONALD, C E Transportation Branch 2pp 20844 277

DOCKET 71-6697 MODEL QE-B500, GENERAL ELECTRIC CO

8310170232 Requests registration as user of Model QE-B500 Forwarding address for all future correspondence & documentation provided
DEAL, R L Chem-Nuclear Systems, Inc 83/09/30 MACDONALD, C E
Transportation Branch 2pp 20796 282

8310190272 Summary of 831007 meeting w/QE in Silver Spring, MD re proposed amends to package design concerning Models QE-200, 1900, 1600 & B500
ODEGAARDEN, R H Transportation Branch 83/10/13 Transportation Branch 2pp 20843 165

DOCKET 71-6771 MODEL BN-1, METROPOLITAN EDISON CO

8310190351 Requests registration as user of Models NUPAC 14/190L, NUPAC 14/190H, NUPAC 14/190M & BN-1 Forwarding address for all future correspondence provided
DEAL, R L Chem-Nuclear Systems, Inc 83/09/22 MACDONALD, C E
Transportation Branch 2pp 20843 171

8310240297 Notification of registration as user of Models BN-1 & NUPAC-14/190L, 14/190H & 14/190M in response to 830922 request
MACDONALD, C E Transportation Branch 83/10/18 DEAL, R
Chem-Nuclear Systems, Inc 1p 20904 350

DOCKET 71-9009 MODEL FL 10-1, GENERAL ELECTRIC CO

8310070017 Requests submittal of consolidated application, w/drawings, incorporating all previous submittals, for renewal of Certificate of Compliance 9009 for Model FL 10-1 packaging Rev 10 will not expire until final NRC determination
MACDONALD, C E Transportation Branch 83/09/22 VAUGHAN, C M
General Electric Co 1p 20671 363

DOCKET 71-9010 MODEL NLI-1/2, NL INDUSTRIES, INC

8310170234 Discusses status of util preparations to remove spent Fuel from Western New York Nuclear Svc Ctr Utilis will rely on DOE to undertake all activities re loading fuel for shipment, per 830812 meeting Ltr forwarded to DOE encl
CHARNOFF, G Shaw, Pittman, Potts & Trowbridge CHARNOFF, G
Wisconsin Electric Power Co CHARNOFF, G Commonwealth Edison Co
83/09/21 MACDONALD, C E Transportation Branch 9pp 20796 273

8310190328 Requests registration as user of Model NLI-1/2 for License DPR-16
FIEDLER, P B General Public Utilities - GPU Service Corp 83/09/26
Office of Nuclear Material Safety & Safeguards, Director 3pp 20842 295

8310250015 Notification of registration as user of Model NLI-1/2 in response to 830926 request
MACDONALD, C E Transportation Branch 83/10/18 SNIDER, T General Public Utilities - GPU Service Corp 1p 20916 109

DOCKETED ITEMS

3

DOCKET 71-9016 MODEL TN-9, NO USERS

8310170234 Discusses status of util preparations to remove spent fuel from Western New York Nuclear Svc Ctr. Utils will rely on DOE to undertake all activities re loading fuel for shipment. per 830812 meeting Ltr forwarded to DOE encl
CHARNOFF, G Shaw, Pittman, Putts & Trowbridge CHARNOFF, G
Wisconsin Electric Power Co CHARNOFF, G Commonwealth Edison Co
83/09/21 MACDONALD, C E Transportation Branch 9pp 20796 273

DOCKET 71-9027 MODEL 741 & 741E, TECHNICAL OPERATIONS, INC

8310170221 Requests registration as user of Models 741, 850, 920 & 771
MALINGWSKI, F A Ebasco Services, Inc (subs of Enserch Corp)
83/09/20 MACDONALD, C E Transportation Branch 2pp 20796 294

8310240292 Notification of registration as user of Models 741, 850, 920 & 771 in response to 830920 request
MACDONALD, C E Transportation Branch 83/10/18 BULLEN, H C
Ebasco Services, Inc (subs of Enserch Corp) 1p 20904 349

DOCKET 71-9032 MODEL 650, TECHNICAL OPERATIONS, INC

8310190293 Requests registration as user of Models 660 & 650
DRIGGERS, S E LaBarge, Inc 83/09/29 Transportation Branch
1p 20842 050

8310170215 Requests registration as user of Tech/Ops Model 650
KAWACHI, M H Navy, Dept of, Pearl Harbor Naval Shipyard 83/10/03
MACDONALD, C E Transportation Branch 1p 20797 361

DOCKET 71-9033 MODEL 660 & 660E, TECHNICAL OPERATIONS, INC

8310190293 Requests registration as user of Models 660 & 650
DRIGGERS, S E LaBarge, Inc 83/09/29 Transportation Branch
1p 20842 050

8310170209 Requests registration as user of Tech/Ops Model 660
KAWACHI, M Navy, Dept of, Pearl Harbor Naval Shipyard 83/10/12
MACDONALD, C E Transportation Branch 1p 20798 085

DOCKET 71-9039 MODEL 715, TECHNICAL OPERATIONS, INC

8310170334 Requests registration as user of Model 715 Rev 6 to Certificate of Compliance 9039 encl
LEWIS, L Duke Power Co 83/09/27 MACDONALD, C E Transportation Branch 1p 20795 269

8310250022 Notification of registration as user of Model 715 in response to 830927 request
MACDONALD, C E Transportation Branch 83/10/18 PARKER, W O Duke Power Co 1p 20908 359

DOCKET 71-9044 MODEL GE-1600, GENERAL ELECTRIC CO

8310190272 Summary of 831007 meeting w/GE in Silver Spring, MD re proposed amendments to package design concerning Models GE-200, 1500, 1600 & 8900
ODEGAARDEN, R H Transportation Branch 83/10/13 Transportation Branch 2pp 20843 165

DOCKET 71-9070 MODEL N-55, ENERGY, DEPT OF

8310170027 Application for rev to Certificate of Compliance 9070 to include fissile powder as authorized contents of overpack shipping container Model N-55
ENGEL, W P Energy, Dept of 83/07/29 MACDONALD, C E Transportation Branch 4pp 20798 348

8310060599 Forwards Rev 9 to Certificate of Compliance 9070 for Model N-55
MACDONALD, C E Transportation Branch 83/09/29 SIMCHUK, J D Nuclear Packaging, Inc 3pp 20661 153

--8310060600 Certificate of Compliance 9070, Rev 9, for Model N-55 Approval record encl
MACDONALD, C E Transportation Branch 83/09/29 4pp 20661 156

8310110090 Amends Certificate of Compliance 9070 to authorize U oxide bearing waste matrix containing up to 5 g U-233 & U-235 as addl contents of Model N-55 package Approval record encl
MACDONALD, C E Transportation Branch 83/09/29 ENGEL, W P Energy, Dept of 2pp 20687 351

DOCKET 71-9080 MODEL 9080, HITTMAN NUCLEAR & DEVELOPMENT CORP

8310050046 Marked-up memo advising that encl Hittman Nuclear & Development Corp 830818 proprietary application, associated SARs & drawings re Model 9080 package design should be placed in PDR
MACDONALD, C E Transportation Branch 83/08/18 SCOTT, S Document Management Branch 1p 20650 076

--8310050056 Forwards responses to NRC 830620 ltr re application for renewal of Certificate of Compliance 9080, authorizing use of Model 9080 radioactive matrix package w/three oversize drawings. Aperture cards are available in PDR
PHILLIPS, J W Hittman Nuclear & Development Corp (subs of Hittman Corp) 83/08/18 MACDONALD, C E Transportation Branch 5pp 20650 077

--8310050065 Replacement pages for "SAR for Model 9080 Radwaste Shipping Cask"
* Hittman Nuclear & Development Corp (subs of Hittman Corp). 83/08/18 23pp 20650 081

--8310050074 Rev 5 to Procedure HNDC-0-001-7, "Cask Handling Procedure for HN-600 Shielded Transport Cask"
* Hittman Nuclear & Development Corp (subs of Hittman Corp). 83/08/15 18pp 20650 104

8310190324 Requests registration as user of Comm Ed Model 7-100 for License DPR-40 Forwarding address for all future correspondence & documentation provided
JONES, W C Omaha Public Power District 83/09/16 MACDONALD, C E Transportation Branch 2pp 20842 293

8310050195 Forwards request for addl info re renewal of Certificate of Compliance 9080 for Model 9080 packaging. Info should be submitted in form of revised pages within 45 days
MACDONALD, C E Transportation Branch 83/09/22 PHILLIPS, J W Hittman Corp 2pp 20650 214

DOCKET 71-9086 MODEL HN-100, SERIES I, HITTMAN NUCLEAR & DEV. CORP

8310190302 Requests registration as user of Hittman Nuclear & Development Corp Model HN-100
ZUPKO, J M Public Service Electric & Gas Co of New Jersey 83/07/29 MACDONALD, C E Transportation Branch, 1p 20840, 325

8310310428 Advises that encl proprietary drawing & 831011 application re Model HN-100 Series I package design should be placed in PDR
MACDONALD, C E Transportation Branch 83/10/14 SCOTT, S Document Management Branch 1p 20965 119

--8310310430 Forwards, for refrence oversize drawing reflecting as-built configuration of drain plug Tube outer edge joined around perimeter of cask body w/existing Fillet weld Aperture card is available in PDR
LEDUC, R J Hittman Nuclear & Development Corp. (subs of Hittman Corp) 83/10/11 MACDONALD, C E Transportation Branch 2pp. 20965 120

8310240308 Notification of registration as user of Model HN-100, Series I in response to 830729 request
MACDONALD, C E Transportation Branch 83/10/18 MIDURA, H J Public Service Electric & Gas Co of New Jersey 1p. 20904 360.

DOCKET 71-9089 MODEL HN-100B, HITTMAN NUCLEAR & DEVELOP. CORP

8310190298 Requests registration as user of Hittman Nuclear & Development Corp Model HN-100B for License DPR-2B
MURPHY, W P Vermont Yankee Nuclear Power Corp 83/09/28 Office of Nuclear Material Safety & Safeguards, Director. 3pp 20841:336

8310250029 Notification of registration as user of Model HN-100B in response to 830928 request.
MACDONALD, C E Transportation Branch 83/10/18 Vermont Yankee Nuclear Power Corp. 1p 20908.358

DOCKETED ITEMS

DOCKET 71-9092 MODEL HN-300, HITTMAN NUCLEAR & DEVELOPMENT CORP

8310170228 Application to revise Certificate of Compliance 9092 for HNDC Model HN-300, extending expiration date to 8/11/30
LEDUC, R J Hittman Nuclear & Development Corp (subs of Hittman Corp) 83/09/30 MACDONALD, C Transportation Branch 1p 20796 286

DOCKET 71-9093 MODEL HN-400, HITTMAN NUCLEAR & DEVELOPMENT CORP

8310170218 Application to revise Certificate of Compliance 9093 for HNDC Model HN-400, extending expiration date to 8/11/30
LEDUC, R J Hittman Nuclear & Development Corp (subs of Hittman Corp) 83/09/30 MACDONALD, C Transportation Branch 1p 20797 359

DOCKET 71-9096 MODEL CNS 21-300, CHEM-NUCLEAR SYSTEMS, INC

8310170211 Requests registration as user of Model CNS 21-300
WELSH, J A International Neutronics, Inc 83/10/04 MACDONALD, C E Transportation Branch 1p 20798 083

DOCKET 71-9100 MODEL KKP-20-4950, KERR-MCQUEE NUCLEAR CORP.

8310050053 Forwards Rev 4 to Certificate of Compliance 9100 for Model KKP-20-4950
MACDONALD, C E Transportation Branch 83/09/26 SHELLEY, W J Kerr-McQuee Nuclear Corp 2pp 20650 145

--8310050057 Certificate of Compliance 9100, Rev 4, for Model KKP-20-4950
MACDONALD, C E Transportation Branch 83/09/26 4pp 20650 147

DOCKET 71-9103 MODEL RAD-WASTE CR. 1, CHEM-NUCLEAR SYSTEMS, INC

8310170192 Forwards response to B30425 questions re Model CNS 6-101 shipping package Rev 1 to SAR for Model CNS 6-101 also encl
POPPE, L K Chem-Nuclear Systems, Inc 83/09/30 MACDONALD, C E Transportation Branch 7pp 20813 011

--8310170195 Rev 1 to "SAR for Chem-Nuclear Sys, Inc Model CNS 6-101 Type A Radwaste Shipping Cask"
* Chem-Nuclear Systems, Inc 83/09/30 12pp 20813 017

DOCKET 71-9107 MODEL 771, TECHNICAL OPERATIONS, INC

8310170221 Requests registration as user of Models 741, 850, 920 & 771
MALINOWSKI, F A Ebasco Services, Inc (subs of Enserch Corp) 83/09/20 MACDONALD, C E Transportation Branch 2pp 20796 294

8310240292 Notification of registration as user of Models 741, 850, 920 & 771 in response to B30920 request
MACDONALD, C E Transportation Branch 83/10/18 BULLEN, H C Ebasco Services, Inc (subs of Enserch Corp) 1p 20904 349

DOCKET 71-9108 MODEL CNS 6-75, CHEM-NUCLEAR SYSTEMS, INC

831010628 Forwards Rev 4 to Certificate of Compliance 9108 for Model CNS 6-75
MACDONALD, C E Transportation Branch 83/09/30, DEAL, R Chem-Nuclear Systems, Inc 3pp 20706 349

--831010631 Certificate of Compliance 9108, Rev 4, for Model CNS 6-75
MACDONALD, C E Transportation Branch 83/09/30 5pp 20706 352

DOCKET 71-9111 MODEL CNS 6-80-2 & CNS 6-80-2A, CHEM-NUCLEAR SYS, INC.

8310170605 Advises that Model CNS 6-80-2 will be used for shipment of radioactive matl generated at Oyster Creek
FIEDLER, P B General Public Utilities - GPU Service Corp. 83/09/16 Office of Nuclear Material Safety & Safeguards, Director 3pp 20814 146

8310260013 Notification of registration as user of Model CNS 6-80-2 in response to B30916 request.
MACDONALD, C E Transportation Branch 83/10/18 SMIDER, T General Public Utilities - GPU Service Corp. 1p 20928 046

DOCKET 71-9126 MODEL 20, 20A, 50, 50A, GAMMA INDUSTRIES

8310170295 Forwards payments for request for renewal of Certificates of Compliance 9126, 9127 & 9128 which expire on 831031
Existing & future packages will be mfg & used according to previously submitted drawings & info
STUCKEY, S G Nuclear System 83/09/13 MACDONALD, C E Transportation Branch 2pp 20796 241

831010625 Forwards Rev 3 to Certificate of Compliance 9126 for Models 20, 20A, 50 & 50A
MACDONALD, C E Transportation Branch 83/10/06 RIDDLE, D H Nuclear System 2pp 20706 357

--831010627 Certificate of Compliance 9126, Rev 3, for Models 20, 20A, 50A
MACDONALD, C E Transportation Branch 83/10/06 3pp 20706 35

DOCKET 71-9127 MODEL 100, 100A, 200, 200A, GAMMA INDUSTRIES

8310170295 Forwards payments for request for renewal of Certificates of Compliance 9126, 9127 & 9128 which expire on 831031
Existing & future packages will be mfg & used according to previously submitted drawings & info
STUCKEY, S G Nuclear System 83/09/13 MACDONALD, C E Transportation Branch 2pp 20796 241

831010621 Forwards Rev 3 to Certificate of Compliance 9127 for Model 100, 100A, 200 & 200A
MACDONALD, C E Transportation Branch 83/10/06 RIDDLE, D H Nuclear System 2pp 20714 352

--831010623 Certificate of Compliance 9127, Rev 3, for Models 100, 100A & 200A
MACDONALD, C E Transportation Branch 83/10/06 3pp 20714 35

DOCKET 71-9128 MODEL C-8, GAMMA INDUSTRIES

8310170295 Forwards payments for request for renewal of Certificates of Compliance 9126, 9127 & 9128 which expire on 831031
Existing & future packages will be mfg & used according to previously submitted drawings & info
STUCKEY, S G Nuclear System 83/09/13 MACDONALD, C E Transportation Branch 2pp 20796 241

8310170355 Requests registration as user of Model C-8
KAWACHI, M H Navy, Dept of, Pearl Harbor Naval Shipyard 83/10/0 MACDONALD, C E Transportation Branch 1p 20793 238

831010611 Forwards Rev 3 to Certificate of Compliance 9128 for Model C-8
MACDONALD, C E Transportation Branch 83/10/06 RIDDLE, D H Nuclear System 2pp 20703 346

--831010614 Certificate of Compliance 9128, Rev 3, for Model C-8
MACDONALD, C E Transportation Branch 83/10/06 3pp 20703 34

DOCKET 71-9132 MODEL T-3, ENERGY, DEPT OF

8310170291 Forwards amended Page 6-6 to T-3 SAR clarifying B30215 request for addl info re test procedure insuring all residual sodium clarified
HANSEN, L J Pacific Nuclear Systems & Services, Inc 83/04/19 MACDONALD, C E Transportation Branch 3pp 20796 242

DOCKET 71-9143 MODEL 920, TECHNICAL OPERATIONS, INC

8310170221 Requests registration as user of Models 741, 850, 920 & 771
MALINOWSKI, F A Ebasco Services, Inc (subs of Enserch Corp) 83/09/20 MACDONALD, C E Transportation Branch 2pp 20796 294

8310240292 Notification of registration as user of Models 741, 850, 920 & 771 in response to B30920 request
MACDONALD, C E Transportation Branch 83/10/18 BULLEN, H C Ebasco Services, Inc (subs of Enserch Corp) 1p 20904 349

DOCKETED ITEMS

393

DOCKET 71-9145 MODEL NUPAC 50-1 5L, -2 5L, -3 0L & -4 0L, NO USERS

B310190285 Application for rev to Certificate of Compliance 9145 for NUPAC 50, upgrading const matl to ASTM A-516 Grade 70 HANSEN, L J Nuclear Packaging, Inc 80/09/19 MACDONALD, C E Transportation Branch 3pp 20840 204

--B310190288 Revised NUPAC 50 SAR
* Nuclear Packaging, Inc 80/09/19 125pp 20840 207

DOCKET 71-9147 MODEL 850, TECHNICAL OPERATIONS, INC

B310170221 Requests registration as user of Models 741, 850, 920 & 771 MALINOWSKI, F A Ebasco Services, Inc (subs of Enserch Corp) 83/09/20 MACDONALD, C E Transportation Branch 2pp 20794 274

B310240292 Notification of registration as user of Models 741, 850, 920 & 771 in response to B30920 request MACDONALD, C E Transportation Branch 83/10/18 BULLEN, H C Ebasco Services, Inc (subs of Enserch Corp) 1p 20904 349

DOCKET 71-9151 MODEL HN-100, SERIES 3, HITTMAN NUCLEAR & DEV CORP

B310030561 Forwards revised pages to B30629 application for Model HN-100, Series 3 packaging, per B30824 request Summary of changes encl W/five oversize drawings Aperture cards are available in PDR VOIT, R E NUB Corp 83/09/12 MACDONALD, C E Division of Fuel Cycle & Material Safety 2pp 20603 025

--B310030568 Rev C to Procedure WM-014, "Operating Instructions for Loading & Unloading NUS-14-170 Series 1 Cask"
* NUB Corp 83/09/12 18pp 20603 027

--B310030574 Rev B to Procedure WM-012, "NUS-14-170 Series 1 Maint"
* NUB Corp 83/09/12 13pp 20603 045

DOCKET 71-9152 MODEL CNS 1-13C II, CHEM-NUCLEAR SYSTEMS, INC

B310070059 Forwards Rev 4 to Certificate of Compliance 9152 for Model CNS 1-13C II MACDONALD, C E Transportation Branch 83/09/26 DEAL, R Chem-Nuclear Systems, Inc 2pp 20671 344

--B310070062 Certificate of Compliance 9152, Rev 4, for Model CNS 1-13C II MACDONALD, C E Transportation Branch 83/09/26 4pp 20671 346

DOCKET 71-9158 MODEL CNS 3-70, RIDIHALGH, EGGERS & ASSOCIATES

B310050021 Ack withdrawal of B20126 application requesting approval of Model CNS 3-70 packaging Review terminated MACDONALD, C E Transportation Branch 83/09/23 EGGERS, P E Ridihaigh, Eggers & Associates 1p 20650 272

DOCKET 71-9159 MODEL NUPAC 14/190L, /190M & /190H, NUCLEAR PACKAGING, INC

B310190351 Requests registration as user of Models NUPAC 14/190L, NUPAC 14/190H, NUPAC 14/190M & SN-1 Forwarding address for all future correspondence provided DEAL, R L Chem-Nuclear Systems, Inc 83/09/22 MACDONALD, C E Transportation Branch 2pp 20843 171

B310240297 Notification of registration as user of Models SN-1 & NUPAC-14/190L, 14/190H & 14/190M in response to B30922 request MACDONALD, C E Transportation Branch 83/10/18 DEAL, R Chem-Nuclear Systems, Inc 1p 20904 350

DOCKET 71-9160 MODEL 20-VS & 40-VS, GULF NUCLEAR, INC

B310130384 Forwards application for Type B certification for 20-VS & 40-VS radiography camera HOPCRAFT, C P Gulf Nuclear, Inc 83/09/16 MACDONALD, C E Transportation Branch 1p 20770 017

--B310130386 Application for Type B certification for 20-VS & 40-VS radiography camera
* Gulf Nuclear, Inc 83/09/16 33pp 20770, 018

DOCKET 71-9163 MODEL GNQ-20, GULF NUCLEAR, INC

B310030028 Requests registration as user of Model GNQ-20 PITTS, R W Petroleum Measurement Corp 83/08/30 MACDONALD, C E Transportation Branch 1p 20602 356

DOCKET 71-9181 MODEL PAS-2, NUCLEAR PACKAGING, INC

B310210331 Forwards Rev 1 to SAR in response to B30727 comments Rev provides testable containment boundary within sample shield cavity Authorization to ship NUPAC PAS-2 packaging by air requested HANSEN, L J Nuclear Packaging, Inc 83/09/09 MACDONALD, C E Transportation Branch 3pp 20882 157

--B310210333 Rev 1 to NUPAS-2 SAR, changing containment boundary sample shield
* Nuclear Packaging, Inc 83/09/09 55pp 20882 160

DOCKET 71-9182 MODEL HUSMAN IRRADIATOR, AGRICULTURE, DEPT OF

B310040171 Forwards request for addl info re B30516 application for Model Husman Irradiator packaging Addl info should be submitted in form of revised pages Response schedule requested within 30 days MACDONALD, C E Transportation Branch 83/09/22 STREUTKER, B R Nuclear Packaging, Inc 3pp 20627 360

B310170344 Forwards Rev 1 amends to Husman Irradiator SAR TEMUS, C J Nuclear Packaging, Inc 83/10/03 MACDONALD, C E Transportation Branch 1p 20796 299

--B310170349 Rev 1 amends to Husman Irradiator SAR
* Nuclear Packaging, Inc 83/10/31 13pp 20796 300

B310310481 Forwards request for addl info re B30516 application, supplemented B31003, for approval of Husman Irradiator packaging Notification of planned submittal date requested within 30 days MACDONALD, C E Transportation Branch 83/10/21 TEMUS, C J Nuclear Packaging, Inc 2pp 20965 188

DOCKET 71-9184 MODEL PAS-1, NUCLEAR PACKAGING, INC

B310200408 Application for certificate of compliance for Model PAS-1 TEMUS, C J Nuclear Packaging, Inc 83/10/06, MACDONALD, C E Transportation Branch 9pp 20874 073

--B310200415 "SAR for NUPAC PAS-1 Packaging to 10CFR71 Type B Packaging Requirements"
* Nuclear Packaging, Inc 83/10/06 137pp 20874 082

DOCKET 71-9180 MODEL OPHS, ENERGY, DEPT OF

B310050025 Forwards Rev O to Certificate of Compliance 9510 for Model General Purpose Heat Source Container MACDONALD, C E Transportation Branch 83/09/23 PRICHARD, R P Energy, Dept of 1p 20650 273

--B310050030 Certificate of Compliance 9510, Rev O, for Model General Purpose Heat Source Container MACDONALD, C E Transportation Branch 83/09/23 5pp 20650, 274

DOCKET 71-9852 MODEL DT-14, ENERGY, DEPT OF

B310060023 Summary of B30922 meeting w/DDE & Union Carbide in Silver Spring, MD re proposed mods to Model DT-14 shipping container LAKE, W H Office of Nuclear Material Safety & Safeguards, Director, 83/09/23 Office of Nuclear Material Safety & Safeguards, Director 1p 20663 362

B310240299 Forwards Rev 2 to Certificate of Compliance 9852 for Model DT-14 MACDONALD, C E Transportation Branch 83/10/18 WEINTRAUB, A A Energy, Dept of 1p 20904 351

--B310240303 Certificate of Compliance 9852, Rev 2, for Model DT-14 MACDONALD, C E Transportation Branch 83/10/18, 4pp 20904, 352

DOCKETED ITEMS

LICENSING OF INDEPENDENT SPENT FUEL STORAGE

DOCKET 72-0001 MORRIS OPERATIONS, GENERAL ELECTRIC CO

8310140212 Forwards IE Insp Rept 72-0001/83-03 on 830729-0922 No
noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 83/09/29 VAN
HOOMIGSEN General Electric Co 2pp 20762 296

--8310140216 IE Insp Rept 72-0001/83-03 on 830729-0922 No noncompliance
noted Major areas inspected spent reactor fuel shipping &
general plant maint activities, radwaste mgt, 10CFR21
reporting & periodic maint of packaging
LOVENDALE, P C , GREGOR, L R , PIRTLE, G L Region 3, Office of
Director 83/09/29 9pp 20762 298

NONDOCKETED ITEMS

CFR COMMISSION MEETING RECORDS

0040117 Transcript of 830916 meeting w/Advisory Panel on
decontamination of TMI-2 in Washington, DC Pp 1-65
* Commissioners 83/09/16 69pp 20634 252 24X
Fiche 50-320, 83/09/16, 8310040117

0040592 Staff requirements memo re 830921 discussion in
Washington, DC re public comments on waste confidence
decision & proposed revs to 10CFR50 & 51 Commission
continued meeting in closed session
HIVLE, J C Office of the Secretary of the Commission MB30921B
83/09/23 ZERDE, J C Office of Policy Evaluations 1p 20627 348

0050107 Staff requirements memo re 830921 affirmation/discussion &
vote in Washington, DC on Washington Legal Foundation motion
to disqualify Commissioner Olinisky Order disposing of
motion approved
HIVLE, J C Office of the Secretary of the Commission MB30921C
83/09/22 Office of the Secretary of the Commission 1p
20450 239

0050442 Transcript of Commission 830927 briefing in Washington, DC re
facility schedule Pp 1-34 Viewgraphs & supporting
documentation encl
* Commissioners 83/09/27 52pp 20640 218 24X
Fiche 50-275, 83/09/27, 8310050442

0050448 Transcript of 830927 briefing in Washington, DC re rept of
Committee on Rights of Individuals in Investigations
Pp 1-39 Supporting documentation encl
* Commissioners 83/09/27 67pp 20640 146

0050450 Transcript of 830928 briefing by Torrey Pines, Inc in
Washington, DC re independent review of util project
Pp 1-66 Supporting documentation encl
* Commissioners 83/09/28 133pp 20640 001 24X
Fiche 50-358, 83/09/28, 8310050450

0060463 Staff requirements memo on 830927 briefing in Washington, DC
re rept of Committee on Rights of Individuals in
Investigations
CHILK, S J Office of the Secretary of the Commission MB30927A
83/09/30 PLAINE, H E Office of the General Counsel HAYES, B B
Office of Investigation 1p 20650 361

0070209 Staff requirements memo re 830927 discussion of proceeding
schedule Commission will hold 831028 public meeting in
Washington, DC re issues related to fuel loading
CHILK, S J Office of the Secretary of the Commission MB30927B
83/09/30 Office of the Secretary of the Commission 1p
20674:362 24X Fiche 50-275, 83/09/30, 8310070209

0110075 Transcript of 830930 affirmation/discussion & vote in
Washington, DC re BECY-83-343, "Final Rule on Temporary OL
Authority " Pp 1-4
* Commissioners 83/09/30 7pp 20682 348

0110427 Transcript of 830930 discussion/possible vote in Washington,
DC on BECY-83-293 re amends to 10CFR50 concerning ATWS
Pp 1-73 Supporting documentation encl
* Commissioners 83/09/30 88pp 20686 048

0120017 Transcript of 831004 public meeting in Washington, DC re
proposed insider safeguards rule Pp 1-94 Viewgraphs encl
* Commissioners 83/10/04, 105pp 20750 189

0120029 Transcript of 831003 open session in Washington, DC re
emergency planning Pp 1-28, Supporting documentation encl
* Commissioners 83/10/03 111pp 20750: 076 24X
Fiche 50-003, 83/10/03, 8310120029

8310120031 Transcript of 831003 briefing in Washington, DC on BWR pipe
crack issues Pp 1-68 Supporting documentation encl
* Commissioners 83/10/03 74pp 20750 001

8310130123 Staff requirements memo re 830930 discussion & possible vote
in Washington, DC on proposed rules on ATWS contained in
BECY-83-293
CHILK, S J Office of the Secretary of the Commission MB30930A
83/10/03 Office of the Secretary of the Commission 1p
20777 021

8310130372 Transcript of 831006 briefing in Washington, DC re results
of GPU & B&W trial matl Pp 1-42 Supporting documentation
encl
* Commissioners 83/10/06 61pp 20770 052 24X
Fiche 50-289, 83/10/06, 8310130372

8310130392 Transcript of 831007 briefing by Swedish representatives on
PIUS reactor in Washington, DC Pp 1-84 Supporting
documentation encl
* Commissioners 83/10/07 84pp 20770 193

8310130403 Staff requirements memo re 831004 discussion of proposed
insider safeguards rule, per BECY-83-311 & 83-311A in
Washington, DC
CHILK, S J Office of the Secretary of the Commission MB31004
83/10/07 DIRCKS, W J Office of the Executive Director for
Operations ZERBE, J E Office of Policy Evaluations 2pp
20769 345

8310130408 Staff requirements memo re 830916 periodic meeting in
Washington, DC w/Advisory Panel on decontamination of TMI-2
CHILK, S J Office of the Secretary of the Commission MB30916C
83/10/07 DIRCKS, W J Office of the Executive Director for
Operations FOUCHARD, J J Office of Public Affairs FRALEY, R F
ACRS - Advisory Committee on Reactor Safeguards 2pp 20769 348
24X Fiche 50-320, 83/10/07, 8310130408

8310170056 Staff requirements memo re 831007 briefing by Swedish
representatives on PIUS reactor
CHILK, S J Office of the Secretary of the Commission MB31007A
83/10/11 Office of the Secretary of the Commission 1p
20798 056

8310170058 Staff requirements memo re 831003 briefing on BWR pipe
crack issues
CHILK, S J Office of the Secretary of the Commission MB31003B
83/10/07 DIRCKS, W J Office of the Executive Director for
Operations 1p 20798 055

8310170321 Staff requirements memo re Commission 831003 briefing by
FEMA on recent emergency planning exercises in vicinity of
facilities Commission noted successful completion of
exercise Enforcement action unnecessary
CHILK, S J Office of the Secretary of the Commission MB31006A
83/10/11 Office of the Secretary of the Commission 1p
20795 277 24X Fiche 50-247, 83/10/11, 8310170321

8310170695 Staff requirements memo re 831006 briefing on results of
GPU vs B&W trial matl & other uncontested matters re TMI-1
restart Commission made no requests & took no action
CHILK, S J Office of the Secretary of the Commission MB31006A
83/10/06 Office of the Secretary of the Commission 1p
20798:158 24X Fiche 50-289, 83/10/06, 8310170695

8310180035 Staff requirements memo on Torrey Pines, Inc 830928 briefing
in Washington, DC re independent review of project mgt
CHILK, S J Office of the Secretary of the Commission MB30928
83/10/03 DIRCKS, W J Office of the Executive Director for
Operations 1p, 20825 038 24X Fiche 50-358, 83/10/03, 8310180035

NONDOCKETED ITEMS

8310180041 Staff requirements memo on 830930 affirmation/discussion & vote in Washington, DC re final rule on temporary OL authority (SECY-83-343/343A) Separate views of Commissioners Glinitsky & Asselstine encl
CHILK, S J Office of the Secretary of the Commission MB30930B
83/10/05 DIRCKS, W J Office of the Executive Director for Operations
KAMMERER, C Office of Congressional Affairs
FOUCHARD, J J Office of Public Affairs. 6pp 20825 032

8310190267 Transcript of 831013 briefing in Washington, DC re automatic data processing organization Pp 1-50 Viewgraphs encl
* Commissioners 83/10/13 70pp 20843 187

8310210147 Staff requirements memo re 831013 briefing in Washington, DC on automatic data processing organization
CHILK, S J Office of the Secretary of the Commission MB31013
83/10/17 Office of the Secretary of the Commission 1p
20883 356

8310270132 Responds to FOIA request for info re possible rev to radiological emergency planning guidance & info on whether NRC emergency planning regulations appropriate in light of anticipated accident scenarios Forwards documents
FELTON, J M Division of Rules and Records. 83/07/15
BRANDENBURG, B Consolidated Edison Co of New York, Inc 1p
20942 235.

8310270145 Staff requirements memo re 821110 briefing in Washington, DC on Sandia consequences study Commission briefed on NUREG/CR-2239 (SAND81-1549), "Technical Guidance for Siting Criteria Development" Viewgraph encl.
CHILK, S J Office of the Secretary of the Commission MB21110B
82/11/18 DIRCKS, W J Office of the Executive Director for Operations 3pp. 20942 237

ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

8310060260 Transcript of ACRS Subcommittee on DHR Sys 831004 meeting in Washington, DC Pp 1-294 Viewgraphs encl
* ACRS - Advisory Committee on Reactor Safeguards 83/10/04
425pp 20642 335

8310120168 Transcript of ACRS Subcommittee on Limerick Generating Station Units 1 & 2 831008 meeting in Pottstown, PA Pp 253-330
* ACRS - Advisory Committee on Reactor Safeguards 83/10/08
278pp 20693-349 24X Fiche 50-352, 83/10/08, 8310120168

8310120176 Transcript of ACRS Subcommittee on Limerick Generating Station Units 1 & 2 831007 meeting in Pottstown, PA Pp 1-252 Viewgraphs encl
* ACRS - Advisory Committee on Reactor Safeguards 83/10/07
272pp 20694, 267. 24X Fiche 50-352, 83/10/07, 8310120176

8310140113 Transcript of ACRS Subcommittee on Metal Components & DHR 831012 meeting in Washington, DC Pp 1-139 Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards 83/10/12
165pp. 20764 011.

8310140115 Transcript of ACRS Subcommittee on Extreme External Phenomena 831012 meeting in Washington, DC Pp 1-116 Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards 83/10/12
136pp. 20764 177.

8310140124 Transcript of ACRS Subcommittee on Class 9 Accidents 831012 meeting in Washington, DC Pp 1-167 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/10/12
257pp. 20763; 087

8310170135 Transcript of ACRS 282nd general meeting on 831013 in Washington, DC Pp 1-352. Supplementary documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/10/13
529pp. 20792 139.

8310180091 Transcript of ACRS 282nd general meeting on 831014 in Washington, DC Pp 353-378 Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards 83/10/14
308pp. 20807 222

8310310462 Summarizes ACRS 282nd meeting on 831013-15 re draft, "Severe Accident Decisions for Existing Nuclear Power Plants." Blending deterministic & probabilistic approaches endorsed
RAY, J J ACRS - Advisory Committee on Reactor Safeguards. 83/10/18
DIRCKS, W J Office of the Executive Director for Operations 1p
20965, 161

8310310465 Summarizes ACRS 282nd meeting on 831013-15 on NRC integrative program for resolution of Unresolved Safety Issues A-3, A-4 & A-5 re PWR steam generators Proposals should be implemented as recommendations only
RAY, J J ACRS - Advisory Committee on Reactor Safeguards 83/10/18
PALLADINO, N J Commissioners 1p 20965 160

ADVCM NRC ADVISORY COMMITTEE

8310030524 Notification of contract execution, Mod 1 to "Advisory Committee for Review of Dfc of Investigation Policy on Rights of Licensee Employees Under Investigation" Contractor Schwalb, Donnenfeld, Bray & Silbert
TOWNSEND, B Administrative Contracts Branch FIN B-8182
NRC-18-83-406 83/09/21 FITZGERALD, J A Office of the General Counsel LEVI, R NRC - No Detailed Affiliation Given 1p
20602 394

8310030534 Mod 1, extending period of performance to 830930 & increasing funding to "Advisory Committee for Review of Dfc of Investigation Policy on Rights of Licensee Employees Under Investigation" Contractor Schwalb, Donnenfeld, Bray & Silbert
TOWNSEND, B Administrative Contracts Branch FIN B-8182
NRC-18-83-406 83/09/21 1p 20602 355

8310040117 Transcript of 830716 meeting w/Advisory Panel on Decontamination of TMI-2 in Washington, DC Pp 1-65
* Commissioners 83/07/16 69pp 20634 232 24X
Fiche 50-320, 83/07/16, 8310040117

8310050448 Transcript of 830927 briefing in Washington, DC re rept of Committee on Rights of Individuals in Investigations
Pp 1-35 Supporting documentation encl
* Commissioners 83/09/27 67pp 20640 146

8310060463 Staff requirements memo on 830927 briefing in Washington, DC re rept of Committee on Rights of Individuals in Investigations
CHILK, S J Office of the Secretary of the Commission MB30927A
83/09/30 PLATNE, H E Office of the General Counsel HAYES, B B Office of Investigation 1p 20630 361

8310130408 Staff requirements memo re 830916 periodic meeting in Washington, DC w/Advisory Panel on decontamination of TMI-2
CHILK, S J Office of the Secretary of the Commission MB30916C
83/10/07 DIRCKS, W J Office of the Executive Director for Operations FOUCHARD, J J Office of Public Affairs FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards 2pp. 20769 348
24X Fiche 50-320, 83/10/07, 8310130408

8310140025 Resigns as chairman of Advisory Panel for Decontamination of TMI-2 Facility should be closed Public deserves faster cleanup
MINNICH, J E Advisory Council for Decontamination of TMI Unit 2
83/10/05 PALLADINO, N J Commissioners 1p 20768 077 24X
Fiche 50-320, 83/10/05, 8310140025

8310190341 Transcript of 830927 public meeting in Middletown, PA re reactor bldg polar crane Pp 1-172 Supporting documentation encl
* Commissioners 83/09/27 212pp 20842 306 24X
Fiche 50-320, 83/09/27, 8310190341

8310200347 Transcript of Advisory Panel for Decontamination of TMI-2 830928 public meeting in Harrisburg, PA Pp 1-109 Supporting documentation encl
* Advisory Council for Decontamination of TMI Unit 2 83/09/28
207pp 20873 095 24X Fiche 50-320, 83/09/28, 8310200347

8310210337 Notification of contract execution, Mod 1A to "Advisory Committee for Review of Dfc of Investigation Policy on Rights of Licensee Employees Under Investigation" Contractor Kator, Scott & Heller
TOWNSEND, B Purchasing Section FIN B-8182 NRC-18-83-409
83/09/20 FITZGERALD, J A Office of the General Counsel LEVI, R NRC - No Detailed Affiliation Given 1p 20882 362

COMMISSION NRC COMMISSIONERS

8310060521 Weekly info rept for wk ending 830923
REHM, T A Office of the Executive Director for Operations
83/09/29 39pp 20662 320

8310060591 Forwards response to 830727 questions re NRC inquiry team 830628 meeting in New Orleans, LA Inquiry team 830714 rept on QA allegations & IE 830804 status rept encl
PALLADINO, N J Commissioners 83/09/08 MARKEY, E J House of Rep. Interior & Insular Affairs 7pp 20661 160 24X
Fiche 50-382, 83/09/08, 8310060591

NONDOCKETED ITEMS

39

- B310060593 Forwards inquiry team rept re GA allegations Meeting to discuss followup requested
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/08/04 CAIN, J M Louisiana Power & Light Co
ip 20661 183 24x Fiche 50-382, 83/09/08, B310060591
- B310060594 Requests info re circumstances of June 1983 interviews w/NRC investigation team
MARKEY, E J House of Rep , Interior & Insular Affairs 83/07/27
PALLADINO, N J Commissioners ip 20661 192 24x
Fiche 50-382, 83/09/08, B310060591
- B310070041 Responds to 830623 request for views on SB 1275.
"Administrative Law Judge (ALJ) Corps Act " Act acceptable
Bill leaves existing Commission authority to use boards
independent of ALJ Corps
PALLADINO, N J Commissioners 83/09/12 FREY, J M President of US
& Executive Offices 2pp 20680 058
- B310070043 Forwards SB 1275, "Administrative Law Judge (ALJ) Corps " Comments due by 830722
SHEENEY, N R President of US & Executive Offices 83/04/23
Office of Congressional Affairs 25pp 20680 060
- B310070363 Responds to 830628 ltr re Inside NRC article reporting J Tourtellotte remarks on backfitting Reassignment of J Tourtellotte due to strong views for reform not acceptable
PALLADINO, N J Commissioners 83/09/13 WEISS, E R Union of Concerned Scientists ip 20664 307
- B310070369 Informs that 830516 request for reassignment of JR Tourtellotte mistakenly not sent to Commissioners
Tourtellotte alleged behavior at conference clarified JR Tourtellotte 830614 response encl
WEISS, E R Union of Concerned Scientists 83/06/28
PALLADINO, N J, GILINSKY, V, AHEARNE, J Commissioners 2pp 20664 308
- B310070377 Clarifies position on need for public predistribution of potassium iodide. Revised rept re cost/benefit & advisability of stockpiling/predistributing being evaluated
PALLADINO, N J Commissioners 83/09/13 MARKEY, E J House of Rep , Interior & Insular Affairs 3pp 20664 335
- B310070380 Comments on NRC negligence in not developing unified natl policy on distribution of potassium iodide. Views expressed at Subcommittee on Oversight & Investigations 820303 hearing
MARKEY, E J House of Rep , Interior & Insular Affairs 83/08/11
PALLADINO, N J Commissioners 3pp 20664 338
- B310070383 Responds to 830818 request to initiate immediate proceedings to solicit public comment on safety of continued plant operation pending full environ review Commission intends to initiate rulemaking per UCS vs NRC proceeding
CHILKIS, J Office of the Secretary of the Commission 83/09/02
WEISS, E R Harmon & Weiss WEISS, E R Union of Concerned Scientists ip 20664:341
- B310070386 Requests Commission immediately commence proceedings to solicit public comment on continued plant operation w/o environ qualification of equipment important to safety.
WEISS, E R Harmon & Weiss WEISS, E R Union of Concerned Scientists 83/08/18 PALLADINO, N J, ASSELSTINE, J, GILINSKY, V Commissioners 2pp 20664 342
- B310110002 Forwards "Rept on Regulatory Utilization of Research," to fulfill Energy & Water Development Appropriations Bill for FY83 requirements for relevancy of NRC research program to regulatory program W/o encl
ROBERTS, T M Commissioners 83/09/15 OTTINGER, R L House of Rep , Energy & Commerce ip 20709 212
- B310110006 Forwards "Rept on Regulatory Utilization of Research," to fulfill Energy & Water Development Appropriations Bill for FY83 requirements for relevancy of NRC research program to regulatory program W/o encl
ROBERTS, T M Commissioners 83/09/15 SIMPSON, A Senate, Environment & Public Works ip 20709 213.
- B310110008 Forwards "Rept on Regulatory Utilization of Research," to fulfill Energy & Water Development Appropriations Bill for FY83 requirements for relevancy of NRC research program to regulatory program W/o encl
ROBERTS, T M Commissioners 83/09/15 UDALL, M House of Rep , Interior & Insular Affairs. ip. 20709-214
- B310110012 Forwards "Rept on Regulatory Utilization of Research," to fulfill Energy & Water Development Appropriations Bill for FY83 requirements for relevancy of NRC research program to regulatory program W/o encl
ROBERTS, T M Commissioners 83/09/15 HATFIELD, M O Senate, Appropriations ip 20709 215
- B310110014 Forwards "Rept on Regulatory Utilization of Research," to fulfill Energy & Water Development Appropriations Bill for FY83 requirements for relevancy of NRC research program to regulatory program
ROBERTS, T M Commissioners 83/09/15 BEVILL, T House of Rep Appropriations ip 20709 216
- B310110015 "Rept on Regulatory Utilization of Research " * Office of Nuclear Regulatory Research, Director 83/08/31 Bipp 20709 217
- B310110073 Confirms Commissioner Asselstine 830809 telcon requesting increase of funds for FY84 for 90 full-time equivalent positions to implement responsibilities under Nuclear Waste Policy Act of 1982
PALLADINO, N J Commissioners 83/09/19 KHEDOURI, F N. Office of Management & Budget ip 20687 336
- B310110352 Forwards response to 830728 request for info on conduct of litigation involving NRC
PALLADINO, N J Commissioners 83/09/13 DINGELL, J D House of Rep , Energy & Commerce 9pp 20713 209
- B310110354 Requests addl info re control & mgt of litigation of agencies within Committee on Energy & Commerce
Jurisdiction Response by 830819 requested
DINGELL, J D House of Rep , Energy & Commerce 83/07/28
PALLADINO, N J Commissioners 2pp 20713 218
- B310110589 Responds to 830817 ltr urging NRC to undertake addl research on effects of work schedules & shift rotations on operational performance as part of human factors program
Expanded research program beyond scope of current plans
PALLADINO, N J Commissioners 83/09/22 GORE, A House of Rep , Science & Technology 2pp 20703 353
- B310110594 Responds to 830817 ltr urging NRC to undertake addl research on effects of work schedules & shift rotations on operational performance as part of human factors program
Expanded research program beyond scope of current plans.
PALLADINO, N J Commissioners 83/09/22 SKEEN, J House of Rep Science & Technology 2pp 20703 355
- B310110597 Urges NRC undertake addl research on effects of work schedules & shift rotations on operational performance as part of human factors program
GORE, A, SKEEN, J. House of Rep., Science & Technology. 83/08/17
PALLADINO, N J Commissioners 2pp 20703 357
- B310110608 Forwards fourth monthly FR notice of amends issued or proposed to be issued based on NBHC determination W/o encl.
DENTON, H R. Office of Nuclear Reactor Regulation, Director 83/09/08 STAFFORD, R T, SIMPSON, A. Senate, Environment & Public Works UDALL, M K House of Rep , Interior & Insular Affairs 2pp 20703 351
- B310110612 Requests appointment of state liaison officer to NRC. Appointee will be invited to natl/state liaison officer
B31206-07 meetings in Washington, DC
PALLADINO, N J Commissioners 83/09/22 HUNT, J B North Carolina, State of ip 20703 359
- B310110615 Notification of natl state liaison officer B31206-07 meetings in Washington, DC Agenda encl
KERR, G W Office of State Programs, Director 83/09/16, Office of State Programs, Director 3pp 20703 360
- B310120467 Weekly info rept for wk ending 830930
REHM, T A Office of the Executive Director for Operations. 83/10/06 65pp. 20750:300.
- B310140025 Resigns as chairman of Advisory Panel for Decontamination of TMI-2. Facility should be closed Public deserves faster cleanup
MINNICH, J E Advisory Council for Decontamination of TMI Unit 2 83/10/05 PALLADINO, N J. Commissioners ip 20768 077 24X
Fiche 50-320, 83/10/05, B310140025
- B310140027 Urges Commission to reject util emergency preparedness plan. State of NY will not impose radiological emergency preparedness plan on Suffolk County County will refrain from implementing plan Public safety cannot be assured
CUOMO, M New York, State of ISBUANCES OL-3. 83/10/04. PALLADINO, N J Commissioners 2pp 20767 349 24X
Fiche 50-322, 83/10/04, B310140027

NONDOCKETED ITEMS

- 8310140028 Forwards Ofc of Investigations rept. "TMI Nuclear Generating Unit 2 Allegations re Safety-Related Mods: QA Procedures & Use of Polar Crane." Prompt attention should be given to mgt controls over Bechtel cleanup activities W/o encl
PALLADINO, N J Commissioners 83/10/07 KUKINS, W General Public Utilities - GPU Service Corp 2pp 20767 347 24X
Fiche 50-320, 83/10/07, 8310140028
- 8310170361 Weekly info rept for wk ending 831007
REHM, T A Office of the Executive Director for Operations
83/10/13 42pp 20793 196
- 8310170686 Responds to 830914 ltr expressing concern re proposed release of radwaste water containing significant amounts of tritium into Susquehanna River Proposal for disposal of processed accident water not yet received
DIRCKS, W J Office of the Executive Director for Operations
83/10/03 BARBANES, P B Senate 4pp 20798 166 24X
Fiche 50-320, 83/10/03, 8310170686
- 8310170690 Expresses concern re proposed release of radwaste water containing significant amounts of tritium into Susquehanna River, citing potential impact on Chesapeake Bay
BARBANES, P B Senate 83/09/14 PALLADINO, N J Commissioners 1p 20798 170 24X Fiche 50-320, 83/10/03, 8310170686
- 8310170694 Responds to 830817 ltr re EPA proposed stds for disposal of high level radwaste Assurance requirements not necessary part of EPA stds & should not be promulgated in 40CFR191.
PALLADINO, N J Commissioners 83/09/29 RUCKELSHAUS, W Environmental Protection Agency. 2pp 20798 159
- 8310170699 Responds to 830511 ltr re NRC views on assurance requirements in EPA proposed stds for disposal of high level radwaste Most public comments favored assurance requirements as essential part of rule
RUCKELSHAUS, W Environmental Protection Agency 83/08/17.
PALLADINO, N J Commissioners. 2pp 20798 161
- 8310170701 Expresses dissatisfaction w/DOE actions in approving EURATOM request to retransfer 143 metric tons of US-origin heavy water from West Germany to Argentina NRC was not provided complete & accurate info on Executive Branch position
PALLADINO, N J Commissioners 83/10/04 HOEDEL, D P Energy, Dept of 3pp 20798 154
- 8310170704 Requests new state liaison officer to NRC be appointed. Natl state liaison meeting will be held on 831206-07 in Washington, DC
PALLADINO, N J Commissioners. 83/09/29 ROCKEFELLER, J West Virginia, State of 1p 20798 130
- 8310180010 Advises that hearing process has not delayed any nuclear power plant operation & that Commission does not know of unnecessary backfit requirements, in response to 830720 inquiry
PALLADINO, N J Commissioners 83/09/29 MITCHELL, G J Senate, Environment & Public Works 1p 20823:076.
- 8310180016 Requests info re possible instances where hearing process has delayed nuclear power plant operation & info re unnecessary backfitting requirements
MITCHELL, G J Senate, Environment & Public Works 83/07/20.
PALLADINO, N J Commissioners 2pp 20825:077
- 8310200062 Responds to 830913 ltr re investigation of QA/QC program at facility
PALLADINO, N J Commissioners 83/10/07 UDALL, M K House of Rep , Interior & Insular Affairs. 3pp. 20872 280 24X
Fiche 50-445, 83/10/07, 8310200062.
- 8310200068 Forwards findings ltr dtd 820907 re CA Atchison & Tompkins-Beckwith, Inc.
BASS, C H Labor, Dept of. 82/09/27 DRIBWELL, D. Region 4, Office of Director 7pp 20873 005
- 8310200073 Requests copies of listed documents re QA/QC program problems at facility.
UDALL, M K. House of Rep , Interior & Insular Affairs. 83/09/13.
PALLADINO, N J Commissioners 2pp. 20873:073. 24X
Fiche 50-445, 83/10/07, 8310200062.
- 8310200442 Responds to 830922 ltr re NRC handling of several working papers for case studies being conducted to support NRC rept to Congress per Section 13 of NRC Authorization Act Three working papers encl
PALLADINO, N J Commissioners. 83/10/07 FORD, W. H. Senate. 3pp. 20871 293 24X Fiche 50-000, 83/10/07, 8310200442.
- 8310200449 Responds to 830922 ltr re NRC handling of several working papers for case studies being conducted to support rept to Congress per Section 13 of NRC Authorization Act Summary chronology of actions encl
PALLADINO, N J Commissioners 83/10/07 MARKEY, E J House of Rep , Interior & Insular Affairs 7pp 20871 298 24X
Fiche 50-000, 83/10/07, 8310200442
- 8310200455 Expresses appreciation for cooperation w/IE activities to comply w/Congressional directive to NRC to perform GA studies Draft working paper for study encl
TAYLOR, J M Division of QA, Safeguards & Inspection Programs (Post 830103) 83/08/02 KELLY, R J Georgia Power Co 1p 20871 307 24X Fiche 50-000, 83/10/07, 8310200442
- 8310200457 Forwards "QA Case Study Working Paper, Case C " Document no longer draft
ALTHAM, W D NRC - No Detailed Affiliation Given 83/09/27 NRC
- No Detailed Affiliation Given 1p 20871 311 24X
Fiche 50-000, 83/10/07, 8310200442
- 8310200459 "QA Case Study Working Paper Case C," revised draft working paper
* Affiliation Unknown 83/09/19 NRC - No Detailed Affiliation Given 43pp 20871 312 24X Fiche 50-000, 83/10/07, 8310200442
- 8310200461 Paper entitled, "NRC Site Assessments & QA Reviews Special Study of Nuclear GA, QA Case Studies," presented at tenth annual Natl Energy Div Conference
ALTHAM, W D GA Branch. 83/10/07 8pp 20871 354 24X
Fiche 50-000, 83/10/07, 8310200442
- 8310200463 Forwards undated "QA Case Study Working Paper, Case A, Draft Working Paper"
ALTHAM, W D NRC - No Detailed Affiliation Given 83/09/27 NRC
- No Detailed Affiliation Given 70pp 20872 016 24X
Fiche 50-000, 83/10/07, 8310200442
- 8310200464 Forwards "QA Case Study Working Paper, Case B," draft working paper
ALTHAM, W D NRC - No Detailed Affiliation Given 83/09/27 NRC
- No Detailed Affiliation Given 73pp 20872 094 24X
Fiche 50-000, 83/10/07, 8310200442
- 8310200466 "QA Case Study Working Paper Case C," draft working paper
* NRC - No Detailed Affiliation Given 83/07/31 51pp
20872 165 24X Fiche 50-000, 83/10/07, 8310200442
- 8310200467 Expresses concern re release of draft repts concerning QA at nuclear power plants to licensees
FORD, W H Senate 83/09/22 PALLADINO, N J Commissioners 2pp 20872 215 24X Fiche 50-000, 83/10/07, 8310200442
- 8310200469 Expresses disappointment re release of draft study on QA programs at Diablo Canyon to licensees, Full explanation requested
MARKEY, E J House of Rep , Interior & Insular Affairs 83/09/21
PALLADINO, N J Commissioners 2pp 20872:217 24X
Fiche 50-000, 83/10/07, 8310200442
- 8310260060 Weekly info rept for wk ending 831014
REHM, T A Office of the Executive Director for Operations
83/10/20 33pp 20921 319
- CONTRACT NRC CONTRACTS AND MODIFICATIONS
- 8310030324 Notification of contract execution, Mod 1 to "Advisory Committee for Review of Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation."
Contractor Schwalb, Donnenfeld, Bray & Silbert
TOWNBEND, B Administrative Contracts Branch FIN B-8182
NRC-18-83-406 83/09/21 FITZGERALD, J A Office of the General Counsel LEVI, R NRC - No Detailed Affiliation Given 1p 20602:354
- 8310030334 Mod 1, extending period of performance to 830930 & increasing funding, to "Advisory Committee for Review of Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation"
SILBERT, E J Schwalb, Donnenfeld, Bray & Silbert REBELLO, J E Administrative Contracts Branch FIN B-8182 NRC-18-83-406 83/09/21 1p 20602 355
- 8310030319 Notification of contract execution "Autoprint 1800 "F" Microfiche Printer," awarded to Tameron, Inc
FIELDER, J A Administrative Contracts Branch NRC-10-83-723
83/09/21. BEBAM, W. Division of Technical Information & Document Control SKOZCLAS, J NRC - No Detailed Affiliation Given 1p 20650:288

NONDOCKETED ITEMS

399

--B310050323 Contract "Autoprint 1800 "F" Microfiche Printer," awarded to Tameron, Inc
* Tameron, Inc MATTIA, M J Division of Contracts
NRC-10-83-723 83/09/21 10pp 20650 289

B310050336 Notification of contract execution, Mod 7 to "Trench Design & Const Techniques " Contractor US Army Corps of Engineers
UMBEL, D M Technical Assistance Contracts Branch FIN B-6981
NRC-02-81-034 83/09/26 DAVIS, J Office of Nuclear Material
Safety & Safeguards, Director PENNIFILL, R NRC - No Detailed
Affiliation Given 1p 20650 049

--B310050337 Mod 7, deobligating funds for FY82, to "Trench Design & Const Techniques "
MARCUSON, W F Army, Dept of, Corps of Engineers GUSTAVE, R P
Division of Contracts FIN B-6981 NRC-02-81-034 83/09/26 1p
20650 050

B310050343 Notification of contract execution "Medical Uses of
Radioisotopes Course for NRC Matl Radiation Specialist
Inspectors," awarded to Univ of Texas Health Science Ctr
DAVIS, K A Administrative Contracts Branch FIN B-8711
NRC-05-83-221 83/09/26 DEYOUNG, R C Director's Office, Office of
Inspection and Enforcement HASSELBERG, F W NRC - No Detailed
Affiliation Given 1p 20635 009

--B310050349 Contract "Medical Uses of Radioisotopes Course for NRC Matl
Radiation Specialist Inspectors," awarded to Univ of
Texas Health Science Ctr
* Texas, Univ of, San Antonio MATTIA, M J Division of
Contracts FIN B-8711 NRC-05-83-221 83/09/26 37pp
20635 010

B310050357 Notification of contract execution, Mod 3 to "Audiovisual
Consultant Svcs " Contractor N Hall
PERLMAN, J Administrative Contracts Branch FIN B-8181
NRC-17-83-398 83/09/27 CHILK, B, MAOEE, W Office of the
Secretary of the Commission 1p 20650 047

--B310050362 Mod 3, extending period of performance to 840228 & adding
addl funds, to "Audiovisual Consultant Svcs "
HALL, N M Hall, N SMITH, P A Technical Assistance Contracts
Branch FIN B-8181 NRC-17-83-398 83/09/27 1p 20650 048

B310050365 Notification of contract execution, Mod 10 to "Study of New
England Seismicity w/Emphasis on MA & NH " Contractor: MIT.
JACOBBS, A Technical Assistance Contracts Branch FIN A-4058
NRC-04-76-209 83/09/26 DATSON, W Office of Nuclear Regulatory
Research, Director MURPHY, A NRC - No Detailed Affiliation Given
1p 20649 355

--B310050370 Mod 10, extending funds through 840831, to "Study of New
England Seismicity w/Emphasis on MA & NH "
KEOHAN, P J Massachusetts Institute of Technology, Cambridge, MA
GUSTAVE, R P Technical Assistance Contracts Branch. FIN A-4058
NRC-04-76-209 83/09/26 5pp 20649 356

B310050367 Notification of contract execution, Mod 4 to "Records Holding
Area Support Svc " Contractor SBA/Maxima Corp
MCLEAREN, T Administrative Contracts Branch NRC-10-82-396
83/09/26 BESAW, W J Division of Technical Information & Document
Control HARRIS, J NRC - No Detailed Affiliation Given 1p.
20650 039

--B310050369 Mod 4, allowing for adjusted billing & deobligating funds, to
"Records Holding Area Support Svc "
JONES, P E Maxima Corp DENNISTON, S F Small Business
Administration HAQAN, T F Administrative Contracts Branch.
NRC-10-82-396 83/09/26 3pp 20650 040

B310050379 Notification of contract execution, Mod 2 to "Programming,
Training, Testing, Conversion & Implementation of Facility
Control Sys " Contractor Boeing Computer Svcs Co
PERLMAN, J Administrative Contracts Branch FIN B-8848,
NRC-33-83-458 83/09/26 BASSETT, H B, WRIGHT, Q Division of Data
Automation & Management Information, 1p 20650 004.

--B310050387 Mod 2, extending period of performance to 831014 & adjusting
cost of money factor, to "Programming, Training, Testing,
Conversion & Implementation of Facility Control Sys."
HOPKINS, H R Boeing Co SMITH, P A Administrative Contracts
Branch FIN B-8848 NRC-33-83-458 83/09/26 1p 20650 005

B310050383 Notification of contract execution, Mod 10 to "Review &
Evaluation of Geologic & Seismic Features of Nuclear Power
Sites " Contractor USGS
FLEENOR, C Technical Assistance Contracts Branch FIN B-6839,
NRC-03-80-113 83/09/26 VOLLMER, R H Division of Engineering.
JACKSON, R. NRC - No Detailed Affiliation Given 1p 20640 361.

--B310050391 Mod 10, terminating effort under Tasks 3 & 10 & obligating
funds, to "Review & Evaluation of Geologic & Seismic
Features of Nuclear Power Sites "
FILSON, J R Interior, Dept of, Geological Survey FIN B-6839
NRC-03-80-113 83/09/26 1p 20640 362

B310050409 Notification of contract execution "Maint & Operation of
LPDRs," awarded to Wheeler Basin, AL Regional Library
HOPPER, A Administrative Contracts Branch NRC-10-83-751
83/09/22 FELTON, J M Division of Rules and Records. BOUDER, J
NRC - No Detailed Affiliation Given 1p 20640 136

--B310050420 Contract "Maint & Operation of LPDRs," awarded to Wheeler
Basin, AL Regional Library
SEARG, C A Decatur, AL REBELLO, J E Division of Contracts
NRC-10-83-751 83/09/22 9pp 20640 137

B310050456 Notification of contract execution, Mod 1 to "Panel Member &
Documentation Review of NUREG Prior to & During Selected
Meetings of Peer Review Group for Review of Draft Rept
Entitled " Contractor D Rowe
TOWNSEND, B L Administrative Contracts Branch FIN B-8968
NRC-04-83-007 83/09/26 BASSETT, O E Division of Accident
Evaluation JANKOWSKI, M W NRC - No Detailed Affiliation Given
1p 20650 031

--B310050458 Mod 1, extending period of performance to 831030, adding one
addl meeting & document review & increasing funds, to "Panel
Member & Documentation Review of NUREG Prior to & During
Selected Meetings of Peer Review Group for Review . "
ROWE, D B Rowe Associates REBELLO, J E Division of Contracts
FIN B-8968 NRC-04-83-007 83/09/26 1p. 20650 032.

B310050459 Notification of contract execution, Mod 3 to "Maint of
Licensing & Insp Planning Profile Sys Software "
Contractor SBA/Sys Architects, Inc
SMITH, P A Administrative Contracts Branch NRC-10-81-395
83/09/29 SPRINGER, M Office of Administration BURTON, J E NRC -
No Detailed Affiliation Given 1p. 20650 001

--B310050460 Mod 3, deobligating balance remaining for closeout, to
"Maint of Licensing & Insp Planning Profile Sys Software "
KAHN, V System Architects, Inc. * Small Business Administration
SMITH, P A Administrative Contracts Branch NRC-10-81-395.
83/09/29 2pp. 20650 002

B310050462 Notification of contract execution, Mod 2 to "Incident
Response Communication Ctr " Contractor Boise Interagency
Fire Ctr
MCLEAREN, T Administrative Contracts Branch NRC-10-83-342.
83/09/28 CORLEY, J H Division of Facilities & Operations.
MELVILLE, T, COHEN, B Telecommunications Branch 1p. 20664 125

--B310050464 Mod 2, obligating addl funds, to "Incident Response
Communication Ctr. "
* Interior, Dept of HAQAN, T F Division of Contracts
NRC-10-83-342 83/09/28 1p 20664 126.

B310050466 Notification of contract execution: "Maint & Operation of
LPDRs," awarded to Phoenix, AZ Public Library
FLYNN, M J Administrative Contracts Branch NRC-10-83-734.
83/09/29 FELTON, J H Division of Rules and Records. BOUDER, J
NRC - No Detailed Affiliation Given 1p 20650 010.

--B310050467 Contract. "Maint & Operation of LPDRs," awarded to
Phoenix, AZ Public Library
* Phoenix, AZ MATTIA, M J Division of Contracts
NRC-10-83-734 83/09/29 18pp 20650 012

B310050539 Notification of contract execution, Mod 9 to "Technical
Assistance in Repository Design " Contractor Golder Assoc
DELOATCH, V Technical Assistance Contracts Branch. FIN B-6983-3.
NRC-02-81-037. 83/09/28. DAVIS, J Office of Nuclear Material
Safety & Safeguards, Director HARTUNG, L NRC - No Detailed
Affiliation Given 1p. 20650 216

--B310050545 Mod 9, modifying Article II re period of performance
milestones & deliverables, to "Technical Assistance in
Repository Design."
TALBOT, R Golder Associates GUSTAVE, R P. Technical Assistance
Contracts Branch. FIN B-6983-3 NRC-02-81-037 83/09/28 1p.
20650 217

B310050549 Notification of contract execution, Mod 16 to "Technical
Assistance in Support of NRC Reactor Licensing Actions
Program 2 " Contractor: Science Applications, Inc.
WOLLETT, S. Technical Assistance Contracts Branch FIN B-8012
NRC-03-82-096, 83/09/28 EISENHUT, D. Division of Licensing
BAJWA, S NRC - No Detailed Affiliation Given 1p. 20650 218

NONDOCKETED ITEMS

- B310050550 Mod 16, providing incremental funding, to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2"
* Science Applications, Inc GUSTAVE, R P Technical Assistance
Contracts Branch FIN B-8012 NRC-03-82-076 83/09/28 2pp
20650 219
- B310050553 Notification of contract execution, Mod 2 to "Development of Reg Guide & Regulatory Analyses" Contractor Analysis & Technology, Inc
JACOBBS, A Technical Assistance Contracts Branch FIN B-8645
NRC-03-83-107 83/09/27 DENTON, H R Office of Nuclear Reactor Regulation, Director BENDER, L NRC - No Detailed Affiliation Given 1p 20650 221
- B310050556 Mod 2, funding extension of contract w/ revised statement of work, "Development of Reg Guide & Regulatory Analyses"
WOODS, V L Analysis & Technology, Inc GUSTAVE, R P Technical Assistance Contracts Branch FIN B-8645 NRC-03-83-107
83/09/27 3pp 20650 222
- B310060007 Notification of contract execution, Mod 1 to "Incident Response Communication Svc" Contractor Boise Interagency Fire Ctr
MCLEAREN, T Contract Policy Branch NRC-10-83-342 83/09/28
CORLEY, J H Division of Facilities & Operations MELILLE, T,
CDHEN, B NRC - No Detailed Affiliation Given 1pp 20664 121
- B310060010 Mod 1, definitizing task order procedures & increasing total amount obligated, to "Incident Response Communication Svc"
WILSON, F Interior, Dept of HAGAN, T Contract Policy Branch
NRC-10-83-342 83/09/28 3pp 20664 122
- B310060071 Notification of contract execution, Mod 10 to "Fission Product Transport Analysis" Contractor Battelle Columbus Labs.
WOLLETT, S Technical Assistance Contracts Branch FIN B-6747
NRC-04-80-177 83/09/28 BATSON, W Office of Nuclear Regulatory Research, Director WALKER, T NRC - No Detailed Affiliation Given 1p 20663 350
- B310060103 Mod 10, providing incremental funding for cost increase & extending period of performance to 840930, to "Fission Product Transport Analysis"
BEWELL, H M Battelle Memorial Institute, Columbus Laboratories
GUSTAVE, R P Division of Contracts FIN B-6747 NRC-04-80-177
83/09/28 2p 20663 351
- B310060109 Notification of contract execution, Mod 3 to "Courses in C-E Facility Design & Operation" Contractor C-E
DELOATCH, V Technical Assistance Contracts Branch FIN B-1301
NRC-05-82-241 83/09/27 BLAHA, J Director's Office, Office of Inspection and Enforcement SHOWE, B NRC - No Detailed Affiliation Given 1p 20661 090
- B310060115 Mod 3, increasing funds & exercising option for addl course, to "Courses in C-E Facility Design & Operation"
LECLAIR, D E Combustion Engineering, Inc GUSTAVE, R P Division of Contracts FIN B-1301 NRC-05-82-241, 83/09/27 1p
20661 091.
- B310060117 Notification of contract execution, Mod 1 to "Mgt & Operation of NRR Reading/Ref Room" Contractor Intersyst, Ltd
GILDEMDORN, A J Administrative Contracts Branch NRC-10-83-725
83/09/27 BEBAW, W J, SCOTT, B Division of Technical Information & Document Control 1p 20661 017
- B310060138 Mod 1, extending period of performance to B31021 & increasing contract amount, to "Mgt & Operation of NRR Reading/Ref Room"
KILPATRICK, O Intersyst, Ltd HAGAN, T F Division of Contracts
NRC-10-83-725 83/09/29 2pp, 20661 018
- B310060122 Notification of contract execution, Mod 11 to "Technical Assistance in Repository Design" Contractor Golder Assoc
DELOATCH, V Technical Assistance Contracts Branch FIN B-6983-3
NRC-02-81-037, 83/09/23 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director HARTUNG, L NRC - No Detailed Affiliation Given 1p, 20661 013
- B310060129 Mod 11, adding funds to cover microfiche cost, to "Technical Assistance in Repository Design"
TALBOT, R Golder Associates GUSTAVE, R P Division of Contracts
FIN B-6983-3 NRC-02-81-037 83/09/23 2pp 20661 014
- B310060140 Notification of contract execution, Mod 9 to "Sheffield Trench Cap Study" Contractor Univ of Illinois
DELOATCH, V Technical Assistance Contracts Branch FIN B-6965-3
NRC-02-80-074 83/09/23 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director SHAFFNER, J NRC - No Detailed Affiliation Given 1p, 20660 361.
- B310060184 Mod 9, adding funds to Article III for contractor to attend conference in Denver, CO to "Sheffield Trench Cap Study"
* Illinois, Univ of, Urbana, IL GUSTAVE, R P Division of Contracts FIN B-6965-3 NRC-02-80-074 83/09/23 1p
20660 362
- B310060154 Notification of contract execution "Maint & Operation of LPDRs," awarded to Rochester, NY Public Library
HOPPER, A Administrative Contracts Branch NRC-10-83-729
83/09/17 FELTON, J M Division of Rules and Records SOUDER, J
NRC - No Detailed Affiliation Given 1p 20660 348
- B310060168 Contract "Maint & Operation of LPDRs," awarded to Rochester, NY Public Library
BUTZ, L M Rochester, NY REBELLO, J E Division of Contracts
NRC-10-83-729 83/09/17 9pp 20660 349
- B310060178 Notification of contract execution, Mod 13 to "Structural Integrity of Water Reactor Boundary Components" Contractor ENSA, Inc
WOLLETT, S Division of Contracts FIN B-8133 NRC-04-82-013
83/09/27 FOREHAND, W Office of Nuclear Regulatory Research, Director VAGINS, M NRC - No Detailed Affiliation Given 1p
20660 326
- B310060191 Mod 13, providing for contractor efforts through B31116 & increasing incremental funding, to "Structural Integrity of Water Reactor Boundary Components"
HABIB, M N ENSA, Inc GUSTAVE, R P Division of Contracts FIN
B-8133 NRC-04-82-013 83/09/27 5pp 20660 327
- B310060278 Notification of contract execution "Maint & Operation of LPDRs," awarded to Shoreham-Wading River, NY Public Library
HOYLE, A Purchasing Section NRC-10-83-728 83/09/13 FELTON, J M
Division of Rules and Records SOUDER, J NRC - No Detailed Affiliation Given 1p 20660 216
- B310060290 Contract "Maint & Operation of LPDRs," awarded to Shoreham-Wading River, NY Public Library
* Shoreham, NY REBELLO, J E Division of Contracts
NRC-10-83-728 83/09/13 9pp 20660 217
- B310060318 Notification of contract execution, Mod 1 to "Panel Member & Documentation Review of NUREG Prior to & During Selected Meetings of Peer Review Group for Review of Draft Rept Entitled "Contractor W Kastenbergs"
TOWNSEND, B L Administrative Contracts Branch FIN B-8990
NRC-04-83-019 83/09/24 BASSETT, D E Division of Accident Evaluation JANKOWSKI, M W NRC - No Detailed Affiliation Given 1p 20660 214
- B310060326 Mod 1, extending period of performance to B31030, adding one addl meeting & increasing funding, to "Panel Member & Documentation Review of NUREG Prior to & During Selected Meetings of Peer Review Group for Review of"
KASTENBERG, W E Kastenbergs, W E REBELLO, J E Division of Contracts FIN B-8990 NRC-04-83-015 83/09/24 1pp
20660 215
- B310060471 Notification of contract execution "Maint & Operation of LPDRs," awarded to Perry, OH Public Library
TOWNSEND, B L Purchasing Section NRC-10-83-736 83/09/20
FELTON, J M Division of Rules and Records SOUDER, J L NRC - No Detailed Affiliation Given 1p 20660 162
- B310060483 Contract "Maint & Operation of LPDRs," awarded to Perry, OH Public Library
LOCKE, D L Perry, OH REBELLO, J E Division of Contracts
NRC-10-83-736 83/09/20 9pp 20660 163
- B310060487 Notification of contract execution "Maint & Operation of LPDRs," awarded to WH Abel Memorial Library
HOPPER, A Purchasing Section NRC-10-83-753 83/09/30
FELTON, J M Division of Rules and Records SOUDER, J NRC - No Detailed Affiliation Given 1p 20660 188
- B310060493 Contract "Maint & Operation of LPDRs," awarded to WH Abel Memorial Library
CROSE, M A Montesano, WA REBELLO, J E Division of Contracts
NRC-10-83-753, 83/09/30 9pp 20660 189
- B310060495 Notification of contract execution "Maint & Operation of LPDRs," awarded to Morris, IL Public Library
HOYLE, A Purchasing Section NRC-10-83-735 83/09/19 FELTON, J M
Division of Rules and Records SOUDER, J NRC - No Detailed Affiliation Given 1p 20660 198
- B310060496 Contract "Maint & Operation of LPDRs," awarded to Morris, IL Public Library
WILSON, P Morris, IL REBELLO, J E Division of Contracts
NRC-10-83-735 83/09/19 9pp 20660 199

NONDOCKETED ITEMS

40

8310060499 Notification of contract execution "Maint & Operation of LPDRs," awarded to White Plains, NY Public Library
MOYLE, A Purchasing Section NRC-10-83-730 83/09/13 FELTON, J M
Division of Rules and Records SOUDER, J NRC - No Detailed
Affiliation Given 1p 20663 269

--8310060501 Contract "Maint & Operation of LPDRs," awarded to White Plains, NY Public Library
DOH, O B White Plains, NY REBELLO, J E Division of Contracts
NRC-10-83-730 83/09/13 9pp 20663 270

8310060503 Notification of contract execution, Mod 4 to "Performance of Engineered Barriers in Geologic Repository " Contractor
Golder Assoc, Inc
DELOATCH, V Technical Assistance Contracts Branch FIN B-6986-3
NRC-02-B1-027 83/09/23 DAVIS, J Office of Nuclear Material
Safety & Safeguards, Director PITIGLIA, L NRC - No Detailed
Affiliation Given 1p 20663 266

--8310060506 Mod 6, adding funding for microfiche requirement, to
"Performance of Engineered Barriers in Geologic Repository "
TALBOT, R Golder Associates FIN B-6986-3 NRC-02-B1-027
83/09/23 2pp 20663 267

8310060507 Notification of contract execution "Maint & Operation of LPDRs," awarded to Florida Intl Univ
MURPHY, L Q Purchasing Section NRC-10-83-726 83/09/19,
FELTON, J M Division of Rules and Records 1p 20663 256

--8310060512 Contract "Maint & Operation of LPDRs," awarded to Florida Intl Univ
MILLER, L Florida International Univ REBELLO, J E Division of
Contracts NRC-10-83-726 83/09/19 9pp 20663 257

8310070099 Notification of contract execution, Mod 1 to "Panel Review of NUREG Prior to Peer Review Group Review of Draft Rept
Entitled 'Radionuclide Release Under LWR Specific Accident
Conditions " Contractor Univ of VA
TOWNSEND, B L Administrative Contracts Branch FIN B-8985
NRC-04-83-010 83/09/26 BASSETT, D E Division of Accident
Evaluation JANKOWSKI, M W NRC - No Detailed Affiliation Given
1p 20671 315

--8310070106 Mod 1, extending period of performance to 831030 & increasing
funding, to "Panel Review of NUREG Prior to Peer Review
Group Review of Draft Rept Entitled 'Radionuclide Release
Under LWR Specific Accident Conditions "
REYNOLDS, A B Virginia, Univ of, Charlottesville, VA
REBELLO, J E Division of Contracts FIN B-8985 NRC-04-83-010
83/09/26 1p 20671 316

8310070115 Notification of contract execution "Maint & Operation of LPDRs," awarded to Minneapolis, MN Public Library & Info Ctr.
MURPHY, L Q Purchasing Section NRC-10-83-744 83/09/21
FELTON, J M Division of Rules and Records SOUDER, J NRC - No
Detailed Affiliation Given 1p 20671 300

--8310070117 Contract "Maint & Operation of LPDRs," awarded to Minneapolis, MN Public Library & Info Ctr
SHANNON, Z Minneapolis, MN REBELLO, J E. Division of Contracts.
NRC-10-83-744 83/09/21 9pp 20671 301

8310070121 Notification of contract execution "Maint & Operation of LPDRs," awarded to Indian River Community College
HOPPER, A Purchasing Section NRC-10-83-750 83/09/17,
FELTON, J M Division of Rules and Records SOUDER, J NRC - No
Detailed Affiliation Given 1p 20680 351

--8310070148 Contract "Maint & Operation of LPDRs," awarded to Indian River Community College
WIDMAN, R P Indian River Community College REBELLO, J E.
Division of Contracts NRC-10-83-750, 83/09/17 9pp 20680-352

8310070165 Notification of contract execution. "Purchase & Installation of Alpha/Beta Counting Sys," awarded to Tennessec, Inc
FALSON, V K Administrative Contracts Branch. FIN B-8367
NRC-28-83-613 83/09/29, FERRI, R T Division of Resource
Management & Administration KOTTAN, J J. NRC - No Detailed
Affiliation Given 1p 20664, 312

--8310070173 Contract. "Purchase & Installation of Alpha/Beta Counting Sys," awarded to Tennessec, Inc
COLE, P A Tennessec, Inc MATTIA, M J. Division of Contracts FIN
B-8367, NRC-28-83-613 83/09/29 22pp. 20664, 313

8310070172 Notification of contract execution "Developing Automatic Contractual Documentation Capability," awarded to Boeing Computer Svcs Co.
COLEMAN, R Administrative Contracts Branch. FIN B-8865,
NRC-33-83-463 83/09/28 BASSETT, H B Office of Resource
Management, Director THOMPSON, R NRC - No Detailed Affiliation
Given. 1p 20680 293

--8310070175 Contract "Developing Automatic Contractual Documentation Capability," awarded to Boeing Computer Svcs Co
HOPKINS, M R Boeing Computer Services, Inc (subs of Boeing Co)
MATTIA, M J Division of Contracts FIN B-8865 NRC-33-83-463
83/09/28 10pp 20680 294

8310070178 Notification of contract execution "Maint & Operation of LPDRs," awarded to Salem, NJ Free Library
MURPHY, L G Administrative Contracts Branch NRC-10-83-752
83/09/26 FELTON, J M Division of Rules and Records SOUDER, J
NRC - No Detailed Affiliation Given 1p 20680 267

--8310070181 Contract "Maint & Operation of LPDRs," awarded to Salem, NJ Free Library
FOGO, E C Salem, NJ REBELLO, J E Division of Contracts
NRC-10-83-752 83/09/26 9pp 20680 268

8310070184 Notification of contract execution "Review of Tornado Missile PRA-South Texas Project," awarded to NBS
WIGGINS, E Technical Assistance Contracts Branch FIN B-8657
NRC-03-83-114 83/09/29 MATTHEW, R J Division of Systems
Integration (post 81005) SINOH, B K NRC - No Detailed Affiliation
Given 1p. 20680 248 24X Fiche 50-498, 83/09/29, 8310070184

--8310070188 Ltr Contract NRC-03-83-114 "Review of Tornado Missile PRA-South Texas Project," awarded to NBS
MORTON, K V Division of Contracts FIN B-8657 NRC-03-83-114
83/09/21 SINIU, E. Commerce, Dept of, National Bureau of
Standards 7pp 20680 249. 24X Fiche 50-498, 83/09/29, 8310070184

8310070185 Notification of contract execution, Mod 9 to "Computer Time-Sharing & Related Svcs," Contractor NIH
BROMBERG, B Administrative Contracts Branch FIN B-1666.
NRC-25-82-312 83/09/22, BASSETT, H S Division of Data Automation
& Management Information SHIELDS, J NRC - No Detailed Affiliation
Given 1p 20679 356

--8310070203 Mod 9, extending period of performance for 1 yr, to "Computer Time-Sharing & Related Svcs "
PRATT, A HHS, Dept of, US Public Health Service HALMAN, E L
Administrative Contracts Branch FIN B-1666 NRC-25-82-312
83/09/22 1p 20679 357

8310070187 Notification of contract execution, Mod 3 to "Evaluation of Matl Accounting Performances at Nuclear Fuel Cycle Facilities " Contractor NUBAC, Inc
JACOBS, A Technical Assistance Contracts Branch FIN B-7379-3
NRC-02-83-027 83/09/22 DAVIS, J Office of Nuclear Material
Safety & Safeguards, Director MILLER, M NRC - No Detailed
Affiliation Given 1p 20679 354

--8310070189 Mod 3, funding action to fix reimbursable costs, to "Evaluation of Matl Accounting Performances at Nuclear Fuel Cycle Facilities "
LUMB, R F. NUBAC, Inc OUSTAVE, R P Technical Assistance
Contracts Branch. FIN B-7379-3, NRC-02-83-027 83/09/22 1p
20679 355

8310070193 Notification of grant execution "Geometric Analysis of Ensemble of Solutions in Two-Phase Flows & Complete Resolution of Problem Choking," awarded to Brown Univ.
UMBEL, D Technical Assistance Contracts Branch FIN Q-1036
NRC-0-04-83-013 83/09/27 SATSON, W Office of Nuclear Regulatory
Research, Director ZUBER, N. NRC - No Detailed Affiliation Given
1p 20680 232

--8310070196 Grant. "Geometric Analysis of Ensemble of Solutions in Two-Phase Flows & Complete Resolution of Problem Choking," awarded to Brown Univ
WUNDERLICH, T K Brown Univ MORTON, M V. Technical Assistance
Contracts Branch. FIN Q-1036. NRC-0-04-83-013 83/09/27 2pp.
20680 233

8310070195 Notification of contract execution, Mod 1 to "Panel Member & Documentation Review of NUREG Prior to & During Selected Meetings of Peer Review Group for Review of Draft Rept
Entitled ...," Contractor: S Levy
TOWNSEND, B L Administrative Contracts Branch FIN B-8989,
NRC-04-83-014 83/09/26, BASSETT, D E. Division of Accident
Evaluation JANKOWSKI, M W NRC - No Detailed Affiliation Given
1p 20679 358

--8310070198 Mod 1, extending period of performance to 831030, adding on
addl meeting & document review & increasing funding, to
"Panel Member & Documentation Review of NUREG Prior to &
During Selected Meetings of Peer Review Group for Review. "
LEVY, S B. Levy, Inc. REBELLO, J E Administrative Contracts
Branch. FIN B-8989 NRC-04-83-014 83/09/26 1p 20679 359.

NONDOCKETED ITEMS

- 8310070197 Notification of contract execution "Hydrogeologic Evaluations," awarded to INTERA Environ Consultants WIGGINS, E Technical Assistance Contracts Branch FIN B-7384-3 NRC-02-83-041 83/09/28 BROWN, R S Office of Nuclear Regulatory Research, Director WIDMAYER NRC - No Detailed Affiliation Given 1p 20680 213
- 8310070200 Contract "Hydrogeologic Evaluations," awarded to INTERA Environ Consultants PAHHA, S B INTERA Environmental Consultants, Inc MORTON, K V Division of Contracts FIN B-7384-3 NRC-02-83-041 83/09/28 18pp 20680 214
- 8310070201 Notification of grant execution "Eight World Conference on Earthquake Engineering," awarded to Earthquake Engineering Research Inst MCDERMOTT, D Technical Assistance Contracts Branch FIN Q-1058 NRC-Q-04-83-010 83/09/28 BATSON, W Office of Nuclear Regulatory Research, Director COSTELLO, J NRC - No Detailed Affiliation Given 1p 20680 210
- 8310070203 Grant "Eight World Conference on Earthquake Engineering," awarded to Earthquake Engineering Research Inst PENZIEN, J Earth Sciences Associates MORTON, K V Technical Assistance Contracts Branch FIN Q-1058 NRC-Q-04-83-010 83/09/28 2pp 20680 211
- 8310070206 Notification of contract execution "Technical Basis for Foreign Exchange of Codes," awarded to Intl Energy Assoc, Ltd JESSUP, B Technical Assistance Contracts Branch FIN D-1132 NRC-04-83-183 83/09/22 BATSON, W Office of Nuclear Regulatory Research, Director MELBER, C NRC - No Detailed Affiliation Given 1p 20679 327
- 8310070210 Contract "Technical Basis for Foreign Exchange of Codes," awarded to Intl Energy Assoc, Ltd ALIKONIS, N A International Energy Associates, Ltd MORTON, K V Administrative Contracts Branch FIN D-1132 NRC-04-83-183 83/09/22 17pp 20679 328
- 8310070213 Notification of contract execution "Behavior of Sub-Critical & Slow-Stable Crack Following Post-Irradiation Thermal Anneal Cycle," awarded to Matls Engineering Assoc, Inc JESSUP, B Technical Assistance Contracts Branch FIN D-1134 NRC-04-83-187 83/09/22 BATSON, W Office of Nuclear Regulatory Research, Director STROBNIDER, J NRC - No Detailed Affiliation Given. 1p 20680 192
- 8310070217 Contract "Behavior of Sub-Critical & Slow-Stable Crack Following Post-Irradiation Thermal Anneal Cycle," awarded to Matls Engineering Assoc, Inc GREENBLATT, M Materials Engineering Associates, Inc MORTON, K V Division of Contracts FIN D-1134 NRC-04-83-187. 83/09/22 17pp 20680 193
- 8310070214 Notification of contract execution "Reviewing Hydrogeologic Investigation of Bedded & Dome Salt Basins - Project A," awarded to Williams & Assoc, Inc WIGGINS, E Technical Assistance Contracts Branch FIN B-7389-3 NRC-02-83-033 83/09/29, BROWN, R S Program Support Branch JOHNSON, R NRC - No Detailed Affiliation Given. 1p. 20680 147
- 8310070221 Contract "Reviewing Hydrogeologic Investigations of Bedded & Dome Salt Basins - Project A," awarded to Williams & Assoc, Inc WILLIAMS, R E Williams & Associates MORTON, K V Division of Contracts FIN B-7389-3 NRC-02-83-033 83/09/29 44pp. 20680 148
- 8310070218 Notification of contract execution "Common Cause Failure Analysis - Data Base Assessment & Development," awarded to JBF Assoc, Inc JESSUP, B Technical Assistance Contracts Branch FIN D-1130 NRC-04-83-183 83/09/22 BATSON, W Office of Nuclear Regulatory Research, Director ROBINSON, R NRC - No Detailed Affiliation Given 1p 20680 129
- 8310070220 Contract "Common Cause Failure Analysis - Data Base Assessment & Development," awarded to JBF Assoc, Inc FUSSELL, J B JBF Associates MORTON, K V Division of Contracts FIN D-1130 NRC-04-83-183 83/09/22 17pp. 20680 130
- 8310070222 Notification of contract execution, "Maint & Operation of LPDRs," awarded to Sacramento, CA Public Library HOYLE, A Administrative Contracts Branch NRC-10-83-739 83/09/29. FELTON, J M Division of Rules and Records SOUDER, J NRC - No Detailed Affiliation Given 1p 20676-348
- 8310070224 Contract "Maint & Operation of LPDRs," awarded to Sacramento, CA Public Library RICHARD, R Sacramento, CA REBELLO, J C Division of Contracts NRC-10-83-739 83/09/29 9pp 20676 349
- 8310070226 Notification of grant execution "Committee on Earthquake Engineering," awarded to Natl Academy of Sciences UMSEL, D M Technical Assistance Contracts Branch FIN Q-1063 NRC-Q-04-83-012 83/09/26 BATSON, W Office of Nuclear Regulatory Research, Director BURNS, J NRC - No Detailed Affiliation Given 1p 20680 034
- 8310070230 Grant "Committee on Earthquake Engineering," awarded to Natl Academy of Sciences SMITH, P National Academy of Sciences MORTON, K V Technical Assistance Contracts Branch FIN Q-1063 NRC-Q-04-83-012 83/09/26 23pp 20680 035
- 8310070228 Notification of contract execution "Maint & Operation of LPDRs," awarded to QA Dow Memorial Library FLYNN, M J Administrative Contracts Branch NRC-10-83-743 83/09/29 FELTON, J Division of Rules and Records SOUDER, J NRC - No Detailed Affiliation Given 1p 20669 348
- 8310070231 Contract "Maint & Operation of LPDRs," awarded to QA Dow Memorial Library BYERS, R Midland County, MI MATTIA, M J Division of Contracts NRC-10-83-743 83/09/29 15pp 20669 349
- 8310070233 Notification of contract execution "Uncertainties in Sys Analysis Part of Seismic PRA," awarded to Future Resources Assoc, Inc JESSUP, B Technical Assistance Contracts Branch FIN D-1129 NRC-04-83-182 83/09/27 BATSON, W Office of Nuclear Regulatory Research, Director MURPHY, J NRC - No Detailed Affiliation Given 1p 20669 330
- 8310070240 Contract "Uncertainties in Sys Analysis Part of Seismic PRA," awarded to Future Resources Assoc, Inc BUDNITZ, R Future Resources Associates, Inc MORTON, K V Division of Contracts FIN D-1129 NRC-04-83-182 83/09/27 17pp 20669 331
- 8310070234 Notification of contract execution "Maint & Operation of LPDRs," awarded to Richland, WA Public Library FLYNN, M J Technical Assistance Contracts Branch NRC-10-83-746 83/09/29 FELTON, J M Division of Rules and Records SOUDER, J NRC - No Detailed Affiliation Given 1p 20664, 344
- 8310070237 Contract "Maint & Operation of LPDRs," awarded to Richland, WA Public Library ROBERTS, D E Richland, WA MATTIA, M J Division of Contracts NRC-10-83-746 83/09/29 15pp 20664 345
- 8310070244 Notification of contract execution "Development of PWR Transient Analysis Model," awarded to S Levy, Inc JESSUP, B Technical Assistance Contracts Branch FIN D-1131 NRC-04-83-184 83/09/27 BATSON, W Office of Nuclear Regulatory Research, Director ZUBER, N NRC - No Detailed Affiliation Given 1p 20669 310
- 8310070267 Contract "Development of PWR Transient Analysis Model," awarded to S Levy, Inc SCHREPPLE, L D S Levy, Inc MORTON, K V Division of Contracts FIN D-1131 NRC-04-83-184 83/09/27 17pp 20669 311
- 8310070329 Notification of contract execution "Mod of Existing Air Pathway Model for Low Level Waste Assessment & Training Course," awarded to NOAA WIGGINS, E, JACOBBS, A Technical Assistance Contracts Branch FIN B-7359-3 NRC-02-83-031 83/09/09, BROWN, R S Program Support Branch NEUDER, B NRC - No Detailed Affiliation Given 1p 20664 273
- 8310070331 Contract "Mod of Existing Air Pathway Model for Low Level Waste Assessment & Training Course," awarded to NOAA MAHLER, R J Commerce, Dept of, Natl Oceanographic & Atmospheric Administration MORTON, K V Technical Assistance Contracts Branch FIN B-7359-3 NRC-02-83-031 83/09/09 11pp 20664 274
- 8310070407 Notification of contract execution "Development of Draft Stds in Area of Rock Mechanics," awarded to ASTM FLENGER, C Technical Assistance Contracts Branch FIN D-1123 NRC-04-83-178 83/09/21, BATSON, W Office of Nuclear Regulatory Research, Director SCHMITT, T NRC - No Detailed Affiliation Given 1p 20676-321.

NONDOCKETED ITEMS

4

--B310070415 Contract "Development of Draft Stds in Area of Rock Mechanics," awarded to ASTM
CAVANAUUGH, W T American Society for Testing & Materials
MORTON, K V Technical Assistance Contracts Branch FIN D-1123
NRC-04-83-178 83/09/21 8pp 20676 322

B310070428 Notification of contract execution, Mod 13 to "Evaluation of Soil Behavior Under Earthquake Loading Conditions"
Contractor Shannon & Wilson, Inc & Agabian Assoc
UMBEL, D Technical Assistance Contracts Branch FIN B-3015
NRC-04-76-200 83/09/28 BATSON, W Office of Nuclear Regulatory Research, Director HARBOUR, J NRC - No Detailed Affiliation Given
1p 20676 319

--B310070429 Mod 13, deobligating funds, to "Evaluation of Soil Behavior Under Earthquake Loading Conditions"
MILLER, R P Shannon & Wilson, Inc * Agabian Associates
GUSTAVE, R P Technical Assistance Contracts Branch FIN B-3015
NRC-04-76-200 83/09/28 1p 20676 320

B310070431 Notification of contract execution, Mod 5 to "Statistical Review of Documents & Statistical Methods in Risk Assessment" Contractor SBA Subcontractor Automated Sciences Group.
BROMBERG, B Administrative Contracts Branch FIN B-1321.
NRC-07-79-312 83/09/19 HALLER, N Office of Management and Program Analysis ABRAMSON, L NRC - No Detailed Affiliation Given
1p 20676 315

--B310070432 Mod 5, extending period of performance to 840926, to "Statistical Review of Documents & Statistical Methods in Risk Assessment"
BENOIT, H Automated Sciences Group, Inc DENNISTON, S F Small Business Administration SMITH, P A Administrative Contracts Branch FIN B-1321 NRC-07-79-312 83/09/19 3pp 20676 316

B310070434 Notification of contract execution, Mod 5 to "Safety Assessment of Concrete Nuclear Structures"
Contractor MIT
UMBEL, D M Technical Assistance Contracts Branch FIN B-6618
NRC-04-79-181 83/09/29 FOREHAND, W Office of Nuclear Regulatory Research, Director BROWZIN, B NRC - No Detailed Affiliation Given
1p 20676 309

--B310070435 Mod 5, providing funds to cover cost overrun, to "Safety Assessment of Concrete Nuclear Structures"
DUMMER, O H Massachusetts Institute of Technology, Cambridge, MA
GUSTAVE, R P Technical Assistance Contracts Branch FIN B-6618
NRC-04-79-181 83/09/29 3pp 20676 310

B310110003 Notification of contract execution, Mod 4 to "Aerospace - Electric Power Workshop Conference on Commercial Nuclear Power," Contractor American Inst of Aeronautics.
UMBEL, D Technical Assistance Contracts Branch FIN O-1005
NRC-04-81-002 83/09/23 BATSON, W Office of Nuclear Regulatory Research, Director EISS, A NRC - No Detailed Affiliation Given
1p 20686 004

--B310110009 Mod 4, extending period of performance to 831231 at no cost, to "Aerospace - Electric Power Workshop Conference on Commercial Nuclear Power"
* American Institute of Aeronautics & Astronautics MORTON, K V
Technical Assistance Contracts Branch FIN O-1005
NRC-04-81-002 83/09/23 1p 20686 005

B310110026 Notification of grant execution "Study of Radionuclide Release from Severe Accidents at Nuclear Power Plants," awarded to APS
UMBEL, D M Technical Assistance Contracts Branch FIN O-1051
NRC-04-83-011 83/09/23 BATSON, W Office of Nuclear Regulatory Research, Director SILBERBERG, M NRC - No Detailed Affiliation Given
1p 20687 354

--B310110029 Grant "Study of Radionuclide Release from Severe Accidents at Nuclear Power Plants," awarded to APS
BURTON, J A American Physical Society, MORTON, K V Technical Assistance Contracts Branch FIN O-1051 NRC-04-83-011
83/09/23 2pp 20687 355

B310110086 Notification of contract execution "NRC Computer Security Program for Unclassified Sensitive Sys," awarded to NBS
BAZIN, J P Administrative Contracts Branch FIN B-8879
NRC-33-83-465 83/09/28 BASSETT, H S, CONSOLI, A Division of Data Automation & Management Information, 1p 20686 010

--B310110089 Contract, "NRC Computer Security Program for Unclassified Sensitive Sys," awarded to NBS.
SHREVE, D B, Commerce, Dept of, National Bureau of Standards
MATTIA, M Administrative Contracts Branch FIN B-8879
NRC-33-83-465 83/09/28 1p 20686 011.

B310110185 Notification of contract execution "Reorganizing & Purging of Safety Reactor Files at PDR & ACRS," awarded to Labat-Anderson, Inc
BAZIN, J P Administrative Contracts Branch NRC-10-83-722
83/09/30 BESAH, W J, SKOCZLAS, J Division of Technical Information & Document Control 1pp 20701 322

--B310110192 Contract "Reorganizing & Purging of Safety Reactor Files at PDR & ACRS," awarded to Labat-Anderson, Inc
LABAT, V Labat-Anderson, Inc DENNISTON, S F Administrative Contracts Branch NRC-10-83-722 83/09/30 15pp 20701 323

B310110262 Notification of contract execution, Mod 1 to "Panel Member Documentation Review of NUREG Prior to & During Selected Meetings of Peer Review Group for Review of Draft"
Contractor LR Zumwalt
TOWNSEND, B L Administrative Contracts Branch FIN B-8986
NRC-04-83-009 83/09/26 BASSETT, O E Division of Accident Evaluation JANKOSKI, M W NRC - No Detailed Affiliation Given
1p 20687 360

--B310110271 Mod 1, extending period of performance to 831030, increasing attendance at addl meeting & increasing funding, to "Panel Meeting & Documentation Review of NUREG Prior to & During Selected Meetings of Peer Review Group for Review of"
ZUMWALT, L R Zumwalt, L R REBELLO, J E Administrative Contracts Branch FIN B-8986 NRC-04-83-009 83/09/26 1p 20687 361

B310110336 Notification of contract execution "Maint & Operation of LPDRs," awarded to Greeley, CO Public Library
MURPHY, L O Administrative Contracts Branch NRC-10-83-742
83/09/13 FELTON, J M Division of Rules and Records SOUDER, J
NRC - No Detailed Affiliation Given 1p 20686 038

--B310110337 Contract "Maint & Operation of LPDRs," awarded to Greeley, CO Public Library
FROMM, E Greeley, CO REBELLO, J E Division of Contracts
NRC-10-83-742 83/09/13 9pp 20686 039

B310110338 Notification of contract execution "Maint & Operation of LPDRs," awarded to Plymouth, MA Public Library
TOWNSEND, B L Administrative Contracts Branch NRC-10-83-748
83/09/29 FELTON, J M Division of Rules and Records SOUDER, J L
NRC - No Detailed Affiliation Given 1p 20713 354

--B310110340 Contract "Maint & Operation of LPDRs," awarded to Plymouth, MA Public Library
* Plymouth, MA REBELLO, J E Division of Contracts
NRC-10-83-748 83/09/29 9pp 20713 355

B310110342 Notification of contract execution "Maint & Operation of LPDRs," awarded to California Polytechnic State Univ
FLYNN, M J Administrative Contracts Branch NRC-10-83-737
83/09/29 FELTON, J M Division of Rules and Records SOUDER, J
NRC - No Detailed Affiliation Given 1p 20686 018

--B310110344 Contract "Maint & Operation of LPDRs," awarded to California Polytechnic State Univ
FLORES, A B California Polytechnic State Univ, San Luis Obispo, CA MATTIA, M J Division of Contracts NRC-10-83-737 83/09/29
19pp 20686 019

B310110364 Responds to FOIA request for seven categories of documents re NRC document control sys. Forwards App A documents App B documents withheld (ref FOIA Exemption 4)
FELTON, J M Division of Rules and Records 83/06/13 BLAIR, L R
Affiliation Unknown, 4pp 20683 002

--B310110414 Mod 5, changing performance evaluation plan in Attachment C of contract, to "Operation & Maint of NRC Document Control Sys"
THAMM, E O Planning Research Corp SMITH, P A Division of Contracts NRC-10-82-356 82/08/06 3pp 20684 268

--B310110419 Mod 6, changing refs to Dfc of Controller in contractual document or billing instructions to Dfc of Resource Mgt, to "Operation & Maint of NRC Document Control Sys"
* Planning Research Corp SMITH, P A Division of Contracts
NRC-10-82-356 82/08/23 1p 20684 271.

B310110494 Notification of contract execution "Software Maint," awarded to Intel Sys Corp
BAZIN, J P Administrative Contracts Branch FIN B-8860
NRC-33-83-461 83/09/27 BASSETT, H S Division of Data Automation & Management Information JOHNSON, C NRC - No Detailed Affiliation Given, 1p 20709 346.

--B310110499 Contract, "Software Maint," awarded to Intel Sys Corp
SINK, J M Intel Corp MATTIA, M J Division of Contracts FIN B-8860 NRC-33-83-461 83/09/27 10pp 20709 347

NONDOCKETED ITEMS

- 8310110506 Notification of contract execution, Mod 1 to "Cost Analyses of Proposed Changes in NRC Requirements " Contractor Science & Engineering Assoc. Inc
GILDENHORN, Administrative Contracts Branch FIN B-8838
NRC-33-83-500 83/09/26 PARRY, L J Division of Data Automation & Management Information FOWLER, G NRC - No Detailed Affiliation Given 1p 20709 344
- 8310110510 Mod 1, correcting error in award amount of basic contract & changing key personnel, to "Cost Analyses of Proposed Changes in NRC Requirements "
ROSS, B R Science & Engineering Associates, Inc HAGAN, T F Division of Contracts FIN B-8838 NRC-33-83-500 83/09/26 1p 20709 345
- 8310110508 Notification of contract execution "Cost Analyses of Proposed Changes in NRC Requirements, (Scope of Work B)," awarded to Science & Engineering Assoc. Inc
HADEY, H A Administrative Contracts Branch FIN B-8838
NRC-33-83-500 83/09/20 TRINER, E G Division of Budget & Analysis FOWLER, G NRC - No Detailed Affiliation Given 1p 20715 175
- 8310110512 Contract "Cost Analyses of Proposed Changes in NRC Requirements, (Scope of Work B)," awarded to Science & Engineering Assoc. Inc
ROSS, B Science & Engineering Associates, Inc MATTIA, M J Division of Contracts FIN B-8838 NRC-33-83-500 83/09/20 1pp 20715 176
- 8310110516 Notification of contract execution "Atomic Safety Licensing & Regulating Peaceful Atomic Energy, 1946-1963," awarded to Univ of CA Press
COLEMAN, R W Administrative Contracts Branch NRC-10-83-338
83/09/29 CHILK, S J, MAZUZAN, G Office of the Secretary of the Commission 1p. 20715 187
- 8310110524 Contract "Atomic Safety Licensing & Regulating Peaceful Atomic Energy, 1946-1963," awarded to Univ of CA Press
MILES, J R Univ of California Press MATTIA, M J Division of Contracts NRC-10-83-338 83/09/29 12pp 20715 188
- 8310110525 Notification of contract execution, Mod 9 to "Graphics/Photographic Svcs." Contractor Robert Charles Moles & Assoc
GILDENHORN, A J Administrative Contracts Branch NRC-05-81-257
83/10/05. BLAHA, J. L Program Support Branch THAYER, C Director's Office, Office of Inspection and Enforcement 1p 20714 326
- 8310110528 Mod 9, extending period of performance to 831031 w/no change in unit prices of contract, to "Graphics/Photographic Svcs "
MOLES, R C Robert Charles Moles & Associates HAGAN, T F Division of Contracts NRC-05-81-257 83/10/05 1p 20714 327
- 8310110533 Notification of contract execution "Robotics Application for Exposure Reduction," awarded to Remote Technology Corp
JESSUP, B Technical Assistance Contracts Branch FIN D-1128
NRC-04-83-181 83/09/22 BATSON, W Office of Nuclear Regulatory Research, Director ROECKLEIN, A NRC - No Detailed Affiliation Given 1p 20704 330
- 8310110549 Contract "Robotics Application for Exposure Reduction," awarded to Remote Technology Corp
WHITE, J R Remote Technology Corp MORTON, K V Division of Contracts FIN D-1128 NRC-04-83-181 83/09/22 17pp 20704.331
- 8310110572 Notification of contract execution "Selection of Earthquake Resistant Design Criteria for Nuclear Power Plants, Methodology & Technical Bases," awarded to Structural & Earthquake Engineering Consultants
EDGEWORTH, P J Technical Assistance Contracts Branch FIN B-8298
NRC-04-83-022 83/09/29 BATSON, W Office of Nuclear Regulatory Research, Director, MURPHY, A. NRC - No Detailed Affiliation Given 1p 20709-071
- 8310110582 Contract "Selection of Earthquake Resistant Design Criteria for Nuclear Power Plants, Methodology & Technical Bases," awarded to Structural & Earthquake Engineering Consultants
LUCO, J E Structural & Earthquake Engineering Consultants
MORTON, K. V, Division of Contracts FIN B-8298 NRC-04-83-022 83/09/29 14pp 20709 072
- 8310110613 Notification of contract execution, "Ultra-High Speed Residue Processor for Shaft Insp Sys Image Enhancement," awarded to Spectron Development Labs
JESSUP, B. Technical Assistance Contracts Branch. FIN D-1133.
NRC-04-83-186 83/09/24. BATSON, W Office of Nuclear Regulatory Research, Director. STROSNIDER, J NRC - No Detailed Affiliation Given 1p 20715 142.
- 8310110616 Contract "Ultra-High Speed Residue Processor For Shaft Insp Sys Image Enhancement," awarded to Spectron Development Labs
MCBRIEN, C S Spectron Development Laboratories MORTON, K V Administrative Contracts Branch FIN D-1133 NRC-04-83-186 83/09/24 17pp 20715 143
- 8310120010 Notification of contract execution, Mod 2 to "Modeling Mesoscale Dispersion & Transport Process for Release Within Coastal Zones During Land/Sea Breezes " Contractor Univ of MN
UMBEL, D M Technical Assistance Contracts Branch FIN B-6048
NRC-04-76-368 83/09/20 BATSON, W Office of Nuclear Regulatory Research, Director ABBEY, R NRC - No Detailed Affiliation Given 1p 20749 212
- 8310120019 Ltr Contract NRC-04-76-368, Mod 2, deobligating FY79 funds, to "Modeling Mesoscale Dispersion & Transport Process for Release Within Coastal Zones During Land/Sea Breezes "
GUSTAVE, R P Technical Assistance Contracts Branch FIN B-6048
NRC-04-76-368 83/07/14 GARLID, M Minnesota, Univ of 1p 20749 213
- 8310120021 Notification of contract execution, Mod 3 to "Automobile Impact Forces on Concrete Wall Panels " Contractor Chiapetta, Welch & Assoc, Ltd
UMBEL, D M Technical Assistance Contracts Branch FIN B-6609
NRC-04-79-188 83/09/23 BATSON, W Office of Nuclear Regulatory Research, Director COSTELLO, J NRC - No Detailed Affiliation Given 1p 20749 181
- 8310120024 Mod 3, adding funds to cover increases in indirect cost rates, to "Automobile Impact Forces on Concrete Wall Panels "
CHIAPETTA, R L Chiapetta, Welch & Associates, Ltd GUSTAVE, R P Division of Contracts FIN B-6609 NRC-04-79-188 83/09/23 1p 20749 182
- 8310120033 Notification of contract execution, Mod 4 to "Reviewing Hydrologic Investigations of BWIP, Project B "
Contractor Golder Assoc
FLEENOR, C Technical Assistance Contracts Branch FIN B-7373-3
NRC-02-82-045 83/09/28 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director LDOSSDON, M NRC - No Detailed Affiliation Given 1p 20715 349
- 8310120035 Mod 4, revising & expanding statement of work, obligating funds & extending period of performance to 840930, to "Reviewing Hydrologic Investigations of BWIP, Project B "
TALBOT, R Golder Associates GUSTAVE, R P Division of Contracts FIN B-7373-3 NRC-02-82-045 83/09/28 12pp 20715 350
- 8310120038 Notification of contract execution, Mod 3 to "Reviewing Hydrologic Investigations of BWIP " Contractor Williams & Assoc
FLEENOR, C Technical Assistance Contracts Branch FIN B-7372-3
NRC-02-82-044 83/09/29 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director LDOSSDON, M NRC - No Detailed Affiliation Given 1p 20715 328
- 8310120040 Mod 3, changing contractors name, revising & expanding statement of work, extending period of performance to 840930 & obligating funds, to "Reviewing Hydrologic Investigations of BWIP "
WILLIAMS, R E Williams & Associates GUSTAVE, R P Division of Contracts FIN B-7372-3 NRC-02-82-044 83/09/29 20pp 20715 329
- 8310120032 Notification of contract execution, Mod 3 to "Preventive & Remedial Maint of Multichannel Analyzers " Contractor Nuclear Data, Inc.
GILDENHORN, A J Administrative Contracts Branch NRC-05-81-260
83/09/28 PAGE, M Region 2, Office of Director 1pp 20715 314
- 8310120055 Mod 3, adding funds for travel & travel time for second yr performance, revising & clarifying statement of work & extending period of performance to 840930, to "Preventive & Remedial Maint of Multichannel Analyzers "
BRACKMAN, T W Nuclear Data, Inc HAGAN, T F Administrative Contracts Branch NRC-05-81-260 83/09/28 12pp 20715 315
- 8310130162 Notification of grant execution "Stability Under Seismic Loading," awarded, to Lehigh Univ
UMBEL, D Technical Assistance Contracts Branch FIN G-1060
NRC-0-04-83-009 83/09/20 BATSON, W Office of Nuclear Reactor Regulation, Director ARNDT, G NRC - No Detailed Affiliation Given 1p 20777 168
- 8310130163 Grant: "Stability Under Seismic Loading," awarded to Lehigh Univ.
GOLDBSTEIN, J I Lehigh Univ, Bethlehem, PA MORTON, K V Technical Assistance Contracts Branch FIN G-1060
NRC-0-04-83-009 83/09/20 2pp 20777 169

NONDOCKETED ITEMS

40

831013019B Notification of contract execution "Reviewing Hydrogeologic Investigations of Bedded & Dome Salt Basins-Project B," awarded to Golder Assoc
WIGGINS, E Technical Assistance Contracts Branch FIN B-7390-3
NRC-02-B3-034 83/09/30 BROWN, R S Program Support Branch
JOHNSON, R NRC - No Detailed Affiliation Given 1p 20772 332

--8310130201 Contract "Reviewing Hydrogeologic Investigations of Bedded & Dome Salt Basins-Project B," awarded to Golder Assoc
TALBOT, R Golder Associates MORTON, K V Division of Contracts
FIN B-7390-3 NRC-02-B3-034 83/09/30 44pp 20772 333

8310130263 Corrected notification of contract execution, Mod 3, to "Preventive & Remedial Maint of Multichannel Analyzers " Contractor Nuclear Data, Inc
GILDENHORN, A J Administrative Contracts Branch NRC-03-B1-260
83/09/28 PAGE, M Region 2, Office of Director 1p 20754 350

8310130380 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements " Contractor State of NY
UMBEL, D M Technical Assistance Contracts Branch FIN B-8355
NRC-28-B3-610 83/09/29 MCOSCAR, J Region 1, Office of Director
COSTELLO, F NRC - No Detailed Affiliation Given 1p 20770 118

--8310130385 Mod 1, adding funds to incorporate TLD program, to "Radiation Monitoring Program Requirements " LEAVY, W F New York, State of GUSTAVE, R P Technical Assistance
Contracts Branch FIN B-8355 NRC-28-B3-610 83/09/29 1p
20770 119

831013038B Notification of contract execution "Maint & Operation of LPDRs," awarded to Univ of New Orleans
FLYNN, M J Administrative Contracts Branch NRC-10-B3-727
83/09/30 FELTON, J Division of Rules and Records SOUDER, J NRC
- No Detailed Affiliation Given 1p 20771 027

--8310130389 Contract "Maint & Operation of LPDRs," awarded to Univ of New Orleans
GIBBS, P M New Orleans, Univ of MATTIA, M J Administrative
Contracts Branch NRC-10-B3-727 83/09/30 15pp 20771 028

8310130404 Notification of contract execution "Region V Data Entry Svcs," awarded to Phoenix Intl/SBA
FIELDB, J A Administrative Contracts Branch FIN B-8891
NRC-33-B3-467 83/09/30 BASSETT, H B Office of Resource
Management, Director HAMIL, K NRC - No Detailed Affiliation
Given 1p 20769 247

--8310130406 Contract "Region V Data Entry Svcs," awarded to Phoenix Intl/SBA
THOMAS, B T Phoenix International MIMS, R Division of
Contracts FIN B-8891 NRC-33-B3-467 83/09/30 2pp
20769, 248

--8310130407 Contract "Region V Data Entry Svcs," awarded to Phoenix Intl/SBA
MIMS, R Small Business Administration * Phoenix International
MATTIA, M J Division of Contracts FIN B-8891 NRC-33-B3-467
83/09/30 2pp 20769 250

8310130417 Notification of contract execution "Licensing Assistance/ Geotechnical & Hydrological Evaluations/URFO," awarded to Goodson & Assoc, Inc
WIGGINS, E Technical Assistance Contracts Branch FIN B-8507
NRC-R64-B3-673 83/09/29 SMITH, R D Uranium Recovery Field
Office GARCIA, P NRC - No Detailed Affiliation Given 1p
20768 332

--8310130418 Contract "Licensing Assistance/Geotechnical & Hydrological Evaluations/URFO," awarded to Goodson & Assoc, Inc
FUJIMOTO, R I Goodson & Associates, Inc FIN B-8507
NRC-R6-B3-673 83/09/29 37pp 20768, 333

8310170060 Notification of contract execution "In Situ Stress Measurements In Earth Crust In Eastern US," awarded to Engineers Intl, Inc
SABDEN, L Technical Assistance Contracts Branch FIN B-8292
NRC-04-B3-016 83/09/30 BATSON, W Office of Nuclear Regulatory
Research, Director SCHMITT, T NRC - No Detailed Affiliation Given
1p 20798 041

--8310170067 Contract "In Situ Stress Measurements In Earth Crust In Eastern US," awarded to Engineers Intl, Inc
SINGH, H M Engineers International, Inc MORTON, K V Division of
Contracts, FIN B-8292 NRC-04-B3-016 83/09/30 13pp,
20798, 042

8310170082 Notification of contract execution, Mod 2 to "Furnishing Engineering, Installation & Maint of Complete Operational Inservice Automatic Telephone Switching Sys/Equipment " Contractor American Telephone & Telegraph
GILDENHORN, A J Administrative Contracts Branch NRC-31-B3-661
83/09/30 COLLINS, J Region 4, Office of Director MELVILLE, T
NRC - No Detailed Affiliation Given 1p 20798 007

--8310170084 Mod 2, expanding base sys & changing sys turnover date to "Furnishing Engineering, Installation & Maint of Complete Operational Inservice Automatic Telephone Switching Sys/Equipment " VOLZER, H J American Telephone & Telegraph Co /American Bell.
HAGEN, T F Division of Contracts NRC-31-B3-661 83/09/30 6pp
20798 008

8310170111 Notification of contract execution, Mod 9 to "Technical Assistance to Support NRC-IE Personnel in Investigations of Incidents " Contractor Parameter, Inc
WOLLETT, S Technical Assistance Contracts Branch FIN B-1302
NRC-05-B2-249 83/09/29 BLAHA, J Director's Office, Office of
Inspection and Enforcement LAUDAN, W NRC - No Detailed Affiliation
Given 1p 20814 154

--8310170550 Mod 9, issuing Task Order 54, to "Technical Assistance to Support NRC-IE Personnel in Investigations of Incidents " LOFFY, R A Parameter, Inc GUSTAVE, R P Technical Assistance
Contracts Branch FIN B-1302 NRC-05-B2-249 83/09/29 3pp
20814 155

8310170112 Notification of contract execution, Mod 4 to "Info Mgt Sys for NRC Operation Ctr " Contractor Phoenix Assoc, Inc
GILDENHORN, A J Administrative Contracts Branch FIN B-8709
NRC-05-B3-218 83/10/11 MUIR, A P Program Support Branch
HINES, J NRC - No Detailed Affiliation Given 1p 20813 123

--8310170118 Mod 4, adding requirement for CEO sys design document & increasing contract amount, to "Info Mgt Sys for NRC Operation Ctr " FENSTERSTOCK, J Phoenix Associates, Inc HAGEN, T F
Administrative Contracts Branch FIN B-8709 NRC-05-B3-218
83/10/11 3pp, 20813 124

8310180101 Notification of contract execution "Stochastic Analysis of Solute Transport in Unsaturated Soil," awarded to MIT
DELOATCH, V Technical Assistance Contracts Branch FIN B-8956
NRC-04-B3-174 83/09/30 BATSON, W Office of Nuclear Regulatory
Research, Director NICHOLSON, T NRC - No Detailed Affiliation
Given 1p 20824 043

--8310180105 Contract "Stochastic Analysis of Solute Transport in Unsaturated Soil," awarded to MIT.
DUMMER, O M Massachusetts Institute of Technology, Cambridge, MA
MORTON, K V Division of Contracts FIN B-8956 NRC-04-B3-174
83/09/30 80pp 20824 044

8310180147 Notification of contract execution, Mod 6 to "Evaluation of Relative Surface Properties of Alternative Nuclear Waste Encapsulants " Contractor Univ of Florida
DELOATCH, V Technical Assistance Contracts Branch FIN F-6352
NRC-04-78-252 83/10/13 BATSON, W Office of Nuclear Regulatory
Research, Director KIM, K NRC - No Detailed Affiliation Given
1p 20827 050

--8310180157 Mod 6, modifying scope of work at no cost & changing title: "Evaluation of Relative Surface Properties of Alternative Nuclear Waste Encapsulants " STEVEN, A R Florida, Univ of, Gainesville, FL GUSTAVE, R P
Technical Assistance Contracts Branch, FIN F-6352 NRC-04-78-252
83/10/13, 4pp, 20827, 051.

8310180168 Notification of contract execution, Mod 2 to "Subscriptions to Publications, Inside Energy/W/Federal Lands, Inside FERC, Inside NRC, Nuclear Fuel, Nuclonics Wk " Contractor McGraw-Hill, Inc
HAWKINS, D A Administrative Contracts Branch, NRC-10-B3-321
83/10/13 BEBAW, W J Division of Technical Information & Document
Control CONYNHAM, M NRC - No Detailed Affiliation Given 1p
20827, 040

--8310180175 Mod 2, cancelling subscription to "Inside FERC" & decrease total contract amount, to "Subscription to Publications: Inside Energy/W/Federal Lands, Inside FERC, Inside NRC, Nuclear Fuel, Nuclonics Wk " FERRANTE, J McGraw-Hill Publications Co HAGEN, T, Division of
Contracts NRC-10-B3-321 83/10/13, 2pp, 20827, 041.

NONDOCKETED ITEMS

- 8310180554 Notification of contract execution, Mod 7 to "Evaluating Radiation Effects, Analytical Techniques & Testing Methods for Evaluation of Radiation Damage in Reactor Vessels " Contractor Naval Research Lab
SILVIR, R M Technical Assistance Contracts Branch FIN B-1151
NRC-03-76-348 83/10/12 DENTON, H R Office of Nuclear Reactor Regulation, Director HOGE, K NRC - No Detailed Affiliation Given
ip 20827 120
- 8310180557 Mod 7, deobligating funds, to "Evaluating Radiation Effects, Analytical Techniques & Testing Methods for Evaluation of Radiation Damage in Reactor Vessels " MCMORRIS, J A Navy, Dept of, Naval Research Lab GUSTAVE, R P Division of Contracts FIN B-1151 NRC-03-76-348 83/10/12 1p 20827 121
- 8310180573 Notification of contract execution, Mod 1 to "Fundamentals of Bias Correction Problems " Contractor Battelle Memorial Inst
DELOATCH, V Technical Assistance Contracts Branch FIN B-8105
NRC-04-82-012 83/10/12 FORHAND, W Office of Nuclear Regulatory Research, Director RIVERS, J D NRC - No Detailed Affiliation Given 1p 20817 359
- 8310180576 Mod 1, changing Articles I & II to extend period of performance 3 months, to "Fundamentals of Bias Correction Problems " ACE, J K Battelle Memorial Institute GUSTAVE, R P Division of Contracts FIN B-8105 NRC-04-82-012 83/10/12 2pp 20817 360
- 8310180581 Notification of contract execution, Mod 11 to "Tornado Parameters for Nuclear Power Plants " Contractor Univ of Chicago
SILVIR, R M Technical Assistance Contracts Branch FIN A-4059
NRC-04-74-239 83/07/11 BATSON, W Office of Nuclear Regulatory Research, Director ABBEY, R NRC - No Detailed Affiliation Given
ip 20817 357
- 8310180585 Ltr Contract NRC-04-74-239, Mod 11, deobligating funds, to "Tornado Parameters for Nuclear Power Plants " GUSTAVE, R P Technical Assistance Contracts Branch FIN A-4059, NRC-04-74-239 83/05/18 SIGAL, D S Chicago, Univ of, Chicago, IL 1p 20817 358
- 8310180592 Notification of contract execution, Mod 6 to "ADP Sys Support " Contractor SBA/Technassociates, Inc
MCLEAREN, T Administrative Contracts Branch FIN B-1664
NRC-25-82-315 83/10/13 BARRY, L W Office of Resource Management, Director BURTON, J NRC - No Detailed Affiliation Given
ip 20817 355
- 8310180596 Mod 6, increasing amount obligated to "ADP Sys Support " * Small Business Administration * Technassociates, Inc HAGAN, T F Division of Contracts FIN B-1664 NRC-25-82-315 83/10/13 1p 20817 356
- 8310190276 Notification of contract execution "Assessment of Implications of Low Enrichment U Fuel for Research Reactors," awarded to Rensselaer Polytechnic Inst
MCDERMOTT, D Technical Assistance Contracts Branch FIN D-1126
NRC-04-83-179 83/09/21 BATSON, W Office of Nuclear Regulatory Research, Director KELBER, C NRC - No Detailed Affiliation Given
ip 20843 177,
- 8310190281 Contract "Assessment Implications of Low Enrichment U Fuel for Research Reactors," awarded to Rensselaer Polytechnic Inst.
LODIUICE, J M Rensselaer Polytechnic Inst, Troy, NY.
MORTON, K V Division of Contracts FIN D-1126 NRC-04-83-179 83/09/21 9pp 20843 178
- 8310200458 Notification of contract execution "Removal of Irradiated & Unirradiated Matl From KRB-A Gundremmingen Reactor, Gunzburg, Federal Republic of Germany," awarded to QO Noel GmbH.
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8942
NRC-04-83-017 83/07/12 FORHAND, W Office of Nuclear Regulatory Research, Director, SERPAN, C Z NRC - No Detailed Affiliation Given
ip 20872 219
- 8310200462 Contract "Removal of Irradiated & Unirradiated Matl From KRB-A Gundremmingen Reactor, Gunzburg, Federal Republic of Germany," awarded to QO Noel GmbH
HURZBURG, G N, QO Noel GmbH MORTON, K V, Division of Contracts FIN B-8942 NRC-04-83-017 83/07/12 60pp 20872, 220.
- 8310210083 Notification of contract execution "Independent Assessment - Destructive Testing & Analysis," awarded to Franklin Inst.
BAISDEN, L Technical Assistance Contracts Branch FIN B-8708
NRC-05-83-216 83/09/30 MUIR, A Director's Office, Office of Inspection and Enforcement LAUDAN, W NRC - No Detailed Affiliation Given
ip 20884 031.
- 8310210097 Contract "Independent Assessment - Destructive Testing & Analysis," awarded to Franklin Inst
ROSENBERG, E B Franklin Institute/Franklin Research Center
MORTON, K V Division of Contracts FIN B-8708 NRC-05-83-216 83/09/30 30pp 20884 032
- 8310210086 Notification of contract execution, Mod 10 to "Graphics/ Photographic Svcs " Contractor Robert Charles Mole & Assoc
GILDENHORN, A J Administrative Contracts Branch FIN B-1297
NRC-05-81-257 83/10/18 BLAHA, J L Program Support Branch
THAYER, C NRC - No Detailed Affiliation Given 1p 20883 341
- 8310210087 Mod 10, adding incremental funding balance, to "Graphics Photographic Svcs " * Robert Charles Moles & Associates HAGAN, T F Administrative Contracts Branch FIN B-1297 NRC-05-81-257 83/10/18 1p 20883 342
- 8310210091 Notification of contract execution, Mod 4 to "Evaluation of Ecosystem Simulation Models as Tools for Assessment of Power Plant Impacts on Fish Populations " Contractor Univ of Washington
WOLLETT, S Administrative Contracts Branch FIN B-7018
NRC-04-80-214 83/10/06 BATSON, W Office of Nuclear Regulatory Research, Director SWANBERG, F NRC - No Detailed Affiliation Given
ip 20883 339
- 8310210093 Mod 4, adding no cost extension to 840630, to "Evaluation of Ecosystem Simulation Models as Tools for Assessment of Power Plant Impacts on Fish Populations " ALLEN, D R Washington Univ MORTON, K V Administrative Contracts Branch FIN B-7018 NRC-04-80-214 83/10/06 1p 20883 340
- 8310210150 Notification of contract execution, Mod 1 to "Reorganizing & Purging of Safety Reactor Files at PDR & ACRS " Contractor Labat-Anderson, Inc/SBA
MCLEAREN, T Administrative Contracts Branch NRC-10-83-722
83/10/17 BESAW, W J Division of Technical Information & Document Control SKOCZLAS, J NRC - No Detailed Affiliation Given
ip 20883 337
- 8310210155 Mod 1, correcting base upon which G&A rate is computed, to "Reorganizing & Purging of Safety Reactor Files at PDR & ACRS " * Small Business Administration * Labat-Anderson, Inc HAGAN, T F Administrative Contracts Branch NRC-10-83-722 83/10/17 1p 20883 338
- 8310210164 Notification of contract execution, Mod 1 to "Development of Nuclear Reactor Data Bank " Contractor Technology Development of California
JACOBS, A Administrative Contracts Branch, FIN B-7077,
NRC-04-80-215 83/09/12 BATSON, W Office of Nuclear Regulatory Research, Director TROUTHAN, C NRC - No Detailed Affiliation Given
ip 20884 083
- 8310210180 Mod 1, extending period of performance to 841030 & adding Tasks 17-23, to "Development of Nuclear Reactor Plant Data Bank " WODARSKI, L J Small Business Administration GREENE, F B Technology Development of California, Inc GUSTAVE, R Administrative Contracts Branch FIN B-7077 NRC-04-80-215 83/09/12 7pp 20884 084
- 8310210189 Notification of contract execution, Mod 7 to "Transient Prototypical Steam Generator MB-2 Research Testing Program " Contractor EPRI/Westinghouse.
BAISDEN, L Administrative Contracts Branch, FIN B-8252
NRC-04-82-020 83/10/14 BATSON, W Office of Nuclear Regulatory Research, Director BECKNER, W NRC - No Detailed Affiliation Given
ip 20884 091
- 8310210198 Mod 7, extending period of performance to 830930 & adding addl funds, to "Transient Prototypical Steam Generator MB-2 Research Testing Program " ROSENBLATT, H B Westinghouse Electric Corp RYTKONEN, B D Electric Power Research Institute MORTON, K V Administrative Contracts Branch FIN B-8252 NRC-04-82-020 83/10/14 2pp 20884 092
- 8310210205 Notification of grant execution, Mod 1 to "Evaluation of Benefits of Response-Time In Situ Testing of Neutron Sensors Used in Nuclear Power Reactor Protection Sys " Grantee, Ohio State Univ Research Foundation
UMBEL, D M Administrative Contracts Branch FIN Q-1044
NRC-Q-04-83-01 83/10/05, BATSON, W Office of Nuclear Regulatory Research, Director HINTZE, A NRC - No Detailed Affiliation Given
ip 20884 094

NONDOCKETED ITEMS

407

--B310210211 Mod 1, extending period of performance to B31130, to "Evaluation of Benefits of Response-Time In Situ Testing of Neutron Sensors Used in Nuclear Power Reactor Protection Sys "

SLOAN, K W Ohio State Univ , Columbus, OH MORTON, K V
Administrative Contracts Branch FIN G-1044 NRC-G-04-B3-01
B3/10/05 1p 20884 095

B310210337 Notification of contract execution, Mod 1A to "Advisory Committee for Review of Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation "

Contractor Kator, Scott & Heller
TOWNSEND, B Purchasing Section FIN B-8182 NRC-18-B3-409
B3/09/20 FITZGERALD, J A Office of the General Counsel LEVI, R
NRC - No Detailed Affiliation Given 1p 20882 362

B310240097 Notification of contract execution, Mod 3 to "Accelerating Establishment of Stds & Adoption as Reg Guides by AEC "

Contractor ANSI
UMBEL, D M Technical Assistance Contracts Branch NRC-01-75-094
B3/10/12 FOREHAND, W Office of Nuclear Regulatory Research, Director TING, P NRC - No Detailed Affiliation Given 1p
20891 357

--B310240098 Mod 3, deobligating balance of funds, to "Accelerating Establishment of Stds & Adoption as Reg Guides by AEC "

MORRISON, J K American National Standards Institute GUSTAVE, R P
Division of Contracts NRC-01-75-094 B3/10/12 1p 20891 358

B310240104 Notification of contract execution, Mod 1 to "Managerial Competencies " Contractor USDA Graduate School

PERLMAN, J Administrative Contracts Branch NRC-10-B3-300
B3/10/19 GOLDMAN, P J , ALLEN, R A Office of Administration 1p
20891 353

--B310240106 Mod 1, clarifying ordering procedures, to "Managerial Competencies "

* Agriculture, Dept of, Graduate School HAGAN, T F
Administrative Contracts Branch NRC-10-B3-300 B3/10/19 1p
20891 354

B310240127 Notification of contract execution, Mod 1 to "Executive Development Program " Contractor USDA Graduate School

PERLMAN, J Administrative Contracts Branch NRC-10-B3-299
B3/10/19 GOLDMAN, P J , ALLEN, R A Office of Administration 1p
20884 361

--B310240130 Mod 1, modifying ordering procedures, to "Executive Development Program "

* Agriculture, Dept of, Graduate School HAGAN, T F Division of
Contracts NRC-10-B3-299 B3/10/19 1p 20884 362

B310260290 Notification of contract execution, Mod 2 to "Classified Waste Paper Destruction Project " Contractor Simkins Industries, Inc

HAWKINS, D A Division of Contracts NRC-10-B2-403 B3/10/19
BRADY, R J Division of Security BURNSIDE, W NRC - No Detailed
Affiliation Given 1p 20918 333

--B310260296 Mod 2, clarifying formula under which Govt shall be reimbursed for classified waste paper, to "Classified Waste Paper Destruction Project "

RUSSELL, V Simkins Industries, Inc SMITH, P A Division of
Contracts NRC-10-B2-403 B3/10/19 1p 20918 334

B310260371 Notification of contract execution, Mod 10 to "Licensing Technical Assistance " Contractor Science Applications Inc

WOLLETT, S Administrative Contracts Branch NRC-02-B3-035
B3/10/13 DAVIS, J, Office of Nuclear Material Safety &
Safeguards, Director LOYSEN, P NRC - No Detailed Affiliation Given
1pp 20918 356

--B310260375 Mod 10, extending period of performance on Tasks 002 to B31231 & 007 to B31130 at no addl cost to govt, to "Licensing Technical Assistance "

FINDLEY, D E Science Applications, Inc GUSTAVE, R P
Administrative Contracts Branch NRC-02-B3-035 B3/10/13 1pp
20918 357

B310270567 Notification of contract execution "Examine Facts in Employee Grievance; Hold Hearing Including Taking of Testimony & Acceptance of Evidentiary Matl & Make Final Written Rept." awarded to L Aronin

MURPHY, L G Administrative Contracts Branch NRC-10-B4-240
B3/10/21 GIRD, P E Division of Organization and Personnel
MORRINKLE, C NRC - No Detailed Affiliation Given 1p 20946 034

--B310270577 Contract "Examine Facts in Employee Grievance; Hold Hearing Including Taking of Testimony & Acceptance of Evidentiary Matl & Make Final Written Rept." awarded to L Aronin

ARONIN, L Aronin, L REBELLO, J E Administrative Contracts
Branch NRC-10-B4-240 B3/10/21 6pp 20946 035

B310270596 Notification of contract execution, Mod 10 to "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents " Contractor Parameter, Inc

WOLLETT, S Technical Assistance Contracts Branch FIN B-1302
NRC-05-B2-249 B3/10/19 BLAHA, J Director's Office, Office of
Inspection and Enforcement LAUDEN, W NRC - No Detailed Affiliation
Given 1p 20946 256

--B310270606 Mod 10, providing for administrative changes, to "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents "

* Parameter, Inc GUSTAVE, R P Division of Contracts FIN
B-1302 NRC-05-B2-249 B3/10/19 2pp 20946 257

B310280062 Notification of contract execution, Mod 3 to "Reviewing Hydrogeologic Investigations of Nevada Test Site - Project C " Contractor Williams & Assoc, Inc

FLAENOR, C Administrative Contracts Branch NRC-02-B2-046
B3/10/19 DAVIS, J Office of Nuclear Material Safety &
Safeguards, Director FOULKE, J NRC - No Detailed Affiliation Given
1p 20964 113

--B310280068 Mod 3, changing contractor name from Williams-Robinette & Assoc to Williams & Assoc, Inc, to "Reviewing Hydrogeologic Investigations of Nevada Test Site - Project C "

WILLIAMS, R E Williams-Robinette & Associates, Inc GUSTAVE, R
Administrative Contracts Branch NRC-02-B2-046 B3/10/19 6pp
20964 114

B310280074 Notification of grant execution, Mod 3, to "Formation of Recommendations on Radiation Protection & Measurement re Technology Base Needed to Assess Safety of Nuclear Power "

Grantee Natl Council on Radiation Protection & Measurements
UMBEL, D Administrative Contracts Branch FIN G-1030
NRC-04-B1-029 B3/10/20 BATSON, W Office of Nuclear Regulatory
Research, Director FOULKE, J NRC - No Detailed Affiliation Given
1p 20964 108

--B310280104 Mod 3, changing method of payment, to "Formation of Recommendations on Radiation Protection & Measurement re Technology Base Needed to Assess Safety of Nuclear Power "

HAY, W R National Council on Radiation Protection & Measurements
MORTON, K V Administrative Contracts Branch FIN G-1030
NRC-04-B1-029 B3/10/20 1p 20964 109

B310280133 Notification of contract execution, Mod 1 to "Technical Assistance in Defense of Appeal of TERA Advanced Svcs Corp (TASC) Before GSA Board of Contract Appeals " Contractor Dataflow Sys, Inc

TOWNSEND, B Administrative Contracts Branch NRC-10-B3-368
B3/10/25 MORRIS, P O Office of Administration AVERY, R E NRC -
No Detailed Affiliation Given 1p 20963 361

--B310280137 Mod 1, adding one addl trip, increasing level of effort & increasing funding, to "Technical Assistance in Defense of Appeal of TERA Advanced Svcs Corp (TASC) Before GSA Board of Contract Appeals "

BOUDNIKOFF, O Dataflow Systems, Inc REBELLO, J E Administrative
Contracts Branch, NRC-10-B3-368 B3/10/25 1p 20963 362

FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES

B310110001 FOIA request for listed documents to be placed in PDR Documents requested are references from NUREG-0800, Pages 3 5 1 6-7

PEDRO, J NUS Corp CD-15-B3-047 B3/06/17 Division of Rules
and Records 1p 20704 136

B310110004 Responds to FOIA request for five documents Forwards documents Documents also available in PDR

FELTON, J M Division of Rules and Records B3/07/01 PEDRO, J NUS
Corp 2pp 20704:137 24X Fiche 30-000, B3/07/01, B310110004

--B310110010 "Appraisal of Fire Effects From Aircraft Crash At Zion Power Reactor Facility "

PINKEL, J I Atomic Energy Commission 72/07/17 35pp
20704 139 24X Fiche: 30-000, B3/07/01, B310110004

--B310110011 Testimony of D9 Eisenhower re Zion/Haukegan Airport interaction

* Atomic Energy Commission B3/07/01 10pp 20704, 174 24X
Fiche 30-000, B3/07/01, B310110004

--B310110013 Forwards preliminary evaluation of aircraft hazards at Pebble Springs site, per 731010 request Site probably acceptable provided reasonable care taken to minimize effective target area

DEYOUNG, R C Atomic Energy Commission, Directorate of Licensing
73/11/23 WILLIAMS, J L Portland General Electric Co 5pp
20704 184

NONDOCKETED ITEMS

- B310110016 Informs that preapplication safety review completed based on
util 730507 submittal of proposed facility design Vital
areas & mods to be made prior to operation discussed
DEVOUNG, R C Atomic Energy Commission, Directorate of Licensing
73/10/12 WILLIAMS, J L Portland General Electric Co 2pp
20704 189
- B310110018 "Aircraft Considerations Preapplication Site Review"
JM Campbell 710519 ltr to CPC encl
* Atomic Energy Commission, Directorate of Licensing 73/10/12
58pp 20704 191 24X Fiche 50-000, B3/07/01, B310110004
- B310110005 FOIA request for SECY-82-279, SECY-82-330 & SECY-83-120
PEDRO, J NUS Corp CD-18-B3-035 B3/06/14 Division of Rules
and Records 1p 20712 279
- B310110007 Responds to FOIA request for SECY-82-279, SECY-82-330 &
SECY-83-120 Forwards documents Documents also available in
PDR
FELTON, J M Division of Rules and Records B3/07/15 PEDRO, J NUS
Corp 1p 20712 280 24X Fiche 50-445, B3/07/15, B310110007
- B208270562 SECY-82-330
Recommends approval of mods to NRC personnel security
clearance program to sharply reduce investigative costs w/o
lessening operational effectiveness
DIRCKS, W J Office of the Executive Director for Operations
B2/08/03 12pp 20712 307
- B310110017 SECY-82-279
Provides info paper on current status of nuclear plant
reliability data sys
DIRCKS, W J Office of the Executive Director for Operations
B2/07/01 26pp 20712 281
- B310110022 SECY-83-120
Recommends issuance of encl proposed order directing ASLB
to resume hearings as soon as possible on issue not
involving informant identities
PLAINE, H M Office of the General Counsel B3/04/01 4pp
20712 319 24X Fiche 50-445, B3/07/15, B310110007
- B310110020 FOIA request for RFP R8-DRM-B3-464
DOHERTY, E A Raytheon Corp EAD 0MD B3 3367 B3/06/30
FELTON, J M Division of Rules and Records 1p 20706 251
- B310110021 Responds to FOIA request for RFP R8-DRM-B3-464, successful
bidders proposal & contract Forwards RFP Successful bidders
proposal & contract not yet available RFP also available in
PDR
FELTON, J M Division of Rules and Records B3/07/15 DOHERTY, E A
Raytheon Corp 1p 20706 252
- B310110025 Requests proposals for R8-ADM-B3-464, "Design, Programming,
Testing, Training, Implementation & Documentation of Licensing
Mgt Sys (LMS)," w/basic contract for ADP development,
NRC-33-83-452 Related info encl
MATTIA, M J Division of Contracts NRC-33-83-452 B3/05/23
Affiliation Unknown 52pp 20706 253
- B310110030 Addl response to FOIA request for winning technical
proposals under RFP R8-DRM-B3-452 resulting in multiple
award task order Contracts NRC-33-83-452-01 through 07
Forwards App C document Document also available in PDR
FELTON, J M Division of Rules and Records B3/06/30 PAUL, L. K
Affiliation Unknown. 2pp 20704 249
- B310110033 "Technical Proposal for Multiple Award Task Order Contract
for ADP Development" Info deleted
* Automation Industries, Inc. VL-C-71026 B2/07/14 65pp
20704 251
- B310110034 Further response to FOIA request for records re NUREG-0862
investigative rept & investigations concerning facilities
Forwards App A documents Commissioner Bradford B11217 memo
withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records B3/06/15 REYNOLDS, J
Center for Law in the Public Interest App. 20713 001 24X
Fiche. 50-275, B3/06/15, B310110034
- B208010014 Requests issuance of final statement clearing RL Cloud
Associates from allegations of wrongdoing in preparation of
"Preliminary Rept. Seismic Verification Program," per NRC
investigation results in NUREG-0862, Issue 3
CLOUD, R L Robert L Cloud Associates, Inc. B2/08/24,
PALLADINO, N J Commissioners. 3pp. 20713. 032 24X
Fiche 50-275, B3/06/15, B310110034
- B310110037 Excerpt from meeting transcript re RL Cloud rept
* NRC - No Detailed Affiliation Given B1/12/17. 3pp
20713 005.
- B310110039 Forwards draft ltrs to Subcommittee on Energy & Environ
Subcommittee on Energy Conservation & Power transmitting NRC
review of NUREG-0862 Comments requested by B20811
KAMMERER, C Office of Congressional Affairs B2/08/09
BICKWIT, L Office of the General Counsel CUMMINGS, J Office of
Inspector & Auditor FITZGERALD, J Office of Investigation 5p.
20713 008 24X Fiche 50-275, B3/06/15, B310110034
- B310110046 Responds to B11217 ltr expressing concern re delays in
licensing process Immediate issue concerns acceptability of
util proposed auditors, RL Cloud Assoc Investigation
scheduled for completion on B21108 & B30201
KAMMERER, C Office of Congressional Affairs B2/01/10
ROUSSELOT, J H House of Rep 1p 20713 013 24X
Fiche 50-275, B3/06/15, B310110034
- B310110048 "Chronology of Events"
* Affiliation Unknown B3/06/15 8pp 20713 015 24X
Fiche 50-275, B3/06/15, B310110034
- B310110057 Draft ltrs re adequacy of NRC investigation into development
of RL Cloud Assoc rept, per NUREG-0862, "Insp Rept of
Preliminary Rept. Seismic Verification Program at Diablo
Canyon Nuclear Power Plant"
PALLADINO, N Commissioners B3/06/15 UDALL, M K House of Rep
Interior & Insular Affairs OTTINGER, R, DINGELL, J House of
Rep, Energy & Commerce 7pp 20713 024 24X
Fiche 50-275, B3/06/15, B310110034
- B310110095 Forwards RL Cloud B20824 request for final statement on
conclusions of Cloud/util investigation to clear Cloud prof
reputation Matter presented in NUREG-0862 & SECY-82-89
Commission guidance requested
DIRCKS, W J Office of the Executive Director for Operations
B3/09/08 PALLADINO, N Commissioners 1p 20713 031 24X
Fiche 50-275, B3/06/15, B310110034
- B310110103 Informs of delay in review of investigation reported in
NUREG-0862 Completion of rept review expected by B20802
CUMMINGS, J J Office of Inspector & Auditor B2/07/15
PALLADINO, N Commissioners 1p 20713 035
- B310110107 Forwards summary documenting record actions of peer review
group
REHM, T A Office of the Executive Director for Operations
B2/02/18 PALLADINO, N, GILINSKY, V, BRADFORD, P Commissioners
1p 20713 036 24X Fiche 50-275, B3/06/15, B310110034
- B310110111 Forwards summary of Region V peer review group assistance w/
investigation of RL Cloud Assoc Related info encl
CORNELL, E K Office of the Executive Director for Operations
CASE, E G Office of Nuclear Reactor Regulation, Director
SNIJEZEK, J H Director's Office, Office of Inspection and
Enforcement B2/02/18 DIRCKS, W J Office of the Executive
Director for Operations 74pp 20713 037 24X
Fiche 50-275, B3/06/15, B310110034
- B310110040 FOIA request for BALP documents, written or routed since
1979, which mention or refer to facility & describe or
provide info on BALP insp findings or conclusions based on
BALP reviews
RIDENHOUR, R Qambit B3/05/04 GRIMSLEY, D C NRC - No Detailed
Affiliation Given 2pp 20713 306 24X Fiche 50-382, B3/05/04,
B310110040
- B310110044 Responds to FOIA request for BALP documents, written or
routed since 1979, which mention or refer to facility &
describe or provide info on BALP insp findings or
conclusions re BALP reviews Forwards App A documents
FELTON, J M Division of Rules and Records B3/07/20 RIDENHOUR, R
Qambit 2pp 20713 308, 24X Fiche 50-000, B3/07/20, B310110044
- B112170188 Advises that Cycle 2 of systematic evaluation of licensee
performance will cover Jul 1980-June 1981 Regional board
meetings will be conducted Jul-Dec 1981 All Cycle 2 NRR
performance evaluation encl
EISENHUT, D O Division of Licensing B1/06/04 Division of
Engineering 4pp 20713.310 24X Fiche 50-382, B3/07/20,
B310110044
- B208230434 Requests input & appropriate comments, re systematic
assessment of licensee performance, (BALP) for Aug 1981-Jul
1982. Response required by B20806 BALP criteria encl
BLACK, S Licensing Branch 3 B2/08/03 Licensing Branch 3
13pp 20713 324, 24X Fiche. 50-382, B3/07/20, B310110044
- B209010214 Forwards draft NRR input for systematic assessment of
licensee performance. Draft based partly on input solicited
from selected staff personnel having contact & involvement
w/util licensing activities
BLACK, S Licensing Branch 3, B2/08/11 EISENHUT, D O Division
of Licensing 3pp 20713 331 24X Fiche. 50-382, B3/07/20,
B310110044

NONDOCKETED ITEMS

409

--B210050447 Forwards final NRR input for Cycle 3 systematic assessment of licensee performance Performance is rated Category 2 Licensee resources adequate although staffing could be improved
BLACK, B Operating Reactors Branch 3 82/08/23 EISENHUT, D G
Division of Licensing 3pp 20713 336 24X Fiche 90-382,
83/07/20, B310110044

--B310110051 SALP rept for Jul 1980 - June 1981 Const allegations reviewed
SEYFRIT, K V Region 4, Office of the Director 83/07/20 10pp
20713 314 24X Fiche 90-382, 83/07/20, B310110044

--B310110059 Forwards case chronology re allegations concerning welding issues at facilities w/o encl
ALDERSON, C E Region 2, Office of the Director 83/02/23
JOHNSON, G E Office of the Executive Legal Director 1p
20713 341 24X Fiche 90-413, 83/07/20, B310110044

B310110065 Further response to FOIA request for records re incineration of radioactive matls by Dow Chemical Co Midland, MI plant
Forwards App B documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/06/20 GARDE, B P
Government Accountability Project 2pp 20704 001

--B310110070 Forwards Div of Compliance info re noncompliance of activities under License 21-00265-04 Corrective steps to be taken requested Related info encl
HAGEMAN, R C Atomic Energy Commission 66/02/07 BEAMER, W H
Dow Chemical Co 36pp 20704 004

--B310110077 Informs that 651229 wipe test of 20 mCi Sr-90 beta source in Barber-Coleman Co instrument revealed leakage of sealed radioactive source Source removed from instrument & now stored in sealed container Source to be replaced
BEAMER, W H Dow Chemical Co 66/01/19 Atomic Energy Commission 1p 20704 041

--B310110101 Insp Findings & Licensee Ack dtd 681007-08 of Licenses 21-00265-04 & 21-00265-06 Insp findings no noncompliance noted Related info encl
* Atomic Energy Commission 68/11/21 10pp 20704 042

--B310110108 Forwards Insp Findings & Licensee Ack re activities under Licenses 21-00265-04, STB-527 & SMB-111 & Div of Compliance Form AEC-592 concerning noncompliance activities under Licenses 21-00265-02 & 21-00265-06
GRIER, B H Atomic Energy Commission 70/06/08, SILVERSTEIN, L
Dow Chemical Co 1p 20704 032

--B310110115 Insp Findings & Licensee Ack dtd 700519-20 of Licenses STB-527, SMB-111 & 21-000265-04 Insp findings no noncompliance noted Related info encl
SCHULTZ, W H Atomic Energy Commission 70/06/08 16pp
20704 053

--B310110125 Responds to 700608 ltr re noncompliance noted for Licenses 21-00265-02 & 21-00265-06 Corrective actions users of byproduct matl will be given formal written approval by radiation hazards committee Related info encl
HOYLE, H R Dow Chemical Co 70/06/16 SCHULTZ, W H Atomic Energy Commission 3pp 20704 069

--B310110130 Ack receipt of 700616 ltr informing NRC of steps taken to correct noncompliance noted in 700608 ltr
GRIER, B H Atomic Energy Commission, 70/06/22 HOYLE, H R Dow Chemical Co 1p 20704 074,

--B310110134 Insp Findings & Licensee Ack dtd 740821-22 of Licenses 21-00265-02, 21-00265-04 & 21-00265-06 Insp findings Part 19 documents not posted Related info encl
* Region 3, Chicago, Office of the Director 74/08/22 12pp,
20704 075

--B310110139 Discusses insp of License 8NM-1451, 21-00265-04 & 21-00265-06 on 761006 & forwards description of noncompliance
ALLAN, J M Region 3, Chicago, Office of the Director 76/10/20
LANGNER, R R Dow Chemical Co 2pp 20704.087,

--B310110143 Notice of noncompliance from insp of License 21-00265-06 on 761006 Noncompliance noted individuals received overexposures when allowed to enter unrestricted area Draft insp rept encl.
* Region 3, Chicago, Office of the Director, 76/10/20, 28pp
20704 089

--B310110147 IE Insp Rept 30-04783/81-01 on 811214-15 No noncompliance noted Major areas inspected review of lab procedures & records, industrial hygiene dept training & bldg tour Related info encl
SLOWINSKI, W J, MADDEN, J R, SRENIANSKI, D J Region 3, Chicago, Office of the Director IE3-79-19 81/12/24 19pp 20704 117

B310110350 Final response to FOIA request for matl re NRC consultation w/EPA to promulgate stds for remedial actions at inactive U processing sites C Kammerer 821222 memo to Commissioners encl
FELTON, J M Division of Rules and Records 83/06/13 DUNN, K
Beers & Dickson 4pp 20712 341

--B310110351 Forwards EPA 821215 press release re environ protection stds for cleanup & long-term control of U mill tailings
KAMMERER, C Office of Congressional Affairs 82/12/22
PALLADINO, N, OILINSKY, V, HEARNE, J P Commissioners 1p
20712 342

B310110353 Responds to FOIA request for Wyoming Fuel Co application for source matl license Forwards requested info Records do not indicate that FOIA request received from P Girouard dtd 830210 W/o encl
FELTON, J M Division of Rules and Records 83/08/04 HOFFMAN, T E
Western Nebraska Resources Council 1p 20712 352

B310110356 FOIA request for Wyoming Fuel Co application for source matl license Requests NRC hold hearing on application Response never received for Girouard 830210 FOIA request
HOFFMAN, T E Western Nebraska Resources Council 83/07/06
FELTON, J M Division of Rules and Records 1p 20712 353

B310110359 FOIA request for seven categories of documents re NRC document control sys
BLAIR, L R Affiliation Unknown 83/03/02 Division of Rules and Records 1p 20683 001

B310110361 Responds to FOIA request for NRC rept re violations at facility over misplaced & misfiled documents during 1981-82 Lists repts identified by Region II ofc prepared in 1981-82 Repts available in PDR
FELTON, J M Division of Rules and Records 83/08/18 FOLEY, J R
Foley, Hoag & Eliot 1p 20712 350 24X Fiche 90-438, 83/08/18, B310110361

B310110364 Responds to FOIA request for seven categories of documents re NRC document control sys, Forwards App A documents, App B documents withheld (ref FOIA Exemption 4)
FELTON, J M Division of Rules and Records 83/06/13 BLAIR, L R
Affiliation Unknown 4pp, 20683 002

--B310110371 Trip rept of 810414-15 visit to DCAA & TERA re DCAA audit of TERA CFY-80 billings to NRC & TERA briefing on development of Boolean search sys
ROWE, P Office of the Executive Director for Operations 81/04/21 Office of the Executive Director for Operations 2pp
20683 042

--B310110375 Forwards 810626 memo documenting technical input to NRC decisions re continued lease or purchase of document control sys computer hardware
BALL, C G Air Force, Dept of 81/07/07 ROWE, P Office of the Executive Director for Operations 14pp, 20683 006

--B310110378 Forwards document control sys (DCS) equipment & software listings & certification stating that listings represent everything required to operate & maintain DCS, per 810513 request Sys schematic will be provided
LONG, J A TERA Corp NRC-10-78-580 TTN-W213 81/06/10
LEBO, C B Division of Contracts 14pp, 20683 044

--B310110384 Forwards federal computer performance evaluation & simulation ctr inputs to document control sys feasibility study
BALL, C G Air Force, Dept of 82/03/31 ROWE, P Office of the Executive Director for Operations 74pp 20683 059

--B310110388 "Document Control Sys Requirements & Feasibility Study," Vols 1-2
* Office of Administration 82/07/31, 371pp 20683 133

--B310110391 "NRC Document Control Sys," monthly progress rept for Apr 1983,
* Planning Research Corp NRC-10-82-356 83/04/30 NRC - No Detailed Affiliation Given 70pp, 20684 283

--B310110393 "NRC Document Control Sys," monthly progress rept for Mar 1983,
* Planning Research Corp NRC-10-82-356, 83/03/31, NRC - No Detailed Affiliation Given, 71pp 20684 353

NONDOCKETED ITEMS

--8310110395 "NRC Document Control Sys." monthly progress rpt for Feb 1983
 * Planning Research Corp NRC-10-82-356 82/02/28 NRC - No
 Detailed Affiliation Given 6pp 20683 061

--8310110400 "NRC Document Control Sys Semiannual Sys Review, Feb-Jul 1982"
 * Planning Research Corp NRC-10-82-356 82/09/30 NRC - No
 Detailed Affiliation Given 6pp 20684 144

--8310110404 Summary of Document Control Sys (DCS) Working Group 821117
 meeting re operational changes to DCS recommended by
 contractor in semiannual sys review under Task 9 of
 contract Meeting agenda encl
 LUNDY, J R Office of Administration 82/12/03 Office of
 Administration 3pp 20684 205

--8310110414 Mod 3, changing performance evaluation plan in Attachment C
 of contract, to "Operation & Maint of NRC Document Control
 Sys"
 THAMM, E G Planning Research Corp SMITH, P A Division of
 Contracts NRC-10-82-356 82/08/06 3pp 20684 268

--8310110419 Mod 6, changing refs to Ofc of Controller in contractual
 document or billing instructions to Ofc of Resource Mgt, to
 "Operation & Maint of NRC Document Control Sys"
 * Planning Research Corp SMITH, P A Division of Contracts
 NRC-10-82-356 82/08/23 1p 20684 271

--8310110422 Consents to subcontract w/Commart (Contract NRC-10-82-356),
 per contractor 830316 & 24 ltrs Subcontract should not be
 used in calculations for obtaining addl fee under Article
 XI
 SMITH, P A Administrative Contracts Branch NRC-10-82-356
 83/04/12 LIPPERINI, A Planning Research Corp 1p 20684 281

--8310110369 Forwards preliminary project plan/customer agreement re NRC
 document control sys, per 810220 & 0319 discussions
 BALL, C O Air Force, Dept of 81/03/31 ROWE, P Office of the
 Executive Director for Operations 1p 20683 033

8310110365 FOIA request for NRC rept re violations at facility over
 misplaced & misfiled documents during 1981-82
 FOLEY, J R Foley, Hoag & Eliot 83/08/09 GILLILAND, J Office of
 Public Affairs 1p 20712 351 24X Fiche 50-438, 83/08/09,
 8310110365

8310110425 FOIA request for info re PND-III-83-027 concerning faulty
 valve radiographs, PND-III-83-026 concerning use of lubricant
 on valve seats & info on DOE/NRC 830419-20 meetings
 concerning geologic repository in salt program
 HIATT, S L Ohio Citizens for Responsible Energy 83/05/10
 FELTON, J M Division of Rules and Records 1p 20706 001 24X
 Fiche 50-000, 83/05/10, 8310110425

10110430 Responds to FOIA request for four different categories of
 documents described in 830310 ltr Forwards matl listed in
 app A responsive to Items 1, 2 & 4 DOE should be contacted
 for matl requested in Item 3 of ltr
 FELTON, J M Division of Rules and Records 83/06/14 HIATT, S L
 via Citizens for Responsible Energy 3pp 20706 002 24X
 chv 50-000, 83/06/14, 8310110430

0110443 Forwards PND & morning rept re faulty Berg-Warner valve
 radiographs Problem may be generic Related info encl
 ITTLE, W S Region 3, Office of Director 83/04/13 POTAPOV, V
 Region 4, Office of Director 15pp 20706 005 24X
 lche 50-000, 83/06/14, 8310110430

10110455 Rev 1 to DMP 200-38 "MSIV 10X Closure Scram Setpoint Check"
 * Affiliation Unknown 79/11/30 4pp 20706 031

8310110458 Rev 0 to DMP 200-39 "MSIV Maint-Electrical" Related info
 encl
 * Affiliation Unknown 83/01/31 9pp. 20706 035

--8310110461 Excerpt from notification of events at two different
 facilities re deficiency concerning control complex chilled
 water sys & info received that please incorrectly used on
 MSIVs, respectively Related info encl
 * Region 3, Office of Director 83/04/08 11pp. 20706 044 24X
 Fiche 50-000, 83/06/14, 8310110430

--8310110464 Rev 1 to GW-482 "Welding Procedure Spec (GW-482)" Related
 info encl
 * Commonwealth Edison Co 81/08/27 7pp 20706 055

--8310110467 Daily rept re events at three different facilities LACBWP
 experienced scram due to low water level PND-III-83-026
 updates use of lubricants on valve seats
 * Region 3, Office of Director 83/04/14 1p 20706 062 24X
 Fiche 50-000, 83/06/14, 8310110430

--8310110478 Responds to 830413 ltr requesting info re use of foreign
 matls on valve seating surfaces Lubricants & cleaning
 solvents used on valve component surfaces per vendor
 recommendations & maint practices
 FARRAR, D L Commonwealth Edison Co 1389B 83/04/22
 KEPLER, J G Region 3, Office of Director 4pp 20706 063 24X
 Fiche 50-000, 83/06/14, 8310110430

--8310110484 Rev 9 to DAP 15-1 Attachment C procedure re feedwater check
 valve
 * Affiliation Unknown 83/04/09 7pp 20706 067

--8310110486 DTS 1600-1 R08
 Rev B to DTS 1600-1 "Primary Containment Penetration Leak
 Rate Test Data Sheet" W/related info
 CHRISTEL Affiliation Unknown 83/03/09 22pp 20706 076

--8310110490 Draft "Integral Sys Testing Program For B&W-Designed NSSS,"
 final rept
 * Babcock & Wilcox Operating Plants Owners Group 83/03/31
 128pp 20706 123

8310110432 FOIA request for RFP RS-ORM-83-500, "Cost Analyses of
 Proposed Changes in NRC Requirements," & SECY 83-157 to be
 placed in PDR
 GRABER, L NUS Corp 08-18-83-059 83/06/21 Division of Rules
 and Records 1p 20706 307

8310110436 Responds to FOIA request for RFP RS-ORM-83-500 &
 SECY-83-157 RS-ORM-83-500 placed in PDR SECY-83-157
 partially withheld (ref FOIA Exemption 5)
 FELTON, J M Division of Rules and Records 83/07/20 GRABER, L
 NUS Corp 2pp 20706 308 24X Fiche 50-322, 83/07/20, 8310110436

--8310110439 SECY-83-157
 Requests approval of proposed order re low power license for
 facility
 PLAINE, H H Office of the General Counsel 83/03/02 4pp
 20706 310 24X Fiche 50-322, 83/07/20, 8310110436

8310110444 Responds to FOIA request for WJ Dirks 830413 memo to BJ
 Chirk re test facility accreditation Document placed in PDR
 FELTON, J M Division of Rules and Records 83/07/20 PEDRO, J NUS
 Corp 1p 20706 305

8310110468 FOIA request for "Topical Rept on Methodology for
 Uncertainty Analysis of LWR Meltdown Accident Consequences"
 & "Methodology for Uncertainty Analysis of LWR Meltdown
 Accident Consequences"
 SHOLLY, S C Union of Concerned Scientists 83/05/06 FELTON, J M
 Division of Rules and Records 1p 20705 001

8310110470 Responds to FOIA request for two 1980 BMNL repts & documents
 per contracts between NRC & BM under which repts were
 produced, Rept placed in PDR
 FELTON, J M Division of Rules and Records 83/06/15 SHOLLY, S
 Union of Concerned Scientists 1p 20705 002

--8310110475 "Topical Rept on Uncertainty Analysis of LWR Meltdown
 Accident Consequences Methodology Development"
 BAYBUTT, P, KURTH, R E Battelle Memorial Institute, Pacific
 Northwest Laboratory FIN A-4067 NRC-04-76-293 78/01/10
 Office of Nuclear Regulatory Research, Director 120pp
 20705-003

--8310110480 "Methodology for Uncertainty Analysis of LWR Meltdown
 Accident Consequences"
 BAYBUTT, P., COX, D C, KURTH, R E Battelle Memorial Institute,
 Pacific Northwest Laboratory FIN A-4067 NRC-04-76-293
 81/05/31 Office of Nuclear Regulatory Research, Director
 84pp 20705 110

8310110496 FOIA request for BWR Owners Group control room survey
 program, reviewed in Generic Ltr 83-18
 WILLIAMS, O G Affiliation Unknown 0L-83-18 83/06/20
 FELTON, J M Division of Rules and Records 1p 20708 001

8310110503 Responds to FOIA request for BWR Owners Group control room
 survey program Requested info placed in LPDR
 FELTON, J M Division of Rules and Records 83/07/08 WILLIAMS, O G
 Affiliation Unknown 1p 20708 002

NONDOCKETED ITEMS

411

- 8310110505 Forwards BWR Owners Group control room program plan, followup
820108 ltr, BWR Owners Group survey suppl & presentation
slides from BWR Owners Group/NRC Jul 1980, Aug 1981, Mar &
Jul 1982 meetings
BITTER, D B General Electric Co MFN-131-82 82/09/14
HEISS, S H Human Factors Engineering Branch 2pp 20708 003
- 8310110509 Requests NRC concurrence on whether control room design
review program being conducted by BWR Owners Group meets
intent of NRC evaluation criteria for detailed control room
design reviews
ARMSTRONG, W BWR Owners Group BWR00-8151 81/08/25 MOORE, V A
Human Factors Engineering Branch 4pp 20708 003
- 8310110511 "BWR Owners Group Control Room Improvements Committee Human
Factors Engineering Control Room Survey"
PANKRATZ, D R, ROSS, K C, MULLEE, O R BWR Owners Group 81/01/19
88pp 20708 009
- 8310110513 "BWR Owners Group Control Room Design Review Program,
Development & Methodology"
* General Electric Co 81/08/01 26pp 20708 096
- 8310110518 "BWR Owners Group Control Room Survey Workshop, Human Factors
Engineering," w/suppl & viewgraphs
* BWR Owners Group 83/08/01 310pp 20708 121
- 8310110520 FOIA request for all records re three specified ltrs, 830209
meeting & discussions between AK Wilson & Region III during
past yr concerning Dow Chemical Co incineration of radwaste
WILSON, A K Environmental Congress of Mid-Michigan 83/05/26
MALLET, B S Region 3, Office of Director 1p 20705 194
- 8310110523 Responds to FOIA request for all records re three specified
ltrs, 830209 meeting & discussions between AK Wilson & Region
III during past yr concerning Dow Chemical Co incineration
of radwaste Forwards documents listed in app
FELTON, J M Division of Rules and Records 83/06/15 WILSON, A K
Environmental Congress of Mid-Michigan 2pp 20705 195
- 8310110534 Forwards two AK Wilson 820727 ltrs re recent amend to
License 21-00265-06 authorizing Dow Chemical Co to
incinerate radwaste Licensee may be in violation of license
Commission should be responsive to ltrs in timely manner
MALLET, B S Region 3, Office of Director 82/08/19 MILLER, J R
Region 3, Office of Director 1p 20705 200
- 8310110538 Advises that Dow Chemical Co may be in violation of License
21-00265-06 by incinerating both toxic & radwaste
simultaneously If practice acceptable to NRC, EIS should be
prepared
WILSON, A K Affiliation Unknown 82/07/27 MALLET, B S Region
3, Office of Director 1p 20705 201
- 8310110541 Requests issuance of EIS re Dow Chemical Co License
21-00265-06 authorizing incineration of radwaste Issues to
be included in EIS discussed List of technical questions to
be considered encl
WILSON, A K Affiliation Unknown 82/07/27 MALLET, B S Region
3, Office of Director 17pp 20705 202
- 8310110547 Requests written justification for issuance of broad scope
License 21-00265-06 to Dow Chemical Co & License Condition
18 re incineration of radwaste
WILSON, A K Affiliation Unknown 82/07/13 MALLET, B S Region
3, Office of Director 1p 20705 219
- 8310110562 Forwards draft response to AK Wilson 820913 & 27 ltrs re Dow
Chemical Co License 21-00265-06 to incinerate byproduct matl
waste Signature requested Handwritten notes of discussions
w/ various parties re Dow Chemical Co encl
MALLET, B S Region 3, Office of Director 82/12/17 MILLER, J R
Region 3, Office of Director 8pp 20705 222
- 8310110576 Submits handwritten comments re draft response to A Wilson
ltrs concerning Dow Chemical Co Undated handwritten note re
conversation w/ P Berg, Govt Accountability Project, encl
HIND, J NRC - No Detailed Affiliation Given 83/05/04
MILLER, J, MALLET, B NRC - No Detailed Affiliation Given 4pp
20705 231
- 8310110583 Responds to 820603, 0727 & 0913 & 830216 ltrs re issuance of
License 21-00265-06 to Dow Chemical Co to incinerate
byproduct waste Response to 830105 ltr will be transmitted
separately w/o stated encls
MEPLER, J Q Region 3, Office of Director 83/06/10 WILSON, A K
Environmental Congress of Mid-Michigan 6pp 20705 338
- 8310110557 Responds to FOIA request for submittals awarded NRC
Contracts RS-NRR-83-107, RS-DRM-83-500 & EDO-83-426 Only RFP
RS-NRR-83-107 resulted in award of Contract NRC-03-83-107
Nonproprietary version of proposal in PDR
FELTON, J M Division of Rules and Records 83/06/13 NEWMAN, K A
Debevoise & Liberman 1p 20709 357
- 8310110560 FOIA request for submittals awarded NRC Contracts
RS-NRR-83-107, RS-DRM-83-500 & EDO-83-426
NEWMAN, K A Debevoise & Liberman 83/05/31 FELTON, J M Division
of Rules and Records 1p 20709 358
- 8310110564 Responds to FOIA request for SECY-82-388, "Withdrawal of
Medical Misadministration Reporting Requirements"
Attachments 1, 6 & 7 exempt Attachments 2, 3, 4 & 5 available
in PDR
FELTON, J M Division of Rules and Records 83/07/15 PRASAD, Q P
Evanston Hosp Evanston, IL 2pp 20709 359
- 8310110567 FOIA request for copy of 54 page rept to NRC Commissioners,
"Withdrawal of Medical Misadministration Reporting
Requirements"
PRASAD, S Q Evanston Hosp Evanston, IL 83/04/25 Region 3,
Office of Director 1p 20709 361
- 8310110571 Final response to FOIA request for documents made available
under FOIA Request 83-153 Final response to FOIA 83-153 &
821222 memo to Commission encl W/o encl
FELTON, J M Division of Rules and Records 83/06/13 KAPPEL, B
Hamel, Park, McCabe & Saunders 1p 20686 361
- 8310110581 FOIA request for three categories of documents re technical
support for util group on ATWS, reactor coolant pump seal
failures & survey & critique of RPB reliability studies.
SHOLLY, S C Union of Concerned Scientists 83/07/28 FELTON, J M
Division of Rules and Records 1p 20714 213
- 8310110586 Responds to FOIA request for three categories of documents
re 811231, 8A1-011-82-SJ, "Technical Support for Util Group
on ATWS," 810327 memo from TE Hurley to DG Eisenhower & 821011
8A1-12200363700 rept Item i in LPDR & Items b & c in PDR
FELTON, J M Division of Rules and Records 83/08/19 SHOLLY, B
Union of Concerned Scientists 1p 20714 214
- 8310110591 "Survey & Critique of Reactor Protection Sys. Reliability
Studies," draft rept
GALYEAN, W J, NELSON, W E, LINDSAY, W E Sandia Laboratories
82/10/11 55pp 20714 223
- 8310120005 FOIA request for documents re costs & const of &
improvements to Western New York Nuclear Svc Ctr, West
Valley, NY
ARNOLD, Q A Shaw, Pittman, Potts & Trowbridge 83/06/27 Office
of Administration 2pp 20751:069, 24X Fiche 50-201, 83/06/27,
8310120005
- 8310120006 Responds to FOIA request for documents re costs & const of
& improvements to Western New York Nuclear Svc Ctr, West
Valley, NY Forwards documents listed in App A Documents also
available in PDR
FELTON, J M Division of Rules and Records 83/07/14 ARNOLD, Q A
Shaw, Pittman, Potts & Trowbridge 3pp 20751 071, 24X
Fiche 50-201, 83/07/14, 8310120006
- 8310120008 Forwards schedule showing source & application of funds for
Mar-June 1966 to demonstrate that vendor has necessary
funds to continue const of facility, per 660322 ltr
RUNION, T C Nuclear Fuel Services, Inc. (subs of Getty Oil Co)
66/03/28 MCBRIDE, J A Atomic Energy Commission 2pp
20751 074 24X Fiche 50-201, 83/07/14, 8310120006
- 8310120009 Forwards schedule showing vendor consolidated balance sheet
as of 660228 & consolidated balance sheet projected for
660331 Add line of credit of \$1,000,000 received from Mfg &
Traders Trust Co Ltr encl
RUNION, T C Nuclear Fuel Services, Inc. (subs of Getty Oil Co)
66/03/22 MCBRIDE, J A Atomic Energy Commission 3pp
20751 076 24X Fiche 50-201, 83/07/14, 8310120006
- 8310120011 Forwards "Info Subsequent to CP Submission 5," from vendor,
requesting extension of const completion date to 660630
Request includes financial data to cover period through
660630
BECHHOEFER, B Q Scharf, Bechhoefer & Baron 66/02/25
MCBRIDE, J A Atomic Energy Commission 1p 20751 081, 24X
Fiche 50-201, 83/07/14, 8310120006
- 8310120012 Application to amend License CBF-1, extending const
completion date to 660630, Certificate of Svc & consolidated
balance sheet encl
RUNION, T C Nuclear Fuel Services, Inc. (subs of Getty Oil Co)
66/02/24 9pp 20751 082 24X Fiche 50-201, 83/07/14, 8310120006

NONDOCKETED ITEMS

- B310120013 Forwards "Info Subsequent to CP Submission 3," containing suppl info requested by NRC Info in Part 1 covers statement of general financial responsibility info contained in second part should be withheld (ref 10CFR2 790)
RUNION, T C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
65/08/25 MCBRIDE, J A Atomic Energy Commission 1p 20751 091
24X Fiche 50-201,83/07/14, B310120006
- B310120014 Application to amend License CSF-1, supplementing or replacing & superseding Paragraph 7 re applicant financial responsibility
RUNION, T C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
65/08/25 App 20751 092 24X Fiche 50-201,83/07/14, B310120006
- B310120015 Forwards "Info Subsequent to CP Submission 2," dtd 650719, Certificate of Svc & marked-up "Info Subsequent to CP Submission 1"
BECHHOEFER, B G Scharfeld, Bechhoefer & Baron 65/07/19
MCBRIDE, J A Atomic Energy Commission 1p 20751 096 24X
Fiche 50-201,83/07/14, B310120006
- B310120020 Discusses current appraisal of NFS reprocessing project Summary of most current cost review encl Addl data will be included in semiannual rept to be filed in Oct 1964, in connection w/ licensing procedure
RUNION, T C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
64/08/17 SCABOROUGH, Q T, Atomic Energy Commission 3pp
20751 137 24X Fiche 50-201,83/07/14, B310120006
- B310120023 Notifies that on 640402, substantially all fixed assets & portion of quick assets of fuel fabrication facility at Port Hope were sold & transferred by NFS to Canadian Westinghouse Co, Ltd
BECHHOEFER, B G Scharfeld, Bechhoefer & Baron 64/03/13
JOHNSON, L E Atomic Energy Commission 1p 20751 140 24X
Fiche 50-201,83/07/14, B310120006
- B310120026 Order amending provisional CP CPCSF-2 to require NFS to file rept covering 6-month period ending Mar 31 & Sept 30 of each yr w/ Director of Div of Licensing
RIGGS, E, WOLMAN, A, CALLIHAN, D Atomic Safety and Licensing Board
Panel 63/11/29 Nuclear Fuel Services, Inc (subs of Getty Oil Co) 4pp 20751 141 24X Fiche 50-201,83/07/14, B310120006
- B310120028 Response to applicant motion for amend to provisional CP CPCSF-2 info provided by applicant in proposed "NFS Exhibit E" & in statement of Commission 630516 memorandum & order
CONNER, T B Nuclear Fuel Services, Inc (subs of Getty Oil Co)
CONNER, T B New York, State of CONNER, T B Atomic Energy Commission 63/11/14 7pp 20751 145 24X Fiche 50-201,83/07/14, B310120006
- B310120030 Statement in support of NFS 631023 motion requesting Commission take actions on loan arrangements & submittal of financial repts Draft NFS motion, Certificate of Svc & term loan agreement encl
RUEBHAUSEN, D M New York, State of * Affiliation Unknown.
63/10/29 23pp 20751 152 24X Fiche 50-201,83/07/14, B310120006
- B310120032 Memorandum & order amending CPCSF-2 by incorporating condition to require applicants to furnish evidence of financial qualifications adequate to constitute proper basis for required finding
MCCOOL, W B Atomic Energy Commission 83/09/13 Nuclear Fuel Services, Inc (subs of Getty Oil Co) 4pp 20751 175 24X
Fiche 50-201,83/07/14, B310120006
- B310120034 Forwards Amend 1 to NFS 630130 CP application submitted by NY State Atomic & Space Development Authority Certificate of Svc encl
RUEBHAUSEN, D M Debevoise & Plimpton 63/04/09 MCCOOL, W B Atomic Energy Commission 1p 20751 179 24X
Fiche 50-201,83/07/14, B310120006
- B310120036 Memorandum of Agreement between NY State Ofc of Atomic Development & NY State Atomic R&D Authority to coordinate respective responsibilities for development of atomic energy Certificate of Svc encl
AKELRAD, M Atomic Energy Commission. TOWNSEND, D, FERQUSON, W New York, State of 63/03/21 13pp 20751 184 24X
Fiche 50-201,83/07/14, B310120006
- B310120039 Responds to 630213 ltr re NFS application for licenses. Memorandum of Agreement between NY State Ofc of Atomic Development & NY State Atomic R&D Authority from Governor of State of NY encl.
TOWNSEND, D. New York, State of. 63/04/08 LOWENSTEIN, R Atomic Energy Commission 2pp 20751 197 24X Fiche 50-201,83/07/14, B310120006
- B310120042 Forwards Amend 4 to Part A of NFS CP application re financial qualifications & related info
STUMBLER, A Scharfeld, Bechhoefer & Baron 63/03/29 CONNER, T B Atomic Energy Commission 1p 20751 199 24X
Fiche 50-201,83/07/14, B310120006
- B310120044 Amend 4 to CP application to construct spent fuel reprocessing plant Amend responds to Commission 630314 ltr, requesting addl financial data re pending application Addl financial info encl
RUNION, T C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
63/03/29 20pp 20751 200 24X Fiche 50-201,83/07/14, B310120006
- B310120047 Forwards Amend 1 to Part A of NFS application for license to construct & operate spent fuel processing plant Certificate of Svc & financial info encl
BECHHOEFER, B G Scharfeld, Bechhoefer & Baron 63/02/13
Atomic Energy Commission 1p 20751 220 24X
Fiche 50-201,83/07/14, B310120006
- B310120049 Amend 1 to Part A of application for license to construct & operate spent fuel processing plant Certificate of Svc & financial info encl
RUNION, T C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
63/02/12 32pp 20751 221 24X Fiche 50-201,83/07/14, B310120006
- B310120207 Application to amend License CSF-1, revising Paragraph 5 - # original application re applicant financial qualifications
RUNION, T C Nuclear Fuel Services, Inc (subs of Getty Oil Co)
* Scharfeld, Bechhoefer & Baron 65/07/15 26pp 20751 097
24X Fiche 50-201,83/07/14, B310120006
- B310120016 Addl response to FOIA request for document re problems w/ Tech Specs applying to RCB leakage determinations in PHWfs
Forwards App A documents
FELTON, J M Division of Rules and Records 63/07/01 VOIGT, H H LeBonour, Lamb, Leiby & MacRae 2pp 20751 001 24X
Fiche 50-000,83/07/07, B310120016
- B003240118 Requests specs for surveillance & limiting conditions to ensure valve integrity if Event 5 valve configuration exists NRC B00223 ltr requesting LWR licensees to indicate if Event 5 valve configuration exists at facility encl
POLK, P J Operating Reactors Branch 3 (Pre B00428) 80/02/29
WETHORE, J Operating Reactors Branch 2 (Pre B00428) 2pp
20751 027
- B003240123 Ltr all LWR licensees requesting that periodic valve tests or continuous surveillance be performed to determine if Event 5 valve configuration exists at facility Requests listed info re valve configuration
EISENHUT, D G Division of Operating Reactors 80/02/23
Division of Operating Reactors 3pp 20751 034
- B007290663 Forwards SER suppl, Revision 1, re periodic leak testing of pressure isolation valves Replaces B00702 transmittal
KNIGHT, J P Assistant Director for Comp & Structures Engineering (Pre B30201) 80/07/16 TEDESCO, R L Assistant Director for Licensing 1p 20751 043 24X Fiche 50-000,83/07/07, B310120016
- B007290676 SER suppl, Revision 1, re periodic leak testing of pressure isolation valves Additions to Tech Specs acceptable
* Assistant Director for Comp & Structures Engineering (Pre B30201) 80/07/16 3pp 20751 044 24X Fiche 50-000,83/07/07, B310120016
- B310120018 Notifies of decision to expand existing contract w/ Franklin Inst to include technical assistance on Generic Activity B-45, "LWR Primary Coolant Sys Pressure Isolation Valves" Mgt concurrence requested
POLK, P J, Operating Reactors Branch 3 (Pre B00428) 80/03/06
BUTCHER, E NRC - No Detailed Affiliation Given 23pp 20751 036
- B310120022 Safety evaluation requiring test of primary coolant sys pressure isolation valves be incorporated into plant Tech Specs
* NRC - No Detailed Affiliation Given 81/04/20 1p 20751 037
24X Fiche 50-000,83/07/07, B310120016
- B310130390 FOIA request for all records on re-review of structural adequacy of diesel generator bldg subsequent to May testimony of R Landsman in ASLB proceedings
GARDE, B P, Government Accountability Project 83/08/08, Office of Administration, 2pp 20769 352 24X Fiche 50-329,83/08/08, B310130390
- B310130394 Responds to FOIA request for all records on re-review of structural adequacy of diesel generator bldg subsequent to May testimony of R Landsman in ASLB proceedings Forwards App A documents Documents also in PDR
FELTON, J M Division of Rules and Records 83/08/25 GARDE, B P Government Accountability Project 2pp 20769 354 24X
Fiche 50-329,83/08/25, B310130394

NONDOCKETED ITEMS

413

- 8308150338 Advises of assignment as member of task group to reevaluate structural design & const adequacy of plant diesel generator bldg
KUD,P T Structural & Geotechnical Engineering Branch 83/08/08
TAN,C P Structural & Geotechnical Engineering Branch 1p
20769 362 24X Fiche 50-498,83/08/23,8310130394
- 8308290029 Requests meeting on 830822 to discuss Landsman concerns that diesel generator bldg inadequate to return to svc based on inability to meet design requirements
VOLLMER,R NRC - No Detailed Affiliation Given 83/08/15
KNIGHT,J NRC - No Detailed Affiliation Given 1p 20769 361
24X Fiche 50-498,83/08/23,8310130394
- 8310130402 FOIA request for list of reporting requirements imposed on public,w/copy of applicable form & ofc,telephone number & room number where filing of reporting requirements made
DAY,M S Washington Knowledge Network 83/08/11 FELTON,J M
Division of Rules and Records 1p 20771 001
- 8310130409 Responds to FOIA request for list of reporting requirements imposed on public,w/copy of applicable form & ofc,telephone number & room number where filings of reporting requirements made
FELTON,J M Division of Rules and Records 83/08/29 DAY,M S
Washington Knowledge Network 1p 20771 002
- 8310130410 "NRC List of Active Repts Approved Under Federal Repts Act as of 830729"
* NRC - No Detailed Affiliation Given 83/07/29 9pp
20771 003
- 8310130412 Responds to FOIA request for any repts of insps or investigations of facilities of Nuclear Medicine Assoc,Inc
No insps or investigations of facility made since 800101 No documents available subj to request
FELTON,J M Division of Rules and Records 83/08/25 KELLY,D L
Peper,Martin,Jensen,Maichel & Hetlage 1p 20769 350
- 8310130413 FOIA request for repts of insps or investigations of facilities of Nuclear Medicine Assoc,Inc since 800101
KELLY,D L Peper,Martin,Jensen,Maichel & Hetlage 83/08/05
Office of Administration 1p 20769 351
- 8310140030 FOIA request for IE Insp Rept 79-19,associated notice of proposed imposition of civil penalties,notice of violation & order to show cause
HAMLIN,J B Shaw, Pittman, Potts & Trowbridge 83/05/31 Office
of Administration 6pp 20794 110 24X Fiche 50-498,83/05/31, 8310140030
- 8310140031 Partial response to FOIA request for documents re IE Insp Rept 79-19 & associated notice of proposed imposition of civil penalties,notice of violation & order to show cause
Forwards App A documents Documents also available in PDR
FELTON,J M Division of Rules and Records 83/08/23 HAMLIN,J B
Shaw, Pittman, Potts & Trowbridge 1p 20794 116 24X
Fiche 50-498,83/08/23,8310140031
- 8008270592 Forwards Region 5 rept of investigation re alleged falsification of QA records by Brown & Root inspector
W/a encl
WARD,W J Office of Inspection & Enforcement, Office of the Director 80/08/01 FORTUNA,R Office of Inspector & Auditor
1p 20795 186 24X Fiche 50-498,83/08/23,8310140031
- 8310140032 "South Texas Project - History"
* NRC - No Detailed Affiliation Given 83/05/31 4pp
20794 117 24X Fiche 50-498,83/08/23,8310140031
- 8310140037 Notification of 800819 meeting w/util & Brown & Root in Bay City,TX to clarify util response to 800430 show cause order
* NRC - No Detailed Affiliation Given 83/10/13 NRC - No Detailed Affiliation Given 4pp 20794 129 24X
Fiche 50-498,83/08/23,8310140031
- 8310140041 Requests formal public hearing,w/full disclosure,re NRC 791110 investigation of South Texas Project
* Affiliation Unknown 80/02/07 NRC - No Detailed Affiliation Given 1p 20794 133 24X Fiche 50-498,83/08/23,8310140031
- 8310140044 NRC proposal to fine Texas Utils for alleged noncompliance w/NRC requirements re Brown & Root QA program & violation of piping weld tests
* NRC - No Detailed Affiliation Given 83/10/13 2pp
20794 134 24X Fiche 50-498,83/08/23,8310140031
- 8310140047 Enforcement history,South Texas Project,Oct 1976 - Mar 1980
* NRC - No Detailed Affiliation Given 83/10/13 3pp
20794 136 24X Fiche 50-498,83/08/23,8310140031
- 8310140050 Discusses notice of violation issued as result of 791110-820207 insps Noncompliance noted QC insp by Brown & Root not sufficiently independent Marked-up copy
* NRC - No Detailed Affiliation Given 83/05/31 NRC - No Detailed Affiliation Given 35pp 20794 139 24X
Fiche 50-498,83/08/23,8310140031
- 8310140052 Forwards draft investigation rept & proposed enforcement action for comment Commission briefing on investigation & enforcement planned for wk of 800414 Draft rept also sent to pertinent NRC personnel
SHEWMAKER,R E Director's Office, Office of Inspection and Enforcement 80/04/01 THORNBURG,H D Director's Office, Office of Inspection and Enforcement 140pp 20794 175 24X
Fiche 50-498,83/08/23,8310140031
- 8310140062 Requisition for payment to Continental Airlines for PBX svc of pig to Houston,TX
* NRC - No Detailed Affiliation Given 80/05/01 2pp
20795 071 24X Fiche 50-498,83/08/23,8310140031
- 8310140088 Advises that,due to seriousness of violations by Brown & Root & util at South Texas Project,Full-scale public hearing in Matagorda County,TX mandatory
VAN HOY,G Affiliation Unknown 80/05/20 STELLO,V Director's Office, Office of Inspection and Enforcement 1p 20795 079 24X
Fiche 50-498,83/08/23,8310140031
- 8310140095 Submits draft generic ltr for use w/incoming correspondence as result of 800430 IE enforcement pkg
STELLO,V Director's Office, Office of Inspection and Enforcement 83/10/13 Affiliation Unknown 3pp 20795 167 24X
Fiche 50-498,83/08/23,8310140031
- 8310170020 FOIA request for documents re NRC &/or NRC consultant participation in Committee on Safety of Nuclear Installation sponsored "Group of Experts on Nuclear Aerosols" & "Group of Experts on Source Terms"
SHOLLY,S C Union of Concerned Scientists 83/05/02 FELTON,J M
Division of Rules and Records 1p 20814 158
- 8310170029 Responds to FOIA request for matl re NRC participation in Committee on Safety of Nuclear Installation sponsored "Group of Experts on Nuclear Aerosols" Forwards App A documents App B documents withheld (ref FOIA Exemption 4)
FELTON,J M Division of Rules and Records 83/06/29 SHOLLY,S C
Union of Concerned Scientists 3pp 20814 159
- 8310170033 Informs that M Silberberg requested to be in Bologna,Italy by 780918 to attend Committee on Safety of Nuclear Installation 780919 meeting Meeting held to complete preliminary rept editing
KELBERG,C N Assistant Director for Advanced Reactor Safety Research 78/08/29 LANASTRA,R Office of Administration 1p 20814 164
- 8310170037 Forwards draft state-of-the-art rept on nuclear aerosols Final revs will be completed at 780920-22 meetings in Bologna,Italy
SILBERBERG,M Experimental Fast Reactor Safety Research Branch 78/08/30 PRODI,V Italy, Govt of 1p 20814 165
- 8310170044 Forwards draft state-of-the-art rept on nuclear aerosols Final revs will be completed at 780920-22 meetings in Bologna,Italy
SILBERBERG,M Experimental Fast Reactor Safety Research Branch 78/08/30 SHOCK,W Germany, Federal Republic of 1p 20814 1
- 8310170047 Forwards draft state-of-the-art rept on nuclear aerosols Final revs will be completed at 780920-22 meetings in Bologna,Italy
SILBERBERG,M Experimental Fast Reactor Safety Research Branch 78/08/30 HILLIARD,R K Hanford Engineering Development 20814 167
- 8310170050 Forwards draft state-of-the-art rept on nuclear aerosols Final revs will be completed at 780920-22 meetings in Bologna,Italy
SILBERBERG,M Experimental Fast Reactor Safety Research Branch 78/08/30 QIESEKE,J A Battelle Memorial Institute, Columbus Laboratories 1p 20814 168
- 8310170055 Forwards draft state-of-the-art rept on nuclear aerosols Final revs will be completed at 780920-22 meetings in Bologna,Italy
SILBERBERG,M Experimental Fast Reactor Safety Research Branch 78/08/30 LANZA,S Italy, Govt of 1p 20814 169
- 8310170057 Forwards draft state-of-the-art rept on nuclear aerosols Final revs will be completed at 780920-22 meetings in Bologna,Italy
SILBERBERG,M Experimental Fast Reactor Safety Research Branch 78/08/30 KITANI,S Japan, Govt of 1p 20814 170

NONDOCKETED ITEMS

- 8310170059 Forwards draft state-of-the-art rept on nuclear aerosols
Final revs will be completed at 780920-22 meetings in
Bologna, Italy
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
78/08/30 HARRISON, S A United Kingdom 1p 20814 171
- 8310170062 Forwards draft state-of-the-art rept on nuclear aerosols
Final revs will be completed at 780920-22 meetings in
Bologna, Italy
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
78/08/30 DOOSSENS, I W Belgium, Govt of, 1p 20814 172
- 8310170066 Forwards draft state-of-the-art rept on nuclear aerosols
Final revs will be completed at 780920-22 meetings in
Bologna, Italy
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
78/08/30 FERMANDJIAN, M France, Govt of, 1p 20814 173
- 8310170072 Forwards draft state-of-the-art rept on nuclear aerosols
Final revs will be completed at 780920-22 meetings in
Bologna, Italy
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
78/08/30 AKAGANE, K Japan, Govt of 1p 20814 174
- 8310170090 Forwards draft state-of-the-art rept on nuclear aerosols
Final revs will be completed at 780920-22 meetings in
Bologna, Italy
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
78/08/30 ABBEY, F United Kingdom Atomic Energy Authority 1p
20814 175
- 8310170094 Forwards draft state-of-the-art rept on nuclear aerosols
Final revs will be completed at 780920-22 meetings in
Bologna, Italy
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
78/08/30 VAN DE VATE, J Netherlands 1p 20814 176.
- 8310170102 Forwards draft state-of-the-art rept on nuclear aerosols
Final revs will be completed at 780920-22 meetings in
Bologna, Italy
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
78/08/30 MANESSE, D France, Govt of, 1p 20814 177
- 8310170110 Comments on aerosol experts group rept Subj: of nuclear
aerosols has significant impact on evaluation of
consequences of postulated reactor accidents
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
78/10/27 ABBEY, F United Kingdom 7pp 20814 178
- 8310170116 Discusses 790214 telcon w/K Stadie re status of NRC
participation at Committee on Safety of Nuclear Installation
specialist meeting in Bournemouth, England Budget restraints
may prevent NRC representation
SILBERBERG, M NRC - No Detailed Affiliation Given 79/02/16
MURLEY, T E Assistant Director for Advanced Reactor Safety
Research 1p 20814 183
- 8310170120 Forwards review ltr & revs to draft state-of-the-art matl
mailed to group of experts. Arrangements for group dinner on
790404 requested
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/03/09 OLIVIER, J P France, Govt of, 1p 20814 186
- 8310170123 Forwards revs to draft state-of-the-art rept on nuclear
aerosols in reactor safety items to be considered listed
Review of revs in preparation for 790403 meeting in Paris
requested
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/03/09 LANZE, S Italy, Govt of, 1p 20814 187
- 8310170128 Forwards revs to draft state-of-the-art rept on nuclear
aerosols in reactor safety items to be considered listed
Review of revs in preparation for 790403 meeting in Paris
requested
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/03/09 SCHOCK, W Germany, Federal Republic of 1p
20814 188
- 8310170130 Forwards revs to draft state-of-the-art rept on nuclear
aerosols in reactor safety items to be considered listed
Review of revs in preparation for 790403 meeting in Paris
requested
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/03/09 SCHIKARSKI, W Q Germany, Federal Republic of 1p
20814 189
- 8310170136 Forwards revs to draft state-of-the-art rept on nuclear
aerosols in reactor safety items to be considered listed
Review of revs in preparation for 790403 meeting in Paris
requested
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/03/09 KITANI, S Japan, Govt of 1p 20814 190
- 8310170140 Forwards revs to draft state-of-the-art rept on nuclear
aerosols in reactor safety items to be considered listed
Review of revs in preparation for 790403 meeting in Paris
requested
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/03/09 HARRISON, S A United Kingdom 1p 20814 191
- 8310170144 Forwards revs to draft state-of-the-art rept on nuclear
aerosols in reactor safety items to be considered listed
Review of revs in preparation for 790403 meeting in Paris
requested
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/03/09 HILLIARD, R K Hanford Engineering Development 1p
20814 192
- 8310170150 Forwards revs to draft state-of-the-art rept on nuclear
aerosols in reactor safety items to be considered listed
Review of revs in preparation for 790403 meeting in Paris
requested
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/03/09 GJESKE, J A Battelle Memorial Institute, Columbus
Laboratories 1p 20814 193
- 8310170161 Forwards revs to draft state-of-the-art rept on nuclear
aerosols in reactor safety items to be considered listed
Review of revs in preparation for 790403 meeting in Paris
requested
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/03/09 DOOSSENS, I W Belgium, Govt of, 1p 20814 194
- 8310170164 Forwards revs to draft state-of-the-art rept on nuclear
aerosols in reactor safety items to be considered listed
Review of revs in preparation for 790403 meeting in Paris
requested
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/03/09 PRODI, V Italy, Govt of, 1p 20814 195
- 8310170166 Forwards revs to draft state-of-the-art rept on nuclear
aerosols in reactor safety items to be considered listed
Review of revs in preparation for 790403 meeting in Paris
requested
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/03/09 MANESSE, M France, Govt of, 1p 20814 196
- 8310170169 Forwards revs to draft state-of-the-art rept on nuclear
aerosols in reactor safety items to be considered listed
Review of revs in preparation for 790403 meeting in Paris
requested
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/03/09 VAN DE VATE, J Netherlands 1p 20814 197
- 8310170171 Forwards revs to draft state-of-the-art rept on nuclear
aerosols in reactor safety items to be considered listed
Review of revs in preparation for 790403 meeting in Paris
requested
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/03/09 ABBEY, F United Kingdom 1p 20814 198
- 8310170176 Forwards revs to draft state-of-the-art rept on nuclear
aerosols in reactor safety items to be considered listed
Review of revs in preparation for 790403 meeting in Paris
requested
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/03/09 AKAGANE, K Japan, Govt of 1p 20814 199
- 8310170180 Forwards revs to draft state-of-the-art rept on nuclear
aerosols in reactor safety items to be considered listed
Review of revs in preparation for 790403 meeting in Paris
requested
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/03/09 FERMANDJIAN, J France, Govt of, 1p 20814 200
- 8310170182 "Nuclear Aerosols in Reactor Safety"
* Organization for Economic Cooperation & Development (Paris)
79/06/30 4pp 20814 201
- 8310170237 Forwards final draft of revised summary statements from
790403 meeting on "Critical Review of Aerosol Instruments,"
for comment Comments requested by 830817 if attendance at
meeting in Seattle not possible
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/07/27 HARRISON, S A United Kingdom 7pp 20814 203
- 8310170242 Forwards final draft of revised summary statements from
790403 meeting on "Critical Review of Aerosol Instruments,"
for comment Comments requested by 790817 if attendance at
meeting in Seattle not possible W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/07/27 SCHOCK, W Germany, Federal Republic of 1p
20814 212

NONDOCKETED ITEMS

- B310170247 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments," for comment Comments requested by 790817 if attendance at meeting in Seattle not possible W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/07/27 PRODI, V Italy, Govt of, ip 20814 213
- B310170252 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments," for comment Comments requested by 790817 if attendance at meeting in Seattle not possible W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/07/27 KITANI, A Japan, Govt of ip 20814 214
- B310170259 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments," for comment Comments requested by 790817 if attendance at meeting in Seattle not possible W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/07/27 VAN DE VATE, J Netherlands ip 20814 215
- B310170265 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments," for comment Comments requested by 790817 if attendance at meeting in Seattle not possible W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/07/27 ABBEY, F United Kingdom ip 20814 216
- B310170269 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments," for comment Comments requested by 790817 if attendance at meeting in Seattle not possible W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/07/27 GIESEKE, J A Battelle Memorial Institute, Columbus Laboratories ip 20814 217
- B310170275 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments," for comment Comments requested by 790817 if attendance at meeting in Seattle not possible W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/07/27 FERNANDJIAN, J France, Govt of, ip 20814 218
- B310170280 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments," for comment Comments requested by 790817 if attendance at meeting in Seattle not possible W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/07/27 OLIVIER, J P France, Govt of, ip 20814 219
- B310170284 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments," for comment Comments requested by 790817 if attendance at meeting in Seattle not possible W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/07/27 SCHIKARSKI, B Germany, Federal Republic of ip 20814 220
- B310170288 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments," for comment Comments requested by 790817 if attendance at meeting in Seattle not possible W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/07/27 AKAGANE, K Japan, Govt of ip 20814 221
- B310170294 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments," for comment Comments requested by 790817 if attendance at meeting in Seattle not possible W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/07/27 HILLIARD, R K Hanford Engineering Development ip 20814 222
- B310170300 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments," for comment Comments requested by 790817 if attendance at meeting in Seattle not possible W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/07/27 LANZA, B Italy, Govt of, ip 20814 223
- B310170303 Forwards "Summary Rept on Critical Review of Aerosol Measurements Techniques " Rept will be highlighted at Committee on Safety of Nuclear Installation meeting W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/10/05 KITANI, A Japan, Govt of ip 20814 224
- B310170305 Forwards "Summary Rept on Critical Review of Aerosol Measurements Techniques " Rept will be highlighted at Committee on Safety of Nuclear Installation meeting W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/10/05 HARRISON, B A United Kingdom ip 20814 225
- B310170309 Forwards "Summary Rept on Critical Review of Aerosol Measurements Techniques " Rept will be highlighted at Committee on Safety of Nuclear Installation meeting W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/10/05 SCHIKARSKI, B Germany, Federal Republic of ip 20814 226
- B310170314 Forwards "Summary Rept on Critical Review of Aerosol Measurements Techniques " Rept will be highlighted at Committee on Safety of Nuclear Installation meeting W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/10/05 FERNANDJIAN, J France, Govt of, ip 20814 227
- B310170319 Forwards "Summary Rept on Critical Review of Aerosol Measurements Techniques " Rept will be highlighted at Committee on Safety of Nuclear Installation meeting W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/10/05 PRODI, V Italy, Govt of, ip 20814 228
- B310170323 Forwards "Summary Rept on Critical Review of Aerosol Measurements Techniques " Rept will be highlighted at Committee on Safety of Nuclear Installation meeting W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch,
79/10/05 GIESEKE, J A Battelle Memorial Institute, Columbus Laboratories ip 20814 229
- B310170326 Forwards "Summary Rept on Critical Review of Aerosol Measurements Techniques " Rept will be highlighted at Committee on Safety of Nuclear Installation meeting W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/10/05 SCHOCK, W Germany, Federal Republic of ip 20814 230
- B310170328 Forwards "Summary Rept on Critical Review of Aerosol Measurements Techniques " Rept will be highlighted at Committee on Safety of Nuclear Installation meeting W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/10/05 ABBEY, F United Kingdom, ip 20814 231
- B310170332 Forwards "Summary Rept on Critical Review of Aerosol Measurements Techniques " Rept will be highlighted at Committee on Safety of Nuclear Installation meeting W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/10/05 HILLIARD, R K Hanford Engineering Development ip 20814 232
- B310170336 Forwards "Summary Rept on Critical Review of Aerosol Measurements Techniques " Rept will be highlighted at Committee on Safety of Nuclear Installation meeting W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/10/05 VAN DE VATE, J, Netherlands ip 20814 233
- B310170340 Forwards "Summary Rept on Critical Review of Aerosol Measurements Techniques " Appreciation expressed for continuing effort & support for Group of Experts on Nuclear Safety Aerosols W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/10/05 OLIVIER, J P France, Govt of, ip 20814 234
- B310170343 Forwards "Summary Rept on Critical Review of Aerosol Measurements Techniques " Rept will be transmitted to Committee on Safety of Nuclear Installation for annual meeting in Nov W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/10/05 MOCHIZUKI, K Japan, Govt of, ip 20814 235
- B310170347 Forwards "Summary Rept on Critical Review of Aerosol Measurements Techniques " Rept will be transmitted to Committee on Safety of Nuclear Installation for annual meeting in Nov W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch,
79/10/05 MAY, F Q Australia, Govt of ip 20814 236
- B310170352 Forwards "Summary Rept on Critical Review of Aerosol Measurements Techniques " Rept will be transmitted to Committee on Safety of Nuclear Installation for annual meeting in Nov W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/10/05 TORGERSON, D C Canada, Govt of, ip 20814 237

NONDOCKETED ITEMS

- B310170358 Notifies of Committee on Safety of Nuclear Installations
800415-17 specialist meeting on nuclear aerosols in reactor
safety in Gatlinburg, TN Recipient participation requested
Background info, purpose & agenda encl W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/11/09 LDNG, J K Office of Nuclear Reactor Regulation,
Director 2pp 20B14 238
- B310170362 Notifies of Committee on Safety of Nuclear Installations
800415-17 specialist meeting on nuclear aerosols in reactor
safety in Gatlinburg, TN Recipient participation requested
Background info, purpose & agenda encl W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/11/09 SHERRY, R R NRC - No Detailed Affiliation Given 2pp
20B14 240
- B310170370 Notifies of Committee on Safety of Nuclear Installations
800415-17 specialist meeting on nuclear aerosols in reactor
safety in Gatlinburg, TN Recipient participation requested
Background info, purpose & agenda encl W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/11/09 LARKIN, J T NRC - No Detailed Affiliation Given 2pp
20B14 242
- B310170374 Notifies of Committee on Safety of Nuclear Installations
800415-17 specialist meeting on nuclear aerosols in reactor
safety in Gatlinburg, TN Recipient participation requested
Background info, purpose & agenda encl W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/11/08 KRESS, S T Oak Ridge National Laboratory 2pp,
20B14 244
- B310170379 Notifies of Committee on Safety of Nuclear Installations
800415-17 specialist meeting on nuclear aerosols in reactor
safety in Gatlinburg, TN Recipient participation requested
Background info, purpose & agenda encl W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/11/08 POWERS, D Sandia Laboratories 2pp 20B14 246
- B310170386 Notifies of Committee on Safety of Nuclear Installations
800415-17 specialist meeting on nuclear aerosols in reactor
safety in Gatlinburg, TN Recipient participation requested
Background info, purpose & agenda encl W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/11/08 MALINAUSKAS, A Oak Ridge National Laboratory 2pp
20B14 248
- B310170391 Notifies of Committee on Safety of Nuclear Installations
800415-17 specialist meeting on nuclear aerosols in reactor
safety in Gatlinburg, TN Recipient participation requested
Background info, purpose & agenda encl W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/11/08 WRIGHT, A Oak Ridge National Laboratory 2pp
20B14 250
- B310170392 Notifies of Committee on Safety of Nuclear Installations
800415-17 specialist meeting on nuclear aerosols in reactor
safety in Gatlinburg, TN Recipient participation requested
Background info, purpose & agenda encl W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/11/08 GIESEKE, J A Battelle Memorial Institute, Columbus
Laboratories 2pp 20B14 252
- B310170396 Notifies of Committee on Safety of Nuclear Installations
800415-17 specialist meeting on nuclear aerosols in reactor
safety in Gatlinburg, TN Recipient participation requested
Background info, purpose & agenda encl W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/11/08 LEE, K Battelle Memorial Institute, Columbus
Laboratories 2pp 20B14 254
- B310170402 Notifies of Committee on Safety of Nuclear Installations
800415-17 specialist meeting on nuclear aerosols in reactor
safety in Gatlinburg, TN Recipient participation requested.
Background info, purpose & agenda encl W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/11/08 ADAMS, R Oak Ridge National Laboratory 2pp
20B14 256
- B310170406 Notifies of Committee on Safety of Nuclear Installations
800415-17 specialist meeting on nuclear aerosols in reactor
safety in Gatlinburg, TN Recipient participation requested.
Background info, purpose & agenda encl W/o encl.
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/11/08 ELRICK, R Sandia Laboratories 2pp 20B14 258
- B310170410 Notifies of Committee on Safety of Nuclear Installations
800415-17 specialist meeting on nuclear aerosols in reactor
safety in Gatlinburg, TN Recipient participation requested
Background info, purpose & agenda encl W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/11/08 JORDAN, M Battelle Memorial Institute, Columbus
Laboratories 2pp 20B14 260
- B310170413 Notifies of Committee on Safety of Nuclear Installations
800415-17 specialist meeting on nuclear aerosols in reactor
safety in Gatlinburg, TN Recipient participation requested
Background info, purpose & agenda encl W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/11/08 PARKER, C W Oak Ridge National Laboratory 2pp
20B14 262
- B310170415 Notifies of Committee on Safety of Nuclear Installations
800415-17 specialist meeting on nuclear aerosols in reactor
safety in Gatlinburg, TN Recipient participation requested
Background info, purpose & agenda encl W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/11/07 CASTLEMAN, A W Colorado, Univ of 2pp 20B14 264
- B310170418 Notifies of Committee on Safety of Nuclear Installations
800415-17 specialist meeting on nuclear aerosols in reactor
safety in Gatlinburg, TN Recipient participation requested
Background info, purpose & agenda encl W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/11/07 COOPER, D Harvard Univ, Cambridge, MA 2pp
20B14 266
- B310170422 Notifies of Committee on Safety of Nuclear Installations
800415-17 specialist meeting on nuclear aerosols in reactor
safety in Gatlinburg, TN Recipient participation requested
Background info, purpose & agenda encl W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/11/07 LOYALKA, S K Missouri, Univ of, Columbia, MO 2pp
20B14 268
- B310170429 Notifies of Committee on Safety of Nuclear Installations
800415-17 specialist meeting on nuclear aerosols in reactor
safety in Gatlinburg, TN Recipient participation requested
Background info, purpose & agenda encl W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/11/07 LIU, B Y Minnesota, Univ of 2pp 20B14 270
- B310170431 Notifies of Committee on Safety of Nuclear Installations
800415-17 specialist meeting on nuclear aerosols in reactor
safety in Gatlinburg, TN Recipient participation requested
Background info, purpose & agenda encl W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/11/07 BROCK, J R Texas, Univ of, Austin, TX 2pp
20B14 272
- B310170434 Notifies of Committee on Safety of Nuclear Installations
800415-17 specialist meeting on nuclear aerosols in reactor
safety in Gatlinburg, TN Recipient participation requested
Background info, purpose & agenda encl W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/11/07 KANAPILLY, G M Inhalation Toxicology Research
Institute 2pp 20B14 274
- B310170438 Notifies of Committee on Safety of Nuclear Installations
800415-17 specialist meeting on nuclear aerosols in reactor
safety in Gatlinburg, TN Recipient participation requested
Background info, purpose & agenda encl W/o encl
SILBERBERG, M Experimental Fast Reactor Safety Research Branch
79/11/07 SEHREL, G A Battelle Memorial Institute, Pacific
Northwest Laboratory 2pp 20B14 276
- B310170444 Lists reasons for deferral of meeting w/Group of Experts :-
Nuclear Aerosols to update 1979 state-of-the-art rept until
late 1982
SILBERBERG, M Fuel Behavior Branch 82/02/22 ROYEN, J France,
Govt of, 2pp 20B14 278
- B310170445 Informs of plans to attend 820422-23 meeting of Committee
Safety of Nuclear Installations Group of Experts on Nuclear
Aerosols in Reactor Safety
SILBERBERG, M Fuel Behavior Branch 82/04/07 ROYEN, J France,
Govt of, 1p 20B14 280
- B310170450 Requests addl listed info re input to draft suppl to
Committee on Safety of Nuclear Installations rept Related
info encl
SILBERBERG, M Fuel Behavior Branch 82/05/13 GIESEKE, J
Battelle Memorial Institute, Columbus Laboratories 3pp
20B14 281
- B310170452 Notifies that J Gieseke & T Kress will attend 820909-10
meetings of Committee on Safety of Nuclear Installation on
Nuclear Aerosols on Reactor Safety experts Related info
encl
SILBERBERG, M NRC - No Detailed Affiliation Given 82/09/31
ROYEN, J France, Govt of, 3pp 20B14 283

NONDOCKETED ITEMS

41

- 8310170457 Discusses Group of Experts under Committee for Safety of Nuclear Installation Working Group 4 meetings & travel funding Travel funding continuing problem Meeting w/W Dircks might be necessary to permit travel by NRC
LAFLEUR, J D Office of International Programs, Director 83/02/03
HOUSTON, R W Office of Nuclear Reactor Regulation, Director 1p 20814 288
- 8310170461 Responds to B21214 request for NRC representation on Committee on Safety of Nuclear Installation principle Working Group 4 Recommendations listed
SILBERBERG, M Accident Source Term Program Office 83/02/28
LAFLEUR, J D Office of International Programs, Director 1p 20814 289
- 8310170463 Advises of NRC representation at Group of Experts on Source Term meeting Resolution of accident source term issue is major NRC objective
HOUSTON, R W Assistant Director for Reactor Safety 83/03/18
LAFLEUR, J D Office of International Programs, Director 1p 20814 290
- 8310170049 Responds to FOIA request for records re 1974-75 research grants to Boarden Chemical Div & Reichold Chemical for research on urea formaldehyde foam insulation No records available subj to request
FELTON, J M Division of Rules and Records 83/09/01 MOSHER, D Citizens Engaged in Removal of Toxic Substances, Inc 2pp 20798 057
- 8310170052 FOIA request for records re 1974-75 research grants to Boarden Chemical Div & Reichold Chemical for research on urea formaldehyde foam insulation
MOSHER, D Citizens Engaged in Removal of Toxic Substances, Inc 83/08/19 NRC - No Detailed Affiliation Given 1p 20798 059
- 831017007B Responds to JP Berg FOIA request for copies of active licenses issued by NRC to Pharmatopes, Inc or Suncor Corp
Forwards App A documents
FELTON, J M Division of Rules and Records 83/06/07 Rosenfeld & Falk, Inc 3pp 20797 001
- 7908060318 Matl/Byproduct License 34-19007-01MD for Pharmatopes, Inc authorizing use of Mo-99, Cs-137, Co-60, Ba-133, I-125 & Xe-133 in production of Tc-99m pertechnetate, instrument calibr & compound mixing
VACCA, P C Licensing Management Branch 79/06/27 6pp 20797 095
- 7908270319 Matl/Byproduct License 34-18484-01MD for Pharmatopes, Inc authorizing use of Mo-99, Cs-137, Co-60, Ba-133, I-125, Xe-133 & byproduct matls in Groups 1-5 in various forms for instrument calibr preparation of radiopharms
VACCA, P C Licensing Management Branch 79/07/24 6pp 20797 108
- 7909140003 Matl/Byproduct License 34-19008-01MD for Pharmatopes, Inc authorizing use of Mo-99, Cs-137, Co-60, Ba-133, I-125, Xe-133 & byproduct matls Groups 1-5 in various forms for distribution & calibr of instruments
WALKER, W J Licensing Management Branch 79/08/09 6pp 20797 069
- 7911300172 Matl/Byproduct License 37-18467-01MD for Pharmaco Nuclear, Inc authorizing use of Mo-99 in Mo-99/Tc-99m generator, Ba-133, Cs-137 & Groups I, II, IV, V byproduct matls for production of Tc-99m & IR-113a chloride
VACCA, P C Licensing Management Branch 79/10/25 6pp 20797 133
- 8001040244 Matl/Byproduct License 21-19219-01MD for Pharmatopes, Inc authorizing use of Mo-99, Cs-137, Co-60, Ba-133, I-125, Xe-133 & any byproduct matl in Groups I, II, IV & V for dispensing & distribution of radiopharms
VACCA, P C Licensing Management Branch 79/11/27 6pp 20797 194
- 8004230428 Matl/Byproduct License 37-18467-01MD for Pharmaco Nuclear, Inc is amended per 800113 application Amend 2 adds any byproduct matl listed in 10CFR31.11(a), in any prepackaged in vitro diagnostic test kits
VACCA, P C Licensing Management Branch 80/03/18 1p 20797 141
- 8006170100 Matl/Byproduct License 12-19333-01MD for Pharmatopes, Inc authorizing use of Mo-99, Cs-137, Co-60, Ba-133, Xe-133 & Groups I-V byproduct matl for instrument calibr & distribution of prepared radiopharms
VACCA, P C Licensing Management Branch, 80/05/06 6pp 20797 217
- 8006200467 Matl/Byproduct License 08-18308-01MD for Pharmatopes, Inc is amended per 800319 1tr Amend 1 authorizes use of U depleted in U-235 as metal encased in stainless steel for shielding matl
VACCA, P C Licensing Management Branch 80/05/25 1p 20797 180
- 8007170062 Matl/Byproduct License 21-19219-01MD for Pharmatopes, Inc is amended per 800319 1tr Amend 1 authorizes U depleted in U-235, as shielding of Mo-99/Tc-99m generators
VACCA, P C Licensing Management Branch 80/06/25 1p 20797 201
- 8007170067 Matl/Byproduct License 34-19007-01MD for Pharmatopes, Inc is amended per 800319 1tr Amend 1 adds U depleted in U-235, as shielding of Mo-99/Tc-99m generators & adds conditions of use
VACCA, P C Licensing Management Branch 80/06/26 1p 20797 101
- 8007170227 Matl/Byproduct License 34-16405-01MD for Pharmaco Nuclear, Inc is amended per 800609 1tr Amend 13 adds U depleted in U-235, as shielding of Mo-99/Tc-99m generators
LAMASTRA, M A Licensing Management Branch 80/06/27 1p 20797 215
- 8009160105 Matl/Byproduct License 24-19360-01MD for Pharmaco Nuclear, Inc, authorizing use of Mo-99 in any Mo-99/Tc-99m generator for production of Tc-99m pertechnetate
* Licensing Management Branch 80/08/22 8pp 20797, 159
- 8009240099 Matl/Byproduct License 37-18467-01MD for Pharmaco Nuclear, Inc is amended per 800609-10 1trs Amend 3 authorizes use of U depleted in U-235 as shielding in Mo-99/Tc-99m generators
* Licensing Management Branch 80/08/21 1p 20797 142
- 8010070328 Matl/Byproduct License 08-18308-01MD for Pharmatopes, Inc is amended per 800910 1tr Amend 2 authorizes MT Hebner, MC Fu, R Irwin, M Vetica & A McKusick as users of licensed matls
VACCA, P C Licensing Management Branch 80/09/12 1p 20797 179
- 8012010377 Matl/Byproduct License 34-19007-01MD for Pharmatopes, Inc is amended per 800903 1tr Amend 2 authorizes MT Hebner, MC Fu, J Fields, BJ Clark & RJ Schnieders as users of licensed matls
DELMEDICO, J Licensing Management Branch 80/11/12 1p 20797 102
- 8012310197 Matl/Byproduct License 12-19333-01MD for Pharmatopes, Inc is amended per 800720 1tr Amend 2 changes reading of Condition 12 re names of users of licensed matl
DELMEDICO, J Licensing Management Branch 80/11/14 1p 20797 223
- 8012310245 Matl/Byproduct License 21-19219-01MD for Pharmatopes, Inc is amended per 800731 1tr Amend 2 changes reading of Condition 12 re names of users of licensed matl
DELMEDICO, J Licensing Management Branch 80/12/03 1p 20797 202
- 8012310507 Matl/Byproduct License 13-19451-01MD for Pharmatopes, Inc authorizes use of Cs-137, Co-60 & Ba-133 sealed sources for instrument calibr
DELMEDICO, J Licensing Management Branch 80/11/14 7pp 20797 234
- 801070406 Matl/Byproduct License 24-19360-01MD for Pharmaco Nuclear, Inc is amended per 801021 1tr Amend 2 changes reading of Conditions 12 & 23 re possession & use of licensed matls
DELMEDICO, J Licensing Management Branch, 80/12/08 1p 20797, 168
- 801090060 Matl/Byproduct License 08-18308-01MD for Pharmatopes, Inc is amended per 801029 & 1117 1trs Amend 3 changes reading of Items 8 A, B, H, K & F, 7 F & B F & Conditions 12 & 20 re use of licensed matl.
DELMEDICO, J Licensing Management Branch 80/12/05 2pp 20797 181.
- 801090109 Matl/Byproduct License 37-18467-01MD for Pharmaco Nuclear, Inc is amended per 801028 1tr Amend 4 changes reading of Items 8 A & 9 A & Condition 23 re distribution, possession & use.
DELMEDICO, J Licensing Management Branch 80/12/03 1p 20797 143
- 80103040697 Matl/Byproduct License 35-19383-01MD for Pharmatopes, Inc authorizes use of Mo-99, Cs-137, Co-60, Ba-133, I-125 & Xe-133 for medical purposes & instrument calibr
DELMEDICO, J, Licensing Management Branch 81/02/03 6pp 20797 063

NONDOCKETED ITEMS

- B103180096 Matl/Byproduct License 13-19451-01MD for Pharmatopes, Inc, is amended per B10120 ltr Amend 1 authorizes MT Hebner, MM Fu, CE Palmer, CR Blaum, DM Donahue or BC Blaum as users of licensed matl
DELMEDICO, J Licensing Management Branch 01/02/20 1p
20797 241
- B104170659 Matl/Byproduct License 12-19333-01MD for Pharmatopes, Inc is amended per B00924 & B10216 ltrs Amend 4 changes reading of Condition 12 re use of licensed matl
DELMEDICO, J Licensing Management Branch 01/03/18 1p
20797 225
- B104170666 Matl/Byproduct License 34-19007-01MD for Pharmatopes, Inc is amended per Amend 3 changing reading of Condition 12 re use of licensed matl
DELMEDICO, J Licensing Management Branch 01/03/18 1p
20797 103
- B104210028 Matl/Byproduct License 12-19333-01MD for Pharmatopes, Inc, is amended per B10120 ltr Amend 3 authorizes users of licensed matl & requires physical presence of one user at place of use
DELMEDICO, J M Licensing Management Branch 01/02/24 1p
20797 224
- B310170132 Amend 15 to Matl/Byproduct License 34-16654-01MD, authorizing use of Mo-99, Xe-133, I-131, Tc-99m for redistribution of generators to authorized recipients, per B21217 application
DELMEDICO, J Licensing Management Branch 03/04/20 7pp
20797 008
- B310170142 Amend 14 to Matl/Byproduct License 34-16654-01MD, revising Condition 12 re users & supervisors of licensed matl, per B21208 ltr.
VACCA, P Licensing Management Branch 02/12/30 1p 20797 015
- B310170147 Amend 13 to Matl/Byproduct License 34-16654-01MD, revising Conditions 12 & 23, re users of licensed matl, per 750711 application & listed ltrs
DELMEDICO, J Licensing Management Branch 02/09/21 1p
20797 016
- B310170154 Amend 12 to Matl/Byproduct License 34-16654-01MD, revising Condition 12 re users of licensed matl, per B11220 ltr
DELMEDICO, J Licensing Management Branch 02/02/03 1p
20797 017
- B310170156 Amend 11 to Matl/Byproduct License 34-16654-01MD, revising Condition 12, re users of licensed matl, per B10612 ltr
DELMEDICO, J Licensing Management Branch 01/07/16 1p
20797 018
- B310170160 Amend 10 to Matl/Byproduct License 34-16654-01MD, revising Conditions 12 & 22, authorizing use of licensed matl by MT Hebner, MM Fu & R Irwin & requiring annual survey meter calibr, per B00908 ltr
DELMEDICO, J Licensing Management Branch 00/12/08 1p.
20797 019
- B310170184 Amend 9 to Matl/Byproduct License 34-16654-01MD, authorizing use of Mo-99, Br-113, Cs-137, Co-60, Am-241, I-125 or I-131 & Xe-133 sealed sources for production of Tc-99m pertechnetate & other listed uses, per B00519 ltr
LAHABTRA, M A Licensing Management Branch. 00/07/03 7pp
20797 020
- B310170191 Amend 14 to Matl/Byproduct License 21-17189-01MD, authorizing use of Mo-99, Xe-133, I-131, Tc-99m sealed sources for production of Tc-99m pertechnetate & other listed uses, per B21217 application
DELMEDICO, J Licensing Management Branch 03/03/07 7pp
20797 027
- B310170194 Amend 16 to Matl/Byproduct License 21-17189-01MD, revising Condition 24 re possession, use, packaging, labeling & distribution of licensed matl in Items 6-B, per B30323 ltr
DELMEDICO, J Licensing Management Branch 03/04/22 1p
20797 034
- B310170196 Amend 15 to Matl/Byproduct License 21-17189-01MD, revising Condition 12 re users of licensed matl, per B30214 ltr
DELMEDICO, J Licensing Management Branch 03/03/12 1p
20797 035
- B310170202 Amend 10 to Matl/Byproduct License 45-17769-01MD, authorizing use of Mo-99, Xe-133, I-131 & Tc-99m sealed sources for production of Tc-99m pertechnetate & redistribution to general & specific licensees, per B21223 application
DELMEDICO, J Licensing Management Branch. 03/03/07. 7pp
20797 036
- B310170205 Amend 11 to Matl/Byproduct License 45-17769-01MD, revising Condition 24 re possession, use, packaging, labeling & distribution of licensed matl described in Items 6-B, per B30324 ltr
DELMEDICO, J Licensing Management Branch 03/04/15 1p
20797 043
- B310170208 Amend 12 to Matl/Byproduct License 45-17769-01MD, revising Condition 24 re possession, use, packaging, labeling & distribution of licensed matl in Items 6-B, per B30427 ltr
DELMEDICO, J Licensing Management Branch 03/06/07 1p
20797 044
- B310170210 Amend 4 to Matl/Byproduct License 34-18309-01MD, authorizing use of Mo-99, Co-60, Ba-133, Cs-137, Xe-133, I-131 & Tc-99m sealed sources for production of Tc-99m pertechnetate per B10910 ltr
DELMEDICO, J Licensing Management Branch 02/02/09 7pp
20797 045
- B310170213 Amend 5 to Matl/Byproduct License 34-18309-01MD, revising Condition 12 re users of licensed matl, per B20309 ltr
DELMEDICO, J Licensing Management Branch 02/03/26 1p
20797 052
- B310170217 Amend 6 to Matl/Byproduct License 34-18309-01MD, revising Conditions 10 & 23 re place of use & possession, use of packaging, labeling & distribution of licensed matl in Items 6-B, per 781003 application
ST MARV, F A Licensing Management Branch 02/06/02 1p
20797 053
- B310170220 Amend 7 to Matl/Byproduct License 34-18309-01MD, revising Condition 12, re users of licensed matl, per B20802 ltr
DELMEDICO, J Licensing Management Branch 02/09/03 1p
20797 054
- B310170223 Amend 8 to Matl/Byproduct License 34-18309-01MD, revising Condition 12 re users of licensed matl, per B21217 ltr
DELMEDICO, J Licensing Management Branch 03/01/13 1p
20797 055
- B310170226 Amend 1 to Matl/Byproduct License 45-18378-01MD, authorizing use of Mo-99, Cs-137, Co-60, Ba-133, I-125 & Xe-133 sealed sources for production of Tc-99m pertechnetate, per 791002 ltr
VACCA, P C Licensing Management Branch 79/12/14 6pp
20797 056
- B310170231 Amend 2 to Matl/Byproduct License 45-18378-01MD, adding U as 35 encased in stainless steel as shielding for Mo-99/Tc-99m generators & amending Condition 23 re possession & use, per B00519 ltr
* Licensing Management Branch 00/08/07 1p 20797 062
- B310170241 Amend 1 to Matl/Byproduct License 34-19008-01MD, adding 91 as depleted U-235 as shielding for Mo-99/Tc-99m generators & amending Condition 24 re possession & use, per B00519 ltr.
VACCA, P C Licensing Management Branch 00/06/26 1p
20797 075
- B310170245 Amend 2 to Matl/Byproduct License 34-19008-01MD, revising Condition 12 re users of licensed matl & authorizing R Irwin as radiation safety officer, per B01022 application
DELMEDICO, J Licensing Management Branch. 00/10/30 1p
20797 076
- B310170250 Amend 3 to Matl/Byproduct License 34-19008-01MD, revising Condition 12, re users of licensed matl & designating WC Wilson as radiation safety officer, per B01022 application
DELMEDICO, J Licensing Management Branch 00/12/03 1p
20797 077
- B310170256 Amend 4 to Matl/Byproduct License 34-19008-01MD, revising Conditions 12 & 24, re users of licensed matl & possession & use of licensed matl in Items 6-B, per B10302 ltr
VACCA, P. Licensing Management Branch 01/03/31 1p 20797 078
- B310170267 Amend 4 to Matl/Byproduct License 34-19007-01MD, revising Condition 12, re users of licensed matl, per B10415 ltr
DELMEDICO, J Licensing Management Branch. 01/06/18 1p
20797 079
- B310170274 Amend 5 to Matl/Byproduct License 34-19007-01MD, revising Condition 12, re users of licensed matl, per B20309 ltr
DELMEDICO, J Licensing Management Branch. 02/03/26 1p
20797 080

NONDOCKETED ITEMS

419

--B310170277 Amend 6 to Matl/Byproduct License 34-19007-O1MD, revising Condition 12, re users of licensed matl, per 821217 ltr
DELMEDICO, J Licensing Management Branch 83/01/14 1p
20797 081

--B310170279 Matl/Byproduct License 37-21092-O1MD for Pharmatopes, Inc, authorizing use of Mo-99/Tc-99m generator, Xe-133, I-131 & Tc-99m for use in production & distribution of Tc-99m pertechnetate
DELMEDICO, J Licensing Management Branch 82/09/13 7pp
20797 082

--B310170282 Amend 4 to Matl/Byproduct License 35-19583-O1MD, adding use of any sealed source matl per 10CFR35.14 for instrument calibr & changing Conditions 12 & 24 re users, possession & distribution, per 821210 ltr
DELMEDICO, J Licensing Management Branch 83/01/11 2pp
20797 089

--B310170286 Amend 5 to Matl/Byproduct License 35-19583-O1MD, revising Condition 24 re possession, use, packaging, labeling & distribution of licensed matl & deleting Condition 25, per 830105 ltr
DELMEDICO, J Licensing Management Branch 83/01/27 1p
20797 091

--B310170290 Amend 1 to Matl/Byproduct License 35-19583-O1MD, revising Condition 12, re users of licensed matl & adding Condition 25 re onsite audits, per 810218 ltr
DELMEDICO, J Licensing Management Branch 81/04/01 1p
20797 092

--B310170293 Amend 2 to Matl/Byproduct License 35-19583-O1MD, revising Condition 25 re possession, use, packaging, labeling & distribution of licensed matl described in Items 6-B, per 810706 ltr
DELMEDICO, J Licensing Management Branch 81/08/12 1p
20797 093

--B310170297 Amend 3 to Matl/Byproduct License 35-19583-O1MD, revising Condition 12, re users of licensed matl, per 820610 ltr
DELMEDICO, J Licensing Management Branch 82/08/27 1p
20797 094

--B310170316 Amend 3 to Matl/Byproduct License 45-18378-O1MD, revising Condition 23 re possession, use, packaging, labeling & distribution of licensed matl described in Items 6-B & adding Conditions 24 & 25, per 800201 ltr
DELMEDICO, J Licensing Management Branch 81/03/05 1p
20797 104

--B310170320 Amend 4 to Matl/Byproduct License 45-18378-O1MD, revising Condition 12, re users of licensed matl
DELMEDICO, J Licensing Management Branch 81/08/31 1p
20797 105

--B310170324 Amend 5 to Matl/Byproduct License 45-18378-O1MD, revising Condition 12, re users of licensed matl, per 830118 ltr
DELMEDICO, J Licensing Management Branch 83/02/09 1p
20797 106

--B310170331 Amend 6 to Matl/Byproduct License 45-18378-O1MD, revising Condition 23 re possession, use, packaging, labeling & distribution of licensed matl & changing licensee name from Pharmatopes, Inc to Syncor Corp, per 830427 ltr
DELMEDICO, J Licensing Management Branch 83/06/07 1p
20797 107

--B310170345 Amend 1 to Matl/Byproduct License 34-18484-O1MD, revising Condition 12, re users of licensed matl & Condition 24 re possession & use of matl, per 791226 ltr
VACCA, P. C Licensing Management Branch 80/02/28 1p 20797 114

--B310170350 Amend 2 to Matl/Byproduct License 34-18484-O1MD, adding U-235 radium plated metal as shielding in linear accelerator & revising Condition 24 re possession & use, per 800519 ltr
VACCA, P. C Licensing Management Branch 80/06/25 1p
20797 115

--B310170354 Amend 3 to Matl/Byproduct License 34-18484-O1MD, revising Condition 12, re users of licensed matl, per 810907 ltr
DELMEDICO, J Licensing Management Branch 81/10/14 1p
20797 116

--B310170359 Amend 4 to Matl/Byproduct License 34-18484-O1MD, revising Condition 12, re users of licensed matl, per 830128 ltr
DELMEDICO, J Licensing Management Branch 83/02/22 1p
20797 117

--B310170363 Amend 1 to Matl/Byproduct License 37-21092-O1MD, revising Condition 12, re users of licensed matl, per 830303 ltr
DELMEDICO, J Licensing Management Branch 83/03/22 1p
20797 118

--B310170367 Amend 2 to Matl/Byproduct License 37-21092-O1MD, revising Condition 22 re possession, use, packaging, labeling & distribution of licensed matl & changing licensee name from Pharmatopes, Inc to Syncor Corp, per 830427 ltr
DELMEDICO, J Licensing Management Branch 83/06/07 1p
20797 119

--B310170372 Amend 14 to Matl/Byproduct License 34-16405-O1MD, revising Condition 12, re users of licensed matl, per 810316 ltr
DELMEDICO, J Licensing Management Branch 81/05/26 1p
20797 120

--B310170376 Amend 15 to Matl/Byproduct License 34-16405-O1MD, revising Condition 12, re users of licensed matl, per 811019 ltr
DELMEDICO, J Licensing Management Branch 81/11/13 1p
20797 121

--B310170381 Amend 16 to Matl/Byproduct License 34-16405-O1MD, adding 150 mCi of 10CFR35.14 sealed source byproduct matl for redistribution to authorized recipients & revising Condition 22 re possession & use, per 820312 ltr
DELMEDICO, J Licensing Management Branch 82/04/13 1p
20797 122

--B310170385 Amend 17 to Matl/Byproduct License 34-16405-O1MD, adding Condition 23 allowing licensee to use Calichek device for linearity test of dose calibrator, per 811210 ltr
DELMEDICO, J Licensing Management Branch 82/04/19 1p
20797 123

--B310170388 Amend 18 to Matl/Byproduct License 34-16405-O1MD, changing licensee name from Pharmaco Nuclear, Inc to Pharmatopes, Inc (Corrected copy)
DELMEDICO, J Licensing Management Branch 83/03/28 1p
20797 124

--B310170399 Amend 12 to Matl/Byproduct License 34-16405-O1MD, authorizing use of Mo-99, Sn-113, Cs-137, I-125, I-131 & Xe-133 for production of Tc-99m pertechnetate, In-113m chloride & instrument calibr, per 791227 ltr
VACCA, P. C Licensing Management Branch 80/01/24 7pp
20797 125

--B310170403 Amend 18 to Matl/Byproduct License 34-16405-O1MD, changing licensee name from Pharmaco Nuclear, Inc to Pharmatopes, Inc, per 821208 ltr
DELMEDICO, J Licensing Management Branch 83/01/31 1p
20797 132

--B310170425 Amend 1 to Matl/Byproduct License 37-18467-O1MD, adding Xe-133 gas solution for distribution to authorized recipients, per 791101 ltr
VACCA, P. C Licensing Management Branch 79/12/20 2pp
20797 139

--B310170433 Amend 5 to Matl/Byproduct License 37-18467-O1MD, revising Condition 23 re possession, use, packaging, labeling & distribution of licensed matl, per 810119 ltr
DELMEDICO, J Licensing Management Branch 81/07/15 1p
20797 144

--B310170437 Amend 6 to Matl/Byproduct License 37-18467-O1MD, revising Subitems B I & 9 A re production of Tc-99m pertechnetate & Condition 23 re possession, use, labeling & distribution of licensed matl, per 810928 ltr
DELMEDICO, J Licensing Management Branch 81/10/23 1p
20797 145

--B310170441 Amend 7 to Matl/Byproduct License 37-18467-O1MD, Condition 12, re users of licensed matl, per 811019 ltr
DELMEDICO, J Licensing Management Branch 81/11/03 1p
20797 146

--B310170447 Matl/Byproduct License 21-21141-O1MD for Pharmatopes, Inc authorizing use of Mo-99, Xe-133, I-131 & Tc-99m for production of Tc-99m pertechnetate & distribution of generators to authorized recipients, per 820720 applicati
DELMEDICO, J Licensing Management Branch 82/10/06 7p
20797 147

--B310170449 Amend 1 to Matl/Byproduct License 21-21141-O1MD, Condition 22 re possession, use, packaging, labeling & distribution of license matl, per 821217 ltr
DELMEDICO, J Licensing Management Branch 82/01/14 1p
20797 154

NONDOCKETED ITEMS

- B310170453 Amend B to Matl/Byproduct License 37-18467-01MD, adding 150 mCi byproduct, source & SNM sealed sources for redistribution to authorized recipients & revising Condition 23 re possession & use, per B30315 ltr
DELMEDICO, J Licensing Management Branch 82/04/13 1p
20797 155
- B310170455 Amend 9 to Matl/Byproduct License 37-18467-01MD, revising Condition 12, re users of licensed matl, per B20510 ltr
DELMEDICO, J Licensing Management Branch 82/06/18 1p
20797 156
- B310170460 Amend 10 to Matl/Byproduct License 37-18467-01MD, changing name of licensee from Pharmaco Nuclear, Inc to Pharmatopes, Inc, per B21110 ltr
DELMEDICO, J Licensing Management Branch 82/12/09 1p
20797 157
- B310170462 Amend 11 to Matl/Byproduct License 37-18467-01MD, revising Condition 23 re possession, use, packaging, labeling & distribution of licensed matl, per B21129 ltr
* Licensing Management Branch 82/01/14 1p 20797 158
- B310170467 Amend 1 to Matl/Byproduct License 24-19360-01MD, revising Conditions 12 & 23, re users of licensed matl & possession & use, per B01021 ltr
DELMEDICO, J Licensing Management Branch 80/12/08 1p
20797 167
- B310170472 Amend 3 to Matl/Byproduct License 24-19360-01MD, revising Item 9 re authorized use & Condition 12 re users of licensed matl, per B10115 & 0510 ltrs
DELMEDICO, J Licensing Management Branch 81/05/26 1p
20797 169
- B310170475 Amend 3 to Matl/Byproduct License 24-19360-01MD, revising Item 9 re authorized use & Conditions 12 & 23 re users & possession & use of licensed matl, per B10115 & 0410 ltrs
DELMEDICO, J Licensing Management Branch 81/09/01 2pp
20797 170
- B310170477 Amend 4 to Matl/Byproduct License 24-19360-01MD, revising Condition 12 re users of licensed matl, per B20510 ltr
DELMEDICO, J Licensing Management Branch 82/06/02 1p
20797 172
- B310170482 Amend 5 to Matl/Byproduct License 24-19360-01MD, revising Condition 23 re possession, use, packaging, labeling & distribution of licensed matl & changing licensee name from Pharmaco Nuclear, Inc to Bynor Corp, per B30427 ltr
DELMEDICO, J Licensing Management Branch 83/06/07 1p
20797 173
- B310170487 Matl/Byproduct License 08-18308-01MD for Pharmatopes, Inc, authorizing use of Mo-99, Cs-137, Co-60, Br-133, I-125, I-131 & Xe-133 for production of Tc-99m pertechnetate, per 781005 application & 781127 ltr
VACCA, P C Licensing Management Branch 78/12/12 5pp
20797 174
- B310170494 Amend 4 to Matl/Byproduct License 08-18308-01MD, revising Conditions 12 & 20 re users of licensed matl & possession & use, per B10626 ltr
DELMEDICO, J Licensing Management Branch 81/07/17 1p
20797 183
- B310170497 Amend 5 to Matl/Byproduct License 08-18308-01MD, revising Condition 12 re users of licensed matl, per B10630 ltr
DELMEDICO, J Licensing Management Branch 81/09/07 1p
20797 184
- B310170502 Amend 6 to Matl/Byproduct License 08-18308-01MD, revising Condition 12, re users of licensed matl, per B20118 ltr
DELMEDICO, J Licensing Management Branch 82/02/03 1p
20797 185
- B310170503 Amend 7 to Matl/Byproduct License 08-18308-01MD, revising Conditions 12 & 20 re users of licensed matl & possession & use, per B20203 ltr
DELMEDICO, J Licensing Management Branch 82/03/12 1p
20797 186
- B310170510 Amend 2 to Matl/Byproduct License 13-19229-01MD, authorizing use of Co-60, Ba-133, Cs-137, I-131 for production of Tc-99m pertechnetate, per 791128 application & B00519 ltr
DELMEDICO, J Licensing Management Branch 81/11/24 7pp
20797 187
- B310170516 Amend 4 to Matl/Byproduct License 21-19219-01MD, revising Condition 12 re users of licensed matl, per B20331 ltr
DELMEDICO, J Licensing Management Branch 82/06/02 1p
20797 200
- B310170521 Amend 3 to Matl/Byproduct License 21-19219-01MD, revising Condition 12, re users of licensed matl, per B20101 ltr
DELMEDICO, J Licensing Management Branch 82/02/05 1p
20797 203
- B310170527 Amend 1 to Matl/Byproduct License 06-19661-01MD, authorizing use of Mo-99, Co-60, Ba-133, Cs-137, I-131 & Tc-99m for production of Tc-99m pertechnetate, per B10612 ltr
DELMEDICO, J Licensing Management Branch 81/07/17 7pp
20797 204
- B310170528 Amend 2 to Matl/Byproduct License 06-19661-01MD, revising Condition 23 re possession, use, packaging, labeling & distribution of licensed matl, per B10715 ltr
DELMEDICO, J Licensing Management Branch 81/08/11 1p
20797 211
- B310170532 Amend 3 to Matl/Byproduct License 06-19661-01MD, revising Condition 12, re users of licensed matl, per B11215 ltr
DELMEDICO, J Licensing Management Branch 82/01/22 1p
20797 212
- B310170535 Amend 5 to Matl/Byproduct License 06-19661-01MD, revising Condition 12, re users of licensed matl, per B30128 ltr
DELMEDICO, J Licensing Management Branch 82/02/15 1p
20797 213
- B310170537 Amend 7 to Matl/Byproduct License 06-19661-01MD, revising Condition 23 re possession, use, packaging, labeling & distribution of licensed matl, per B20318 ltr
* Licensing Management Branch 82/04/07 1p 20797 214
- B310170546 Amend 1 to Matl/Byproduct License 12-19333-01MD, adding U depleted in U-235, as metal encased in stainless steel as shielding for Mo-99/Tc-99m generators, per B00518 & 24 ltrs
VACCA, P C Licensing Management Branch 80/07/24 5pp
20797 216
- B310170570 Amend 5 to Matl/Byproduct License 12-19333-01MD, revising Conditions 12 & 23 re users of licensed matl & possession & use, per B10414 ltr
DELMEDICO, J Licensing Management Branch 81/07/20 1p
20797 226
- B310170574 Amend 6 to Matl/Byproduct License 12-19333-01MD, revising Condition 12 re users of licensed matl, per B10909 ltr
DELMEDICO, J Licensing Management Branch 81/10/15 1p
20797 227
- B310170578 Amend 7 to Matl/Byproduct License 12-19333-01MD, revising Item B A to read 65 Ci, per undated ltr received B20222
DELMEDICO, J Licensing Management Branch 82/06/03 1p
20797 228
- B310170580 Amend 8 to Matl/Byproduct License 12-19333-01MD, revising Condition 12 re users of licensed matl, per B20502 ltr
DELMEDICO, J Licensing Management Branch 82/06/04 1p
20797 229
- B310170585 Amend 9 to Matl/Byproduct License 12-19333-01MD, revising Subitem B F to read 2.5 Ci & adding Condition 24 re fume hood airflow rating, per B11204 ltr
DELMEDICO, J Licensing Management Branch 82/06/24 1p
20797 230
- B310170587 Amend 10 to Matl/Byproduct License 12-19333-01MD, revising Condition 12 re users of licensed matl, per B20707 ltr
DELMEDICO, J Licensing Management Branch 82/08/13 1p
20797 231
- B310170590 Amend 11 to Matl/Byproduct License 12-19333-01MD, revising Condition 12 re users of licensed matl, per B20723 ltr
DELMEDICO, J Licensing Management Branch 82/08/26 1p
20797 232
- B310170593 Amend 12 to Matl/Byproduct License 12-19333-01MD, revising Condition 12 re users of licensed matl, per B20602 ltr
DELMEDICO, J Licensing Management Branch 82/10/01 1p
20797 233
- B310170615 Amend 2 to Matl/Byproduct License 13-19451-01MD, revising Condition 12 re users of licensed matl, per B10328 ltr
DELMEDICO, J Licensing Management Branch 81/04/20 1p
20797 242

NONDOCKETED ITEMS

421

--B310170618 Amend 3 to Matl/Byproduct License 13-19451-01MD, revising Condition 12 re users of licensed matl, per B10812 ltr
DELHEDICO, J Licensing Management Branch 81/09/24 1p
20797 243

--B310170625 Amend 4 to Matl/Byproduct License 13-19451-01MD, revising Condition 12 re users of licensed matl, per B10709 ltr
DELHEDICO, J Licensing Management Branch 81/10/14 1p
20797 244

--B310170628 Amend 5 to Matl/Byproduct License 13-19451-01MD, revising Condition 24 re possession & use of licensed matl, per B11218 ltr
DELHEDICO, J Licensing Management Branch 82/01/19 1p
20797 245

--B310170635 Amend 6 to Matl/Byproduct License 13-19451-01MD, revising Condition 12 re users of licensed matl, per B20518 telegram
VACCA, P C Licensing Management Branch 82/05/19 1p
20797 246

--B310170637 Amend 8 to Matl/Byproduct License 13-19451-01MD, revising Condition 12 re users of licensed matl, per B20727 ltr
DELHEDICO, J Licensing Management Branch 82/08/30 1p
20797 247

--B310170640 Amend 8 to Matl/Byproduct License 13-19451-01MD, revising Condition 12 re users of licensed matl, per B30406 ltr
DELHEDICO, J Licensing Management Branch 83/05/16 1p
20797 248

--B310170645 Amend 7 to Matl/Byproduct License 13-19451-01MD, revising Condition 12 re users of licensed matl, per B20730 telegram
DELHEDICO, J Licensing Management Branch 82/08/02 1p
20797 249

--B310170650 Matl/Byproduct License 29-19608-01MD for Pharmatopes, Inc authorizing use of Mo-99, Co-60, Ba-133, Cs-137, I-125, Xe-133, I-131 & Tc-99m for various uses, per B01202 application
DELHEDICO, J Licensing Management Branch 81/05/21 7pp
20797 250

--B310170652 Amend 2 to Matl/Byproduct License 29-19608-01MD, changing expiration date to B60531 & revising Conditions 10 & 24 re place of use & possession, use, packaging, labeling & distribution of licensed matl, per B10225 ltr
DELHEDICO, J Licensing Management Branch 81/03/28 1p
20797 257

--B310170660 Amend 2 to Matl/Byproduct License 29-19608-01MD, changing expiration date to B60531 & revising Conditions 10, 12 & 24 re place of use, users & possession & use of licensed matl, respectively, per B10225 ltr (Corrected copy)
DELHEDICO, J Licensing Management Branch 81/07/28 1p
20797 258

--B310170665 Amend 3 to Matl/Byproduct License 29-19608-01MD, changing license address & revising Conditions 10 & 24 re place of use & possession, use, packaging, labeling & distribution of licensed matl, per B10804 ltr
DELHEDICO, J Licensing Management Branch 81/09/02 1p
20797 259

--B310170668 Amend 4 to Matl/Byproduct License 29-19608-01MD, revising Condition 12 re users of licensed matl, per B10825 ltr
DELHEDICO, J Licensing Management Branch 81/10/20 1p
20797 260

--B310170673 Amend 5 to Matl/Byproduct License 29-19608-01MD, revising Condition 12 re users of licensed matl, per B20713 ltr
DELHEDICO, J Licensing Management Branch 82/08/16 1p
20797 261

--B310170676 Amend 6 to Matl/Byproduct License 29-19608-01MD, revising Conditions 12 & 24 re users of licensed matl & possession, use, packaging, labeling & distribution, per B21208 ltr
DELHEDICO, J Licensing Management Branch 83/03/23 1p
20797 262

--B310170677 Amend 7 to Matl/Byproduct License 29-19608-01MD, changing license name from Pharmatopes, Inc to Sincor Corp & revising Condition 24 re possession, use, packaging, labeling & distribution of licensed matl, per B30427 ltr
* Licensing Management Branch 83/06/07 1p, 20797, 263

--B310170681 Amend 16 to Matl/Byproduct License 24-16617-01MD, authorizing use of Mo-99, Xe-133, I-131, Tc-99m for production of Tc-99m pertechnetate & other uses, per B21221 application
DELHEDICO, J Licensing Management Branch 83/04/25 7pp
20797 264

--B310170684 Amend 17 to Matl/Byproduct License 24-16617-01MD revising Condition 23 re possession, use, packaging, labeling & distribution of licensed matl & changing licensee name to Sincor Corp, per B30427 ltr
DELHEDICO, J Licensing Management Branch 83/06/07 1p
20797 271

B310170101 FOIA request for copies of active licenses issued by NRC to Pharmatopes, Inc or Sincor Corp
BERQ, J P Sincor International 83/05/10 Office of Administration 4pp 20797 004

B310180531 FOIA request for Target Technology, Ltd documents re pipe supports
WEISS, E R Union of Concerned Scientists 83/08/11 FELTON, J M Division of Rules and Records 1p 20825 005 24X
Fiche 50-333, 83/08/11, B310180531

B310180534 Responds to FOIA request for Target Technology, Ltd documents re pipe supports Forwards document encl Document also available in PDR
FELTON, J M Division of Rules and Records 83/09/06 WEISS, E R Union of Concerned Scientists 1p 20825 006 24X
Fiche 50-333, 83/09/06, B310180534

--B310180538 Comments on pipe support design noncompliance w/FSAR
Summary of B30627 meeting w/S&W re list of 20 unacceptable supports submitted on B30103 discussed
DAINOFF, J Target Technology Ltd 83/06/30 GUAQUIL, L Power Authority of the State of New York 3pp 20825 007, 24X
Fiche 50-333, 83/09/06, B310180534

B310180556 Responds to FOIA request for names & addresses of past licensees permitted to mfg glazes, paints, dyes, enamels, glasses & ceramics w/o entls.
FELTON, J M Division of Rules and Records 83/09/08 THOMAS, A W Greater Reston Arts Center, Inc 1p 20825 344

B310180559 FOIA request for names & addresses of past licensees permitted to mfg glazes, paints, dyes, enamels, glasses & ceramics
THOMAS, A W Greater Reston Arts Center, Inc 83/08/20 NRC - No Detailed Affiliation Given 1p 20825 345

B310180566 FOIA request for name, title, phone number & address of all individuals directly in charge of maint activities on NRC computer equipment/sys using disk drives &/or dot matrix printers
SIMPSON, R O Granada Data Systems, Inc 83/08/16 Office of Administration 1p 20825 341

B310180571 Responds to FOIA request for name, title, phone number & address of all individuals directly in charge of maint activity on NRC computer equipment/sys using disk drives &/or dot matrix printers List Furnishing info encl
FELTON, J M Division of Rules and Records 83/09/06 SIMPSON, R O Granada Data Systems, Inc 1p 20825 342

--B310180575 List of all NRC individuals directly in charge of maint activity on NRC computer equipment/sys using disk drives &/or dot matrix printers
* NRC - No Detailed Affiliation Given 83/09/06 1p 20825 343

B310180582 FOIA request for VS Noonan B30426 memo to BJ Youngblood re addl info needed by Equipment Qualification Branch to complete review of environ qualification of mechanical equipment
PEDRO, J, NUS Corp CD-18-B3-263 83/08/17 Division of Rules and Records 1p 20817-329 24X Fiche 50-445, 83/08/17, B310180582

B310180586 FOIA request for util corporate chart in FSAR
CONSTAB, J Pro-Tech Support Services, Inc. 83/08/17 Office of Administration 1p 20825-323 24X Fiche 50-508, 83/08/17, B310180586

B310180588 Responds to FOIA request for VS Noonan B30426 memo re addl info needed by Equipment Qualification Branch to complete review of environ qualification of mechanical equipment Forwards document.
FELTON, J M Division of Rules and Records 83/09/06 PEDRO, J, NUS Corp 1p 20817-330 24X Fiche 50-445, 83/09/06, B310180588

--B305060124 Forwards request for addl info necessary to complete review of licensees B30330 info re environ qualification of safety-related mechanical equipment located in harsh environ
NOONAN, V B Equipment Qualification Branch. 83/04/26 YOUNGBLOOD, B J Licensing Branch 1 2pp 20817 331 24X
Fiche 50-445, 83/09/06, B310180588

NONDOCKETED ITEMS

8310180590 Responds to FOIA request for util corporate chart in PSAR
Forwards chart
FELTON, J M Division of Rules and Records 83/09/06 CONSTAS, J
Pro-Tech Support Services, Inc 1p 20825 324 24X
Fiche 50-508, 83/09/06, 8310180590

8310180595 FOIA request for all documents & records re radiation
surveys of Makepeace, Inc
SULLIVAN, J W Affiliation Unknown 83/08/30 NORRIS, P G Office of
Administration 1p 20825 336

--8310180602 FOIA request for all records re radiation contamination
surveys of DE Makepeace, Div of Engelhard Industries
SULLIVAN, J W Affiliation Unknown 83/08/30 CROCKER, H Region
I, Office of Director 2pp 20825 337

8310180597 FOIA request for list of mods to containment undertaken by
util in response to NUREG-0487
HAFNER, B Suffolk Nuclear Study Group 83/04/25 Office of
Administration 1p 20827 124 24X Fiche 50-322, 83/04/25,
8310180597

8310180600 Responds to FOIA request for info re mods to containment
undertaken by util info contained in Rev 5 to Plant Design
Assessment Rept Util not required to rept changes but must
comply w/acceptance criteria in Rev 5
FELTON, J M Division of Rules and Records 83/09/06 HAFNER, B
Suffolk Nuclear Study Group 1p 20827 123 24X
Fiche 50-322, 83/09/06, 8310180600

8310180603 Responds to FOIA request for all documents re Makepeace, Inc
or Englehard, Inc Info available in PDR
FELTON, J M Division of Rules and Records 83/09/06 SULLIVAN, J W
Affiliation Unknown 1p 20825 340

8310180609 FOIA request for complete set of BNL repts on seismic design
of facilities
CALBOYAS, C D Affiliation Unknown 83/08/16 Region 5, Office of
Director 4pp 20824 315 24X Fiche 50-275, 83/08/16, 8310180609

8310180610 Responds to FOIA request for complete set of BNL repts on
seismic design of facilities Documents listed in app
available in PDR
FELTON, J M Division of Rules and Records 83/09/01 CALBOYAS, C D
Affiliation Unknown 2pp 20824 317 24X Fiche 50-275, 83/09/01,
8310180610

--8310180613 Summary & evaluation rept of RL Cloud & Assoc rept, "Diablo
Canyon Unit 1 IDVP - Verification Program for P&E
Corrective Action."
* Brookhaven National Laboratory 83/09/01 4pp 20824 321
24X Fiche 50-275, 83/09/01, 8310180610

--8310180615 Summary & evaluation rept of RF Reedy rept, "Development of
Svc-Related Contractor List for Nonseismic Design Work
Performed for Diablo Canyon Nuclear Power Plant, Unit 1 Prior
to 780601, Phase II"
* Brookhaven National Laboratory 83/09/01 3pp 20824 325
24X Fiche: 50-275, 83/09/01, 8310180610

--8310180617 Summary & evaluation rept of RL Cloud & Assoc rept, "Diablo
Canyon Unit 1 IDVP - Verification of Design Analysis Hosgri
Spectra."
* Brookhaven National Laboratory 83/09/01 3pp 20824 328
24X Fiche 50-275, 83/09/01, 8310180610.

--8310180619 Summary & evaluation rept of RL Cloud & Assoc rept "Diablo
Canyon Unit 1 IDVP - Soils - Intake Structure"
* Brookhaven National Laboratory 83/09/01 3pp 20824 331
24X Fiche 50-275, 83/09/01, 8310180610

--8310180621 Summary & evaluation rept of RL Cloud & Assoc rept, "Diablo
Canyon Unit 1 IDVP - Soil - Outdoor Water Storage Tanks"
* Brookhaven National Laboratory 83/09/01 3pp 20824 334
24X Fiche 50-275, 83/09/01, 8310180610.

--8310180623 Summary & evaluation rept of RL Cloud & Assoc rept, "Diablo
Canyon Unit 1 IDVP - Small Bore Piping Rept"
* Brookhaven National Laboratory 83/09/01 6pp 20824 337
24X Fiche 50-275, 83/09/01, 8310180610.

--8310180624 Summary & evaluation rept of RL Cloud & Assoc rept, "Diablo
Canyon Unit 1 IDVP - HVAC Components."
* Brookhaven National Laboratory 83/09/01 5pp 20824 343
24X Fiche 50-275, 83/09/01, 8310180610.

--8310180626 Summary & evaluation rept of RL Cloud & Assoc rept, "IDVP
Valves."
* Brookhaven National Laboratory 83/09/01 4pp 20824 348
24X Fiche: 50-275, 83/09/01, 8310180610

--8310180627 Summary & evaluation rept of RL Cloud & Assoc rept, "IDVP -
HVAC Duct & Supports Rept"
* Brookhaven National Laboratory 83/09/01 5pp 20824 352
24X Fiche 50-275, 83/09/01, 8310180610

8310180618 FOIA request for documents submitted by util for
consideration of candidate companies or methodologies to
perform const implementation overview of const completion
plan
GARDE, B P Government Accountability Project 83/08/05 Office
of Administration 2pp 20839 110 24X Fiche 50-329, 83/08/05,
8310180618

8310180625 Responds to FOIA request for records submitted by util &
reviewed during consideration of candidate companies or
methodologies re const implementation overview Forwards
documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/09/01 GARDE, B P
Government Accountability Project 3pp 20839 112 24X
Fiche 50-329, 83/09/01, 8310180625

--8210280450 Forwards util 821005 three-part independent review program,
consisting of biennial quality audits, INPD-type const
evaluation & independent design verification of auxiliary
feedwater sys Meeting scheduled for 821019 to discuss plan
NOVAK, T M Assistant Director for Licensing 82/10/07
VOLLMER, R H Division of Engineering 1p 20839 124 24X
Fiche 50-329, 83/09/01, 8310180625

--8212300076 Documents conclusions reached at 821207 meeting in Bethesda,
MD re QA implementation at Facility Region 3 insp of diesel
generator bldg & util decision to stop certain safety-
related work being performed by Dochtel
HERNAN, R W Licensing Branch 4 82/12/21 NOVAK, T M Assistant
Director for Licensing 3pp 20839 125 24X
Fiche 50-329, 83/09/01, 8310180625

--8310180628 Forwards util 820312 response to Interrogatory IV re
Contention B on independent design audit
* NRC - No Detailed Affiliation Given 82/10/01 NRC - No
Detailed Affiliation Given 1p 20839 115 24X
Fiche 50-329, 83/09/01, 8310180625

--8310180629 Response to Interrogatory IV re Contention B on independent
design audit
* Consumers Power Co 82/05/12 Stamiris, B 8pp 20839 116
24X Fiche 50-329, 83/09/01, 8310180625

--8310180630 Forwards util revised plan for const completion Program
includes measures to be taken as result of work slowdown &
elements of QA implementation & third-party assessments
requested by NRC w/o encl
HERNAN, R Division of Licensing 83/01/12 ADENAM, E NRC - No
Detailed Affiliation Given 1p 20839 128 24X
Fiche 50-329, 83/09/01, 8310180625

--8310190034 Rev 1 to Quality Control Instruction 10 OI, "Const
Implementation Overview Assessment"
THOMPSON, J C Stone & Webster Engineering Corp 83/06/27 6pp
20839 134 24X Fiche 50-329, 83/09/01, 8310180625

--8310190036 Rev 0 to Verification Attribute Checklist P-2 20V, "Pipe
Supports"
BARANOW, S W Stone & Webster Engineering Corp 83/07/21 10pp
20839 140 24X Fiche 50-329, 83/09/01, 8310180625

--8310190038 Rev 1 to third-party const implementation overview approval
KELLY, R D Stone & Webster Engineering Corp 83/08/05 5pp
20839 150 24X Fiche 50-329, 83/09/01, 8310180625

--8310190042 Rev 1 to Quality Control Instruction 15 OI, "Nonconformance
Identification & Reporting"
BARANOW, S W Stone & Webster Engineering Corp 83/08/05 5pp
20839 155 24X Fiche 50-329, 83/09/01, 8310180625

--8310190047 Rev 1 For third-party const implementation overview re QA
plan
BARANOW, S W, WALTERS, C., KELLY, R D Stone & Webster Engineering
Corp 83/08/05 4pp 20839 160 24X Fiche 50-329, 83/09/01,
8310180625

8310190035 FOIA request for AEC Rept TID-2021, "Some Aspects of Stored
Energy in Irradiated Graphite, Part II, Storage of Energy in
Graphite on Irradiation"
AFTERGOOD, S Committee to Bridge the Gap 83/08/26 Office of
Administration 1p 20839 164

- 8310190041 Responds to FOIA request for AEC Rept TID-2021, "Some Aspects of Stored Energy in Irradiated Graphite, Part II: Storage of Energy on Irradiation" NRC does not possess document Rept may be obtained from Oak Ridge TN
FELTON, J M Division of Rules and Records 03/09/13 AFTERGOOD, S
Committee to Bridge the Gap 1p 20839 165
- 8310190046 FOIA request to place SECY-83-183, SECY-83-195, SECY-83-269 & SECY-83-342 in PDR
BUCKLES, R NUS Corp CD-18-83-253 03/08/15 Division of Rules and Records 1p 20838 272
- 8310190049 Responds to FOIA request Forwards documents Documents also available in PDR
FELTON, J M Division of Rules and Records 03/09/13 BUCKLES, R
NUS Corp 1p 20838 273
- 8307220156 SECY-83-269
Provides rept on fire protection rule for future plants (SECY-82-267), summarizing licensee fire protection exemption requests, disposition of requests & generic issues raised by requests
DIRCKS, W J Office of the Executive Director for Operations 03/07/05 82pp 20838 297
- 8310190053 SECY-83-183
Informs of first integrated schedule amend for implementing new & existing requirements at operating plants Action represents first step towards developing industry-wide approach for establishing realistic schedules
DIRCKS, W J Office of the Executive Director for Operations 03/05/13 23pp 20838 274
- 8310190059 FOIA request for info on effects of sabotage on PHRs & BHRs & fault tree analyses
SHOLLY, B C Union of Concerned Scientists 03/07/20 FELTON, J M
Division of Rules and Records 1p 20839 077
- 8310190062 Responds to FOIA request for info on effects of sabotage on PHRs & BHRs & fault tree analyses Forwards documents
NUREG/CR-3268 will be issued in 2 months Remaining requested items not found in PDR
FELTON, J M Division of Rules and Records 03/09/12 SHOLLY, B C
Union of Concerned Scientists 1p 20839 078
- 8310190088 FOIA request for RA Udell & R Alvarez 820422 ltr to Commissioner Palladino & H Denton 820603 response
PEDRO, J NUS Corp CD-18-83-279 03/08/22 Division of Rules and Records 1p 20838 178
- 8310190093 Responds to FOIA request for RA Udell & R Alvarez 820422 ltr to Chairman Palladino & H Denton 820603 response Forwards documents Documents also available in PDR
FELTON, J M Division of Rules and Records 03/09/07 PEDRO, J NUS Corp 1p 20838 199
- 8205140137 Forwards English language abstract of Inst fuer Energie und Umweltforschung study, "Secondary Side Emissions From Pressurized LWRs for Normal Operation & Selected Accidents" Comments on study submitted
DIRCKS, W J Office of the Executive Director for Operations 02/05/07 PALLADINO, N Commissioners 6pp 20838 203
- 8205140143 "Secondary Loop Releases of LWRs in Normal Operation & in Selected Breakdowns"
Koch, T Germany, Federal Republic of 02/05/07 50pp 20838 214
- 8206140401 Responds to 820422 ltr transmitting Inst fuer Energie und Umweltforschung rept re steam generator tube problems, Rept reviewed & comments listed in 820507 ltr to Chairman Palladino No new issues presented
BENTON, H R Office of Nuclear Reactor Regulation, Director, 02/06/03 UDELL, R A Critical Mass Energy Project, 3pp 20838 200
- 8206140403 Forwards Inst fuer Energie und Umweltforschung rept "Secondary Loop Releases of LWRs in Normal Operation & in Selected Breakdowns" Evidence presented re accident scenarios involving steam generator tubes
UDELL, R A Critical Mass Energy Project, 02/04/22 PALLADINO, N J Commissioners, 5pp 20838 209
- 8310190300 Appeals denial of FOIA request for documents re caseload forecast panel 830419 meeting on plant const Denial effectively denied bulk of documents requested
GARDE, B P Government Accountability Project 03/08/10
DIRCKS, W J Office of the Executive Director for Operations 2pp 20840 326 24X Fiche 50-329, 83/08/10, 8310190300
- 8310190305 Responds to appeal re denial of FOIA request for documents on caseload forecast panel 830419 meeting on plant const All documents identified sub; to request Appeal re T Novak draft ltr to JW Cook meet
DIRCKS, W J Office of the Executive Director for Operations 03/09/13 GARDE, B P Government Accountability Project 1p 20840 328 24X Fiche 50-329, 83/09/13, 8310190305
- 8310190306 FOIA request for comments on NUREG/CR-1278, "Handbook for Human Reliability Analysis W/Emphasis on Nuclear Power Plant Applications"
SHOLLY, B C Union of Concerned Scientists 03/08/06 FELTON, J M
Division of Rules and Records 1p 20840 337
- 8310190309 Responds to FOIA request for comments on NUREG/CR-1278, "Handbook for Human Reliability Analysis W/Emphasis on Nuclear Power Plant Applications" Forwards document Document also available in PDR
FELTON, J M Division of Rules and Records 03/09/12 SHOLLY, B
Union of Concerned Scientists 1p 20840 338
- 8310190313 SAND82-7056
"Peer Group Study of Draft Handbook for Human Reliability Analysis W/Emphasis on Nuclear Power Plant Applications, NUREG/CR-1278"
BRUNE, R L, WEINSTEIN, M, FITZWATER, M E Human Performance Technologies, Inc 03/01/31 229pp 20840 339
- 8310190311 FOIA request for documents re caseload forecast panel 830419 meeting on plant const.
GARDE, B P Government Accountability Project 03/07/11 Office of Administration 2pp 20840 329 24X Fiche 50-329, 83/07/11, 8310190311
- 8310190316 Responds to FOIA request for documents re caseload forecast panel 830419 meeting on plant const Info partially withheld JW Cook draft ltr to TM Novak (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 03/08/09 GARDE, B P
Government Accountability Project 6pp 21116 001 24X Fiche 50-329, 83/08/09, 8310190316
- 8310190318 FOIA request for copies of winning proposals issued for RFPs RS-NRR-83-092 & RS-NRR-83-093, "Severe Accident Consequence Mitigation" & "Severe Accident Core/Vessel/Containment Interactions," respectively
STEWART, D Battelle Memorial Institute, Columbus Laboratories 03/08/24 GRIMBLEY, D Division of Rules and Records 1p 20841 208
- 8310190321 FOIA request for documents re formulation of Board Notification 83-63
GROEBCH, O L Citizens for Safe Energy 03/08/22 Office of the General Counsel 2pp 20841 288
- 8310190322 Responds to FOIA request for copies of winning proposals issued for RFPs re severe accident Forwards RFPs RS-NRR-83-093 RFP-RS-NRR-83-092 available in PDR
FELTON, J M Division of Rules and Records 03/09/13 STEWART, D
Battelle Memorial Institute, Columbus Laboratories 1p 20841 209
- 8310190326 Forwards proposal "Severe Accident Core/Vessel/Containment Interactions" Deletion of travel regulations requested Core-reimbursement type contract recommended
DAVIS, R L Purdue Research Foundation DBP #A634 03/01/27
Division of Contracts, 2pp 20841 210
- 8310190329 "Severe Accident Core/Vessel/Containment Interactions"
THEODANOUS, T O, LYKOUDES, P S, HANCOCK, J C Purdue Research Foundation RS-NRR-83-093, 02/01/31, 71pp 20841 212
- 8310190325 Responds to FOIA request for documents re formulation of Board Notification 83-63 Forwards document Board notification, w/encs, previously distributed to Citizens for Safe Energy
FELTON, J M Division of Rules and Records 03/09/15, GROEBCH, O L
Citizens for Safe Energy 1p 20841 290
- 8310190337 FOIA request for documents re degradation of fuel assemblies while in spent fuel storage pools in US nuclear power plants
MAXWELL, B Rochester Post-Bulletin, Rochester, MN 03/09/10, NRC
- No Detailed Affiliation Given 1p 20844 057
- 8310190340 Responds to FOIA request for documents re degradation of fuel assemblies while in spent fuel pool in US nuclear power plants Forwards App A documents App B documents available in PDR
FELTON, J M Division of Rules and Records 03/09/15 MAXWELL, B
Rochester Post-Bulletin, Rochester, MN 5pp 20844 058, 24X Fiche 50-282, 83/09/15, 8310190340.

NONDOCKETED ITEMS

- B310170386 Informs of preliminary assessment of fuel assembly degradation observed in spent fuel storage pool & actions taken to assess failure mechanism & safety implication potential
WU,P Chemical Engineering Branch 82/12/22 BENAROYA,V
Chemical Engineering Branch 3pp 20844 074 24X
Fiche 50-282,83/09/15,8310190340
- B304200240 Forwards matl presented by util during B30223 meeting re fuel assembly failure in spent fuel pool Review establishing NRC position on listed issues requested Working meeting scheduled for B30420 Encl withheld
DIANNI,D C Operating Reactors Branch 3 TAC 49353 83/04/08
WU,P NRC - No Detailed Affiliation Given 2pp 20844 129 24X
Fiche 50-282,83/09/15,8310190340
- B303050044 Describes plan for review of Northern States Power Co & Westinghouse submittal on fuel assembly degradation while in spent fuel storage pool, prompted by fuel assembly cracking incident at Prairie Island
WU,P Chemical Engineering Branch 83/04/20 BENAROYA,V
Chemical Engineering Branch 2pp 20844 131 24X
Fiche 50-282,83/09/15,8310190340
- B303240300 Advises of informal preliminary review of potential safety issues that may exist as result of in-core fuel assembly nozzle separations Westinghouse analysis indicates no problem associated w/prevention of control rod insertions
TOKAR,M Core Performance Branch TAC 49353 83/05/16 WU,P
Chemical Engineering Branch 2pp 20844 134 24X
Fiche 50-282,83/09/15,8310190340
- B308180258 Forwards B30617 SER re fuel assembly corrosion in spent fuel pool & draft info notice addressing corrosion problems at BWRs & PWRs Fuel assembly bulge joint B11216 failure w/o precedent & w/o determined cause w/o encls
BENAROYA,V Chemical Engineering Branch 83/08/02 HOLAHAN,O
Operating Reactors Assessment Branch 2pp 20844 136 24X
Fiche 50-282,83/09/15,8310190340
- B310190344 Forwards proposed subjs of discussion for upcoming NRC- licensee-vendor meeting on spent fuel assembly failure evaluation Main concern lies in possible generic implication & licensee/vendor conclusion on failure mechanism
WU,P Chemical Engineering Branch 82/01/17 Chemical Engineering Branch 4pp 20844 070 24X Fiche 50-282,83/09/15,8310190340
- B310190358 Forwards safety evaluation of fuel assembly failure event during fuel handling in spent fuel pool in Dec 1981 Evidence insufficient to deduce generic effect.
JOHNSTON,W V Assistant Director for Matls, Chem & Environ Technology (Post B30201) 83/04/20 LAINAS,O C Assistant Director for Operating Reactors 4pp 20844 133 24X
Fiche 50-282,83/09/15,8310190340
- B310190360 Safety evaluation concluding that evidence insufficient to draw generic conclusions from Dec 1981 fuel pool assembly failure event
* NRC - No Detailed Affiliation Given 83/04/20 17pp
20844 137 24X Fiche 50-282,83/09/15,8310190340
- B310190361 Safety evaluation of spent fuel assembly degradation Event was isolated incident.No generic implications exist Draft IE info notice re potential contamination of RCS encl
* NRC - No Detailed Affiliation Given 83/06/17 12pp
20844 160 24X Fiche 50-282,83/09/15,8310190340
- B310200026 FOIA request for correspondence between Chairman Palladino & DOJ re investigation of alleged falsification of RCS leak rate tests News article dtd 830523 from Patriot News encl
VO10Y,H H LeBoeuf, Lamb, Leiby & MacRae 83/05/26 Office of Administration 2pp 20844 238 24X Fiche 50-289,83/09/15,8310200026
- B310200032 Responds to FOIA request for correspondence between Chairman Palladino & DOJ re investigation of alleged falsification of RCS leak rate tests Forwards App A documents Portions of requested documents withheld (ref FOIA Exemption 7)
FELTON,J M Division of Rules and Records 83/09/15 VO10Y,H H LeBoeuf, Lamb, Leiby & MacRae 2pp 20844 236 24X
Fiche 50-289,83/09/15,8310200032
- B310200038 Ack receipt of B30317 ltr re DOJ investigation into allegations re possible criminal wrongdoing Separate NRC investigation will be initiated
PALLADINO,N J, Commissioners 83/05/27, JENSON,D L Justice, Dept. of 1p 20844 240 24X Fiche 50-289,83/09/15,8310200032
- B310200044 Requests that DOJ investigation on allegations re falsification of RCS leak rate tests be completed by B30315 Response within 2 wks requested Info partially deleted.
PALLADINO,N J Commissioners. 83/04/11. SMITH,W F Justice, Dept of 2pp 20844 241 24X Fiche 50-289,83/09/15,8310200032
- B310200048 Responds to B30411 ltr re TMI-1 restart / DOJ investigation into allegations re mgt competence Investigation being pursued diligently but will not be completed by requested date Info partially deleted
JENSON,D L Justice, Dept of 83/05/17 PALLADINO,N J Commissioners 4pp 20844 243 24X Fiche 50-289,83/09/15,8310200032
- B310200353 FOIA request for comments on proposed rule 10CFR50 re ATWS NRC evaluation of comments & draft/final versions of rule
HIATT,S L Ohio Citizens for Responsible Energy 83/08/17
FELTON,J M Division of Rules and Records 1p 20868 272
- B310200356 Responds to FOIA request for proposed ATWS rule,NRC evaluation of comments & draft/final version of rule
Forwards Documents 1-8 of App A Documents 9 & 10 partially withheld (ref FOIA Exemption 5)
FELTON,J M Division of Rules and Records 83/09/23 HIATT,S L Ohio Citizens for Responsible Energy 3pp 20868 273
- B307280124 Provides status of ATWS rulemaking in response to B20430 request
DIRCKS,W J Office of the Executive Director for Operations 82/06/11 PALLADINO,N J Commissioners 2pp 20871 079
- B307290223 Summarizes ACRS 279th meeting on B30707-09 re proposed final rule on ATWS Comprehensive program encompassing all plant safety-related sys recommended Consideration should be given to listed comments before rule issued in final form
RAY,J J ACRS - Advisory Committee on Reactor Safeguards 83/07/15 PALLADINO,N J Commissioners 4pp 20871 079
- B308080690 Forwards response to ACRS B30715 ltr re proposed final rule re ATWS Rev to rule not warranted
DIRCKS,W J Office of the Executive Director for Operations 83/07/27 RAY,J J ACRS - Advisory Committee on Reactor Safeguards 5pp 20871 288
- B310200357 Comments on proposed rule 10CFR50 & petition for rulemaking PRM-50-29 re stds for reduction of risk from ATWS event
Opposes rule & rulemaking due to lack of technical justification in basic premises & cost of implementation
BOUCHCY,O D Washington Public Power Supply System 46FR57521 003 82/04/15 Docketing & Services Branch 5pp 20868 264
- B310200359 Requests brief paper be prepared describing status of ATWS rule & plans for resolution Response due by B20521
PALLADINO,N J Commissioners 82/04/30 DIRCKS,W J Office of the Executive Director for Operations 1p 20871 078
- B310200364 Requests listed info needed in order to act on REC-83-2: "Amends to 10CFR50 re ATWS Events"
ASSELBTINE,J K Commissioners 83/08/11 DIRCKS,W J Office of the Executive Director for Operations 2pp 20871 293
- B310200374 FOIA request for access to documents re investigations of Nuclear Matls & Equipment Corp & ZM Shapiro, company president
LISTER,G E Patterson, Belknap, Webb & Tyler FIALKA,J Affiliation Unknown 83/08/19 SNIDER,W J Justice, Dept of 3pp 20874 219
- B310200379 Responds to FOIA request for documents re DOJ investigation of Nuclear Matls & Equipment Corp & ZM Shapiro, company president Forwards seven documents Documents also available in PDR
FELTON,J M Division of Rules and Records 83/09/15 LISTER,G E Patterson, Belknap, Webb & Tyler 1p 20874 222
- B310200383 Responds to 780912 request for T McTiernan 780630 memo re loss of U from NUREC facility in Apollo,PA w/o encls
KELLEY,J L Office of the General Counsel 78/09/18 HEYMANN,P B Justice, Dept of 1p 20874 223
- B310200387 Requests assistance for newly appointed Commissioner Aheer re investigation of NUREC
GOSBICK,L V Office of the Executive Director for Operations 78/10/04 HEYMANN,P B Justice, Dept of 1p 20874 224
- B310200391 Responds to J Conran 780303 allegations re conduct of BOC/QIA inquiry into EDD testimony, per 780620 request Memo should be available to public
MC TIERNAN,T J Office of Inspector & Auditor 78/06/30 HENDRIE,J, GILINSKY,V, KENNEDY,R T Commissioners 19pp 20874 226
- B310200394 Comments on J Conran Mar 1977 ltr to Congressman Udall re conduct of OIA/BOC investigation
FITZGERALD,J A Office of the General Counsel 78/06/29 Office of the General Counsel 7pp 20874 245

NONDOCKETED ITEMS

426

- B310200398 Concedes w/Fitzgerald memo re investigation into EDO testimony
CRANE, P Office of the General Counsel 78/05/29 Office of the General Counsel 6pp 20874 252
- B310200404 Documents circumstances leading to J Conrad allegations re unavailability of union representative for second interview in Gossick-Gilinsky Rept
MCNIERNAN, J J Office of Inspector & Auditor 78/02/23 Office of Inspector & Auditor 3pp 20874 258
- B310210001 Requests FBI repts an investigation of RE Diesacker allegations re NUMEC
CUMMINGS, J J Office of Inspector & Auditor 80/06/11 MARTIN, J Justice, Dept of 1p 20874 225
- B310200448 FOIA request for E&G Rept EGO-CDD-6001, "Model for Release of Fission Products from Fuel Pellets & Debris"
PASCHALL, A INFO/DOC 83/08/25 Office of Administration 1p 20859 339
- B310200450 Responds to FOIA request for E&G Rept EGO-CDD-6001, "Model for Release of Fission Products from Fuel Pellets & Debris"
NRC does not have reft Rept may be obtainable from E&G
FELTON, J M Division of Rules and Records 83/09/13 PASCHALL, A INFO/DOC 1p 20859 340
- B310210307 FOIA request for records re radioactive substances at Maywood Chemical Works or Stepan Chemical Co
TYKULSKER, D Ball, Hayden, Kiernan & Livingston 83/09/12 NRC - No Detailed Affiliation Given 2pp 20884 175
- B310210311 Responds to FOIA request for records re Maywood Chemical Works or Stepan Chemical Co Forwards responses to FOIA Requests B1-38, B1-196, B1-197, B2-390, B2-464 & B3-212 w/o encls
FELTON, J M Division of Rules and Records 83/09/22 TYKULSKER, D Ball, Hayden, Kiernan & Livingston 1p 20884 177
- B310210315 Responds to FOIA request for documents re decision to conduct Caseload Forecast Panel meetings & only tour facility & any documents re rationale or basis for decision Forwards documents
FELTON, J M Division of Rules and Records 83/07/29 SUGARMAN, R Sugarmann & Denuworth 2pp 20883 170 24X Fiche 50-352, 83/07/29, B310210315
- B303230300 Requests Caseload Forecast Panel site visit to update assessment of const completion status
EISENHUT, D G Division of Licensing 83/03/16 HARTFIELD, R A Management Information Branch 1p 20883 194 24X Fiche 50-352, 83/07/29, B310210315
- B310210320 FOIA request for plant manager IM 7, filing labels
LEE, G W Trans-Continental Consultants, Inc 83/09/13 Division of Rules and Records 1p 20884 171
- B310210323 Responds to FOIA request for list of plant managers in label form Forwards requested list w/o encl
FELTON, J M Division of Rules and Records 83/09/22 LEE, G W Trans-Continental Consultants, Inc 1p 20884 172
- B310210324 FOIA request for Westinghouse 800708 notification of unrevised safety question under 10CFR50.59 re boron dilution
GRABER, L D NUS Corp CD-18-83-325 83/09/08 Division of Rules and Records 1p 20884 173
- B310210325 Responds to FOIA request for Westinghouse 800708 notification of reviewed safety question Document available in PDR
FELTON, J M Division of Rules and Records 83/09/21 GRABER, L D NUS Corp 1p 20884 174
- B310210327 FOIA request for all documents re significantly high rate of equipment failures for GE BWR/4 rated at 2,436 MW
HAFNER, B Suffolk Nuclear Study Group 83/07/05 Office of Administration 1p 20882 222
- B310210329 Responds to FOIA request for all documents re significantly high rate of equipment failures for GE BWR/4 rated at 2,436 MW Forwards App A documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/07/28 HAFNER, B Suffolk Nuclear Study Group 2pp 20882 223 24X Fiche 50-000, 83/07/28, B310210329
- B210180246 Submits preliminary account of events associated w/820825 reactor trip Reactor tripped from 99% power due to overpower condition on average power range monitor Caused by closure of one isolation valve on C main steam line
RUBIN, S D Reactor Operations Analysis Branch AEOD/E240 82/09/29 SEYFRIT, K V Reactor Operations Analysis Branch 3pp 20882 249 24X Fiche 50-000, 83/07/28, B310210329
- B301180313 Evaluates LERs for Jul 1981 - Oct 1982 in support of upcoming SALP review LERs minimally adequate in narrative sections Large number considered mgt deficiency-related
SEYFRIT, K V Director's Office 83/01/12 LEWIS, R Division of Project & Resident Programs 2pp 20882 225 24X Fiche 50-000, 83/07/28, B310210329
- B302020202 Summarizes evaluation of LERs for 1982 in support of upcoming SALP review Licensee performance adequate
SEYFRIT, K V Reactor Operations Analysis Branch 83/01/26 STAROSTECKI, R Division of Project & Resident Programs 3pp 20882 254 24X Fiche 50-000, 83/07/28, B310210329
- B302180539 Discusses results of evaluation of LERs for Jul 1981 - Dec 1982, for SALP reft Quality & quantity of LERs within range of average BWR facility
SEYFRIT, K V Reactor Operations Analysis Branch 83/02/09 LEWIS, R C Division of Project & Resident Programs 3pp 20882 257 24X Fiche 50-000, 83/07/28, B310210329
- B303030103 Comments of LERs submitted from Feb 1982 - Jan 1983, in support of SALP review LERs generally prepared adequately w/occasional exceptions Licensee performance typical of average BWR facility in initial phase of plant startup
SEYFRIT, K V Reactor Operations Analysis Branch 83/02/22 STAROSTECKI, R Division of Project & Resident Programs 2pp 20882 263 24X Fiche 50-000, 83/07/28, B310210329
- B303240341 Summarizes evaluation of LERs for 1982 LER submittals usually acceptable Potential mgt weakness indicated by large number of procedural deficiencies, lack of followup repts committed to & possible training problems
SEYFRIT, K V Reactor Operations Analysis Branch 83/03/15 LEWIS, R C Division of Project & Resident Programs 4pp 20882 269 24X Fiche 50-000, 83/07/28, B310210329
- B303240364 Summarizes evaluation of LERs for Mar 1982 - Feb 1983 LER submittals acceptable Supplemental or followup info would improve operational experience analysis
SEYFRIT, K V Reactor Operations Analysis Branch 83/03/16 STAROSTECKI, R Division of Project & Resident Programs 3pp 20882 273 24X Fiche 50-000, 83/07/28, B310210329
- B306100008 Discusses evaluation of LERs submitted during appraisal period May 1982-Apr 1983 for technical accuracy, completeness & intelligibility Screening for trends & patterns produced few cases which could indicate potential mgt weakness
SEYFRIT, K V Reactor Operations Analysis Branch 83/05/18 STAROSTECKI, R Division of Project & Resident Programs 3pp 20882 276 24X Fiche 50-000, 83/07/28, B310210329
- B310240012 Partial response to FOIA request for transcripts of deposition testimony prepared in discovery in DL proceeding for facilities Forwards App A documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/08/10. AHLERS, D M Palmetto Alliance 3pp 20885 001 24X Fiche 50-413, 83/08/10, B310240012
- B310240014 Transcript of M Birch deposition in Charlotte, NC re Contention 27
BIRCH, M Duke Power Co 83/05/11 126pp 20885 008 24X Fiche 50-413, 83/08/10, B310240012
- B310240017 Transcript of CW Graves deposition in Charlotte, NC re Contention 8
GRAVES, C W Duke Power Co 83/05/12 44pp 20885 134 24X Fiche 50-413, 83/08/10, B310240012
- B310240018 Transcript of PK Vandoorn deposition in Charlotte, NC re Contention 6
VANDDOORN, P K Duke Power Co 83/05/19 150pp 20885 178 24X Fiche 50-413, 83/08/10, B310240012
- B310240021 Transcript of WR McAfee deposition in Charlotte, NC re Contention 6
MCAFEE, W R Palmetto Alliance, 83/03/19 128pp 20885 328 24X Fiche 50-413, 83/08/10, B310240012
- B310240022 Transcript of NL Hoopengardner deposition in Charlotte, NC re Contention 6
HOOPENGARDNER Palmetto Alliance 83/05/19 47pp 20886 094 24X Fiche 50-413, 83/08/10, B310240012

NONDOCKETED ITEMS

- B310240024 Transcript of NR Hoopingarner deposition in Charlotte, NC re Contention 6
HOOPINGARNER, N Palmetto Alliance 83/05/20 109pp 20886 142 24X
Fiche 50-413, 83/08/10, B310240012
- B310240030 Transcript of GE Vaughn deposition in Charlotte, NC re Contention 7
VAUGHN, G E Duke Power Co 83/05/20 41pp 20886 231 24X
Fiche 50-413, 83/08/10, B310240012
- B310240032 Transcript of JC Bryant deposition in Charlotte, NC re Contention 6 & 7
BRYANT, J C NRC - No Detailed Affiliation Given 83/05/20 80pp
Fiche 50-413, 83/08/10, B310240012
- B310240038 Transcript of PK Vandoorn deposition in Charlotte, NC re Contention 6, Vol II
VANDOORN, P K Duke Power Co 83/05/20 137pp 20887 011 24X
Fiche 50-413, 83/08/10, B310240012
- B310240040 Transcript of BQ Addis deposition in Charlotte, NC re Contention 6
ADDIS, B Q Duke Power Co 83/06/27 129pp 20887 139 24X
Fiche 50-413, 83/08/10, B310240012
- B310240043 Transcript of GH Bell deposition in Charlotte, NC re Contention 6
BELL, G H Duke Power Co 83/06/27 75pp 20887 269 24X
Fiche 50-413, 83/08/10, B310240012
- B310240047 Transcript of JC Rogers deposition in Charlotte, NC re Contention 6
ROGERS, J C Duke Power Co 83/06/27 32pp 20887 346 24X
Fiche 50-413, 83/08/10, B310240012
- B310240049 Transcript of WD Henry deposition in Charlotte, NC re Contention 6
HENRY, W D Duke Power Co 83/06/28 133pp 20888 017 24X
Fiche 50-413, 83/08/10, B310240012
- B310240053 Transcript of DG Beam deposition in Charlotte, NC re Contention 6
BEAM, D G Duke Power Co 83/06/28 81pp 20888 152 24X
Fiche 50-413, 83/08/10, B310240012
- B310240055 Transcript of WD Henry deposition in Charlotte, NC re Contention 6
HENRY, W D Duke Power Co 83/06/29 65pp 20888 235 24X
Fiche 50-413, 83/08/10, B310240012
- B310240056 Transcript of AE Allum 830629 deposition in Charlotte, NC re Contention 6
ALLUM, A E Duke Power Co 83/06/29 114pp 20888 306 24X
Fiche 50-413, 83/08/10, B310240012
- B310240057 Transcript of CR Baldwin 830629 deposition in Charlotte, NC re Contention 6
BALDWIN, C R Duke Power Co 83/06/29 191pp 20889 052 24X
Fiche 50-413, 83/08/10, B310240012
- B310240058 Transcript of JE Orogan deposition in Charlotte, NC Related info encl
GROGAN, J E Duke Power Co 83/07/01 27pp 20889 241 24X
Fiche 50-413, 83/08/10, B310240012
- B310240059 Transcript of MH Bradley deposition in Charlotte, NC re Contention 6
BRADLEY, M H Duke Power Co 83/07/07 56pp 20889 270 24X
Fiche 50-413, 83/08/10, B310240012
- B310240060 Transcript of CN Alexander deposition in Charlotte, NC re Contention 6 Related info encl
ALEXANDER, C N Duke Power Co 83/07/07 110pp 20889 327 24X
Fiche 50-413, 83/08/10, B310240012
- B310240061 Transcript of WS Lee deposition in Charlotte, NC Related info encl
LEE, W S Duke Power Co 83/07/12 78pp 20890 074 24X
Fiche 50-413, 83/08/10, B310240012
- B310240062 Transcript of RA Morgan deposition in Charlotte, NC re Contention 6
MORGAN, R A Duke Power Co 83/07/13 120pp 20890 153 24X
Fiche 50-413, 83/08/10, B310240012
- B310240065 Transcript of BW Deaton deposition in Charlotte, NC re Contention 6
DEATON, B W Duke Power Co. 83/07/14 49pp 20890 274 24X
Fiche 50-413, 83/08/10, B310240012
- B310240068 Transcript of S Ledford deposition in Charlotte, NC re Contention 6
LEDFORD, S Duke Power Co 83/07/14 26pp 20890 325 24X
Fiche 50-413, 83/08/10, B310240012
- B310240073 Transcript of JC Shropshire deposition in Charlotte, NC re Contention 6 Related info encl
SHROPSHIRE, J C Duke Power Co 83/07/14 87pp 20890 353 24X
Fiche 50-413, 83/08/10, B310240012
- B310240076 Transcript of L Bifford deposition in Charlotte, NC re Contention 6
BIFFORD, W L Duke Power Co 83/07/14 38pp 20891 083 24X
Fiche 50-413, 83/08/10, B310240012
- B310240167 FOIA request for documents re M Adler &/or Scorpio Music Distributors, Inc & documents re investigation concerning Thomas Jefferson Univ Hosp & DA Zane
JACOBSON, P J Jacobson, P J 83/06/06 NRC - No Detailed Affiliation Given 2pp 20891 303
- B310240171 Partial response to FOIA request for documents re M Adler &/or Scorpio Music Distributors, Inc & investigation concerning Thomas Jefferson Univ Hosp & DA Zane
FELTON, J M Division of Rules and Records 83/07/06 JACOBSON, P J Jacobson, P J 2pp 20891 305
- 7906250181 Discusses IE insp of License 37-00148-06 on 781109 & 14 forwards notice of violation
MCCLINTOCK, R D Region 1, Philadelphia, Office of the Director 78/12/18 SWEENEY, F Thomas Jefferson Hosp Philadelphia, PA 2pp 20891 319
- 7906250189 Notice of violation from insp on 781109 & 14 Noncompliance noted coffee was drunk in labs, radiopharms were injected w/o waterproof gloves & syringe shields & Dfc of Radiation safety was not notified of spill
* Region 1, Philadelphia, Office of the Director 78/12/18 2pp 20891 321
- B310240173 Authorizes release of records to PJ Jacobson
ADLER, M Affiliation Unknown 83/06/01 NRC - No Detailed Affiliation Given 1p 20891 307
- B310240175 Discusses statements made by DA Zane, radiation technologist at Thomas Jefferson Univ Hosp, Philadelphia, PA, detailing radioactive matl misuse & personnel abuses
ADLER, M Affiliation Unknown 78/07/20 HENDRIE, J M Commissioners 9pp 20891 308
- B310240176 Ack receipt of 780720 ltr Several issues raised require anal
analysis & further inquiry
ABBOTT, D G Office of Inspector & Auditor 78/08/09 ADLER, M Affiliation Unknown 1p 20891 317
- B310240181 Forwards 781004 memo re complaint concerning Thomas Jefferson Univ Hosp Basis for radiological conditions, per M Adler 780720 ltr will be examined w/o stated encl w/draft field notes of IE Insp Rept 30-02941/78-02
ALLAN, J M Region 1, Philadelphia, Office of the Director 78/10/12 HIGGINSBOTHAM, L Division of Fuel Facility & Materials Safety 1p 20891 323
- B310240185 Responds to 780720 ltr re general disregard for good radiological safety practices at Thomas Jefferson Univ Hosp
Unannounced insp conducted on 781109 & 14 Noncompliance re failure to follow safety procedures identified
ORRIS, B H NRC - No Detailed Affiliation Given 78/02/01 ADLER, M Affiliation Unknown 2pp 20891 332
- B310240189 Responds to FOIA request for copies of ltrs to Univ of Michigan following insps of broad license from 1980-82
Forwards App A documents w/o encl Documents also in PDR
FELTON, J M Division of Rules and Records 83/07/08 SAENGER, E L Univ of Cincinnati Medical Ctr, Cincinnati, OH 2pp 20907 165
- B310240190 FOIA request for copies of ltrs to Univ of Michigan following insps of broad license from 1980-82
SAENGER, E L Univ of Cincinnati Medical Ctr, Cincinnati, OH 83/06/24 Division of Rules and Records 1p 20907 167
- B310240191 Final response to FOIA request for documents re M Adler &/or Scorpio Music Distributors & investigation of Thomas Jefferson Univ Hosp & DA Zane Document released in 830706 ltr
FELTON, J M Division of Rules and Records 83/09/06 JACOBSON, P J Jacobson, P J 1p 20903 245

NONDOCKETED ITEMS

427

- 8310240192 FOIA request for four categories of documents
SHOLLY, S C Union of Concerned Scientists 83/06/07 FELTON, J M
Division of Rules and Records 1p 20884 178
- 8310240193 Responds to FOIA request for four categories of documents
Forwards App A documents responsive to Items 1, 2 & 3
Records re Item 4 can be obtained from DOE
FELTON, J M Division of Rules and Records 03/07/01 SHOLLY, S
Union of Concerned Scientists 2pp 20884 179
- 8310240194 "Rept to Commission, Review of NRC Reactor Safeguards
Program"
CUMMING, J J Office of Inspector & Auditor 83/04/30 144pp
20884 181
- 8310240195 Summary of 830910 meeting w/ LAGL in Los Alamos, NM re TRAC/
MIRAS review & integration
HAN, J T, AUDETTE, R NRC - No Detailed Affiliation Given
83/05/24 MARINO, G P, CURTIS, R T NRC - No Detailed Affiliation
Given 4pp 20884 325
- 8310240196 FOIA request for agency records relevant to &/or generated
in connection w/ NRC investigations, insp or repts on
allegations made by R Gunderson & W Royce re facilities
BERNABEI, L Government Accountability Project 83/08/05 Office
of Administration 2pp 20903 249 24X Fiche 50-528, 83/08/05,
8310240196
- 8310240197 Partial response to L Bernabei 830805 FOIA request for
agency records relevant to &/or generated in connection w/
NRC investigations, insp or repts on allegations made by
R Gunderson & W Royce Forwards App A documents
FELTON, J M Division of Rules and Records 83/09/08 GARDE, B
Government Accountability Project 4pp 20903 231 24X
Fiche 50-528, 83/09/08, 8310240197
- 8206080487 Comments on 820511 ltr re allegations of improper
electrical work Inquiry being made
DIRCKS, W J Office of the Executive Director for Operations
82/05/26 WOODS, T O Arizona Public Service Co 1p 20904 128
24X Fiche 50-528, 83/09/08, 8310240197
- 8310240199 Requests assistance in disclosing worker allegations re
problems at facility Various allegations by workers re
const, QA & QC problems existing at plant discussed
MORRISON, J R Palo Verde Intervention Fund 82/12/07 GARDE, B
Government Accountability Project 3pp 20903 332 24X
Fiche 50-528, 83/09/08, 8310240197
- 8310240201 Submits list of plant electrician allegations that author
considers readily documented w/o further investigation Some
items listed already documented in rough form
ECKHARDT, J H NRC - No Detailed Affiliation Given 82/12/17
SHACKLETON, O NRC - No Detailed Affiliation Given 1p
20903 335 24X Fiche 50-528, 83/09/08, 8310240197
- 8310240203 Submits results from informal 830323 meeting re unreviewed
affidavits from Oovt Accountability Project Shackleton
analyzed Gunderson Affidavit & will identify any new areas
to Region V
HARBUT, P P Region 5, Office of Director 83/07/23
STERNBERG, D M, YOUNG, T, FIORELLI, G NRC - No Detailed
Affiliation Given 1p 20903 336 24X Fiche 50-528, 83/09/08,
8310240197
- 8310240207 Discusses 830442 telcon re terminations & crimping
tools Harbut allegation logs & related mats encl
HARBUT, P P NRC - No Detailed Affiliation Given 83/09/08 NRC -
No Detailed Affiliation Given 16pp 20903 339
- 8310240209 Notifies of results of Dept of Labor compliance actions in
W Royce vs Bechtel Corp case Lists actions required to abate
violation & provide appropriate relief Right to appeal
findings within 5 days of ltr receipt permitted
BREEN, J Labor, Dept of 82/12/20 BUTLER, B Bechtel Corp
2pp 20903 362
- 8310240212 Forwards Dept of Labor 830324 Recommended Decision & Order
of Administrative Law Judge in W Royce vs Bechtel Corp case
BUTLER, B D Bechtel Corp, 83/03/30 Bechtel Corp 12pp
20904 601 24X Fiche 50-528, 83/09/08, 8310240197
- 8310240213 Requests review of NRC serious mishandling of investigation
of worker allegations re deficiencies in electrical work &
startup testing program at facilities, on behalf of
R Gunderson & W Royce Related matl encl
BERNABEI, L Government Accountability Project 83/07/14
PALLADINO, N, GILINSKY, V, AHEARNE, J Commissioners 19pp
20904 613 24X Fiche 50-528, 83/09/08, 8310240197
- 8310240217 Requests response to issues raised by J Morrison 830703 ltr
expressing concerns w/ manner in which Regional V & Ofc of
Investigation handled allegations of violations at plant
J Morrison 830703 ltr encl
UDALL, H K House of Rep, Interior & Insular Affairs 83/07/17
PALLADINO, N Commissioners 4pp 20904 640 24X
Fiche 50-528, 83/09/08, 8310240197
- 8310240218 Submits list of documents in Region V files which apply
to Young & Bernabei FOIA-83-161 request for documents re
allegations of electrical problems Related matl encl
ALEXANDER, I Region 5, Office of Director 83/05/06 TOMS, V
NRC - No Detailed Affiliation Given 5pp 20904 645 24X
Fiche 50-528, 83/09/08, 8310240197
- 8310240219 Forwards M Young & L Bernabei FOIA request for documents
re allegations of R Gunderson & senior Bechtel manager FOIA
time record form should be completed & returned
GRIMBLEY, D H NRC - No Detailed Affiliation Given 83/03/31
WILSON, V Office of Nuclear Reactor Regulation, Director
SWEENEY, M Office of the General Counsel 2pp 20904 649 24X
Fiche 50-528, 83/09/08, 8310240197
- 8310240220 Requests that documents be provided in attached FOIA Request
83-450 Documents required to be delivered to I Alexander by
830817 Forwards FOIA Request 83-450 & list of documents on
sub; Documents need not be duplicated
HARBUT, P P Region 5, Office of Director 83/08/14 MARTIN, J,
STERNBERG, D, YOUNG, T NRC - No Detailed Affiliation Given 4pp
20904 651 24X Fiche 50-528, 83/09/08, 8310240197
- 8310240221 Forwards L Bernabei FOIA request for documents in connection
w/ NRC investigations, insp repts or repts on allegations made
by R Gunderson & W Royce re facilities List of questions for
response to NL Toms requested by 830816
GRIMBLEY, D H NRC - No Detailed Affiliation Given 83/08/09
BROWN, N Office of the Secretary of the Commission, SWEENEY, M
Office of the General Counsel 2pp 20904 655 24X
Fiche 50-528, 83/09/08, 8310240197
- 8310240222 Notifies that special, unannounced insp scheduled at
facility on 830404-08 Team consisting of author, A Johnson, J
Burdoon, O Fiorelli & L Vorsterbruggen will examine facts
surrounding as many allegations as possible during insp
YOUNG, T Region 5, Office of Director 83/03/31 STERNBERG, D
NRC - No Detailed Affiliation Given 1p 20904 659 24X
Fiche 50-528, 83/09/08, 8310240197
- 8310240223 Discusses NRC insp entrance interview conducted on 830615, to
describe NRC planned insp activities Lists NRC inspectors &
areas of investigation NRC will be primarily investigating
allegations during visit Related matl encl
IDEW, E Arizona Public Service Co OAD 82 S 94 82/06/15
RODELL, J A Arizona Public Service Co 4pp 20904 102 24X
Fiche 50-528, 83/09/08, 8310240197
- 8310240227 Discusses status of special insp re allegations, in response
to 830411 memo Lists items not addressed Efforts will be
concluded & pertinent repts issued on listed items prior to
830601 Relevant documents issued & received encl
HARTIN, J B Region 5, Office of Director 83/05/02
CUNNINGHAM, O H Office of the Executive Legal Director 2pp
20904 106 24X Fiche 50-528, 83/09/08, 8310240197
- 8310240236 Notifies that author had no involvement in investigation
into allegations at facility per Harbut 830816 memo No
relevant documents re FOIA Request 83-450 in author
possession
JOHNSON, P NRC - No Detailed Affiliation Given 83/08/18
ALEXANDER, I NRC - No Detailed Affiliation Given 1p 20904 111
24X Fiche 50-528, 83/09/08, 8310240197
- 8310240239 Forwards documents re FOIA request for NRC investigation,
insps or repts on allegations made by R Gunderson & W Royce
concerning facilities Except of installation spec for cable
splicing encl
ALEXANDER, I Region 5, Office of Director 83/08/19 TOMS, N
NRC - No Detailed Affiliation Given 9pp 20904 112 24X
Fiche 50-528, 83/09/08, 8310240197
- 8310240241 Notifies of receipt of T Woods 820511 ltr to NRC re
allegations about safety at facilities Requests to be
advised of any action taken by NRC in sub; matter
RUDD, E House of Rep 82/05/19 PALLADINO, N J Commissioners
1p 20904 129 24X Fiche 50-528, 83/09/08, 8310240197
- 8310240246 Ack receipt of 820519 ltr to Chairman Palladino expressing
concern re allegations of improper electrical work at
facilities Region V initiated independent inquiry into
matter w/ legal assistance
KAMMERER, C Office of Congressional Affairs 82/06/01 RUDD, E
House of Rep 1p 20904 130 24X Fiche 50-528, 83/09/08,
8310240197

NONDOCKETED ITEMS

- B310240251 Discusses immediate effectiveness review of facilities re analysis of pending insp/investigation items identified in Oic of Insp & EDD repts of B30325 & 29 Presumes SECY will extend review time to accommodate Commission consideration ASSELSTINE, J K Commissioners. B3/04/01 PALLADINO Commissioners 1p 20904 131 24X Fiche 50-528, B3/09/08, B310240197
- B310240233 FOIA request for three listed documents to be placed in PDR PEDRO, J NUS Corp, CO-18-B3-01B B3/06/06 Division of Rules and Records 1p 20891 224
- B310240234 Further response to FOIA request for winning technical proposals under RFP RB-DRM-B3-452 resulting in multiple award task order Contracts NRC-33-B3-452-01 through 07 Forwards App D document Addl records undergoing review FELTON, J M Division of Rules and Records B3/07/08 PAUL, L K Affiliation Unknown 2pp 20907 168
- B310240238 "Multiple Award Task Order Contract for ADP Development," technical proposal * Rehab Group, Inc RB-DRM-B3-452 B2/07/14 96pp 20907.171
- B310240235 Responds to FOIA request for three documents to be placed in PDR, Forwards documents listed in app FELTON, J M Division of Rules and Records B3/07/11 PEDRO, J NUS Corp 2pp 20891 225
- B011030238 Notification of B00903 meeting w/OE in Bethesda, MD to discuss proposed BWR feedwater nozzle leakage detection sys SNAIDER, R P. Systematic Evaluation Program Branch B0/08/14 KNIEL, K Generic Issues Branch 1p 20891 228
- B011070749 Summary of B00903 meeting w/OE to discuss draft NEDE-24265-P (proprietary) re proposed feedwater nozzle surveillance instrumentation sys List of attendees encl SNAIDER, R P. Generic Issues Branch B0/09/15 KNIEL, K Generic Issues Branch 3pp 20891 229
- B102402010 Summary of B01217 meeting w/utills & vendors in Bethesda, MD re inclusion of linear elastic fracture mechanics in resolution of potential for low fracture toughness & lamellar tearing on component supports SNAIDER, R Generic Issues Branch B0/12/30 KNIEL, K Generic Issues Branch 6pp 20891 233
- B310240237 Responds to FOIA request for RFP RB-DRM-B3-500 & SECY-B3-157 Forwards RFP & related info SECY undergoing review for disclosure determination, RFP also available in PDR FELTON, J M. Division of Rules and Records. B3/07/06 GRABER, L NUS Corp 1p 20915:233
- B305130302 Forwards RFP RB-DRM-B3-500, "Cost Analyses of Proposed Changes in NRC Requirements" MATTIA, M J Administrative Contracts Branch B3/03/16 Affiliation Unknown 6pp 20915 255
- B305130304 REP RB-DRM-B3-500, "Cost Analyses of Proposed Changes in NRC Requirements" * Division of Contracts B3/03/16 52pp 20915 261
- B305130306 "Regulatory Analysis Guidelines of NRC" * NRC - No Detailed Affiliation Given B2/12/13 160pp 20916 001
- B310240279 FOIA request for Online Computer Sys, Inc bid proposal for Contract RB-DRM-B3-454, "Automated Library Sys" Expresses reservations & concerns re propriety of decision to award contract to Online Computer Sys, Inc DICK, R S Avatar Systems, Inc B3/05/13 COLEMAN, R NRC - No Detailed Affiliation Given 1p 20908 011
- B310240281 Responds to FOIA request for successful proposal under RFP RB-DRM-B3-454 Confirms B30527 telcon agreement to accept nonproprietary version of proposal, excluding cost proposal entirely Forwards document Document also available in PDR FELTON, J M Division of Rules and Records B3/07/11 DICK, R S Avatar Systems, Inc 1p 20908 012
- B310240286 "Automated Library Sys at NRC Using Integrated Library Sys (ILS)," proposal in response to RFP RB-DRM-B3-454 Proprietary info & cost proposal withheld * Online Computer Systems, Inc B3/01/18 Division of Technical Information & Document Control 40pp 20908 013
- B310240312 Responds to FOIA request for FOIA requests received during past 4 months from journalists, television, radio news, newspaper & magazine reporters Forwards documents listed in app W/o encl FELTON, J M Division of Rules and Records B3/10/11 KOLI, E. Cable News Network, Inc 2pp 20907 159
- B310240315 FOIA request for FOIA requests received during past 4 months from journalists, television, radio news, newspaper & magazine reporters. KOLI, E Cable News Network, Inc B3/09/29 NRC - No Detailed Affiliation Given 1p 20907 161
- B310240320 Addl response to FOIA request for documents re Tech Spec problems applicable to RCS leakage determinations in PWRs Forwards App A documents Documents also available in PDR FELTON, J M Division of Rules and Records B3/07/14 VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 2pp 20907 036 24X Fiche 50-348, B3/07/14, B310240320
- B010010786 Trip rept for site visit re development of portable calculator for RCS leak rates for PWRs Forwards programs for TI 59 & HP 41C calculators used during visit to compute leak rate WOODRUFF, D C Division of Reactor Operations Inspections B0/08/14 JORDAN, E L Division of Reactor Operations Inspection 27pp 20907 039 24X Fiche 50-348, B3/07/14, B310240320
- B310250002 Responds to FOIA request for distribution list used for mailing NUREG-0737 (Suppl 1), "Control Room Design Reviews" Forwards list W/o encl FELTON, J M Division of Rules and Records B3/07/14 DEBOR, J Biotechnology, Inc 1p 20908 337
- B310250007 FOIA request for distribution list used for mailing NUREG-0737 (Suppl 1), "Control Room Design Reviews" Info received will be used to support until conference on NUREG-0737 DEBOR, J Biotechnology, Inc B3/07/05 Division of Rules and Records 1p 20908 338
- B310250009 Responds to appeal re denial of FOIA request for SECY-B2-388 "Withdrawal of Medical Misadministration Reporting Requirements" Forwards Attachments 2, 3, 4 & 5 Attachments 1, 6, 7 & two page analysis withheld (ref FOIA Exemption 5) CHILK, B J Office of the Secretary of the Commission B3/07/01 ERNSTHAL, W L Society of Nuclear Medicine 3pp 20916 231
- B310250014 Discusses B20108 meeting w/J Halprin of FDA re misadministration reporting rules FDA comparable rules listed Rules have little relevance to misadministration FDA does not plan to engage in reporting CUNNINGHAM, R E Division of Fuel Cycle & Material Safety B2/01/15 Division of Fuel Cycle & Material Safety 1p 20916:233
- B310250017 Summary of B10811 preliminary meeting w/Joint Commission on Accreditation of Hosps Meeting attendees, purpose, program scope, mode of operation, info on misadministrations & conclusions provided ROCHE-FARMER, L NRC - No Detailed Affiliation Given B1/08/18 NRC - No Detailed Affiliation Given 2pp 20916 254
- B310250019 Summary of B10806 meeting w/S Kidder, Dept of Health & Human Svcs Meeting purpose, program scope, mode of operation & conclusions provided ROCHE-FARMER, L NRC - No Detailed Affiliation Given B1/08/28 NRC - No Detailed Affiliation Given 2pp 20916 255

NONDOCKETED ITEMS

429

- 8310250024 Notification of B20119 meeting w/Joint Commission on Accreditation of Hosps (JCAH) to determine feasibility of JCAH taking over day-to-day operations of misadministration reporting requirements
ROCHE, L. A. Uranium Fuel Licensing Branch 82/01/22 Uranium Fuel Licensing Branch 1p 20916 257
- 8310250025 Summary of meeting on petitions for rulemaking on misadministration rule by American College of Radiology, SNM & American Soc of Therapeutic Radiologists Meeting agenda & list of attendees provided
ROCHE-FARMER, L. NRC - No Detailed Affiliation Given 81/09/11 NRC - No Detailed Affiliation Given 1p 20916 258
- 8310250014 Discusses B20108 meeting w/J Halprin of FDA re misadministration reporting rules FDA comparable rules listed Rules have little relevance to misadministration FDA does not plan to engage in reporting
CUNNINGHAM, R. E. Division of Fuel Cycle & Material Safety 82/01/15 Division of Fuel Cycle & Material Safety 1p 20916 253
- 8310250017 Summary of B10811 preliminary meeting w/Joint Commission on Accreditation of Hosps Meeting attendees, purpose, program scope, mode of operation, info on misadministrations & conclusions provided
ROCHE-FARMER, L. NRC - No Detailed Affiliation Given 81/08/18 NRC - No Detailed Affiliation Given 2pp 20916 234
- 8310250019 Summary of B10806 meeting w/S Kidder, Dept of Health & Human Svcs Meeting purpose, program scope, mode of operation & conclusions provided
ROCHE-FARMER, L. NRC - No Detailed Affiliation Given 81/08/28 NRC - No Detailed Affiliation Given 2pp 20916 235
- 8310250024 Notification of B20119 meeting w/Joint Commission on Accreditation of Hosps (JCAH) to determine feasibility of JCAH taking over day-to-day operations of misadministration reporting requirements
ROCHE, L. A. Uranium Fuel Licensing Branch 82/01/22 Uranium Fuel Licensing Branch 1p 20916 257
- 8310250025 Summary of meeting on petitions for rulemaking on misadministration rule by American College of Radiology, SNM & American Soc of Therapeutic Radiologists Meeting agenda & list of attendees provided
ROCHE-FARMER, L. NRC - No Detailed Affiliation Given 81/09/11 NRC - No Detailed Affiliation Given 1p 20916 258
- 8310250026 FOIA request for SECY-83-030, "TMI-Related Requirements at Operating Reactors," to be placed in PDR
BUCKLES, R. NUS Corp CD-15-83-049 83/06/24 Division of Rules and Records 1p 20916 177
- 8310250028 Responds to FOIA request for SECY-83-030, "TMI-Related Requirements at Operating Reactors," to be placed in PDR
Forwards requested document Document also available in PDR
FELTON, J. M. Division of Rules and Records 83/07/15 BUCKLES, R. NUS Corp 1p 20916 178
- 8310250030 SECY-83-030
Advices of NRR plan to take licensing action on TMI action plan requirements specified in NUREG-0737 scheduled for implementation after B10630
DIRCKS, W. J. Office of the Executive Director for Operations 83/01/21 31pp 20916 179
- 8310250031 FOIA request for A Szukiewicz B20809 & B30114 memos to K Kniel, summarizing NRC B20728 & 1229-30 meetings w/EG&G re Unresolved Safety Issue A-47, to be placed in PDR
BUCKLES, R. NUS Corp CD-15-83-100 83/06/30 Division of Rules and Records 1p 20908 281
- 8310250032 Responds to FOIA request that A Szukiewicz B20809 & B30114 memos to K Kniel, summarizing NRC B20728 & 1229-30 meetings w/EG&G re Unresolved Safety Issue A-47, be placed in PDR
Forwards documents
FELTON, J. M. Division of Rules and Records 83/07/15 BUCKLES, R. NUS Corp 1p 20908 282.
- 8208240121 Summary of B20728 meeting w/EG&G, ID in Bethesda, MD re Unresolved Safety Issue A-47, "Safety Implications of Control Sys " Modeling of control sys to begin in Aug 1982
W/o handouts
SZUKIEWICZ, A. J. Generic Issues Branch 82/08/09 KNEIL, K. Generic Issues Branch 35pp 20908 288
- 8301250200 Summary of B21229 & 30 meetings w/EG&G in Idaho Falls, ID re status & progress of Browns Ferry plant review & progress on Unresolved Safety Issue A-47 concerning safety implications of control sys Agenda & attendance list encl
SZUKIEWICZ, A. Generic Issues Branch 83/01/14 KNEIL, K. Generic Issues Branch 5pp 20908 283
- 8310250675 Appeals denial of FOIA request for SECY-82-388, "Withdrawal of Medical Misadministration Reporting Requirements " ERNSTHAL, H. L. Society of Nuclear Medicine 83/03/08 Office of the Executive Director for Operations 1p 20916 234
- 8310260008 Addl response to FOIA request for 17 categories of records Forwards documents listed in Apps B, C & D Info re fraudulent practices of Ray Miller, Inc available in PDR
FELTON, J. M. Division of Rules and Records 83/06/23 CLEWETT, J. Public Citizen Litigation Group 15pp 20920 001 24X
Fiche 50-000, 83/06/23, 8310260008
- 8207260091 Discusses licensee May 1982 testing & evaluations of steam extraction line elbow which ruptured on B20628, in response to B20709 request for addl steam line break info
EISENHUT, D. G. Division of Licensing 82/07/14 REHM, T. A. Office of the Executive Director for Operations 2pp 20920 020 24X
Fiche 50-000, 83/06/23, 8310260008
- 8211020311 Summary of operating reactor events B20929 meeting. Viewgraphs encl
MIRAGLIA, F. J. Assistant Director for Safety Assessment 82/10/03 EISENHUT, D. G. Division of Licensing 4pp 20921 099.
- 8211040474 Forwards summary of B21013 operating reactor event meeting to brief of director, div directors & representatives on current events
MIRAGLIA, F. J. Assistant Director for Safety Assessment. 82/10/21 EISENHUT, D. G. Division of Licensing 5pp 20921 103
- 8212130174 Summary of Operating Reactor Events B21124 meeting re BWR pipe crack indications & various events
MIRAGLIA, F. J. Assistant Director for Safety Assessment 82/12/01 EISENHUT, D. G. Division of Licensing 8pp 20921 114
- 8304010047 Forwards list of rankings of nuclear power plants w/respect to population within 10 & 20 miles, in response to Senator Simpson B20317 ltr
VOLLMER, R. H. Division of Engineering 83/03/23 FUNCHES, J. Planning & Program Analysis Staff 4pp 20921 136
- 8310260027 Forwards initial info re B30628 steamline break event at facility, per B20702 telcon request Review of licensee actions continuing
MARTIN, R. D. Region 2, Office of Director 83/07/07 REHM, T. A. Office of the Executive Director for Operations 5pp 20920 022 24X
Fiche 50-000, 83/06/23, 8310260008
- 8310260031 Forwards "Rept on Effects of Lightning on Nuclear Power Station Sys," in response to question of frequency of lightning on nuclear power plants
RYDER, C. ACRS - Advisory Committee on Reactor Safeguards 82/12/09 RAY, J. ACRS - Advisory Committee on Reactor Safeguards 1p 20920 032
- 8310260034 "Rept on Effects of Lightning on Nuclear Power Station Sys " RYDER, C. P. ACRS - Advisory Committee on Reactor Safeguards 82/12/31 18pp 20920 033
- 8310260037 Forwards "Rept on Comparison of BALP Evaluations & Outage Rates of Nuclear Power Plants " RYDER, C. ACRS - Advisory Committee on Reactor Safeguards 82/11/19 MOELLER, D. ACRS - Advisory Committee on Reactor Safeguards 1p 20920 317
- 8310260041 "Rept on Comparison on SALP Evaluations & Outage Rates of Nuclear Power Plants RYDER, C. ACRS - Advisory Committee on Reactor Safeguards 82/11/30 5pp 20920 318
- 8310260049 Forwards "Power Outages at Commercial Nuclear Power Reactors During 1976 - 1979 " RYDER, C. ACRS - Advisory Committee on Reactor Safeguards 83/03/27 MOELLER, D. ACRS - Advisory Committee on Reactor Safeguards 1p 20920 323
- 8310260050 "Power Outages at Commercial Nuclear Power Reactors During 1976 - 1979 " RYDER, C. ACRS - Advisory Committee on Reactor Safeguards 83/03/27 23pp 20920 324

NONDOCKETED ITEMS

- B310260053 Summary of B20122 operating reactor events meeting Next meeting scheduled for B20203 Meeting attendees, events discussed & significant event elements encl
LAINAS, G C Assistant Director for Operating Reactors 82/01/28
EISENHUT, D G Division of Licensing 13pp 20920 347
- B310260058 Summary of B20211 operating reactor events meeting Next meeting scheduled for B20224 Meeting attendees, events discussed & significant event elements encl
LAINAS, G C Assistant Director for Operating Reactors 82/02/23
EISENHUT, D G Division of Licensing 11pp 20920 360
- B310260061 Summary of B20303 operating reactor events meeting Next meeting scheduled for B20310 Meeting attendees, events discussed & significant event elements encl
LAINAS, G C Assistant Director for Operating Reactors 82/03/08
EISENHUT, D G Division of Licensing 8pp 20921 009
- B310260066 Summary of B20317 operating reactor events meeting Next meeting scheduled for B20324 Meeting attendees, events discussed & significant event elements encl
LAINAS, G C Assistant Director for Operating Reactors 82/03/22
EISENHUT, D G Division of Licensing 4pp 20921 017
- B310260069 Summary of B20331 operating reactor events meeting Next meeting scheduled for B20407 Meeting attendees, events & significant event elements encl
LAINAS, G C Assistant Director for Operating Reactors 82/04/05
EISENHUT, D G Division of Licensing 11pp 20921 021
- B310260071 Summary of B20421 operating reactor events meeting Next meeting scheduled for B20428 Meeting attendees, events discussed & significant event elements encl
LAINAS, G C Assistant Director for Operating Reactors 82/04/26
EISENHUT, D G Division of Licensing 10pp 20921 032
- B310260075 Summary of B20505 operating reactor events meeting Next meeting scheduled for B20519 Meeting attendees, events discussed & significant event elements encl
LAINAS, G C Assistant Director for Operating Reactors 82/05/14
EISENHUT, D G Division of Licensing 9pp 20921 042
- B310260078 Summary of B20527 operating reactor events meeting Next meeting scheduled for B20609 Meeting attendees, events discussed & significant event elements encl
LAINAS, G C Assistant Director for Operating Reactors 82/06/03
EISENHUT, D G Division of Licensing 8pp 20921 051
- B310260080 Summary of B20616 operating reactor events meeting Next meeting scheduled for B20623 Meeting attendees, events discussed & significant event elements encl
LAINAS, G C Assistant Director for Operating Reactors 82/06/24
EISENHUT, D G Division of Licensing 9pp 20921 059
- B310260082 Summary of B20707 operating reactor events meeting Next meeting scheduled for B20721 Meeting attendees, events discussed & significant event elements encl
LAINAS, G C Assistant Director for Operating Reactors 82/07/14
EISENHUT, D G Division of Licensing 7pp 20921 068
- B310260085 Summary of B20811 operating reactor events meeting Next meeting scheduled for B20825 Meeting attendees, events discussed & significant event elements encl
IPPOLITO, T A Assistant Director for Operating Reactors 82/08/24
EISENHUT, D G Division of Licensing 12pp 20921 087
- B310260086 Summary of B20915 operating reactor events meeting Meeting attendees, events discussed & significant event elements encl
MIRAGLIA, F J Assistant Director for Operating Reactors 82/09/21
EISENHUT, D G Division of Licensing 5pp 20921 094
- B310260089 Summary of B21027 operating reactor events meeting Meeting attendees & events briefing encl
MIRAGLIA, F J Assistant Director for Operating Reactors 82/10/27
EISENHUT, D G Division of Licensing 6pp 20921 108
- B310260091 Summary of B21216 operating reactor events meeting Meeting attendees & events briefing encl
MIRAGLIA, F J Assistant Director for Operating Reactors 82/12/20
EISENHUT, D G Division of Licensing 6pp 20921 123
- B310260092 Summary of B30113 operating reactor events meeting Meeting attendees & events briefing encl
MIRAGLIA, F J Assistant Director for Operating Reactors 83/01/13
EISENHUT, D G Division of Licensing 7pp 20921 129
- B310260096 Describes facility B21203 flood & corrective actions taken Chronology of events encl, including notification of event & procedure for briefing commissioner
PERKINS, K E NRC - No Detailed Affiliation Given 83/06/08
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 11pp 20921 136 24X Fiche 50-010, 83/06/23, B310260008
- B310260103 "Review Procedure for Routine Insp, Operational Data & LEF," * Office of Nuclear Material Safety & Safeguards, Director 83/06/23 9pp 20921 147
- B310260016 FOIA request for matl re Ohmart Corp on & offsite radiation-related incidents
CARPENTER, T Cincinnati Alliance for Responsible Energy 83/03/18
Region 3, Office of Director 1p 20927 001
- B310260019 Responds to FOIA request for matl re Ohmart Corp on & offsite radiation-related incidents Forwards App A documents App B documents partially withheld (ref FOIA Exemptions 6 & 7)
FELDMAN, J M Division of Rules and Records 83/07/15 CARPENTER, T Cincinnati Alliance for Responsible Energy 10pp 20927 002
- B202230210 Informs that on B20121, 100 mCi Cs-137 sealed source capsule received from 3M company showing 0.01 microcurie of removable contamination Capsule removed & returned to 3M Original container decontaminated
CDDK, H L Ohmart Corp 82/02/12 Region 3, Office of Director 1p 20927 359
- B310260021 Discusses 650614 telcon w/C Stearns re Ohmart gauge owned by DuPont License 07-00455-15 not restricted from installing Ohmart gauges License permits use of matl throughout US except in Agreement States
ALLAN, J M Atomic Energy Commission 65/06/14 Atomic Energy Commission 1p 20927 012
- B310260023 Forwards 650611 telegram reporting 650608 Cs-137 contamination Region III investigation concluded occurrence not reportable per 10CFR20
ALLAN, J M Atomic Energy Commission 65/06/14 ROEDER, J R Atomic Energy Commission 1p 20927 013
- B310260025 Telecopy ltr informing of 650608 release of 100 uCi Cs-137 Cleanup complete
CDDK, H L Ohmart Corp 65/06/11 ALLAN, J Atomic Energy Commission 1p 20927 014
- B310260026 Insp Findings & Licensee Ack dtd 620117 of License 34-00637-01 Insp findings rooms & areas not properly posted to indicate presence of radioactive matl
OPARKA, E J Atomic Energy Commission 62/01/17 1p 20927 015
- B310260028 Forwards telegram confirming telcon rept of contamination incident at Ohmart Corp W/o encl
ROEDER, J R Atomic Energy Commission 65/06/17 PAGE, R G Atomic Energy Commission 1p 20927 016
- B310260030 Discusses telcon w/T Brackett re Taylor Chain Co insp rept which Region III requested enforcement action be delayed & investigation of illegal shipments from Ohmart
DAVIS, J G Atomic Energy Commission 62/11/30 Atomic Energy Commission 1p 20927 017
- B310260032 Comments on 650623 telcon w/L Cook to inform that 650608 Cs-137 contamination incident was not considered reportable. Requested whole body count to be supplied.
FOSTER, D L Atomic Energy Commission 65/06/23 Atomic Energy Commission 1p 20927 018
- B310260033 Discusses inquiry into possible unauthorized possession of 1,000 mCi Sr-90 in beta gauge
KIRKMAN, R W Atomic Energy Commission 63/06/26 RADELOFF, W A Atomic Energy Commission 8pp 20927 019
- B310260035 Discusses telcon w/RQ Cavanaugh re 630805 & 23 investigations of License 34-00637-01
RADELOFF, W A Atomic Energy Commission 63/09/06 Atomic Energy Commission 1p 20927 027
- B310260038 Comments on 650702 telcon w/J Roeder re request that Ohmart Corp submit rept on recent Cs-137 contamination incident not considered reportable Ohmart will submit rept per Condition 17 of license
ALLAN, J M Atomic Energy Commission 65/07/02 Atomic Energy Commission 1p 20927 028

NONDOCKETED ITEMS

431

- B310260040 Discusses telcon w/RQ Cavanaugh re investigation of License 34-00639-01
RADELOFF, W A Atomic Energy Commission 63/08/28 Atomic Energy Commission 1p 20927 029
- B310260043 Confirms that NRC will not correspond w/Dhmart Corp re 650610 investigation concerning damaged 50 mCi Cs-137 sealed source as enforcement action inappropriate No noncompliance found
HANDLER, R Atomic Energy Commission 65/07/28 Atomic Energy Commission 1p 20927 030
- B310260044 Discusses telcon w/WO Miller re location of file record of 1959 meeting w/Dhmart, JR Mason, Miller & others Dhmart claims to have been told to operate w/byproduct matl-contained gauges
RADELOFF, W A Atomic Energy Commission 63/08/26 Atomic Energy Commission 1p 20927 031
- B310260047 Discusses telcon w/RQ Cavanaugh re investigation of Dhmart Corp
RADELOFF, W A Atomic Energy Commission 63/08/01 Atomic Energy Commission 1p 20927 032
- B310260048 Ack receipt of 650719 ltr informing of Cs-137 source rupture
PAGE, R Q Atomic Energy Commission 65/07/28 COOK, H L Dhmart Corp 1p 20927 033
- B310260051 Discusses telcon w/W Kerr re L&R definition of developing, testing, distribution & demonstrating at Dhmart Corp
Permission to rent byproduct matl contained gauges to customers questioned
RADELOFF, W A Atomic Energy Commission 63/07/17 Atomic Energy Commission 1p 20927 034
- B310260052 Forwards telegram from Region III re personnel exposure under License 34-00639-01 w/o encl
MILLER, M R Atomic Energy Commission 65/11/12 PAGE, R Q Atomic Energy Commission 1p 20927 035
- B310260055 Discusses telcon w/RQ Cavanaugh re issuance of License 34-00639-01 concerning rental of byproduct matl contained in gauges
RADELOFF, W A Atomic Energy Commission 63/07/17 Atomic Energy Commission 1p 20927 036
- B310260056 Comments on 660426 ltr from Dhmart Corp reporting overexposure of employee Region III will investigate matter during next insp
ALLAN, J M Atomic Energy Commission 66/04/28 Atomic Energy Commission 1p 20927 037
- B310260059 Discusses telcon w/RQ Cavanaugh re status of Region I investigation concerning Dhmart Corp transfer of 1,000 mCi Sr-90 beta gauge to AVCO Corp
RADELOFF, W A Atomic Energy Commission 63/07/17 Atomic Energy Commission 1p 20927 038
- B310260062 Forwards 630626 memos from Region I w/results of investigation at Dhmart Corp & requests addl investigation w/o encl
DUDINSKI, L Atomic Energy Commission 63/07/05 PRICE, E R Atomic Energy Commission 1p 20927 039
- B310260065 Ack receipt of 661027 ltr reporting overexposure of employee to radiation
PRICE, E R Atomic Energy Commission 66/11/09 KING, J H Dhmart Corp 1p 20927 040
- B310260067 Requests NRC withdrawal of matl attached to 630703 ltr addressed to R Cunningham Matters clarified & acceptable plan of action finalized at 631218 meeting in Bethesda, MD
COOK, H L Dhmart Corp 63/12/31 PRICE, E R Atomic Energy Commission 1p 20927 041
- B310260070 Comments on 661121 telcon w/D Griffin to rept stolen 50 uCi radium source in steel capsule on 661118 Police notified
HAPP, E T Atomic Energy Commission 66/11/21 Atomic Energy Commission 1p 20927 042
- B310260072 Ack receipt of 631231 ltr re 631218 meeting concerning authorization of installation of equipment containing byproduct matl only by employees of Dhmart Corp
PRICE, E R Atomic Energy Commission 64/01/29 COOK, H L Dhmart Corp 2pp 20927 043
- B310260076 Comments on 661121 telcon w/J Peterson re 05 uCi Sr-90, 50 uCi radium & 05 uCi Cs-137 sources stolen from D Griffin car Matter referred to police
ALLAN, J M Atomic Energy Commission 66/11/23 Atomic Energy Commission 2pp 20927 045
- B310260077 Discusses 640626 telcon w/H Baldwin re lost Co-60 source at Dhmart Corp
ALLAN, J M Atomic Energy Commission 64/06/26 Atomic Energy Commission 1p 20927 047
- B310260081 Informs of plans to investigate lost 20 uCi Co-60 source from License 34-00639-01 site
ROY, G W Atomic Energy Commission 64/06/26 Atomic Energy Commission 1p 20927 048
- B310260084 Discusses 640626 telcon w/HA Radloff re lost 20 uCi Co-60 source from Dhmart Corp Dump & city incinerator will be surveyed on 640626
MILLER, M R Atomic Energy Commission 64/06/29 Atomic Energy Commission 1p 20927 049
- B310260087 Comments on 670515 telcon w/HL Cook re corrective steps taken concerning 670426 insp Portion of tag on gauge w/ combination will attach to manual & packing slip
FOSTER, D L Atomic Energy Commission 67/05/17 Atomic Energy Commission 1p 20927 050
- B310260090 Forwards 670413 ltr from United Kingdom Ministry of Transport describing 670223 release of radioactive matls on SB American Press Investigation of involvement of Dhmart Corp requested
BYRD, H K Transportation, Dept of 67/05/10 BECK, C K Atomic Energy Commission 3pp 20927 051
- B310260093 Comments on 670519 telcon w/AJ Stevens to arrange joint investigation of compliance of Dhmart Co concerning break up of shipping containers during shipments to United Kingdom
FOSTER, D L Atomic Energy Commission 67/05/19 Atomic Energy Commission 1p 20927 056
- B310260095 Responds to 670510 request for joint investigation of radioactive matl packaging practices of Dhmart Corp
Investigation planned for wk of 670605
BECK, C K Atomic Energy Commission 67/05/25 BYRD, H K Transportation, Dept of 1p 20927 057
- B310260099 Forwards 640626 memo re lost source at Dhmart Corp Rept of 640629 investigation in preparation
RADELOFF, W A Atomic Energy Commission 64/07/06 Atomic Energy Commission 1p 20927 058
- B310260100 Forwards investigation rept dtd 640710 of Dhmart Corp, License 34-00639-01 w/o encl
ALLAN, J M Atomic Energy Commission 64/07/24 ROEDER, J Atomic Energy Commission 1p 20927 061
- B310260102 Submits matter to be reviewed during next insp re high exposure during Fourth Quarter 1973, per 731229 ltr
NOELIUS, C E Region 3, Chicago, Office of the Director 74/02/04 Region 3, Chicago, Office of the Director 1p 20927 089
- B310260105 Informs of loss of 20 uCi Co-60 sealed source on 640601
Caused by inadvertently leaving source in storage box left w/trash collection Procedure for authorizing discard of boxes changed
COOK, H L Dhmart Corp 64/07/15 Atomic Energy Commission 2pp 20927 062
- B310260107 Notifies of employee overexposure to radiation based on 1973 film badge rept Overexposure occurred while handling variety of Cs-137 sealed sources. Employee reassigned jobs not handling radiation sources Info deleted
KING, J H Dhmart Corp 73/12/29 Atomic Energy Commission, Directorate of Regulatory Operations 2pp 20927 090
- B310260108 Discusses 640626 telcon w/HL Cook from Dhmart Corp reporting lost 20 uCi Co-60 sealed source McCarthy & Baenger from Cincinnati General Hosp will attempt to locate source in city dump & incinerator.
ROY, G W Atomic Energy Commission 64/06/26 Atomic Energy Commission 2pp 20927 059.
- B310260111 Forwards 640724 memo re investigation rept dtd 640710 of Dhmart Corp & 640715 ltr reporting lost source w/o encl
ROEDER, J R Atomic Energy Commission 64/07/31 PAGE, R Q Atomic Energy Commission 1p 20927 064

NONDOCKETED ITEMS

- B310260112 Submits matter to be reviewed re rept of high film badge in Ohmart 741021 ltr Info deleted
NORELIUS, C E Region 3, Chicago, Office of the Director
74/11/06 Region 3, Chicago, Office of the Director 2pp
20927 092
- B310260115 Discusses insp of Licenses 34-00639-01 & 34-00639-02 on 640612, 19 & 29 Noncompliance noted byproduct matl sealed sources not leak tested at intervals of 6 months or less & lead container not properly labeled
PRICE, E R Atomic Energy Commission 64/08/06 OHMART, P E
Ohmart Corp 2pp 20927 063
- B310260116 Advises of overexposure of employee to radiation per Sept 1974 film badge rept Overexposure occurred while handling variety of Cs-137 sealed sources Employee reassigned to jobs not involving handling of radiation sources Info deleted
KING, J H Ohmart Corp 74/10/21 Atomic Energy Commission,
Directorate of Regulatory Operations 1p 20927 094
- B310260119 Submits matter to be reviewed re high film badge exposure reported in Ohmart 750122 ltr
NORELIUS, C E Region 3, Chicago, Office of the Director
75/01/27 Region 3, Chicago, Office of the Director 1p
20927 095
- B310260120 Informs that 670517 memo route slip provided details re package failure of several containers of radioactive matl enroute to United Kingdom from Ohmart Corp Region III will visit Ohmart w/DOE on 670603, per request
PHILLIP, G A Atomic Energy Commission 67/06/01 Atomic Energy
Commission 1p 20927 067
- B310260121 Responds to 640806 ltr re noncompliance noted in Licenses 34-00639-01 & 34-00639-02 Corrective actions administrative procedure changes will be initiated within 60 days
COOK, H L Ohmart Corp 64/08/20 PRICE, E R Atomic Energy
Commission 1p 20927 068
- B310260124 Advises of employee overexposure to radiation based on Dec 1974 film badge rept Overexposure occurred while handling variety of Cs-137 sealed sources Employee reassigned to jobs not involving radiation sources Info deleted
KING, J H Ohmart Corp 75/01/22 Atomic Energy Commission,
Directorate of Regulatory Operations 2pp 20927 096
- B310260125 Informs that no noncompliance noted during 670605 investigation at Ohmart Corp re failure of radioactive matl packaging during shipping Enforcement action inappropriate
HANDLER, R Atomic Energy Commission 67/06/30 Atomic Energy
Commission 1p 20927 069
- B310260126 Ack receipt of 640820 ltr informing of corrective actions re matters described in 640806 notice concerning Licenses 34-00639-01 & 34-00639-02
PRICE, E R Atomic Energy Commission 64/08/27 COOK, H L Ohmart
Corp 1p 20927 070
- B310260127 Forwards rept of investigation w/DOE re packaging of radioactive matl lost at sea Matter considered closed
DUBINSKI, L Atomic Energy Commission 67/07/06 BECK, C K
Atomic Energy Commission 1p 20927 071
- B310260128 Submits matter to be reviewed during next insp re high film badge exposure per Ohmart Corp 750430 ltr
* Region 3, Chicago, Office of the Director 75/02/26 Region
3, Chicago, Office of the Director 1p 20927 098
- B310260129 Requests response to 640827 ltr re corrective actions of matters described in 640806 notice concerning Licenses 34-00639-01 & 34-00639-02
PRICE, E R Atomic Energy Commission 64/11/28 COOK, H L Ohmart
Corp 1p 20927 079
- B310260130 Comments on joint investigation of shipping damage to Ohmart radioactive matl package inadequacy of cover-plate flange bolts indicates need for more substantive packaging design criteria
BECK, C K Atomic Energy Commission 67/07/08 BYRD, W K
Transportation, Dept of 1p 20927 074
- B310260131 Ack receipt of 671127 ltr reporting exposure of individuals to radiation, Administrative change noted
LOW, L D Atomic Energy Commission, 67/12/11 COOK, H L Ohmart
Corp 1p 20927 075
- B310260132 Advises of employee overexposure to radiation based on Mar 1975 film badge rept Overexposure occurred while handling various Cs-137 sealed sources Employee reassigned to jobs not involving radiation Info deleted
KING, J H Ohmart Corp 75/04/30 Atomic Energy Commission,
Directorate of Regulatory Operations 3pp 20927 099
- B310260133 Responds to 641125 request for followup rept on corrective actions per 640806 notice Wipe test interval sys data will be placed on addressograph plates
COOK, H L Ohmart Corp 64/12/11 PRICE, E R Atomic Energy
Commission 2pp 20927 080
- B310260135 Comments on 671215 telcon w/L Cook re 671127 ltr concerning 10CFR20 103(b)(1) & (2) interpretations Ltr will be sent to Washington, DC for evaluation
FOSTER, D L Atomic Energy Commission 67/12/15 Atomic Energy
Commission 1p 20927 076
- B310260136 Advises that on 750630, employee film badge recorded overexposure to radiation Addl info will be forwarded when obtained
KELLY, G Ohmart Corp 75/06/30 LANERGAN, G T Region 3,
Chicago, Office of the Director 5pp 20927 102
- B310260137 Ack receipt of 641211 ltr responding to NRC 640827 & 1125 ltrs re fourth & final enforcement
PRICE, E R Atomic Energy Commission 64/12/17 COOK, H L Ohmart
Corp 1p 20927 082
- B310260138 Advises of 681220 telcon w/E Giebel re discovery of Ohmart Corp label & radiation sign on street in Cincinnati, OH on 681209 Person finding label sustained no radiation exposure
ALLAN, J M Atomic Energy Commission 68/12/27 ROEDER, J R
Atomic Energy Commission 2pp 20927 077
- B310260139 Comments on 750630 telcon w/OT LanerGAN re employee overexposure to radiation, based on June 1975 film badge rept Film badge may be invalid due to employee exposure to dentil x-rays Info deleted
LANERGAN, G T Region 3, Chicago, Office of the Director
75/06/30 Region 3, Chicago, Office of the Director 1p
20927 112
- B310260140 Forwards 650609 telegram from Region III re 650608 containment incident
ROEDER, J R Atomic Energy Commission 65/06/11 PAGE, R G
Atomic Energy Commission 1p 20927 083
- B310260142 Comments on 770223 telcon w/F Klein re complaint from former Ohmart employee concerning incorrect training & practices while working w/radiation sources Info deleted
PHILLIP, G A Region 3, Chicago, Office of the Director 77/03/09
Region 3, Chicago, Office of the Director 5pp 20927 107
- B310260144 Ack receipt of 770526 & 0617 ltrs informing NRC of steps taken to correct noncompliance identified in 770511 ltr
ROY, G W Division of Fuel Facility & Materials Safety 77/07/28
COOK, H L Ohmart Corp 1p 20927 113
- B310260146 Responds to 770511 ltr re calculated dose received by personnel from Oct 1976 - Mar 1977, training program & source handling procedures Trainees will be subj to verbal exam
COOK, H L Ohmart Corp 77/05/26 THOMPSON, D Office of
Inspection & Enforcement, Office of the Director 3pp 20927 114
- B310260149 Suppl 770414, 0512 & 26 ltrs re noncompliance concerning handling unshielded sources & exposure of individuals to radiation Info deleted
COOK, H L Ohmart Corp 77/06/17 THOMPSON, D Office of
Inspection & Enforcement, Office of the Director 24pp
20927 117
- B310260153 Comments on 690326 telcon w/G Kelley re lost shipment of 100 mCi Pb-210 source sent to Memorex Corp from Ohmart Corp Rept will be given to US Public Health Bvc in Chicago & Cincinnati if TWA can not locate shipment
ALLAN, J M Atomic Energy Commission 69/04/04 ROEDER, J R
Atomic Energy Commission 2pp 20927 072
- B310260155 Ack receipt of rept submitted per 10CFR20 403, received on 791203
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/12/28
DIRLING, F N Ohmart Corp 1p 20927 142
- B310260157 Discusses 690626 insp of License 34-00639-01 re leaking 0.5 mCi Cs-137 source Removable contamination found when source leak tested on 690612
ALLAN, J M Atomic Energy Commission 69/07/25 ROEDER, J R
Atomic Energy Commission 1p 20927 084
- B310260158 Informs of 690429 receipt of sealed source w/removable contamination in excess of 0.05 uCi Vial cap & filter paper replaced
KELLY, G A Ohmart Corp 69/06/26 Atomic Energy Commission
1p 20927 085

NONDOCKETED ITEMS

433

- B310260159 Advises that on 800220, personnel drilling through steel source housing inadvertently ruptured 100 mCi Cs-137 radioactive source. Caused by improper procedure. Personnel & area decontaminated & new procedures developed.
DERLING, F. N. Ohmart Corp 80/03/28 KEPLER, J. G. Region 3, Office of Director 15pp 20927 160
- B310260161 Discusses 681120 memo re State of FL problems w/ unauthorized individuals installing generally licensed gauges distributed by Ohmart Corp. Ohmart not advising customers of requirement info deleted.
ALLAN, J. M. Atomic Energy Commission 68/11/29 ROEDER, J. R. Atomic Energy Commission 3pp 20927 177
- B310260162 Ack receipt of 690626 ltr informing of leak test revealing presence of removable contamination on Cs-137 source.
ROEDER, J. R. Atomic Energy Commission 69/07/09 KELLY, G. A. Ohmart Corp 1p 20927 086
- B310260163 Responds to 721004 ltr re items of noncompliance noted in 720913-14 insp. Corrective actions addl safes obtained for storage of sealed sources & leak test forms issued to supervisors responsible for leak tests.
KELLY, G. A. Ohmart Corp 72/10/23 GRIER, B. H. Region 3, Chicago Office of the Director 2pp 20927 087
- B310260164 Informs of RF Warnick 800221 telcon w/ individual expressing concern re friend employed by Ohmart Corp. Friend drilled into radioactive source & was contaminated. Info deleted.
PHILLIP, G. A. Region 3, Office of Director 80/03/07 Region 3, Office of Director 1p 20927 180
- B310260165 Ack receipt of 721023 ltr informing AEC of steps taken to correct items of noncompliance noted in insp of Licenses 34-00639-01, 34-00639-030 & SNM-1091.
GRIER, B. H. Region 3, Chicago, Office of the Director 72/11/02 KELLY, G. A. Ohmart Corp 1p 20927 181
- B310260167 Informs that 690626 reinsp revealed Dec 1968 leak test of 40 mCi Cd-109 sealed source indicated leaking source. Supplier repaired source & returned source to Ohmart on 690510. No further leakage noted.
ALLAN, J. M. Atomic Energy Commission 69/07/25 ROEDER, J. R. Atomic Energy Commission 1p 20927 196
- B310260168 Ack receipt of 730202 ltr Transfer of devices not specifically authorized for transfer to general licensees under License 34-00639-030 may result in noncompliance w/ regulations.
DIANNELLI, J. M. Atomic Energy Commission, Directorate of Licensing 73/02/14 KELLY, G. A. Ohmart Corp 2pp 20927 182
- B310260169 Notifies that Dec 1968 leak test of 40 mCi Cd-109 sealed source revealed 0.0018 uCi removable contamination. Capsule repaired.
KELLY, G. A. Ohmart Corp 69/07/08 Atomic Energy Commission 1p 20927 197
- B310260170 Advises of shipment of Model CL-30 Cs-137 gauge to customer prior to NRC approval of request for amend to License 34-00639-030.
KELLY, G. A. Ohmart Corp 73/02/02 MALARD, J. Atomic Energy Commission, Directorate of Licensing 2pp 20927 184
- B310260171 Ack receipt of 690708 ltr reporting detection of removable contamination on Cd-109 source.
ROEDER, J. R. Atomic Energy Commission 69/07/24 KELLY, G. A. Ohmart Corp 1p 20927 198
- B310260172 Application to amend License 34-00639-030, changing design of Model CS gauges to incorporate detector housing revs Model CX detector housing replaced w/ Model EX-1(S) detector housing.
KELLY, G. A. Ohmart Corp 73/02/02 MALARD, J. Atomic Energy Commission, Directorate of Licensing 2pp 20927 186
- B310260173 Advises of 700126 receipt of 25 mCi Co-60 sealed sources w/ removable contamination in excess of 0.05 uCi. Container returned to Gamma Industries on 700211.
KELLY, G. A. Ohmart Corp 70/02/25 Atomic Energy Commission 1p 20927 199
- B310260174 Ack receipt of 731229 ltr reporting exposure of individual to radiation during Fourth Quarter 1973.
DAVIS, J. Q. Atomic Energy Commission, Directorate of Regulatory Operations 74/01/11 KING, J. H. Ohmart Corp 1p 20927 188
- B310260175 Forwards 740521 ltr from State of CA & NRC 740604 reply Inquiry into Ohmart Corp practices re installation of generally licensed devices requested.
BLANC, G. A. Atomic Energy Commission, Directorate of Licensing 74/06/07 THORNBURG, H. D. Atomic Energy Commission, Directorate of Regulatory Operations 1p 20927 189
- B310260176 Informs that on 700202 leak test of Co-60 source revealed 0.01 uCi removable contamination & 0.025 uCi contamination on interior of shipping container.
ALLAN, J. M. Atomic Energy Commission 70/03/04 ROEDER, J. R. Atomic Energy Commission 1p 20927 200
- B310260177 Responds to 740521 ltr re practices concerning installation of generally licensed devices w/ respect to Ohmart Corp, distinction must be made between device being placed in svc & being installed.
BLANC, G. A. Atomic Energy Commission, Directorate of Licensing 74/06/07 PICKLER, D. A. California, State of 1p 20927 190
- B310260178 Ack receipt of 700225 ltr informing of detection of removable contamination on Co-60 source.
ROEDER, J. R. Atomic Energy Commission 70/03/12 KELLY, G. A. Ohmart Corp 1p 20927 201
- B310260180 Requests info re obligations of distributor of devices under G-type license, per 10CFR32.51 to ensure that device distributed as generally licensed installed by authorized licensee Ohmart Corp policy listed.
PICKLER, D. A. California, State of 74/05/21 BLANC, G. A. Atomic Energy Commission 1p 20927 191
- B310260182 Informs of 710513 telcon w/ Kelly re loss of two 1 uCi Br-90 sealed sources. Sources possibly fell on floor & swept away to city incinerator.
ALLAN, J. M. Atomic Energy Commission 71/05/28 ROY, G. W. Atomic Energy Commission 2pp 20927 202
- B310260183 Responds to 711210 ltr re interpretation of installation used in 10CFR31.5 concerning installation of licensed devices by authorized person.
HARLESS, B. L. Atomic Energy Commission 72/01/03 WARD, J. O. California, State of 2pp 20927 192
- B310260184 Notifies of loss of two 1 uCi sealed sources on 710512. Sources possibly sent to incinerator in trash search continuing.
KELLY, G. A. Ohmart Corp 71/05/12 ALLAN, J. M. Atomic Energy Commission 1p 20927 204
- B310260185 Comments on interpretation of "install" used in 10CFR31.5(b)(2), per recent NRC ltr re License 12-11184-020. Authorized person must be physically present & supervise installation.
WARD, J. O. California, State of 71/12/10 HARLESS, B. L. Atomic Energy Commission 2pp 20927 194
- B310260188 Notifies of loss of two 1 uCi sealed sources on 710512. Sources possibly sent to incinerator in trash search continuing.
KELLY, G. A. Ohmart Corp 71/09/19 ALLAN, J. M. Atomic Energy Commission 1p 20927 205
- B310260191 Forwards Mobil Chemical Co 710521 & State of FL Dept of Health 710528 ltrs re Ohmart Corp transfer of Cs-137 density gauges to unauthorized recipient.
HANDLER, R. Atomic Energy Commission 71/06/02 ALLAN, R. Atomic Energy Commission 3pp 20927 206
- B310260193 Submits program for correcting apparent mislabeling of certain devices distributed to general licensees under Condition 11A of License 34-00639-030. Authorization to use label, Part 38-21335 in progress.
KELLY, G. A. Ohmart Corp 74/10/31 ALLAN, J. M. Atomic Energy Commission, Directorate of Licensing 2pp 20927 212
- B310260195 Advises of 710512 loss of two 1 uCi Br-90 sources. Radioactive matl mistaken for small pieces of wire considered trash. 3M Co will separately package & label each source in sealed vial.
KELLY, G. A. Ohmart Corp 71/06/10 Atomic Energy Commission 2pp 20927 209
- B310260197 Forwards Amend 5 to License 34-00639-030 Amend omits provision in Condition 17(c)(3), per 10CFR31.5(d)(4), re svcs involving radioactive matl performed by authorized person w/o encl.
DIANNELLI, J. M. Atomic Energy Commission, Directorate of Licensing 73/04/18 KELLY, G. A. Ohmart Corp 1p 20927 214

NONDOCKETED ITEMS

- B310260199 Ack receipt of 710610 ltr reporting loss of two 1 uCi Sr-90 sources
LOW, L D Atomic Energy Commission 71/07/08 KELLY, G A Ohmart Corp 1p 20927 211
- B310260204 Advises of amend to License 34-00639-030 to reflect current requirements re labeling of devices to be distributed to general licensees under 10CFR31.5 Related info encl
BELL, J M Atomic Energy Commission, Directorate of Licensing 74/10/02 KELLY, J A Ohmart Corp 5pp 20927 215
- B310260207 Discusses insp of License 34-00639-030 on 741015 & forwards notice of violation
ALLAN, J M Region 3, Chicago, Office of the Director 75/01/23 COOK, H L Ohmart Corp 2pp 20927 220
- B310260210 Notice of noncompliance from insp of License 34-00639-030 on 741015 Noncompliance noted seven devices distributed under license in 1974 not labeled to indicate AEC or Agreement State requirements met
* Region 3, Chicago, Office of the Director 75/01/23 1p 20927 222
- B310260213 Comments on 741015 insp of License 34-00639-030 re distribution & installation of generally licensed gauges Ohmart makes distinction between "place in svc" & "installation" for generally licensed devices
ALLAN, J M Region 3, Chicago, Office of the Director 75/01/19 THORNBURO, H D Atomic Energy Commission, Directorate of Regulatory Operations 4pp 20927 223
- B310260218 Submits instructions for review of unauthorized transfer during insp
* Region 3, Chicago, Office of the Director 76/05/10 Region 3, Chicago, Office of the Director 1p 20927 227
- B310260223 Informs of erroneous distribution of Model BQCD-90 gauge to License 12-02032-01 before application to amend license for shipment added to License 34-00639-030 Model now added to license
KELLY, G A Ohmart Corp 76/04/15 BASSIN, N Radioisotopes Licensing Branch (Pre 790501) 1p 20927 228
- B310260226 Forwards ltr received from Ohmart Corp re installation of gauge at Joanna Western Mills Co Device installed prior to authorization for distribution to general licensees w/o encl
BINGER, B Radioisotopes Licensing Branch (Pre 790501) 76/04/29 ROY, G W Office of Inspection & Enforcement, Office of the Director 1p 20927 229
- B310260229 Forwards external ltrs dtd 760311, 0608 & 1013 between State of AL & Ohmart Corp re svc & installation of specifically licensed devices by Ohmart Ltrs discuss lack of personnel monitoring equipment, survey meter & operating procedures
KERN, G W Assistant Director for State Agreements Programs 76/11/10 ROY, G W Office of Inspection & Enforcement, Office of the Director BINGER, B Radioisotopes Licensing Branch (Pre 790501) 8pp 20927 230
- B310260234 Forwards draft order to suspend source handling & loading operations under License 34-00639-01 Order based on employee overexposure while handling sealed sources of various radioactive matls in gauges Addl investigations planned
KEPPLER, J G Region 3, Chicago, Office of the Director 77/04/06 THOMPSON, D Office of Inspection & Enforcement, Office of the Director 6pp 20927 238
- B310260238 Responds to 770407 order suspending License 34-00639-01 Procedures to reduce overexposure while handling radioactive sources listed
COOK, H L Ohmart Corp 77/04/14 VOLGENAU, E Office of Inspection & Enforcement, Office of the Director 14pp 20927 244
- B310260240 Order to show cause & order suspending License 34-00639-01 based on employee overexposure while handling sealed sources of various radioactive matls
VOLGENAU, E Office of Inspection & Enforcement, Office of the Director 77/04/07 Ohmart Corp 7pp 20927 258
- B310260243 Forwards draft ltr detailing results of insp disclosing three items of noncompliance, including overexposure Order to show cause & order suspending license issued to Ohmart on 770407 re violation of source handling activities
NORRELIUS, C E Region 3, Chicago, Office of the Director 77/05/03 ELLIS, W P Office of Inspection & Enforcement, Office of the Director 8pp 20927 265
- B310260250 IE Insp Repts 70-1144/77-01, 30-05634/77-01 & 30-05635/77-01 on 770330-0401 & 11-12 Noncompliance noted individual received overexposure while handling licensed matl & no evaluation made of extremity exposure
SCHULTZ, W H, PHILLIP, G A, LONERGAN, G T Region 3, Chicago, Office of the Director 30-5635/77-01 77/05/04 17pp 20927 273
- B310260252 Order reinstating License 34-00639-01 due to full, effective & prompt correction of violations
VOLGENAU, E Office of Inspection & Enforcement, Office of the Director 77/04/18 Ohmart Corp 1p 20927 290
- B310260258 Advises that review of records & procedures to refine doses reveal percentage of personnel receiving calculated overexposure to hands same as reported in 770414 ltr Arrangements made w/local hosp to examine employees
COOK, H L Ohmart Corp 77/05/12 VOLGENAU, E Office of Inspection & Enforcement, Office of the Director 1p 20927 291
- B310260265 Discusses IE Insp Repts 70-1144/77-01, 30-05634/77-01 & 30-05635/77-01 on 770330-0401 & 11-12 Ltr & insp rept will be placed in PDR unless licensee believes portions are proprietary & should be withheld
KEPPLER, J G Region 3, Chicago, Office of the Director 77/05/11 COOK, H L Ohmart Corp 2pp 20927 292
- B310260271 Repts receipt of shipment w/container exceeding 230 MR/MR at surface due to shifing of container inside larger cardboard box Shipper & carrier notified
LIVINGSTON, A J Ohmart Corp 77/05/23 SCHULTZ, B Region 3, Chicago, Office of the Director 1p 20927 311
- B310260275 Discusses 770523 telcon w/AJ Livingston reporting receipt of Co-137 package exceeding Part 20 limits Condition due to lead container shifting in larger cardboard box during shipment
SCHULTZ, W H Region 3, Chicago, Office of the Director 77/05/23 Region 3, Chicago, Office of the Director 1p 20927 312
- B310260278 Confirms 770609 telcon re time extension in providing info concerning exposure of Ohmart personnel to industrial radiation sources Exam indicates no evidence of radiation injury
BAENDER, E L Univ of Cincinnati Medical Ctr, Cincinnati, OH 77/06/09 ALLAN, J Region 3, Chicago, Office of the Director 1p 20927 313
- B310260280 Ack receipt of 780323 ltr reporting receipt of leaking sources & resultant contamination of several tools discovered on 780320 Performance of cleanup operation on tools & return of sources to supplier also ack
PAOLARO, J A Region 3, Chicago, Office of the Director 78/04/10 LIVINGSTON, A J Ohmart Corp 2pp 20927 314
- B310260282 Informs that on 780320, wipe test of Co-60 source, received from Gamma Industries on 771227, revealed presence of 02 uCi removable contamination Subsequently, wipe of tools, equipment & employees revealed between 001- 005 uCi contamination
LIVINGSTON, A J Ohmart Corp 78/03/23 NRC - No Detailed Affiliation Given 2pp 20927 316
- B310260287 Discusses insp of Licenses SNM-1091, 34-00639-01 & 34-00639-030 on 770330-0401 & 11-12 & forwards notice of violation
THOMPSON, D Office of Inspection & Enforcement, Office of the Director 77/05/11 COOK, P L Ohmart Corp 3pp 20927 318
- B310260288 Notice of violation from insp on 770330-0401 & 11-12 Noncompliance noted licensee used licensed matl in manner as to cause individuals in restricted area to receive whole body dose in excess of 125 rems in calendar quarter
* Atomic Energy Commission 77/05/11 3pp 20927 321
- B310260295 Forwards comparison of four highest exposures during Apr insp & first 2 months of third & fourth quarters Badges U3 & P5 received readings minimal in wks time since Landover repts less than 10 mr gamma, 40 mr beta & 20 mr neutron
LIVINGSTON, A J Ohmart Corp 78/01/11 VOLGENAU, E Office of Inspection & Enforcement, Office of the Director 2pp 20927 324
- B310260298 Responds to 791217 ltr Forwarding insp rept re shipment of radioactive matls, arriving at Ohmart Corp w/excessive surface radiation level readings w/o stated correspondence to Baltimore, MD ofc requesting investigation
MCANDREW, A R Transportation, Dept of, Federal Highway Administration, HMC-11 1 80/01/04 KEPPLER, J G Region 3, Office of the Director 1p 20927 336

NONDOCKETED ITEMS

435

- B310260300 Telecopy ltr informing that on 800220, personnel drilling through steel source housing inadvertently ruptured radioactive source containing 100 mCi insoluble radioactive Cs-137 source Area & personnel decontaminated
DIRLING, F M Ohmart Corp 83/07/15 WIEDEMAN, D NRC - No Detailed Affiliation Given 1p 20927 346
- B310260303 Notifies that in Nov 1979, Ohmart inadvertently shipped one Weight ART 4100 Series scale to Kaiser Cement Corp in CA Caused by misinterpretation of license which authorizes possession of one scale Future shipments to be approved
DIRLING, F M Ohmart Corp 80/05/13 SCHULTZ, B Region 3, Office of Director 1p 20927 347
- B310260317 Notifies that some time in Dec 1981, Ohmart Corp inadvertently transferred gauges labeled Densart Series 300, SH-100, Cs-137 & 50 mCi to Fiberboard Corp Transfer not per NRC regulations for stated reasons Related info encl
FRANKASZEK, J J California, State of 82/04/13 Region 3, Office of Director 4pp 20927 360
- B310260321 Forwards B20316 ltr from Static Control Sys 3M explaining that sealed source capsule received by Ohmart had surface contamination exceeding allowable limit Source has contaminated weld Matter closed
COOK, H L Ohmart Corp 82/03/24 Region 3, Office of Director 3pp 20928 001
- B310260325 Discusses 650609 telcon w/JM Allan reporting contamination incident occurring at Ohmart Corp on 650608 Incident occurred during unloading of Cs-137 sealed source from gauge Employee urine samples recommended Info deleted
ROEDER, J R Atomic Energy Commission 65/06/10 Atomic Energy Commission 1p 20928 004
- B310260327 Lists info discussed w/D Foster during 650610 telcon re Cs-137 contamination Info deleted
ALLAN, J M Atomic Energy Commission 65/06/10 Atomic Energy Commission 1p 20928 005
- B310260329 Repts leaking Cs-137 source on 650608, resulting in spill & contamination of facilities & personnel Facility & personnel decontaminated Info deleted
ALLAN, J M Atomic Energy Commission 65/06/09 ROEDER, J R Atomic Energy Commission 3pp 20928 006
- B310260332 Discusses 650609 telcon w/HL Cook re spill from Cs-137 source, removed from Model SHRM holder, which contaminated personnel & facilities Facility & personnel decontaminated Info deleted
ROY, G W Atomic Energy Commission 65/06/09 Atomic Energy Commission 2pp 20928 009
- B310260337 Lists questions & responses from 650609 telcon w/L Cook re Cs-137 contamination Info deleted
ALLAN, J M Atomic Energy Commission 65/06/09 Atomic Energy Commission 2pp 20928 011
- B310260338 Discusses 651108 telcon w/HL Cook re film badge rept indicating overexposure of Ohmart employee Overexposure occurred while working w/300 Sr-90 source Info deleted
ROY, G W Atomic Energy Commission 65/11/08 Atomic Energy Commission 2pp 20928 013
- B310260341 Discusses 651109 telcon w/RS Laudauer re film badge appearing to have been exposed to low energy radiation No evidence on film of damage, contamination or routine reasons for erroneous results Info deleted
ROY, G W Atomic Energy Commission 65/11/09 Atomic Energy Commission 1p 20928 015
- B310260345 Repts exposure of Ohmart personnel to two 300 mCi Sr-90 sources during wk of 651025 Processor requested to reinterpret film Info deleted
ALLAN, J M Atomic Energy Commission 65/11/09 ROEDER, J R Atomic Energy Commission 2pp 20928 016
- B310260347 Repts personnel film badge reading of 49 37 rem beta & 1 28 rem gamma Possible exposure obtained while experimenting w/ 300 mCi Sr-90 Info deleted
COOK, H L Ohmart Corp 65/11/09 Atomic Energy Commission 2pp 20928 018
- B310260351 Forwards telecopy ltr reporting exposure of Ohmart employee w/o encl Info deleted
MILLER, H R Atomic Energy Commission 65/11/12 PAGE, R O Atomic Energy Commission 1p 20928 020
- B310260334 Notifies that Ohmart Corp 651130 ltr reporting high film badge exposure not placed in PDR as incident not reportable per 10CFR20.405 Individual exposure to radioactive matl in excess of limit doubtful
HANDLER, R Atomic Energy Commission 65/12/08 Atomic Energy Commission 1p 20928 021
- B310260336 Ack receipt of 651130 ltr reporting high film badge exposure
PRICE, E R Atomic Energy Commission 65/12/08 COOK, H L Ohmart Corp 1p 20928 022
- B310260339 Advises that film badge of employee indicated exposure of 49 37 rem beta & 1 28 rem gamma while handling two 300 mc Sr-90 sources Technician did not receive same exposure as film badge indicated Info deleted
COOK, H L Ohmart Corp 65/11/30 Atomic Energy Commission 3pp 20928 023
- B310260361 Ack receipt of 660426 ltr reporting exposure of employee to radiation
PRICE, E R Atomic Energy Commission 66/03/04 KING, J H Ohmart Corp 1p 20928 026
- B310260366 Advises of employee radiation exposure for First Quarter 1966 film badge rept Employee received radiation while handling various quantities of Cs-137 sealed sources Info deleted
KING, J H Ohmart Corp 66/04/26 Atomic Energy Commission 3pp 20928 027
- B310260372 Advises that 661027 rept of personnel overexposure will be reviewed during next insp Info deleted
ALLAN, J M Atomic Energy Commission 66/10/31 Atomic Energy Commission 2pp 20928 030
- B310260374 Notifies of employee overexposure to radiation in Third Quarter 1966 Radiation occurred while handling gauges containing Cs-137 sealed source Info deleted
KING, J H Ohmart Corp 66/10/27 Atomic Energy Commission 2pp 20928 032
- B310260378 Ack receipt of 671127 ltr informing AEC of steps taken to correct noncompliance noted in 671108 ltr & Form AEC-392 w/o stated encl
ORIER, B H Atomic Energy Commission 67/12/18 COOK, H L Ohmart Corp 1p 20928 034
- B310260384 Advises that rept to Commission re apparent overexposure to employees mailed on 671127 Notice mailed to employee on 671127
COOK, H L Ohmart Corp 67/11/27 Atomic Energy Commission 1p 20928 035
- B310260388 Advises of failure to rept two overexposures to personnel due to misunderstanding & oversight Individuals no longer employed by licensee Info deleted
COOK, H L Ohmart Corp 67/11/27 Atomic Energy Commission 2pp 20928 036
- B310260394 Advises of expansion of educational programs & rev to administrative procedures to assure personnel do not receive overexposure to radiation Preliminary wipe test procedure encl
COOK, H L Ohmart Corp 67/11/27 BRIER, B H Atomic Energy Commission 3pp 20928 038
- B310270011 Addl response to FOIA request for four documents re TMI restart & SECY-B3-98B & SECY-B3-98D Items 1, 2, 4 & 5 encl Item 3 included within Item 2 Review of Item 6 incomplete
FELTON, J M Division of Rules and Records 83/07/15 DANIELSON, L M MHB Technical Associates 1p 20940 309 24X Fiche 50-289, 83/07/15, B310270011
- B310270020 Responds to FOIA request for BJ Chilk B30413 memo to WJ Dirchs re alternate plans for test facility accreditation
Forwards document
FELTON, J M Division of Rules and Records 83/07/18 LEAVEY, M E Stone & Webster, Inc 1p 20943 123
- B310040261 Marked-up memo informing that Commission decided not to issue notice of proposed rulemaking on accreditation of qualification testing organizations Specific alternative actions provided
CHILK, B J Office of the Secretary of the Commission, 83/04/13 DIRCKS, W J Office of the Executive Director for Operations 3pp 20943 125

NONDOCKETED ITEMS

- 8310270027 Responds to FOIA request for info re licensed medical institutions & private physicians in State of PA Forwards computer printout W/o encl
FELTON, J M Division of Rules and Records 83/07/15 GOULDIN, J A Williamsport Hosp Williamsport, PA 1p 20940 342
- 8310270031 FOIA request for list of private physicians licensed in State of PA
GOULDIN, J A Williamsport Hosp Williamsport, PA 83/06/20 ABRAHAM, K Region I, Office of Director 1p 20940 343
- 8310270035 FOIA request for all documents containing info re emission of radioactive iodine & other fission products during accident at facility
ROGERS, H A Affiliation Unknown 83/06/07 Office of the General Counsel 1p 20940 344 24X Fiche 50-320, 83/06/07, 8310270037
- 8310270040 Responds to FOIA request for documents containing info re emission of radioactive iodine & other fission products during reactor accidents Forwards App A documents App B documents can be purchased from NRC
FELTON, J M Division of Rules and Records 83/07/06 ROGERS, H A Affiliation Unknown App 20940 345 24X Fiche 50-320, 83/07/06, 8310270040
- 8310270041 Forwards draft "Comparison of Iodine Behavior During TMI-2 Accident W/Predictions Based on WASH-1400 Methodology"
POSTMA, A K Benton City Technology 82/04/13 PASADA, W F Accident Evaluation Branch 41pp 20940 349 24X Fiche 50-320, 83/07/06, 8310270040
- 8310270044 Draft "Comparison of Iodine Behavior During TMI-2 Accident W/Predictions Based on WASH-1400 Methodology"
POSTMA, A K Benton City Technology 82/04/13 40pp 20940 350 24X Fiche 50-320, 83/07/06, 8310270040
- 8310270045 8M1-2104
Draft "PWR-Large Dry Containment-Radionuclide Release Under Specific Accident Conditions"
+ Battelle Memorial Institute, Columbus Laboratories + Sandia Laboratories 83/02/09 Office of Nuclear Regulatory Research, Director 348pp 20941 028
- 8310270051 Responds to FOIA request for "Westinghouse Advanced PWR Licensing Control Document," dtd Aug 1982, to be placed in PDR Document withheld (ref FOIA Exemption 4)
FELTON, J M Division of Rules and Records 83/07/14 PEDRO, J NUS Corp 1p 20942 016
- 8310270057 FOIA request for "Westinghouse Advanced PWR Licensing Control Document," dtd Aug 1982, to be placed in PDR Rept referenced at NRC 821130 meeting w/Westinghouse
PEDRO, J NUS Corp CD-18-83-021 83/06/08 Division of Rules and Records 1p 20942 017
- 8310270065 FOIA request for draft BNL rept, "Grouping of LWR According to DHR Capability," transcript of 830519 meeting re ATWS rulemaking, transcript of ACRS 830526-27 meeting, LWR hydrogen manual & 8M1-2104, Vol 2
HIATT, B L Ohio Citizens for Responsible Energy 83/06/13 FELTON, J M Division of Rules and Records 1p 20942 271
- 8310270070 FOIA request for info re nuclear cooperation between US & South Africa, training of South African personnel in US, sale of nuclear materials to South Africa & strategic value of South African U to US, for period of 1960-65
KEYTERRING, N E New Hampshire, Univ of, 83/09/08 NRC - No Detailed Affiliation Given 1p 20942 194
- 8310270071 Responds to FOIA request for five separate categories of documents Forwards App A documents responsive to Items 1, 2 & 3 of request Item 4 re LWR hydrogen manual should be published during Sept 1983 Item 5 not available
FELTON, J M Division of Rules and Records 83/07/14 HIATT, S L Ohio Citizens for Responsible Energy 2pp 20942 272
- 8310270075 Draft "Grouping of LWRs for Evaluation of DHR Capability"
KAROL, R, FREED, A, PERKINS, K R Brookhaven National Laboratory 82/12/31 NRC - No Detailed Affiliation Given 77pp 20942 278
- 8310270074 Responds to FOIA request for info re nuclear cooperation between South Africa & US for period of 1960-65 Forwards documents listed in App A Documents also available in PDR DOE should be contacted for further info
FELTON, J M Division of Rules and Records 83/10/11 KETTERING, N E New Hampshire, Univ of, 3pp 20942 195
- 8310270080 Forwards License XR-42 for cancellation W/o encl
KELLY, J P Treasury, Dept of, U S Customs Service 1-WIM-JTC 10 66/01/27 Atomic Energy Commission 1p 20942 198
- 8310270084 Export clearance continuation sheet for period 631129-650315
* Treasury, Dept of, U S Customs Service 65/03/15 1p 20942 199
- 8310270092 Expresses appreciation for expeditious handling of Export License XR-42
ABEL, L E Allis-Chalmers Corp 63/11/14 CASE, E G Atomic Energy Commission 1p 20942 200
- 8310270097 Advises of issuance of amend to License XR-42, increasing total price & extending expiration date to 651231
PRICE, E R Atomic Energy Commission 63/11/14 LYONS, T D Allis-Chalmers Corp 2pp 20942 201
- 8310270100 Authorizes clearance of partial shipment on 631115 against License XR-42, permitting export of nuclear reactor to South Africa Amended license forthcoming
PRICE, E R Atomic Energy Commission 63/11/14 COLLIGAN, W Treasury, Dept of, U S Customs Service 2pp 20942 203
- 8310270105 Application for amend to Export License XR-42, extending date to 651231 & increasing value
LYONS, T D Allis-Chalmers Corp 63/11/12 MASON, N D Atomic Energy Commission 2pp 20942 205
- 8310270109 Forwards License XR-42 issued to Allis-Chalmers, covering mail destined for South Africa, for placement in file No shipments made yet
HESSING, A W Affiliation Unknown 61/12/18 Treasury, Dept of, U S Customs Service 1p 20942 207
- 8310270113 License for Allis-Chalmers Mfg Co to export nuclear reactor to South Africa
KIRK, R L Atomic Energy Commission 61/06/14 2pp 20942 208
- 8310270116 Informs of 610620 FR publication of notice of issuance of License XR-42 to Allis-Chalmers Mfg Co, authorizing export of nuclear reactor to South Africa
FREDERICK, R J Atomic Energy Commission 61/06/21 Atomic Energy Commission 1p 20942 209
- 8310270122 Informs of issuance of license to Allis-Chalmers Mfg Co, authorizing export of 20,000 kW thermal nuclear reactor to South Africa
KIRK, R L Atomic Energy Commission 61/06/15 RAMEY, J T Congress (Joint & Rotating Committees, etc) 1p 20942 211
- 8310270127 Forwards, for FR publication, notice of issuance of utilization facility export license to Allis-Chalmers Mfg Co W/o encl
* Atomic Energy Commission 61/06/14 EBERHART, D C National Archives & Records Service 1p 20942 212
- 8310270133 Forwards License XR-42 issued to Allis-Chalmers Mfg Co, authorizing export of nuclear reactor to South Africa Govt of South Africa should be advised that license does not imply Commission assumption of responsibility for safety
LOWENSTEIN, R Atomic Energy Commission 61/06/14 WELLS, A A Atomic Energy Commission 1p 20942 213
- 8310270139 Forwards License XR-42, authorizing export of nuclear reactor to South Africa W/o encl
KIRK, R L Atomic Energy Commission 61/06/14 NICKEL, H C Allis-Chalmers Corp 1p 20942 214
- 8310270144 Informs that since no request for formal hearing filed, License XR-42 issued to Allis-Chalmers Mfg Co, authorizing export of nuclear reactor to South Africa
LOWENSTEIN, R Atomic Energy Commission 61/06/14 PRICE, H L Atomic Energy Commission 1p 20942 215
- 8310270147 Notice of issuance of License XR-42 to Allis-Chalmers Mfg Co, authorizing export of nuclear reactor to South Africa
KIRK, R L Atomic Energy Commission 61/06/14 1p 20942 216
- 8310270151 Recommends issuance of license to Allis-Chalmers Mfg Co, authorizing export of nuclear reactor to South Africa
WELLS, A A Atomic Energy Commission 61/05/31 LOWENSTEIN, R Atomic Energy Commission 1p 20942 218
- 8310270156 Informs of 610224 FR publication of Allis-Chalmers Mfg Co 610106 application for license to export nuclear reactor to South Africa
FREDERICK, R J Atomic Energy Commission 61/02/28 EDWARDS, C T Atomic Energy Commission 1p 20942 219

NONDOCKETED ITEMS

437

--B310270199 Forwards for FR publication, notice of Allis-Chalmers Mfg Co 610106 application for license to export nuclear reactor to South Africa
* Atomic Energy Commission 61/02/17 EBERHART, D C National Archives & Records Service 1p 20942 220

--B310270163 Notice of issuance of Allis-Chalmers Mfg Co 610106 application for license to export nuclear reactor to South Africa
KIRK, R L Atomic Energy Commission 61/02/16 2pp 20942 221

--B310270168 Informs of receipt of Allis-Chalmers 610106 application for license to export nuclear reactor to South Africa W/o encl
KIRK, R L Atomic Energy Commission 61/02/17 RAMEY, J T Congress (Joint & Rotating Committees, etc) 1p 20942 223

--B310270170 Forwards Allis-Chalmers Mfg Co 610106 application for license to export nuclear reactor to South Africa W/o encl
PRICE, H L Atomic Energy Commission 61/02/16 WELLS, A A Atomic Energy Commission 1p 20942 224

--B310270174 Forwards FR notice of issuance of application for license to export nuclear reactor to South Africa W/o encl
KIRK, R L Atomic Energy Commission 61/02/16 NICKEL, H C Allis-Chalmers Corp 1p 20942 225

--B310270177 Forwards FR notice of issuance of Allis-Chalmers Mfg Co application for license to export nuclear reactor to South Africa W/o encl
MASON, H D Atomic Energy Commission 61/01/26 HUGHES, W E Atomic Energy Commission 1p 20942 226

--B310270182 Furnishes info requested by NRC re application for license to export nuclear reactor to South Africa Roberts Const Co will be prime contractor South African Atomic Energy Board will be reactor owner
NICKEL, H C Allis-Chalmers Corp 61/01/13 PRICE, H L Atomic Energy Commission 1p 20942 227

--B310270186 Forwards application for license to export nuclear reactor to South Africa
NICKEL, H C Allis-Chalmers Corp 61/01/10 PRICE, H L Atomic Energy Commission 1p 20942 228

--B310270189 Application for license to export nuclear reactor to South Africa
CASPER, R M Allis-Chalmers Corp 61/01/06 4pp 20942 229

B310270082 Responds to FOIA request for successful proposal under RFP EDO-83-434 Requested records nonexistent NRC did not award contract since svcs not required File closed
FELTON, J M Division of Rules and Records 83/07/20 NEWMAN, K A Debevoise & Liberman 1p 20942 269

B310270085 FOIA request for successful proposal under RFP EDO-83-436, "Developing Decisionmaking Rationale for Establishing New Regulatory Requirements"
NEWMAN, K A Debevoise & Liberman 83/07/14 FELTON, J M Division of Rules and Records 1p 20942 270

B310270089 Responds to FOIA request for Contract NRC-33-83-454 & successful proposal submitted by On-Line Computer Sys, Inc Nonproprietary version available in PDR & filed under FOIA Request 83-274 (R Dick)
FELTON, J M Division of Rules and Records NRC-33-83-454 83/07/13 MASSENGALE, E W ORI, Inc 1p 20942 267

B310270093 FOIA request for successful proposal & Contract NRC-33-83-454 awarded to On-Line Computer Sys, Inc
MASSENGALE, E ORI, Inc NRC-33-83-454 83/06/16 Division of Rules and Records 1p 20942 268

B310270099 FOIA request for Ocean Data Sys, Inc (Global Weather Dynamics, Inc) response to RFP 88-MPA-82-319
GLICKMAN, T WSI Corp. 83/06/23 ROBINSON, L. Division of Rules and Records 1p 20942 242

B310270104 Responds to FOIA request for Ocean Data Sys, Inc/Global Weather Dynamics, Inc proposal submitted per 88-MPA-82-319 Nonproprietary version of technical proposal can be found under FOIA Request 83-353 located in PDR
FELTON, J M Division of Rules and Records 83/07/19 GLICKMAN, T WSI Corp 1p 20942 243

--B310270107 Forwards Proposal 897346 "Comprehensive Current (Real-Time) Geophysical Data Storage & Retrieval Sys," in response to RFP 88-MPA-82-319 Proposal remains valid for 90 days.
* Global Weather Dynamics, Inc 82/08/27 Division of Contracts 1p 20942, 244

--B310270110 Technical Proposal 897346 "Comprehensive Current (Real-Time) Geophysical Data Storage & Retrieval Sys," submitted in response to RFP 88-MPA-82-319
* Global Weather Dynamics, Inc 88-MPA-82-319 82/08/03 22pp 20942 245

B310270117 Responds to FOIA request for SECY-82-489 & SECY-82-13E to be placed in PDR SECY-82-489 placed in PDR SECY-82-13E not located
FELTON, J M Division of Rules and Records 83/07/15 GRABER, L D NUS Corp 1p 20942 240

B310270121 FOIA request for SECY-82-489 & SECY-82-13E to be placed in PDR
GRABER, L D NUS Corp CD-LIB-7153 83/05/06 Division of Rules and Records 1p 20942 241

B310270126 FOIA request for documents re discussions within Commission or communications between EDO & FEMA concerning possible rev to radiological emergency planning guidance, per NUREG-0654/FEA-REP-1, Rev 1
LEVIN, J J Power Authority of the State of New York BRANDENBURG, B Consolidated Edison Co of New York, Inc 83/05/16 FELTON, J Division of Rules and Records 2pp 20942 233

B310270132 Responds to FOIA request for info re possible rev to radiological emergency planning guidance & info on whether NRC emergency planning regulations appropriate in light of anticipated accident scenarios Forwards documents
FELTON, J M Division of Rules and Records 83/07/15 BRANDENBURG, B Consolidated Edison Co of New York, Inc 1p 20942, 235

--B310270138 Agrees w/actions recommended in B10204 memo Draft memo re emergency planning rule requested Recommendation by B10217 requested
AHEARNE, J NRC - No Detailed Affiliation Given 81/02/09 NRC - No Detailed Affiliation Given 1p 20942 236

--B310270145 Staff requirements memo re B2110 briefing in Washington, DC on Sandia consequences study Commission briefed on NUREG/CR-2239 (SAND81-1349), "Technical Guidance for Siting Criteria Development" Viewgraph encl
CHILK, B J Office of the Secretary of the Commission HB2110B 82/11/18 DIRCKB, W J Office of the Executive Director for Operations 3pp 20942 237

B310270250 Responds to FOIA request for Polk & Schierling B30218 memo to Knighton & Lear re reverification program Memo placed in PDR
FELTON, J M Division of Rules and Records 83/07/15 BUCKLES, R NUS Corp 1p 20943 065 24X Fiche 50-275, 83/07/15, B310270250

B310270255 FOIA request for Polk & Schierling B30218 memo to Knighton & Lear re reverification program to be placed in PDR
BUCKLES, R NUS Corp CD-18-83-102 83/06/30 Division of Rules and Records 1p 20943 066 24X Fiche 50-275, 83/06/30, B310270255

B310270262 Second response to FOIA request for NRC rept on investigation of charges that Bechtel representatives onsite prior to Bechtel nomination to conduct independent mgt review Documents in App A available in PDR
FELTON, J M Division of Rules and Records 83/07/14 ANDERSON, P H Shaw, Pittman, Potts & Trowbridge 2pp. 20943 067 24X Fiche 50-358, 83/07/14, B310270262

B310270281 Further response to FOIA request for metl re enactment of Section 13(c) of Public Law 97-415 requiring NRC to undertake pilot program to study two plants where const, QA & QC deficiencies identified, Forwards SECY-83-032A
FELTON, J M Division of Rules and Records 83/07/18 HAMLIN, J B Shaw, Pittman, Potts & Trowbridge 1p 20943 071

--B310270286 SECY-83-032A
Requests info rept on status of implementation of QA initiatives identified in SECY-82-352
DIRCKB, W J. Office of the Executive Director for Operations 83/04/21 16pp. 20943 072

B310270298 Appeals denial of FOIA request for placement of IE Investigation Rept 1-83-003 in PDR
KILCOYNE, J J Kilcoyne, J. J. 83/05/31 Office of the Secretary of the Commission. 1p 20942, 356, 24X Fiche 50-289, 83/05/31, B310270298

B310270304 Responds to appeal re denial of FOIA request for IE Investigation Rept 1-83-003 Forwards document Document also available in PDR Portions of rept withheld (ref FOIA Exemptions 5 & 7)
CHILK, B J. Office of the Secretary of the Commission. 83/10/03 KILCOYNE, J J Kilcoyne, J. J. 2pp 20942, 359 24X Fiche 50-289, 83/10/03, B310270304

NONDOCKETED ITEMS

- 8310270324 IE Investigation Rept 1-83-003 on 830125-0211 Status closed
Major area investigated alleged compromise of preemployment
psychological exams
CHRISTOPHER, R., HAYES, B. B. Office of Investigation 83/02/23
58pp 20942 361 24X Fiche 50-289, 83/10/03, 8310270304
- 8310270340 FOIA request for placement of listed LERs in PDR
GRABER, L. D. NUS Corp CD-18-83-324 83/09/08 Division of Rules
and Records 2pp. 20938 038 24X Fiche 50-000, 83/09/08, 8310270340
- 8310270347 Responds to FOIA request for release of 23 LERs to PDR
Forwards 12 LERs to be released Documents also available in
PDR One LER canceled Eight LERs not received
FELTON, J. M. Division of Rules and Records 83/09/29 GRABER, L. D.
NUS Corp 1p 20938 060 24X Fiche 50-000, 83/09/29, 8310270347
- 8310270354 LER 83-002/01T-0 on 830405, spent fuel assembly X-13 dropped
back into rack from fully lifted position Caused by cable
stress due to limit switch failure Insp for cladding damage
will be conducted W/830419 ltr
BARRY, Z. E., WILLIAMS, J. W. Florida Power & Light Co PNS-LI-83
83/04/19 O'REILLY, J. P. Region 3, Office of Director 4pp
20938 061 24X Fiche 50-000, 83/09/29, 8310270347
- 8310270339 LER 83-002/03L-0 on 830109, power loss in RCIC governor
control sys occurred Caused by failed Pacific Electric 70-
watt resistor Resistor replaced w/improved design W/830208
ltr
TOLLERSON, J. L., MUSDOLF, D. Northern States Power Co 83/02/08
Region 3, Office of Director 3pp 20938 065 24X
Fiche 50-000, 83/09/29, 8310270347
- 8310270344 LER 83-003/03L-0 on 830207, RHR loop B made inoperable due to
unmaintainable RHR 12 HX differential pressure Caused by
piston ring wear Graphite rings replaced w/spring loaded
Teflon rings W/830309 ltr
CARPENTER, O. L., MUSDOLF, D. Northern States Power Co 83/03/09
Region 3, Office of Director 3pp 20938 068 24X
Fiche 50-000, 83/09/29, 8310270347
- 8310270380 LER 83-004/03L-0 on 830210, measured flow of 3,100 cfm for
train B standby gas treatment did not meet min Tech Spec
requirement of 3,150 cfm. Caused by clogged demisters
Demisters cleaned & procedure will be revised W/830311 ltr
IVERSON, O., MUSDOLF, D. Northern States Power Co 83/03/11
Region 3, Office of Director 3pp 20938 071 24X
Fiche 50-000, 83/09/29, 8310270347
- 8310270390 LER 83-007/03L-0 on 830411, essential motor control ctr 133A
feeder breaker tripped Caused by drifted right phase
overcurrent trip device Device replaced & breaker reclosed &
replaced W/830511 ltr
MUSDOLF, D. Northern States Power Co 83/05/11 Region 3, Office
of Director 3pp 20938 074 24X Fiche 50-000, 83/09/29, 8310270347
- 8310270410 LER 83-008/03L-0 on 830413, leak in feedwater heater
extraction steam trip outlet pipe 15A found. Caused by steam
erosion Leaking pipe section replaced & erosion program will
be accelerated & amended. W/830516 ltr
MAYER, P., MUSDOLF, D. Northern States Power Co 83/05/13 Region
3, Office of Director 3pp 20938 077 24X Fiche 50-000,
83/09/29, 8310270347.
- 8310270414 LER 83-009/01T-0 on 830504, HPCI Woodward Governor EGR
hydraulic actuator coil discovered grounded Caused by faulty
wire lead insulation. Emergency generator reactor & HPCI
tube oil replaced Sample being analyzed. W/830518 ltr
WOJCICHOWSKI, A. V., MUSDOLF, D. Northern States Power Co 83/05/18
Region 3, Office of Director 3pp 20938 080 24X
Fiche 50-000, 83/09/29, 8310270347
- 8310270415 LER 82-023/03L-0 on 821121, containment pressure sensing line
found capped Caused by personnel error. Units will be
labeled W/831230 ltr.
HUNSTAD, A. A. Northern States Power Co 82/12/21. Region 3,
Office of Director 2pp. 20938 085 24X Fiche: 50-000, 83/09/29,
8310270347
- 310270418 LER 82-026/03L-0 on 821115, turbine driven auxiliary
feedwater pump 11 failed to deliver full flow of 200 gpm to
steam generators Caused by unscrewed governor valve Valve
sent reinstalled & staked in position W/821215 ltr
HUNSTAD, A. A., MUSDOLF, D. Northern States Power Co 82/12/15
Region 3, Office of Director 2pp. 20938 087 24X
Fiche: 50-000, 83/09/29, 8310270347.
- 110270421 LER 83-001/01T-0 on 830204, Exxon ECCS analysis error
discovered. Caused by input error into codes W/830218 ltr
HUNSTAD, A. A., MUSDOLF, D. Northern States Power Co. 83/02/18
Region 3, Office of Director 3pp 20938 089 24X
Fiche. 50-000, 83/09/29, 8310270347
- 8310270425 LER 83-007/03L-0 on 830330, steam line radiation monitors
discovered inoperable Monitors repaired & surveillance
procedure revised to include daily check W/830429 ltr
MUSDOLF, D. Northern States Power Co 83/04/29 Region 3, Office
of Director 3pp 20938 092 24X Fiche 50-000, 83/09/29,
8310270347
- 8310270427 LER 83-011/03L-0 on 830510, diesel generator D2 tripped
Caused by drift in Dryer pressure switch Model 1822 J
Switch recalibr
HUNSTAD, A. A., MUSDOLF, D. Northern States Power Co 83/05/24
Region 3, Office of Director 3pp 20938 095 24X
Fiche 50-000, 83/09/29, 8310270347
- 8310270429 LER 83-008/03L-0 on 830410, right hand stop valve failed
Caused by separation of valve disc from clapper arm disc
Valve repaired & will be replaced at next refueling outage
Left hand stop valve also inspected W/830510 ltr
HUNSTAD, A. A., MUSDOLF, D. Northern States Power Co 83/05/10
Region 3, Office of Director 3pp 20938 098 24X
Fiche 50-000, 83/09/29, 8310270347
- 8310270355 FOIA request for release of SECY-82-242 & SECY-83-317 to
PDR
PEDRO, J. NUS Corp CD-18-83-247 83/08/12 Division of Rules
and Records 1p 20943 295
- 8310270360 Responds to FOIA request for SECY-82-242 & SECY-83-317
Forwards SECY-82-242 SECY-83-317 withheld (ref FOIA
Exemption 5)
FELTON, J. M. Division of Rules and Records 83/09/29 PEDRO, J. NUS
Corp 2pp 20943 296
- 8206240098 SECY-82-242
Requests Commission approval re mod of NRC regulations
involving requirements for fracture toughness of RCPB,
including surveillance of neutron radiation embrittlement
of reactor vessel beltline matl
DIRCKS, W. J. Office of the Executive Director for Operations
82/06/14 39pp 20943 298
- 8310270366 FOIA request for SECY-83-278 & SECY-83-270, transmitting
830624 "Rept on Adequacy & Safety of Relief Valve Testing &
Performance"
WEISS, E. R. Union of Concerned Scientists 83/08/30 FELTON, J.
Division of Rules and Records 1p 20943 128
- 8310270369 Responds to FOIA request for SECY-83-278 & SECY-83-270,
transmitting 830624 "Rept on Adequacy & Safety of Relief
Valve Testing & Performance." Forwards requested documents
FELTON, J. M. Division of Rules and Records 83/10/04 WEISS, E. R.
Union of Concerned Scientists 1p 20943 129 24X
Fiche 50-289, 83/10/04, 8310270369
- 8307270430 SECY-83-278
Forwards revised certification & noncertification status
tables per 830622 request Table J revised to clarify insp
status of certification items for which insp previously
noted as not applicable
DIRCKS, W. J. Office of the Executive Director for Operations
83/07/11 43pp 20943 130 24X Fiche: 50-289, 83/10/04, 8310270369
- 8307220250 SECY-83-270
Provides summary of primary sys relief & safety valve
testing & performance since TMI-2 accident per NUREG-0737,
Item II D 1
DIRCKS, W. J. Office of the Executive Director for Operations
83/07/03 122pp 20943 173
- 8310270465 FOIA request for current printouts of computerized steam
generator status info & addl summary info on US or foreign
steam generator status
CONNER, L. Doc-Search Associates 83/08/29 NRC - No Detailed
Affiliation Given. 1p 20937 242
- 8310270468 Responds to FOIA request for current printouts &
interpretive keys of computerized steam generator status
info & addl summary info on US or foreign status Forwards
printout & Congressman Markey ltr. Info available in PDR
FELTON, J. M. Division of Rules and Records 83/10/04 CONNER, L.
Doc-Search Associates 1p 20937 243
- 8212150242 Forwards util responses to Generic Ltr 82-22 re economic &
worker safety aspects of steam generator tube degradation
problem per NRC 821027 ltr
HAMMERER, C. Office of Congressional Affairs GL-82-22 82/11/30
MARKEY, E. J. House of Rep., Interior & Insular Affairs 2pp
20937 327.

NONDOCKETED ITEMS

439

--B212190246 Forwards completed questionnaire in response to Generic Ltr B2-22, "Congressional Request for Info re Steam Generator Tube Integrity." No major steam generator repairs anticipated in next 3 yrs
MUSOLF, D Northern States Power Co GL-B2-22 82/11/11
Office of Nuclear Reactor Regulation, Director 2pp 20937 336

--B212290072 Forwards addl responses to info requested in B21026 ltr re steam generator integrity (Generic Ltr B2-22) & list of licensees which have & have not responded
KAMMERER, C Office of Congressional Affairs GL-B2-22 82/12/10
MARKEY, E J House of Rep, Interior & Insular Affairs 3pp
20937 356

--B310270470 Computer printout of steam generator status info
* NRC - No Detailed Affiliation Given 83/10/04 83pp
20937 244

B310270496 FOIA request for list of utils accused of making matl false statements from Jan 1975 to present
HAFNER, B Suffolk Nuclear Study Group 83/06/27 Office of the
Administration 1p 20928 353

B310270501 Responds to FOIA request for list of utils accused of making matl false statements from Jan 1975 to present Forwards requested list Addl info re listed utils available in PDR
FELTON, J M Division of Rules and Records 83/07/28 HAFNER, B
Suffolk Nuclear Study Group 1p 20928 354

--B310270505 List of utils accused of making matl false statements from Jan 1975 to present
* NRC - No Detailed Affiliation Given 83/07/28 2pp
20928 355

B310270503 Partial response to FOIA request for documents re emergency operation facilities located 10-20 miles from nuclear plant & documents approving or denying request to locate at distance greater than 20 miles App A documents in PDR
FELTON, J M Division of Rules and Records 83/07/28 O'NEILL, J H
Shaw, Pittman, Potts & Trowbridge 2pp 20928 357

B310270508 Appeals denial of FOIA request for DOE/NRC Form 741 detailing movement of South African origin matl Reasons for confidential nature of Form 741 requested
KNAPIK, M McGraw-Hill Publications Co 83/06/10 Office of the
Executive Director for Operations 1p 20928 329

B310270512 FOIA request for records relating to commenting on, supporting, criticizing or otherwise referring to NRC recommendation that emergency operation facilities be located at distance between 10 & 20 miles from plant
O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/06/21 Office
of Administration 1p 20928 359

B310270514 Responds to appeal re denial of FOIA request for DOE/NRC Forms 741 detailing movement of South African origin matl Appeal denied Document withheld (ref FOIA Exemption 4)
DIRCKS, W J Office of the Executive Director for Operations
83/07/26 KNAPIK, M McGraw-Hill Publications Co 2pp 20928 330

B310270527 FOIA request for three categories of documents re B30606 gas leak at facility
AROYROS, D Chamlin, Schottland, Rosen, Cavanagh & Uliano 83/06/22
NRC - No Detailed Affiliation Given 1p 20937 224 24X
Fiche 50-219, 83/06/22, B310270527

B310270541 Responds to FOIA request for three categories of documents re B30606 gas leak at facility Forwards App A documents
FELTON, J M Division of Rules and Records 83/07/22 AROYROS, D L
Chamlin, Schottland, Rosen, Cavanagh & Uliano 2pp 20937 225 24X
Fiche 50-000, 83/07/22, B310270541

--B310270547 Submits morning rept for Region I, listing B30606 & 07 events
ALLAN, J M Region I, Office of Director 83/06/07 BLAHA, J
Program Support Branch 1p 20937 228 24X Fiche 50-000,
83/07/22, B310270541

B310280071 FOIA request for AEOD rept, "Loss of Shutdown Cooling & Subsequent Boron Dilution at San Onofre 2," dtd 830425 & info re fuel rod degradation problem described in IE Info Notice B2-27
HIATT, S L Ohio Citizens for Responsible Energy IEIN-B2-27
83/04/29 FELTON, J M Division of Rules and Records 1p
20962 155 24X Fiche 50-361, 83/06/29, B310280071

B310280079 Responds to FOIA request for AEOD rept, "Loss of Shutdown Cooling & Subsequent Boron Dilution at San Onofre 2," dtd 830425 & documents re fuel rod degradation problem described in IE Info Notice B2-27 Forwards App A documents
FELTON, J M Division of Rules and Records 83/07/28 HIATT, S L
Ohio Citizens for Responsible Energy 2pp 20962 156 24X
Fiche 50-000, 83/07/28, B310280079

--B305030115 Forwards "Loss of Shutdown Cooling & Subsequent Boron Dilution," engineering evaluation rept
CINTULA, T C Reactor Operations Analysis Branch AEOD/E310.
83/04/25 SEYFRIT, K V Reactor Operations Analysis Branch 1p
20962 239 24X Fiche 50-000, 83/07/28, B310280079.

--B305030120 AEOD/E310
"Loss of Shutdown Cooling & Subsequent Boron Dilution," engineering evaluation summary
* Director's Office 83/04/25 13pp 20962 240 24X
Fiche 50-000, 83/07/28, B310280079

--B305160184 Forwards draft IE info notice on possible safety concern to all PWRs re encl engineering evaluation rept on 830314 & 24 loss of shutdown cooling & subsequent boron dilution
HELTEMES, C J Docketing & Services Branch 83/05/06 JORDAN, E L
Division of Emergency Preparedness & Engineering Response (Post 830103) 1p 20962 238 24X Fiche 50-000, 83/07/28, B310280079.

--B310280132 Forwards IE Circular B0-17, "Fuel Pin Damage Due to Water Jet From Baffle Plate Corner," for issuance on 800723 Draft transmittal ltr also encl
MOSELEY, N C Division of Reactor Operations Inspections
80/07/21 ORIER, D H Region 1, Philadelphia, Office of the
Director O'REILLY, J P Region 2, Atlanta, Office of the
Director KEPLER, J G Region 3, Chicago, Office of the Director
2pp 20962 163

--B310280136 Forwards safety evaluations prepared by licensees & Region V re loose fuel pellets & clad pieces in RCS
CREWS, J L Division of Resident Reactor Project & Engineering
Programs 82/07/22 CLARK, R A Operating Reactors Branch 3
4pp 20962 220 24X Fiche 50-000, 83/07/28, B310280079

--B310280138 Safety evaluation re loose fuel pellets & clad pieces in RCS Strong evidence exists that no more than 20 pellets remain in RCS Licensee performed comprehensive evaluation of proposed operation Related info encl
* Region 3, Office of Director 82/07/21 12pp 20962 226, 24X
Fiche 50-000, 83/07/28, B310280079

--B310280168 LER 50-266/75-1B on 751217, during Cycle 3-4 refueling, discovered section of fuel rod missing Caused by water impingement through baffle plate while failed assembly in Cycle 2 position H-I investigation in progress W/751230 ltr
BODE, P E BURSTEIN, S Wisconsin Electric Power Co 75/12/30
RUSCHIE, D C Office of Nuclear Reactor Regulation, Director 10pp
20962 253 24X Fiche 50-000, 83/07/28, B310280079

--B310280171 LER 50-266/76-12 on 761222, wall cladding defects noted in one rod of fuel assembly 007 Caused by rod vibrating against rod retaining grid springs Peening of core baffle plate joints, completed in Nov 1976, should prevent recurrence
BODE, P E Wisconsin Electric Power Co 77/01/04 3pp
20962 263 24X Fiche 50-000, 83/07/28, B310280079

B310280169 Appeals partial denial of FOIA request for correspondence between Chairman Palladino & DOJ re investigation of alleged falsification of RCS leak rate tests
VOIGT, H H LeBeauf, Lamb, Leiby & MacRae 83/09/19 CHILK, S J
Office of the Secretary of the Commission 2pp 20965 055 24X
Fiche 50-289, 83/09/19, B310280169

B310280172 Responds to appeal re partial denial of FOIA request for correspondence between Chairman Palladino & DOJ re investigation of alleged falsification of RCS leak rate tests. Info partially withheld (ref FOIA Exemption 3)
CHILK, S J Office of the Secretary of the Commission 83/10/14
VOIGT, H H LeBeauf, Lamb, Leiby & MacRae 2pp 20965 057 24X
Fiche 50-289, 83/10/14, B310280172

--B310280179 Comments on questions raised in B30517 ltr to Chairman Palladino re communication between agencies DOJ should commit to completion date for investigation Supporting documentation encl
CUMMINGS, J J Office of Inspector & Auditor 83/05/31.
JENSEN, D L Justice, Dept of App 20965 064 24X
Fiche 50-289, 83/10/14, B310280172

B310280174 FOIA request for all internal nonpublic documentation re const flaws & improper conduct by inspectors, util contractors or subcontractors
MCINNIS, D News & Observer 83/07/19 FELTON, J Division of Rules
and Records 1p 20963 287 24X Fiche 50-400, 83/07/19, B310280174.

NONDOCKETED ITEMS

- 8310280176 Responds to FOIA request for internal nonpublic documentation re const flaws & improper conduct of NRC inspectors & util contractors or subcontractors Forwards documents listed in App A
FELTON, J M Division of Rules and Records 83/09/23 VADEN, T News & Observer 3pp 20963 288 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280193 Documents O Zachar 790212 request for current status of remand hearing & NRC actions re recommendations in Ofc of Inspector & Auditor rept Recommendations will be adopted
FOSTER, W H Office of Inspector & Auditor 79/02/13 Office of Inspector & Auditor 1p 20963 291 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280197 Forwards draft Ofc of Inspector & Auditor 781109 rept on inquiry into alleged omission of line inspector views from CP hearing, for perusal w/o encl
MURRAY, J P Deputy Executive Legal Director 78/12/18 CUMMINGS, J J Office of Inspector & Auditor 3pp 20963 292 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280202 Documents telcon w/FC Centrell re insp file in preparation for testimony Instructions not received to review file Centrell relied solely on personal notes & records to prepare testimony
FOSTER, W H Office of Inspector & Auditor 78/11/01 Office of Inspector & Auditor 1p 20963 293 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280207 Advises that ASLAB Chairman, AS Rosenthal will decline interview, claiming purposelessness
FOSTER, W H Office of Inspector & Auditor 78/10/26 Office of Inspector & Auditor 1p 20963 296 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280211 Advises that IE Manual Chapter 94010-B only written policy for preparing testimony for licensing hearings, per 781025 telcon w/RC Paulus
FOSTER, W H Office of Inspector & Auditor 78/10/26 Office of Inspector & Auditor 1p 20963 297 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280214 Forwards AS Rosenthal 781024 memo to OQ Abston, for perusal
ABSTON, D O Office of Inspector & Auditor 78/10/23 HENDRIE, J M Commissioners 1p 20963 298 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280218 Advises that ASLAB members not willing to be interviewed due to possible future involvement in case
ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel 78/10/24 ABSTON, D O Office of Inspector & Auditor 1p 20963 299 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280222 Requests interview w/ASLAB members to discuss impact of omission of line inspector views from written & oral testimony
ABSTON, D O Office of Inspector & Auditor 78/10/24 ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel 1p 20963 300 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280225 Forwards info re Ofc of Inspector & Auditor interview of ASLAB (ref Yore 781019 memo to Commissioners)
FRYE, J H Atomic Safety and Licensing Board Panel 78/10/20 ROSENTHAL, A S KELLEY, J L, ABSTON, D O NRC - No Detailed Affiliation Given 1p 20963 301 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280236 Forwards DH Gamble 781019 memo, for interest.
ABSTON, D O Office of Inspector & Auditor 78/10/20 HENDRIE, J M Commissioners 1p 20963 312 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280238 Summarizes A Rosenthal 781019 telcon opposing potential interview w/ASLAB members, citing unpleasantness of ASLB interview Ofc of Inspector & Auditor must assure different line of questioning before interview is granted.
GAMBLE, D H Office of Inspector & Auditor 78/10/19 Office of Inspector & Auditor 2pp 20963 313 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280242 Forwards documentation of 781017 conversation w/JM Varela, former AEC employee re V Brownlee. Conversation connected w/ current investigation.
DAVIS, J O Director's Office, Office of Inspection and Enforcement 78/10/19 ABSTON, D O Office of Inspector & Auditor 1p 20963 315 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280244 Documents 781017 conversation w/J Varela, former Region II employee, Brownlee directed Varela to change info in insp rept, causing dispute
DAVIS, J O Director's Office, Office of Inspection and Enforcement 78/10/19 Director's Office, Office of Inspection and Enforcement 1p 20963 316 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280246 Documents 781017 conversation w/C Barth (DELD) re testimony forwarded to ASLB before 771004 hearing ASLB should be required to read testimony before hearing
FOSTER, W H Office of Inspector & Auditor 78/10/18 Office of Inspector & Auditor 1p 20963 317 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280248 Advises of Ofc of Inspector & Auditor inability to procure useful info during interview w/ASLB due to ASLB unresponsiveness
ABSTON, D O Office of Inspector & Auditor 78/10/17 HENDRIE, J M, GILINSKY, V, KENNEDY, R T Commissioners 2pp 20963 324 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280250 Advises that HA Wilbur perusal of Dance testimony disclosed no ref to GA problems listed in subj insp repts
FOSTER, W H Office of Inspector & Auditor 78/10/10 Office of Inspector & Auditor 1p 20963 326 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280254 Forwards case assignments for ASLB members OQ Bright, JV Leeds & IW Smith, per request
FITTI, C J Atomic Safety and Licensing Board Panel 78/10/06 GAMBLE, D H Office of Inspector & Auditor 6pp 20963 327 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280256 Forwards Acting General Counsel opinion indicating no ex parte problem w/Ofc of Inspector & Auditor interview of ASLB members
ABSTON, D O Office of Inspector & Auditor 78/10/03 YORE, J R, ROSENTHAL, A S Atomic Safety and Licensing Board Panel 1p 20963 333 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280259 Informs of 781003 conversation w/I Smith of ASLB re Ofc of Inspector & Auditor interview w/ASLB members, to fulfill Commission order Interview will probably not be granted due to ex parte rule
FOSTER, W H Office of Inspector & Auditor 78/10/03 Office of Inspector & Auditor 1p 20963 335 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280263 Summarizes continued attempts to gain ASLB interview through 780927 conversation w/JV Leeds Leeds will not cooperate, citing ex parte rule
FOSTER, W H Office of Inspector & Auditor 78/09/27 Office of Inspector & Auditor 2pp 20963 336 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280265 Informs of alleged improprieties re deficiency discrepancy repts & corresponding logbook entries
YORSE, J Y Office of Investigation Q2-83-011 83/03/04 ALBERGON, C Y NRC - No Detailed Affiliation Given 1p 20963 338 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280270 Discusses alleged improprieties re deficiency discrepancy repts & corresponding logbook entries
BURCH, R H Office of Investigation Q2-83-011 83/03/03 Office of Investigation 1p 20963 339 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280299 Advises that no new info revealed after inquiry of alleged improprieties re deficiency discrepancy repts & corresponding logbook entries
YORSE, J Y Office of Investigation Q2-83-011 83/05/06 TODD, G NRC - No Detailed Affiliation Given 1p 20963 340 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280303 Advises that inquiry into alleged improprieties re deficiency discrepancy repts & corresponding logbook entries closed Util cited for violation
BURCH, R H Office of Investigation Q2-83-011 83/05/04 Office of Investigation 1p 20963 341 24X Fiche 50-400, 83/09/23, 8310280176
- 8310280183 Appeals partial denial of FOIA request for four categories of info re Canceled Forecast Panel 830330-31 meeting & site visit.
FALKENHEINER, D Louisiana Consumer's League, Inc FALKENHEINER, D Falkenheiner, D 83/09/01 Office of the Executive Director for Operations 2pp 20963 342 24X Fiche 50-458, 83/09/01, 8310280183

NONDOCKETED ITEMS

441

- 8310280187 Responds to appeal re partial denial of FOIA request for four categories of info re Caseload Forecast Panel 830330-31 meeting & site visit Forwards complete version of requested documents
DIRCKS, W J Office of the Executive Director for Operations
83/10/18 FALKENHEIMER, D Falkenheimer, D 1p 20963 344 24X
Fiche 50-458, 83/10/18, 8310280187
- 8310280199 Calculations re facility components Supporting documentation
encl
* Gulf States Utilities Co 83/03/30 11pp 20963 350 24X
Fiche 50-458, 83/10/18, 8310280187
- 8310280204 Appeals denial of FOIA request for Ofc of Investigation
repts re allegations concerning presence of Bechtel
representative at facility prior to Nov 1982
DEVINE, T Government Accountability Project 83/06/16 CHILK, S J
Office of the Secretary of the Commission 2pp 20964 192 24X
Fiche 50-358, 83/06/16, 8310280204
- 8310280212 Responds to appeal re denial of FOIA request for Ofc of
Investigation repts concerning facility Grants appeal in
part Forwards document info partially withheld (ref FOIA
Exemption 7)
CHILK, S J Office of the Secretary of the Commission 83/08/24
DEVINE, T Government Accountability Project 2pp 20964 198 24X
Fiche 50-358, 83/08/24, 8310280212
- 8310280220 IE Investigation Rept H-83-001 on 830120-0301 No
noncompliance noted Major areas investigated allegations
re presence of Bechtel representatives at facility prior to
Nov 1982 Affidavit encl info deleted
OILBERT, E C, WARD, W J, HAYES, B B Office of Investigation
83/03/11 60pp 20964 205 24X Fiche 50-358, 83/08/24, 8310280212
- 8310280224 Submits revised proposal for providing completion svcs for
facility Rev to proposal, originally submitted on 821108,
responds to Commission 821122 order to show cause List of
independent review team members encl
REINSCH, H O Bechtel Corp 82/11/23 DICKHONER, W H Cincinnati Gas
& Electric Co 7pp 20964 265 24X Fiche 50-358, 83/08/24,
8310280212
- 8310280229 Suppls 821123 ltr in response to JO Keppler 821228 request,
directed to util, re Bechtel mgt role Soderholm involvement
discussed
WAHL, H W Bechtel Corp 82/12/29 DICKHONER, W H Cincinnati Gas
& Electric Co 6pp 20964 296 24X Fiche 50-358, 83/08/24,
8310280212
- 8310280231 Forwards description of steps to be taken to identify
necessary organizational & procedural action, resumes of
Phase I team members, summaries of Bechtel nuclear
experience & contract forms info deleted
REINSCH, H O Bechtel Corp 82/11/08 DICKHONER, W H Cincinnati
Gas & Electric Co 48pp 20964 308 24X Fiche 50-358, 83/08/24,
8310280212
- 8310280220 IE Investigation Rept H-83-001 on 830120-0301 No
noncompliance noted Major areas investigated allegations
re presence of Bechtel representatives at facility prior to
Nov 1982 Affidavit encl info deleted
OILBERT, E C, WARD, W J, HAYES, B B Office of Investigation
83/03/11 60pp 20964 205 24X Fiche 50-358, 83/08/24, 8310280212
- 8310280224 Submits revised proposal for providing completion svcs for
facility Rev to proposal, originally submitted on 821108,
responds to Commission 821122 order to show cause List of
independent review team members encl
REINSCH, H O Bechtel Corp 82/11/23 DICKHONER, W H Cincinnati
Gas & Electric Co 7pp 20964 265 24X Fiche 50-358, 83/08/24,
8310280212
- 8310280229 Suppls 821123 ltr in response to JO Keppler 821228 request,
directed to util, re Bechtel mgt role Soderholm involvement
discussed
WAHL, H W Bechtel Corp 82/12/29 DICKHONER, W H Cincinnati Gas
& Electric Co 6pp 20964 296 24X Fiche 50-358, 83/08/24,
8310280212
- 8310280231 Forwards description of steps to be taken to identify
necessary organizational & procedural action, resumes of
Phase I team members, summaries of Bechtel nuclear
experience & contract forms info deleted
REINSCH, H O Bechtel Corp 82/11/08 DICKHONER, W H Cincinnati
Gas & Electric Co 48pp 20964 308 24X Fiche 50-358, 83/08/24,
8310280212
- 8310310017 FOIA request for documents re integrated leak rate tests for
listed facilities to be placed in PDR
CONNER, L Affiliation Unknown 83/05/02 NRC - No Detailed
Affiliation Given 1p 21004 270 24X Fiche 50-000, 83/05/02,
8310310017
- 8310310031 Responds to FOIA request for documents re integrated leak
rate tests for facilities to be placed in PDR Forwards
documents to be placed in PDR & list of facilities for which
repts are unavailable
FELTON, J M Division of Rules and Records 83/07/06 CONNER, L
Affiliation Unknown 1p 21004 271 24X Fiche 50-000, 83/07/06,
8310310031
- 8310310056 "Reactor Containment Bldg Integrated Leak Rate Test "
* Nebraska Public Power District 76/11/30 250pp 21004 272
24X Fiche 50-000, 83/07/06, 8310310031
- 8310310058 "Integrated Leak Rate Test Computer Program for Primary
Containment "
* Power Authority of the State of New York 74/03/20 100pp
21005 179 24X Fiche 50-000, 83/07/06, 8310310031
- 8310310061 YAE-1055
"Integrated Primary Containment Leakage Rate Test "
TARNUTZER, E C Vermont Yankee Nuclear Power Corp 72/02/07
67pp 21005 280 24X Fiche 50-000, 83/07/06, 8310310031
- 8310310064 "Reactor Containment Bldg Integrated Leakage Rate Test
Rept " W/770528 ltr
ULLRICH, W T Philadelphia Electric Co 77/04/04 109pp
21005 313 24X Fiche 50-000, 83/07/06, 8310310031
- 8310310067 "Reactor Containment Bldg Integrated Leak Rate Test,"
summary technical rept
ROMAN, W D Ebasco Services, Inc (subs of Enserch Corp)
76/02/14 56pp 21006 065 24X Fiche 50-000, 83/07/06, 8310310031
- 8310310068 Operating Procedures 13100 L, "Integrated Leak Rate Test "
ROMAN, W D Ebasco Services, Inc (subs of Enserch Corp)
75/11/01 200pp 21006 159 24X Fiche 50-000, 83/07/06,
8310310031
- 8310310070 "Containment Leak Rate Tests," Type B & C test repts
* Florida Power & Light Co 76/02/14 9pp 21006 329 24X
Fiche 50-000, 83/07/06, 8310310031
- 8310310072 "Reactor Containment Bldg Integrated Leak Rate Test "
W/730612 ltr
* Millstone Point Co 73/03/31 120pp 21006 334 24X
Fiche 50-000, 83/07/06, 8310310031
- 8310310073 Forwards "Reactor Containment Bldg Integrated Leak Rate
Test," including analysis & interpretation of Type A test
results & summary analysis of Type B & C tests performed
since last Type A test in Oct 1972
WHITE, L D Rochester Gas & Electric Corp 76/05/19 PURPLE, R A
Office of Nuclear Reactor Regulation, Director 1p 21007 099
24X Fiche 50-000, 83/07/06, 8310310031
- 8310310076 "Reactor Containment Bldg Integrated Leak Rate Test "
* Rochester Gas & Electric Corp 76/02/28 120pp 21007 096
24X Fiche 50-000, 83/07/06, 8310310031
- 8310310077 "Reactor Containment Bldg Integrated Leak Rate Test "
* Indiana & Michigan Power Co 75/02/26 67pp 21007 215 24X
Fiche 50-000, 83/07/06, 8310310031
- 8310310080 "Reactor Containment Bldg Integrated Leak Rate Test
(Preoperational) "
* Indiana & Michigan Power Co * American Electric Power Co ,
Inc 78/04/10 121pp 21007 283 24X Fiche 50-000, 83/07/06,
8310310031
- 8310310063 FOIA request for documents re const & operation of C-E
plants List of info required submitted
BELL, N Coalition for Safe Power 83/03/31 Office of
Administration 1p 20998 173 24X Fiche 50-000, 83/03/31,
8310310063
- 8310310096 FOIA request for SECY-82-7, 82-121, 82-141, 82-141A, 82-168,
82-221, 82-243, 82-251, 82-460, 82-466, 82-483, 83-30, 83-44, 83-72,
83-93 & 83-105 to be placed in PDR
SHOLLY, S C Union of Concerned Scientists 83/07/14 FELTON, J M
Division of Rules and Records 2pp 21000 144
- 8310310097 Responds to FOIA request that 14 SECYs be placed in PDR
Forwards App A documents SECY-82-466 withheld (ref FOIA
Exemption 5)
FELTON, J M Division of Rules and Records 83/09/19 SHOLLY, S C
Union of Concerned Scientists 3pp 21000 146 24X
Fiche 50-320, 83/09/19, 8310310097

NONDOCKETED ITEMS

--B203120050 SECY-82-077

Inform Commission of NRC progress in developing criteria & strategies re use of potassium iodide (KI) to block thyroid gland in event of accidental release of radioiodine. Validity of distribution of KI to general public questioned. DIRCKS, W J Office of the Executive Director for Operations 82/02/19 11pp 21000 256

--B204070171 SECY-82-121

Advises of current status of studies assessing potential technical, regulatory & socioeconomic impacts of proposed alternatives for accident water disposition. * Office of the Executive Director for Operations 82/03/18 13pp 21000 149 24X Fiche 50-320, 83/09/19, 8310310097

--B205030988 SECY-82-168

Informs of revision of 10CFR20, stds for protection against radiation, & efforts to ascertain adverse technical & economic impacts on NRC & licensee of revised regulation. Comparison of 10CFR20 salient issues w/alternatives encl. DIRCKS, W J Office of the Executive Director for Operations 82/04/21 8pp 21000 169

--B206100323 SECY-82-221

Forwards study re NRC role in contested nuclear power reactor initial licensing proceedings. Study concludes that different "neutral" NRC role should be adopted on trial basis in selected cases. BICKWIT, L Office of the General Counsel 82/06/03 48pp 21000 177

--B206250316 SECY-82-251

Provides Commission w/rept re property insurance for decontamination of nuclear reactors as published in NUREG-0891. DIRCKS, W J Office of the Executive Director for Operations 82/06/16 4pp 21000 248

--B206300342 SECY-82-243

Informs Commission of status of NRC activities re development of improved safeguards info sys. DIRCKS, W J Office of the Executive Director for Operations 82/06/10 3pp 21000 249

--B211290108 SECY-82-460

Informs Commission of historical & current rates of license issuance & exam failures for reactor operators & senior reactor operators. DIRCKS, W J Office of the Executive Director for Operations 82/11/17 4pp 21000 252

--B302160056 SECY-83-044

Submits alternatives for scope of guidelines for post-accident recovery in event of nuclear-related accidents. Recommends deferment of plan development until completion of severe accident & source term research. DIRCKS, W J Office of the Executive Director for Operations 83/01/31 16pp 21000 276

B304220088 SECY-83-126

Requests approval for publication of proposed rule ensuring that certain contractors & subcontractors of 10CFR50 licensees post NRC Form 3. DIRCKS, W J Office of the Executive Director for Operations 83/04/06 4pp 21000 162

--B310310116 SECY-82-141A

Informs of historical & current rates of license issuance & exam failures for reactor & senior reactor operators. Supporting data encl. Failure rates of 27% & 25% for reactor operator & senior reactor operator, respectively noted. DIRCKS, W J Office of the Executive Director for Operations 83/08/23 3pp 21000 166

--B310310131 SECY-82-483

Informs of present status of TH1-1 restart certification effort & provides update on NUREG-0737 items status. DIRCKS, W J Office of the Executive Director for Operations 82/12/09 16pp 21000 260 24X Fiche 50-289, 83/09/19, 8310310097

--B310310136 SECY-83-072

Informs of historical & current rates of license issuance & exam failures for reactor operators & senior reactor operator. Pass/fail rate remained consistent throughout Third Quarter FY82. DIRCKS, W J Office of the Executive Director for Operations 83/02/18 4pp 21000 292

--B310310140 SECY-83-093

Transmits INPO "Performance Objectives & Criteria for Corporate Evaluations" & informs of plans to defer further action on TH1 Action Plan Item I B 1 1 W/p encl. DIRCKS, W J Office of the Executive Director for Operations. 83/03/09 3pp 21000 296

GEN TEC IS GENERIC TECHNICAL ISSUES

B310030308 Forwards response to 830816 memo re 830125 main feedwater line break Response based on NUREG-0918, NUREG-0691 & proposed rev to Jan-Mar 80 rept. DIRCKS, W J Office of the Executive Director for Operations 83/09/21 ASSELSTINE, J K Commissioners 13pp 20604 039 24X Fiche 50-309, 83/09/21, 8310030308

--B306020357 Operating Reactor Event Memorandum 83-01 re 830125 loss-of-main-feedwater event which resulted in rupture of main feedwater line 2 Plant-specific PRA studies addressing Generic Issue A-01 on water hammer recommended. EISENHUT, D O Division of Licensing 83/05/20 SPECIS, T Division of Safety Technology VOLLMER, R Division of Engineering HATTSON, R Division of Systems Integration (post 811005) 17pp 20604 052 24X Fiche 50-309, 83/09/21, 8310030308

--B310030316 Requests responses to listed questions re main feedwater line break due to water hammer. ASSELSTINE, J K Commissioners 83/08/16 DIRCKS, W J Office of the Executive Director for Operations 3pp 20604 071 24X Fiche 50-309, 83/09/21, 8310030308

B310030641 Forwards Alden Research Lab 830916 test results re transport of reflective metallic insulation. Completed evaluation will be used for resolution of Unresolved Safety Issue A-43, "Containment Sump Performance". KNIEL, K Generic Issues Branch 83/09/23 FARRAR, D L Commonwealth Edison Co STALAY, R Atomic Industrial Forum BUDZIK, D M Consumers Power Co 2pp 20626 293

--B310030645 Forwards summary of results of transportation tests on pipe insulation sample. Test results on foil sheets not yet received. BROCARD, D N Alden Research Laboratory 83/09/16 BERKIZ, A Generic Issues Branch 14pp 20626 295

B310040052 Forwards 9-month response for NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants". Electrical interlocks prevent main hoist of reactor bldg crane from being used over reactor well or spent fuel pool. CURTIS, N W Pennsylvania Power & Light Co PLA-1843 83/09/29 SCHWENCER, A Licensing Branch 2 63pp 20608 143 24X Fiche 50-388, 83/09/29, 8310040052

B310040310 Forwards addl info requested in 830810 telcon re Franklin Research Ctr 830617 draft technical evaluation rept on util response to Phase 1 of NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants". FAY, C W Wisconsin Electric Power Co 83/09/28 MILLER, J R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 8pp 20613 096 24X Fiche 50-266, 83/09/28, 8310040310

B310040498 Respec of Contention I-41 re sys interaction Certificate of Svc encl. DORSEY, J A Limerick Ecology Action 83/09/28 BRENNER, L Atomic Safety and Licensing Board Panel 8pp 20625 152 24X Fiche 50-352, 83/09/28, 8310040498

B310040530 Comments on draft Task Action Plan for Generic Issue A-29, "Nuclear Power Plant Design for Reduction of Vulnerability to Sabotage". Final responsibility for selection of criteria belongs w/NRC. STARK, S J General Electric Co MFN-179-83 83/09/29 FIDRAVANTE, N E Auxiliary Systems Branch 7pp 20623 281

B310040572 Forwards responses to 830728 request for addl info required to resolve open items in Franklin Research Ctr technical evaluation rept on control of heavy loads. Info on Sections 2a & 2b re turbine bldg crane to be submitted by 831024. MUSOLF, D Northern States Power Co 83/09/27 Office of Nuclear Reactor Regulation, Director 5pp 20622 270 24X Fiche 50-263, 83/09/27, 8310040572

B310040597 Forwards response to draft technical evaluation rept assessing conformance w/general load handling guidelines of NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants." Addl response will be provided by 831115. LEMPQES, T E Niagara Mohawk Power Corp 83/09/30 EISENHUT, D O Division of Licensing 9pp 20625 327 24X Fiche 50-220, 83/09/30 8310040597

B310050144 Discusses 830307 & 17 ltrs re pressurized thermal shock flux reduction Commitment to fuel mgt plan for Cycle 6 & estimated schedules for fuel mgt plans to be used in subsequent cycles requested in 30 days. EISENHUT, D O Division of Licensing 83/09/12 HUKILL, H D General Public Utilities - GPU Service Corp 5pp 20630 209 24X Fiche 50-289, 83/09/12, 8310050144

NONDOCKETED ITEMS

443

8310040413 Forwards "HB Robinson Fluence Reduction Analysis for Partial-Length Shield Assembly Concept," documenting results of flux reduction program to resolve pressurized thermal shock issue
CUTTER, A B Carolina Power & Light Co LAP-83-439 83/09/30
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
20641 291 24X Fiche 50-261,83/09/30,8310060413

--8310060418 R-83-030
"HB Robinson Fluence Reduction Analysis for Partial-Length Shield Assembly Concept"
* Technology for Energy Corp * Carolina Power & Light Co
83/09/30 198pp 20641 293 24X Fiche 50-261,83/09/30,
8310060413

8310070216 "Resolution of Generic Issue C-8, 'MSIV Leakage & Leak Control Sys Failure, Task 2 Base Case Benchmark Calculation," 1tr rept
MURPHY, D W, ES910, T H Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2529 83/09/23 RIDGELY, J Office of Nuclear Reactor Regulation, Director 8pp 20679 345

8310070408 Forwards SER re control of heavy loads based on util response to 801222 generic ltr Guidelines in NUREG-0612, Section 5.1.1 & 5.3 satisfied
VARGA, S A Operating Reactors Branch 1 83/09/20 DOLAN, J Indiana & Michigan Electric Co 2pp 20675 332 24X
Fiche 50-315,83/09/20,8310070408

--8310070409 Safety evaluation re control of heavy loads Guidelines in NUREG-0612, Section 5.1.1 & 5.3 satisfied
* NRC - No Detailed Affiliation Given 83/09/20 2pp
20675 334 24X Fiche 50-315,83/09/20,8310070408

--8309040263 TER-C5506-344/345
"Control of Heavy Loads (C-10) Indiana & Michigan Electric Co, DC Cook Nuclear Plant Units 1 & 2," technical evaluation rept
VOSBURY, F W Franklin Institute/Franklin Research Center
NRC-03-81-130 TAC 07981 83/09/01 SINGH, A NRC - No Detailed Affiliation Given 33pp 20675 336 24X Fiche 50-315,83/09/20,
8310070408

8310110345 NUREG-1018
SEISMIC QUALIFICATION OF EQUIPMENT IN OPERATING PLANTS
Status Report, Unresolved Safety Issue A-46
CHANG, T Y Division of Safety Technology 83/09/30 87pp
Available at NRC 44 50 20714 074

8310110454 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept re NUREG-0612, "Control of Heavy Loads (Phase I)" Phase I acceptable Need for single failure-proof handling equipment will be addressed in Phase II
STOLZ, J F Operating Reactors Branch 4 83/09/21 DAUER, E O Philadelphia Electric Co 3pp 20712 076 24X
Fiche 50-277,83/09/21,8310110454

--8310110459 Safety evaluation re util 810618, 1222, 820520, 1023 & 83081C responses to NUREG-0612, "Control of Heavy Loads (Phase I)" Phase I acceptable
* NRC - No Detailed Affiliation Given 83/09/09 2pp
20712 079 24X Fiche 50-277,83/09/21,8310110454

8310110492 Requests brief summary of key points made during 830818 telcon & results of flux reduction program due to revised results for surveillance wall capsule 263 Submittal requested within 120 days of ltr receipt
MILLER, J R Operating Reactors Branch 3 83/09/24 GARRITY, J H Maine Yankee Atomic Power Co 3pp 20714 357 24X
Fiche 50-309,83/09/24,8310110492

8310120252 Forwards response to Phase I of NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants," per BJ Youngblood 830811 request for addl info All cranes & hoists purchased to Sargent & Lundy specs
WILLIAMS, J Cincinnati Gas & Electric Co L02-83-0163 83/10/04
DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp.
20692 103 24X Fiche 50-358,83/10/06,8310120252

8310120407 Forwards nonproprietary rept & Suppl 1 to "HB Robinson Unit 2, Cycle 10 SAR" Also forwards proprietary "ECCS & Plant Transient Analyses" & "Mechanical Design Rept" Repts withheld (ref 10CFR2 790)
UTLEY, E E Carolina Power & Light Co LAP-83-446 83/10/05
VARGA, S A Operating Reactors Branch 1 14pp 20697 176 24X
Fiche 50-261,83/10/05,8310120407

--8310120415 XN-NF-83-72
Nonproprietary "HB Robinson Unit 2, Cycle 10 SAR"
STONE, I Z, ADAMS, F T, LAMBERT, W L Exxon Nuclear Co, Inc (subs of Exxon Corp) 83/09/01 37pp 20697 188 24X
Fiche 50-261,83/10/05,8310120407

--8310120422 XN-NF-83-72 801
Nonproprietary Suppl 1 to "HB Robinson Unit 2, Cycle 10 SAR"
STONE, I Z, ADAMS, F T, LAMBERT, W L Exxon Nuclear Co, Inc (subs of Exxon Corp) 83/09/14 28pp 20697 227 24X
Fiche 50-261,83/10/05,8310120407

8310180132 Motion for summary disposition of Contention I-62
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/12 Atomic Safety and Licensing Board Panel
1p 20807 097 24X Fiche 50-352,83/10/12,8310180132

--8310180139 Memorandum in support of motion for summary disposition of Contention I-62 re pressurized thermal shock (PTS) PTS will not be problem due to conservative design, matl selection, const, testing, operation & surveillance
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/12 Atomic Safety and Licensing Board Panel 15pp 20807 098 24X Fiche 50-352,83/10/12,8310180132

8310180166 Forwards FSAR Section 9.1 re reactor bldg crane, revised in response to NUREG-0612 Changes will be incorporated into next FSAR amend
CURTIS, N W Pennsylvania Power & Light Co PLA-1847 83/10/13
SCHWENGER, A Licensing Branch 2 28pp 20809 001 24X
Fiche 50-388,83/10/13,8310180166

8310180193 Forwards response to requests for addl info re special lifting devices used for control of heavy loads (ref NUREG-0612)
HAIR, J E Pacific Gas & Electric Co 83/10/12 CRUTCHFIELD, D Operating Reactors Branch 5, 22pp 20809 061 24X
Fiche 50-244,83/10/12,8310180193

8310180381 Suppl 830720 response to Generic Ltr 81-07, "Control of Heavy Loads," in response to NRC finding in IE Insp Rept 83-11, dtd 830420. Info documents util methodology for compliance w/NUREG-0612 & ANSI N 14.6
UHRIG, R E Florida Power & Light Co 0L-81-07 83/10/07
EISENHUT, D O Division of Licensing 2pp 20803 201, 24X
Fiche 50-250,83/10/07,8310180381

8310180473 Responds to 831006 request for addl info re changes to emergency & abnormal procedures following review of Preliminary Safety Concern 22-82, "Potential for Pressurized Thermal Shock"
WESTAFER, O R Florida Power Corp 3F-1083-11 83/10/14,
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 20802 028 24X Fiche 50-302,83/10/14,8310180473

8310200050 Forwards Franklin Research Ctr draft technical evaluation rept re control of heavy loads, based on 830131, 0502, 06 & 0610 responses to NRC requests for addl info Telcon will be arranged after 831028 to discuss comments
STOLZ, J F Operating Reactors Branch 4 83/10/06 CROUSE, R P Toledo Edison Co 3pp 20844 299, 24X Fiche 50-346,83/10/06,
8310200050

--8308180560 TER-C5506-348 DRFT
"Control of Heavy Loads (C-10), Toledo Edison Co, Davis-Beesse Nuclear Power Station Unit 1," draft technical evaluation rept.
BOMBERGER, C J, AHMED, N Franklin Institute/Franklin Research Center NRC-03-81-130 TAC 10993 83/08/09 SINGH, A NRC - No Detailed Affiliation Given 33pp 20844 302 24X
Fiche 50-346,83/10/06,8310200050

8310200260 Responds to EQ40 Phase I recommendations re special lifting device, per NUREG-0612, "Control of Heavy Loads" Util 830509 commitment to restrict crane hoist speeds reduced possibility of overstress in lifting devices
SCHUYLER, J O Pacific Gas & Electric Co 83/10/14 KNIIGHTON, Q W Licensing Branch 3 8pp 20830 078 24X Fiche 50-275,83/10/14,
8310200260

8310200284 Addresses SEP Topic V-6, "Reactor Vessel Integrity," documented in NUREG-0369, "Evaluation of Integrity of SEP Reactor Vessels" SEP Topic V-6 resolved as result of evaluation performed per pressurized thermal shock issue
KRIEGER, R W Southern California Edison Co 1E8-78-12 83/10/13
CRUTCHFIELD, D Operating Reactors Branch 5, 2pp 20829 320 24X
Fiche: 50-206,83/10/13,8310200284

8310240235 Responds to FOIA request for three documents to be placed PDR Forwards documents listed in app
FELTON, J M Division of Rules and Records 83/07/11 PEDRO, J N Corp 2pp 20891 225

--8102260210 Summary of 801217 meeting w/utilis & vendors in Bethesda, re inclusion of linear elastic fracture mechanics in resolution of potential for low fracture toughness & lamellar tearing on component supports
BNAIDER, R Generic Issues Branch 80/12/30 KNIEL, K Generic Issues Branch 8pp 20891 233

NONDOCKETED ITEMS

--801030238 Notification of 800903 meeting w/GE in Bethesda, MD to discuss proposed BWR feedwater nozzle leakage detection sys
SNAIDER, R P Systematic Evaluation Program Branch 80/08/14
KNIEL, K Generic Issues Branch 1p 20891 228

--8011190749 Summary of 800903 meeting w/GE to discuss draft NEDE-24265-P (proprietary) re proposed feedwater nozzle surveillance instrumentation sys List of attendees encl
SNAIDER, R P Generic Issues Branch 80/09/15 KNIEL, K Generic Issues Branch 3pp 20891 229

8310250031 FOIA request for A Szukiewicz 820809 & 830114 memos to K Kniel, summarizing NRC 820728 & 1229-30 meetings w/EG&Q re Unresolved Safety Issue A-47, to be placed in PDR
BUCKLES, R NUS Corp CD-18-83-100 83/06/30 Division of Rules and Records 1p 20908 281

8310250032 Responds to FOIA request that A Szukiewicz 820809 & 830114 memos to K Kniel, summarizing NRC 820728 & 1229-30 meetings w/EG&Q re Unresolved Safety Issue A-47, be placed in PDR
Forwards documents
FELTON, J M Division of Rules and Records 83/07/15 BUCKLES, R NUS Corp 1p 20908 282

--8208240121 Summary of 820728 meeting w/EG&Q, ID in Bethesda, MD re Unresolved Safety Issue A-47, "Safety Implications of Control Sys " Modeling of control sys to begin in Aug 1982
W/o handouts
SZUKIEWICZ, A J Generic Issues Branch 82/08/09 KNEIL, K Generic Issues Branch 3pp 20908 288

--8301250200 Summary of 821227 & 30 meetings w/EG&Q in Idaho Falls, ID re status & progress of Browns Ferry plant review & progress on Unresolved Safety Issue A-47 concerning safety implications of control sys. Agenda & attendance list encl
SZUKIEWICZ, A J Generic Issues Branch 83/01/14 KNIEL, K Generic Issues Branch 3pp 20908 283

8310270071 Responds to FOIA request for five separate categories of documents. Forwards App A documents responsive to Items 1, 2 & 3 of request Item 4 re LWR hydrogen manual should be published during Sept 1983 Item 5 not available
FELTON, J M Division of Rules and Records 83/07/14 HIATT, B L Ohio Citizens for Responsible Energy 2pp 20942 272

--8310270075 Draft "Grouping of LWRs for Evaluation of DHR Capability " KAROL, R, FRESCO, A, PERKINS, K R Brookhaven National Laboratory 82/12/31 NRC - No Detailed Affiliation Given 77pp, 20942 278

8310270377 Responds to 830826 request for review of draft task action plan for Generic Issue A-29 "Nuclear Power Plant Design for Reduction of Vulnerability to Sabotage " Div of Sys Integration should manage technical aspects of plan
EISENHUT, D O Division of Licensing 83/10/18 MATTSO, R J Division of Systems Integration (post 811005) 2pp 20943:111

8309080358 Forwards task action plan for Generic Issue A-49, "Nuclear Power Plant Design for Reduction of Vulnerability to Sabotage " Scope of task expanded to include consideration of sabotage vulnerability in existing plants.
MATTSO, R J Division of Systems Integration (post 811005). 83/08/26 EISENHUT, D O Division of Licensing 2pp, 20943.113

8309080363 Task Action Plan A-29 "Nuclear Power Plant Design for Reduction of Vulnerability to Sabotage " FIORAVANTE, N Auxiliary Systems Branch 83/08/26 7pp 20943 115

8310280123 Responds to 830912 ltr re fuel mgt plan for Cycle 4 & estimated schedules for fuel mgt plans used to meet pressurized thermal shock flux reduction Commit to in-out-in fuel mgt plan
HUMILL, H D General Public Utilities - OPU Service Corp 8211-83-309 83/10/24 EISENHUT, D O Division of Licensing 2pp 20929 244 24X Fiche 50-289, 83/10/24, 8310280123

8310310446 NUREG-0577 R01
POTENTIAL FOR LOW FRACTURE TOUGHNESS AND LAMELLAR TEARING IN PWR STEAM GENERATOR AND REACTOR COOLANT PUMP SUPPORTS
Unresolved Safety Issue A-12
+ Division of Safety Technology 83/10/31 70pp Available at NRC. #4 50 21000.304.

8310310445 Summarizes ACRS 282nd meeting on 831013-15 on NRC integrated program for resolution of Unresolved Safety Issues A-3, A-4 & A-5 re PWR steam generators. Proposals should be implemented as recommendations only.
RAY, J. J. ACRS - Advisory Committee on Reactor Safeguards. 83/10/18 PALLADINO, N J Commissioners. 1p. 20965:160.

I&E INSPECTION AND ENFORCEMENT

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20777 350 24X Fiche 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378

8308300689 PND-I-83-087A on 830824, patient orally administered 100 mCi Tc-99m labelled DTPA for gastric emptying study instead of 100 uCi Caused by typographical error in written procedures
Procedures revised
NICOLosi, J Region 1, Office of Director 83/08/26 1p 20206 281

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20682 026 24X Fiche 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning, Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129, 24X Fiche 50-000, 83/10/11, 8308300761

8308310105 EN-83-055 on 830901, notice of violation & proposed imposition of civil penalty will be issued in amount of \$2,500 based on multiple examples of radiation safety program failure
FLACK, E, AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/08/29. 1p 20227 027

8308310330 PND-I-83-090 on 830826, employee film badge for Jul 1983 showed exposure of 7.77 rem Badge exposure not believed to be actual exposure to employee Addl info requested from badge vendor to determine source of exposure
FRIEDMAN, L, GLENN, J Region 1, Office of Director 83/08/26 1p 20227 203

8310030440 EN-83-060 on or about 830929, notice of violation & proposed imposition of civil penalty in amount of \$100,000 will be issued to licensee Action based on inadequate reassessment of fire protection features, per 10CFR50, App R
GREGG, J, AXELRAD, J Office of International Programs, Director 83/09/26 1p. 20602 089 24X Fiche 50-344, 83/09/26, 8310030440

8310030461 PND-II-83-078 on 830925, recriticality achieved after 1-yr shutdown to modify drywell cooling sys & other areas Low power physics testing will be conducted during next 3-wk period
WATSON, L., JULIAN, C A Region 2, Office of Director 83/09/26 1p 20601 048 24X Fiche 50-416, 83/09/26, 8310030461

NONDOCKETED ITEMS

445

8310030476 PNO-IV-83-029 on 830926, unit shut down due to inability to comply w/Tech Spec action statement following discovery that station battery 2011 failed quarterly surveillance test on 830922 Condition not recognized by mgt until 830926
JOHNSON, W D, CALLAN, L J Region 4, Office of Director 83/09/27
ip 20601 066 24X Fiche 50-368, 83/09/27, 8310030476

8310030520 EN-83-014A on 830318, notice of violation & proposed imposition of civil penalties in amount of \$4,000 issued to licensee Action based on failure to adhere to license conditions while administering radiolodine
FLACK, E, AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/09/29 ip 20601 185

8310040213 PMS-I-83-019 on 830923, licensee contract security organization suspended two security guards Guard admitted to bringing illegal substance on site Other guard did not report incident Both guards terminated 830926
MADDEN, W, GODY, A Region 1, Office of Director 83/09/28 ip 20614 273 24X Fiche 50-272, 83/09/28, 8310040213

8310040214 EN-83-032A on 830503, notices of violation & proposed imposition of civil penalty in amount of \$80,000 issued to Util based on violation of Tech Spec requirement & failure to adequately implement aspects of QA program
KLINGLER, G, AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/09/29 ip 20617 240 24X Fiche 50-272, 83/09/29, 8310040214

8310040396 PNO-V-83-041 on 830929, approx 60 items discovered in unrestricted storage areas Surveys continuing Press release expected
WENSLAWSKI, F, KIRSCH, D Region 5, Office of Director 83/09/29 ip 20619 168 24X Fiche 50-206, 83/09/29, 8310040396

8310040455 PNO-I-83-099 on 830930, contract for bargaining unit (Util Workers Union of America, Local 497) expires if strike occurs, insp will be provided to confirm of plant transition by mgt personnel
HOLDEN, C, HIGGINS, J, GREENMAN, E Region 1, Office of Director 83/09/29 ip 20623 325 24X Fiche 50-309, 83/09/29, 8310040455

8310030536 EN-83-063 on 831007, notice of violation & proposed imposition of civil penalty in amount of \$8,000 will be issued, based on failure to follow emergency procedures & to perform survey, causing radiation exposure to individual
FLACK, E, AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/10/05 ip 20630 339

8310060005 EN-83-061 on 831006, notice of violation & proposed imposition of \$40,000 civil penalty will be issued based on Util failure to place main steam line high radiation trip sys in tripped condition when both channels inoperable
KLINGLER, G, AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/10/03 ip 20649 294 24X Fiche 50-220, 83/10/03, 8310060005

8310060040 PNO-I-83-098A strike of Intl Brotherhood of Electrical Workers possible after contract expires Union meeting to vote on licensee proposal set for 831005 Licensee contingencies in event of strike acceptable
TRIPP, L, KEIMIG, R Region 1, Office of Director 83/09/30 ip 20647 084 24X Fiche 50-334, 83/09/30, 8310060040

8310060051 PNO-I-83-100 on 830929, potential overpressurization of low pressure piping at pump suction occurred Event attributed to malfunctioning check valve Seal leak repaired Valve apparently stuck partially open
JOHNSON, J, CALLO, R Region 1, Office of Director 83/09/30 ip 20647 073 24X Fiche 50-293, 83/09/30, 8310060051

8310060092 EN-83-062 on 831006, notices of violation & proposed imposition of \$1,000 civil penalty to be issued Action based on violation of Tech Specs re alterations made to core configuration
CRAIG, J, AXELRAD, J Director's Office, Office of Inspection and Enforcement EN-83-62 83/10/03 ip 20647 177 24X Fiche 50-062, 83/10/03, 8310060092

8310060253 PNO-I-83-009B on 830930, licensee & Util Workers of America negotiations failed to produce settlement Operations turned over to supervisory personnel Settlement approved by union membership on 831001
HOLDEN, C, HIGGINS, J, GREENMAN, E Region 1, Office of Director 83/10/03 ip 20647 033 24X Fiche 50-309, 83/10/03, 8310060253

8310060264 PNO-III-83-091 on 831001, 6-month outage commenced for refueling, routine maint & replacement of two steam generators Authorization to replace generators received on 830930
JACKMAN, I, SHAFER, W Region 3, Office of Director 83/10/03 ip 20645 265 24X Fiche 50-266, 83/10/03, 8310060264

8310060344 Updated PNO-I-83-099A on 830930, negotiations continuing between Util & Util Workers of America to settle terms of contract expiring at midnight Plans in place for NRC insp coverage of operations to ensure smooth mgt transition
HOLDEN, C, HIGGINS, J, GREENMAN, E Region 1, Office of Director 83/09/30 ip 20646 127 24X Fiche 50-309, 83/09/30, 8310060344

8310060428 PNO-III-83-089 on 830929, temporary restraining order requested to prevent shipment of spent reactor fuel through State of OH denied Pretrial conference set for 831006 Local govts alleged inadequate preparation by local agencies
STRASNA, J, HENCZAR, W Region 3, Office of Director 83/09/30 2pp 20641 221 24X Fiche 50-000, 83/09/30, 8310060428

8310070333 PNO-V-83-042 on 830929, unusual event declared when unidentified leakage from RCS of 1 l9 gpm discovered Caused by high penalty factor applied in response to 1 h observation Reactor & sys normal after 20% trip test
KIRSCH, D Region 5, Office of Director 83/09/29 ip 20651 002 24X Fiche 50-362, 83/09/29, 8310070333

8310110191 EN-83-064 on 831006, notice of confirmatory order for mod of CPs issued Order requires const implementation overview program to provide reasonable assurance that facility can be completed in accordance w/regulatory requirements
STONE, J, HEISHMAN, R Director's Office, Office of Inspection and Enforcement 83/10/06 ip 20665 007 24X Fiche 50-329, 83/10/06, 8310110191

8310120065 PNO-V-83-043 on 830929, two manual valves incorrectly closed, isolating all charging pump flow to RCS Plant being shut down due to excessive leakage from RCS On 830930, Tech Spec violation recognized & valves opened.
ECKHARDT, J Region 5, Office of Director 83/10/03 ip 20658 296 24X Fiche 50-362, 83/10/03, 8310120065

8310120066 PNO-V-83-044 on 831003, employee suffered heart attack during work Personnel taken to hosp No news release planned
MORRILL, M J Region 5, Office of Director 83/10/04 ip 20676 157 24X Fiche 50-275, 83/10/04, 8310120066

8310120124 PNO-I-83-103 on 831004, licensee commenced 6-day outage to repair moisture separator reheater tube leaks Leaks indicated in four of six reheaters Unit will be maintained in hot shutdown Cooling fan motors replaced
KENNY, T, KISTER, W Region 1, Office of Director 83/10/05 ip 20676 154 24X Fiche 50-247, 83/10/05, 8310120124

8310120230 PNO-III-83-085 on 830913, decontamination of onsite & offsite facilities completed as result of 830913 source damage incident Licensee must submit decontamination plan by 831019
WIDEMAN, D, HIND, J Region 1, Office of Director 83/10/06 ip 20692 178

8310120231 PNO-V-83-038A on 830917, plant shut down following discovery of steam generator A tube leak One insp lane tube (78-2) plugged on 830927 Two of 360 tubes inspected showed localized thinning of approx 25%
JOHNSON, P, YOUNG, T Region 5, Office of Director 83/10/03 ip 20692 107 24X Fiche 50-312, 83/10/03, 8310120231

8310120256 PNO-III-83-090 on 830930, licensee notified resident inspector of allegation of improper training & certification of individuals conducting reviews of safety-related records for HJ Kaiser Co, principal site contractor
SCHEIDT, E, FORNEY, W Region 3, Office of Director 83/10/03 ip 20691 330 24X Fiche 50-358, 83/10/03, 8310120256

8310120306 PNO-I-83-102A on 831004, 50 Ci Co-60 radiography source retrieved w/o incident No contamination indicated in recovery area Source loaded into exposure device & will be leak tested before being placed in svc.
NICLOSI, J, KINNEMAN, J Region 1, Office of Director 83/10/05 ip 20701 011

8310120309 PNO-III-83-093 on 830930, facility shut down for scheduled refueling outage Licensee expected to conduct ultrasonic testing of large diameter stainless steel pipe in drywell, per NRC order Insp will continue for 16 wks
TONGUE, T, WALKER, R Region 3, Office of Director 83/10/03 ip 20701 009 24X Fiche 50-249, 83/10/03, 8310120309

8310120321 PNO-V-83-039A on 830919, PDV opened at 29 psig due to addl weight of indicating rod added to operating handle during recent refueling outage Rod removed, PDV closed on 830929 by placing V nitrogen bubble in pressurizer
JOHNSON, P, YOUNG, T Region 5, Office of Director 83/10/03 ip 20700 299 24X Fiche 50-312, 83/10/03, 8310120321

NONDOCKETED ITEMS

- 8310120446 PNO-III-83-092 on 831004, marijuana found in truck owned by carpenter employed by Bechtel Corp Individual fired by Bechtel & left site No action planned by Region III State of HI will be notified
HARRISON, J., HARNICK, R. Region 3, Office of Director 83/10/04
ip 20698 325 24X Fiche 50-329, 83/10/04, 8310120446
- 8310140038 PNO-I-83-106 on 831007, plant shutdown from 100% power due to apparent hydrogen leakage into generator stator water cooling sys. Similar occurrence on 830819 resulted in 5-wk outage States of NJ & DE informed
LINVILLE, J., JACOBS, R., NORRHOLM, L. Region 1, Office of Director 83/10/07
ip 20748 083 24X Fiche 50-311, 83/10/07, 8310140038
- 8310140060 EN-83-065 on 831013, order to show cause & order temporarily suspending license, effective immediately, issued Action based on 830928 & 30 insps revealing that personnel monitoring devices & survey meter not obtained.
KLINGLER, G., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/10/13
ip 20768 001
- 8310140068 PNO-I-83-104, on 830704, during RHR & recirculation piping weld insp, 20 of 126 welds examined evidenced intergranular stress corrosion cracking Licensee repairing 16 welds by clad overlay technique
BLOUGH, A. R., TRIPP, L. E. Region 1, Office of Director 83/10/07
ip 20764 359 24X Fiche 50-277, 83/10/07, 8310140068
- 8310140082 PNO-I-83-105 on 831007, seismic event occurred in northeastern US w/ magnitude of 5.2 on Richter scale in NY & 4.0 in NH No damage to equipment identified
GALLO, R. M., GREENHANE, G. Region 1, Office of Director 83/10/07
ip 20766 116 24X Fiche 50-000, 83/10/07, 8310140082
- 8310140090 PNO-III-83-095 on 831005, B&W issued stop work order on Class I piping hanger installation Stop work applies to both small bore & large bore piping & is based on deficiencies identified in hangers during Bechtel insp
HARRISON, J., GARDNER, R. Region 3, Office of Director 83/10/06
ip 20767 039 24X Fiche 50-329, 83/10/06, 8310140090
- 8310140142 PNO-II-83-080 on 831007, tank truck loaded w/sand & water containing 10 mCi Ir-192 leaked when sand tracer slurry pumped out into remote well in Ritchie County, WV Contaminated sand & soil being held by licensee for decay
POTTER, J. P., COLLINS, D. M. Region 2, Office of Director 83/10/11
ip 20763 020
- 8310140153 PNO-V-83-046 on 831003, while in Mode 3 & attempting to determine why LP turbine stop valve would not fully shut, discovered debris inside moisture separator reheater Turbine not damaged
ECKHARDT, J. Region 5, Office of Director 83/10/04
ip 20762 362 24X Fiche 50-362, 83/10/04, 8310140153
- 8310140237 EN-83-066 on 831013, order to show cause & order temporarily suspending license issued, effective immediately Insp on 831006-07 revealed unauthorized persons using moisture gauges containing radioactive matl
FLACK, E., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/10/13
ip 20762 040
- 8310140255 PNO-III-83-094, on 830930, contamination found on empty spent fuel cask shipped from facility Trailer used to transport empty spent fuel casks experienced brake problems on 831005 All shipments under insp
LOVENDALE, P., GREGER, L. R. Region 3, Office of Director 83/10/06
2pp 20759 238 24X Fiche 50-266, 83/10/06, 8310140255
- 8310140284 PNO-V-83-045 on 831003, two reactor trip breakers failed 30 day surveillance test Cause of failure under investigation Breakers placed in open position & replaced w/ spares
ECKHARDT, J. Region 5, Office of Director 83/10/04
ip 20759 236 24X Fiche 50-361, 83/10/04, 8310140284
- 8310170310 PNO-I-83-103A on 831004, licensee began unscheduled outage to repair moisture separator reheater tube leaks NRC notified on 831011 of reactor coolant leak on steam generator 22 hot leg manway Plant will be in cold shutdown for repairs
FOLLEY, T., JACOBS, R., NORRHOLM, L. Region 1, Office of Director 83/10/12
ip 20786 131 24X Fiche 50-247, 83/10/12, 8310170310
- 8310180199 EN-83-068 on 831019, notice of violation & proposed imposition of civil penalties in amount of \$2,000 to be issued to licensee Action based on 12 apparent violations re use of byproduct matls by unauthorized individuals
FLACK, E., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/10/14
ip 20807 053
- 8310180413 EN-83-067 notice of violation & proposed imposition of civil penalty in amount of \$2,000 will be issued re eight examples of failure to comply w/NRC requirements, one involving unauthorized use of nuclear moisture density gauge
FLACK, E., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/10/17
ip 20803 311
- 8310180446 PNO-III-83-096 on 831011, during routine inservice insp, small crack discovered on 6-inch piping in reactor water cleanup sys Crack not in sys affected by NRC 830823 order or IE Bulletins 82-03 & 83-02 Situation being evaluated
DANIELSON, D., WALKER, R. Region 3, Office of Director 83/10/13
ip 20801 343 24X Fiche 50-265, 83/10/13, 8310180446
- 8310180467 PNO-I-83-107 on 831011, trip from full power occurred when main feedwater pump 22 tripped Containment sump pumping frequency increased due to stopping & restarting of reactor coolant pump Plant cooldown began 831012 to repair sump
TRIMBLE, D., SWETLAND, P. Region 1, Office of Director 83/10/12
ip 20802 031 24X Fiche 50-318, 83/10/12, 8310180467
- 8310190236 PNO-II-83-082 on 831015, control room operator trainee killed instantly when fist-sized hole blew open in wall of 24-inch carbon steel pipe attached to high pressure feedwater drain pump Cause under investigation
LANDIS, K., DANCE, H. Region 2, Office of Director 83/10/17
2pp 20818 078 24X Fiche 50-280, 83/10/17, 8310190236
- 8310200152 PNO-III-83-097 on 831013, 13 maint & janitorial workers at site resigned due to internal investigation re marijuana & alcohol use during working hours All safety-related const suspended
HILL, W., FORNEY, W. Region 3, Office of Director 83/10/14
ip 20836 321 24X Fiche 50-358, 83/10/14, 8310200152
- 8310200160 PNO-I-83-108 on 831013, film badge exposed to 3,370 mrem during month of Aug 1983 Licensee conducting investigation to determine validity of preliminary findings Event not considered to be whole body exposure
DAVIS, J., KINNEHAN, J., JOYNER, J. Region 1, Office of Director 83/10/14
ip 20834 093
- 8310200176 PNO-V-83-047 on 831011, licensee received notification from Radiation Detection Co of one film badge indicating potential whole body exposure of 18 rem Film badge not representative of exposure
SHERMAN, C., WENSLAWSKI, F. Region 5, Office of Director 83/10/12
ip 20835 315 24X Fiche 50-224, 83/10/12, 8310200176
- 8310210030 EN-83-069 on 831026, notice of violation & proposed imposition of civil penalty in amount of \$100,000 to be issued Action based on fireline relocation activities performed in "B" soils w/o prior NRC authorization
KLINGLER, G., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/10/20
ip 20853 344 24X Fiche 50-329, 83/10/20, 8310210030
- 8310210122 PNO-III-83-099 on 831015, unit shut down for steam generator tube leak exam & repair Unit will be shut down for 2-3 wks Region & resident inspector will monitor course of action
BOYD, D., SHAFER, W. Region 3, Office of Director 83/10/17
ip 20858 250 24X Fiche 50-316, 83/10/17, 8310210122
- 8310210151 PNO-III-83-098 on 831014, Region III informed of discovery of circumferential crack indications in steam generator tubes near & in support plates, identified during eddy current testing Util estimates 20 to 50% of tubes affected
HOLZNER, M., BOYD, D. Region 3, Office of Director 83/10/14
ip 20855 318 24X Fiche 50-255, 83/10/14, 8310210151
- 8310250065 PNO-III-83-084 licensee identified & reported to NRC that contractor welding svc employee received 59 mrem occupational overexposure during Third Quarter 1983 Licensee reviewing all circumstances associated w/event
DEBS, B., GIBSON, A. F. Region 2, Office of Director 83/10/20
ip 20876 085 24X Fiche 50-259, 83/10/20, 8310250065
- 8310250335 PNO-V-83-049 on 831018, const craft person injured working on 12 kv circuit breaker Workman accidentally contacted hot const power supply circuit, smoke observed coming from manhole, Plant unaffected
MORRILL, P. Region 5, Office of Director 83/10/19
ip 20878 127 24X Fiche 50-206, 83/10/19, 8310250335
- 8310250543 PNO-V-83-048 on 831013, Region V notified by NRR of temp compensation error w/Barton Model 760 pressure transmitters Same problem exists w/Model 764 steam generator narrow-range water level transmitters Setpoints revised on 831014
HAIST, D. Region 5, Office of Director 83/10/18
ip 20901 323 24X Fiche 50-344, 83/10/18, 8310250543

NONDOCKETED ITEMS

447

8310270224 PNO-11-83-085 during ultrasonic exam of 28-inch recirculation sys discharge piping, suspect indications identified in two welds Addl analyses of data for proper categorization continuing State of NC informed
BLAKE, J, HARDIN, A Region 2, Office of Director 83/10/21 1p
20924 044 24X Fiche 50-325, 83/10/21, 8310270224

8310270384 PNO-11-83-102 on 831020, security officer received bomb threat phone call from unidentified male Shift engineer instituted emergency procedures Search of vital areas conducted w/negative results Threat determined hoax
BLANGER, J, CREED, J Region 3, Office of Director 83/10/21 1p
20923 287 24X Fiche 50-295, 83/10/21, 8310270384

8310270487 PNO-11-83-101 on 831021, licensee employee discovered suspicious looking package near equipment on third level of turbine bldg Portion of bldg evacuated & MI State Police notified Package dismantled & confirmed nonexplosive
CREED, J Region 3, Office of Director 83/10/21 1p 20922 001
24X Fiche 50-341, 83/10/21, 8310270487

8310310258 PNS-V-83-010 on 830912, latest bimonthly physical inventory indicated difference (ID gain) occurred in high enriched U HTOR Fuel mfg area Past IDs did not exceed limit of error Current gain reduces cumulative ID by one half
WIEDER, A V, NELSON, G B Region 5, Office of Director 83/10/20 2pp 20947 160

8310310275 PNO-11-83-106 on 831025, two men in pickup truck parked outside facility delivered bomb threat Training reactor shut down & bldg searched No bomb discovered
KERS, D A, CREED, J R Region 3, Office of Director 83/10/26 1p
20947 114 24X Fiche 50-087, 83/10/26, 8310310275

8310310284 PNS-V-83-011 on 831024, San Francisco Chronicle published article re use & sale of illegal drugs by current & former facility personnel Drug-related accidents or injuries not cited Repts believed to be untrue or exaggerated
SCHAFER, D W, NORDERHAUG, L R Region 5, Office of Director 83/10/24 1p 20961 282 24X Fiche 50-206, 83/10/24, 8310310284

8310310318 PNO-11-83-105 on 831025, Troxler soil density & moisture gauge, Model 3401B, containing 10 mCi Cs-137 & 50 mCi Am-241 reportedly stolen from const site
WIEDERMAN, D O, AXELSON, W L Region 3, Office of Director 83/10/26 1p 20961 213

8310310361 PNO-1-83-109 on 831024, licensee reported that radiographs associated w/Class I piping improperly read by vendor during outage mod work in 1981 & 1982 Part 21 implications under evaluation
BLOUGH, A R, TRIPP, L E Region 1, Office of Director 83/10/25 1p 20961 121 24X Fiche 50-277, 83/10/25, 8310310361

8310310406 EN-83-070 on 831103, notice of violation & proposed imposition of civil penalty will be issued in amount of \$4,000. Action based on breakdown in mgt oversight & control of radiation safety program
FLACK, E, AXELRAD, J Director's Office, Office of Inspection and Enforcement EN-83-070 83/10/27 1p 20959 183

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

8310030131 Comments on review of draft NUREG re LER sys, per 830829 request
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/09/26 HELTEMES, C J Director's Office 50pp 20603 148

--8309070071 Forwards draft NUREG on revised LER sys Comments requested by 830914
HELTENES, C J Director's Office 83/08/29 DENTON, H R Office of Nuclear Reactor Regulation, Director DEYOUNG, R C Director's Office, Office of Inspection and Enforcement MINOQUE, R B Office of Nuclear Regulatory Research, Director 108pp 20603 149

8310060134 Requests results of review be sent to F Miraglia by 831003 re EPRI list of 254 generic safety issues classified as not applicable to design certification, in EPRI standardized LWR plant design evaluation program
EISENHUT, D G Division of Licensing 83/09/21 SPEIS, T Division of Safety Technology VOLLMER, R H Division of Engineering MATTSOHN, R J Division of Systems Integration (post 811005) 1p 20661 008

8310060142 Forwards "Procedures for Regional Implementation of Operator Licensing Functions"
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/09/21 COLLINS, J T Region 4, Office of Director MARTIN, J B Region 5, Office of Director 2pp 20661 001

--8310060143 "Procedures for Regional Implementation of Operator Licensing Functions"
DENTON, H R Office of Nuclear Reactor Regulation, Director 82/11/22 3pp 20661 003

8310060355 Forwards response to 830729 ltr requesting info re purchase of flanges from Ray Miller, Inc
LETSCHE, D E Letco, Inc 83/09/27 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 20646 090

8310060515 Expresses regret for cancellation of 830907 meeting w/ Z Rehtblatt re alleged flaws in ANSI/ANS-56 B-1981 & App J to 10CFR50 concerning containment leak rate testing Concerns should be directed to RES
KEPPLER, J C Region 3, Office of Director 83/09/14 WHICHER, J M Businessmen for the Public Interest 3pp 20662 362

8310070125 Responds to 830921 ltr re Ray Miller, Inc substandard matl. All Ray Miller, Inc matl purchased used in mfg of form chemicals
HOESCHAR, E E Allied Chemical Corp 83/09/30 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 20659 021

--8310070129 Advises that Allied Chemical Corp was end user for all Ray Miller, Inc substandard matl listed on encl computer printout
HOESCHAR, E E Allied Chemical Corp 83/09/30 NRC - No Detailed Affiliation Given 3pp 20659 022

8310070285 Ack receipt of 830919 ltr re detection of deficiencies in quality resulting from fraudulent actions by suppliers QA program instituted.
YENZER, B E Ebasco Services, Inc (subs of Enserch Corp) 83/09/29 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 20657 001

8310110570 Forwards documents to be placed on document control sys
MONTGOMERY, J M Office of Policy Evaluations 83/10/03 Document Management Branch 28pp 20715 200

--8310110579 Forwards 821008 proposal entitled "Backfitting Rule," urg Commission not to publish advanced notice of proposed rulemaking
WALSH, C Atomic Industrial Forum 83/07/07 PALLADINO, N J Commissioners 8pp 20715 201

--8310110588 Forwards response to 830209 memo re accuracy of costs & reasonableness of backfits Previous backfitting cost problems worthy of attention
ZERBE, J E Office of Policy Evaluations 83/05/20 AHEARNE, J F Commissioners 21pp 20715 207

8310110604 Requests re-review of final draft rept. "Seismic Qualification of Auxiliary Feedwater Sys II" Significant number of editorial problems exist
BEARD, J T Operating Reactors Assessment Branch FIN A-0429 83/09/15 LU, B Lawrence Livermore Laboratory 1p 20701-362,

8310130042 Proposes pilot project to provide desktop microcomputer terminal at each atty workstation Project would eliminate 50% of first draft retyping & improve research & analysis & atty time & work item scheduling mgt
OLMSTEAD, W J Regulations Division 83/10/06 DUBE, N L Office of the Executive Legal Director 3pp 20726-290

8310130068 Notices of informal assessment of Region I & II implementation of 10CFR50.54(P) & 10CFR70.32 licensing responsibilities Meetings scheduled for Region I on 830920 & Region II on 830922
EISENHUT, D G Division of Licensing 83/09/16 MARTIN, T. T. Division of Engineering & Technical Programs. STOMR, J P. Division of Emergency Preparedness & Materials Safety 3pp 20774-360

8310130080 Delegates & assigns certain operator licensing functions Regions IV & V Functions include processing applications, preparing, administering & grading exams & issuing & denying licenses.
DIRCKS, W J Office of the Executive Director for Operations DENTON, H R Office of Nuclear Reactor Regulation, Director 0128-83-4 83/09/21 COLLINS, J T Region 4, Office of Director MARTIN, J B Region 5, Office of Director 4pp 20777 044.

8310130128 Forwards "Development of Guidelines for Upgrading Maint Procedures in Nuclear Power Plants," interim rept.
MORSESTERN, M Battelle Human Affairs Research Centers 83/06/01 ODDMAN, M NRC - No Detailed Affiliation Given 1p 20774-260.

NONDOCKETED ITEMS

--8310130134 "Development of Guidelines for Upgrading Maint Procedures in Nuclear Power Plants," interim rept
BARNES, V E , EARLE, T C , MORGENSTERN, M Battelle Human Affairs
Research Centers 83/06/30 NRC - No Detailed Affiliation
Given 94pp 20774 261

8310140092 Advises that time for Commission to review Director's
Decision 00-83-12 expired Commission declined review
Decision became final agency action on 831011
CHILK, S J Office of the Secretary of the Commission 09-83-12
83/10/13 600DL E Affiliation Unknown 1p 20767 026

8310170302 Ack receipt of 830915 ltr re Section 2 2 2 of Generic Ltr
83-28 Concurs w/NUTAC mission to develop practical approach
that will contribute to safety & reliability of nuclear
plants
EISENHUT, D G Division of Licensing 0L-83-28 83/09/28
GRIFFING, E P Detroit Edison Co 1p 20796 238

8310180019 Comments on draft NRC/QRNL rept, "Precursor to Potential
Severe Core Damage Accident 1980-81 Status Rept," in
response to 830827 memo Foreword should be rewritten to put
use of PRA methodology in perspective for general public
EISENHUT, D G Division of Licensing 83/10/06 SPEIS, T P
Division of Safety Technology 3pp 20825 065

8310190187 Informs that, effective 831001, all correspondence re
radiological affairs support program & GW Hendrix
(Code 112N) should be forwarded to Naval Sea Sys Command
LABDON, T A Navy, Dept of, Naval Facilities Engrg Command
11277AL 83/10/14 NRC - No Detailed Affiliation Given 1p
20820 220

8310200397 Forwards draft agenda for US/Federal Republic of Germany
831019-21 technical exchange meetings in Oak Ridge, TN re
core melt
LARKINS, J T Containment Systems Branch 83/10/05 MINOGUE, R ,
ROBB, D , BASSETT, D Office of Nuclear Regulatory Research, Director
7pp 20899 211

8310210330 Notification of 831021 meeting w/NMSS in Bethesda, MD to
discuss assumptions used in vital area identification
Meeting closed to public
MCPEEK, E W Standardization & Special Projects Branch 83/10/13
THOMAS, C D Standardization & Special Projects Branch 2pp.
20884 168

8310310464 Suggests that PORFLD computer code be included in
benchmarking study to compare & evaluate several computer
codes to be used for high level waste repository analyses.
WRIGHT, R J High Level Waste Technical Development Branch 00571
83/08/24. OLSQN, O L Energy, Dept. of 1p 20965 178

NUREG NUREG REPORTS AND RELATED CORRESPONDENCE

8309120437 Provides proposed responses to questions re BER (NUREG-0853)
Confirmatory Issue 1 concerning degraded core hydrogen
control & emergency plan dose assessment reporting sys
NELSON, R M Illinois Power Co. U-0661 83/09/06 SCHWENGER, A
Licensing Branch 2 6pp 20335 248 24X Fiche 50-461, 83/09/06,
8309120437

8310030080 Forwards safety evaluation accepting snow sampling & vent
procedures subj to described mod to Item 6 35 of Procedure
8C-452 License Conditions 2 C(9)1 through 20 (ref
NUREG-0916) satisfied
CRUTCHFIELD, D Operating Reactors Branch 5 83/09/29 MAIER, J E
Rochester Gas & Electric Corp 2pp 20590 069 24X
Fiche 50-244, 83/09/29, 8310030080

--8310030082 Safety evaluation supporting snow sampling & vent procedures
subj to mod to Procedure 8C-452
* Office of Nuclear Reactor Regulation, Director 83/09/29 4pp
20590 071 24X Fiche 50-244, 83/09/29, 8310030080

8310030140 Comments on potential for flooding of plant site resulting
from failure of Quodnough Dike &/or Windsor Dam at Quabbin
Reservoir Based on Franklin Research Ctr analysis, flooding
protection measures provide protection against dam failure
CRUTCHFIELD, D. Operating Reactors Branch 5. L805-83-09-033
83/09/26 CDUNSL, W O Connecticut Yankee Atomic Power Co 4pp
20591 071 24X Fiche 50-213, 83/09/26, 8310030140

8310030141 Advises that 820715 & 0930 requests for NRC to concur w/
intent to move emergency support ctr & associated functions
from Point Beach Energy Info Ctr to Milwaukee unacceptable,
per NUREG-0737, Suppl 1 & Generic Ltr 82-33
EISENHUT, D G Division of Licensing 0L-82-33 83/09/14
BURSTEIN, S Wisconsin Electric Power Co 6pp 20604 033 24X
Fiche: 50-266, 83/09/14, 8310030141

8310030167 Forwards Amend 33 to FSAR Amend revises responses to
NUREG-0737, II K items & NRC questions & updates Sections
2 5 1, 3 1-3, 3 11-12 & 5 2 Affidavit encl
OOLDBERG, J H Houston Lighting & Power Co 87-HL-AE-993 83/09/2/
DENTON, H Office of Nuclear Reactor Regulation, Director 5pp
20593 323 24X Fiche 50-498, 83/09/27, 8310030167

--8310030168 Amend 33 to FSAR, revising responses to NUREG-0737, II K items
& NRC questions & updating Sections 2 5 1, 3 1-3, 3 11-12 &
5 2
* Houston Lighting & Power Co 83/09/27 377pp 20593 328 21X
Fiche 50-498, 83/09/27, 8310030167

8310030303 Forwards Rev 1 to BAW-1762, "Auxiliary Feedwater Sys
Reliability Study for WPPSS Unit 1," in response to
NUREG-0737, Item II E 1 1
SORENSEN, O C Washington Public Power Supply System 0L-82-14
83/09/23 ADENHAM, E O Licensing Branch 4 1p 20593 181 24X
Fiche 50-460, 83/09/23, 8310030303

--8310030306 BAW-1762 R01
Rev 1 to "Auxiliary Feedwater Sys Reliability Study of WPPSS
Unit 1 "
* Babcock & Wilcox Co 0L-82-14 83/06/30 41pp 20593 183
24X Fiche 50-460, 83/09/23, 8310030303

8310030308 Forwards response to 830816 memo re 830125 main feedwater
line break Response based on NUREG-0918, NUREG-0691 &
proposed rev to Jan-Mar AD rept
DIRCKS, W J Office of the Executive Director for Operations
83/09/21 ASSELSTINE, J K Commissioners 13pp 20604 039 24X
Fiche 50-309, 83/09/21, 8310030308

8310030353 Forwards B&W Owners Group final rept, "Bounding Analytical
Assessment of NUREG-0630 Models on LOCA kW/ft Limits W/Use
of FLECSER " Approval requested
MARSHALL, J R Arkansas Power & Light Co 1CAN098310 83/09/23
STOLZ, J F Operating Reactors Branch 4 1p 20592 200 24X
Fiche 50-313, 83/09/23, 8310030353

--8310030356 77-1140898-01
"Bounding Analytical Assessment of NUREG-0630 Models on
LOCA kW/ft Limits W/Use of FLECSER "
* Babcock & Wilcox Operating Plants Owners Group 83/09/30,
108pp 20592 201. 24X Fiche 50-313, 83/09/23, 8310030356

8310030354 Requests extension to Apr 1984 to comply w/final rule re TMI
Action Item I A.1 3, "Shift Manning " Justification for
granting request provided
HARRINGTON, W D Boston Edison Co 83-244 83/09/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 20592 340
24X Fiche 50-293, 83/09/27, 8310030354

8310030361 Discusses agreement w/NRC affecting surveillance
requirements in NUREG-0892, SER Suppl 2 re TMI Action Item
II, K 3 28 on automatic depressurization sys Bottle pressure
verification changed to 31 days
SORENSEN, O C Washington Public Power Supply System 002-83-861
83/09/23 SCHWENGER, A Licensing Branch 2 3pp 20592 131 24X
Fiche 50-397, 83/09/23, 8310030361

8310030391 Forwards description of Class A radiation dose assessment
model, per util 830415 ltr Meteorological info & dose
assessment sys Class A (ACR180) program will be primary
dose assessment model in emergency operations facility
ALEXICH, M P Indiana & Michigan Electric Co AEP NRC 07738
83/09/27 DENTON, H R Office of Nuclear Reactor Regulation,
Director 7pp 20593 056 24X Fiche 50-315, 83/09/27, 8310030391.

8310030419 Forwards draft NUREG-1020, Vol 1, "GPU vs B&W Lawsuit Review
& Effect on TMI-1 " Portions of Category 10 withheld since
info pertains to ongoing investigations.
CHILK, B J Office of the Secretary of the Commission 83/09/30
Atomic Safety and Licensing Board Panel 111pp 20602 103 24X
Fiche 50-289, 83/09/30, 8310030419

8310030425 Forwards proprietary "Final Assessment of Palo Verde Nuclear
Generation Station Fuel Assembly Spacer Grid Impact Loads
Under Faulted Conditions," per SER (NUREG-0857) Section
4 2 1, Affidavit encl. Rept withheld (ref 10CFR2 790)
VAN BRUNT, E E Arizona Public Service Co ANPP-27883-WF0/
83/09/26 KNIIGHTON, G. Licensing Branch 3 7pp 20602 219 24X
Fiche 50-528, 83/09/26, 8310030425

8310030443 Informs that Section 4 31 of integrated plant safety
assessment rept (NUREG-0822) dtd Jan 1983 complete, except
for implementation of mods to diesel generator trips by end
of Cycle 11 outage & IE post-implementation review
CRUTCHFIELD, D Operating Reactors Branch 5 L805-83-09-046
83/09/29 FIEDLER, P B General Public Utilities - GPU Service Corp
2pp 20602 063 24X Fiche 50-219, 83/09/29, 8310030443

8310030485 Forwards schedule for responding to 830824 request for addl info on inadequate core cooling instrumentation sys. per NUREG-0737, Item II F 2, "Inadequate Core Cooling" RODRIGUEZ, R J Sacramento Municipal Utility District RJR 83-677 83/09/28 STOLZ, J F Operating Reactors Branch 4 2pp 20401 077 24X Fiche 50-312, 83/09/28, 8310030485

8310030571 Board Notification 83-138A informs of change to previously stated position in NUREG-0680, Suppl 2 RCS leak rate tests contain inadequacies & deviations from regulatory & procedural requirements EISENHUT, D Q Division of Licensing 83/09/23 PALLADINO, N, QILINSKY, V, ROBERTS, T Commissioners 5pp 20607 335 24X Fiche 50-289, 83/09/23, 8310030571

8310030601 Forwards comments on 830331 detailed control room design review final rpt per Suppl 1 to NUREG-0737 Rept acceptable Meeting to discuss comments before 831017 preimplementation audit recommended ADENSAH, E Q Licensing Branch 4 83/09/19 COOK, J W Consumers Power Co 10pp 20607 343 24X Fiche 50-329, 83/09/19, 8310030601

8310030603 Forwards safety evaluation concurring w/licensee conclusions that NUREG-0737, Item II K 3 2 requirements met w/existing PORV, safety valve & reactor high trip pressure setpoints. Automatic PORV isolation sys (Item II K 3 1) not required VARGA, S A Operating Reactors Branch 1 83/09/23 CLAYTON, F L Alabama Power Co 14pp 20604 212 24X Fiche 50-348, 83/09/23, 8310030603

8310040016 Forwards one oversize revised flow diagram to comply w/Section 10 4 9 of SER re License Condition 20, loss of primary source of condensate storage water Aperture card is available in PDR TUCKER, H B Duke Power Co 83/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E Q Licensing Branch 4 2pp 20615 034 24X Fiche 50-413, 83/09/28, 8310040016

8310040033 Confirms procedure for estimating core damage since restart from recent outage in response to NRC 830902 ltr Procedure not formalized, but will be incorporated as normal plant operation procedure LATHAM, H K Sacramento Municipal Utility District RJR-83-665 83/09/26 STOLZ, J F Operating Reactors Branch 4 1p 20608 124 24X Fiche 50-312, 83/09/26, 8310040033

8310040035 Forwards safety evaluation of licensee responses to requirements of NUREG-0737, Item II B 1, "RCS Vents" Item completed LLL technical evaluation rpt encl VARGA, S A Operating Reactors Branch 1 83/09/19 BAYNE, J P Power Authority of the State of New York 9pp 20634 321 24X Fiche 50-286, 83/09/19, 8310040035

--8306030372 TF-334/0806A "Selected Operating Reactor Issues Program II RCS Vents (NUREG-0737, Item II B 1)," Final technical evaluation rpt HELD, J T Energy Incorporated * Laurence Livermore Laboratory FIN A-0250 TAC 44379 83/02/14 ALBERTHAL, G Division of Licensing 6pp 20634 330 24X Fiche 50-286, 83/09/19, 8310040035

8310040052 Forwards 9-month response for NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants" Electrical interlocks prevent main hoist of reactor bldg crane from being used over reactor well or spent fuel pool CURTIS, N W Pennsylvania Power & Light Co PLA-1843 83/09/29 SCHWENCER, A Licensing Branch 2 63pp 20608 143 24X Fiche 50-388, 83/09/29, 8310040052

8310040110 Forwards final schedule for satisfying requirements of Generic Ltr 82-33 re Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability" SCHWENCER, A Licensing Branch 2 61-82-33, 83/09/26 BAUER, E Q Philadelphia Electric Co 4pp 20634 336 24X Fiche 50-352, 83/09/26, 8310040110

8310040111 Responds to 830531 & 0826 ltrs requesting amend to 830318 confirmatory order re NUREG-0737, Item II F 1.5, "Containment Water Level Monitor" Amend not required. Environ qualification will be addressed in 10CFR50 49 audit STOLZ, J F Operating Reactors Branch 4 83/09/02 TUCKER, H B Duke Power Co 5pp 20627 351 24X Fiche 50-269, 83/09/02, 8310040111

8310040120 Forwards "Control of Heavy Loads at Nuclear Power Plants, VC Summer Nuclear Station, Unit 1 (PHASE I)," EQ&O technical evaluation rpt Synopsis re NRC interpretation of NUREG-0612 guidelines for resolution of open items encl NOVAK, T M Assistant Director for Licensing 83/09/16 DIXON, O W South Carolina Electric & Gas Co 2pp 20640 274 24X Fiche 50-395, 83/09/16, 8310040120

8310040123 EQ&O-HS-4371 "Control of Heavy Loads at Nuclear Power Plants, VC Summer Nuclear Station, Unit 1 (PHASE I)," technical evaluation rpt FRIEDERICH, S EQ&O, Inc FIN A-6457 83/08/31 NRC - No Detailed Affiliation Given 49pp 20640 276 24X Fiche 50-395, 83/09/16, 8310040120

8310040227 Forwards info to resolve SER License Condition 7 per IMI Action Plan Item II B 3, "Post-Accident Sampling Sys." W/two oversize drawings Aperture cards are available in PDR Proprietary info withheld (ref 10CFR2 790) EDELMAN, H R Cleveland Electric Illuminating Co PY-CEI/NRR-0060 83/09/16 VOUNOBLOOD, B J Licensing Branch 1 4pp 20612 067 24X Fiche 50-440, 83/09/16, 8310040227

--8310040229 "Evaluation of Post-Accident Sampling Sys for Perry Nuclear Power Plant" * Cleveland Electric Illuminating Co 83/07/31 31pp. 20612 071 24X Fiche 50-440, 83/09/16, 8310040227

--8310040231 Preliminary Rev 0 to Procedure CHI-22, Chemistry Equipment Instruction, "Single Channel Analyzer Canberra" WESTBROOK, W W Cleveland Electric Illuminating Co 83/09/16 17pp 20612 102 24X Fiche 50-440, 83/09/16, 8310040227

--8310040234 Preliminary Rev 0 to Procedure CHI-12, Chemistry Equipment Instruction, "Multi-Channel Analyzer, Canberra, Series 85" WESTBROOK, W W Cleveland Electric Illuminating Co 83/09/16 18pp 20612 119 24X Fiche 50-440, 83/09/16, 8310040227

8310040239 Advises that assessment of two viable options for location of primary emergency operations facilities, per Suppl 1 to NUREG-0737, scheduled for completion in early Nov 1983 Final decision expected by 831119 MURPHY, W P Vermont Yankee Nuclear Power Corp FVY 83-104 83/09/29 VASSALLO, D B Operating Reactors Branch 2 2pp 20617 266 24X Fiche 50-271, 83/09/29, 8310040239.

8310040287 Forwards Rev 2 to 830414 response to Suppl 1 to NUREG-0737, including rpt on review of Reg Guide 1 97 TUCKER, H B Duke Power Co 83/09/26 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E Q Licensing Branch 4 91pp 20614 077 24X Fiche 50-413, 83/09/26, 8310040287

8310040300 Forwards IE Insp Rept 50-312/83-24, Portions of post-accident sampling sys (NUREG-0737, Item II B 3) inoperable. Reasonable degree of sys reliability remains undemonstrated WENSLAWSKI, F A Region 3, Office of Director 83/09/23 STOLZ, J F Operating Reactors Branch 4 1p 20612 338 24X Fiche 50-312, 83/09/23, 8310040300

--8310040311 IE Insp Rept 50-312/83-24 on 830912-16 Noncompliance not licensee unable to sample containment atmosphere using post-accident sampling sys, hydrogen monitors or reactor bldg atmosphere monitor NORTH, H S, YUHAS, Q P Region 3, Office of Director, WENSLAWSKI, F A Region 4, Office of Director, 83/09/23 12pp 20612 341 24X Fiche 50-312, 83/09/23, 8310040300

8310040301 Forwards B&W "Bounding Analytical Assessment of NUREG-063 Models on LOCA kW/Ft Limits W/Use of FLECBET," completing response to NUREG-0630 Compensating models documented & justification for model use provided WESTAFER, O R Florida Power Corp 3F-0983-20 83/09/29 STOLZ, J F Operating Reactors Branch 4 2pp 20612 227 24X Fiche 50-302, 83/09/29, 8310040301

--8310040304 77-1140898-01 "Bounding Analytical Assessment of NUREG-0630 Models on LOCA kW/Ft Limits W/Use of FLECBET," Babcock & Wilcox Co 83/09/30 109pp 20612 227 24X Fiche 50-302, 83/09/29, 8310040301.

8310040310 Forwards addl info requested in 830810 telcon re Franklin Researc. Ctr 830617 draft technical evaluation rpt on util response to Phase 1 of NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants" FAY, C W Wisconsin Electric Power Co, 83/09/28, MILLER, J R Office of Nuclear Reactor Regulation, Director 8pp 20613 096 24X Fiche 50-266, 83/09/28, 8310040310

8310040336 Forwards Procedure AD NP 16, "Nuclear Production Direct Emergency Procedure Generation Program," per NUREG-0737, Suppl 1 (Generic Ltr 82-33). WILLIAMS, J Cincinnati Gas & Electric Co, LO7-83-0168, 83/09/ DENTON, H R Office of Nuclear Reactor Regulation, Director, 2p 20617 133 24X Fiche 50-358, 83/09/30, 8310040336

NONDOCKETED ITEMS

- 8310040353 Forwards "Pressurizer Relief Valve Qualification," & Rev 1 to "Pressurizer Safety Valve Operability Rept," per NUREQ-0737, Item I D 1 Design load stresses on piping & fittings within allowable limits LUNOVALL, A E Baltimore Gas & Electric Co 03/09/28 MILLER, J R Operating Reactors Branch 3 App 20615 036 24X Fiche 50-317, 83/09/28, 8310040353
- 8310040363 Forwards response to NRC 830601 SER re Westinghouse Owners Group emergency response guidelines per Suppl 1 to NUREQ-0737 SHEPPARD, J J Westinghouse Operating Plants Owners Group SHEPPARD, J J Carolina Power & Light Co 00-105 83/09/27 EISENHUT, D G Division of Licensing 42pp 20620 235
- 8310040387 Submits evaluation of existing Westinghouse STB provisions, ASME Code Section XI, Reactor Safety Study (WASH 1400), NUREQ-0677 & EG&G rept, "Inservice Leak Testing of Primary Pressure Isolation Valves," as applicable to plant design CLAYTON, F L Alabama Power Co 83/09/27 VARDA, S A Office of Nuclear Reactor Regulation, Director 16pp 20625 200 24X Fiche 50-348, 83/09/27, 8310040387
- 8310040402 Forwards results of preliminary lighting survey for main control room, per 830727 request & NUREQ-0700 HILLS, L M Tennessee Valley Authority 83/09/29 ADENSAH, E Licensing Branch 4 2pp 20617 352 24X Fiche 50-390, 83/09/29, 8310040402
- 8310040415 Forwards "Implementation of NUREQ-0619 Feedwater Nozzle Cracking," & proprietary "Peach Bottom Atomic Power Station, Unit 2, Feedwater Nozzle Fracture Mechanics Analysis to Show " Proprietary rept withheld (ref 10CFR2 790) GALLAGHER, J M Philadelphia Electric Co 83/09/29 EISENHUT, D G Division of Licensing 2pp 20623 303 24X Fiche 50-277, 83/09/29, 8310040415
- 8310040429 "Implementation of NUREQ-0619 Feedwater Nozzle Cracking " Affidavit encl * Philadelphia Electric Co 83/09/30 19pp 20623 305 24X Fiche 50-277, 83/09/29, 8310040415
- 8310040420 Confirms that technical support ctr designed to be continuously habitable for 30 days Following post-accident release described in Reg Guide 1.4, Rev 2, dtd June 1974 Shielding conforms w/NUREG-0737, Items II B 2 & III A 1 2 WEBSTER, R R Florida Power Corp 3F-0983-19 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20619 040 24X Fiche 50-302, 83/09/30, 8310040420
- 8310040434 Forwards safety analysis re basis on which selected parameters for safety parameter display sys sufficient to assess safety status of each function for wide range of events per Generic Ltr 82-33, Suppl 1 to NUREQ-0737 GALLAGHER, J M Philadelphia Electric Co 0L-82-33 83/09/28 EISENHUT, D G Division of Licensing 8pp 20619 108 24X Fiche 50-277, 83/09/28, 8310040434
- 0040431 Forwards safety evaluation supporting Westinghouse licensee responses to NUREQ-0737, Items II K 3 1, "Automatic PORV isolation" & II K 3 2, "Rept on PORVs" & Franklin Research re "Operating Reactor PORV Repts (F-37), TMI Action " HUTCHFIELD, D Operating Reactors Branch 5 L805-83-09038, 3/09/27, MAIER, J E Rochester Gas & Electric Corp 17pp, 0624 106 24X Fiche 50-244, 83/09/27, 8310040431
- 0040436 Forwards safety evaluation of NUREQ-0737, Item II B 3, Post-Accident Sampling Sys " Util meets sit of il ritarie Comments requested within 30 days W/o encl ADSEN, G L NRC - No Detailed Affiliation Given 83/09/22 SE, O R Public Service Co of Colorado 1p 20624 225 24X Fiche 50-267, 83/09/22, 8310040436
- 8040498 Respec of Contention I-41 re sys interaction Certificate of re encl DORBEY, J A Linerick Ecology Action DORBEY, J A Dorsey, J A 1/09/28 BRENNER, L , COLE, R F , MORRIS, P A Atomic Safety and Licensing Board Panel 8pp 20625 132 24X Fiche 50-332, 83/09/28, 8310040498
- 040532 Forwards IE Insp Rept 50-528/83-38 on 830801-31. No noncompliance noted SHOP, T W Division of Resident/Reactor Project & Engineering programs 83/09/19 ANDOGNINI, G C Arizona Public Service Co p 20624 010 24X Fiche 50-528, 83/09/19, 8310040532
- 10040537 IE Insp Rept 50-528/83-38 on 830801-31. No noncompliance noted Major areas inspected: equipment qualification, startup testing, TMI followup items, NSSB problems & plant mod *DRELLI, O , JOHNSTON, O , YOUNG, T. Region 5, Office of Director 33/09/15, 7pp 20624 012 24X Fiche 50-528, 83/09/19, 8310040537
- 8310040551 Forwards GE Axtell & RM Marusich testimony re Christa-Maria emergency planning Contention 9(6) GALLD, J J Isham, Lincoln & Beale GALLD, J Consumers Power Co 83/09/30 BLOCH, P B , PARIS, O H , SHON, F J Atomic Safety and Licensing Board Panel 1p 20622 130 24X Fiche 50-155, 83/09/30, 8310040551
- 8310040560 Testimony of RM Marusich re Christa-Maria Contention 9(6) on emergency planning - radiation monitoring Util has capability to assess degree of core damage promptly following accident MARUSICH, R M Consumers Power Co 83/09/30 16pp 20622 131 24X Fiche 50-155, 83/09/30, 8310040551
- 8310040564 Testimony of CE Axtell re Christa-Maria Contention 9(6) on emergency planning - radiation monitoring Use of noble gas effluent monitors, in-plant iodine instruments & containment high-range radiation monitors discussed AXTELL, C E Consumers Power Co ISSUANCES OLA 83/09/30 13pp 20622 147 24X Fiche 50-155, 83/09/30, 8310040551
- 8310040561 Forwards "Program Plan For Implementation of Control Room Design Review of Beaver Valley Power Station," following guidelines in Suppl 1 to NUREQ-0737, per Generic Ltr 82-33 CAREY, J J Duquesne Light Co 0L-82-33 83/09/29 EISENHUT, D G Division of Licensing 3pp 20622 165 24X Fiche 50-334, 83/09/29, 8310040561
- 8310040569 "Program Plan For Implementation of Control Room Design Review of Beaver Valley Nuclear Power Station " * Duquesne Light Co 83/09/27 88pp 20622 168 24X Fiche 50-334, 83/09/27, 8310040561
- 8310040577 Forwards response to draft technical evaluation rept assessing conformance w/general load handling guidelines of NUREQ-0612, "Control of Heavy Loads at Nuclear Power Plants," Addl response will be provided by 831115 LEHPQEB, T E Niagara Mohawk Power Corp 83/09/30 EISENHUT, D G Division of Licensing 9pp 20625 327 24X Fiche 50-220, 83/09/30, 8310040577
- 8310040620 Rept on mod of automatic depressurization sys logic in response to ASLB request ASLB should defer further consideration pending status rept on implementation of Option 2, due by 840115 Certificate of Svc encl ELLIS, T S Long Island Lighting Co ELLIS, T S Hunton & Williams ISSUANCES OL 83/09/30 7pp 20626 055 24X Fiche 50-322, 83/09/30, 8310040620
- 8310040648 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept, "ECCS Repts (F-47) Action Plan Requirements, Toledo Edison Co, Davis-Besse Nuclear Power Station, Unit 1 " NUREQ-0737, Item II K 3 17 requirements met STOLZ, J F Operating Reactors Branch 4 83/09/01 CRDUSE, R P Toledo Edison Co 4pp 20627 285 24X Fiche 50-346, 83/09/01, 8310040648
- 8212010152 TER-C5306-273 "ECCS Repts (F-47), TMI Action Plan Requirements, Davis-Besse Nuclear Power Station, Unit 1," technical evaluation rept VOSBURY, F W Franklin Institute/Franklin Research Center NRC-03-81-130 82/11/24 CHOW, E NRC - No Detailed Affiliation Given 14pp 20627 289 24X Fiche 50-346, 83/09/01, 8310040648
- 8310040650 Advises that changes re sonic flow devices meet requirements of NUREQ-0737, Item II E 1 2, "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication" & are acceptable based on review of licensee 830524 & 0825 ltrs STOLZ, J F Operating Reactors Branch 4 83/09/22 HUKILL, H D General Public Utilities - OPU Service Corp 5pp 20627 319 24X Fiche 50-289, 83/09/22, 8310040650
- 8310050004 Advises that NUREQ-0737, Item II B 2 2, "Design Review of Plant Shielding - Corrective Actions for Access to Vital Areas," requirements met based on review of licensee 800102, 31, 1015, 810108, 820415, 0707 & 830513 submittals STOLZ, J F Operating Reactors Branch 4 83/09/12 BAUER, E O Philadelphia Electric Co 5pp 20650 242 24X Fiche 50-277, 83/09/12, 8310050004
- 8310050101 Forwards summary of proposed integrated plant safety assessment (NUREG-0827) & SEP Topics III-3 A, III-4 B & VIII-1 A Printing error in NUREQ-0485 corrected to read 01/01/84. LINDER, F Dairyland Power Cooperative LAC-7324 83/09/29 CRUTCHFIELD, D Operating Reactors Branch 5 21pp 20628 289 24X Fiche 50-409, 83/09/29, 8310050101

NONDOCKETED ITEMS

4E

8310050148 Forwards safety evaluation re NUREG-0737, Item II K 3 2 & Westinghouse Owners Group Rept WCAP-9804 based on results encl in Franklin Research Ctr technical evaluation rept Automatic PORV isolation sys not required
VARGA, S A Operating Reactors Branch 1 83/09/13 D'TOOLE, J D 14pp 20639 100 24X
Consolidated Edison Co of New York, Inc
Fiche 50-247, 83/09/13 8310050148

8310050217 NUREG/CR-3534 V01
HEAVY SECTION STEEL TECHNOLOGY PROGRAM QUARTERLY PROGRESS
REPORT FOR JANUARY - MARCH 1983
PUOH, C E Oak Ridge National Laboratory FIN D-0119
ORNL/TM-B787/V1 83/09/30 Division of Engineering Technology
191pp 20636 354

8310050224 NUREG/CR-3299
CORE MELT MATERIALS INTERACTIONS EVALUATIONS Final Report,
April 1980 - April 1983
SHANSON, D G CASTLE, J N, ANDERSON, P D Applied Science Associates,
Inc FIN B-6823 83/09/30 Division of Systems Integration (post
811005) 277pp 20635 318

8310050232 NUREG-0852 S02
SAFETY EVALUATION REPORT RELATED TO THE FINAL DESIGN OF THE
STANDARD NUCLEAR STEAM SUPPLY REFERENCE SYSTEM, CESSAR SYSTEM
80 Docket No 50-470 (Combustion Engineering, Incorporated)
* Office of Nuclear Reactor Regulation, Director 83/09/30 163pp
20635 151 24X Fiche 50-470, 83/09/30, 8310050232

8310050239 NUREG/CR-3472 V01
SURFACE PROPERTIES AND PERFORMANCE PREDICTION OF ALTERNATIVE
WASTE FORMS
MENCH, L L, CLARK, D E Florida State Univ 83/09/30 Division of
Health, Siting & Waste Management 99pp 20636 250

8310050244 NUREG-0750 V17 N04
NUCLEAR REGULATORY COMMISSION ISSUANCES April 1983
Pages 525-729
* Division of Technical Information & Document Control 83/04/30
210pp 21020 313

8310050253 NUREG/CR-3401
LABORATORY-SCALE SODIUM-CARBONATE AGGREGATE CONCRETE
INTERACTIONS
WESTRICH, H R, STOCKMAN, H W, SUD-ANTTILA, A Sandia Laboratories
FIN A-1054 SAND83-1502 83/09/30 Division of Accident
Evaluation 64pp 20635 084

8310050297 Forwards safety evaluation on installation of RCS high point
vents per NUREG-0737, Item II B 1, "RCS Vents" & final
technical evaluation rept Vent sys acceptable subj to post-
implementation audit
STOLZ, J F Operating Reactors Branch 4 83/08/08 WILGUS, W S
Florida Power Corp 3pp 20650 057 24X Fiche 50-302, 83/08/08,
8310050297

--8310050304 Safety evaluation supporting installation of RCS high point
vents per NUREG-0737, Item II B 1, "RCS Vents"
* NRC - No Detailed Affiliation Given 83/05/26 10pp
20650 060 24X Fiche 50-302, 83/08/08, 8310050297

-8306080106 TF-370/0817A
"Selected Operating Reactor Issues Program II: RCS Vents
(NUREG-0737, Item II B 1), " Final technical evaluation rept
HELD, J T Energy Incorporated HELD, J T Lawrence Livermore
Laboratory FIN A-0250 TAC 44363 83/03/14 ALBERTHAL, G
Division of Licensing 6pp 20650 070 24X Fiche 50-302,
83/08/08, 8310050297

8310050331 NUREG/CR-3437
DATA ANALYSIS USING BINOMIAL FAILURE RATE COMMON CAUSE
MODEL
ATHOOD, C L EQ&G, Inc FIN A-6283 EQO-2271 83/09/30
Division of Risk Analysis 28pp 20639 059

10050335 NUREG/CR-3464
THE APPLICATION OF FRACTURE PROOF DESIGN METHODS USING
TEARING INSTABILITY THEORY TO NUCLEAR PIPING POSTULATING
CIRCUMFERENTIAL THROUGH WALL CRACKS
PARIS, P C, TADA, H Del Research Corp * EQ&G, Inc FIN A-6449
83/09/30 Division of Engineering 203pp Available at NRC
16 00. 20638 223

0050339 NUREG-0020 V07 N06
LICENSED OPERATING REACTORS STATUS SUMMARY REPORT Data As Of
lay 31, 1983 (Gray Book)
Management Information Branch 83/09/30 396pp 20637, 187

8310050435 Forwards NUREG-1000, Vol 2, "Generic Implications of ATWS
Events at Salem Nuclear Power Plant" & SECY-83-248,
"Generic Actions for Licensees & Staff in Response to ATWS
Events at Salem " W/o encls
ROTHSCHILD, M U Hearing Branch 1 83/09/27 BLOCH, P B,
JORDAN, W H, MCCOLLOM, K A Atomic Safety and Licensing Board Panel
1p 20628 362 24X Fiche 50-445, 83/09/27, 8310050435

8310050492 Forwards IE Insp Rept 50-341/83-18 on 830822-26 No
noncompliance noted
LITTLE, H S Region 3, Office of Director 83/09/23 WELLS, A
Detroit Edison Co 2pp 20628 352 24X Fiche 50-341, 83/09/23,
8310050492

--8310050497 IE Insp Rept 50-341/83-18 on 830822-26 No noncompliance
noted Major areas inspected action taken on 100FR50 93(e)
Items, IE bulletins, IE circulars, previous insp findings &
electrical design review
WILLIAMS, C C, AHMED, I H, NAIDU, K R Region 3, Office of
Director ICB-75-04 83/09/22 8pp 20628 354 24X
Fiche 50-341, 83/09/23, 8310050492

8310050512 Responds to ASLAB request for NRC Final position on review
of upgraded auxiliary feedwater sys & related questions. Util
rescheduled completion of upgraded sys to refueling Outage B
currently estimated in Apr 1986
LEBS, R Hearing Branch 3 ISSUANCES SP 83/09/27
ROSENTHAL, A B, BUCK, J H, KOHL, C N Atomic Safety and Licensing
Appeal Panel 3pp 20634 050 24X Fiche 50-312, 83/09/27,
8310050512

--8310050521 Affidavit of ED Sylvester re ASLAB questions on installation
of Upgraded auxiliary feedwater sys per TH1 Item II E 1 i
Upgraded design will not meet current reliability
guidelines SER encl
SYLVESTER, E D Auxiliary Systems Branch ISSUANCES SP 83/09/27
46pp 20634 076 24X Fiche 50-312, 83/09/27, 8310050512

8310050524 Forwards SER re util response to NUREG-0737, Item II B 1,
"RCS Vents" Item complete
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-10-002
83/10/03 FARRAR, D L Commonwealth Edison Co 6pp 20632 335
24X Fiche 50-237, 83/10/03, 8310050524

--8310050534 TF-380/0623A
"Selected Operating Reactor Issues Program II: RCS Vents
(NUREG-0737, Item II B 1), " Final technical evaluation rept
for Dresden Units 2 & 3
HELD, J T Lawrence Livermore Laboratory FIN A-0250 TAC 44269
83/04/06 ALBERTHAL, G NRC - No Detailed Affiliation Given 4pp
20632 341 24X Fiche 50-237, 83/10/03, 8310050524

8310050537 Memorandum & order granting util request to defer further
consideration of mod to automatic depressurization sys
logic pending receipt of util status rept on progress of
implementation of mods by 840116
BRENNER, L Atomic Safety and Licensing Board Panel 83/10/03
Long Island Lighting Co 4pp 20629 354 24X Fiche 50-322,
83/10/03, 8310050537

8310060021 Forwards "Control Room Design Review Program Plan," per
830415 & 0720 commitments in response to Suppl 1 to
NUREG-0737
RODRIGUEZ, R J Sacramento Municipal Utility District RJR-83-674
83/09/30 STOLZ, J F Operating Reactors Branch 4 1p 20649 262
24X Fiche 50-312, 83/09/30, 8310060021

--8310060022 "Control Room Design Review Program Plan "
* Sacramento Municipal Utility District 83/09/30 14pp
20649 263 24X Fiche 50-312, 83/09/30, 8310060021

8310060031 Forwards Amend 81 to License DPR-62 & safety evaluation
Amend revises Tech Spec re instrumentation used to monitor
water level in suppression chamber of primary containment
sys (NUREG-0737, Item II F 1 5)
HACKAY, S D Operating Reactors Branch 2 83/09/22 UTLEY, E E
Caroline Power & Light Co 2pp 20664 101 24X
Fiche 50-324, 83/09/22, 8310060031

8310060079 NUREG/CR-3486
RADIOLOGICAL SURVEY OF THE NUCLEAR FUEL SERVICES, INC ERWIN
PLANT BURIAL SITE
DOOTH, L F, NYERGES, P L, GROFF, D W Radiation Management Corp FIN
B-6901 83/09/30 Division of Fuel Cycle & Material Safety
54pp 20664 001.

8310060157 Provides addl comments on AD rept to Congress for Second
Quarter CY83 re proposed update of AD 73-8, "Cracks in Pipes
at BHRs"
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/09/27 HELTHER, C J Director's Office 8pp 20663 289

NONDOCKETED ITEMS

--B309160028 Forwards draft Commission paper, ltr to Congress & Second Quarter CY83 AD rept to Congress (NUREG-0090) Updated info requested
 HELTEMES, C J Director's Office 83/08/31 DENTON, H R Office of Nuclear Reactor Regulation, Director DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director MINOQUE, R B Office of Nuclear Regulatory Research, Director 46pp 20663 297

B310060211 Forwards SAR for safety parameter display sys. in response to Generic Ltr 82-33, per NUREG-0757, Suppl 1 & Util 830415 ltr Implementation schedule for safety parameter display sys encl
 CURTIS, N W Pennsylvania Power & Light Co PLA-1882 83/09/30 SCHWENGER, A Licensing Branch 2 98pp 20646 279 24X Fiche 50-387, 83/09/30, B310060211

B310060226 Forwards plan & schedule for resolution of NUREG-0737, Item II K 3.5, "Automatic Trip of Reactor Coolant Pumps," (Generic Ltr 83-10), per NRC 830208 request Operating procedures for pumps to be revised
 CROUSE, R P Toledo Edison Co. 987 83/10/03 EISENHUT, D O Division of Licensing 6pp 20647 015 24X Fiche 50-346, 83/10/03, B310060226

B310060357 Submits amended implementation schedule for Suppl 1 to NUREG-0737 requirements for safety parameter display sys & Reg Guide 1.47 Listing of parameters available for display encl
 DRUMMOND, F J Louisiana Power & Light Co W3P83-2936 83/09/29 KNEIGHTON, G W Licensing Branch 3 3pp 20646 107 24X Fiche 50-382, 83/09/29, B310060357

B310060357 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept of util response to TMI Item II K 3.17, "Rept on Outages of ECCS"
 VARQA, S A Licensing Branch 1 83/09/27 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 4pp 20664 127 24X Fiche 50-272, 83/09/27, B310060357

--B310010087 TER-C5506-294
 "ECCS Repts (F-47) TMI Action Plan Requirements, FBE&O, Salem Nuclear Generating Station Unit 1," technical evaluation rept
 VOSBURY, F W, OVERBECK, G J, LUDINGTON, B W Franklin Institute/Franklin Research Center NRC-03-80-130 82/09/28 CHON, E NRC - No Detailed Affiliation Given 14pp 20664 131 24X Fiche 50-272, 83/09/27, B310060357

B310060583 Comments on proposed design for compliance w/NUREG-0737, Item II, K 3.13, "Separate HFIC & RCIC Initiation Levels" re automatic restart Proposal acceptable
 VASSALLO, D B Operating Reactors Branch 2 83/09/19 PARRIS, H O Tennessee Valley Authority 3pp 20661 204 24X Fiche 50-259, 83/09/19, B310060583

B310070084 Forwards safety evaluation of util response to NUREG-0737, Item II D 1, "Reliability Engineering" re safety & relief valve testing Requirements met Item resolved
 VASSALLO, D B Operating Reactors Branch 2 83/09/22 BAYNE, J P Power Authority of the State of New York 17pp 20671:317 24X Fiche 50-333, 83/09/22, B310070084

B310070097 Forwards safety evaluation of design of RCS vents Design conforms w/requirements of NUREG-0737, Item II, B.1, QDC 1.2, 4, 14, 30 & 31 & 10CFR50.44(c)(3)(iii) w/exception of positive valve position indication
 VARQA, S A Operating Reactors Branch 1 83/09/27 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 3pp 20673:349 24X Fiche 50-272, 83/09/27, B310070097

--B310070103 Safety evaluation of RCS vent design Design complies w/NUREG-0737, Item II B.1, QDC 1.2, 4, 14, 30 & 31 & 10CFR50.44
 * NRC - No Detailed Affiliation Given 83/05/17 6pp 20673:352 24X Fiche 50-272, 83/09/27, B310070097

--B306080112 TF-343/0809A
 "Selected Operating Reactor Issues Program II RCS Vents (NUREG-0737, Item II B 1)," final technical evaluation rept for Salem 1 & 2.
 HELD, J T Energy Incorporated, FIN A-0250, TAC 44405 83/02/23 ALBERTHAL, O Division of Licensing, 6pp. 20673 358 24X Fiche 50-272, 83/09/27, B310070097

B310070110 NUREG/CR-3475
 CRITICAL DISCHARGE OF INITIALLY SUBCOOLED WATER THROUGH SLITS.
 AMDB, C N, SCHROCK, V E, Lawrence Berkeley Laboratory FIN B-3043 LBL-16363 83/09/30, Division of Accident Evaluation 298pp Available at NRC. \$7.00. 20672 001

B310070116 NUREG-0420 S04
 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF THE SHOREHAM NUCLEAR POWER STATION, UNIT NO 1 DOCKET NO 50-322 (Long Island Lighting Company)
 * Division of Licensing 83/09/30 71pp Available at NRC \$4 50 20671 122 24X Fiche 50-322, 83/09/30, B310070116

B310070154 NUREG/CR-3327
 ANALYSIS OF STRONG-MOTION DATA FROM THE NEW HAMPSHIRE EARTHQUAKE OF 18 JANUARY 1982
 CHANG, F K Army, Dept of, Army Engineer Waterways Experiment Station FIN B-8251 83/09/30 Division of Health, Siting & Waste Management 76pp Available at NRC \$4 50 20671 193

B310070166 Advises that automatic PORV isolation will not be provided ! PORV & block valve control sys will not be modified, based on "Probabilistic Analysis & Operational Data in Response to NUREG-0737, Item II K 3.2 for Westinghouse NSSS Plants"
 LIDEN, E A Public Service Electric & Gas Co of New Jersey 83/09/27 VARQA, S Operating Reactors Branch 1 2pp 20659 108 24X Fiche 50-272, 83/09/27, B310070166

B310070250 Forwards "Detailed Control Room Design Review of Plant, St Lucie Unit 2 Nuclear Power Station (NUREG-0737, Suppl 1)," per 830415 commitment
 UHRIG, R E Florida Power & Light Co L-83-504 83/09/30 EISENHUT, D O Division of Licensing 1p 20659 128 24X Fiche 50-389, 83/09/30, B310070250

--B310070253 "Detailed Control Room Design Review of Plant, St Lucie Unit 2 Nuclear Power Station," summary rept
 UHRIG, R E Florida Power & Light Co 83/09/30 315pp 20659 129 24X Fiche 50-389, 83/09/30, B310070250

B310070291 Forwards "Position Paper on Reg Guide 1.97" & "Response to NUREG-0737, Suppl 1 & Reg Guide 1.97 Application to Emergency Response Facilities"
 ZIMMERMAN, S R Carolina Power & Light Co LAP-83-408 83/09/30 VASSALLO, D B Operating Reactors Branch 2 1p 20655 177 24X Fiche 50-324, 83/09/30, B310070291

--B310070293 "Position Paper on Reg Guide 1.97"
 BROWN, H E, WASENKO, M Carolina Power & Light Co 83/08/09 33pp 20655 178 24X Fiche 50-324, 83/09/30, B310070291

--B310070295 "Response to NUREG-0737, Suppl 1 & Reg Guide 1.97 Application to Emergency Response Facilities"
 BROWN, H E, WASENKO, M Carolina Power & Light Co 83/08/09 77pp 20655 211 24X Fiche 50-324, 83/09/30, B310070291

B310070317 NUREG/CR-3384
 VISA - A COMPUTER CODE FOR PREDICTING THE PROBABILITY OF REACTOR PRESSURE VESSEL FAILURE
 RTEVENS, D L, KLECKER, R W, SIMONEN, F A Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2310 PNL-4774 83/09/30 Division of Engineering Technology 92pp Available at NRC. \$4 50 20679 236

B310070320 NUREG/CR-3487
 REGIONAL-INTERSTATE SITE REVIEW PROCEDURE LOW-LEVEL RADIOACTIVE WASTE DISPOSAL FACILITY
 * Southern States Energy Board FIN B-50206 83/09/30 Division of Health, Siting & Waste Management 123pp Available at NRC \$5 00 20679 113

B310070323 NUREG/CR-3425
 LOW-ENERGY PHOTON DOSE DEPOSITION IN TISSUE SLAB AND SPHERICAL PHANTOMS
 NELSON, R F, CHILTON, A B Illinois, Univ of, Urbana, IL FIN B-8101 83/09/30 Division of Facility Operations 60pp Available at NRC \$4 50 20669 245

B310070340 Forwards Suppl 1 to plant-specific evaluation of EPRI safety & relief valve performance testing submitted on 821215 Suppl details adequacy of inlet & discharge piping for pressurizer safety & relief valves per TMI Item II D 1
 BAYNE, J P Power Authority of the State of New York IPN-83-82 83/09/30 VARQA, S A Operating Reactors Branch 1 8pp 20652 157 24X Fiche 50-286, 83/09/30, B310070340

B310070349 Forwards payment of fees for 830503 & 0601 applications for amends to License DPR-64 Payment made under protest pending final determination of legality of fee schedule
 BAYNE, J P Power Authority of the State of New York IPN-83-83 83/09/30 MILLER, W O License Fee Management Branch 2pp 20651 097 24X Fiche 50-286, 83/09/30, B310070349

B310070406 Forwards GER re util 791231 submittal concerning design of RCS vents Vent sys in conformance w/guidelines of NUREG-0737, Item II B 1 Item closed
 VARQA, S A Operating Reactors Branch 1, 83/09/23 UTLEY, E E Carolina Power & Light Co 14pp 20676 330 24X Fiche 50-261, 83/09/23, B310070406

NONDOCKETED ITEMS

8310070408 Forwards SER re control of heavy loads based on utility response to 801222 generic ltr Guidelines in NUREQ-0612, Section 5.1.1 & 5.3 satisfied
VARQA, S A Operating Reactors Branch 1 83/09/20 DOLAN, J
Indiana & Michigan Electric Co 2pp 20675 332 24X
Fiche 50-315, 83/09/20, 8310070408

--8310070409 Safety evaluation re control of heavy loads Guidelines in NUREQ-0612, Section 5.1.1 & 5.3 satisfied
* NRC - No Detailed Affiliation Given 83/09/20 2pp
20675 334 24X Fiche 50-315, 83/09/20, 8310070408

--8309060263 TER-C5506-344/345
"Control of Heavy Loads (C-10) Indiana & Michigan Electric Co, DC Cook Nuclear Plant Units 1 & 2," technical evaluation report
VOSSBURY, F W, DOMBERGER, C R Franklin Institute/Franklin Research Center NRC-03-B1-130 TAC 07980 83/09/01 SINKH, A NRC - No Detailed Affiliation Given 33pp 20675 336 24X
Fiche 50-315, 83/09/20, 8310070408

8310070411 NUREQ/CR-2482 V04
REVIEW OF DOE WASTE PACKAGE PROGRAM Subtask 1.1 - National Waste Package Program, October 1982 - March 1983
SDD, P Brookhaven National Laboratory BNL-NUREG-51494 83/09/30
Division of Waste Management 180pp Available at NRC \$6 00
20675 001

8310070414 NUREQ/CR-3473
ROCK MASS SEALING-EXPERIMENTAL ASSESSMENT OF BOREHOLE PLUG PERFORMANCE Annual Report, June 1982 - May 1983
DAFMAN, J K, STORMANT, J C, COLBURN, N I Arizona, Univ of, Tucson, AZ FIN D-6627 83/09/30 Division of Health, Siting & Waste Management 298pp Available at NRC \$7 50 20676 006

8310070426 NUREQ/CR-3122
POTENTIAL DAMAGING FAILURE MODES OF HIGH-AND MEDIUM-VOLTAGE ELECTRICAL EQUIPMENT
HOV, H C Oak Ridge National Laboratory FIN B-1672 DRNL/NSIC-213 83/08/31 Director's Office 90pp Available at NRC \$4 50
20674 238

8310070436 NUREQ/CR-3371 V02
TASK ANALYSIS OF NUCLEAR POWER PLANT CONTROL ROOM CREWS
VOLUME 2 Data Results
BURGV, D, LCMFOS, C, MILLER, A General Physics Corp FIN B-7471 GP-R-221020 83/09/30 Division of Facility Operations 353pp
Available at NRC \$8 00 20673 001

8310070437 NUREQ-1020 V01
GPU V. B&W LAWSUIT REVIEW AND ITS EFFECT ON TMI-1 General Public Utilities Corporation, et al V The Babcock & Wilcox Company, et al Three Mile Island Nuclear Station, Unit 1
Docket No 50-289
* Office of Nuclear Reactor Regulation, Director 83/09/30 85pp
Available at NRC \$5 00 20674 126 24X Fiche 50-289, 83/09/30, 8310070437

8310070439 NUREQ-1011
FINAL ENVIRONMENTAL STATEMENT RELATED TO STEAM GENERATOR REPAIR AT THE POINT BEACH NUCLEAR PLANT, UNIT 1 Docket No 50-266 (Wisconsin Electric Power Company)
COLBURN, T G Division of Licensing 83/09/30 60pp Available at NRC \$4 50 20672 249 24X Fiche 50-266, 83/09/30, 8310070439

8310070441 NUREQ-1020 V02
GPU V. B&W LAWSUIT REVIEW AND ITS EFFECT ON TMI-1 General Public Utilities Corporation, et al V The Babcock & Wilcox Company, et al Three Mile Island Nuclear Station, Unit 1
Docket No 50-289
* Office of Nuclear Reactor Regulation, Director 83/09/30 832pp
20677 001 24X Fiche 50-289, 83/09/30, 8310070441

8310070442 NUREQ/CR-2850 V02
POPULATION DOSE COMMITMENTS DUE TO RADIOACTIVE RELEASES FROM NUCLEAR POWER PLANT SITES IN 1980
BAKER, D A, PELOQUIN, R A Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2243 PNL-4221 83/08/31 Division of Data Automation & Management Information 122pp Available at NRC \$4 50 20674 001

831010001 FOIA request for listed documents to be placed in PDR. Documents requested are references from NUREQ-0800, Pages 3, 5, 16-7
PEDRO, J NUB Corp. CD-18-83-047. 83/06/17 Division of Rules and Records 1p 20704 136

831010023 NUREQ/CR-2000 V02 N8
LICENSEE EVENT REPORT (LER) COMPILATION For Month of August 1983
* Oak Ridge National Laboratory FIN A-9135 DRNL/NSIC-200 83/09/30 Director's Office 154pp 20703 128.

831010032 NUREQ/CR-3345
AN ASSESSMENT OF POTENTIAL INCREASES IN RISK DUE TO DEGRADATION OF STEAM GENERATOR AND REACTOR COOLANT PUMP SUPPORTS Seismic Safety Margins Research Program
BOHN, M P, WELLS, J E, SHIEH, L C Lawrence Livermore Laboratory
FIN A-0439 UCID-19719 83/08/31 Division of Safety Technology 105pp Available at NRC \$4 75 20703 018

831010034 Further response to FOIA request for records re NUREQ-0861
Investigative report & investigations concerning Facilities Forwards App A documents Commissioner Bradford 811217 memo withheld (ref FOIA Exemption B)
FELTON, J M Division of Rules and Records 83/06/15 REYNOLDS, J Center For Law in the Public Interest App 20713 001

--831010039 Forwards draft ltr to Subcommittee on Energy & Environment Subcommittee on Energy Conservation & Power transmitting NRC review of NUREQ-0862 Comments requested by 820811
KAMMERER, C Office of Congressional Affairs 82/08/09
BICKWIT, L Office of the General Counsel 5pp 20713-008

--831010057 Draft ltr re adequacy of NRC investigation into de of RL Cloud Assoc report, re NUREQ-0862. "Insp Rept of Preliminary Rept Seismic Verification Program at Diablo Canyon Nuclear Power Plant"
PALLADINO, N Commissioners 83/06/15 UDALL, M K House of Interior & Insular Affairs 7pp 20713 024

--831010095 Forwards RL Cloud 820824 request for final statement on conclusions of Cloud/util investigation to clear Cloud proof reputation Matter presented in NUREQ-0862 & SECV-82-89. Commission guidance requested
DIRCKS, W J Office of the Executive Director for Operations 83/09/08 PALLADINO, N Commissioners 1p 20713 031.

--831010103 Informs of delay in review of investigation reported in NUREQ-0862 Completion of report review expected by 820802
CUMMINGS, J J Office of Inspector & Auditor 82/07/15.
PALLADINO, N Commissioners 1p 20713 035

831010056 Requests release of full unexpurgated version of recently completed NUREQ-1020, "GPU vs B&W Lawsuit Review & Effect on TMI-1"
DIECKAMP, H General Public Utilities - GPU Service Corp 83/10/04
PALLADINO, N, ASSELSTINE, J K, BERNTHAL, F Commissioners. 3pp
20665 003 24X Fiche 50-289, 83/10/04, 831010056

831010112 Forwards Phase 1 response for Criteria 1, 2d, 3, 6, 11a & 11b of NUREQ-0737, Item II B 3 re post-implementation review of util post-accident sampling sys Remaining responses will be submitted in 6 months
DAYNE, J P Power Authority of the State of New York JPN-83-85 83/10/05 VASSALLO, D D Operating Reactors Branch 2 18pp
20667 278 24X Fiche 50-333, 83/10/05, 831010112

831010169 NUREQ-0730 V17 N03
NUCLEAR REGULATORY COMMISSION ISSUANCES March 1983 Pp 331-324
* Division of Technical Information & Document Control 83/03/31
200pp 21021 167

831010171 NUREQ/CP-0047
TRANSACTIONS OF THE ELEVENTH WATER REACTOR SAFETY RESEARCH INFORMATION MEETING To Be Held At National Bureau of Standards, Gaithersburg, Maryland, October 24-28, 1983.
* Office of Nuclear Regulatory Research, Director 83/09/30 37pp
Available at NRC \$8 00 20702 001

831010174 NUREQ/CR-2631
A LOGICAL FRAMEWORK FOR IDENTIFYING EQUIPMENT IMPORTANT TO SAFETY IN NUCLEAR POWER PLANTS
GALLUP, D R, VANNOI, H G Sandia Laboratories FIN A-1353
BANDEZ-2726 83/09/30 Division of QA, Safeguards & Inspection Programs (Post 830103) 32pp 20709 297

831010204 Forwards safety evaluation re thermal-hydraulic analysis of 820125 steam generator tube rupture incident Item 7 resolved Reviews of Items 1, 3, 4, 5 & 17 complete Remaining items still under review
CRUTCHFIELD, D Operating Reactors Branch 5 LBOS-83-10-008 83/10/05 MAIER, J E Rochester Gas & Electric Corp 2pp
20665 308 24X Fiche 50-244, 83/10/05, 831010204

--831010206 Safety evaluation supporting licensee evaluation of 830125 steam generator tube rupture incident, per NUREQ-0916
* Office of Nuclear Reactor Regulation, Director 83/10/05. 6pp
20665 310 24X Fiche 50-244, 83/10/05, 831010204

NONDOCKETED ITEMS

8310110217 Forwards status of NUREQ-0822 issues requiring refined engineering analysis or continuation of ongoing evaluation; per 830810 request Addl submittal dates inadvertently omitted by NRC, indicated by asterisks
FIEDLER, P B General Public Utilities - GPU Service Corp 83/10/04
CRUTCHFIELD, D Operating Reactors Branch 5 4pp 20665 036 24X
Fiche 50-219, 83/10/04, 8310110217

8310110222 Forwards application for amend to License DPR-64, changing radiological ETS Sections 6.5.6 B, 6.9 & 6.10 to reflect draft Rev 3 to NUREQ-0472, in response to NRC 820907 1tr
BAYNE, J P Power Authority of the State of New York IPN-83-84
83/09/30 VARGA, S A Operating Reactors Branch 1 2pp 20669 138
24X Fiche 50-286, 83/09/30, 8310110222

--8310110228 Application for amend to License DPR-64, changing radiological ETS Sections 6.5.6 B, 6.9 & 6.10 to reflect draft Rev 3 to NUREQ-0472, in response to NRC 820907 1tr
BAYNE, J P Power Authority of the State of New York 83/09/30
9pp 20669 140 24X Fiche 50-286, 83/09/30, 8310110222

--8310110231 Proposed Tech Spec changes revising Sections 6.5.6 B, 6.9 & 6.10 to reflect draft Rev 3 to NUREQ-0472
* Power Authority of the State of New York 83/09/30 96pp
20669 149 24X Fiche 50-286, 83/09/30, 8310110222

8310110276 Forwards four oversize drawings, closing out NUREQ-0892, SER Outstanding Issue 29 re vacuum breaker valves Valve response meets containment design bases for response time & flow capacity Aperture cards are available in PDR
SORENSEN, O C Washington Public Power Supply System 002-83-872
83/09/28 SCHWENCER, A Licensing Branch 2 2pp 20665 325 24X
Fiche 50-397, 83/09/28, 8310110276

8310110332 Forwards draft Tech Specs to require use of shorting links during initial source range monitors/intermediate range monitors overlap demonstration or post-mod, per NUREQ-0123
SORENSEN, O C Washington Public Power Supply System 002-83-880
83/10/03 SCHWENCER, A Licensing Branch 2 7pp 20666 068 24X
Fiche 50-397, 83/10/03, 8310110332

8310110341 Responds to approval request for info collection re DOE/NRC Forms 741 & 741A for nuclear matl transaction rept & NUREQ/BR-0006, Request approved through 860630 under OMB Number 3150-0003 per Paperwork Reduction Act
SCURRY, N Office of Management & Budget OMB 3150-0003 83/10/03
SCOTT, S Document Management Branch 2pp 20713 199

8310110345 NUREQ-1018
SEISMIC QUALIFICATION OF EQUIPMENT IN OPERATING PLANTS
Status Report, Unresolved Safety Issue A-46
CHANG, T Y Division of Safety Technology 83/09/30 87pp
Available at NRC #4 50 20714 074

8310110347 NUREQ/CR-3259
LEAK DETECTION SYSTEMS FOR URANIUM MILL TAILINGS
IMPOUNDMENTS WITH SYNTHETIC LINERS
MYERS, D A, TYLER, S W, MITCHELL, D H Battelle Memorial Institute,
Pacific Northwest Laboratory FIN B-2476 PNL-4694 83/09/30
Division of Waste Management 53pp Available at NRC #4 00
20714 023

8310110411 Forwards request for addl info re NUREQ-0737 items & safety-related structures, sys & components controlled by QA program (FSAR Table 3.2-1) Responses should be submitted as changes to FSAR by 831027
SCHWENCER, A Licensing Branch 2 83/09/27 RHODE, O K Niagara
Mohawk Power Corp 7pp 20713 344 24X Fiche 50-410, 83/09/27,
8310110411

10110442 Informs that commitment to add high radiation signal for purge & vent valve isolation meets requirements of NUREQ-0737, Item II, E 4.2.7, "Primary Containment High Radiation to Close Vent & Purge Valves"
STOLZ, J F Operating Reactors Branch 4 83/09/29 BECKMAN, J T
Georgia Power Co 2pp 20706 319, 24X Fiche 50-321, 83/09/29,
8310110442

10110446 Forwards FES (NUREG-1011) re repair of steam generators & notice of availability W/o encl
MILLER, J R Operating Reactors Branch 3 83/09/30 PERRIN, S
Environmental Protection Agency 2pp 20704 351 24X
Fiche 50-266, 83/09/30, 8310110446

0110454 Forwards safety evaluation & Franklin Research Ctr technical valuation rept re NUREQ-0612, "Control of Heavy Loads (Phase I) - Phase I acceptable Need for single failure-proof andling equipment will be addressed in Phase II.
TOLZ, J F Operating Reactors Branch 4 83/09/21 BAUER, E O
Philadelphia Electric Co 3pp 20712 076 24X
Fiche 50-277, 83/09/21, 8310110454

--8310110459 Safety evaluation re util 810618, 1222, 820520, 1025 & 830810 responses to NUREQ-0612, "Control of Heavy Loads (Phase I)"
Phase I acceptable
* NRC - No Detailed Affiliation Given 83/09/09 2pp
20712 079 24X Fiche 50-277, 83/09/21, 8310110454

--8309020392 TER-C5506-379/380
"Control of Heavy Loads (C-10), Philadelphia Electric Co, Peach Bottom Atomic Power Station, Units 2 & 3," technical evaluation rept
SARGENT, I H, DOMBERGER, C Franklin Institute/Franklin Research Center TAC 08070 83/08/31 SINGH, A NRC - No Detailed Affiliation Given 32pp 20712 081 24X Fiche 50-277, 83/09/21, 8310110454

8310110457 Notice of availability of FES (NUREG-1011) re steam generator repair
MILLER, J R Operating Reactors Branch 3 83/09/30 2pp
20706 317 24X Fiche 50-266, 83/09/30, 8310110457

8310110460 Forwards safety evaluation re util responses to NUREQ-0737 Item II F 1.4, "Containment Pressure Monitor," Item II F 1.5, "Containment Water Level Monitor" & Item II F 1.6, "Containment Hydrogen Monitor" Items resolved
VARGA, S A Operating Reactors Branch 1 83/09/21 O'TOOLE, J D
Consolidated Edison Co of New York, Inc 10pp 20707 353 24X
Fiche 50-247, 83/09/21, 8310110460

8310110466 Forwards safety evaluation re util responses to NUREQ-0737, Item II K 3.1, "Automatic PORV Isolation," Item II K 3.2, "Rept on PORVs" & GE Owners Group generic rept Review complete Responses acceptable
MILLER, J R Operating Reactors Branch 3 83/09/23 COUNCIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities) 14pp
20712 114 24X Fiche 50-336, 83/09/23, 8310110466

--8307200260 TER-C5506-409
"Operating Reactor PORV Repts (F-37), TMI Action Plan Requirements, C-E Owners Group (CEN-145)," technical evaluation rept
OVERBECK, O J, JENKINS, S M, DELGAIZO, T J Franklin Institute/Franklin Research Center NRC-03-81-130 83/07/18
CHOW, E NRC - No Detailed Affiliation Given 52pp 20712 128
24X Fiche 50-336, 83/09/23, 8310110466

8310110471 Forwards safety evaluation of util responses to NUREQ-0737, Item II E 1.1, "Auxiliary Feeder Sys" Item I re protection from internal missiles unacceptable Requests committed to NRC position within 30 days
STOLZ, J F Operating Reactors Branch 4 DMB 016 83/09/26
RODRIGUEZ, R J Sacramento Municipal Utility District 46pp
20711 320 24X Fiche 50-312, 83/09/26, 8310110471

8310110472 Forwards Franklin Research Ctr "Operating Reactor PORV Repts (F-37) TMI Action Plan Requirements Generic Rept-B&W Designed Units," technical evaluation rept & NRR safety evaluation accepting B&W response to TMI Item II K 3.2
STOLZ, J F Operating Reactors Branch 4 83/09/26 GRIFFIN, J H
Arkansas Power & Light Co 3pp 20712 004 24X
Fiche 50-313, 83/09/26, 8310110472

--8308310422 Forwards safety evaluation accepting B&W licensee contention that requirements of NUREQ-0737, Item II K 3.2 met w/existing PORV, safety valve & high pressure reactor trip setpoints
ROWSOME, F H Assistant Director for Technology Review 83/08/24
LAINAS, O C Assistant Director for Operating Reactors 14pp
20712 007 24X Fiche 50-313, 83/09/26, 8310110472

--8307250463 TER-C5506-410
"Operating Reactor PORV Repts (F-37) TMI Action Plan Requirements Generic Rept - B&W Designed Units," technical evaluation rept
OVERBECK, O J, DELGAIZO, T J Franklin Institute/Franklin Research Center NRC-03-81-130, 83/07/20 CHOW, E NRC - No Detailed Affiliation Given 58pp 20712 019, 24X Fiche 50-313, 83/09/26, 8310110472

8310110476 Forwards safety evaluation supporting installation of RCS high point vents per NUREQ-0737, Item II B 1
STOLZ, J F Operating Reactors Branch 4 83/09/27 RODRIGUEZ, R J
Sacramento Municipal Utility District 9pp 20712 265 24X
Fiche 50-312, 83/09/27, 8310110476

--8306080055 TF-367/0817A
"Selected Operating Reactor Issues Program II RCS Vents (NUREG-0737, Item II B 1)," final technical evaluation rept for Rancho Seco I.
HELD, J T Energy Incorporated FIN A-0250 TAC 44402 83/03/14
ABERTHAL, O NRC - No Detailed Affiliation Given 9pp
20712 274 24X Fiche 50-312, 83/09/27, 8310110476

NONDOCKETED ITEMS

451

8310110483 Forwards safety evaluation re NUREG-0737, Item II B 3, "Post-Accident Sampling Sys (PASS) " Core damage estimate procedure including comparison of PASS data w/other plant parameters, should be provided Item complete
MILLER, J R Operating Reactors Branch 3 83/09/28 UHRIG, R E
Florida Power & Light Co 13pp 20714 328 24X
Fiche 50-335, 83/09/28, 8310110483

8310110532 NUREG-0383 V02 R06
DIRECTORY OF CERTIFICATES OF COMPLIANCE FOR RADIOACTIVE
MATERIALS PACKAGES Certificates Of Compliance
* Division of Fuel Cycle & Material Safety 83/09/30 418pp
Available at NRC \$11 00 20710 001

8310110543 Forwards SCR re util 791231, 810621 & 820402 responses to NUREG-0737, Item II B 1, "RCS Vents " & "Selected Operating Reactor Issues Program II RCS Vents (NUREG-0737, Item II B 1)," final technical evaluation rept
MILLER, J R Operating Reactors Branch 3 83/09/20 COUNSEL, H G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 11pp
20712 180 24X Fiche 50-336, 83/09/20, 8310110543

--8306080045 TF-349/0812A
"Selected Operating Reactor Issues Program II RCS Vents (NUREG-0737, Item II B 1)," final technical evaluation rept
HCLD, J T Energy Incorporated * Lawrence Livermore Laboratory
FIN A-0250 TAC 44385 83/03/02 ALBERTHAL, G NRC - No Detailed
Affiliation Given 6pp 20712 191 24X Fiche 50-336, 83/09/20, 8310110543

8310110560 NUREG/CR-3048
CLOSEOUT OF IE BULLETIN 80-21 VALVE PARTS SUPPLIED BY
MALCOLM FOUNDRY
FOLEY, H J, HENNICK, A Parameter, Inc FIN D-1013 PARAMETER
IE-12 83/09/30 Division of Emergency Preparedness & Engineering
Response (Post 830103) 35pp Available at NRC \$3 75 20714 281

8310110593 NUREG-0383 V03 R03
DIRECTORY OF CERTIFICATES OF COMPLIANCE FOR RADIOACTIVE
MATERIALS PACKAGES Summary Report Of NRC Approved Quality
Assurance Programs For Radioactive Material Packages
* Division of Fuel Cycle & Material Safety 83/09/20 42pp
Available at NRC \$5 50 20715 001

8310110630 Forwards comments on NUREG-1020 re GPU vs B&W lawsuit review & effects on TMI-1 Errors in App B should be corrected to reflect findings concerning relevance & materiality of lawsuit documents
MATTHEW, R J Division of Systems Integration (post 811005)
83/09/22 FISENHUT, D G Division of Licensing 3pp 20714 278
24X Fiche 50-289, 83/09/22, 8310110630

8310120051 Advises that comments re NUREG-1020 "GPU vs B&W Lawsuit Review & Effect on TMI-1," were faxed to R Capra on 830920.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/27 FISENHUT, D G Division of
Licensing 1p 20715 327 24X Fiche 50-289, 83/09/27, 8310120051

8310120054 Concurs in draft NUREG-1020 "GPU vs B&W Lawsuit Review & Effect on TMI-1 "
VOLLNER, H H Division of Engineering 83/09/26 RUSSELL, W T. NRC
- No Detailed Affiliation Given 1p 20749 355 24X
Fiche 50-289, 83/09/26, 8310120054

8310120057 Forwards IC/Region I comments re Subj Area 5 of NUREG-1020 "GPU vs B&W Lawsuit Review & Effect on TMI-1," constituting concurrence w/NUREG
TAYLOR, J M Division of QA, Safeguards & Inspection Programs (Post 830103) 83/09/23 FISENHUT, D G Division of Licensing 1p
20749 354 24X Fiche 50-289, 83/09/23, 8310120057

8310120059 Forwards marked-up Tech Spec re ECCS in response to 830923 request for proposed change to surveillance requirements on automatic depressurization sys backup air supply, per SCR, NUREG-0892 & Item II K 3 20
SORENSEN, G C Washington Public Power Supply System 002-83-891
83/10/06 SCHWENCER, A Licensing Branch 2 2pp 20697-101 24X
Fiche 50-397, 83/10/06, 8310120059

8310120060 Forwards NUREG-1020 "GPU vs B&W Lawsuit & Effect on TMI-1 " Distribution of Category 10 section "Mgt Competence/ Integrity" should be limited pending OFC of Investigations completion of investigation
DIRCKB, W J Office of the Executive Director for Operations
83/09/28 PALLADINO, N J Commissioners 2p 20715 362 24X
Fiche 50-289, 83/09/28, 8310120060

8310120072 Discusses actions to be taken to resolve turbine missile issue identified in SSER 4, Section 1 9, including development of turbine & valve maint programs described in NUREG-0800 for main turbine throttle & governing valves
DRUMMOND, F J Louisiana Power & Light Co 43F83-0328 83/10/05
KNIGHTON, G W Licensing Branch 3 2pp 20697 161 24X
Fiche 50-382, 83/10/05, 8310120072

8310120090 Forwards IE Insp Rept 50-220/83-20 on 830721 & 25-0826 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/09/20
RHODE, G K Niagara Mohawk Power Corp 2pp 20697 128 24X
Fiche 50-220, 83/09/20, 8310120090

--8310120096 IE Insp Rept 50-220/83-20 on 830721 & 25-0826 No noncompliance noted Major areas inspected licensee action on previous insp findings, operational safety verification, physical security surveillance testing & safety sys
HUDSON, G D, MCDREARY, R A Region 1, Office of Director
LAZARUS, H J Division of Project & Resident Programs 83/09/16
12pp 20697 130 24X Fiche 50-220, 83/09/20, 8310120090

8310120191 Forwards info re NUREG-0737, Item II F 2, "Instrumentation for Detection of Inadequate Core Cooling," in response to 830906 request Addl info will be submitted by 840215
SIMPSON, E C Florida Power Corp 3F-1063-09 83/10/07 STOLZ, J F
Operating Reactors Branch 4 6pp 20695 320 24X
Fiche 50-302, 83/10/07, 8310120191

8310120194 Forwards addl info on NUREG-0737, Item II K 3 17, "Rept on Outages of ECCS", per 830829 telcon & NRC 830819 1st Addl data factored into probabilistic safety study submitted on 830305
OTTOLE, J D Consolidated Edison Co of New York, Inc 83/09/30
VARONA, S A Operating Reactors Branch 1 5pp 20696 098 24X
Fiche 50-247, 83/09/30, 8310120194

8310120198 Forwards IE Insp Rept 50-286/83-16 on 830816-0915 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/09/20
BRONB, J C Power Authority of the State of New York 2pp
20695 335 24X Fiche 50-286, 83/09/20, 8310120198

--8310120199 IE Insp Rept 50-286/83-16 on 830816-0915 No noncompliance noted Major areas inspected maint review of monthly operating rept, TMI task action plan status, licensee actions on previous insp findings, plant tour & surveillance
KENNY, T J, RUSSBACH, L W, NORRHOUGH, L Region 1, Office of Director 83/09/19 12pp 20695 337 24X Fiche 50-286, 83/09/20, 8310120198

8310120219 Responds to unresolved issues contained in draft SER, NUREG-1002 dtd 830715 Some items re NRC site audits unresolved
SHARTZ, E D Commonwealth Edison Co 7329N 83/09/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 44pp 20692 179
24X Fiche 50-456, 83/09/30, 8310120219

8310120232 Forwards response to Phase I of NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants," per BJ Youngblood 830811 request for addl info All cranes & hoists purchased to Sargent & Lundy specs
WILLIAMS, J Cincinnati Gas & Electric Co LOZ-83-0163 83/10/06
DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp
20692 103 24X Fiche 50-358, 83/10/06, 8310120232

8310120335 Discusses proposed implementation of emergency preparedness training plan First phase, per NUREG-0654, will be completed prior to fuel load Detailed schedules will be completed & made available for review upon concurrence
SORENSEN, G Washington Public Power Supply System 002-83-886
83/10/04 SCHWENCER, A Licensing Branch 2 2pp 20699 277 24X
Fiche 50-397, 83/10/04, 8310120335

8310120349 Advises that due to uncertainty in instrumentation availability & manpower resources, instrumentation necessary to meet Reg Guide 1 97 requirements will be implemented by third refueling outage per Suppl 1 to NUREG-0737
DALE, L F Mississippi Power & Light Co 0L-82-33 83/10/10
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp,
20700 231 24X Fiche 50-416, 83/10/10, 8310120349

8310120359 Advises that util has incorporated three LRO-11 position papers into OL application Position Paper 3-C80, "Periodic Low Pressure Leakage Testing of Druegell," constituting response to Confirmatory Issue 66 of BER (NUREG-0853)
NELSON, R H Illinois Power Co U-0071 83/09/30 SCHWENCER, A
Licensing Branch 2 3pp 20700 206 24X Fiche 50-461, 83/09/30, 8310120359

NONDOCKETED ITEMS

- 8310120373 Requests 2-yr extension to implementation date in amended rule 10CFR50.44(m) requiring min number of licensed operators & senior operators on shift at all times TMI Item 1 A 1 3 implemented using shift technical advisor MANGAN, C V Niagara Mohawk Power Corp 83/10/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20699 197 24X Fiche 50-220, 83/10/06, 8310120373
- 8310130018 Forwards SORT qualification summary of equipment list update & response to SSER 3 (NUREG-0798) open items TAUBER, H Detroit Edison Co EP2-65,621 83/10/04 YOUNGBLOOD, B J Licensing Branch 1 68pp 20725 123 24X Fiche 50-341, 83/10/04, 8310130018
- 8310130077 Forwards request for OMB review & supporting statement re Std Form 83 & supporting statements for DOE/NRC Forms 742 & 742C MORRIS, P O Office of Administration 83/10/03 SCURRY, N Office of Management & Budget 1p 20777 011
- 8310130106 Forwards safety evaluation supporting util response to TMI Item II D 1, "Safety & Relief Valve Testing" Issue resolved VASSALLO, D B Operating Reactors Branch 2 83/09/30, PILANT, J M Nebraska Public Power District 17pp 20777 027 24X Fiche 50-298, 83/09/30, 8310130106
- 8310130122 Forwards for review & comment, final draft of Chapter 10 to NUREG-1020, "Mgt Competence/Integrity" Requests determination as to which portions of chapter cannot be publicly released H/O encl DENTON, H R Office of Nuclear Reactor Regulation, Director 83/09/20 HAYES, B B Office of Investigation 1p 20777 074
- 8310130130 NUREG-1022 LICENSEE EVENT REPORT SYSTEM Description Of System And Guidelines For Reporting HERBON, F J Director's Office 83/09/30 88pp 20772 189
- 8310130133 NUREG-0090 V06 NO1 REPORT TO CONGRESS ON ABNORMAL OCCURRENCES January-March 1983 * Director's Office 83/09/30 49pp 20772 280
- 8310130143 NUREG/CR-3451 BENCHMARK PROBLEMS FOR RADIOLOGICAL ASSESSMENT CODES MILLS, M, VOGT, D J, MANN, B Teknekron Research, Inc 83/09/30 Division of Waste Management 91pp 20773 015
- 8310130149 NUREG-0485 V05 NO8 SYSTEMATIC EVALUATION PROGRAM STATUS SUMMARY REPORT Data As Of August 31, 1983 (Buff Book) * Office of Resource Management, Director 83/09/30 74pp 20773 109
- 8310130151 NUREG-0383 V01 R06 DIRECTORY OF CERTIFICATES OF COMPLIANCE FOR RADIOACTIVE MATERIALS PACKAGES Summary Report Of NRC Approved Packages * Division of Fuel Cycle & Material Safety 83/09/30 432pp 20773 186
- 8310130217 Forwards Amends 75 & 56 to Licenses DPR-58 & DPR-74, respectively Amends change Tech Spec to require redundant containment hydrogen analyzers to satisfy requirements of NUREG-0737, TMI Action Item II F 1 6 VARQA, S A Operating Reactors Branch 1 83/09/30 DOLAN, J Indiana & Michigan Electric Co. DOLAN, J American Electric Power Service Corp 3pp 20777 180 24X Fiche 50-315, 83/09/30, 8310130217
- 8310130222 Amends 75 & 56 to Licenses DPR-58 & DPR-74, respectively, changing Tech Spec to require redundant containment hydrogen analyzers to satisfy requirements of NUREG-0737, TMI Action Item II F 1 6 VARQA, B A Operating Reactors Branch 1 DPR-74 A 056 83/09/30 9pp 20777 183 24X Fiche 50-315, 83/09/30, 8310130217
- 8310130276 Forwards evaluation of util 830831 plant design submittal in response to integrated plant BAR (NUREG-0827) Section 4 24 1, App K, "Electrical Instrumentation & Control Reviews for LACBMR" Issue resolved CRUTCHFIELD, D Operating Reactors Branch 5 LB05-83-10-016 83/10/07 LINDER, F Dairyland Power Cooperative 7pp 20723 198 24X Fiche 50-409, 83/10/07, 8310130276
- 8310130326 Forwards list of long-term actions that should be addressed in BER input Only noncertification items to be addressed in review, EISENHUT, D. O. Division of Licensing 83/08/12 MATTHEW, R J Division of Systems Integration (post 811005), THOMPSON, H L Division of Human Factors Safety JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 831013), 5pp 20754 332 24X Fiche 50-289, 83/08/12, 8310130326
- 8310130382 Forwards Franklin Research Ctr "Operating Reactor PORV Repts (F-37), TMI Action Plan Requirements, Generic Rept - B&W Designed Units," technical evaluation rept & NRR safety evaluation accepting B&W response to TMI Item II K 3 2 STOLZ, J F Operating Reactors Branch 4 83/09/23 CROUSE, R P Toledo Edison Co 3pp 20770 120 24X Fiche 50-346, 83/09/23, 8310130382
- 8310130393 Summary of 830908 meeting w/utills soliciting feedback on proposed NRC human factors review of safety parameter display sys Encl marked-up NUREG-0833 revised to resolve 830908 comments BELTRACCHI, L Human Factors Engineering Branch 83/09/16 MOORE, V A Human Factors Engineering Branch 72pp 20769 271
- 8310130421 Forwards safety evaluation & technical evaluation rept re NUREG-0737, TMI Items II K 3 1, "Automatic PORV Isolation" & II K 3 2, "Rept on PORVs" Requirements met STOLZ, J F Operating Reactors Branch 4 83/09/30 WILGUS, W S Florida Power Corp 3pp 20769 167 24X Fiche 50-302, 83/09/30, 8310130421
- 8310140196 Forwards Rev O to "Plant-Unique Analysis Rept of Torus Suppression Chamber," Mark I containment program technical rept, per acceptance criteria in App A to NUREG-0661 DAYNE, J P Power Authority of the State of New York JPN-83-88 83/10/11 VASSALLO, D B Operating Reactors Branch 2 1p 20762 084 24X Fiche 50-333, 83/10/11, 8310140196
- 8310140202 TR-9321-1 R00 Rev O to "Plant-Unique Analysis Rept of Torus Suppression Chamber," Mark I containment program technical rept for James A Fitzpatrick Nuclear Power Plant * Teledyne Engineering Services 83/08/11 144pp 20762 086 24X Fiche 50-333, 83/10/11, 8310140196
- 8310140221 Responds to 830823 request for position re NUREG-0737, Item II E 4.2(7), "Containment Isolation on High Radiation" Completion of evaluation anticipated by 831201 MANGAN, C V Niagara Mohawk Power Corp 83/10/12 VASSALLO, D B Operating Reactors Branch 2 1p 20761 182 24X Fiche 50-220, 83/10/12, 8310140221
- 8310140223 Advises that in initial evaluation of SEP Topic VI-4, "Containment Isolation Sys (Electrical)" penetrations erroneously evaluated against GDC 53 instead of GDC 57 Addl mods to plant configuration unnecessary KRIEGER, R W Southern California Edison Co 83/09/30 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 20761 179 24X Fiche 50-206, 83/09/30, 8310140223
- 8310140254 Forwards fourth semiannual "Rept on Environ Qualification Program for Duane Arnold Energy Ctr" covering safety-related electrical equipment MCCOUGHY, R W Iowa Electric Light & Power Co NO-83-3368 83/09/30 DENTON, H Office of Nuclear Reactor Regulation, Director 2pp 20759 300 24X Fiche 50-331, 83/09/30, 8310140254
- 8310140258 "Rept on Environ Qualification Program for Duane Arnold Energy Ctr," fourth semiannual rept * Bechtel Corp IEB-79-01B 83/09/22 420pp 20759 302 24X Fiche 50-331, 83/09/30, 8310140254
- 8310140278 Forwards draft response to 830915 Request for Addl Info RAI 271 2 re qualification of automatic depressurization sys accumulators per TMI Item II K 3 2B Response will be incorporated in Nov 1983 FSAR rev BRADLEY, E J Philadelphia Electric Co GOVT 1-1(NRC) 83/10/05 SCHWENGER, A Licensing Branch 2 9pp 20761 186 24X Fiche 50-352, 83/10/05, 8310140278
- 8310170001 Forwards 830908 memo requesting support for NRC rept on GPU vs B&W lawsuit review Arrangements should be made to accommodate requested schedule STEELE, H L Division of Technical Information & Document Control 83/09/09 MCVEIGH, H D Division of Technical Information & Document Control JOHANNSEN, J Cross Branch 1p 20814 048 24X Fiche 50-289, 83/09/09, 8310170001
- 8310170002 Requests assistance in arranging resources for production & publication of NRC evaluation of GPU vs B&W lawsuit review & impact on restart of TMI-1 (NUREG-1020) Flow chart w/projected milestones encl RUSSELL, W T GPU/B&W Lawsuit Review Team 83/09/08 BESAW, W J Division of Technical Information & Document Control 3pp 20814 049 24X Fiche 50-289, 83/09/09, 8310170001
- 8310170009 Forwards Suppl 4 to NUREG-0420, "BER re Operation of Shoreham Nuclear Power Station, Unit 1" SCHWENGER, A Licensing Branch 2 83/09/30 POLLOCK, M S Long Island Lighting Co 3pp 20814 067 24X Fiche 50-322, 83/09/30, 8310170009

NONDOCKETED ITEMS

457

8310170014 Forwards revised listing of subj area contents for GPU vs B&W lawsuit review, per 830727 & 0805 & 12 ltrs
RUSSELL, W T GPU/B&W Lawsuit Review Team 83/08/18 MORISSEAU, D.
PICKETT, D, HAASS, W NRC - No Detailed Affiliation Given 14pp
20813 285 24X Fiche 50-289, 83/08/18, 8310170014

8310170018 Forwards draft NUREG-1020, "GPU vs B&W Lawsuit Review & Effect on TMI-1 " Draft does not include Chapter 10 re mgt competence/integrity Comments or concurrence requested
W/n encl
RUSSELL, W T GPU/B&W Lawsuit Review Team 83/09/19 EISENHUT, D G
Division of Licensing MATTSO, R J Division of Systems Integration
(post 811005) THOMPSON, H L Division of Human Factors Safety
2pp 20798 358 24X Fiche 50-289, 83/09/19, 8310170018

8310170025 Forwards final draft Chapter 10 to NUREG-1020 entitled "Mgt Competence/Integrity " Changes, comments or concurrence requested by 830922 W/o encl
EISENHUT, D G Division of Licensing 83/09/20 MATTSO, R J
Division of Systems Integration (post 811005) THOMPSON, H L
Division of Human Factors Safety TAYLOR, J M Division of QA,
Safety & Inspection Programs (Post 831013) 2pp 20798 353
24X Fiche 50-289, 83/09/20, 8310170025

8310170032 Requests assistance in arranging resources for production & publication of NRC evaluation of GPU vs B&W lawsuit review & impact on TMI-1 restart (NUREG-1020)
RUSSELL, W T GPU/B&W Lawsuit Review Team 83/09/08 BESAW, W J
Division of Technical Information & Document Control 3pp
20798 334 24X Fiche 50-289, 83/09/08, 8310170032

8310170039 Forwards SER & technical evaluation rept re licensee responses to NUREG-0737, Items II K 3 1, "Automatic PORV Isolation" & II K 3 2, "Rept on PORVs"
VARGA, S A Operating Reactors Branch 1 83/10/05 UDERITZ, R A
Public Service Electric & Gas Co of New Jersey 3pp 20812 162
24X Fiche 50-272, 83/10/05, 8310170039

8310170043 Advises of disapproval of exception to habitability requirements for emergency operation facility (EOF), per 830503 ltr Plans for establishing EOF per Suppl 1 to NUREG-0737 (Generic Ltr 82-33) requested by 831128
EISENHUT, D G Division of Licensing 83-82-33 83/09/29
WITHERS, B D Portland General Electric Co 5pp 20798 035 24X
Fiche 50-344, 83/09/29, 8310170043

8310170088 Forwards Franklin Research Ctr "Operating Reactor PORV Repts (F-37) TMI Action Plan Requirements, C-E Owners Group (CEN-145)," technical evaluation rept & safety evaluation supporting responses to TMI Items II K 3 1 & II K 3 2
MILLER, J R Operating Reactors Branch 3 83/10/06 UHRIG, R E
Florida Power & Light Co 3pp 20813 135 24X
Fiche 50-335, 83/10/06, 8310170088

--8310170092 Safety evaluation supporting C-E licensee responses to NUREG-0737, Item II K 3 2, "Rept on PORVs"
* NRC - No Detailed Affiliation Given 83/10/06 62pp
20813 138 24X Fiche 50-335, 83/10/06, 8310170088

8310170159 Forwards clarification of evaluation of pipe whip, jet impingement & breaks within pipe tunnel (SEP Topic III 5 B), per 830720 request transmitting integrated plant safety assessment program (NUREG-0827)
LINDER, F Dairyland Power Cooperative LAC-9351 83/10/06
CRUTCHFIELD, D Operating Reactors Branch 5 4pp 20788 347 24X
Fiche 50-409, 83/10/06, 8310170159

8310170204 Forwards SSER 2 (NUREG-0852) re CESSAR & application for final design approval W/o encl
THOMAS, C D Standardization & Special Projects Branch 83/09/30
SCHERER, A E Combustion Engineering, Inc 2pp 20798 092 24X
Fiche 50-470, 83/09/30, 8310170204

8310170235 Forwards response to telcon request for addl clarification of response to Question 640 01 a & b re emergency operating procedures generation package SER (NUREG-0892) Confirmatory Issue 15 re emergency procedures review closed
SORENSEN, G C Washington Public Power Supply System 002-83-908
83/10/11 SCHWENCER, A Licensing Branch 2 69pp 20787 013 24X
Fiche 50-397, 83/10/11, 8310170235

8310170298 Forwards loose parts detection sys conformance evaluation, including action requested in NUREG-0892, SER Section 4 & 6
SORENSEN, G C Washington Public Power Supply System 002-83-860
83/09/29 SCHWENCER, A Licensing Branch 2 8pp 20785 186 24X
Fiche 50-397, 83/09/29, 8310170298

8310170373 Forwards SER re reactor coolant pump trip & restart criteria after 820125 tube failure incident Adequate steps taken addressing items, based on info provided in 821122 ltr & 830422 response to Generic Ltr 83-10d Items 8 & 9 resolved
CRUTCHFIELD, D Operating Reactors Branch 5 83-83-10D 83/10/14
MAIER, J E Rochester Gas & Electric Corp 2pp 20788 005 24X
Fiche 50-244, 83/10/14, 8310170373

--8310170378 SER supporting resolution of SER Items 8 & 9 re reactor coolant pump trip & restart criteria after 820125 tube failure incident
* Office of Nuclear Reactor Regulation, Director 83/10/14 5pp
20785 007 24X Fiche 50-244, 83/10/14, 8310170373

8310170394 Forwards draft App D to radiological emergency response plans for Towns of Newfields, New Castle, North Hampton & Brentwood, NH, entitled "Cross-Reference to NUREG-0654 "
LESSY, R P Hearing Branch 3 ISSUANCES DL 83/10/12 HOYT, H
Atomic Safety and Licensing Board Panel 26pp 20785 045 24X
Fiche 50-443, 83/10/12, 8310170394

8310170495 Request that NUREG-0123, "Std BWR Tech Specs," be revised to previous format, based on need to provide adequate time frame for completion of WPPSS-2 power ascension testing program
Susquehanna test duration data encl
SORENSEN, G C Washington Public Power Supply System 002-83-900
83/10/10 SCHWENCER, A Licensing Branch 2 3pp 20784 015 24X
Fiche 50-000, 83/10/10, 8310170495

8310170545 Provides addl info re NUREG-0737, Item II K 3 22, justifying use of HPCI logic for RCIC suction switchover RCIC sys not safety-related & is not intended as backup for HPCI sys
RYBAK, B Commonwealth Edison Co 7434N 83/10/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 20784 320 24X
Fiche 50-254, 83/10/07, 8310170545

8310170656 Requests rev to confirmatory order contained in 830314 ltr for NUREG-0737 Items II F 1 1 & II F 1 2 to specify new 840101 completion date Replacement of Geiger-Mueller in detectors will be completed by 840101
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 810880, 83/09/27
MILLER, J G Operating Reactors Branch 3 2pp 20782 070 24X
Fiche 50-245, 83/09/27, 8310170656

8310170674 Forwards IE Insp Rept 50-312/83-16 on 830606-10, 13 & 21-22 No noncompliance noted
WENSLAWSKI, F A Region 5, Office of Director 83/09/16
RODRIGUEZ, R J Sacramento Municipal Utility District 2pp
20779 295 24X Fiche 50-312, 83/09/16, 8310170674.

--8310170678 IE Insp Rept 50-312/83-16 on 830606-10, 13 & 21-22 No noncompliance noted Major areas inspected environ protection, followup on RODs, info notices, onsite events, noncompliance items & NUREG-0737, Items II B 3 & II F 1
NORTH, H S, WENSLAWSKI, F A Region 5, Office of Director 83/09/16 10pp 20779 297 24X Fiche 50-312, 83/09/16, 8310170674

8310170708 Advises that requirements of NUREG-0737, Item II K 3 2 re rept on PORVs met w/existing PORV safety valve & reactor high pressure trip setpoints Automatic PORV isolation sys (Item II K 3 1) not needed
MILLER, J R Operating Reactors Branch 3 83/10/04 GARRITY, J H
Maine Yankee Atomic Power Co 3pp 20813 200 24X
Fiche 50-309, 83/10/04, 8310170708

8310170715 Forwards safety evaluation of FSAR Amend 38 re NUREG-0737, Item II F 2, "Detection of Inadequate Core Cooling," Amend unacceptable Justification for proposed late implementation of in-core thermocouples requested
YOUNGLOOD, B J Licensing Branch 1 83/10/07 GRAY, R J Texas
Utilities Generating Co 4pp 20798 122 24X Fiche 50-445,
83/10/07, 8310170715

8310170722 Forwards comments on util detailed control room design review submitted in response to Generic Ltr 82-33, "Suppl 1 to NUREG-0737 Requirements for Emergency Response Capability " Info mgt sys discussion needs more detail
YOUNGLOOD, B J Licensing Branch 1 83-82-33 83/10/05
KOEHLER, G L Kansas Gas & Electric Co 10pp 20798 100 24X
Fiche 50-000, 83/10/05, 8310170722

8310170723 Forwards FES re steam generator repair (NUREG-1011) W/o encl
MILLER, J R Operating Reactors Branch 3 83/09/30 FAY, C W
Wisconsin Electric Power Co 2pp 20798 096 24X
Fiche 50-266, 83/09/30, 8310170723

8310180020 Forwards comments on 820812 detailed control room design review program plan Plan unacceptable per NUREG-0737, Suppl 1 Comments & response will be basis for telcon within 15 days of ltr date
MILLER, J R Operating Reactors Branch 3 83/10/04 GARRITY, J H
Maine Yankee Atomic Power Co 10pp 20823 055 24X
Fiche 50-309, 83/10/04, 8310180020

8310180071 NUREG-0996
SAFETY EVALUATION REPORT RELATED TO THE RENEWAL OF THE OPERATING LICENSE FOR THE UNIVERSITY OF OKLAHOMA RESEARCH Reactor Docket No 50-112.
* Division of Licensing 83/09/30, 57pp 20826 174 24X
Fiche 50-112, 83/09/30, 8310180071

NONDOCKETED ITEMS

- 8310180076 NUREG/CR-2574
BWR REFILL-REFLOOD PROGRAM TASK 4 7 - MODEL DEVELOPMENT
TRAC-BWR COMPONENT MODELS
CHEUNG, Y K, PARAMESWARAN, V, SHAUG, J C General Electric Co FIN
B-5877 EPRI NP-2376 83/09/30 Division of Accident Evaluation
120pp Available at NRC \$5 00 20826 235
- 8310180079 NUREG/CR-3050
CLOSEOUT OF IE BULLETIN 81-02 AND SUPPLEMENT Failure Of
Gate-Type Valves To Close Against Differential Pressure
FOLEY, W J, HENNICK, A Parameter, Inc FIN B-1013 PARAMETER
IE-12 83/09/30 Division of Emergency Preparedness & Engineering
Response (Post 830103) 51pp Available at NRC \$4 50 20826 11
- 8310180085 NUREG/CR-2573
BWR REFILL-REFLOOD PROGRAM TASK 4 7 - MODEL DEVELOPMENT
BASIC MODELS FOR THE BWR VERSION OF TRAC
ANDERSEN, J O, CHU, K H, SHAUG, J C General Electric Co FIN
B-5877 EPRI NP-2376 83/09/30 Division of Accident Evaluation
113pp 20826 001
- 8310180092 Ack receipt of 830915 request for info concerning open
issues re mgt integrity identified in 830519 & 0715 memos to
Commission NRC evaluation of open issues proceeding w/
exception of GPU vs B&W lawsuit record
DIRCKS, W J Office of the Executive Director for Operations
83/10/07 DIECKAMP, H General Public Utilities - GPU Service Corp
1p 20824 125 24X Fiche 50-289, 83/10/07, 8310180092
- 8310180099 Requests NRC provide identification & evaluation of specific
concerns remaining or developed as result of evaluation of
open issues Also requests all related recent insp repts &
basis for concern in other areas
DIECKAMP, H General Public Utilities - GPU Service Corp
83/09/15 DIRCKS, W J Office of the Executive Director for
Operations App 20824 128 24X Fiche 50-289, 83/10/07,
8310180092
- 8310180098 Forwards "Summary Rept & Program Plan for Control Room
Design Review," per 830707 ltr re NUREG-0737, Item I D 1
activities
MANGAN, C V Niagara Mohawk Power Corp 83/09/30 VASSALLO, D B
Operating Reactors Branch 2 1p 20807 184 24X
Fiche 50-220, 83/09/30, 8310180098
- 8310180102 "Summary Rept & Program Plan for Control Room Design
Review"
* Niagara Mohawk Power Corp 83/09/30 23pp 20807 185 24X
Fiche 50-220, 83/09/30, 8310180098
- 8310180118 NUREG/CR-3223
BWR REFILL, REFLOOD PROGRAM FINAL REPORT
MYERS, L L General Electric Co * Electric Power Research
Institute FIN B-5877 EPRI NP-3093 83/09/30 Division of
Accident Evaluation 142pp Available at NRC \$5 30 20825 176
- 8310180131 Advises that continued operation until completion of mods re
NUREG-0737, Item II E 4 2 concerning gap opening of two sys.
justified Licensee committed to modifying logic at first
refueling outage
SCHWENGER, A Licensing Branch 2 83/09/29 CURTIS, N H
Pennsylvania Power & Light Co 3pp 20827 077 24X
Fiche 50-387, 83/09/29, 8310180131
- 8310180166 Forwards FSAR Section 9 i re reactor bldg crane, revised in
response to NUREG-0612 Changes will be incorporated into
next FSAR amend
CURTIS, N H Pennsylvania Power & Light Co PLA-1667 83/10/13
SCHWENGER, A Licensing Branch 2 28pp 20809 001 24X
Fiche 50-388, 83/10/13, 8310180166
- 8310180169 NUREG-1016
SAFETY EVALUATION REPORT RELATED TO THE RENEWAL OF THE
OPERATING LICENSE FOR THE RESEARCH REACTOR AT THE IOWA
STATE UNIVERSITY Docket No. 50-116
* Division of Licensing 83/09/30 83pp Available at NRC
\$4 75. 20825 089 24X Fiche 50-116, 83/09/30, 8310180169.
- 8310180193 Forwards response to requests for addl info re special
lifting devices used for control of heavy loads
(ref NUREG-0612)
MAIER, J E Pacific Gas & Electric Co 83/10/12 CRUTCHFIELD, D
Operating Reactors Branch 5 22pp 20809 061. 24X
Fiche 50-244, 83/10/12, 8310180193
- 8310180196 Informs that based on review of 830414 submittal, licensee
forward command post (emergency operations facility)
complies w/requirements of Table 1 to Suppl 1 of NUREG-0737
MADSEN, O L Region 4, Office of Director 83/08/16 LEE, D R
Public Service Co. of Colorado. 1p 20808 341. 24X
Fiche 50-267, 83/08/16, 8310180196
- 8310180317 Forwards Rev 1 to "Emergency Procedure Generation Package,
& Rev 1 to "Writers Guide For Emergency Operating
Procedures," per Generic Ltr 82-33 (NUREG-0737, Suppl 1)
Listed SER items resolved
KOESTER, G L Kansas Gas & Electric Co KMLNRC 83-132 83/10/14
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
20803 101 24X Fiche 50-482, 83/10/14, 8310180317
- 8310180344 Revises schedule for submittal of svc water sys analysis
identified in Integrated Plant Safety Assessment, NUREG-0826
& associated SEP Topic IV-3 Delays due to upgrades per
NUREG-0737, Item III D 3 4 Analysis expected by 831230
COUNCIL, W G Connecticut Yankee Atomic Power Co 810915 83/10/0
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 20802 358 24X
Fiche 50-213, 83/10/07, 8310180344
- 8310180347 Comments on NUREG-1020 re GPU vs B&W lawsuit review NRC di
not make reasonable technical judgments, leaving issues that
should have been resolved re mgt integrity as issues
potentially involving integrity
DIECKAMP, H General Public Utilities - GPU Service Corp 83/10/14
FALLADINO, N J, ASSELSTINE, J K, BERNTHAL, F Commissioners 35pp
20804 301 24X Fiche 50-289, 83/10/14, 8310180347
- 8310180379 Approves request for withholding listed proprietary info re
inadequate core cooling per TMI Item II F 2 from public
disclosure (ref 10CFR2 790)
CRUTCHFIELD, D Operating Reactors Branch 5 1805-83-10-029
83/10/11 WIESEMANN, R A Westinghouse Electric Corp 2pp
20826 355
- 8310180381 Suppl 830720 response to Generic Ltr 81-07, "Control of
Heavy Loads," in response to NRC finding in IE Insp Rept
83-11, dtd 830620 Info documents util methodology for
compliance w/NUREG-0612 & ANSI N 14 6
UHRIG, R E Florida Power & Light Co L-83-515 83/10/07
EISENHUT, D G Division of Licensing 2pp 20803 201 24X
Fiche 50-250, 83/10/07, 8310180381
- 8310180385 Forwards list of new licensing actions, completed actions &
action summary During Last Quarter FY83, considerable time
spent on Rev 1 to update FSAR & preparation of confirmatory
order for NUREG-0737 items in Suppl 1
WAGNER, P C Region 4, Office of Director 83/10/06 MADSEN, O L
Region 4, Office of Director 8pp 20803 207 24X
Fiche 50-267, 83/10/06, 8310180385
- 8310180421 Informs of proposed minor changes to commitments made in
response to implementation instructions of NUREG-0770, re
short-term lessons learned Duty technical advisor quarters
will be incorporated in boundary control ctr
FAY, C W Wisconsin Electric Power Co 83/10/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20803 306
24X Fiche 50-266, 83/10/10, 8310180421
- 8310180422 Requests relief from scheduler requirements of 830325
confirmatory orders to install redundant in-containment
radiation monitors, per NUREG-0737, Item II F 1 3 requirement
Mod will be completed before startup in Cycle 7
KAMMER, D S Tennessee Valley Authority 83/10/12 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20803 308
24X Fiche 50-259, 83/10/12, 8310180422
- 8310180424 Responds to D Vassallo 830823 ltr re automatic closing of
containment purge & vent valves on high radiation signal
(NUREG-0737, Item II F 4 2(7)) Facility will be modified, as
result of evaluation of BWR Owners Group position
MCGAUGHY, R W Iowa Electric Light & Power Co NO-83-3453
83/10/13 DENTON, H R Office of Nuclear Reactor Regulation,
Director 1p 20803 305 24X Fiche 50-331, 83/10/13, 8310180424
- 8310180435 Forwards Rev 0 to "Detailed Control Room Design Review
Program Plan, per NUREG-0737, Suppl 1 (Generic Ltr 82-33)
HARRINGTON, W D Boston Edison Co 83-259 83/10/14 VASSALLO, D B
Operating Reactors Branch 4 1p 20803 358 24X
Fiche 50-293, 83/10/14, 8310180435
- 8310180438 Rev 0 to Procedure 2 2 11/090983, "Detailed Control Room
Design Review Program Plan"
* Boston Edison Co GL-B2-33 83/10/31 100pp 20803 359 24X
Fiche 50-293, 83/10/14, 8310180435
- 8310180503 Clarifies util 820617 ltr describing emergency operations
facility ventilation, per NUREG-0696 Charcoal will not be
provided in ventilation sys
SDRENSEN, O C Washington Public Power Supply System 002-83-910
83/10/12 SCHWENGER, A Licensing Branch 2 1p. 20801 188 24X
Fiche 50-397, 83/10/12, 8310180503

NONDOCKETED ITEMS

- 8310200378 NUREG/CR-3081
CLOSEOUT OF IE BULLETIN 80-05 VACUUM CONDITION RESULTING
IN DAMAGE TO LOW PRESSURE TANKS WHICH MAY CONTAIN PRIMARY
SYSTEM WATER
FOLEY, W J, HENNICK, A Parameter, Inc FIN B-1013 PARAMETER
IE-12 83/10/31 Division of Emergency Preparedness & Engineering
Response (Post 830103) 52pp Available at NRC #4 25 20863 231
- 8310200382 NUREG-0540 V05 N07
TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE
July 1-31, 1983
* Division of Technical Information & Document Control 83/09/30
535pp 20863 286
- 8310200388 NUREG/CR-1278
HANDBOOK OF HUMAN RELIABILITY ANALYSIS WITH EMPHASIS ON
NUCLEAR POWER PLANT APPLICATIONS
SWAIN, A D, GUTTMAN, H E Sandia Laboratories FIN A-1188
9AND80-0200 83/10/31 Division of Facility Operations 499pp
20861 139
- 8310200389 NUREG/CR-3280
TRAC-PFI DEVELOPMENTAL ASSESSMENT
BOYACK, B E Los Alamos Scientific Laboratory FIN A-7016
LA-9704-MS 83/09/30 Division of Accident Evaluation 506pp
20865 096
- 8310210152 NUREG-0835 DRFT
HUMAN FACTORS REVIEW GUIDELINES FOR THE SAFETY PARAMETER
DISPLAY SYSTEM FINAL REPORT
* Human Factors Engineering Branch 83/09/19 53pp 20883 197
- 8310210179 Comments on incorrect statements noted in 830929 trip rept
Correct milestone date for Unit 1 hot functional testing is
Nov 1983 & May 1984 for fuel loading
TUCKER, H B Duke Power Co 83/10/13 GILINSKY, V Commissioners
2pp 20856 125 24X Fiche 50-413, 83/10/13, 8310210179
- 8310210270 Application for amend to Licenses DPR-57 & NPF-5
transferring radiological effluent Tech Spec from App B to
App A
GUICHAL, L Georgia Power Co NED-83-309 83/10/17 STOLZ, J F
Operating Reactors Branch 4 App 20846 290 24X
Fiche: 50-321, 83/10/17, 8310210270
- 8310210277 Proposed Tech Spec transferring radiological effluent Tech
Spec from App B to App A
* Georgia Power Co 83/10/17 128pp. 20846 296 24X
Fiche 50-321, 83/10/17, 8310210270
- 8310210302 Forwards Rev 3 to implementation schedule in 830415 response
to Generic Ltr 82-33, Suppl 1 to NUREG-0737, "Requirements
for Emergency Response Capability"
WEAVER, J D Nebraska Public Power District QL-82-33 83/10/18
SIEGEL, B Operating Reactors Branch 2 3pp. 20851 061 24X
Fiche 50-298, 83/10/18, 8310210302
- 8310210310 Forwards response to 830104 request for addl info re
NUREG-0737, Item II.D.1 "Relief & Safety Valve Test
Requirements" "Tex" quencher utilized at discharge pipe
exit
SINCLAIR, J B Vermont Yankee Nuclear Power Corp FVY 83-110
83/10/17 VASSALLO, D B Operating Reactors Branch 2. 15pp
20851 137 24X Fiche: 50-271, 83/10/17, 8310210310
- 8310240134 Provides status of mods Required for Generic Ltr 82-28 re
inadequate core cooling instrumentation & NUREG-0737, Item
II.F.2 Issues include environ qualification of two ICCI
subsystems & installation of core exit thermocouple
LUNDVALL, A E Baltimore Gas & Electric Co QL-83-28 83/10/14
MILLER, J R Operating Reactors Branch 3 3pp 20881 166 24X
Fiche: 50-317, 83/10/14, 8310240134
- 8310240143 Forwards "Control Room Design Review Program Plan: Hope Creek
Generating Station," in response to Generic Ltr 82-33, Item
3 Summary rept will be submitted by 840815
MITTL, R L Public Service Electric & Gas Co of New Jersey
QL-82-33 83/10/17 SCHWENGER, A Licensing Branch 2 2pp
20880 039 24X Fiche: 50-354, 83/10/17, 8310240143
- 8310240145 "Control Room Design Review Program Plan: Hope Creek
Generating Station"
* Essex Corp. 83/10/14 52pp. 20880:041 24X
Fiche 50-354, 83/10/17, 8310240143
- 8310240162 Notifies of resolution of NUREG-0737, TMI Action Plan Item
II.K.2.17, "Potential for Voiding in RCB During Transients"
Results of analysis presented in GEN-199 applicable to
facilities w/stated exception.
LUNDVALL, A E Baltimore Gas & Electric Co 83/10/19. MILLER, J R.
Operating Reactors Branch 3 1p. 20881-312. 24X
Fiche: 50-317, 83/10/19, 8310240162
- 8310240243 Forwards SER & technical evaluation rept re NUREG-0737, Item
I A 2.1, "Upgrading of Reactor Operator & Senior Reactor
Operator Training" & II B 4, "Training for Mitigating Core
Damage" Requirements met
VASSALLO, D B Operating Reactors Branch 2 83/10/12 PARRIS, H G
Tennessee Valley Authority 4pp 20891 123 24X
Fiche 50-259, 83/10/12, 8310240243
- 8208310352 SAI-186-029-50
"Improvements in Training & Requalification Programs As
Required By TMI Action Items I A 2.1 & II B 4 for Browns
Ferry Nuclear Plants, Units 1, 2 & 3," technical evaluation
rept
* Science Applications, Inc NRC-03-82-096 82/08/25 NRC -
No Detailed Affiliation Given 15pp 86280 216 24X
Fiche 50-000, 83/10/12, 8310240243
- 8310250002 Responds to FOIA request for distribution list used for
mailing NUREG-0737 (Suppl 1), "Control Room Design Reviews"
Forwards list w/o encl
FELTON, J M Division of Rules and Records 83/07/14 DEBOR, J
Biotechnology, Inc 1p 20908 337
- 8310250007 FOIA request for distribution list used for mailing NUREG-
0737 (Suppl 1), "Control Room Design Reviews" Info received
will be used to support until conference on NUREG-0737
DEBOR, J Biotechnology, Inc 83/07/05 Division of Rules and
Records 1p 20908 338
- 8310250028 Responds to FOIA request for SECY-83-030, "TMI-Related
Requirements at Operating Reactors," be placed in PDR
Forwards requested document Document also available in
PDR
FELTON, J M Division of Rules and Records 83/07/15 BUCKLES, R
NUB Corp 1p 20916 178
- 8310250030 SECY-83-030
Advises of NRR plan to take licensing action on TMI action
plan requirements specified in NUREG-0737 scheduled for
implementation after 810630
DIRKES, W J Office of the Executive Director for Operations
83/01/21 31pp 20916 179
- 8310250248 Forwards IE Insp Repts 50-269/83-28, 50-270/83-28 &
50-287/83-28 on 830811-0910 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/27
TUCKER, H B Duke Power Co 1p 20899 074 24X
Fiche 50-269, 83/09/27, 8310250248
- 8310250256 IE Insp Repts 50-269/83-28, 50-270/83-28 & 50-287/83-28 on
830811-0910, No noncompliance noted Major areas inspected
operations, maint surveillance, training & NUREG-0737 items
BRYANT, J Region 2, Office of Director 50-287/83-28 83/09/27
10pp 20899 075. 24X Fiche 50-269, 83/09/27, 8310250248
- 8310250274 Updates present status & describes tasks performed over
previous 6 months per requirements of Generic Ltr 82-33 &
Suppl 1 to NUREG-0737 re control room design review Figure
2-2 encl
HARBALL, J R Arkansas Power & Light Co QL-82-33 83/10/20
EISENHUT, D O Division of Licensing 4pp 20902 340 24X
Fiche 50-315, 83/10/20, 8310250274
- 8310250281 Advises of delay in providing addl info re NUREG-0737,
Item II B 3 concerning post-accident sampling sys, per 830714
request, due to outage beginning ahead of schedule Info
expected by 831025
HARBALL, J R Arkansas Power & Light Co 0CAN108310 83/10/17
STOLZ, J F Operating Reactors Branch 4 MILLER, J R Operating
Reactors Branch 3 1p 20898 362 24X Fiche 50-368, 83/10/17,
8310250281
- 8310250320 Forwards IE Insp Repts 50-280/83-23 & 50-281/83-23 on
830816-17 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/09/23
STEWART, H L Virginia Electric & Power Co 2pp 20900 084, 24X
Fiche: 50-280, 83/09/23, 8310250320
- 8310250328 IE Insp Repts 50-280/83-23 & 50-281/83-23 on 830811-17 No
noncompliance noted Major areas inspected review of TMI
Action Item II B 2, plant mods for vital area access, posting,
labelling & control of radiological areas
HOSEY, C M Region 2, Office of Director 50-281/83-23 83/09/21
4pp. 20900 086 24X Fiche: 50-280, 83/09/23, 8310250320
- 8310250391 Forwards FEMA 830928 ltr providing status of final findings
of offsite preparedness State & local plans & preparedness
adequate to protect public
PAPERIELLO, C J Region 3, Office of Director 83/10/21 DOLAN, J F
American Electric Power Service Corp DOLAN, J E Indiana &
Michigan Electric Co 1p 20897 280 24X Fiche 50-315, 83/10/21,
8310250391

NONDOCKETED ITEMS

46

- 8310250401 Comments on status of offsite emergency preparedness State & local plans & preparedness adequate to protect health & safety of public. Approval conditional on verification of public alerting & notification sys per NUREG-0654
MCLAUGHLIN, D Federal Emergency Management Agency 83/09/28
DIRCKS, W J Office of the Executive Director for Operations 1p
20897 281 24X Fiche 50-315, 83/10/21, 8310250391
- 8310250414 Forwards IE Insp Repts 50-338/83-22 & 50-339/83-22 on 830815-19 & 0919-20 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/10/05
STEWART, W L Virginia Electric & Power Co 2pp 20897 227 24X
Fiche 50-338, 83/10/05, 8310250414
- 8310250428 IE Insp Repts 50-338/83-22 & 50-339/83-22 on 830815-19 & 0919-20 No noncompliance noted. Major areas inspected liquid & gaseous effluent releases, effluent control instrumentation, reactor coolant water quality & NUREG-0737
WRAV, J R Region 2, Office of Director 50-339/83-22 83/09/30
9pp 20897 229 24X Fiche 50-338, 83/10/05, 8310250414
- 8310250433 Forwards safety evaluation of C-E Owners Group Rept CEN-197 compliance w/NUREG-0737, Item II K 2 17, "Voiding in RCS During Transients" Requirements met. Item closed
CRUTCHFIELD, D Operating Reactors Branch 5 83/10/19
VANDEWALLE, D J Consumers Power Co 9pp 20897 037 24X
Fiche 50-255, 83/10/19, 8310250433
- 8310250463 Informs that facility will be in compliance w/NUREG-0737, Item II F 2 re inadequate core cooling instrumentation, per 830728 ltr. in response to 830627 safety evaluation, pending completion of upgraded procedures
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-10-048
83/10/24 KAY, J A Yankee Atomic Electric Co 5pp 20897 149
24X Fiche 50-029, 83/10/24, 8310250463
- 8310250474 Ack receipt of 830923 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-23 & 50-325/83-23
O'REILLY, J P Region 2, Office of Director 83/10/11 UTLEY, E E
Carolina Power & Light Co 1p 20900 061 24X
Fiche 50-324, 83/10/11, 8310250474
- 8310250501 IE Insp Repts 50-324/83-23 & 50-325/83-23 on 830626-30 Noncompliance noted large quantity shipment in CNS-3-55 shipping cask not leak tested prior to delivery of package to carrier for transport
ALBRIGHT, R H, BARR, K P Region 2, Office of Director
50-325/83-23 83/08/05 7pp 20900 068 24X
Fiche 50-324, 83/10/11, 8310250474
- 8310250514 Ack receipt of 830810 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-26 & 50-370/83-33 Evaluation of radiation hazard associated w/ transfer of neutron source adequate. Violation withdrawn
O'REILLY, J P Region 2, Office of Director 83/10/07 TUCKER, H B
Duke Power Co 2pp 20901 279 24X Fiche 50-369, 83/10/07, 8310250514
- 8310250540 IE Insp Repts 50-369/83-26 & 50-370/83-33 on 830606-10 Noncompliance noted failure to perform adequate neutron radiation survey to evaluate extent of radiation hazards present prior to permitting worker entry
COLLINS, T R, BARR, K P Region 2, Office of Director.
50-370/83-33 83/06/28 6pp 20901 287 24X
Fiche 50-369, 83/10/07, 8310250514
- 8310250677 Forwards SER re 830427 submittal on NUREG-0737, Item II K 2 17 re voiding in RCS during anticipated transients in C-E plants. Voids generated in RCS accounted for in present analysis modes. Review complete
MILLER, J R Operating Reactors Branch 3 83/10/11 GARRITY, J H
Maine Yankee Atomic Power Co 10pp 20908 339 24X
Fiche 50-309, 83/10/11, 8310250677
- 8310250681 Forwards SER (NUREG-0944) & FR notice re full-term OL application Provisional OL/full-term OL conversion issue will be resolved by ASLB w/o SER
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-10-038
83/10/14 MAIER, J E Rochester Gas & Electric Corp 2pp
20908 331 24X Fiche 50-244, 83/10/14, 8310250681
- 8310250682 Notice of availability of SER for full-term OL (NUREG-0944)
CRUTCHFIELD, D Operating Reactors Branch 3 83/10/14 1p
20908 333 24X Fiche 50-244, 83/10/14, 8310250681
- 8310260206 Forwards Amend 20 to GESSAR-II, responding to Confirmatory Issue 18 of SER, Suppl 1 to NUREG-0979, revised responses to NRC 820825 ltr re communication & lighting sys & updating interface tables of Subsection 1.9.1
SHERWOOD, G O General Electric Co MFN 185-83 83/10/04
EISENHUT, D O Division of Licensing 3pp 20909 001 24X
Fiche 50-447, 83/10/04, 8310260206
- 8310260211 Amend 20 to GESSAR-II
* General Electric Co 22A7007 83/10/04 205pp 20909 004
24X Fiche 50-447, 83/10/04, 8310260206
- 8310260212 Forwards response to 831004 request re NUREG-0737, Item II E 4 2, "Containment Purge & Vent Valves," design evaluation W/13 oversize drawings. Aperture cards are available in PDR
DALTROFF, S L Philadelphia Electric Co 83/10/19 STOLZ, J F
Operating Reactors Branch 4 72pp 20909 277 24X
Fiche 50-277, 83/10/19, 8310260212
- 8310260316 Summary of 830707 meeting w/util in Bethesda, MD re overpressurization of standby gas treatment sys ductwork & Filters Issue resolved. Disposition discussed in SER.
NUREG-0991 issued in Aug 1983
MARTIN, R E Licensing Branch 2 83/10/19 Licensing Branch 2
19pp 20921 220 24X Fiche 50-352, 83/10/19, 8310260316
- 8310260346 Summary of Caseload Forecast Panel 830810-12 meetings w/util in Clinton, IL re const status of facility. Viewgraphs encl.
ABELSON, H Licensing Branch 2 83/10/17 Licensing Branch 2
164pp 20918 084 24X Fiche 50-461, 83/10/17, 8310260346
- 8310260353 Forwards SER (NUREG-0821) "Integrated Plant SAR" for full committee review on util full term DL application W/o encl.
MIRALTA, F J Division of Licensing LS05-83-10-039 83/10/14
RAY, J J ACRS - Advisory Committee on Reactor Safeguards 1p
20918 332 24X Fiche 50-244, 83/10/14, 8310260353
- 8310260381 NUREG/CR-3445
COST-BENEFIT ANALYSIS OF UNFIRED PUO2 PELLETS AS AN ALTERNATIVE PLUTONIUM SHIPPING FORM
HISHIMA, J, BRACKENBUSH, L, LIBBY, R A Battelle Memorial Institute
Pacific Northwest Laboratory FIN 8-2424 PNL-4806 83/10/31
Division of Risk Analysis 47pp Available at NRC #4 00
20918 248
- 8310260397 NUREG/CR-3499
SEVERE RAIL AND TRUCK ACCIDENTS TOWARD A DEFINITION OF BOUNDING ENVIRONMENTS FOR TRANSPORTATION PACKAGES
EGGERS, P Ridgely, Eggers & Associates FIN 8-6621 83/10/31
Division of Risk Analysis 358pp Available at NRC #8 00
20919 001
- 8310260423 NUREG/CR-3199
GUIDANCE FOR DISPOSAL OF URANIUM MILL TAILINGS LONG-TERM STABILIZATION OF EARTHEN COVER MATERIALS
VOORHEES, L D, SALE, M J, WEBB, J W Oak Ridge National Laboratory
FIN 8-0279 ORNL/TM-8685 83/10/31 Division of Safeguards
110pp Available at NRC #4 75 20926 016
- 8310260427 NUREG/CR-2146 V03
DYNAMIC ANALYSIS TO ESTABLISH NORMAL SHOCK AND VIBRATION OF RADIOACTIVE MATERIAL SHIPPING PACKAGES Final Summary Report
FIELDS, S R Hanford Engineering Development Laboratory FIN 8-2283
HEAD-THE 83-18 83/10/31 Division of Risk Analysis 295pp
Available at NRC #7 50 20925 081
- 8310270130 Requests review & concurrence w/proposed post-accident shielding alternate solution mod (NUREG-0737, Item II B 2), per 830521 & 0615 responses to Generic Ltr 82-05
HUMILL, H D General Public Utilities - OPU Service Corp
5211-83-280 83/10/21 STOLZ, J F Operating Reactors Branch 4
6pp 20925 022 24X Fiche 50-289, 83/10/21, 8310270130
- 8310270132 Responds to FOIA request for info re possible rev to radiological emergency planning guidance & info on whether NRC emergency planning regulations appropriate in light of anticipated accident scenarios. Forwards documents
FELTON, J M Division of Rules and Records 83/07/15
BRANDENBURG, B Consolidated Edison Co of New York, Inc. 1p
20942 235
- 8310270145 Staff requirements memo re 821110 briefing in Washington, D.C. on Sandia consequences study. Commission briefed on NUREG/CR-2239 (SAND81-1549), "Technical Guidance for Biting Criteria Development" Viewgraph encl.
CHILK, S J Office of the Secretary of the Commission, MS2110B
82/11/18 DIRCKS, W J Office of the Executive Director for Operations, 3pp 20942 237
- 8310270143 Forwards SER re restart following steam generator tube rupture event on 820123, per NUREG-0916. Generator tube fiber optic insp acceptable, based on info in util 821122 ltr.
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-10-054
83/10/25 MAIER, J E Rochester Gas & Electric Corp 2pp
20924 138 24X Fiche 50-244, 83/10/25, 8310270143
- 8310270149 Safety evaluation supporting steam generator tube fiber optic insp
* Office of Nuclear Reactor Regulation, Director 83/10/25 2pp
20924 140 24X Fiche 50-244, 83/10/25, 8310270143

NONDOCKETED ITEMS

8310270300 Supplis 830325 response to 830111 request for addl info re NUREQ-0737, Item II B 3, "Post-Accident Sampling " Interim core damage assessment procedure in use until Westinghouse Owners Group methodology completed by end of 1983
STEWART, W L Virginia Electric & Power Co 038A 83/10/20
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
20923.193 24X Fiche 50-000, 83/10/20, 8310270300

8310270369 Responds to FOIA request for SECY-83-278 & SECY-83-270, transmitting 830624 "Rept on Adequacy & Safety of Relief Valve Testing & Performance " Forwards requested documents
FELTON, J M Division of Rules and Records 83/10/04 WEISS, E R
Union of Concerned Scientists 1p 20943 129 24X
Fiche 50-289, 83/10/04, 8310270369

-8307220250 SECY-83-270
Provides summary of primary sys relief & safety valve testing & performance since TMI-2 accident per NUREQ-0737, Item II D 1
DIRCKS, W J Office of the Executive Director for Operations
83/07/05. 122pp 20943 173

8310270443 Forwards comments on Rev 5A to emergency plan Comments will be categorized as improvement items since SER states plan meets 10CFR50 47(b) stds & 10CFR50 App E requirements, per NUREQ-0830
PAPERIELLO, C J Region 3, Office of Director 83/10/25
MATTHEWB, D B Emergency Preparedness Branch App 20923 091 24X
Fiche 50-483, 83/10/25, 8310270443

8310270552 Releases public version of revised emergency plan
FELTON, J M Division of Rules and Records 83/10/21 Document
Management Branch 1p 20944 017 24X Fiche 50-461, 83/10/21,
8310270552

-8310270569 Forwards public version of draft Amend 28 to FSAR, App 13 G consisting of Rev 2 to Emergency Plan OAP1890 008 Rev should resolve SER Outstanding Issue 18 (NUREG-0853)
NELSON, R M Illinois Power Co U-0675 83/10/14 SCHWENCER, A
Licensing Branch 2 1p 20944 018 24X Fiche 50-461, 83/10/21,
8310270552

8310270555 Forwards safety evaluation supporting design of reactor coolant vent sys per requirement of 10CFR50 44(c)(3)(iii) & NUREQ-0737, Item II B 1
MILLER, J R Operating Reactors Branch 3 83/09/22 FAY, C W
Wisconsin Electric Power Co 7pp 20944 003 24X
Fiche 50-246, 83/09/22, 8310270555

8310270602 Informs that requirements of NUREQ-0737, Item II K 3 17, "Rept on Outages of ECCS," met Review of item complete
VAROA, B A Operating Reactors Branch 1 83/10/19 D'TOOLE, J
Consolidated Edison Co of New York, Inc 2pp 20946 259 24X
Fiche 50-247, 83/10/19, 8310270602

8310280009 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept re NUREQ-0737, Items II K 3 1, "Automatic PORV Isolation" & II K 3 2, "Rept on PORVs " Response acceptable
CRUTCHFIELD, D Operating Reactors Branch 3 LS05-83-10-050
83/10/20 VANDENALLE, D J Consumers Power Co 3pp 20934 109
24X Fiche 50-255, 83/10/20, 8310280009

8310280044 Forwards "Detailed Control Room Design Review Program Plan for JA Fitzpatrick Nuclear Power Plant," in response to 821217 Generic Ltrs 82-33 & 83-18, Suppl 1 to NUREQ-0737 & TMI Action Item I D 1
BAYNE, J P Power Authority of the State of New York GL-82-33
83/10/24 VASSALLO, D B Operating Reactors Branch 2 2pp
20934:348 24X Fiche 50-333, 83/10/24, 8310280044

-8310280054 "Detailed Control Room Design Review Program Plan for JA Fitzpatrick Nuclear Power Plant "
* Power Authority of the State of New York GL-82-33 83/10/19
86pp. 20934 350 24X Fiche 50-333, 83/10/24, 8310280044.

8310280082 Provides schedule for submittal of core damage assessment procedure, eleventh criterion of NUREQ-0737, Item II B 3, "Post-Accident Sampling Sys " Procedure will be submitted prior to startup following Fall 1984 refueling outage
WILLIAMS, J W Florida Power & Light Co L-83-925 83/10/25
MILLER, J R Operating Reactors Branch 3 1p 20934 103 24X
Fiche 50-335, 83/10/25, 8310280082

8310280087 Forwards safety evaluation re review of util submittal addressing NUREQ-0737, Item II K 2 17, "Voiding in RCS During Anticipated Transients " Steam void will not result in unacceptable consequences
MILLER, J R Operating Reactors Branch 3 83/10/17 JONES, W C
Omaha Public Power District 9pp. 20941 349 24X
Fiche 50-285, 83/10/17, 8310280087

8310280096 Responds to SER Open Item 6 re NUREQ-0737, Item II F 2, "Instrumentation for Detection of Inadequate Core Cooling," providing updated FSAR pages concerning core exit thermocouples & reactor vessel level measurement
TUCKER, H B Duke Power Co 83/10/19 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch
4 13pp 20935 191 24X Fiche 50-413, 83/10/19, 8310280096

8310280099 Forwards B&W Owners Group rept "Bounding Analytical Assessment of NUREQ-0630 Models on LOCA kW/Ft Limits W/Use of FLECSSET "
RODRIGUEZ, R J Sacramento Municipal Utility District RJR 83-705
83/10/21 STOLZ, J F Operating Reactors Branch 4 1p 20935 212
24X Fiche 50-312, 83/10/21, 8310280099

8310280105 Forwards update of progress of control room habitability mods, per 830922 ltr re TMI Item III D 3 4 HVAC equipment operating at approx 2/3 design capacity Updated work list & schedules encl
TUCKER, H B Duke Power Co 83/10/24 DENTON, H R Office of
Nuclear Reactor Regulation, Director 2pp 20935 324 24X
Fiche 50-269, 83/10/24, 8310280105

8310280127 Responds to NRC 830926 ltr re schedule for meeting emergency response capability requirements Const schedule will permit fuel loading by 840801 Full scale emergency preparedness exercise rescheduled to 840725
BOYER, V S Philadelphia Electric Co 83/10/25 SCHWENCER, A
Licensing Branch 2 3pp 20929 273 24X Fiche 50-352, 83/10/25,
8310280127

8310280128 Forwards safety evaluation re util 830929 response to NUREQ-0827 re integrated safety assessment rept, Sections 4 26 & 4 26 3 Commitments & justification for not modifying certain Foxboro & Honeywell recorders acceptable
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-10-041
83/10/27 LINDER, F Dairymead Power Cooperative 2pp 20929 038
24X Fiche 50-409, 83/10/27, 8310280128

--8310280134 Safety evaluation re util 830929 response to NUREQ-0827 integrated plant safety assessment rept, Sections 4 26 & 4 26 3 Commitments & justification acceptable
* Operating Reactors Branch 5 83/10/27 2pp 20929 040 24X
Fiche 50-409, 83/10/27, 8310280128

8310280141 Advises that commitments in util 830930 ltr re SEP Topic VI-4, "Containment Isolation Sys (Electrical)," NUREQ-0578 & NUREQ-0737, Item II E 4 2 acceptable No mods to steam generator sample & blowdown lines required
PAULSON, W Operating Reactors Branch 5 LS05-83-10-064 83/10/27
DIETRICH, R Southern California Edison Co 4pp 20929 042 24X
Fiche 50-206, 83/10/27, 8310280141

8310280161 Discusses 831006 response to request for addl info re integrated plant safety assessment rept (NUREG-0827), Section 4 12, "Pipe Break Outside Containment " Criteria for jet impingement provided Section complete Evaluation encl
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-10-062
83/10/27 LINDER, F Dairymead Power Cooperative 2pp 20929 221
24X Fiche 50-409, 83/10/27, 8310280161

--8310280163 Safety evaluation supporting integrated plant safety assessment rept (NUREG-0827), Section 4 12, "Pipe Break Outside Containment "
* NRC - No Detailed Affiliation Given 83/10/27 1p 20929 223
24X Fiche 50-409, 83/10/27, 8310280161

8310280173 Forwards latest response to NUREQ-0737, Item II D 3, "Direct Indication of Relief & Safety Valve Position," reflecting as-installed location of acoustic monitoring sys accelerometer
MILLS, L M Tennessee Valley Authority 83/10/24 ADENSAM, E
Licensing Branch 4 2pp 20929 006 24X Fiche 50-390, 83/10/24,
8310280173

8310310054 Advises that pipe stresses & support loads due to dead weight of water in pipe, concurrent thermal effects & effects of postulated earthquake within design allowables reviewed, per NUREQ-0737, Item II D 1
RYBAK, B Commonwealth Edison Co 7484N 83/10/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 20931 146
24X Fiche 50-254, 83/10/20, 8310310054

8310310066 Responds to 830815 request for addl info re NUREQ-0737, Item II B 3, "Post-Accident Sampling Sys," providing supplemental info concerning two of four open criteria & schedule for responding to remaining requests
BAYNE, J P Power Authority of the State of New York IPN-83-89
83/10/26 VAROA, S A Operating Reactors Branch 1 Bpp 20931 037
24X Fiche 50-286, 83/10/26, 8310310066

NONDOCKETED ITEMS

463

8310310097 Responds to FOIA request that 16 SECYs be placed in PDR
Forwards App A documents SECY-82-466 withheld (ref FOIA
Exemption 5)
FELTON, J M Division of Rules and Records 83/09/19 SHOLLY, S C
Union of Concerned Scientists 3pp 21000 146

--8310310140 SECY-83-093
Transmits INPO "Performance Objectives & Criteria for
Corporate Evaluations" & informs of plans to defer further
action on TMI Action Plan Item I B 1 1 W/o encl
DIRCKS, W J Office of the Executive Director for Operations
83/03/09 3pp 21000 296

8310310106 NUREG/CR-3215 V02 ER
ORGANIZATIONAL ANALYSIS AND SAFETY FOR UTILITIES WITH
NUCLEAR POWER PLANTS
* Battelle Memorial Institute, Pacific Northwest Laboratory
PNL-4655 83/10/19 Division of Facility Operations 2pp
20965 329

8310310111 NUREG-0980 V12 N09
REGULATORY LICENSING STATUS SUMMARY REPORT Data As Of
September 30, 1983 (Blue Book)
* Management Information Branch 83/10/31 63pp 20999:146

8310310114 NUREG/CR-2830
PERMISSIBLE RADIONUCLIDE LOADING FOR ORGANIC ION EXCHANGE
RESINS FROM NUCLEAR POWER PLANTS
MACKENZIE, D R, LIN, M, BARLETTA, R E Brookhaven National
Laboratory FIN A-3159 BNL-NUREG-31565 83/10/31 Division of
Waste Management 105pp 20999 210

8310310118 NUREG-0748 V03 N08
OPERATING REACTORS LICENSING ACTIONS SUMMARY Data As of
August 31, 1983 (Orange Book)
* Management Information Branch 83/10/31, 452pp 21002 107

8310310121 NUREG-0750 V17 101
INDEXED TO NUCLEAR REGULATORY COMMISSION ISSUANCES
January - March 1983
* NRC - No Detailed Affiliation Given 83/03/31 65pp 20965 190

8310310123 Forwards safety evaluation based on util submittals re
NUREG-0737, I B 2, "Design Review of Plant Shielding Access
to Vital Areas " Requirements met
MILLER, J R Operating Reactors Branch 3 83/10/12 HUSDOLF, D M
Northern States Power Co 3pp 20965 324 24X
Fiche 50-282, 83/10/12, 8310310123

8310310125 Forwards safety evaluation based on review of B20108
submittal adopting C-E Owners Group analysis on TMI Action
Item II K 2 17, "Potential for Voiding in RCS During
Transients " Analysis acceptable Item complete
MILLER, J R Operating Reactors Branch 3 83/10/05 UHRIG, R E
Florida Power & Light Co 9pp 20965 332 24X
Fiche 50-335, 83/10/05, 8310310125

8310310129 Forwards safety evaluation based on review of util responses
to NUREG-0737 Items Requirements of NUREG-0737, Item
II K 3 2 met
MILLER, J R Operating Reactors Branch 3 83/09/30 JONES, W C
Omaha Public Power District 14pp 21000-079 24X
Fiche 50-285, 83/09/30, 8310310129

8310310137 Forwards safety evaluation re review of util submittal
addressing NUREG-0737 Item II K 3 17, "Rept on Outages of
ECCB " Requirements met
VASSALLO, D B Operating Reactors Branch 2 83/10/14 UTLEY, E E
Carolina Power & Light Co 4pp 20965 250 24X
Fiche 50-324, 83/10/14, 8310310137

--8306160513 TER-C5506-174/175
"ECCB Repts (F-47) TMI Action Plan Requirements, Brunswick
Steam Electric Plant, Units 1 & 2," technical evaluation
rept
VOBBURY, F W, OVERBECK, G J Franklin Institute/Franklin Research
Center NRC-03-B1-130 83/06/13 CHOW, E NRC - No Detailed
Affiliation Given 22pp 20965 254 24X Fiche 50-324, 83/10/14,
8310310137

8310310180 Forwards safety evaluation based on review of util responses
to NUREG-0737, Items II K 3 1, "Automatic PORV Isolation" &
II K 3 2, "Rept on PORVs " Requirements met.
MILLER, J R Operating Reactors Branch 3 83/10/12 LUNDVALL, A E
Baltimore Gas & Electric Co 14pp 21000.037 24X
Fiche 50-317, 83/10/12, 8310310180

8310310188 NUREG-0966 V03 N01-3
STANDARDS DEVELOPMENT STATUS SUMMARY REPORT, Data As Of
September 30, 1983 (Green Book)
* Program & Administrative Services Branch 83/10/31 90pp
21003 091

8310310191 NUREG/CR-2000 V02 N9
LICENSEE EVENT REPORT (LER) COMPILATION For Month Of
September 1983
* Oak Ridge National Laboratory FIN A-9135 ORNL/NSIC-200
83/10/31 Director's Office. 162pp 21003 187

8310310208 NUREG/CR-3352
FUMIGATION POTENTIAL AT INLAND AND COASTAL POWER PLANT
SITE
LINDSEY, C G, RAMSDALE, J V Battelle Memorial Institute, Pacific
Northwest Laboratory FIN B-2514 PNL-4760. 83/10/31 Division
of Systems Integration (post B11003) 32pp Available at NRC
\$3 75 21000 001

8310310209 NUREG/CR-2571
BWR REFILL-REFLOOD PROGRAM TASK 4 B - TRAC-BWR MODEL
QUALIFICATION FOR BWR SAFETY ANALYSIS FINAL REPORT
ALAMOR, M General Electric Co FIN B-5877 EPRI NP-2377
83/10/31 Division of Accident Evaluation 263pp Available at
NRC \$6 50 21004 001

8310310248 NUREG/CR-2893
CORRELATION OF NEUTRON DATA TAKEN AT COMMERCIAL NUCLEAR
SITES
RATHBUN, L A, ENDRES, G W Battelle Memorial Institute, Pacific
Northwest Laboratory FIN B-2423 PNL-4395 83/10/31 Division
of Facility Operations 32pp Available at NRC \$3 75 20999.315

8310310306 Responds to 830906 request to reevaluate position on
NUREG-0737, Item II E 4 2(7) Monitor capable of promptly &
reliably providing isolation signal would not be
sufficiently sensitive to detect release rates
HARRINGTON, W D Boston Edison Co 83/10/25, VASSALLO, D B.
Operating Reactors Branch 2 2pp 20961 227. 24X
Fiche 50-293, 83/10/25, 8310310306

8310310307 Submits results of engineering evaluation of two possible
mode to automatic depressurization sys logic per NUREG-0737,
Item II K 3 18 Problem better addressed by using
symptom-based emergency operating procedure
MURPHY, W P Vermont Yankee Nuclear Power Corp FVY 83-111
83/10/26 VASSALLO, D B Operating Reactors Branch 2 2pp
20961 224 24X Fiche 50-271, 83/10/26, 8310310307

8310310410 Forwards B&W Owners Group Analysis Committee/Core
Performance Committee Rept "Bounding Analytical Assessment
of NUREG-0630 Models on LOCA kW/ft Limits W/Use of FLECSSET."
HUMILL, H D General Public Utilities - OPU Service Corp
5211-83-305 83/10/21 HUMAK, T Assistant Director for Licensing
1p 20961 001. 24X Fiche 50-289, 83/10/21, 8310310410

--8310310413 77-1140898-01
"Bounding Analytical Assessment of NUREG-0630 Models on
LOCA kW/ft Limits W/Use of FLECSSET "
* Babcock & Wilcox Operating Plants Owners Group 83/09/30
104pp 20961 002 24X Fiche 50-289, 83/10/21, 8310310410.

8310310433 Forwards Amend 36 to License DPR-34 & safety evaluation
Amend revises administrative Tech Specs to incorporate
various editorial & format corrections, per NUREG-0737, Item
I A 1 3
WAGNER, P C Region 4, Office of Director 83/10/13 LEE, O R
Public Service Co of Colorado 2pp 20959 194 24X
Fiche 50-267, 83/10/13, 8310310433.

--8310310435 Amend 36 to License DPR-34, revising administrative Tech
Specs to incorporate various editorial & format corrections,
per NUREG-0737, Item I A 1 3
JOHNSON, E H Region 4, Office of Director 83/10/13. 34pp
20959 196 24X Fiche 50-267, 83/10/13, 8310310433

8310310439 Responds to 830907 request for mod to NRC 830701 order
confirming util commitments to implement certain post-TMI-
related items set forth in NUREG-0737 to extend completion
date for Item II B 3 to 831201, Request acceptable
STOLZ, J F Operating Reactors Branch 4 83/10/14 BECKHAM, J T
Georgia Power Co 2pp. 24X Fiche 50-321, 83/10/14, 8310310439

--8310310440 Order granting extension until 831201 to complete
Item II B 3, "Post-Accident Sampling." Commitments on
applicable NUREG-0737 requirements from Generic Ltr 82-03
encl
EISENHUT, D G Division of Licensing. 01-82-03 83/10/14.
Georgia Power Co 3pp 20965.164. 24X Fiche 50-321, 83/10/14,
8310310439

8310310444 NUREG/CR-3081
REVIEW OF CRYSTAL RIVER NUCLEAR GENERATING STATION UNIT 3
EMERGENCY FEEDWATER SYSTEM RELIABILITY ANALYSIS
YOUNGBLOOD, R, PAPAZOULOU, I A Brookhaven National Laboratory FIN
A-3393 BNL-NUREG-51626 83/10/31. Division of Safety
Technology 43pp Available at NRC \$3 75 21001.016 24X
Fiche 50-302, 83/10/31, 8310310444

NONDOCKETED ITEMS

8310310446 NUREG-0577 R01
POTENTIAL FOR LOW FRACTURE TOUGHNESS AND LAMELLAR TEARING
IN PWR STEAM GENERATOR AND REACTOR COOLANT PUMP SUPPORTS
Unresolved Safety Issue A-12
* Division of Safety Technology 83/10/31. 70pp Available at
NRC \$4.90 21000 304.

8310310447 NUREG/CR-3151
COMPLEX RADIATION DEGRADATION BEHAVIOR OF PVC MATERIALS
UNDER ACCELERATED AGING CONDITIONS
CLOUGH, R L, GILLEN, K T. Sandia Laboratories FIN A-1051
SAND82-1414 83/10/31. Division of Engineering 20pp
20965 122

8310310449 NUREG/CR-3450
A SUMMARY OF REPOSITORY DESIGN MODELS
CURTIS, R H, WART, R J, BKIBA, E L. Acres American, Inc FIN B-6985
83/10/31 Division of Waste Management 217pp Available at
NRC. \$6.50 21001 063

8310310452 NUREG-1021
OPERATOR LICENSING EXAMINER STANDARDS
* Division of Human Factors Safety. 83/10/31 180pp Available at
NRC. \$6.00 21001 284

ORQ CORRESPONDENCE WITH OTHER ORGANIZATIONS

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder
Qualification Tests " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/24 Consolidated Edison Co. of New
York, Inc 117pp 20734:022 24X Fiche: 50-000, 83/09/24, 8308300340

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
Detectors Positioned at Control Room Ventilation Air
Intakes " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New
York, Inc. 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342

8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse
Type BA-1 Differential Relays " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/26 Consolidated Edison Co. of New
York, Inc 118pp 20778 001 24X Fiche: 50-000, 83/09/26, 8308300345

8308300349 IE Info Notice 83-64, "Lead Shielding Attached to
Safety-Related Bys W/o 10CFR50 59 Evaluation " Svc list
encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/29. Consolidated Edison Co. of New
York, Inc 115pp 20716:324 24X Fiche 50-000, 83/09/29, 8308300349

8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass
Loops Used in Westinghouse Plants " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New
York, Inc 76pp. 20827:213 24X Fiche 50-000, 83/10/07, 8308300378

8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical
Facility " Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/07 Consolidated Edison Co. of New
York, Inc 79pp. 20882 026 24X Fiche: 50-000, 83/10/07, 8308300752

8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect
Causes Production of Noxious Gases " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New
York, Inc. 117pp. 21043:075 24X Fiche: 50-000, 83/10/11, 8308300759

8308300761 IE Info Notice 83-68, "Respirator User Warning Defective
Self-Contained Breathing Apparatus Air Cylinders " Svc list
encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/10/11 Consolidated Edison Co. of New
York, Inc 120pp 20827 129 24X Fiche: 50-000, 83/10/11, 8308300761

810040510 Position on schedule of offsite emergency planning issues
Hearings on New Hampshire radiological emergency response
plans & local plans should be postponed until Mar 1984
Certificate of Svc encl
CABBERY, S P. Federal Emergency Management Agency ISSUANCES OL
83/09/27 29pp 20625:216 24X Fiche 50-443, 83/09/27, 8310040510

8310050378 Forwards NRC memo requesting FEMA Regional Assistance
Committee (RAC) review of applicant transition plan by
831201 Hearings on admitted contentions may commence as
scheduled on 831205, in absence of completion of RAC review
BORDENICK, D M Hearing Branch 3 ISSUANCES OL-3 83/09/28
LAURENSEN, J A, LIVINGSTON, M S, KLINE, J R Atomic Safety and
Licensing Board Panel 3pp 20632 348 24X Fiche 50-322, 83/09/28,
8310050378

8310050439 Forwards EL Jordan 830915 ltr requesting Regional Assistance
Committee review of util transition plan of offsite
emergency preparedness Findings & determinations expected by
831201
REPKA, D A Hearing Branch 3 ISSUANCES OL-3 83/09/28
ROSENTHAL, A S, EDLES, G J, WILBER, H A Atomic Safety and Licensing
Appeal Panel 3pp 20630 360 24X Fiche 50-322, 83/09/28,
8310050439

8310050548 Forwards post-exercise/post-drill assessments, per JB Bragg
830608 commitment Previously noted deficiencies corrected
MCLOUGHLIN, D Federal Emergency Management Agency 83/09/29
DIRCKS, W J Office of the Executive Director for Operations 2pp
20629 267 24X Fiche 50-003, 83/09/29, 8310050548

--8310050552 Post-exercise assessment of 830824-25 exercise, Rockland
County, for Indian Point Nuclear Power Station
* Federal Emergency Management Agency 83/09/26 56pp
20629 269 24X Fiche 50-003, 83/09/29, 8310050548

--8310050554 Post-drill assessment of 830823 drill of Westchester County
bus evacuation procedures for Indian Point Nuclear Power
Station
* Federal Emergency Management Agency 83/09/15 9pp
20629 328 24X Fiche 50-003, 83/09/29, 8310050548

8310060053 Informs that based on FEMA 830811 memo & rept, deficiencies
identified in 821211 emergency exercise adequately
addressed or corrected during 830601 mini-exercise No
enforcement actions re deficiencies will be taken
MURLEY, T E Region I, Office of Director 83/09/27 RANDAZZO, J D
Maine Yankee Atomic Power Co 2pp 20647 056 24X
Fiche 50-309, 83/09/27, 8310060053

8310110339 Responds to approval request for info collection re 10CFR50
concerning domestic licensing of production & utilization
facilities Request approved through 850430 under OMB Number
3150-0011 per Paperwork Reduction Act
SCURRY, N Office of Management & Budget OMB 3150-0011 83/10/03
SCOTT, S Document Management Branch 2pp 20713 197

8310110341 Responds to approval request for info collection re DOE/NRC
Forms 741 & 741A for nuclear matl transaction rept &
NUREG/BR-0006 Request approved through 860630 under OMB
Number 3150-0003 per Paperwork Reduction Act
SCURRY, N Office of Management & Budget OMB 3150-0003 83/10/03
SCOTT, S Document Management Branch 2pp 20713 199

8310110343 Responds to approval request for info collection re medical
license occupational ALARA program Request approved through
860531 under OMB Number 3150-0045 per Paperwork Reduction
Act
SCURRY, N Office of Management & Budget OMB 3150-0045 83/10/03
SCOTT, S Document Management Branch 2pp 20713 201

8310110346 Responds to approval request for info collection re
application for medical matls license Request approved
through 860930 under OMB Number 3150-0041 per Paperwork
Reduction Act
SCURRY, N Office of Management & Budget OMB 3150-0041 83/10/03
SCOTT, S Document Management Branch 2pp 20713 203

8310110348 Responds to approval request for info collection re IAEA
Form N-71, design info questionnaire Request approved through
860630 under OMB Number 3150-0056 per Paperwork Reduction
Act
SCURRY, N Office of Management & Budget OMB 3150-0056 83/10/03
SCOTT, S Document Management Branch 2pp 20713 205

8310110349 Responds to approval request for info collection re DOE/NRC
Form 740M, concise note Request approved through 860630 under
OMB Number 3150-0057 per Paperwork Reduction Act
SCURRY, N Office of Management & Budget OMB 3150-0057 83/10/03
SCOTT, S Document Management Branch 2pp 20713 207

8310130077 Forwards request for OMB review & supporting statement re
Std Form 83 & supporting statements for DOE/NRC Forms 742 &
742C
NORRY, P G Office of Administration 83/10/03 SCURRY, N Office
of Management & Budget 1p 20777 011

NONDOCKETED ITEMS

465

B310130305 Forwards FEMA 830929 ltr transmitting FEMA Region II post-exercise assessment of 830824 exercise of State of NY radiological emergency response interim plan for implementing compensating measures for Rockland County HASSELL, D P Hearing Branch 1 ISSUANCES SP 83/10/04 GLEASON, G P Atomic Safety and Licensing Board Panel 1p 20719 204 24X Fiche 50-247, 83/10/04, B310130305

B310170346 Advises that util does not object to ASLD taking official notice of EPA rept, "Protective Action Evaluation Part II, Evacuation & Sheltering as Protective Actions Against Nuclear Accidents Involving Gaseous Release " Part I encl COPELAND, V G Isham, Lincoln & Beale COPELAND, V G Commonwealth Edison Co 83/10/10 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 20786 030 24X Fiche 50-454, 83/10/10, B310170346

B310170500 Response opposing Suffolk County 830917 motion to compel discovery re emergency planning Matl not relevant but is subj to privilege Requisite showing for privilege made Unexecuted Affidavit & Certificate of Svc encl GLASS, S M Federal Emergency Management Agency ISSUANCES OL-3 83/10/12 Atomic Safety and Licensing Board Panel. 8pp 20784 001 24X Fiche 50-322, 83/10/12, B310170500

B310200211 Forwards INPD evaluations on util mgt Svc list encl BLAKE, E L Shaw, Pittman, Potts & Trowbridge ISSUANCES SP 83/10/18 EDLES, G J Atomic Safety and Licensing Appeal Panel 47pp 20832 331 24X Fiche 50-000, 83/10/18, B310200211

B310210007 Forwards request for OMB review & supporting statement re Std Form-83 & supporting statement covering NRC Form 57 reporting & recordkeeping requirements NORRY, P G Office of Administration 83/10/18 SCURRY, N Office of Management & Budget 1p 20883 344

B310250147 Forwards std order for DOE work: "Technical Assistance Support for Region V Physical Security Insp." issued to LLL ADAMS, C Energy, Dept of FIN 8-8561 83/09/16 MARTIN, J B Region 5, Office of Director 1p 20897 269

--B310250152 Std order for DOE work: "Technical Assistance Support for Region V Physical Security Insp." issued to LLL MARTIN, J B Region 5, Office of Director MACCUSKY, J Lawrence Livermore Laboratory FIN 8-8561 95-83-002 83/09/16 1p 20897 270

B310250391 Forwards FEMA 830928 ltr providing status of final findings of offsite preparedness State & local plans & preparedness adequate to protect public PAPERIELLO, C J Region 3, Office of Director 83/10/21 DOLAN, J E American Electric Power Service Corp 1p 20897 280 24X Fiche 50-319, 83/10/21, B310250391

--B310250401 Comments on status of offsite emergency preparedness State & local plans & preparedness adequate to protect health & safety of public Approval conditional on verification of public alerting & notification sys per NUREG-0654 MCCLAUGHLIN, D Federal Emergency Management Agency 83/09/28 DIRCKS, W J Office of the Executive Director for Operations 1p 20897 281 24X Fiche 50-315, 83/10/21, B310250391

B310250491 Forwards final FEMA rule on review & approval of state & local radiological emergency plans & preparedness Rule effective 831028 BORDENICK, B M Hearing Branch 3 ISSUANCES OL-3 83/10/18 LAURENSEN, J A, KLINE, J R., SHON, F. J Atomic Safety and Licensing Board Panel. 15pp 20897 127 24X Fiche 50-322, 83/10/18, B310250491

PR PROPOSED RULE

B310030283 Package of three comments on proposed rule 10CFR50 re emergency planning & preparedness for production & utilization facilities & frequency & participation of exercises GALLAGHER, J W Philadelphia Electric Co WHITTIER, G D Maine Yankee Atomic Power Co, SHIELDS, B W. Public Service Co of Indiana, Inc 48FR33307 83/09/23, CHILK, B J Office of the Secretary of the Commission 6pp 20592 315

B310030300 Comments on draft Commission policy statement re engineering expertise on shift Supports policy statement. STEWART, W L Virginia Electric & Power Co. 48FR33781 005 83/09/21 Docketing & Services Branch 1p. 20591;013.

B310030311 Package of four comments on draft Commission policy statement re engineering expertise on shift. WISENBURG, M R Houston Lighting & Power Co. HOUGHTON, T C XMC, Inc FARRAR, D L Commonwealth Edison Co 48FR33781 83/09/23 CHILK, S J Office of the Secretary of the Commission 15pp. 20591 014

B310030333 Comments on draft Commission policy statement re engineering expertise on shift. Opposes rule HARRIS, J Affiliation Unknown 48FR33781 021 83/09/20 Docketing & Services Branch 2pp 20590 205.

B310030341 Package of four comments on draft Commission policy statement re engineering expertise on shift ONNER, M W Affiliation Unknown BRDEHL, D J Portland General Electric Co JONES, D W Memphis State Univ, Memphis, TN 48FR33781 83/09/26 CHILK, S J Office of the Secretary of the Commission 8pp 20590 307

B310030364 Package of three comments supporting proposed rule 10CFR50 re emergency planning & preparedness for production & utilization facilities, frequency & participation of exercises KOESTER, G L Kansas Gas & Electric Co DALE, L F Mississippi Power & Light Co BRDEHL, D J Portland General Electric Co 48FR33307 83/09/26 Docketing & Services Branch 5pp. 20593 004

B310030366 Package of two comments opposing proposed rule 10CFR50 re emergency planning & preparedness for production & utilization facilities, frequency & participation of exercises LEHIS, M I Lewis, M HIATT, B L Affiliation Unknown 48FR33307 83/09/26 Office of the Secretary of the Commission 2pp 20592 198

B310030396 Package of seven comments supporting draft Commission policy statement on engineering expertise on shift THORPE, J R General Public Utilities - GPU Service Corp KENYON, B D Pennsylvania Power & Light Co SCHUYLER, J O Pacific Gas & Electric Co 48FR33781 83/09/26 CHILK, B J Office of the Secretary of the Commission 14pp 20592 352

B310040008 Comments on interim policy re investigations & adjudicatory proceedings statement of policy Recommends insp & investigation ofcs be given greater discretion re board notifications KNOTTS, J B Debevoise & Liberman 48FR36358 002 83/09/27 CHILK, B J Office of the Secretary of the Commission 6pp 20608 106

B310040030 Comments on proposed rule 10CFR50 re immediate reporting requirements for operating nuclear reactors BAKER, K R Affiliation Unknown 46FR41894 021. 83/09/22 CHILK, B J Office of the Secretary of the Commission. 1p 20608 123

B310040291 Package of three comments re draft Commission policy statement on engineering expertise on shift to combine senior reactor operator & shift technical advisor functions BAYNE, J P Power Authority of the State of New York MARSHALL, J R Arkansas Power & Light Co WILLIAMS, J W Atomic Industrial Forum 48FR33781 83/09/28, CHILK, S J Office of the Secretary of the Commission. 8pp 20614 199

B310040297 Package of two comments on proposed rule 10CFR50 re frequency & participation of emergency planning & preparedness exercises CAPONE, D W Union Electric Co. ZIMMERMAN, S Carolina Power & Light Co 48FR33307 83/09/28 CHILK, B J. Office of the Secretary of the Commission 4pp 20614 195

B310040307 Package of two comments supporting proposed rule 10CFR50 re emergency planning & preparedness for production & utilization facilities, frequency & participation of exercises ANDOGGINI, G C Arizona Public Service Co HELFRICH, R E Yankee Atomic Electric Co 48FR33307, 83/09/29 Docketing & Services Branch 4pp 20613-092

B310040334 Package of five comments on draft Commission policy statement on engineering expertise on shift. COUNSIL, W G, WERNER, R. P. Connecticut Yankee Atomic Power Co, COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 48FR33781. 83/09/29 CHILK, B J. Office of the Secretary of the Commission. 13pp 20617:120

B310050422 Comments on draft Commission policy statement re engineering expertise on shift Supports statement. MUSBOLF, D Northern States Power Co 48FR33781 031 83/09/23 Docketing & Services Branch. 1p. 20630, 343

NONDOCKETED ITEMS

B310050425 Comments on draft Commission policy statement re engineering expertise on shift Opposes rule
PARKYN, J D Affiliation Unknown 48FR33781 030 83/09/23
Docketing & Services Branch 1p 20630 344

B310050431 Comments on proposed rule 10CFR50 re emergency planning & preparedness for production & utilization facilities & frequency of exercises
COUNSIL, W O Connecticut Yankee Atomic Power Co COUNSIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W O Northeast Utilities 48FR33307 072 83/09/30
Office of the Secretary of the Commission 17pp 20633 320

B310070146 Requests FR publication of final rule 10CFR55 re transfer of licensing authority to Region IV & V administrators Public announcement encl
THOMPSON, H L Division of Human Factors Safety 83/09/28
FELTON, J M Division of Rules and Records 3pp 20680 331

--B310070153 "Completion of Regionalization of Operator Licensing Function by Assignment of Function to Regions IV & V,"
10CFR55 final rule Responsibility for issuing operator & senior reactor operator licenses assigned to Regions IV & V
DIRCKS, W J Office of the Executive Director for Operations
83/09/21 10pp 20680 334

B310120255 Comments on NRC draft policy statement re engineering expertise on shift Supports establishment of alternative approach to use of shift technical advisor, however, min goals & stds required for training courses should be limited
BRADBURY, R B Stone & Webster Engineering Corp. 48FR33781 032
83/09/30 Docketing & Services Branch 1p 20691 051

B310120270 Comments on proposed rule 10CFR50 re emergency planning & preparedness for production & utilization facilities, frequency & participation of exercises
COUNSIL, W O Connecticut Yankee Atomic Power Co COUNSIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W O Northeast Utilities 48FR33307 074 83/09/30
Docketing & Services Branch 16pp 20693 097

B310120275 Comments on NRC policy statement re engineering expertise on shift Recommends Commission allow individual licensees flexibility in meeting policy statement requirements
FAY, C H Wisconsin Electric Power Co 48FR33781 034 83/10/07
CHILK, S J Office of the Secretary of the Commission 2pp
20693 006

B310120299 Comments on proposed rule 10CFR50 re local & state govt participation in emergency preparedness exercises Opposes rule
HDLT, J Public Interest Research Group, New York 48FR33307 073
83/10/01 NRC - No Detailed Affiliation Given 6pp 20691 310

B310120339 Comments on draft NRC policy statement re nuclear reactor operator degree requirements Opposes requirement that operators must obtain college credits as part of license training or retraining
LABARGE, D E Professional Reactor Operator Society 48FR33781 033
83/10/01 CHILK, S J Office of the Secretary of the Commission 13pp 20700 214

B310130003 Forwards response to 830916 request for review of draft rulemaking package proposing amends to 10CFR50 re emergency preparedness w/o encl.
OLMSTEAD, W J Regulations Division 83/10/06, BERNERO, R M
Accident Source Term Program Office 1p 20723 235

B310180416 Comments on draft Commission policy statement on engineering expertise on shift Requests language of draft policy statement be amended to recognize Bachelor of Prof Studies in Nuclear Industrial Operations
DALE, L F Mississippi Power & Light Co 48FR33781 034, 83/10/06
Docketing & Services Branch 2pp, 20803 219.

B310180522 Expresses disagreement w/technical justification for

728

352

--B310180605 Advises that encl amend to 10CFR55 re assignment of licensing responsibilities for operators & senior operators to regions will be published in FR Amend issued as final rule, effective upon publication W/o stated encl
DENTON, H R Office of Nuclear Reactor Regulation, Director
48FR33243 83/09/30 UDALL, M K House of Rep, Interior & Insular Affairs 1p 20817 353

--B310180607 Advises that encl amend to 10CFR55 re assignment of licensing responsibilities for operators & senior operators to regions will be published in FR Amend issued as final rule, effective upon publication W/o stated encl
DENTON, H R Office of Nuclear Reactor Regulation, Director
48FR33243 83/09/30 SIMPSON, A Senate, Environment & Public Works 1p 20817 354

B310250331 Comments on proposed rules 10CFR40, 70 & 73 re implementation of convention on physical protection of nuclear matl Opposes rule
HARMON, D W Braunkohle Transport & Storage, Inc 48FR32182 001
83/10/10 Docketing & Services Branch 2pp 20897 335

B310250346 Comments on proposed rules 10CFR40, 70 & 73 re implementation of convention on physical protection of nuclear matl Recommends Sections 73 73(a)(1) & 73 74(a)(3) be deleted
NILSON, R Exxon Nuclear Co, Inc (subs of Exxon Corp) 48FR32182 002 83/10/12 Docketing & Services Branch 2pp 20898 075

B310250393 Comments on proposed rules 10CFR40, 70 & 73 re implementation of convention on physical protection of nuclear matl Rules should be revised to require physical protection equivalent to Annex I & II
MOWRY, W R GA Technologies, Inc /General Atomic Co 48FR32182 003
83/10/13 Docketing & Services Branch 2pp 20898 151

B310290448 Requests comment period be extended 2 months for proposed rule 10CFR73 re physical protection requirements for nonpower reactor licensees possessing formula quantities of BSNM
RICHARDS, W J American Nuclear Society 48FR34036 001 83/10/12
CHILK, S J Office of the Secretary of the Commission, 1p
20897 108

PRM PETITION FOR RULEMAKING

B310030527 Comments on petition for rulemaking PRM-50-36 from Nuclear Util Backfitting & Reform Group More attention would be devoted to investigating event & completing corrective action if resident inspector becomes point-of-contact
ZIMMERMAN, S R Carolina Power & Light Co 48FR28282 017 83/09/23
CHILK, S J Docketing & Services Branch 4pp 20601 203

PROJ PROJECTS - PREDOCKET LICENSING

B310050197 Forwards proprietary "Westinghouse Pretendering Module B Integrated Control & Protection Sys" Rept withheld (ref 10CFR2 790)
RAHE, E P Westinghouse Electric Corp NS-EPR-2818 83/09/23
EISENHUT, D G Division of Licensing 2pp, 20628 348

--B310050212 Requests proprietary classification per 10CFR2 790 for encl rept, "Westinghouse Pretender Module B Integrated Control & Protection Sys"
WIESEMANN, R A Westinghouse Electric Corp AW-83-71 83/09/23
EISENHUT, D G Division of Licensing 1p 20628 350

B310060267 Forwards proprietary "Westinghouse Advanced PWR Pretendering Module 9 - Component Cooling Sys," supplementing B21101 submittal Rept withheld (ref 10CFR2 790)
RAHE, E P Westinghouse Electric Corp NS-EPR-2829 83/09/30
EISENHUT, D G Office of Nuclear Reactor Regulation, Director 2pp 20646 151

--B310060270 Requests "Westinghouse Advanced PWR Pretendering Module 9 - Component Cooling Sys," be withheld per 10CFR2 790.
WIESEMANN, R A Westinghouse Electric Corp AW-83-79 83/09/30
EISENHUT, D G Office of Nuclear Reactor Regulation, Director 1p 20646 153

B310070156 Forwards Director's Decision 83-14, denying 830909 10CFR2 206 petition re transport of spent nuclear fuel from West Valley
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director
DD-83-14 83/09/30 CELEDREZZE, A J, Ohio, State of 2pp
20680 308 24X Fiche 50-000, 83/09/30, B310070156.

NONDOCKETED ITEMS

467

--B310070161 Forwards Director's Decision B3-14, denying B30824 10CFR2 206 petition re transport of spent nuclear fuel from West Valley
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director DD-B3-14 83/09/30 RESNIKOFF, M Sierra Club 1p 20680 309 24X Fiche 50-000, 83/09/30, B310070156

--B310070167 Notice of issuance of Director's Decision B3-14, denying State of OH & Sierra Club B30909 & 0824, respectively, 10CFR2 206 petitions re transport of spent nuclear fuel from West Valley
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director DD-B3-14 83/09/30 2pp 20680 310 24X Fiche 50-000, 83/09/30, B310070156

--B310070171 Director's Decision B3-14, denying State of OH & Sierra Club B30909 & 0824, respectively, 10CFR2 206 petitions re transport of spent nuclear fuel from West Valley Request for hearing & for preparation of EIS denied
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director DD-B3-14 83/09/30 18pp 20680 312 24X Fiche 50-000, 83/09/30, B310070156

B310070174 Notification of B31004 meeting w/Westinghouse in Bethesda, MD to discuss WCAP-10243 (NP) "Review Plan for Upgrading Licensed Power of Advanced PWR Power Plant"
MORAN, D H Standardization & Special Projects Branch 83/09/26 THOMAS, C O Standardization & Special Projects Branch 1p 20680 291

B310110004 Responds to FOIA request for five documents Forwards documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/07/01 PEDRO, J NUS Corp 2pp 20704 137 24X Fiche 50-000, 83/07/01, B310110004

--B310110013 Forwards preliminary evaluation of aircraft hazards at Pebble Springs site, per 731010 request Site probably acceptable provided reasonable care taken to minimize effective target area
DEVOUNG, R C Atomic Energy Commission, Directorate of Licensing 73/11/23 WILLIAMS, J L Portland General Electric Co 5pp 20704 184

--B310110016 Informs that preapplication safety review completed based on until 730507 submittal of proposed facility design Vital areas & mods to be made prior to operation discussed
DEVOUNG, R C Atomic Energy Commission, Directorate of Licensing 73/10/12 WILLIAMS, J L Portland General Electric Co 2pp 20704 189

--B310110018 "Aircraft Considerations Preapplication Site Review"
JM Campbell 710519 ltr to CPC encl
* Atomic Energy Commission, Directorate of Licensing 73/10/12 58pp 20704 191 24X Fiche 50-000, 83/07/01, B310110004

B310130334 Forwards Rev 2 to "Topical SAR for Castor Ic Cask ISFSI (Dry Storage)"
ROLLINS, J D Gesellschaft fuer Nuklear Service, mbH 22847 83/09/09 Division of Fuel Cycle & Material Safety 2pp 20771 043

--B310130336 Rev 2 to "Topical SAR for Castor Ic Cask ISFSI (Dry Storage)"
* Gesellschaft fuer Nuklear Service, mbH 22847 83/07/31 461pp 20771 045

B310270051 Responds to FOIA request for "Westinghouse Advanced PWR Licensing Control Document," dtd Aug 1982, to be placed in PDR Document withheld (ref FOIA Exemption 4)
FELTON, J M Division of Rules and Records 83/07/14 PEDRO, J NUS Corp 1p 20942 016

B310270057 FOIA request for "Westinghouse Advanced PWR Licensing Control Document," dtd Aug 1982, to be placed in PDR Rept referenced at NRC 821130 meeting w/Westinghouse
PEDRO, J NUS Corp CD-18-B3-021 83/06/08 Division of Rules and Records 1p 20942 017

B310280106 Forwards proprietary version of Westinghouse Advanced PWR RESAR SP/90 - Module 1, "Primary Side Safeguards Sys Module" Rept withheld (ref 10CFR2 770)
RAHE, E P Westinghouse Electric Corp NS-EPR-2842 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 76pp 20934 198

--B310280110 Application for withholding Westinghouse Advanced PWR RESAR SP/90, "Primary Side Safeguards Sys Module," from public disclosure
WIESEMANN, R A Westinghouse Electric Corp AW-B3-93 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 9pp 20934 276

B310280147 Forwards B30930 Director's Decision B3-14, denying State of OH & Sierra Club 10CFR2 206 petitions re transportation of spent fuel from West Valley facility, per B30930 request
CUNNINGHAM, R E Division of Fuel Cycle & Material Safety DD-B3-14 83/10/18 MILLER, F Environmental Policy Institute 2pp 20961 329 24X Fiche 50-000, 83/10/18, B310280147

PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

B310030244 Final deficiency rept re offset lead-in guides on Wachter spent fuel cells Initially reported on B30318 Engineering Change Notice 4043 issued revising Wachter Assoc, Inc drawings Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 10CFR 050 55E 83/09/21, O'REILLY, J P Region 2, Office of Director 2pp 20591 069 24X Fiche 50-390, 83/09/21, B310030244

B310030257 First interim deficiency rept re broken pin carrier plates on ERCH motors mfg by Siemens-Allis Initially reported on B30824 Vendor in process of determining max loading applied to bushings Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 10CFR 050 55E 83/09/21, O'REILLY, J P Region 2, Office of Director 2pp 20591 060 24X Fiche 50-390, 83/09/21, B310030257

B310030373 Final & interim deficiency rept for Units 1 & 2, respectively re incorrect operation of Div 1 & 11 diesel generator load shedding & sequencing sys panels w/automatic test feature on line Initially reported B30921 Also reportable per Part 21
HCOAUGHY, J P Mississippi Power & Light Co 10CFR 050 55E 83/09/21 O'REILLY, J P Region 2, Office of Director 4pp 20593 083 24X Fiche 50-416, 83/09/21, B310030373

B310030374 Second interim deficiency rept re failure of Agastat GP series relays to change state when called to operate Caused by svc aging in mild environ in combination w/mechanical configurations & tolerances of internal parts
HCOAUGHY, J P Mississippi Power & Light Co 10CFR 050 55E 83/09/22 O'REILLY, J P Region 2, Office of Director 5pp 20592 190 24X Fiche 50-416, 83/09/22, B310030374

B310030462 Final deficiency rept re heat loss from Power Sys diesels Initially reported on B20729 Heat loss tests performed on B21120 & B30223 confirmed temps near safety-related equipment exceeded limits Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 10CFR 050 55E 83/09/23 O'REILLY, J P Region 2, Office of Director 3pp 20601 049 24X Fiche 50-390, 83/09/23, B310030462

B310030506 Revised Final deficiency rept re sheared motor pinion keys in Limitorque motor operators Initially reported on B20830 Condition only applies to Watts Bar Keys will be replaced by B40201 Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 10CFR 050 55E 83/09/22 O'REILLY, J P Region 2, Office of Director 3pp 20601 194 24X Fiche 50-000, 83/09/22, B310030506

B310040232 Part 21 rept re plant mod implementing fire protection, including blocking vent paths from reactor bldg rooms containing high energy lines Initially reported on B30928 Six rooms require reanalysis
CONN, W O Burns & Roe Co BRGO-RD-B3-013 83/09/29 Director's Office, Office of Inspection and Enforcement 2pp 20613 201 24X Fiche 50-397, 83/09/29, B310040232

B310040331 Part 21 rept re control circuits for safety-related valves CAC-PCV-1A & 1B powered from non-Class 1E power supply Caused by failure to recognize valves have two safety-related functions: isolation & oxygen/hydrogen recombination
CONN, W O Burns & Roe Co BRGO-RD-B3-041 83/09/29 Director's Office, Office of Inspection and Enforcement 2pp 20617 118 24X Fiche 50-397, 83/09/29, B310040331

B310040410 Final deficiency rept re auxiliary feedwater sys containment isolation valves Initially reported on B30822 Sys design modified to require performance sys function of safety-grade active valves Also reported per Part 21
OPREA, Q W Houston Lighting & Power Co 10CFR 050 55E 83/09/21 COLLINS, J T Region 4, Office of Director 5pp 20619 035 24X Fiche 50-49B, 83/09/21, B310040410

B310060016 Final deficiency rept re valve position indication problems w/EMD gate Valves Initially reported on B30203 Westinghouse equipment engineers provided w/instructions re valve function Also reportable under Part 21
MILLS, L M Tennessee Valley Authority 10CFR 050 55E 83/09/29, O'REILLY, J P Region 2, Office of Director 2pp 20648 354 24X Fiche 50-390, 83/09/29, B310060016

NONDOCKETED ITEMS

- 8310060027 Final deficiency rept re containment spray miniflow valve design error Initially reported on 820305 Westinghouse internal design assurance & verification procedures revised Also reportable under Part 21
MILLS, L M Tennessee Valley Authority 10CFR 050 55E 83/09/29
O'REILLY, J P Region 2, Office of Director 2pp 20647 091 24X
Fiche 50-390, 83/09/29, 8310060027
- 8310060036 Third interim Deficiency Rept 77 re shop welding defects in seismic Class I cable tray, conduit & HVAC hangers Initially reported on 820802 Final rept expected by 840301 Also reportable per 10CFR21
PARSONS, R M Carolina Power & Light Co 10CFR 050 55E 83/09/29
O'REILLY, J P Region 2, Office of Director 4pp 20647 087 24X
Fiche 50-400, 83/09/29, 8310060036
- 8310060221 Potential Part 21 rept re defective ITY-Grinnell hydraulic snubbers Initially reported in 830928 telcon Deficient snubber valve blocks will be remachined & snubbers rebuilt
JOHNSON, B D Consumers Power Co 83/09/30 KEPLER, J O Region 3, Office of Director 4pp 20647 021 24X Fiche 50-255, 83/09/30, 8310060221
- 8310060336 Interim deficiency rept, Item 143 re weld deficiencies in sections of ducts CC-1 & CC-2 & transformers ID1, ID2, IE1 & IE2 from Gould & Brown-Boveri Util awaiting vendor response Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co 10CFR 050 55E 83/09/29
O'REILLY, J P Region 2, Office of Director 1p 20646 092 24X
Fiche 50-400, 83/09/29, 8310060336
- 8310060342 Final deficiency rept re steam generator lower support bolts Initially reported on 820610 Reheat treatments provide adequate strength at operating temp, sufficient fracture toughness & crack resistance Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 10CFR 050 55E 83/09/30
O'REILLY, J P Region 2, Office of Director 3pp 20646 077 24X
Fiche 50-390, 83/09/30, 8310060342
- 8310060343 Part 21 rept re Gould unitized starters supplied as spare parts Initially reported on 830923 Final rept expected 831130
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire SBN-568 83/09/28 Region 1, Office of Director 4pp 20646 135 24X Fiche 50-443, 83/09/28, 8310060343
- 8310060476 Fifth interim deficiency rept re setpoint program for overpressure mitigation sys Initially reported on 820521 Util conducted PDRV response time tests Next rept expected by 840103 Also reportable under Part 21
MILLS, L M Tennessee Valley Authority 10CFR 050 55E 83/09/30
O'REILLY, J P Region 2, Office of Director 2pp 20641 017 24X
Fiche 50-390, 83/09/30, 8310060476
- 8310070163 Part 21 rept re potential defects in molded case of 100-amp frame, multi-pole E & HE series circuit breakers Initially reported on 830902
ERHARDT, J V Gould, Inc GA15/REN/D0 83/09/26 MURLEY, T E Region 1, Office of Director 10pp 20659 095 24X
Fiche 50-000, 83/09/26, 8310070163
- 8310070301 Potential Part 21 rept re Underrange characteristic of Model N-E110H transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X
Fiche 50-000, 83/09/30, 8310070301
- 8310120092 Part 21 rept re snubber failure during shock arrestor test Caused by broken capstan spring, Vendor effecting corrective action w/J Evans Co to inspect shock arrestors containing Evans springs
HADNAQV, P A Pacific Scientific 83/09/14 Region 3, Office of Director 4pp 20696 167 24X Fiche 50-482, 83/09/14, 8310120092
- 8310120237 Final deficiency rept re ambiguous outputs from Barton pressure transmitters in RCS Initially reported on 830409 Addl RCS transmitters installed outside containment Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 10CFR 050 55E 83/10/03
O'REILLY, J P Region 2, Office of Director 3pp 20692 172 24X
Fiche 50-390, 83/10/03, 8310120237
- 8310120367 Second interim deficiency rept, Items 95 & 72 & Part 21 rept re shop welding deficiencies in seismic I pipe hangers supplied by Bergen-Paterson Initially reported on 820813 & 1105 All active hangers corrected.
PARSONS, R M Carolina Power & Light Co 10CFR 050 55E 83/10/03
O'REILLY, J P Region 3, Office of Director 5pp 20699 295 24X
Fiche 50-400, 83/10/03, 8310120367
- 8310140075 Final deficiency rept for Unit 1 & interim deficiency rept for Unit 2 re potential rupture of high pressure fuel injection lines on Div I & II diesel generators during engine operation Also reportable under Part 21 for Unit 1
MCGAUGHY, J P Mississippi Power & Light Co 10CFR 050 55E 83/10/05
O'REILLY, J P Region 2, Office of Director 5pp 20768 018 24X Fiche 50-416, 83/10/05, 8310140075
- 8310140259 Final Deficiency Rept DER 83-45 re cable separations in control room panels Initially reported on 830707 Procedures revised to ref Const Spec 13-EM-306 for separation criteria requirements Also reportable per Part 21
VAN BRUNT, E E Arizona Public Service Co 10CFR 050 55E 83/09/26
STERNBERG, D M Region 3, Office of Director 13pp 20762 069 24X Fiche 50-528, 83/09/26, 8310140259
- 8310140277 Second interim deficiency rept re welds on baffle plates in core support assembly mgt by B&W Initially reported on 830302 Baffle plates on former bolt locking pin welds repaired Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 10CFR 050 55E 83/10/03
O'REILLY, J P Region 2, Office of Director 19pp 20761 195 24X
Fiche 50-438, 83/10/03, 8310140277
- 8310170153 Interim deficiency rept re Rockwell Intl microswitch in post-LOCA hydrogen recombiners Initially reported on 830811 Final rept will be submitted by 830909 Also reported per Part 21
MANNO, B F Niagara Mohawk Power Corp 10CFR 050 55E 83/09/01
STAROSTECKI, R Division of Project & Resident Programs 2pp 20787 114 24X Fiche 50-410, 83/09/01, 8310170153
- 8310170400 Final Deficiency Rept PRD-83/15 re defective Sprague Type 40D capacitor on Brown Boveri Electric low voltage circuit breakers equipped w/solid state trip devices Initially reported on 831002 Also reportable per Part 21
MCGAUGHY, J P Mississippi Power & Light Co AECM-83/0666 83/10/10
O'REILLY, J P Region 2, Office of Director 3pp 20785 080 24X Fiche 50-416, 83/10/10, 8310170400
- 8310170469 Second interim Deficiency Rept RDC 78(83) re exhaust line back pressures exceeding manufacturer recommendations on standby diesel generators for HPCS Initially reported on 830809 Further mods required Also reported per Part 21
EDELHAN, M R Cleveland Electric Illuminating Co 10CFR 050 55E 83/10/06
KEPLER, J O Region 3, Office of Director 2pp 20784 101 24X Fiche 50-440, 83/10/06, 8310170469
- 8310180305 Final Deficiency Rept DR-80 re defective piston skirt castings installed in emergency diesel generator engines supplied by Transamerica Delaval Initially reported on 821124 Piston skirts replaced Also reported per Part 21
BOOKER, J E Gulf States Utilities Co 10CFR 050 55E 83/10/06
COLLINS, J T Region 4, Office of Director 2pp 20803 096 24X
Fiche 50-458, 83/10/06, 8310180305
- 8310200165 Part 21 rept re static temp calibr check on transmitters Initially reported on 831013 Caused by irregular setpoint for pressurizer pressure safety injection function New 1.829 psig setpoint recommended
RAHE, E P Westinghouse Electric Corp NS-EPR-2837 83/10/13
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 20834 078 24X Fiche 50-000, 83/10/13, 8310200165
- 8310210068 Final deficiency rept for Unit 1 & third interim deficiency rept for Unit 2 re loose mail in steam generator Initially reported on 830325, Caused by lack of work controls Also reportable per Part 21 Next rept due by 840706
MILLS, L M Tennessee Valley Authority 10CFR 050 55E 83/10/13
O'REILLY, J P Region 2, Office of Director 4pp 20837 270 24X
Fiche 50-390, 83/10/13, 8310210068
- 8310210115 Interim deficiency rept re calibr technique for temp compensation on Barton transmitters Westinghouse Part 21 rept described undefined errors at abnormal & accident temps Next rept in 14 days
SMITH, W O Indiana & Michigan Electric Co 83/10/14 KEPLER, J O Region 3, Office of Director 1p 20898 254 24X
Fiche 50-319, 83/10/14, 8310210115
- 8310210255 Part 21 rept re potential defects in molded case, 100 ampere frame, multi-pole E & HE series circuit breakers Encl suppl 830926 ltr
FENNETEAU, M M Gould, Inc GA15-MMF-D0 83/10/14 MURLEY, T E Region 1, Office of Director 2pp 20851 047 24X
Fiche 50-458, 83/10/14, 8310210255
- 8310250505 Part 21 rept re safety-related control circuits for CAC-FCV-1A & 1B, being powered from non-Class IE power supply Initially reported on 830928 PED 218-E-C105 issued to provide Class IE power supplies to two valves
CONN, W O Burns & Roe Co BR00-RD-83-014 83/09/29 Director's Office, Office of Inspection and Enforcement 2pp 20902 078 24X
Fiche 50-397, 83/09/29, 8310250505

8310260186 Part 21 rept re potentially defective Presray airlock seal in drywell personnel airlock supplied by WJ Woolley. Initially reported by vendor on 830919. New seal being designed by Presray Corp will be installed when available. DALE, L F Mississippi Power & Light Co AECM-83/0674 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20915 250 24X Fiche 50-416, 83/10/24, 8310260186

8310270206 Part 21 rept re engine mounted electrical cables Defective cable not installed as 830927 ltr states Parts shipped & installed on Gulf States River Bend Site (Engine Serial 74039/40 DSR 48) Instruction for cable changeout due in Nov. BOYER, R E Transamerica Delaval, Inc 83/10/20 Director's Office, Office of Inspection and Enforcement 1p 20924 108 24X Fiche 50-000, 83/10/20, 8310270206

8310270395 Interim deficiency rept re Westinghouse centrifugal charging pumps at min allowable flow rate when RCS reaches value below pressurizer safety valve setpoint pressure. Initially reported on 800509. Also reported per Part 21. SHIELDS, S W Public Service Co of Indiana, Inc 10CFR 50.55E 83/10/20 KEPLER, J G Region 3, Office of Director 2pp 20924 034 24X Fiche 50-546, 83/10/20, 8310270395

8310270430 Final Deficiency Rept DER 83-43 re improper crimp terminations in 12 cabinets furnished by Harlo Corp. Initially reported on 830708. Harlo cabinets for all units will be inspected & reworked. Also reportable per Part 21. VAN BRUNT, E E Arizona Public Service Co 10CFR 50.55E 83/09/27 BISHOP, T W Division of Resident Reactor Project & Engineering Programs 6pp 20923 085 24X Fiche 50-528, 83/09/27, 8310270430

8310270433 Final Deficiency Rept PRD-83/12 for Unit 1 & interim rept for Unit 2 re failure of Agastat OP series relays to switch. Initially reported on 830902. Deficiency reportable per Part 21 for Unit 1. Investigation ongoing for Unit 2. MCQUAGHY, J P Mississippi Power & Light Co PRD-83/12 83/10/17 O'REILLY, J P Region 2, Office of Director 5pp 20923 044 24X Fiche 50-416, 83/10/17, 8310270433

8310280065 Second interim deficiency rept re OE reactor mode switch. Initially reported on 830407. Mode switch redesigned. Sample will be independently tested. Also reported per Part 21. Final rept will be submitted by Dec 1983. CURTIS, N W Pennsylvania Power & Light Co 10CFR 50.55E 83/09/30 MURLEY, T E Region 1, Office of Director 6pp 20929 020 24X Fiche 50-388, 83/09/30, 8310280065

8310280093 Potential const deficiency rept re Basler Electric Co resistors installed in emergency diesel generators. Initially reported on 830901 & reported by vendor under Part 21 on 830819. Final rept expected by 831100. MARTIN, T J Public Service Electric & Gas Co of New Jersey 10CFR 50.55E 83/09/30 MURLEY, T E Region 1, Office of Director 2pp 20935 322 24X Fiche 50-354, 83/09/30, 8310280093

8310280094 RO on 831004, 138-kV station auxiliary power supply lost when pilot wire receiver relay tripped. Cause under investigation. Supply reestablished to all 6 9-kV buses. Also reported per Part 21. JACKSON, C W Consolidated Edison Co of New York, Inc 10CFR 50.55E 83/10/05 MURLEY, T E Region 1, Office of Director 1p 20935 065 24X Fiche 50-247, 83/10/05, 8310280094

8310280130 Final deficiency rept re water hammer in essential svc water sys. Initially reported on 830505. Vacuum breakers will be installed during first refueling outage. Also reported per Part 21. CURTIS, N W Pennsylvania Power & Light Co 10CFR 50.55E 83/09/22 MURLEY, T E Region 1, Office of Director 7pp 20929 254 24X Fiche 50-387, 83/09/22, 8310280130

8310280139 Interim deficiency rept re isolation of nitrogen makeup sys. Also reportable per Part 21. Initially reported on 830912. Permanent design mod will be implemented. Final rept will be submitted in Dec 1983. CURTIS, N W Pennsylvania Power & Light Co 10CFR 50.55E 83/10/10 MURLEY, T E Region 1, Office of Director 5pp. 20929 009 24X Fiche 50-388, 83/10/10, 8310280139

8310310074 Part 21 rept re design deficiency involving combination supports for Class IE cable trays & HVAC ducts. Initially reported on 831025. Due to misclassification, supports specified w/less than full safety-related QA program. MEYERS, B L Bechtel Corp BLSM-83/269 83/10/27, DEYOUNG, R Director's Office, Office of Inspection and Enforcement 3pp. 20931 043 24X Fiche 50-000, 83/10/27, 8310310074

8310310135 Supplemental Part 21 rept re shock arresters w/cracked capstan spring tangs. Attached customer list reflects companies which received affected arresters. List of serial numbers also encl. HADNAGY, P A Pacific Scientific PT21 83-029-000 83/10/20 HAIST, D Region 5, Office of Director 94pp 20949.005.

8310310273 Part 21 rept re defective byproduct matl, Ir-192, in Model 200-520-009. Initially reported on 831013. Caused by corroded wire strands in cross-sectional areas. Defective unit removed & rept requesting preventive action from supplier issued. * Navy, Dept of 83/10/17 Region 5, Office of Director 4pp 20961 313

8310310348 Final deficiency rept re Target Rock pressurizer PORVs failure to open. Initially reported on 830922. Analyses could not identify cause for compressed rings. Valves modified by vendor. Also reportable per Part 21. MILLS, L M Tennessee Valley Authority 10CFR 50.55E 83/10/21 O'REILLY, J P Region 2, Office of Director 3pp 20937-074 24X Fiche 50-390, 83/10/21, 8310310348

QA999 QUALITY ASSURANCE INSPECTIONS

8308300705 Forwards QA Program Insp Rept 99900831/83-01 on 830516-18 & notices of violation & nonconformance. POTAPQVS, U Region 4, Office of Director 83/08/05, PLEUNIK, B ICO Puerto Rico, Inc 2pp 20206 308.

--8308300712 Notice of violation from insp on 830516-18 * Region 4, Office of Director 83/08/05, 1p 20206.310

--8308300716 Notice of nonconformance from insp on 830516-18 * Region 4, Office of Director 83/08/05 5pp 20206 311

--8308300722 QA Program Insp Rept 99900831/83-01 on 830516-18. Noncompliance noted. QA program failed to identify or describe organization functions & failed to provide measures to assure requirements included in procurement. MCNEILL, W. BARNES, I. Region 4, Office of Director, 83/08/05 18pp 20206 316

8310030342 Forwards QA Program Insp Rept 99900021/83-01 on 830725-29 & notice of nonconformance. POTAPQVS, U Region 4, Office of Director 83/09/16 BONES, J E Pullman - Swindell Associates, Inc 2pp 20590 316

--8310030348 Notice of nonconformance from insp on 830725-29 * Region 4, Office of Director 83/09/16 2pp 20590.318

--8310030352 QA Program Insp Rept 99900021/83-01 on 830725-29. Noncompliance noted. Failure to perform required annual mgt audit of effective implementation of corporate functions at const sites. NDRHAM, D E, BARNES, I. Region 4, Office of Director 83/09/12 15pp 20590 320

8310030379 Forwards QA Program Insp Rept 99900330/83-01 on 830801-04 & notices of violation & nonconformance. POTAPQVS, U Region 4, Office of Director, 83/09/13 SAUTER, D M Westinghouse Electric Corp 3pp 20592 176

--8310030381 Notice of violation from insp on 830801-04 * Division of Vendor & Technical Programs 83/09/13 1p. 20592 179

--8310030383 Notice of nonconformance from insp on 830801-04 * Division of Vendor & Technical Programs, 83/09/13 2pp 20592 180

--8310030387 QA Program Insp Rept 99900330/83-01 on 830801-04. Noncompliance noted. Outdated 10CFR21 posted & insp records re quality control checks on critical parts of undervoltage trip devices incomplete. POTAPQVS, I Region 4, Office of Director MCNEILL, W.M Divi of Vendor & Technical Programs 83/09/12 8pp 20592 182

NONDOCKETED ITEMS

310030450 Notice of violation from insp on 830726-29
* Region 4, Office of Director 83/09/16 1p 20602 045

310030454 Notice of nonconformance from insp on 830726-29
* Region 4, Office of Director 83/09/16 1p 20602 046

310030457 QA Program Insp Rept 99900712/83-01 on 830726-29
Noncompliance noted Section 206 of 1974 Energy
Reorganization Act not posted & corrective actions for QA
manual rev & welder monitoring & weld insp not accomplished
ELLERSHAU, L E, BARNES, I Region 4, Office of Director 83/09/08
11pp 20602 047

0030464 Ack receipt of 830721 & 0912 ltrs informing NRC of steps
taken to correct nonconformance noted in QA Program Insp
Rept 99900104/83-01
POTAPOVS, U Region 4, Office of Director 83/09/27 MILLER, T D
Westinghouse Electric Corp 1p 20601 052

310030469 Responds to NRC 830822 ltr re nonconformance noted in QA
Program Insp Rept 99900104/83-01 Corrective actions product
& process audit reviews will be conducted Code
Interpretation 3-82-17 encl
MILLER, T D Westinghouse Electric Corp PA-83-074 83/09/12
POTAPOVS, U Region 4, Office of Director 2pp 20601 053

0040242 Forwards QA Program Insp Rept 99900271/83-01 on 830801-03
notice of nonconformance
POTAPOVS, U Region 4, Office of Director 83/09/12 KOCH, W H
Bessmount, Inc 2pp 20613 203

310040246 Notice of nonconformance from insp on 830801-03
* Region 4, Office of Director 83/09/12 2pp 20613 206

310040249 QA Program Insp Rept 99900271/83-01 on 830801-03
Noncompliance noted: sensor stretched diagram, completed in
June 1983, had wrong procedure number Internal audit log not
maintained
ELLER, R E, BARNES, I Region 4, Office of Director 83/09/07
12pp 20613 208

040343 Ack receipt of 830822 ltr informing NRC of steps taken to
correct nonconformance noted in QA Program Insp Rept
99900507/83-02
POTAPOVS, U Region 4, Office of Director 83/09/30 PATTERSON, R W
Sargent & Lundy, Inc 1p 20617 280

10040349 Responds to NRC 830722 ltr re nonconformance noted in QA
Program Insp Rept 99900507/83-02 Corrective actions client
audits not documented in QA coordination section meeting
notes from Mar 1982 - Mar 1983 will be surveyed
TAYLOR, H S Sargent & Lundy, Inc 83/08/22 POTAPOVS, U Region
4, Office of Director 10pp 20617 281

040382 Ack receipt of 830802 ltr informing NRC of steps taken to
correct nonconformance noted in QA Program Insp Rept
99900919/83-01
POTAPOVS, U Region 4, Office of Director 83/09/30 DAVIS, A G
East-West Technology Corp 1p 20620 280

10040383 Responds to NRC 830624 ltr re nonconformance noted in QA
Program Insp Rept 99900919/83-01 Corrective actions all
procurement documents for quality-related activities will be
reviewed by QA manager Internal audits implemented
DAVIS, T M East-West Technology Corp 83/08/02 POTAPOVS, U
Region 4, Office of Director 3pp 20620 281

040422 Ack receipt of 830707 & 0902 ltrs informing NRC of steps
taken to correct nonconformance noted in QA Program Insp
Rept 99900015/83-01
POTAPOVS, U Region 4, Office of Director 83/09/30 TUTTROW, R E
Bowline Corp 1p 20619 137.

0040426 Responds to NRC 830801 ltr re nonconformance noted in QA
Program Insp Rept 99900015/83-01 Corrective actions copies
of 10CFR21 posted & customer notified to verify that
magnetic particle test rept received w/shipment
TUTTROW, R E Bowline Corp 83/09/02 POTAPOVS, U Region 4,
Office of Director 17pp 20619 138

0040433 Ack receipt of 830707 response to QA Program Insp Rept
99900015/83-01, Addl info re records retention methods &
documentation furnished to Baldwin Assoc & B&W re heat treat
ment requested
POTAPOVS, U Region 4, Office of Director 83/08/01
TUTTROW, R E Bowline Corp 2pp 20619 153

--8310040437 Responds to 830617 notice of violation contained in QA
Program Insp Rept 99900015/83-01 Corrective actions QA
personnel instructed to track exam procedure numbers
TUTTROW, R E Bowline Corp 83/07/07 POTAPOVS, U Region 4,
Office of Director 10pp 20619 157

8310040432 Forwards QA Program Insp/Investigation Rept 99900345/82-04
notice of nonconformance for IE Investigation Repts
99900345/82-02 & 99900345/82-03
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement EA-82-132 82/12/22 LYONS, B P Hayward Tyler Pump
Co 3pp 20624 237

--8310040441 Notice of nonconformance from insp on 820104-0826
* Director's Office, Office of Inspection and Enforcement
82/12/22 9pp 20624 240

--8310040453 QA Program Insp/Investigation Rept 99900345/82-04 on 820103-
0826 Noncompliance noted training records & indoctrination
schedules did not meet engineering stds & corrective actions
not implemented by appropriate mgt
MATAKES, R E A, DROMERICK, A W, PERANICH, M W Region 4, Office of
Director 82/11/12 274pp 20624 249

8310040485 Ack receipt of 830906 ltr informing NRC of steps taken to
correct nonconformance noted in QA Program Insp Rept
99900501/83-02
POTAPOVS, U Region 4, Office of Director 83/09/30 WAHL, H W
Bechtel Corp 1p 20625 167

--8310040488 Responds to NRC 830808 ltr re nonconformance noted in QA
Program Insp Rept 99900501/83-02 Corrective actions project
engineering procedures issued to incorporate mgt engineering
directive revs will not be delayed in future
WAHL, H W Bechtel Corp 83/09/06 POTAPOVS, U Region 4, Office
of Director 2pp 20625 168

8310040576 Forwards QA Program Insp Rept 99900537/83-01 on 830815-10
& notices of nonconformance & violation
POTAPOVS, U Region 4, Office of Director 83/09/16 SKJEI, R C
John A Blume & Associates, Engineers (subs URS Corp) 2pp
20622 330

--8310040579 Notice of violation from insp on 830815-10
* Region 4, Office of Director 83/09/16 1p 20622 332

--8310040586 Notice of nonconformance from insp on 830815-10
* Region 4, Office of Director 83/09/16 1p 20622 333

--8310040596 QA Program Insp Rept 99900537/83-01 on 830815-10
Noncompliance noted contrary to 10CFR21, licensee did not
adopt appropriate procedures to provide for evaluating
deviations or informing licensee or purchaser of deviation
BRICKLEY, R H, HALE, C J Region 4, Office of Director 83/09/13
10pp 20622 334

8310130288 Confirms QA program insp at Southwest Research Inst on
831011-14, per 830919 telcon
POTAPOVS, U Region 4, Office of Director 83/10/04 DESSEY, R L
Southwest Research Institute 1p 20719 149

8310180142 Confirms QA program insp at Lynchburg, VA site on 831031-
1104, per 830928 telcon
POTAPOVS, U Region 4, Office of Director 83/10/07 DENHAM, F K
Limitorque Corp 1p 20807 096

8310180154 Confirms QA program insp at Oak Ridge, TN plant on 831011-14,
per 830919 telcon
POTAPOVS, U Region 4, Office of Director 83/10/06 LORENZ, H
Gilbert/Commonwealth Cos 1p 20809 193

8310180201 Confirms QA program insp at Aurora, IL plant on 831017-21, per
830920 telcon
POTAPOVS, U Region 4, Office of Director 83/09/30 WILSON, A K
Henry Pratt Co 1p 20808 338

8310180216 Ack receipt of 830317, 0805 & 31 ltrs informing NRC of steps
taken to correct nonconformance noted in QA Program Insp
Rept 99900294/82-01 Effective date for implementation of
Item A is 830831
POTAPOVS, U Region 4, Office of Director 83/10/07 NEWMAN, B
Amarace Corp 2pp 20806 176

--8310180313 Responds to NRC 830714 ltr requesting addl info re
nonconformance noted in QA Program Insp Rept 99900294/82-01
Corrective actions NRC will be advised only of intended
action & hold all items open until action complete
MARTIN, H G Amarace Corp 83118 83/08/31 POTAPOVS, U
Region 4, Office of Director 3pp 20806 178

NONDOCKETED ITEMS

471

- B310180323 Ack receipt of NRC 830714 ltr requesting addl info re nonconformance noted in QA Program Insp Rept 99900296/B2-01 Due to vacations, response cannot be provided until early Sept
MARTIN, M G Amerace Corp QA 83111 83/08/05 POTAPQVS, U Region 4, Office of Director 1p 20806 181
- B310180332 Ack receipt of 830317 ltr in response to NRC 830222 ltr re nonconformance noted in QA Program Insp Rept 99900296/B2-01 Addl info needed for Item A re description of steps taken to ensure commitments honored
POTAPQVS, U Region 4, Office of Director 83/07/14 NEWMAN, E Amerace Corp 2pp 20806 182
- B310180340 Responds to NRC 830222 ltr re nonconformance noted in QA Program Insp Rept 99900296/B2-01 Corrective actions Audit Procedure Q2 19 1 revised to call for check of ERN & advance ERN for signature
MARTIN, M G Amerace Corp QA 83046 83/03/17 POTAPQVS, U Region 4, Office of Director 4pp 20806 184
- B310180291 Ack receipt of 830921 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900532/B3-01
POTAPQVS, U Region 4, Office of Director 83/10/06 MOORE, G E Control Data Corp 1p 20806 361
- B310180299 Responds to NRC 830824 ltr re nonconformance noted in QA Program Insp Rept 99900932/B3-01 Corrective actions hotline log for previously reported PIPESD error will be modified to cross-reference Software Problem Rept SPR PIP0008
MOORE, G E Control Data Corp 83/09/21 POTAPQVS, U Region 4, Office of Director 3pp 20806 362
- B310180297 Confirms QA program insp at Pensacola, FL plant on 831017-21, per 830923 telcon
POTAPQVS, U Region 4, Office of Director 83/10/06 MILLER, T D Westinghouse Electric Corp 1p 20806 350
- B310180312 Ack receipt of 830418 & 0812 ltrs informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 99900904/B2-02
POTAPQVS, U Region 4, Office of Director 83/09/30 MIGNOGNA, T Limitorque Corp 1p 20806 266
- B310180314 Responds to NRC 830613 ltr re nonconformances noted in QA Program Insp Rept 99900904/B2-02 Corrective actions revs made to QA manual, Section VII, Pages 2,3 & 5 Review of cited purchase orders revealed vendors in accordance w/10CFR50
MCQUILLAN, P G Limitorque Corp 83/08/12 POTAPQVS, U Region 4, Office of Director 2pp 20806 267
- B310180318 Ack receipt of 830418 ltr informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 99900904/B2-02 Addl info required re QA manual & procedures
POTAPQVS, U Region 4, Office of Director 83/06/13 MIGNOGNA, T Limitorque Corp 4pp 20806 269
- B310180326 Responds to NRC 830225 ltr re nonconformances noted in QA Program Insp Rept 99900904/B2-02 Corrective actions provisions of Part 21 inapplicable since developmental program does not impact previously supplied actuator
MCQUILLAN, P G Limitorque Corp 83/04/18 POTAPQVS, U Region 4, Office of Director 2pp 20806 273
- B310180346 Forwards QA Program Insp Rept 99900702/B3-01 on 830725-29 & notices of violation & nonconformance
POTAPQVS, U Region 4, Office of Director 83/09/30 JONES, W F Harrison-Knudsen Co, Inc 3pp 20803 020
- B310180350 Notice of violation from insp on 830725-29
* Region 4, Office of Director 83/09/30 2pp 20803 023
- B310180353 Notice of nonconformance from insp on 830725-29
* Region 4, Office of Director 83/09/30 2pp 20803 025
- B310180358 QA Program Insp Rept 99900702/B3-01 on 830725-29 Noncompliance noted re heat radiated concerns did not include date on which info obtained & number & location of diesel generators w/failed heat radiators not identified.
FOSTER, W C, BARNES, I Region 4, Office of Director 83/09/24 15pp 20803 027
- B310180360 Forwards QA Program Insp Rept 99900334/B3-01 on 830711-15 & notices of nonconformance & violation
POTAPQVS, U Region 4, Office of Director 83/10/03, MATHEWS, C Transamerica Delaval, Inc 2pp 20804 269
- B310180365 Notice of violation from insp on 830711-15
* Region 4, Office of Director 83/10/03 1p 20804 271
- B310180371 Notice of nonconformance from insp on 830711-15
* Region 4, Office of Director 83/10/03 4pp 20804 272
- B310180378 QA Program Insp Rept 99900334/B3-01 on 830711-15 Noncompliance noted responsible officer did not notify NRC re jacket water pump shaft failures on emergency diesel generators
BUTTON, J W, BARNES, I Region 4, Office of Director. 83/09/27 25pp 20804 276
- B310180395 Ack receipt of 830908 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900369/B3-01
POTAPQVS, U Region 4, Office of Director 83/09/30 EHRHARD, E R Automatic Switch Co 1p 20803 217
- B310180400 Responds to NRC 830818 ltr re nonconformance noted in QA Program Insp Rept 99900369/B3-01 Corrective actions Procedure MP-1-051 modified by including statement that nuclear work handled under 10CFR50 inapplicable
OLSEN, L Automatic Switch Co 83/09/08 POTAPQVS, U Region 4, Office of Director 1p 20803 218
- B310180396 Ack receipt of 830719 & 0906 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900070/B3-01
POTAPQVS, U Region 4, Office of Director. 83/10/06, MILLER, J W Associated Piping & Engineering Corp (subs of Johnson Controls, Inc) 1p 20801 122
- B310180401 Responds to NRC 830811 ltr re nonconformance noted in QA Program Insp Rept 99900070/B3-01 Corrective actions Ebasco approved procedure for performance of actual buttering of PWHT revised Revised procedure encl
JORDAN, R L Associated Piping & Engineering Corp (subs of Johnson Controls, Inc) JORDAN, R L Johnson Controls, Inc 83/09/06 POTAPQVS, U Region 4, Office of Director 9pp 20801 123
- B310180404 Rev 3 to Welding Procedure Spec WPB 852-5634, "GTAW, SMAW, SAW Welding of Stainless Steel to QMAW Buttered Carbon Steel W/Heat Treat"
* Associated Piping & Engineering Corp (subs. of Johnson Controls, Inc) * Johnson Controls, Inc 82/10/07 10pp 20801 132
- B310180406 Addendum to Rev 0 to Welding Procedure Spec WPB 852-5634, "GTAW, SMAW, SAW Welding of Stainless Steel to QMAW Buttered Carbon Steel W/Heat Treat"
* Associated Piping & Engineering Corp (subs of Johnson Controls, Inc) * Johnson Controls, Inc 82/09/27 3pp 20801 142
- B310180407 Addendum to Rev 3 to Procedure BPPF-1002, "Heat Treatment of Carbon & Low Alloy Steel Matls P-No Groups 1,3,4 & 5 ASME Section III"
* Associated Piping & Engineering Corp (subs of Johnson Controls, Inc) * Johnson Controls, Inc 82/09/30 3pp. 20801 145
- B310180411 Rev 3 to Procedure BPPF-1002, "Heat Treatment of Carbon & Low Alloy Steel Matls P-No Groups 1,3,4 & 5, ASME Section III"
* Associated Piping & Engineering Corp (subs. of Johnson Controls, Inc) 82/03/11 3pp 20801 148
- B310180415 Ack receipt of 830719 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900070/B3-01 Submittal of documented evidence that dissimilar metal weld procedure approved requested
POTAPQVS, U Region 4, Office of Director. 83/08/11, MILLER, J W Associated Piping & Engineering Corp (subs of Johnson Controls, Inc), 1p 20801 153
- B310180429 Ack receipt of 830513 ltr informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 99900323/B3-01
POTAPQVS, U Region 4, Office of Director 83/09/30 ADAMS, J Conax Corp 1p 20803 294
- B310180431 Responds to NRC 830413 ltr re nonconformances noted in QA Program Insp Rept 99900323/B3-01 Corrective actions, Procedure IPS-1071 established for evaluation of reported deviations & nonconformance under Part 21.
BURDURE, R L Conax Corp. 83/05/13 POTAPQVS, U, Region 4, Office of Director 2pp 20803 295
- B310180433 Confirms QA program insp at Huntsville, AL plant on 831017-20, per 831011 telcon
POTAPQVS, U Region 4, Office of Director. 83/10/13 PATEL, M C Patel Engineers 1p 20803 299

NONDOCKETED ITEMS

8310180441 Forwards QA Program Insp Rept 99900525/83-02 on 830802-05
 notices of nonconformance & violation
 POTAPOVS,U Region 4, Office of Director 83/09/20 LORENZ,H
 Gilbert/Commonwealth Cos 3pp 20802 126

--8310180442 Notice of violation from insp on 830802-05
 * Region 4, Office of Director 83/09/20 1p 20802 129

--8310180445 Notice of nonconformance from insp on 830802-05
 * Region 4, Office of Director 83/09/20 1p 20802: 130

--8310180450 QA Program Insp Rept 99900525/83-02 on 830802-05
 Noncompliance noted failure to retest substantial safety
 hazards per Part 21
 HARRELL,P H , HALE,C J Region 4, Office of Director 83/08/31
 17pp 20802 131

8310180451 Forwards QA Program Insp Rept 99900902/83-02 on 830628-0701
 No noncompliance noted
 POTAPOVS,U Region 4, Office of Director 83/09/19 HOLBROOK,W H
 Wyler Sales Corp 2pp 20802 090

--8310180455 QA Program Insp Rept 99900902/83-02 on 830628-0701 No
 noncompliance noted Major areas inspected, evaluation of QA
 controls for Wyle engineering development & review &
 approval of qualification plans & assessment repts
 JOHNSON,A R , PHILLIPS,H S Region 4, Office of Director
 83/09/16 15pp 20802 092

8310180476 Confirms QA program insp at Boston,MA plant on 831017-20,
 per 830920 telcon
 POTAPOVS,U Region 4, Office of Director 83/10/13 BALDWIN,F B
 Stone & Webster Engineering Corp 1p 20801 342

8310180515 Forwards QA Program Insp Rept 99900345/83-01 on 830825
 No noncompliance noted
 POTAPOVS,U Region 4, Office of Director 83/09/22 PARRIN,R L
 Hayward Tyler Pump Co 2pp 20801 164

--8310180519 QA Program Insp Rept 99900345/83-01 on 830825 No
 noncompliance noted Major areas inspected liquid penetrant
 exam of spare ASTM B164 Class A pump shafts returned from
 Comanche Peak Steam Electric Station
 BARNES,I Region 4, Office of Director 83/09/15 5pp
 20801 166

8310180526 Ack receipt of 830523,0719 & 0819 ltrs informing NRC of
 steps taken to correct violation & nonconformance noted in
 QA Program Insp Rept 99900311/83-01
 POTAPOVS,U Region 4, Office of Director 83/09/30 GREENE,R F
 General Electric Co 1p 20799 101

--8310180527 Responds to NRC 830714 ltr re deviation & nonconformance
 noted in QA Program Insp Rept 99900311/83-01 Corrective
 actions posting requirements for 10CFR21 & Section 206
 revised to indicate location of documents
 GREENE,R F General Electric Co 83/08/19 POTAPOVS,U Region 4,
 Office of Director 3pp 20799 102

--8310180528 Confirms 830719 telcon re extension to 830829 to respond to
 830714 request for addl info re QA Program Insp Rept
 99900311,
 KANTHANN,R A General Electric Co 83/07/19, POTAPOVS,U Region
 4, Office of Director 1p 20799 105

--8310180530 Ack receipt of 830523 ltr informing NRC of steps taken to
 correct violation & nonconformance noted in QA Program Insp
 Rept 99900311/83-01
 POTAPOVS,U Region 4, Office of Director, 83/07/14,
 KANTHANN,R A General Electric Co 2pp 20799 106

--8310180532 Responds to NRC 830425 ltr re violation & nonconformance
 noted in QA Program Insp Rept 99900311/83-01 Corrective
 actions all customers notified of mod to meet requirements
 of ANSI Std C37.20-1974
 GREENE,R F General Electric Co 83/05/23, POTAPOVS,U Region
 4, Office of Director 6pp, 20799 108.

8310250005 Forwards QA Program Insp Rept 99900060/83-02 on 830822-26
 & notice of nonconformance Description of corrective actions
 requested within 30 days of ltr date
 POTAPOVS,U Region 4, Office of Director, 83/10/06 PATTARINI,D M
 Target Rock Corp, 2pp, 20895 259

--8310250006 Notice of nonconformance from insp on 830822-26,
 * Region 4, Office of Director, 83/10/06 2pp, 20895:261

--8310250008 QA Program Insp Rept 99900060/83-02 on 830822-26
 Noncompliance noted measures not established for selection &
 assessment of contractor (Q-TEK Corp) performing vendor
 audit svcs, per 10CFR50, App B
 KELLEY,W D , BARNES,I Region 4, Office of Director 83/10/04
 7pp 20895 263

8310250010 Ack receipt of 830916 ltr informing NRC of steps taken to
 correct deviation & nonconformance noted in QA Program Insp
 Rept 99900338/83-01
 POTAPOVS,U Region 4, Office of Director 83/10/20 BOLD,E R
 Siemens-Allis, Inc 1p 20894 179

--8310250011 Responds to NRC 830819 ltr re deviation & nonconformance
 noted in QA Program Insp Rept 99900338/83-01 Corrective
 actions engineering change order form revised to include
 area for indication of review for Part 21 reportability
 BOLD,E R Siemens-Allis, Inc 83/09/16 POTAPOVS,U Region 4,
 Office of Director 3pp 20894 180

8310250104 Confirms QA program insp at Santa Ana,CA plant on 831114-18,
 per 831012 telcon
 POTAPOVS,U Region 4, Office of Director 83/10/20 HESS,L R
 Pacific Air Products Co 1p 20896 247

8310250123 Forwards QA Program Insp Rept 99900277/83-01 on 830606-10
 notices of nonconformance & violation
 POTAPOVS,U Region 4, Office of Director 83/09/21 REED,E S
 Rockbestos Co 3pp 20899 276

--8310250127 Notice of violation from insp on 830606-10
 * Region 4, Office of Director 83/09/21 1p 20899 279

--8310250130 Notice of nonconformance from insp on 830606-10
 * Region 4, Office of Director 83/09/21 4pp 20899 280

--8310250136 QA Program Insp Rept 99900277/83-01 on 830606-10 Violation
 noted safety-related testing svcs procured from Isomedic, Inc
 w/o specifying in procurement documents that provisions of
 10CFR21 applied
 SMITH,A L , PHILLIPS,H S Region 4, Office of Director 83/09/06
 30pp 20899 284

8310250140 Ack receipt of 830919 ltr informing NRC of steps taken to
 correct nonconformance noted in QA Program Insp Rept
 99900787/83-01
 POTAPOVS,U Region 4, Office of Director 83/10/13 SANFORD,R S
 ALFAB, Inc 1p 20896 348

--8310250148 Responds to NRC 830825 ltr re nonconformance noted in QA
 Program Insp Rept 99900787/83-01 Corrective actions
 defective matl rept issued & dispositioned to scrap conduit
 seismic supports Rept approved by QA manager
 GRANTHAM,B ALFAB, Inc, 83/09/19 Region 4, Office of
 Director 7pp 20896 349

8310250199 Forwards QA Program Insp Rept 99900918/83-01 on 830613-16
 notice of nonconformance
 POTAPOVS,U Region 4, Office of Director 83/10/07 FARWELL,C R
 Farwell & Hendrix, Inc 2pp 20893 328

--8310250201 Notice of nonconformance from insp on 830613-16
 * Region 4, Office of Director 83/10/07 1p 20893 330

--8310250206 QA Program Insp Rept 99900918/83-01 on 830613-16
 Noncompliance noted, purchase orders did not contain suitable
 instructions that App B to 10CFR50 & 21 requirements imposed
 on suppliers providing safety-related equipment
 AGEER,J R , PHILLIPS,H S Region 4, Office of Director 83/09/26
 13pp 20893:331

8310250265 Forwards QA Program Insp Rept 99900500/83-01 on 830808-12
 notice of nonconformance
 POTAPOVS,U Region 4, Office of Director 83/10/06 REINSCH,H D
 Bechtel Corp, 3pp 20899 132

--8310250267 Notice of nonconformance from insp on 830808-12
 * Region 4, Office of Director 83/10/06 3pp 20899 155

--8310250270 QA Program Insp Rept 99900500/83-01 on 830808-12,
 Noncompliance noted Procurement Supplier Quality Forms
 PSQ-223s missing instructions re implementation of problem
 investigation request sys not provided
 BREAU,D O , HALE,C J Region 4, Office of Director 83/09/26
 26pp 20899:158

8310250272 Confirms QA program insp at Anaheim,CA plant on 831031-1104,
 per 831012 telcon,
 POTAPOVS,U Region 4, Office of Director 83/10/20, HADNAGY,P A
 Pacific Scientific 1p 20899 184

NONDOCKETED ITEMS

473

8310250357 Ack receipt of 830926 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900271/83-01
POTAPOVS,U Region 4, Office of Director 83/10/20 KOCH,W H
Rosemount, Inc 1p 20898 095

--8310250359 Rev H-1 to Procedure 66(1) "Change Order " Supporting documentation encl
HABIGER,A Rosemount, Inc 83/09/30 21pp 20898 096

8310250362 Ack receipt of 830616 & 0902 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 9900906/83-01
POTAPOVS,U Region 4, Office of Director 83/09/23 MOLNAR,J
American Environments Co , Inc 1p 20898 091

--8310250368 Responds to NRC 830901 telcon re nonconformance noted in QA Program Insp Rept 99900906/83-01 Original 830606 transmittal of vendor purchase order & receiving design & test control procedures forwarded w/o encl
VALERO,B American Environments Co , Inc 83/09/02 HUBBARD,G
Region 4, Office of Director 1p 20898 092

8310250377 Forwards QA Program Insp Rept 99900902/83-03 on 830709-12 No noncompliance noted
POTAPOVS,U Region 4, Office of Director 83/10/06 HOLBROOK,W H
Wyle Laboratories 2pp 20898 163

--8310250385 QA Program Insp Rept 99900902/83-03 on 830809-12 No noncompliance noted Major areas inspected evaluation of QA controls for engineering development, review & approval of seismic & dynamic qualification test plans & Repts
JOHNSON,A R , PHILLIPS,H S Region 4, Office of Director 83/09/28 10pp 20898 165

8310250395 Ack receipt of 830923 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900908/83-01
POTAPOVS,U Region 4, Office of Director 83/10/07 WELT,M A
Process Technology, Inc 1p 20897 282

--8310250397 Responds to NRC 830811 ltr re nonconformance noted in QA Program Insp Rept 99900908/83-01 Corrective actions QA manual revised to specify requirements of 10CFR50.App B
BUCKLEY,R Process Technology, Inc 83/09/23 POTAPOVS,U
Region 4, Office of Director 1p 20897 283

8310250405 Ack receipt of 830926 ltr informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 99900521/83-02
POTAPOVS,U Region 4, Office of Director 83/10/12 HINKLEMAN,L ,
Bechtel Corp 1p 20897 216

--8310250408 Responds to NRC 830826 ltr re Nonconformance D noted in QA Program Insp Rept 99900521/83-02 Corrective actions QA review underway Extension to 831226 to submit response to Nonconformance A requested
HINKLEMAN,L G Bechtel Corp 83/09/26 POTAPOVS,U Region 4, Office of Director 2pp 20897 217

8310250413 Ack receipt of 830415 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900914/83-01
POTAPOVS,U Region 4, Office of Director 83/10/12 ISON,W
National Technical Systems 1p 20897 238

--8310250420 Responds to NRC 830322 ltr re nonconformance noted in QA Program Insp Rept 99900914/83-01 Corrective actions purchase orders signed,manual revised & interim QA audit performed on 830728
DONGLOH,W P National Technical Systems 83/04/13 POTAPOVS,U
Region 4, Office of Director 1p 20897 239

8310250432 Forwards QA Program Insp Rept 99900926/83-01 on 830719-20 ' notices of violation & nonconformance
POTAPOVS,U Region 4, Office of Director 83/10/06 RANDALL,M W
Nuclear Qualification Services 3pp 20897 164

--8310250435 Notice of violation from insp on 830719-20
* Region 4, Office of Director 83/10/06 1p 20897 167

--8310250441 Notice of nonconformance from insp on 830719-20
* Region 4, Office of Director 83/10/06 2pp 20897 168

--8310250447 QA Program Insp Rept 99900926/83-01 on 830719-20 Noncompliance noted required procedures for Projects 1086, 1134 & 1027 not developed or adopted & failure to post documents re matl regulation & Energy Reorganization Act
HUBBARD,G T , PHILLIPS,H S Region 4, Office of Director 83/09/23 11pp 20897 170

8310250497 Confirms QA program insp at Oakland,CA facility on 831017-21,per 830920 telcon
POTAPOVS,U Region 4, Office of Director 83/10/14 BOYER,R E
Transamerica Delaval, Inc 1p 20897 068

8310250503 Ack receipt of 830525 & 0808 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900722/83-01
POTAPOVS,U Region 4, Office of Director 83/10/12 JOHNSON,I D
Robert Shaw Controls Co 1p 20902 080

--8310250510 Responds to NRC 830701 ltr re nonconformance noted in QA Program Insp Rept 99900722/83-01 Corrective actions spring & stem assemblies removed from stock,reworked to drawing configuration,inspected & replaced in stock
GIESLER,J V Robert Shaw Controls Co 83/08/08 POTAPOVS,U
Region 4, Office of Director 1p 20902 081

--8310250515 Ack receipt of 830525 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900722/83-01 Addl info re spring & stem assemblies, due in 25 days
POTAPOVS,U Region 4, Office of Director 83/07/01 JOHNSON,I D
Robert Shaw Controls Co 1p 20902 082

--8310250525 Responds to NRC ltr re nonconformance noted in QA Program Insp Rept 99900722/83-01 Corrective actions dept responsible for bulletin board instructed of importance of 10CFR21 posting requirement
GIESLER,J V Robert Shaw Controls Co 83/05/25 POTAPOVS,U
Division of Vendor & Technical Programs 2pp 20902 083

8310250511 Forwards QA Program Insp Rept 99900209/83-03 on 830822-26 & notice of nonconformance
POTAPOVS,U Region 4, Office of Director 83/10/06 NOREEN,H
Bergen-Paterson Pipe Support Corp 2pp 20901 033

--8310250518 Notice of nonconformance from insp on 830822-26
* Region 4, Office of Director 83/10/06 3pp 20901 035

--8310250524 QA Program Insp Rept 99900209/83-03 on 830822-26 Noncompliance noted mfg Operation & checkpoint on NDE/ Fabrication record for Lot 96735 clamps not signed off & dtd & Lot 97109 clamps crossed out & not signed off
OLLER,R E , DARNES,I Region 4, Office of Director 83/10/03 14pp 20901 038

8310250532 Confirms QA program insp at Norco,CA facility on 831031-1104,per 831017 telcon
POTAPOVS,U Region 4, Office of Director 83/10/19 SADLER,R C
Wyle Laboratories 1p 20902 058

8310250537 Forwards QA Program Insp Rept 99900920/83-01 on 830412-15 No noncompliance noted
POTAPOVS,U Region 4, Office of Director 83/06/13 ARND,D,H
Westinghouse Electric Corp 2pp 20901 260

--8310250541 QA Program Insp Rept 99900920/83-01 on 830412-15 No noncompliance noted Major areas inspected QA program product assurance manual & four supplemental procedures & compliance w/10CFR21 requirements
JOHNSON,A R , PHILLIPS,H S Region 4, Office of Director 83/06/07 17pp 20901 262

8310250592 Ack receipt of 830627 & 0906 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900818/83-01
POTAPOVS,U Region 4, Office of Director 83/10/12 RICHARDS,D H
Louis P Canuso, Inc 1p 20900 129

--8310250604 Suppl 830627 response to NRC 830803 ltr re nonconformance noted in QA Program Insp Rept 99900818/83-01 Corrective actions nuclear suppl integrated into purchase order procedures as of 821201
RICHARDS,D Louis P Canuso, Inc 83/09/06 POTAPOVS,U Region 4, Office of Director 4pp 20900 130

--8310250610 Ack receipt of 830627 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900818/83-01
POTAPOVS,U Region 4, Office of Director 83/08/03 RICHARDS,D H Louis P Canuso, Inc 2pp 20900 134

--8310250616 Responds to NRC 830602 ltr re nonconformance noted in QA Program Insp Rept 99900818/83-01 Corrective actions 10CFR21, Section 206 of Energy Reorganization Act of 1974 & Procedure 0 C 11 posted
RICHARDS,D Louis P Canuso, Inc 83/06/27 POTAPOVS,U Region 4, Office of Director 3pp 20900 136

NONDOCKETED ITEMS

REGOOD REGULATORY GUIDES

8310030414 Identifies specific Reg Guide 1 97 accident monitoring equipment sys for which extension requested, per 830520 & 0824 ltrs Schedules for upgrading equipment provided w/bases for extension request
CLAYTON, F L Alabama Power Co 83/09/27 VARGA, S A Office of Nuclear Reactor Regulation, Director 22pp 20593 087 24X
Fiche 50-348, 83/09/27, 8310030414

8310040287 Forwards Rev 2 to 830414 response to Suppl 1 to NUREG-0737 including rept on review of Reg Guide 1 97
TUCKER, H B Duke Power Co 83/09/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 91pp 20614 077 24X
Fiche 50-413, 83/09/26, 8310040287

8310070291 Forwards "Position Paper on Reg Guide 1 97" & "Response to NUREG-0737, Suppl 1 & Reg Guide 1 97 Application to Emergency Response Facilities."
ZIMMERMAN, S R Carolina Power & Light Co LAP-83-408 83/09/30 VASSALLO, D B Operating Reactors Branch 2 1p 20655 177 24X
Fiche 50-324, 83/09/30, 8310070291

-8310070293 "Position Paper on Reg Guide 1 97"
BRODWIN, W E Carolina Power & Light Co 83/08/09 33pp 20655 178 24X Fiche 50-324, 83/09/30, 8310070291

-8310070295 "Response to NUREG-0737, Suppl 1 & Reg Guide 1 97 Application to Emergency Response Facilities."
BRODWIN, W E Carolina Power & Light Co 83/08/09 77pp 20655 211 24X Fiche 50-324, 83/09/30, 8310070291

8310070420 Reg Guide 1 85, Rev 21, "Halls Code Case Acceptability, ASME Section III Div 1"
* Office of Nuclear Regulatory Research, Director 83/09/30 11p 20674 332

8310120175 Forwards revised Section 3 13 to FSAR Rev references until previously submitted position on Reg Guide 1 97 Rev will be incorporated in next FSAR amend
CURTIS, N W Pennsylvania Power & Light Co PLA-1822 83/09/30 SCHWENGER, A Licensing Branch 2 2pp 20695 290 24X
Fiche 50-388, 83/09/30, 8310120175

8310120349 Advises that due to uncertainty in instrumentation availability & manpower resources, instrumentation necessary to meet Reg Guide 1 97 requirements will be implemented by third refueling outage per Suppl 1 to NUREG-0737
JALEL, F Mississippi Power & Light Co AECM-83/0652 83/10/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20700 231 24X Fiche 50-416, 83/10/10, 8310120349

831014068 Requests comments, refs & info to clarify Rev 2 to Reg Guide 3 & Rev 1 to Reg Guide 1 145 (Tasks SD 806-B & SS 724-4)
RUONON, L Canada, Atomic Energy Control Board 83/10/03 Locking & Services Branch 1p 20802 030

8310190343 Provides matrix showing applicability of QA program manual 0 Reg Guide 7 10 for shipment of reactor pressure vessel surveillance capsules, per 830920 telcon
ORRIS, E B MABRITO, B Southwest Research Institute 22875 3/09/21 GORDON, L Transportation Branch 3pp 20842 303

8310240244 Agenda for CRGR Meeting 4B on 831020 in Bethesda, MD to discuss proposed exemption from CRGR review on proposed rulemaking re codes & stds, proposed Rev 2 to Reg Guide 1 105 & proposed plant operating staff degree requirements
STELLO, V Committee to Review Generic Requirements 83/10/14 MATSON, R J Office of Nuclear Reactor Regulation, Director JORDAN, E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 2pp 20907 284

8310250557 Comments on revs to proposed Reg Guide 1 82, Rev 1, per 830906 request Reg guide should be revised to prevent further requirements on designs which preclude air ingestion into, or blocking of suction lines used in DHR
IRK, J F General Electric Co MFN-192-83 83/10/17 SPEIS, T P Division of Safety Technology 2pp 20900 314

8310260348 Forwards application to amend License SUA-551, reflecting current conditions or practices or to correlate w/monitoring frequency per Reg Guides 8 30 & 8 31
AFF, B J Getty/Petrochemicals Co 00633 83/09/27 OARCIA, P Anium Recovery Field Office 1p 20928 083

8310260352 Application for amend to License SUA-551, reflecting current conditions or practices or to correlate w/monitoring frequency per Reg Guides 8 30 & 8 31
* Getty/Petrochemicals Co 00633 83/09/22 11pp 20928 084

RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS

8310050145 "Accident Aerosol Characterization," Aug 1983 monthly progress rept
QMCZARSKI, P C Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2287 83/09/20 BERNSTEIN, S Division of Risk Analysis 9pp 20650 228

8310050329 "Definition of Scenarios & Evaluation of Methods for Analyzing Source Terms of Major Accidents Involving U Hexafluoride at NRC Licensed Fuel Cycle Facilities," monthly progress rept for Aug 1983
SIMAN-TOV, M Union Carbide Corp FIN B-0495 83/09/16 BERNSTEIN, S Transportation & Materials Risk Branch 3pp 20650 225

8310070216 "Resolution of Generic Issue C-8, 'MSIV Leakage & Leak Control Sys Failure, Task 2 Base Case Benchmark Calculation,'" 1tr rept
MURPHY, D W, ESSIG, T H Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2529 83/09/23 RINGELY, J Office of Nuclear Reactor Regulation, Director 8pp 20679 345

8310200344 "Investigation of Ventilation Component Response to Large Pressure Pulses," monthly progress rept for Aug 1983
GREGORY, W S Los Alamos Scientific Laboratory FIN A-7028 83/10/03 SOLBERG, D Transportation & Materials Risk Branch 6pp 20874 063

8310280131 Quarterly rept for Jul-Sept 1983 for Contract NRC-04-B1-195-02 re integrated geological/geophysical study of northern extensions of New Madrid fault zone
BRAILE, L W HINZE, W J Purdue Univ, West Lafayette, IN KELLER, G R Texas, Univ of, El Paso TX NRC-04-B1-195-02 83/10/01 Office of Nuclear Regulatory Research, Director 13pp 20965 089

REVIEW GRP NRC RESEARCH REVIEW GROUPS

8310070363 Responds to 830628 1tr re Inside NRC article reporting J Tourtellotte remarks on backfitting Reassignment of J Tourtellotte due to strong views for reform not acceptable
PALLADINO, N J Commissioners 83/09/13 WEISS, E R Union of Concerned Scientists 1p 20664 307

-8310070369 Informs that 830516 request for reassignment of JR Tourtellotte mistakenly not sent to Commissioners
Tourtellotte alleged behavior at conference clarified JR Tourtellotte 830614 response encl
WEISS, E R Union of Concerned Scientists 83/06/28 PALLADINO, N, OILINSKY, V, AHEARNE, J Commissioners 2pp 20664 308

8310240244 Agenda for CRGR Meeting 4B on 831020 in Bethesda, MD to discuss proposed exemption from CRGR review on proposed rulemaking re codes & stds, proposed Rev 2 to Reg Guide 1 105 & proposed plant operating staff degree requirements
STELLO, V Committee to Review Generic Requirements 83/10/14 MATSON, R J Office of Nuclear Reactor Regulation, Director JORDAN, E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 2pp 20907 284

8310270436 Designates JH Sniezel as CRGR chairman & member alternative in author absence
STELLO, V Regional Operations & Generic Requirements 83/10/24 MATSON, R Office of Nuclear Reactor Regulation, Director JORDAN, E Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R Office of Nuclear Material Safety & Safeguards, Director 2pp 20923 049

SECY POSITION PAPERS BEFORE THE COMMISSION

8308190179 SECY-83-311
Requests approval of encl rulemaking actions re revised requirements for safeguarding power reactors
DIRCKS, W J Office of the Executive Director for Operations 83/07/29 232pp 20716 123

8309080114 SECY-83-343
Requests Commission approval of publication of final rule implementing legislation authorizing issuance of temporary QLS
DIRCKS, W J Office of the Executive Director for Operations 83/08/17 110pp 20716 001

NONDOCKETED ITEMS

8310110007 Responds to FOIA request for SECY-82-279, SECY-82-330 & SECY-83-120 Forwards documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/07/15 PEDRO, J NUS Corp 1p 20712 280

--8310110017 SECY-82-279
Provides info paper on current status of nuclear plant reliability data sys
DIRCKS, W J Office of the Executive Director for Operations 82/07/01 26pp 20712 281

--8208270562 SECY-82-330
Recommends approval of mods to NRC personnel security clearance program to sharply reduce investigative costs w/o lessening operational effectiveness
DIRCKS, W J Office of the Executive Director for Operations 82/08/03 12pp 20712 307

--8310110022 SECY-83-120
Recommends issuance of encl proposed order directing ASLD to resume hearings as soon as possible on issue not involving informant identities
PLAINE, H H Office of the General Counsel 83/04/01 4pp 20712 319

8310110436 Responds to FOIA request for RFP RS-DRM-83-500 & SECY-83-157 RS-DRM-83-500 placed in PDR SECY-83-157 partially withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/07/20 GRABER, L NUS Corp 2pp 20706 308 24X Fiche 50-322, 83/07/20, 8310110436

--8310110439 SECY-83-157
Requests approval of proposed order re low power license for facility
PLAINE, H H Office of the General Counsel 83/05/02 4pp 20706 310 24X Fiche 50-322, 83/07/20, 8310110436

8310120025 SECY-83-311A
Recommends Commission approve amends to proposed insider safeguards rules as set forth in Encls A, B & C of SECY-83-311 for publication in FR
DIRCKS, W J Office of the Executive Director for Operations 83/07/15 131pp 20749 214

8310190049 Responds to FOIA request Forwards documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/07/13 BUCKLES, R NUS Corp 1p 20838 273

--8310190053 SECY-83-183
Informs of first integrated schedule amend for implementing new & existing requirements at operating plants Action represents first step towards developing industry-wide approach for establishing realistic schedules
DIRCKS, W J Office of the Executive Director for Operations 83/05/13 23pp 20838 274

--8307220196 SECY-83-269
Provides rept on fire protection rule for future plants (SECY-82-267), summarizing licensee fire protection exemption requests, disposition of requests & generic issues raised by requests
DIRCKS, W J Office of the Executive Director for Operations 83/07/05 52pp 20838 297

8310240263 Final response to FOIA request for three categories of records re interim storage of spent nuclear fuel at commercial power plants Forwards documents listed in app Documents also available in PDR
FELTON, J M Division of Rules and Records 83/07/11 DELL, N Coalition for Safe Power 2pp 20891 142

--8304030526 SECY-83-112
Requests approval to publish for public comment proposed new 10CFR53 establishing procedures & criteria enabling NRC to determine whether adequate spent fuel storage capacity cannot reasonably be provided at individual reactor site
DIRCKS, W J Office of the Executive Director for Operations 83/03/23 50pp 20891 175

831025002B Responds to FOIA request for SECY-83-030, "TMI-Related Requirements at Operating Reactors," be placed in PDR Forwards requested document Document also available in PDR
FELTON, J M Division of Rules and Records 83/07/15 BUCKLES, R NUS Corp 1p 20916 178,

--8310250030 SECY-83-030
Advises of NRR plan to take licensing action on TMI action plan requirements specified in NUREG-0737 scheduled for implementation after B10630
DIRCKS, W J Office of the Executive Director for Operations 83/01/21 31pp 20916 179

8310270281 Further response to FOIA request for matl re enactment of Section 13(c) of Public Law 97-415 requiring NRC to undertake pilot program to study two plants where const. OA & QC deficiencies identified Forwards SECY-83-032A
FELTON, J M Division of Rules and Records 83/07/18 HAMLIN, J B Shaw, Pittman, Potts & Trowbridge 1p 20943 071

--8310270286 SECY-83-032A
Requests info rept on status of implementation of OA initiatives identified in SECY-82-352
DIRCKS, W J Office of the Executive Director for Operations 83/04/21 16pp 20943 072

8310270360 Responds to FOIA request for SECY-82-242 & SECY-83-317 Forwards SECY-82-242 SECY-83-317 withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/09/29 PEDRO, J. NUS Corp 2pp 20943 296

--820624009B SECY-82-242
Requests Commission approval re mod of NRC regulations involving requirements for fracture toughness of RCPD, including surveillance of neutron radiation embrittlement of reactor vessel beltline matl
DIRCKS, W J Office of the Executive Director for Operations 82/06/14 39pp 20943 298

8310270369 Responds to FOIA request for SECY-83-278 & SECY-83-270, transmitting B30624 "Rept on Adequacy & Safety of Relief Valve Testing & Performance" Forwards requested documents
FELTON, J M Division of Rules and Records 83/10/04 WEISS, E R Union of Concerned Scientists 1p 20943 129

--8307270430 SECY-83-278
Forwards revised certification & noncertification status tables per B30622 request Table 1 revised to clarify insp status of certification items for which insp previously noted as not applicable
DIRCKS, W J Office of the Executive Director for Operations 83/07/11 43pp 20943 130 24X Fiche 50-289, 83/10/04, 8310270369

--8307220250 SECY-83-270
Provides summary of primary sys relief & safety valve testing & performance since TMI-2 accident per NUREG-0737, Item II D 1
DIRCKS, W J Office of the Executive Director for Operations 83/07/05 122pp 20943 173

8310310097 Responds to FOIA request that 16 SECYs be placed in PDR Forwards App A documents SECY-82-466 withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/09/19, SHOLLY, S. C. Union of Concerned Scientists 3pp 21000 146

--8203120050 SECY-82-077
Informs Commission of NRC progress in developing criteria & strategies re use of potassium iodide (KI) to block thyroid gland in event of accidental release of radiiodine Validity of distribution of KI to general public questioned
DIRCKS, W J Office of the Executive Director for Operations 82/02/19 11pp 21000 256

--8204070171 SECY-82-121
Advises of current status of studies assessing potential technical, regulatory & socioeconomic impacts of proposed alternatives for accident water disposition
* Office of the Executive Director for Operations 82/03/18 13pp 21000 147 24X Fiche 50-320, 83/09/19, 8310310097

--8304220088 SECY-83-126
Requests approval for publication of proposed rule ensuring that certain contractors & subcontractors of 10CFR50 licensees post NRC Form 3
DIRCKS, W J Office of the Executive Director for Operations 83/04/06 4pp 21000 162

--8310310116 SECY-82-141A
Informs of historical & current rates of license issuance & exam failures for reactor & senior reactor operators Supporting data encl Failure rates of 27% & 25% for reactor operator & senior reactor operator, respectively noted
DIRCKS, W J Office of the Executive Director for Operations 83/08/23 3pp 21000 166

NONDOCKETED ITEMS

--8205050588 SECY-82-168

Inform of revision of 10CFR20, stds for protection against radiation, & efforts to ascertain adverse technical & economic impacts on NRC & licensee of revised regulation
Comparison of 10CFR20 salient issues w/alternatives encl
DIRCKS, W J Office of the Executive Director for Operations
82/04/21 8pp 21000 169

--8206100323 SECY-82-221

Forwards study re NRC role in contested nuclear power reactor initial licensing proceedings Study concludes that different "neutral" NRC role should be adopted on trial basis in selected cases
BICKWIT, L Office of the General Counsel 82/06/03 68pp
21000 177

--8206300342 SECY-82-243

Informs Commission of status of NRC activities re development of improved safeguards info sys
DIRCKS, W J Office of the Executive Director for Operations
82/06/10 3pp 21000 245

--8206250316 SECY-82-251

Provides Commission w/rept re property insurance for decontamination of nuclear reactors as published in NUREG-0891
DIRCKS, W J Office of the Executive Director for Operations
82/06/16 4pp 21000 248

--8211290108 SECY-82-460

Informs Commission of historical & current rates of license issuance & exam failures for reactor operators & senior reactor operators
DIRCKS, W J Office of the Executive Director for Operations
82/11/17 4pp 21000 252

--8310310131 SECY-82-483

Inform of present status of TMI-1 restart certification effort & provides update on NUREG-0737 items status
DIRCKS, W J Office of the Executive Director for Operations
82/12/09 16pp 21000 260 24X Fiche 50-289, 83/09/19, 831031009

--8302160056 SECY-83-044

Submits alternatives for scope of guidelines for post-accident recovery in event of nuclear-related accidents Recommends deferment of plan development until completion of severe accident & source term research
DIRCKS, W J Office of the Executive Director for Operations
83/01/31 16pp 21000 276

--8310310136 SECY-83-072

Inform of historical & current rates of license issuance & exam failures for reactor operators & senior reactor operator Pass/fail rate remained consistent throughout Third Quarter FY82
DIRCKS, W J Office of the Executive Director for Operations
83/02/18 4pp 21000 292

--8310310140 SECY-83-093

Transmits INPO "Performance Objectives & Criteria for Corporate Evaluations" & informs of plans to defer further action on TMI Action Plan Item I B 1.1 W/o encl
DIRCKS, W J Office of the Executive Director for Operations
83/03/09 3pp 21000 296

STATE PROG STATE PROGRAMS

8310070271 Forwards responses to 830726 ltr requesting addl info to amplify 830225 technical observation re state radiation control program & personnel staffing
BOLON, L R New York, State of 83/09/14 ALLAN, J M Region 1, Office of Director 3pp. 20656-357

8310070320 NUREG/CR-3487

REGIONAL-INTERSTATE SITE REVIEW PROCEDURE LOW-LEVEL RADIOACTIVE WASTE DISPOSAL FACILITY
• Southern States Energy Board FIN B-50206 83/09/30, Division of Health, Siting & Waste Management 123pp Available at NRC
95 00. 20679-113

8310110612 Requests appointment of state liaison officer to NRC

Appointee will be invited to natl/state liaison officer
831206-07 meetings in Washington, DC
PALLADINO, N J Commissioners 83/09/22 HUNT, J B North Carolina, State of 1p 20703 359

--8310110615 Notification of natl state liaison officer 831206-07

meetings in Washington, DC Agenda encl
KERR, O W Office of State Programs, Director 83/09/16 Office of State Programs, Director 3pp 20703 360

8310130380 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements" Contractor State of NY
UMBEL, D M Technical Assistance Contracts Branch FIN B-8359
NRC-28-B3-610 83/09/29 MCSGAR, J Region 1, Office of Director
COSTELLO, F NRC - No Detailed Affiliation Given 1p 20770 118

--8310130385 Mod 1, adding funds to incorporate TLD program, to "Radiation

Monitoring Program Requirements"
LEAVY, W F New York, State of GUSTAVE, R P Technical Assistance
Contracts Branch FIN B-8355 NRC-28-B3-610 83/09/29 1p
20770 119

8310170704 Requests new state liaison officer to NRC be appointed Natl.

state liaison meeting will be held on 831206-07 in Washington, DC
PALLADINO, N J Commissioners 83/09/29 ROCKEFELLER, J West Virginia, State of 1p 20798 190

8310200179 Forwards NRC evaluation of NY State Dept of Environ

Conservation radiation control program for period 820303-830310
MURLEY, T E Region 1, Office of Director 83/09/06 MERGES, P New York, State of 1p 20835 079

--8310200181 Rept of NRC evaluation of NY State Dept of Environ

Conservation radiation control program for period 820303-830510
MURLEY, T E Region 1, Office of Director 83/06/28 50pp
20835 080

8310250116 Ack receipt of 830914 response to comments & recommendations

Following review of radiation control program Training & technical assistance plan details for NY Dept of Environ Conservation radiation control program encl
MURLEY, T E Region 1, Office of Director 83/10/19 WILLIAMS, H O New York, State of 5pp 20894 065

--8310250119 Discusses NRC 830628 evaluation of radiation control

program Problems associated w/program being evaluated under agreement state program options Accepts 830628 offer to provide dept w/technical assistance
WILLIAMS, H O New York, State of 83/09/14 MURLEY, T E Region 1, Office of Director 2pp 20894 070

8310260318 Responds to questions in 830930 ltr re NRC regulatory

program for U milling Applicable manual chapters encl
NUSSBAUMER, D A Assistant Director for State Agreements Programs
83/10/11 SPAIN, M Virginia, Commonwealth of, 31pp 20910 301

8310280103 Forwards 830913 ltr from State of NV, responding to NRC

830822 ltr on RADMAN code
NUSSBAUMER, D A Assistant Director for State Agreements Programs
83/09/21 HIGGINSBOTHAM, L Low Level Waste Licensing Branch 2pp
20961 358

--8310280107 Responds to NRC 830822 ltr re RADMAN computer code No

objections raised to use of code by persons licensed to dispose of radwaste at Beatty site
VADEN, J Nevada, State of 83/09/13 NUSSBAUMER, D A Assistant Director for State Agreements Programs 1p 20961 359

8310310271 Forwards technical comments & recommendations on NH Dept of

Welfare radiological health program, per 830829-0902 review & evaluation Prioritization of steps under consideration to improve program recommended
MURLEY, T E Region 1, Office of Director 83/10/24 WALLACE, W T New Hampshire, State of 8pp 20947 127

TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

8310030203 Forwards "Rept of Engineering Assessment, Present Pond Line"

Sys Tailings Impoundment, Sweetwater U Project, Near Rawlins, WY for Minerals Exploration Co" & "Tailings Impoundment Leak Analysis"
KLEIN, T J Union 76 Minerals Exploration Co 00585 83/09/07
SMITH, R D Uranium Recovery Field Office 2pp 20603 078

--8310030210 "Rept of Engineering Assessment, Present Pond Liner Sys

Tailings Impoundment, Sweetwater U Project Near Rawlins, WY for Minerals Exploration Co"
BODDY, J R Union 76 Minerals Exploration Co 00585 83/07/29
19pp 20603 080

8310030303 Forwards Rev 1 to BAW-1762, "Auxiliary Feedwater Sys

Reliability Study for WPPSS Unit 1," in response to NUREG-0737, Item II E 1.1
BORGENSEN, O C Washington Public Power Supply System 0L-82-14,
83/09/23 ADENBAUM, E O Licensing Branch 4 1p 20593:181 24X
Fiche 50-460, 83/09/23, 8310030303

NONDOCKETED ITEMS

477

0030306 BAW-1762 R01
ev 1 to "Auxiliary Feedwater Sys Reliability Study of WPPSS
Unit 1"
Babcock & Wilcox Co GL-82-14 83/06/30 41pp 20593 183
4X Fiche 50-460,83/09/23,8310030303

30353 Forwards B&W Owners Group final rept, "Bounding Analytical
Assessment of NUREG-0630 Models on LOCA kW/Ft Limits W/Use
FLECSET " Approval requested
SHALL, J R Arkansas Power & Light Co 1CAN098310 83/09/23
LZ, J F Operating Reactors Branch 4 1p 20592 200 24X
he 50-313,83/09/23 8310030353

0030356 77-1140898-01
Bounding Analytical Assessment of NUREG-0630 Models on
LOCA kW/Ft Limits W/Use of FLECSET "
Babcock & Wilcox Operating Plants Owners Group 83/09/30
08pp 20592 201 24X Fiche 50-313,83/09/23,8310030353

30620 Advises that encl B&W rept, "Response to GPU Nuclear
stations Concerning HPI Actuation at TH1-2 About 5 41 AM
790328," completed assessment of EDS Nuclear analysis
t provided to util on 830909 & to NRC on 830915
JKB, W J Office of the Executive Director for Operations
39/26 PALLADINO, N Commissioners 3pp 20626 351 24X
ie 50-289,83/09/26,8310030620

30650 Forwards info requested at 830824 presentation re
formance of teams using crack-tip diffraction method More
will be available at intergranular stress corrosion
king 830907-09 workshop
G J Electric Power Research Institute 83/09/07
ADIND, N J Commissioners 4pp 20607 356

10026 Affidavit supporting withholding of Mark 1 Containment
ram document, "Response Factors Appropriate for Use W/CO
onic Response Combination Design Rules "
WDDO, D O General Electric Co 83/07/29 3pp 20608 119 24X
ie 50-219,83/07/29,8310040026

0301 Forwards B&W "Bounding Analytical Assessment of NUREG-0630
is on LOCA kW/Ft Limits W/Use of FLECSET," completing
onse to NUREG-0630 Compensating models documented &
ification for model use provided
AFER, G R Florida Power Corp 3F-0983-20 83/09/29
Z, J F Operating Reactors Branch 4 2pp 20612 227 24X
e 50-302,83/09/29,8310040301

040304 77-1140898-01
ounding Analytical Assessment of NUREG-0630 Models on LOCA
/Ft Limits W/Use of FLECSET "
Babcock & Wilcox Co 83/09/30 109pp 20612 229 24X
che 50-302,83/09/29,8310040301

0353 Forwards "Pressurizer Relief Valve Qualification," & Rev 1
Pressurizer Safety Valve Operability Rept," per
0-0737, Item II D.1 Design load stresses on piping &
ings within allowable limits
VALL, A E Baltimore Gas & Electric Co 83/09/28 MILLER, J R
ating Reactors Branch 3 4pp 20615 036 24X
e 50-317,83/09/28,8310040353

040355 "Pressurizer Relief Valve Discharge Piping Qualification
pt on Task 0308B
ITH, J V, VENTURA, J C Bechtel Corp 83/09/23 134pp
515 040 24X Fiche 50-317,83/09/28,8310040353

340357 GEN-24B(R) R01
/ 1 to "Pressurizer Safety Valve Operability Rept "
Combustion Engineering, Inc 83/09/30 100pp 20615 194 24X
che 50-317,83/09/28,8310040353

3363 Forwards response to NRC 830601 SER re Westinghouse Owners
emergency response guidelines per Suppl 1 to
3-0737
ARD, J J Westinghouse Operating Plants Owners Group
ARD, J J Carolina Power & Light Co 00-105 83/09/27
HUT, D G Division of Licensing 42pp 20620 235

3415 Forwards "Implementation of NUREG-0619 Feedwater Nozzle
ing," & proprietary "Peach Bottom Atomic Power Station,
2, Feedwater Nozzle Fracture Mechanics Analysis to Show
Proprietary rept withheld (ref 10CFR2 790)
GHER, J W Philadelphia Electric Co 83/09/29 EISENHUT, D G
ion of Licensing 2pp 20623 303 24X Fiche 50-277,83/09/29
140415

1185 Forwards proprietary rev to NEDE-24011-P-A-6, "OE Std
cation for Reactor Fuel," documenting expanded approach
ability Affidavit encl Rev withheld (ref 10CFR2 790)
ILEY, J S General Electric Co MFN-183-83 83/09/30
B, C O Standardization & Special Projects Branch 6pp
1342

8310070197 Forwards proprietary "Westinghouse Pretendering Module 8
Integrated Control & Protection Sys " Rept withheld
(ref 10CFR2 790)
RAHE, E P Westinghouse Electric Corp NS-EPR-2818 83/09/23
EISENHUT, D G Division of Licensing 2pp 20628 348

--8310050212 Requests proprietary classification per 10CFR2 790 for encl
rept, "Westinghouse Pretender Module 8 Integrated Control &
Protection Sys "
WIESEMANN, R A Westinghouse Electric Corp AW-83-71 83/09/23
EISENHUT, D G Division of Licensing 1p 20628 350

8310050346 Forwards "RODEX2 Temp Prediction Conservatism," in response
to NRC request for addl info withheld (ref 10CFR2 790)
COPELAND, R A Exxon Nuclear Co, Inc (subs of Exxon Corp)
RAC 066 83 83/10/03 THOMAS, C O Standardization & Special
Projects Branch 1p 20632 343

8310050400 Forwards requested info for use in determining fee to be
assessed for review of XN-NF-78-44(NP), "Generic Analysis
of Control Rod Ejection Transient for PWR "
THOMAS, C O Standardization & Special Projects Branch 83/09/21
BERKOW, H N Management Analysis Branch 2pp 20640 359

8310050463 Forwards application to amend License DPR-20, modifying basis
for limiting safety sys settings for reactor protection sys
VANDEHALLE, D J Consumers Power Co 83/09/29 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 20630 055 24X
Fiche 50-255,83/09/29,8310050463

--8310050470 XN-NF-83-37
"Rod Withdrawal Transient Reanalysis for Palisades Reactor "
FRYER, B C, CHANDLER, J C, KAYSER, W V Exxon Nuclear Co, Inc
(subs of Exxon Corp) 83/08/26 57pp 20630 064 24X
Fiche 50-255,83/09/29,8310050463

8310060267 Forwards proprietary "Westinghouse Advanced PWR
Pretendering Module 9 - Component Cooling Sys,"
supplementing B21101 submittal Rept withheld (ref
10CFR2 790)
RAHE, E P Westinghouse Electric Corp NS-EPR-2829 83/09/30
EISENHUT, D G Office of Nuclear Reactor Regulation, Director 2pp
20646 151

--8310060270 Requests "Westinghouse Advanced PWR Pretendering Module 9 -
Component Cooling Sys," be withheld per 10CFR2 790
WIESEMANN, R A Westinghouse Electric Corp AW-83-79 83/09/30
EISENHUT, D G Office of Nuclear Reactor Regulation, Director 1p
20646 153

8310070104 Forwards evaluation accepting XN-NF-78-44 (NP) "Generic
Analysis of Control Rod Ejection Transient for PWR," for
referencing in license applications Requests nonproprietary
version within 3 months of receipt of ltr
THOMAS, C O Standardization & Special Projects Branch 83/09/21
CHANDLER, J C Exxon Nuclear Co, Inc (subs of Exxon Corp) 1p
20681 001

--8310070112 Evaluation accepting XN-NF-78-44 (NP) "Generic Analysis of
Control Rod Ejection Transient for PWR," for referencing in
license applications
* NRC - No Detailed Affiliation Given 83/09/21 6pp
20681 002

8310070174 Notification of 831004 meeting w/Westinghouse in Bethesda, MD
to discuss WCAP-10263 (NP) "Review Plan for Upgrading
Licensed Power of Advanced PWR Power Plant "
MORAN, D H Standardization & Special Projects Branch 83/09/26
THOMAS, C O Standardization & Special Projects Branch 1p
20680 291

8310070264 Forwards proprietary XN-NF-691 (P), "Stability Evaluation of
BWR Cores " Rept withheld (ref 10CFR2 790)
CHANDLER, J C Exxon Nuclear Co, Inc (subs of Exxon Corp)
83/09/30 THOMAS, C O Standardization & Special Projects Branch
1p 20694 329

8310070264 Forwards proprietary "Dresden 2/3 Nuclear Generating Plant
Suppression Pool Temp Response," "EI Hatch Nuclear Power
Station Units 1 & 2 Suppression Pool Temp Response" & Mark
1 830825 meeting viewgraphs Repts withheld (ref 10CFR2 790)
PFEFFERLEN, H C General Electric Co MFN-180-83 83/09/30
VASSALLO, D B Operating Reactors Branch 2 61pp 20811 292 24X
Fiche 50-000,83/09/30,8310070264

8310070281 Forwards proprietary "Compliance of OE BWR Fuel Designs to
Stability Licensing Criteria Response to Stability Action
item From NRC re Single Loop Operation " W/affidavit Rept
withheld
PFEFFERLEN, H C General Electric Co MFN-181-83 83/09/30
THOMAS, C O Standardization & Special Projects Branch 5pp
20697 065

NONDOCKETED ITEMS

8310070310 Forwards proprietary "Compliance of GE BWR Fuel Designs to Stability Licensing Criteria-Stability ." supporting amend to GE Ltr NEDE-24011 Affidavit encl Rept withheld
PFEFFERLEN, M C General Electric Co MFN-182-83 83/09/30
THOMAS, C D Standardization & Special Projects Branch 3pp
20652 219

8310070344 Ack receipt of 830809 ltr transmitting rept of retrofit plan for Beinau Nuclear Plant Rept should be treated as commercial privileged info & encl W/o encl
KRIEGER, R W Southern California Edison Co 83/09/28
CRUTCHFIELD, D Operating Reactors Branch 3 1p 20651 099

8310070359 Discusses progress of life testing at Wyle Labs for boiling water version of actuator referenced in Rept G&W-FSD 232B, expected in Oct 1983 Test exceeded full vibration loading expected in 40-yr plant life before mechanical failure
WEISZ, D A Gulf & Western Industries, Inc FDS 83-233 83/09/28
THOMAS, C D Standardization & Special Projects Branch 2pp
20651 093

8310110142 Forwards proprietary Westinghouse responses to NRC Request 1 for addl info on WCAP-10271, "Evaluation of Surveillance Frequencies " & proprietary Suppl 1 to "Evaluation of Surveillance " Encl withheld (ref 10CFR2 790)
SHEPPARD, J J Westinghouse Operating Plants Owners Group
SHEPPARD, J J Carolina Power & Light Co 00-106 83/10/04
THOMAS, C D Standardization & Special Projects Branch 2pp
20669 076

--8310110149 Authorizes use of Affidavit CAW-83-67 re withholding of proprietary responses to NRC Request 1 for addl info on 830728 WCAP-10271 & Suppl 1 to "Evaluation of Surveillance Frequencies & Out of Svc Times for Reactor Protection "
WIESEMANN, R A Westinghouse Electric Corp CAW-83-67 83/09/13
THOMAS, C D Standardization & Special Projects Branch 1p
20669 078

8310110503 Responds to FOIA request for BWR Owners Group control room survey program Requested info placed in LPDR
FELTON, J M Division of Rules and Records 83/07/08 WILLIAMS, O G
Affiliation Unknown 1p 20708 002

--8310110511 "BWR Owners Group Control Room Improvements Committee Human Factors Engineering Control Room Survey "
FANKRATZ, D R, ROSS, K C, MULLEE, G R BWR Owners Group 81/01/14
88pp 20708 009

--8310110513 "BWR Owners Group Control Room Design Review Program, Development & Methodology "
* General Electric Co 81/08/01 26pp 20708 096

-8310110518 "BWR Owners Group Control Room Survey Workshop, Human Factors Engineering," w/suppls & vignettes
* BWR Owners Group 83/08/01 310pp 20708 121

8310120312 Forwards technical rept "Mark I Containment Program Plant-Unique Analysis Rept of Torus Attached Piping for Vermont Yankee Nuclear Power Plant "
SINGLAIR, J B Vermont Yankee Nuclear Power Corp FVY 83-108
83/10/06 VASSALLO, D B Operating Reactors Branch 2 1p
20697 255 24X Fiche 50-271, 83/10/06, 8310120312

--8310120315 TR-5319-2
"Mark I Containment Program Plant-Unique Analysis Rept of Torus Attached Piping for Vermont Yankee Nuclear Power Plant "
* Teledyne Engineering Services 83/10/03 95pp 20697 256
24X Fiche 50-271, 83/10/06, 8310120312

8310120324 Advises that Ray Miller, Inc Purchase Orders 63023 & 51810 were for items used at Mt Storm Fossil Power Station & util was end user items were not sold to any other company or individual
BROWN, C A Virginia Electric & Power Co 83/10/03 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 4pp
20700 316

8310120407 Forwards nonproprietary rept & Suppl 1 to "HB Robinson Unit 2, Cycle 10 SAR " Also forwards proprietary "ECCS & Plant Transient Analyses " & "Mechanical Design Rept " Repts withheld (ref 10CFR2 790)
UTLEY, E E Carolina Power & Light Co LAP-83-446 83/10/05
VARQA, B A Operating Reactors Branch 1 14pp 20697 176 24X
Fiche 50-261, 83/10/05, 8310120407.

--8310120415 XN-NF-83-72
Nonproprietary "HB Robinson Unit 2, Cycle 10 SAR "
STONE, I Z, ADAMS, F T, LAMBERT, W L Exxon Nuclear Co, Inc (subs of Exxon Corp) 83/09/01 39pp 20697 188 24X
Fiche 50-261, 83/10/05, 8310120407

--8310120422 XN-NF-83-72 501
Nonproprietary Suppl 1 to "HB Robinson Unit 2, Cycle 10 SAR "
STONE, I Z, ADAMS, F T, LAMBERT, W L Exxon Nuclear Co, Inc (subs of Exxon Corp) 83/09/14 28pp 20697 227 24X
Fiche 50-261, 83/10/05, 8310120407

8310130097 Forwards nonproprietary & proprietary responses to 830802 telcon request for addl info re proposed Tech Spec change concerning in-core detectors Affidavit encl Proprietary rept withheld (ref 10CFR2 790)
ORIFFIN, J M Arkansas Power & Light Co 2CAN098311 83/09/30
MILLER, J R Operating Reactors Branch 3 10pp 20725 277 24X
Fiche 50-368, 83/09/30, 8310130097

--8310130109 CEN-255(A)-NP
Nonproprietary "Responses to NRC Questions re Arkansas Nuclear Unit 2 Cycle 3 Tech Spec Change " Proprietary info deleted (ref 10CFR2 790)
* Combustion Engineering, Inc 83/08/31 5pp 20725 287 24X
Fiche 50-368, 83/09/30, 8310130097

8310140143 Forwards proprietary "Rancho Seco Cycle 7 Reload Rept - Vol 1 - Mark B2 Fuel Assembly Design Rept," in support of Cycle 9 reload planned for late 1984 Rept withheld (ref 10CFR2 790)
TUCKER, H B Duke Power Co 83/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 20766 067 24X Fiche 50-000, 83/10/07, 8310140143

--8310140145 Forwards proprietary "Rancho Seco Cycle 7 Reload Rept - Vol 1 - Mark B2 Fuel Assembly Design Rept," Apr 1983 Affidavit supporting determination of proprietary nature of rept encl
TAYLOR, J H Babcock & Wilcox Co 83/09/19 MINER, S Office of Nuclear Reactor Regulation, Director 8pp 20766 069 24X
Fiche 50-000, 83/10/07, 8310140143

8310140152 Notices of B&W Owners Group ATWS Committee 830826 meeting in Bethesda, MD re conceptual designs for diverse scram sys & proposed reactor trip breaker liability monitoring program to address Generic Ltr 83-28
ENDS, J T Babcock & Wilcox Operating Plants Owners Group ENOS, J, Arkansas Power & Light Co OLC-103-03 83/10/05 EISENHUT, D G
Division of Licensing 1p 20765 066

8310140163 Forwards Rev 2 to "QA for American Inst of Steel Const Nuclear Quality Certification Program," per Region IV 830902 ltr of approval Revised pages sent to holders of controlled copies
PESHEK, C American Institute of Steel Construction, Inc 83/10/11
NRC - No Detailed Affiliation Given 2pp 20765 008

--8310140165 Advises that proposed Rev 2 to "QA for American Inst of Steel Const Nuclear Quality Certification Program," meets 10CFR50, App B criteria & is acceptable
POTAPOV, U Region 4, Office of Director 83/09/02 PESHEK, C
American Institute of Steel Construction, Inc 2pp 20765 010

--8310140174 FCTPN-7B
Rev 2 to "QA for American Inst of Steel Const Nuclear Quality Certification Program "
PESHEK, C American Institute of Steel Construction, Inc 83/09/16 15pp 20765 012

8310140227 Forwards nonproprietary response to 830923 request for addl info on WCAP-8720, Addendum 2, "Revised PAD Code Thermal Safety Model" (proprietary) & WCAP-8785 (nonproprietary)
RAHE, E P Westinghouse Electric Corp NS-EPR-2832 83/09/30
THOMAS, C D Standardization & Special Projects Branch 3pp
20761 247

8310140239 Forwards nonproprietary & proprietary approved versions of Vol 4 of "Exxon Nuclear Co (ENC) Methodology for BWRs Application of ENC Methodology to BWR Reloads " Proprietary version withheld (ref 10CFR2 790)
CHANDLER, J C Exxon Nuclear Co, Inc (subs of Exxon Corp) JCC 091 83 83/09/30 THOMAS, C D Standardization & Special Projects Branch 1p 20759 240

--8310140244 XN-NF-80-19(NP)(A)1V4
Nonproprietary approved version of Vol 4 of "Exxon Nuclear Co (ENC) Methodology for BWRs Application of ENC Methodology to BWR Reloads "
CHANDLER, J C, OWSEY, G F, STOUT, R B Exxon Nuclear Co, Inc (subs of Exxon Corp) 83/09/14 58pp 20759 241

8310170091 Forwards repts on 821205 main generator failure & proprietary & nonproprietary repts on seven main transformer failures occurring between 801129 & 821205 Proprietary rept withheld (ref 10CFR2 790)
STEWART, W L Virginia Electric & Power Co 482 83/10/05
DENTON, H R Office of Nuclear Reactor Regulation, Director
MILLER, J R Operating Reactors Branch 3 2pp 20789 207 24X
Fiche 50-338, 83/10/05, 8310170091

NONDOCKETED ITEMS

- 8310170107 Nonproprietary version of "Transformer Rept on Events at North Anna Power Station"
COSSAART, J., PETRIE, E., SKODGLUND, J. Westinghouse Electric Corp
83/06/16 276pp 20789 226 24X Fiche 50-338, 83/10/05,
8310170091
- 8310170190 Forwards Rev F to GA program manual Historical document containing all changes to GA manual since first edition issued in Aug 1973 encl
COUNSIL, W. G. Northeast Utilities Service Co COUNSIL, W. G. Northeast Utilities 810911 83/09/30 MURLEY, T. E. Region 1, Office of Director 2pp 20787 116 24X Fiche 50-423, 83/09/30, 8310170190
- 8310170198 Rev F to GA program manual
KELLY, R. B., ALLEN, W. F., SMITH, L. S. Stone & Webster Engineering Corp 81/04/06 589pp 20787 118 24X Fiche 50-423, 83/09/30, 8310170190
- 8310170540 Forwards Rev 1 to Vol 3 to "GESTR-LOCA & SAFER Models for Evaluation of LOCA" Encl withheld (ref 10CFR2 790)
QUIRK, J. F. General Electric Co MFN-187-83 83/10/06 THOMAS, C. D. Standardization & Special Projects Branch 5pp 20782 183
- 8310180370 Approves request for withholding CEN-181-P generic responses re inadequate core cooling per TMI Item II F 2 from public disclosure (ref 10CFR2 790)
CRUTCHFIELD, D. Operating Reactors Branch 5 LS05-83-10-033 83/10/11 SCHERER, A. E. Combustion Engineering, Inc 4pp 20827 010
- 8310180379 Approves request for withholding listed proprietary info re inadequate core cooling per TMI Item II F 2 from public disclosure (ref 10CFR2 790)
CRUTCHFIELD, D. Operating Reactors Branch 5 LS05-83-10-029 83/10/11 WIESEMANN, R. A. Westinghouse Electric Corp 2pp 20826 355
- 8310180533 Approves Bill 125 & 1201 requests for withholding CEN-185, Suppl 2-P "Heated Junction Thermocouple Phase II Test Rept" re TMI Item II F 2 from public disclosure (ref 10CFR2 790)
CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/11 SCHERER, A. E. Combustion Engineering, Inc 4pp 20825 001
- 8310180560 Discusses SER re GE proposal to delete control rod drop accident from std GE-BWR reload package for banked withdrawal sequence plants w/o encl
THOMAS, C. D. Standardization & Special Projects Branch 83/10/13 RUBENSTEIN, L. B. Assistant Director for Core & Plant Systems 1p 20824 398
- 8310190009 Forwards proprietary "Koch Process Sys VR-Sys 350 Low Level Radwaste Vol Reduction Sys" Rept withheld
ABRAMS, R. Koch Industries, Inc 83/10/05 THOMAS, C. D. Standardization & Special Projects Branch 1p 20823 127
- 8310190043 Forwards "VEPCO NOMAD Code & Model" Rept is one of series discussing nuclear reload licensing & core follow support capabilities
STEWART, W. L. Virginia Electric & Power Co 945 83/10/14 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 20822 335 24X Fiche 50-000, 83/10/14, 8310190043
- 8310190057 VEP-NFE-1
"VEPCO NOMAD Code & Model"
BOWMAN, S. M. Virginia Electric & Power Co 83/09/30 118pp 20822 337 24X Fiche 50-000, 83/10/14, 8310190043
- 8310190097 Forwards Rev 14 to operational GA program Rev addresses organizational & programmatic changes to GA program
SHEPARD, A. M. Yankee Atomic Electric Co FVY 83-109 83/10/12 MURLEY, T. E. Region 1, Office of Director 1p 20822 117 24X Fiche 50-000, 83/10/12, 8310190097
- 8310190105 YOGAP-I-A R14
Rev 14 to operational GA program
PETERSON, W. K., SHEPARD, A. M., MURPHY, W. P. Yankee Atomic Electric Co 83/10/12 134pp 20822 118 24X Fiche 50-000, 83/10/12, 8310190097
- 8310200170 Forwards summary of test results & basis for conclusions for Model DD-30 circuit breaker undervoltage trip attachment, per IE Bulletin 83-01
RAHE, E. P. Westinghouse Electric Corp IEB-83-01 83/10/05 DENTON, H. Office of Nuclear Reactor Regulation, Director 17pp 20834 054
- 8310200193 Forwards proprietary "Westinghouse Response to NRC Question at 830901 Meeting on Pretendering Module 4 - Reactor Sys" & application for withholding proprietary info per 10CFR2 790
RAHE, E. P. Westinghouse Electric Corp NS-EPR-2830 83/09/30 EISENHUT, D. G. Office of Nuclear Reactor Regulation, Director 2pp 20833 259
- 8310200199 Application for withholding proprietary info in "Westinghouse Response to NRC Questions at 830901 Meeting on Pretendering Module 4 - Reactor Sys," per 10CFR2 790
WIESEMANN, R. A. Westinghouse Electric Corp AH-83-82 83/09/30 EISENHUT, D. G. Office of Nuclear Reactor Regulation, Director 1p 20833 261
- 8310210020 Forwards proprietary version of "Rancho Seco Cycle 7 Reload Rept, Vol 1, Mark BZ Fuel Assembly Design Rept" Vol 2 will be submitted in Fall 1984 Rept withheld
MATTIMOE, J. J. Sacramento Municipal Utility District 83/10/18 EISENHUT, D. G. Division of Licensing 1p 20838 201 24X Fiche 50-312, 83/10/18, 8310210020
- 8310210139 Forwards proprietary XN-NF-82-25(P)(A), "Generic Mechanical Design Rept Exxon 17x17 Fuel Assembly" & Rev 1 to XN-NF-82-21(P)(A), "Application of Exxon Nuclear Co PWR Thermal Margin" Repts withheld (ref 10CFR2 790)
CHANDLER, J. C. Exxon Nuclear Co, Inc (subs of Exxon Corp) JCC 095 83 83/10/07 THOMAS, C. D. Standardization & Special Projects Branch 2pp 20851 055
- 8310250013 Discusses topical rept evaluation of NEDE-24326-P, "GE Environ Qualification Program" Disclaimer contained in rept makes transition into topical rept program impossible
Recommendations remain on Perry docket
MIRAGLIA, F. J. Assistant Director for Safety Assessment 83/10/17 NOVAK, T. M. Assistant Director for Licensing 2pp 20916 210
- 8310250018 Forwards topical rept evaluation of NEDE-24326-P, "GE Environ Qualification Program" Qualification methodology presented No plant-specific qualification parameters
Developed Rept acceptable
KNIGHT, J. P. Assistant Director for Comp & Structures Engineering (Post 830201) 83/07/14 MIRAGLIA, F. J. Assistant Director for Safety Assessment 2pp 20916 212
- 8310250021 Topical rept evaluation of NEDE-24326-P, "GE Environ Qualification Program" Rept acceptable
* Commissioners 83/07/14 17pp 20916 214
- 8310250273 Responds to IE Bulletin 83-07 re apparently fraudulent products sold by Ray Miller, Inc Ray Miller, Inc products placed in inventory for in-house maint needs Items isolated & will be discarded
AUSTIN, H. A. Babcock & Wilcox Co IEB-83-07 83/09/23 MURLEY, T. E. Region 1, Office of Director 2pp 20899 021
- 8310250577 Assists in resolving TMI Action Item II K 3 30 re small break LOCA methods Response listed in three segments Part 1 completed by C-E, Part 2 to be performed by C-E & Part 3 represents new work not considered part of CEN-203-P
WELLS, R. W. C-E Operating Plants Owners Group WELLS, R. W. Northeast Utilities RWH-83-54 83/10/12 THOMAS, C. D. Standardization & Special Projects Branch 2pp 20900 348
- 8310260156 Forwards Rev 1 to Suppl 3 of "Probabilistic Risk Assessment of Effects of PORVs on Depressurization & DHR" Changes are result of detailed treatment of automatic PORV cases & complete analysis of auxiliary feedwater restoration
VAN BRUNT, E. E. Arizona Public Service Co ANPP-28004-WFQ/ 83/10/13 KNIGHTON, G. Licensing Branch 3 3pp 20914 178 24X Fiche 50-328, 83/10/13, 8310260156
- 8310260160 CEN-239 903 R01
Rev 1 to Suppl 3 of "Probabilistic Risk Assessment of Effects of PORVs on Depressurization & DHR"
* Combustion Engineering, Inc 83/09/30 373pp 20914-181 24X Fiche 50-328, 83/10/13, 8310260156
- 8310260237 Forwards "Trojan Nuclear Plant Cycle & Startup & Power Escalation Physics Testing Rept"
WITHERS, B. D. Portland General Electric Co 83/10/14 MARTIN, J. B. Region 5, Office of Director 1p 20912 024 24X Fiche 50-344, 83/10/14, 8310260237
- 8310260279 Forwards nonproprietary & proprietary versions of "Counterflow Preheat Steam Generator Tube Expansion Rept" & "Counterflow Preheat Steam Generator Tube Vibration Summary Rept" Proprietary version withheld (ref 10CFR2 790)
RAHE, E. P. Westinghouse Electric Corp NS-EPR-2814 83/08/26 EISENHUT, D. G. Division of Licensing 2pp 20909 354 24X Fiche 50-445, 83/08/26, 8310260279

NONDOCKETED ITEMS

- B310260281 Application for withholding proprietary versions of "Counterflow Preheat Steam Generator Tube Expansion Rept" & "Counterflow Preheat Steam Generator Tube Vibration Summary Rept," per 10CFR2 790 Affidavit encl
WIESEMAN, R A Westinghouse Electric Corp AW-83-53 83/08/26
EISENHUT, D G Division of Licensing 9pp 20909 358 24X
Fiche 50-445, 83/08/26, 8310260279
- B310260284 86PR-8301
Nonproprietary version of "Counterflow Preheat Steam Generator Tube Expansion Rept"
* Westinghouse Electric Corp 83/06/30 140pp 20910 005 24X
Fiche 50-445, 83/08/26, 8310260279
- B310260286 86PR-8302
Nonproprietary version of "Counterflow Preheat Steam Generator Tube Vibration Summary Rept"
* Westinghouse Electric Corp 83/06/30 180pp 20910 144 24X
Fiche 50-445, 83/08/26, 8310260279
- B310270006 Notification of B31026 meeting w/C-E in Bethesda, MD to discuss use of pipe whip restraints in C-E std SAR design
MEYER, G C Standardization & Special Projects Branch 83/10/19
THOMAS, C O Standardization & Special Projects Branch 2pp
20940 165 24X Fiche 50-470, 83/10/19, 8310270006
- B310270038 Forwards CASE-TR2, "QA Program for Nuclear Section of Coordinating Agency for Supplier Evaluation," in response to NRC 830826 request
BAJADA, E C, SHANSHIGER, T G Coordinating Agency for Supplier Evaluation (CASE Assoc) * Cleveland Electric Illuminating Co 83/10/05
NRC - No Detailed Affiliation Given 1p 20937 162
- B310270050 Evaluation of proposed Rev 2 to "QA Program for Nuclear Section of Coordinating Agency for Supplier Evaluation" Rev acceptable
POTAPQVS, U Region 4, Office of Director 83/08/26 BAJADA, E C Coordinating Agency for Supplier Evaluation (CASE Assoc) 2pp
20937 164
- B310270055 CASE-TR2 R02
Rev 2 to "QA Program for Nuclear Section of Coordinating Agency for Supplier Evaluation"
* Coordinating Agency for Supplier Evaluation (CASE Assoc) 83/09/30 40pp 20937 166
- B310270051 Responds to FOIA request for "Westinghouse Advanced PWR Licensing Control Document," dtd Aug 1982, to be placed in PDR Document withheld (ref FOIA Exemption 4)
FELTON, J M Division of Rules and Records 83/07/14 PEDRO, J NUS Corp 1p 20942 016
- B310270057 FOIA request for "Westinghouse Advanced PWR Licensing Control Document," dtd Aug 1982, to be placed in PDR Rept referenced at NRC B21130 meeting w/Westinghouse
PEDRO, J NUS Corp CD-83-021 83/06/08 Division of Rules and Records 1p 20942 017
- B310270594 Forwards "Recommendations for Improvement of Equipment Qualification Methodology & Criteria," Contract NRC-04-81-185, Task 3 summary rept
CAMPBELL, W E Mechanical/Structural Engineering Branch
NRC-04-81-185 83/10/21 MORRIS, B Electrical Engineering Branch
NOONAN, V Equipment Qualification Branch BQSNK, R J Materials Engineering Branch 1p 20928 255
- B310270598 8WRI-4582-003
"Recommendations for Improvement of Equipment Qualification Methodology & Criteria," Contract NRC-04-81-185, Task 3 summary rept
KANA, D D, POMERENINO, D J Southwest Research Institute
NRC-04-81-185 83/10/01 Office of Nuclear Regulatory Research, Director 68pp 20928 257
- B310280007 Forwards draft answers to NRC Request 2 for addl info on WCAP-10079(P) Response should be withheld (ref 10CFR2 790)
WIESEMAN, R A Westinghouse Electric Corp AW-83-85 83/10/10
THOMAS, C O Standardization & Special Projects Branch 1p
20929 036
- B310280017 Requests draft answers to NRC Request 2 for addl info on WCAP-10079(P) be treated as proprietary (ref 10CFR2 790)
RAHE, E P Westinghouse Electric Corp NS-EPR-2838 83/10/10
THOMAS, C O Standardization & Special Projects Branch 1p
20929 037
- B310280099 Forwards B&W Owners Group rept "Bounding Analytical Assessment of NUREG-0630 Models on LOCA kW/ft Limits W/Use of FLECSSET"
RODRIGUEZ, R J Sacramento Municipal Utility District RJR 83-705
83/10/21 STOLZ, J F Operating Reactors Branch 4 1p 20935 212
24X Fiche 50-312, 83/10/21, 8310280099
- B310280106 Forwards proprietary version of Westinghouse Advanced PWR RESAR SP/90 - Module 1, "Primary Side Safeguards Sys Module" Rept withheld (ref 10CFR2 790)
RAHE, E P Westinghouse Electric Corp NS-EPR-2842 83/10/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 76pp
20934 198
- B310280110 Application for withholding Westinghouse Advanced PWR RESAR SP/90, "Primary Side Safeguards Sys Module," from public disclosure
WIESEMAN, R A Westinghouse Electric Corp AW-83-93 83/10/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 9pp
20934 276
- B310310410 Forwards B&W Owners Group Analysis Committee/Core Performance Committee Rept "Bounding Analytical Assessment of NUREG-0630 Models on LOCA kW/ft Limits W/Use of FLECSSET"
HUKILL, H D General Public Utilities - GPU Service Corp 5211-83-303 83/10/21 NOVAK, T Assistant Director for Licensing 1p 20961 001 24X Fiche 50-289, 83/10/21, 8310310410
- B310310413 77-1140898-01
"Bounding Analytical Assessment of NUREG-0630 Models on LOCA kW/ft Limits W/Use of FLECSSET"
* Babcock & Wilcox Operating Plants Owners Group 83/09/30 104pp 20961 002 24X Fiche 50-289, 83/10/21, 8310310410
- B310310476 Approves request for withholding Rev 3 to B&W Topical Rept 00B, "Assessment of TH-1 Plant Safety for Return to Svc After Steam Generator Repair" (ref 10CFR2 790)
STOLZ, J F Operating Reactors Branch 4 83/10/11 HUKILL, H D General Public Utilities - GPU Service Corp 5pp 20965 183 24X
Fiche 50-289, 83/10/11, 8310310476
- B310310489 Summary of 830826 meeting w/B&W Owners Group re implementation of Generic Ltr 83-28 concerning defenses against ATWS & proposed ATWS rule for B&W plants List of attendees & viewgraphs encl
KADAMBT, P Operating Reactors Branch 4 GL-83-28 83/10/20
Operating Reactors Branch 4 13pp 20965 147 24X
Fiche 50-000, 83/10/20, 8310310489
- B310310505 Notification of B31026 meeting w/Westinghouse in Bethesda, MD to discuss proprietary portions of review of Westinghouse safety parameter display sys
DICK, G F Operating Reactors Branch 5 83/10/20 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 20965 181
- WASH REGULATORY PUBLICATIONS - PRE-NUREG SERIES
- B310040387 Submits evaluation of existing Westinghouse STB provisions ASME Code Section XI, Reactor Safety Study (WASH 1400), NUREG-0677 & EG&G rept on "Inservice Leak Testing of Primary Pressure Isolation Valves" as applicable to plant design
CLAYTON, F L Alabama Power Co 83/09/27 VARGA, S A Office of Nuclear Reactor Regulation, Director 16pp 20625 200 24X
Fiche 50-348, 83/09/27, 8310040387
- B310120016 Addl response to FOIA request for document re problems w/ Tech Specs applying to RCS leakage determinations in PWRs
Forwards App A documents
FELTON, J M Division of Rules and Records 83/07/07 VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 2pp 20751 001 24X
Fiche 50-000, 83/07/07, 8310120016
- B003240118 Requests specs for surveillance & limiting conditions to ensure valve integrity if Event 5 valve configuration exists NRC B00223 ltr requesting LWR licensees to indicate if Event 5 valve configuration exists at facility encl
POLK, P J Operating Reactors Branch 3 (Pre B00428) 80/02/27
WETHORE, J Operating Reactors Branch 2 (Pre B00428) 2pp
20751 027
- B003240123 Ltr all LWR licensees requesting that periodic valve test or continuous surveillance be performed to determine if Event 5 valve configuration exists at facility Requests listed info re valve configuration
EISENHUT, D G Division of Operating Reactors 80/02/25
Division of Operating Reactors 3pp 20751 034
- B310120018 Notifies of decision to expand existing contract w/Franklin Inst to include technical assistance on Generic Activity D-4B, "LWR Primary Coolant Sys Pressure Isolation Valves" Mgt concurrence requested
POLK, P J Operating Reactors Branch 3 (Pre B00428) 80/03/06
BUTCHER, E NRC - No Detailed Affiliation Given 23pp 20751 001
- B310120019 Forwards draft answers to NRC Request 2 for addl info on primary coolant sys
FELTON, J M Division of Rules and Records 83/07/07
Fiche 50-000, 83/07/07, 8310120019
- B1/04/20 1p. 20751 05

NONDOCKETED ITEMS

8310270040 Responds to FOIA request for documents containing info re emission of radioactive iodine & other fission products during reactor accidents Forwards App A documents App B documents can be purchased from NRC
FELTON, J M Division of Rules and Records 83/07/06 ROGERS, H A Affiliation Unknown 4pp 20940 345 24X Fiche 50-320, 83/07/06, 8310270040

--8310270041 Forwards draft "Comparison of Iodine Behavior During TMI-2 Accident W/Predictions Based on WASH-1400 Methodology"
POSTMA, A K Benton City Technology 82/04/13 PASDAQ, W F Accident Evaluation Branch 41pp 20940 349 24X Fiche 50-320, 83/07/06, 8310270040

--8310270044 Draft "Comparison of Iodine Behavior During TMI-2 Accident W/Predictions Based on WASH-1400 Methodology"
POSTMA, A K Benton City Technology 82/04/13 40pp 20940 350 24X Fiche 50-320, 83/07/06, 8310270040

--8310270045 BML-2104
Draft "PWR-Large Dry Containment-Radionuclide Release Under Specific Accident Conditions"
* Battelle Memorial Institute, Columbus Laboratories * Sandia Laboratories 83/02/09 Office of Nuclear Regulatory Research Director 348pp 20941 028

WASTE MGT NUCLEAR WASTE MANAGEMENT

8310030605 Forwards revised "Summary Protocol UMTRAP Vicinity Properties Identification - Characterization - Inclusion," resulting from concerns & comments discussed during 830909 meeting & in response to 830916 ltr for review
BAUBLITZ, J E Energy, Dept of 83/09/19 HIGGINBOTHAM, L Low Level Waste Licensing Branch 1p 20603 001

--8310030610 "Summary Protocol UMTRAP Vicinity Properties Identification - Characterization - Inclusion" One oversize diagram encl
Aperture card is available in PDR
* Energy, Dept of 83/09/30 25pp 20603 002

8310050408 "Funding Assurances for Closure, Post-closure & Long-Term Care of Low Level Waste Disposal Facility," technical position
* NRC - No Detailed Affiliation Given 82/06/30 18pp 20649 337

8310050413 "Near Surface Disposal Facility Design & Operation," technical position
PANGBURN, G C Low Level Waste Licensing Branch PENNIFILL, R A Division of Waste Management 82/11/30 18pp 20649 318

8310060516 Responds to 830824 ltr requesting certain NRC computer codes Codes & associated documentation will be provided as expeditiously as practical Codes still under development & may not be used in licensing effort
BUNTING, J O Licensing Process & Integration Branch 83/09/16 HOVIS, J B Hovis, Cockrill, Weaver & Bjur 3pp 20662 359

8310110624 Forwards "Status of NRC Concerns Pertaining to Site Characterization Rept," consisting of dispositions/response tables prepared by BWIP covering NRC comments on draft site characterization rept
OLSON, D L Energy, Dept of 000560 83/09/21 WRIGHT, R J High Level Waste Technical Development Branch 1p 20707 001

--8310110626 SD-BWI-DIC-001 R00
Rev 0 to "Status of NRC Concerns Pertaining to Site Characterization Rept"
RUTZ, A C Energy, Dept of 000560 83/09/01 318pp 20707 002

8310130008 Forwards preliminary DES re remedial actions at former Union Carbide Corp sites in Rifle, Garfield County, CO Comments requested by 831028
MORLEY, J A Energy, Dept of 83/10/03 MARTIN, D Low Level Waste Licensing Branch 1p 20775 001

--8310130011 DES re remedial actions at former Union Carbide Corp sites in Rifle, Garfield County, CO
* NUS Corp 83/09/30 500pp 20775 002

8310130046 Summary of 830810 meeting w/DOE, NRC & EPA re transfer of Durita site of ranchers to govt for UMTRAP & SUPERFUND
HAZLE, A J Colorado, State of 83/08/11 Colorado, State of 4pp 20776 214

8310130067 Forwards draft "Plan for Implementing EPA Stds for U Mill Tailings Remedial Action Sites" Rapid prereview by 830930 requested Draft plan will be revised during wk of 831003 in preparation for 831003 & 04 meetings
BAUBLITZ, J E Energy, Dept of 83/09/27 HIGGINBOTHAM, L Division of Waste Management 2pp 20776 198

--8310130071 Draft "Plan for Implementing EPA Stds for U Mill Tailings Remedial Action Sites"
MORLEY, J A Energy, Dept of 83/09/30 54pp 20776 160

8310170139 "Designation of Preferred Candidate Repository Horizon for BWIP"
* Energy, Dept of 83/10/14 3pp 20813 041

8310170338 "Summary of Basis for Identification of Cohasset Flow as Preferred Candidate Repository Horizon" Meeting agenda & mgt meeting log encl
* Energy, Dept of 83/09/30 32pp 20795 240

8310190265 Forwards proposed method for qualifying process control program for stability of solidified waste at Ginna Station Assurance that program meets requirements of 10CFR61 requested
DUGGAN, G J Science Applications, Inc 83/09/23 JOHNSON, T C N - No Detailed Affiliation Given 5pp 20842 288

8310210130 Notification of 831129-1201 meetings w/DOE, State of WA, Rockwell & affected Indian Tribes in Richland, WA to discuss resolution of NRC concerns re underground testing portions of site characterization rept
* NRC - No Detailed Affiliation Given 83/10/12 NRC - No Detailed Affiliation Given 2pp 20883 195

8310210335 Summary of 830829-0901 BWIP Performance Assessment Workshop in Richland, WA
FEHRINGER, D J High Level Waste Licensing Management Branch 83/09/22 BROWNING, R E, COMELLA, P, BELL, M J NRC - No Detailed Affiliation Given 9pp 20883 161

8310240242 Requests assistance for input into implementation of TOUGH computer program on BNL sys Code will be used in assessment of high level waste repositories Tape preprocessor programs & sample input sets encl W/o tape
BELL, M J High Level Waste Licensing Management Branch 83/09/23 BASSETT, H S Division of Data Automation & Management Information 19pp 20907 286

8310240252 Forwards "Nonisothermal Flow Modeling of Hanford Site," as discussed at Aug 1983 workshop on performance assessment of BWIP at Richland, WA W/o encl
WEBER, M F High Level Waste Licensing Management Branch 83/09/27 LEHMAN, L L Affiliation Unknown 1p 20907 279

8310240253 Designates addl Edgemont, SD vicinity properties identified in encl radiological assessment repts for remedial action under Public Law 97-415 W/o encl
COFFMAN, F E Energy, Dept of 83/10/05 ROMATOWSKI, R Q Energy, Dept of 1p 20907 278

8310240255 Responds to 830919 ltr re possible discussions among State of UT, EPA, NRC & DOE concerning interpretations of EPA stds, design criteria & costing methodology Meeting w/EPA & NRC scheduled for early Nov in Albuquerque
MORLEY, J A Energy, Dept of 83/10/06 MASON, J O Utah, State of 1p 20907 276

8310240260 Submits proposed agenda for regulatory issues session at Annual Civilian Radwaste Mgt Info Meeting scheduled for 831212-13 in Washington, DC
MILLER, H J High Level Waste Technical Development Branch 83/09/09 SHAHEEN, J Energy, Dept of 2pp 20907, 266

8310240262 Forwards review package from WA State re DOE designed high integrity container for disposal of EPICOR-II resins at Hanford disposal facility W/o encl
HIGGINBOTHAM, L Low Level Waste Licensing Branch 83/09/15 GAMBILL, W Meteorology & Effluent Treatment Branch BNYDER, B J TMI Program Office MACDONALD, C Transportation Branch 1p 20907 356

8310240265 Trip rept of 830926-29 site visit to Vitro UMTRAP re surface & subsurface hydrology concerning potentially proposed remedial actions including stabilization in place Meeting agenda encl
WEBER, M F Division of Waste Management 83/10/04 KNAPP, M R Division of Waste Management 10pp 20907 346

NONDOCKETED ITEMS

10240266 Forwards radiological assessment repts for properties in Edgemont, SD for consideration re remedial action under UMTRA W/o encls
MARTIN, D Low Level Waste Licensing Branch 83/09/30 BAUBLITZ, J Energy, Dept of 1p 20907 345

10240267 Recommends concurrence on cooperative agreement between DOE & Navajo Tribe for remedial action on Indian lands No unresolved concerns remaining
MARTIN, D E Uranium Recovery Licensing Branch 83/10/05
HIGGINBOTHAM, L Uranium Recovery Licensing Branch 1p 20907 343

8310240271 Forwards, for concurrence, Cooperative Agreement DE-FC04-83AL16298 between DOE & Navajo Tribe Agreement supports UMTRA in Navajo lands, per Public Law 95-604
CONE, T C Energy, Dept of 83/09/16 HIGGINBOTHAM, L Low Level Waste Licensing Branch 1p 21035 044

10240270 Forwards comments on test program developed to demonstrate compliance w/waste form stability requirements of 10CFR61, submitted on 830909 Test program acceptable if comments incorporated & test results meet technical position
HIGGINBOTHAM, L Low Level Waste Licensing Branch 83/09/30
LANE, R G US Gypsum Co 4pp 20907 334

10240276 "Branch Position on Explorations for Design & Evaluation of J Mill Tailings Retention Sys"
* Uranium Recovery Licensing Branch 79/01/31 2pp 20907 328

10250095 Forwards, for consideration & review, proposed agreement between DOE & util to provide for disposal of residual radioactive matts
MORLEY, J A Energy, Dept of 83/10/03 DONOVAN, T K Tennessee Valley Authority 12pp 20916 165

10250102 Forwards, for review & comment, draft "Plan for Implementing EPA Sids for UMTRA Sites." Meetings scheduled on 831103 & 04 in Albuquerque to discuss implementation plan & design analysis process
MORLEY, J A Energy, Dept of 83/10/07 HIGGINBOTHAM, L High Level Waste Licensing Management Branch 1p 20916 110

8310250107 Draft Procedure UMTRA-DOE/AL - 163, "Plan for Implementing EPA Sids for UMTRA Sites"
MORLEY, J A Energy, Dept of 83/10/31 54pp 20916, 111

0250680 Submits proposed schedule for submittal of rept on polyethylene high integrity containers Rept scheduled for submittal by 831226
EARBON, S D Chem-Nuclear Systems, Inc TR-83-P0420 83/10/04
HIGGINBOTHAM, L Low Level Waste Licensing Branch, 1p 20908-354

0260074 Forwards "Assessment of Radionuclide Apparent Solubilities by Conservative Estimation of Steady-State Concentration," NRC draft technical position Summary of comments will be completed by 831130
JUSTUS, P S High Level Waste Technical Development Branch 3/09/30 MILLER, H J High Level Waste Technical Development Branch 1p 20921 267

8310260083 "Assessment of Radionuclide Apparent Solubilities by Conservative Estimation of Steady-State Concentration," NRC draft technical position
* High Level Waste Technical Development Branch 83/09/30 50pp 20921 268

0260088 Forwards request for approval to use high integrity containers to bury EPICOR II prefilters from TMI-2
IPSHER, W M US Ecology, Inc (formerly Nuclear Engineering) 3/07/01 KIRNER, N Washington, State of, Dept of Social & Health services 27pp 20921 239

0260094 Forwards add supportive info providing data on how high integrity container (HIC) will meet present criteria use in low level radwaste disposal, for inclusion in HIC use application
IPSHER, W M US Ecology, Inc (formerly Nuclear Engineering) 3/09/16, KIRNER, N, Washington, State of, Dept of Social & Health services 10pp 20921 162

0260318 Responds to questions in 830930 ltr re NRC regulatory program for U milling Applicable manual chapters encl.
NUSSBAUMER, D A Assistant Director for State Agreements Programs, 3/10/11 SPAIN, M Virginia, Commonwealth of, 31pp 20918-301.

0280076 Forwards, for review, DES section on geohydrology at Vitro site Comments requested by 831027
ATTHEWS, M L Energy, Dept of, 83/10/17 MARTIN, D E, Low Level Waste Licensing Branch, 100pp 20964 028

8310280080 Forwards correspondence w/EPA for past 3 yrs, including EPA 830817 response re duality of regulation for nuclear waste sites at Hanford, WA & Beatty, NV
EASON, C F US Ecology, Inc (formerly Nuclear Engineering) 00A-83-539 83/09/30 LOHAUS, P Division of Waste Management 9pp 20965 068

8310280103 Forwards 830913 ltr from State of NV, responding to NRC 830822 ltr on RADMAN code
NUSSBAUMER, D A Assistant Director for State Agreements Programs 83/09/21 HIGGINBOTHAM, L Low Level Waste Licensing Branch 2pp 20961 358

--8310280107 Responds to NRC 830822 ltr re RADMAN computer code No objections raised to use of code by persons licensed to dispose of radwaste at Beatty site
VADEN, J Nevada, State of 83/09/13 NUSSBAUMER, D A Assistant Director for State Agreements Programs 1p 20961 359

8310280111 Forwards Rev 1 to TMI-2 Operating Procedure 2104-4 96, "Dewatering of EPICOR Liners at EPICOR II," per 830919 discussion
GRANT, P J TMI Program Office 83/09/19 JOHNSON, T NRC - No Detailed Affiliation Given 1p 20964 001

--8310280116 Rev 1 to TMI-2 Operating Procedure 2104-4 96, "Dewatering of EPICOR Liners at EPICOR II"
* General Public Utilities - GPU Service Corp 81/04/24 24pp 20964 002

8310280162 Order directing designated groups to identify, within 2 wks representatives & interest for oral presentation to Commission re DOE general guidelines for recommendation of sites for nuclear waste repositories
CHILK, S J Office of the Secretary of the Commission 83/10/26 2pp 20929 224

8310280283 Forwards Rev B to "Deep Borehole Strategic Correlation Charts & Structure Cross Sections," per M Guzowski request
OLSON, D L Energy, Dept of 00572 83/10/13 WRIGHT, R J High Level Waste Technical Development Branch 1p 20962 001

--8310280299 SD-BWI-DP-035 R B
Rev B to "Deep Borehole Strategic Correlation Charts & Structure Cross Sections"
CROSBY, R W Energy, Dept of 83/09/07 142pp 20962 002

8310310182 Notifies of 831103-04 meetings in Albuquerque, NM to discuss & receive comments on draft, "Plan for Implementing EPA Sids for UMTRA Sites" Draft agenda encl
MORLEY, J A Energy, Dept of 83/10/18 HIGGINBOTHAM, L Low Level Waste Licensing Branch 2pp 20965 276

8310310204 Informs of establishment of public ref ctr in Olympia, WA Requests assistance in obtaining public documents written or sponsored by NRC to aid in development of ctr
STEVENS, D Washington, State of 83/10/05 BUNTING, J D Licensing Process & Integration Branch 1p 20965 303

8310310451 Forwards requested info re Salt Lake City Vitro Mill Site as requested in 831006 telcon
PRICE, J D Jacobs Engineering Group, Inc 83/10/17 WEBER, M NRC - No Detailed Affiliation Given 8pp 20965 170

EXPORT AND IMPORT LICENSES

8309230037 License for Exxon Nuclear Co, Inc to export 3,163 kg U-235, contained in 76,762 kg U, to Taiwan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/09/13 2pp 20488 270

8310030196 Forwards IE Matl Control & Accounting Safeguards Insp Rept 110-0313083-01 on 830914 of activities under Export License XSNM-2027 No noncompliance noted
NORDERHAUG, L R Region 5, Office of Director 83/09/28 NAKAI, T Marubeni America Corp (subs of Marubeni Corp) 2pp 20390 153

--8310030213 IE Matl Control & Accounting Safeguards Insp Rept 110-03133/83-01 on 830914 No noncompliance noted Major areas inspected shipping drum identification & tamper seal numbers to shipment packing lists Details withheld (ref 10CFR2 790)
NELSON, G B, WIEDER, A V, BROCK, B L Region 5, Office of Director 83/09/28 1p, 20390 155

8310060056 Submits Dfc of Intl Programs findings re BMI 830830 application for license to import 23 g enriched U from Canada Import acceptable
MCORE, R N Assistant Director for Export/Import & International Safeguards 83/09/28 Assistant Director for Export/Import & International Safeguards 1p 20663 361

NONDOCKETED ITEMS

483

8310060059 Application to amend license to export U-235 to Yugoslavia, increasing quantity & extending expiration date to 901231
HERSCH, H M Westinghouse Electric Corp MMH-413 83/09/19
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 1p 20663 360

8310060060 Forwards application to renew export license, extending expiration date to accommodate requirement to ship sources containing Cf-252 to West Germany in Nov 1983
JANZOW, E F Monsanto Research Corp 83/09/19 HEMBY, E Assistant Director for Export/Import & International Safeguards 1p 20663 357

--8310060065 Application to renew general export license
JANZOW, E F Monsanto Research Corp 825 3000 83/09/16 2pp 20663 358

8310060081 Forwards application to export 7,770 kg U. containing 283 605 kg U-235, to Switzerland
HANNETT, B A Transnuclear, Inc RBU-428 83/09/20 MOORE, R N Office of International Programs, Director 1p 20663 354

-8310060084 Application for license to export 7,770 kg U. containing 283 605 kg U-235, to Switzerland
HANNETT, B A Transnuclear, Inc RBU-428 83/09/20 2pp 20663 355

8310060090 Application to amend import license, extending expiration date to Dec 1988
FOSTER, C M Edlow International Co 83/09/08 MOORE, N Assistant Director for Export/Import & International Safeguards 1p 20663 353

8310060094 Executive Branch position re Nikko Wolverine, Inc application to export 434 lb reactor grade Zircaloy-4 tubing to United Kingdom License should be granted
DEVINE, J B State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 83/09/16 SHEA, J R Office of International Programs, Director 2pp 20663 348

8310060098 Amend 1 to license for Edlow Intl Co extending expiration date to 881231
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/09/21 1p 20663 347

8310060104 License for BMI to import 23 g U. enriched to 93 15%, from Canada
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/09/28 2pp 20663 345

8310060107 License for Biadex, Inc to import 4 mg I-125 from Israel
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/09/22 1p 20663 344

8310060108 License for Amersham Corp to export 2 Ci Cm-244, contained in sealed sources, to Canada
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/09/27 1p 20663 343

8310060114 Amend 3 to Westinghouse export license, extending expiration date from 841231 to 891231
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 0146 83/09/22 1p 20661 089

8310060116 License for B-J Enterprises Inc to export 2,000 element cups & 90 head cups for cobalt adjuster element, reactivity control units & adjuster unit, to Canada
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards AECL 1983 83/09/28 1p 20661 088

8310060120 Application for license to export one WX33356 BF3 detector & four uncompensated ionization chambers to West Germany
HEATHER, W H Westinghouse Electric Corp IE 10552 83/09/14 1p 20661 016

8310060123 Amend 3 to Westinghouse export license, extending expiration date to 891231
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards WP-42090-ARB 83/09/22 1p 20661 012

8310060126 License for Carpenter Technology Corp to export 240 Zircaloy BWR fuel channels to Italy
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards SPD 5732 83/09/28 1p 20661 011

8310060130 Application for license to export 119 kg U hexafluoride, contained in 3,434 kg U. to Japan
FOSTER, C M Edlow International Co KLK-17 83/09/22 1p 20661 010

8310060131 License for Carpenter Technology Corp to export 230 Zircaloy BWR fuel channels to Italy
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards SPD 5732 83/09/28 1p 20661 009

8310060135 Application for license to export 115,424 lb tantalite ore, containing 590 lb U. to West Germany
COYLE, F T KBI Corp 83/09/28 1p 20661 007

8310060141 License for Edlow Intl Co to export 40 mg Cf-252, as cermet wire, to United Kingdom
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards AMER-84 83/09/22 1p 20661 006

8310060143 Amend 2 to Sigma Chemical Co export license, extending expiration date to 851001
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards D-22 83/09/23 1p 20660 360

8310060147 License for Saunders-Roe Developments, Inc to export 360,000 Ci tritium, incorporated in SAFETY-10 TM exit signs, to Canada
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/09/22 1p 20660 359

8310060152 License for IRT Corp to export 11 7 mCi Cf-252, contained in sealed neutron source, to Israel
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards TUBE PS-600 83/09/27 1p 20660 358

8310060156 License for Mitsui & Co, Inc to export 96 kg U-235, contained in 3,632 kg U. to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards MBK TR-14 83/09/28 2pp 20660 346

8310060162 Application for license to export six immersion heaters to Korea
K-C Industries, Inc 50-393 83/09/14 1p 20660 345

8310060177 Application to amend export license, extending expiration date by 5 yrs & increasing value of export
MOORE, W R QA Technologies, Inc /General Atomic Co IEL-5034 83/09/14 ZIMMERMAN, J Assistant Director for Export/Import & International Safeguards 1p 20660 332

8310060180 Ltr of assurance re export of 96 kg U-235, contained in 3,632 kg U. to Japan
SHIRAKAWA, T Japan, Govt of 83/09/07 RAYMOND, J F Energy, Dept of 1p 20660 325

8310060183 License for Exxon Nuclear Co, Inc to export 2,000 kg U-235, contained in 32,000 kg U. to West Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/09/21 2pp 20660 312

8310060187 Requests cancellation of 820505 application to export 50,000 pieces seamless zirconium tubing to Argentina
SHINOHARA, K C Itoh & Co (America), Inc 83/09/12 HEMBY, E O NRC - No Detailed Affiliation Given 1p 20660 311

8310060234 Informs that License XSNM-2043 may be issued No matl changed circumstances since issuance of License XSNM-2046
MOORE, R N Assistant Director for Export/Import & International Safeguards 83/09/21 Assistant Director for Export/Import & International Safeguards 1p 20660 309

8310060240 Forwards C Itoh & Co 830912 ltr requesting license application for export of zirconium tubing to Argentina be withdrawn Records should be so marked W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/09/22 STOIBER, C State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 1p 20660 310

8310060405 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/09/28 RAYMOND, J Energy, Dept of 1p 20660 209

8310060412 Application for license to export 82 microgram Pu-239, Sr-90 & Y-90, contained in calibr std set & 32 microgram Pu-239, contained in alpha calibr std set, to South Korea
ESPINOZA, G J Eberline Instrument Corp 80 NO 894286 83/09/07 1p 20660 208

8310060415 Ltr of assurance re export of 7,770 kg U to Switzerland
MARCHAL, J European Communities, Commission of 83/09/23 RAYMOND, J Energy, Dept of 1p 20660 085

NONDOCKETED ITEMS

8310060420 Ltr of assurance re export of 383 kg U-235 to West Germany
 MARCHAL, J European Communities, Commission of 83/09/12
 RAYMOND, J Energy, Dept of 1p 20660 084

8310060424 Ltr of assurance re export of 2,000 kg U-235 to
 West Germany
 MARCHAL, J European Communities, Commission of 83/09/12
 RAYMOND, J Energy, Dept of 1p 20660 362

8310120453 Amend 1 to Mitsui & Co (USA), Inc export license, changing
 licensee name from Mitsubiline Travel Svc American, Inc to
 Mitsui Air Intl, Inc
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards 83/10/05 1p 20751 283

8310120455 Application to amend licenses to export to reflect name
 change in licensee section
 REYES, A J Mitsui & Co (USA), Inc (subs of Mitsui & Co, Ltd)
 83/09/21 HENBY, E Assistant Director for Export/Import &
 International Safeguards 1p 20751 282

8310120459 Amend 2 to Mitsui Air Intl, Inc export licenses adding "on
 behalf of Mitsui & Co (USA), Inc." in licensee section
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards 83/10/05 1p 20751 281

8310120461 Amend 1 to Mitsui & Co (USA), Inc export license, changing
 name of licensee from Mitsubiline Travel Svc America, Inc to
 Mitsui Air Intl, Inc
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards 83/10/05 1pp 20751 280

8310130023 Amend 1 to Westinghouse export license, revising Condition 7
 to reflect recent changes to 10CFR71
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards MMH 83/10/06 2pp 20777 001

8310130030 Amend 1 to Mitsui Air Intl, Inc export license, changing name
 of licensee from Mitsubiline Travel Svc America, Inc to Mitsui
 Air Intl, Inc
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards 83/10/05 1p 20776 323

8310130032 Amend 1 to Mitsui Air Intl, Inc export license, changing name
 of licensee from Mitsubiline Travel Svc America, Inc to Mitsui
 Air Intl, Inc
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards 83/10/05 1p 20776 322

8310130034 Amend 1 to Mitsui Air Intl, Inc export license, changing name
 of licensee from Mitsubiline Travel Svc America, Inc to
 Mitsui Air Intl, Inc
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards 83/10/05 1p 20776 254

8310130038 Amend 1 to Mitsui Air Intl, Inc export license, changing name
 of licensee from Mitsubiline Travel Svc America, Inc to Mitsui
 Air Intl, Inc
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards 83/10/05 1p 20776 253

8310130050 License for Eberline Instrument Corp to export 114
 micrograms Pu-239, contained in calibr std sets, to South
 Korea
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards SO MO 894286 83/10/06 2pp 20774 358

8310130075 License for Circle Seal Controls to export check valve, Part
 Number P148-34 & quality documentation to Canada
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards P 30282 83/09/30 2pp 20774 356

8310130086 Amend 1 to Transnuclear, Inc export license, extending
 expiration date to 861231
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards TNP-414 83/10/05 2pp 20777 048

8310130092 License for Westinghouse to export 29 ex-core ion chambers
 Type 24016, to Canada
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards RMR 83/09/30 2pp 20777 050

8310130147 License for Westinghouse to export one BF 3 detector, Model
 JK 33356 & four uncompensated ionization chambers, Model
 JK33358, to West Germany
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards ZE 10552 83/10/04 2pp 20777 063

8310130349 Application for license to export fuel assembly components
 end plugs, Zircaloy fuel rod springs, stainless steel fuel
 tubing, Zircaloy nozzles-top & bottom, stainless steel thimble
 assembly instrumentation tubes & grids to United Kingdom
 HERSCH, M M Westinghouse Electric Corp MMH-416 83/09/29 1p
 20754 326

8310130355 Requests Executive Branch position re Westinghouse
 application for license to export, superseding 830511 & 25
 requests
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards 83/10/05 STOIBER, C R State, Dept of, Bureau of
 Oceans & Intl Environ & Scientific Affairs 1p 20754 325

8310130364 Amend 4 to GE export license, consolidating original licens-
 issued 781117 & all subsequent amends through Amend 3 issued
 821013
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards BDW-099-82 83/09/70 1p 20770 355

8310130367 Amend 3 to Monsanto Research Corp export license, extending
 expiration date to 851101 & adding condition that Govt
 approval be obtained before any reexport of matl can be made
 to listed countries
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards B25 5000 83/10/03 2pp 20770 356

8310130369 Application for license to export 25 kg U dioxide pellets
 to Norway
 WILSON, B D General Electric Co BDW-101-83 83/09/22 1p
 20770 358

8310130371 Advises that second aspect of 831022 amend request to
 authorize export of Australian-origin matl will not be
 required at present
 WILSON, B D General Electric Co BDW-97-83 83/09/16 WRIGHT B
 NRC - No Detailed Affiliation Given 1p 20770 359

8310130391 Application for license to export equivalent of 5 kg
 deuterium oxide liquid over 2-yr period to Portugal
 * Sigma Chemical Co D-110 83/09/26 1p 20770 353

8310130396 Application to amend licenses to export, extending expiration
 date 3 addl yrs
 HANNETT, B A Transnuclear, Inc 83/09/28 MOORE, R N Office of
 International Programs, Director 1p 20770 360

8310130399 Application to amend licenses to export, changing licensee
 section to Mitsui Air Intl, Inc
 REYES, A J Mitsubiline Travel Service of America, Inc 83/09/21
 HENBY, E Office of International Programs, Director 1p
 20770 361

8310130401 License for K-C Industries, Inc to export six immersion
 heaters, Model P/N 24030672761, to South Korea
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards 5 D-393 83/10/07 1p 20770 362

8310130405 Amend 1 to Mitsui Air Intl, Inc export license, changing name
 of licensee from Mitsubiline Travel Svc America, Inc to Mitsui
 Air Intl, Inc
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards 83/10/05 1p 20769 347

8310130419 Amend 1 to Mitsui & Co USA, Inc export license changing name
 of licensee from Mitsubiline Travel Svc America, Inc to Mitsui
 Air Intl, Inc
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards 83/10/05 1p 20754 359

8310130422 Application to amend licenses to export, changing licensee
 section to Mitsui Air Intl, Inc
 REYES, A J Mitsubiline Travel Service of America, Inc 83/09/21
 HENBY, E Assistant Director for Export/Import & International
 Safeguards 1p 20769 239

8310170023 Amend B to Transnuclear, Inc import license, extending
 expiration date to 861231
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards 83/10/07 2pp 20798 355

8310170038 Amend 2 to Transnuclear, Inc export license extending
 expiration date to 861201
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards NUK 248 UES/EU/ 83/10/07 2pp 20798 330

8310170041 Amend 1 to Transnuclear, Inc import license, extending
 expiration date to 860101
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards 83/10/07 2pp 20798 362

NONDOCKETED ITEMS

481

8310170679 Amend 2 to GA Technologies, Inc export license, extending expiration date to 831101, increasing dollar value & changing licensee name from GA Co to GA Technologies, Inc
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards IEL-2000 83/10/07 1p 20798 220

8310180001 Forwards application for export license for minor nuclear export Ltr of assurance required W/O encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/10/06 RAYMOND, J Energy, Dept of 1p 20825 088

8310180075 Application for license to export 467 kg U, contained in 13,518 kg U hexafluoride, to Japan
FOSTER, C M Edlow International Co KLK-18 83/10/05 1p 20824 124

8310180112 Application to amend license to export, revising max fuel enrichments
WILSON, B D General Electric Co BDW-108-83 83/10/06
WRIGHT, B L Office of International Programs, Director 1p 20824 042

8310180113 Application for license to export 792 kg U, contained in 22,955 kg U hexafluoride, to Japan
FOSTER, C M Edlow International Co KLK-19 83/10/05 1p 20824 041

8310180143 Forwards application to export 160 millicuries Cf-252 to France
HANNETT, B A Transnuclear, Inc TNP-430 83/10/07 MOORE, R N Office of International Programs, Director 3pp 20827 055

--8310180148 Application for license to export 160 millicuries Cf-252 to France
HANNETT, B A Transnuclear, Inc TNP-430 83/10/07 1p 20827 058

8310180151 Forwards application to export U hexafluoride to Japan
SHIMA, S Mitsui & Co (USA), Inc (subs of Mitsui & Co, Ltd)
HSA-5483-02 83/10/05 Assistant Director for Export/Import & International Safeguards 2pp 20827 047

--8310180155 Application for license to export U hexafluoride, contained in 11,708 kg U, to Japan
SHIMA, S Mitsui & Co (USA), Inc (subs of Mitsui & Co, Ltd)
HSA-5483-02 83/10/05 1p 20827 049

8310180159 License for KBI-Div of Cabot Corp to export natural U, contained in 115,424 lbs tantalite ore, to West Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/10/11 2pp 20827 044

8310180164 License for Nikko Wolverine, Inc to export reactor grade Zircaloy-4 tubing to United Kingdom
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 1309 83/10/12 1p 20827 043

8310180302 Application for license to import 13,000 kg 1 75% U-235 from France
HANNETT, B A Transnuclear, Inc TNP 429 83/10/03 MOORE, R N Office of International Programs, Director 2pp 20826 338

8310180304 Ltr of assurance re export of 309 kg U-235, contained in 11,345 kg U, to Japan
SHIRAKAWA, T Japan, Govt of 83/10/06 RAYMOND, J F Energy, Dept of 1p 20826 360

8310180307 Ltr of assurance re export of 937 kg U-235, contained in 32,445 kg U, to Japan
SHIRAKAWA, T Japan, Govt of 83/10/06 RAYMOND, J F Energy, Dept of 1p 20826 361

8310180310 Application to amend licenses to export to accommodate std deviation allowance in fuel design
WILSON, B D General Electric Co BDW-108-83 83/10/06
WRIGHT, B L NRC - No Detailed Affiliation Given 1p 20826 362

8310180341 Application for license to import 4 mg U-235, in form of U oxide, from United Kingdom
GREEN, A R Centronic, Inc 83/10/04 MOORE, R N Office of International Programs, Director 1p 20827 123

8310180555 Amend 1 to license for B&W to import 25.2 kg U, containing up to 23.7 kg U-235, from Canada
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/10/14 1p 20827 122

8310180561 Application for Amend 1 to import license, increasing quantity to 23 700 kg U-235
REGAN, N A Babcock & Wilcox Co 83/10/10 1p 20824 357

8310180562 Telcopy application to amend license to export correcting ultimate consignee address
FOSTER, C Edlow International Co 83/10/05 WRIGHT, B Assistant Director for Export/Import & International Safeguards 1p 20827 118

--8310180565 Telcopy application to amend license to export changing ultimate consignee address
* Edlow International Co 83/10/03 MOORE, R N Office of International Programs, Director 1p 20827 119

8310180564 License for Saunders-Roe Developments, Inc to export 360,000 Ci tritium to all destinations except Kampuchea, North Korea, Cuba & Vietnam
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/10/12 2pp 20827 116

8310180577 Forwards application to export natural enriched U hexafluoride, in form of cylinder heels, to Canada
WILSON, B D General Electric Co BDW-105-83 83/10/05 HEMB, E N Office of International Programs, Director 1p 20827 108

--8310180580 Application for license to export natural enriched U hexafluoride, in form of cylinder heels, to Canada
WILSON, B D General Electric Co BDW-106-83 83/10/05 1p 20827 109

8310200331 Ltr of assurance re export of 21.4 g U-235, contained in 24 g U, to Canada
DOISVENUE, L Canada, Atomic Energy Control Board 83/09/28
RAYMOND, J F Energy, Dept of 3pp 20844 269

8310240300 License for Westinghouse to export specially designed or prepared fuel assembly components to United Kingdom
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards MMH-416 83/10/19 2pp 20904 356

8310240301 Forwards application to export three demonstration fuel elements, w/low enriched U, to Sweden
FOSTER, C M Edlow International Co 83/10/13 MOORE, R N Assistant Director for Export/Import & International Safeguards 1p 20907 031

--8310240302 Application for license to export three demonstration fuel elements, w/low enriched U, to Sweden
FOSTER, C M Edlow International Co STUDB-B&W 83/10/13 1p 20907 032

8310240306 Informs that License X8NM-2057 may be issued No matl changed circumstances since issuance of License X8NM-2055
MOORE, R N Assistant Director for Export/Import & International Safeguards 83/10/17 Assistant Director for Export/Import & International Safeguards 1p 20907 033

--8310240309 License for OE to export 309 kg U-235, contained in 11,345 kg U, to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards BDW-073-83 83/10/17 2pp 20907 034

8310240311 Application to amend import license, extending expiration date to 870101
WILSON, B D General Electric Co BDW-112-83 83/10/11
WRIGHT, B L Assistant Director for Export/Import & International Safeguards 1p 20904 361

8310240313 Application for license to export initial fuel loadings for NSSS to Egypt
MACPHERSON, B J Combustion Engineering, Inc. 83/10/07 Assistant Director for Export/Import & International Safeguards 4pp 20907 323

8310240314 License for OE to export 937 kg U-235, contained in 32,445 kg U, to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards BDW-074-83 83/10/17 2pp 20907 321

8310240316 Forwards application for export license for minor nuclear export Ltr of assurance required, W/O encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/10/18 RAYMOND, J Energy, Dept of 1p 20907 320

NONDOCKETED ITEMS

310240322 Informs that License XSNM-2058 may be issued. No matl changed circumstances since issuance of License XSNM-2055
MOORE, R N Assistant Director for Export/Import & International Safeguards 83/10/17 Assistant Director for Export/Import & International Safeguards 1p 20907 162

310250016 Application for license to export one compensated ionization chamber, Model HL230B4, to Japan
HEETHER, W H Westinghouse Electric Corp ZE 60282 83/10/11 3pp 20908 360

310250020 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/10/17 RAYMOND, J Energy, Dept of 1p 20916 108.

310250135 Application for license to export reload fuel for 950 to 1300 MW electrical NSSS to Egypt
MACPHERSON, B J Combustion Engineering, Inc 83/10/07 Assistant Director for Export/Import & International Safeguards 4pp 20908 333

310250142 License for Sigma Chemical Co to export 5.0 kg deuterium oxide to Portugal
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards D-110 83/10/18 2pp 20908 331.

310250150 License for Transnuclear, Inc to export 160.0 mCi Cf-252, as oxide, to France
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards TNP-430 83/10/17 1p 20908 330.

310250158 Application for license to export one 950 to 1,300 MW NSSS to Egypt
MACPHERSON, B J Combustion Engineering, Inc 83/10/07 Assistant Director for Export/Import & International Safeguards 3pp 20908 327

310250164 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/10/19 RAYMOND, J Energy, Dept of 1pp 20908 326

310250172 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/10/17 RAYMOND, J Energy, Dept of 1p 20908 325

310250178 Requests Executive Branch position re Transnuclear, Inc application for license to export highly enriched U to Switzerland.
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/10/18 STOIBER, C State, Dept. of, Bureau of Oceans & Intl. Environ & Scientific Affairs. 1p 20908 323

310250658 Application for license to export Pu-239 alpha calibr std, Model DNS-10, to Canada
LITTLE, J Eberline Instrument Corp SOND893347. 83/10/11 1p 20908 280

0260004 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/10/18 RAYMOND, J Energy, Dept of 1pp. 0921 193

0260009 Application to amend export license, extending expiration date to 870101
ILSDON, B D General Electric Co BDW-111-B3 83/10/11 WRIGHT Office of International Programs, Director 1pp 20928 047

0260015 Application for license to export natural enrichment U, as U oxide power, to Canada
General Electric Co BDW-110-B3 83/10/10. 1p. 20928 082

0260018 Application for license to export three BFD proportional counters, Model ML-24010, to Belgium
HEETHER, W H Westinghouse Electric Corp ZE-20644. 83/10/14. 1p 0921 362

0260020 License for Battelle Columbus Labs to export 23 g U, contained in 21.4 g U-235, to Canada.
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83-1, 83/10/19, 2pp 20921 360

8310260022 Application for license to export fission counter, Model RS-P6-1608-110 & neutron compensated ionization chamber, Model RS-C1-2514-115, to Mexico
* Reuter-Stokes, Inc D-9986 83/09/19 2pp 20926 357

8310260036 Forwards application to export spare valve assemblies & parts for support of installed units on fuel handling equipment to Argentina
DAVIS, E H Marotta Scientific Controls, Inc 83/10/05 Assistant Director for Export/Import & International Safeguards 1pp 20921 357

--8310260042 Application for license to export spare valve assemblies & parts for support of installed units on fuel handling equipment to Argentina
DAVIS, E H Marotta Scientific Controls, Inc SD 60131 83/10/04 1p 20921 358

8310260039 Amend 1 to GE import license, extending expiration date to 870101
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/10/18 2pp 20921 355

8310260057 Amend 1 to Eberline Instrument Corp export license, revising Condition 9 to take into account recent changes to 10CFR71
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards SD NO 894259 83/10/19 2pp 20921 352

8310260064 Application for license to export 0.008 g Np-237 standardized solution to Canada
* Amersham Corp 83/10/17 1p 20921 318

8310260068 Forwards application for license to export spare parts for ball spline assemblies that load & unload fuel elements into reactor to Canada
SCHAUB, J B General Motors Corp 83/10/06 HEMBY, E Assistant Director for Export/Import & International Safeguards 1p 20918 361

--8310260073 Application for license to export spare parts for ball spline assemblies that load & unload fuel elements into reactor to Canada
SCHAUB, J B General Motors Corp WD 84100 83/10/03 1p 20918 362

8310260079 Requests Executive Branch position re C-E applications for license to export 10 nuclear fuel reloads, nuclear fuel for initial core & 950 to 1,300 MW electrical NSSS to Egypt
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/10/20 STOIBER, C R State, Dept of 1p 20921 266

8310260323 Application for license to import natural U ore concentrates, containing approx 1,500,000 lb U-308
MOYER, R E Pathfinder Mines Corp 83/10/18 MOORE, N Assistant Director for Export/Import & International Safeguards 1p 20918 345

8310260328 Amend 2 to Eberline Instrument Corp export license, revising Condition 9 on Page 2 to take into account recent changes to 10CFR71, effective 830906
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards SD NO 894286 83/10/19 2pp 20918 346

8310270074 Responds to FOIA request for info re nuclear cooperation between South Africa & US for period of 1960-65 Forwards documents listed in App A Documents also available in PDR DOE should be contacted for further info
FELTON, J M Division of Rules and Records 83/10/11 KETTERING, N E New Hampshire, Univ of, 3pp 20942 195

--8310270080 Forwards License XR-42 for cancellation W/o encl
KELLY, J P Treasury, Dept of, U S Customs Service J-WIM-JTC 1G 66/01/27 Atomic Energy Commission 1p 20942 198

--8310270092 Expresses appreciation for expeditious handling of Export License XR-42
ABEL, L E Allis-Chalmers Corp 63/11/14 CASE, E G Atomic Energy Commission 1p 20942 200

--8310270097 Advises of issuance of amend to License XR-42, increasing total price & extending expiration date to 631231
PRICE, E R Atomic Energy Commission 63/11/14 LYONS, T D Allis-Chalmers Corp 2pp 20942 201

--8310270100 Authorizes clearance of partial shipment on 631115 against License XR-42, permitting export of nuclear reactor to South Africa, Amended license forthcoming
PRICE, E R Atomic Energy Commission 63/11/14 COLLIGAN, W Treasury, Dept of, U S Customs Service 2pp 20942 203

NONDOCKETED ITEMS

487

--B310270105 Application for amend to Export License XR-42, extending date to 651231 & increasing value
LYONS, T D Allis-Chalmers Corp 63/11/12 MASON, N D Atomic Energy Commission, 2pp 20942 205

--B310270109 Forwards License XR-42 issued to Allis-Chalmers, covering matl destined for South Africa, for placement in file No shipments made yet
MESSING, A W Affiliation Unknown 61/12/18 Treasury, Dept of, U S Customs Service 1p 20942 207

--B310270113 License for Allis-Chalmers Mfg Co to export nuclear reactor to South Africa
KIRK, R L Atomic Energy Commission 61/06/14 2pp 20942 208

--B310270116 Informs of 610620 FR publication of notice of issuance of License XR-42 to Allis-Chalmers Mfg Co, authorizing export of nuclear reactor to South Africa
FREDERICK, R J Atomic Energy Commission 61/06/21 Atomic Energy Commission 1p 20942 209

--B310270122 Informs of issuance of license to Allis-Chalmers Mfg Co, authorizing export of 20,000 kW thermal nuclear reactor to South Africa
KIRK, R L Atomic Energy Commission 61/06/15 RAHEY, J T Congress (Joint & Rotating Committees, etc) 1p 20942 211

--B310270133 Forwards License XR-42 issued to Allis-Chalmers Mfg Co, authorizing export of nuclear reactor to South Africa Govt of South Africa should be advised that license does not imply Commission assumption of responsibility for safety
LOWENSTEIN, R Atomic Energy Commission 61/06/14 WELLS, A A Atomic Energy Commission 1p 20942 213

--B310270139 Forwards License XR-42, authorizing export of nuclear reactor to South Africa w/o encl
KIRK, R L Atomic Energy Commission 61/06/14 NICKEL, H C Allis-Chalmers Corp 1p 20942 214

--B310270144 Informs that since no request for formal hearing filed, License XR-42 issued to Allis-Chalmers Mfg Co, authorizing export of nuclear reactor to South Africa
LOWENSTEIN, R Atomic Energy Commission 61/06/14 PRICE, H L Atomic Energy Commission 1p 20942 215

--B310270147 Notice of issuance of License XR-42 to Allis-Chalmers Mfg Co, authorizing export of nuclear reactor to South Africa
KIRK, R L Atomic Energy Commission 61/06/14 1p 20942 216

B310270540 Amend 1 to Eberline Instrument Corp export license, revising Condition 9 on Page 2 to take into account recent changes to 10CFR71, effective 830906
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 80 ND 894286 83/10/19 2pp 20938 035

B310270543 Amend 2 to GE export license, extending expiration date to 870101
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 80 ND 79202 83/10/19 2pp 20938 037

B310280026 Forwards application to export 4 879 kg U-235, contained in 10 747 kg U hexafluoride, to Switzerland
HANNETT, B A Transnuclear, Inc NUK-431 83/10/13 MOORE, N Office of International Programs, Director 1p 20964 136

--B310280033 Application for license to export 4 879 kg U, contained in 10 747 kg U hexafluoride, to Switzerland End use statement encl
HANNETT, B A Transnuclear, Inc NUK-431 83/10/13 7pp 20964 137

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AAMODT, N O	8310260294	50-289 Q	ALDEN, W M	8310260263*	50-277 R	ANDERSEN, M W	8310210090	50-331 S
ABEL, L E	8310270092*	FOIA	ALDEN, W M	8310200264*	50-277 R	ANDERSEN, M W	8310270290	50-331 S
ABELSON, H	8310260346	50-461 A	ALDERSON, C E	8310110059*	50-413 Q	ANDERSON, C	8310060012*	50-410 Q
ABRAMS, R	8310190009	TOPREP	ALEXANDER, C N	8310240060*	50-413 T	ANDERSON, C	8310190180*	50-443 Q
ABSTON, O O	8310240176*	FOIA	ALEXANDER, I	8310240218*	50-528 Q	ANDERSON, C J	8310200270*	50-289 Q
ABSTON, O O	8310280214*	50-400 A	ALEXANDER, I	8310240239*	50-528 Q	ANDERSON, F D	8310050224	NUREQ
ABSTON, O O	8310280222*	50-400 A	ALEXICH, M P	8310030386	50-315 P	ANDERSON, P H	8310140119*	50-275 R
ABSTON, O O	8310280236*	50-400 A	ALEXICH, M P	8310030391	50-315 F	ANDERSON, P H	8310280164	50-400 Q
ABSTON, O O	8310280248*	50-400 A	ALEXICH, M P	8310030379*	50-315 F	ANDERSON, P H	8310280164	50-400 Q
ABSTON, O O	8310280256*	50-400 A	ALEXICH, M P	8310050563	50-315 P	ANDOGNINI, Q C	8310040307	PR
ACE, J K	8310180376*	CONTRACT	ALEXICH, M P	8310060006	50-315 P	ANDROSIK, R	8310250387	50-317 S
ADAMS, C	8310250147	DRQ	ALEXICH, M P	8310140040	50-315 P	ANDROSIK, R	8310280081	50-317 S
ADAMS, C	8310250416	50-275 Q	ALEXICH, M P	8310200158	50-315 P	ANDRUS, N J	8310140295	40-4492
ADAMS, C	8310250391	50-312 P	ALEXICH, M P	8310270196*	50-315 F	ANTHONY, R L	8310270277	50-352 Q
ADAMS, F T	8310120415*	50-261 P	ALIKONIS, N A	8310070210*	CONTRACT	ANTHONY, R L	8310190044*	50-352 Q
ADAMS, F T	8310120422*	50-261 P	ALLAN, J M	8310110139*	70-1487	APOSTOLAKIS, Q	8310200184*	50-275 T
ADCOCK, B R	8310210413*	50-170 F	ALLAN, J M	8310240181*	FOIA	APOSTOLAKIS, Q	8310200184*	50-275 T
ADDTB, B Q	8310240040*	50-413 T	ALLAN, J M	8310260021*	FOIA	ARAND, J J	8310140045	50-373 S
ADDTSON, E T	8310210295	50-352 H	ALLAN, J M	8310260023*	FOIA	ARAND, J J	8310140069	50-373 S
ADENSAM, E Q	8310030601	50-329 F	ALLAN, J M	8310260038*	FOIA	ARCHITZEL, R	8310310230*	50-317 Q
ADENSAM, E Q	8310030606	50-329 F	ALLAN, J M	8310260056*	FOIA	ARCHITZEL, R E	8310200107*	50-317 Q
ADENSAM, E Q	8310120043	50-327 P	ALLAN, J M	8310260076*	FOIA	ARCHIBOLD, D	8310280081	50-317 S
ADENSAM, E Q	8310120046*	50-327 P	ALLAN, J M	8310260077*	FOIA	ARIAS, J	8310030262	50-251 S
ADENSAM, E Q	8310120050*	50-327 P	ALLAN, J M	8310260100*	FOIA	ARIAS, J	8310270277	50-251 S
ADENSAM, E Q	8310120056*	50-327 P	ALLAN, J M	8310260138*	FOIA	ARMERBUST, A J	8310170390	27-39
ADENSAM, E Q	8310130029	50-328 P	ALLAN, J M	8310260153*	FOIA	ARMSTRONG, S	8310180321*	50-482 E
ADENSAM, E Q	8310130039*	50-328 P	ALLAN, J M	8310260157*	FOIA	ARMSTRONG, S	8310180325*	50-482 E
ADENSAM, E Q	8310170133	50-327 P	ALLAN, J M	8310260161*	FOIA	ARMSTRONG, W	8310110509*	FOIA
ADENSAM, E Q	8310170234*	50-327 P	ALLAN, J M	8310260167*	FOIA	ARNOLD, Q A	8310120005	50-201 I
ADENSAM, E Q	8310170289	50-329 P	ALLAN, J M	8310260176*	FOIA	ARNOLD, R C	8310130088	50-320 P
ADENSAM, E Q	8310170710	50-369 P	ALLAN, J M	8310260182*	FOIA	ARNOLD, R C	8310130114	50-289 P
ADENSAM, E Q	8310170719*	50-369 P	ALLAN, J M	8310260207*	FOIA	ARNOLD, R C	8310180575*	50-320 P
ADENSAM, E Q	8310170725	50-370 A	ALLAN, J M	8310260213*	FOIA	ARNOLD, R C	8310180548*	50-320 P
ADENSAM, E Q	8310180604	50-424 A	ALLAN, J M	8310260327*	FOIA	ARNOLD, R C	8310180548*	50-320 P
ADENSAM, E Q	8310180606*	50-424 A	ALLAN, J M	8310260329*	FOIA	ARNOLD, R C	8310180548*	50-320 P
ADENSAM, E Q	8310210106	50-424 M	ALLAN, J M	8310260337*	FOIA	ARNON, L	8310270577*	CONTRACT
ADENSAM, E Q	8310210109*	50-424 M	ALLAN, J M	8310260345*	FOIA	ARMUND, V C	8310170675*	70-984
ADENSAM, E Q	8310210341	50-328 P	ALLAN, J M	8310260372*	FOIA	ASSELBTINE, J K	8310030316*	50-309 S
ADENSAM, E Q	8310280037	50-369 P	ALLAN, J M	8310270547*	50-277 S	ASSELBTINE, J K	8310200364*	FOIA
ADENSAM, E Q	8310310443	50-438 A	ALLEN, D R	8310210093*	CONTRACT	ASSELBTINE, J K	8310240251*	50-528 Q
ADISOMA, O B	8310070414	NUREQ	ALLEN, M T	8310190238	50-324 S	ATKINSON, R V	8310250047	50-352 H
ADLER, M	8310240173*	FOIA	ALLEN, W F	8310170198*	50-423 A	ATWOOD, C L	8310050331	NUREQ
ADLER, M	8310240175*	FOIA	ALLISON, D P	8310190270*	50-434 Q	AUDETTE, R	8310240195*	FOIA
AFTERGOOD, B	8310190035	FOIA	ALLUM, A E	8310240056*	50-413 T	AULICK, D D	8310060193*	50-400 Q
AGEE, J R	8310250206*	QA999	ALQUIST, A E	8310240169	50-275 U	AULICK, D D	8310060193*	50-400 Q
AQDBTI, F E	8310210052	50-341 A	ALSNORTH, M	8310040565*	50-382 A	AULICK, D D	8310060203*	50-400 Q
AQDBTI, F E	8310210281	50-341 A	ALTMAN, W D	8310180517*	50-275 P	AULICK, D D	8310060203*	50-400 Q
AHEARNE, J	8310270138*	FOIA	ALTMAN, W D	8310200437*	COMMISSION	AULICK, D D	8310060323	50-400 Q
AHMED, I H	8310050497*	50-341 Q	ALTMAN, W D	8310200461*	COMMISSION	AULICK, D D	8310060323	50-400 Q
AHMED, N	8308180560*	50-346 P	ALTMAN, W D	8310200463*	COMMISSION	AULICK, D D	8310170543	50-400 Q
ALAMQIR, M	8310310209	NUREQ	ALTMAN, W D	8310200464*	COMMISSION	AULICK, D D	8310170543	50-400 Q
ALBRIGHT, R H	8310040168*	50-261 Q	AMOS, C N	8310070110	NUREQ	AULICK, D D	8310170608*	50-400 Q
ALBRIGHT, R H	8310250477*	50-324 Q	ANANDAPPA, A	8310210127	50-237 S	AULICK, D D	8310170608*	50-400 Q
ALBRIGHT, R H	8310250501*	50-324 Q	ANDERSEN, J Q	8310180085	NUREQ	AULUCK, R	8310130212	50-397 A
ALDEN, W M	8310200261*	50-277 R	ANDERSEN, M	8310190068	50-331 R	AULUCK, R	8310130426	50-397 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AUSTIN, G	8310120108	50-295 R	BAJADA, E C	8310270038	TOPREP	BAUBLITZ, J E	8310030605	WASTE MOT
AUSTIN, M A	8310070028*	70-364	BAKER, D A	8310070442	MUREG	BAUBLITZ, J E	8310130067	WASTE MOT
AUSTIN, M A	8310070035*	70-364	BAKER, K R	8310040030	PR	BAUER, T L	8310110396*	50-192 F
AUSTIN, M A	8310070040*	70-364	BALDWIN, C R	8310240057*	50-413 T	BAUER, T L	8310110429*	50-192 F
AUSTIN, M A	8310250273	TOPREP	BALDWIN, M S	8310170098*	50-338 S	BAVEREIS, E I	8310120262	50-317 S
AXELRAD, J	8308310105	I&E	BALL, C G	8310110369*	FOIA	BAUNACK, W	8310140166*	50-289 Q
AXELRAD, J	8310030440	50-344 S	BALL, C G	8310110375*	FOIA	BAUTER, T A	8310310144	50-400 Q
AXELRAD, J	8310030520	I&E	BALL, C G	8310110384*	FOIA	BAUTER, T A	8310310146	50-400 Q
AXELRAD, J	8310040214	50-272 Q	BALLINGER, P L	8310190024	50-298 R	BAUTER, T A	8310310200	50-483 Q
AXELRAD, J	8310050536	I&E	BANAGAS, L J	8310040207	50-267 S	BAUTER, T A	8310310200	50-483 Q
AXELRAD, J	8310060005	50-220 Q	BANERJI, S K	8310170308	40-8801	DAYBUTT, P	8310110475*	FOIA
AXELRAD, J	8310060092	50-62 S	BANERJI, S K	8310200409	40-8801	DAYBUTT, P	8310110480*	FOIA
AXELRAD, J	8310140060	I&E	BARAMORE, S	8310190042*	50-329 A	DAYNE, J P	8310040291	PR
AXELRAD, J	8310140237	I&E	BARAMORE, S	8310190031	50-219 R	DAYNE, J P	8310070248	50-286 V
AXELRAD, J	8310180199	I&E	BARAN, R	8310190031	50-219 R	DAYNE, J P	8310070340	50-286 P
AXELRAD, J	8310180413	I&E	BARANOW, S W	8310170360*	50-329 Q	DAYNE, J P	8310070349	50-286 P
AXELRAD, J	8310210020	50-329 Q	BARANOW, S W	8310170564*	50-329 Q	DAYNE, J P	8310110112	50-333 P
AXELRAD, J	8310310406	40-299	BARANOW, S W	8310170567*	50-329 Q	DAYNE, J P	8310110222	50-286 P
AXELRAD, J A	8310050078	50-250 Q	BARANOW, S W	8310170571*	50-329 Q	DAYNE, J P	8310110228*	50-286 P
AXELRAD, J A	8310130146	50-410 Q	BARANOW, S W	8310170575*	50-329 Q	DAYNE, J P	8310130113	50-333 Q
AXELRAD, J A	8310190226	40-672	BARANOW, S W	8310170598*	50-329 Q	DAYNE, J P	8310140196	50-333 P
AXELRAD, J A	8310270493	50-255 Q	BARANOW, S W	8310170602*	50-329 Q	DAYNE, J P	8310170480	50-333 Q
AXELRAD, M	8310120036*	50-201 I	BARANOW, S W	8310170606*	50-329 Q	DAYNE, J P	8310170554	50-286 P
AXELRAD, M	8310180354	50-275 T	BARANOW, S W	8310170610*	50-329 Q	DAYNE, J P	8310170655*	50-333 P
AXELSON, W L	8310180116	50-456 Q	BARANOW, S W	8310190036*	50-329 A	DAYNE, J P	8310210126	50-333 F
AXELSON, W L	8310180187	50-373 Q	BARANOW, S W	8310270176*	50-329 Q	DAYNE, J P	8310240114	50-286 P
AXELSON, W L	8310180195	50-282 Q	BARANOW, S W	8310310114	MUREG	DAYNE, J P	8310240135	50-286 F
AXELSON, W L	8310180197	50-358 Q	BARANOW, S W	8310310114	MUREG	DAYNE, J P	8310280044	50-333 F
AXELSON, W L	8310180202	50-346 Q	BARNES, I	8308300722*	QA999	DAYNE, J P	8310310043	50-333 P
AXELSON, W L	8310180203	50-235 Q	BARNES, I	8310030352*	QA999	DAYNE, J P	8310310066	50-286 P
AXELSON, W L	8310180203	50-235 Q	BARNES, I	8310030459*	QA999	DAYNE, J P	8310310066	50-286 P
AXELSON, W L	8310180205	50-305 Q	BARNES, I	8310040249*	QA999	DAYNE, J P	8310310364	50-333 Q
AXELSON, W L	8310180206	50-331 Q	BARNES, I	8310180358*	QA999	DAZIN, J P	8310110086	CONTRACT
AXELSON, W L	8310180215	50-440 Q	BARNES, I	8310180378*	QA999	DAZIN, J P	8310110185	CONTRACT
AXELSON, W L	8310180233	50-546 Q	BARNES, I	8310180519*	QA999	DAZIN, J P	8310110494	CONTRACT
AXELSON, W L	8310180238	50-254 Q	BARNES, I	8310250008*	QA999	DEACH, Q	8310230169	40-6622
AXELSON, W L	8310180260	50-483 Q	BARNES, I	8310250526*	QA999	DEACHUM, S B	8310120221*	50-155 T
AXELSON, W L	8310180261	50-266 Q	BARNES, P L	8310120061	50-265 Q	DEAM, D Q	8310240053*	50-413 T
AXELSON, W L	8310180262	50-155 Q	BARNES, P L	8310120290	50-373 Q	DEAMER, W H	8310110097*	FOIA
AXELSON, W L	8310180265	50-329 Q	BARNES, P L	8310200273	50-237 P	DEARD, J T	8310110604	MISC
AXELSON, W L	8310180268	50-10 Q	BARNES, V E	8310130134*	MISC	DEARDEN, D A	8310030311	PR
AXELSON, W L	8310180271	50-461 Q	BARNETT, B J	8310280166	50-483 M	DEATTY, E J	8310250217	50-244 S
AXELSON, W L	8310180274	50-409 Q	BARR, K	8310140170*	50-320 Q	DEAVER, B	8310110421*	50-369 F
AXELSON, W L	8310180283	50-295 Q	BARR, K P	8310040168*	50-261 Q	DEAVER, B	8310270146*	50-369 F
AXELSON, W L	8310180288	50-263 Q	BARR, K P	8310040340*	70-143	BECHHOEFER, B Q	8310120011*	50-201 I
AXELSON, W L	8310180289	50-341 Q	BARR, K P	8310040499*	50-321 Q	BECHHOEFER, B Q	8310120015*	50-201 I
AXELSON, W L	8310180295	50-454 Q	BARR, K P	8310040508*	70-27	BECHHOEFER, B Q	8310120023*	50-201 I
AXELSON, W L	8310180376	50-315 Q	BARR, K P	8310040637*	70-1151	BECHHOEFER, B Q	8310120047*	50-201 I
AXELSON, W L	8310250375	70-2977	BARR, K P	8310230328*	50-280 Q	BECHHOEFER, C	8310030514	50-329 Q
AXELSON, W L	8310310318	I&E	BARR, K P	8310250387*	50-348 Q	BECHHOEFER, C	8310110210	50-329 Q
AXELSON, W L	8310310342	50-341 Q	BARR, K P	8310250428*	50-338 Q	BECHHOEFER, C	8310280100	50-329 Q
AXTELL, C E	8310040373*	50-155 T	BARR, K P	8310250477*	50-324 Q	BECHHOEFER, C	8310310211	50-329 Q
AXTELL, C E	8310040364*	50-155 T	BARR, K P	8310250501*	50-324 Q	BECK, I J	8308310512*	50-267 Q
BACHMANN, R Q	8310170493	50-266 Q	BARR, K P	8310250540*	50-369 Q	BECK, C K	8310260095*	FOIA
BACHMANN, R Q	8310230160	50-155 Q	BARR, K P	8310250554*	70-1113	BECK, C K	8310260130*	FOIA
BACHUS, R A	8310030355	50-443 Q	BARR, K P	8310250621*	50-335 Q	BECK, J W	8310210275*	50-329 R
BACHUS, R A	8310030355	50-443 Q	BARRETT, L H	8310050146	50-320 R	BECKER, B D	8310060321*	50-454 Q
BACHUS, R A	8310110227	50-443 Q	BARRETT, L H	8310050326	50-320 R	BECKER, B D	8310060321*	50-454 Q
BACHUS, R A	8310110227	50-443 Q	BARRETT, L H	8310060164	50-320 R	BECKER, B D	8310180279*	50-454 Q
BACHUS, R A	8310120107	50-443 Q	BARRETT, L H	8310060181	50-320 R	BECKER, B D	8310180279*	50-454 Q
BACHUS, R A	8310120107	50-443 Q	BARRETT, L H	8310110531	50-320 P	BECKER, J D	8310270384	50-295 S
BACHUS, R A	8310120111*	50-443 Q	BARRETT, L H	8310180007	50-320 R	BELL, G H	8310240043*	50-413 T
BACHUS, R A	8310120111*	50-443 Q	BARRETT, L H	8310180122	50-320 R	BELL, J	8310140166*	50-289 Q
BACHUS, R A	8310120113*	50-443 Q	BARRETT, L H	8310190245	50-320 P	BELL, J M	8310260204*	FOIA
BACHUS, R A	8310120113*	50-443 Q	BARRY, Z E	8310270354*	50-291 S	BELL, M J	8310240242	WASTE MOT
BACHUS, R A	8310120122*	50-443 Q	BARTH, C	8310170626	50-400 Q	BELL, N	8310310063	50-317 P
BACHUS, R A	8310120122*	50-443 Q	BARTH, C A	8310030508	50-400 Q	BELLOTTI, F X	8310040256	50-443 Q
BACHUS, R A	8310120126*	50-443 Q	BARTH, C A	8310030565	50-400 Q	BELLOTTI, F X	8310040262*	50-443 Q
BACHUS, R A	8310120126*	50-443 Q	BARTH, C A	8310170632*	50-400 Q	BELLOTTI, F X	8310040277*	50-443 Q
BACHUS, R A	8310120135*	50-443 Q	BARTH, C A	8310230125	50-400 Q	BELTRACCHI, L	8310130393	MUREG
BACHUS, R A	8310120135*	50-443 Q	BARTH, C A	8310250167	50-400 Q	BENIS, P	8310230339*	50-261 Q
BACHUS, R A	8310120141*	50-443 Q	BARTH, C A	8310250469	50-400 Q	BENNETT, C J	8310250627*	50-261 Q
BACHUS, R A	8310120141*	50-443 Q	BARTER, W D	8310190243	MUREG	BENNETT, C J	8310070432*	CONTRACT
BAER, R E	8310060391*	50-382 Q	BASKIN, K P	8305240501	50-206 P	BENZ, E F	8310040613*	50-400 Q
BAER, R E	8310180161*	50-298 Q	BASKIN, K P	8310110128	50-361 P	BENZ, E F	8310250632*	50-400 Q
BAETSEN, L A	8310120206	50-305 F	BASKIN, K P	8310110133*	50-361 P	BENARDY, V.	8308180258*	50-282 S
BATLEY, F C	8310030431*	QA999	BASKIN, K P	8310270454	50-361 S	BENNETT, C J	8310250293	50-254 P
BAIR, O G	8310140246	50-344 S	BASKIN, K P	8310200068*	COMMISSION	BENNETT, C J	8310070432*	CONTRACT
BAIR, O G	8310250444	50-344 S	BASKIN, K P	8310200400*	50-440 A	BENNETT, C J	8310040369*	50-155 T
BAIRD, J B	8310030457*	50-267 Q	BASSO, L F	8310200154	50-318 S	BERBERIAN, M J	8310070301	50-10 S
BAIRD, J B	8310180246*	50-285 Q	BASSO, L F	8310250287	50-318 S	BERG, J P	8310170101	FOIA
BAIRD, J B	8310310264*	50-443 Q	BASSO, L F	8310250369	50-318 S	BERGER, J D	8310170011	40-86
BAIRD, J B	8310310286*	50-298 Q	BASSO, L F	8310250399	50-318 S	BERNABEI, L	8310110071	50-329 Q
BAISDEN, L	8310170060	CONTRACT	BATES, J W	8310040342*	70-824	BERNABEI, L	8310170383	50-329 Q
BAISDEN, L	8310210083	CONTRACT	BATTERSON, S	8310190012	50-29 R	BERNABEI, L	8310170383	50-329 Q
BAISDEN, L	8310210189	CONTRACT	BATTERSON, S	8310190033	50-309 R	BERNABEI, L	8310170393	50-329 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BERNABEI, L	8310170393	50-329 G	BLAKE, E L	8310110280	50-382 0	BOOKER, J E	8310270181	50-458
BERNABEI, L	8310170427	50-329 G	BLAKE, E L	8310110280	50-382 0	BOOKER, J E	8310280011	50-458
BERNABEI, L	8310170427	50-329 G	BLAKE, E L	8310120395	50-289 0	BOOKER, J E	8310280030	50-458
BERNABEI, L	8310170524	50-329 G	BLAKE, E L	8310120395	50-289 0	BOOKER, J E	8310280053	50-458
BERNABEI, L	8310170524	50-329 G	BLAKE, E L	8310170398	50-382 0	BOOKER, J E	8310280084	50-458
BERNABEI, L	8310190050	50-329 G	BLAKE, E L	8310170398	50-382 0	BOOKER, J E	8310280117	50-458
BERNABEI, L	8310240194	50-328 G	BLAKE, E L	8310180355	50-289 0	BORTH, L F	8310060079	70-143
BERNABEI, L	8310240215*	50-328 G	BLAKE, E L	8310180355	50-289 0	BORDENICK, B M	8310050359	50-322
BERNABEI, L	8310270345	50-329 G	BLAKE, E L	8310200211	50-289 0	BORDENICK, B M	8310050378	50-322
BERNABEI, L	8310270345	50-329 G	BLAKE, E L	8310200211	50-289 0	BORDENICK, B M	8310050395	50-322
BERNABEI, L	8310280145	50-329 G	BLAKE, E L	8310210249	50-289 0	BORDENICK, B M	8310050427	50-322
BERNABEI, L	8310280145	50-329 G	BLAKE, E L	8310210249	50-289 0	BORDENICK, B M	8310130245	50-322
BERNHOF, S L	8310210304	50-305 S	BLAKE, E L	8310310195	50-382 0	BORDENICK, B M	8310170465	50-322
BERNHOF, S L	8310210317	50-305 S	BLAKE, E L	8310310195	50-382 0	BORDENICK, B M	8310240033	50-322
BERNSTEIN, B	8310190213	50-333 S	BLAKE, E L	8310310198	50-289 0	BORDINE, T C	8310040264	50-155
BERNTHAL, F	8310180145	50-247 G	BLAKE, E L	8310310198	50-289 0	BORDINE, T C	8310120110	50-155
BERRY, A E	8310210223	50-251 S	BLAKE, E L	8310310382	50-289 0	BORDINE, T C	8310130296	50-155
BERRYMAN, R M	8310190057*	50-280 P	BLAKE, E L	8310310382	50-289 0	BORDINE, T C	8310170465	50-155
BERTUCCA, J	8310070414	NJREO	BLAKE, J	8310270224	50-325 S	BORDINE, T C	8310170486	50-155
BESS, J E	8310130252*	50-458 G	BLAKE, J J	8310040283*	50-259 G	BORDINE, T C	8310170552	50-155
BESS, J E	8310170683	50-445 T	BLAKE, J J	8310040316*	50-250 0	BORDINE, T C	8310270245	50-155
BETOURNE, G P	8310130218*	50-155 T	BLAKE, J J	8310040427*	50-390 0	BOTTNER, L	8310240067	50-329
BETTENHAUSEN, L	8310060046*	50-388 G	BLAKE, J J	8310250257*	50-259 0	BOTTNER, L A	8310240023	50-329
BIBB, H E	8310040454*	50-335 G	BLAKE, J J	8310250300*	50-327 0	BOTTNER, L A	8310240033	50-329
BIBB, H E	8310250528*	50-335 G	BLAKE, J J	8310250404*	50-413 G	BOUCHEY, G D	8310200357*	FOIA
BICEHOUSE, H J	8310120217*	50-277 G	BLAKE, J J	8310250446*	50-280 G	BOUKNIGHT, R J	8310040465	50-395
BICKWIT, L	8206100323*	FOIA	BLANC, G A	8310260175*	FOIA	BOUKNIGHT, R J	8310070278	50-395
BIDINGER, G H	8310040144	70-1151	BLANC, G A	8310260177*	FOIA	BOUKNIGHT, R J	8310310392	50-395
BIDINGER, G H	8310110599	70-371	BLANKENHEVER, J	8310120322	50-346 B	BOUKNIGHT, R J	8310310394	50-395
BIDINGER, G H	8310240078	70-1151	BLESSING, L	8310140080	50-302 P	BOURNIA, A	8310310196	50-374
BIGGS, J M	8310180369*	50-275 T	BLOCH, P D	8310040184	50-155 0	BOYMAKER, N J	8310310055	50-317
BIRCH, M	8310240014*	50-413 T	BLOCH, P D	8310110266	50-445 0	BOYMAN, S M	8310190057*	50-280
BIRKENHEIMER, J	8310190056	50-322 G	BLOCH, P D	8310130194	50-155 0	BOYACK, D E	8310200389	NJREO
BIRKENHEIMER, J	8310190056	50-322 G	BLOCH, P D	8310140018	50-445 0	BOYD, D	8310210122	50-316
BISBEE, G D	8310030397	50-443 G	BLOCH, P D	8310140083	50-445 0	BOYD, D	8310210151	50-255
BISHOP, T W	8310030109	50-206 V	BLOCH, P D	8310270228	50-445 0	BOYD, D C	8310040255*	50-255
BISHOP, T W	8310030142	50-397 V	BLOCH, P B	8310270293	50-445 0	BOYD, D C	8310060374*	50-155
BISHOP, T W	8310030145	50-344 V	BLOCH, S	8310050478*	50-155 T	BOYD, D C	8310240096*	50-295
BISHOP, T W	8310030149	50-312 V	BLOUGH, J N	8310030199	40-8452	BOYD, D C	8310240100*	50-315
BISHOP, T W	8310030154	50-528 V	BLOUGH, A R	8310140068	50-277 S	BOYER, L	8310060367*	50-324
BISHOP, T W	8310030285	50-275 V	BLOUGH, A R	8310210278*	50-277 G	BOYER, L E	8310060564*	50-324
BISHOP, T W	8310040532	50-528 G	BLOUGH, A R	8310310361	50-277 S	BOYER, R E	8310270206	50-312
BISHOP, T W	8310120192	50-397 G	BLUBAUGH, R E	8310190106	40-3453	BOYER, V S	8310110300*	50-352
BISHOP, T W	8310120248	50-397 G	BLUMBERG, N	8310140166*	50-289 G	BOYER, V S	8310110307*	50-352
BISHOP, T W	8310170428	50-397 G	BOARDMAN, J R	8310040577*	50-285 G	BOYER, V S	8310120388*	50-352
BISHOP, T W	8310170468	50-528 G	BOARDMAN, J R	8310180414*	50-498 G	BOYER, V S	8310140101*	50-352
BISHOP, T W	8310170473	50-275 G	BOATRIGHT, P A	8310130249	71-5908	BOYER, V S	8310280127	50-352
BISHOP, T W	8310170481	50-397 G	BOBE, P E	8310280168*	50-266 S	BRACKENBUSH, L	8310260381	NJREO
BISHOP, T W	8310170612	50-397 G	BOBE, P E	8310280171*	50-266 S	BRACKMAN, T H	8310120055*	CONTRACT
BISHOP, T W	8310170653	50-508 G	BODDY, J R	8310030211*	40-858	BRADSHAW, R B	8310120255	PR
BISHOP, T W	8310180331	50-397 G	BODINE, J C	8310270094*	50-244 F	BRADFORD, L	8310270372	50-289
BISHOP, T W	8310180367*	50-344 G	BOGART, T	8310140266*	50-302 R	BRADFORD, W H	8310040384*	50-346
BISHOP, T W	8310180477	50-361 S	BOHN, M P	8310110032	NJREO	BRADLEY, E J	8309130030*	50-352
BISHOP, T W	8310200175	50-275 H	BOISVENUE, L	8310200331	XPDRTLIC	BRADLEY, E J	8310050437	50-352
BISHOP, T W	8310200180	50-275 G	BOLD, E R	8310250011*	GA999	BRADLEY, E J	8310070243	50-352
BISHOP, T W	8310200194	50-397 G	BOLDON, A E	8310110099	50-123 V	BRADLEY, E J	8310140097	50-352
BISHOP, T W	8310200208	50-206 G	BOLDON, A E	8310110113*	50-123 V	BRADLEY, E J	8310140101*	50-352
BISHOP, T W	8310210043	50-397 G	BOMBERGER, C	8308180560*	50-346 P	BRADLEY, E J	8310140278	50-352
BISHOP, T W	8310210055	50-397 G	BOMBERGER, C	8309020392*	50-277 P	BRADLEY, E J	8310250035	50-352
BISHOP, T W	8310250348*	50-275 P	BOMBERGER, C R	8309060263*	50-315 P	BRADLEY, E J	8310110024*	50-155
BISHOP, T W	8310280036	50-275 G	BOOKER, H R	8310170751	50-289 P	BRADLEY, W H	8310210186	50-413
BISHOP, T W	8310280060	50-275 G	BOOKER, J E	8307260003	50-458 A	BRADLEY, W H	8310240059*	50-413
BISHOP, T W	8310310244	50-275 G	BOOKER, J E	8310030549	50-458 S	BRADY, J A	8310200443*	50-320
BISHOP, T W	8310310274	50-275 G	BOOKER, J E	8310040126	50-458 S	BRADY, J A	8310270396*	50-289
BISHOP, T W	8310310296	50-312 G	BOOKER, J E	8310040130	50-458 S	BRADY, L W	8310280131	REG
BISHOP, T W	8310310332	50-275 G	BOOKER, J E	8310040318	50-458 S	BRADLEY, L B	8310190045	50-368
BISHOP, T W	8310310396	50-528 G	BOOKER, J E	8310040496*	50-458 S	BRANAGAN, E F	8310170626	50-400
BISHOP, T W	8310310401	50-312 G	BOOKER, J E	8310060074	50-458 S	BRANDENBURG, B	8310270126	FOIA
BISSETT, P H	8310190251*	50-334 G	BOOKER, J E	8310070319	50-458 A	BRANNIN, J P	8310250060	50-389
BITTER, D B	8310110505*	FOIA	BOOKER, J E	8310130183	50-458 S	BREAUX, D Q	8310250270*	GA999
BLACK, S	8208230434*	50-382 G	BOOKER, J E	8310130210	50-458 S	BREEN, J	8310240209*	FOIA
BLACK, S	8209010314*	50-382 G	BOOKER, J E	8310130215	50-458 S	BRENNER, L	8310040183	50-352
BLACK, S	8210050447*	50-382 G	BOOKER, J E	8310130256	50-458 S	BRENNER, L	8310040187	50-352
BLAIR, L R	8310110359	FOIA	BOOKER, J E	8310130258	50-458 S	BRENNER, L	8310050537	50-322
BLAKE, E L	8310030351	50-289 G	BOOKER, J E	8310130322	50-458 S	BRENNER, L	8310060192	50-322
BLAKE, E L	8310030351	50-289 G	BOOKER, J E	8310180269	50-458 S	BRENNER, L	8310110052	50-352
BLAKE, E L	8310030403	50-289 G	BOOKER, J E	8310180303	50-458 S	BRENNER, L	8310240188	50-352
BLAKE, E L	8310030403	50-289 G	BOOKER, J E	8310180305	50-458 S	BREY, H L	8310040169	50-267
BLAKE, E L	8310040392	50-289 G	BOOKER, J E	8310180460	50-458 S	BREY, H L	8310130286	50-267
BLAKE, E L	8310040392	50-289 G	BOOKER, J E	8310180461	50-458 S	BREY, H L	8310210253	50-267
BLAKE, E L	8310110205	50-289 G	BOOKER, J E	8310210149	50-458 S	BRICKLEY, R H	8310040596*	GA999
BLAKE, E L	8310110205	50-289 G	BOOKER, J E	8310210175	50-458 S	BRIDEN, D W	8310110087*	50-346
BLAKE, E L	8310110224	50-289 G	BOOKER, J E	8310210201	50-458 S	BRIDGES, T L	8310250570*	50-409
BLAKE, E L	8310110224	50-289 G	BOOKER, J E	8310210221	50-458 A	BRIDGES, T L	8310190203*	50-352
BLAKE, E L	8310110272	50-289 G	BOOKER, J E	8310210262	50-458 S	BRIGHT, O O	8310040192	50-142

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BRIGHT, O O	8310110218	50-400 Q	BURNETT, R F	8310240226	70-1113	CARLISLE, C S	8310250425	50-397 S
BRIGHT, O O	8310260263	50-142 Q	BURNETT, R F	8310260046	70-1257	CARLISLE, C S	8310250453	50-397 S
BRITTON, W H	8310040628*	70-1151	BURNETT, R F	8310270494	70-1100	CARLISLE, C S	8310270444	50-397 A
BROCARD, D N	8310030645*	GEN TEC IS	BURNETT, R F	8310270515	70-371	CARLSON, J D	8310170479*	50-275 Q
BROCK, B L	8310030213*	XPORTLIC	BURNETT, R F	8310270571	70-143	CARPENTER, G L	8310270364*	50-243 Q
BROCKOV, S J	8310130152*	50-537 Q	BURNETT, R F	8310270589	70-135	CARPENTER, J H	8310110218	50-400 Q
BROEHL, D J	8310030341	FR	BURNS, L S	8310180152*	50-352 Q	CARPENTER, T	8310260016	FOIA
BROEHL, D J	8310030364	FR	BURSTEIN, S	8310130004	50-266 P	CARR, A V	8310110068	50-491 Q
BROEHL, D J	8310060259	50-344 F	BURSTEIN, S	8310210044	50-266 F	CARR, A V	8310110068	50-491 Q
BROMBERG, B	8310070185	CONTRACT	BURSTEIN, S	8310280168*	50-266 S	CARR, A V	8310110294	50-413 Q
BROMBERG, B	8310070431	CONTRACT	BURSTEIN, S	8310310370	50-266 F	CARROW, H	8310030441	50-400 Q
BROWN, J C	8310170603	50-286 R	BURTON, J A	8310110029*	CONTRACT	CARROW, H	8310030478*	50-400 Q
BROWN, J C	8310190202	50-286 R	BUSH, M W	8310190058	50-352 Q	CARROW, H	8310040563*	50-400 Q
BROOKS, E H	8310040294*	50-269 Q	BUTLER, S D	8310240212*	50-528 Q	CARROW, H	8310260207*	50-400 Q
BROOKS, H L	8310050401*	50-413 T	BUTLER, S D	8310250517*	50-327 Q	CARSON, R	8310200082*	50-254 F
BROWN, C A	8310120324	TOPREP	BUTLER, S D	8310250624*	50-327 Q	CARTER, S E	8310180152*	50-352 Q
BROWN, C H	8310170483*	50-263 Q	BUTZ, L M	8310060166*	CONTRACT	CARUSO, M A	8310030504*	50-155 T
BROWN, C H	8308150385*	50-387 S	BYERS, R.	8310070231*	CONTRACT	CARVER, A M	8310110058	50-382 A
BROWN, Q D	8310190917	40-3453	BYRD, R	8310030296	50-416 S	CASABON, M	8310130267*	50-400 E
BROWN, Q D	8310310375	40-8084	BYRD, R	8310030490	50-416 S	CASABON, M	8310130271*	50-400 E
BROWN, J Y	8310270370	50-358 H	BYRD, R	8310040364	50-416 S	CASE, E O	8310110111*	50-275 P
BROWN, R L	8310030420*	50-458 Q	BYRD, R	8310040417	50-416 S	CASE, E O	8310180572*	50-298 P
BROWN, R L	8310180149*	50-458 Q	BYRD, R	8310060001	50-416 S	CASPER, R M	8310260202	FOIA
BROWN, S M	8310270003	50-213 F	BYRD, R	8310060002	50-416 S	CASSIDY, B P	8310040510	50-443 Q
BROWN, W B	8310240070	70-1201	BYRD, R	8310060401	50-416 S	CASSIDY, H G	8310260291	50-546 Q
BROWN, W B	8310240074	70-143	BYRD, R	8310070170	50-416 S	CASSIDY, T J	8310240091*	50-266 Q
BROWN, W B	8310240088	70-27	BYRD, R	8310070192	50-416 S	CASTLE, J N	8310030224	NUREQ
BROWN, W B	8310240099	70-2983	BYRD, R	8310070305	50-416 S	CATCHPOLE, G J	8310180172	40-8745
BROWN, W B	8310240101	70-27	BYRD, R	8310140122	50-416 S	CATHEY, D	8310030438	50-416 S
BROWN, W B	8310240210	70-27	BYRD, R	8310170474	50-416 S	CATHEY, D E	8309060068	50-416 S
BROWN, W B	8310240214	70-143	BYRD, R	8310170512	50-416 S	CATHEY, D E	8310030317	50-416 S
BROWN, W B	8310240224	70-1151	BYRD, R	8310190109	50-416 S	CATHEY, D E	8310060025	50-416 S
BROWN, W B	8310240225	70-25	BYRD, R	8310190111	50-416 S	CATHEY, D E	8310060112	50-416 S
BROWN, W B	8310240228	70-824	BYRD, R	8310210019	50-416 S	CATHEY, D E	8310070239	50-416 S
BROWN, W B	8310240229	70-1151	BYRD, R	8310210182	50-416 S	CATHEY, D E	8310120419	50-416 S
BROWN, W B	8310240230	70-1151	BYRD, R	8310270235	50-416 S	CATHEY, D E	8310140051	50-416 S
BROWN, W B	8310240231	70-143	BYRD, R	8310270397	50-416 S	CATHEY, D E	8310140061	50-416 S
BROWN, W B	8310240240	70-1257	BYRD, W K	8310260090*	FOIA	CATHEY, D E	8310170458	50-416 S
BROWN, W B	8310260029	70-143	BYRON, P M	8310170643*	50-341 Q	CATHEY, D E	8310190098	50-416 S
BROWN, W B	8310260433	70-27	CAHILL, W J.	8310030232	50-458 C	CATHEY, D E	8310190234	50-416 S
BROWN, W B	8310270538	70-195	GAIN, J M	8310040359	50-382 A	CATHEY, D E	8310190257	50-416 S
BROWN, W B	8310270556	70-27	GAIN, J M	8310260002	50-382 A	CATHEY, D E	8310270336	50-416 S
BROWN, W B	8310270562	70-824	CALLAN, L J	8310030476	50-368 S	CATTON, I	8310050224	NUREQ
BROWN, W B	8310270564	70-364	CALLAN, L J	8310130226*	50-313 Q	CAUSEY, J C	8310270327	50-366 P
BROWN, W B	8310270626	70-1257	CALLAN, L J	8310130335*	50-313 Q	CAVANAUGH, W T	8310070415*	CONTRACT
BROWN, W E	8310070293*	50-324 F	CALLIHAN, D	8310120026*	50-201 I	CAYEN, C F	8310170322	71-137
BROWN, W E	8310070293*	50-324 F	CALSOYAS, C D	8310180609	50-275 P	CERNE, A	8310070232	50-443 A
BROWN, W L	8310040601	40-8380	CAMP, A L	8310190283	NUREQ	CESARE, J O	8310190006	50-416 R
BROWNE, C I	8310070091*	50-275 Q	CAMPBELL, S E	8310030349	50-454 H	CHACKES, K M	8310040225	50-483 Q
BROWNLEE, V.	8310040307*	50-269 Q	CAMPBELL, W E	8310270594	TOPREP	CHACKES, K M	8310040225	50-483 Q
BROWNLEE, V	8310250236*	50-269 Q	CANPE, K M	8310050461	50-155 T	CHAFFE, A E	8310200214*	50-206 Q
BROWN, F L	8310060079	70-143	CANTANO, R	8310120288*	70-372	CHAMBERS, G T	8310060380	50-260 S
BRUNE, R L	8310190313*	FOIA	CANNY, J	8310260150	50-266 P	CHAMBERS, G T	8310270073	50-260 S
BRUNNER, J E	8310250041	50-329 Q	CANTRELL, F B	8310040384*	50-348 Q	CHAN, E I	8310050216	50-397 Q
BRUNNER, J E	8310250073	50-329 Q	CANTRELL, F S	8310250190*	50-259 Q	CHAN, E I	8310050423	50-352 Q
BRyant, J	8310040507*	50-269 Q	CANTWELL, P F	8310170609	50-304 S	CHAN, E I	8310250286	50-293 Q
BRyant, J	8310250256*	50-269 Q	CAPHTON, D	8310200092*	50-271 Q	CHAN, Y F	8310120218*	50-155 T
BRyant, J C	8310240032*	50-413 T	CAPHTON, D L	8310190283	50-334 Q	CHANDLER, J C	8310050470*	50-255 P
BUCKLES, J A	8310240119	50-315 J	CAPLAN, J S	8310190283	NUREQ	CHANDLER, J C	8310070260	TOPREP
BUCKLES, R	8310190046	FOIA	CAPONE, D W	8310040297	PR	CHANDLER, J C	8310140239	TOPREP
BUCKLES, R	8310250026	FOIA	CAPRA, R A	8310170022	50-289 P	CHANDLER, J C	8310140244*	TOPREP
BUCKLES, R	8310250031	FOIA	CAPRA, R A	8310170747	50-289 P	CHANDLER, J C	8310210139	TOPREP
BUCKLES, R	8310270255	50-475 F	CARBEINER, R E	8310170519	50-302 S	CHANDLER, L J	8310050454	50-275 Q
BUCKLEY, B C	8310170670	50-400 F	CARDARELLI, R D	8310050110	70-1257	CHANDLER, L J	8310130017	50-275 Q
BUCKLEY, B C	8310170124	50-400 E	CAREY, J J	8310040400	50-334 Q	CHANDLER, L J	8310130019*	50-275 Q
BUCKLEY, B C	8310180185	50-400 F	CAREY, J J	8310040561	50-334 F	CHANDLER, L J	8310250283	50-275 Q
BUCKLEY, R	8310250399*	GA999	CAREY, J J	8310120257	50-334 F	CHANDLER, L J	8310250467	50-275 Q
UDNITZ, R	8310070240*	CONTRACT	CAREY, J J	8310140208	50-334 F	CHANEY, H D	8310060026*	50-313 Q
UFE, J L	8310070306	50-302 S	CAREY, J J	8310180322*	50-334 Q	CHANEY, H D	8310060464*	50-382 Q
UFE, J L	8310140123	50-302 S	CAREY, J J	8310180432	50-334 F	CHANO, F K	8310070134	NUREQ
UFE, J L	8310140187	50-302 S	CAREY, J J	8310190019	50-334 R	CHANG, T Y	8310110245	NUREQ
UFE, J L	8310140233	50-302 S	CAREY, J J	8310210238	50-334 P	CHAPLIN, S.	8310190060	50-320 S
UFE, J L	8310210021	50-302 S	CAREY, J J	8310270154	50-334 P	CHAPLIN, S D	8310200155	50-320 S
UJTING, J D	8310060516	WASTE MGT	CARLEY, A	8310270510*	50-155 F	CHAPLIN, S D	8310250434	50-320 S
URCH, R H	8310280370*	50-400 A	CARLEY, A	8310270593*	50-155 F	CHARNLEY, J S	8310050185	TOPREP
		50-400 A	CARLISLE, C S	8309300331	50-397 S	CHARNOFF, O	8310170234	71-9010
		50-352 T	CARLISLE, C S	8310120196*	50-397 Q	CHARNOFF, O	8310170234	71-9010
		50-397 Q	CARLISLE, C S	8310120250*	50-397 Q	CHARNOFF, O	8310170234	71-9010
		50-271 R	CARLISLE, C S	8310170507*	50-397 Q	CHASNOFF, B A	8310250049	27-39
		50-329 Q	CARLISLE, C S	8310180341*	50-397 Q	CHASNOFF, B A	8310250051	27-39
		50-329 Q	CARLISLE, C S	8310200200*	50-397 Q	CHAUDHARY, S K	8310190203*	50-352 Q
		NUREQ	CARLISLE, C S	8310250088	50-397 A	CHEN, P.	8310050500*	50-155 T
		50-289 Q	CARLISLE, C S	8310250092	50-397 S	CHEN, S.	8310210240*	50-244 P
		50-416 A	CARLISLE, C S	8310250144	50-397 S	CHEUNG, Y K	8310180076	NUREQ
			CARLISLE, C S	8310250290	50-397 S	CHIAPETTA, R L	8310120024*	CONTRACT

PERSONAL AUTHOR INDEX

493

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CHICHESTER, G	8310050508	50-443 H	CHURCHILL, D W	8310190212	50-382 Q	COLQMBQ, R W	8310270452	50-312 B
CHICHESTER, G	8310050508	50-443 H	CHURCHILL, D W	8310200102	50-266 Q	CON, V N	8308030382*	50-315 Q
CHILK, S J	8310030419	50-289 Q	CHURCHILL, D W	8310200102	50-266 Q	CON, V N	8309200506*	50-267 Q
CHILK, S J	8310030528	50-443 Q	CILLIS, M	8310210256*	50-228 Q	CONDRA, R D	8310170011	40-86
CHILK, S J	8310040217	50-483 Q	CINTULA, T C	8305030115*	50-361 S	CONE, T C	8310240271*	WASTE MOT
CHILK, S J	8310040261*	FOIA	CIPOLLA, A J	8310170623	40-3392	CONLON, T E	8310040042*	50-321 Q
CHILK, S J	8310040267	50-155 Q	CLARDY, L S	83100601A5*	50-331 Q	CONLON, T E	8310200057*	50-440 Q
CHILK, S J	8310040274	50-341 Q	CLARK, D E	8310050239	MUREQ	CONLON, T E	8310250236*	50-537 Q
CHILK, S J	8310040280	50-289 Q	CLARK, L	8310130216	50-20 F	CONLON, T E	8310250380*	50-438 Q
CHILK, S J	8310040302	50-275 Q	CLARK, P R	8310260143	50-289 P	CONLON, T E	8310250452*	50-416 Q
CHILK, S J	8310060197	50-266 Q	CLARK, R J	8310110521	50-259 P	CONLON, T E	8310250498*	50-348 Q
CHILK, S J	8310060463	10CFR	CLARK, R J	8310270523	50-239 Q	CONLON, T E	8310250567*	50-327 Q
CHILK, S J	8310070209	50-275 Q	CLAUSS, J M	8310130232*	50-341 A	CONLON, T E	8310270426*	50-440 Q
CHILK, S J	8310070383	COMMISSION	CLAYTON, F L	8310030147	50-348 F	CONN, W G	8310040232	50-397 F
CHILK, S J	8310110049	50-443 Q	CLAYTON, F L	8310030414	50-348 P	CONN, W G	8310040331	50-397 S
CHILK, S J	8310110050	50-289 Q	CLAYTON, F L	8310040377*	50-348 Q	CONN, W G	8310250505	50-397 S
CHILK, S J	8310110061	50-440 Q	CLAYTON, F L	8310040387	50-348 P	CONNAUGHTON, K	8310040430*	50-454 Q
CHILK, S J	8310110114	50-275 U	CLAYTON, F L	8310040438	50-348 F	CONNER, E	8310140166*	50-287 Q
CHILK, S J	8310110191*	50-275 U	CLAYTON, F L	8310060096	50-348 P	CONNER, E L	8310050455	50-352 A
CHILK, S J	8310110223	50-289 Q	CLAYTON, F L	8310070138	50-348 S	CONNER, E L	8310190203*	50-352 Q
CHILK, S J	8310110238	50-289 Q	CLAYTON, F L	8310070290	50-364 S	CONNER, L	8310270465	FOIA
CHILK, S J	8310120405	50-341 Q	CLAYTON, F L	8310070296	50-348 S	CONNER, L	8310310017	50-3
CHILK, S J	8310120412	50-275 Q	CLAYTON, F L	8310120330	50-348 S	CONNER, T B	8310050515	50-382 Q
CHILK, S J	8310130123	10CFR	CLAYTON, F L	8310140194	50-348 P	CONNER, T B	8310050515	50-352 Q
CHILK, S J	8310130224	50-440 Q	CLAYTON, F L	8310140226	50-348 S	CONNER, T B	8310110216*	50-358 Q
CHILK, S J	8310130403	10CFR	CLAYTON, F L	8310170407	50-348 P	CONNER, T B	8310110269	50-358 Q
CHILK, S J	8310130408	50-320 P	CLAYTON, F L	8310170416	50-348 P	CONNER, T B	8310110269	50-358 Q
CHILK, S J	8310140092	MISC	CLAYTON, F L	8310180124	50-348 R	CONNER, T B	8310110286	50-358 Q
CHILK, S J	8310140242	50-155 Q	CLAYTON, F L	8310180134	50-364 R	CONNER, T B	8310110286	50-358 Q
CHILK, S J	8310140247	50-155 Q	CLAYTON, F L	8310180308	50-348 Q	CONNER, T B	8310120028*	50-201 I
CHILK, S J	8310140250	50-266 Q	CLAYTON, F L	8310190071	50-364 R	CONNER, T B	8310120028*	50-201 I
CHILK, S J	8310140294	50-289 P	CLAYTON, F L	8310210022	50-348 P	CONNER, T B	8310120028*	50-201 I
CHILK, S J	8310170056	10CFR	CLAYTON, F L	8310210259	50-348 P	CONNER, T B	8310210153	50-358 Q
CHILK, S J	8310170098	10CFR	CLAYTON, F L	8310250422	50-348 P	CONNER, T B	8310210153	50-358 Q
CHILK, S J	8310170321	50-247 F	CLAYTON, F L	8310250477*	50-348 Q	CONNER, T B	8310270381	50-354 Q
CHILK, S J	8310170424	50-443 Q	CLAYTON, F L	8310270061	50-364 S	CONSTABLE, O L	8310310408*	50-382 Q
CHILK, S J	8310170695	50-289 P	CLAYTON, F L	8310270374	50-348 P	CONTE, R	8310180384	50-308 H
CHILK, S J	8310180035	50-358 A	CLELAND, L L	8310250631*	50-312 P	CONTE, R	8310140166*	50-287 Q
CHILK, S J	8310180041	10CFR	CLEMONSON, F	8310050415*	50-413 T	COOK, D	8310170271	50-254 S
CHILK, S J	8310180338	50-309 Q	CLEMONSON, F	8310050514*	50-155 T	COOK, H L	8202230210*	FOIA
CHILK, S J	8310190091	50-266 Q	CLEMENTS, W L	8310040395	50-289 Q	COOK, H L	8310260025*	FOIA
CHILK, S J	8310190261	50-275 Q	CLINE, W E	8310250304*	50-390 Q	COOK, H L	8310260067*	FOIA
CHILK, S J	8310210147	10CFR	CLINE, W E	8310250578*	50-324 Q	COOK, H L	8310260105*	FOIA
CHILK, S J	8310240268*	FOIA	CLOBIUS, O J	8310250315	50-213 S	COOK, H L	8310260121*	FOIA
CHILK, S J	8310250009	FOIA	CLOBIUS, O J	8310250321	50-213 S	COOK, H L	8310260133*	FOIA
CHILK, S J	8310260241	50-266 Q	CLOUD, R L	8208010014*	50-275 P	COOK, H L	8310260146*	70-1144
CHILK, S J	8310270145*	FOIA	CLOUD, R L	8310180361*	50-275 T	COOK, H L	8310260146*	70-1144
CHILK, S J	8310270218	50-443 Q	CLOUD, R L	8310180369*	50-275 T	COOK, H L	8310260238*	FOIA
CHILK, S J	8310270234	50-529 Q	CLOUGH, R L	8310310447	MUREQ	COOK, H L	8310260258*	FOIA
CHILK, S J	8310270259	50-289 Q	COFFMAN, F E	8310240253	WASTE MOT	COOK, H L	8310260321*	FOIA
CHILK, S J	8310270297	50-10 Q	COHEN, I	8310210266*	50-309 Q	COOK, H L	8310260347*	FOIA
CHILK, S J	8310270304	50-289 Q	COLBURN, N I	8310070414	MUREQ	COOK, H L	8310260359*	FOIA
CHILK, S J	8310270317	50-338 Q	COLBURN, T Q	8310070439	50-266 P	COOK, H L	8310260384*	FOIA
CHILK, S J	8310270367	50-329 Q	COLBURN, T Q	8310130052	50-266 P	COOK, H L	8310260388*	FOIA
CHILK, S J	8310280066	50-341 Q	COLBURN, T Q	8310130199	50-266 P	COOK, H L	8310260394*	FOIA
CHILK, S J	8310280162	WASTE MOT	COLBURN, T Q	8310170079	50-266 P	COOK, J	8310120435	50-333 R
CHILK, S J	8310280172	50-289 P	COLBURN, T Q	8310240116	50-266 P	COOK, J L	83102800203*	50-397 Q
CHILK, S J	8310280212	50-358 Q	COLE, P A	8310070173*	CONTRACT	COOK, J W	8309090259	50-329 S
CHILTON, A D	8310070323	MUREQ	COLE, R F	8310120398	50-458 Q	COOK, J W	8310070142	50-329 A
CHOKSHI, N C	8310130001	50-155 T	COLEMAN, R	8310070172	CONTRACT	COOK, J W	8310120320	50-329 A
CHOULES, N C	8310140215*	50-373 Q	COLEMAN, R J	8310180270	50-275 H	COOK, J W	8310170421	50-329 S
CHOULES, N C	8310270440*	50-305 Q	COLEMAN, R W	8310110516	CONTRACT	COOK, J W	8310250101	50-329 S
CHOW, E	8303230482*	50-255 P	COLEY, J L	8310040283*	50-239 Q	COOK, J W	8310270265	50-329 S
CHRIBBOTIMOS, M	8310250613*	50-254 Q	COLEY, J L	8310250259*	50-259 Q	COOK, J W	8310270352*	50-329 Q
CHRISTA-MARIA	8310040545	50-155 T	COLEY, J L	8310250464*	50-280 Q	COOK, J W	8310310078	50-329 R
CHRISTA-MARIA	8310040620	50-155 T	COLLINS, D J	8310060019*	50-244 Q	COOK, K W	8310120226	50-382 A
CHRISTA-MARIA	8310040621*	50-155 T	COLLINS, D J	8310120217*	50-277 Q	COOK, K W	8310250496	50-382 E
CHRISTA-MARIA	8310040624*	50-155 T	COLLINS, D M	8310140142	1&E	COOK, R J	8310170534*	50-329 Q
CHRISTEL	8310110486*	FOIA	COLLINS, J T	8310030358	50-298 Q	COOK, R J	8310170591*	50-329 Q
CHRISTEL, B	8310270477	50-249 S	COLLINS, J T	8310030395	50-445 Q	COOKE, F E	8310180152*	50-352 Q
CHRISTIANSON, F	8310250642*	50-461 Q	COLLINS, J T	8310030411*	50-445 Q	COOL, D A	8310050013	70-1151
CHRISTMAN, J N	8310170365	50-322 Q	COLLINS, J T	8310040407	50-267 P	COONEY, M J	8310200137	50-278 S
CHRISTMAN, J N	8310170365	50-322 Q	COLLINS, J T	8310070144*	50-382 A	COONEY, M J	8310200257	50-277 R
CHRISTOPHER, R	8310270324*	50-289 Q	COLLINS, J T	8310140422	50-267 Q	COONEY, M J	8310250279	50-278 S
CHRISTOPHER, R	8310270462*	50-443 Q	COLLINS, M E	8310140080*	50-302 P	COONEY, M J	8310230382	50-277 S
CHRISTOPHER, R	8310270474*	50-443 Q	COLLINS, S T	8310270013	50-29 Q	COOPER, J H	8310310281*	50-275 Q
CHRISTOPHER, R	8310030405	50-260 S	COLLINS, T R	8310250540*	50-369 Q	COOPER, W E	8310170214	50-275 R
CHU, K H	8310180085	MUREQ	COLQMBQ, R W	8310040419	50-312 R	COOPER, W E	8310170464	50-275 R
CHURCHILL, B W	8310040233	50-382 Q	COLQMBQ, R W	8310170216	50-312 R	COOPER, W E	8310180361*	50-275 T
CHURCHILL, B W	8310040233	50-382 Q	COLQMBQ, R W	8310120145	50-312 S	COOPER, W E	8310180375*	50-275 T
CHURCHILL, B W	8310110274	50-266 Q	COLQMBQ, R W	8310120150	50-312 S	COOPER, W E	8310260260	50-275 R
CHURCHILL, B W	8310110274	50-266 Q	COLQMBQ, R W	8310120167	50-312 S	COOPER, W E	8310270241	50-275 R
CHURCHILL, B W	8310170569	50-382 Q	COLQMBQ, R W	8310120186	50-312 S	COPELAND, R A	8310050346	TOPREP
CHURCHILL, B W	8310170569	50-382 Q	COLQMBQ, R W	8310250598	50-312 S	COPELAND, V G	8310120365	50-155 Q
CHURCHILL, B W	8310190212	50-382 Q	COLQMBQ, R W	8310270451	50-312 S	COPELAND, V G	8310120365	50-155 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
COPELAND, V G	8310170346	50-454 Q	CROSSMAN, W A	8310030392*	50-498 Q	CRUTCHFIELD, D	8310280128	50-409 F
COPELAND, V G	8310170346	50-454 Q	CROSSMAN, W A	8310030420*	50-458 Q	CRUTCHFIELD, D	8310280161	50-409 F
COPELAND, V G	8310310206	50-155 Q	CROSSMAN, W A	8310040157*	50-382 Q	CRUTCHFIELD, D	8310310052	50-237 P
COPELAND, V G	8310310206	50-155 Q	CROSSMAN, W A	8310040546*	50-498 Q	CRUTCHFIELD, D	8310310283	50-29 P
CORRETT, J S	8310170748	71-6601	CROSSMAN, W A	8310040577*	50-285 Q	CRUTCHFIELD, D	8310310360	50-29 P
CORMIER, W H	8310030394	50-142 Q	CROSSMAN, W A	8310060391*	50-382 Q	CULLEN, D P	8310070306	50-302 S
CORNELL, E K	8310110111*	50-275 P	CROSSMAN, W A	8310060464*	50-382 Q	CULLEN, D P	8310210021	50-302 S
CORYELL, G P	8310040197*	70-143	CROSSMAN, W A	8310130190*	50-498 Q	CUMMINGS, J C	8310190283	NUREQ
CROSSART, J	8310170107*	50-338 S	CROSSMAN, W A	8310130230*	50-498 Q	CUMMINGS, J J	8310110103*	FOIA
COSTANTINO, C J	8310210358*	50-275 T	CROSSMAN, W A	8310130252*	50-458 Q	CUMMINGS, J J	8310210001*	FOIA
COSTELLO, N J	8310280088	50-443 U	CROSSMAN, W A	8310180149*	50-458 Q	CUMMINGS, J J	8310240194*	FOIA
COTTER, B P	8310040194	27-39	CROSSMAN, W A	8310180414*	50-498 Q	CUMMINGS, J J	8310280179*	50-289 P
COTTER, B P	8310120398	50-458 Q	CROSSMAN, W A	8310130190*	50-382 Q	CUMMINGS, J E	8310130226*	50-313 Q
COTTER, B P	8310260268	27-39	CROUSE, R P	8310040226	50-346 F	CUMMINGS, J E	8310130335*	50-313 Q
COTTER, B P	8310260305	50-293 Q	CROUSE, R P	8310040345	50-346 F	CUNNINGHAM, A L	8310040517*	50-250 Q
COUNSEL, W G	8310030335	50-423 A	CROUSE, R P	8310120103	50-346 P	CUNNINGHAM, A L	8310250352*	70-143
COUNSEL, W G	8310030335	50-423 A	CROUSE, R P	8310170492	50-346 P	CUNNINGHAM, A L	8310250438*	50-280 Q
COUNSEL, W G	8310030428	50-245 P	CROUSE, R P	8310170599	50-346 P	CUNNINGHAM, G H	8310130164	50-230 Q
COUNSEL, W G	8310030428	50-245 P	CROUSE, R P	8310180513	50-346 R	CUNNINGHAM, G H	8310280144	50-322 U
COUNSEL, W G	8310040161	50-423 K	CROUSE, R P	8310250226	50-346 P	CUNNINGHAM, R E	8310250014*	FOIA
COUNSEL, W G	8310040161	50-423 K	CROW, W T	8310250235*	50-346 P	CUNNINGHAM, R E	8310280147	50-10 P
COUNSEL, W G	8310040334	PR	CROW, W T	8310040137*	70-2945	CUMMO, M	8310140027	50-322 F
COUNSEL, W G	8310040334	PR	CROW, W T	8310070037*	40-8027	CURRAN, D	8310130158	50-443 Q
COUNSEL, W G	8310040334	PR	CROW, W T	8310170693*	70-143	CURRAN, D	8310110158	50-443 Q
COUNSEL, W G	8310040521	50-423 C	CROW, W T	8310180015*	70-143	CURRAN, D	8310110165*	50-443 Q
COUNSEL, W G	8310040521	50-423 C	CROWLEY, D R	8310250464*	50-280 Q	CURRAN, D	8310110165*	50-443 Q
COUNSEL, W G	8310050431	PR	CRUTCHFIELD, D	8310030080	50-244 P	CURRAN, D	8310110170*	50-443 Q
COUNSEL, W G	8310050431	PR	CRUTCHFIELD, D	8310030140	50-213 P	CURRAN, D	8310110170*	50-443 Q
COUNSEL, W G	8310050431	PR	CRUTCHFIELD, D	8310030263	50-219 P	CURRAN, D	8310110175*	50-443 Q
COUNSEL, W G	8310060035	50-245 F	CRUTCHFIELD, D	8310030268*	50-219 P	CURRAN, D	8310110175*	50-443 Q
COUNSEL, W G	8310060035	50-245 F	CRUTCHFIELD, D	8310030443	50-219 P	CURRAN, D	8310140191	50-443 Q
COUNSEL, W G	8310060205	50-245 F	CRUTCHFIELD, D	8310030492	50-155 P	CURRAN, D	8310140191	50-443 Q
COUNSEL, W G	8310060205	50-245 F	CRUTCHFIELD, D	8310040451	50-244 P	CURRAN, D	8310180329	50-443 Q
COUNSEL, W G	8310060262*	50-213 F	CRUTCHFIELD, D	8310050054	50-29 P	CURRAN, D	8310180329	50-443 Q
COUNSEL, W G	8310120259	50-245 F	CRUTCHFIELD, D	8310050091	50-206 H	CURRAN, D	8310310202	50-443 Q
COUNSEL, W G	8310120270	PR	CRUTCHFIELD, D	8310050324	50-237 P	CURRAN, D	8310310202	50-443 Q
COUNSEL, W G	8310120270	PR	CRUTCHFIELD, D	8310070365	50-244 P	CURTIS, C M	8310190014	50-321 R
COUNSEL, W G	8310120270	PR	CRUTCHFIELD, D	8310070368*	50-244 P	CURTIS, N W	8310170698	40-2061
COUNSEL, W G	8310120375	50-213 P	CRUTCHFIELD, D	8310110140	50-237 Q	CURTIS, N W	8310040052	50-388 A
COUNSEL, W G	8310170190	50-423 A	CRUTCHFIELD, D	8310110161	50-29 P	CURTIS, N W	8310040421	50-388 A
COUNSEL, W G	8310170190	50-423 A	CRUTCHFIELD, D	8310110168	50-237 P	CURTIS, N W	8310040640	50-388 A
COUNSEL, W G	8310170504	50-245 P	CRUTCHFIELD, D	8310110193	50-213 F	CURTIS, N W	8310060211	50-387 F
COUNSEL, W G	8310170504	50-245 P	CRUTCHFIELD, D	8310110204	50-244 S	CURTIS, N W	8310070160	50-388 A
COUNSEL, W G	8310170563	50-423 A	CRUTCHFIELD, D	8310120104	50-409 P	CURTIS, N W	8310070336	50-388 E
COUNSEL, W G	8310170563	50-423 A	CRUTCHFIELD, D	8310120203	50-29 P	CURTIS, N W	8310120067	50-388 A
COUNSEL, W G	8310170656	50-245 P	CRUTCHFIELD, D	8310120272	50-409 P	CURTIS, N W	8310120080	50-388 A
COUNSEL, W G	8310170656	50-245 P	CRUTCHFIELD, D	8310120274	50-155 P	CURTIS, N W	8310120105	50-388 A
COUNSEL, W G	8310180344	50-213 P	CRUTCHFIELD, D	8310120303	50-237 P	CURTIS, N W	8310120144	50-388 A
COUNSEL, W G	8310180409	50-213 P	CRUTCHFIELD, D	8310120308	50-213 P	CURTIS, N W	8310120175	50-388 A
COUNSEL, W G	8310180409	50-213 P	CRUTCHFIELD, D	8310120328	50-244 P	CURTIS, N W	8310130207	50-387 P
COUNSEL, W G	8310180409	50-213 P	CRUTCHFIELD, D	8310120334	50-219 P	CURTIS, N W	8310130213*	50-387 P
COUNSEL, W G	8310180449	50-245 P	CRUTCHFIELD, D	8310120354	50-29 P	CURTIS, N W	8310140056	50-388 Q
COUNSEL, W G	8310180469	50-245 P	CRUTCHFIELD, D	8310120373	50-206 P	CURTIS, N W	8310140077	50-388 A
COUNSEL, W G	8310200187	50-336 P	CRUTCHFIELD, D	8310120411	50-213 P	CURTIS, N W	8310140114	50-387 P
COUNSEL, W G	8310200187	50-336 P	CRUTCHFIELD, D	8310120424	50-237 P	CURTIS, N W	8310140155	50-387 P
COUNSEL, W G	8310200229	50-336 P	CRUTCHFIELD, D	8310130137	50-255 P	CURTIS, N W	8310170145	50-388 A
COUNSEL, W G	8310200229	50-336 P	CRUTCHFIELD, D	8310130203	50-409 F	CURTIS, N W	8310180166	50-388 A
COUNSEL, W G	8310270021*	50-213 F	CRUTCHFIELD, D	8310130276	50-409 P	CURTIS, N W	8310180426	50-387 P
COUNSEL, W G	8310280313*	50-213 F	CRUTCHFIELD, D	8310170243	50-255 F	CURTIS, N W	8310180437	50-388 A
COVER, L E	8310110032	NUREQ	CRUTCHFIELD, D	8310170360	50-29 P	CURTIS, N W	8310180454	50-388 A
COX, D C	8310110480*	FOIA	CRUTCHFIELD, D	8310170373	50-244 S	CURTIS, N W	8310180480	50-387 P
COX, F	8310110240*	50-280 F	CRUTCHFIELD, D	8310180370	TOPREP	CURTIS, N W	8310180507	50-387 P
COX, F	8310260436*	50-280 F	CRUTCHFIELD, D	8310180379	TOPREP	CURTIS, N W	8310210292	50-388 A
COYLE, F T	8310060135	XPORTRIC	CRUTCHFIELD, D	8310180452	50-155 P	CURTIS, N W	8310250106	50-387 P
CRATO, J	8310030440	50-344 S	CRUTCHFIELD, D	8310180459*	50-155 P	CURTIS, N W	8310250476	50-387 Q
CRATO, J	8310060092	50-62 S	CRUTCHFIELD, D	8310180533	TOPREP	CURTIS, N W	8310270214	50-387 H
CRANE, C J	8104070444*	50-206 P	CRUTCHFIELD, D	8310180614	50-155 F	CURTIS, N W	8310280065	50-388 S
CRANE, P A	8310200398*	FOIA	CRUTCHFIELD, D	8310190131	50-409 F	CURTIS, N W	8310280130	50-387 S
CRANE, P A	8310030384	50-275 Q	CRUTCHFIELD, D	8310200003	50-409 P	CURTIS, N W	8310280139	50-388 S
CRANE, P A	8310040578*	50-275 P	CRUTCHFIELD, D	8310200005*	50-409 P	CURTIS, N W	8310280155	50-388 A
CRANE, P A	8310190219	50-275 Q	CRUTCHFIELD, D	8310210199	50-133 F	CURTIS, R H	8310310449	NUREQ
CRANE, P A	8310240174	50-275 Q	CRUTCHFIELD, D	8310250188	50-237 P	CUTTER, A B	8310060413	50-261 P
CRANE, P A	8310270263	50-275 Q	CRUTCHFIELD, D	8310250195*	50-237 P	CUTTER, A B	8310110145	50-261 F
CRANLEY, D E	8310110100*	50-327 F	CRUTCHFIELD, D	8310250307	50-155 Q	D'AMICO, L	8310260217	50-382 H
CRANLEY, J	8310270384	50-295 S	CRUTCHFIELD, D	8310250433	50-255 P	D'ANGELO, A	8310200214*	50-206 Q
CRANLEY, J	8310270487	50-341 S	CRUTCHFIELD, D	8310250463	50-29 P	D'ANGELO, A	8310310304*	50-312 Q
CRANLEY, J R	8310250582*	70-2977	CRUTCHFIELD, D	8310250566	50-409 P	D'ANGELO, A J	8310310398*	50-328 Q
CRANLEY, J R	8310310275	50-87 S	CRUTCHFIELD, D	8310250630	50-206 P	D'ANGELO, A J	8310310405*	50-312 Q
CRANLEY, J R	8310310347*	50-341 Q	CRUTCHFIELD, D	8310250681	50-244 P	DAEMAN, J J K	8310070414	NUREQ
CRANLEY, J	8310200214*	50-206 Q	CRUTCHFIELD, D	8310250682*	50-244 P	DAINDRA, J	8310180538*	50-333 P
CRANLEY, J L	8310280136*	50-344 S	CRUTCHFIELD, D	8310270143	50-244 Q	DALE, L F	8309060068	50-416 S
CRANLEY, H W	8310210266*	50-309 Q	CRUTCHFIELD, D	8310270238	50-29 P	DALE, L F	8309090416	50-416 S
CRANLEY, H W	8310270194*	50-29 Q	CRUTCHFIELD, D	8310270331	50-219 P	DALE, L F	8310030294	50-416 S
CRANLEY, M A	8310060493*	CONTRACT	CRUTCHFIELD, D	8310280009	50-255 P	DALE, L F	8310030317	50-416 S
CRANLEY, R H	8310280295*	WASTE MGT	CRUTCHFIELD, D	8310280112	50-213 P	DALE, L F	8310030325	50-416 S

PERSONAL AUTHOR INDEX

495

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DALE, L. F.	8310030364	PR	DANCE, H. C.	8310290320	50-280 Q	DELMEDICO, J.	8310170213*	FOIA
DALE, L. F.	8310030430	50-416 S	DANCE, H. C.	8310290354	50-269 Q	DELMEDICO, J.	8310170220*	FOIA
DALE, L. F.	8310030438	50-416 S	DANCE, H. C.	8310290383	50-413 Q	DELMEDICO, J.	8310170223*	FOIA
DALE, L. F.	8310030472	50-416 S	DANCE, H. C.	8310290388	50-280 Q	DELMEDICO, J.	8310170245*	FOIA
DALE, L. F.	8310030490	50-416 S	DANCE, H. C.	8310290398	50-413 Q	DELMEDICO, J.	8310170250*	FOIA
DALE, L. F.	8310040364	50-416 S	DANCE, H. C.	8310290400	50-335 Q	DELMEDICO, J.	8310170267*	FOIA
DALE, L. F.	8310040417	50-416 S	DANCE, H. C.	8310290414	50-338 Q	DELMEDICO, J.	8310170274*	FOIA
DALE, L. F.	8310040001	50-416 S	DANCE, H. C.	8310290429	50-280 Q	DELMEDICO, J.	8310170277*	FOIA
DALE, L. F.	8310040002	50-416 S	DANCE, H. C.	8310290459	50-280 Q	DELMEDICO, J.	8310170279*	FOIA
DALE, L. F.	8310060025	50-416 S	DANCE, H. C.	8310290516	50-335 Q	DELMEDICO, J.	8310170282*	FOIA
DALE, L. F.	8310060112	50-416 S	DANCE, H. C.	8310290615	50-335 Q	DELMEDICO, J.	8310170286*	FOIA
DALE, L. F.	8310060401	50-416 S	DANCE, H. C.	8310290701	50-321 Q	DELMEDICO, J.	8310170290*	FOIA
DALE, L. F.	8310070169	50-416 S	DANCE, H. C.	8310290735	50-250 Q	DELMEDICO, J.	8310170293*	FOIA
DALE, L. F.	8310070170	50-416 S	DANESE, F. L.	8310170087	50-266 F	DELMEDICO, J.	8310170297*	FOIA
DALE, L. F.	8310070192	50-416 S	DANIELSON, D.	8310180446	50-265 S	DELMEDICO, J.	8310170316*	FOIA
DALE, L. F.	8310070239	50-416 S	DANIELSON, D. H.	8310040179*	50-346 Q	DELMEDICO, J.	8310170320*	FOIA
DALE, L. F.	8310070305	50-416 S	DANIELSON, D. H.	8310290164*	50-373 Q	DELMEDICO, J.	8310170324*	FOIA
DALE, L. F.	8310120281	50-416 P	DANIELSON, D. H.	8310290280*	50-358 Q	DELMEDICO, J.	8310170331*	FOIA
DALE, L. F.	8310120349	50-416 F	DANIELSON, D. H.	8310270450*	50-255 Q	DELMEDICO, J.	8310170334*	FOIA
DALE, L. F.	8310120419	50-416 S	DAU, G. J.	8310030650	TOPREP	DELMEDICO, J.	8310170359*	FOIA
DALE, L. F.	8310120436	50-416 P	DAUGHERTY, F.	8310210275*	50-329 R	DELMEDICO, J.	8310170363*	FOIA
DALE, L. F.	8310120444	50-416 P	DAVALLE, R. Q.	8310210173*	50-397 A	DELMEDICO, J.	8310170367*	FOIA
DALE, L. F.	8310140051	50-416 S	DAVENPORT, K. E.	8310040253*	50-269 Q	DELMEDICO, J.	8310170372*	FOIA
DALE, L. F.	8310140061	50-416 S	DAVIS, A. B.	8310290148*	50-10 Q	DELMEDICO, J.	8310170376*	FOIA
DALE, L. F.	8310140122	50-416 S	DAVIS, A. B.	8310210003	50-358 A	DELMEDICO, J.	8310170381*	FOIA
DALE, L. F.	8310140160	50-416 S	DAVIS, A. B.	8310240137*	50-440 Q	DELMEDICO, J.	8310170385*	FOIA
DALE, L. F.	8310140169	50-416 S	DAVIS, E. H.	8310260036	XPORTLIC	DELMEDICO, J.	8310170388*	FOIA
DALE, L. F.	8310170408	50-416 S	DAVIS, E. H.	8310260042*	XPORTLIC	DELMEDICO, J.	8310170403*	FOIA
DALE, L. F.	8310170438	50-416 S	DAVIS, J. Q.	8310290160	1&E	DELMEDICO, J.	8310170433*	FOIA
DALE, L. F.	8310170474	50-416 S	DAVIS, J. Q.	8310070020	50-10 P	DELMEDICO, J.	8310170437*	FOIA
DALE, L. F.	8310170512	50-416 S	DAVIS, J. Q.	8310070025*	50-10 P	DELMEDICO, J.	8310170441*	FOIA
DALE, L. F.	8310180306	50-416 P	DAVIS, J. Q.	8310070156	50-10 Q	DELMEDICO, J.	8310170447*	FOIA
DALE, L. F.	8310180330	50-416 E	DAVIS, J. Q.	8310070161*	50-10 Q	DELMEDICO, J.	8310170449*	FOIA
DALE, L. F.	8310180352	50-416 P	DAVIS, J. Q.	8310070167*	50-10 Q	DELMEDICO, J.	8310170453*	FOIA
DALE, L. F.	8310180416	PR	DAVIS, J. Q.	8310070171*	50-10 Q	DELMEDICO, J.	8310170455*	FOIA
DALE, L. F.	8310180430	50-416 F	DAVIS, J. Q.	8310260030*	FOIA	DELMEDICO, J.	8310170460*	FOIA
DALE, L. F.	8310190006	50-416 R	DAVIS, J. Q.	8310260174*	FOIA	DELMEDICO, J.	8310170467*	FOIA
DALE, L. F.	8310190037	50-416 P	DAVIS, J. Q.	8310280242*	50-400 A	DELMEDICO, J.	8310170472*	FOIA
DALE, L. F.	8310190098	50-416 S	DAVIS, J. Q.	8310280244*	50-400 A	DELMEDICO, J.	8310170475*	FOIA
DALE, L. F.	8310190109	50-416 S	DAVIS, K. A.	8310050343	CONTRACT	DELMEDICO, J.	8310170477*	FOIA
DALE, L. F.	8310190111	50-416 S	DAVIS, L. A.	8310280170*	40-299	DELMEDICO, J.	8310170482*	FOIA
DALE, L. F.	8310190232	50-416 S	DAVIS, R. Q.	8310190326*	FOIA	DELMEDICO, J.	8310170494*	FOIA
DALE, L. F.	8310190234	50-416 S	DAVIS, T. M.	8310040383*	0A999	DELMEDICO, J.	8310170497*	FOIA
DALE, L. F.	8310190257	50-416 S	DAVIS, W.	8310310154*	50-508 A	DELMEDICO, J.	8310170502*	FOIA
DALE, L. F.	8310210019	50-416 S	DAY, M. S.	8310130402	FOIA	DELMEDICO, J.	8310170505*	FOIA
DALE, L. F.	8310210182	50-416 S	DAY, R. S.	8310250128*	50-206 P	DELMEDICO, J.	8310170510*	FOIA
DALE, L. F.	8310210314	50-416 Q	DEAGAZIO, A. W.	8310110540	50-346 P	DELMEDICO, J.	8310170516*	FOIA
DALE, L. F.	8310290262	50-416 Q	DEAL, R. L.	8310170232	71-6697	DELMEDICO, J.	8310170521*	FOIA
DALE, L. F.	8310260186	50-416 S	DEAL, R. L.	8310190351	71-6771	DELMEDICO, J.	8310170527*	FOIA
DALE, L. F.	8310260220	50-416 P	DEATON, B. W.	8310240065*	50-413 T	DELMEDICO, J.	8310170528*	FOIA
DALE, L. F.	8310260276	50-416 P	DEBBAGE, A. G.	8310040043*	50-261 Q	DELMEDICO, J.	8310170532*	FOIA
DALE, L. F.	8310270037	50-416 S	DEBBAGE, A. G.	8310040203*	50-324 Q	DELMEDICO, J.	8310170535*	FOIA
DALE, L. F.	8310270160	50-416 S	DEBBAGE, A. G.	8310250449*	50-250 Q	DELMEDICO, J.	8310170570*	FOIA
DALE, L. F.	8310270167	50-416 S	DEBBAGE, A. G.	8310250492*	50-327 Q	DELMEDICO, J.	8310170574*	FOIA
DALE, L. F.	8310270229	50-416 S	DEBOR, J.	8310250007	FOIA	DELMEDICO, J.	8310170578*	FOIA
DALE, L. F.	8310270235	50-416 S	DEBB, B.	8310250065	50-259 S	DELMEDICO, J.	8310170580*	FOIA
DALE, L. F.	8310270336	50-416 S	DEBB, B. T.	8310250387*	50-348 Q	DELMEDICO, J.	8310170583*	FOIA
DALE, L. F.	8310270397	50-416 S	DECKER, T. R.	8310250363*	50-269 Q	DELMEDICO, J.	8310170587*	FOIA
DALE, L. F.	8310310044	50-416 P	DEFAYETTE, R.	8310200268*	50-123 Q	DELMEDICO, J.	8310170590*	FOIA
DALE, L. F.	8310310126	50-416 Q	DELANEY, C. E.	8310250038	50-272 Q	DELMEDICO, J.	8310170593*	FOIA
DALTROFF, S. L.	8310140203	50-277 Q	DELGAIZO, T. J.	8307200260*	50-336 P	DELMEDICO, J.	8310170615*	FOIA
DALTROFF, S. L.	8310200196*	50-277 Q	DELGAIZO, T. J.	8307250463*	50-313 P	DELMEDICO, J.	8310170618*	FOIA
DALTROFF, S. L.	8310260212	50-277 P	DELMEDICO, J.	8012010577*	FOIA	DELMEDICO, J.	8310170625*	FOIA
DALTROFF, S. L.	8310280257*	50-277 F	DELMEDICO, J.	8012310197*	FOIA	DELMEDICO, J.	8310170628*	FOIA
DANCE, H.	8310190236	50-280 S	DELMEDICO, J.	8012310245*	FOIA	DELMEDICO, J.	8310170637*	FOIA
DANCE, H. C.	8310030294	50-280 Q	DELMEDICO, J.	8012310307*	FOIA	DELMEDICO, J.	8310170640*	FOIA
DANCE, H. C.	8310040012	50-321 Q	DELMEDICO, J.	8101070486*	FOIA	DELMEDICO, J.	8310170645*	FOIA
DANCE, H. C.	8310040146	50-413 Q	DELMEDICO, J.	8101090060*	FOIA	DELMEDICO, J.	8310170650*	FOIA
DANCE, H. C.	8310040178*	50-321 Q	DELMEDICO, J.	8101090109*	FOIA	DELMEDICO, J.	8310170652*	FOIA
DANCE, H. C.	8310040215	50-424 Q	DELMEDICO, J.	8103060697*	FOIA	DELMEDICO, J.	8310170660*	FOIA
DANCE, H. C.	8310040247	50-269 Q	DELMEDICO, J.	8103180096*	FOIA	DELMEDICO, J.	8310170665*	FOIA
DANCE, H. C.	8310040252	50-280 F	DELMEDICO, J.	8104170659*	FOIA	DELMEDICO, J.	8310170668*	FOIA
DANCE, H. C.	8310040290	50-269 Q	DELMEDICO, J.	8104170666*	FOIA	DELMEDICO, J.	8310170673*	FOIA
DANCE, H. C.	8310040305	50-250 Q	DELMEDICO, J.	8310170132*	FOIA	DELMEDICO, J.	8310170676*	FOIA
DANCE, H. C.	8310040329	50-413 Q	DELMEDICO, J.	8310170147*	FOIA	DELMEDICO, J.	8310170681*	FOIA
DANCE, H. C.	8310040351	50-321 F	DELMEDICO, J.	8310170154*	FOIA	DELMEDICO, J.	8310170684*	FOIA
DANCE, H. C.	8310040406	50-413 Q	DELMEDICO, J.	8310170156*	FOIA	DELMEDICO, J. M.	8104210028*	FOIA
DANCE, H. C.	8310040425	50-269 V	DELMEDICO, J.	8310170160*	FOIA	DELOATCH, V.	8310050339	CONTRACT
DANCE, H. C.	8310040447	50-335 Q	DELMEDICO, J.	8310170191*	FOIA	DELOATCH, V.	8310060109	CONTRACT
DANCE, H. C.	8310040484	50-269 Q	DELMEDICO, J.	8310170194*	FOIA	DELOATCH, V.	8310060122	CONTRACT
DANCE, H. C.	8310040495*	50-269 Q	DELMEDICO, J.	8310170196*	FOIA	DELOATCH, V.	8310060140	27-39 CONTRACT
DANCE, H. C.	8310040504	50-250 Q	DELMEDICO, J.	8310170202*	FOIA	DELOATCH, V.	8310060503	CONTRACT
DANCE, H. C.	8310250225	50-413 Q	DELMEDICO, J.	8310170203*	FOIA	DELOATCH, V.	8310180101	CONTRACT
DANCE, H. C.	8310250231	50-537 Q	DELMEDICO, J.	8310170208*	FOIA	DELOATCH, V.	8310180147	CONTRACT
DANCE, H. C.	8310250248	50-269 Q	DELMEDICO, J.	8310170210*	FOIA	DELOATCH, V.	8310180573	CONTRACT

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DENISON, E	8310040509	50-275 R	DIEDERICH, O J	8310060186	50-373 S	DIRCKS, W J	8304050526*	FOIA
DENISON, E	8310070086	50-275 R	DIEDERICH, O J	8310060198	50-373 S	DIRCKS, W J	8304220089*	FOIA
DENISON, E	8310070091*	50-275 R	DIEDERICH, O J	8310060271	50-373 S	DIRCKS, W J	8307220156*	FOIA
DENISON, E	8310070094	50-275 R	DIEDERICH, O J	8310120109	50-373 S	DIRCKS, W J	8307220250*	FOIA
DENISON, E	8310070100*	50-275 R	DIEDERICH, O J	8310140045	50-373 S	DIRCKS, W J	8307270430*	50-289 P
DENISON, E	8310070151	50-275 R	DIEDERICH, O J	8310140057	50-373 S	DIRCKS, W J	8308080690*	FOIA
DENISON, E	8310070208	50-275 R	DIEDERICH, O J	8310140069	50-373 S	DIRCKS, W J	8308190179	SECY
DENISON, E	8310070212*	50-275 R	DIEDERICH, O J	8310140073	50-373 S	DIRCKS, W J	8309080114	SECY
DENISON, E	8310070215	50-275 R	DIEDERICH, O J	8310140263	50-373 S	DIRCKS, W J	8310030308	50-309 S
DENISON, E	8310070227*	50-275 R	DIEDERICH, O J	8310180273	50-373 S	DIRCKS, W J	8310030620	50-289 P
DENISON, E	8310070251	50-275 R	DIEDERICH, O J	8310210222	50-373 S	DIRCKS, W J	8310070080	50-346 P
DENISON, E	8310070257*	50-275 R	DIEDERICH, O J	8310270267	50-373 S	DIRCKS, W J	8310070153*	PR
DENISON, E	8310120078	50-275 P	DIEDERICH, O J	8310270274	50-373 S	DIRCKS, W J	8310110017*	50-275 P
DENISON, E	8310140117	50-275 R	DIEDERICH, O J	8310270276	50-373 S	DIRCKS, W J	8310110095*	SECY
DENISON, E	8310140119*	50-275 R	DIEDERICH, O J	8310270490	50-373 S	DIRCKS, W J	8310120025	
DENISON, E	8310280157	50-275 P	DIETZ, C R	8309200175	50-324 S	DIRCKS, W J	8310120060	50-289 P
DENKOWSKI, W J	8310130261*	50-400 E	DIETZ, C R	8310030202	50-324 S	DIRCKS, W J	8310130080	MISC
DENNISTON, S. F	8310050369*	CONTRACT	DIETZ, C R	8310030209	50-324 S	DIRCKS, W J	8310130142	50-498 H
DENNISTON, S. F.	8310070432*	CONTRACT	DIETZ, C R	8310030422	50-324 S	DIRCKS, W J	8310170686	50-320 U
DENNISTON, S. F.	8310110192*	CONTRACT	DIETZ, C R	8310040306*	50-324 S	DIRCKS, W J	8310180092	50-289 P
DENNY, I. L.	8310120314	40-2061	DIETZ, C R	8310040362	50-324 S	DIRCKS, W J	8310190053*	FOIA
DENNY, I. L.	8310310362*	40-2061	DIETZ, C R	8310040412	50-325 S	DIRCKS, W J	8310190305	50-329 A
DENTON, H.	8305060071*	50-255 P	DIETZ, C R	8310040412	50-261 Q	DIRCKS, W J	8310210068	50-358 R
DENTON, H. R.	8206140401*	FOIA	DIETZ, C R	8310040582	50-325 S	DIRCKS, W J	8310290030*	FOIA
DENTON, H. R.	8310030131	MISC	DIETZ, C R	8310040593	50-324 S	DIRCKS, W J	8310270286*	FOIA
DENTON, H. R.	8310050071	50-250 S	DIETZ, C R	8310060075	50-324 S	DIRCKS, W J	8310270514	FOIA
DENTON, H. R.	8310060142	MISC	DIETZ, C R	8310060218	50-325 S	DIRCKS, W J	8310270635	40-672
DENTON, H. R.	8310060145*	MISC	DIETZ, C R	8310060237	50-324 S	DIRCKS, W J	8310280187	50-458 A
DENTON, H. R.	8310060157	NUREQ	DIETZ, C R	8310060383	50-324 S	DIRCKS, W J	8310310116*	FOIA
DENTON, H. R.	8310060576	50-263 F	DIETZ, C R	8310120300	50-325 S	DIRCKS, W J	8310310131*	50-289 P
DENTON, H. R.	8310060580	50-333 Q	DIETZ, C R	8310120426	50-324 S	DIRCKS, W J	8310310136*	FOIA
DENTON, H. R.	8310110608	COMMISSION	DIETZ, C R	8310130124	50-324 R	DIRCKS, W J	8310310140*	FOIA
DENTON, H. R.	8310130080	MISC	DIETZ, C R	8310140011	50-325 S	DIRLING, F	8310260300*	FOIA
DENTON, H. R.	8310130122	NUREQ	DIETZ, C R	8310140053	50-325 S	DIRLING, F N	8310260159*	FOIA
DENTON, H. R.	8310130189	50-387 S	DIETZ, C R	8310170414	50-325 S	DIRLING, F N	8310260303*	FOIA
DENTON, H. R.	8310180601	PR	DIETZ, C R	8310170396	50-324 S	DISCHLER, S A	8310070414	NUREQ
DENTON, H. R.	8310180605*	PR	DIETZ, C R	8310170604	50-324 S	DIXON, O W	8310030343	50-395 S
DENTON, H. R.	8310180607*	PR	DIETZ, C R	8310190141	50-325 S	DIXON, O W	8310030473	50-395 S
DENTON, H. R.	8310210303	50-409 P	DIETZ, C R	8310190227	50-325 S	DIXON, O W	8310030582*	50-395 F
DENTON, H. R.	8310310213	50-320 P	DIETZ, C R	8310190238	50-324 S	DIXON, O W	8310040465	50-395 S
DENTON, H. R.	8310310214*	50-320 P	DIETZ, C R	8310250237	50-324 S	DIXON, O W	8310070002	50-395 S
DERKS, P S	8310190260	50-133 R	DIETZ, C R	8310250396	50-324 S	DIXON, O W	8310070126	50-395 S
DEVINCENITIS, J	8310030341	PR	DIETZ, C R	8310250460*	50-324 Q	DIXON, O W	8310070278	50-395 S
DEVINCENITIS, J	8310030341	PR	DIETZ, C R	8310250521	50-325 S	DIXON, O W	8310070338	50-395 S
DEVINCENITIS, J	8310060343	50-443 S	DIGNAN, T G	8310110092*	50-443 Q	DIXON, O W	8310170443	50-395 S
DEVINCENITIS, J	8310060343	50-443 S	DIGNAN, T G	8310110092*	50-443 Q	DIXON, O W	8310170568	50-395 S
DEVINCENITIS, J	8310120263	50-443 A	DIGNAN, T G	8310120133	50-443 Q	DIXON, O W	8310190028	50-395 R
DEVINCENITIS, J	8310120263	50-443 A	DIGNAN, T G	8310120133	50-443 Q	DIXON, O W	8310200252	50-395 Q
DEVINCENITIS, J	8310210250*	50-443 Q	DIGNAN, T G	8310120428	50-443 Q	DIXON, O W	8310210128	50-395 S
DEVINCENITIS, J	8310210250*	50-443 Q	DIGNAN, T G	8310120428	50-443 Q	DIXON, O W	8310260107	50-395 E
DEVINE, J B	8310060094	XPORTRIC	DIGNAN, T G	8310180153*	50-443 Q	DIXON, O W	8310260117	50-395 B
DEVINE, T.	8310060245	50-358 Q	DIGNAN, T G	8310180153*	50-443 Q	DIXON, O W	8310260232	50-395 P
DEVINE, T.	8310060245	50-358 Q	DIGNAN, T G	8310180170*	50-443 Q	DIXON, O W	8310260255	50-395 P
DEVINE, T.	8310060239*	50-358 Q	DIGNAN, T G	8310180170*	50-443 Q	DIXON, O W	8310280005	50-395 D
DEVINE, T.	8310060266*	50-358 Q	DIGNAN, T G	8310200267	50-443 Q	DIXON, O W	8310310234	50-395 S
DEVINE, T.	8310060266*	50-358 Q	DIGNAN, T G	8310200267	50-443 Q	DIXON, O W	8310310234	50-395 S
DEVINE, T.	8310280204	50-358 Q	DIGNAN, T G	8310200267	50-443 Q	DIXON, O W	8310310392	50-395 S
DEWANDER, E. P.	8310110239*	50-280 F	DIGNAN, T G	8310200277	50-443 Q	DIXON, O W	8310310394	50-395 S
DEWANDER, E. P.	8310110268*	50-280 F	DIGNAN, T G	8310200277	50-443 Q	DODDS, R T	8310170432*	50-397 Q
DEWEY, L. B.	8310250264	50-329 Q	DIGNAN, T G	8310260234	50-443 Q	DODDS, R T	8310170621*	50-397 Q
DEWITT, R. B	8310310379*	50-155 P	DIGNAN, T G	8310260234	50-443 Q	DODDS, R T	8310170663*	50-308 Q
DEYOUNG, R. C	8310040432	QA999	DIGNAN, T G	8310260261*	50-443 Q	DODDS, R T	8310180367*	50-344 Q
DEYOUNG, R. C.	8310060593*	50-362 U	DIGNAN, T G	8310260261*	50-443 Q	DODDS, R T	8310210045*	50-397 Q
DEYOUNG, R. C.	8310110013*	FOIA	DIGNAN, T G	8310260266*	50-443 Q	DODDS, R T	8310210060*	50-397 Q
DEYOUNG, R. C	8310110016*	FOIA	DIGNAN, T G	8310260266*	50-443 Q	DOERFLEIN, L T	8310190168*	50-333 Q
DEYOUNG, R. C.	8310110016*	FOIA	DIGNAN, T G	8310260272*	50-443 Q	DOHERTY, E A	8310110020	FOIA
DEYOUNG, R. C.	8310110381	50-272 Q	DIGNAN, T G	8310260272*	50-443 Q	DOHERTY, J F	8310040481	50-293 Q
DEYOUNG, R. C.	8310110387*	50-272 Q	DIGNAN, T G	8310260272*	50-255 P	DOHERTY, J F	8310110202	50-443 Q
DEYOUNG, R. C.	8310190266	50-494 Q	DIANNI, D C	8205270433*	50-282 B	DOHERTY, J F	8310110316	50-443 Q
DEYOUNG, R. C.	8310200375	50-329 A	DIANNI, D C	8304200240*	50-255 P	DOHERTY, J F	8310260262	50-443 Q
DEYOUNG, R. C.	8310200380*	50-329 A	DIANNI, D C	8307050513	50-282 P	DONNELLO, W P.	8310250420*	QA999
DEYOUNG, R. C.	8310200386*	50-329 A	DIANNI, D C	8310130072	50-282 P	DONNELLO, W P.	8310250420*	QA999
DEYOUNG, R. C.	8310200392*	50-329 A	DIANNI, D C	8310170329	50-282 P	DONNELLO, W P.	8310280078*	50-329 Q
DEYOUNG, R. C.	8310240245	50-413 A	DILLB, R. C.	8310250045	50-275 U	DONNELLO, W P.	8310280078*	50-329 Q
DEYOUNG, R. C.	8310240249*	50-413 A	DINWELL, J. D.	8310110354*	COMMISSION	DOOLITTLE, E L	8310050453	50-423 A
DIAZ, N. J	8310110366*	50-83 F	DIRCKS, W J	8203120050*	FOIA	DOOLITTLE, E L	8310180077	50-423 Q
DICK, O. F.	8310120344	50-244 F	DIRCKS, W J	8205050588*	FOIA	DOOLITTLE, E L	8310240044	50-423 A
DICK, O. F.	8310190027	50-244 F	DIRCKS, W J	8205140137*	FOIA	DOROSHOW, J	8310260274	50-289 Q
DICK, O. F.	8310310503	TOPREP	DIRCKS, W J	8206080487*	50-328 A	DORBEY, J A	8310040498	50-352 Q
DICK, R. B.	8310240279	FOIA	DIRCKS, W J	8206240098*	FOIA	DORBEY, J A	8310040498	50-352 Q
DICKERSON, M. M	8310030350*	50-267 Q	DIRCKS, W J	8206250316*	FOIA	DOUBINOFF, B.	8310280137*	CONTRACT
DICKERSON, M. M	8310030350*	50-267 Q	DIRCKS, W J	8206300342*	FOIA	DOUGHERTY, J B	8310200108	50-322 Q
DICKERSON, R. A	8310040328*	50-267 S	DIRCKS, W J	8207280124*	FOIA	DOUGHERTY, J B	8310200108	50-322 Q
DICKINSON, A. C	8310200161	50-219 S	DIRCKS, W J	8208270562*	FOIA	DOUGLASS, S J	8310070087	40-8794
DIECKAMP, H.	8310110056	50-289 P	DIRCKS, W J	8211290108*	FOIA	DOUGLASS, S J	8310070092*	40-8794
DIECKAMP, H.	8310180099*	50-289 P	DIRCKS, W J	8212130165*	50-267 P	DOW, O B	8310060501*	CONTRACT
DIECKAMP, H.	8310180347	50-289 P	DIRCKS, W J	8302160056*	FOIA	DOWNING, O.	8310060595*	50-346 F

PERSONAL AUTHOR INDEX

497

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DRAB, J. B.	8310130261*	50-400 E	EDDLEMAN, W.	8310030375*	50-400 Q	EISENHUT, D. Q.	8310270377	GEN TEC 18
DRAPER, D. M.	8310120445*	50-316 S	EDDLEMAN, W.	8310030377*	50-400 Q	EISENHUT, D. Q.	8310280142*	50-334 F
DRIGGERS, S. E.	8310190293	71-7032	EDDLEMAN, W.	8310030380*	50-400 Q	EISENHUT, D. Q.	8310310134	50-454 Q
DROMERICK, A. W.	8310040453*	GA999	EDDLEMAN, W.	8310040518	50-400 Q	EISENHUT, D. Q.	8310310440*	50-321 F
DRUGA, R. J.	8310230595	50-334 S	EDDLEMAN, W.	8310040523	50-400 Q	ELLERSHAW, L. E.	8310030459*	GA999
DRUMMOND, F. J.	8310030259	50-382 S	EDDLEMAN, W.	8310120370	50-400 Q	ELLIOT, B. J.	8310050392*	50-413 Y
DRUMMOND, F. J.	8310030363	50-382 S	EDDLEMAN, W.	8310140072	50-400 Q	ELLIOTT, C. W.	8310140071	50-352 Q
DRUMMOND, F. J.	8310030368	50-382 S	EDDLEMAN, W.	8310230037	50-400 Q	ELLIS, D. W.	8310230277	50-29 B
DRUMMOND, F. J.	8310030448	50-382 S	EDDLEMAN, W.	8310250040	50-400 Q	ELLIS, D. W.	8310230418	50-29 B
DRUMMOND, F. J.	8310030482	50-382 S	EDDLEMAN, W.	8310250086	50-400 Q	ELLIS, J.	8310040230	50-445 Q
DRUMMOND, F. J.	8310030507	50-382 S	EDDLEMAN, W.	8310270331	50-400 Q	ELLIS, J.	8310120414	50-445 Q
DRUMMOND, F. J.	8310030540	50-382 S	EDELMAN, M. R.	8310040227	50-440 S	ELLIS, J.	8310180163*	50-445 Q
DRUMMOND, F. J.	8310040372	50-382 S	EDELMAN, M. R.	8310040404	50-440 S	ELLIS, J.	8310180339	50-445 Q
DRUMMOND, F. J.	8310100512	50-382 S	EDELMAN, M. R.	8310060340	50-440 S	ELLIS, J.	8310180342*	50-445 Q
DRUMMOND, F. J.	8310040366*	50-382 A	EDELMAN, M. R.	8310060392	50-440 S	ELLIS, J.	8310280059	50-445 Q
DRUMMOND, F. J.	8310060357	50-382 F	EDELMAN, M. R.	8310120286	50-440 S	ELLIS, T. B.	8310040430	50-322 Q
DRUMMOND, F. J.	8310070235	50-382 A	EDELMAN, M. R.	8310170469	50-440 S	ELLIS, T. B.	8310040630	50-322 Q
DRUMMOND, F. J.	8310120072	50-382 E	EDELMAN, M. R.	8310170613	70-2968	ELLIS, T. B.	8310170409	50-322 Q
DRUMMOND, F. J.	8310130266*	50-382 Q	EDELMAN, M. R.	8310200238	50-440 E	ELLIS, T. B.	8310170409	50-322 Q
DRUMMOND, F. J.	8310310091	50-382 A	EDELMAN, M. R.	8310210112	50-440 S	ELMS, A.	8310190007	50-213 R
DRUMMOND, F. J.	8310310315	50-382 Q	EDELMAN, M. R.	8310240165	50-440 A	ELROD, B. A.	8310040454*	50-335 Q
DRUMMOND, F. J.	8310310367	50-382 Q	EDELMAN, M. R.	8310230489	50-441 S	ELROD, B. A.	8310230528*	50-335 Q
DU BOUCHET	8310280006*	50-382 A	EDELMAN, M. R.	8310270030	50-440 S	ELBASSER, T. C.	8310190188*	50-423 Q
DU BOUCHET, A. V.	8310040573*	50-382 A	EDELMAN, M. R.	8310310030	50-440 A	ELBASSER, T. C.	8310120088*	70-1100
DUBINSKI, L.	8310260062*	FOIA	EDELMAN, M. R.	8310310378	50-440 A	ELBASSER, T. C.	8310180209*	50-213 Q
DUBINSKI, L.	8310260127*	FOIA	EDGAR, G. L.	8310260292	50-337 Q	ELBASSER, T. C.	8310180447*	50-213 Q
DUBOIS, D. L.	8310180232*	50-298 Q	EDGAR, G. L.	8310260292	50-337 Q	ELBASSER, T. C.	8310200169*	70-820
DUBRY, N. E.	8310240100*	50-315 Q	EDGEMORTH, P. J.	8310110572	CONTRACT	ELBASSER, T. C.	8310240115*	50-225 Q
DUCK, J. R.	8310140130	50-390 J	EDISON, G. E.	8310240039	50-482 A	ELBASSER, T. C.	8310270299*	50-134 Q
DUCK, J. R.	8310140260	50-302 J	EDISON, G. E.	8310240075	50-482 A	ENCH, R. L.	8310050005	50-155 F
DUDLEY, R. F.	8310060003	50-29 F	EDISON, G. E.	8310240135	50-455 F	ENCH, R. L.	8310050314*	50-155 T
DUGGAN, G. J.	8310190265	WASTE MGT	EGGENBERGER, A.	8310120225*	50-125 T	ENDREB, G. W.	8310310268	MUREO
DUGGIN, G. E.	8310030218	50-327 S	EGGENBERGER, A.	8310120225*	50-125 T	ENGEL, D. W.	8310070317	MUREO
DUGSTAD, D.	8310190035	50-282 R	EGGERS, P.	8310260397	MUREO	ENGEL, M. P.	8310170027	71-7070
DUMMER, G. H.	8310070435*	CONTRACT	EHABZ, J. L.	8310040239*	50-382 Q	ENGEL, M. P.	8310170739	71-6400
DUMMER, G. H.	8310180105*	CONTRACT	EHABZ, J. L.	8310040239*	50-382 Q	ENNIS, J. D.	8310170149*	50-416 Q
DUNAHAY, F. R.	8310240096*	50-295 Q	EISENHUT, D. Q.	8303240123*	FOIA	ENNIS, J. D.	8310260221*	70-1113
DUNAHAY, F. R.	8310270313*	50-266 Q	EISENHUT, D. Q.	8112170188*	50-382 Q	ENOS, J. T.	8310140132	TOPREP
DUNAB, W. J.	8310110187	50-266 Q	EISENHUT, D. Q.	8207260091*	50-269 S	ENOS, J. T.	8310140132	TOPREP
DUNLAP, J. H.	8310120156*	50-223 Q	EISENHUT, D. Q.	8303230300*	50-332 A	ENDMAN, C. A.	8310250683*	50-59 F
DUNLAP, J. H.	8310250603*	50-193 Q	EISENHUT, D. Q.	8306020357*	50-309 S	ERHARDT, J. V.	8310070163	50-245 S
DUNLAP, J. H.	8310270178*	70-371	EISENHUT, D. Q.	8308300355	50-275 P	ERHARDT, R. J.	8310210027	50-329 A
DUNLOP, J. M.	8310120143*	50-29 Q	EISENHUT, D. Q.	8308300357	50-247 P	ERHARDT, R. J.	8310260331	50-329 A
DUNNING, T. G.	8310210392*	50-275 T	EISENHUT, D. Q.	8308300358	50-275 P	ERNSTHAL, H. L.	8310250675	FOIA
DUPONT, S. Q.	8310030502*	50-373 Q	EISENHUT, D. Q.	8308300763	50-247 P	ESPINOZA, C. J.	8310060412	XPORTLIC
DUPREE, D. C.	8310190066	50-327 R	EISENHUT, D. Q.	8308300766	50-275 T	ESPINOZA, B.	8310130267*	50-400 E
DURAND, R. J.	8310260340*	50-329 A	EISENHUT, D. Q.	8308300771	50-244 P	ESPINOZA, B.	8310130271*	50-400 E
DURBIN, S. L.	8310120376	50-275 Q	EISENHUT, D. Q.	8308300775	50-275 F	ESPINOZA, B.	8310130277*	50-400 E
DURBIN, S. L.	8310120381*	50-275 Q	EISENHUT, D. Q.	8308300781	50-275 F	ESSIP, T. H.	8310070216	REG
DURBIN, S. L.	8310120386*	50-275 Q	EISENHUT, D. Q.	8308310029	50-275 P	EVANS, C. A.	8310040160*	50-445 Q
DURBIN, S. L.	8310310141	50-275 Q	EISENHUT, D. Q.	8308310050	50-322 S	EVANS, C. A.	8310040644*	50-267 Q
DURDEL, R.	8310060395*	50-346 F	EISENHUT, D. Q.	8310030141	50-265 F	EVANS, L. Q.	8310170262	70-2067
DURDURE, R. L.	8310180431*	GA999	EISENHUT, D. Q.	8310030407*	50-382 A	EVANS, P. A.	8310030405*	50-413 Q
DURR, J. P.	8310060048*	50-244 Q	EISENHUT, D. Q.	8310030571	50-289 P	EVERETT, R. J.	8310030502	40-6659
DURR, J. P.	8310190142*	50-443 Q	EISENHUT, D. Q.	8310030600*	50-346 P	EVERETT, R. J.	8310130380*	40-8084
DUB, R.	8310180273	50-373 S	EISENHUT, D. Q.	8310030602	50-312 F	EWERT, G. F.	8310240131	50-329 A
DUVALL, D. D.	8310120224	50-341 S	EISENHUT, D. Q.	8310040061	50-289 Q	EWERT, G. F.	8310270066	50-329 A
DYNNER, A. R.	8310040618	50-322 Q	EISENHUT, D. Q.	8310040639	50-362 F	EWERT, G. F.	8310310369	50-329 A
DYNNER, A. R.	8310040618	50-322 Q	EISENHUT, D. Q.	8310040642*	50-362 F	EYSTER, R. E.	8310280018	50-142 T
DZEDZY, J. L.	8310280083	50-352 H	EISENHUT, D. Q.	8310050077	50-346 F	FABRIKANT, J. I.	8310060212*	50-400 Q
DZIADOSZ, D.	8310190037*	50-280 P	EISENHUT, D. Q.	8310050144	50-289 P	FABRIKANT, J. I.	8310060212*	50-400 Q
EAGLE, J.	8310060249	50-265 S	EISENHUT, D. Q.	8310060064*	50-416 P	FALCONER, D.	8310040907*	50-269 Q
EARLE, D. K.	8310200109	50-341 H	EISENHUT, D. Q.	8310060134	MISC	FALCONER, D.	8310250336*	50-269 Q
EARLE, T. C.	8310130134*	MISC	EISENHUT, D. Q.	8310060213	50-213 P	FALKENHEIMER, D.	8310280183	50-458 A
EARLEY, A. F.	8310060300	50-322 Q	EISENHUT, D. Q.	8310070048*	50-293 P	FALKENHEIMER, D.	8310280183	50-458 A
EARLEY, A. F.	8310060300	50-322 Q	EISENHUT, D. Q.	8310070140	50-382 A	FALSON, V. K.	8310070165	CONTRACT
EARLEY, A. F.	8310120119	50-322 Q	EISENHUT, D. Q.	8310070393*	50-298 F	FANNING, G.	8310170557	50-304 S
EARLEY, A. F.	8310120119	50-322 Q	EISENHUT, D. Q.	8310110246	50-289 P	FARRAR, D. L.	8310030311	PR
EARLEY, A. F.	8310310128	50-322 Q	EISENHUT, D. Q.	8310120041*	50-387 P	FARRAR, D. L.	8310040162*	50-456 Q
EARLEY, A. F.	8310310128	50-322 Q	EISENHUT, D. Q.	8310120329	50-29 P	FARRAR, D. L.	8310040260*	50-454 Q
EASON, C. F.	8310280080	27-48	EISENHUT, D. Q.	8310130068	MISC	FARRAR, D. L.	8310040444	50-373 F
ECKERT, H. J.	8310040381*	50-155 T	EISENHUT, D. Q.	8310130326	50-289 P	FARRAR, D. L.	8310110478*	50-237 S
ECKERT, H. J.	8310040381*	50-155 T	EISENHUT, D. Q.	8310130342	50-289 P	FARRAR, D. L.	8310120401*	50-454 Q
ECKERT, J. P.	8310040470*	70-27	EISENHUT, D. Q.	8310140291	50-289 P	FARRAR, D. L.	8310140049*	50-10 Q
ECKERT, J. P.	8310260179*	70-27	EISENHUT, D. Q.	8310140302	50-289 Q	FARRAR, D. L.	8310140104*	50-10 Q
ECKHARDT, J.	8310120065	50-362 S	EISENHUT, D. Q.	8310170025	50-289 P	FARRAR, D. L.	8310170671*	50-456 Q
ECKHARDT, J.	8310140133	50-362 S	EISENHUT, D. Q.	8310170063	50-344 F	FARRAR, D. L.	8310170718	70-2973
ECKHARDT, J.	8310140284	50-361 S	EISENHUT, D. Q.	8310170266	50-397 F	FARRAR, D. L.	8310240077*	50-456 Q
ECKHARDT, J. H.	8310240201*	50-328 A	EISENHUT, D. Q.	8310170296*	50-393 P	FARRAR, D. L.	8310250361*	50-373 Q
ED, D. D.	8310170356*	50-454 Q	EISENHUT, D. Q.	8310170302	MISC	FARRELL, E. V.	8310250410	50-317 S
ED, D. D.	8310170356*	50-454 Q	EISENHUT, D. Q.	8310170542*	50-275 Q	FARRELL, E. V.	8310310407*	50-409 Q
EDDINGS, M. Q.	8310190066	50-327 R	EISENHUT, D. Q.	8310180019	MISC	FASAND, A.	8310140170*	50-320 Q
EDDLEMAN, W.	8310030367	50-400 Q	EISENHUT, D. Q.	8310200248*	50-454 Q	FAW, R. E.	8310130070	50-188 R
EDDLEMAN, W.	8310030369*	50-400 Q	EISENHUT, D. Q.	8310210344*	50-328 P	FAY, C. W.	8310030616*	50-266 F
EDDLEMAN, W.	8310030372*	50-400 Q	EISENHUT, D. Q.	8310240269	50-317 S	FAY, C. W.	8310030447	50-266 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FAY, C. W.	8310040310	50-266 P	FELTON, J. M.	8310110444	FOIA	FELTON, J. M.	8310250656	50-483 F
FAY, C. W.	8310040623	50-266 H	FELTON, J. M.	8310110470	FOIA	FELTON, J. M.	8310250660	50-285 F
FAY, C. W.	8310070303	50-266 V	FELTON, J. M.	8310110503	FOIA	FELTON, J. M.	8310250668	50-331 F
FAY, C. W.	8310120089	50-266 G	FELTON, J. M.	8310110523	FOIA	FELTON, J. M.	8310250673	50-259 F
FAY, C. W.	8310120275	PR	FELTON, J. M.	8310110557	FOIA	FELTON, J. M.	8310260008	50-10 S
FAY, C. W.	8310170380	50-301 S	FELTON, J. M.	8310110564	FOIA	FELTON, J. M.	8310260019	70-1144
FAY, C. W.	8310180119	50-266 R	FELTON, J. M.	8310110571	FOIA	FELTON, J. M.	8310260428	50-280 F
FAY, C. W.	8310180421	50-266 P	FELTON, J. M.	8310110586	FOIA	FELTON, J. M.	8310260431	50-263 F
FAY, C. W.	8310180490	50-266 P	FELTON, J. M.	8310120006	50-201 I	FELTON, J. M.	8310270005	50-331 F
FAY, C. W.	8310200202	50-301 P	FELTON, J. M.	8310120016	50-339 P	FELTON, J. M.	8310270009	50-10 F
FEHRINGER, D. J.	8310210335	WASTE MGT	FELTON, J. M.	8310130102	50-344 F	FELTON, J. M.	8310270011	50-289 P
FEIERABEND, C. D.	8310240102*	50-282 Q	FELTON, J. M.	8310130307	50-285 F	FELTON, J. M.	8310270018	50-213 F
FEIL, R. A.	8310170621*	50-397 Q	FELTON, J. M.	8310130310	50-409 F	FELTON, J. M.	8310270020	FOIA
FEIL, R. A.	8310210045*	50-397 Q	FELTON, J. M.	8310130312	50-317 F	FELTON, J. M.	8310270024	50-254 F
FEIL, R. A.	8310210060*	50-397 Q	FELTON, J. M.	8310130394	50-329 A	FELTON, J. M.	8310270026	50-369 F
FELTON, J. M.	8310030229	50-373 F	FELTON, J. M.	8310130409	FOIA	FELTON, J. M.	8310270027	FOIA
FELTON, J. M.	8310030564	50-315 F	FELTON, J. M.	8310130412	FOIA	FELTON, J. M.	8310270039	50-309 F
FELTON, J. M.	8310030573	50-395 F	FELTON, J. M.	8310140031	50-498 G	FELTON, J. M.	8310270040	50-320 P
FELTON, J. M.	8310030609	50-266 F	FELTON, J. M.	8310170003	50-317 F	FELTON, J. M.	8310270049	50-389 F
FELTON, J. M.	8310040121	50-10 F	FELTON, J. M.	8310170006	50-289 F	FELTON, J. M.	8310270051	FOIA
FELTON, J. M.	8310050327	50-289 F	FELTON, J. M.	8310170029	FOIA	FELTON, J. M.	8310270071	FOIA
FELTON, J. M.	8310050340	50-317 F	FELTON, J. M.	8310170049	FOIA	FELTON, J. M.	8310270074	FOIA
FELTON, J. M.	8310060243	50-313 F	FELTON, J. M.	8310170070	FOIA	FELTON, J. M.	8310270076	50-244 F
FELTON, J. M.	8310060256	50-213 F	FELTON, J. M.	8310170707	50-373 F	FELTON, J. M.	8310270082	FOIA
FELTON, J. M.	8310060265	50-369 F	FELTON, J. M.	8310170735	50-148 F	FELTON, J. M.	8310270089	FOIA
FELTON, J. M.	8310060474	50-315 F	FELTON, J. M.	8310170741	50-321 F	FELTON, J. M.	8310270104	FOIA
FELTON, J. M.	8310060481	50-387 F	FELTON, J. M.	8310180029	50-341 F	FELTON, J. M.	8310270117	FOIA
FELTON, J. M.	8310060490	50-335 F	FELTON, J. M.	8310180534	50-333 P	FELTON, J. M.	8310270119	50-289 F
FELTON, J. M.	8310060519	50-280 F	FELTON, J. M.	8310180556	FOIA	FELTON, J. M.	8310270132	FOIA
FELTON, J. M.	8310060529	50-289 F	FELTON, J. M.	8310180571	FOIA	FELTON, J. M.	8310270250	50-275 P
FELTON, J. M.	8310060533	50-387 F	FELTON, J. M.	8310180588	50-445 A	FELTON, J. M.	8310270262	50-358 G
FELTON, J. M.	8310060541	50-234 F	FELTON, J. M.	8310180590	50-308 H	FELTON, J. M.	8310270281	FOIA
FELTON, J. M.	8310060549	50-289 F	FELTON, J. M.	8310180600	50-322 A	FELTON, J. M.	8310270347	50-29 G
FELTON, J. M.	8310060555	50-324 F	FELTON, J. M.	8310180603	FOIA	FELTON, J. M.	8310270360	FOIA
FELTON, J. M.	8310060566	50-280 F	FELTON, J. M.	8310180610	50-275 P	FELTON, J. M.	8310270369	50-289 P
FELTON, J. M.	8310060590	50-346 F	FELTON, J. M.	8310180623	50-329 A	FELTON, J. M.	8310270393	50-289 F
FELTON, J. M.	8310060597	50-313 F	FELTON, J. M.	8310190041	FOIA	FELTON, J. M.	8310270468	FOIA
FELTON, J. M.	8310070128	50-370 F	FELTON, J. M.	8310190049	FOIA	FELTON, J. M.	8310270481	50-317 F
FELTON, J. M.	8310070134	50-269 F	FELTON, J. M.	8310190062	FOIA	FELTON, J. M.	8310270491	50-155 F
FELTON, J. M.	8310070403	50-280 F	FELTON, J. M.	8310190093	FOIA	FELTON, J. M.	8310270501	FOIA
FELTON, J. M.	8310110604	50-295 F	FELTON, J. M.	8310190291	50-313 F	FELTON, J. M.	8310270503	FOIA
FELTON, J. M.	8310110607	50-445 A	FELTON, J. M.	8310190294	50-313 F	FELTON, J. M.	8310270518	50-344 F
FELTON, J. M.	8310110619	50-155 F	FELTON, J. M.	8310190309	FOIA	FELTON, J. M.	8310270526	50-10 F
FELTON, J. M.	8310110621	FOIA	FELTON, J. M.	8310190316	50-329 A	FELTON, J. M.	8310270532	50-29 F
FELTON, J. M.	8310110627	50-305 F	FELTON, J. M.	8310190322	FOIA	FELTON, J. M.	8310270541	50-277 G
FELTON, J. M.	8310110630	FOIA	FELTON, J. M.	8310190325	FOIA	FELTON, J. M.	8310270552	50-461 F
FELTON, J. M.	8310110634	50-275 P	FELTON, J. M.	8310190340	50-282 S	FELTON, J. M.	8310270566	50-275 F
FELTON, J. M.	8310110635	50-331 F	FELTON, J. M.	8310200032	50-289 P	FELTON, J. M.	8310270582	50-275 F
FELTON, J. M.	8310110642	50-331 F	FELTON, J. M.	8310200079	50-254 F	FELTON, J. M.	8310270590	50-155 F
FELTON, J. M.	8310110644	50-382 G	FELTON, J. M.	8310200356	FOIA	FELTON, J. M.	8310280079	50-361 S
FELTON, J. M.	8310110664	50-309 F	FELTON, J. M.	8310200379	FOIA	FELTON, J. M.	8310280176	50-400 A
FELTON, J. M.	8310110665	40-17	FELTON, J. M.	8310200410	50-135 F	FELTON, J. M.	8310280191	50-10 F
FELTON, J. M.	8310110667	50-269 F	FELTON, J. M.	8310200416	50-373 F	FELTON, J. M.	8310280206	50-373 F
FELTON, J. M.	8310110672	50-369 F	FELTON, J. M.	8310200426	50-289 F	FELTON, J. M.	8310280252	50-277 F
FELTON, J. M.	8310110682	50-346 F	FELTON, J. M.	8310200437	50-320 F	FELTON, J. M.	8310280253	50-3 F
FELTON, J. M.	8310110691	50-387 F	FELTON, J. M.	8310200450	FOIA	FELTON, J. M.	8310280307	50-10 F
FELTON, J. M.	8310110696	50-327 F	FELTON, J. M.	8310210311	FOIA	FELTON, J. M.	8310280311	50-213 F
FELTON, J. M.	8310110702	50-320 F	FELTON, J. M.	8310210315	50-352 A	FELTON, J. M.	8310310031	50-3 P
FELTON, J. M.	8310110709	50-445 F	FELTON, J. M.	8310210323	FOIA	FELTON, J. M.	8310310097	50-320 P
FELTON, J. M.	8310110718	50-373 F	FELTON, J. M.	8310210325	FOIA	FENN, D. D.	8310120374*	50-29 P
FELTON, J. M.	8310110724	50-346 F	FELTON, J. M.	8310210329	50-321 S	FENNETEAU, H. M.	8310210255	50-458 S
FELTON, J. M.	8310110735	50-269 F	FELTON, J. M.	8310210359	50-346 F	FENSTERSTOCK, J.	8310170118*	CONTRACT
FELTON, J. M.	8310110776	50-263 F	FELTON, J. M.	8310210362	50-259 F	FERGUSON, J. H.	8310270021*	50-213 F
FELTON, J. M.	8310110866	50-280 F	FELTON, J. M.	8310210366	50-285 F	FERGUSON, W.	8310120036*	50-201 I
FELTON, J. M.	8310110195	50-259 F	FELTON, J. M.	8310210374	50-295 F	FERKIN, Z. G.	8310060305	50-352 Q
FELTON, J. M.	8310110234	50-267 F	FELTON, J. M.	8310210384	50-289 F	FERKIN, Z. G.	8310140019	50-412 Q
FELTON, J. M.	8310110237	50-280 F	FELTON, J. M.	8310210389	50-305 F	FERKIN, Z. G.	8310140091	50-412 Q
FELTON, J. M.	8310110244	50-317 F	FELTON, J. M.	8310210412	50-170 F	FERKIN, Z. G.	8310180140	50-412 Q
FELTON, J. M.	8310110253	50-155 F	FELTON, J. M.	8310210414	50-482 F	FERLIC, K.	8310180386*	50-5 G
FELTON, J. M.	8310110263	50-280 F	FELTON, J. M.	8310240012	50-413 T	FERNANDEZ, W.	8310060089	50-333 S
FELTON, J. M.	8310110325	50-254 F	FELTON, J. M.	8310240171	FOIA	FERRANTE, J.	8310180175*	CONTRACT
FELTON, J. M.	8310110329	50-285 F	FELTON, J. M.	8310240189	FOIA	FEV, F. L.	8310110180*	50-263 F
FELTON, J. M.	8310110350	FOIA	FELTON, J. M.	8310240191	FOIA	FEV, F. L.	8310260435*	50-263 F
FELTON, J. M.	8310110353	FOIA	FELTON, J. M.	8310240193	FOIA	FIALKA, J.	8310200374	FOIA
FELTON, J. M.	8310110361	50-438 G	FELTON, J. M.	8310240197	50-528 G	FIEDLER, P. B.	8310110217	50-219 P
FELTON, J. M.	8310110362	50-83 F	FELTON, J. M.	8310240234	FOIA	FIEDLER, P. B.	8310110399*	50-219 F
FELTON, J. M.	8310110364	FOIA	FELTON, J. M.	8310240235	FOIA	FIEDLER, P. B.	8310170335	50-219 P
FELTON, J. M.	8310110380	50-192 F	FELTON, J. M.	8310240237	FOIA	FIEDLER, P. B.	8310170605	71-9111
FELTON, J. M.	8310110385	50-219 F	FELTON, J. M.	8310240263	FOIA	FIEDLER, P. B.	8310190031	50-219 R
FELTON, J. M.	8310110413	50-369 F	FELTON, J. M.	8310240281	FOIA	FIEDLER, P. B.	8310190328	71-9010
FELTON, J. M.	8310110424	50-192 F	FELTON, J. M.	8310240312	FOIA	FIEDLER, P. B.	8310200161	50-219 S
FELTON, J. M.	8310110430	50-237 G	FELTON, J. M.	8310240320	50-348 P	FIEDLER, P. B.	8310270158*	50-219 Q
FELTON, J. M.	8310110433	50-315 F	FELTON, J. M.	8310250002	FOIA	FIEDLER, J.	8310030301	50-321 J
FELTON, J. M.	8310110436	50-322 A	FELTON, J. M.	8310250028	FOIA	FIELDS, D.	8310140268*	50-302 R
FELTON, J. M.	8310110437	50-313 F	FELTON, J. M.	8310250032	FOIA	FIELDS, J. A.	8310030319	CONTRACT

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FIELDS, J A	8310130404	CONTRACT	FRAMM, R	8310200279	50-311 S	GALLAGHER, J W	8310200172*	50-277
FIELDS, J S	8310200221	50-387 B	FRAMM, R	8310200238	50-272 S	GALLAGHER, J W	8310260208*	50-443
FIELDS, S R	8310260427	MUREO	FRAMM, R	8310200244	50-311 S	GALLE, D P	8310280314*	50-10
FILKINS, D L	8310203035	50-244 S	FRAMM, R	8310203025	50-272 S	QALLO, J	8310040365	50-155
FILSON, J R	8310050391*	CONTRACT	FRAMM, R	8310203090	50-272 S	QALLO, J	8310040365	50-155
FINDLEY, D C	8310260375*	CONTRACT	FRAMM, R	83102030407	50-311 S	QALLO, J	8310040376	50-155
FINKEL, A	8310060012*	50-410 Q	FRAMM, R	83102030470	50-311 S	QALLO, J	8310040376	50-155
FIOREAVANTE, N	8309080363*	GEN TEC IS	FRAMM, R	83102030647	50-311 S	QALLO, J	8310040505	50-155
FIORRELLI, G	8310040537*	50-528 Q	FRAMM, R	83102800024	50-272 S	QALLO, J	8310040505	50-155
FITTI, C J	8310280234*	50-400 A	FRAME, P W	8310170011	40-866	QALLO, J	8310040505	50-155
FITZGERALD, J A	8310200394*	FOIA	FRANKABZEK, J J	8310260317*	FOIA	QALLO, J	8310040548	50-155
FITZIBBONS, R	8310310145	50-155 Q	FREDERICK, R J	8310270116*	FOIA	QALLO, J	8310040551	50-155
FITZIBBONS, R	8310310145	50-155 Q	FREDERICK, R J	8310270136*	FOIA	QALLO, J	8310040551	50-155
FITZIBBONS, R	8310310391	50-155 Q	FREEMAN, O J	8310210173*	50-397 A	QALLO, J	8310040553	50-155
FITZIBBONS, R	8310310391	50-155 Q	FREEMAN, M	8310260411	40-876B	QALLO, J	8310040553	50-155
FITZPATRICK, B	8310270313*	50-266 Q	FREEMAN, M D	8310260377	40-876B	QALLO, J	8310040594	50-155
FITZWATER, M E	8310190313*	FOIA	FRENCH, L D	8310250232	50-27 S	QALLO, J	8310040594	50-155
FLACH, W T	8310280122*	50-311 Q	FRENCH, L D	8310280018	50-27 S	QALLO, J	8310050483	50-155
FLACK, E	8308310105	I&E	FRESCO, A	8310270075*	FOIA	QALLO, J	8310050483	50-155
FLACK, E	8310030920	I&E	FRIEDERICH, S	8310040123*	50-395 P	QALLO, J	8310050483*	50-155
FLACK, E	8310050536	I&E	FRIEDMAN, L	8308310330	I&E	QALLO, J	8310050483*	50-155
FLACK, E	8310140237	I&E	FROMM, E	8310110337*	CONTRACT	QALLO, J	8310110045	50-155
FLACK, E	8310180199	I&E	FRYE, D L	8310040324*	50-267 S	QALLO, J	8310110045	50-155
FLACK, E	8310180413	I&E	FRYE, J H	8310040192	50-142 Q	QALLO, J	8310110063	50-155
FLACK, E	8310310406	40-299	FRYE, J H	8310110034	50-142 Q	QALLO, J	8310110063	50-155
FLEENOR, C	8310050383	CONTRACT	FRYE, J H	8310110214	50-358 Q	QALLO, J	8310120211	50-155
FLEENOR, C	8310070407	CONTRACT	FRYE, J H	8310120372	50-70 Q	QALLO, J	8310120211	50-155
FLEENOR, C	8310120033	CONTRACT	FRYE, J H	8310260205	50-358 Q	QALLO, J	8310130174	50-155
FLEENOR, C	8310120038	CONTRACT	FRYE, J H	8310260263	50-142 Q	QALLO, J	8310130174	50-155
FLEENOR, C	8310280062	CONTRACT	FRYE, J H	8310280225*	50-400 A	QALLO, J	8310130214	50-155
FLIPPID, T A	8310310408*	50-382 Q	FRYE, J H	8310310240	50-142 Q	QALLO, J	8310130214	50-155
FLORIS, A B	8310110344*	CONTRACT	FRYER, B C	8310050470*	50-255 P	QALLO, J	8310140074	50-155
FLYNN, M J	8310050466	CONTRACT	FRYLING, R	8310030484	50-354 Q	QALLO, J	8310140074	50-155
FLYNN, M J	8310070228	CONTRACT	FUENKADORN, K	8310070414	MUREO	QALLO, J	8310170420	50-155
FLYNN, M J	8310070234	CONTRACT	FUHRMAN, G R	8310040342	50-317 S	QALLO, J	8310170420	50-155
FLYNN, M J	8310110342	CONTRACT	FUHS, A	8310270400	50-254 S	QALLO, J	8310180222	50-155
FLYNN, M J	8310130388	CONTRACT	FUJIMOTO, R I	8310130418*	CONTRACT	QALLO, J	8310180222	50-155
FOGARTY, D J	8310120298	50-206 Q	FULLER, C H	8310170260	50-267 R	QALLO, J	8310180230	50-155
FOGARTY, D J	8310190008	50-206 H	FURSE, M C	8310060319	50-454 Q	QALLO, J	8310180230	50-155
FOGQ, E C	8310070181*	CONTRACT	FURSE, M C	8310060319	50-454 Q	QALLO, J	8310180335	50-155
FOLEY, J R	8310110365	50-438 Q	FURSE, M C	8310060321*	50-454 Q	QALLO, J	8310180335	50-155
FOLEY, T	8310170310	50-247 S	FURSE, M C	8310180275	50-454 Q	QALLO, J	8310180348	50-155
FOLEY, W J	8310110580	MUREO	FURSE, M C	8310180275	50-454 Q	QALLO, J	8310180348	50-155
FOLEY, W J	8310180079	MUREO	FURSE, M C	8310180279*	50-454 Q	QALLO, J	8310200225	50-309
FOLEY, W J	8310280378	MUREO	FURSE, M C	8310180279*	50-454 Q	QALLO, J	8310200225	50-309
FORD, E J	8310190188*	50-423 Q	FUSSELL, J D	8310070220*	CONTRACT	QALLO, J	8310240128	50-155
FORD, E J	8310250517*	50-327 G	GAD, R K	8310110083	50-443 Q	QALLO, J	8310240128	50-155
FORD, E J	8310250624*	50-327 G	GAD, R K	8310110083	50-443 Q	QALLO, J	8310240132*	50-155
FORD, J T	8310170076	70-1201	GAD, R K	8310110092*	50-443 Q	QALLO, J	8310240132*	50-155
FORD, J T	8310170740	70-1201	GAD, R K	8310110092*	50-443 Q	QALLO, J	8310310139	50-155
FORD, W H	8310200467*	COMMISSION	GAD, R K	8310120133	50-443 Q	QALLO, J	8310310139	50-155
FORMICA, C D	8310130261*	50-400 E	GAD, R K	8310120133	50-443 Q	QALLO, J	8310310206	50-155
FORNEY, W	8310120256	50-358 S	GAD, R K	8310120428	50-443 Q	QALLO, J	8310310206	50-155
FORNEY, W	8310200132	50-358 S	GAD, R K	8310120428	50-443 Q	QALLO, J	8310310391	50-155
FORNEY, W L	8310050530*	50-358 Q	GAD, R K	8310140015	50-443 Q	QALLO, J	8310310391	50-155
FORNEY, W L	8310050546*	50-358 Q	GAD, R K	8310180130	50-443 Q	QALLO, R	8310040393*	50-410
FORTUNA, R	8310270462*	50-443 Q	GAD, R K	8310180130	50-443 Q	QALLO, R	8310060051	50-293
FORTUNA, R	8310270474*	50-443 Q	GAD, R K	8310180133*	50-443 Q	QALLO, R M	8310140082	50-29
FORTUNA, R A	8310040453*	QA999	GAD, R K	8310180133*	50-443 Q	QALLO, R M	8310140245*	50-271
FOSTER, C	8310180562	XPORTLIC	GAD, R K	8310180165	50-443 Q	QALLO, R M	8310190135*	50-410
FOSTER, C M	8310060090	XPORTLIC	GAD, R K	8310180165	50-443 Q	QALLO, R M	8310260437	50-293
FOSTER, C M	8310060130	XPORTLIC	GAD, R K	8310180170*	50-443 Q	QALLUP, D R	8310101174	MUREO
FOSTER, C M	8310180095	XPORTLIC	GAD, R K	8310180170*	50-443 Q	QALM, D T	8310170197	70-498
FOSTER, C M	8310180113	XPORTLIC	GAD, R K	8310200267	50-443 Q	QALVEAN, W J	8310110591*	FOIA
FOSTER, C M	8310240301	XPORTLIC	GAD, R K	8310200267	50-443 Q	QAMBLE, D H	8310280238*	50-400
FOSTER, C M	8310240302*	XPORTLIC	GAD, R K	8310200277	50-443 Q	QARCIA, E H	8310310249*	50-73
FOSTER, D L	8310260032*	FOIA	GAD, R K	8310200277	50-443 Q	QARCIA, H L	8310180149*	50-458
FOSTER, D L	8310260087*	FOIA	GAD, R K	8310260254	50-443 Q	QARCIA, P J	8310200446	40-8584
FOSTER, D L	8310260093*	FOIA	GAD, R K	8310260254	50-443 Q	QARCIA, P J	8310200436	40-6622
FOSTER, D L	8310260135*	FOIA	GAD, R K	8310260261*	50-443 Q	GARDE, B P	8310130390	50-329
FOSTER, D O	8310120296	50-424 S	GAD, R K	8310260261*	50-443 Q	GARDE, B P	8310180436	50-329
FOSTER, D O	8310170566	50-424 S	GAD, R K	8310260266*	50-443 Q	GARDE, B P	8310180465*	50-329
FOSTER, D O	8310190125	50-424 A	GAD, R K	8310260266*	50-443 Q	GARDE, B P	8310180618	50-329
FOSTER, D O	8310190126*	50-424 A	GAD, R K	8310260272*	50-443 Q	GARDE, B P	8310190300	50-329
FOSTER, D O	8310270315	50-424 S	GAD, R K	8310260272*	50-443 Q	GARDE, B P	8310190311	50-329
FOSTER, W E	8310180358*	QA999	GAGLIARDO, J E	8310180500	50-285 Q	GARDNER, R	8310140070	50-329
FOSTER, W H	8310280193*	50-400 Q	GAHM, J W	8310130236	50-267 Q	GARDNER, R B	8310170591*	50-329
FOSTER, W H	8310280202*	50-400 A	GAJIC, Z	8310180174	50-295 S	GARDNER, R N	8310170446*	50-329
FOSTER, W H	8310280207*	50-400 A	GALEN, R E	8310140063	50-483 Q	GARDNER, R N	8310170534*	50-329
FOSTER, W H	8310280211*	50-400 A	GALEN, R E	8310140063	50-483 Q	GARNER, L W	8310040332*	50-324
FOSTER, W H	8310280246*	50-400 A	GALLAGHER, E J	8310200454	50-320 Q	GARRITY, J H	8310210294*	50-309
FOSTER, W H	8310280250*	50-400 A	GALLAGHER, J W	8310030283	PR	GARRITY, J H	8310270200	50-309
FOSTER, W H	8310280259*	50-400 A	GALLAGHER, J W	8310040159	50-277 P	GARY, Q L	8310130268	50-445
FOSTER, W H	8310280263*	50-400 A	GALLAGHER, J W	8310040415	50-277 P	GARY, R J	8310030516	50-445
FRAMM, R	8310190178	50-311 S	GALLAGHER, J W	8310040434	50-277 F	GARY, R J	8310050403	50-445

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
GARY, R J	8310130278	50-445 S	GODDARD, R J	8310130031	50-155 0	GREEN, R F	8310180527*	QA999
GARY, R J	8310140180	50-445 K	GODDARD, R J	8310130169	50-309 0	GREENBLATT, M	8310070217*	CONTRACT
GARY, R J	8310180179	50-445 K	GODDY, A	8310040213	50-272 S	GREENE, F S	8310201080*	CONTRACT
GARY, R J	8310180484*	50-445 Q	GODDY, A T.	8310120143*	50-29 0	GREENE, R F	8310180532*	QA999
GARY, R J	8310180488*	50-445 Q	GODDY, A T	8310120156*	50-223 0	GREENE, T	8310170746*	50-321 F
GARY, R J	8310280003	50-445 S	GODDY, A T.	8310120201*	70-135	GREENMAN, E	8310040455	50-309 B
GAUNY, R D	8310280261*	50-3 F	GODDY, A T.	8310240083*	70-1100	GREENMAN, E	8310060253	50-309 B
GAVIDAN, F X	8310310059	50-537 A	GODDY, A T	8310250529*	50-272 0	GREENMAN, E	8310060344	50-309 B
GAUTIS, S	8310140021	50-443 Q	GODDY, A T	8310250603*	50-193 0	GREENMAN, E	8310310230*	50-317 Q
GEARS, G	8310210336	50-277 G	GODDY, A T.	8310270178*	70-371	GREENMAN, E	8310070016	70-364
GEORGE, D E	8310140256	50-304 S	GOLDBERG, J H	8310030167	50-498 K	GREENMAN, E	8310070027*	70-364
GEORGEV, G B	8310040433*	QA999	GOLDBERG, J H	8310140110	50-498 V	GREENMAN, E	8310140082	50-29 B
GERDEMAN, F W	8310070402	40-7867	GOLDBERG, S	8310200072*	50-271 0	GREER, W B	8310070414	MUREQ
GERDEMAN, F W	8310180104	40-8678	GOLDBERG, S C	8310050373	50-440 0	GREER, L R	8310040360*	70-36
GERDEMAN, F W	8310180129	40-8678	GOLDBERG, S C	8310130144	50-440 0	GREER, L R	8310050364*	50-87 Q
GERDEMAN, F W	8310180133	40-8674	GOLDSTEIN, J I	8310130163*	CONTRACT	GREER, L R	8310120204*	50-116 Q
GERNER, L	8310060545*	50-254 F	GONZALES, J C	8310140274*	50-329 S	GREER, L R	8310140216*	70-1308
GERNER, L	8310270028*	50-254 F	GOODMAN, L S	8310170354	50-409 B	GREER, L R	8310140255	50-266 B
GERRETS, T F	8310040134	50-382 S	GOODMAN, L S	8310190027	50-409 R	GREER, L R	8310210074*	50-10 Q
GERRETS, T F	8310190131	50-382 S	GOODWIN, D C	8310060407	50-276 S	GREER, L R	8310270313*	50-266 Q
GERRETS, T F	8310210258	50-382 S	GORE, A	8310110597*	COMMISSION	GREER, R J	8310250445*	70-820
GERRETS, T F	8310210290	50-382 S	GOSBICK, L V	8310200387*	FOIA	GREORY, W S	8310200344	REB
GERRETS, T F	8310210293	50-382 S	GOTCH, G.	8310130137*	50-389 Q	GREHAM, S C	8310270292	50-261 P
GERRETS, T F	8310280012	50-382 S	GOULD, T L	8310190073	50-320 S	GRIER, B H	8310110108*	40-17
GERRETS, T F	8310280069	50-382 S	GOULD, T L	8310190173	50-320 S	GRIER, B H	8310110130*	FOIA
GERRETS, T F	8310310292	50-382 S	GOULD, T L	8310190205	50-320 S	GRIER, B H	8310240185*	FOIA
GERRETS, T F	8310310300	50-382 S	GOULD, T L	8310200095	50-320 S	GRIER, B H	8310260163*	70-1144
GERUSKY, T M	8310030453	50-289 Q	GOULD, T L	8310250317	50-320 S	GRIER, B H	8310260378*	FOIA
GIANNELLI, J M	8310260168*	FOIA	GOULD, T L	8310250478	50-320 S	GRIFFIN, H B	8310180223*	50-445 Q
GIANNELLI, J M	8310260177*	FOIA	GOULD, T L	8310250629	50-320 S	GRIFFIN, H B	8310180229*	50-445 Q
GIBBONS, T D	8310250498*	50-348 Q	GOULDIN, J A	8310270031	FOIA	GRIFFIN, J M	8310030337	50-368 P
GIBBONS, T D	8310250569*	50-327 Q	GRABER, L.	8310110432	FOIA	GRIFFIN, J M	8310120079	50-313 P
GIBBS, J J	8310240183	50-400 Q	GRABER, L D	8310210324	FOIA	GRIFFIN, J M	8310130097	50-368 P
GIBBS, J J	8310240183	50-400 Q	GRABER, L D	8310270121	FOIA	GRIFFITH, B C	8310060295	50-413 Q
GIBBS, P M	8310130389*	CONTRACT	GRABER, L D	8310270340	50-29 S	GRIMBLEY, D H	8310240219*	50-528 A
GIBSON, A F	8310250063	50-259 S	GRACE, R H	8310190033	50-309 R	GRIMBLEY, D H	8310240221*	50-528 Q
GIBSON, J	8310170207	50-336 R	GRAEBER, K L	8310120108	50-295 R	GRUBSCH, O L	8310190321	FOIA
GIBSON, J.	8310250167	50-336 R	GRAEBER, K L	8310120174	50-295 S	GRUFF, D W	8310060079	70-143
GIESLER, C W	8310040617	50-305 P	GRAEBER, K L	8310140256	50-304 S	GRUGAN, J E	8310240058*	50-413 T
GIESLER, C W	8310060334*	50-305 Q	GRAEBER, K L	8310170557	50-304 S	GRUBSHAN, H	8310040175	50-460 Q
GIESLER, C W	8310110028*	50-305 F	GRAEBER, K L	8310170561	50-295 S	GRUBSHAN, H	8310180320	50-460 Q
GIESLER, C W	8310120244*	50-305 F	GRAEBER, K L	8310170579	50-304 S	GRUBSHAN, H	8310200240	50-460 Q
GIESLER, C W	8310120337	50-305 P	GRAEBER, K L	8310170588	50-295 S	GRUBSHAN, H	8310210203	50-460 Q
GIESLER, C W	8310170341	50-305 R	GRAEBER, K L	8310170609	50-304 S	GRUBSHAN, H	8310310226	50-460 Q
GIESLER, C W	8310180522	PR	GRAEBER, K L	8310210218	50-304 S	GRUTENHUIS, H	8310180583	50-305 P
GIESLER, C W	8310210304	50-305 S	GRAEBER, K L	8310270289	50-295 S	GUCHA, L T	8310070287	50-321 P
GIESLER, C W	8310210317	50-305 S	GRAHAM, D.	8310140268*	50-302 R	GUCHA, L T	8310110126	50-321 P
GIESLER, C W	8310210394*	50-305 F	GRAHAM, J J	8310190120	50-387 S	GUCHA, L T	8310210270	50-321 P
GIESLER, J V	8310250510*	QA999	GRAHAM, R. A.	8310190135*	50-410 Q	GUCHA, L T	8310310265	50-366 P
GIESLER, J V	8310250525*	QA999	GRANT, J	8310040393*	50-410 Q	GUCHA, L T	8310310308	50-321 P
GILBERT, E C	8310280220*	50-338 Q	GRANT, J.	8310190135*	50-410 Q	GUILD, R	8308300480	50-413 Q
GILBERTS, D E	8310250288*	50-282 Q	GRANT, J. M.	8310190203*	50-352 Q	GUILD, R	8308300480	50-413 Q
GILBERTS, D E	8310250561*	50-263 Q	GRANT, N W.	8310190023	50-250 R	GUILD, R	8308300486*	50-413 Q
GILDENHORN	8310110506	CONTRACT	GRANT, P J	8310280111	WASTE MGT	GUILD, R.	8308300486*	50-413 Q
GILDENHORN, A J	8310060117	CONTRACT	GRANT, T J.	8310110412*	50-400 Q	GUINN, F K	8310040309*	70-143
GILDENHORN, A J	8310110525	CONTRACT	GRANT, W. B.	8310040360*	70-36	GUINN, F K	8310040350*	70-143
GILDENHORN, A J	8310120052	CONTRACT	GRANT, W. B.	8310050544*	50-87 Q	GUINN, F K.	8310050473*	70-143
GILDENHORN, A J	8310130263	CONTRACT	GRANT, W. B.	8310120204*	50-116 Q	GUINN, F K	8310050535*	70-143
GILDENHORN, A J	8310170082	CONTRACT	GRANT, W. B.	8310140216*	70-1308	GUINN, F K	8310070145*	70-143
GILDENHORN, A J	8310170112	CONTRACT	GRANTHAM, B	8310250148*	QA999	GUINN, F K.	8310170680	70-143
GILDENHORN, A J	8310210086	CONTRACT	GRAVES, G. H.	8310240017*	50-413 T	GUINN, F. K.	8310190290	70-143
GILDER, M L.	8310170670*	50-440 Q	GRAVES, R. H.	8310190007	50-213 R	GUINN, F. K.	8310250340*	70-143
GILFOY, R	8310130277*	50-400 E	GRAVES, R. H.	8310250315	50-213 S	GUINN, F. K.	8310250500	70-143
GILINSKY, V	8310030408	50-289 Q	GRAVES, R. H	8310250321	50-213 S	GUINDAKER, W. F	8310040245*	50-382 Q
GILINSKY, V	8310070085*	50-346 P	GRAY, E H	8310190142*	50-443 Q	GUINDAKER, W. F	8310040245*	50-382 Q
GILINSKY, V	8310190054	50-275 Q	GREEN, A R	8310180541	XPORTLIC	GUSTAFSON, R B	8310170083	70-371
GILINSKY, V	8310270656*	40-672	GREEN, H J.	8310030218	50-327 S	GUSTAVE, R.	8310210180*	CONTRACT
GILLEN, D M	8310240095*	40-8681	GREEN, H J.	8310030240	50-328 S	GUSTAVE, R.	8310280068*	CONTRACT
GILLEN, K T	8310310447	MUREQ	GREEN, H J.	8310030405	50-260 S	GUSTAVE, R. P	8310050337*	CONTRACT
GILLETT, W T	8310190064	50-316 R	GREEN, H J.	8310030432	50-259 S	GUSTAVE, R. P.	8310050370*	CONTRACT
GILLETT, W T	8310190070	50-315 R	GREEN, H J.	8310060083	50-327 S	GUSTAVE, R. P.	8310050545*	CONTRACT
GLASS, S. M	8310170500	50-322 Q	GREEN, H J	8310060377	50-296 S	GUSTAVE, R. P	8310050550*	CONTRACT
GLASS, S. M	8310270239	50-322 Q	GREEN, H J.	8310060380	50-260 S	GUSTAVE, R. P.	8310050556*	CONTRACT
GLASSFIEGEL, H	8310270282	50-440 Q	GREEN, H J.	8310060407	50-296 S	GUSTAVE, R. P.	8310060103*	CONTRACT
GLEASON, J. P.	8310090509	50-483 Q	GREEN, H J.	8310140087	50-328 S	GUSTAVE, R. P.	8310060113*	CONTRACT
GLEASON, J. P.	8310190085	50-247 Q	GREEN, H J.	8310140129	50-259 S	GUSTAVE, R. P.	8310060129*	CONTRACT
GLEASON, J. P.	8310260224	50-247 Q	GREEN, H J.	8310140200	50-260 S	GUSTAVE, R. P.	8310060184*	27-39
GLEASON, J. P.	8310270307	50-247 Q	GREEN, H J.	8310170276	50-327 S	GUSTAVE, R. P.	8310060191*	CONTRACT
GLENN, J	8308310330	FOIA	GREEN, H J.	8310170592	50-327 S	GUSTAVE, R. P.	8310070189*	CONTRACT
GLOCKMAN, T.	8310270099	FOIA	GREEN, H J.	8310170597	50-327 S	GUSTAVE, R. P.	8310070429*	CONTRACT
GLOERSEN, W	8310140267*	50-237 Q	GREEN, H J.	8310170658	50-328 S	GUSTAVE, R. P.	8310070435*	CONTRACT
GLOERSEN, W. B	8310040198*	50-331 Q	GREEN, H J.	8310190124	50-327 S	GUSTAVE, R. P.	8310120019*	CONTRACT
GLOVER, M. S	8310110079*	50-369 F	GREEN, H J.	8310210228	50-259 S	GUSTAVE, R. P.	8310120024*	CONTRACT
GODDARD, R J	8310050410	50-354 Q	GREEN, H J.	8310250077	50-327 S	GUSTAVE, R. P.	8310120035*	CONTRACT
GODDARD, R. J.	8310050443	50-322 Q	GREEN, H J	8310270073	50-260 S	GUSTAVE, R. P.	8310120040*	CONTRACT

PERSONAL AUTHOR INDEX

501

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
GUSTAVE, R P	8310130385*	CONTRACT	HAMID, A A	8308310512*	50-267 Q	HASSELL, D F	8310130233	50-329 Q
GUSTAVE, R P	8310170550*	CONTRACT	HAMILTON, P	8310180111	50-293 R	HASSELL, D F	8310130305	50-247 Q
GUSTAVE, R P	8310180137*	CONTRACT	HAMILIN, J B	8310140030	50-498 Q	HAUGHEY, M F	8310070194	50-410 A
GUSTAVE, R P	8310180557*	CONTRACT	HAN, J T	8310240195*	FOIA	HAVIAN, E	8310250043	50-275 Q
GUSTAVE, R P	8310180576*	CONTRACT	HANAFORD, T	8310030102	50-361 R	HAVIAN, E	8310250043	50-275 Q
GUSTAVE, R P	8310180585*	CONTRACT	HANCOCK, J C	8310190329*	FOIA	HAVIAN, E	8310280097	50-275 Q
GUSTAVE, R P	8310240098*	CONTRACT	HANDLER, R	8310260043*	FOIA	HAVIAN, E	8310280097	50-275 Q
GUSTAVE, R P	8310260375*	CONTRACT	HANDLER, R	8310260125*	FOIA	HAVIAN, E R	8310040539	50-275 Q
GUSTAVE, R P	8310270606*	CONTRACT	HANDLER, R	8310260191*	FOIA	HAVIAN, E R	8310040539	50-275 Q
GUTKNECHT, P J	8310110347	NJREG	HANDLER, R	8310260354*	FOIA	HAWKINS, D A	8310180168	CONTRACT
GUTTERMAN, A H	8310110220	50-498 Q	HANNETT, B A	8310060081	XPORTLIC	HAWKINS, D A	8310260290	CONTRACT
GUTTERMAN, A H	8310110220	50-498 Q	HANNETT, B A	8310060084*	XPORTLIC	HAWKINS, E F	8310200373*	40-7869 Q
GUTTMANN, H E	8310200388	NJREG	HANNETT, B A	8310130396	XPORTLIC	HAYES, B B	8310140035*	50-289 Q
QWYNN, T P	8310090546*	50-358 G	HANNETT, B A	8310180143	XPORTLIC	HAYES, B B	8310170577	50-445 Q
HAAS, M N	8310060191*	CONTRACT	HANNETT, B A	8310180148*	XPORTLIC	HAYES, B B	8310200235	50-358 Q
HAAS, P M	8310190243	NJREG	HANNETT, B A	8310180302	XPORTLIC	HAYES, B B	8310270324*	50-289 Q
HAASS, W P	8310210381*	50-275 T	HANNETT, B A	8310280026	XPORTLIC	HAYES, B B	8310270442*	50-443 Q
HAASS, W P	8310250182*	50-275 T	HANNETT, B A	8310280033*	XPORTLIC	HAYES, B B	8310270474*	50-443 Q
HABIGER, A	8310280359*	QA999	HANSEN, E M	8310120374*	50-29 P	HAYES, B B	8310280220*	50-358 Q
HACKNEY, B D	8310140274*	50-529 S	HANSEN, L J	8310170291	71-9132	HAYES, D W	8310040430*	50-454 Q
HACKNEY, C A	8310030457*	50-267 Q	HANSEN, L J	8310190285	71-9145	HAYES, D W	8310060309*	50-461 Q
HACKNEY, C A	8310310286*	50-298 Q	HANSEN, L J	8310210331	71-9181	HAYES, D W	8310170577	50-445 Q
HADNAGY, P A	8310120092	50-482 S	HARDESTY, D	8310310130*	50-416 G	HAYES, D W	8310310293*	50-461 Q
HADNAGY, P A	8310310135	PT21	HARDROVE, T W	8310260003	40-2259	HAYNES, D W	8310280242*	50-461 Q
HAFNER, B	8310180597	50-322 A	HARDIN, A	8310270224	50-325 S	HAYNES, J O	8310250145	50-361 S
HAFNER, B	8310210327	FOIA	HARDING, M	8310190124	50-327 S	HAYNES, J O	8310250455	50-266 S
HAFNER, B	8310270496	FOIA	HARDING, M R	8310030218	50-327 S	HAYNES, J O	8310250463	50-362 S
HAGAN, T	8310060010*	CONTRACT	HARDING, M R	8310030240	50-328 S	HAYNES, J O	8310250495	50-362 S
HAGAN, T	8310180175*	CONTRACT	HARDING, M R	8310060083	50-327 S	HAYNES, J O	8310270416	50-362 S
HAGAN, T F	8310050369*	CONTRACT	HARDING, M R	8310230077	50-327 S	HAYNES, J O	8310270428	50-362 S
HAGAN, T F	8310050464*	CONTRACT	HARLESS, B L	8310260183*	FOIA	HAYNES, J O	8310270432	50-362 S
HAGAN, T F	8310060138*	CONTRACT	HARMON, D W	8310250331	PR	HAYNES, J O	8310270434	50-361 S
HAGAN, T F	8310110310*	CONTRACT	HARRAN, Q	8310170015	50-245 R	HAYNES, J O	8310270439	50-362 S
HAGAN, T F	8310110528*	CONTRACT	HARRAN, Q	8310200129	50-245 R	HAYNES, J O	8310270448	50-362 S
HAGAN, T F	8310120053*	CONTRACT	HARRELL, E W	8310070328	50-338 S	HAYNES, J O	8310270463	50-361 S
HAGAN, T F	8310170118*	CONTRACT	HARRELL, E W	8310140161	50-338 S	HAYNES, J O	8310270495	50-362 S
HAGAN, T F	8310180596*	CONTRACT	HARRELL, E W	8310210047	50-339 S	HAYNES, J O	8310270498	50-361 S
HAGAN, T F	8310210087*	CONTRACT	HARRELL, E W	8310210058	50-338 S	HAYNES, J O	8310310326	50-361 S
HAGAN, T F	8310210155*	CONTRACT	HARRELL, P H	8310180450*	QA999	HAZLE, A J	8310130066	HABTE NOT
HAGAN, T F	8310240106*	CONTRACT	HARRINGTON, W D	8309190140	50-293 R	HEAD, Q F	8310070279	50-321 P
HAGAN, T F	8310240130*	CONTRACT	HARRINGTON, W D	8310030354	50-293 P	HEAD, Q F	8310120265	50-321 P
HAGAN, T F	8310110070*	FOIA	HARRINGTON, W D	8310120307	50-293 P	HEALY, R J	8310190283	NJREG
HAGEN, T F	8310170084*	CONTRACT	HARRINGTON, W D	8310120330	50-293 P	HEBDON, F J	8310130130	NJREG
HAGEY, H A	8310110508	CONTRACT	HARRINGTON, W D	8310180111	50-293 R	HEETHER, W H	8310060120	XPORTLIC
HAQUE, R L	8310240003*	50-301 Q	HARRINGTON, W D	8310180435	50-293 F	HEETHER, W H	8310250018	XPORTLIC
HAQUE, R L	8310270313*	50-266 Q	HARRINGTON, W D	8310180479	50-293 P	HEETHER, W H	8310260018	XPORTLIC
HAIRSTON, W Q	8310030439	50-364 S	HARRINGTON, W D	8310180491	50-293 P	HEIL, C W	8310250360*	50-321 Q
HAIRSTON, W Q	8310070138	50-348 S	HARRINGTON, W D	8310190174	50-293 S	HEIDEL, C H	8310170594*	50-341 K
HAIRSTON, W Q	8310070290	50-364 S	HARRINGTON, W D	8310250137	50-293 S	HEIDER, L H	8310190012	50-29 N
HAIRSTON, W Q	8310070299*	50-348 S	HARRINGTON, W D	8310250282	50-293 S	HEISHMAN, R	8310110191	50-329 Q
HAIRSTON, W Q	8310070302*	50-348 S	HARRINGTON, W D	8310250544	50-293 K	HELD, J T	8306030372*	50-286 P
HAIRSTON, W Q	8310120354*	50-348 S	HARRINGTON, W D	8310270230*	50-293 Q	HELD, J T	8306080053*	50-312 P
HAIRSTON, W Q	8310120363*	50-348 S	HARRINGTON, W D	8310310144	50-293 P	HELD, J T	8306080063*	50-336 P
HAIRSTON, W Q	8310120371*	50-348 S	HARRINGTON, W D	8310310290	50-293 P	HELD, J T	8306080106*	50-302 P
HAIRSTON, W Q	8310140229*	50-348 S	HARRINGTON, W D	8310310306	50-293 P	HELD, J T	8306080106*	50-302 P
HAIRSTON, W Q	8310140235*	50-348 S	HARRIS, B L	8310250370*	50-409 P	HELD, J T	8306080112*	50-272 P
HAIRSTON, W Q	8310180124	50-348 R	HARRIS, D R	8310200051	50-225 P	HELD, J T	8306130436*	50-346 P
HAIRSTON, W Q	8310180134	50-364 R	HARRIS, D R	8310200055*	50-225 P	HELD, J T	8310050534*	50-237 P
HAIRSTON, W Q	8310190071	50-364 R	HARRIS, D R	8308310512*	50-267 Q	HELFRIED, R E	8310040307	PR
HAIRSTON, W Q	8310270108*	50-364 S	HARRIS, J	8310030333	PR	HELFRIED, R E	8310040324	PR
HAIRSTON, W Q	8310270115*	50-364 S	HARRIS, J R	8310250236*	50-537 Q	HELLER, J K	8310040255*	50-255 Q
HAIST, D	8310250543	50-344 S	HARRIS, M S	8310170490	50-331 S	HELLER, R A	8310040322*	50-267 S
HAIST, D P	8310170663*	50-508 Q	HARRIS, M S	8310250481	50-331 S	HELMES, C J	8305160184*	50-361 S
HALE, C J	8310040596*	QA999	HARRISON, F	8310130124	50-324 R	HELMES, C J	8309070071*	MTSC
HALE, C J	8310180450*	QA999	HARRISON, Q	8310130020	50-352 Q	HELMES, C J	8309160058*	NJREG
HALE, C J	8310250270*	QA999	HARRISON, Q	8310240254	50-461 A	HELMES, C J	8310060171	50-251 S
HALL, B L	8310030305*	50-280 Q	HARRISON, J	8310120446	50-329 S	HELMES, C J	8310060173*	50-251 S
HALL, B L	8310070294*	50-324 Q	HARRISON, J	8310140090	50-329 S	HELMES, C J	8310060179*	50-251 S
HALL, B L	8310270023*	50-321 Q	HARRISON, J J	8310050393	50-329 A	HELMES, C J	8310060185*	50-251 S
HALL, D P	8310040204	50-461 S	HARRISON, J J	8310140270	50-329 A	HELMES, C J	8310060190*	50-251 S
HALL, D P	8310040238	50-461 S	HARRISON, J J	8310170436	50-329 A	HELMES, C J	8310060194*	50-251 S
HALL, D P	8310060409*	50-461 Q	HARRISON, J J	8310170464*	50-329 Q	HENCH, L L	8310050239	NJREG
HALL, D P	8310110105	50-461 H	HARRISON, J J	8310170534*	50-329 Q	HENDRICKSON, R.	8310030093	50-116 P
HALL, D P	8310120077	50-461 S	HARRISON, J J	8310170572*	50-329 Q	HENDRICKSON, R	8310030123	50-116 F
HALL, D P	8310120181	50-461 A	HARRISON, J J	8310170591*	50-329 Q	HENNICK, A.	8310110580	NJREG
HALL, D P	8310120441	50-461 S	HARRISON, J J	8310210319*	50-329 Q	HENNICK, A.	8310180079	NJREG
HALL, D P	8310200201	50-461 K	HARRISON, J J	8310250499	50-329 A	HENNICK, A.	8310200378	NJREG
HALL, D P	8310250619	50-461 Q	HARRISON, J J	8310270165	50-329 Q	HENRY, H O	8310210192*	50-413 T
HALL, N M	8310050362*	CONTRACT	HARRISON, J J	8310310417*	50-329 Q	HENRY, H O	8310240049*	50-413 T
HALL, R E	8310130190*	50-498 Q	HARSTEAD, Q A	8310040573*	50-382 A	HENRY, H O	8310240053*	50-413 T
HALL, R E	8310130211*	50-298 Q	HARSTEAD, Q A	8310280006*	50-382 A	HENBLEY, K D	8310170036	70-143
HALL, R E	8310130230*	50-498 Q	HARTMANN, P L	8310240096*	50-295 Q	HENBLEY, K D	8310170724	70-143
HALLMAN, V D	8310180224*	50-135 Q	HARTMANN, P L	8310270313*	50-266 Q	HENBLEY, K D	8310170737	70-143
HALMAN, E L	8310070203*	CONTRACT	HASSE, R A	8310140215*	50-373 Q	HERBEK, R F	8310240187	50-247 Q
HAMEL, D B	8310120421	50-331 B	HASSELL, D F	8310130010	50-329 Q	HERMANSKY, J	8310210146	40-299

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HERNAN, R	8310130070	50-302 P	HOLYOAK, R H	8310110123*	50-373 F	HUKILL, H D	8310200061	50-289 S
HERNAN, R	8310180630*	50-329 A	HOLYOAK, R H	8310170711*	50-373 F	HUKILL, H D	8310200430*	50-289 F
HERNAN, R	8310210116	50-302 P	HOLYOAK, R H	8310200424*	50-373 F	HUKILL, H D	8310210037	50-289 R
HERNAN, R. W	8212300076*	50-329 A	HOLZMER, H	8310210131	50-255 S	HUKILL, H D	8310210085	50-289 P
HERNANDEZ, Q H	8310310341*	50-275 Q	HONOLICH, J	8310170070	50-400 F	HUKILL, H D	8310210283*	50-289 Q
HERR, R K	8310180223*	50-445 Q	HOOD, D	8310030342	50-329 A	HUKILL, H D	8310230253	50-289 S
HERR, R K	8310180229*	50-445 Q	HOOD, D S	8310070109	50-329 A	HUKILL, H D	8310230261	50-289 P
HERRINGTON, W N	8310030437*	50-267 Q	HOOD, D S	8310210134	50-329 A	HUKILL, H D	8310230294	50-289 S
HERRMANN, T	8310230385	50-333 S	HOKKER, C A	8310030400	40-8807	HUKILL, H D	8310230430	50-289 S
HERSCH, M M	8310060039	XPORTLIC	HOOPENGARDNER	8310240022*	50-413 T	HUKILL, H D	8310230589	50-289 S
HERSCH, M M	8310130349	XPORTLIC	HOOPINGARNER, N	8310240024*	50-413 T	HUKILL, H D	8310230606	50-289 S
HERSHEY, S P	8310260273	50-352 Q	HOPCRAFT, C P	8310130384	71-9160	HUKILL, H D	8310270130	50-289 P
HERSHEY, S P	8310260273	50-352 Q	HOPKINS, H R	8310050387*	CONTRACT	HUKILL, H D	8310280108	50-289 P
HEBS, J F	8310140076*	50-155 T	HOPKINS, H R	8310070175*	CONTRACT	HUKILL, H D	8310280115*	50-289 P
HEBS, J F	8310140076*	50-155 T	HOPKINS, J B	8310270135	50-395 P	HUKILL, H D	8310280123	50-289 P
HEBSNER, R	8310270537*	50-10 F	HOPPA, J L	8310040080	50-317 P	HUKILL, H D	8310310410	50-289 P
HETRICK, N P.	8310120171	50-320 H	HOPPER, A	8310050409	CONTRACT	HULL, R E	8310130252*	50-458 Q
HEYCOCK, P W	8310130157*	50-389 Q	HOPPER, A	8310060154	CONTRACT	HUNNICUTT, D	8310030457*	50-267 Q
HIATT, S L	8310030366	PR	HOPPER, A	8310060487	CONTRACT	HUNNICUTT, D	8310040644*	50-267 Q
HIATT, S L	8310110425	50-237 S	HOPPER, A	8310070121	CONTRACT	HUNNICUTT, D	8310060015*	50-267 Q
HIATT, S L	8310120099	50-440 Q	HORIN, W A	8310110322	50-445 Q	HUNNICUTT, D M	8310030350*	50-267 Q
HIATT, S L	8310180337	50-440 Q	HORIN, W A	8310110322	50-445 Q	HUNNICUTT, D M	8310040186*	50-445 Q
HIATT, S L	8310190061	50-440 Q	HORIN, W A	8310180158	50-445 Q	HUNNICUTT, D M	8310040240*	50-445 Q
HIATT, S L	8310200353	FOIA	HORIN, W A	8310180158	50-445 Q	HUNNICUTT, D M	8310040589*	50-267 Q
HIATT, S L	8310270065	FOIA	HORIN, W A	8310180163*	50-445 Q	HUNNICUTT, D M	8310130211*	50-298 Q
HIATT, S L	8310280071	50-361 S	HORIN, W A	8310210184	50-445 Q	HUNNICUTT, D M	8310180219*	50-445 Q
HICKEY, W P.	8310040519*	50-155 T	HORIN, W A	8310210184	50-445 Q	HUNNICUTT, D M	8310180227*	50-445 Q
HICKEY, W P.	8310040519*	50-155 T	HORTON, Q	8310040100	40-299	HUNNICUTT, D M	8310180232*	50-278 Q
HIETALA, J J	8310140057	50-373 S	HOSCHAR, E E	8310070125	MISC	HUNNICUTT, D M	8310180472*	50-445 Q
HIQGINBOTHAM, L	8310240262	WASTE MGT	HOSCHAR, E E	8310070129*	MISC	HUNNICUTT, D M	8310310264*	50-445 Q
HIQGINBOTHAM, L	8310240270	WASTE MGT	HOSEY, C M	8310250328*	50-280 Q	HUNNICUTT, D M	8310310286*	50-298 Q
HIQGINS, J	8310040453	50-309 S	HOSEY, C M	8310250354*	70-1113	HUNSTAD, A A	8310120102	50-282 S
HIQGINS, J	8310060253	50-309 S	HOUGHTON, T. C	8310030311	PR	HUNSTAD, A A	8310120340	50-306 S
HIQGINS, J	8310060344	50-309 S	HOUSTON, R	8310060198	50-373 S	HUNSTAD, A A	8310170641	50-306 S
HIQGINS, J	8310190159*	50-309 Q	HOUSTON, R W	8306090346*	50-346 P	HUNSTAD, A A	8310270415*	50-282 S
HIQGINS, J	8310310230*	50-317 Q	HOUSTON, R W	8310140073	50-373 S	HUNSTAD, A A	8310270418*	50-282 S
HIQGINS, J C	8310200107*	50-317 Q	HOUSTON, R W	8310140263	50-373 S	HUNSTAD, A A	8310270421*	50-282 S
HILDT, B	8310060364*	50-443 U	HOUSTON, R W	8310170463*	FOIA	HUNSTAD, A A	8310270427*	50-282 S
HILL, W	8310200152	50-358 S	HOUSTON, R W	8310270274	50-373 S	HUNSTAD, A A	8310270429*	50-306 S
HILL, W M	8310030392*	50-498 Q	HOUSTON, R W	8310270276	50-373 S	HUNT, M D	8310250452*	50-416 Q
HIND, J	8310110576*	FOIA	HOWE, P W	8310040380	50-324 P	HUNTER, D R	8310140150*	50-461 Q
HIND, J	8310120230	1&E	HOWE, P W	8310040385	50-324 P	HUNTER, D R	8310140215*	50-373 Q
HIND, J A	8310120276	50-305 Q	HOWE, P W	8310060054	50-324 P	HUNTER, D R	8310270440*	50-305 Q
HIND, J A	8310140261	50-254 Q	HOWE, P W	8310200166	50-324 Q	HUNTER, D R	8310310407*	50-409 Q
HIND, J A	8310140264*	50-254 Q	HOWE, P W	8310200206	50-324 P	HURBT, A	8310110074*	50-289 J
HIND, J A	8310250197*	50-255 Q	HOWE, P W	8310210264	50-324 P	IBEN, C	8310170491	50-254 S
HIND, J A	8310250284*	50-282 Q	HOWE, P W	8310250036	50-324 P	IDE, H E	8310240223*	50-528 Q
HIND, J A	8310250548*	50-155 Q	HOWE, P W	8310250120	50-324 F	IDEKER, R L	8310170299	70-143
HIND, J A	8310250550*	50-263 Q	HOWE, P W	8310250480*	50-324 Q	INGRAM, F	8310110052	50-289 H
HIND, J A	8310310325	50-305 Q	HOWE, P W	8310260141	50-324 P	INMAN, S C	8310250424*	50-313 Q
HIND, J A	8310310333*	50-305 Q	HOWLETT, L H	8310280178*	40-299	IPPOLITO, T A	8310260085*	FOIA
HINKLEMAN, L Q	8310250408*	04999	HOY, H C.	8310070426	NJREQ	IRWIN, D P	8310310124	50-322 Q
HINZE, W J	8310280131	REG	HOYLE, A	8310060278	CONTRACT	IRWIN, D P	8310310124	50-322 Q
HIPSHER, W M.	8310120063	27-39	HOYLE, A	8310060495	CONTRACT	IVERSON, O	8310270380*	50-266 S
HIPSHER, W M	8310260088	WASTE MGT	HOYLE, A	8310060499	CONTRACT	JABBOUR, K N	8310070150*	50-413 C
HIPSHER, W M	8310260094	WASTE MGT	HOYLE, A	8310070222	CONTRACT	JABBOUR, K N	8310110607	50-413 F
HIPSHER, W M	8310280281	27-48	HOYLE, H R	8310110125*	FOIA	JABBOUR, K N	8310110636	50-413 A
HODADY, S D	8310120292*	70-372	HOYLE, J C	8310040592	10CFR	JABBOUR, K N	8310190264	50-413 E
HODCHENDOMER, L	8310120171	50-320 H	HOYLE, J C	8310050107	10CFR	JABLONSKI, F J	8310060309*	50-461 Q
HODDON, A P.	8310030432*	50-352 Q	HOYT, H F.	8310250044	50-443 Q	JABLONSKI, F J	8310310293*	50-461 Q
HODDON, A. P	8310170511	50-352 Q	HOYT, H. F.	8310280109	50-443 Q	JACKIW, I	8310060264	50-266 S
HOFFMAN, B	8310180038	40-8027	HUBBARD, Q T.	8310250447*	04999	JACKIW, I N	8310240003*	50-301 Q
HOFFMAN, Q L.	8310180136	40-8839	HUBBARD, R B	8310200178	50-275 T	JACKIW, I N	8310240102*	50-282 Q
HOFFMAN, Q L.	8310280178*	40-299	HUBBARD, R B	8310200178	50-275 T	JACKSON, C W	8310280094	50-247 S
HOFFMAN, T. E	8310110356	FOIA	HUBBARD, R B	8310270377*	50-275 T	JACKSON, L H	8310040335*	50-413 Q
HOGAN, J. P.	8310180319	50-89 P	HUDSON, B D	8310120096*	50-220 Q	JACOBBS, A	8310050365	CONTRACT
HOLCOMBE, J C	8310110133*	50-361 P	HUETER, L J	8310140216*	70-1308	JACOBBS, A	8310050353	CONTRACT
HOLDEN, C	8310040455	50-309 S	HUETER, L J	8310210074*	50-10 Q	JACOBBS, A	8310070187	CONTRACT
HOLDEN, C	8310060293	50-309 S	HUFFMAN, Q N	8310040413*	50-413 Q	JACOBBS, A	8310070329	CONTRACT
HOLDEN, C	8310060344	50-309 S	HUFFMAN, Q N	8310040480*	50-302 Q	JACOBBS, A	8310210164	CONTRACT
HOLDEN, C F.	8310140245*	50-271 Q	HUFFMAN, Q N	8310230392*	50-413 Q	JACOBBS, R	8310140038	50-311 S
HOLDEN, C F.	8310190159*	50-309 Q	HUGHES, P O	8310230409*	50-333 Q	JACOBBS, R	8310170310	50-247 S
HOLDER, E T.	8310060377	50-296 S	HUGHES, P O	8310140187	50-302 S	JACOBBS, R H	8310140279*	50-272 Q
HOLLEY, J.	8310180369*	50-275 T	HUKILL, H D	8310140233	50-302 S	JACOBSON, P J	8310240167	FOIA
HOLLEY, W L.	8310060015*	50-267 Q	HUKILL, H D	8310030103	50-289 P	JAFFE, D	8310310479	50-317 P
HOLLEY, W L.	8310060026*	50-313 Q	HUKILL, H D	8310060390	50-289 P	JAFFE, D H	8310070176	50-317 P
HOLONICH, J J	8310170124	50-400 E	HUKILL, H D	8310070074	50-289 P	JAMISON, J D	8310030457*	50-267 Q
HOLONICH, J J.	8310180185	50-400 F	HUKILL, H D	8310070309	50-289 V	JANG, J	8310140236*	50-271 Q
HOLONICH, J J.	8310240039	50-482 A	HUKILL, H D	8310120360	50-289 R	JANZOW, E F	8310060060	XPORTLIC
HOLONICH, J J	8310240075	50-482 A	HUKILL, H D	8310140108	50-289 R	JANZOW, E F	8310060065*	XPORTLIC
HOLONICH, J. J.	8310280121	50-482 Q	HUKILL, H D	8310140251	50-289 P	JAPE, F	8310040147*	50-390 Q
HOLT, J.	8310120299	PR	HUKILL, H D	8310170007*	50-289 F	JAPE, F	8310040150*	50-413 Q
HOLTZ, J. L.	8310190019	50-374 R	HUKILL, H D	8310180372*	50-289 Q	JAPE, F	8310040167*	50-416 Q
HOLMAY, F. I.	8310040533	50-443 Q	HUKILL, H D	8310190161	50-289 S	JAPE, F	8310040253*	50-267 Q
HOLMAY, F. I.	8310120178	50-443 Q	HUKILL, H D	8310190164	50-289 S	JAPE, F	8310040294*	50-269 Q

PERSONAL AUTHOR INDEX

503

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
JAPE, F	8310040563*	50-390 Q	JONES, G T	8310030376	50-296 S	KAMMER, D S	8310250494*	50-327 C
JAPE, F	8310050419*	50-413 T	JONES, G T	8310140127	50-260 S	KAMMERER, C	8212150242*	FOIA
JAPE, F	8310250216*	50-416 Q	JONES, G T	8310190186	50-259 R	KAMMERER, C	8212290072*	FOIA
JAPE, F	8310250230*	50-413 Q	JONES, G T	8310250360	50-260 S	KAMMERER, C	8310110039*	50-275 F
JAUDON, J P	8310130259*	50-482 Q	JONES, P E	8310050369*	CONTRACT	KAMMERER, C	8310110046*	50-275 F
JAUDON, J P	8310130295*	50-285 A	JONES, V	8310190016	50-280 R	KAMMERER, C	8310110351*	FOIA
JEANE, G S	8310310154*	50-308 Q	JONES, W B	8310040186*	50-442 Q	KAMMERER, C	8310240246*	50-528 U
JENKINS, G R	8310040413*	50-413 Q	JONES, W B	8310180472*	50-445 Q	KANA, D D	8310270598*	TOPREP
JENKINS, G R	8310040480*	50-302 Q	JONES, W C	8310050255*	50-285 P	KANE, R. S	8310180380*	50-199 C
JENKINS, G R	8310250304*	50-390 Q	JONES, W C	8310050310*	50-285 P	KANE, R. S	8310180383*	50-199 C
JENKINS, G R	8310250363*	50-269 Q	JONES, W C	8310110330*	50-285 F	KANGA, B K	8310030500	50-320 F
JENKINS, G R	8310250372*	50-413 Q	JONES, W C	8310120094	50-285 Q	KANGA, B K	8310030055	50-320 F
JENKINS, G R	8310250394*	50-280 Q	JONES, W C	8310130308*	50-285 F	KANGA, B K	8310110106*	50-320 F
JENKINS, G R	8310250409*	50-335 Q	JONES, W C	8310180162	50-285 R	KANGA, B K	8310180380*	50-320 F
JENKINS, G R	8310250578*	50-324 Q	JONES, W C	8310180506*	50-285 Q	KANGA, B K	8310130064	50-320 F
JENKINS, R B	8310120221*	50-155 T	JONES, W C	8310190324	71-9080	KANGA, B K	8310130082	50-320 F
JENKINS, S M	8307200260*	50-336 P	JONES, W C	8310210008	50-285 Q	KANGA, B K	8310030138	50-320 F
JENG, W H	8310120098	50-341 A	JONES, W C	8310210370*	50-285 F	KANGA, B K	8310170539	50-320 F
JENG, W H	8310120190	50-341 A	JONES, W C	8310250265*	50-285 F	KANGA, B K	8310180200	50-320 F
JENG, W H	8310180034*	50-341 F	JOOSTEN, J K	8310030412	50-413 Q	KANGA, B K	8310190060	50-320 F
JENSON, D L	8310200048*	50-289 P	JORDAN, E L	8308300340	50-3 Q	KANGA, B K	8310198075	50-320 F
JESSUP, B	8310070206	CONTRACT	JORDAN, E L	8308300342	50-3 Q	KANGA, B K	8310190173	50-320 F
JESSUP, B	8310070213	CONTRACT	JORDAN, E L	8308300345	50-3 Q	KANGA, B K	8310198085	50-320 F
JESSUP, B	8310070218	CONTRACT	JORDAN, E L	8308300349	50-3 Q	KANGA, B K	8310200095	50-320 F
JESSUP, B	8310070233	CONTRACT	JORDAN, E L	8308300378	50-3 Q	KANGA, B K	8310200155	50-320 F
JESSUP, B	8310070244	CONTRACT	JORDAN, E L	8308300732	50-3 Q	KANGA, B K	8310230317	50-320 F
JESSUP, B	8310110533	CONTRACT	JORDAN, E L	8308300739	50-3 Q	KANGA, B K	8310250434	50-320 F
JESSUP, B	8310110613	CONTRACT	JORDAN, E L	8308300761	50-3 Q	KANGA, B K	8310250478	50-320 F
JOACHIM, M	8310180135	50-142 H	JORDAN, E L	8310120051	50-289 P	KANGA, B K	8310250629	50-320 F
JOHANSEN, C	8310140237	50-344 J	JORDAN, L V	8310170206	70-27	KANGA, B K	8310280102	50-320 F
JOHNSON, A D	8310180367*	50-344 Q	JORDAN, R L	8310180401*	QA999	KANGA, B K	8310310164*	50-320 C
JOHNSON, A R	8310180455*	QA999	JORDAN, R L	8310180401*	QA999	KANTMANN, R A	8310180528*	QA999
JOHNSON, A R	8310250385*	QA999	JORDAN, W H	8310110266	50-445 Q	KAPLAN, S	8310170379	50-304 E
JOHNSON, A R	8310250541*	QA999	JORDAN, W H	8310140083	50-445 Q	KARMAN, M	8310050447	50-261 C
JOHNSON, B	8310260309	50-537 A	JORDAN, W H	8310270228	50-445 Q	KAROL, R	8310270075*	FOIA
JOHNSON, B D	8310060221	50-255 S	JORDAN, W H	8310270293	50-445 Q	KARR, J W	8310060269	50-329 C
JOHNSON, B D	8310120064	50-255 S	JORDAN, W S	8310110158	50-443 Q	KARR, J W	8310120101	50-329 C
JOHNSON, B D	8310120249	50-255 S	JORDAN, W S	8310110158	50-443 Q	KARR, J W	8310270257	50-329 C
JOHNSON, B D	8310120331	50-255 S	JORDAN, W S	8310110163*	50-443 Q	KARR, J W	8310270266*	50-329 C
JOHNSON, B D	8310250250	50-255 S	JORDAN, W S	8310110163*	50-443 Q	KARR, J W	8310310390	50-329 C
JOHNSON, B D	8310250462	50-255 S	JORDAN, W S	8310110170*	50-443 Q	KASTENBERG, W E	8310060326*	CONTRACT
JOHNSON, B D	8310270162	50-255 S	JORDAN, W S	8310110170*	50-443 Q	KAUFFMAN, J T	8310110157	50-387 F
JOHNSON, C C	8310170683	50-445 T	JORDAN, W S	8310110173*	50-443 Q	KAUFFMAN, P H	8310040209	50-275 C
JOHNSON, D J	8310070229	50-352 V	JORDAN, W S	8310110175*	50-443 Q	KAUFFMAN, P H	8310040212*	50-275 C
JOHNSON, E H	8310180478	50-445 Q	JORDAN, W S	8310140191	50-443 Q	KAUFFMAN, P H	8310040219*	50-275 C
JOHNSON, E H	8310310279	50-298 Q	JORDAN, W S	8310140191	50-443 Q	KAWACHI, M	8310170209	71-9033
JOHNSON, E H	8310310294	50-267 Q	JORDAN, W S	8310180329	50-443 Q	KAWACHI, M H	8310170215	71-9032
JOHNSON, E H	8310310298	50-267 Q	JORDAN, W S	8310180329	50-443 Q	KAWACHI, M H	8310170355	71-9128
JOHNSON, C H	8310310435*	50-267 P	JORDAN, W S	8310310202	50-443 Q	KAY, J A	8310040108	50-29 F
JOHNSON, Q E	8310050386	50-413 T	JORDAN, W S	8310310202	50-443 Q	KAY, J A	8310040330	50-29 F
JOHNSON, Q E	8310050406	50-413 Q	JORGENSEN, B L	8310040253*	50-255 Q	KAYSER, W V	8310050470*	50-255 F
JOHNSON, Q C	8310090562	50-413 Q	JOYNER, J	8310200160	1&E	KEATING, D E	8310200280*	50-338 C
JOHNSON, J	8310060051	50-293 S	JULIAN, C	8310040494*	50-335 Q	KEATING, D E	8310270450*	50-255 C
JOHNSON, J L	8310270524*	40-8698	JULIAN, C A	8310030461	50-416 S	KEIMIG, R	8310060600	50-334 F
JOHNSON, J H	8310250631*	50-312 F	JULIAN, C A	8310250624*	50-327 Q	KEISER, H	8310060558*	50-387 F
JOHNSON, K I	8310070317	NUREQ	JUNGE, M A	8310200147	50-317 S	KEISER, H W	8310190120	50-387 F
JOHNSON, L E	8310130252*	50-458 Q	JUNGE, M A	8310250411	50-318 S	KEISER, H W	8310190145	50-387 F
JOHNSON, P	8310120251	50-312 S	JUNGE, M A	8310250587	50-317 S	KEISER, H W	8310190230	50-387 F
JOHNSON, P	8310120321	50-312 S	JUNGE, M A	8310250599	50-318 S	KEISER, H W	8310200271	50-387 F
JOHNSON, P	8310240236*	50-526 A	JUSTUS, P S	8310260074	WASTE MOT	KEISER, H W	8310250204	50-387 F
JOHNSON, P. H	8310170470*	50-526 Q	KADAMBI, P	8310310489	50-269 P	KEISER, H W	8310250219	50-387 F
JOHNSON, R Q	8310250239	50-263 J	KAHLE, J B	8310040340*	70-143	KEISER, H W	8310250228	50-387 F
JOHNSON, T L	8310180384	40-8698	KAHLE, J B	8310040499*	50-321 Q	KEISER, H W	8310250242	50-387 F
JOHNSON, T L	8310200452	40-8674	KAHLE, J B	8310040508*	70-27	KEISER, H W	8310250245	50-387 F
JOHNSON, V P	8310260201*	50-443 A	KAHN, V	8310050460*	CONTRACT	KEISER, H W	8310250266	50-387 F
JOHNSON, W	8310060026*	50-313 Q	KAIBER, H	8310060486*	50-387 F	KEISER, H W	8310250345	50-387 F
JOHNSON, W D	8310030476	50-368 S	KALIVIANAKIS, N	8310060249	50-265 S	KEISER, H W	8310250386	50-387 F
JOHNSON, W D	8310040577*	50-285 S	KALIVIANAKIS, N	8310120198	50-254 S	KEISER, H W	8310250402	50-387 F
JOHNSON, W D	8310130171*	50-285 Q	KALIVIANAKIS, N	8310170271	50-254 S	KEISER, H W	8310250555	50-387 F
JOHNSON, W D	8310130178*	50-482 Q	KALIVIANAKIS, N	8310170353	50-254 R	KEISER, H W	8310250594	50-387 F
JOHNSON, W D	8310130226*	50-313 Q	KALIVIANAKIS, N	8310170491	50-254 S	KEISER, H. W.	8310250622	50-387 F
JOHNSON, W D	8310130251*	50-482 Q	KALIVIANAKIS, N	8310170661	50-265 S	KEISER, H. W.	8310280123	50-387 F
JOHNSON, W D	8310130259*	50-482 Q	KALIVIANAKIS, N	8310180109	50-254 R	KEISER, H. W.	8310310305	50-387 F
JOHNSON, W D	8310130295*	50-285 Q	KALIVIANAKIS, N	8310180263	50-254 R	KELBER, C N	8310170033*	FOIA
JOHNSON, W D	8310130335*	50-313 Q	KALIVIANAKIS, N	8310210016	50-265 S	KELLER, Q R.	8310280131	REB
JOHNSON, W D	8310180246*	50-285 Q	KALIVIANAKIS, N	8310210054	50-265 S	KELLER, R	8310180386*	50-5
JOHNSON, W P	8310260261*	50-443 Q	KALIVIANAKIS, N	8310270400	50-254 S	KELLEY, D. L.	8310040186*	50-445 C
JOHNSON, W P	8310260266*	50-443 Q	KALIVIANAKIS, N	8310270404	50-254 S	KELLEY, D. L.	8310180472*	50-445 C
JOHNSON, G	8310040537*	50-528 Q	KAMMER, D S	8310270419	50-265 S	KELLEY, J. L.	8310040177	50-413 C
JOHNSON, W V	8310190358*	50-282 S	KAMMER, D S	8310110100*	50-327 F	KELLEY, J. L.	8310110209	50-400 C
JOLLEY, J R	8310310014	50-317 F	KAMMER, D S	8310180315	50-390 F	KELLEY, J. L.	8310110218	50-400 C
JONES, D	8310060252*	50-358 Q	KAMMER, D S	8310180422	50-259 P	KELLEY, J. L.	8310140065	50-400 C
JONES, D W	8310030341	PR	KAMMER, D S	8310030443	50-327 P	KELLEY, J. L.	8310200383*	FOIA
JONES, D W	8310040148*	70-1151	KAMMER, D S	8310210023	50-390 A	KELLEY, J. L.	8310270319	50-400 C
JONES, D W	8310040493*	70-27	KAMMER, D S	8310250367	50-390 Q	KELLEY, L	8310190202	50-286

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KELLEY, B	8310280146*	50-322 U	KING, J W	8310130232*	50-341 A	KNOP, R C	8310060453*	50-483 Q
KELLEY, D	8310280008*	QA999	KING, J H	8310260107*	FOIA	KNOP, R C	8310170525	50-454 Q
KELLEY, D L	8310130413	FOIA	KING, J H	8310260116*	FOIA	KNOP, R C	8310170529*	50-454 Q
KELLEY, G	8310280136*	FOIA	KING, J H	8310260124*	FOIA	KNOP, R C	8310170629	50-341 Q
KELLEY, G	8310280184*	FOIA	KING, J H	8310260132*	FOIA	KNOP, R C	8310170636*	50-341 Q
KELLY, G	8310280188*	FOIA	KING, J H	8310260366*	FOIA	KNOP, R C	8310170662	50-440 Q
KELLY, G A	8310280198*	FOIA	KING, J H	8310260374*	FOIA	KNOP, R C	8310170667*	50-440 Q
KELLY, G A	8310280163*	FOIA	KINNEGAN, J	8310120306	I&E	KNOP, R C	8310240066	50-346 Q
KELLY, G A	8310280169*	FOIA	KINNEGAN, J	8310200160	I&E	KNOP, R C	8310240121	50-440 Q
KELLY, G A	8310280170*	FOIA	KINNEGAN, J D	8310170143	40-86	KNOP, R C	8310250636	50-461 Q
KELLY, G A	8310260172*	FOIA	KINNEY, W W	8310240115*	50-225 Q	KNOP, R C	8310310289	50-461 Q
KELLY, G A	8310260173*	FOIA	KINNEY, W W	8310270295*	50-134 Q	KNOP, R C	8310040008	PR
KELLY, G A	8310260193*	FOIA	KINTNER, L L	8310240133	50-338 A	KNOP, R C	8310210382*	50-275 T
KELLY, G A	8310260195*	FOIA	KIRK, C	8310101024	50-327 S	KNOP, R C	8310060406*	50-313 P
KELLY, G A	8310260223*	FOIA	KIRK, G B	8310030240	50-328 S	KNOP, R C	8310250636	50-461 Q
KELLY, J	8310040140*	50-445 Q	KIRK, R L	8310270113*	FOIA	KOCH, T	8310030364	PR
KELLY, J	8310040444*	50-267 Q	KIRK, R L	8310270122*	FOIA	KOESTER, G L	8310040386	50-482 S
KELLY, J P	8310270080*	FOIA	KIRK, R L	8310270139*	FOIA	KOESTER, G L	8310130192	50-482 S
KELLY, L	8310170603	50-286 R	KIRK, R L	8310270147*	FOIA	KOESTER, G L	8310130223	50-482 S
KELLY, R B	8310170198*	50-423 A	KIRK, R L	8310270163*	FOIA	KOESTER, G L	8310130231	50-482 S
KELLY, R B	8310190038*	50-329 A	KIRK, R L	8310270168*	FOIA	KOESTER, G L	8310170644	70-2960
KELLY, R B	8310190047*	50-329 A	KIRK, R L	8310270174*	FOIA	KOESTER, G L	8310210171	50-482 S
KELLY, T	8310170561	50-295 S	KIRKMAN, W W	8310260033*	FOIA	KOESTER, G L	8310180256	50-482 S
KELLY, H J	8310070158	50-275 S	KIRSCH, D	8310040396	50-206 S	KOESTER, G L	8310180317	50-482 E
KELLY, H J	8310120136	50-275 S	KIRSCH, D	8310070333	50-362 S	KOESTER, G L	8310180389	50-482 S
KELLY, H J	8310120280	50-275 S	KIRSCH, D F	8310170479*	50-275 Q	KOESTER, G L	8310210075	70-2960
KELLY, H J	8310190051	50-275 R	KIRSCH, D F	8310200214*	50-206 Q	KOESTER, G L	8310210188	50-482 S
KELLY, H J	8310230539	50-275 B	KIRSCH, D F	8310200224*	50-206 Q	KOESTER, G L	8310210244	50-482 S
KELLY, H J	8310230639	50-275 S	KIRSCH, D F	8310310251*	50-275 Q	KOESTER, G L	8310210415*	50-482 F
KELLY, H J	8310270376	50-275 S	KIRSCH, D F	8310310341*	50-275 Q	KOESTER, G L	8310250034	50-482 A
KEMPER, J S	8310040124	50-352 A	KISH, J N	8310270440*	50-303 Q	KOESTER, G L	8310250084	50-482 Q
KEMPER, J S	8310040296	50-352 A	KISH, J N	8310310407*	50-409 Q	KOESTER, G L	8310250133	50-482 A
KEMPER, J S	8310040431	50-352 A	KISTER, H	8310120124	50-247 S	KOLB, L E	8310030343	50-395 S
KEMPER, J S	8310110132	50-352 E	KISTER, H B	8310110179	50-272 S	KOLB, L E	8310070126	50-395 S
KEMPER, J S	8310120148	50-352 A	KISTER, H B	8310190168*	50-333 Q	KOLB, L E	8310070338	50-395 S
KEMPER, J B	8310120392	50-352 E	KLECKER, R W	8310070317	MUREQ	KOLB, L E	8310310234	50-395 S
KEMPER, J B	8310140093	50-352 A	KLEIN, T J	8310030203	40-8584	KOLB, M W	8310270283	50-263 S
KEMPER, J B	8310140197	50-352 A	KLEIN, T J	8310030221	40-8584	KOLB, J E	8310240315	FOIA
KEMPER, J B	8310170225	70-2988	KLEINSORGE, W P	8310040316*	50-230 Q	KONKLIN, J E	8310040540*	50-346 Q
KEMPER, J B	8310180423	50-352 C	KLEINSORGE, W P	8310230404*	50-413 Q	KONKLIN, J E	8310050382*	50-440 Q
KEMPER, J B	8310250419	50-277 Q	KLIMM, R D	8310030491*	50-153 Q	KONKLIN, J E	8310060462*	50-483 Q
KEMPER, J B	8310280013	50-352 B	KLIMM, R D	8310030491*	50-153 Q	KONKLIN, J E	8310170643*	50-341 Q
KEMPTHORNE, P J	8310210241*	50-275 T	KLINE, J R	8310040194	27-39	KONKLIN, J E	8310170670*	50-440 Q
KENNEDY, D H	8310120253	50-255 R	KLINGLER, G	8310040214	50-272 Q	KONKLIN, J E	8310240137*	50-440 Q
KENNY, T	8310120124	50-247 S	KLINGLER, G	8310060005	50-220 Q	KOON, A R	8310210128	50-395 S
KENNY, T J	8310120199*	50-286 Q	KLINGLER, G	8310140060	I&E	KOBLA, B M	8310070037*	40-8027
KENT, O J	8310190039	50-344 R	KLINGLER, G	8310210030	50-329 Q	KOUSARI, B	8310070414	MUREQ
KENYON, B D	8310030396	PR	KNAPICK, M	8310270508	FOIA	KOVACK, T J	8310060545*	50-254 F
KENYON, B D	8310180356*	50-387 Q	KNEE, H E	8310190243	MUREQ	KOVACK, T J	8310200082*	50-254 F
KENYON, B D	8310190080	50-387 R	KNICELEY, J R	8310140216*	70-1308	KOYAMA, E	8310170669	70-984
KENYON, B D	8310250246	50-387 P	KNICELEY, J R	8310250582*	70-2977	KRAUS, H J	8310120304	50-358 A
KENYON, B D	8310250252*	50-387 P	KNICELEY, J R	8310310347*	50-341 Q	KRAUS, D F	8310140029	50-315 S
KENYON, B D	8310270449	50-387 P	KNIEL, K	8310030641	GEN TEC 18	KRAUS, D F	8310140139*	50-316 S
KENYON, B D	8310270483*	50-387 P	KNIGHT, J P	8007290663	50-339 P	KRAUS, D F	8310270172	50-316 S
KEDHAN, P J	8310030370*	CONTRACT	KNIGHT, J P	8310030059*	50-329 A	KRAUS, D F	8310270213*	50-315 S
KEPFLER, J Q	8310050341	50-329 A	KNIGHT, J P	8310210355*	50-275 T	KRECHTING, J E	8310180361*	50-275 T
KEPFLER, J Q	8310060395	50-461 Q	KNIGHT, J P	8310210357*	50-275 T	KRECHTING, J E	8310180375*	50-275 T
KEPFLER, J Q	8310060497	50-358 A	KNIGHT, J P	8310210358*	50-275 T	KREH, J L	8310250304*	50-390 Q
KEPFLER, J Q	8310060515	MISC	KNIGHT, J P	8310210385*	50-275 T	KRICH, R M	8310170351	50-255 B
KEPFLER, J Q	8310110583*	FOIA	KNIGHT, J P	8310250018*	TOPREP	KRIEGER, R W	8310070283	50-206 P
KEPFLER, J Q	8310130234	50-358 A	KNIGHT, J P	8310250332*	50-275 T	KRIEGER, R W	8310070344	TOPREP
KEPFLER, J Q	8310140054	50-358 A	KNIGHT, M R	8310250294	50-289 S	KRIEGER, R W	8310120170	50-206 P
KEPFLER, J Q	8310180267	50-358 R	KNIGHT, M R	8310250430	50-289 S	KRIEGER, R W	8310130127	50-206 P
KEPFLER, J Q	8310200157	50-358 Q	KNIGHTON, Q W	8310040643*	50-362 P	KRIEGER, R W	8310130316	50-206 P
KEPFLER, J Q	8310210067	50-358 A	KNIGHTON, Q W	8310060508	50-362 P	KRIEGER, R W	8310140223	50-206 P
KEPFLER, J Q	8310210105	50-358 Q	KNIGHTON, Q W	8310060510	50-412 A	KRIEGER, R W	8310200284	50-206 P
KEPFLER, J Q	8310240107	50-329 A	KNIGHTON, Q W	8310060514	50-412 A	KRIEGER, R W	8310250194	50-206 P
KEPFLER, J Q	8310230191	50-253 Q	KNIGHTON, Q W	8310060524	50-412 A	KRUO, H E	8310250216*	50-416 Q
KEPFLER, J Q	8310230275	50-282 Q	KNIGHTON, Q W	8310060530	50-412 A	KUBICKI, D J	8310210378*	50-275 T
KEPFLER, J Q	8310230522	50-153 Q	KNIGHTON, Q W	8310060537*	50-389 P	KUBICKI, D J	8310250182*	50-275 T
KEPFLER, J Q	8310250538	50-263 Q	KNIGHTON, C W	8310170539	50-275 Q	KUCZYNSKI, L A	8310190080	50-387 R
KEPFLER, J Q	8310250576	50-358 Q	KNIGHTON, C W	8310180177*	50-361 P	KUCZYNSKI, L A	8310190145	50-387 S
KEPFLER, J Q	8310260155*	FOIA	KNIGHTON, C W	8310180620	50-275 F	KUCZYNSKI, L A	8310200271	50-387 S
KEPFLER, J Q	8310260234*	FOIA	KNIGHTON, C W	8310200036	50-412 M	KUCZYNSKI, L A	8310250242	50-387 S
KEPFLER, J Q	8310260265*	70-1144	KNIGHTON, C W	8310200042*	50-412 M	KUCZYNSKI, L A	8310250245	50-387 S
KEPFLER, J Q	8310310356	40-2061	KNIGHTON, C W	8310200070	50-382 A	KUCZYNSKI, L A	8310250266	50-387 S
KERR, G W	8310110615*	COMMISSION	KNIGHTON, C W	8310200171	50-382 A	KUCZYNSKI, L A	8310250386	50-387 S
KERR, G W	8310260229*	FOIA	KNIGHTON, C W	8310210134	50-275 P	KUCZYNSKI, L A	8310250555	50-387 S
KERS, D A	8310310275	50-87 S	KNIGHTON, C W	8310270254	50-382 A	KUCZYNSKI, L A	8310250622	50-387 S
KERS, L	8310140267*	50-237 Q	KNOP, R C	8310040158	50-454 Q	KUECHLE, C	8310210218	50-304 S
KESSEL, D T	8310310359	50-220 S	KNOP, R C	8310040268	50-483 Q	KUNCL, L Q	8310110178	50-298 P
KETTERING, N E	8310270070	FOIA	KNOP, R C	8310040424	50-454 Q	KUNCL, L Q	8310180471	50-298 Q
KIBLER, D R	8310120400	50-331 S	KNOP, R C	8310040526	50-346 Q	KUNCL, L Q	8310310310	50-298 Q
KILCOYNE, J J	8310270298	50-289 Q	KNOP, R C	8310060282	50-461 Q	KUNDALKAR, R	8310250128*	50-206 P
KILCOYNE, J J	8310060138*	CONTRACT	KNOP, R C	8310060449	50-483 Q	KUOP, P	8310210358*	50-275 T

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KUD, P	8310210391*	50-275 T	LEDUC, R J	8310310430*	71-9086	LEWIS, R C	8310040502	50-416
KUD, P T	8308150308*	50-329 A	LEE, O W	8310210320	FOIA	LEWIS, R C	8310040595	50-400
KUPIEC, C F	8310190283	NUREG	LEE, J	8310040483	50-320 H	LEWIS, R C	8310040608*	50-400
KURTH, R E	8310110475*	FOIA	LEE, O R	8310130193	50-267 P	LEWIS, R C	8310110157	50-324
KURTH, R E	8310110480*	FOIA	LEE, O R	8310130200*	50-267 P	LEWIS, R C	8310250131	50-239
KUYKENDALL, J C	8310180399	71-504	LEE, O R	8310130260	50-267 P	LEWIS, R C	8310250166	50-239
KYLE, W C	8310280177*	40-299	LEE, O R	8310130272	50-267 P	LEWIS, R C	8310250174*	50-239
LA VIE, S F	8310180434*	50-334 F	LEE, O R	8310130275*	50-267 P	LEWIS, R C	8310250208	50-400
LAMARCO, D C	8310120339	PR	LEE, O R	8310130281	50-267 P	LEWIS, R C	8310250247*	50-239
LABAT, V	8310110192*	CONTRACT	LEE, O R	8310130300	50-267 P	LEWIS, R C	8310250268*	50-416
LABOON, T A	8310190187	HTSC	LEE, O R	8310130303*	50-267 P	LEWIS, R C	8310250403	50-327
LACEY, W S	8310250946	50-334 S	LEE, O R	8310130324*	50-267 P	LEWIS, R C	8310250426	50-230
LACEY, W S	8310250955	50-334 S	LEE, W S	8310240061*	50-413 T	LEWIS, R C	8310250442*	50-230
LACEY, W S	8310280010	50-334 S	LEECH, P H	8310240103	50-336 P	LEWIS, R C	8310250434*	50-327
LAFLEUR, J D	8310170437*	FOIA	LEMPQES, C	8310070436	NUREG	LEWIS, R C	8310250437*	50-324
LAINAS, O C	8310260053*	FOIA	LEMPQES, T E	8310040597	50-220 P	LEWIS, R C	8310250468*	50-324
LAINAS, O C	8310260058*	FOIA	LEMPQES, T E	8310060361	50-220 F	LEWIS, R C	8310250475	50-327
LAINAS, O C	8310260061*	FOIA	LEMPQES, T E	8310140111	50-220 R	LEWIS, R C	8310250519	50-321
LAINAS, O C	8310260066*	FOIA	LEMPQES, T E	8310190169	50-220 S	LEWIS, R C	8310250530*	50-369
LAINAS, O C	8310260069*	FOIA	LEMPQES, T E	8310270212*	50-220 Q	LEWIS, R C	8310250580	50-369
LAINAS, O C	8310260071*	FOIA	LEMPQES, T E	8310270217*	50-220 Q	LEWIS, R C	8310250618*	50-261
LAINAS, O C	8310260075*	FOIA	LEMPQES, T E	8310310335*	50-220 S	LEWIS, R C	8310250646*	50-269
LAINAS, O C	8310260078*	FOIA	LENAHAN, J J	8310040042*	50-321 Q	LEWIS, S C	8310250047	50-332
LAINAS, O C	8310260080*	FOIA	LENTINE, F Q	8310110117	50-295 P	LIDBY, R A	8310260381	NUREG
LAINAS, O C	8310260082*	FOIA	LENTINE, F Q	8310140173*	50-295 Q	LIBERTONICZ, F	8310030226	50-458
LAKE, W H	8310060023	71-9852	LENTINE, F Q	8310180110	50-295 Q	LIDERTONICZ, F	8310030226	50-458
LAMASTRA, M	8310120217*	50-277 Q	LENTINE, F Q	8310200151	50-295 P	LICHTENBERGER	8310180027	70-1100
LAMASTRA, M A	8307170227*	FOIA	LENTINE, F Q	8310310049	50-295 P	LICHTENBERGER	8310190192	70-1100
LAMASTRA, M A	8310170184*	FOIA	LENTINE, F Q	8310310060	50-295 P	LICHTENBERGER	8310190215	70-1100
LAMBERT, W L	8310120415*	50-261 P	LESSY, R F	8310050381*	50-443 Q	LICHTENBERGER	8310310287*	70-1100
LAMBERT, W L	8310120422*	50-261 P	LESSY, R F	8310050388*	50-443 Q	LICITRA, E. A	8310050010	50-528
LANDORF, L C	8310170589	50-341 K	LESSY, R P	8310050366	50-443 Q	LICITRA, E. A	8310050347	50-528
LANDIS, K	8310190236	50-280 S	LESSY, R P	8310050373	50-443 Q	LICKUB, R M	8310140013	50-305
LANDIS, K	8310250528*	50-335 Q	LESSY, R P	8310050436	50-312 Q	LIDEN, E. A	8310060325	50-311
LANDSMAN, R B	8310170534*	50-329 Q	LESSY, R P	8310050472	50-443 Q	LIDEN, E. A	8310060327	50-311
LANDSMAN, R B	8310170591*	50-329 Q	LESSY, R P	8310050474*	50-443 Q	LIDEN, E. A	8310070003	50-272
LANDSMAN, R B	8310210319*	50-329 Q	LESSY, R P	8310050477*	50-443 Q	LIDEN, E. A	8310070166	50-272
LANEY, R V	8310250093*	50-397 A	LESSY, R P	8310050480*	50-443 Q	LIDEN, E. A	8310180231	50-272
LANEY, R V	8310250097*	50-397 A	LESSY, R P	8310050512	50-312 Q	LIDEN, E. A	8310180398*	50-272
LANG, T	8310120239	50-346 S	LESSY, R P	8310050551	50-443 Q	LIDEN, E. A	8310200318	50-311
LANG, T	8310120391	50-346 S	LESSY, R P	8310050557	27-39	LIDEN, E. A	8310210285	50-272
LANGBURY, R D	8310050502*	50-373 Q	LESSY, R P	83100530046	50-443 Q	LIDEN, E. A	8310230257	50-272
LANNING, W D	8310060199*	50-251 S	LESSY, R P	8310170394	50-443 Q	LIDEN, E. A	8310280119	50-311
LANPHER, L C	8310190209	50-322 Q	LESSY, R P	8310250319	50-443 Q	LIDEN, E. A	8310310225	50-311
LANPHER, L C	8310190209	50-322 Q	LETSCHE, D E	8310060355	MISC	LIDSTONE, C.	8310240043	40-8584
LANPHER, L C	8310200217	50-322 Q	LETSCHE, K	8310040199	50-322 Q	LIEBERMAN, J	8310180364	50-321
LANPHER, L C	8310200217	50-322 Q	LETSCHE, K	8310040199	50-322 Q	LIN, M	8310310114	NUREG
LANPHER, L C	8310200262	50-322 Q	LETSCHE, K J	8310030456	50-322 Q	LINDER, F	8310050101	50-409
LANPHER, L C	8310200262	50-322 Q	LETSCHE, K J	8310030456	50-322 Q	LINDER, F	8310130311*	50-409
LANPHER, L C	8310240160	50-322 Q	LETSCHE, K J	8310050416	50-322 Q	LINDER, F	8310170159	50-409
LANPHER, L C	8310240160	50-322 Q	LETSCHE, K J	8310050416	50-322 Q	LINDER, F	8310170364	50-409
LAPP, R E	8310110530	50-250 P	LETSCHE, K J	8310270239	50-322 Q	LINDER, F	8310190027	50-409
LARKINS, J T	8310200399	MISC	LEVIN, H A	8310170624	50-329 A	LINDER, F	8310210002	50-409
LABATER, O T	8310050501*	50-155 Q	LEVIN, H A	8310210272	50-329 R	LINDER, F	8310310163*	50-409
LABATER, O T	8310050501*	50-155 Q	LEVIN, H A	8310210275*	50-329 R	LINDHOLM, U S	8310280149*	50-259
LATHAM, W	8310120358*	50-312 Q	LEVIN, J J	8310270126	FOIA	LINDHOLM, U S	8310280150*	50-259
LATHAM, W K	8310040033	50-312 P	LEVINE, J M	8310060253*	50-313 F	LINDHOLM, U S	8310280151*	50-259
LATHAM, W K	8310250598	50-312 S	LEVINE, J M	8310110440*	50-313 F	LINDSAY, W E	8310110591*	FOIA
LAUER, R J	8310240172	50-329 Q	LEVINE, J M	8310130180	50-368 S	LINDSEY, C G	8310310208	NUREG
LAUER, R J	8310240172	50-329 Q	LEVINE, J M	8310190295*	50-313 F	LINDSEY, D J	8310190082	50-333
LAURENSEN, J A	8310040196	50-322 Q	LEVY, D	8310260302	50-142 H	LINNEHAN, J J	8310200373*	40-7869
LAURENSEN, J A	8310040202	50-322 Q	LEVY, B	8310070198*	CONTRACT	LINNEHAN, J J	8310250658	40-8674
LAURENSEN, J A	8310040286	50-322 Q	LEWIS, D R	8310060363	50-443 U	LINNEHAN, J J	8310240095*	40-8681
LAURENSEN, J A	8310170401	50-322 Q	LEWIS, E	8310140067	50-454 Q	LINNEHAN, J J	8310270324*	40-8698
LAURENSEN, J A	8310310190	50-322 Q	LEWIS, E	8310310127	50-454 Q	LINNEBERGER, O	8310120398	50-458
LAURENSEN, J A	8310310248	50-322 Q	LEWIS, L	8310170334	71-9039	LINTAKAS, A	8310210222	50-373
LAVERTY, J H	8310110208	50-358 Q	LEWIS, M I	8310030366	PR	LINVILLE, J	8310140038	50-311
LAVERTY, J H	8310180243	50-352 Q	LEWIS, M I	8310040334	PR	LINVILLE, J C.	8310140279*	50-272
LAVERTY, J H	8310180243	50-352 Q	LEWIS, M I	8310040491	50-352 Q	LIPARULO, N J	8310140044*	50-315
LAWSON, L T	8310210312	50-369 J	LEWIS, M I	8310270268	50-352 Q	LISTER, S E	8310200374	FOIA
LAZARUS, W J	8310120096*	50-220 Q	LEWIS, M I	8310270356*	50-352 Q	LITTLE, B H.	8310170643*	50-341
LAZARUS, W J	8310210220*	50-244 Q	LEWIS, M I	8310270362*	50-352 Q	LITTLE, J	8310250658	EXPORTLIC
LAZO, L	8310050392	50-412 A	LEWIS, R C	8310040046	50-416 P	LITTLE, W B	8310040174	50-346
LAZO, R M	8310120390	70-25	LEWIS, R C	8310040220	50-400 Q	LITTLE, W B.	8310040257	50-454
LE, A K	8309290506*	50-267 Q	LEWIS, R C	8310040269	50-261 Q	LITTLE, W B	8310050492	50-341
LEAVERTON, W	8310210054	50-265 S	LEWIS, R C	8310040313	50-413 Q	LITTLE, W S	8310110443*	50-316
LEAVY, W F.	8310130385*	CONTRACT	LEWIS, R C.	8310040323*	50-413 Q	LITTLE, W S.	8310140179	50-454
LECLAIR, D C	8310060115*	CONTRACT	LEWIS, R C	8310040354	50-321 Q	LITTLE, W S	8310200045	50-440
LEDDICK, R S	8310030060	50-382 K	LEWIS, R C.	8310040394	50-416 F	LITTLE, W S	8310200049*	50-440
LEDDICK, R S	8310030063*	50-382 K	LEWIS, R C	8310040405	50-250 Q	LITTLE, W S	8310200053*	50-440
LEDDICK, R S	8310070001	50-382 H	LEWIS, R C.	8310040458	50-335 Q	LITTLE, W S	8310200159	50-373
LEDDICK, R S	8310070247	50-382 A	LEWIS, R C.	8310040466	50-302 Q	LITTLE, W S	8310200276	50-358
LEDFOORD, S	8310240068*	50-413 T	LEWIS, R C	8310040468*	50-321 Q	LITTLE, W S	8310240069	50-456
LEDUC, R J	8310170218	71-9093	LEWIS, R C.	8310040475*	50-302 Q	LITTLE, W S	8310270446	50-235
LEDUC, R J	8310170228	71-9092	LEWIS, R C	8310040476	50-302 Q	LIVERMORE, H H.	8310280642*	50-461

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LIVINGSTON, A J	8310260271*	FOIA	MACDONALD, C E	8310070062*	71-9152	MADSEN, G L	8310180214	50-445 Q
LIVINGSTON, A J	8310260282*	FOIA	MACDONALD, C E	8310110090	71-9070	MADSEN, G L	8310180218	50-445 Q
LIVINGSTON, A J	8310260295*	FOIA	MACDONALD, C E	8310110402	71-505	MADSEN, G L	8310180225	50-298 Q
LOCKE, D L	8310060483*	CONTRACT	MACDONALD, C E	8310110410*	71-505	MADSEN, G L	8310180412	50-498 Q
LOCKER, R F.	8310110073	50-275 Q	MACDONALD, C E	8310110416	71-506	MADSEN, G L	8310180466	50-443 Q
LOFY, R A	8310170350*	CONTRACT	MACDONALD, C E	8310110423*	71-506	MADSEN, G L	8310310256	50-445 Q
LOJUDICE, J M	8310190281*	CONTRACT	MACDONALD, C E	8310110611	71-9128	MADSEN, G L	8310310388*	50-267 F
LOHR, J	8310250369	50-318 S	MACDONALD, C E	8310110614*	71-9128	MADSEN, G L	8310310402	50-382 Q
LOMBARDO, J J	8310210209	50-219 P	MACDONALD, C E	8310110619	71-6166	MAGER, T R	8310060310	50-413 T
LOMBARDO, J J	8310240124	50-219 P	MACDONALD, C E	8310110621	71-9127	MAGER, T R	8310060310	50-413 T
LOMERGAN, O T	8310260139*	FOIA	MACDONALD, C E	8310110622*	71-6166	MAHLER, R J	8310070331*	CONTRACT
LOMERGAN, O T	8310260280*	FOIA	MACDONALD, C E	8310110623*	71-9127	MAHON, C R	8310200147	50-317 S
LONG, J A	8310110378*	FOIA	MACDONALD, C E	8310110625	71-9126	MAIER, J E	8310180192	50-244 P
LOTTITO, E M	8310190148	50-317 R	MACDONALD, C E	8310110627*	71-9126	MAIER, J E	8310180193	50-244 P
LOUBERACK, T E	8310240032	40-8714	MACDONALD, C E	8310110629	71-9108	MAIER, J E	8310250217	50-244 S
LOVE, R. S.	8310140192*	50-454 Q	MACDONALD, C E	8310110631*	71-9108	MAIER, J E	8310250303	50-244 B
LOVENDALE, P	8310140253	50-266 S	MACDONALD, C E	8310120001	71-6478	MAIER, J E	8310270086*	50-244 F
LOVENDALE, P C	8310140216*	70-1308	MACDONALD, C E	8310120002*	71-6478	MAIER, P	8310270410*	50-263 S
LOVENDALE, P C	8310270313*	50-266 Q	MACDONALD, C E	8310190237	71-3593	MALINDSKI, F A	8310170221	71-9027
LOW, L. D	8310260131*	FOIA	MACDONALD, C E	8310190240*	71-3593	MALLET, B S	8310110534*	FOIA
LOW, L. D	8310260199*	FOIA	MACDONALD, C E	8310200012	71-6144	MALLET, B S	8310110562*	FOIA
LOWENSTEIN, R	8310270132*	FOIA	MACDONALD, C E	8310240237	71-3430	MALODY, C W	8310120357*	70-1257
LOWENSTEIN, R	8310270144*	FOIA	MACDONALD, C E	8310240239*	71-3430	MALODY, C W	8310130208	70-1257
LUBBOCK, D Q	8310040231	50-275 Q	MACDONALD, C E	8310240289	71-6574	MALODY, C W	8310170233	70-1257
LUBBOCK, D Q	8310040525	50-275 Q	MACDONALD, C E	8310240292	71-9027	MALODY, C W	8310170236*	70-1257
LUBBOCK, D Q	8310050396	50-275 Q	MACDONALD, C E	8310240297	71-6771	MANGAN, C V	8310040631	50-220 P
LUBBOCK, D Q	8310180328	50-275 Q	MACDONALD, C E	8310240299	71-9852	MANGAN, C V	8310060149	50-220 F
LUCK, W D.	8310260292	50-537 Q	MACDONALD, C E	8310240303*	71-9852	MANGAN, C V	8310120077	50-220 P
LUCKS, A. S.	8310170538*	50-329 Q	MACDONALD, C E	8310240305	71-503	MANGAN, C V	8310120205	50-220 P
LUCKS, A. S.	8310170544*	50-329 Q	MACDONALD, C E	8310240307*	71-503	MANGAN, C V	8310120373	50-220 P
LUCKS, A. S.	8310170549*	50-329 Q	MACDONALD, C E	8310240308	71-9086	MANGAN, C V	8310120406	50-220 P
LUCKS, A. S.	8310170555*	50-329 Q	MACDONALD, C E	8310240317	71-504	MANGAN, C V	8310120416*	50-220 P
LUCKS, A. S.	8310170559*	50-329 Q	MACDONALD, C E	8310240319*	71-504	MANGAN, C V	8310140221	50-220 P
LUCKS, A. S.	8310170616*	50-329 Q	MACDONALD, C E	8310250015	71-9010	MANGAN, C V	8310170586	50-220 P
LUCKS, A. S.	8310170622*	50-329 Q	MACDONALD, C E	8310250022	71-9039	MANGAN, C V	8310180098	50-220 P
LUCKS, A. S.	8310170627*	50-329 Q	MACDONALD, C E	8310250029	71-9089	MANGAN, C V	8310210171	50-220 P
LUCKS, A. S.	8310170634*	50-329 Q	MACDONALD, C E	8310260013	71-9111	MANGAN, C V	8310310228	50-410 K
LUCO, J E	8310110382*	CONTRACT	MACDONALD, C E	8310310428	71-9086	MANGAN, C V	8310310228	50-410 A
LUDINGTON, B W	8310010087*	50-272 P	MACDONALD, C E	8310310481	71-9182	MANN, B	8310130143	NUREG
LUDINGTON, B W	8306160602*	50-302 P	MACE, E M	8310210174	50-298 S	MANN, S F	8310170153	50-410 S
LUEBKE, E A	8310040192	50-142 Q	HACKAY, B	8310240080	50-324 F	MANN, S F	8310280052	50-410 S
LUEBKE, E A	8310040194	27-39	HACKAY, S D	8310050451	50-324 F	MANN, S F	8310280070*	FOIA
LUEBKE, E A	8310260263	50-142 Q	HACKAY, S D	8310060031	50-324 P	MARCHAL, J	8310060415	XPOR TLIC
LUMB, R F	8310070189*	CONTRACT	HACKAY, S D	8310060043*	50-324 P	MARCHAL, J	8310060420	XPOR TLIC
LUNDVALL, A. E	8310040353	50-317 P	HACKAY, S D	8310240138	50-324 P	MARCHAL, J	8310060424	XPOR TLIC
LUNDVALL, A. E	8310200241	50-317 P	HACKAY, S D.	8310280129	50-324 F	MARCHI, M L	8310120209*	50-305 F
LUNDVALL, A. E	8310210210*	50-317 Q	HACKENZIE, D R	8310310114	NUREG	MARCHI, M L	8310120214*	50-305 F
LUNDVALL, A. E	8310240072	50-317 P	HACPERSON, B J	8310240313	XPOR TLIC	MARCHI, M L	8310120216*	50-305 F
LUNDVALL, A. E	8310240134	50-317 P	HACPERSON, B J	8310250135	XPOR TLIC	MARCHI, M L	8310120220*	50-305 F
LUNDVALL, A. E	8310240162	50-317 P	HACPERSON, B J	8310250198	XPOR TLIC	MARCHI, M L	8310120223*	50-305 F
LUNDVALL, A. E	8310310303	50-317 P	HACRUSKY, J	8310250423*	50-275 Q	MARCHI, M L	8310120227*	50-305 F
LUNDY, J R	8310110404*	FOIA	HACRUSKY, J	8310250600*	50-312 P	MARCHI, M L	8310120232*	50-305 F
LYCZKOWSKI, J V	8310040319*	50-155 T	HACSHAIN, D M	8310120341*	50-305 P	MARCHI, M L	8310120235*	50-305 F
LYCZKOWSKI, J V	8310040319*	50-155 T	HACSHAIN, D M	8310120343*	50-305 P	MARCHI, M L	8310120238*	50-305 F
LYXOUBIS, P B	8310190329*	FOIA	HADDEN, J. R	8310110147*	FOIA	MARCOUX, W C	8310050298	50-285 P
LYNCH, M D.	8310240103	50-341 A	HADDEN, W	8310040213	50-272 S	MARCOUX, W C	8310050298	50-285 P
LYONS, P J L	8310260416	40-299	MADEDA, T. J	8310140216*	70-1308	MARCOUX, W F	8310050337*	CONTRACT
LYONS, P J L	8310280165	40-299	MADEDA, T. J	8310250582*	70-2977	MARIANI, L P	8310030396	PR
LYONS, T D	8310270105*	FOIA	MADEDA, T. J	8310270313*	50-266 Q	MARKEY, E J	8310060594*	50-382 U
MA, J.	8310170484*	50-382 Q	MADEDA, T. J	8310310347*	50-341 Q	MARKEY, E J	8310070380*	COMMISSION
MABRITO, B	8310190343	71-505	MADSEN, G. L.	8310030344	50-267 Q	MARKEY, E J	8310200469*	50-275 U
MACCUSKY, J.	8310250152*	ORQ	MADSEN, G. L.	8310030385	50-498 Q	MARKEY, E J	8310270042*	50-309 F
MACDONALD, C E	8310050193	71-9060	MADSEN, G. L.	8310030402	50-458 Q	MARKT, D	8310270042*	50-309 F
MACDONALD, C E	8310040094	71-466	MADSEN, G. L.	8310030446	50-267 Q	MARKT, D E	8310270534*	50-29 F
MACDONALD, C E	8310040099*	71-466	MADSEN, G. L.	8310040153	50-382 Q	MARSHALL, J R	8310030332	50-313 P
MACDONALD, C E	8310040171	71-9182	MADSEN, G. L.	8310040156	50-445 Q	MARSHALL, J R	8310030353	50-313 P
MACDONALD, C E	8310050014	71-39	MADSEN, G. L.	8310040181	50-445 Q	MARSHALL, J R	8310030416	50-313 F
MACDONALD, C E	8310050016	71-6003	MADSEN, G. L.	8310040223	50-445 Q	MARSHALL, J R	8310040149	50-368 S
MACDONALD, C E	8310050019	71-4909	MADSEN, G. L.	8310040456	50-267 P	MARSHALL, J R	8310040154	50-313 S
MACDONALD, C E	8310050021	71-9158	MADSEN, G. L.	8310040536	50-498 Q	MARSHALL, J R	8310040206	50-368 S
MACDONALD, C E	8310050025	71-9510	MADSEN, G. L.	8310040558	50-267 Q	MARSHALL, J R	8310040271	PR
MACDONALD, C E	8310050030*	71-9510	MADSEN, G. L.	8310040580	50-267 Q	MARSHALL, J R	8310040338	50-368 S
MACDONALD, C E	8310050041*	71-6003	MADSEN, G. L.	8310060013	50-267 Q	MARSHALL, J R	8310060402	50-313 F
MACDONALD, C E	8310050046	71-9080	MADSEN, G. L.	8310060379	50-382 Q	MARSHALL, J R	8310060601*	50-313 F
MACDONALD, C E	8310050053	71-9100	MADSEN, G. L.	8310060459	50-382 Q	MARSHALL, J R	8310120447	50-313 P
MACDONALD, C E	8310050057*	71-9100	MADSEN, G. L.	8310130176	50-498 Q	MARSHALL, J R	8310130283	50-368 S
MACDONALD, C E	8310050097	71-5088	MADSEN, G. L.	8310130206	50-298 Q	MARSHALL, J R	8310140094	50-368 F
MACDONALD, C E	8310050114	71-5059	MADSEN, G. L.	8310130221*	50-298 Q	MARSHALL, J R	8310140225	50-313 P
MACDONALD, C E	8310050124	71-37	MADSEN, G. L.	8310130221	50-498 Q	MARSHALL, J R	8310180189	50-368 S
MACDONALD, C E	8310050133*	71-37	MADSEN, G. L.	8310130247	50-458 Q	MARSHALL, J R	8310180457	50-368 S
MACDONALD, C E	8310060599	71-9070	MADSEN, G. L.	8310130262	50-382 Q	MARSHALL, J R	8310180489	50-368 S
MACDONALD, C E	8310060600*	71-9070	MADSEN, G. L.	8310180144	50-458 Q	MARSHALL, J R	8310180529	50-368 S
MACDONALD, C E	8310070005	71-5957	MADSEN, G. L.	8310180156	50-298 Q	MARSHALL, J R	8310190045	50-368 R
MACDONALD, C E	8310070017	71-9009	MADSEN, G. L.	8310180196	50-267 F	MARSHALL, J R	8310190117	50-313 R
MACDONALD, C E	8310070039	71-9152	MADSEN, G. L.	8310180212	50-267 P	MARSHALL, J R	8310240033	50-313 J

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MARSHALL, J R	B310250141	50-313 Q	MATTIA, M J	B310050323*	CONTRACT	MCDUFFIE, M A	B310210245	50-261
MARSHALL, J R	B310250153	50-313 Q	MATTIA, M J	B310050349*	CONTRACT	MCDUFFIE, M A	B310250371	50-261
MARSHALL, J R	B310250274	50-313 F	MATTIA, M J	B310050467*	CONTRACT	MCDUFFIE, M A	B310250638	50-400
MARSHALL, J R	B310250281	50-368 P	MATTIA, M J	B310070173*	CONTRACT	MCDUFFIE, M A	B310260134	50-400
MARSHALL, J R	B310250417	50-313 Q	MATTIA, M J	B310070175*	CONTRACT	MCDUFFIE, M A	B310260147	50-400
MARSHALL, J R	B310250533	50-368 P	MATTIA, M J	B310070231*	CONTRACT	MCDUFFIE, M A	B310260152	50-400
MARSHALL, J R	B310250559	50-313 F	MATTIA, M J	B310070237*	CONTRACT	MCDUFFIE, M A	B310260259	50-400
MARSHALL, J R	B310310368	50-368 S	MATTIA, M J	B310110025*	FOIA	MCDUFFIE, M A	B310280014	50-400
MARSHALL, J S	B310210081	50-445 A	MATTIA, M J	B310110344*	CONTRACT	MCDUFFIE, M A	B310310027	50-261
MARSTON, R R	B310250394*	50-280 Q	MATTIA, M J	B310110499*	CONTRACT	MCFARLAND, C R	B310040244*	50-438
MARTIN, D	B310240266	WASTE MGT	MATTIA, M J	B310110512*	CONTRACT	MCFARLAND, C R	B310040345*	50-413
MARTIN, D E	B310240267	WASTE MGT	MATTIA, M J	B310110524*	CONTRACT	MCFARLAND, C R	B310250406*	50-370
MARTIN, M Q	B310110407*	50-400 Q	MATTIA, M J	B310110524*	CONTRACT	MCGARRY, J M.	B310030406	50-413
MARTIN, J B	B310030457*	50-267 Q	MATTIA, M J	B310130407*	CONTRACT	MCGARRY, J M	B310030406	50-413
MARTIN, J B	B310180362	50-344 Q	MATTINOE, J J	B310120150	50-312 S	MCGAUGHY, J P	B310030373	50-416
MARTIN, J B	B310200220	50-206 Q	MATTINOE, J J	B310120186	50-312 S	MCGAUGHY, J P	B310030374	50-416
MARTIN, J B	B310240227*	50-588 Q	MATTINOE, J J	B310120394	50-312 P	MCGAUGHY, J P.	B310060227	50-416
MARTIN, J B	B310250132*	ORQ	MATTINOE, J J	B310140249	50-312 Q	MCGAUGHY, J P.	B310130117	50-416
MARTIN, J B	B310230423*	50-275 Q	MATTINOE, J J	B310210020	50-312 P	MCGAUGHY, J P.	B310140007	50-417
MARTIN, J B	B310250600*	50-312 P	MATTINOE, J J	B310250210	50-312 P	MCGAUGHY, J. P	B310140075	50-416
MARTIN, L E	B310180227*	50-445 Q	MATTSON, R J	B302090523*	50-255 P	MCGAUGHY, J. P	B310170400	50-416
MARTIN, M A	B310070289*	50-528 S	MATTSON, R J	B309080358*	GEN TEC IS	MCGAUGHY, J P	B310250389	50-416
MARTIN, M Q	B310180313*	QA999	MATTSON, R J	B310110574*	50-247 P	MCGAUGHY, J P	B310270433	50-416
MARTIN, M Q	B310180323*	QA999	MATTSON, R J	B310110630	50-289 P	MCGAUGHY, R W	B310140254	50-331
MARTIN, M Q	B310180340*	QA999	MATTSON, R J	B310130155	50-289 P	MCGAUGHY, R. W	B310170405	50-331
MARTIN, R D	B310260027*	50-270 S	MAUPIN, M W	B310190200	50-338 Q	MCGAUGHY, R W	B310180198	50-331
MARTIN, R E	B310030360	50-392 A	MAUPIN, M W	B310190200	50-338 Q	MCGAUGHY, R W	B310180424	50-331
MARTIN, R E	B310070190	50-392 E	MAUPIN, M W	B310260279	50-338 Q	MCGAUGHY, R W	B310200182	50-331
MARTIN, R E	B310260316	50-392 E	MAUPIN, M W	B310260279	50-338 Q	MCGAUGHY, R. W.	B310270459	50-331
MARTIN, R G	B310040339	50-309 P	MAURO, J J	B310060238*	50-400 Q	MCGILTONN, C H	B310210173*	50-397
MARTIN, R K	B310280177*	40-299	MAURO, J J	B310060238*	50-400 Q	MCGUIRE, D R	B310030305*	50-280
MARTIN, T J	B310280075	50-354 S	MAURO, J J	B310110407*	50-400 Q	MCGUIRE, D R	B310070259*	70-143
MARTIN, T J	B310280093	50-354 S	MAXWELL, B	B310190337	FOIA	MCGUIRE, D R	B310070294*	50-324
MARTIN, T J	B310280101	50-394 S	MAXWELL, D	B310210313	50-237 S	MCGUIRE, D R.	B310170149*	50-416
MARTIN, T T	B310030158	50-247 Q	MAXWELL, G. F	B310040613*	50-400 Q	MCGUIRE, D R	B310170238*	50-259
MARTIN, T T	B310030345	50-412 Q	MAXWELL, G. F	B310250632*	50-400 Q	MCGUIRE, D R	B310170246*	70-27
MARTIN, T T	B310040449	50-317 F	MAY, E L	B310250523	50-29 S	MCGUIRE, D R	B310170322*	50-261
MARTIN, T T	B310060004	50-410 Q	MAY, E L	B310280015	50-29 S	MCGUIRE, D R	B310210034*	50-259
MARTIN, T T	B310060017	50-244 Q	MAY, W R	B310280104*	CONTRACT	MCGUIRE, D R	B310210070*	50-324
MARTIN, T T.	B310060041	50-388 Q	MAYWEATHER, L	B310190092	50-361 R	MCGUIRE, D R	B310260221*	70-1113
MARTIN, T T	B310060044	50-244 Q	MCAFFEE, W R	B310240021*	50-413 T	MCGUIRE, D R	B310270023*	50-321
MARTIN, T T	B310060341	50-334 Q	MCALLISTER, B A	B310190231	50-309 S	MCGURREN, H J	B310050371	50-275
MARTIN, T T	B310120137	50-29	MCAHPINE, E J.	B310040148*	70-1151	MCGURREN, H J	B310130163	50-275
MARTIN, T T	B310120193	50-283 Q	MCAHPINE, E J.	B310040197*	70-143	MCGURREN, H J	B310210350	50-275
MARTIN, T T	B310120195	70-133	MCAHPINE, E J.	B310040342*	70-824	MCGURREN, H J	B310250176	50-275
MARTIN, T T	B310120212	50-277 Q	MCAHPINE, E J.	B310040493*	70-27	MCGURREN, H J	B310250326	50-275
MARTIN, T T	B310140195	50-286 Q	MCAHPINE, E J.	B310260114*	70-1151	MCINNIS, D.	B310280174	50-400
MARTIN, T T	B310140234	50-271 Q	MCAHPINE, E J.	B310260194*	70-1113	MCINTOSH, J. T.	B310110076*	50-269
MARTIN, T T	B310180137	70-2808	MCDANIEL, A R.	FOIA		MCINTOSH, J. T.	B310110141*	50-269
MARTIN, T T	B310180349	50-387 Q	MCDERREARY, R. A	B310120096*	50-220 Q	MCINTOSH, M D	B310060266*	50-369
MARTIN, T T	B310180366	50-289 Q	MCDERREARY, R A	B310190142*	50-443 Q	MCKINNEY, C J	B310070002	50-395
MARTIN, T T	B310190133	50-443 Q	MCDRIDE, C. S	B310110616*	CONTRACT	MCKINNEY, C J	B310170443	50-395
MARTIN, T T	B310190172	50-443 Q	MCDRIDE, L M	B310040322*	50-267 B	MCKINNEY, C. J	B310170568	50-395
MARTIN, T T	B310190246	50-334 Q	MCDRIDE, L M	B310040324*	50-267 B	MCLAUGHLIN, D	B310250401*	50-315
MARTIN, T T	B310200088	50-271 Q	MCDRIDE, L M	B310040328*	50-267 B	MCLAUGHLIN, L	B310190104	50-389
MARTIN, T T	B310200218	50-289 Q	MCDRIDE, M	B310060349*	50-334 Q	MCLAREN, T	B310050367	CONTRACT
MARTIN, T T	B310210243	50-443 Q	MCDRIDE, M	B310140236*	50-271 Q	MCLAREN, T	B310050462	CONTRACT
MARTIN, T T	B310210265	50-309 Q	MCCLESKEY, K E	B310270239	50-322 Q	MCLAREN, T.	B310060007	CONTRACT
MARTIN, T T	B310210280	50-289 Q	MCCLLINTOCK, R. O	7906250181*	FOIA	MCLAREN, T.	B310180592	CONTRACT
MARTIN, T T.	B310210286	50-309 Q	MCCOLLUM, K A	B310110266	50-445 Q	MCLAREN, T	B310210190	CONTRACT
MARTIN, T T.	B310240082	70-1100	MCCOLLUM, K A	B310140085*	50-445 Q	MCLAUGHLIN, D.	B310050548	50-3
MARTIN, T T.	B310250440	70-820	MCCOLLUM, K A	B310270228	50-445 Q	MCNORRIS, J A	B310180553*	CONTRACT
MARTIN, T T.	B310250512	50-272 Q	MCCOLLUM, K. A	B310270229	50-445 Q	MCNULLEN, R B	B310130152*	50-537
MARTIN, T T.	B310250597	50-193 Q	MCCONNELL, T	B310070131*	50-370 F	MCNAMARA, A E.	B310190032	50-244
MARTIN, T T	B310270164	70-371	MCCONNELL, T L	B310110079*	50-369 F	MCNEILL, C A	B310060089	50-333
MARTIN, T T.	B310270184	50-29 Q	MCCONNELL, T L	B310110421*	50-369 F	MCNEILL, C A	B310120435	50-333
MARTIN, T T.	B310270207	50-220 Q	MCCONNELL, T L	B310270146*	50-369 F	MCNEILL, C. A	B310170533	50-333
MARTIN, T T	B310270225	50-293 Q	MCCOOL, W B	B310120032*	50-201 I	MCNEILL, C A	B310190082	50-333
MARTIN, T T	B310310337	70-474	MCDANIEL, A	B310040282	50-261 Q	MCNEILL, C. A	B310190150	50-333
MARTIN, T T	B310310414	70-2430	MCDERMOTT, D	B310070201	CONTRACT	MCNEILL, C A	B310190213	50-333
MARTIN, T T	B310310419	70-2319	MCDERMOTT, D	B310190276	CONTRACT	MCNEILL, C. A.	B310200134	50-333
MARTIN, W Q	B310120143*	50-29 Q	MCDERMOTT, D	B310200458	CONTRACT	MCNEILL, C.	B310070257*	50-275
MARUSICH, R M	B310040560*	50-155 T	MCDONALD, D Q.	B310180298	50-250 H	MCNEILL, C. A.	B310250412	50-333
MARUSICH, R M	B310110293*	50-155 T	MCDONALD, D Q.	B310270129	50-250 P	MCNEILL, C. A.	B310250585	50-333
MASON, C C	B310190066	50-327 R	MCDONOUGH, C. L	B310110302	50-456 C	MCNEILL, C A	B310250614	50-333
MASON, H. D	B310270177*	FOIA	MCDUFFIE, M A.	B310070120	50-400 A	MCNEILL, C. A.	B310310203	50-333
MASBENGAL, E	B310270093	FOIA	MCDUFFIE, M A.	B310110119	50-400 E	MCNEILL, R	B310070257*	50-275
MASTERSON, V	B310060271	50-373 S	MCDUFFIE, M A.	B310120180	50-400 E	MCNEILL, W.	B308300722*	QA999
MATAKES, RE A	B310040453*	QA999	MCDUFFIE, M A.	B310130240	50-400 E	MCNEILL, M. H	B310030387*	QA999
MATHIAU, C	B310110184*	50-263 F	MCDUFFIE, M. A.	B310140126	50-400 E	MCPECK, E W	B310210330	HISC
MATTHEWS, D B	B310170028	50-289 F	MCDUFFIE, M A	B310180311	50-400 E	MCPIERSON, B R.	B310140129	50-259
MATTHEWS, M L	B310280076	WASTE MGT	MCDUFFIE, M A	B310180474	50-400 E	MCQUILLAN, P Q.	B310180314*	QA999
MATTHEWS, T. P	B310180162	50-285 R	MCDUFFIE, M. A	B310210024	50-400 E	MCQUILLAN, P Q.	B310180326*	QA999
MATTIA, M	B310110089*	CONTRACT	MCDUFFIE, M. A	B310210046	50-261 P	MCTIERNAN, J. J	B310200401*	FOIA
MATTIA, M. J.	B305130302*	FOIA	MCDUFFIE, M A	B310210136	50-400 F	MCTIERNAN, T. J	B310200391*	FOIA

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MEDFORD, M O	8310030110	50-206 F	MILLER, L K	8310030346	50-272 R	HILLS, L M	8310140277	50-438 S
MEDFORD, M O	8310040009	50-361 P	MILLER, L K	8310180114	50-311 R	HILLS, L M	8310170264	50-390 S
MEDFORD, M O	8310120397	50-361 P	MILLER, L K	8310200174	50-272 R	HILLS, L M	8310170733	70-2941
MEDFORD, M O	8310130012	50-206 F	MILLER, L K	8310210041	50-311 R	HILLS, L M	8310180388	50-390 A
MEDFORD, M O	8310200177	50-361 P	MILLER, M	8310110635	50-329 A	HILLS, L M	8310190089	50-390 S
MEDFORD, M O	8310210260	50-362 P	MILLER, M A	8310110377	50-329 A	HILLS, L M	8310190127	50-390 S
MEDFORD, M O	8310250124	50-206 P	MILLER, M A	8310120464	50-329 F	HILLS, L M	8310190220	50-438 S
MEDFORD, M O	8310270101	50-206 P	MILLER, M A	8310130045	50-329 A	HILLS, L M	8310190224	50-390 S
MEDLOCK, R L	8310030241	40-8432	MILLER, M A	8310190263	50-329 E	HILLS, L M	8310210011	50-390 S
MENCZER, W	8310060428	50-10 S	MILLER, M E	8310200247	50-334 G	HILLS, L M	8310210015	50-390 S
MENDENHALL, E	8310210016	50-263 S	MILLER, M E	8310260301	50-537 G	HILLS, L M	8310210042	50-390 S
MENDONCA, M M	8310170479*	50-273 G	MILLER, M I	8310060314	50-454 G	HILLS, L M	8310210049	50-390 S
MENDONCA, M M	8310310231*	50-273 G	MILLER, M I	8310060314	50-454 G	HILLS, L M	8310210048	50-390 S
MERRITT, B	8310210165	50-249 S	MILLER, M I	8310060321*	50-454 G	HILLS, L M	8310210078*	50-259 G
MERRITT, B	8310270424	50-249 S	MILLER, M I	8310060321*	50-454 G	HILLS, L M	8310210078	50-390 S
MERRIWEATHER, N	8310200037*	50-440 G	MILLER, M R	8310260052*	FOIA	HILLS, L M	8310210178	50-438 A
MERRIWEATHER, N	8310270426*	50-440 G	MILLER, M R	8310260084*	FOIA	HILLS, L M	8310210301	50-390 E
MESLER, R B	8310210237	50-148 F	MILLER, M R	8310260351*	FOIA	HILLS, L M	8310210383*	50-259 F
MESSING, A M	8310270109*	FOIA	MILLER, R P	8310070429*	CONTRACT	HILLS, L M	8310250012	50-390 S
MEYER, G C	8310270006	50-470 A	MILLER, T D	8310030469*	GA999	HILLS, L M	8310250034	50-390 A
MEYER, G C	8310280306	50-470 A	MILLER, W H	8310250498*	50-348 G	HILLS, L M	8310250082	50-259 P
MEYER, T A	8310050310	50-413 T	MILLER, W O	8310030625	50-339 P	HILLS, L M	8310250110	50-438 S
MEYER, T A	8310060310	50-413 T	MILLER, W O	8310060568	50-301 P	HILLS, L M	8310250138*	50-259 G
MEYER, W A	8310190347	50-186 F	MILLER, W O	8310130424	50-206 F	HILLS, L M	8310250149	50-438 S
MEYERS, B L	8310310074	50-482 S	MILLER, W O	8310180025	50-302 P	HILLS, L M	8310250162	50-390 S
MICHAELS, T B	8310140290	50-289 P	MILLER, W O	8310180280	50-348 P	HILLS, L M	8310250165	50-390 G
MILES, D E	8310070414	NUREG	MILLER, W O	8310210075	50-250 P	HILLS, L M	8310250170*	50-259 G
MILES, J R	8310110324*	CONTRACT	MILLER, W O	8310210080	50-313 P	HILLS, L M	8310250173	50-390 S
MILHOAN, J L	8310190270*	50-454 G	MILLER, W O	8310210101	50-298 P	HILLS, L M	8310250229	50-259 G
MILLER, A	8310070436	NUREG	MILLER, W O	8310210157	50-317 P	HILLS, L M	8310250233	50-390 S
MILLER, C A	8310210358*	50-273 T	MILLER, W O	8310210351	50-334 P	HILLS, L M	8310250240*	50-259 G
MILLER, D B	8310140273*	50-329 A	MILLER, W S	8310280083	50-352 H	HILLS, L M	8310250306*	50-438 G
MILLER, D B	8310170237	50-329 A	MILLIGAN, H H	8310310434*	50-322 S	HILLS, L M	8310250313*	50-438 G
MILLER, D B	8310170439*	50-329 A	MILLS, L M	8310030214	50-390 S	HILLS, L M	8310250312	50-390 S
MILLER, D B	8310170714	50-329 A	MILLS, L M	8310030233	50-390 S	HILLS, L M	8310250378	50-390 S
MILLER, D B	8310250058	50-329 A	MILLS, L M	8310030244	50-390 S	HILLS, L M	8310250436*	50-327 G
MILLER, D E	8310140216*	70-1308	MILLS, L M	8310030252	50-390 S	HILLS, L M	8310250484*	50-327 G
MILLER, H J	8310240260	WASTE MGT	MILLS, L M	8310030257	50-390 S	HILLS, L M	8310250502*	50-327 G
MILLER, J F	8310120369	50-29 P	MILLS, L M	8310030338	50-390 S	HILLS, L M	8310260364	40-1341
MILLER, J F	8310120374*	50-29 P	MILLS, L M	8310030365	50-390 S	HILLS, L M	8310270150	50-390 S
MILLER, J R	8310060520	50-313 F	MILLS, L M	8310030370	50-390 S	HILLS, L M	8310270183	50-390 S
MILLER, J R	8310070179*	50-317 P	MILLS, L M	8310030388	50-390 S	HILLS, L M	8310270248	50-438 S
MILLER, J R	8310070183*	50-335 P	MILLS, L M	8310030399	50-390 S	HILLS, L M	83102800021	50-327 P
MILLER, J R	8310110446	50-266 P	MILLS, L M	8310030404	50-390 S	HILLS, L M	8310280022	50-327 P
MILLER, J R	8310110457	50-266 P	MILLS, L M	8310030424	50-390 S	HILLS, L M	8310280148	50-259 P
MILLER, J R	8310110466	50-336 P	MILLS, L M	8310030436	50-390 S	HILLS, L M	8310280173	50-390 A
MILLER, J R	8310110483	50-335 P	MILLS, L M	8310030462	50-390 S	HILLS, L M	8310280321	40-1341
MILLER, J R	8310110492	50-309 P	MILLS, L M	8310030473	50-390 S	HILLS, L M	8310310142	50-259 P
MILLER, J R	8310110497	50-389 P	MILLS, L M	8310030506	50-390 S	HILLS, L M	8310310148	50-390 S
MILLER, J R	8310110498	50-282 P	MILLS, L M	8310030519	50-390 S	HILLS, L M	8310310157	50-438 S
MILLER, J R	8310110504	50-266 P	MILLS, L M	8310030538	50-390 S	HILLS, L M	8310310320	50-390 S
MILLER, J R	8310110543	50-336 P	MILLS, L M	8310040138	50-390 S	HILLS, L M	8310310348	50-390 S
MILLER, J R	8310130033	50-266 P	MILLS, L M	8310040172	50-438 S	HILLS, L M	8310310387	50-259 F
MILLER, J R	8310130036*	50-266 P	MILLS, L M	8310040180	50-390 S	HILLS, L M	8310310429	50-327 P
MILLER, J R	8310130044*	50-266 P	MILLS, L M	8310040193	50-390 S	HILLS, M	8310130143	NUREG
MILLER, J R	8310130056*	50-266 P	MILLS, L M	8310040271*	50-259 G	MINS, R	8310130406*	CONTRACT
MILLER, J R	8310130076*	50-282 P	MILLS, L M	8310040402	50-390 F	MINS, R	8310130407*	CONTRACT
MILLER, J R	8310130202*	50-266 P	MILLS, L M	8310040452	50-259 F	MINECK, D L	8310120380	50-331 S
MILLER, J R	8310130423	50-389 P	MILLS, L M	8310040544	50-390 S	MINECK, D L	8310120400	50-331 S
MILLER, J R	8310170088	50-335 P	MILLS, L M	8310040549	50-390 S	MINECK, D L	8310120421	50-331 S
MILLER, J R	8310170708	50-309 P	MILLS, L M	8310060008	50-390 S	MINECK, D L	8310170490	50-331 S
MILLER, J R	8310170723	50-266 P	MILLS, L M	8310060009	50-390 S	MINECK, D L	8310170581	50-331 S
MILLER, J R	8310180020	50-309 F	MILLS, L M	8310060016	50-390 S	MINECK, D L	8310190068	50-331 R
MILLER, J R	8310180405	50-285 G	MILLS, L M	8310060027	50-390 S	MINECK, D L	8310210090	50-331 S
MILLER, J R	8310180410*	50-285 G	MILLS, L M	8310060087	50-390 S	MINECK, D L	8310250481	50-331 S
MILLER, J R	8310180608	50-344 P	MILLS, L M	8310060095	50-390 S	MINECK, D L	8310270290	50-331 S
MILLER, J R	8310240108*	50-376 P	MILLS, L M	8310060331	50-390 S	MINER, S	8310050517*	50-312 G
MILLER, J R	8310240113*	50-336 P	MILLS, L M	8310060342	50-390 S	MINER, S	8310280072	50-312 P
MILLER, J R	8310240122*	50-266 P	MILLS, L M	8310060436	50-390 S	MINNICH, J E	8310120171	50-320 H
MILLER, J R	8310240216	50-309 P	MILLS, L M	8310060476	50-390 S	MINNICH, J E	8310140025	50-320 P
MILLER, J R	8310250677	50-309 P	MILLS, L M	8310060488	50-390 S	MIRALIA, F J	8310140292	50-289 P
MILLER, J R	8310260358	50-309 P	MILLS, L M	8310110199*	50-239 F	MIRALIA, F J	8211020311*	FOIA
MILLER, J R	8310260429	50-309 P	MILLS, L M	8310120100	50-390 S	MIRALIA, F J	8211040474*	FOIA
MILLER, J R	8310270355	50-266 P	MILLS, L M	8310120169	50-390 S	MIRALIA, F J	8212130174*	FOIA
MILLER, J R	8310280087	50-285 P	MILLS, L M	8310120210	50-390 S	MIRALIA, F J	8310180551	50-155 G
MILLER, J R	8310280098	50-266 P	MILLS, L M	8310120228	50-438 S	MIRALIA, F J	8310250013	TOPREP
MILLER, J R	8310310123	50-282 F	MILLS, L M	8310120236	50-390 S	MIRALIA, F J	8310260086*	FOIA
MILLER, J R	8310310125	50-335 P	MILLS, L M	8310120237	50-390 S	MIRALIA, F J	8310260087*	FOIA
MILLER, J R	8310310129	50-285 P	MILLS, L M	8310120332	50-390 S	MIRALIA, F J	8310260091*	FOIA
MILLER, J R	8310310173	50-282 G	MILLS, L M	8310120336	50-390 S	MIRALIA, F J	8310260092*	FOIA
MILLER, J R	8310310177*	50-282 G	MILLS, L M	8310120389	50-390 S	MIRALIA, F J	8310260353	50-244 P
MILLER, J R	8310310180	50-317 P	MILLS, L M	8310120396	50-390 S	MISAK, A	8310270404	50-254 R
MILLER, J R	8310310458	50-335 S	MILLS, L M	8310140017	50-390 S	MISAK, A L	8310180263	50-254 R
MILLER, J R	8310310479	50-317 P	MILLS, L M	8310140048	50-390 S	MISHKHA, J	8310260381	NUREG
MILLER, L	8310060512*	CONTRACT	MILLS, L M	8310140224	50-390 A	MISSIO, D	8310120239	50-346 S

PERSONAL AUTHOR INDEX

509

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MITCHELL, D H	8310120391	50-346 S	MORTON, K V	8310210198*	CONTRACT	MUSOLF, D	8310120102	50-282 S
MITCHELL, G J	8310110347	NJREQ	MORTON, K V	8310210211*	CONTRACT	MUSOLF, D	8310120340	50-306 S
MITTL, R L	8310180016*	COMMISSION	MORTON, K V	8310280104*	CONTRACT	MUSOLF, D	8310120432	50-263 H
MITTL, R L	8310200239	50-354 E	MOSELEY, N C	8310280132*	FOIA	MUSOLF, D	8310170641	50-306 S
MITTL, R L	8310240143	50-354 F	MOSHER, D	8310170052	FOIA	MUSOLF, D	8310190021	50-263 R
MITTL, R L	8310250215	50-354 A	MOSLAK, T	8310140170*	50-320 Q	MUSOLF, D	8310190055	50-282 R
MIZUNO, G S	8310250260	50-445 Q	MOWRY, W R	8310060177	XPORTLIC	MUSOLF, D	8310210237	50-263 S
MIZUNO, G S	8310250295	50-445 Q	MOWRY, W R	8310130270	71-6346	MUSOLF, D	8310270283	50-263 S
MOEGENBERG, D	8310180189	50-368 S	MOWRY, W R	8310170064	71-6346	MUSOLF, D	8310270359*	50-263 S
MOELLER, P A	8310210195	50-272 F	MOWRY, W R	8310250393	PR	MUSOLF, D	8310270364*	50-263 S
MOLES, R C	8310110528*	CONTRACT	MOYER, R E	8310260323	XPORTLIC	MUSOLF, D	8310270380*	50-266 S
MOLNAR, J R	8310190031	50-219 R	MROCKA, E J	8310180336	50-245 S	MUSOLF, D	8310270390*	50-263 S
MONTGOMERY, D M	8310040517*	50-250 Q	MROCKA, E J	8310180336	50-245 S	MUSOLF, D	8310270410*	50-263 S
MONTGOMERY, D M	8310250352*	70-143	MROCKA, E J	8310190015	50-245 S	MUSOLF, D	8310270414*	50-263 S
MONTGOMERY, D M	8310250438*	50-280 Q	MROCKA, E J	8310190015	50-245 R	MUSOLF, D	8310270418*	50-282 S
MONTGOMERY, J L	8310030457*	50-267 Q	MROCKA, E J	8310190207	50-336 R	MUSOLF, D	8310270421*	50-282 S
MONTGOMERY, J L	8310180246*	50-285 Q	MROCKA, E J	8310190207	50-336 R	MUSOLF, D	8310270423*	50-282 S
MONTGOMERY, J M	8310110570	MISC	MROCKA, E J	8310200129	50-245 R	MUSOLF, D	8310270427*	50-282 S
MOONEY, J A	8310040122	50-329 A	MROCKA, E J	8310200167	50-336 R	MUSOLF, D	8310270429*	50-306 S
MOONEY, J A	8310050296	50-329 A	MROCKA, E J	8310250263	50-245 S	MYERS, D A	8310110347	NJREQ
MOONEY, J A	8310050322	50-329 A	MROCKA, E J	8310250263	50-245 S	MYERS, D D	8310040332*	50-324 Q
MOORE, D E	8310170238*	50-259 Q	MROCKA, E J	8310250263*	50-373 Q	MYERS, D D	8310270390*	50-321 Q
MOORE, D E	8310210034*	50-259 Q	MULHOLLAND, P J	8310260423	NJREQ	MYERS, L L	8310180118	NJREQ
MOORE, D E	8310180299*	0A999	MULLEE, G R	8310110511*	FOIA	MYRABO, A L	8310190021	50-263 R
MOORE, R D	8310270537*	50-10 F	MUMA, E	8310050494*	50-155 Q	NADEAU, J P	8310040553	50-443 Q
MOORE, R D	8310280209*	50-10 F	MUMA, E	8310050494*	50-155 Q	NADEAU, J P	8310120178	50-443 Q
MOORE, R D	8310280314*	50-10 F	MUMA, E	8310140078*	50-155 T	NAIDU, K R	8310050497*	50-341 Q
MOORE, R N	8310060056	XPORTLIC	MUMA, E	8310140078*	50-155 T	NAPUDA, Q	8310140170*	50-320 Q
MOORE, R N	8310060234	XPORTLIC	MURLEY, T E	8310060053	50-309 F	NARABO, A	8310200092*	50-271 Q
MOORE, R N	8310240306	XPORTLIC	MURLEY, T E	8310140003	50-311 Q	NARBUT, P	8310240207*	FOIA
MOORE, R N	8310240322	XPORTLIC	MURLEY, T E	8310200179	State Prog	NARBUT, P	8310240220*	50-328 A
MOORE, S N	8310240126	50-261 P	MURLEY, T E	8310200181*	State Prog	NARBUT, P P	8310240230*	50-328 A
MORAN, D H	8310070174	PROJ	MURLEY, T E	8310250116	State Prog	NARDACCI, O. A	8310120128*	50-289 R
MORAN, D H	8310310179	50-546 Q	MURLEY, T E	8310270052	50-334 Q	NARDI, A J	8310170330	70-1151
MORGAN, R A	8310240066*	50-413 T	MURLEY, T E	8310270180	50-219 P	NARDI, A J	8310200451	71-5450
MORGAN, R E	8310030426	50-261 S	MURLEY, T E	8310270581	50-220 Q	NARDI, A J	8310240248	70-1143
MORGAN, R E	8310040282	50-261 Q	MURLEY, T E	8310270585*	50-220 Q	NARDI, A J	8310260045	70-1143
MORGAN, R E	8310040516	50-261 S	MURLEY, T E	8310270639*	40-672	NARDCCI, P. B	8310040403	50-370 S
MORGAN, R E	8310070136	50-261 S	MURLEY, T E	8310270644*	40-672	NARDCCI, P. B	8310060063*	50-369 S
MORGAN, R E	8310070308	50-261 S	MURLEY, T E	8310270647*	40-672	NARDCCI, P. B	8310060068*	50-369 S
MORGAN, R E	8310070322	50-261 S	MURLEY, T E	8310270652*	40-672	NARDCCI, P. B	8310060255	50-370 S
MORGAN, R E	8310170541	50-261 S	MURLEY, T E	8310310271	State Prog	NARDCCI, P. B	8310060384	50-369 S
MORGAN, R E	8310250596*	50-261 Q	MURPHY, C E	8310120448*	50-316 S	NARDCCI, P. B	8310120413	50-369 S
MORGENSTERN, M	8310130128	MISC	MURPHY, C E	8310210120	50-316 S	NARDCCI, P. B	8310170248	50-369 S
MORGENSTERN, M	8310130134*	MISC	MURPHY, D W	8310070216	REG	NARDCCI, P. B	8310170384	50-369 S
MORLEY, J A	8310130008	WASTE MOT	MURPHY, L Q	8310060507	CONTRACT	NARDCCI, P. B	8310170430	50-369 S
MORLEY, J A	8310130071*	WASTE MOT	MURPHY, L Q	8310070115	CONTRACT	NARDCCI, P. B	8310210005	50-369 S
MORLEY, J A	8310240255	WASTE MOT	MURPHY, L Q	8310070178	CONTRACT	NARDCCI, P. B	8310210077	50-370 S
MORLEY, J A	8310250095	WASTE MOT	MURPHY, L Q	8310110336	CONTRACT	NARDCCI, P. B	8310210308	50-369 S
MORLEY, J A	8310250102	WASTE MOT	MURPHY, L Q	8310270567	CONTRACT	NARDCCI, P. B	8310210309	50-369 S
MORLEY, J A	8310250107*	WASTE MOT	MURPHY, W P	8310040259	50-271 F	NARDCCI, P. B	8310250071	50-369 S
MORLEY, J A	8310310182	WASTE MOT	MURPHY, W P	8310180096	50-271 R	NARDCCI, P. B	8310250076*	50-369 S
MORRILL, P.	8310250355	50-206 S	MURPHY, W P	8310190105*	50-29 P	NARDCCI, P. B	8310250080*	50-369 S
MORRILL, P. J	8310120066	50-275 S	MURPHY, W P	8310190298	71-9089	NARDCCI, P. B	8310270048	50-370 S
MORRILL, P. J	8310210378*	50-275 T	MURPHY, W P	8310310266	50-271 P	NARDCCI, P. B	8310270173	50-369 S
MORRISON, J K	8310240098*	CONTRACT	MURPHY, W P	8310310307	50-271 F	NARDCCI, P. B	8310270209	50-370 S
MORRISON, J. R.	8310240199*	50-328 Q	MURRAY, B	8310060015*	50-267 Q	NARDCCI, P. B	8310270310	50-370 S
MORRONIELLO, A	8310250613*	50-254 Q	MURRAY, B	8310060026*	50-313 Q	NARROW, L	8310190142*	50-443 Q
MORTON, K L	8310190117	50-313 R	MURRAY, B	8310060039*	50-382 Q	NEIGHBOR, J D.	8310110078	50-280 P
MORTON, K V	8310070188*	50-498 A	MURRAY, B	8310060464*	50-382 Q	NEIGHBOR, J D.	8310120003	50-280 P
MORTON, K V	8310070196*	CONTRACT	MURRAY, B	8310180161*	50-298 Q	NEISLER, J H	8310060462*	50-483 Q
MORTON, K V	8310070200*	CONTRACT	MURRAY, J P	8310140055*	50-358 A	NELLIS, C A	8310270537*	50-10 F
MORTON, K V	8310070205*	CONTRACT	MURRAY, J P	8310280197*	50-400 A	NELSON, Q B	8310030213*	XPORTLIC
MORTON, K V	8310070210*	CONTRACT	MURRAY, T D	8310060365	50-346 S	NELSON, Q B	8310180123*	70-734
MORTON, K V	8310070217*	CONTRACT	MURRAY, T D	8310060595*	50-346 F	NELSON, Q. B.	8310310256	70-734
MORTON, K V	8310070220*	CONTRACT	MURRAY, T D	8310110087*	50-346 F	NELSON, M A	8310170007*	50-289 F
MORTON, K V	8310070221*	CONTRACT	MURRAY, T D	8310110131*	50-346 F	NELSON, M A	8310200430*	50-289 F
MORTON, K V	8310070230*	CONTRACT	MURRAY, T D	8310120222	50-346 S	NELSON, R F	8310070323	NJREQ
MORTON, K V	8310070240*	CONTRACT	MURRAY, T D	8310120239	50-346 S	NELSON, R M	8309120437	50-461 E
MORTON, K V	8310070267*	CONTRACT	MURRAY, T D	8310120322	50-346 S	NELSON, R M	8310120359	50-461 E
MORTON, K V	8310070331*	CONTRACT	MURRAY, T D	8310120391	50-346 S	NELSON, R M	8310140228	50-461 E
MORTON, K V	8310070415*	CONTRACT	MURRAY, T D	8310170369	50-346 S	NELSON, R M	8310210009	50-461 A
MORTON, K V	8310110009*	CONTRACT	MURRAY, T D	8310170375	50-346 S	NELSON, R M	8310270569*	50-461 F
MORTON, K V	8310110029*	CONTRACT	MURRAY, T D	8310170498	50-346 S	NELSON, W E	8310110591*	FOIA
MORTON, K V	8310110549*	CONTRACT	MURRAY, T D	8310190020	50-346 R	NERGES, V	8310060534	50-389 P
MORTON, K V	8310110582*	CONTRACT	MURRAY, T D	8310190166	50-346 R	NEUMANN, M. R.	8310200342	40-8697
MORTON, K V	8310110616*	CONTRACT	MURRAY, T D	8310210363*	50-346 F	NEVILLE, J. T.	8310250047	50-352 H
MORTON, K V	8310130165*	CONTRACT	MUSELER, W J.	8310310224*	50-322 Q	NEWMAN, K A	8310110560	FOIA
MORTON, K V	8310130201*	CONTRACT	MUSOLF, D	8312190246*	FOIA	NEWMAN, K A	8310270085	FOIA
MORTON, K V	8310170067*	CONTRACT	MUSOLF, D	8310040572	50-263 P	NEYLEAN, A J.	8310040522	50-358 A
MORTON, K V	8310180105*	CONTRACT	MUSOLF, D	8310050422	PR	NICHOLAS, H. H	8310060046*	50-388 Q
MORTON, K V	8310190281*	CONTRACT	MUSOLF, D	8310060216	50-263 P	NICHOLAS, H. H	8310190203*	50-352 Q
MORTON, K V	8310200462*	CONTRACT	MUSOLF, D	8310070238	50-263 V	NICKEL, H. C.	8310270182*	FOIA
MORTON, K V	8310210093*	CONTRACT	MUSOLF, D	8310070272	50-263 S	NICKEL, H. C.	8310270186*	FOIA
MORTON, K V	8310210097*	CONTRACT	MUSOLF, D	8310070311	50-263 P	NICOLARAS, H	8310070157	50-263 F

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
NICOLARAS, H	8310240149	50-263 P	NORRIS, E B	8310280149*	50-259 P	O'REILLY, J P	8310250508	50-338 Q
NICOLOSI, J	8308300689	I&E	NORRIS, E B	8310280150*	50-259 P	O'REILLY, J P	8310250514	50-369 Q
NICOLOSI, J	8310120304	I&E	NORRIS, E B	8310280151*	50-259 P	O'REILLY, J P	8310250565	50-324 Q
NIGHTINGALE, E	8310050546*	50-358 Q	NORRIS, P Q	8310130077	ORG	O'REILLY, J P	8310250635	50-269 Q
NELSON, R	8310250346	PR	NORRIS, P Q	8310210007	ORG	O'TOOLE, J D	8310040228	50-247 F
NIX, H C	8310030247	50-321 S	NORTH, H B	8310040311*	50-312 Q	O'TOOLE, J D	8310120194	50-247 P
NIX, H C	8310030304	50-321 S	NORTH, H B	8310170678*	50-312 Q	O'TOOLE, J D	8310120242	50-247 P
NIX, H C	8310030318	50-366 S	NORTHSTROM, T E	8310310134*	50-508 A	O'TOOLE, J D	8310120297	50-247 P
NIX, H C	8310030319	50-366 S	NORTON, B	8310110120	50-275 Q	O'TOOLE, J D	8310120366	50-247 P
NIX, H C	8310030336	50-366 S	NORTON, B	8310110120	50-275 Q	O'TOOLE, J D	8310130111	50-3 P
NIX, H C	8310030359	50-366 S	NORTON, B	8310110298	50-275 Q	O'TOOLE, J D	8310130115*	50-3 P
NIX, H C	8310030382	50-366 S	NORTON, B	8310110298	50-275 Q	O'TOOLE, J D	8310170163	50-247 S
NIX, H C	8310030410	50-321 S	NORTON, B	8310110301*	50-275 Q	O'TOOLE, J D	8310260304	50-3 F
NIX, H C	8310030415	50-366 S	NORTON, B	8310110301*	50-275 Q	O'TOOLE, J D	8310280261*	50-3 F
NIX, H C	8310030433	50-366 S	NORWOOD, D W	8310030432	50-259 S	OVERO, C R	8310040137*	50-382 Q
NIX, H C	8310030442	50-366 S	NOVACHEK, F	8310040322*	50-267 S	OVERO, C R	8310040546*	50-498 J
NIX, H C	8310030481	50-321 S	NOVACHEK, F J	8310040207	50-267 S	OVERO, C R	8310120242	50-247 P
NIX, H C	8310030486	50-366 S	NOVACHEK, F J	8310040324*	50-267 S	DEGAARDEN, R H	8310060332	71-6400
NIX, H C	8310030510	50-366 S	NOVACHEK, F J	8310040328*	50-267 S	DEGAARDEN, R H	8310030075	71-6144
NIX, H C	8310040366*	50-321 Q	NOVAK, T M	8310280430*	50-329 A	DEGAARDEN, R H	8310190272	71-5939
NIX, H C	8310040409	50-366 S	NOVAK, T M	8308300352	50-382 A	OLE, K M	8310180138	40-8768
NIX, H C	8310040524	50-321 S	NOVAK, T M	8310110298	50-275 Q	OLLER, R E	8310040249*	GA999
NIX, H C	8310060011	50-366 S	NOVAK, T M	8308300777	50-454 Q	OLLER, R E	8310250526*	GA999
NIX, H C	8310120408	50-366 S	NOVAK, T M	8308300779	50-413 E	OLMSTEAD, W J	8207150081*	50-29 P
NIX, H C	8310140014	50-321 S	NOVAK, T M	8308310032	50-329 A	OLMSTEAD, W J	8310130003	PR
NIX, H C	8310140144	50-321 S	NOVAK, T M	8308310045	50-413 S	OLMSTEAD, W J	8310130042	MISC
NIX, H C	8310140241	50-321 P	NOVAK, T M	8310030604	50-327 P	OLSEN, A F	8310170730	70-824
NIX, H C	8310170183	50-366 P	NOVAK, T M	8310030604	50-327 P	OLSEN, L	8310180400*	GA999
NIX, H C	8310170397	50-321 S	NOVAK, T M	8310040120	50-395 P	OLSHAN, L N	8310110605	50-454 A
NIX, H C	8310170509	50-366 S	NOVAK, T M	8310050076	50-369 P	OLSHAN, L N	8310130049	50-454 A
NIX, H C	8310170531	50-366 S	NOVAK, T M	8310110374	50-424 A	OLSHAN, L N	8310240031	50-454 A
NIX, H C	8310170582	50-321 S	NOVAK, T M	8310110600	50-482 A	OLSON, D L	8310110624	WASTE MOT
NIX, H C	8310170584	50-366 S	NOVAK, T M	8310170031	50-390 A	OLSON, D L	8310280283	WASTE MOT
NIX, H C	8310170743*	50-321 F	NOVAK, T M	8310170048	50-329 A	ONNER, M W	8310030341	PR
NIX, H C	8310170746*	50-321 F	NOVAK, T M	8310170261	50-327 P	OPARKA, E J	8310260026*	FOIA
NIX, H C	8310190014	50-321 R	NOVAK, T M	8310170721	50-329 A	OPREA, Q W	8310040289	50-498 S
NIX, H C	8310230061	50-366 S	NOVAK, T M	8310190199	50-327 P	OPREA, Q W	8310040410	50-498 S
NIX, H C	8310230212	50-366 S	NOVAK, T M	8310210131	50-369 P	OPREA, Q W	8310130187	50-498 S
NIX, H C	8310230285	50-366 S	NOVAK, T M	8310310172	50-400 A	OPREA, Q W	8310130265	50-498 S
NIX, H C	8310250291	50-366 S	NUSSBAUMER, D A	8310260318	WASTE MOT	OPREA, Q W	8310130319	50-498 S
NIX, H C	8310250311	50-366 S	NUSSBAUMER, D A	8310280103	WASTE MOT	OPREA, Q W	8310180290	50-498 S
NIX, H C	8310250312	50-366 S	NYERGES, P L	8310060079	70-143	OPREA, Q W	8310020193	50-498 S
NIX, H C	8310250343	50-366 S	O'CONNOR, J T	8310170308	40-8801	ORDERS, W T	8310040332*	50-324 Q
NIX, H C	8310250506	50-366 S	O'CONNOR, J T	8310200409	40-8801	ORLOSKY, P M	8310140222	50-37 R
NIX, H C	8310310236	50-366 S	O'CONNOR, P W	8310130047	50-546 A	OSBORN, M	8310240199	50-289 H
NIX, H C	8310310259	50-366 S	O'NEILL, J	8309130169	50-153 Q	OSTER, J	8310240071	50-10 J
NIX, H C	8310310260	50-366 S	O'NEILL, J	8310110207	50-153 Q	OVERBECK, Q J	8310010087*	50-272 P
NIX, H C	8310310297	50-321 S	O'NEILL, J	8310170375	50-346 S	OVERBECK, Q J	8306160513*	50-324 P
NIX, H C	8310310363	50-366 S	O'NEILL, J H	8310040538	50-400 Q	OVERBECK, Q J	8306160602*	50-302 P
NOONAN, V B	8303060124*	50-445 A	O'NEILL, J H	8310040538	50-400 Q	OVERBECK, Q J	8307200260*	50-336 P
NOONAN, V B	8309300064*	50-382 A	O'NEILL, J H	8310060188	50-400 Q	OVERBECK, Q J	8307230463*	50-313 P
NORDERHAUG, L R	8310030198	XPORTLIC	O'NEILL, J H	8310060188	50-400 Q	OWCZARSKI, P C	8310050145	REB
NORDERHAUG, L R	8310030213*	XPORTLIC	O'NEILL, J H	8310110150	50-400 Q	OWLEY, Q F	8310140244*	TOPREP
NORDERHAUG, L R	8310040221	50-275 Q	O'NEILL, J H	8310110150	50-400 Q	PADUANO, H N	8310130157*	50-389 Q
NORDERHAUG, L R	8310040397	50-397 Q	O'NEILL, J H	8310110153*	50-400 Q	PAGE, R Q	8310040133	70-2945
NORDERHAUG, L R	8310180120	70-734	O'NEILL, J H	8310110153*	50-400 Q	PAGE, R Q	8310050177	40-8794
NORDERHAUG, L R	8310180123*	70-734	O'NEILL, J H	8310170620*	50-400 Q	PAGE, R Q	8310060343	70-2988
NORDERHAUG, L R	8310180217	70-734	O'NEILL, J H	8310170620*	50-400 Q	PAGE, R Q	8310060348*	70-2988
NORDERHAUG, L R	8310310284	50-206 S	O'NEILL, J H	8310170630*	50-400 Q	PAGE, R Q	8310070034	40-8027
NORELIUS, C.	8310140036	50-10 Q	O'NEILL, J H	8310170630*	50-400 Q	PAGE, R Q	8310070211	40-6500
NORELIUS, C E	8310040352	50-373 Q	O'NEILL, J H	8310270512	FOIA	PAGE, R Q	8310110441	40-6500
NORELIUS, C E	8310120302	50-454 Q	O'NEILL, J H	8310280051	50-400 Q	PAGE, R Q	8310170691	70-143
NORELIUS, C E	8310120326	50-153 Q	O'NEILL, J H	8310280051	50-400 Q	PAGE, R Q	8310180011	70-143
NORELIUS, C E	8310140099	50-10 Q	O'REILLY, J P	8310040174	50-321 Q	PAGE, R Q	8310210099	40-6500
NORELIUS, C E	8310170666	50-456 Q	O'REILLY, J P	8310040263	50-416 Q	PAGE, R Q	8310260048*	FOIA
	50-10 Q		O'REILLY, J P	8310040354	50-261 P	PAGE, R Q	8310270576	40-6740
	50-10 Q		O'REILLY, J P	8310040416	50-395 S	PAGLIARO, J A	8310260280*	FOIA
	50-123 Q		O'REILLY, J P	8310040442	50-327 Q	PAHWA, S B	8310070200*	CONTRACT
	50-123 Q		O'REILLY, J P	8310040446*	50-327 Q	PALLADINO, N	8310110057*	50-275 P
	50-301 Q		O'REILLY, J P	8310040487	50-259 Q	PALLADINO, N J	8310030413	50-289 Q
	50-301 Q		O'REILLY, J P	8310040511	50-369 F	PALLADINO, N J	8310030622*	50-289 P
	50-295 Q		O'REILLY, J P	8310040528	50-416 Q	PALLADINO, N J	8310060591	50-382 U
	50-295 Q		O'REILLY, J P	8310040588	50-424 Q	PALLADINO, N J	8310070041	COMMISSION
	FOIA		O'REILLY, J P	8310040622	70-1151	PALLADINO, N J	8310070363	COMMISSION
	FOIA		O'REILLY, J P	8310040632*	70-1151	PALLADINO, N J	8310070377	COMMISSION
	70-1144		O'REILLY, J P	8310070241	50-324 Q	PALLADINO, N J	8310110093	COMMISSION
	FOIA		O'REILLY, J P	8310070273	50-324 Q	PALLADINO, N J	8310110352	COMMISSION
	50-153 T		O'REILLY, J P	8310210032	50-259 Q	PALLADINO, N J	8310110589	COMMISSION
	50-153 T		O'REILLY, J P	8310210071	50-259 Q	PALLADINO, N J	8310110594*	COMMISSION
	GA999		O'REILLY, J P	8310250336	70-143	PALLADINO, N J	8310110612	COMMISSION
	50-286 Q		O'REILLY, J P	8310250344*	70-143	PALLADINO, N J	8310110617	50-54 U
	50-311 S		O'REILLY, J P	8310250350	50-302 Q	PALLADINO, N J	8310140028	50-320 Q
	50-247 S		O'REILLY, J P	8310250451	50-324 Q	PALLADINO, N J	8310170694	COMMISSION
	50-272 Q		O'REILLY, J P	8310250474	50-324 Q	PALLADINO, N J	8310170701	COMMISSION
	71-505		O'REILLY, J P	8310250488*	50-324 Q	PALLADINO, N J	8310170704	COMMISSION

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PALLADINO, N J	8310180010	COMMISSION	PASTVA, M J	8310120300	50-325 S	PETTENGILL, H J	8310200009	40-299
PALLADINO, N J	8310200038*	50-289 P	PASTVA, M J	8310120426	50-324 S	PETTENGILL, H J	8310200446	40-898
PALLADINO, N J	8310200044*	50-289 P	PASTVA, M J	8310140011	50-325 S	PETTENGILL, H J	8310240094	40-845
PALLADINO, N J	8310200062	50-445 U	PASTVA, M J	8310140053	50-325 S	PETTY, J C	8310170536	50-267
PALLADINO, N J	8310200359*	FOIA	PASTVA, M J	8310170414	50-325 S	FFAFF, S J	8310260348	40-665
PALLADINO, N J	8310200442	50-424 U	PASTVA, M J	8310170596	50-324 S	FFAFF, S J	8310270545	40-665
PALLADINO, N J	8310200449*	COMMISSION	PASTVA, M J	8310170604	50-324 S	PFEFFERLEN, H C	8310070264	50-237
PALMER, R A	8310120188	50-316 S	PASTVA, M J	8310190141	50-325 S	PFEFFERLEN, H C	8310070281	TOPREP
PALMER, R A	8310140084	50-315 S	PASTVA, M J	8310190227	50-325 S	PFEFFERLEN, H C	8310070310	TOPREP
PALMER, R A	8310140140*	50-316 S	PASTVA, M J	8310230237	50-324 S	PHILLIPACPOULO	8310210358*	50-275
PALMER, R A	8310140141*	50-316 S	PASTVA, M J	8310250396	50-324 S	PHILLIP, G A	8310260120*	FOIA
PALMER, R A	8310170611*	50-316 S	PASTVA, M J	8310250521	50-325 S	PHILLIP, G A	8310260142*	FOIA
PALMER, R A	8310210191*	50-315 S	PATON, W D	8310050418	50-329 Q	PHILLIP, G A	8310040164*	FOIA
PALMER, R A	8310210197*	50-315 S	PATTERSON, H	8310130253	71-303	PHILLIP, G A	8310260230*	70-114
PALMER, R A	8310210199*	50-315 S	PATTERSON, J P	8310040198*	50-331 Q	PHILLIPS, H S	8310180455*	QA999
PALMER, R A	8310210202*	50-315 S	PATTERSON, W F	8310050366	50-443 Q	PHILLIPS, H S	8310250136*	QA999
PALMER, R A	8310270226	50-315 S	PATTERSON, W F	8310050373	50-443 Q	PHILLIPS, H S	8310250206*	QA999
PANCIERA, V	8310040222*	50-424 Q	PATTERSON, W F	8310050381*	50-443 Q	PHILLIPS, H S	8310250285*	QA999
PANCIERA, V W	8310250560*	50-321 Q	PATTERSON, W F	8310050388*	50-443 Q	PHILLIPS, H S	8310250447*	QA999
PANBURN, G C	8310050413	WASTE MGT	PATTERSON, W F	8310050398	50-443 Q	PHILLIPS, H S	8310250541*	QA999
PANBURN, G C	8310200349	40-8102	PATTERSON, W F	8310050472	50-443 Q	PHILLIPS, J W	8310050056*	71-908
PANBURN, G C	8310200412	40-8102	PATTERSON, W F	8310050474*	50-443 Q	PHILLIPS, M	8310140267*	50-237
PANBURN, G C	8310240094	40-8452	PATTERSON, W F	8310050477*	50-443 Q	PHILLIPS, M P	8310040198*	50-331
PANKRATZ, D R	8310110311*	FOIA	PATTERSON, W F	8310050480*	50-443 Q	PHILLIPS, M P	8310050485*	50-155
PAOLINO, R	8310200270*	50-289 Q	PATTERSON, W F	8310050551	50-443 Q	PHILLIPS, M P	8310140013*	50-305
PAPAZOGLOU, I A	8310310444	50-302 P	PATTERSON, W F	8310130046	50-443 Q	PHILLIPS, M P	8310140271*	50-254
PAPERIELLO, C J	8310040195	50-331 Q	PATTERSON, W F	8310130255	50-443 Q	PHILLIPS, M P	8310180257*	50-373
PAPERIELLO, C J	8310040359	70-36	PATTERSON, W F	8310250319	50-443 Q	PICHUMANI, R	8310170484*	50-382
PAPERIELLO, C J	8310050539	50-87 Q	PATTISON, R S	8310060502	40-8084	PICKLER, D A	8310260180*	FOIA
PAPERIELLO, C J	8310120202	50-116 Q	PAUL, R A	8310210074*	50-10 Q	PIEHL, R H	8310210204	50-315
PAPERIELLO, C J	8310120241	50-305 F	PAUL, R A	8310270313*	50-266 Q	PIEHL, R H	8310210212*	50-316
PAPERIELLO, C J	8310120269	50-263 F	PAUL, K, Q L	8310250190*	50-259 Q	PIEHL, R H	8310270271*	50-315
PAPERIELLO, C J	8310140002	50-305 Q	PAULSON, W A	8310280141	50-206 P	PIEMONTESE, A P	8310190230	50-387
PAPERIELLO, C J	8310140013*	50-305 Q	PAULSON, W A	8310060195	50-206 P	PIEMONTESE, A P	8310250219	50-387
PAPERIELLO, C J	8310140181	70-36	PAULSON, W A	8310250254	50-206 P	PIEMONTESE, A P	8310250228	50-387
PAPERIELLO, C J	8310140212	70-1308	PAYNE, K	8310250047	50-352 H	PIEMONTESE, A P	8310250345	50-387
PAPERIELLO, C J	8310140262	50-237 Q	PEARSON, S D	8310250680	WASTE MGT	PIEMONTESE, A P	8310250402	50-387
PAPERIELLO, C J	8310140267*	50-237 Q	PEARSON, W R	8310250113	50-133 P	PIEMONTESE, A P	8310250594	50-387
PAPERIELLO, C J	8310140271*	50-234 Q	PECK, S I	8310060079	70-143	PIERINGER, P	8310200047	50-318
PAPERIELLO, C J	8310180230	50-373 Q	PEDRO, J	8310110001	FOIA	PIERINGER, P	8310250221	50-318
PAPERIELLO, C J	8310210053	50-10 Q	PEDRO, J	8310110005	FOIA	PIERINGER, P	8310250443	50-318
PAPERIELLO, C J	8310210061*	50-10 Q	PEDRO, J	8310180582	50-445 A	PIERINGER, P A	8310250287	50-318
PAPERIELLO, C J	8310250391	50-315 F	PEDRO, J	8310190088	FOIA	PILANT, J M	8310040574	50-298
PAPERIELLO, C J	8310270190	50-315 F	PEDRO, J	8310240233	FOIA	PILANT, J M	8310140190	50-298
PAPERIELLO, C J	8310270294	50-266 Q	PEDRO, J	8310270057	FOIA	PILANT, J M	8310200350	50-298
PAPERIELLO, C J	8310270303*	50-266 Q	PEDRO, J	8310270355	FOIA	PINKEL, I I	8310110010*	50-295
PAPERIELLO, C J	8310270435	50-254 Q	PEERY, W W	8310040637*	70-1151	PIRTLE, O L	8310140216*	70-1306
PAPERIELLO, C J	8310270443	50-483 F	PELIZZA, M S	8310210123	40-8786	PIRTLE, O L	8310270315*	50-264
PAPERIELLO, C J	8310310158	50-409 Q	PELKE, P R	8310240137*	50-440 Q	PITTS, R W	8310030028	71-916
PAPERIELLO, C J	8310310285	50-483 Q	PELLETIER, J P	8310250308	50-271 S	PLAIN, H H	8310110022*	50-445
PARAMESWARAN, V	8310180076	NUREG	PELLETIER, J P	8310250334	50-271 S	PLAIN, H H	8310110439*	50-322
PARAMORE, B	8310070436	NUREG	PELLETIER, J P	8310250379	50-271 S	PLAIN, H H	8310260230	50-358
PARIS, O H	8310040184	50-155 Q	PELLETIER, J P	8310250531	50-271 S	PLIM, G	8310250377*	50-295
PARIS, O H	8310250048	50-320 Q	PELLETIER, J P	8310250626	50-271 S	PLISCO, L	8310260270*	50-289
PARIS, O H	8310260224	50-247 Q	PELOQUIN, J	8310070442	NUREG	POSKI, T.	8310140267*	50-237
PARIS, P C	8310050335	NUREG	PENNIFILL, R A	8310050413	WASTE MGT	POSKI, T.	8310180257*	50-373
PARKER, M E	8310170643*	50-341 G	PENZIEN, J	8310070203*	CONTRACT	POSKI, T. J	8310140271*	50-254
PARKS, B	8310030254	50-389 S	PERANICH, M W	8310040453*	QA999	PLUMLEE, O L	8310030350*	50-267
PARKS, B	8310260145*	50-324 P	PERKINS, K E	8310260076*	50-10 S	PLUMLEE, O L	8310040589*	50-267
PARKS, B	8310260148*	50-324 P	PERKINS, K R	8310270075*	FOIA	POHLMAN, D. L	8310110135*	50-361
PARKS, D M	8310250039	50-389 S	PERLIS, R Q	8310050388*	50-443 Q	POINDEXTER, T C	8310180046	50-320
PARKS, B. M	8310250337	50-389 S	PERLIS, R Q	8310050402	50-412 Q	POINDEXTER, T E.	8310190249	71-148
PARKYN, J D	8310050425	PR	PERLIS, R Q	8310050457	50-483 Q	POLK, H E.	8310210398*	50-275
PARSONS, R M	8310030526	50-400 S	PERLIS, R Q	8310050533	50-412 Q	POLK, H E.	8310210391*	50-275
PARSONS, R M	8310040224*	50-400 Q	PERLIS, R Q	8310170419	50-483 Q	POLK, P. J	8003240118*	FOIA
PARSONS, R M	8310040282	50-261 Q	PERLIS, R Q	8310250163	50-483 Q	POLK, P. J.	8310120018*	FOIA
PARSONS, R M	8310040600*	50-400 Q	PERLIS, R Q	8310250297	50-412 Q	POLK, P. J.	8310130041	50-286
PARSONS, R M	8310040603*	50-400 Q	PERLIS, R Q	8310250545	50-498 Q	POMERINER, D. J	8310270398*	TOPREP
PARSONS, R M	8310040606*	50-400 Q	PERLMAN, J	8310050337	CONTRACT	POPPE, L K	8310170192	71-9103
PARSONS, R M	8310060036	50-400 S	PERLMAN, J	8310050379	CONTRACT	POPPE, L K	8310190332	71-5803
PARSONS, R M	8310060336	50-400 S	PERLMAN, J	8310240104	CONTRACT	PORTER, R	8310200154	50-318
PARSONS, R M	8310120246	50-400 S	PERLMAN, J	8310240127	CONTRACT	PORTER, R	8310250249	50-317
PARSONS, R M	8310120367	50-400 S	PERSINKO, D	8310050495*	50-155 T	PORTER, R	8310250410	50-317
PARSONS, R M	8310190171	50-400 S	PERSINKO, D	8310130001	50-155 T	PORTZ, R	8310110036*	50-331
PARSONS, R M	8310250211*	50-400 Q	PEGHEK, C	8310140163	TOPREP	PORTZ, R.	8310110035*	50-331
PASCHALL, A A	8310200448	FOIA	PESHEK, C	8310140174*	TOPREP	PORTZ, R.	8310250669*	50-331
PASTOR, R J	8310180420	50-352 D	PETERS, A	8310310425*	70-2319	POSSEY, W. H.	8310250109	50-358
PASTVA, M J	8310030202	50-324 S	PETERS, M A	8310270267	50-373 S	POSTMA, A. K.	8310270041*	50-320
PASTVA, M J	8310030209	50-324 S	PETERSON, D. A	8310120254	50-255 R	POSTMA, A. K.	8310270044*	50-320
PASTVA, M J	8310030422	50-324 S	PETERSON, W K.	8310190105*	50-29 P	POTAPOV, I	8310030387*	QA999
PASTVA, M J	8310040362	50-324 S	PETRAK, T Q.	8310170388	50-293 S	POTAPOV, U.	8308300705	QA999
PASTVA, M J	8310040412	50-325 S	PETRARCA, D. J	8310210240	50-334 P	POTAPOV, U.	8310030342	QA999
PASTVA, M J	8310040582	50-325 S	PETRIE, E	8310170107*	50-338 S	POTAPOV, U.	8310030379	QA999
PASTVA, M J	8310060237	50-324 S	PETRIE, L	8310060494*	50-335 F	POTAPOV, U.	8310030444	QA999
PASTVA, M J	8310060383	50-324 S	PETTENGILL, H	8310200456	40-6622	POTAPOV, U.	8310030445	QA999

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
POTAPOVS, U	8310030464	QA999	PUCCI, J A	8310240050	50-329 A	REBELLO, J E	8310050420*	CONTRACT
POTAPOVS, U	8310040242	QA999	PUCCI, J A	8310240063	50-329 A	REBELLO, J E	8310050458*	CONTRACT
POTAPOVS, U	8310040343	QA999	PUCCI, J A	8310240084	50-329 A	REBELLO, J E	8310060168*	CONTRACT
POTAPOVS, U	8310040382	QA999	PUCCI, J A	8310240136	50-329 A	REBELLO, J E	8310060290*	CONTRACT
POTAPOVS, U	8310040422	QA999	PUCCI, J A	8310270066	50-329 A	REBELLO, J E	8310060326*	CONTRACT
POTAPOVS, U	8310040433*	QA999	PUGH, C E	8310050217	NUREG	REBELLO, J E	8310060483*	CONTRACT
POTAPOVS, U	8310040485	QA999	PUNT, N A	8310130219	50-289 H	REBELLO, J E	8310060493*	CONTRACT
POTAPOVS, U	8310040576	QA999	PURDY, Q R	8310140024*	50-445 T	REBELLO, J E	8310060496*	CONTRACT
POTAPOVS, U	8310130288	QA999	PURDY, Q R	8310140024*	50-445 T	REBELLO, J E	8310060501*	CONTRACT
POTAPOVS, U	8310140165*	TOPREP	PURPLE, R A	8310240261*	50-250 P	REBELLO, J E	8310060512*	CONTRACT
POTAPOVS, U	8310180142	QA999	PURVIS, F.	8310200203*	50-397 Q	REBELLO, J E	8310070106*	CONTRACT
POTAPOVS, U	8310180154	QA999	QUAMME, D L	8310130219	50-329 A	REBELLO, J E	8310070117*	CONTRACT
POTAPOVS, U	8310180201	QA999	QUAMME, D L	8310270171*	50-329 Q	REBELLO, J E	8310070148*	CONTRACT
POTAPOVS, U	8310180216	QA999	QUAMME, D L	8310310366	50-329 A	REBELLO, J E	8310070181*	CONTRACT
POTAPOVS, U	8310180291	QA999	QUICK, D R	8310250271*	50-416 Q	REBELLO, J E	8310070198*	CONTRACT
POTAPOVS, U	8310180297	QA999	QUICK, D R	8310250333*	50-438 Q	REBELLO, J E	8310070224*	CONTRACT
POTAPOVS, U	8310180312	QA999	QUICK, D R	8310250517*	50-327 Q	REBELLO, J E	8310110271*	CONTRACT
POTAPOVS, U	8310180318*	QA999	QUIRK, J F	8310170340	TOPREP	REBELLO, J E	8310110337*	CONTRACT
POTAPOVS, U	8310180332*	QA999	QUIRK, J F	8310250357	RECON	REBELLO, J E	8310110340*	CONTRACT
POTAPOVS, U	8310180346	QA999	RADELOFF, W A	8310260035*	FOIA	REBELLO, J E	8310270577*	CONTRACT
POTAPOVS, U	8310180360	QA999	RADELOFF, W A	8310260040*	FOIA	REBELLO, J E	8310280137*	CONTRACT
POTAPOVS, U	8310180393	QA999	RADELOFF, W A	8310260044*	FOIA	REBELLOWSKI, T	8310190188*	50-423 Q
POTAPOVS, U	8310180396	QA999	RADELOFF, W A	8310260047*	FOIA	REBELLOWSKI, T A	8310180209*	50-213 Q
POTAPOVS, U	8310180415*	QA999	RADELOFF, W A	8310260051*	FOIA	REBELLOWSKI, T A	8310180447*	50-213 Q
POTAPOVS, U	8310180429	QA999	RADELOFF, W A	8310260055*	FOIA	REED, J G	8310120420	50-483 Q
POTAPOVS, U	8310180433	QA999	RADELOFF, W A	8310260059*	FOIA	REEDY, R F	8310180361*	50-275 T
POTAPOVS, U	8310180441	QA999	RADELOFF, W A	8310260099*	FOIA	REEVES, E A	8310280085	50-348 P
POTAPOVS, U	8310180451	QA999	RAHE, E P	8310050197	PROJ	REGAN, N A	8310170229	70-27
POTAPOVS, U	8310180476	QA999	RAHE, E P	8310060267	PROJ	REGAN, N A	8310170315	70-27
POTAPOVS, U	8310180515	QA999	RAHE, E P	8310140227	TOPREP	REGAN, N A	8310170727	70-27
POTAPOVS, U	8310180526	QA999	RAHE, E P	8310200165	50-247 B	REGAN, N A	8310180561	XPORTLIC
POTAPOVS, U	8310180530*	QA999	RAHE, E P	8310200170	TOPREP	REGAN, N A	8310280333	71-5797
POTAPOVS, U	8310250005	QA999	RAHE, E P	8310200193	TOPREP	REGAN, N A	8310280418	70-27
POTAPOVS, U	8310250010	QA999	RAHE, E P	8310260277	50-445 A	REGAN, N A	8310260166*	70-27
POTAPOVS, U	8310250104	QA999	RAHE, E P	8310280017*	TOPREP	REGISTER, B F	8310270417	40-8599
POTAPOVS, U	8310250123	QA999	RAHE, E P	8310280106	PROJ	REHM, T A	8310060521	COMMIBSIGN
POTAPOVS, U	8310250140	QA999	RAHSDILL, J V	8310310208	NUREG	REHM, T A	8310110107*	50-275 P
POTAPOVS, U	8310250199	QA999	RANDEN, L D	8310030539	40-8786	REHM, T A	8310120467	COMMIBSIGN
POTAPOVS, U	8310250265	QA999	RANGANATH, S	8310180152*	50-352 Q	REHM, T A	8310170361	COMMIBSIGN
POTAPOVS, U	8310250272	QA999	RASKIN, D B	8310120418	50-275 Q	REHM, T A	8310260060	COMMIBSIGN
POTAPOVS, U	8310250357	QA999	RATHBUN, L A	8310310268	NUREG	REID, M J	8310040282	50-261 Q
POTAPOVS, U	8310250362	QA999	RAWSON, R J	8310110632	50-289 Q	REINBACH, H O	8310280224*	50-358 A
POTAPOVS, U	8310250377	QA999	RAWSON, R J	8310130048	50-289 Q	REINBACH, H O	8310280231*	50-358 A
POTAPOVS, U	8310250395	QA999	RAWSON, R J	8310130175	50-289 P	REITER, L	8310130002*	50-155 T
POTAPOVS, U	8310250405	QA999	RAWSON, R J	8310250338	50-289 Q	REITTER, R	8310060263*	50-358 Q
POTAPOVS, U	8310250413	QA999	RAY, H B	8310030102	50-361 R	REITLER, E K	8310170219	70-1151
POTAPOVS, U	8310250432	QA999	RAY, H B	8310070304	50-361 B	REPKA, D A	8310050439	50-322 Q
POTAPOVS, U	8310250497	QA999	RAY, H B	8310120070	50-361 S	REPKA, D A	8310300303	50-322 Q
POTAPOVS, U	8310250503	QA999	RAY, H B	8310120073	50-361 B	REPKA, D A	8310170419	50-483 Q
POTAPOVS, U	8310250511	QA999	RAY, H B	8310120075	50-362 S	REPKA, D A	8310250375	50-322 T
POTAPOVS, U	8310250513*	QA999	RAY, H B	8310120116	50-361 B	REPKA, D A	8310270239	50-322 Q
POTAPOVS, U	8310250532	QA999	RAY, H B	8310120130	50-361 B	REBBLER, W C	8310120125	50-289 R
POTAPOVS, U	8310250537	QA999	RAY, H B	8310120146	50-361 B	REVELEY, W T	8310140016	50-322 Q
POTAPOVS, U	8310250592	QA999	RAY, H B	8310120152	50-361 B	REVELEY, W T	8310140016	50-322 Q
POTAPOVS, U	8310250610*	QA999	RAY, H B	8310120164	50-361 B	REYES, A J	8310120455	XPORTLIC
POTAPOVS, U	8310270050*	TOPREP	RAY, H B	8310120172	50-362 B	REYES, A J	8310130399	XPORTLIC
POTTER, J. P.	8310140142	1&E	RAY, H B	8310120183	50-362 S	REYES, A J	8310130422	XPORTLIC
POULK, R M	8309200175	50-324 S	RAY, H B	8310120184	50-206 B	REYES, L A	8310050502*	50-373 Q
POULK, R M	8310060075	50-324 S	RAY, H B	8310120258	50-206 Q	REYES, L A	8310270140*	50-454 Q
POULK, R M	8310060383	50-324 B	RAY, H B	8310120278	50-206 P	REYNOLDS, A B	8310070106*	CONTRACT
POULK, R M	8310250521	50-325 B	RAY, H B	8310120338	50-362 S	REYNOLDS, J	8310040212*	50-275 Q
PRABHAKARA, M K	8310040381*	50-155 T	RAY, H B	8310120342	50-361 S	REYNOLDS, J	8310040212*	50-275 Q
PRABHAKARA, M K	8310040381*	50-155 T	RAY, H B	8310120347*	50-361 S	REYNOLDS, J	8310050421	50-275 Q
PRASAD, S G	8310110567	FOIA	RAY, H B	8310120351*	50-361 S	REYNOLDS, J	8310050421	50-275 Q
PRATT, A	8310070203*	CONTRACT	RAY, H B	8310140023	50-362 B	REYNOLDS, J	8310110058	50-275 Q
PREISTER, D. J.	8310180163*	50-445 Q	RAY, H B	8310140125	50-362 B	REYNOLDS, J	8310110127	50-275 Q
PREUSS, M	8310120158	50-234 B	RAY, H B	8310140167	50-362 B	REYNOLDS, J	8310110127	50-275 Q
PREVATTE, R. L	8310040613*	50-400 Q	RAY, H B	8310140218	50-362 B	REYNOLDS, J	8310110317	50-275 Q
PREVATTE, R. L	8310250632*	50-400 Q	RAY, H B	8310180486*	50-361 S	REYNOLDS, J	8310110317	50-275 Q
PRICE, E. R.	8310260065*	FOIA	RAY, H B	8310190010	50-206 R	REYNOLDS, J	8310110317	50-275 Q
PRICE, E. R.	8310260072*	FOIA	RAY, H B	8310190092	50-361 R	REYNOLDS, J	8310130243	50-275 Q
PRICE, E. R.	8310260115*	FOIA	RAY, H B	8310270439	50-362 S	REYNOLDS, J	8310130243	50-275 Q
PRICE, E. R.	8310260126*	FOIA	RAY, H B	8310270498	50-361 B	REYNOLDS, J	8310180160	50-275 Q
PRICE, E. R.	8310260129*	FOIA	RAY, J J	8307290223*	FOIA	REYNOLDS, J	8310180160	50-275 Q
PRICE, E. R.	8310260137*	FOIA	RAY, J J	8310310462	ACRB	REYNOLDS, J	8310180248	50-275 Q
PRICE, E. R.	8310260356*	FOIA	RAY, J J	8310310465	ACRB	REYNOLDS, J	8310180248	50-275 Q
PRICE, E. R.	8310260361*	FOIA	RAYMOND, W J	8310140245*	50-271 Q	REYNOLDS, J	8310210242*	50-275 T
PRICE, E. R.	8310270097*	FOIA	RAYNOR, J W	8310200004	50-318 S	REYNOLDS, J	8310210242*	50-275 T
PRICE, E. R.	8310270100*	FOIA	RAYNOR, J W	8310200047	50-318 S	REYNOLDS, J	8310240158	50-275 Q
PRICE, H L	8310270170*	FOIA	RAYNOR, J W	8310250221	50-318 S	REYNOLDS, J	8310240158	50-275 Q
PRICE, J. B.	8310310451	WASTE MGT	REAMER, C W	8310140020	50-482 Q	REYNOLDS, J	8310260277	50-275 Q
PROCTOR, S. D	8310040467	50-329 Q	REAMER, C W	8310170556	50-498 Q	REYNOLDS, J	8310260277	50-275 Q
PROCTOR, S. D	8310250053	50-329 Q	REAVIS, J A	8310180100	50-369 R	REYNOLDS, J. R.	8310210228	50-275 T
PUCCI, J. A.	8310240029	50-329 A	REAVIS, J A	8310180167	50-369 R	REYNOLDS, J. R.	8310210228	50-275 T
PUCCI, J. A.	8310240033	50-329 A	REBELLO, J E	8310030534*	CONTRACT	REYNOLDS, J. R.	8310260236	50-275 Q

PERSONAL AUTHOR INDEX

513

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
REYNOLDS, J R	8310260236	50-275 Q	ROGERS, P	8310040149	50-368 S	RUSSELL, L B	8310250587	50-317 S
REYNOLDS, J R	8310270358	50-275 Q	ROGERS, P	8310040154	50-313 S	RUSSELL, L B	8310250599	50-318 S
REYNOLDS, J R	8310270358	50-275 Q	ROGERS, P	8310040206	50-368 S	RUSSELL, L B	8310280081	50-317 S
REYNOLDS, J R	8310310141	50-275 Q	ROGERS, P	8310040338	50-368 S	RUSSELL, V.	8310260294*	CONTRACT
REYNOLDS, J R	8310310141	50-275 Q	ROGERS, P	8310130283	50-368 S	RUSSELL, W T	8310120058	50-289 P
REYNOLDS, N S	8310060316	50-445 Q	ROGERS, P.	8310180457	50-368 S	RUSSELL, W T	8310130108	50-289 P
REYNOLDS, N S	8310060316	50-445 Q	ROGERS, P	8310180489	50-368 S	RUSSELL, W T	8310130186*	50-289 P
REYNOLDS, N S	8310110322	50-445 Q	ROGERS, P	8310180529	50-368 S	RUSSELL, W T	8310140294	50-289 P
REYNOLDS, N S	8310110322	50-445 Q	ROGERS, P	8310310368	50-368 S	RUSSELL, W T	8310170002	50-289 P
REYNOLDS, N S	8310140022	50-445 T	ROGERS, W H	8310170746*	50-321 F	RUSSELL, W T	8310170012	50-289 Q
REYNOLDS, N S	8310140022	50-445 T	ROLLINS, J D	8310130334	PROJ	RUSSELL, W T	8310170014	50-289 P
REYNOLDS, N S	8310140066	50-508 G	ROMAN, T W	8310140111	50-220 R	RUSSELL, W T	8310170018	50-289 P
REYNOLDS, N S	8310140066	50-508 Q	ROMAN, W D	8310310067*	50-250 P	RUSSELL, W T	8310170032	50-289 P
REYNOLDS, N S	8310140066	50-508 Q	ROMAN, W D	8310310068*	50-250 P	RUSSELL, W T	8310170043	50-289 P
REYNOLDS, N S	8310140086	50-508 G	ROMANO, F R	8310030437	50-352 Q	RUSSELL, W T	8310170717	50-289 P
REYNOLDS, N S	8310170412	50-445 Q	ROMANO, F R	8310180419	50-352 Q	RUTBERG, J	8310250289	50-352 Q
REYNOLDS, N S	8310170412	50-445 Q	ROMANO, F R	8310310336	50-352 Q	RUTLEDGE, C	8310040603	40-B502
REYNOLDS, N S	8310170417*	50-445 Q	ROMANO, F R	8310310353*	50-352 Q	RUTLEDGE, C	8310210102	40-B502
REYNOLDS, N S	8310170417*	50-445 Q	ROMANO, F R	8310310371*	50-352 Q	RUTLEDGE, C.	8310210107*	40-B502
REYNOLDS, N S	8310280126	50-508 Q	ROMNEY, N D	8310070007*	50-329 A	RUTZ, A C	8310110626*	WASTE MGT
REYNOLDS, N S	8310280126	50-508 Q	ROOD, H	8310180173	50-361 P	RYBAK, B	8310040320	50-237 P
REYNOLDS, N S	8310310175	50-508 Q	ROSE, J T	8310310454*	50-322 S	RYBAK, B	8310040471	50-237 P
REYNOLDS, N S	8310310175	50-508 Q	ROSENBERG, E B	8310210097*	CONTRACT	RYBAK, B	8310120189	50-237 P
REYNOLDS, S	8310140170*	50-320 Q	ROSENBLATT, H B.	8310210198*	CONTRACT	RYBAK, B	8310120409	50-245 Q
REYNOLDS, S D	8310190203*	50-352 Q	ROSENTHAL, A S	8310280218*	50-400 A	RYBAK, B	8310170337	50-237 Q
RHEE, S	8310060373	50-237 S	ROSLIE, E	8310040200	50-460 Q	RYBAK, B	8310170545	50-254 P
RICE, D A	8310250327	50-29 S	ROSS, B	8310110512*	CONTRACT	RYBAK, B	8310170553	50-237 S
RICE, D A	8310250421	50-29 S	ROSS, B R	8310110510*	CONTRACT	RYBAK, B	8310260001	50-10 P
RICHARD, D D	8310170619*	50-316 S	ROSS, K C	8310110511*	FOIA	RYBAK, B	8310310054	50-254 P
RICHARD, R	8310070224*	CONTRACT	ROSS, W J	8310250300*	50-327 Q	RYDER, C	8310260031*	FOIA
RICHARDS, B L	8310260114*	70-1151	ROSSBACH, L W	8310120199*	50-286 Q	RYDER, C	8310260037*	FOIA
RICHARDS, D	8310250604*	QA999	ROTELLA, T S	8310030398	50-389 S	RYDER, C.	8310260041*	FOIA
RICHARDS, D	8310250616*	QA999	ROTELLA, T S	8310030448	50-389 S	RYDER, C	8310260049*	FOIA
RICHARDS, S	8310170180*	50-443 Q	ROTH, J	8310120088*	70-1100	RYDER, C	8310260050*	FOIA
RICHARDS, W J	8310250448	FR	ROTH, J J	8310200169*	70-B20	RYDER, C P	8310260054*	FOIA
RICHTER, L	8310060365	50-346 S	ROTHMAN, R L	8310120152*	50-537 Q	RYTKONEN, B D	8310210198*	CONTRACT
RICHTER, B W	8310280122*	50-311 Q	ROTHSCHILD, H U	8310030424	50-445 Q	SABADDS, J W	8310040342*	70-824
RIDENHOUR, R	8310110040	50-382 Q	ROTHSCHILD, H U	8310030430	50-445 Q	SABADDS, J W	8310260194*	70-1113
RIDGWAY, D A	8310110272	50-289 Q	ROTHSCHILD, H U	8310030435	50-445 Q	SAENGER, E L	8310240190	FOIA
RIDGWAY, K R	8310200268*	50-123 Q	ROTHSCHILD, H U	8310030525	50-445 Q	SAENGER, E L	8310260278*	FOIA
RIEGER, E.	8310120026*	50-201 I	ROTHSCHILD, H U	8310130031	50-445 Q	SALE, H J	8310260423	NUREG
RILEY, J L	8310110270	50-413 T	ROTHSCHILD, H U	8310170488	50-445 Q	SALE, H J	8310180622	70-2946
RING, M	8310270140*	50-454 Q	ROTHSCHILD, H U	8310250489	50-445 Q	SAHANTIGU, F J	8310210241*	50-275 T
RITSHER, J A	8310260187	50-443 A	ROWE, D B	8310030458*	CONTRACT	SAHELSON, A	8310120403	50-461 Q
ROBERTS, H W	8310130251*	50-482 Q	ROWE, P	8310110371*	FOIA	SANBORN, J	8310240085*	70-1100
ROBERTS, D C	8310070237*	CONTRACT	ROWBOM, F H	8308310422*	50-313 P	BANDERS, C F	8310250310	70-1151
ROBERTS, T M	8310110002	COMMISSION	ROY, Q W	8310240081*	FOIA	BANDERS, W F	8310040222*	50-424 Q
ROBERTS, T M	8310110006*	COMMISSION	ROY, Q W	8310260108*	FOIA	BANDHOP, J R	8310170283	NUREG
ROBERTS, T M	8310110008*	COMMISSION	ROY, Q W	8310260144*	FOIA	BARBANES, P S	8310170690*	50-320 U
ROBERTS, T M	8310110012*	COMMISSION	ROY, Q W	8310260332*	FOIA	SARGENT, I H	8309020392*	50-277 P
ROBERTS, T M	8310110014*	COMMISSION	ROY, Q W	8310260338*	FOIA	SARSOUR, B	8310190167*	50-346 R
ROCHE, L A	8310250024*	FOIA	ROY, Q W	8310260341*	FOIA	SARSOUR, B	8310190170*	50-346 R
ROCHE-FARNER, L	8310250017*	FOIA	RUBIN, D	8310180246*	50-366 S	SATHER, A	8310170572*	50-329 Q
ROCHE-FARNER, L	8310250019*	FOIA	RUBELSHAUB, H	8310170699*	COMMISSION	SATHER, A	8310310417*	50-329 Q
ROCHE-FARNER, L	8310250025*	FOIA	RUDD, E	8310240241*	50-528 U	SAUNDERS, J H	8310190283	NUREG
RODDIS, L H	8310250093*	50-397 A	RUDY, C R	8310180403	40-6500	SAUNDERS, R.	8310060523*	50-280 F
RODDIS, L H	8310250097*	50-397 A	RUEBHAUSEN, D H	8310120034*	50-201 I	SAUNDERS, R.	8310110240*	50-280 F
RODRIGUEZ, R J	8310030488	50-312 P	RUEBHAUSEN, D H	8310120030*	50-201 I	SAUNDERS, R.	8310190016	50-280 R
RODRIGUEZ, R J	8310040317	50-312 P	RUFF, A B	8310250380*	50-438 Q	SAUNDERS, R.	8310260436*	50-280 F
RODRIGUEZ, R J	8310040419	50-312 R	RUITER, Q H	8310170341	50-305 R	SCALET, D C	8310210342	50-447 A
RODRIGUEZ, R J	8310040547	50-312 P	RULAND, W H	8310040384*	50-348 Q	SCARANO, R A	8310310239	50-27 Q
RODRIGUEZ, R J	8310060021	50-312 F	RUNION, T C.	8310120008*	50-201 I	SCARANO, R A	8310310352	50-139 Q
RODRIGUEZ, R J	8310070275	50-312 S	RUNION, T C	8310180009*	50-201 I	SCHAEFER, D W	8310310284	50-206 S
RODRIGUEZ, R J	8310120087	50-312 P	RUNION, T C	8310120012*	50-201 I	SCHAPKER, J F	8310040340*	50-546 Q
RODRIGUEZ, R J	8310120145	50-312 S	RUNION, T C	8310120013*	50-201 I	SCHAUB, J B.	8310260068	XPORTLIC
RODRIGUEZ, R J	8310120160	50-312 R	RUNION, T C.	8310120014*	50-201 I	SCHAUB, J B	8310260073*	XPORTLIC
RODRIGUEZ, R J	8310120167	50-312 S	RUNION, T C	8310120020*	50-201 I	SCHAUFELBERGER	8310040348	50-298 Q
RODRIGUEZ, R J	8310170216	50-312 R	RUNION, T C	8310120044*	50-201 I	SCHIEB, Q N	8310140200	50-260 S
RODRIGUEZ, R J	8310180094	50-312 Q	RUNION, T C	8310120049*	50-201 I	SCHIEDLIN, E	8310120256	50-358 S
RODRIGUEZ, R J.	8310210038	50-312 P	RUNION, T C	8310120207*	50-201 I	SCHERER, A E	8310070274	50-470 A
RODRIGUEZ, R J	8310270451	50-312 S	RUSHMORE, J W	8310140043	50-220 J	SCHERRER, J B.	8308300317*	50-213 P
RODRIGUEZ, R J	8310270452	50-312 S	RUSHMORE, J W	8310140134	50-220 J	SCHIERLING, H	8310170185	50-275 P
RODRIGUEZ, R J	8310280099	50-312 P	RUSSELL, L B	8310030344*	50-317 F	SCHIERLING, H E	8310210355*	50-275 T
ROEDER, J R	8310260028*	FOIA	RUSSELL, L B	8310110258*	50-317 F	SCHIERLING, H E	8310210357*	50-275 T
ROEDER, J R	8310260111*	FOIA	RUSSELL, L B.	8310200004	50-318 S	SCHIERLING, H E	8310210385*	50-275 T
ROEDER, J R.	8310260140*	FOIA	RUSSELL, L B.	8310200047	50-318 S	SCHIERLING, H E.	8310250182*	50-275 T
ROEDER, J R	8310260162*	FOIA	RUSSELL, L B	8310200147	50-318 S	SCHIERLING, H E	8310250332*	50-275 T
ROEDER, J R.	8310260171*	FOIA	RUSSELL, L B	8310200154	50-318 S	SCHMIDT, Q R.	8310140274*	50-529 S
ROEDER, J R	8310260178*	FOIA	RUSSELL, L B	8310200221	50-318 S	SCHMIDT, H C.	8310040604	50-445 A
ROEDER, J R.	8310260323*	FOIA	RUSSELL, L B	8310200249	50-317 S	SCHMIDT, H C	8310040604	50-445 A
ROESSET, J M	8310200190*	50-275 T	RUSSELL, L B.	8310200287	50-318 S	SCHMIDT, H C	8310110116*	50-445 F
ROGERS, H. A.	8310270035	50-320 P	RUSSELL, L B	8310200369	50-318 S	SCHMIDT, H C	8310110173	50-445 F
ROGERS, H. R.	8310060083	50-327 S	RUSSELL, L B	8310200410	50-317 S	SCHMIDT, H C.	8310200149	50-445 K
ROGERS, H. R.	8310250077	50-327 S	RUSSELL, L B	8310200411	50-318 S	SCHMIDT, H C.	8310270175	50-445 F
ROGERS, J. C.	8310240047*	50-413 T	RUSSELL, L B.	8310200443	50-318 S	SCHMIDT, H C.	8310270185	50-445 F

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SCHMIDT, H C	8310280041	50-445 A	SCHWENGER, A	8310110411	50-410 A	SHAHER, W	8310060264	50-266 S
SCHMITTENDORF, Q	8310190002	50-338 R	SCHWENGER, A	8310110462	50-387 P	SHAHER, W	8310210122	50-316 S
SCHNELL, D F	8310040273*	50-483 Q	SCHWENGER, A	8310120007	50-374 A	SHAHER, W D	8310040250	50-255 Q
SCHNELL, D F	8310040334	FR	SCHWENGER, A	8310120027	50-397 F	SHAHER, W D	8310060150	50-331 Q
SCHNELL, D F	8310120069	50-483 R	SCHWENGER, A	8310120037	50-387 P	SHAHER, W D	8310060360	50-153 Q
SCHNELL, D F	8310210098	50-483 S	SCHWENGER, A	8310130343	50-416 P	SHAHER, W D	8310060372*	50-155 Q
SCHNELL, D F	8310250661*	50-483 F	SCHWENGER, A	8310130411	50-354 A	SHAHER, W D	8310120293	50-315 Q
SCHREPPLE, L D	8310070267*	CONTRACT	SCHWENGER, A	8310170009	50-322 E	SHAHER, W D	8310140173	50-295 Q
SCHROCK, V E	8310070110	NUREQ	SCHWENGER, A	8310170045	50-410 A	SHAHER, W D	8310170476	50-263 Q
SCHROEDER, B A	8310120273	50-237 R	SCHWENGER, A	8310170046	50-387 P	SHAHER, W D	8310240042	50-266 Q
SCHROEDER, C W	8310120433	50-373 P	SCHWENGER, A	8310170048	50-387 P	SHAHER, W D	8310240086	50-282 Q
SCHROEDER, C W	8310130132	50-374 A	SCHWENGER, A	8310170131	50-397 A	SHAHER, W D	8310240093	50-315 Q
SCHROEDER, C W	8310170426	50-374 A	SCHWENGER, A	8310170167	50-416 P	SHAHER, W D	8310260605	50-254 Q
SCHROEDER, C W	8310180249	50-373 K	SCHWENGER, A	8310170664	50-373 F	SHANBAKY, M	8310060349*	50-334 Q
SCHROEDER, C W	8310180281	50-373 P	SCHWENGER, A	8310170716	50-410 A	SHANBAKY, M	8310140236*	50-271 Q
SCHROEDER, C W	8310180377	50-373 P	SCHWENGER, A	8310170745	50-410 A	SHANBAKY, M M	8310060019*	50-244 Q
SCHROEDER, C W	8310180425	50-373 P	SCHWENGER, A	8310180131	50-387 P	SHANBAKY, M M	8310120217*	50-277 Q
SCHROEDER, C W	8310190258	50-373 P	SCHWENGER, A	8310190222	50-416 H	SHANNON, J B	8310260357	40-8064
SCHROEDER, C W	8310210056	50-374 S	SCHWENGER, A	8310200031	50-397 A	SHANNON, Z	8310070117*	CONTRACT
SCHROEDER, L	8310070436	NUREQ	SCHWENGER, A	8310210125	50-354 A	SHAUB, E	8310200092*	50-271 Q
SCHULTZ, W H	8310110115*	40-17	SCHWENGER, A	8310240247	50-416 S	SHAUB, E T	8310190251*	50-334 Q
SCHULTZ, W H	8310260250*	70-1144	SCHWENGER, A	8310240272	50-458 E	SHAUG, J C	8310180076	NUREQ
SCHULTZ, W H	8310260275*	FOIA	SCHWENGER, A	8310240275	50-373 P	SHAUG, J C	8310180085	NUREQ
SCHULTZ, R D	8310140150*	50-461 Q	SCHWENGER, A	8310250684	50-373 P	SHEA, J J	8310270193	50-245 Q
SCHUM, W S	8310130178*	50-482 Q	SCHWENGER, A	8310260014	50-458 A	SHEARIN, R L	8310110409*	50-400 Q
SCHUSTER, M D	8310030151*	50-27 F	SCHWENGER, A	8310260017	50-458 Q	SHEETS, H E	8310250093*	50-397 A
SCHUSTER, M D	8310040226*	50-275 Q	SCHWENGER, A	8310170632*	50-400 Q	SHEETS, H E	8310250097*	50-397 A
SCHUYLER, J O	8310030396	PR	SCHWENGER, A	8310120333*	50-29 P	SHELLEY, W J	8310120310	40-2061
SCHUYLER, J O	8310040141	50-275 F	SCOTT, D J	8310040136*	50-10 F	SHELLEY, W J	8310180392	40-2061
SCHUYLER, J O	8310040570	50-275 P	SCOTT, D J	8310060373	50-237 S	SHELLEY, W J	8310250662	40-2061
SCHUYLER, J O	8310040585*	50-275 P	SCOTT, D J	8310120273	50-237 R	SHEPARD, A M	8310190097	50-29 P
SCHUYLER, J O	8310040591*	50-275 P	SCOTT, D J	8310210127	50-237 S	SHEPARD, A M	8310190105*	50-29 P
SCHUYLER, J O	8310040598*	50-275 P	SCOTT, D J	8310210165	50-249 S	SHEPHERD, R E	8310270462*	50-443 Q
SCHUYLER, J O	8310070236	50-275 F	SCOTT, D J	8310210297	50-237 S	SHEPHERD, R E	8310270474*	50-443 Q
SCHUYLER, J O	8310120362	50-275 S	SCOTT, D J	8310210313	50-237 S	SHEPPARD, J J	8310040363	TOPREP
SCHUYLER, J O	8310120402	50-275 F	SCOTT, D J	8310270017*	50-10 F	SHEPPARD, J J	8310040363	TOPREP
SCHUYLER, J O	8310120404	50-275 E	SCOTT, D J	8310270424	50-249 S	SHEPPARD, J J	8310110142	TOPREP
SCHUYLER, J O	8310140121	50-275 P	SCOTT, D J	8310270477	50-249 S	SHEPPARD, J J	8310110142	TOPREP
SCHUYLER, J O	8310170285	50-275 P	SCOTT, L H	8310130136	50-302 Q	SHERMAN, C	8310200176	50-224 S
SCHUYLER, J O	8310170471	50-323 A	SCOTT, R J	8310190020	50-346 R	SHERMAN, C I	8310040399*	50-18 Q
SCHUYLER, J O	8310170489	50-275 P	SCOTT, R J	8310040226*	50-275 Q	SHERMAN, C I	8310310241*	50-27 Q
SCHUYLER, J O	8310170514	50-275 E	SCOTT, R J	8310180367*	50-344 Q	SHERMAN, C I	8310310357*	50-139 Q
SCHUYLER, J O	8310170517	50-275 E	SCOTT, R J	8310170432*	50-397 Q	SHERMAN, M P	8310190283	NUREQ
SCHUYLER, J O	8310170565	50-275 F	SCOTT, R J	8310110339	ORQ	SHERR, T S	8310060558	70-1426
SCHUYLER, J O	8310170657	50-275 E	SCOTT, R J	8310110341	ORQ	SHERR, T S	8310060562	50-266 F
SCHUYLER, J O	8310180458	50-275 P	SCOTT, R J	8310110343	ORQ	SHERR, T S	8310180048	70-1462
SCHUYLER, J O	8310180463	50-275 E	SCOTT, R J	8310110346	ORQ	SHERR, T S	8310180052	50-266 F
SCHUYLER, J O	8310190063	50-275 E	SCOTT, R J	8310110348	ORQ	SHERR, T S	8310210158	50-186 F
SCHUYLER, J O	8310190137	50-275 E	SCOTT, R J	8310110349	ORQ	SHERWOOD, Q G	8310040026	50-219 P
SCHUYLER, J O	8310190197	50-275 P	SCOTT, R J	8310030349	50-454 H	SHERWOOD, Q G	8310260106	50-447 K
SCHUYLER, J O	8310200131	50-275 E	SEAR, C A	8310050420*	CONTRACT	SHERWOOD, Q G	8310260206	50-447 K
SCHUYLER, J O	8310200144	50-275 F	SEAR, C A	8310030428	50-245 P	SHERWOOD, R E	8310140052*	50-498 Q
SCHUYLER, J O	8310200183*	50-275 Q	SEAR, C F	8310030428	50-245 P	SHEH, L C	8310110032	NUREQ
SCHUYLER, J O	8310200206	50-275 P	SEAR, J R	8310250384*	50-322 T	SHELDON, S W	8310030283	PR
SCHUYLER, J O	8310210227	50-275 P	SEIDLE, W C	8310040567	50-285 Q	SHELDON, S W	8310040428	50-546 A
SCHUYLER, J O	8310210233	50-275 R	SEIDLE, W C	8310060020	50-313 Q	SHELDON, S W	8310060337	50-546 S
SCHUYLER, J O	8310210247	50-275 P	SEIDLE, W C	8310130168	50-285 Q	SHELDON, S W	8310170330	50-547 S
SCHUYLER, J O	8310210284	50-275 R	SEIDLE, W C	8310130172	50-482 Q	SHELDON, S W	8310210025	50-546 S
SCHUYLER, J O	8310250115	50-275 R	SEIDLE, W C	8310130220	50-313 Q	SHELDON, S W	8310240081*	50-546 Q
SCHUYLER, J O	8310270572*	50-275 F	SEIDLE, W C	8310130241	50-482 Q	SHELDON, S W	8310270395	50-546 S
SCHUYLER, J O	8310270575*	50-275 F	SEIDLE, W C	8310130257	50-482 Q	SHELDON, S W	8310270458	50-546 S
SCHUYLER, J O	8310270580*	50-275 F	SEIDLE, W C	8310130292	50-285 Q	SHIFFER, J D	8310070158	50-275 S
SCHUYLER, J O	8310270586*	50-275 F	SEIDLE, W C	8310130306	50-285 F	SHIFFER, J D	8310120136	50-275 S
SCHUYLER, J O	8310270588*	50-275 F	SEIDLE, W C	8310130330	50-313 Q	SHIFFER, J D	8310120280	50-275 S
SCHUYLER, J O	8310280048*	50-275 Q	SEIDLE, W C	8310180242	50-285 Q	SHIFFER, J D	8310250108	50-275 S
SCHUYLER, J O	8310280061	50-275 F	SELLS, D E	8310070182	50-335 P	SHIFFER, J D	8310250539	50-275 S
SCHUYLER, J O	8310280067*	50-275 Q	SELLS, D E	8310130377	50-335 P	SHIFFER, J D	8310250639	50-275 S
SCHWARTZ, A J	8310140039	50-153 Q	SELLS, D E	8310270531	50-335 S	SHIFFER, J D	8310270376	50-275 S
SCHWEIBINZ, E	8310120287	50-358 H	SERBU, R J	8310050419*	50-413 T	SHIMA, S	8310180191	XPORTRIC
SCHWEIBINZ, E R	8310050530*	50-358 Q	SERINI, B L	8310040137*	70-2945	SHIMA, S	8310180155*	XPORTRIC
SCHWENGER, A	8310030081	50-416 P	SERINI, D L	8310060553*	70-2988	SHINDHARA, K	8310060187	XPORTRIC
SCHWENGER, A	8310030085*	50-416 P	SEWELL, H M	8310060103*	CONTRACT	SHIRAKAWA, T	8310060180	XPORTRIC
SCHWENGER, A	8310030104*	50-416 P	SEYFRIT, K V	8301180513*	50-321 S	SHIRAKAWA, T	8310180304	XPORTRIC
SCHWENGER, A	8310030590	50-322 A	SEYFRIT, K V	8302020202*	50-333 S	SHIRAKAWA, T	8310180307	XPORTRIC
SCHWENGER, A	8310040105	50-374 A	SEYFRIT, K V	8302180539*	50-259 S	SHIRAKAWA, T	8310140080*	50-302 P
SCHWENGER, A	8310040110	50-352 F	SEYFRIT, K V	8303030103*	50-387 S	SHOENAKER, C J	8310030496	50-322 Q
SCHWENGER, A	8310050067	50-416 P	SEYFRIT, K V	8303240341*	50-324 S	SHOENAKER, C J	8310110043	50-358 Q
SCHWENGER, A	8310050073	50-416 P	SEYFRIT, K V	8303240364*	50-277 S	SHOENAKER, C J	8310110047	50-289 Q
SCHWENGER, A	8310050085	50-461 A	SEYFRIT, K V	8304010008*	50-271 S	SHOENAKER, C J	8310110212	50-352 Q
SCHWENGER, A	8310050087	50-410 A	SEYFRIT, K V	8304170106*	50-206 Q	SHOENAKER, C J	8310110225	50-289 Q
SCHWENGER, A	8310050125	50-387 P	SEYFRIT, K V	8306170442*	50-206 Q	SHOENAKER, C J	8310110320	50-329 Q
SCHWENGER, A	8310050131	50-410 A	SEYFRIT, K V	8306230142*	50-206 Q	SHOENAKER, C J	8310120385	50-275 Q
SCHWENGER, A	8310060032	50-416 P	SEYFRIT, K V	8310110051*	50-382 Q	SHOENAKER, C J	8310130167	50-445 Q
SCHWENGER, A	8310060037*	50-416 P	SHACKLETON, Q C	8310200232*	50-206 Q	SHOENAKER, C J	8310130197	50-491 Q
SCHWENGER, A	8310060057	50-416 P	SHAFER, P W	8310130311*	50-409 F	SHOENAKER, C J	8310180333	50-508 Q

PERSONAL AUTHOR INDEX

515

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SHOEMAKER, C J	8310210177	50-553 0	SILBERBERG, M	8310170347*	FOIA	SMITH, J L	8310190003	50-322 A
SHOEMAKER, C J	8310240180	50-483 0	SILBERBERG, M	8310170352*	FOIA	SMITH, J V	8310040355*	50-317 P
SHOEMAKER, C J	8310260256	50-289 0	SILBERBERG, M	8310170358*	FOIA	SMITH, L S	8310170198*	50-423 A
SHOEMAKER, C J	8310260270	50-273 0	SILBERBERG, M	8310170362*	FOIA	SMITH, M A	8310030559	40-8786 Q
SHOEMAKER, C J	8310280070	50-445 0	SILBERBERG, M	8310170370*	FOIA	SMITH, M E	8310110291	50-332
SHOEMAKER, C J	8310280118	50-322 0	SILBERBERG, M	8310170374*	FOIA	SMITH, P	8310070230*	CONTRACT
SHOEMAKER, C J	8310310181	50-273 0	SILBERBERG, M	8310170379*	FOIA	SMITH, P A	8310050362*	CONTRACT
SHOEMAKER, C J	8310310431	50-329 0	SILBERBERG, M	8310170386*	FOIA	SMITH, P A	8310050387*	CONTRACT
SHOLLY, S C	8310110468	FOIA	SILBERBERG, M	8310170391*	FOIA	SMITH, P A	8310050459	CONTRACT
SHOLLY, S C	8310110581	FOIA	SILBERBERG, M	8310170392*	FOIA	SMITH, P A	8310050460*	CONTRACT
SHOLLY, S C	8310170020	FOIA	SILBERBERG, M	8310170396*	FOIA	SMITH, P A	8310070432*	CONTRACT
SHOLLY, S C	8310190059	FOIA	SILBERBERG, M	8310170402*	FOIA	SMITH, P A	8310110414*	FOIA
SHOLLY, S C	8310190306	FOIA	SILBERBERG, M	8310170406*	FOIA	SMITH, P A	8310110419*	FOIA
SHOLLY, S C	8310240192	FOIA	SILBERBERG, M	8310170410*	FOIA	SMITH, P A	8310110422*	FOIA
SHOLLY, S C	8310310096	FOIA	SILBERBERG, M	8310170413*	FOIA	SMITH, P A	8310260296*	CONTRACT
SHON, F J	8310040184	50-155 0	SILBERBERG, M	8310170415*	FOIA	SMITH, P J	8310280323	40-2259
SHON, F J	8310250048	50-320 0	SILBERBERG, M	8310170418*	FOIA	SMITH, R D	8310200371	40-7869
SHON, F J	8310260224	50-247 0	SILBERBERG, M	8310170422*	FOIA	SMITH, R D	8310200419	40-8452
SHOPENN, N M	8310310380*	40-8084	SILBERBERG, M	8310170429*	FOIA	SMITH, R D	8310200438	40-8584
SHOTWELL, J A	8310040272*	50-443 0	SILBERBERG, M	8310170431*	FOIA	SMITH, R D	8310200470	40-8674
SHOTWELL, J A	8310110192	50-443 0	SILBERBERG, M	8310170434*	FOIA	SMITH, R D	8310200471	40-6622
SHOTWELL, J A	8310120147	50-443 0	SILBERBERG, M	8310170438*	FOIA	SMITH, R D	8310240090	40-8681
SHOTWELL, J A	8310120151*	50-443 0	SILBERBERG, M	8310170444*	FOIA	SMITH, R D	8310110419*	40-8102
SHOTWELL, J A	8310180368	50-443 0	SILBERBERG, M	8310170445*	FOIA	SMITH, R D	8310270141	40-8781
SHOTWELL, J A	8310180379*	50-443 0	SILBERBERG, M	8310170450*	FOIA	SMITH, R D	8310270519	40-8698
SHREVE, D B	8310110089*	CONTRACT	SILBERBERG, M	8310170452*	FOIA	SMITH, R H	8310270194*	50-29 0
SHROPSHIRE, J C	8310240073*	50-413 T	SILBERG, J E	8310170461*	FOIA	SMITH, W Q	8310060369	50-315 8
SIEBER, J D	8310240146	50-334 F	SILBERG, J E	8310270330	50-440 0	SMITH, W Q	8310120188	50-316 8
SIEGEL, A I	8310190243	NUREQ	SILBERT, E J	8310270330	50-440 0	SMITH, W Q	8310120193	50-316 8
SIFFORD, W L	8310240076*	50-413 T	SILVERMAN, F S	8310030534*	CONTRACT	SMITH, W Q	8310120197	50-316 8
SILBERBERG, M	8310170037*	FOIA	SILVIS, R M	8310290038	50-272 0	SMITH, W Q	8310120234	50-316 8
SILBERBERG, M	8310170044*	FOIA	SILVIS, R M	8310180554	CONTRACT	SMITH, W Q	8310120260	50-315 8
SILBERBERG, M	8310170047*	FOIA	SILVIS, R M	8310180581	CONTRACT	SMITH, W Q	8310120343	50-315 8
SILBERBERG, M	8310170050*	FOIA	SIMAN-TOV, M	8310050329	RES	SMITH, W Q	8310120379	50-316 8
SILBERBERG, M	8310170055*	FOIA	SIMON, J A	8310170572*	50-329 0	SMITH, W Q	8310120443	50-316 8
SILBERBERG, M	8310170057*	FOIA	SIMON, J A	8310310417*	50-329 0	SMITH, W Q	8310140029	50-315 8
SILBERBERG, M	8310170059*	FOIA	SIMONEN, A K	8310070317	NUREQ	SMITH, W Q	8310140084	50-315 8
SILBERBERG, M	8310170062*	FOIA	SIMPSON, A F	8310110620*	50-54 U	SMITH, W Q	8310140137	50-316 8
SILBERBERG, M	8310170066*	FOIA	SIMPSON, E C	8310120191	50-302 P	SMITH, W Q	8310170337	50-315 8
SILBERBERG, M	8310170072*	FOIA	SIMPSON, E C	8310120387	50-302 P	SMITH, W Q	8310170387	50-315 8
SILBERBERG, M	8310170090*	FOIA	SIMPSON, E C	8310140123	50-302 S	SMITH, W Q	8310170607	50-316 8
SILBERBERG, M	8310170094*	FOIA	SIMPSON, E C	8310140233	50-302 S	SMITH, W Q	8310190064	50-316 8
SILBERBERG, M	8310170102*	FOIA	SIMPSON, E C	8310180436	50-302 P	SMITH, W Q	8310190070	50-315 8
SILBERBERG, M	8310170110*	FOIA	SIMPSON, R D	8310180566	FOIA	SMITH, W Q	8310210036	50-315 P
SILBERBERG, M	8310170116*	FOIA	SINCLAIR, J B	8310050166	50-29 P	SMITH, W Q	8310210040	50-315 8
SILBERBERG, M	8310170120*	FOIA	SINCLAIR, J B	8310120312	50-271 P	SMITH, W Q	8310210115	50-315 8
SILBERBERG, M	8310170123*	FOIA	SINCLAIR, J B	8310210310	50-271 P	SMITH, W Q	8310210120	50-316 8
SILBERBERG, M	8310170128*	FOIA	SINDERMAN, R W	8310040367*	50-155 T	SMITH, W Q	8310210137	50-315 8
SILBERBERG, M	8310170130*	FOIA	SINDERMAN, R W	8310040557*	50-155 T	SMITH, W Q	8310210187	50-315 8
SILBERBERG, M	8310170136*	FOIA	SINDERMAN, R W	8310040568*	50-155 T	SMITH, W Q	8310210206	50-316 8
SILBERBERG, M	8310170140*	FOIA	SINDERMAN, R W	8310050489*	50-155 0	SMITH, W Q	8310270172	50-316 8
SILBERBERG, M	8310170144*	FOIA	SINGER, B	8310260226*	FOIA	SMITH, W Q	8310270204	50-315 8
SILBERBERG, M	8310170150*	FOIA	SINGH, A	8310050415*	50-413 T	SMITH, W Q	8310270226	50-315 8
SILBERBERG, M	8310170161*	FOIA	SINGH, M H	8310170067*	CONTRACT	SMYTH, C W	8310210037	50-289 R
SILBERBERG, M	8310170164*	FOIA	SINISI, J M	8310240026	50-29 J	SNIDER, R	8102260210*	FOIA
SILBERBERG, M	8310170166*	FOIA	SINISI, J M	8310240148	50-29 J	SNIDER, R. P.	8011050238*	FOIA
SILBERBERG, M	8310170169*	FOIA	SINISI, J M	8310270461	50-245 J	SNIDER, R. P.	8011190749*	FOIA
SILBERBERG, M	8310170171*	FOIA	SINK, J M	8310110499*	CONTRACT	SNIDER, C S	8310230056	50-443 Q
SILBERBERG, M	8310170176*	FOIA	SINKIN, L	8310260249	50-498 0	SNELL, W.	8310140267*	50-237 G
SILBERBERG, M	8310170180*	FOIA	SINKIN, L	8310260249	50-498 0	SNELL, W. Q	8310140013*	50-305 G
SILBERBERG, M	8310170237*	FOIA	SINKIN, L	8310260269	50-498 0	SNIEZEK, J H	8310110111*	50-275 P
SILBERBERG, M	8310170242*	FOIA	SINKIN, L	8310260269	50-498 0	SNOW, B A	8310190032	50-244 R
SILBERBERG, M	8310170247*	FOIA	SKEEN, J.	8310110597*	COMMISSION	SNYDER, B J	8310240256	50-320 P
SILBERBERG, M	8310170252*	FOIA	SKIBA, E. L	8310310449	NUREQ	SOLDAT, K L	8310260381	NUREQ
SILBERBERG, M	8310170259*	FOIA	SKINNER, P H	8310250560*	50-321 G	SOLINT, J A	8310250412	50-333 8
SILBERBERG, M	8310170265*	FOIA	SKOGLUND, J	8310170107*	50-338 8	SOLLEY, B W	8310210224	50-259 8
SILBERBERG, M	8310170269*	FOIA	SKOV, D D	8310060176	70-249 F	SOLON, L R	8310070271	State Prog
SILBERBERG, M	8310170275*	FOIA	SLAWINSKI, W J	8310120288*	70-372	SOMERVILLE, K O	8310260414	40-8783
SILBERBERG, M	8310170280*	FOIA	SLOAN, K W.	8310210211*	CONTRACT	SOD, P	8310070411	NUREQ
SILBERBERG, M	8310170284*	FOIA	SLOWINSKI, W J.	8310110147*	FOIA	SODNO, A L	8310030181*	40-8794
SILBERBERG, M	8310170288*	FOIA	SMITH, A L	8310250136*	0A999	SODNO, A L	8310170693*	70-143
SILBERBERG, M	8310170296*	FOIA	SMITH, B. H.	8310040360*	70-36	SODNO, Q	8310120335	50-397 F
SILBERBERG, M	8310170300*	FOIA	SMITH, G. C.	8310250529*	50-272 G	SODNO, Q. C	8309300239	50-460 F
SILBERBERG, M	8310170303*	FOIA	SMITH, G. C.	8310270178*	70-371	SODNO, Q. C	8310030303	50-460 A
SILBERBERG, M	8310170305*	FOIA	SMITH, H. L.	8310140138*	50-316 S	SODNO, Q. C	8310030339	50-508 A
SILBERBERG, M	8310170309*	FOIA	SMITH, I. W.	8310040188	50-289 0	SODNO, Q. C	8310030357	50-397 A
SILBERBERG, M	8310170314*	FOIA	SMITH, I. W.	8310050488	50-454 0	SODNO, Q. C	8310030361	50-397 F
SILBERBERG, M	8310170319*	FOIA	SMITH, I. W.	8310140026	50-289 0	SODNO, Q. C	8310030366	PR
SILBERBERG, M	8310170323*	FOIA	SMITH, J. C	8308300607	40-6622	SODNO, Q. C	8310040440	50-397 A
SILBERBERG, M	8310170326*	FOIA	SMITH, J. C	8310030224	40-6622	SODNO, Q. C	8310070277	50-397 W
SILBERBERG, M	8310170328*	FOIA	SMITH, J. E.	8310030394	PR	SODNO, Q. C	8310070342	50-397 A
SILBERBERG, M	8310170332*	FOIA	SMITH, J. E.	8310110080*	50-269 F	SODNO, Q. C	8310110276	50-397 F
SILBERBERG, M	8310170336*	FOIA	SMITH, J. E.	8310110141*	50-269 F	SODNO, Q. C	8310110332	50-397 A
SILBERBERG, M	8310170340*	FOIA	SMITH, J. L.	8310120264	50-322 E	SODNO, Q. C	8310120359	50-397 A
SILBERBERG, M	8310170343*	FOIA	SMITH, J. L.	8310140231	50-322 E	SODNO, Q. C	8310120155	50-397 F

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SORENSEN, O C	8310120261	50-397 A	STAROSTECKI, R	8310200163	70-820	STOHR, J P	8310050327	70-143
SORENSEN, O C	8310120267	50-397 A	STAROSTECKI, R	8310201085	50-309 Q	STOHR, J P	8310070139	70-143
SORENSEN, O C	8310140176	50-508 A	STAROSTECKI, R	8310210207	50-317 Q	STOHR, J P	8310070256	70-143
SORENSEN, O C	8310170212	50-397 E	STAROSTECKI, R	8310210214	50-244 Q	STOHR, J P	8310110164	70-143
SORENSEN, O C	8310170233	50-397 E	STAROSTECKI, R	8310210269	50-277 Q	STOHR, J P	8310110181	70-143
SORENSEN, O C	8310170298	50-397 E	STAROSTECKI, R	8310240110	50-225 Q	STOHR, J P	8310170239	70-27
SORENSEN, O C	8310170313	50-397 A	STAROSTECKI, R	8310270155	50-219 Q	STOHR, J P	8310250547	70-1113
SORENSEN, O C	8310170446	50-397 F	STAROSTECKI, R	8310270291	50-134 Q	STOHR, J P	8310260097	70-143
SORENSEN, O C	8310170495	50-397 A	STAROSTECKI, R	8310270323	50-412 Q	STOHR, J P	8310260104	70-1151
SORENSEN, O C	8310180367	50-397 E	STAROSTECKI, R	8310270445	50-443 Q	STOHR, J P	8310260154	70-27
SORENSEN, O C	8310180449	50-397 A	STAROSTECKI, R	8310310161	50-320 Q	STOHR, J P	8310260190	70-1113
SORENSEN, O C	8310180503	50-397 F	STAROSTECKI, R	8310310222	50-322 Q	STOHR, J P	8310260215	70-1113
SORENSEN, O C	8310190152	50-508 A	STAROSTECKI, R	8310310227	50-317 Q	STOHR, J P	8310260297	70-1113
SORENSEN, O C	8310210168	50-397 A	STAROSTECKI, R	8310310282	70-1100 Q	STOLZ, J F	8310030418	50-289 F
SORENSEN, O C	8310210224	50-460 A	STAROSTECKI, R	8310310338	50-410 Q	STOLZ, J F	8310030598	50-346 F
SORENSEN, O C	8310210305	50-397 A	STEELE, H L	8310170001	50-289 P	STOLZ, J F	8310030611	50-312 P
SORENSEN, O C	8310240150	50-397 A	STEFANO, J	8310200395	50-440 A	STOLZ, J F	8310040111	50-269 P
SORENSEN, O C	8310260113	50-397 A	STEFANO, J	8310200397*	50-440 A	STOLZ, J F	8310040647	50-269 P
SORENSEN, O C	8310260169	50-508 F	STEFANO, J J	8310200404*	50-440 A	STOLZ, J F	8310040648	50-346 P
SORENSEN, O C	8310310149	50-508 A	STELLO, V	8304200046*	50-253 P	STOLZ, J F	8310040650	50-289 P
SORENSEN, O C	8310190154*	50-508 A	STELLO, V	8310140095*	50-498 Q	STOLZ, J F	8310050004	50-277 F
SORENSEN, O C	8310170743*	50-321 F	STELLO, V	8310240244	REVIEW GRP	STOLZ, J F	8310050049	50-313 P
SOUTH, D L	8310070414	NJREG	STELLO, V	8310270436	REVIEW GRP	STOLZ, J F	8310050051	50-277 Q
SPECTER, B M	8310270094*	50-244 F	STEPHENS, T R	8310120343	50-315 S	STOLZ, J F	8310050060	50-302 F
SPEER, H J	8310190010	50-206 R	STEPHENS, T R	8310120449*	50-316 S	STOLZ, J F	8310050119	50-312 F
SPESSARD, R L	8310060330	50-305 Q	STEPHENS, V M	8310070100*	50-275 R	STOLZ, J F	8310050297	50-302 P
SPESSARD, R L	8310120253	50-254 P	STEPHENS, V M	8310070212*	50-275 R	STOLZ, J F	8310060320	50-313 F
SPESSARD, R L	8310120305	50-341 Q	STEPHENS, V M	8310070257*	50-275 R	STOLZ, J F	8310110442	50-321 P
SPESSARD, R L	8310270422	50-440 Q	STEPHENSON, C J	8310190161	50-289 S	STOLZ, J F	8310110454	50-277 P
SPESSARD, R L	8310270423*	50-440 Q	STEPHENSON, C J	8310250589	50-289 S	STOLZ, J F	8310110471	50-312 P
SPESSARD, R L	8310310397	50-409 Q	STEPTOE, P P	8310190048	50-329 Q	STOLZ, J F	8310110472	50-313 P
SPESSARD, R L	8310310400*	50-409 Q	STEPTOE, P P	8310190048	50-329 Q	STOLZ, J F	8310110474	50-312 P
SRENIANSKI, D J	8310110147*	FDIA	STEPTOE, P P	8310200234	50-329 Q	STOLZ, J F	8310110844*	50-346 P
SRENIANSKI, D J	8310120279	70-572	STEPTOE, P P	8310200254	50-329 Q	STOLZ, J F	8310110845	50-269 P
SRENIANSKI, D J	8310120283*	70-572	STEVENS, A R	8310180157*	CONTRACT	STOLZ, J F	8310110861*	50-269 P
SRENIANSKI, D J	8310120288*	70-572	STEVENS, D	8310310204	WASTE MGT	STOLZ, J F	8310130382	50-346 P
ST LAURENT, N	8310280018	50-29 B	STEVENS, D L	8310070317	NJREG	STOLZ, J F	8310130421	50-302 P
ST LAURENT, N N	8310250232	50-29 B	STEVENS, J L	8310200108	50-309 S	STOLZ, J F	8310170100*	50-313 P
ST LAURENT, N N	8310250277	50-29 B	STEWART, C C	8310310418*	70-2430	STOLZ, J F	8310170307*	50-289 P
ST LAURENT, N N	8310250327	50-29 S	STEWART, D	8310190318	FDIA	STOLZ, J F	8310180367	50-346 P
ST LAURENT, N N	8310250418	50-29 S	STEWART, J M	8310140207*	50-369 P	STOLZ, J F	8310180611	50-313 P
ST LAURENT, N N	8310250421	50-29 S	STEWART, J P	8310200214*	50-204 Q	STOLZ, J F	8310200016	50-277 F
ST LAURENT, N N	8310250523	50-29 S	STEWART, R C	8310180219*	50-445 Q	STOLZ, J F	8310200041	50-346 P
ST LAURENT, N N	8310280015	50-29 S	STEWART, W L	8310030300	PR	STOLZ, J F	8310200050	50-346 P
ST MARY, F A	8310170217*	FDIA	STEWART, W L	8310040450	50-280 Q	STOLZ, J F	8310200054	50-313 P
STALBERG, D	8310310130*	50-416 Q	STEWART, W L	8310040550	50-338 Q	STOLZ, J F	8310200064	50-302 P
STANGE, B J	8310050334*	50-289 F	STEWART, W L	8310040587	50-338 P	STOLZ, J F	8310201119*	50-302 P
STANGE, B J	8310060332*	50-289 F	STEWART, W L	8310060523*	50-280 F	STOLZ, J F	8310210143	50-302 P
STANGE, B J	8310060551*	50-289 F	STEWART, W L	8310060577*	50-280 F	STOLZ, J F	8310260339*	50-289 P
STANGE, B J	8310200443*	50-320 F	STEWART, W L	8310070418*	50-280 F	STOLZ, J F	8310280143	50-289 P
STANGE, B J	8310210390*	50-289 F	STEWART, W L	8310110137	50-280 P	STOLZ, J F	8310310439	50-321 P
STANGE, B J	8310270123*	50-289 F	STEWART, W L	8310120114	50-338 P	STOLZ, J F	8310310476	50-289 P
STANGE, B J	8310270376*	50-289 F	STEWART, W L	8310120140	50-338 P	STONE, I Z	8310120415*	50-261 P
STARK, R H	8310030405	50-537 A	STEWART, W L	8310130103	50-338 P	STONE, I Z	8310120422*	50-261 P
STARK, R H	8310130159	50-537 A	STEWART, W L	8310130145	50-338 P	STONE, J	8310110191	50-329 Q
STARK, B J	8310040930	GEN TEC 18	STEWART, W L	8310140094	50-280 P	STORHANT, J C	8310070414	NJREG
STARKEY, R J	8310040283*	50-261 Q	STEWART, W L	8310170091	50-338 S	STOUT, D M	8310260373	40-8829
STARKEY, R J	8310040473	50-261 Q	STEWART, W L	8310180277	50-338 F	STOUT, R B	8310140824*	TOPREF
STARKEY, R J	8310230608*	50-261 Q	STEWART, W L	8310180301	50-280 F	STRASNA, J	8310060428	50-10 S
STAROSTECKI, P	8310140240	50-271 Q	STEWART, W L	8310180309	50-338 P	STREETER, J F	8310030389*	50-440 Q
STAROSTECKI, R	8310040389	50-410 Q	STEWART, W L	8310180440	50-338 P	STREETER, J F	8310030493	50-373 Q
STAROSTECKI, R	8310070321	50-293 Q	STEWART, W L	8310190002	50-338 R	STREETER, J F	8310030498*	50-373 Q
STAROSTECKI, R	8310120062	70-1100	STEWART, W L	8310190016	50-280 R	STREETER, J F	8310140147	50-461 Q
STAROSTECKI, R	8310120070	50-220 Q	STEWART, W L	8310190043	50-280 P	STREETER, J F	8310140148*	50-461 Q
STAROSTECKI, R	8310120198	50-266 Q	STEWART, W L	8310190112	50-338 P	STREETER, J F	8310140213	50-373 Q
STAROSTECKI, R	8310140132	50-320 Q	STEWART, W L	8310200101	50-280 P	STREETER, J F	8310250356	50-373 Q
STAROSTECKI, R	8310140162	50-289 Q	STEWART, W L	8310200289	50-338 P	STREETER, J F	8310270128	50-454 Q
STAROSTECKI, R	8310140171	50-334 P	STEWART, W L	8310230066	50-339 S	STREETER, J F	8310270134*	50-454 Q
STAROSTECKI, R	8310140272	50-309 P	STEWART, W L	8310230456	50-280 Q	STREETER, J F	8310270438	50-305 Q
STAROSTECKI, R	8310140276	50-272 Q	STEWART, W L	8310260432*	50-280 F	STREIT, R L	8310110032	NJREG
STAROSTECKI, R	8310170163	50-309 Q	STEWART, W L	8310270300	50-280 P	STRETARS, D A	8310250607	50-312 R
STAROSTECKI, R	8310180204	50-213 Q	STOCKMAN, H W	8310050223	NJREG	STROENIG, J	8310070317	NJREG
STAROSTECKI, R	8310180316	50-334 Q	STODDART, P Q	8310250409*	50-335 Q	STRUMHABER, M	8310040288	50-275 Q
STAROSTECKI, R	8310180377	50-199 Q	STOHR, J P	8309200181	70-27	STRUMHABER, M	8310110053	50-275 Q
STAROSTECKI, R	8310180382	50-5 Q	STOHR, J P	8310040143	70-1151	STRUMHABER, M	8310200195*	50-275 T
STAROSTECKI, R	8310180391	50-272 Q	STOHR, J P	8310040190	70-143	STRUMHABER, M	8310260277	50-275 Q
STAROSTECKI, R	8310180439	50-213 Q	STOHR, J P	8310040312*	70-143	STRUMHABER, M	8310270338	50-275 Q
STAROSTECKI, R	8310190128	50-410 Q	STOHR, J P	8310040337	70-824	STRUMHABER, M	8310270348*	50-275 Q
STAROSTECKI, R	8310190139	50-309 Q	STOHR, J P	8310040346	70-143	STUART, K J	8310250625*	50-312 P
STAROSTECKI, R	8310190157	50-333 Q	STOHR, J P	8310040464	70-27	STUCKEY, S Q	8310170295	71-9126
STAROSTECKI, R	8310190176	50-352 Q	STOHR, J P	8310040486*	70-27	STUMBLER, A	8310120042*	50-201 I
STAROSTECKI, R	8310200007	50-334 Q	STOHR, J P	8310040489	70-27	SUBRAMONIAN, N	8308030016*	50-293 Q
STAROSTECKI, R	8310200099	50-317 Q	STOHR, J P	8310040503	70-27	SULLIVAN, J W	8310180602*	FDIA
STAROSTECKI, R	8310200162	50-277 Q	STOHR, J P	8310050471	70-143	SULLIVAN, J W	8310180595	FDIA
						SUMMERS, R J	8310140279*	50-272 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJ CATE
SUD-ANTTILA, A	8310050253	NUREG	THOMAS, H	8310040563*	50-390 G	TOOLE, R. J	8310170007*	50-28
SUTTON, J. W	8310180378*	QA999	THOMASON, P. V	8310060374	50-298 S	TOOLE, R. J	8310200008	50-28
SVENSSON, B. A	8310190070	50-315 R	THOMASON, P. V	8310190024	50-298 R	TOOLE, R. J	8310200011	50-28
SWAIN, A. D	8310200388	NUREG	THOMASON, P. V	8310210174	50-298 S	TOOLE, R. J	8310200430*	50-28
SWANSIGER, T. G	8310270038	TOPREP	THOMPSON, D	8310260287*	70-1144	TOOLE, R. J	8310250352	50-28
SWANSON, D. G	8310050224	NUREG	THOMPSON, H. L.	8310070146	PR	TOURIGNY, E. G	8310130061	50-28
SWANSON, E. R	8310240100*	50-315 G	THOMPSON, H. L.	8310110354	50-289 P	TOWNSEND, B	8310030524	CONTR
SWARTZ, E. D	8310120219	50-456 E	THOMPSON, J. C	8310190034*	50-329 A	TOWNSEND, B	8310210337	CONTR
SWARTZ, E. D	8310170411	50-454 S	THOMPSON, R. H	8310120301	50-302 S	TOWNSEND, B	8310280133	CONTR
SWARTZ, E. D	8310170573	50-454 S	THOMPSON, T	8310140236*	50-271 G	TOWNSEND, B. L	8310050456	CONTR
SWARTZ, E. D	8310180252	50-456 C	THOMSEN, F. T	8310030390	50-522 G	TOWNSEND, B. L	8310060318	CONTR
SWARTZ, E. D	8310270188	50-456 S	THOMSEN, F. T	8310030390	50-522 G	TOWNSEND, B. L	8310060471	CONTR
SWEENEY, N. R	8310070043*	COMMISSION	THOMUS, L	8310140170*	50-320 Q	TOWNSEND, B. L	8310210099	CONTR
SWETLAND, P	8310180467	50-318 S	THORGERSON, J. G	8310210317	50-305 S	TOWNSEND, B. L	8310070195	CONTR
SWETLAND, P	8310190159*	50-309 G	THORNBERRY, R. C	8310190051	50-275 R	TOWNSEND, B. L	8310110262	CONTR
SWIGER, M. A	8310050520	50-440 G	THORNTON, P	8310240132*	50-155 G	TOWNSEND, B. L.	8310110338	CONTR
SWIGER, M. A	8310050520	50-440 G	THORNTON, P	8310240132*	50-155 G	TOWNSEND, O	8310120036*	50-20
SYDNOR, R	8310250249	50-317 S	THORNTON, P	8310310139	50-155 G	TOWNSEND, O	831020037*	50-20
SYLVESTER, E. D	8310050521*	50-312 Q	THORNTON, P	8310310139	50-155 G	TRAMM, T. R.	8310040354	50-45
SZCZECZ, R. A	8310190164	50-289 S	THORPE, J. R	8310030396	PR	TRAMM, T. R.	8310120427	50-45
SZCZECZ, R. A	8310200061	50-289 S	THULL, T. S	8310180336	50-245 S	TRAMM, T. R.	8310210234	50-45
SZCZECZ, R. A	8310250253	50-289 S	THULL, T. S	8310250263	50-245 S	TRAVIESO-DIAZ	8310030401	50-31
SZCZECZ, R. A	8310250606	50-289 S	TIETZ, G	8310110327*	50-254 F	TRAVIESO-DIAZ	8310030401	50-31
SZUKIEWICZ, A	8310250200*	FOIA	TIETZ, G	8310270028*	50-254 F	TRAVIS, W. H	8310170175*	71-35
SZUKIEWICZ, A. J	8308240121*	FOIA	TILLMAN, A	8310170246*	70-27	TRAVIS, W. H	8310190335	71-35
TADA, H	8310050335	NUREG	TIPPS, S. B	8310030247	50-321 S	TREBY, S. A.	8310050433	50-44
TALBOT, R	8310050545*	CONTRACT	TIPPS, S. B	8310030304	50-321 S	TREBY, S. A.	8310180163*	50-44
TALBOT, R	8310060129*	CONTRACT	TIPPS, S. B	8310030318	50-366 S	TRENT, N	8310250067*	50-35
TALBOT, R	8310060506*	CONTRACT	TIPPS, S. B	8310030319	50-366 S	TREPPA, D. C	8310310184*	50-27
TALBOT, R	8310120035*	CONTRACT	TIPPS, S. B	8310030336	50-366 S	TRIMBLE, D	8310180467	50-31
TALBOT, R	8310130201*	CONTRACT	TIPPS, S. B	8310030339	50-366 S	TRIMBLE, D	8310190159*	50-30
TAM, P. S	8310130188	50-334 P	TIPPS, S. B	8310030382	50-366 S	TRIMBLE, D	8310310230*	50-31
TANBLING, T. N	8310200268*	50-123 Q	TIPPS, S. B	8310030410	50-321 S	TRIMBLE, D. C	8310200107*	50-31
TAPIO, J. I	8310170683	50-445 T	TIPPS, S. B	8310030415	50-366 S	TRIOLO, B.	8308030382*	50-31
TARNUZZER, E. C	8310310061*	50-271 P	TIPPS, S. B	8310030433	50-366 S	TRIOLO, B.	8309160203*	50-28
TAUBER, H	8310130018	50-341 E	TIPPS, S. B	8310030442	50-366 S	TRIPP, L	8310060040	50-33
TAUBER, H	8310130229	50-341 A	TIPPS, S. B	8310030481	50-321 S	TRIPP, L. E	8310130395	50-33
TAUBER, H	8310180470	50-341 A	TIPPS, S. B	8310030486	50-366 S	TRIPP, L. E	8310140068	50-27
TAYLOR, G. J	8310190028	50-395 R	TIPPS, S. B	8310030510	50-366 S	TRIPP, L. E	8310180121	50-41
TAYLOR, H. S	8310040349*	QA999	TIPPS, S. B.	8310040409	50-366 S	TRIPP, L. E	8310200010*	50-33
TAYLOR, J	8310310130*	50-416 Q	TIPPS, S. B	8310040524	50-321 S	TRIPP, L. E	8310200021*	50-33
TAYLOR, J. H	8310140145*	50-269 P	TIPPS, S. B	8310060011	50-366 S	TRIPP, L. E	8310210278*	50-27
TAYLOR, J. M	8310040390	50-346 Q	TIPPS, S. B	8310120408	50-366 S	TRIPP, L. E	8310310361	50-27
TAYLOR, J. M	8310120057	50-289 P	TIPPS, S. B	8310140014	50-321 S	TROSKOSKI, W. H	8310200010*	50-33
TAYLOR, J. M	8310180505*	50-275 P	TIPPS, S. B	8310140144	50-321 S	TROSKOSKI, W. H	8310200021*	50-33
TAYLOR, J. M	8310180511*	50-275 P	TIPPS, S. B	8310170397	50-321 S	TRUDUP, Q. L.	8310250352*	70-14
TAYLOR, J. M	8310200244*	50-454 Q	TIPPS, S. B	8310170509	50-366 S	TROWBRIDGE, Q. F	8310110272	50-28
TAYLOR, J. M	8310200455*	50-424 U	TIPPS, S. B	8310170531	50-366 S	TROWBRIDGE, Q. F	8310110272	50-28
TAYLOR, P. A	8310040190*	50-413 G	TIPPS, S. B	8310170582	50-321 S	TROWBRIDGE, Q. F	8310210148	50-28
TAYLOR, P. A	8310250230*	50-413 G	TIPPS, S. B	8310170584	50-366 S	TROWBRIDGE, Q. F	8310210148	50-28
TAYLOR, R. Q	8310040240*	50-445 Q	TIPPS, S. B	8310250212	50-366 S	TROWBRIDGE, Q. F	8310210200	50-32
TAYLOR, R. Q	8310170683	50-445 T	TIPPS, S. B	8310250285	50-366 S	TROWBRIDGE, Q. F	8310210200	50-32
TAYLOR, R. Q	8310170688*	50-445 T	TIPPS, S. B	8310250291	50-366 S	TROWBRIDGE, Q. F	8310240166	50-28
TEMUS, C. J	8310170344	71-9182	TIPPS, S. B	8310250311	50-366 S	TROWBRIDGE, Q. F	8310240166	50-28
TEMUS, C. J	8310200408	71-9184	TIPPS, S. B	8310250312	50-366 S	TROWBRIDGE, Q. F	8310240184	50-28
TENZER, B. E	8310070285	MISC	TIPPS, S. B.	8310250343	50-366 S	TROWBRIDGE, Q. F	8310240184	50-28
TERAO, D	8310050558*	50-247 P	TIPPS, S. B	8310250506	50-366 S	TROWBRIDGE, Q. F	8310240184	50-28
THADANI, M. C	8310270535	50-331 P	TIPPS, S. B	8310310236	50-366 S	TRUDUP, L.	8310180468	RECOD
THAMM, E. G.	8310110414*	FOIA	TIPPS, S. B	8310310259	50-366 S	TSAL, S. E.	8310140042*	50-31
THEOFANOUS, T. G	8310190329*	FOIA	TIPPS, S. B	8310310280	50-366 S	TSAL, S. E.	8310140046*	50-31
THOM, T	8310190186	50-259 R	TIPPS, S. B	8310310297	50-321 S	TUCKER, H. B.	8310030396	PR
THOMAS, A. W	8310180559	FOIA	TIPPS, S. B	8310310363	50-366 S	TUCKER, H. B.	8310030423	50-28
THOMAS, B. L	8310140133	50-254 Q	TIPPS, S. B	8310170522*	50-261 Q	TUCKER, H. B.	8310040016	50-41
THOMAS, B. T.	8310130406*	CONTRACT	TIPPS, S. B	8310070259*	70-143 Q	TUCKER, H. B.	8310040287	50-41
THOMAS, C. D	8310050028	50-83 F	TIPPS, S. B	8310210070*	50-324 G	TUCKER, H. B.	8310040319*	50-41
THOMAS, C. D.	8310050044	50-199 P	TODD, A. J	8310260242*	50-344 P	TUCKER, H. B.	8310040368	50-36
THOMAS, C. D.	8310050047*	50-199 P	TODD, P.	8310270419	50-265 S	TUCKER, H. B.	8310040403	50-37
THOMAS, C. D.	8310050400	TOPREP	TOKAR, H.	8305240300*	50-282 S	TUCKER, H. B.	8310040474	50-36
THOMAS, C. D.	8310070104	TOPREP	TOLFF, M. L.	8310130267*	50-400 E	TUCKER, H. B.	8310040492*	50-26
THOMAS, C. D.	8310110426	50-406 Q	TOLFF, M. L.	8310130271*	50-400 E	TUCKER, H. B.	8310040575	50-26
THOMAS, C. D.	8310170204	50-470 E	TOLFF, M. L.	8310130277*	50-400 E	TUCKER, H. B.	8310040599	50-41
THOMAS, C. D.	8310170728	50-116 P	TOLL, J. B.	8310040258	50-164 F	TUCKER, H. B.	8310060038	50-41
THOMAS, C. D.	8310170731	50-116 P	TOLL, J. B.	8310140118	50-164 F	TUCKER, H. B.	8310060052	50-41
THOMAS, C. D.	8310170734	50-123 P	TOLLESON, J. L	8310270359*	50-263 S	TUCKER, H. B.	8310060098	50-36
THOMAS, C. D.	8310180560	TOPREP	TOLSON, R. G.	8310140024*	50-445 T	TUCKER, H. B.	8310060255	50-37
THOMAS, C. D.	8310210088	50-27 F	TOLSON, R. G.	8310210196*	50-445 Q	TUCKER, H. B.	8310060268*	50-36
THOMAS, C. D.	8310210124	50-2 P	TOME, A. E.	8310040611*	50-155 T	TUCKER, H. B.	8310060384	50-36
THOMAS, C. D.	8310210132*	50-2 P	TOME, A. E.	8310040611*	50-155 T	TUCKER, H. B.	8310060426	50-26
THOMAS, C. D.	8310210138	50-166 V	TOMLINSON, D. P	8310040611*	50-498 Q	TUCKER, H. B.	8310070131*	50-37
THOMAS, C. D.	8310210162	50-83 F	TOMLINSON, D. P	8310060024	50-155 P	TUCKER, H. B.	8310070143*	50-26
THOMAS, C. D.	8310240147	50-166 F	TOMLINSON, D. P	8310060024	50-155 P	TUCKER, H. B.	8310110076*	50-26
THOMAS, C. D.	8310270232	50-37 P	TOMLINSON, D. P	8310060047	50-255 P	TUCKER, H. B.	8310110141*	50-26
THOMAS, C. D.	8310270243*	50-37 P	TOMLINSON, D. P	8310070177	50-255 P	TUCKER, H. B.	8310110141*	50-26
THOMAS, C. D.	8310140070*	50-454 Q	TOMLINSON, D. P	8310120309	50-249 S	TUCKER, H. B.	8310110141*	50-26
THOMAS, D. C	8310140070*	50-454 Q	TOMLINSON, D. P	8310170151*	40-86	TUCKER, H. B.	8310120413	50-36
THOMAS, D. C	8310140070*	50-454 Q	TOMLINSON, D. P	8310070263	50-289 S	TUCKER, H. B.	8310140143	50-26

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
TUCKER, H B	8310140159	50-269 S	UPRIGHT, C M	8310040043*	50-261 Q	VANDODRN, P K	8310240018*	50-413 T
TUCKER, H B	8310140205	50-369 P	UPRIGHT, C M	8310040203*	50-324 Q	VANDODRN, P K	8310240038*	50-413 T
TUCKER, H B	8310140253	50-269 P	UPRIGHT, C M	8310040244*	50-438 Q	VANDONI, M G	8310110174	MUREG
TUCKER, H B	8310170248	50-369 S	UPRIGHT, C M	8310040335*	50-413 Q	VARANE, L S	8310200203*	50-397 Q
TUCKER, H B	8310170384	50-369 S	UPRIGHT, C M	8310040345*	50-413 Q	VARELA, A A	8310060048*	50-244 Q
TUCKER, H B	8310170430	50-369 S	UPRIGHT, C M	8310250406*	50-390 Q	VARGA, S A	8310030603	50-348 P
TUCKER, H B	8310170536	50-269 S	UPRIGHT, C M	8310250449*	50-250 Q	VARGA, S A	8310030613	50-348 P
TUCKER, H B	8310180100	50-369 R	UPRIGHT, C M	8310040424*	50-327 Q	VARGA, S A	8310030659	50-250 P
TUCKER, H B	8310180167	50-269 R	URBANCK, T	8310250381*	50-322 T	VARGA, S A	8310030663	50-286 P
TUCKER, H B	8310180444	50-269 F	USI, V	8310110234*	50-317 F	VARGA, S A	8310040035	50-286 P
TUCKER, H B	8310190165	50-413 E	USI, V	8310130313*	50-317 F	VARGA, S A	8310040051	50-305 Q
TUCKER, H B	8310190195	50-413 E	USI, V	8310170005*	50-317 F	VARGA, S A	8310040060*	50-305 Q
TUCKER, H B	8310190262	50-413 E	UTLEY, E E	8310030161	50-261 P	VARGA, S A	8310040068	50-305 P
TUCKER, H B	8310210005	50-369 S	UTLEY, E E	8310070246*	50-324 Q	VARGA, S A	8310050017	50-348 P
TUCKER, H B	8310210028	50-369 S	UTLEY, E E	8310120266	50-400 F	VARGA, S A	8310050102	50-315 P
TUCKER, H B	8310210077	50-370 S	UTLEY, E E	8310120407	50-261 P	VARGA, S A	8310050148	50-247 P
TUCKER, H B	8310210111	50-413 S	UTLEY, E E	8310160427	50-324 F	VARGA, S A	8310060935	50-364 P
TUCKER, H B	8310210179	50-413 A	UTLEY, E E	8310200143	50-324 Q	VARGA, S A	8310060946	50-315 P
TUCKER, H B	8310210308	50-369 S	VACCA, P	8310170142*	FOIA	VARGA, S A	8310060947	50-261 P
TUCKER, H B	8310210309	50-369 S	VACCA, P	8310170256*	FOIA	VARGA, S A	8310060957	50-272 P
TUCKER, H B	8310240131	50-269 P	VACCA, P	8310170345*	FOIA	VARGA, S A	8310070049	50-364 Q
TUCKER, H B	8310250071	50-369 S	VACCA, P C	7908060318*	FOIA	VARGA, S A	8310070054*	50-364 Q
TUCKER, H B	8310250074	50-369 S	VACCA, P C	7908270319*	FOIA	VARGA, S A	8310070097	50-272 P
TUCKER, H B	8310250524*	50-369 Q	VACCA, P C	7911300172*	FOIA	VARGA, S A	8310070406	50-261 P
TUCKER, H B	8310250665*	50-269 Q	VACCA, P C	8001040244*	FOIA	VARGA, S A	8310070408	50-315 P
TUCKER, H B	8310270048	50-370 S	VACCA, P C	8004230428*	FOIA	VARGA, S A	8310110081*	50-280 P
TUCKER, H B	8310270079	50-269 Q	VACCA, P C	8006170100*	FOIA	VARGA, S A	8310110334*	50-315 P
TUCKER, H B	8310270136*	50-369 F	VACCA, P C	8006300467*	FOIA	VARGA, S A	8310110454	50-295 Q
TUCKER, H B	8310270173	50-369 S	VACCA, P C	8007170062*	FOIA	VARGA, S A	8310110460	50-247 P
TUCKER, H B	8310270209	50-370 S	VACCA, P C	8007170067*	FOIA	VARGA, S A	8310110465	50-286 Q
TUCKER, H B	8310270310	50-370 S	VACCA, P C	8010070320*	FOIA	VARGA, S A	8310130025	50-315 Q
TUCKER, H B	8310270412	50-269 S	VACCA, P C	8310170224*	FOIA	VARGA, S A	8310130191*	50-334 P
TUCKER, H B	8310270482	50-413 S	VACCA, P C	8310170241*	FOIA	VARGA, S A	8310130217	50-315 P
TUCKER, H B	8310280029	50-269 F	VACCA, P C	8310170350*	FOIA	VARGA, S A	8310130222*	50-315 P
TUCKER, H B	8310280096	50-413 E	VACCA, P C	8310170399*	FOIA	VARGA, S A	8310130415	50-295 P
TUCKER, H B	8310280105	50-269 P	VACCA, P C	8310170425*	FOIA	VARGA, S A	8310130416*	50-295 P
TUCKER, H B	8310280124	50-269 F	VACCA, P C	8310170487*	FOIA	VARGA, S A	8310130439*	50-272 P
TUCKER, H B	8310310416	50-369 F	VACCA, P C	8310170546*	FOIA	VARGA, S A	8310170042	50-295 P
TURK, S E	8310130130	50-537 Q	VACCA, P C	8310170635*	FOIA	VARGA, S A	8310170200	50-286 P
TURK, S E	8310130156*	50-537 Q	VADEN, J	8310280107*	WASTE NOT	VARGA, S A	8310180579	50-247 P
TURK, S E	8310170478	50-382 Q	VALERO, B	8310250368*	QA999	VARGA, S A	8310180589*	50-305 P
TUSZKA, M E	8310070133	50-312 P	VAN BRUNT, E E	8310030425	50-328 E	VARGA, S A	8310240258	50-250 P
TUTTEROW, R E	8310040426*	QA999	VAN BRUNT, E E	8310040375	50-328 F	VARGA, S A	8310270153*	50-250 P
TUTTEROW, R E	8310040437*	QA999	VAN BRUNT, E E	8310070006	50-328 S	VARGA, S A	8310270602	50-247 P
TYKULSKER, D	8310210307	FOIA	VAN BRUNT, E E	8310070147	50-328 S	VARGA, S A	8310280072*	50-348 P
TYLER, S W	8310110347	MUREG	VAN BRUNT, E E	8310070284	50-328 S	VARGA, S A	8310280140	50-334 F
UDALL, M K	8310200073*	50-445 U	VAN BRUNT, E E	8310070337	50-329 S	VASSALLO, D B	8310060573	50-263 F
UDALL, M K	8310240217*	50-328 U	VAN BRUNT, E E	8310070352	50-328 S	VASSALLO, D B	8310060574	50-220 P
UDELL, R A	8306140403*	FOIA	VAN BRUNT, E E	8310130126	50-328 A	VASSALLO, D B	8310060581	50-220 P
UDERITZ, R A	8310090159	50-272 P	VAN BRUNT, E E	8310140012	50-328 S	VASSALLO, D B	8310060583	50-259 P
UEBBING, R	8310120222	50-344 S	VAN BRUNT, E E	8310140238	50-328 S	VASSALLO, D B	8310060586	50-263 P
UHL, W O	8310240168	50-322 Q	VAN BRUNT, E E	8310140259	50-328 S	VASSALLO, D B	8310070045	50-293 P
UHRIG, R E	8310040145	50-250 F	VAN BRUNT, E E	8310140265	50-329 S	VASSALLO, D B	8310070061	50-259 P
UHRIG, R E	8310040334	PR	VAN BRUNT, E E	8310210252	50-328 A	VASSALLO, D B	8310070063	50-259 P
UHRIG, R E	8310070250	50-389 F	VAN BRUNT, E E	8310250099	50-328 S	VASSALLO, D B	8310070068	50-259 P
UHRIG, R E	8310070253*	50-389 F	VAN BRUNT, E E	8310250146	50-328 A	VASSALLO, D B	8310070084	50-330 P
UHRIG, R E	8310110138	50-250 Q	VAN BRUNT, E E	8310250415	50-328 S	VASSALLO, D B	8310070114	50-220 Q
UHRIG, R E	8310110296	50-250 P	VAN BRUNT, E E	8310250568	50-328 S	VASSALLO, D B	8310070123*	50-220 Q
UHRIG, R E	8310130009	50-335 P	VAN BRUNT, E E	8310260156	50-328 A	VASSALLO, D B	8310070391	50-298 F
UHRIG, R E	8310130125	50-250 P	VAN BRUNT, E E	8310270409	50-530 S	VASSALLO, D B	8310070395	50-259 P
UHRIG, R E	8310130153	50-389 Q	VAN BRUNT, E E	8310270413	50-529 S	VASSALLO, D B	8310070399	50-259 P
UHRIG, R E	8310140217	50-389 S	VAN BRUNT, E E	8310270430	50-528 S	VASSALLO, D B	8310110536*	50-259 P
UHRIG, R E	8310170222	50-335 F	VAN BRUNT, E E	8310270460	50-529 S	VASSALLO, D B	8310130106	50-298 P
UHRIG, R E	8310170240	50-250 F	VAN BRUNT, E E	8310310138	50-528 S	VASSALLO, D B	8310170119	50-331 P
UHRIG, R E	8310180381	50-250 Q	VAN BRUNT, E E	8310310316	50-528 S	VASSALLO, D B	8310180569	50-298 P
UHRIG, R E	8310250431*	50-250 Q	VAN BRUNT, E E	8310310372	50-528 A	VASSALLO, D B	8310240139	50-259 F
UHRIG, R E	8310250437*	50-250 Q	VAN COTT, H	8310070436	MUREG	VASSALLO, D B	8310240144*	50-324 P
ULLRICH, W T	8310310064*	50-278 P	VAN HOY, G	8310140088*	50-498 Q	VASSALLO, D B	8310240152*	50-263 P
UMBEL, D	8310070193	CONTRACT	VAN VLIEET, J	8310170304	50-289 P	VASSALLO, D B	8310240154	50-259 P
UMBEL, D	8310070428	CONTRACT	VAN VLIEET, J	8310260334	50-289 P	VASSALLO, D B	8310240243	50-259 P
UMBEL, D	8310110003	CONTRACT	VANBRUNT, E E	8310250079	50-528 S	VASSALLO, D B	8310310117	50-331 P
UMBEL, D	8310130162	CONTRACT	VANDEBURGH, C	8310270140*	50-454 Q	VASSALLO, D B	8310310137	50-324 P
UMBEL, D	8310280074	CONTRACT	VANDEWALLE, D	8310260118	50-155 F	VAUGHAN, C H	8310130225	70-1113
UMBEL, D M	8310050336	CONTRACT	VANDEWALLE, D J	8310050463	50-255 P	VAUGHAN, C H	8310170061	70-1113
UMBEL, D M	8310070226	CONTRACT	VANDEWALLE, D J	8310050465*	50-255 P	VAUGHAN, C H	8310170155	70-1113
UMBEL, D M	8310070434	CONTRACT	VANDEWALLE, D J	8310060080	50-155 P	VAUGHAN, C H	8310170249	70-1113
UMBEL, D M	8310110026	CONTRACT	VANDEWALLE, D J	8310120229*	50-155 T	VAUGHAN, C H	8310250427	70-1113
UMBEL, D M	8310120010	CONTRACT	VANDEWALLE, D J	8310120318	50-255 Q	VAUGHAN, C H	8310260307*	70-1113
UMBEL, D M	8310120021	CONTRACT	VANDEWALLE, D J	8310120327*	50-155 Q	VAUGHN, G E	8310240030*	50-413 T
UMBEL, D M	8310130380	CONTRACT	VANDEWALLE, D J	8310130179*	50-155 T	VENDELL, T E	8310030389*	50-440 Q
UMBEL, D M	8310210205	CONTRACT	VANDEWALLE, D J	8310180464	50-255 F	VENTURA, J C	8310040355*	50-317 P
UMBEL, D M	8310240097	CONTRACT	VANDEWALLE, D J	8310200256	50-255 Q	VERGEE, A W	8310140021	50-443 Q
UNKLE, T J	8310250443	50-318 S	VANDEWALLE, D J	8310250203*	50-255 Q	VERRELLI, D	8310170141	50-416 Q
UNBAL, A I	8310040573*	50-382 A	VANDEWALLE, D J	8310270219	50-155 P	VERRELLI, D	8310170189	50-259 Q
UNBAL, A I	8310280006*	50-382 A	VANDEWALLE, D J	8310310376	50-155 P	VERRELLI, D	8310170520	50-261 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
VERRELLI, D	8310210044	50-324 Q	WALKER, R	8310180446	50-265 S	WELCH, F	8310050507*	50-151
VERRELLI, D M	8310040037	50-261 Q	WALKER, R D	8310060163*	50-331 Q	WELCHER, D K	8310120260	50-311
VERRELLI, D M	8310040140	50-390 Q	WALKER, R D	8310170483*	50-263 Q	WELLS, A A	8310270131*	FOIA
VERRELLI, D M	8310040163	50-416 Q	WALKER, R D	8310250613*	50-254 Q	WELLS, D A	8310120311*	50-341
VERRELLI, D M	8310040166	50-261 Q	WALKER, W J	7909140005*	FOIA	WELLS, D A	8310210066	50-341
VERRELLI, D M	8310040182	50-324 Q	HALL, C F	8310050344*	50-317 F	WELLS, D A	8310250114	50-341
VERRELLI, D M	8310040211	50-438 Q	WALKER, W K	8310200330	71-6679	WELLS, D A	8310270447	50-341
VERRELLI, D M	8310040265	50-259 Q	WALSH, J D	8310120384*	50-352 Q	WELLS, J E	831010032	NUREQ
VERRELLI, D M	8310040275*	50-259 Q	WALSH, J D	8310120384*	50-352 Q	WELLS, R A	8310200265	50-326
VERRELLI, D M	8310040298	50-324 Q	WALSKE, C	8310110579*	NISC	WELLS, R W	8310250577	TOPREF
VERRELLI, D M	8310040321*	50-324 Q	WALTERS, C	8310190047*	50-329 A	WELLS, R W	8310250577	TOPREF
VERRELLI, D M	8310040347	50-261 F	WAMBACH, T V	8310250096	50-255 P	WELSH, J A	8310170211	71-906
VERRELLI, D M	8310040374	50-348 Q	WANG, P C	8310210358*	50-275 T	WENSLAWSKI, F	8310040391	50-19
VERRELLI, D M	8310040378*	50-348 Q	WARD, J O	8310260185*	FOIA	WENSLAWSKI, F	8310040396	50-204
VERRELLI, D M	8310040423	50-390 Q	WARD, R T	8310170098*	50-338 S	WENSLAWSKI, F	8310200176	50-224
VERRELLI, D M	8310040494	50-416 V	WARD, W	8310270462*	50-443 Q	WENSLAWSKI, F A	8310040300	50-311
VERRELLI, D M	8310040555	50-390 Q	WARD, W	8310270474*	50-443 Q	WENSLAWSKI, F A	8310040308*	50-311
VERRELLI, D M	8310040581	50-348 F	WARD, W J	8008270592*	50-498 Q	WENSLAWSKI, F A	8310040391*	50-311
VERRELLI, D M	8310250214	50-416 Q	WARD, W J	8310280220*	50-358 Q	WENSLAWSKI, F A	8310040399*	50-18
VERRELLI, D M	8310250234	50-259 Q	WARDWELL, R E	8310280170*	40-299	WENSLAWSKI, F A	8310120245	50-344
VERRELLI, D M	8310250299	50-327 Q	WARENBURG, D	8310280175*	40-299	WENSLAWSKI, F A	8310120348	70-121
VERRELLI, D M	8310250301	50-438 Q	WARENBURG, D	8310040207	50-267 S	WENSLAWSKI, F A	8310120355	50-311
VERRELLI, D M	8310250303	50-390 Q	WARENBURG, D	8310040313	50-267 S	WENSLAWSKI, F A	8310120355	50-311
VERRELLI, D M	8310250318*	50-438 Q	WARENBURG, D	8310040325	50-267 P	WENSLAWSKI, F A	8310170678*	50-311
VERRELLI, D M	8310250322	50-261 Q	WARENBURG, D	8310170260	50-267 R	WENSLAWSKI, F A	8310210254	50-226
VERRELLI, D M	8310250373	50-438 Q	WARENBURG, D W	8310040210	50-267 Q	WENSLAWSKI, F A	8310210256*	50-226
VERRELLI, D M	8310250374	50-348 Q	WARENBURG, D W	8310040276	50-267 Q	WENSLAWSKI, F A	8310310233	50-73
VERRELLI, D M	8310250397	50-390 Q	WARENBURG, D W	8310110236*	50-267 F	WENSLAWSKI, F A	8310310241*	50-27
VERRELLI, D M	8310250439	50-416 Q	WARNER, D L	8310170030	70-820	WENSLAWSKI, F A	8310310249*	50-73
VERRELLI, D M	8310250472	50-348 Q	WARNICK, R	8310120446	50-329 S	WENSLAWSKI, F A	8310310357*	50-135
VERRELLI, D M	8310250485*	50-348 Q	WARNICK, R F	8310050518	50-358 Q	WERMIEL, J S	8310210355*	50-271
VERRELLI, D M	8310250502*	50-327 Q	WARNICK, R F	8310050522*	50-358 Q	WERMIEL, J S	8310210357*	50-271
VERRELLI, D M	8310250563	50-327 Q	WARNICK, R F	8310050538	50-358 Q	WERMIEL, J S	8310210371*	50-271
VERRELLI, D M	8310250588	50-261 Q	WARNICK, R F	8310050540*	50-358 Q	WERMIEL, J S	8310210387*	50-271
VERRELLI, D M	8310250593	50-327 Q	WARNICK, R F	8310120179	50-329 A	WERMIEL, J S	8310250332*	50-271
VERRELLI, D M	8310250601*	50-261 Q	WARNICK, R F	8310120325	50-329 Q	WERNER, R P	8310040334	PR
VERRELLI, D M	8310250611*	50-327 Q	WARNICK, R F	8310140135	50-358 Q	WERNER, R P	8310040334	PR
VERRELLI, D M	8310250628	50-400 Q	WARNICK, R F	8310170451	50-358 Q	WERNER, R P	8310040334	PR
VISSING, G S	8310110618	50-313 P	WARNICK, R F	8310170459	50-329 Q	WESTAFER	8310070306	50-301
VISSING, G S	8310130140	50-313 Q	WARNICK, R F	8310170513	50-329 Q	WESTAFER, G R	8310040301	50-301
VISSING, G S	8310170096	50-313 P	WARNICK, R F	8310170558	50-329 Q	WESTAFER, G R	8310040420	50-301
VDGLER, B H	8310050429	50-352 Q	WARNICK, R F	8310170562*	50-329 Q	WESTAFER, G R	8310040463	50-301
VDGLER, B H	8310130037	50-352 Q	WARNICK, R F	8310170583	50-329 Q	WESTAFER, G R	8310040472*	50-301
VDGLER, B H	8310250342	50-352 Q	WARNICK, R F	8310210316	50-329 Q	WESTAFER, G R	8310070307	50-301
VDGLER, B H	8310250364*	50-352 Q	WARNICK, R F	8310260285*	50-329 A	WESTAFER, G R	8310120301	50-301
VDOT, D	8310130143	NUREQ	WARNICK, R F	8310270341	50-329 Q	WESTAFER, G R	8310140079	50-301
VDOT, H H	8310110182	50-289 Q	WARNICK, R F	8310310411	50-329 Q	WESTAFER, G R	8310140243	50-301
VDOT, H H	8310200026	50-289 F	WART, R J	8310310449	NUREQ	WESTAFER, G R	8310170519	50-301
VDOT, H H	8310280169	50-289 P	WASENKO, M	8310070293*	50-324 F	WESTAFER, G R	8310180473	50-301
VDOT, R E	8310030361	71-9151	WASENKO, M	8310070295*	50-324 F	WESTAFER, G R	8310210021	50-301
VDOLGENAU, E	8310260240	FOIA	WATERS, J R	8310240096*	50-295 Q	WESTAFER, G R	8310250374*	50-301
VDOLGENAU, E	8310260252*	FOIA	WATSON, L	8310030461	50-416 S	WESTAFER, G R	8310250458	50-301
VDOLGER, B H	8310280171	50-458 M	WATSON, L J	8310250360*	50-321 Q	WESTBROOK, W W	8310040231*	50-441
VDOLK, W Q	8310180123	40-8348	WEAVER, J D	8310210302	50-298 F	WESTBROOK, W W	8310040234*	50-441
VDOLMER, R	8308290029*	50-329 A	WEBB, D F	8310190146	50-358 Q	WESTERMAN, T F	8310170683	50-441
VDOLMER, R	8310130269*	50-329 A	WEBB, J H	8310260423	NUREQ	WESTERMAN, T F	8310180161*	50-291
VDOLMER, R H	8304010047*	FOIA	WEBB, W E	8310110203*	50-259 F	WESTPHAL, B S	8310120109	50-371
VDOLMER, R H	8310050206*	50-244 P	WEBER, M F	8310240252	WASTE MGT	WESTRICH, H R	8310050253	NUREQ
VDOLMER, R H	8310120054	50-289 P	WEBER, M F	8310240265	WASTE MGT	WETHY, C M	8310060492*	50-331
VDOLZER, H J	8310170084*	CONTRACT	WEBSTER, B H	8310040282	50-261 Q	WETHY, C M	8310270053*	50-381
VDORHEES, L D	8310260423	NUREQ	WEEKS, E D	8310190260	50-133 R	WETTERHAHN, M J	8310040627	50-351
VORSE, J Y	8310280265*	50-400 A	WEINKAM, E J	8310130084	50-458 F	WETTERHAHN, M J	8310040627	50-351
VORSE, J Y	8310280299*	50-400 A	WEINKAM, E J	8310260442	50-458 A	WETTERHAHN, M J	8310050557	27-39
VOSBURY, F. W.	8210010087*	50-272 P	WEINSTEIN, M.	8310190313*	FOIA	WETTERHAHN, M J	8310110275	50-351
VOSBURY, F. W.	8212010152*	50-346 P	WEINTRAUB, A A	8310170170	71-8595	WETTERHAHN, M J	8310110275	50-351
VOSBURY, F. W.	8306160913*	50-324 P	WEINTRAUB, A A	8310170306	71-6550	WETTERHAHN, M J	8310110277*	50-351
VOSBURY, F. W.	8306160602*	50-302 P	WEINTRAUB, A A	8310170342	71-4907	WETTERHAHN, M J	8310110278*	50-351
VOSBURY, F. W.	8309060263*	50-315 P	WEINTRAUB, A A	8310170744	71-3939	WETTERHAHN, M J	8310110284*	50-351
VUMBACO, F. J	8310050316	40-672	WEISE, B	8310250339*	50-261 Q	WETTERHAHN, M J	8310110284*	50-351
WAGNER, A G	8310250271*	50-416 Q	WEISE, B	8310250527*	50-261 Q	WETTERHAHN, M J	8310110287*	50-351
WAGNER, D	8310070219	50-354 A	WEISEMANN, R A	8310280007	TOPREF	WETTERHAHN, M J	8310110287*	50-351
WAGNER, D	8310070223	50-354 A	WEISS, D	8310070090*	40-8794	WETTERHAHN, M J	8310110292*	50-351
WAGNER, M E	8310130048	50-289 Q	WEISS, D J	8310170233*	70-1113	WETTERHAHN, M J	8310110297*	50-351
WAGNER, M E	8310250338	50-289 Q	WEISS, E R	8310050528	50-289 Q	WETTERHAHN, M J	8310110297*	50-351
WAGNER, P C	8310180385	50-267 P	WEISS, E R	8310070369*	COMMISSION	WETTERHAHN, M J	8310110305	50-351
WAGNER, P C	8310310384	50-267 P	WEISS, E R	8310070386*	COMMISSION	WETTERHAHN, M J	8310110305	50-351
WAGNER, P C	8310310433	50-267 P	WEISS, E R	8310070386*	COMMISSION	WETTERHAHN, M J	8310110312*	50-351
WAHL, H W	8310040488*	04999	WEISS, E R	8310180531	50-333 P	WETTERHAHN, M J	8310110312*	50-351
WAHL, H W	8310280229*	50-358 A	WEISS, E R	8310200231	50-289 Q	WETTERHAHN, M J	8310120364	50-351
WALD, J J	8310040341*	50-358 F	WEISS, E R	8310250046	50-289 Q	WETTERHAHN, M J	8310120364	50-351
WALDORF, J	8310260145*	50-324 P	WEISS, E R	8310260306	50-289 Q	WETTERHAHN, M J	8310120368*	50-351
WALDORF, J M	8310260148*	50-324 P	WEISS, E R	8310260308*	50-289 Q	WETTERHAHN, M J	8310120368*	50-351
WALKER, M A	8310060381*	50-298 S	WEISS, E R	8310270366	FOIA	WETTERHAHN, M J	8310120377*	50-351
WALKER, E L	8310060422	71-6144	WEISZ, D A	8310070359	TOPREF	WETTERHAHN, M J	8310120377*	50-351
WALKER, R	8310120309	50-249 S	WELCH, F	8310050507*	50-155 Q	WETTERHAHN, M J	8310180132	50-351

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WETTERHAHN, M J	8310180132	50-352 Q	WILHITE, M	8310270289	50-295 B	WILSON, B D	8310260009	XPORTRIC
WETTERHAHN, M J	8310180139*	50-352 Q	WILLARD, J	8310170498	50-346 B	WILSON, D L	8310270015*	50-331 F
WETTERHAHN, M J	8310180139*	50-352 Q	WILLIAMS, C C	8310050497*	50-341 Q	WILSON, F	8310060010*	CONTRACT
WETTERHAHN, M J	8310180146*	50-352 Q	WILLIAMS, C C	8310140192*	50-454 Q	WILSON, J L	8310060384*	50-280 F
WETTERHAHN, M J	8310180146*	50-352 Q	WILLIAMS, D	8310120062	50-352 A	WILSON, J L	8310040208	50-280 S
WETTERHAHN, M J	8310180234	50-352 Q	WILLIAMS, D L	8310240102*	50-282 Q	WILSON, J L	8310070164	50-280 S
WETTERHAHN, M J	8310180234	50-352 Q	WILLIAMS, F C	8310030463	50-329 Q	WILSON, J L	8310210306	50-280 S
WETTERHAHN, M J	8310180237*	50-352 Q	WILLIAMS, F C	8310030463	50-329 Q	WILSON, J L	8310250609	50-280 S
WETTERHAHN, M J	8310180237*	50-352 Q	WILLIAMS, F C	8310110310	50-329 Q	WILSON, P	8310060496*	CONTRACT
WETTERHAHN, M J	8310310231	50-352 Q	WILLIAMS, F C	8310110310	50-329 Q	WILSON, R F	8310110200	50-289 F
WETTERHAHN, M J	8310310231	50-352 Q	WILLIAMS, F C	8310280073	50-329 Q	WILSON, V H	8310200407*	50-440 A
WEYANT, P A	8310170078*	50-338 E	WILLIAMS, F C	8310280073	50-329 Q	WILSON, W E	8310030143	50-27 F
WHALEN, R J	8310210297	50-237 S	WILLIAMS, H O	8310230119*	State Prog	WINSOWSKI, W S	8310120240*	50-305 F
WHICHER, J M	8310040205	50-454 Q	WILLIAMS, J	8310040336	50-358 F	WINTERHOFF, D R	8310270490	50-373 S
WHICHER, J M	8310040205	50-454 Q	WILLIAMS, J	8310040439	50-358 K	WISE, R	8310030457*	50-267 G
WHICHER, J M	8310040205	50-454 Q	WILLIAMS, J	8310120252	50-358 A	WISBENDURG, M R	8310030311	PR
WHICHER, J M	8310040205	50-454 Q	WILLIAMS, J	8310120383	50-358 S	WITHERS, B D	8310060099	50-344 F
WHICHER, J M	8310110278	50-367 Q	WILLIAMS, J	8310120442	50-358 S	WITHERS, B D	8310060261*	50-344 F
WHICHER, J M	8310110278	50-367 Q	WILLIAMS, J	8310130242	50-358 K	WITHERS, B D	8310060491	50-344 F
WHICHER, J M	8310200097	50-454 Q	WILLIAMS, J	8310170348	50-358 S	WITHERS, B D	8310110189	50-344 F
WHICHER, J M	8310200097	50-454 Q	WILLIAMS, J	8310170404	50-358 S	WITHERS, B D	8310110196*	50-344 F
WHICHER, J M	8310200097	50-454 Q	WILLIAMS, J	8310170448	50-358 S	WITHERS, B D	8310120247*	50-344 F
WHICHER, J M	8310210204	50-454 Q	WILLIAMS, J	8310170454*	50-358 Q	WITHERS, B D	8310180417	50-314 A
WHICHER, J M	8310210219*	50-454 Q	WILLIAMS, J	8310170485	50-358 S	WITHERS, B D	8310200188	50-344 F
WHICHER, J M	8310210219*	50-454 Q	WILLIAMS, J	8310170515	50-358 A	WITHERS, B D	8310200192*	50-344 F
WHICHER, J M	831020019*	50-454 Q	WILLIAMS, J	8310170649	50-358 S	WITHERS, B D	8310260237	50-344 F
WHIPPLE, O H	8310060222*	50-400 Q	WILLIAMS, J	8310180296	50-358 S	WITHERS, B D	8310270521*	50-344 F
WHITE, O D	8310260381	MUREG	WILLIAMS, J	8310200098	50-358 S	WITHERS, B D	8310310299	50-344 F
WHITE, O S	8310180343	50-412 Q	WILLIAMS, J	8310200209	50-358 A	WITTENBURG, K C	8310060186	50-373 S
WHITE, J R.	8310110349*	CONTRACT	WILLIAMS, J	8310200212*	50-358 A	WITZNER, D G	8310210215*	50-316 S
WHITE, J R.	8310120217*	50-277 Q	WILLIAMS, J	8310200215*	50-358 A	WIZNER, D G	8310270223*	50-316 S
WHITE, L. D.	8310310073*	50-244 P	WILLIAMS, J	8310200222*	50-358 A	WODARSKI, L J	8310210180*	CONTRACT
WHITE, R	8310250631*	50-312 P	WILLIAMS, J	8310200227*	50-358 A	WOHL, M L	8310050481*	50-155 T
WHITENER, H L	8310040147*	50-390 Q	WILLIAMS, J	8310200230*	50-358 A	WOJCHOWSKI, A V	8310270414*	50-263 B
WILLIAM, R. O	8310040344	50-508 A	WILLIAMS, J.	8310200234*	50-358 A	WOLF, J F	8310140089	50-522 Q
WHITNEY, O	8310250282	50-293 S	WILLIAMS, J	8310210110*	50-358 Q	WOLF, J F	8310250048	50-320 Q
WHITNEY, O O	8309190140	50-293 R	WILLIAMS, J	8310210113*	50-358 Q	WOLF, J F	8310170243	MUREG
WHITNEY, O O	8310190174	50-293 S	WILLIAMS, J	8310240161	50-358 Q	WOLFE, R	8310170369	50-346 S
WHITNEY, O O	8310200226	50-293 S	WILLIAMS, J	8310250366	50-358 S	WOLFE, S J	8310130209	50-289 Q
WHITNEY, O O	8310250137	50-293 S	WILLIAMS, J	8310250487	50-358 S	WOLFE, S J	8310240163	50-338 Q
WHITNEY, O O	8310280045	50-293 S	WILLIAMS, J.	8310250586*	50-358 Q	WOLFE, S J	8310250042	50-289 Q
WHITTIER, O D	83103100283	PR	WILLIAMS, J	8310260098	50-358 Q	WOLFE, B J	8310270326	50-338 Q
WHITTIER, O D	8310040616	50-309 V	WILLIAMS, J H	8310210278*	50-277 Q	WOLLETT, S	8310030549	CONTRACT
WHITTIER, O D	8310070159	50-309 P	WILLIAMS, J W	8310250039	50-389 S	WOLLETT, S	8310060091	CONTRACT
WHITTIER, O D	8310070202	50-309 P	WILLIAMS, J W	8310030254	50-389 S	WOLLETT, S	8310060178	CONTRACT
WHITTIER, O D	8310120165	50-309 S	WILLIAMS, J W	8310030262	50-251 S	WOLLETT, S	8310170111	CONTRACT
WHITTIER, O D	8310170168*	50-309 Q	WILLIAMS, J W	8310030398	50-389 S	WOLLETT, S	8310210091	CONTRACT
WHITTIER, O D	8310190231	50-309 S	WILLIAMS, J W	8310030448	50-389 S	WOLLETT, S	8310260371	CONTRACT
WHITTIER, O D	8310200108	50-309 S	WILLIAMS, J W	8310040291	PR	WOLLETT, S	8310270596	CONTRACT
WHITTIER, O D	8310210194*	50-309 Q	WILLIAMS, J W	8310180208	50-335 P	WOLMAN, A	8310120026*	50-201 I
WHITTIER, O D	8310210208*	50-309 Q	WILLIAMS, J W	8310180254	50-335 P	WOLTNER, E	8310120201*	70-135
WHITTIER, O D	8310250063	50-309 P	WILLIAMS, J W	8310180324	50-250 P	WODD, E C	8310250280	50-309 S
WHITTIER, O D	8310250384	50-309 S	WILLIAMS, J W	8310180359	50-250 S	WODDHEAD, C P	8310310479	50-317 P
WHITTIER, O D	8310270208*	50-309 F	WILLIAMS, J W	8310190023	50-250 R	WODDUFF, D C	8310010786*	50-348 P
WHITTLESEY, K A	8310130178*	50-482 G	WILLIAMS, J W	8310190104	50-389 S	WODDS, V L	8310050556*	CONTRACT
WHITTLESEY, K A	8310170683	50-445 T	WILLIAMS, J W	8310210223	50-251 S	WODLEVER, E J	8310030360*	50-412 Q
WICKS, F	8310110121	50-225 P	WILLIAMS, J W	8310240140	50-335 P	WODLEVER, E J	8310310062	50-412 K
WICKS, F.	8310200035*	50-225 P	WILLIAMS, J W	8310250060	50-389 S	WODLEVER, E J	8310310089	50-412 A
WIDMAN, R P.	8310070148*	CONTRACT	WILLIAMS, J W	8310250337	50-389 S	WODLEVER, E J	8310310309	50-412 F
WIEBE, J	8310140170*	50-320 Q	WILLIAMS, J W	8310270120	50-335 P	WRAY, J R	8310250428*	50-338 Q
WIEDEMAN, D.	8310120230	I&E	WILLIAMS, J W	8310270211	50-389 P	WRAY, J R	8310250621*	50-335 Q
WIEDEMAN, D. O	8310310318	I&E	WILLIAMS, J W	8310270249	50-250 Q	WRAY, R	8310180369*	50-275 T
WIEDER, A V.	8310030213*	XPORTRIC	WILLIAMS, J W	8310270277	50-251 S	WRIGHT, C L	8310070136	50-261 B
WIEDER, A V.	8310310238	70-734	WILLIAMS, J W	8310270394*	50-251 B	WRIGHT, C L	8310070322	50-261 B
WIEBEMANN, R A	8310050212*	PROJ	WILLIAMS, J W	8310280082	50-335 P	WRIGHT, C L	8310170541	50-261 B
WIEBEMANN, R A	8310060270*	PROJ	WILLIAMS, J W	8310280153	50-335 P	WRIGHT, Q C.	8310060374*	50-155 Q
WIEBEMANN, R A	8310110149*	TOPREP	WILLIAMS, J W	8310310015	50-335 P	WRIGHT, N A	8310130010	50-329 Q
WIEBEMANN, R A	8310200199*	TOPREP	WILLIAMS, O O	8310110496	FOIA	WRIGHT, N A	8310130233	50-329 Q
WIEBEMANN, R A	8310260267*	50-400 E	WILLIAMS, R E	8310070221*	CONTRACT	WRIGHT, N A	8310250100	50-352 Q
WIEBEMANN, R A	8310260281*	50-445 A	WILLIAMS, R E	8310120040*	CONTRACT	WRIGHT, R J.	8310310464	MISC
WIEBEMANN, R A	8310280019*	50-400 E	WILLIAMS, R E	8310280068*	CONTRACT	WRIGHT, R W	8310040244*	50-438 Q
WIEBEMANN, R A	8310280110*	PROJ	WILLIAMS, R E	8310200083	50-358 S	WRIGHT, R W.	8310190344*	50-413 Q
WIGGINS, E.	8310070184	50-498 A	WILLIAMS, T.	8310140136*	50-358 Q	WRIGHT, R W	8310040345*	50-413 Q
WIGGINS, E.	8310070197	CONTRACT	WILBEY, W B	8310120313	50-277 R	WRIGHT, S V	8310310207	27-48
WIGGINS, E.	8310070214	CONTRACT	WILSON, A K	8310110520	FOIA	WU, P	8310070386*	50-282 S
WIGGINS, E.	8310070329	CONTRACT	WILSON, A K	8310110538*	FOIA	WU, P.	8305050044*	50-282 B
WIGGINS, E.	8310130198	CONTRACT	WILSON, A K.	8310110541*	FOIA	WU, P.	8310190344*	50-282 B
WIGGINS, E.	8310130417	CONTRACT	WILSON, A K	8310110547*	FOIA	WUNDERLICH, T K	8310070196*	CONTRACT
WIGGINTON, D.	8310060028	50-315 P	WILSON, B D	8310130369	XPORTRIC	HURZBURG, O N	8310200462*	CONTRACT
WIGGINTON, D.	8310070223	50-316 P	WILSON, B D.	8310130371	XPORTRIC	WYNGARDEN, S D.	8310180015*	70-143
WIGGINTON, D L	8310110333	50-315 P	WILSON, B D	8310180112	XPORTRIC	YANDELL, L A	8310130171*	50-285 G
WILCOVE, M N	8310130028	50-320 Q	WILSON, B D	8310180310	XPORTRIC	YANDELL, P I	8310120233*	50-135 T
WILCOX, J D	8310250333*	50-438 Q	WILSON, B D.	8310180577	XPORTRIC	YANDELL, P I	8310120233*	50-135 T
WILD, P A.	8310170466*	50-329 Q	WILSON, B D.	8310180580*	XPORTRIC	YIN, I T	8310040179*	50-346 Q
WILGUB, W B	8310140187	50-302 S	WILSON, B D	8310240311	XPORTRIC	YORK, H.	8310040427*	50-390 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
YOST, R A	8310170548	50-358 R	ZIMMERMAN, J V	8309250037	XPORTLIC	ZIMMERMAN, J V	8310180564	XPORTLIC
YOUNG, F	8310140166*	50-289 Q	ZIMMERMAN, J V	8310060098	XPORTLIC	ZIMMERMAN, J V	8310240300	XPORTLIC
YOUNG, M	8310050475*	50-454 Q	ZIMMERMAN, J V	8310060104	XPORTLIC	ZIMMERMAN, J V	8310240309*	XPORTLIC
YOUNG, M A	8310050440	50-454 Q	ZIMMERMAN, J V	8310060107	XPORTLIC	ZIMMERMAN, J V	8310240314	XPORTLIC
YOUNG, M A	8310050452	50-454 Q	ZIMMERMAN, J V	8310060108	XPORTLIC	ZIMMERMAN, J V	8310240316	XPORTLIC
YOUNG, M A	8310050468*	50-454 Q	ZIMMERMAN, J V	8310060114	XPORTLIC	ZIMMERMAN, J V	8310250020	XPORTLIC
YOUNG, M A	8310130014	50-454 Q	ZIMMERMAN, J V	8310060115	XPORTLIC	ZIMMERMAN, J V	8310250142	XPORTLIC
YOUNG, M A	8310250117	50-454 Q	ZIMMERMAN, J V	8310060123	XPORTLIC	ZIMMERMAN, J V	8310250150	XPORTLIC
YOUNG, M A	8310250486	50-454 Q	ZIMMERMAN, J V	8310060126	XPORTLIC	ZIMMERMAN, J V	8310250164	XPORTLIC
YOUNG, M A	8310250504*	50-454 Q	ZIMMERMAN, J V	8310060131	XPORTLIC	ZIMMERMAN, J V	8310250172	XPORTLIC
YOUNG, M A	8310250513	50-454 Q	ZIMMERMAN, J V	8310060141	XPORTLIC	ZIMMERMAN, J V	8310250178	XPORTLIC
YOUNG, M L	8310040533	50-443 Q	ZIMMERMAN, J V	8310060143	XPORTLIC	ZIMMERMAN, J V	8310260004	XPORTLIC
YOUNG, M L	8310120178	50-443 Q	ZIMMERMAN, J V	8310060147	XPORTLIC	ZIMMERMAN, J V	8310260020	XPORTLIC
YOUNG, P T	8310130273*	50-400 E	ZIMMERMAN, J V	8310060152	XPORTLIC	ZIMMERMAN, J V	8310260039	XPORTLIC
YOUNG, T	8310040537*	50-528 Q	ZIMMERMAN, J V	8310060156	XPORTLIC	ZIMMERMAN, J V	8310260057	XPORTLIC
YOUNG, T	8310120251	50-312 S	ZIMMERMAN, J V	8310060183	XPORTLIC	ZIMMERMAN, J V	8310260079	XPORTLIC
YOUNG, T	8310120321	50-312 S	ZIMMERMAN, J V	8310060240	XPORTLIC	ZIMMERMAN, J V	8310260328	XPORTLIC
YOUNG, T	8310170470*	50-528 Q	ZIMMERMAN, J V	8310060405	XPORTLIC	ZIMMERMAN, J V	8310270540	XPORTLIC
YOUNG, T	8310240222*	50-528 Q	ZIMMERMAN, J V	8310120453	XPORTLIC	ZIMMERMAN, J V	8310270543	XPORTLIC
YOUNG, T	8310310304*	50-312 Q	ZIMMERMAN, J V	8310120459	XPORTLIC	ZIMMERMAN, R P	8310270220*	50-244
YOUNG, T	8310310398*	50-528 Q	ZIMMERMAN, J V	8310120461	XPORTLIC	ZIMMERMAN, S	8310040297	FR
YOUNG, T	8310310405*	50-312 Q	ZIMMERMAN, J V	8310130023	XPORTLIC	ZIMMERMAN, S R	8310030527	FRM
YOUNGBLOOD, B J	8310110376	50-482 F	ZIMMERMAN, J V	8310130030	XPORTLIC	ZIMMERMAN, S R	8310060561*	50-324
YOUNGBLOOD, B J	8310110383	50-546 C	ZIMMERMAN, J V	8310130032	XPORTLIC	ZIMMERMAN, S R	8310070291	50-324
YOUNGBLOOD, B J	8310110495	50-440 E	ZIMMERMAN, J V	8310130034	XPORTLIC	ZIMMERMAN, S R	8310190162	50-261
YOUNGBLOOD, B J	8310110501	50-546 C	ZIMMERMAN, J V	8310130038	XPORTLIC	ZIMMERMAN, S R	8310200058	50-324
YOUNGBLOOD, B J	8310110602	50-423 E	ZIMMERMAN, J V	8310130050	XPORTLIC	ZIMMERMAN, S R	8310250450	50-400
YOUNGBLOOD, B J	8310170069	50-423 A	ZIMMERMAN, J V	8310130075	XPORTLIC	ZUMWALT, L R	8310110271*	CONTRAC
YOUNGBLOOD, B J	8310170193	50-423 A	ZIMMERMAN, J V	8310130086	XPORTLIC	ZUPKO, J M	8310180114	50-311
YOUNGBLOOD, B J	8310170713	50-482 F	ZIMMERMAN, J V	8310130092	XPORTLIC	ZUPKO, J M	8310190178	50-311
YOUNGBLOOD, B J	8310170715	50-445 A	ZIMMERMAN, J V	8310130147	XPORTLIC	ZUPKO, J M	8310190302	71-9086
YOUNGBLOOD, B J	8310170722	50-482 F	ZIMMERMAN, J V	8310130355	XPORTLIC	ZUPKO, J M	8310200014	71-6574
YOUNGBLOOD, B J	8310170726	50-423 A	ZIMMERMAN, J V	8310130364	XPORTLIC	ZUPKO, J M	8310200174	50-272
YOUNGBLOOD, B J	8310280195	50-546 Q	ZIMMERMAN, J V	8310130367	XPORTLIC	ZUPKO, J M	8310200279	50-311
YOUNGBLOOD, B J	8310310153	50-546 A	ZIMMERMAN, J V	8310130401	XPORTLIC	ZUPKO, J M	8310210041	50-311
YOUNGBLOOD, B J	8310310168	50-456 A	ZIMMERMAN, J V	8310130405	XPORTLIC	ZUPKO, J M	8310250238	50-272
YOUNGBLOOD, B J	8310310170	50-423 A	ZIMMERMAN, J V	8310130419	XPORTLIC	ZUPKO, J M	8310250244	50-311
YOUNGBLOOD, R	8310310444	50-302 P	ZIMMERMAN, J V	8310170023	XPORTLIC	ZUPKO, J M	8310250325	50-272
YOUNGLING, E J	8310310454*	50-322 S	ZIMMERMAN, J V	8310170038	XPORTLIC	ZUPKO, J M	8310250390	50-272
YUHAS, G P	8310040311*	50-312 Q	ZIMMERMAN, J V	8310170041	XPORTLIC	ZUPKO, J M	8310250407	50-311
YUNDT, C P	8310140246	50-344 S	ZIMMERMAN, J V	8310170679	XPORTLIC	ZUPKO, J M	8310250470	50-311
YUNDT, C P	8310190039	50-344 R	ZIMMERMAN, J V	8310180001	XPORTLIC	ZUPKO, J M	8310250567	50-311
YUNDT, C P	8310250444	50-344 S	ZIMMERMAN, J V	8310180159	XPORTLIC	ZUPKO, J M	8310280024	50-272
ZERBE, J E	8310110588*	MISC	ZIMMERMAN, J V	8310180164	XPORTLIC	ZURAKOWSKI, P R	8310030213*	XPORTLIC
ZIBULSKY, H	8310240085*	70-1100	ZIMMERMAN, J V	8310180355	XPORTLIC			

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJ CATE
ALFAB, Inc	8310250148*	QA999		8310170423*	50-34
Aamodts	8310260294	50-289 Q		8310180124	50-34
Acres American, Inc	8310310449	NUREG		8310180134	50-36
Acton Environ Testing Corp	8310130267*	50-400 E		8310180308	50-34
	8310130267*	50-400 E		8310190071	50-36
	8310130271*	50-400 E		8310210022	50-34
	8310130271*	50-400 E		8310210239	50-34
	8310130277*	50-400 E		8310210239	50-34
Aero Nav Laboratories, Inc	8310130280*	50-400 E		8310210261*	50-34
Agabian Associates	8310070429*	CONTRACT		8310210261*	50-34
Agriculture, Dept of, Graduate School	8310240106*	CONTRACT		8310250422	50-34
	8310240130*	CONTRACT		8310250479*	50-34
Air Force, Dept of	8310110369*	FOIA		8310270061	50-36
	8310110375*	FOIA		8310270108*	50-36
	8310110384*	FOIA		8310270113*	50-36
Air and Water Pollution Patrol	8310030437	50-352 Q		8310270374	50-34
	8310180419	50-352 Q		8310270378*	50-34
	8310310336	50-352 Q	Alden Research Laboratory	8310030645*	GEN T
	8310310336	50-352 Q	Allied Chemical Corp	8310070125	MISC
	8310310353*	50-352 Q		8310070129*	MISC
	8310310353*	50-352 Q		8310170623	40-33
	8310310371*	50-352 Q		8310170633*	40-33
	8310310371*	50-352 Q	Allis-Chalmers Corp	8310270092*	FOIA
Alabama Power Co	8310030417	50-348 F		8310270105*	FOIA
	8310030414	50-348 F		8310270182*	FOIA
	8310030414	50-348 F		8310270186*	FOIA
	8310030439	50-364 S		8310270189*	FOIA
	8310040377*	50-348 Q	Amerace Corp	8310180313*	QA999
	8310040387	50-348 F		8310180323*	QA999
	8310040387	50-348 F		8310180340*	QA999
	8310040436	50-348 F	American Electric Power Co, Inc	8310310080*	50-31
	8310060096	50-348 F	American Environments Co, Inc	8310250368*	QA999
	8310070138	50-348 S	American Institute of Aeronautics & Astronautics	8310110009*	CONTR.
	8310070290	50-364 S	American Institute of Steel Construction, Inc.	8310140163	TOPREI
	8310070296	50-348 S		8310140174*	TOPREI
	8310070296	50-348 S		8310240098*	CONTR.
	8310070299*	50-348 S	American National Standards Institute	8310140295	40-44
	8310070302*	50-348 S	American Nuclear Corp	8310140297*	40-44
	8310120350	50-348 S		8310030396	PR
	8310120350	50-348 S		8310030396	PR
	8310120356*	50-348 S	American Nuclear Insurers	8310250448	PR
	8310120363*	50-348 S	American Nuclear Society	8310110029*	CONTR.
	8310120371*	50-348 S		8310070415*	CONTR.
	8310140194	50-348 P	American Physical Society	8310170084*	CONTR.
	8310140194	50-348 P	American Society for Testing & Materials		
	8310140199*	50-348 P	American Telephone & Telegraph Co		
	8310140199*	50-348 P	/American Bell		
	8310140226	50-348 S	Amer sham Corp	8310260064	XPORTI
	8310140229*	50-348 S			
	8310140235*	50-348 S	Anaheim, CA	8310110133*	50-36
	8310170407	50-348 P	Analysis & Technology, Inc	8310050556*	CONTR.
	8310170407	50-348 P	Anthony, R.L.	8310190040	50-35
	8310170416	50-348 P		8310190040	50-35
	8310170416	50-348 P		8310190044*	50-35
	8310170423*	50-348 P	Applied Science Associates, Inc	8310190044*	50-35
				8310050224	NUREG

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Arizona Public Service Co	8310030425	50-528 E		8310230141	50-313 G
	8310030425	50-528 E		8310230193	50-313 G
	8310040307	PR		8310230274	50-313 F
	8310040375	50-528 F		8310230281	50-368 P
	8310040375	50-528 F		8310230417	50-313 G
	8310040375	50-528 F		8310230533	50-368 F
	8310070006	50-528 S		8310230559	50-313 F
	8310070147	50-528 S		8310310368	50-368 S
	8310070147	50-528 S	Army, Dept of	8310270417	40-8599
	8310070147	50-528 S	Army, Dept of, Army Engineer Waterways Experiment Station	8310070194	NUREG
	8310070286	50-528 S			
	8310070339	50-529 S	Army, Dept of, Corps of Engineers	8310050337*	CONTRACT
	8310070352	50-528 S	Aronin, L	8310270577*	CONTRACT
	8310070352	50-528 S	Associated Piping & Engineering Corp (subs of Johnson Controls, Inc)	8310180401*	QA999
	8310070352	50-528 S			
	8310130126	50-528 A		8310180404*	QA999
	8310130126	50-528 A		8310180406*	QA999
	8310130126	50-528 A			
	8310140012	50-528 S		8310180407*	QA999
	8310140012	50-528 B		8310180411*	QA999
			Atlas Minerals	8310190106	40-3453
	8310140238	50-528 S	Atomic Industrial Forum	8310040291	PR
	8310140259	50-528 G		8310110579*	MISC
	8310140269	50-529 S			
	8310210252	50-528 A	Automated Sciences Group, Inc	8310070432*	CONTRACT
	8310240223*	50-528 Q	Automatic Switch Co	8310180400*	QA999
			Automation Industries, Inc	8310110033*	FOIA
			Avatar Systems, Inc	8310240279	FOIA
	8310250079	50-528 S	BHR Owners Group	8310110509*	FOIA
	8310250079	50-528 S			
	8310250146	50-528 A		8310110511*	FOIA
	8310250415	50-528 S		8310110518*	FOIA
	8310250415	50-528 S		8310030306*	50-460 A
			Dabcock & Wilcox Co	8310040304*	50-302 P
	8310250415	50-528 S		8310040470*	70-27
	8310250568	50-528 S			
	8310250568	50-528 S		8310070028*	70-364
	8310250568	50-528 S		8310070032*	70-364
	8310250568	50-528 S		8310070035*	70-364
	8310260156	50-528 A		8310070038*	70-364
				8310070040*	70-364
	8310260156	50-528 A			
	8310270409	50-530 S		8310070042*	70-364
	8310270413	50-529 S		8310140145*	50-269 P
	8310270430	50-528 S		8310170034	70-27
	8310270460	50-529 S		8310170065	70-27
				8310170076	70-1201
	8310310138	50-528 S			
	8310310316	50-528 S		8310170081	70-27
	8310310372	50-528 A		8310170206	70-27
Arizona, Univ of, Tucson, AZ	8310070414	NUREG		8310170229	70-27
Arkansas Power & Light Co	8310030332	50-313 P		8310170315	70-27
				8310170727	70-27
	8310030337	50-368 P			
	8310030340*	50-368 P		8310170730	70-824
	8310030353	50-313 P		8310170740	70-1201
	8310030416	50-313 F		8310180561	XPORTLIC
	8310030416	50-313 F		8310200333	71-5797
				8310200418	70-27
	8310030482	50-382 S			
	8310040149	50-368 S		8310250273	TOPREP
	8310040154	50-313 S		8310250424*	50-313 G
	8310040206	50-368 S		8310260166*	70-27
	8310040291	PR		8310260179*	70-27
			Dabcock & Wilcox Operating Plants Owners Group	8310030356*	50-313 P
	8310040538	50-368 S			
	8310060250*	50-313 F		8310110490*	FOIA
	8310060250*	50-313 F		8310140152	TOPREP
	8310060402	50-313 P		8310310413*	50-289 P
	8310060601*	50-313 F		8310030355	50-443 G
				8310110227	50-443 G
	8310060601*	50-313 F			
	8310110440*	50-313 F		8310120107	50-443 G
	8310120079	50-313 P		8310120107	50-443 G
	8310120079	50-313 P		8310120111*	50-443 G
	8310120081*	50-313 P		8310120111*	50-443 G
				8310120115*	50-443 G
	8310120081*	50-313 P			
	8310120083*	50-313 P		8310120115*	50-443 G
	8310120083*	50-313 P		8310120122*	50-443 G
	8310120447	50-313 P		8310120122*	50-443 G
	8310130097	50-368 P		8310120126*	50-443 G
				8310120126*	50-443 G
	8310130180	50-368 S			
	8310130283	50-368 S		8310120135*	50-443 G
	8310140096	50-368 F		8310120135*	50-443 G
	8310140152	TOPREP		8310120141*	50-443 G
	8310140225	50-313 P		8310120141*	50-443 G
				8310210307	FOIA
	8310180189	50-368 S	Ball, Hayden, Kiernan & Livingston		
	8310180457	50-368 S			
	8310180489	50-368 S			
	8310180529	50-368 S	Baltimore Gas & Electric Co	8310040080	50-317 P
	8310190045	50-368 R		8310040080	50-317 P
				8310040353	50-317 P
	8310190117	50-313 R		8310040542	50-317 S
	8310190292*	50-313 F		8310040542	50-317 S
	8310190292*	50-313 F			
	8310190295*	50-313 F		8310050344*	50-317 F
	8310240035	50-313 J		8310110254*	50-317 F

CORPORATE SOURCE INDEX

525

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310110254*	50-317 F	Biotechnology, Inc	8310070436	NUREG
	8310110258*	50-317 F		8310250007	FOIA
	8310110258*	50-317 F	Boeing Co	8310050387*	CONTRACT
	8310120262	50-317 S	Boeing Computer Services, Inc (subs of Boeing Co)	8310070175*	CONTRACT
	8310130313*	50-317 F	Boston Edison Co	8309190140	50-293 R
	8310170005*	50-317 F		8310030354	50-293 P
	8310170005*	50-317 F		8310120307	50-293 P
	8310190148	50-317 R		8310120330	50-293 P
	8310190148	50-317 R		8310180111	50-293 R
	8310200004	50-318 S		8310180433	50-293 F
	8310200047	50-318 S		8310180438*	50-293 F
	8310200147	50-317 S		8310180479	50-293 P
	8310200154	50-318 S		8310180483*	50-293 P
	8310200241	50-317 P		8310180491	50-293 P
	8310210210*	50-317 Q		8310190174	50-293 S
	8310210210*	50-317 Q		8310200226	50-293 S
	8310240072	50-317 P		8310250137	50-293 S
	8310240072	50-317 P		8310250282	50-293 S
	8310240134	50-317 P		8310250344	50-293 K
	8310240134	50-317 P		8310250349*	50-293 K
	8310240162	50-317 P		8310270230*	50-293 Q
	8310250221	50-318 S		8310280043	50-293 S
	8310250249	50-317 S		8310310144	50-293 P
	8310250287	50-318 S		8310310290	50-293 P
	8310250369	50-318 S		8310310306	50-293 P
	8310250410	50-317 S	Bowline Corp	8310040426*	QA999
	8310250411	50-318 S		8310040437*	QA999
	8310250443	50-318 S	Braunkohle Transport & Storage, Inc	8310250331	PR
	8310250587	50-317 S	Brookhaven National Laboratory	8310070411	NUREG
	8310250599	50-318 S		8310180613*	50-275 P
	8310270485*	50-317 F		8310180615*	50-275 P
	8310280081	50-317 S		8310180617*	50-275 P
	8310310014	50-317 F		8310180619*	50-275 P
	8310310014	50-317 F		8310180621*	50-275 P
	8310310055	50-317 F		8310180623*	50-275 P
Battelle Human Affairs Research Centers	8310310303	50-317 P		8310180624*	50-275 P
Battelle Memorial Institute	8310130128	MISC		8310180626*	50-275 P
	8310130134*	MISC		8310180627*	50-275 P
Battelle Memorial Institute, Columbus Laboratories	8310180576*	CONTRACT		8310270075*	FOIA
	8310060103*	CONTRACT		8310310114	NUREG
Battelle Memorial Institute, Pacific Northwest Laboratory	8310190318	FOIA	Brown & Root Corp (subs of Halliburton Corp)	8310310444	50-302 P
	8310270045*	FOIA		8310140024*	50-445 T
	8310030457*	50-267 Q	Brown Boveri Corp (subs of Brown Boveri & Co, Ltd)	8310120224	50-341 S
	8310050145	REG	Brown Univ	8310070196*	CONTRACT
	8310070216	REG	Burns & Roe Co	8310040232	50-397 F
	8310070317	NUREG		8310040331	50-397 S
	8310070442	NUREG	Businessmen for the Public Interest	8310250305	50-397 S
	8310110347	NUREG		8310110278	50-367 Q
	8310110475*	FOIA	C-E Operating Plants Owners Group	8310210204	50-454 Q
	8310110480*	FOIA		8310250377	TDPREP
	8310170669	70-984	C. Itch & Co (America), Inc.	8310060187	XPORTLIC
	8310170675*	70-984	CEPA	8310260273	50-352 Q
	8310260381	NUREG	Cable News Network, Inc.	8310240315	FOIA
	8310310106	NUREG	California Polytechnic State Univ, San Luis Obispo, CA	8310110344*	CONTRACT
	8310310208	NUREG	California, State of	8310040209	50-275 Q
Bear Creek Uranium Co	8310310268	NUREG		8310040209	50-275 Q
	8310030199	40-8452		8310040212*	50-275 Q
	8310030241	40-8452		8310040212*	50-275 Q
	8310030250*	40-8452		8310040219*	50-275 Q
Bechtel Corp	8310040127*	50-352 A		8310040219*	50-275 Q
	8310040129*	50-352 A		8310040228	50-275 Q
	8310040131*	50-352 A		8310110053	50-275 Q
	8310040355*	50-317 P		8310120376	50-275 Q
	8310040488*	QA999		8310120376	50-275 Q
	8310120384*	50-352 Q		8310120381*	50-275 Q
	8310130131*	50-206 P		8310120381*	50-275 Q
	8310130323*	50-206 P		8310120386*	50-275 Q
	8310140238*	50-331 R		8310200178	50-275 T
	8310140274*	50-529 S		8310200178	50-275 T
	8310170244*	50-250 F		8310200184*	50-275 T
	8310210142*	50-329 A		8310200184*	50-275 T
	8310210229*	50-275 P		8310200190*	50-275 T
	8310240212*	50-528 Q		8310200190*	50-275 T
	8310250128*	50-206 P		8310200195*	50-275 T
	8310250408*	QA999		8310200195*	50-275 T
	8310280224*	50-358 A		8310200195*	50-275 T
	8310280229*	50-358 A		8310240169	50-275 U
	8310280231*	50-358 A		8310240169	50-275 U
	8310310074	50-482 S		8310250045	50-275 U
Benton City Technology	8310270041*	50-320 P		8310260180*	FOIA
	8310270044*	50-320 P			
Big State X-Ray	8310150253	71-503		8310260185*	FOIA

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310260277	50-275 G		8310070246*	50-324 G
	8310260317*	FOIA		8310070291	50-324 F
	8310270338	50-275 G		8310070291	50-324 F
	8310270338	50-275 G		8310070293*	50-324 F
	8310270348*	50-275 G		8310070293*	50-324 F
				8310070295*	50-324 F
	8310270348*	50-275 G		8310070295*	50-324 F
	8310270377*	50-275 G		8310070308	50-261 S
	8310310141	50-275 G		8310070322	50-261 S
California, Univ of, Los Angeles, CA	8310030394	50-142 G		8310110119	50-400 E
	8310200184*	50-275 T			
				8310110119	50-400 E
Canada, Atomic Energy Control Board	8310180468	REQD		8310110142	TOPREP
	8310200331	XPORTLIC		8310110145	50-261 F
	8310110270	50-413 T		8310110150	50-400 G
Carolina Environmental Study Group	8309200175	50-324 S		8310110150	50-400 G
Carolina Power & Light Co	8310030161	50-261 P			
				8310110155*	50-400 G
	8310030202	50-324 S		8310110155*	50-400 G
	8310030209	50-324 S		8310110407*	50-400 G
	8310030422	50-324 S		8310110407*	50-400 G
	8310030426	50-261 S		8310110409*	50-400 G
	8310030441	50-400 G			
				8310110409*	50-400 G
	8310030441	50-400 G		8310110412*	50-400 G
	8310030478*	50-400 G		8310110412*	50-400 G
	8310030478*	50-400 G		8310120180	50-400 E
	8310030526	50-400 S		8310120180	50-400 E
	8310030527	PRM			
				8310120246	50-400 S
	8310040224*	50-400 G		8310120266	50-400 F
	8310040262	50-261 G		8310120268*	50-400 F
	8310040285*	50-261 G		8310120268*	50-400 F
	8310040297	PR		8310120300	50-325 S
	8310040306*	50-324 G			
				8310120367	50-400 S
	8310040362	50-324 S		8310120367	50-400 S
	8310040363	TOPREP		8310120407	50-261 P
	8310040380	50-324 P		8310120426	50-324 S
	8310040385	50-324 P		8310130124	50-324 R
	8310040385	50-324 P			
				8310130124	50-324 R
	8310040388*	50-324 P		8310130240	50-400 E
	8310040388*	50-324 P		8310130293*	50-400 E
	8310040412	50-325 S		8310130294*	50-400 E
	8310040473	50-261 G		8310140011	50-325 S
	8310040478	50-261 G			
				8310140053	50-325 S
	8310040516	50-261 S		8310140126	50-400 E
	8310040538	50-400 G		8310170414	50-325 S
	8310040538	50-400 G		8310170541	50-261 S
	8310040541*	50-400 G		8310170543	50-400 G
	8310040541*	50-400 G			
				8310170543	50-400 G
	8310040582	50-325 S		8310170596	50-324 S
	8310040593	50-324 S		8310170604	50-324 S
	8310040600*	50-400 G		8310170608*	50-400 G
	8310040600*	50-400 G		8310170608*	50-400 G
	8310040603*	50-400 G			
				8310170620*	50-400 G
	8310040603*	50-400 G		8310170620*	50-400 G
	8310040606*	50-400 S		8310170630*	50-400 G
	8310060036	50-400 S		8310170630*	50-400 G
	8310060036	50-400 S		8310180174	50-261 P
	8310060036	50-324 P			
				8310180311	50-400 E
	8310060054	50-324 P		8310180311	50-400 E
	8310060066*	50-324 P		8310180427	50-324 F
	8310060066*	50-324 P		8310180427	50-324 F
	8310060075	50-324 S		8310180474	50-400 E
	8310060188	50-400 G			
				8310190141	50-325 S
	8310060188	50-400 G		8310190162	50-261 G
	8310060193*	50-400 G		8310190171	50-400 S
	8310060193*	50-400 G		8310190227	50-325 S
	8310060203*	50-400 G		8310190238	50-324 S
	8310060203*	50-400 G			
				8310200058	50-324 P
	8310060212*	50-400 G		8310200058	50-324 P
	8310060218	50-325 S		8310200143	50-324 G
	8310060222*	50-400 G		8310200166	50-324 G
	8310060222*	50-400 G		8310200168*	50-324 G
	8310060237	50-324 S			
				8310200206	50-324 P
	8310060238*	50-400 G		8310200206	50-324 P
	8310060238*	50-400 G		8310210024	50-400 E
	8310060323	50-400 G		8310210024	50-400 E
	8310060323	50-400 G		8310210046	50-261 P
	8310060336	50-400 S			
				8310210046*	50-261 P
	8310060336	50-400 S		8310210136	50-400 F
	8310060383	50-324 S		8310210136	50-400 F
	8310060413	50-261 P		8310210245	50-261 P
	8310060418*	50-261 P		8310210246*	50-261 P
	8310060561*	50-324 F			
				8310210264	50-324 P
	8310060564*	50-324 F		8310210264	50-324 P
	8310060567*	50-324 F		8310210268*	50-324 P
	8310070120	50-400 A		8310210268*	50-324 P
	8310070120	50-400 A		8310240183	50-400 G
	8310070136	50-261 S			

CORPORATE SOURCE INDEX

527

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310240183	50-400 Q		8310250680	WASTE MGT
	8310250036	50-324 P	Chemical Waste Management, Inc	8310120319*	50-277 R
	8310250036	50-324 P	Chiapetta, Welch & Associates, Ltd	8310120024*	CONTRACT
	8310250120	50-324 F	Christa-Maria	8310040545	50-155 T
	8310250211*	50-400 Q		8310040620	50-155 T
	8310250237	50-324 S		8310040621*	50-155 T
	8310250396	50-324 S		8310040624*	50-155 T
	8310250450	50-400 R	Cincinnati Alliance for Responsible Energy	8310260016	FOIA
	8310250450	50-400 R	Cincinnati Gas & Electric Co	8310040336	50-358 F
	8310250460*	50-324 Q		8310040341*	50-358 F
	8310250480*	50-324 Q		8310040459	50-358 K
	8310250521	50-325 S		8310110269	50-358 Q
	8310250571	50-261 Q		8310110286	50-358 Q
	8310250571	50-261 Q		8310120252	50-358 A
	8310250596*	50-261 Q		8310120304	50-358 A
	8310250608*	50-261 Q		8310120383	50-358 S
	8310250638	50-400 E		8310120442	50-358 S
	8310250638	50-400 E		8310130237*	50-358 A
	8310260134	50-400 E		8310130242	50-358 K
	8310260134	50-400 E		8310140136*	50-358 Q
	8310260141	50-324 P		8310170348	50-358 S
	8310260141	50-324 P		8310170404	50-358 S
	8310260143*	50-324 P		8310170448	50-358 S
	8310260143*	50-324 P		8310170454*	50-358 Q
	8310260147	50-400 E		8310170485	50-358 S
	8310260147	50-400 E		8310170515	50-358 A
	8310260148*	50-324 P		8310170518*	50-358 A
	8310260148*	50-324 P		8310170649	50-358 S
	8310260152	50-400 E		8310180296	50-358 S
	8310260152	50-400 E		8310200083	50-358 S
	8310260259	50-400 E		8310200098	50-358 S
	8310260259	50-400 E		8310200209	50-358 A
	8310280014	50-400 E		8310200212*	50-358 A
	8310280014	50-400 E		8310200215*	50-358 A
	8310280051	50-400 Q		8310200222*	50-358 A
	8310280051	50-400 Q		8310200227*	50-358 A
	8310280164	50-400 Q		8310200230*	50-358 A
	8310280164	50-400 Q		8310200234*	50-358 A
	8310310027	50-261 P		8310210110*	50-358 Q
	8310310032*	50-261 P		8310210113*	50-358 Q
Center for Law in the Public Interest	8310310146	50-400 Q		8310210153	50-358 Q
	8310040212*	50-275 Q		8310240161	50-358 Q
	8310040539	50-275 Q		8310250366	50-358 S
	8310050421	50-275 Q		8310250487	50-358 S
	8310110058	50-275 Q		8310250586*	50-358 Q
	8310110058	50-275 Q		8310260098	50-358 Q
	8310110127	50-275 Q		8310250109	50-358 H
	8310110127	50-275 Q	Cincinnati, OH	8310040230	50-445 Q
	8310110317	50-275 Q	Citizens Association for Sound Energy	8310120414	50-445 Q
	8310130243	50-275 Q		8310180163*	50-445 Q
	8310180160	50-275 Q		8310180339	50-445 Q
	8310180160	50-275 Q		8310180339	50-445 Q
	8310180248	50-275 Q		8310180342*	50-445 Q
	8310180248	50-275 Q		8310180342*	50-445 Q
	8310210228	50-275 T		8310280059	50-445 Q
	8310210228	50-275 T		8310260249	50-498 Q
	8310210242*	50-275 T	Citizens Concerned About Nuclear Power, Inc	8310260269	50-498 Q
	8310210242*	50-275 T		8310170052	FOIA
	8310240188	50-275 Q		8310190321	FOIA
	8310250043	50-275 Q	Citizens Engaged in Removal of Toxic Substances, Inc.	8310040227	50-440 E
	8310260236	50-275 Q	Citizens for Safe Energy	8310040227	50-440 E
	8310260236	50-275 Q	Cleveland Electric Illuminating Co.	8310040231*	50-440 E
	8310260277	50-275 Q		8310040231*	50-440 E
	8310270358	50-275 Q		8310040234*	50-440 E
	8310270358	50-275 Q		8310040234*	50-440 E
	8310280097	50-275 Q		8310040234*	50-440 E
	8310280097	50-275 Q		8310040234*	50-440 E
	8310310141	50-275 Q		8310040234*	50-440 E
	8310310141	50-275 Q		8310040404	50-440 B
Centronic, Inc	8310180541	XP0RTLIC		8310040404	50-440 B
	8310040225	50-483 Q		8310030520	50-440 Q
Charles & Hoare	8310270527	50-219 S		8310060340	50-440 B
Chamlin, Schottland, Rosen, Cavanagh & Uliano	8310050494*	50-155 Q		8310060340	50-440 B
Charlevoix, MI	8310050501*	50-155 Q		8310060392	50-440 B
	8310050507*	50-155 Q		8310060392	50-440 B
	8310140076*	50-155 T		8310120286	50-440 B
	8310140076*	50-155 T		8310120286	50-440 B
Chem-Nuclear Systems, Inc.	8310170192	71-9105		8310170469	50-440 B
	8310170195*	71-9105		8310170613	70-2968
	8310170232	71-6697		8310200238	50-440 E
	8310170748	71-6601		8310210112	50-440 S
	8310170750*	71-6601		8310240165	50-440 A
	8310190332	71-5805		8310250483	50-441 S
	8310190351	71-6771		8310270030	50-440 S

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310270030	50-440 G		8310120427	50-454 E
	8310270038	TOPREP		8310120427	50-454 E
	8310270252	50-440 G		8310120427	50-454 E
	8310270252	50-440 G		8310120427	50-454 E
	8310270330	50-440 G		8310120433	50-373 P
	8310310050	50-440 A		8310120433	50-373 P
	8310310050	50-440 A		8310130132	50-374 A
	8310310378	50-440 A		8310140045	50-373 S
Cleveland-Cliffs Iron Co	8310240052	40-8714		8310140049*	50-10 G
Coalition for Safe Power	8310040200	50-460 G		8310140057	50-373 S
	8310310063	50-317 P		8310140069	50-373 S
Colorado, State of	8310130066	WASTE MGT		8310140073	50-373 S
Combustion Engineering, Inc	8310040357*	50-317 P		8310140104*	50-10 Q
	8310060115*	CONTRACT		8310140133	50-254 G
	8310070274	50-470 A		8310140175*	50-295 G
	8310130109*	50-368 P		8310140256	50-304 S
	8310180027	70-1100		8310140263	50-373 S
	8310180031*	70-1100		8310170234	71-9010
	8310190192	70-1100		8310170271	50-254 S
	8310190215	70-1100		8310170337	50-237 Q
	8310200245*	50-317 P		8310170337	50-237 Q
	8310240313	XPERTLIC		8310170337	50-237 Q
	8310250135	XPERTLIC		8310170346	50-454 Q
	8310250158	XPERTLIC		8310170346	50-454 Q
	8310260160*	50-328 A		8310170353	50-254 R
	8310310287*	70-1100		8310170353	50-254 R
Commerce, Dept of, National Bureau of	8310110089*	CONTRACT		8310170356*	50-454 Q
Standards				8310170356*	50-454 Q
Commerce, Dept of, Natl Oceanographic &	8310070331*	CONTRACT		8310170411	50-454 S
Atmospheric Administration				8310170411	50-454 S
	8310120367	50-29 P		8310170411	50-454 S
	8310120374*	50-29 P		8310170411	50-454 S
	8310190035	FOIA		8310170411	50-454 S
Committee to Bridge the Gap	8310030238*	50-373 F		8310170426	50-374 A
Commonwealth Edison Co	8310030311	PR		8310170491	50-254 S
	8310040136*	50-10 F		8310170543	50-254 P
	8310040162*	50-456 G		8310170553	50-237 S
	8310040260*	50-454 G		8310170557	50-304 S
	8310040320	50-237 P		8310170561	50-295 S
	8310040444	50-373 F		8310170573	50-454 S
	8310040444	50-373 F		8310170573	50-454 S
	8310040471	50-237 P		8310170573	50-454 S
	8310040554	50-454 K		8310170573	50-454 S
	8310040554	50-454 K		8310170579	50-304 S
	8310040554	50-454 K		8310170588	50-295 S
	8310040554	50-454 K		8310170609	50-304 S
	8310040554	50-454 K		8310170661	50-265 S
	8310060184	50-373 S		8310170671*	50-454 Q
	8310060198	50-373 S		8310170711*	50-373 F
	8310060249	50-265 S		8310170718	70-2973
	8310060271	50-373 S		8310180109	50-254 R
	8310060314	50-454 G		8310180110	50-295 Q
	8310060317	50-454 Q		8310180110	50-295 Q
	8310060317	50-454 Q		8310180249	50-373 K
	8310060321*	50-454 Q		8310180252	50-454 C
	8310060321*	50-454 Q		8310180263	50-254 R
	8310060373	50-237 S		8310180263	50-254 R
	8310060545*	50-254 F		8310180273	50-373 S
	8310060545*	50-254 F		8310180275	50-454 Q
	8310110117	50-295 P		8310180275	50-454 Q
	8310110117	50-295 P		8310180275	50-454 Q
	8310110123*	50-373 F		8310180275	50-454 Q
	8310110302	50-456 C		8310180275*	50-454 Q
	8310110302	50-456 C		8310180279*	50-454 Q
	8310110304*	50-456 C		8310180281	50-373 P
	8310110304*	50-456 C		8310180281	50-373 P
	8310110327*	50-254 F		8310180351*	50-456 C
	8310110327*	50-254 F		8310180351*	50-456 C
	8310110464*	FOIA		8310180397	50-373 P
	8310110478*	50-237 S		8310180397	50-373 P
	8310120061	50-265 Q		8310180425	50-373 P
	8310120108	50-295 R		8310190258	50-373 P
	8310120108	50-295 R		8310200082*	50-254 F
	8310120109	50-373 S		8310200082*	50-254 F
	8310120158	50-254 S		8310200131	50-295 P
	8310120174	50-295 S		8310200273	50-237 P
	8310120189	50-237 P		8310200273	50-237 P
	8310120219	50-456 E		8310200273	50-237 P
	8310120219	50-456 E		8310200273	50-237 P
	8310120273	50-237 R		8310200424*	50-373 F
	8310120273	50-237 R		8310210016	50-265 S
	8310120290	50-373 Q		8310210054	50-265 S
	8310120401*	50-454 Q		8310210056	50-374 S
	8310120409	50-265 Q		8310210127	50-237 S
	8310120427	50-454 E		8310210165	50-249 S

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310210218	50-304 S		8310120368*	50-352 Q
	8310210222	50-373 S		8310120377*	50-352 Q
	8310210234	50-454 F		8310120377*	50-352 Q
	8310210234	50-454 F		8310180132	50-352 Q
	8310210236*	50-454 F		8310180132	50-352 Q
	8310210236*	50-454 F		8310180139*	50-352 Q
	8310210236*	50-454 F		8310180139*	50-352 Q
	8310210297	50-237 S		8310180146*	50-352 Q
	8310210313	50-237 S		8310180146*	50-352 Q
	8310210377*	50-295 F		8310180234	50-352 Q
	8310240067	50-329 Q		8310180234	50-352 Q
	8310240071	50-10 J		8310180237*	50-352 Q
	8310240077*	50-456 Q		8310180237*	50-352 Q
	8310250293	50-254 P		8310180243	50-352 Q
	8310250293	50-254 P		8310180243	50-352 Q
	8310250298*	50-254 P		8310210153	50-358 Q
	8310250298*	50-254 P		8310270381	50-354 Q
	8310250298*	50-254 P		8310310231	50-352 Q
	8310250298*	50-254 P	Consolidated Edison Co of New York, Inc	8310040228	50-247 F
	8310250302*	50-254 P		8310120194	50-247 P
	8310250302*	50-254 P		8310120242	50-247 F
	8310250361*	50-373 Q		8310120243*	50-247 F
	8310260001	50-10 P		8310120297	50-247 F
	8310270017*	50-10 F		8310120366	50-247 P
	8310270017*	50-10 F		8310130111	50-3 P
	8310270017*	50-10 F		8310130111	50-3 P
	8310270028*	50-254 F		8310130115*	50-3 P
	8310270028*	50-254 F		8310130115*	50-3 P
	8310270032*	50-254 F		8310130119*	50-3 P
	8310270032*	50-254 F		8310130119*	50-3 P
	8310270188	50-456 S		8310190163	50-247 S
	8310270267	50-373 S		8310260304	50-3 F
	8310270274	50-373 S		8310270126	FDIA
	8310270276	50-373 S		8310280094	50-247 S
	8310270289	50-295 S		8310280261*	50-3 F
	8310270400	50-254 S		8310280267*	50-3 F
	8310270404	50-254 S	Consumers Power Co	8309090259	50-329 S
	8310270419	50-265 S		8310030465	50-329 Q
	8310270424	50-249 S		8310040122	50-329 A
	8310270477	50-249 S		8310040264	50-155 P
	8310270490	50-373 S		8310040264*	50-155 P
	8310270537*	50-10 F		8310040265*	50-155 T
	8310280209*	50-10 F		8310040367*	50-155 T
	8310280215*	50-373 F		8310040367*	50-155 T
	8310280314*	50-10 F		8310040373*	50-155 T
	8310310049	50-295 P		8310040376	50-155 T
	8310310054	50-254 P		8310040381*	50-155 T
	8310310054	50-254 P		8310040505	50-155 T
	8310310060	50-295 P		8310040519*	50-155 T
Community Legal Services, Inc	8310260273	50-352 Q		8310040548	50-155 T
Jonas Corp	8310180431*	QA999		8310040551	50-155 T
Connecticut Yankee Atomic Power Co	8310040334	PR		8310040553	50-155 T
	8310050431	PR		8310040597*	50-155 T
	8310060262*	50-213 F		8310040560*	50-155 T
	8310120270	PR		8310040564*	50-155 T
	8310120375	50-213 P		8310040568*	50-155 T
	8310180344	50-213 P		8310040594	50-155 T
	8310180409	50-213 P		8310040611*	50-155 T
	8310190007	50-213 R		8310050296	50-329 A
	8310250315	50-213 S		8310050296	50-329 A
	8310250321	50-213 S		8310050322	50-329 A
	8310270021*	50-213 F		8310050322	50-329 A
	8310280313*	50-213 F		8310050463	50-255 P
Jonner & Wetterhahn	8310040627	50-352 Q		8310050465*	50-255 P
	8310050515	50-352 Q		8310050469*	50-255 P
	8310110208	50-358 Q		8310050483	50-155 Q
	8310110216*	50-358 Q		8310050486*	50-155 Q
	8310110269	50-358 Q		8310050489*	50-155 Q
	8310110275	50-352 Q		8310050491*	50-155 Q
	8310110275	50-352 Q		8310050494*	50-155 Q
	8310110277*	50-352 Q		8310050501*	50-155 Q
	8310110277*	50-352 Q		8310050507*	50-155 Q
	8310110284*	50-352 Q		8310060024	50-155 P
	8310110284*	50-352 Q		8310060030*	50-155 P
	8310110284*	50-358 Q		8310060047	50-255 P
	8310110287*	50-352 Q		8310060080	50-155 P
	8310110287*	50-352 Q		8310060221	50-255 S
	8310110297*	50-352 Q		8310070142	50-329 A
	8310110297*	50-352 Q		8310070142	50-329 A
	8310110305	50-352 Q		8310070177	50-255 P
	8310110312*	50-352 Q		8310110024*	50-155 F
	8310110312*	50-352 Q		8310110045	50-155 T
	8310120364	50-352 Q		8310110063	50-155 Q
	8310120364	50-352 Q		8310110259*	50-155 F
	8310120368*	50-352 Q		8310110293*	50-155 T

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310110310	50-329 Q		8310250250	50-255 S
	8310120064	50-255 S		8310250462	50-255 S
	8310120110	50-155 S		8310250507*	50-329 A
	8310120211	50-155 T		8310250507*	50-329 A
	8310120215*	50-155 T		8310260118	50-155 F
	8310120218*	50-155 T		8310260202	50-400 Q
	8310120221*	50-155 T		8310260202	50-400 Q
	8310120225*	50-155 T		8310260209*	50-400 Q
	8310120229*	50-155 T		8310260209*	50-400 Q
	8310120233*	50-155 T		8310260331	50-329 A
	8310120249	50-255 S		8310260331	50-329 A
	8310120254	50-255 A		8310270066	50-329 A
	8310120318	50-255 Q		8310270066	50-329 A
	8310120320	50-329 A		8310270162	50-255 S
	8310120327*	50-155 Q		8310270171*	50-329 Q
	8310120331	50-255 S		8310270171*	50-329 Q
	8310120365	50-155 Q		8310270219	50-155 F
	8310130174	50-155 T		8310270221*	50-155 F
	8310130179*	50-155 T		8310270245	50-155 S
	8310130214	50-155 T		8310270265	50-329 S
	8310130218*	50-155 T		8310270352*	50-329 Q
	8310130276	50-155 T		8310270352*	50-155 F
	8310140074	50-155 T		8310270352*	50-155 F
	8310140076*	50-155 T		8310270352*	50-155 F
	8310140078*	50-155 T		8310270352*	50-155 F
	8310140273*	50-329 A		8310270352*	50-155 F
	8310140273*	50-329 A		8310270352*	50-155 F
	8310170257	50-329 A		8310270352*	50-155 F
	8310170257	50-329 A		8310270352*	50-155 F
	8310170351	50-255 S		8310270352*	50-155 F
	8310170420	50-155 Q		8310280073	50-329 Q
	8310170421	50-329 Q		8310280073	50-329 Q
	8310170439*	50-329 A		8310280078*	50-329 Q
	8310170465	50-155 S		8310310078	50-329 R
	8310170486	50-155 S		8310310078	50-329 R
	8310170552	50-155 S		8310310139	50-155 Q
	8310170714	50-329 A		8310310145	50-155 Q
	8310170714	50-329 A		8310310206	50-155 Q
	8310180222	50-155 Q		8310310366	50-329 A
	8310180224*	50-155 Q		8310310366	50-329 A
	8310180230	50-155 Q		8310310367	50-329 A
	8310180335	50-155 Q		8310310369	50-329 A
	8310180348	50-155 Q		8310310376	50-155 F
	8310180464	50-255 F		8310310379*	50-155 F
	8310180629*	50-329 Q		8310310383*	50-155 F
	8310190048	50-329 Q		8310310391	50-155 Q
	8310190048	50-329 Q		8310180299*	QA999
	8310200225	50-309 Q	Control Data Corp	8310270038	TOPREP
	8310200254	50-329 Q	Coordinating Agency for Supplier		
	8310200254	50-329 Q	Evaluation (CASE Assoc)		
	8310200256	50-255 Q	Critical Mass Energy Project	8310270055*	TOPREP
	8310200265	50-329 A		8206140403*	FOIA
	8310200265	50-329 A			
	8310200417*	50-155 F	Cumberland County, PA	8310130219	50-289 H
	8310200423*	50-155 F	D'Appolonia Consulting Engineers, Inc	8310120225*	50-155 T
	8310210027	50-329 A		8310130299*	50-155 F
	8310210027	50-329 A	Dairyland Power Cooperative	8310050101	50-409 P
	8310240023	50-329 A		8310130311*	50-409 F
	8310240023	50-329 A			
	8310240027	50-329 A		8310170159	50-409 P
	8310240029	50-329 A		8310170364	50-409 S
	8310240029	50-329 A		8310190027	50-409 R
	8310240029	50-329 A		8310210002	50-409 S
	8310240033	50-329 A		8310310163*	50-409 Q
	8310240033	50-329 A			
	8310240050	50-329 A	DataFlow Systems, Inc	8310280137*	CONTRACT
	8310240050	50-329 A	Dauphin County, PA	8310120171	50-320 H
	8310240063	50-329 A	DeKalb Area Alliance For Responsible	8310040205	50-454 Q
	8310240084	50-329 A	Energy		
	8310240128	50-155 Q		8310200097	50-454 Q
	8310240131	50-329 A		8310210219*	50-454 Q
	8310240132*	50-155 Q			
	8310240136	50-329 A	Debevoise & Liberman	8310030406	50-413 Q
	8310240172	50-329 Q		8310040008	PR
	8310240172	50-329 Q		8310060316	50-445 Q
	8310250041	50-329 Q		8310110068	50-491 Q
	8310250041	50-329 Q		8310110322	50-445 Q
	8310250053	50-329 Q			
	8310250053	50-329 Q		8310110560	FOIA
	8310250058	50-329 A		8310140022	50-445 T
	8310250058	50-329 A		8310140066	50-508 Q
	8310250073	50-329 Q		8310140086	50-508 Q
	8310250073	50-329 Q		8310170412	50-445 Q
	8310250073	50-329 Q		8310170412	50-445 Q
	8310250101	50-329 S		8310170417*	50-445 Q
	8310250101	50-329 S		8310170417*	50-445 Q
	8310250203*	50-255 Q		8310180158	50-445 Q
	8310250203*	50-255 Q		8310210184	50-445 Q
				8310270085	FOIA
				8310280126	50-508 Q
				8310310175	50-508 Q

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Debevoise & Plimpton	8310120034*	50-201 I	8310110141*	50-269 F	
Detatur, AL	8310030420*	CONTRACT	8310110294	50-413 Q	
Defense, Dept of, Defense Nuclear Agency	8310210413*	50-170 F	8310110294	50-413 Q	
Del Research Corp	8310050335	NUREG	8310110418*	50-369 F	
Delaware, State of	8310250038	50-272 G	8310110421*	50-369 F	
Detroit Edison Co	8310120098	50-341 A	8310120413	50-369 B	
	8310120190	50-341 A	8310140143	50-269 P	
	8310120311*	50-341 Q	8310140157	50-269 B	
	8310130018	50-341 E	8310140205	50-369 P	
	8310130229	50-341 A	8310140205	50-369 P	
	8310170594*	50-341 K	8310140207*	50-369 P	
	8310170600*	50-341 K	8310140207*	50-369 P	
	8310180034*	50-341 F	8310140233	50-269 P	
	8310180037*	50-341 F	8310140233	50-269 P	
	8310180042*	50-341 F	8310140233	50-269 P	
	8310180470	50-341 A	8310170248	50-369 B	
	8310200107	50-341 H	8310170334	71-9039	
	8310210052	50-341 A	8310170384	50-369 B	
	8310210066	50-341 B	8310170430	50-369 B	
	8310210281	50-341 A	8310170536	50-269 B	
	8310250114	50-341 B	8310180100	50-369 R	
	8310270447	50-341 B	8310180100	50-369 R	
Doc-Search Associates	8310270465	FOIA	8310180167	50-269 R	
Doherty, J F	8310040481	50-293 Q	8310180444	50-269 F	
	8310110202	50-443 Q	8310180444	50-269 F	
	8310110202	50-443 Q	8310180444	50-269 F	
	8310110316	50-443 Q	8310180444	50-269 F	
	8310110316	50-443 Q	8310180444	50-269 F	
	8310260262	50-443 Q	8310190165	50-413 E	
Don L. Warner, Inc	8310170030	70-820	8310190165	50-413 E	
Dorsey, J A	8310040498	50-392 Q	8310190193	50-413 E	
Dougherty, J B	8310200105	50-322 Q	8310190193	50-413 C	
Dow Chemical Co	8310110097*	FOIA	8310190262	50-413 E	
	8310110125*	FOIA	8310190262	50-413 E	
Drexel Univ , Philadelphia, PA	8308310912*	50-267 Q	8310210005	50-369 B	
Duke Power Co	8310030396	PR	8310210020	50-369 B	
	8310030406	50-413 Q	8310210077	50-370 B	
	8310030406	50-413 Q	8310210111	50-413 B	
	8310030409*	50-413 Q	8310210111	50-413 B	
	8310030409*	50-413 Q	8310210177	50-413 A	
	8310030423	50-287 B	8310210179	50-413 A	
	8310040016	50-413 E	8310210186	50-413 T	
	8310040287	50-413 F	8310210186	50-413 T	
	8310040319*	50-413 Q	8310210192*	50-413 T	
	8310040368	50-369 P	8310210192*	50-413 T	
	8310040403	50-370 B	8310210308	50-369 B	
	8310040471	50-369 P	8310210309	50-369 B	
	8310040471	50-369 P	8310210312	50-369 J	
	8310040482*	50-369 P	8310240014*	50-413 T	
	8310040482*	50-369 P	8310240017*	50-413 T	
	8310040492*	50-269 Q	8310240018*	50-413 T	
	8310040492*	50-269 Q	8310240030*	50-413 T	
	8310040492*	50-269 Q	8310240030*	50-413 T	
	8310040575	50-269 Q	8310240038*	50-413 T	
	8310040575	50-269 Q	8310240038*	50-413 T	
	8310040575	50-269 Q	8310240040*	50-413 T	
	8310040577	50-413 Q	8310240040*	50-413 T	
	8310040038	50-413 B	8310240043*	50-413 T	
	8310040038	50-413 B	8310240043*	50-413 T	
	8310040032	50-413 B	8310240047*	50-413 T	
	8310040052	50-413 B	8310240047*	50-413 T	
	8310040058	50-369 B	8310240049*	50-413 T	
	8310040058	50-369 B	8310240049*	50-413 T	
	8310040063*	50-369 B	8310240053*	50-413 T	
	8310040068*	50-369 B	8310240053*	50-413 T	
	8310040255	50-370 B	8310240055*	50-413 T	
	8310040268*	50-369 F	8310240055*	50-413 T	
	8310040275	50-413 Q	8310240056*	50-413 T	
	8310040310	50-413 T	8310240056*	50-413 T	
	8310040310	50-413 T	8310240057*	50-413 T	
	8310040384	50-369 B	8310240057*	50-413 T	
	8310040426	50-269 B	8310240060*	50-413 T	
	8310070131*	50-370 F	8310240060*	50-413 T	
	8310070143*	50-269 F	8310240061*	50-413 T	
	8310070152*	50-269 F	8310240062*	50-413 T	
	8310070152*	50-269 F	8310240063*	50-413 T	
	8310070152*	50-269 F	8310240063*	50-413 T	
	8310110068	50-491 Q	8310240065*	50-413 T	
	8310110076*	50-269 F	8310240068*	50-413 T	
	8310110076*	50-269 F	8310240068*	50-413 T	
	8310110076*	50-269 F	8310240073*	50-413 T	
	8310110076*	50-269 F	8310240073*	50-413 T	
	8310110077*	50-369 F	8310240073*	50-413 T	
	8310110079*	50-369 F	8310240073*	50-413 T	
	8310110080*	50-269 F	8310240073*	50-413 T	
	8310110080*	50-269 F	8310240073*	50-413 T	
	8310110080*	50-269 F	8310240073*	50-413 T	
	8310110080*	50-269 F	8310240073*	50-413 T	

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310240076*	50-413 T		8310310067*	50-250 P
	8310240076*	50-413 T		8310310068*	50-250 P
	8310240151	50-269 P	Eberline Instrument Corp	8310060412	XPORTLIC
	8310250071	50-369 S		8310250658	XPORTLIC
	8310250074	50-369 S	Eddleman, W	8310030367	50-400 G
	8310250074	50-369 S		8310030367	50-400 G
	8310250076*	50-369 S		8310030369*	50-400 G
	8310250080*	50-369 S		8310030369*	50-400 G
	8310250524*	50-369 G		8310030372*	50-400 G
	8310250665*	50-269 G		8310030372*	50-400 G
	8310270048	50-370 S		8310030375*	50-400 G
	8310270079	50-269 G		8310030375*	50-400 G
	8310270136*	50-369 F		8310030377*	50-400 G
	8310270146*	50-369 F		8310030377*	50-400 G
	8310270173	50-369 S		8310030380*	50-400 G
	8310270209	50-370 S		8310030380*	50-400 G
	8310270310	50-370 S		8310040918	50-400 G
	8310270412	50-269 S		8310040923	50-400 G
	8310270482	50-413 S		8310120370	50-400 G
	8310270482	50-413 S		8310140072	50-400 G
	8310280029	50-269 F		8310250037	50-400 G
	8310280029	50-269 F		8310250037	50-400 G
	8310280029	50-269 F		8310250040	50-400 G
	8310280096	50-413 E		8310250040	50-400 G
	8310280105	50-269 P		8310250086	50-400 G
	8310280105	50-269 P		8310270351	50-400 G
	8310280124	50-269 F	Edgar, G L	8310260292	50-537 G
	8310310416	50-369 F	Edlow International Co	8310060090	XPORTLIC
	8310310416	50-369 F		8310060130	XPORTLIC
Duquesne Light Co	8310030360*	50-412 G		8310180095	XPORTLIC
	8310040400	50-334 G		8310180113	XPORTLIC
	8310040411*	50-334 G		8310180562	XPORTLIC
	8310040561	50-334 F		8310180569*	XPORTLIC
	8310040569*	50-334 F		8310240301	XPORTLIC
	8310120257	50-334 P		8310240302*	XPORTLIC
	8310140208	50-334 F		8310030650	TOPREP
	8310180322*	50-334 G	Electric Power Research Institute	8310180118	NUREG
	8310180432	50-334 F		8310210198*	CONTRACT
	8310180434*	50-334 F	Energy Incorporated	8306030372*	50-286 P
	8310190019	50-334 R		8306080059*	50-312 P
	8310210238	50-334 P		8306080069*	50-336 P
	8310210240*	50-334 P		8306080106*	50-302 P
	8310240146	50-334 F		8306080112*	50-272 P
	8310250546	50-334 S		8306130456*	50-346 P
	8310250595	50-334 S		8310030605	WASTE MGT
	8310270154	50-334 P	Energy, Dept of	8310030610*	WASTE MGT
	8310280010	50-334 S		8310110624	WASTE MGT
	8310310062	50-412 K		8310110626*	WASTE MGT
	8310310089	50-412 A		8310130008	WASTE MGT
	8310310309	50-412 F		8310130067	WASTE MGT
EDS Nuclear, Inc	8310180481*	50-387 P		8310130071*	WASTE MGT
	8310180485*	50-387 P		8310170027	71-9070
	8310180493*	50-387 P		8310170139	WASTE MGT
	8310180497*	50-387 P		8310170170	71-5595
	8310180498*	50-387 P		8310170175*	71-5595
	8310180501*	50-387 P		8310170306	71-6550
	8310180504*	50-387 P		8310170338	WASTE MGT
	8310180509*	50-387 P		8310170342	71-4909
	8310180510*	50-387 P		8310170739	71-6400
	8310180514*	50-387 P		8310170744	71-5939
	8310180518*	50-387 P		8310180138	40-8768
	8310180520*	50-387 P		8310190335	71-5595
	8310180523*	50-387 P		8310240253	WASTE MGT
	8310180529*	50-387 P		8310240255	WASTE MGT
EQ&O, Inc	8310040123*	50-395 P		8310240271*	WASTE MGT
	8310050331	NUREG		8310250095	WASTE MGT
	8310050335	NUREG		8310250102	WASTE MGT
	8310250570*	50-409 P		8310250107*	WASTE MGT
	8310310346*	50-275 G		8310250147	ORO
	8310310354*	50-275 G		8310250416	50-275 G
ENBA, Inc.	8310060191*	CONTRACT		8310250416	50-275 G
EDE, Inc.	8310120233*	50-155 T		8310250423*	50-275 G
East Metallurgical, Inc.	8310200422	71-6144		8310250423*	50-275 G
Earth Sciences Associates	8310070205*	CONTRACT		8310250591	50-312 P
East-West Technology Corp	8310040383*	0A999		8310250591	50-312 P
Ebasco Services, Inc (subs of Enserch Corp)	8310040239*	50-382 G		8310250591	50-312 P
	8310040245*	50-382 G		8310260292	50-537 G
	8310060238*	50-400 G		8310280076	WASTE MGT
	8310070285	MISC		8310280283	WASTE MGT
	8310130291*	50-400 E		8310280295*	WASTE MGT
	8310170221	71-9027	Energy, Dept of, Clinch River Breeder Reactor Plant	8310310182	WASTE MGT
	8310170230*	50-335 F	Engineers International, Inc	8310310059	50-537 A
	8310170325*	50-335 F		8310170067*	CONTRACT

CORPORATE SOURCE INDEX

533

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Environmental Congress of Mid-Michigan	8310110520	FOIA		8310280082	50-335 P
Environmental Protection Agency	8310060406*	50-313 P		8310280153	50-335 P
	8310170697*	COMMISSION		8310310015	50-335 P
	8310240126	50-261 P		8310310070*	50-230 P
Essex Corp	8310240145*	50-354 F	Florida Power Corp	8310040301	50-302 P
European Communities, Commission of	8310060415	XPORTLIC		8310040420	50-302 F
	8310060420	XPORTLIC		8310040463	50-302 P
	8310060424	XPORTLIC		8310040472*	50-302 Q
Evanston Hosp Evanston, IL	8310110567	FOIA		8310070306	50-302 S
Exxon Corp	8310260357	40-8064		8310070307	50-302 S
Exxon Nuclear Co, Inc (subs of Exxon Corp)	8310050346	TOPREP		8310120191	50-302 P
	8310050470*	50-255 P		8310120301	50-302 S
	8310070260	TOPREP		8310120387	50-302 P
	8310120357*	70-1257		8310130136	50-302 Q
	8310120415*	50-261 P		8310140079	50-302 P
	8310120422*	50-261 P		8310140080*	50-302 P
	8310130208	70-1257		8310140123	50-302 S
	8310140239	TOPREP		8310140187	50-302 S
	8310140244*	TOPREP		8310140233	50-302 S
	8310170233	70-1257		8310140243	50-302 R
	8310170236*	70-1257		8310140266*	50-302 R
	8310210139	TOPREP		8310140268*	50-302 R
	8310250346	PR		8310170517	50-302 S
Fallenheimer, D	8310280183	50-438 A		8310180436	50-302 P
Federal Emergency Management Agency	8310040510	50-443 G		8310180473	50-302 P
	8310050348	50-3 F		8310210021	50-302 S
	8310050552*	50-3 F		8310250374*	50-302 Q
	8310090354*	50-3 F		8310250458	50-302 Q
	8310170500	50-322 Q	Florida State Univ	8310050239	NUREQ
	8310250401*	50-319 F	Florida, Univ of, Gainesville, FL	8310110366*	50-83 F
	8310270239	50-322 Q		8310180157*	CONTRACT
Fisher Controls Co	8310260239*	50-277 P	Foley, Hoag & Eliot	8310110365	50-438 Q
Florida International Univ	8310060512*	CONTRACT	Foxboro Corp	8310070301	50-10 S
Florida Power & Light Co	8310030294	50-389 S	Franklin Institute/Franklin Research Center	8104070444*	50-206 P
	8310030262	50-251 S		8210010087*	50-272 P
	8310030398	50-389 S		8210210152*	50-346 P
	8310030448	50-389 S		8301210240*	50-244 P
	8310040145	50-250 F		8306160513*	50-324 P
	8310040334	PR		8306160602*	50-302 P
	8310060492*	50-335 F		8307200260*	50-336 P
	8310060494*	50-335 F		8307250463*	50-313 P
	8310070250	50-389 F		8308030016*	50-295 Q
	8310070253*	50-389 F		8308030382*	50-315 Q
	8310110138	50-250 Q		8308180560*	50-346 P
	8310110296	50-250 P		8308300317*	50-213 P
	8310130009	50-335 P		8308310512*	50-267 Q
	8310130123	50-250 P		8309020392*	50-277 P
	8310130153	50-389 Q		8309060263*	50-315 P
	8310130154*	50-389 Q		8309160203*	50-286 Q
	8310130157*	50-389 Q		8309200506*	50-267 Q
	8310140217	50-389 S		8310210097*	CONTRACT
	8310170222	50-335 F	Future Resources Associates, Inc	8310070240*	CONTRACT
	8310170224*	50-335 F	QA Technologies, Inc /General Atomic Co	8310060177	XPORTLIC
	8310170240	50-250 F		8310130270	71-6346
	8310170240	50-250 F		8310130274*	71-6346
	8310180208	50-335 P		8310170064	71-6346
	8310180208	50-335 P		8310180319	50-89 P
	8310180211*	50-335 P		8310250393	PR
	8310180211*	50-335 P	QO Noel OmbH	8310200462*	CONTRACT
	8310180254	50-335 P	Qambit	8310110040	50-382 Q
	8310180324	50-250 P		8310040026	50-219 P
	8310180324	50-250 P	General Electric Co.	8310040330	GEN TEC IS
	8310180327*	50-250 P		8310050185	TOPREP
	8310180327*	50-250 P		8310070264	50-237 P
	8310180339	50-250 S		8310070281	TOPREP
	8310180359	50-250 S		8310070310	TOPREP
	8310180381	50-250 Q		8310110505*	FOIA
	8310180381	50-250 Q		8310110513*	FOIA
	8310190023	50-250 R		8310130223	70-1113
	8310190104	50-389 S		8310130228*	70-1113
	8310210223	50-251 B		8310130369	XPORTLIC
	8310240140	50-335 P		8310130371	XPORTLIC
	8310250039	50-389 S		8310170061	70-1113
	8310250060	50-389 S		8310170153	70-1113
	8310250337	50-389 S		8310170158*	70-1113
	8310250431*	50-250 Q		8310170249	70-1113
	8310250437*	50-250 Q		8310170340	TOPREP
	8310270053*	50-389 F		8310180076	NUREQ
	8310270067*	50-389 F		8310180085	NUREQ
	8310270120	50-335 P		8310180112	XPORTLIC
	8310270211	50-389 P		8310180118	NUREQ
	8310270247	50-250 Q		8310180310	XPORTLIC
	8310270277	50-251 S		8310180527*	QA999
	8310270384*	50-251 S		8310180528*	QA999

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310180332*	QA999		8310250430	50-289 S
	8310180577	XPORTLIC		8310250434	50-320 S
	8310180580*	XPORTLIC		8310250478	50-320 S
	8310240311	XPORTLIC		8310250552	50-289 S
	8310250427	70-1113		8310250589	50-289 S
	8310250557	REQ02		8310250606	50-289 S
	8310260009	XPORTLIC		8310250629	50-320 S
	8310260015	XPORTLIC		8310260143	50-289 P
	8310260106	50-447 K		8310270125*	50-289 F
	8310260206	50-447 K		8310270130	50-289 P
	8310260211*	50-447 K		8310270158*	50-219 Q
	8310260307*	70-1113		8310270396*	50-289 F
General Motors Corp	8310310209	NUREQ		8310280102	50-320 P
	8310260068	XPORTLIC		8310280108	50-289 P
	8310260073*	XPORTLIC		8310280115*	50-289 P
General Physics Corp	8310070436	NUREQ		8310280116*	WASTE MOT
	8310190283	NUREQ		8310280123	50-289 P
General Public Utilities - GPU Service Corp	8310030103	50-289 P		8310310144*	50-320 Q
	8310030396	PR	Georgia Power Co	8310310410	50-289 P
	8310030500	50-320 P		8310030247	50-321 S
	8310050055	50-320 P		8310030304	50-321 S
	8310050061*	50-320 P		8310030318	50-366 S
	8310050334*	50-289 F		8310030319	50-366 S
	8310060390	50-289 P		8310030336	50-366 S
	8310060532*	50-289 F		8310030397	50-366 S
	8310060551*	50-289 F		8310030382	50-366 S
	8310070076	50-289 P		8310030410	50-321 S
	8310070082*	50-289 P		8310030415	50-366 S
	8310070263	50-289 S		8310030433	50-366 S
	8310070309	50-289 V		8310030442	50-366 S
	8310110036	50-289 Q		8310030481	50-321 S
	8310110106*	50-320 F		8310030486	50-366 S
	8310110200	50-289 P		8310030510	50-366 S
	8310110217	50-219 P		8310040366*	50-321 Q
	8310120125	50-289 R		8310040409	50-366 S
	8310120125	50-289 R		8310040524	50-321 S
	8310120360	50-289 R		8310060011	50-366 S
	8310130005	50-320 P		8310070279	50-321 P
	8310130064	50-320 P		8310070280*	50-321 P
	8310130082	50-320 P		8310070287	50-321 P
	8310130088	50-320 P		8310070287	50-321 P
	8310130093*	50-320 P		8310110126	50-321 P
	8310130099*	50-320 P		8310120265	50-321 P
	8310130114	50-289 P		8310120265	50-321 P
	8310130138	50-320 P		8310120296	50-424 S
	8310130141*	50-320 P		8310120408	50-366 S
	8310140108	50-289 R		8310140014	50-321 S
	8310140251	50-289 P		8310140144	50-321 S
	8310170007*	50-289 F		8310140241	50-321 P
	8310170335	50-219 P		8310170183	50-366 P
	8310170605	71-9111		8310170397	50-321 S
	8310170639	50-320 P		8310170509	50-366 S
	8310170647*	50-320 P		8310170531	50-366 S
	8310180099*	50-289 P		8310170566	50-424 S
	8310180200	50-320 P		8310170582	50-321 S
	8310180347	50-289 P		8310170584	50-366 S
	8310180347	50-289 P		8310170743*	50-321 F
	8310180372*	50-289 Q		8310170746*	50-321 F
	8310180337	50-320 P		8310190014	50-321 R
	8310180548*	50-320 P		8310190125	50-424 A
	8310190031	50-219 R		8310190125	50-424 A
	8310190060	50-320 S		8310190126*	50-424 A
	8310190075	50-320 S		8310210270	50-321 P
	8310190161	50-289 S		8310210270	50-321 P
	8310190164	50-289 S		8310210277*	50-321 P
	8310190173	50-320 S		8310210277*	50-321 P
	8310190205	50-320 S		8310210279*	50-321 P
	8310190328	71-9010		8310210279*	50-321 P
	8310200008	50-289 S		8310250061	50-366 S
	8310200011	50-289 S		8310250212	50-366 S
	8310200061	50-289 S		8310250285	50-366 S
	8310200073	50-320 S		8310250291	50-366 S
	8310200155	50-320 S		8310250311	50-366 S
	8310200161	50-219 S		8310250312	50-366 S
	8310200430*	50-289 F		8310250343	50-366 S
	8310200443*	50-320 F		8310250506	50-366 S
	8310210037	50-289 R		8310270315	50-424 S
	8310210085	50-289 P		8310270327	50-366 P
	8310210283*	50-289 Q		8310270334*	50-366 P
	8310210390*	50-289 F		8310310236	50-366 S
	8310250253	50-289 S		8310310257	50-366 S
	8310250261	50-289 P		8310310265	50-366 P
	8310250294	50-289 S		8310310280	50-366 S
	8310250317	50-320 S		8310310297	50-321 S

CORPORATE SOURCE INDEX

53

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Germany, Federal Republic of Gesellschaft fuer Nuklear Service, mbH	8310310308	50-321 P	8310070319	50-458 A	
	8310310363	50-366 S		8310130183	
	8205140143*	FOIA		8310130210	
	8310130334	PROJ		8310130215	
	8310130336*	PROJ		8310130236	
Getty/Petrochemicals Co	8310260348	40-6659	8310130238	50-458 S	
	8310260352*	40-6659		8310130322	
	8310270545	40-6659		8310180269	
	8310140080*	50-302 P		8310180303	
Gilbert/Commonwealth Cos Global Weather Dynamics, Inc	8310270107*	FOIA	8310180305	50-458 S	
	8310270110*	FOIA		8310180460	
	8310050345*	CONTRACT		8310180461	
	8310060129*	CONTRACT		8310210149	
Golder Associates	8310060506*	CONTRACT	8310210175	50-458 S	
	8310120035*	CONTRACT		8310210201	
	8310130201*	CONTRACT		8310210221	
	8310280322*	40-1341		8310210221	
Goodson & Associates, Inc Gould, Inc	8310130418*	CONTRACT	8310210262	50-458 S	
	8310070163	50-245 S		8310270181	
	8310210255	50-458 S		8310280011	
	8310130248*	50-400 E		8310280030	
Goulds Pumps, Inc	8310130254*	50-400 E	8310280053	50-458 S	
	8310060245	50-358 Q		8310280084	
	8310060259*	50-358 Q		8310280117	
	8310060266*	50-358 Q		8310280199*	
Government Accountability Project	8310060269	50-329 Q	8310070203*	CONTRACT	
	8310060269	50-329 Q		8310080491*	
	8310060291*	50-329 Q		8310080491*	
	8310060291*	50-329 Q		8310080491*	
	8310110071	50-329 Q	8310260427	CONTRACT	
	8310120101	50-329 Q		NUREG	
	8310120101	50-329 Q		8310070386*	
	8310130390	50-329 A		COMMISSION	
	8310170383	50-329 Q	8310110158	50-443 Q	
	8310170383	50-329 Q		8310110158	
	8310170393	50-329 Q		8310110165*	
	8310170393	50-329 Q		8310110165*	
	8310170427	50-329 Q	8310110170*	50-443 Q	
	8310170427	50-329 Q		8310110170*	
	8310170524	50-329 Q		8310110175*	
	8310170524	50-329 Q		8310110175*	
	8310170524	50-329 Q	8310140191	50-443 Q	
	8310180456	50-329 Q		8310140191	
	8310180456	50-329 Q		8310180329	
	8310180456*	50-329 Q		50-443 Q	
	8310180618	50-329 A	8310250046	50-289 Q	
	8310190050	50-329 Q		8310310202	
	8310190050	50-329 Q		831040573*	
	8310190300	50-329 A		50-382 A	
	8310190311	50-329 A	8310280006*	50-382 A	
	8310240196	50-528 Q		8310050056*	
	8310240215*	50-528 Q		71-9080	
	8310270257	50-329 Q		8310050065*	
	8310270257	50-329 Q	8310050074*	71-9080	
	8310270257	50-329 Q		8310170218	
	8310270266*	50-329 Q		8310170228	
	8310270266*	50-329 Q		8310310430*	
	8310270345	50-329 Q	8310240241*	50-528 U	
	8310280145	50-329 Q		8310110354*	
	8310280145	50-329 Q		COMMISSION	
	8310280204	50-358 Q		8310060894*	
	8310310390	50-329 Q	8310070380*	50-382 U	
	8310310390	50-329 Q		COMMISSION	
	8310310390	50-329 Q		8310200073*	
	8310310390	50-329 Q		50-443 U	
	8310310390	50-329 Q	8310200469*	50-273 U	
	8310180566	FOIA		8310240217*	
	8310180559	FOIA		50-528 U	
	8310110337*	CONTRACT		8310110597*	
	8310040461*	50-358 K	8310030167	COMMISSION	
	8308300480	50-413 Q		8310030167	
	8308300480	50-413 Q		50-498 K	
	8308300486*	50-413 Q		8310030311	
	8308300486*	50-413 Q	8310040289	PR	
	8310070359	TOPREP		8310040289	
	8310130384	71-9160		50-498 S	
	8310130386*	71-9160		8310040410	
	8307260003	50-458 A	8310130187	50-498 S	
	8310030226	50-458 K		8310130187	
	8310030226	50-458 K		50-498 S	
	8310030232	50-458 C		8310130265	
	8310030232	50-458 C	8310130265	50-498 S	
	8310030549	50-458 S		8310130319	
	8310040126	50-458 S		50-498 S	
	8310040130	50-458 S		8310130319	
	8310040318	50-458 S	8310130319	50-498 S	
	8310040496	50-458 S		8310140110	
	8310040615*	50-458 A		8310140110	
	8310060074	50-458 S		8310180290	
	8310070319	50-458 A	8310210193	50-498 S	
				8310210193	
				50-498 S	
				50-498 S	
			8310190313*	FOIA	
				8310040630	
				50-322 Q	
				8310060300	
			8310120119	50-322 Q	
				8310120119	
				50-322 Q	
				8310140016	
			8310170365	50-322 Q	
				8310170365	
				50-322 Q	
				8310190200	

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Hydro-Engineering	8310260299	50-338 Q		8310210215*	50-316 S
	8310310124	50-322 Q		8310270172	50-316 S
	8310310128	50-322 Q		8310270196*	50-315 F
	8310180136	40-8839 Q		8310270196*	50-315 F
	8310280178*	40-299		8310270204	50-315 S
INFO/DQC INTERA Environmental Consultants, Inc Ichthyological Associates, Inc Illinois Power Co	8310200448	FOIA	Indiana & Michigan Power Co	8310270213*	50-315 S
	8310070200*	CONTRACT		8310270223*	50-315 S
	8310120128*	50-289 R		8310270226	50-315 S
	8309120437	50-461 E		8310270271*	50-315 S
	8310040204	50-461 S		8310310077*	50-315 P
	8310040238	50-461 S		8310310080*	50-316 P
	8310060409*	50-461 Q		8310110499*	CONTRACT
	8310110105	50-461 H		8310050464*	CONTRACT
	8310120077	50-461 S		8310060010*	CONTRACT
	8310120181	50-461 A		8310050391*	CONTRACT
Illinois, State of	8310120359	50-461 E	Intel Corp Interior, Dept of Interior, Dept of, Geological Survey	8310070210*	CONTRACT
	8310120441	50-461 SS		8310110530	50-250 P
	8310140228	50-461 EE		8310170211	71-9096
	8310200201	50-461 K		8310060138*	CONTRACT
	8310200205*	50-461 K		8310110036*	50-331 F
	8310210009	50-461 A		8310110038*	50-331 F
	8310250619	50-461 Q		8310110055*	50-331 F
	8310270569*	50-461 FF		8310110060*	50-331 F
	8310270574*	50-461 FF		8310120380	50-331 S
	8310120403	50-461 Q		8310120400	50-331 B
Illinois, Univ of, Urbana, IL	8310170356*	50-454 Q	International Energy Associates, Ltd International Institute of Safety & Health International Neutronics, Inc Intersyst, Ltd Iowa Electric Light & Power Co	8310120421	50-331 S
	8310170698	40-2061		8310140254	50-331 R
	8310250049	27-39		8310170405	50-331 R
	8310250051	27-39		8310170490	50-331 S
	8310060184*	27-39		8310170581	50-331 R
	8310070323	NUREG		8310180198	50-331 P
	8310070148*	CONTRACT		8310180424	50-331 P
	8310030386	50-315 P		8310190068	50-331 R
	8310030391	50-315 P		8310200182	50-331 P
	8310030579*	50-315 P		8310200186*	50-331 P
Indian River Community College Indiana & Michigan Electric Co	8310030579*	50-315 F	Iowa State Univ, Ames, IA	8310210090	50-331 S
	8310030563	50-315 P		8310250481	50-331 S
	8310030567*	50-315 P		8310250669*	50-331 F
	8310060006	50-315 P		8310250670*	50-331 F
	8310060329*	50-315 P		8310270015*	50-331 F
	8310060369	50-315 S		8310270019*	50-331 F
	8310060477*	50-315 F		8310270290	50-331 S
	8310110434*	50-315 F		8310270459	50-331 Q
	8310120188	50-316 S		8310030093	50-116 P
	8310120193	50-316 S		8310030100*	50-116 P
Isham, Lincoln & Beale	8310120197	50-315 S		8310030123	50-116 F
	8310120234	50-316 S		8310030465	50-329 Q
	8310120260	50-315 S		8310030465	50-329 Q
	8310120343	50-315 S		8310040365	50-155 T
	8310120379	50-316 S		8310040376	50-155 T
	8310120443	50-316 S		8310040467	50-329 Q
	8310120445*	50-316 S		8310040467	50-329 Q
	8310120448*	50-316 S		8310040505	50-155 T
	8310120449*	50-316 S		8310040548	50-155 T
	8310140029	50-315 S		8310040551	50-155 T
	8310140040	50-315 P		8310040553	50-155 T
	8310140040	50-315 P		8310040594	50-155 T
	8310140084	50-315 S		8310050483	50-155 G
	8310140137	50-316 S		8310050486*	50-155 G
	8310140138*	50-316 S		8310060314	50-454 Q
	8310140139*	50-316 S		8310060319	50-454 Q
	8310140140*	50-316 S		8310060321*	50-454 Q
	8310140141*	50-316 S		8310110045	50-155 T
	8310170357	50-315 S		8310110063	50-155 Q
	8310170387	50-315 S		8310110310	50-329 Q
	8310170387	50-315 S		8310120211	50-155 T
	8310170407	50-316 S		8310120365	50-155 Q
	8310170611*	50-316 S		8310130174	50-155 T
	8310170619*	50-316 S		8310130214	50-155 T
	8310190064	50-316 R		8310140074	50-155 T
	8310190070	50-315 R		8310170346	50-454 Q
	8310200198	50-315 P		8310170420	50-155 Q
	8310200198	50-315 P		8310180222	50-155 Q
	8310210036	50-315 P		8310180230	50-155 Q
	8310210040	50-315 S		8310180275	50-454 Q
	8310210113	50-315 S		8310180275	50-454 Q
	8310210120	50-316 S		8310180279*	50-454 Q
	8310210137	50-315 S		8310180279*	50-454 Q
	8310210187	50-315 S		8310180335	50-155 Q
	8310210191*	50-315 S		8310180348	50-155 Q
	8310210197*	50-315 S		8310190048	50-329 Q
	8310210199*	50-315 S		8310200225	50-309 Q
	8310210202*	50-315 S		8310200254	50-329 Q
	8310210206	50-316 S			
	8310210212*	50-316 S			

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310240128	30-155 G	Kansas State Univ	8310130090	50-188 R
	8310240132*	30-155 G	Kansas, Univ of, Lawrence, KS	8310170738*	50-148 F
	8310240172	30-327 G		8310210237	50-148 F
	8310280073	30-327 G		8310210239*	50-148 F
	8310310139	30-155 G	Kastenberg, W E	8310060326*	CONTRACT
	8310310145	30-155 G			
	8310310206	30-155 G	Kensington, NH	8310140021	50-443 G
	8310310391	30-155 G	Kentucky, Commonwealth of,	8310270370	50-358 H
JBF Associates	8310070220*	CONTRACT	Kerr-McQee Chemical Corp (subs of	8310120314	40-2061
Jacobs Engineering Group, Inc	8310310451	WASTE MGT	Kerr-McQee Corp)		
				8310180392	40-2061
Jacobson, P J	8310240167	FOIA		8310250662	40-2061
Jamesbury Corp	8310130282*	30-400 E			
Japan, Govt of	8310060180	XPORLILC	Kerr-McQee Corp	8310310362*	40-2061
	8310180304	XPORLILC		8310120310	40-2061
	8310180307	XPORLILC		8310180038	40-8027
			Kerr-McQee Nuclear Corp	8310260377	40-8768
				8310260411	40-8768
Jersey Central Power & Light Co	8310110399*	50-219 F			
	8310180348*	50-320 P			
Johnson Controls, Inc	8310180401*	QA999	Kilcoyne, J J	8310270298	50-289 G
	8310180404*	QA999	Kirkpatrick, Lockhart, Hill, Christopher	8310030496	50-322 G
	8310180406*	QA999	& Phillips		
				8310040199	50-322 G
				8310040618	50-322 G
Joint Applicants-Bouth Texas Project	8310180407*	QA999		8310050416	50-322 G
Joint Intervenor-Callaway	8310110220	50-498 G			
Joint Intervenor-Diablo Canyon	8310040225	50-483 G			
	8310040212*	50-275 G		8310190036	50-322 G
	8310040212*	50-275 G		8310190209	50-322 G
				8310200217	50-322 G
				8310200262	50-322 G
				8310240160	50-322 G
	8310040539	50-275 G			
	8310040539	50-275 G			
	8310050421	50-275 G	Koch Industries, Inc	8310190009	TOPREP
	8310110058	50-275 G	Labarge, Inc	8310190293	71-9032
	8310110058	50-275 G	Labat-Anderson, Inc	8310110192*	CONTRACT
				8310210155*	CONTRACT
			Labor, Dept of	8310200068*	COMMISSION
	8310110127	50-275 G			
	8310110127	50-275 G			
	8310110317	50-275 G			
	8310110317	50-275 G			
	8310130243	50-275 G			
				8310240209*	FOIA
				8310070110	NUREG
			Lawrence Berkeley Laboratory	8306030372*	50-286 P
			Lawrence Livermore Laboratory	8306080065*	50-336 P
				8306080106*	50-302 P
	8310180160	50-275 G			
	8310180160	50-275 G			
	8310180248	50-275 G			
	8310180248	50-275 G			
	8310210228	50-275 T			
				8306130456*	50-346 P
				8310050534*	50-237 P
				8310060212*	50-400 G
				8310070133	50-312 P
				8310110032	NUREG
	8310210228	50-275 T			
	8310210241*	50-275 T			
	8310210241*	50-275 T			
	8310210242*	50-275 T			
	8310210242*	50-275 T			
				8310250152*	DRG
				8310250600*	50-312 P
				8310250625*	50-312 P
				8310250625*	50-312 P
				8310250631*	50-312 P
	8310240158	50-275 G			
	8310240158	50-275 G			
	8310250043	50-275 G			
	8310250043	50-275 G			
	8310260236	50-275 G			
				8310250631*	50-312 P
				8310050245	50-285 P
				8310050298	50-285 F
				8310110182	50-289 G
				8310170589	50-341 K
	8310260236	50-275 G			
	8310260277	50-275 G			
	8310270358	50-275 G			
	8310270358	50-275 G			
	8310270361*	50-275 G			
				8310200026	50-289 F
				8310280169	50-289 F
			League of Women Voters of Rockford, IL	8310040005	50-454 G
				8310140067	50-454 G
				8310140067	50-454 G
	8310270361*	50-275 G			
	8310280097	50-275 G			
	8310280097	50-275 G			
	8310310141	50-275 G			
	8310310141	50-275 G			
Justice, Dept of	8310200048*	50-289 P			
K-C Industries, Inc	8310060162	XPORLILC	Lehigh Univ, Bethlehem, PA	8310130165*	CONTRACT
KBI Corp.	8310060135	XPORLILC	Letco, Inc	8310060355	MIBC
KMC, Inc.	8310030311	PR			
Kansas Gas & Electric Co	8310030364	PR	Lewis, M	8310030366	PR
				8310040491	50-352 G
				8310270268	50-352 G
				8310270268	50-352 G
				8310270356*	50-352 G
	8310040386	50-482 S			
	8310130192	50-482 S			
	8310130223	50-482 S			
	8310130231	50-482 S			
	8310170644	70-2960			
				8310270356*	50-352 G
				8310270362*	50-352 G
				8310270362*	50-352 G
				8310270368*	50-352 G
				8310270368*	50-352 G
	8310170654*	70-2960			
	8310180171	50-482 S			
	8310180256	50-482 S			
	8310180317	50-482 E	Limerick Ecology Action	8310040498	50-352 G
	8310180321*	50-482 E		8310140071	50-352 G
			Limitorque Corp	8310130261*	50-400 E
				8310130273*	50-400 E
				8310180314*	QA999
	8310180325*	50-482 E			
	8310180389	50-482 S			
	8310210095	70-2960			
	8310210100*	70-2960			
	8310210188	50-482 S	Long Island Lighting Co	8310180326*	QA999
				8310040630	50-322 G
				8310060300	50-322 G
				8310120119	50-322 G
				8310120121*	50-322 G
	8310210244	50-482 S			
	8310210415*	50-482 F			
	8310250054	50-482 A			
	8310250084	50-482 G			
	8310250133	50-482 A			
				8310120264	50-322 E
				8310140016	50-322 G
				8310140231	50-322 E

CORPORATE SOURCE INDEX

539

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Minneapolis, MN	8310070117*	CONTRACT		8310310044	50-416 P
Mississippi Power & Light Co	8309060068	50-416 S		8310310126	50-416 Q
	8307090416	50-416 S		8310310130*	50-416 Q
	8310030296	50-416 S	Missouri Joint Municipal Electric Utility	8310280166	50-483 M
	8310030317	50-416 S	Commission		
			Missouri, Univ of, Columbia, MO	8310170308	40-8801
	8310030325	50-416 S			
	8310030364	PR		8310190347	50-184 F
	8310030373	50-416 S		8310200409	40-8801
	8310030373	50-416 S	Missouri, Univ of, Rolla	8310110099	50-123 V
	8310030374	50-416 S		8310110110*	50-123 V
				8310110113*	50-123 V
	8310030430	50-416 S			
	8310030438	50-416 S	Mitsui & Co (USA), Inc. (subs of Mitsui	8310120455	XPORLILIC
	8310030472	50-416 S	& Co., Ltd.)		
	8310030490	50-416 S		8310180151	XPORLILIC
	8310040364	50-416 S		8310180155*	XPORLILIC
			Mitsui Line Travel Service of America,	8310130399	XPORLILIC
	8310040417	50-416 S	Inc		
	8310040001	50-416 S		8310130422	XPORLILIC
	8310040002	50-416 S			
	8310040025	50-416 S	MolyCorp, Inc.	8310070087	40-8794
	8310060112	50-416 S		8310070092*	40-8794
			Monsanto Research Corp	8310060060	XPORLILIC
	8310060227	50-416 P		8310060065*	XPORLILIC
	8310060401	50-416 S		8310120292*	70-572
	8310070169	50-416 S			
	8310070170	50-416 S		8310180403	40-6300
	8310070192	50-416 S	Montesano, WA	8310060493*	CONTRACT
			Morris, IL	8310060496*	CONTRACT
	8310070239	50-416 S	NUS Corp	8310030561	71-9151
	8310070305	50-416 S		8310030568*	71-9151
	8310120281	50-416 P			
	8310120349	50-416 F		8310030574*	71-9151
	8310120349	50-416 F		8310040381*	50-155 T
				8310110001	FOIA
	8310120419	50-416 S		8310110005	FOIA
	8310120436	50-416 P		8310110432	FOIA
	8310120438*	50-416 P			
	8310120444	50-416 P		8310130011*	WASTE MGT
	8310120444	50-416 P		8310130129*	50-528 A
				8310180382	50-445 A
	8310130117	50-416 P		8310190046	FOIA
	8310130121*	50-416 P		8310190088	FOIA
	8310140007	50-417 S			
	8310140051	50-416 S		8310210324	FOIA
	8310140061	50-416 S		8310240233	FOIA
				8310250026	FOIA
	8310140075	50-416 S		8310250031	FOIA
	8310140075	50-416 S		8310270057	FOIA
	8310140122	50-416 S			
	8310140160	50-416 S		8310270121	FOIA
	8310140169	50-416 S		8310270255	50-275 P
				8310270340	50-29 S
	8310170400	50-416 S		8310270355	FOIA
	8310170408	50-416 S	NUSAC, Inc	8310070189*	CONTRACT
	8310170458	50-416 S			
	8310170474	50-416 S	NUTECH Engineers, Inc	8310130232*	50-341 A
	8310170512	50-416 S		8310140103*	50-352 A
			National Academy of Sciences	8310070230*	CONTRACT
	8310180306	50-416 P	National Council on Radiation Protection	8310280104*	CONTRACT
	8310180330	50-416 E	& Measurements		
	8310180330	50-416 E	National Technical Systems	8310250420*	GA999
	8310180352	50-416 P			
	8310180352	50-416 P	Navy, Dept of	8310310273	PT21
			Navy, Dept of, Naval Facilities Engrg	8310190187	MISC
	8310180416	PR	Command		
	8310180430	50-416 F	Navy, Dept of, Naval Research Lab	8310180357*	CONTRACT
	8310180430	50-416 F	Navy, Dept of, Pearl Harbor Naval	8310170209	71-9033
	8310190006	50-416 R	Shipyard		
	8310190037	50-416 P		8310170215	71-9032
	8310190098	50-416 S		8310170355	71-9128
	8310190109	50-416 S	Nebraska Public Power District	8310040348	50-298 Q
	8310190111	50-416 S		8310040374	50-298 P
	8310190232	50-416 S		8310060376	50-298 S
	8310190234	50-416 S		8310060381*	50-298 S
	8310190257	50-416 S		8310110178	50-298 P
	8310210019	50-416 S		8310110183*	50-298 P
	8310210182	50-416 S		8310140190	50-298 P
	8310210314	50-416 Q		8310180471	50-298 Q
	8310290262	50-416 Q		8310190024	50-298 R
	8310250389	50-416 Q		8310200350	50-298 F
	8310260186	50-416 S		8310210174	50-298 S
	8310260186	50-416 S		8310210302	50-298 F
	8310260220	50-416 P		8310310056*	50-298 P
	8310260220	50-416 P		8310310310	50-298 Q
	8310260276	50-416 P	Nevada, State of	8310280107*	WASTE MGT
	8310270037	50-416 S	New England Coalition on Nuclear	8310110158	50-443 Q
	8310270160	50-416 S	Pollution		
	8310270167	50-416 S		8310110158	50-443 Q
	8310270229	50-416 S		8310110165*	50-443 Q
				8310110165*	50-443 Q
	8310270235	50-416 S			
	8310270336	50-416 S		8310110170*	50-443 Q
	8310270397	50-416 S		8310110170*	50-443 Q
	8310270433	50-416 S		8310110175*	50-443 Q
	8310310044	50-416 P		8310110175*	50-443 Q

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310140191	50-443 Q		8310170190	50-423 A
	8310180329	50-443 Q		8310170504	50-245 P
	8310310202	50-443 Q		8310170963	50-423 A
New Hampshire, State of	8310030397	50-443 Q		8310170656	50-245 P
New Hampshire, Univ of,	8310270070	FOIA		8310180336	50-245 S
New Orleans, Univ of	8310130389*	CONTRACT		8310180409	50-213 P
New York, State Univ of, Buffalo, NY	8310140222	50-57 R		8310180469	50-245 P
New York, State of	8310070271	State Prog		8310190015	50-245 R
	8310120028*	50-201 I		8310190207	50-336 R
	8310120030*	50-201 I		8310200187	50-336 P
	8310120036*	50-201 I		8310200229	50-336 P
	8310120039*	50-201 I		8310250263	50-245 S
	8310130385*	CONTRACT		8310250377	TOPREP
	8310140027	50-322 F	Northeast Utilities Service Co	8310040527*	50-423 C
	8310240187	50-247 Q		8310170190	50-423 A
	8310250117*	State Prog		8310120246*	FOIA
News & Observer	8310280174	50-400 A	Northern States Power Co	8310040572	50-263 P
Niagara Mohawk Power Corp	8310040597	50-220 P		8310050422	PR
	8310040631	50-220 P		8310060216	50-263 P
	8310060149	50-220 F		8310070238	50-263 V
	8310060361	50-220 F		8310070272	50-263 S
	8310120097	50-220 P		8310070311	50-263 P
	8310120205	50-220 P		8310070314*	50-263 P
	8310120208*	50-220 P		8310070316*	50-263 P
	8310120373	50-220 P		8310110180*	50-263 F
	8310120406	50-220 P		8310110184*	50-263 F
	8310120416*	50-220 P		8310120102	50-282 S
	8310140043	50-220 J		8310120340	50-306 S
	8310140111	50-220 R		8310120432	50-263 H
	8310140134	50-220 J		8310170641	50-306 S
	8310140221	50-220 P		8310190021	50-263 R
	8310170153	50-410 S		8310190055	50-282 R
	8310170586	50-220 P		8310210257	50-263 S
	8310180098	50-220 P		8310250239	50-263 J
	8310180102*	50-220 P		8310250288*	50-282 Q
	8310190169	50-220 S		8310250288*	50-282 Q
	8310210171	50-220 P		8310250561*	50-263 Q
	8310270212*	50-220 Q		8310250561*	50-263 Q
	8310270217*	50-220 Q		8310250561*	50-263 Q
	8310280052	50-410 S		8310260435*	50-263 F
	8310310228	50-410 A		8310260438*	50-263 F
	8310310228	50-410 K		8310270283	50-263 S
	8310310238*	50-410 C		8310270359*	50-263 S
	8310310243*	50-410 K		8310270364*	50-263 S
	8310310359	50-220 S		8310270380*	50-266 S
Northeast Nuclear Energy Co (subs. of Northeast Utilities)	8310030335	50-423 A		8310270390*	50-263 S
	8310030428	50-245 P		8310270410*	50-263 S
	8310040161	50-423 K		8310270414*	50-263 S
	8310040164*	50-423 K		8310270415*	50-282 S
	8310040334	PR		8310270418*	50-282 S
	8310040521	50-423 C		8310270421*	50-282 S
	8310050431	PR		8310270425*	50-282 S
	8310060035	50-245 F		8310270427*	50-282 S
	8310060205	50-245 F		8310270429*	50-306 S
	8310120259	50-245 F	Norton, Burke, Berry & French	8310110120	50-275 Q
	8310120259	50-245 F		8310110298	50-275 Q
	8310120270	PR		8310110298	50-275 Q
	8310170504	50-245 P		8310110301*	50-275 Q
	8310170504	50-245 P		8310110301*	50-275 Q
	8310170508*	50-245 P	Nuclear Assurance Corp	8310170087	50-266 F
	8310170508*	50-245 P		8310120055*	CONTRACT
	8310170563	50-423 A	Nuclear Data, Inc	8310040309*	70-143
	8310170656	50-245 P	Nuclear Fuel Services, Inc (subs of Getty Oil Co)		
	8310170656	50-245 P		8310040350*	70-143
	8310180336	50-245 S		8310050473*	70-143
				8310050535*	70-143
	8310180409	50-213 P		8310070145*	70-143
	8310180469	50-245 P		8310120008*	50-201 I
	8310190015	50-245 R		8310120009*	50-201 I
	8310190207	50-336 R		8310120012*	50-201 I
	8310200129	50-245 R		8310120013*	50-201 I
	8310200167	50-336 R		8310120014*	50-201 I
	8310200187	50-336 P		8310120020*	50-201 I
	8310200229	50-336 P		8310120028*	50-201 I
	8310200233*	50-336 P		8310120044*	50-201 I
	8310200263	50-245 S		8310120049*	50-201 I
ortheast Utilities	8310030335	50-423 A		8310120207*	50-201 I
	8310030428	50-245 P		8310170036	70-143
	8310040161	50-423 K		8310170299	70-143
	8310040334	PR		8310170680	70-143
	8310040521	50-423 C		8310170724	70-143
	8310050431	PR		8310170737	70-143
	8310060035	50-245 F		8310190270	70-143
	8310060205	50-245 F		8310250340*	70-143
	8310120270	PR		8310250350	70-143

CORPORATE SOURCE INDEX

541

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Nuclear Metals, Inc	8310050516	40-672		8310050313*	50-285 P
Nuclear Packaging, Inc	8310170344	71-9182		8310110330*	50-285 F
	8310170349*	71-9182		8310120094	50-285 Q
	8310190285	71-9143		8310130308*	50-285 F
	8310190288*	71-9143		8310130309*	50-285 F
	8310200408	71-9184		8310180142	50-285 R
	8310200415*	71-9184		8310180506*	50-285 Q
	8310210331	71-9181		8310190324	71-9080
	8310210333*	71-9181		8310210008	50-285 Q
Nuclear System	8310170295	71-9126		8310210370*	50-285 F
O'Neill, J	8309130169	50-155 O		8310250667*	50-285 F
O Corp	8310110207	50-155 O	Online Computer Systems, Inc	8310240286*	FOIA
ORF, Inc	8310130249	71-5908	Organization for Economic Cooperation & Development (Paris)	8310170182*	FOIA
Oak Ridge National Laboratory	8310270093	FOIA	Our Lady of Lourdes Hosp , Camden, NJ	8310310425*	70-2319
	8310050217	NUREG	Pacific Gas & Electric Co	8310030384	50-275 Q
	8310070426	NUREG		8310030384	50-275 Q
	8310110023	NUREG		8310030396	PR
	8310170011	40-86		8310040141	50-275 F
	8310190243	NUREG		8310040251	50-275 Q
	8310260423	NUREG		8310040251	50-275 Q
	8310310191	NUREG		8310040525	50-275 Q
Office of Management & Budget	8310110339	ORG		8310040525	50-275 Q
	8310110341	ORG		8310040570	50-275 P
	8310110343	ORG		8310040578*	50-275 P
	8310110346	ORG		8310040585*	50-275 P
	8310110348	ORG		8310040591*	50-275 P
	8310110349	ORG		8310040598*	50-275 P
Ogle Petroleum, Inc	8310180172	40-8743		8310050396	50-275 Q
Ohio Citizens for Responsible Energy	8310110425	50-237 S		8310050396	50-275 Q
	8310120099	50-440 Q		8310070158	50-275 S
	8310180337	50-440 Q		8310070236	50-275 F
	8310180337	50-440 Q		8310110073	50-275 Q
	8310190061	50-440 Q		8310110073	50-275 Q
	8310190061	50-440 Q		8310110120	50-275 Q
	8310200333	FOIA		8310110120	50-275 Q
	8310270065	FOIA		8310110298	50-275 Q
Ohio State Univ , Columbus, OH	8310280071	50-361 S		8310110298	50-275 Q
Ohio, State of	8310210211*	CONTRACT		8310110301*	50-275 Q
	8310040519*	50-155 T		8310110301*	50-275 Q
	8310170548	50-358 R		8310120136	50-275 S
Ohmart Corp	8302230210*	FOIA		8310120280	50-275 S
	8310260025*	FOIA		8310120362	50-275 S
	8310260067*	FOIA		8310120402	50-275 F
	8310260105*	FOIA		8310120404	50-275 E
	8310260107*	FOIA		8310170285	50-275 F
	8310260116*	FOIA		8310170471	50-323 A
	8310260121*	FOIA		8310170489	50-275 P
	8310260124*	FOIA		8310170489	50-275 P
	8310260132*	FOIA		8310170514	50-275 E
	8310260133*	FOIA		8310170517	50-275 E
	8310260136*	FOIA		8310170545	50-275 F
	8310260146*	70-1144		8310170637	50-275 E
	8310260149*	70-1144		8310180193	50-244 P
	8310260158*	FOIA		8310180328	50-275 Q
	8310260159*	FOIA		8310180328	50-275 Q
	8310260163*	FOIA		8310180458	50-275 P
	8310260169*	FOIA		8310180453	50-275 E
	8310260170*	FOIA		8310190051	50-275 R
	8310260172*	FOIA		8310190063	50-275 E
	8310260173*	FOIA		8310190137	50-275 E
	8310260184*	FOIA		8310190197	50-275 P
	8310260188*	FOIA		8310190197	50-275 P
	8310260193*	FOIA		8310190219	50-275 Q
	8310260195*	FOIA		8310190219	50-275 Q
	8310260223*	FOIA		8310190260	50-133 R
	8310260238*	FOIA		8310200131	50-275 E
	8310260258*	FOIA		8310200144	50-275 F
	8310260271*	FOIA		8310200183*	50-275 Q
	8310260282*	FOIA		8310200260	50-275 P
	8310260295*	FOIA		8310210227	50-275 P
	8310260300*	FOIA		8310210227	50-275 P
	8310260303*	FOIA		8310210233	50-275 R
	8310260321*	FOIA		8310210235*	50-275 R
	8310260347*	FOIA		8310210247	50-275 P
	8310260359*	FOIA		8310210284	50-275 R
	8310260364*	FOIA		8310210284	50-275 R
	8310260374*	FOIA		8310210288*	50-275 R
	8310260384*	FOIA		8310210288*	50-275 R
	8310260388*	FOIA		8310240174	50-275 Q
	8310260394*	FOIA		8310240174	50-275 Q
Oklahoma State Univ.	8310140085*	50-445 Q		8310250108	50-275 S
Omaha Public Power District	8310050255*	50-285 P		8310250113	50-275 R
	8310050271*	50-285 P		8310250539	50-275 S
	8310050298	50-285 P		8310250639	50-275 S
	8310050310*	50-285 P			

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310270263	50-275 Q		8310250219	50-387 S
	8310270376	50-275 S		8310250228	50-387 S
	8310270572*	50-275 F		8310250242	50-387 S
	8310270573*	50-275 F		8310250245	50-387 S
	8310270575*	50-275 F		8310250246	50-387 P
	8310270580*	50-275 F		8310250252*	50-387 P
	8310270580*	50-275 F		8310250258*	50-387 P
	8310270586*	50-275 F		8310250266	50-387 S
	8310270586*	50-275 F		8310250345	50-387 S
	8310270588*	50-275 F		8310250386	50-387 S
	8310280048*	50-275 Q		8310250402	50-387 S
	8310280057	50-275 T		8310250476	50-387 Q
	8310280061	50-275 F		8310250555	50-387 S
	8310280067*	50-275 Q		8310250594	50-387 S
Pacific Nuclear Systems & Services, Inc	8310170291	71-9132		8310250622	50-387 S
Pacific Scientific	8310120092	50-482 S		8310270214	50-387 H
	8310310135	PT21		8310270214	50-387 H
Palmetto Alliance	8308300480	50-413 Q		8310270449	50-387 P
	8308300480	50-413 Q		8310270453*	50-387 P
	8308300486*	50-413 Q		8310270457*	50-387 P
	8308300486*	50-413 Q		8310280065	50-388 S
	8310240021*	50-413 T		8310280065	50-388 S
	8310240021*	50-413 T		8310280125	50-387 S
	8310240022*	50-413 T		8310280130	50-387 S
	8310240022*	50-413 T		8310280139	50-388 S
	8310240024*	50-413 T		8310280139	50-388 S
Palo Verde Intervention Fund	8310240199*	50-528 Q		8310280155	50-388 A
Parameter, Inc	8310110580	NURE0		8310310505	50-387 S
	8310170550*	CONTRACT		8310310505	50-387 S
	8310180079	NURE0	Pennsylvania, Commonwealth of,	8310030453	50-289 Q
	8310200378	NURE0		8310060305	50-352 Q
	8310270606*	CONTRACT		8310120062	50-352 A
Pathfinder Mines Corp	8308300607	40-6622		8310140019	50-412 Q
	8308300610*	40-6622		8310140091	50-412 Q
	8310030205	40-2259		8310180140	50-412 Q
	8310030224	40-6622		8310180420	50-352 D
	8310260003	40-2259		8310130413	FOIA
	8310260006*	40-2259	Peper, Martin, Jensen, Maitchel & Hatlage	8310030390	50-522 Q
	8310260323	XP0RTLIC	Perkins, Cole, Stone, Olsen & Williams	8310060483*	CONTRACT
	8310260323	40-2259	Perry, OH	8310030028	71-9163
			Petroleum Measurement Corp		
Patterson, Belknap, Webb & Tyler	8310200374	FOIA	Philadelphia Electric Co	8309130054	50-352 Q
Pennsylvania Power & Light Co	8310030396	PR		8310030283	PR
	8310040052	50-388 A		8310040124	50-352 A
	8310040421	50-388 A		8310040124	50-352 A
	8310040640	50-388 A		8310040189	50-277 P
	8310060211	50-387 F		8310040189	50-277 P
	8310060211	50-387 F		8310040191*	50-277 P
	8310060486*	50-387 F		8310040296	50-352 A
	8310060486*	50-387 F		8310040415	50-277 P
	8310060538*	50-387 F		8310040415	50-277 P
	8310070160	50-388 A		8310040429*	50-277 P
	8310070336	50-388 E		8310040431	50-352 A
	8310110094*	50-387 F		8310040431	50-352 A
	8310110197	50-387 R		8310040434	50-277 F
	8310120067	50-388 A		8310040627	50-352 Q
	8310120080	50-388 A		8310040627	50-352 Q
	8310120105	50-388 A		8310050437	50-352 K
	8310120144	50-388 A		8310050437	50-352 K
	8310120175	50-388 A		8310050515	50-352 Q
	8310130207	50-387 P		8310050515	50-352 Q
	8310130213*	50-387 P		8310070243	50-352 A
	8310140056	50-388 Q		8310070243	50-352 A
	8310140077	50-388 A		8310110132	50-352 E
	8310140114	50-387 P		8310110132	50-352 E
	8310140155	50-387 P		8310110275	50-352 Q
	8310140156*	50-387 P		8310110275	50-352 Q
	8310170145	50-388 A		8310110277*	50-352 Q
	8310170148*	50-388 A		8310110277*	50-352 Q
	8310180166	50-388 A		8310110284*	50-352 Q
	8310180356*	50-387 Q		8310110284*	50-352 Q
	8310180426	50-387 P		8310110287*	50-352 Q
	8310180426	50-387 P		8310110287*	50-352 Q
	8310180437	50-388 A		8310110291	50-352 Q
	8310180454	50-388 A		8310110291	50-352 Q
	8310180480	50-387 P		8310110292*	50-352 Q
	8310180507	50-387 P		8310110292*	50-352 Q
	8310190080	50-387 R		8310110297*	50-352 Q
	8310190120	50-387 S		8310110297*	50-352 Q
	8310190145	50-387 S		8310110300*	50-352 Q
	8310190230	50-387 S		8310110300*	50-352 Q
	8310200221	50-387 S		8310110305	50-352 Q
	8310200271	50-387 S		8310110305	50-352 Q
	8310210292	50-388 A		8310110307*	50-352 Q
	8310250106	50-387 P		8310110312*	50-352 Q
	8310250204	50-387 S		8310110312*	50-352 Q

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310120148	50-352 A		8310110194*	50-344 F
	8310120148	50-352 A		8310110201*	50-344 F
	8310120313	50-277 R		8310120247*	50-344 Q
	8310120364	50-352 G		8310130104*	50-344 F
	8310120364	50-352 G		8310140246	50-344 B
	8310120368*	50-352 G		8310140257	50-344 J
	8310120368*	50-352 G		8310180417	50-314 A
	8310120377*	50-352 G		8310190039	50-344 R
	8310120377*	50-352 G		8310200188	50-344 F
	8310120384*	50-352 G		8310200192*	50-344 P
	8310120384*	50-352 G		8310200198*	50-344 F
	8310120388*	50-352 G		8310250444	50-344 B
	8310120388*	50-352 G		8310260237	50-344 P
	8310120392	50-352 E		8310260242*	50-344 P
	8310120392	50-352 E		8310260246*	50-344 P
	8310140093	50-352 A		8310270521*	50-344 F
	8310140093	50-352 A		8310310299	50-344 P
	8310140097	50-352 A		8310310301*	50-344 P
	8310140097	50-352 A	Power Authority of the State of New York	8310040291	PR
	8310140101*	50-352 A		8310060089	50-333 B
	8310140101*	50-352 A		8310070248	50-286 V
	8310140197	50-352 A		8310070340	50-286 P
	8310140197	50-352 A		8310070349	50-286 P
	8310140203	50-277 Q		8310110112	50-333 P
	8310140278	50-352 A		8310110222	50-286 P
	8310140278	50-352 A		8310110228*	50-286 P
	8310170225	70-278B		8310110231*	50-286 P
	8310180132	50-352 G		8310120435	50-333 R
	8310180132	50-352 G		8310130113	50-333 Q
	8310180139*	50-352 G		8310140196	50-333 P
	8310180139*	50-352 G		8310170480	50-333 Q
	8310180146*	50-352 G		8310170533	50-333 F
	8310180146*	50-352 G		8310170554	50-286 P
	8310180152*	50-352 G		8310170603	50-286 R
	8310180234	50-352 G		8310170655*	50-333 F
	8310180234	50-352 G		8310170659*	50-333 F
	8310180237*	50-352 G		8310190082	50-333 B
	8310180237*	50-352 G		8310190150	50-333 B
	8310180243	50-352 Q		8310190202	50-286 R
	8310180243	50-352 Q		8310190213	50-333 B
	8310180423	50-352 C		8310200134	50-333 B
	8310200137	50-278 B		8310210126	50-333 F
	8310200172*	50-277 Q		8310210129*	50-333 F
	8310200196*	50-277 Q		8310240114	50-286 P
	8310200257	50-277 R		8310240155	50-286 F
	8310200257	50-277 R		8310250296	50-333 B
	8310200261*	50-277 R		8310250412	50-333 B
	8310200261*	50-277 R		8310250565	50-333 B
	8310200263*	50-277 R		8310250614	50-333 B
	8310200264*	50-277 R		8310270126	FOIA
	8310250035	50-352 K		8310280044	50-333 F
	8310250279	50-278 S		8310280054*	50-333 F
	8310250382	50-277 S		8310310043	50-333 P
	8310250419	50-277 Q		8310310046*	50-333 P
	8310260212	50-277 P		8310310050*	50-333 P
	8310280013	50-352 S		8310310066	50-286 P
	8310280013	50-352 S		8310310203	50-333 B
	8310280127	50-352 F		8310310364	50-333 Q
	8310280257*	50-277 F	President of US & Executive Offices	8310070043*	COMMIBSION
	8310280271*	50-277 F		8310280146*	50-322 U
Philadelphia, PA	8310310064*	50-278 P	Pro-Tech Support Services, Inc	8310180586	50-508 H
Phoenix Associates, Inc	8310310231	50-352 G	Process Technology, Inc	8310250399*	QA999
Phoenix International	8310190058	50-352 G	Professional Reactor Operator Society	8310120339	PR
	8310170118*	CONTRACT	Project Management Corp.	8310260292	50-337 Q
	8310130406*	CONTRACT	Public Interest Research Group, New York	8310120299	PR
Phoenix, AZ	8310130407*	CONTRACT			
Planning Research Corp	8310050467*	CONTRACT	Public Service Co of Colorado	8310040169	50-267 Q
	8310110391*	FOIA		8310040207	50-267 B
	8310110393*	FOIA		8310040210	50-267 Q
	8310110395*	FOIA		8310040276	50-267 G
	8310110400*	FOIA		8310040315	50-267 B
	8310110414*	FOIA		8310040322*	50-267 B
	8310110419*	FOIA		8310040324*	50-267 B
Plateau Resources, Ltd	8310070402	40-7869		8310040325	50-267 P
	8310180104	40-8698		8310040328*	50-267 B
	8310180129	40-8698		8310110236*	50-267 F
	8310180133	40-8674		8310130193	50-267 P
	8310110340*	CONTRACT		8310130200*	50-267 P
Plymouth, MA	8310030341	PR		8310130204*	50-267 P
Portland General Electric Co	8310030364	PR		8310130236	50-267 Q
	8310060099	50-344 F		8310130260	50-267 P
	8310060258	50-344 F		8310130272	50-267 P
	8310060261*	50-344 F		8310130275*	50-267 P
	8310060491	50-344 F		8310130279*	50-267 P
	8310110189	50-344 P		8310130281	50-267 P
				8310130284*	50-267 P

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Public Service Co of Indiana, Inc	8310130286	50-267 Q		8310210195	50-272 F
	8310130300	50-267 P		8310210195	50-272 F
	8310130303*	50-267 P		8310210285	50-272 P
	8310130304*	50-267 P		8310210285	50-272 P
	8310130324*	50-267 P		8310240143	50-354 F
	8310130328*	50-267 P		8310250215	50-354 A
	8310170260	50-267 R		8310250238	50-272 S
	8310210293	50-267 P		8310250244	50-311 S
	8310030283	PR		8310250257	50-272 V
	8310040428	50-346 A		8310250325	50-272 S
	8310040428	50-346 A		8310250390	50-272 S
	8310060337	50-346 S		8310250407	50-311 S
	8310060337	50-346 S		8310250470	50-311 S
	8310170530	50-347 S		8310250567	50-311 S
	8310210025	50-346 S		8310280024	50-272 S
Public Service Co of New Hampshire	8310240081*	50-346 Q		8310280075	50-354 S
	8310270393	50-346 S		8310280093	50-354 S
	8310270393	50-346 S		8310280101	50-354 S
	8310270438	50-346 S		8310280119	50-311 Q
	8310270438	50-346 S		8310280122*	50-311 Q
	8310030341	PR		8310310225	50-311 Q
	8310060343	50-443 S		8310310229*	50-311 Q
	8310110083	50-443 Q	Puget Sound Power & Light Co	8310030390	50-322 Q
	8310110083	50-443 Q	Purdue Research Foundation	8310190326*	FOIA
	8310110092*	50-443 Q		8310190329*	FOIA
	8310110092*	50-443 Q	Purdue Univ, West Lafayette, IN	8310280131	RES
	8310120133	50-443 Q	Radiation Management Corp	8310060079	70-143
	8310120133	50-443 Q		8310120316*	50-277 R
	8310120263	50-443 A	Raytheon Corp	8310110020	FOIA
	8310120263	50-443 A	Reed, J G	8310120420	50-483 Q
Public Service Electric & Gas Co of New Jersey	8310120428	50-443 Q	Rehab Group, Inc	8310240238*	FOIA
	8310120428	50-443 Q	Remote Technology Corp	8310110549*	CONTRACT
	8310180150	50-443 Q	Rensselaer Polytechnic Inst, Troy, NY	8310110121	50-225 P
	8310180150	50-443 Q		8310110122*	50-225 P
	8310180153*	50-443 Q		8310190281*	CONTRACT
	8310180153*	50-443 Q		8310200051	50-225 P
	8310180165	50-443 Q		8310200055*	50-225 P
	8310180165	50-443 Q	Reuter-Stokes, Inc	8310260022	XPORTRIC
	8310180170*	50-443 Q	Richland, WA	8310070237*	CONTRACT
	8310180170*	50-443 Q	Ridgely, Eggers & Associates	8310260397	NUREG
	8310200267	50-443 Q	Rio Algom, Ltd	8310060302	40-8084
	8310200267	50-443 Q	Robert Charles Mules & Associates	8310210528*	CONTRACT
	8310200277	50-443 Q		8310210087*	CONTRACT
	8310200277	50-443 Q	Robert L. Cloud Associates, Inc	8208010014*	50-275 P
	8310210250*	50-443 Q		8310040309	50-275 R
	8310260201*	50-443 A		8310040315*	50-275 R
	8310260234	50-443 Q		8310070086	50-275 R
	8310260254	50-443 Q		8310070091*	50-275 R
	8310260261*	50-443 Q		8310070094	50-275 R
	8310260261*	50-443 Q		8310070100*	50-275 R
	8310260266*	50-443 Q		8310070151	50-275 R
	8310260266*	50-443 Q		8310070155*	50-275 R
	8310260272*	50-443 Q		8310070208	50-275 R
	8310260272*	50-443 Q		8310070212*	50-275 R
	8309190260	50-272 F		8310070215	50-275 R
	8309190260	50-272 F		8310070227*	50-275 R
	8310030346	50-272 R		8310070231	50-275 R
	8310030346	50-272 R		8310070237*	50-275 R
	8310030484	50-354 Q		8310120078	50-275 P
	8310050159	50-272 P		8310140117	50-275 R
	8310050159	50-272 P		8310140119*	50-275 R
	8310050164*	50-272 P	Robert Shaw Controls Co	8310280157	50-275 P
	8310050164*	50-272 P		8310250310*	GA999
	8310050174*	50-272 P	Rochester Gas & Electric Corp	8310250325*	GA999
	8310060325	50-311 P		8310140121	50-275 P
	8310060327	50-311 P		8310180192	50-244 P
	8310060328*	50-311 P		8310190032	50-244 R
	8310070003	50-272 P		8310250217	50-244 S
	8310070166	50-272 P		8310250303	50-244 S
	8310180114	50-311 R		8310270086*	50-244 F
	8310180251	50-272 K		8310270094*	50-244 F
	8310180251	50-272 K		8310310073*	50-244 P
	8310180253*	50-272 K		8310310076*	50-244 P
	8310180253*	50-272 K	Rochester Post-Bulletin, Rochester, MN	8310190337	FOIA
	8310180398*	50-272 Q	Rochester, NY	8310060168*	CONTRACT
	8310190178	50-311 S	Rockwell International Corp	8310170071	70-25
	8310190302	71-9086	Rocky Mountain Energy Co	8310200342	40-8697
	8310200014	71-6574	Ropes & Gray	8310110083	50-443 Q
	8310200174	50-272 R		8310110083	50-443 Q
	8310200239	50-354 E		8310110092*	50-443 Q
	8310200279	50-311 S		8310110092*	50-443 Q
	8310200318	50-311 P		8310120133	50-443 Q
	8310200323*	50-311 P		8310120428	50-443 Q
	8310210041	50-311 R		8310120428	50-443 Q

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310140015	50-443 G		8310260307	50-537 A
	8310140015	50-443 G		8310260375*	CONTRACT
	8310180150	50-443 G		8310280070*	50-329 C
	8310180150	50-443 G		8310030355	50-443 C
	8310180153*	50-443 G	Seacoast Anti-Pollution League	8310110227	50-443 C
	8310180153*	50-443 G		8310120107	50-443 C
	8310180165	50-443 G		8310120107	50-443 C
	8310180165	50-443 G		8310120111*	50-443 C
	8310180170*	50-443 G		8310120111*	50-443 C
	8310180170*	50-443 G		8310120115*	50-443 C
	8310200267	50-443 G		8310120115*	50-443 C
	8310200267	50-443 G		8310120122*	50-443 C
	8310200277	50-443 G		8310120122*	50-443 C
	8310200277	50-443 G		8310120126*	50-443 C
	8310260187	50-443 A		8310120126*	50-443 C
	8310260187	50-443 A		8310120135*	50-443 C
	8310260254	50-443 G		8310120135*	50-443 C
	8310260254	50-443 G		8310120141*	50-443 C
	8310260261*	50-443 G		8310120141*	50-443 C
	8310260266*	50-443 G		8310120141*	50-443 C
	8310260272*	50-443 G	Senate	8310170690*	50-320 U
	8310260272*	50-443 G		8310200467*	COMMISSION
Rosemount, Inc.	8310250359*	GA999	Senate, Environment & Public Works	8310110620*	50-54 U
Rome Associates	8310050458*	CONTRACT		8310180016*	COMMISSION
Rye Nuclear Intervention Committee	8310050508	50-443 H	Shannon & Wilson, Inc	8310070429*	CONTRACT
	8310040533	50-443 G	Shaw, Pittman, Potts & Trowbridge	8310030351	50-209 Q
Rye, NH	8310050508	50-443 H		8310030401	50-312 Q
	8310120178	50-443 G		8310030403	50-209 Q
S Levy, Inc	8310070198*	CONTRACT		8310040231	50-382 Q
	8310070267*	CONTRACT		8310040392	50-209 Q
				8310040538	50-400 Q
Sacramento Municipal Utility District	8310030401	50-312 G		8310050530	50-440 Q
	8310030485	50-312 P		8310060108	50-400 Q
	8310040033	50-312 P		8310060108	50-400 Q
	8310040317	50-312 P		8310060193*	50-400 Q
	8310040419	50-312 R		8310060193*	50-400 Q
	8310040547	50-312 P		8310060203*	50-400 Q
	8310060021	50-312 F		8310060203*	50-400 Q
	8310060022*	50-312 F		8310060323	50-400 Q
	8310070275	50-312 S		8310060323	50-400 Q
	8310120087	50-312 P		8310110150	50-400 Q
	8310120145	50-312 S		8310110150	50-400 Q
	8310120150	50-312 S		8310110155*	50-400 Q
	8310120160	50-312 R		8310110155*	50-400 Q
	8310120161*	50-312 R		8310110205	50-289 Q
	8310120167	50-312 S		8310110224*	50-289 Q
	8310120186	50-312 S		8310110272	50-289 Q
	8310120358*	50-312 Q		8310110274	50-266 Q
	8310120394	50-312 P		8310110280	50-382 Q
	8310140249	50-312 Q		8310120005	50-201 I
	8310170216	50-312 R		8310120195	50-289 Q
	8310180094	50-312 G		8310140030	50-498 Q
	8310210020	50-312 P		8310140063	50-483 Q
	8310210038	50-312 P		8310170234	71-9010
	8310250210	50-312 P		8310170398	50-382 Q
	8310250598	50-312 S		8310170343	50-400 Q
	8310250607	50-312 R		8310170343	50-400 Q
	8310270451	50-312 S		8310170369	50-382 Q
	8310270452	50-312 S		8310170608*	50-400 Q
	8310280099	50-312 P		8310170608*	50-400 Q
Sacramento, CA	8310070224*	CONTRACT		8310170620*	50-400 Q
				8310170620*	50-400 Q
Salem, NJ	8310070181*	CONTRACT		8310170630*	50-400 Q
San Clemente, CA	8310180270	50-275 H		8310170630*	50-400 Q
San Diego Gas & Electric Co	8310110133*	50-361 P		8310170630*	50-400 Q
Sandia Laboratories	8310050253	NUREG		8310180355	50-289 Q
	8310110174	NUREG		8310190212	50-382 Q
	8310110591*	FOIA		8310200102	50-266 Q
	8310190283	NUREG		8310200211	50-289 Q
	8310200388	NUREG		8310210140	50-289 Q
	8310270045*	FOIA		8310210200	50-320 Q
	8310310447	NUREG		8310210249	50-289 Q
Sargent & Lundy, Inc	8310040349*	GA999		8310240166	50-289 Q
Save the Valley - Save Marble Hill	8310260291	50-546 Q		8310240183	50-400 Q
Scharfeld, Bechhoefer & Baron	8310120011*	50-201 I		8310240104	50-289 Q
	8310120015*	50-201 I		8310270330	50-440 Q
	8310120023*	50-201 I		8310270312	FOIA
	8310120042*	50-201 I		8310280051	50-400 Q
	8310120047*	50-201 I		8310280051	50-400 Q
	8310120207*	50-201 I		8310280164	50-400 Q
Schwalb, Donnenfeld, Bray & Silbert	8310030534*	CONTRACT		8310280164	50-400 Q
Science & Engineering Associates, Inc.	8310110510*	CONTRACT		8310310146	50-400 Q
	8310110512*	CONTRACT			
Science Applications, Inc	8208310352*	50-259 P		8310310195	50-382 Q
	8209200354*	50-220 Q		8310310198	50-289 Q
	8310050530*	CONTRACT		8310310200	50-483 Q
	8310190265	WASTE MGT	Shoreham Opponents Coalition	8310310382	50-289 Q
				8310200103	50-322 Q

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Shoreham, NY	8310060290*	CONTRACT		8310130012	50-206 F
Siemens-Albis, Inc	8310250011*	QA799		8310130127	50-206 P
Sigma Chemical Co	8310130391	XPORTLIC		8310130316	50-206 P
Sinking Industries, Inc	8310260296*	CONTRACT		8310140023	50-362 S
Sinkin, L A	8310260249	50-498 Q		8310140125	50-362 S
Mississippi Alliance for the Environment (SAFE)	8310260269	50-498 Q		8310140167	50-362 S
	8310030149	50-454 H		8310140218	50-362 S
				8310140223	50-206 P
	8310040205	50-454 Q		8310180486*	50-361 S
	8310200097	50-454 Q		8310190008	50-206 H
	8310210219*	50-454 Q			
Small Business Administration	8310050369*	CONTRACT		8310190008	50-206 H
	8310050460*	CONTRACT		8310190008	50-206 H
	8310070432*	CONTRACT		8310190010	50-206 R
	8310130407*	CONTRACT		8310190092	50-361 R
	8310180396*	CONTRACT		8310200177	50-361 P
	8310210155*	CONTRACT		8310200177	50-361 P
	8310210180*	CONTRACT		8310200284	50-206 P
Society of Nuclear Medicine	8310250675	FDIA		8310210260	50-362 P
South Carolina Electric & Gas Co	8310030343	50-395 S		8310250124	50-206 P
	8310030475	50-395 S		8310250145	50-361 S
	8310030582*	50-395 F		8310250196	50-206 P
	8310030587*	50-395 F		8310250455	50-206 S
	8310040465	50-395 S		8310250463	50-362 S
	8310070002	50-395 S		8310250495	50-362 S
	8310070126	50-395 S		8310270101	50-206 P
	8310070278	50-395 S		8310270416	50-362 S
	8310070338	50-395 S		8310270428	50-362 S
	8310170443	50-395 S		8310270432	50-362 S
	8310170548	50-395 S		8310270434	50-361 S
	8310190028	50-395 R		8310270439	50-362 S
	8310200252	50-395 Q		8310270448	50-362 S
	8310210128	50-395 S		8310270454	50-361 S
	8310260109	50-395 E		8310270454	50-361 S
	8310260117	50-395 S		8310270463	50-361 S
	8310260222	50-395 P		8310270495	50-362 S
	8310260255	50-395 P		8310270498	50-361 S
	8310280005	50-395 D		8310310326	50-361 S
	8310310224	50-395 S		8310310326	50-361 S
	8310310392	50-395 S		8310070320	NUREG
	8310310394	50-395 S		8310130285*	50-400 E
South Hampton, NH	8310140021	50-443 Q			
Southern California Edison Co	8305240501	50-264 P		8310130285*	50-400 E
	8310030102	50-361 R		8310130287*	50-400 E
	8310030110	50-206 F		8310130287*	50-400 E
	8310030110	50-206 F		8310130289*	50-400 E
				8310130289*	50-400 E
	8310030110	50-206 F			
	8310040009	50-361 P		8310130290*	50-400 E
	8310040009	50-361 P		8310130290*	50-400 E
	8310070283	50-206 P		8310190343	71-505
	8310070304	50-361 S		8310210013*	50-285 Q
				8310270398*	TDPREP
	8310070344	TDPREP			
	8310110128	50-361 P		8310280122*	50-311 Q
	8310110128	50-361 P		8310280149*	50-259 P
	8310110133*	50-361 P		8310280150*	50-259 P
	8310110133*	50-361 P		8310280151*	50-259 P
				8310110616*	CONTRACT
	8310110136*	50-361 P			
	8310110136*	50-361 P		8310170383	50-329 Q
	8310120070	50-361 S		8310170383	50-329 Q
	8310120073	50-361 S		8310170393	50-329 Q
	8310120075	50-362 S		8310170393	50-329 Q
				8310170427	50-329 Q
	8310120116	50-361 S		8310170427	50-329 Q
	8310120130	50-361 S		8310170524	50-329 Q
	8310120146	50-361 S		8310170524	50-329 Q
	8310120152	50-361 S		8310270345	50-329 Q
	8310120164	50-361 S		8310280145	50-329 Q
	8310120170	50-206 P			
	8310120172	50-362 S		8310060094	XPORTLIC
	8310120183	50-362 S			
	8310120184	50-206 S		8310120255	PR
	8310120258	50-206 Q		8310170198*	50-423 A
				8310190034*	50-329 A
	8310120278	50-206 P		8310190036*	50-329 A
	8310120278	50-206 P			
	8310120278	50-206 P		8310190038*	50-329 A
	8310120298	50-206 Q		8310190038*	50-329 A
	8310120298	50-206 Q		8310190042*	50-329 A
				8310190042*	50-329 A
	8310120298	50-206 Q		8310190047*	50-329 A
	8310120338	50-362 S			
	8310120342	50-361 S		8310190047*	50-329 A
	8310120347*	50-361 S		8310200203*	50-397 Q
	8310120351*	50-361 S		8310310065*	50-412 K
				8310310312*	50-412 F
	8310120397	50-361 P		8310030226	50-458 K
	8310120397	50-361 P			
	8310130012	50-206 F		8310030238*	50-458 C
	8310130012	50-206 F		8310170466*	50-329 Q
				8310170538*	50-329 Q

CORPORATE SOURCE INDEX

547

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310170544*	50-329 G		8310030376	50-296 S
	8310170549*	50-329 G		8310030388	50-390 S
	8310170555*	50-329 G		8310030388	50-390 S
	8310170559*	50-329 G		8310030388	50-390 S
	8310170560*	50-329 G		8310030388	50-390 S
	8310170564*	50-329 G		8310030388	50-390 S
	8310170567*	50-329 G		8310030397	50-390 S
	8310170571*	50-329 G		8310030397	50-390 S
	8310170575*	50-329 G		8310030404	50-390 S
	8310170598*	50-329 G		8310030404	50-390 S
	8310170602*	50-329 G		8310030405	50-260 S
	8310170606*	50-329 G		8310030424	50-390 S
	8310170610*	50-329 G		8310030424	50-390 S
	8310170616*	50-329 G		8310030432	50-259 S
	8310170622*	50-329 G		8310030436	50-390 S
	8310170627*	50-329 G		8310030436	50-390 S
	8310170634*	50-329 G		8310030436	50-390 S
	8310270176*	50-329 G		8310030462	50-390 S
	8310110582*	CONTRACT		8310030462	50-390 S
Structural & Earthquake Engineering Consultants	83101130298*	50-155 P		8310030473	50-390 S
Structural Mechanics Associates	8310130302*	50-155 P		8310030473	50-390 S
Suffolk County, NY	8310030436	50-322 G		8310030506	50-390 S
	8310040179*	50-322 G		8310030506	50-390 S
	8310040618*	50-322 G		8310030506	50-390 S
	8310050416	50-322 G		8310030506	50-390 S
	8310190056	50-322 G		8310030506	50-390 S
	8310200217	50-322 G		8310030519*	50-390 S
	8310240160	50-322 G		8310030519*	50-390 S
	8310270239*	50-322 G		8310030538	50-390 S
Suffolk Nuclear Study Group	8310180577*	50-322 A		8310030538	50-390 S
	8310210327	FOIA		8310030538	50-390 S
	8310270496	FOIA		8310030538	50-390 S
	8310170101	FOIA		8310040138*	50-390 S
Syncor International System Architects, Inc	8310050460*	CONTRACT		8310040138	50-390 S
TERA Corp	8310040235*	50-247 F		8310040172	50-438 S
	8310110378*	FOIA		8310040180	50-390 S
	8310170624	50-329 A		8310040180	50-390 S
	8310210272	50-329 R		8310040193	50-390 S
	8310210272	50-329 R		8310040193	50-390 S
	8310210275*	50-329 R		8310040271*	50-259 G
	8310210275*	50-329 R		8310040402*	50-390 F
	8310050323*	CONTRACT		8310040402*	50-390 F
Tamoran, Inc	8310180538*	50-333 P		8310040432	50-259 F
Target Technology Ltd	8310280016	50-142 T		8310040432	50-259 F
Taylor Associates	8310180596*	CONTRACT		8310040432	50-259 F
Technassociates, Inc	8310250093*	50-397 A		8310040432	50-259 F
Technical Audit Associates, Inc	8310250097*	50-397 A		8310040544	50-390 S
Technology Development of California, Inc	8310210180*	CONTRACT		8310040544	50-390 S
Technology for Energy Corp	8310060418*	50-261 P		8310040549	50-390 S
Technetron Research, Inc	8310130143	NUREG		8310060008	50-390 S
	8310310449	NUREG		8310060008	50-390 S
Telodyne Engineering Services	8310120315*	50-271 P		8310060009	50-390 S
	8310140202*	50-333 P		8310060009	50-390 S
	8310170214	50-273 R		8310060016*	50-390 S
	8310170227*	50-273 R		8310060016	50-390 S
	8310170646	50-273 R		8310060027	50-390 S
	8310170651*	50-273 R		8310060027	50-390 S
	8310260260	50-273 R		8310060053	50-327 S
	8310260264*	50-273 R		8310060087	50-390 S
	8310270241	50-273 R		8310060087	50-390 S
	8310030451*	QA999		8310060095	50-390 S
Telodyne, Inc	8310070173*	CONTRACT		8310060095	50-390 S
Tenneco, Inc	8310030214	50-390 S		8310060331	50-390 S
Tennessee Valley Authority	8310030214	50-390 S		8310060331	50-390 S
	8310030218	50-327 S		8310060331	50-390 S
	8310030233	50-390 S		8310060331	50-390 S
	8310030233	50-390 S		8310060342	50-390 S
	8310030233	50-390 S		8310060342*	50-390 S
	8310030233	50-390 S		8310060377	50-296 S
	8310030240	50-328 S		8310060380	50-260 S
	8310030244	50-390 S		8310060407	50-296 S
	8310030244	50-390 S		8310060436	50-390 S
	8310030252	50-390 S		8310060436	50-390 S
	8310030252	50-390 S		8310060476	50-390 S
	8310030257	50-390 S		8310060488	50-390 S
	8310030257	50-390 S		8310110100*	50-327 F
	8310030338	50-390 S		8310110199*	50-259 F
	8310030338	50-390 S		8310110203*	50-259 F
	8310030365	50-390 S		8310120100	50-390 S
	8310030365	50-390 S		8310120100	50-390 S
	8310030370	50-390 S		8310120169	50-390 S
	8310030370	50-390 S		8310120169	50-390 S

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310120210	50-390 S		8310210386*	50-299 F
	8310120210	50-390 S		8310250012	50-390 S
	8310120228	50-438 S		8310250012	50-390 S
	8310120236	50-390 S		8310250034	50-390 A
	8310120237	50-390 S		8310250034	50-390 A
	8310120237	50-390 S		8310250077	50-327 S
	8310120332	50-390 S		8310250082	50-299 P
	8310120332	50-390 S		8310250110	50-438 S
	8310120336	50-390 S		8310250138*	50-299 O
	8310120336	50-390 S		8310250149	50-438 S
	8310120389	50-390 S		8310250149	50-438 S
	8310120389	50-390 S		8310250162	50-390 S
	8310120396	50-390 S		8310250162	50-390 S
	8310120396	50-390 S		8310250165	50-390 S
	8310140017	50-390 S		8310250165	50-390 S
	8310140048	50-390 S		8310250170*	50-299 Q
	8310140087	50-328 S		8310250173	50-390 S
	8310140127	50-260 S		8310250173	50-390 S
	8310140129	50-259 S		8310250229	50-299 Q
	8310140200	50-260 S		8310250233	50-390 S
	8310140224	50-390 A		8310250240*	50-299 Q
	8310140224	50-390 A		8310250240*	50-299 Q
	8310140277	50-438 S		8310250240*	50-299 Q
	8310170264	50-390 S		8310250306*	50-438 Q
	8310170264	50-390 S		8310250313*	50-438 Q
	8310170276	50-327 S		8310250360	50-260 S
	8310170592	50-327 S		8310250367	50-390 Q
	8310170597	50-327 S		8310250371	50-390 S
	8310170658	50-328 S		8310250371	50-390 S
	8310170658	50-328 S		8310250378	50-390 S
	8310170733	70-2941		8310250436*	50-327 Q
	8310180315	50-390 F		8310250436*	50-327 Q
	8310180315	50-390 F		8310250484*	50-327 Q
	8310180388	50-390 A		8310250484*	50-327 Q
	8310180388	50-390 A		8310250494*	50-327 Q
	8310180422	50-259 P		8310250602*	50-327 Q
	8310180443	50-327 P		8310250602*	50-327 Q
	8310190046	50-327 R		8310260364	40-1341
	8310190089	50-390 S		8310270073	50-260 S
	8310190089	50-390 S		8310270150	50-390 S
	8310190089	50-390 S		8310270150	50-390 S
	8310190089	50-390 S		8310270183	50-390 S
	8310190124	50-327 S		8310270183	50-390 S
	8310190127	50-390 S		8310270248	50-438 S
	8310190127	50-390 S		8310280021	50-327 P
	8310190186	50-259 R		8310280022	50-327 P
	8310190220	50-438 S		8310280022	50-327 P
	8310190224	50-390 S		8310280027*	50-327 P
	8310190224	50-390 S		8310280027*	50-327 P
	8310190224	50-390 S		8310280040*	50-327 P
	8310190224	50-390 S		8310280040*	50-327 P
	8310210011	50-390 S		8310280148	50-259 P
	8310210011	50-390 S		8310280173	50-390 A
	8310210011	50-390 S		8310280321	40-1341
	8310210011	50-390 S		8310310142	50-259 P
	8310210015	50-390 S		8310310148	50-390 S
	8310210015	50-390 S		8310310157	50-438 S
	8310210023	50-390 A		8310310320	50-390 S
	8310210023	50-390 A		8310310320	50-390 S
	8310210042	50-390 S		8310310348	50-390 S
	8310210042	50-390 S		8310310387	50-259 F
	8310210049	50-390 S		8310310387	50-259 F
	8310210049	50-390 S		8310310387	50-259 F
	8310210049	50-390 S		8310310429	50-327 P
	8310210049	50-390 S		8310310429	50-327 P
	8310210049	50-390 S		8310310438*	50-327 P
	8310210049	50-390 S		8310310438*	50-327 P
	8310210068	50-390 S		8310250683*	50-59 F
	8310210078*	50-259 Q		8310030516	50-445 S
	8310210078*	50-259 Q		8310050403	50-445 Q
	8310210078*	50-259 Q		8310050403	50-445 Q
	8310210096	50-390 S		8310050412*	50-445 Q
	8310210096	50-390 S		8310050412*	50-445 Q
	8310210096	50-390 S		8310060316	50-445 Q
	8310210096	50-390 S		8310110322	50-445 Q
	8310210178	50-438 A		8310130268	50-445 S
	8310210178	50-438 A		8310130278	50-445 S
	8310210226	50-259 S		8310140022	50-445 T
	8310210301	50-390 E		8310140022	50-445 T
	8310210301	50-390 E		8310140024*	50-445 T
	8310210383*	50-259 F		8310140024*	50-445 T
	8310210383*	50-259 F		8310140180	50-445 K
	8310210383*	50-259 F		8310170412	50-445 Q

Texas A&M Univ , College Station, TX

Texas Utilities Generating Co

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310170412	50-445 G	Transportation, Dept of	8310260090*	FOIA
	8310170417*	50-445 G		8310260150	50-266 P
	8310170417*	50-445 G	Transportation, Dept of, Federal Highway	8310260298*	FOIA
	8310180158	50-445 G	Administration		
	8310180163*	50-445 G	Treasury, Dept of, U S Customs Service	8310270292	50-261 P
				8310270080*	FOIA
	8310180163*	50-445 G		8310270084*	FOIA
	8310180179	50-445 K		8310050557	27-39
	8310180183*	50-445 K	US Ecology, Inc (Formerly Nuclear		
	8310180379	71-504	Engineering)	8310120063	27-39
	8310180484*	50-445 G		8310170390	27-39
				8310200330	71-6679
	8310180488*	50-445 G			
	8310210081	50-445 A		8310260088	WASTE MGT
	8310210184	50-445 G		8310260094	WASTE MGT
	8310210196*	50-445 G		8310200080	27-40
	8310210196*	50-445 G		8310280281	27-40
				8310310207	27-40
Texas Utilities Services, Inc	8310280003	50-445 S			
	8310040504	50-445 A		8310030203	40-8584
	8310040504	50-445 A	Union 76 Minerals Exploration Co	8310030210*	40-8584
	8310040504	50-445 A		8310030221	40-8584
	8310040504	50-445 A		8310040100	40-299
	8310040504	50-445 A	Union Carbide Corp.	8310050329	REB
	8310110116*	50-445 F		8310170262	70-2067
	8310110173	50-445 F		8310260416	40-299
	8310110177*	50-445 F		8310280165	40-299
	8310200149	50-445 K		8310280167*	40-299
	8310200149	50-445 K		8310280177*	40-299
	8310270175	50-445 F			
	8310270175	50-445 F			
	8310270185	50-445 F	Union Electric Co	8310040273*	50-483 G
	8310270185	50-445 F		8310040297	PR
	8310280041	50-445 A		8310040334	PR
				8310120067	50-483 R
Texas, State of				8310140063	50-483 Q
Texas, Univ of, Austin, TX	8310280041	50-445 A			
	8310180163*	50-445 G		8310210090	50-483 S
	8310110386*	50-192 F		8310220661*	50-483 F
	8310110390*	50-192 F		8310280664*	50-483 F
	8310110392*	50-192 F		8310310200	50-483 Q
				8310180125	40-8348
Texas, Univ of, El Paso, TX	8310110429*	50-192 F	Union Oil Co of California		
Texas, Univ of, San Antonio	8310280131	REG			
Thomas, D.C	8310050349*	CONTRACT			
Three Mile Island Alert	8310140070*	50-454 Q	Union of Concerned Scientists	8310050328	50-289 Q
	8310260274	50-289 Q		8310070369*	COMMISSION
				8310070386*	COMMISSION
				8310110460	FOIA
				8310110581	FOIA
Toledo Edison Co	8310270372	50-289 G			
	8310060226	50-346 P		8310170020	FOIA
	8310060345	50-346 F		8310180531	50-333 P
	8310060365	50-346 S		8310190059	FOIA
	8310060575*	50-346 F		8310190306	FOIA
				8310200231	50-289 Q
	8310110085*	50-346 F			
	8310110087*	50-346 F		8310240192	FOIA
	8310110131*	50-346 F		8310260306	50-289 Q
	8310120103	50-346 F		8310260308*	50-289 Q
	8310120222	50-346 S		8310270366	FOIA
				8310310096	FOIA
	8310120237	50-346 S	United Engineers & Constructors, Inc	8310190267	71-148
	8310120322	50-346 S	(subs of Raytheon Co)		
	8310120391	50-346 S			
	8310170367	50-346 S	United Nuclear Corp	8310210223*	50-460 A
	8310170375	50-346 S		8310170003	70-371
				8310250445*	70-820
	8310170492	50-346 P	Univ of California Press	8310110524*	CONTRACT
	8310170498	50-346 P			
	8310170597	50-346 P			
	8310180513	50-346 R	Univ of Cincinnati Medical Ctr,	8310240190	FOIA
			Cincinnati, OH		
	8310190020	50-346 R			
	8310190166	50-346 R		8310260270*	FOIA
	8310190167*	50-346 R	Uranium UBA, Inc	8310260414	40-8783
	8310190170*	50-346 R		8310260418*	40-8783
	8310210363*	50-346 F	Uranium Resources, Inc	8310210123	40-8784
	8310250226	50-346 P	Vermont Electric Cooperative, Inc	8310260200*	50-443 A
	8310250235*	50-346 P	Vermont Yankee Nuclear Power Corp.	8310040289	50-271 F
	8310250241*	50-346 P		8310050166	50-29 P
	8310040522	50-358 A		8310120312	50-271 P
Torrey Pines Technology	8310240178	50-346 A		8310180096	50-271 R
	8310240178	50-346 A		8310190298	71-9089
	8310240179*	50-346 A		8310210310	50-271 P
	8310240179*	50-346 A		8310250308	50-271 S
	8310240182*	50-346 A		8310250334	50-271 S
	8310240182*	50-346 A		8310250379	50-271 S
				8310250331	50-271 S
Trans-Continental Consultants, Inc	8310210320	FOIA		8310250626	50-271 S
Transamerica Delaval, Inc	8310270206	50-318 S		8310310041*	50-271 P
Transnuclear, Inc.	8310060081	XPORTLIC		8310310246	50-271 P
	8310060084*	XPORTLIC		8310310307	50-271 F
	8310130396	XPORTLIC			
			Virginia Electric & Power Co	8310030300	PR
	8310180143	XPORTLIC		8310040208	50-280 S
	8310180148*	XPORTLIC		8310040430	50-280 Q
	8310180302	XPORTLIC		8310040530	50-338 Q
	8310280026	XPORTLIC		8310040587	50-338 P
	8310280033*	XPORTLIC			
				8310040587	50-338 P

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310040590*	50-338 P		8310030396	PR
	8310040590*	50-338 P		8310040440	50-397 A
	8310040523*	50-280 F		8310070277	50-397 K
	8310040577*	50-280 F		8310070342	50-397 A
	8310040577*	50-280 F		8310070346*	50-397 A
	8310040584*	50-280 F		8310110276	50-397 E
	8310070144	50-280 S		8310110332	50-397 A
	8310070328	50-338 S		8310120059	50-397 E
	8310070418*	50-280 F		8310120155	50-397 E
	8310110137	50-280 P		8310120196*	50-397 Q
	8310110190*	50-280 F		8310120250*	50-397 Q
	8310110239*	50-280 F		8310120261	50-397 A
	8310110239*	50-280 F		8310120267	50-397 A
	8310110240*	50-280 F		8310120339	50-397 F
	8310110240*	50-280 F		8310140066	50-508 Q
	8310110268*	50-280 F		8310140086	50-508 Q
	8310120114	50-338 P		8310140176	50-508 A
	8310120114	50-338 P		8310140182*	50-508 A
	8310120140	50-338 P		8310170212	50-397 E
	8310120140	50-338 P		8310170235	50-397 E
	8310120324	TOPREP		8310170298	50-397 E
	8310130103	50-338 P		8310170313	50-397 A
	8310130103	50-338 P		8310170446	50-397 F
	8310130107*	50-338 P		8310170495	50-397 A
	8310130107*	50-338 P		8310170499*	50-397 A
	8310130145	50-338 P		8310170507*	50-397 Q
	8310130145	50-338 P		8310180341*	50-397 Q
	8310130148*	50-338 P		8310180387	50-397 E
	8310130148*	50-338 P		8310180449	50-397 A
	8310140094	50-280 P		8310180453*	50-397 A
	8310140094	50-280 P		8310180503	50-397 F
	8310140161	50-338 S		8310190152	50-508 A
	8310170091	50-338 S		8310190154*	50-508 A
	8310170091	50-338 S		8310200200*	50-397 Q
	8310170098*	50-338 S		8310200357*	FOIA
	8310180277	50-338 F		8310210168	50-397 A
	8310180301	50-280 F		8310210173*	50-397 A
	8310180309	50-338 P		8310210224	50-460 A
	8310180309	50-338 P		8310210305	50-397 A
	8310180440	50-338 P		8310240150	50-397 A
	8310190002	50-338 R		8310250088	50-397 A
	8310190016	50-280 R		8310250092	50-397 B
	8310190043	50-280 P		8310250144	50-397 B
	8310190043	50-280 P		8310250290	50-397 B
	8310190043	50-280 P		8310250425	50-397 B
	8310190043	50-280 P		8310250453	50-397 B
	8310190057*	50-280 P		8310260113	50-397 A
	8310190057*	50-280 P		8310260122*	50-397 A
	8310190112	50-338 P		8310260189	50-508 F
	8310190112	50-338 P		8310270444	50-397 A
	8310190130*	50-338 P		8310280126	50-508 Q
	8310190130*	50-338 P		8310310149	50-508 A
	8310190200	50-338 Q		8310310151*	50-508 A
	8310190200	50-338 Q		8310310154*	50-508 A
	8310200101	50-280 P		8310310175	50-508 Q
	8310200101	50-280 P	Washington State Univ., Pullman, WA	8310030143	50-27 F
	8310200289	50-338 P	Washington Univ.	8310210093*	CONTRACT
	8310210047	50-339 B	Washington, State of	8310040344	50-508 A
	8310210058	50-338 S		8310310204	WASTE MGT
	8310210306	50-280 B	Water, Waste & Land, Inc	8310030215*	40-8584
	8310250066	50-339 S		8310280170*	40-299
	8310250456	50-280 Q		8310280175*	40-299
	8310250456	50-280 Q	Western Nebraska Resources Council	8310110356	FOIA
	8310250609	50-280 S	Westinghouse Electric Corp.	8310030469*	QA999
	8310260299	50-338 Q		8310040628*	70-1151
	8310260299	50-338 Q		8310050197	PROJ
	8310260432*	50-280 F		8310050212*	PROJ
	8310260432*	50-280 F		8310060059	XPORTLIC
	8310260436*	50-280 F		8310060120	XPORTLIC
	8310270300	50-280 P		8310060267	PROJ
	8310270300	50-280 P		8310060270*	PROJ
	8310270300	50-280 P		8310060310	50-413 T
	8310210299*	50-124 F		8310110149*	TOPREP
Virginia Polytechnic Institute & State Univ., Blacksburg, VA	8310070106*	CONTRACT		8310130349	XPORTLIC
Virginia, Univ. of, Charlottesville, VA	8310170151*	40-86		8310140042*	50-315 P
W. R. Grace & Co.	8310270099	FOIA		8310140046*	50-315 P
WBI Corp.	8310130402	FOIA		8310140227	TOPREP
Washington Knowledge Network	8309300239	50-460 F		8310170107*	50-338 S
Washington Public Power Supply System	8309300246*	50-460 F		8310170197	70-698
	8309300331	50-397 S		8310170203*	70-698
	8310030303	50-460 A		8310170219	70-1151
	8310030339	50-508 A		8310170330	70-1151
	8310030357	50-397 A		8310200165	50-247 S
	8310030361	50-397 E		8310200170	TOPREP
				8310200193	TOPREP

CORPORATE SOURCE INDEX

551

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310200199*	TOPREP		8310240051*	50-266 Q
	8310200451	71-5450		8310280168*	50-266 S
	8310210198*	CONTRACT		8310280171*	50-266 S
	8310240248	70-1143		8310310370	50-266 F
	8310240250*	70-1143	Wisconsin Public Service Corp	8310040617	50-305 P
	8310250016	XPORTLIC		8310060334*	50-305 Q
	8310250310	70-1151		8310110028*	50-305 F
	8310260018	XPORTLIC		8310110031*	50-305 F
	8310260045	70-1143		8310120206	50-305 F
	8310260054*	70-1143		8310120209*	50-305 F
	8310260267*	50-400 E		8310120214*	50-305 F
	8310260279	50-445 A		8310120216*	50-305 F
	8310260279	50-445 A		8310120220*	50-305 F
	8310260281*	50-445 A		8310120223*	50-305 F
	8310260281*	50-445 A		8310120227*	50-305 F
	8310260283*	50-400 E		8310120232*	50-305 F
	8310260284*	50-445 A		8310120235*	50-305 F
	8310260284*	50-445 A		8310120238*	50-305 F
	8310260286*	50-445 A		8310120240*	50-305 F
	8310260286*	50-445 A		8310120244*	50-305 F
	8310280007	TOPREP		8310120337	50-305 P
	8310280017*	TOPREP		8310120341*	50-305 P
	8310280019*	50-400 E		8310120345*	50-305 P
	8310280106	PROJ		8310170341	50-305 R
	8310280110*	PROJ		8310180522	PR
Westinghouse Operating Plants Owners Group	8310040363	TOPREP		8310210304	50-305 S
	8310110142	TOPREP		8310210317	50-305 S
Whitaker, J M	8310040205	50-454 Q		8310210394*	50-305 F
	8310110278	50-367 Q		8310210396*	50-305 F
	8310200097	50-454 Q	Wood-Leaver & Associates, Inc	8310040611*	50-155 T
	8310210219*	50-454 Q	Wyoming Fuel Co	8310260373	40-8829
White Plains, NY	8310060501*	CONTRACT	Wyoming Mineral Corp	8310040605	40-8502
Whiting Corp	8310120215*	50-155 T		8310210102	40-8502
	8310130297*	50-155 P		8310210107*	40-8502
	8310130301*	50-155 P	Wyoming, State of	8310030559	40-8786
Williams & Associates	8310070221*	CONTRACT		8310210146	40-299
	8310120040*	CONTRACT		8310240045	40-8584
Williams-Robinette & Associates, Inc	8310280068*	CONTRACT		8310250169	40-6622
Williamsport Hosp Williamsport, PA	8310270031	FDIA	Yankee Atomic Electric Co	8310030341	PR
Wisconsin Electric Power Co	8310030447	50-266 Q		8310040108	50-29 P
	8310030447	50-266 Q		8310040307	PR
	8310030616*	50-266 F		8310040330	50-29 P
	8310030624*	50-266 F		8310040333*	50-29 P
	8310040310	50-266 P		8310040334	PR
	8310040310	50-266 P		8310060343	50-443 S
	8310040623	50-266 H		8310120263	50-443 A
	8310070303	50-266 V		8310190012	50-29 R
	8310070303	50-266 V		8310190097	50-29 P
	8310110187	50-266 J		8310190097	50-29 P
	8310110274	50-266 Q		8310190097	50-29 P
	8310110274	50-266 Q		8310190105*	50-29 P
	8310120089	50-266 Q		8310190105*	50-29 P
	8310120089	50-266 Q		8310190105*	50-29 P
	8310120275	PR		8310210250*	50-443 Q
	8310130004	50-266 P		8310250232	50-29 S
	8310130004	50-266 P		8310250277	50-29 S
	8310170234	71-9010		8310250327	50-29 S
	8310170380	50-301 S		8310250418	50-29 S
	8310180119	50-266 R		8310250421	50-29 S
	8310180119	50-266 R		8310250523	50-29 S
	8310180421	50-266 P		8310270042*	50-309 F
	8310180421	50-266 P		8310270534*	50-29 F
	8310180490	50-266 P		8310280015	50-29 S
	8310180490	50-266 P		8310280018	50-29 S
	8310180492*	50-266 P	Zumwalt, L R	8310110271*	CONTRACT
	8310180492*	50-266 P			
	8310180493*	50-266 P			
	8310180493*	50-266 P			
	8310180499*	50-266 P			
	8310180502*	50-266 P			
	8310180502*	50-266 P			
	8310200102	50-266 Q			
	8310200202	50-301 P			
	8310210044	50-266 F			
	8310210044	50-266 F			

REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
02-0160-1102 R01	8310180481*	50-387	P	NUREG-0377 R01	8310310446	NUREG	
02-0160-1102 R1 APPB	8310180493*	50-387	P	NUREG-0380 V12 N09	8310310111	NUREG	
02-0160-1102 R1 APPC	8310180497*	50-387	P	NUREG-0730 V17 N03	8310110169	NUREG	
02-0160-1102 R1 APPD	8310180498*	50-387	P	NUREG-0748 V03 N08	8310310118	NUREG	
02-0160-1102 R1 APPE	8310180501*	50-387	P	NUREG-0750 V17 101	8310310121	NUREG	
02-0160-1102 R1 APPF	8310180504*	50-387	P	NUREG-0750 V17 N04	8310050244	NUREG	
02-0160-1131 RO APPB	8310180514*	50-387	P	NUREG-0835 DRFT	8310210132	NUREG	
02-0160-1131 RO APPC	8310180518*	50-387	P	NUREG-0847	8310190342	NUREG	
02-0160-1131 RO APPD	8310180520*	50-387	P	NUREG-0852 S02	8310050232	50-470	E
02-0160-1131 RO APPE	8310180523*	50-387	P	NUREG-0996	8310180071	50-112	E
02-0160-1131 RO APPF	8310180525*	50-387	P	NUREG-1011	8310070439	50-266	P
02-0160-1131 R00	8310180509*	50-387	P	NUREG-1016	8310180167	50-116	E
0383-03 FA	8310140274*	50-329	B	NUREG-1018	8310110345	NUREG	
1126-F1 V01	8310250093*	50-397	A	NUREG-1020 V01	8310070437	50-289	0
1126-F3 V03	8310250097*	50-397	A	NUREG-1020 V02	8310070441	50-289	0
14331-2 R01	8310130267*	50-400	E	NUREG-1021	8310310452	NUREG	
14331-3 R01	8310130271*	50-400	E	NUREG-1022	8310130130	NUREG	
14801-1 R01	8310130277*	50-400	E	NUREG/CP-0047	8310110171	NUREG	
15737-2-007-102 R03	8310170647*	50-320	P	NUREG/CR-1278	8310200388	NUREG	
5-6167-5	8310130288*	50-400	E	NUREG/CR-2000 V02 N8	8310110023	NUREG	SANDBO-0200 ORNL/NSIC-200
77-1140898-01	8310030356*	50-313	P	NUREG/CR-2000 V02 N9	8310310191	NUREG	ORNL/NSIC-200
83-024	8310310130*	50-416	G	NUREG/CR-2146 V03	8310260427	NUREG	HEOL-THE 83-18
8304-1	8310040573*	50-382	A	NUREG/CR-2482 V04	8310070411	NUREG	BNL-NUREG-5147*
8304-2	8310280006*	50-382	A	NUREG/CR-2571	8310310209	NUREG	EPRI NP-2377
8310050145	8310050145	REG		NUREG/CR-2573	8310180083	NUREG	EPRI NP-2375
8310050329	8310050329	REG		NUREG/CR-2574	8310180076	NUREG	EPRI NP-2376
8310060515	8310060515	MISC		NUREG/CR-2631	8310110174	NUREG	SANDBO-2726
8310070216	8310070216	REG		NUREG/CR-2667	8310190243	NUREG	ORNL/TH-8300
8310200344	8310200344	REG		NUREG/CR-2726	8310190243	NUREG	SANDBO-1137
8310280131	8310280131	REG		NUREG/CR-2830	8310310114	NUREG	BNL-NUREG-31563
AE00/E310	8305030120*	50-361	B	NUREG/CR-2850 V02	8310070442	NUREG	PNL-4221
B0037	8310130261*	50-400	E	NUREG/CR-2893	8310310268	NUREG	PNL-4393
B0045	8310130273*	50-400	E	NUREG/CR-3048	8310110500	NUREG	PARAMETER 1E-12
BAW-1762 R01	8310030306*	50-460	A	NUREG/CR-3050	8310180079	NUREG	PARAMETER 1E-12
BMC-2104	8310270045*	FOIA		NUREG/CR-3051	8310200378	NUREG	PARAMETER 1E-12
CASE-TR2 R02	8310270055*	TOPREP		NUREG/CR-3081	8310310444	50-302	P
CEN-239 S03 R01	8310260160*	50-528	A	NUREG/CR-3122	8310070426	NUREG	BNL-NUREG-51626
CEN-248(8) R01	8310040337*	50-317	P	NUREG/CR-3151	8310310447	NUREG	ORNL/NSIC-213
CEN-255(A)-NP	8310130109*	50-368	P	NUREG/CR-3199	8310260423	NUREG	SANDBO-1414
DTS 1600-1 R08	8310110486*	FOIA		NUREG/CR-3215 V02 ER	8310310106	NUREG	ORNL/TH-8683
E00-HB-6371	8310040123*	50-395	P	NUREG/CR-3223	8310180118	NUREG	PNL-4655
FCTPN-78	8310140174*	TOPREP		NUREG/CR-3259	8310110347	NUREG	EPRI NP-3093
GA-C17258 V01	8310240178	50-546	A	NUREG/CR-3280	8310260389	NUREG	PNL-4694
GA-C17258 V02	8310240179*	50-546	A	NUREG/CR-3299	8310050224	NUREG	LA-9704-HS
GA-C17258 V03	8310240182*	50-546	A	NUREG/CR-3327	8310070134	NUREG	
QADR-55 ADD04	8310130274*	71-6346	22911	NUREG/CR-3334 V01	8310050217	NUREG	ORNL/TH-8787/V1
NUREG-0020 V07 N06	8310050339	NUREG		NUREG/CR-3345	8310110032	NUREG	UCID-19719
NUREG-0090 V06 N01	8310130133	NUREG		NUREG/CR-3352	8310310208	NUREG	PNL-4760
NUREG-0383 V01 R06	8310130151	NUREG		NUREG/CR-3371 V02	8310070436	NUREG	CP-R-221020
NUREG-0383 V02 R06	8310110532	NUREG		NUREG/CR-3384	8310070317	NUREG	PNL-4774
NUREG-0383 V03 R03	8310110593	NUREG		NUREG/CR-3401	8310050253	NUREG	SANDBO-1502
NUREG-0420 S04	8310070116	50-322	E	NUREG/CR-3423	8310070323	NUREG	
NUREG-0485 V05 N08	8310130149	NUREG		NUREG/CR-3437	8310050331	NUREG	E00-2271
NUREG-0540 V05 N07	8310200382	NUREG		NUREG/CR-3445	8310260381	NUREG	PNL-4806
NUREG-0566 V03 N01-3	8310310188	NUREG		NUREG/CR-3450	8310310449	NUREG	

REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
NUREG/CR-3451	8310130143	NUREG		SECY-83-157	8310110439*	50-322	A
NUREG/CR-3464	8310050335	NUREG		SECY-83-183	8310190033*	FOIA	
NUREG/CR-3472 VOI	8310050239	NUREG		SECY-83-269	8307220156*	FOIA	
NUREG/CR-3473	8310070414	NUREG		SECY-83-270	8307220230*	FOIA	
NUREG/CR-3475	8310070110	NUREG	LDL-16363	SECY-83-278	8307270430*	50-289	P
NUREG/CR-3486	8310060079	70-143		SECY-83-311	8308190179	SECY	
NUREG/CR-3487	8310070320	NUREG		SECY-83-311A	8310120025	SECY	
NUREG/CR-3499	8310260397	NUREG		SECY-83-343	8309080114	SECY	
P 103-4-839-054 RO1	8310070100*	50-273	R	SFR-CC-01 1 RO1	8310250128*	50-206	P
P 103-4-839-035 RO1	8310070212*	50-273	R	SQPR-8301	8310260284*	50-445	A
P 103-4-839-061 RO1	8310070091*	50-273	R	SQPR-8302	8310260286*	50-445	A
P 103-4-839-065 RO1	8310140119*	50-273	R	SWRI-6582-003	8310270398*	TOPREP	
P103-4-839-038 RO1	8310040515*	50-273	R	TER-C5257-179	8104070444*	50-206	P
P103-4-839-060 RO1	8310070227*	50-273	R	TER-C5506-174/175	8306160513*	50-324	P
P103-4-839-063 RO1	8310070155*	50-273	R	TER-C5506-241 RO1	8308030382*	50-315	Q TAC 42859
P103-4-839-068 RO1	8310070257*	50-273	R	TER-C5506-242	8309200506*	50-267	Q TAC 42925
PGE-1023-(B3)	8310310301*	50-344	P	TER-C5506-243 RO1	8308030016*	50-293	Q IER-80-11
PGE-1040	8310260246*	50-344	P	TER-C5506-261	8309160203*	50-286	Q IER-80-11
R-83-030	8310060418*	50-261	P	TER-C5506-272	8306160602*	50-302	P
RDD 84:5303-04 02	8310230424*	50-313	Q	TER-C5506-273	8212010152*	50-344	P
SAI-186-028-11	8209200354*	50-220	Q	TER-C5506-294	8210010087*	50-272	P
SAI-186-029-50	8208310352*	50-259	P	TER-C5506-344/345	8309060263*	50-315	P TAC 07980
SAND82-7056	8310190313*	FOIA		TER-C5506-348 DRFT	8308180560*	50-346	P TAC 10993
SD-SWI-DIC-001 ROO	8310110626*	WASTE HOT	000360	TER-C5506-379/380	8309020392*	50-277	P TAC 08070
SD-SWI-DF-035 R B	8310280295*	WASTE HOT		TER-C5506-409	8307200260*	50-336	P
SECY-82-077	8203120050*	FOIA		TER-C5506-410	8307250463*	50-313	P
SECY-82-121	8204070171*	50-320	P	TER-C5506-412	8308300317*	50-213	P TAC 41315
SECY-82-141A	8310310114*	FOIA		TER-C5506-93	8301210240*	50-244	P TAC 8097
SECY-82-168	8205050588*	FOIA		TF-334/0806A	8306030372*	50-286	P TAC 44379
SECY-82-221	8206100323*	FOIA		TF-343/0809A	8306080112*	50-272	P TAC 44405
SECY-82-242	8206240098*	FOIA		TF-349/0812A	8306080065*	50-336	P TAC 44385
SECY-82-243	8206300342*	FOIA		TF-366/0817A	8306130456*	50-346	P TAC 44364
SECY-82-251	8206250316*	FOIA		TF-367/0817A	8306080055*	50-312	P TAC 44402
SECY-82-279	8310110017*	FOIA		TF-370/0817A	8306080106*	50-302	P TAC 44363
SECY-82-330	8208270362*	FOIA		TF-380/0823A	8310050534*	50-237	P TAC 44369
SECY-82-460	8211290108*	FOIA		TR-5319-2	8310120315*	50-271	P
SECY-82-463	8310310131*	50-289	P	TR-5321-1 ROO	8310140202*	50-333	P
SECY-83-030	8310290030*	FOIA		VEP-NFE-1	8310190057*	50-280	P
SECY-83-032A	8310270268*	FOIA		XN-NF-80-19(NP) (A1V4	8310140244*	TOPREP	
SECY-83-044	8302160056*	FOIA		XN-NF-83-57	8310050470*	50-255	P
SECY-83-072	8310310136*	FOIA		XN-NF-83-72	8310120415*	50-261	P
SECY-83-093	8310310140*	FOIA		XN-NF-83-72 S01	8310120422*	50-261	P
SECY-83-112	8304050526*	FOIA		VAEC-1055	8310310061*	50-271	P
SECY-83-120	8310110022*	50-445	A	VODAP-I-A R14	8310190105*	50-29	P
SECY-83-126	8304220068*	FOIA					

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7906230181	8310240171	83/07/06	FOIA	8206240098	8310270360	83/09/29	FOIA
7906230189	8310240171	83/07/06	FOIA	8206250316	8310310097	83/09/19	FOIA
7908060316	8310170078	83/06/07	FOIA	8206300342	8310310097	83/09/19	FOIA
7908270319	8310170078	83/06/07	FOIA	8207150081	8310120329	83/10/03	50-29 P
7909140005	8310170078	83/06/07	FOIA	8207260091	8310260008	83/06/23	50-269 S
7911300172	8310170078	83/06/07	FOIA	8207280124	8310200354	83/09/23	FOIA
8001040244	8310170078	83/06/07	FOIA	8208010014	8310110034	83/06/15	50-275 P
8003240118	8310120016	83/07/07	FOIA	8208230434	8310110044	83/07/20	50-382 Q
8003240123	8310120016	83/07/07	FOIA	8208240121	8310250032	83/07/15	FOIA
8004230428	8310170078	83/06/07	FOIA	8208270562	8310110007	83/07/15	FOIA
8006170100	8310170078	83/06/07	FOIA	8208310352	8310240243	83/10/12	50-239 P
8006400467	8310170078	83/06/07	FOIA	8209010314	8310110044	83/07/20	50-382 Q
8007170062	8310170078	83/06/07	FOIA	8209200354	8310070114	83/09/19	50-220 Q
8007170067	8310170078	83/06/07	FOIA	8210010087	8310060557	83/09/27	50-272 P
8007170227	8310170078	83/06/07	FOIA	8210050447	8310110044	83/07/20	50-382 Q
8007290663	8310120016	83/07/07	50-339 P	8210180246	8310210329	83/07/28	50-366 S
8007290674	8310120016	83/07/07	50-339 P	8210280450	8310180625	83/09/01	50-329 A
8008270592	8310140031	83/08/23	50-498 Q	8211020311	8310260008	83/06/23	FOIA
8009160105	8310170078	83/06/07	FOIA	8211040474	8310260008	83/06/23	FOIA
8009240099	8310170078	83/06/07	FOIA	8211290108	8310310097	83/09/19	FOIA
8010010786	8310240320	83/07/14	50-348 P	8212010152	8310040648	83/09/01	50-346 P
8010070328	8310170078	83/06/07	FOIA	8212130165	8310040407	83/09/22	50-267 P
8011050238	8310240235	83/07/11	FOIA	8212130174	8310260008	83/06/23	FOIA
8011190749	8310240235	83/07/11	FOIA	8212150242	8310270468	83/10/04	FOIA
8012010577	8310170078	83/06/07	FOIA	8212150244	8310270468	83/10/04	FOIA
8012310197	8310170078	83/06/07	FOIA	8212290072	8310270468	83/10/04	FOIA
8012310243	8310170078	83/06/07	FOIA	8212300074	8310180625	83/09/01	50-329 A
8012310507	8310170078	83/06/07	FOIA	8301070386	8310190340	83/09/15	50-282 S
8101070486	8310170078	83/06/07	FOIA	8301180513	8310210329	83/07/28	50-321 S
8101090060	8310170078	83/06/07	FOIA	8301210240	8310070345	83/09/39	50-244 P
8101090109	8310170078	83/06/07	FOIA	8301250200	8310250032	83/07/15	FOIA
8102260210	8310240235	83/07/11	FOIA	8302020202	8310210329	83/07/28	50-333 S
8103060697	8310170078	83/06/07	FOIA	8302090523	8307050513	83/06/08	50-255 P
8103180096	8310170078	83/06/07	FOIA	8302160054	8310310097	83/09/19	FOIA
8104070444	8309240301	83/05/20	50-206 P	8302180539	8310210329	83/07/28	50-239 S
8104170659	8310170078	83/06/07	FOIA	8303030103	8310210329	83/07/28	50-387 S
8104170666	8310170078	83/06/07	FOIA	8303230300	8310210315	83/07/29	50-352 A
8104210028	8310170078	83/06/07	FOIA	8303230482	8307050513	83/06/08	50-255 P
8112170188	8310110044	83/07/20	50-382 Q	8303240341	8310210329	83/07/28	50-324 S
8202230210	8310260019	83/07/15	FOIA	8303240364	8310210329	83/07/28	50-277 S
8203120050	8310310097	83/09/19	FOIA	8304010047	8310260008	83/06/23	FOIA
8204070171	8310310097	83/09/19	50-320 P	8304050526	8310240263	83/07/11	FOIA
8205050588	8310310097	83/09/19	FOIA	8304200046	8307050513	83/06/08	50-255 P
8205140137	8310190093	83/09/07	FOIA	8304200240	8310190340	83/09/15	50-282 S
8205140143	8310190093	83/09/07	FOIA	8304220088	8310310097	83/09/19	FOIA
8205270433	8307050513	83/06/08	50-255 P	8305030115	8310280079	83/07/28	50-361 S
8206080487	8310240197	83/09/08	50-528 A	8305030120	8310280079	83/07/28	50-361 S
8206100323	8310310097	83/09/19	FOIA	8305050044	8310190340	83/09/15	50-282 S
8206140401	8310190093	83/09/07	FOIA	8305060071	8307050513	83/06/08	50-255 P
8206140403	8310190093	83/09/07	FOIA	8305060124	8310180588	83/09/04	50-445 A

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8305130302	8310240237	83/07/06	FOIA	8310030375	8310030367	83/09/27	50-400 Q
8305130304	8310240237	83/07/06	FOIA	8310030377	8310030367	83/09/27	50-400 Q
8305130306	8310240237	83/07/06	FOIA	8310030380	8310030367	83/09/27	50-400 Q
8305160184	8310280079	83/07/28	50-361 S	8310030381	8310030379	83/09/13	0A999
8305240300	8310190340	83/09/13	50-282 S	8310030383	8310030379	83/09/13	0A999
8306010008	8310210329	83/07/28	50-271 S	8310030387	8310030379	83/09/13	0A999
8306020337	8310030308	83/09/21	50-309 S	8310030392	8310030385	83/09/07	50-498 Q
8306030372	8310040035	83/09/19	50-286 P	8310030407	8308300352	83/09/29	50-382 A
8306080035	8310110476	83/09/27	50-312 P	8310030409	8310030406	83/09/27	50-413 Q
8306080045	8310110543	83/09/20	50-334 P	8310030411	8310030393	83/08/29	50-445 Q
8306080106	8310050297	83/08/08	50-302 P	8310030420	8310030402	83/08/17	50-458 Q
8306080112	8310070097	83/09/27	50-272 P	8310030421	8310030418	83/09/15	50-287 P
8306090346	8310070080	83/09/28	50-346 P	8310030450	8310030445	83/09/16	0A999
8306130456	8310200041	83/10/05	50-346 P	8310030451	8310030444	83/09/27	0A999
8306160513	8310310137	83/10/14	50-324 P	8310030454	8310030445	83/09/16	0A999
8306160602	8310200064	83/10/06	50-302 P	8310030457	8310030446	83/08/08	50-267 Q
8306170106	8310200220	83/10/14	50-206 Q	8310030459	8310030445	83/09/16	0A999
8306170442	8310200220	83/10/14	50-206 Q	8310030469	8310030446	83/09/27	0A999
8306230142	8310200220	83/10/14	50-206 Q	8310030478	8310030441	83/09/23	50-400 Q
8307200260	8310110466	83/09/23	50-334 P	8310030497	8310030492	83/09/30	50-155 P
8307220156	8310190049	83/09/13	FOIA	8310030534	8310030524	83/09/21	CONTRACT
8307220230	8310270369	83/10/04	FOIA	8310030568	8310030561	83/09/12	71-9151
8307230163	8310110472	83/09/26	50-313 P	8310030574	8310030561	83/09/12	71-9151
8307270430	8310270369	83/10/04	50-289 P	8310030579	8310030564	83/09/28	50-315 F
8307290223	8310200356	83/09/23	FOIA	8310030582	8310030573	83/09/28	50-395 F
8308030016	8310110456	83/09/12	50-295 Q	8310030587	8310030573	83/09/28	50-395 F
8308030382	8310130025	83/09/20	50-315 Q	8310030600	8310030598	83/09/07	50-346 P
8308080570	8310200356	83/09/23	FOIA	8310030607	8310030604	83/09/23	50-327 P
8308150338	8310130394	83/08/25	50-329 A	8310030610	8310030605	83/09/19	WASTE MOT
8308150385	8310130189	83/10/04	50-387 S	8310030615	8310030613	83/09/20	50-348 P
8308180258	8310190340	83/09/15	50-282 S	8310030616	8310030609	83/09/28	50-266 F
8308180560	8310200050	83/10/06	50-346 P	8310030622	8310030620	83/09/26	50-289 P
8308290029	8310130394	83/08/25	50-329 A	8310030624	8310030609	83/09/28	50-266 F
8308300317	8310030140	83/09/26	50-213 P	8310030645	8310030641	83/09/23	GEN TEC 18
8308300486	8308300480	83/08/26	50-413 Q	8310040042	8310040012	83/09/08	50-321 Q
8308300610	8308300607	83/07/08	40-6622	8310040043	8310040037	83/09/02	50-261 Q
8308300712	8308300705	83/08/05	0A999	8310040056	8310040051	83/09/16	50-305 Q
8308300716	8308300705	83/08/05	0A999	8310040060	8310040051	83/09/16	50-305 Q
8308300722	8308300705	83/08/05	0A999	8310040072	8310040068	83/09/20	50-305 P
8308310422	8310110472	83/09/26	50-313 P	8310040099	8310040094	83/09/23	71-466
8308310512	8310310294	83/10/18	50-267 Q	8310040123	8310040120	83/09/16	50-395 P
8309020392	8310110454	83/09/21	50-277 P	8310040127	8310040124	83/09/30	50-382 A
8309060263	8310070408	83/09/20	50-315 P	8310040129	8310040124	83/09/30	50-382 A
8309070071	8310030131	83/09/26	MISC	8310040131	8310040124	83/09/30	50-382 A
8309080358	8310270379	83/10/18	GEN TEC 18	8310040136	8310040121	83/09/22	50-10 F
8309080363	8310270379	83/10/18	GEN TEC 18	8310040137	8310040133	83/09/23	70-2945
8309160058	8310060157	83/09/27	NOREG	8310040147	8310040140	83/09/09	50-390 Q
8309160203	8310110465	83/09/23	50-286 Q	8310040148	8310040143	83/09/01	70-1151
8309200506	8310310274	83/10/18	50-267 Q	8310040150	8310040146	83/09/08	50-413 Q
8309300064	8310200070	83/10/04	50-382 A	8310040157	8310040153	83/08/29	50-382 Q
8309300246	8309300239	83/09/22	50-460 F	8310040160	8310040156	83/09/02	50-445 Q
8310030063	8310030060	83/09/28	50-382 K	8310040162	8310040158	83/09/27	50-456 Q
8310030067	8310030060	83/09/28	50-382 K	8310040164	8310040161	83/09/30	50-423 K
8310030082	8310030080	83/09/29	50-244 P	8310040167	8310040163	83/09/08	50-416 Q
8310030085	8310030081	83/09/13	50-416 P	8310040168	8310040166	83/09/07	50-261 Q
8310030088	8310030081	83/09/13	50-416 P	8310040178	8310040174	83/09/15	50-321 Q
8310030100	8310030093	83/09/28	50-116 P	8310040179	8310040176	83/09/21	50-346 Q
8310030104	8310030081	83/09/15	50-416 P	8310040186	8310040181	83/08/24	50-445 Q
8310030151	8310030143	83/09/27	50-27 F	8310040191	8310040189	83/09/29	50-277 P
8310030168	8310030167	83/09/27	50-498 K	8310040197	8310040190	83/09/08	70-143
8310030210	8310030203	83/09/07	40-8584	8310040198	8310040195	83/09/16	50-331 Q
8310030213	8310030198	83/09/28	XPORTLIC	8310040203	8310040182	83/08/30	50-324 Q
8310030215	8310030203	83/09/07	40-8584	8310040212	8310040209	83/09/27	50-275 Q
8310030236	8310030229	83/09/28	50-373 F	8310040219	8310040209	83/09/29	50-275 Q
8310030238	8310030232	83/09/27	50-458 C	8310040222	8310040215	83/09/01	50-424 Q
8310030250	8310030241	83/09/08	40-8452	8310040224	8310040220	83/09/13	50-400 Q
8310030268	8310030263	83/09/28	50-219 P	8310040226	8310040221	83/09/20	50-275 Q
8310030272	8310030263	83/09/28	50-219 P	8310040229	8310040227	83/09/16	50-440 E
8310030305	8310030294	83/09/28	50-280 Q	8310040231	8310040227	83/09/16	50-440 E
8310030306	8310030303	83/09/23	50-460 A	8310040234	8310040227	83/09/16	50-440 E
8310030316	8310030308	83/09/21	50-309 S	8310040235	8310040228	83/07/13	50-247 F
8310030340	8310030337	83/09/27	50-368 P	8310040239	8310040233	83/09/30	50-382 Q
8310030347	8310030344	83/07/21	50-267 Q	8310040240	8310040223	83/08/24	50-445 Q
8310030348	8310030342	83/09/16	0A999	8310040244	8310040211	83/09/02	50-439 Q
8310030350	8310030344	83/07/21	50-267 Q	8310040245	8310040233	83/09/30	50-382 Q
8310030352	8310030342	83/09/16	0A999	8310040246	8310040242	83/09/12	0A999
8310030356	8310030353	83/09/23	50-313 Q	8310040249	8310040242	83/09/12	0A999
8310030360	8310030345	83/09/12	50-412 Q	8310040253	8310040247	83/09/09	50-269 Q
8310030369	8310030367	83/09/27	50-400 Q	8310040255	8310040250	83/09/13	50-255 Q
8310030372	8310030367	83/09/27	50-400 Q	8310040260	8310040257	83/09/28	50-454 Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

557

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8310040261	8310270020	83/07/18	FOIA	8310040500	8310040484	83/09/28	50-249 Q
8310040262	8310040256	83/09/29	50-443 Q	8310040501	8310040464	83/09/26	70-27
8310040266	8310040264	83/09/28	50-155 P	8310040507	8310040484	83/09/28	50-249 Q
8310040271	8310040265	83/09/14	50-259 Q	8310040508	8310040464	83/09/26	70-27
8310040272	8310040256	83/09/29	50-443 Q	8310040515	8310040509	83/10/01	50-275 R
8310040273	8310040268	83/09/30	50-483 Q	8310040517	8310040504	83/09/09	50-250 Q
8310040275	8310040265	83/09/14	50-259 Q	8310040519	8310040505	83/09/30	50-155 T
8310040277	8310040256	83/09/29	50-443 Q	8310040527	8310040521	83/09/27	50-423 C
8310040278	8310040265	83/09/14	50-259 Q	8310040531	8310040526	83/09/13	50-546 Q
8310040283	8310040265	83/09/14	50-259 Q	8310040537	8310040532	83/09/19	50-528 Q
8310040285	8310040269	83/09/13	50-261 Q	8310040540	8310040526	83/09/13	50-546 Q
8310040294	8310040290	83/08/30	50-269 Q	8310040541	8310040538	83/09/29	50-400 Q
8310040304	8310040301	83/09/29	50-302 P	8310040546	8310040536	83/08/29	50-498 Q
8310040306	8310040298	83/09/22	50-324 Q	8310040557	8310040553	83/09/29	50-155 T
8310040308	8310040300	83/09/23	50-312 Q	8310040560	8310040551	83/09/30	50-155 T
8310040309	8310040303	83/09/21	70-143	8310040563	8310040555	83/09/12	50-390 Q
8310040311	8310040300	83/09/23	50-312 Q	8310040564	8310040551	83/09/30	50-155 T
8310040312	8310040303	83/09/21	70-143	8310040565	8310040559	83/09/29	50-282 A
8310040314	8310040303	83/09/21	70-143	8310040566	8310040558	83/09/06	50-267 Q
8310040316	8310040305	83/08/30	50-250 Q	8310040568	8310040548	83/09/30	50-155 T
8310040319	8310040313	83/09/22	50-413 Q	8310040569	8310040561	83/09/27	50-334 F
8310040321	8310040298	83/09/22	50-324 Q	8310040571	8310040567	83/08/19	50-285 Q
8310040322	8310040315	83/09/16	50-267 S	8310040573	8310040559	83/09/29	50-282 A
8310040323	8310040313	83/09/22	50-413 Q	8310040577	8310040567	83/08/19	50-285 Q
8310040324	8310040315	83/09/16	50-267 S	8310040578	8310040570	83/09/29	50-275 P
8310040326	8310040298	83/09/22	50-324 Q	8310040579	8310040576	83/09/16	QA999
8310040327	8310040313	83/09/22	50-413 Q	8310040583	8310040580	83/08/24	50-267 Q
8310040328	8310040315	83/09/16	50-267 S	8310040585	8310040570	83/09/29	50-275 P
8310040332	8310040298	83/09/22	50-324 Q	8310040586	8310040576	83/09/16	QA999
8310040333	8310040330	83/09/30	50-29 P	8310040589	8310040580	83/08/24	50-267 Q
8310040335	8310040313	83/09/22	50-413 Q	8310040590	8310040587	83/09/29	50-338 P
8310040340	8310040303	83/09/21	70-143	8310040591	8310040570	83/09/29	50-275 P
8310040341	8310040336	83/09/30	50-358 F	8310040596	8310040576	83/09/16	QA999
8310040342	8310040337	83/09/29	70-824	8310040598	8310040570	83/09/29	50-275 P
8310040343	8310040329	83/09/02	50-413 Q	8310040600	8310040595	83/09/13	50-400 Q
8310040349	8310040343	83/09/30	QA999	8310040603	8310040595	83/09/13	50-400 Q
8310040350	8310040346	83/09/20	70-143	8310040606	8310040595	83/09/13	50-400 Q
8310040355	8310040353	83/09/28	50-317 P	8310040610	8310040595	83/09/13	50-400 Q
8310040357	8310040353	83/09/28	50-317 P	8310040611	8310040594	83/09/30	50-155 T
8310040360	8310040359	83/09/16	70-36	8310040613	8310040595	83/09/13	50-400 Q
8310040366	8310040356	83/09/19	50-321 Q	8310040615	8307260003	83/06/10	50-458 A
8310040367	8310040365	83/09/30	50-155 T	8310040621	8310040620	83/09/25	50-155 T
8310040369	8310040365	83/09/30	50-155 T	8310040624	8310040620	83/09/25	50-155 T
8310040373	8310040374	83/09/19	50-348 Q	8310040628	8310040622	83/09/23	70-1151
8310040377	8310040374	83/09/19	50-348 Q	8310040632	8310040622	83/09/23	70-1151
8310040378	8310040374	83/09/19	50-348 Q	8310040635	8310040622	83/09/23	70-1151
8310040381	8310040376	83/09/30	50-155 T	8310040637	8310040622	83/09/23	70-1151
8310040383	8310040382	83/09/30	QA999	8310040642	8310040639	83/09/16	50-362 P
8310040384	8310040374	83/09/19	50-348 Q	8310040643	8310040639	83/09/16	50-362 P
8310040388	8310040385	83/09/27	50-324 P	8310040644	8310040558	83/09/06	50-267 Q
8310040393	8310040389	83/09/28	50-410 Q	8310050022	8310050017	83/09/21	50-348 P
8310040399	8310040391	83/09/15	50-18 Q	8310050030	8310050025	83/09/23	71-7510
8310040411	8310040400	83/09/22	50-334 Q	8310050041	8310050016	83/09/26	71-6003
8310040413	8310040406	83/09/13	50-413 Q	8310050047	8310050044	83/09/23	50-199 P
8310040426	8310040422	83/09/30	QA999	8310050056	8310050046	83/08/18	71-9080
8310040427	8310040423	83/09/12	50-390 Q	8310050057	8310050053	83/09/26	71-9100
8310040429	8310040415	83/09/29	50-277 P	8310050059	8308300767	83/10/11	50-329 A
8310040430	8310040424	83/09/23	50-454 Q	8310050061	8310050055	83/09/30	50-320 P
8310040433	8310040422	83/09/30	QA999	8310050065	8310050046	83/08/18	71-9080
8310040437	8310040422	83/09/30	QA999	8310050074	8310050046	83/08/18	71-9080
8310040441	8310040432	82/12/22	QA999	8310050082	8310050077	83/09/23	50-346 F
8310040446	8310040442	83/09/20	50-327 Q	8310050133	8310050124	83/09/23	71-37
8310040453	8310040432	82/12/22	QA999	8310050164	8310050159	83/08/26	50-272 P
8310040454	8310040447	83/09/14	50-335 Q	8310050174	8310050159	83/08/26	50-272 P
8310040461	8310040459	83/09/30	50-358 K	8310050181	8310050177	83/09/21	40-8794
8310040468	8310040356	83/09/17	50-321 Q	8310050206	8308300771	83/10/06	50-244 P
8310040470	8310040464	83/09/26	70-27	8310050212	8310050197	83/09/23	PROJ
8310040472	8310040466	83/09/23	50-302 Q	8310050255	8310050245	83/10/03	50-285 P
8310040475	8310040466	83/09/23	50-302 Q	8310050271	8310050245	83/10/03	50-285 P
8310040477	8310040466	83/09/23	50-302 Q	8310050304	8310050297	83/08/08	50-302 P
8310040479	8310040356	83/09/19	50-321 Q	8310050310	8310050298	83/10/03	50-285 P
8310040480	8310040466	83/09/23	50-302 Q	8310050315	8310050298	83/10/03	50-285 P
8310040482	8310040474	83/09/22	50-369 P	8310050323	8310050319	83/09/21	CONTRACT
8310040486	8310040464	83/09/26	70-27	8310050334	8310050327	83/09/26	50-289 F
8310040488	8310040485	83/09/30	QA999	8310050337	8310050336	83/09/26	CONTRACT
8310040492	8310040484	83/09/28	50-269 Q	8310050344	8310050340	83/09/26	50-317 F
8310040493	8310040489	83/09/14	70-27	8310050349	8310050343	83/09/26	CONTRACT
8310040495	8310040484	83/09/28	50-269 Q	8310050362	8310050357	83/09/27	CONTRACT
8310040499	8310040356	83/09/19	50-321 Q	8310050369	8310050367	83/09/26	CONTRACT

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8310050370	8310050365	83/09/26	CONTRACT	8310060103	8310060091	83/09/28	CONTRACT
8310050381	8310050373	83/09/29	50-443 Q	8310060115	8310060109	83/09/27	CONTRACT
8310050382	8310050375	83/09/29	50-440 Q	8310060129	8310060122	83/09/23	CONTRACT
8310050387	8310050379	83/09/26	CONTRACT	8310060138	8310060117	83/09/29	CONTRACT
8310050388	8310050373	83/09/29	50-443 Q	8310060145	8310060142	83/09/21	MISC
8310050389	8310050375	83/09/29	50-440 Q	8310060165	8310060158	83/09/21	50-331 Q
8310050391	8310050383	83/09/26	CONTRACT	8310060168	8310060154	83/09/17	CONTRACT
8310050392	8310050386	83/09/30	50-413 T	8310060175	8310060171	83/09/26	50-251 S
8310050401	8310050386	83/09/30	50-413 T	8310060179	8310060171	83/09/26	50-251 S
8310050412	8310050403	83/09/28	50-445 Q	8310060184	8310060140	83/09/23	27-39
8310050415	8310050386	83/09/30	50-413 T	8310060185	8310060171	83/09/26	50-251 S
8310050419	8310050386	83/09/30	50-413 T	8310060190	8310060171	83/09/26	50-251 S
8310050420	8310050409	83/09/22	CONTRACT	8310060191	8310060178	83/09/27	CONTRACT
8310050432	8310050429	83/09/30	50-352 Q	8310060193	8310060188	83/10/03	50-400 Q
8310050458	8310050456	83/09/26	CONTRACT	8310060194	8310060171	83/09/26	50-251 S
8310050460	8310050459	83/09/29	CONTRACT	8310060199	8310060171	83/09/26	50-251 S
8310050464	8310050462	83/09/28	CONTRACT	8310060203	8310060188	83/10/03	50-400 Q
8310050465	8310050463	83/09/29	50-255 P	8310060212	8310060188	83/10/03	50-400 Q
8310050467	8310050466	83/09/29	CONTRACT	8310060222	8310060188	83/10/03	50-400 Q
8310050468	8310050452	83/09/30	50-454 Q	8310060238	8310060188	83/10/03	50-400 Q
8310050469	8310050463	83/09/29	50-255 P	8310060250	8310060243	83/09/30	50-313 F
8310050470	8310050463	83/09/29	50-255 P	8310060252	8310060245	83/10/03	50-358 Q
8310050473	8310050471	83/09/21	70-143	8310060259	8310060245	83/10/03	50-358 Q
8310050474	8310050472	83/09/26	50-443 Q	8310060261	8310060258	83/07/18	50-344 F
8310050475	8310050452	83/09/30	50-454 Q	8310060262	8310060256	83/09/30	50-213 F
8310050477	8310050472	83/09/26	50-443 Q	8310060263	8310060245	83/10/03	50-358 Q
8310050478	8310050461	83/09/30	50-155 T	8310060266	8310060245	83/10/03	50-358 Q
8310050480	8310050472	83/09/26	50-443 Q	8310060268	8310060265	83/10/03	50-369 F
8310050481	8310050461	83/09/30	50-155 T	8310060270	8310060267	83/09/30	PROJ
8310050485	8310050461	83/09/30	50-155 T	8310060290	8310060278	83/09/13	CONTRACT
8310050486	8310050483	83/10/02	50-155 Q	8310060291	8310060269	83/10/03	50-329 Q
8310050489	8310050483	83/10/02	50-155 Q	8310060309	8310060282	83/09/14	50-461 Q
8310050491	8310050483	83/10/02	50-155 Q	8310060321	8310060319	83/09/30	50-454 Q
8310050494	8310050483	83/10/02	50-155 Q	8310060326	8310060310	83/09/24	CONTRACT
8310050495	8310050461	83/09/30	50-155 T	8310060328	8310060327	83/09/28	50-311 P
8310050497	8310050492	83/09/23	50-341 Q	8310060329	8310060304	83/10/03	50-315 P
8310050498	8310050493	83/09/22	50-373 Q	8310060334	8310060330	83/09/30	50-305 Q
8310050500	8310050461	83/09/30	50-155 T	8310060349	8310060341	83/09/22	50-334 Q
8310050501	8310050483	83/10/02	50-155 Q	8310060364	8310060363	83/10/04	50-443 U
8310050502	8310050493	83/09/22	50-373 Q	8310060372	8310060360	83/09/21	50-155 Q
8310050504	8310050461	83/09/30	50-155 T	8310060374	8310060360	83/09/21	50-155 Q
8310050507	8310050483	83/10/02	50-155 Q	8310060381	8310060376	83/09/27	50-298 S
8310050514	8310050461	83/09/30	50-155 T	8310060391	8310060379	83/08/19	50-382 Q
8310050517	8310050512	83/09/27	50-312 Q	8310060406	8310060402	83/06/10	50-313 P
8310050521	8310050512	83/09/27	50-312 Q	8310060409	8310060395	83/10/03	50-461 Q
8310050522	8310050518	83/09/23	50-358 Q	8310060418	8310060413	83/09/30	50-261 P
8310050530	8310050518	83/09/23	50-358 Q	8310060453	8310060449	83/09/23	50-483 Q
8310050534	8310050524	83/10/03	50-237 P	8310060462	8310060449	83/09/23	50-483 Q
8310050535	8310050527	83/09/29	70-143	8310060464	8310060459	83/08/22	50-382 Q
8310050540	8310050538	83/09/22	50-358 Q	8310060479	8310060474	83/09/30	50-215 F
8310050545	8310050539	83/09/28	CONTRACT	8310060483	8310060471	83/09/20	CONTRACT
8310050546	8310050538	83/09/22	50-358 Q	8310060486	8310060481	83/09/22	50-387 F
8310050550	8310050549	83/09/28	CONTRACT	8310060492	8310060490	83/09/22	50-335 F
8310050552	8310050548	83/09/29	50-3 F	8310060493	8310060487	83/09/30	CONTRACT
8310050554	8310050548	83/09/29	50-3 F	8310060494	8310060490	83/09/22	50-335 F
8310050556	8310050553	83/09/27	CONTRACT	8310060496	8310060495	83/09/19	CONTRACT
8310050558	8308300357	83/09/29	50-247 P	8310060501	8310060499	83/09/13	CONTRACT
8310050564	8310050559	83/09/21	50-87 Q	8310060506	8310060503	83/09/23	CONTRACT
8310050567	8310050563	83/07/29	50-315 P	8310060512	8310060507	83/09/19	CONTRACT
8310060010	8310060007	83/09/28	CONTRACT	8310060523	8310060519	83/09/30	50-280 F
8310060012	8310060004	83/09/22	50-410 Q	8310060532	8310060529	83/09/30	50-289 F
8310060014	8310060013	83/08/22	50-267 Q	8310060537	8310060534	83/09/16	50-389 P
8310060015	8310060013	83/08/22	50-267 Q	8310060538	8310060533	83/09/30	50-387 F
8310060019	8310060017	83/09/22	50-244 Q	8310060540	8310060535	83/09/16	50-364 P
8310060022	8310060021	83/09/30	50-312 F	8310060545	8310060541	83/09/30	50-294 F
8310060026	8310060020	83/08/01	50-313 Q	8310060548	8310060543	83/09/23	70-2988
8310060030	8310060024	83/09/30	50-155 P	8310060551	8310060549	83/09/30	50-289 F
8310060037	8310060033	83/09/23	50-416 P	8310060552	8310060547	83/09/27	50-261 P
8310060043	8310060031	83/09/22	50-324 P	8310060553	8310060543	83/09/23	70-2988
8310060046	8310060041	83/09/22	50-388 Q	8310060561	8310060555	83/09/30	50-324 F
8310060048	8310060044	83/09/22	50-244 Q	8310060564	8310060555	83/09/30	50-324 F
8310060049	8310060031	83/09/22	50-324 P	8310060576	8310060573	83/09/21	50-263 F
8310060050	8310060033	83/09/23	50-416 P	8310060577	8310060566	83/10/05	50-280 F
8310060063	8310060058	83/09/28	50-369 S	8310060578	8310060574	83/09/21	50-220 F
8310060064	8310060057	83/09/23	50-416 P	8310060584	8310060566	83/10/05	50-280 F
8310060065	8310060060	83/09/19	XPORTLIC	8310060593	8310060591	83/09/08	50-382 U
8310060066	8310060054	83/10/03	50-324 P	8310060594	8310060591	83/09/08	50-382 U
8310060068	8310060058	83/09/28	50-369 S	8310060595	8310060590	83/10/05	50-346 F
8310060071	8310060057	83/09/23	50-416 P	8310060600	8310060599	83/09/29	71-9070
8310060084	8310060081	83/09/20	XPORTLIC				

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

559

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8310060601	8310060597	83/10/05	50-313 F	8310070316	8310070311	83/09/29	50-263 P
8310070007	8310210134	83/10/12	50-329 A	8310070331	8310070329	83/09/09	CONTRACT
8310070024	8310070016	83/09/23	70-364	8310070346	8310070342	83/09/27	50-397 A
8310070025	8310070020	83/09/22	50-10 P	8310070368	8310070365	83/09/29	50-244 P
8310070027	8310070016	83/09/23	70-364	8310070369	8310070363	83/09/13	COMMISSION
8310070028	8310070016	83/09/23	70-364	8310070372	8310070365	83/09/29	50-244 P
8310070032	8310070016	83/09/23	70-364	8310070380	8310070377	83/09/13	COMMISSION
8310070035	8310070016	83/09/23	70-364	8310070386	8310070383	83/09/02	COMMISSION
8310070037	8310070034	83/09/28	40-8027	8310070393	8310070391	83/09/21	50-298 F
8310070038	8310070016	83/09/23	70-364	8310070409	8310070408	83/09/20	50-315 P
8310070040	8310070016	83/09/23	70-364	8310070415	8310070407	83/09/21	CONTRACT
8310070042	8310070016	83/09/23	70-364	8310070418	8310070403	83/09/30	50-280 F
8310070043	8310070041	83/09/12	COMMISSION	8310070429	8310070428	83/09/26	CONTRACT
8310070048	8310070045	83/09/22	50-293 P	8310070432	8310070431	83/09/19	CONTRACT
8310070052	8310070049	83/09/22	50-364 G	8310070435	8310070434	83/09/27	CONTRACT
8310070054	8310070049	83/09/22	50-364 G	8310110006	8310110002	83/09/15	COMMISSION
8310070062	8310070059	83/09/26	71-9152	8310110008	8310110002	83/09/15	COMMISSION
8310070082	8310070076	83/09/30	50-289 P	8310110009	8310110003	83/09/23	CONTRACT
8310070085	8310070080	83/09/28	50-346 P	8310110010	8310110004	83/07/01	50-295 F
8310070090	8310070087	83/08/02	40-8794	8310110011	8310110004	83/07/01	50-295 T
8310070091	8310070086	83/10/02	50-275 R	8310110012	8310110002	83/09/15	COMMISSION
8310070092	8310070087	83/08/02	40-8794	8310110013	8310110004	83/07/01	FOIA
8310070100	8310070094	83/10/04	50-275 R	8310110014	8310110002	83/09/15	COMMISSION
8310070103	8310070097	83/09/27	50-272 P	8310110015	8310110002	83/09/15	COMMISSION
8310070106	8310070099	83/09/26	CONTRACT	8310110016	8310110004	83/07/01	FOIA
8310070112	8310070104	83/09/21	TOPREP	8310110017	8310110007	83/07/15	FOIA
8310070117	8310070115	83/09/21	CONTRACT	8310110018	8310110004	83/07/01	FOIA
8310070119	8310070114	83/09/19	50-220 Q	8310110022	8310110007	83/07/15	50-445 A
8310070123	8310070114	83/09/19	50-220 Q	8310110024	8310110019	83/10/05	50-155 F
8310070129	8310070125	83/09/30	MISC	8310110025	8310110021	83/07/15	FOIA
8310070131	8310070128	83/09/26	50-370 F	8310110028	8310110027	83/10/05	50-305 F
8310070143	8310070134	83/10/04	50-269 F	8310110029	8310110026	83/09/23	CONTRACT
8310070144	8310070140	83/09/22	50-382 A	8310110031	8310110027	83/10/05	50-305 F
8310070145	8310070139	83/10/04	70-143	8310110033	8310110030	83/06/30	FOIA
8310070148	8310070121	83/09/17	CONTRACT	8310110036	8310110035	83/10/05	50-331 F
8310070152	8310070134	83/10/04	50-269 F	8310110037	8310110034	83/06/15	FOIA
8310070153	8310070146	83/09/28	PR	8310110038	8310110035	83/10/05	50-331 F
8310070155	8310070151	83/10/02	50-275 R	8310110039	8310110034	83/06/15	50-275 P
8310070161	8310070156	83/09/30	50-10 Q	8310110046	8310110034	83/06/15	50-275 P
8310070167	8310070156	83/09/30	50-10 Q	8310110048	8310110034	83/06/15	50-275 P
8310070171	8310070156	83/09/30	50-10 Q	8310110051	8310110044	83/07/20	50-382 G
8310070173	8310070165	83/09/27	CONTRACT	8310110055	8310110042	83/10/05	50-331 F
8310070175	8310070172	83/09/28	CONTRACT	8310110057	8310110034	83/06/15	50-275 P
8310070179	8310070176	83/09/22	50-317 P	8310110059	8310110044	83/07/20	50-413 Q
8310070180	8310070176	83/09/22	50-317 P	8310110060	8310110042	83/10/05	50-331 F
8310070181	8310070178	83/09/26	CONTRACT	8310110066	8310110064	83/10/05	50-309 F
8310070183	8310070182	83/09/22	50-335 P	8310110069	8310110064	83/10/05	50-309 F
8310070186	8310070182	83/09/22	50-335 P	8310110070	8310110065	83/06/20	FOIA
8310070188	8310070184	83/09/29	50-498 A	8310110074	8310110062	83/10/05	50-289 H
8310070189	8310070187	83/09/22	CONTRACT	8310110076	8310110067	83/10/05	50-269 F
8310070196	8310070193	83/09/27	CONTRACT	8310110077	8310110072	83/10/07	50-369 F
8310070198	8310070195	83/09/26	CONTRACT	8310110079	8310110072	83/10/07	50-369 F
8310070200	8310070197	83/09/28	CONTRACT	8310110080	8310110067	83/10/05	50-269 F
8310070203	8310070185	83/09/22	CONTRACT	8310110081	8310110078	83/09/22	50-280 P
8310070205	8310070201	83/09/28	CONTRACT	8310110084	8310110078	83/09/22	50-280 P
8310070210	8310070206	83/09/22	CONTRACT	8310110085	8310110082	83/10/05	50-346 F
8310070212	8310070208	83/10/01	50-275 R	8310110087	8310110082	83/10/05	50-346 F
8310070217	8310070213	83/09/22	CONTRACT	8310110089	8310110086	83/09/28	CONTRACT
8310070220	8310070218	83/09/22	CONTRACT	8310110092	8310110083	83/10/05	50-443 Q
8310070221	8310070214	83/09/29	CONTRACT	8310110094	8310110091	83/10/05	50-387 F
8310070224	8310070222	83/09/29	CONTRACT	8310110095	8310110034	83/06/15	50-275 P
8310070227	8310070215	83/10/04	50-275 R	8310110097	8310110065	83/06/20	FOIA
8310070230	8310070226	83/09/26	CONTRACT	8310110100	8310110096	83/10/05	50-327 F
8310070231	8310070228	83/09/29	CONTRACT	8310110101	8310110065	83/06/20	FOIA
8310070237	8310070234	83/09/29	CONTRACT	8310110103	8310110034	83/06/15	FOIA
8310070240	8310070233	83/09/27	CONTRACT	8310110106	8310110102	83/10/05	50-320 F
8310070246	8310070241	83/10/05	50-324 Q	8310110107	8310110034	83/06/15	50-275 P
8310070253	8310070250	83/09/30	50-389 F	8310110108	8310110065	83/06/20	40-17
8310070257	8310070251	83/10/05	50-275 R	8310110110	8310110099	83/10/05	50-123 V
8310070259	8310070256	83/08/12	70-143	8310110111	8310110034	83/06/15	50-275 P
8310070267	8310070244	83/09/27	CONTRACT	8310110113	8310110099	83/10/05	50-123 V
8310070280	8310070279	83/09/29	50-321 P	8310110115	8310110065	83/06/15	40-17
8310070282	8310070273	83/09/01	50-324 G	8310110116	8310110109	83/10/05	50-445 F
8310070289	8310070286	83/09/16	50-528 B	8310110122	8310110121	83/10/05	50-225 P
8310070293	8310070291	83/09/30	50-324 F	8310110123	8310110118	83/10/05	50-373 F
8310070294	8310070273	83/09/01	50-324 Q	8310110125	8310110065	83/06/20	FOIA
8310070295	8310070291	83/09/30	50-324 F	8310110130	8310110065	83/06/20	FOIA
8310070299	8310070296	83/09/30	50-348 B	8310110131	8310110124	83/10/05	50-346 F
8310070302	8310070296	83/09/30	50-348 B	8310110133	8310110128	83/10/03	50-361 P
8310070314	8310070311	83/09/29	50-263 P	8310110134	8310110065	83/06/20	FOIA

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8310110136	8310110128	83/10/03	50-361 P	8310110423	8310110416	83/09/29	71-506
8310110139	8310110053	83/06/20	70-1487	8310110429	8310110424	83/10/05	50-192 F
8310110141	8310110135	83/10/05	50-269 F	8310110434	8310110433	83/10/05	50-315 F
8310110143	8310110065	83/06/20	FOIA	8310110437	8310110436	83/07/20	50-322 A
8310110147	8310110065	83/06/20	FOIA	8310110440	8310110437	83/10/05	50-313 F
8310110149	8310110142	83/10/04	TOPREP	8310110443	8310110430	83/06/14	50-316 S
8310110151	8310110114	83/10/05	50-275 U	8310110453	8310110430	83/06/14	FOIA
8310110155	8310110150	83/10/05	50-400 Q	8310110458	8310110430	83/06/14	FOIA
8310110165	8310110158	83/10/05	50-443 Q	8310110459	8310110434	83/09/21	50-277 P
8310110166	8310110161	83/10/05	50-29 P	8310110461	8310110430	83/06/14	50-237 S
8310110170	8310110158	83/10/05	50-443 Q	8310110464	8310110430	83/06/14	FOIA
8310110173	8310110158	83/10/05	50-443 Q	8310110467	8310110430	83/06/14	50-237 S
8310110177	8310110173	83/10/04	50-445 F	8310110475	8310110470	83/06/15	FOIA
8310110180	8310110176	83/10/05	50-263 F	8310110478	8310110430	83/06/14	50-237 S
8310110183	8310110178	83/09/26	50-298 P	8310110480	8310110470	83/06/15	FOIA
8310110184	8310110176	83/10/05	50-263 F	8310110484	8310110430	83/06/14	FOIA
8310110190	8310110184	83/10/05	50-280 F	8310110486	8310110430	83/06/14	FOIA
8310110192	8310110185	83/09/30	CONTRACT	8310110490	8310110430	83/06/14	FOIA
8310110196	8310110189	83/10/04	50-344 F	8310110499	8310110494	83/09/27	CONTRACT
8310110199	8310110195	83/10/05	50-239 F	8310110505	8310110303	83/07/08	FOIA
8310110201	8310110189	83/10/04	50-344 F	8310110507	8310110498	83/09/27	50-282 P
8310110203	8310110195	83/10/05	50-259 F	8310110509	8310110503	83/07/08	FOIA
8310110206	8310110204	83/10/05	50-244 S	8310110510	8310110504	83/09/26	CONTRACT
8310110216	8310110208	83/10/06	50-358 Q	8310110511	8310110503	83/07/08	FOIA
8310110228	8310110222	83/09/30	50-286 P	8310110512	8310110308	83/09/20	CONTRACT
8310110231	8310110222	83/09/30	50-286 P	8310110513	8310110503	83/07/08	FOIA
8310110236	8310110234	83/10/03	50-267 F	8310110518	8310110503	83/07/08	FOIA
8310110239	8310110237	83/10/05	50-280 F	8310110524	8310110514	83/09/29	CONTRACT
8310110240	8310110237	83/10/05	50-280 F	8310110528	8310110525	83/10/05	CONTRACT
8310110254	8310110244	83/10/05	50-317 F	8310110534	8310110523	83/06/15	FOIA
8310110258	8310110244	83/10/05	50-317 F	8310110536	8310110521	83/09/28	50-259 P
8310110259	8310110255	83/10/05	50-155 F	8310110538	8310110523	83/06/15	FOIA
8310110268	8310110263	83/10/05	50-280 F	8310110541	8310110523	83/06/15	FOIA
8310110271	8310110262	83/09/26	CONTRACT	8310110544	8310110540	83/09/30	50-346 P
8310110277	8310110275	83/10/06	50-352 Q	8310110547	8310110523	83/06/15	FOIA
8310110284	8310110275	83/10/06	50-352 Q	8310110548	8310110540	83/09/30	50-346 P
8310110287	8310110275	83/10/06	50-352 Q	8310110549	8310110533	83/09/22	CONTRACT
8310110292	8310110275	83/10/06	50-352 Q	8310110551	8310110521	83/09/28	50-259 P
8310110293	8310110045	83/10/04	50-155 T	8310110551	8310110521	83/09/29	50-269 P
8310110297	8310110291	83/10/05	50-352 Q	8310110561	8310110545	83/09/29	50-269 P
8310110300	8310110291	83/10/05	50-352 Q	8310110562	8310110523	83/06/15	FOIA
8310110301	8310110298	83/10/06	50-275 Q	8310110569	8310110545	83/09/29	50-269 P
8310110304	8310110302	83/10/06	50-456 C	8310110574	8308300763	83/10/04	50-247 F
8310110307	8310110305	83/10/04	50-352 Q	8310110575	8310110545	83/09/29	50-269 P
8310110312	8310110291	83/10/05	50-352 Q	8310110576	8310110523	83/06/15	FOIA
8310110327	8310110325	83/10/05	50-254 F	8310110579	8310110570	83/10/03	MISC
8310110330	8310110329	83/10/05	50-285 F	8310110582	8310110572	83/09/29	CONTRACT
8310110334	8310110333	83/09/20	50-315 P	8310110583	8310110523	83/06/15	FOIA
8310110335	8310110333	83/09/20	50-315 P	8310110588	8310110570	83/10/03	MISC
8310110337	8310110336	83/09/13	CONTRACT	8310110591	8310110584	83/08/19	FOIA
8310110340	8310110336	83/09/29	CONTRACT	8310110594	8310110589	83/09/22	COMMISSION
8310110344	8310110342	83/09/29	CONTRACT	8310110597	8310110589	83/09/22	COMMISSION
8310110351	8310110350	83/06/13	FOIA	8310110614	8310110611	83/10/06	71-9128
8310110354	8310110352	83/09/13	COMMISSION	8310110615	8310110612	83/09/22	COMMISSION
8310110366	8310110362	83/10/05	50-83 F	8310110616	8310110613	83/09/24	CONTRACT
8310110369	8310110364	83/06/14	FOIA	8310110620	8310110617	83/09/22	50-54 U
8310110371	8310110364	83/06/13	FOIA	8310110622	8310110619	83/10/06	71-6166
8310110375	8310110364	83/06/13	FOIA	8310110623	8310110621	83/10/06	71-9127
8310110378	8310110364	83/06/13	FOIA	8310110626	8310110624	83/09/21	WASTE MAT
8310110384	8310110364	83/06/13	FOIA	8310110627	8310110625	83/10/06	71-9126
8310110386	8310110360	83/10/05	50-192 F	8310110631	8310110628	83/09/30	71-9108
8310110387	8310110381	83/09/29	50-272 Q	8310120002	8310120001	83/10/06	71-6478
8310110388	8310110364	83/06/13	FOIA	8310120008	8310120006	83/07/14	50-201 I
8310110390	8310110360	83/10/05	50-192 F	8310120009	8310120006	83/07/14	50-201 I
8310110391	8310110364	83/06/13	FOIA	8310120011	8310120006	83/07/14	50-201 I
8310110392	8310110360	83/10/05	50-192 F	8310120012	8310120006	83/07/14	50-201 I
8310110393	8310110364	83/06/13	FOIA	8310120013	8310120006	83/07/14	50-201 I
8310110395	8310110364	83/06/13	FOIA	8310120014	8310120006	83/07/14	50-201 I
8310110399	8310110385	83/09/30	50-219 F	8310120015	8310120006	83/07/14	50-201 I
8310110400	8310110364	83/06/13	FOIA	8310120018	8310120016	83/07/07	FOIA
8310110404	8310110364	83/06/13	FOIA	8310120019	8310120010	83/09/20	CONTRACT
8310110407	8310110150	83/10/05	50-400 Q	8310120020	8310120006	83/07/14	50-201 I
8310110409	8310110150	83/10/05	50-400 Q	8310120022	8310120014	83/07/07	50-346 P
8310110410	8310110402	83/09/29	71-505	8310120023	8310120006	83/07/14	50-201 I
8310110412	8310110150	83/10/05	50-400 Q	8310120024	8310120021	83/09/23	CONTRACT
8310110414	8310110364	83/06/13	FOIA	8310120026	8310120006	83/07/14	50-201 I
8310110418	8310110413	83/10/05	50-369 F	8310120028	8310120006	83/07/14	50-201 I
8310110419	8310110364	83/06/13	FOIA	8310120030	8310120006	83/07/14	50-201 I
8310110421	8310110413	83/10/05	50-369 F	8310120032	8310120006	83/07/14	50-201 I
8310110422	8310110364	83/06/13	FOIA	8310120034	8310120006	83/07/14	50-201 I
				8310120035	8310120033	83/09/28	CONTRACT

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

561

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8310120036	8310120006	83/07/14	50-201 I	8310120374	8310120369	83/10/03	50-29 P
8310120039	8310120006	83/07/14	50-201 I	8310120377	8310120364	83/10/07	50-352 Q
8310120040	8310120038	83/09/29	CONTRACT	8310120381	8310120376	83/10/07	50-275 Q
8310120041	8310120037	83/09/28	50-387 P	8310120384	8310120364	83/10/07	50-352 Q
8310120042	8310120006	83/07/14	50-201 I	8310120385	8310120376	83/10/07	50-275 Q
8310120044	8310120006	83/07/14	50-201 I	8310120398	8310120364	83/10/07	50-352 Q
8310120045	8310120037	83/09/28	50-387 P	8310120401	8310120302	83/10/05	50-454 Q
8310120046	8310120043	83/09/30	50-327 P	8310120415	8310120407	83/10/05	50-261 P
8310120047	8310120006	83/07/14	50-201 I	8310120416	8310120406	83/09/26	50-220 P
8310120048	8310120043	83/09/30	50-327 P	8310120422	8310120407	83/10/05	50-261 P
8310120049	8310120006	83/07/14	50-201 I	8310120438	8310120436	83/10/07	50-416 P
8310120050	8310120043	83/09/30	50-327 P	8310120445	8310120443	83/09/28	50-316 B
8310120055	8310120052	83/09/28	CONTRACT	8310120448	8310120443	83/09/28	50-316 B
8310120056	8310120043	83/09/30	50-327 P	8310120449	8310120443	83/09/28	50-316 B
8310120081	8310120079	83/09/30	50-313 P	8310130002	8310130001	83/10/07	50-155 T
8310120083	8310120079	83/09/30	50-313 P	8310130011	8310130008	83/10/03	WASTE MAT
8310120085	8310120082	83/09/19	70-1100	8310130019	8310130017	83/10/05	50-275 Q
8310120088	8310120082	83/09/19	70-1100	8310130026	8310130025	83/09/20	50-313 Q
8310120096	8310120090	83/09/20	50-220 Q	8310130036	8310130033	83/09/30	50-266 P
8310120111	8310120107	83/10/07	50-443 Q	8310130039	8310130029	83/09/29	50-328 P
8310120115	8310120107	83/10/07	50-443 Q	8310130040	8310130033	83/09/30	50-266 P
8310120121	8310120119	83/10/07	50-322 Q	8310130043	8310130029	83/09/29	50-328 P
8310120122	8310120107	83/10/07	50-443 Q	8310130044	8310130033	83/09/30	50-266 P
8310120126	8310120107	83/10/07	50-443 Q	8310130056	8310130052	83/09/30	50-266 P
8310120128	8310120125	83/10/07	50-289 R	8310130062	8310130052	83/09/30	50-266 P
8310120135	8310120107	83/10/07	50-443 Q	8310130071	8310130067	83/09/27	WASTE MAT
8310120139	8310120137	83/09/10	50-29 Q	8310130076	8310130072	83/10/03	50-282 P
8310120141	8310120107	83/10/07	50-443 Q	8310130079	8310130072	83/10/03	50-282 P
8310120143	8310120137	83/09/10	50-29 Q	8310130093	8310130088	83/09/30	50-320 P
8310120151	8310120147	83/10/07	50-443 Q	8310130099	8310130088	83/09/30	50-320 P
8310120156	8310120153	83/09/21	50-223 Q	8310130104	8310130102	83/10/06	50-344 F
8310120161	8310120160	83/09/16	50-312 R	8310130107	8310130103	83/10/07	50-338 P
8310120176	8310120172	83/09/28	50-397 Q	8310130109	8310130097	83/09/30	50-368 P
8310120177	8310120176	83/09/20	50-286 Q	8310130115	8310130111	83/09/29	50-3 P
8310120201	8310120175	83/09/19	70-135	8310130119	8310130111	83/09/29	50-3 P
8310120204	8310120202	83/09/23	50-116 Q	8310130121	8310130117	83/10/11	50-416 P
8310120207	8310120006	83/07/14	50-201 I	8310130129	8310130126	83/09/29	50-528 A
8310120208	8310120205	83/10/05	50-220 P	8310130131	8310130127	83/10/11	50-206 P
8310120209	8310120206	83/09/29	50-305 F	8310130134	8310130128	83/06/30	MISC
8310120213	8310120212	83/09/22	50-277 Q	8310130141	8310130138	83/09/23	50-320 P
8310120214	8310120206	83/09/29	50-305 F	8310130148	8310130145	83/10/04	50-338 P
8310120215	8310120211	83/10/08	50-155 T	8310130152	8310130150	83/10/06	50-537 Q
8310120216	8310120206	83/09/29	50-305 F	8310130154	8310130153	83/10/06	50-389 Q
8310120217	8310120212	83/09/22	50-277 Q	8310130156	8310130150	83/10/06	50-537 Q
8310120218	8310120211	83/10/08	50-155 T	8310130157	8310130153	83/10/06	50-389 Q
8310120220	8310120206	83/09/29	50-305 F	8310130165	8310130162	83/09/20	CONTRACT
8310120221	8310120211	83/10/08	50-155 T	8310130171	8310130168	83/08/10	50-285 Q
8310120223	8310120206	83/09/29	50-305 F	8310130178	8310130172	83/08/22	50-482 Q
8310120225	8310120211	83/10/08	50-155 T	8310130179	8310130174	83/10/11	50-155 T
8310120227	8310120206	83/09/29	50-305 F	8310130186	8310130175	83/07/26	50-289 P
8310120229	8310120211	83/10/08	50-155 T	8310130190	8310130176	83/08/22	50-498 Q
8310120232	8310120206	83/09/29	50-305 F	8310130191	8310130188	83/09/30	50-334 P
8310120233	8310120211	83/10/08	50-155 T	8310130195	8310130188	83/09/30	50-334 P
8310120235	8310120206	83/09/29	50-305 F	8310130200	8310130193	83/09/28	50-267 P
8310120238	8310120206	83/09/29	50-305 F	8310130201	8310130198	83/09/30	CONTRACT
8310120240	8310120206	83/09/29	50-305 F	8310130202	8310130199	83/10/06	50-266 P
8310120243	8310120242	83/05/20	50-247 P	8310130204	8310130193	83/09/28	50-267 P
8310120244	8310120241	83/10/06	50-305 F	8310130205	8310130199	83/10/06	50-266 P
8310120247	8310120245	83/10/07	50-344 Q	8310130211	8310130206	83/09/13	50-298 Q
8310120250	8310120248	83/09/28	50-397 Q	8310130213	8310130207	83/10/07	50-387 P
8310120268	8310120246	83/10/04	50-400 F	8310130218	8310130214	83/10/08	50-155 T
8310120283	8310120279	83/10/07	70-572	8310130222	8310130217	83/09/30	50-315 P
8310120288	8310120279	83/10/07	70-572	8310130226	8310130220	83/08/10	50-313 Q
8310120292	8310120279	83/10/07	70-572	8310130227	8310130221	83/09/07	50-498 Q
8310120311	8310120305	83/10/07	50-341 Q	8310130228	8310130225	83/09/30	70-1113
8310120315	8310120312	83/10/06	50-271 P	8310130230	8310130221	83/09/07	50-498 Q
8310120316	8310120313	83/09/22	50-277 R	8310130232	8310130229	83/10/04	50-341 A
8310120319	8310120313	83/09/22	50-277 R	8310130237	8310130234	83/10/07	50-358 A
8310120327	8310120326	83/10/05	50-155 Q	8310130246	8310130241	83/09/06	50-482 Q
8310120333	8310120329	83/10/05	50-29 P	8310130248	8310130240	83/09/19	50-400 E
8310120341	8310120337	83/10/05	50-305 P	8310130251	8310130241	83/09/04	50-482 Q
8310120345	8310120337	83/10/05	50-305 P	8310130252	8310130247	83/08/19	50-458 Q
8310120347	8310120342	83/09/28	50-361 S	8310130254	8310130240	83/09/19	50-400 E
8310120351	8310120342	83/09/28	50-361 S	8310130259	8310130257	83/09/13	50-482 Q
8310120356	8310120330	83/10/04	50-348 S	8310130261	8310130240	83/09/19	50-400 E
8310120357	8310120348	83/10/06	70-1257	8310130266	8310130262	83/10/06	50-382 Q
8310120358	8310120355	83/10/06	50-312 Q	8310130267	8310130240	83/09/19	50-400 E
8310120363	8310120350	83/10/04	50-348 S	8310130269	8308300767	83/10/11	50-329 A
8310120368	8310120364	83/10/07	50-352 Q	8310130271	8310130240	83/09/19	50-400 E
8310120371	8310120350	83/10/04	50-348 S	8310130273	8310130240	83/09/19	50-400 E

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8310130274	8310130270	83/09/19	71-6346	8310140174	8310140163	83/10/11	TOPREP
8310130275	8310130272	83/09/28	50-267 P	8310140175	8310140173	83/10/06	50-295 Q
8310130277	8310130240	83/09/19	50-400 E	8310140182	8310140176	83/09/13	50-508 A
8310130279	8310130272	83/09/28	50-267 P	8310140188	8310140181	83/10/11	70-36
8310130280	8310130240	83/09/19	50-400 E	8310140192	8310140179	83/09/29	50-434 Q
8310130282	8310130240	83/09/19	50-400 E	8310140199	8310140194	83/10/06	50-348 P
8310130284	8310130281	83/09/28	50-267 P	8310140202	8310140196	83/10/11	50-333 P
8310130285	8310130240	83/09/19	50-400 E	8310140207	8310140205	83/10/07	50-369 P
8310130287	8310130240	83/09/19	50-400 E	8310140215	8310140213	83/09/29	50-373 Q
8310130289	8310130240	83/09/19	50-400 E	8310140216	8310140212	83/09/29	70-1308
8310130290	8310130240	83/09/19	50-400 E	8310140229	8310140226	83/10/06	50-348 S
8310130291	8310130240	83/09/19	50-400 E	8310140235	8310140226	83/10/06	50-348 S
8310130293	8310130240	83/09/19	50-400 E	8310140236	8310140234	83/09/26	50-271 Q
8310130294	8310130240	83/09/19	50-400 E	8310140244	8310140239	83/09/30	TOPREP
8310130295	8310130292	83/08/22	50-285 Q	8310140245	8310140240	83/09/27	50-271 Q
8310130297	8310130296	83/10/07	50-153 P	8310140258	8310140254	83/09/30	50-331 R
8310130298	8310130296	83/10/07	50-153 P	8310140264	8310140261	83/09/29	50-234 Q
8310130299	8310130296	83/10/07	50-153 P	8310140266	8310140243	83/10/11	50-302 R
8310130301	8310130296	83/10/07	50-153 P	8310140267	8310140262	83/09/26	50-272 Q
8310130302	8310130296	83/10/07	50-153 P	8310140268	8310140243	83/10/11	50-302 R
8310130303	8310130300	83/09/28	50-267 P	8310140271	8310140261	83/09/29	50-234 Q
8310130304	8310130300	83/09/28	50-267 P	8310140273	8310140270	83/10/06	50-329 A
8310130306	8310130307	83/10/06	50-285 F	8310140274	8310140269	83/09/23	50-329 S
8310130309	8310130307	83/10/06	50-285 F	8310140279	8310140276	83/09/26	50-272 Q
8310130311	8310130310	83/10/06	50-409 F	8310140277	8310140275	83/08/22	40-4492
8310130313	8310130312	83/10/06	50-317 F	8310170002	8310170001	83/09/09	50-289 P
8310130323	8310130316	83/10/11	50-206 P	8310170003	8310170003	83/10/06	50-317 F
8310130324	8310130260	83/09/28	50-267 P	8310170007	8310170006	83/10/06	50-289 F
8310130328	8310130260	83/09/28	50-267 P	8310170033	8310170029	83/06/29	FOIA
8310130333	8310130330	83/09/16	50-313 Q	8310170037	8310170029	83/06/29	FOIA
8310130335	8310130330	83/09/16	50-313 Q	8310170044	8310170029	83/06/29	FOIA
8310130336	8310130334	83/09/09	PRDJ	8310170047	8310170029	83/06/29	FOIA
8310130385	8310130380	83/09/29	CONTRACT	8310170050	8310170029	83/06/29	FOIA
8310130386	8310130384	83/09/16	71-9160	8310170055	8310170029	83/06/29	FOIA
8310130389	8310130388	83/09/30	CONTRACT	8310170057	8310170029	83/06/29	FOIA
8310130406	8310130404	83/09/30	CONTRACT	8310170059	8310170029	83/06/29	FOIA
8310130407	8310130404	83/09/30	CONTRACT	8310170062	8310170029	83/06/29	FOIA
8310130410	8310130409	83/08/29	FOIA	8310170066	8310170029	83/06/29	FOIA
8310130416	8310130415	83/09/23	50-295 P	8310170067	8310170060	83/09/30	CONTRACT
8310130418	8310130417	83/09/29	CONTRACT	8310170072	8310170029	83/06/29	FOIA
8310140004	8310140003	83/09/26	50-311 Q	8310170084	8310170082	83/09/30	CONTRACT
8310140013	8310140002	83/09/28	50-303 Q	8310170090	8310170029	83/06/29	FOIA
8310140024	8310140022	83/10/12	50-445 T	8310170092	8310170088	83/10/06	50-335 P
8310140032	8310140031	83/08/23	50-498 Q	8310170094	8310170029	83/06/29	FOIA
8310140035	8310140026	83/10/13	50-289 Q	8310170098	8310170091	83/10/05	50-338 S
8310140037	8310140031	83/08/23	50-498 Q	8310170100	8310170096	83/10/07	50-313 P
8310140041	8310140031	83/08/23	50-498 Q	8310170102	8310170029	83/06/29	FOIA
8310140042	8310140040	83/10/10	50-315 P	8310170106	8310170096	83/10/07	50-313 P
8310140044	8310140031	83/08/23	50-498 Q	8310170107	8310170091	83/10/05	50-338 S
8310140046	8310140040	83/10/10	50-315 P	8310170110	8310170029	83/06/29	FOIA
8310140047	8310140031	83/08/23	50-498 Q	8310170116	8310170029	83/06/29	FOIA
8310140049	8310140036	83/10/11	50-10 Q	8310170118	8310170112	83/10/11	CONTRACT
8310140050	8310140031	83/08/23	50-498 Q	8310170120	8310170029	83/06/29	FOIA
8310140052	8310140031	83/08/23	50-498 Q	8310170123	8310170029	83/06/29	FOIA
8310140055	8310140054	83/10/07	50-358 A	8310170125	8310170119	83/09/26	50-331 P
8310140062	8310140031	83/08/23	50-498 Q	8310170128	8310170029	83/06/29	FOIA
8310140070	8310140067	83/10/13	50-454 Q	8310170130	8310170029	83/06/29	FOIA
8310140076	8310140074	83/10/10	50-153 T	8310170132	8310170078	83/06/07	FOIA
8310140078	8310140074	83/10/10	50-153 T	8310170136	8310170029	83/06/29	FOIA
8310140080	8310140079	83/10/11	50-302 P	8310170140	8310170029	83/06/29	FOIA
8310140085	8310140083	83/10/12	50-445 Q	8310170142	8310170078	83/06/07	FOIA
8310140088	8310140031	83/08/23	50-498 Q	8310170144	8310170029	83/06/29	FOIA
8310140095	8310140031	83/08/23	50-498 Q	8310170147	8310170078	83/06/07	FOIA
8310140101	8310140097	83/10/07	50-352 A	8310170148	8310170145	83/10/12	50-388 A
8310140103	8310140097	83/10/07	50-352 A	8310170149	8310170141	83/10/11	50-416 Q
8310140104	8310140099	83/10/11	50-10 Q	8310170150	8310170029	83/06/29	FOIA
8310140119	8310140117	83/10/11	50-275 R	8310170151	8310170143	83/09/23	40-86
8310140134	8310140132	83/09/27	50-320 Q	8310170154	8310170078	83/06/07	FOIA
8310140136	8310140135	83/10/06	50-338 Q	8310170156	8310170078	83/06/07	FOIA
8310140138	8310140137	83/10/05	50-316 S	8310170157	8310170143	83/09/23	40-86
8310140139	8310140137	83/10/05	50-316 S	8310170158	8310170155	83/10/03	70-1113
8310140140	8310140137	83/10/05	50-316 S	8310170160	8310170078	83/06/07	FOIA
8310140141	8310140137	83/10/05	50-316 S	8310170161	8310170029	83/06/29	FOIA
8310140145	8310140143	83/10/07	50-267 P	8310170164	8310170029	83/06/29	FOIA
8310140148	8310140147	83/09/29	50-461 Q	8310170165	8310170143	83/09/23	40-86
8310140150	8310140147	83/09/29	50-461 Q	8310170166	8310170029	83/06/29	FOIA
8310140156	8310140155	83/10/11	50-387 P	8310170168	8310170163	83/10/07	50-309 Q
8310140165	8310140163	83/10/11	TOPREP	8310170169	8310170029	83/06/29	FOIA
8310140166	8310140162	83/09/27	50-289 Q	8310170171	8310170029	83/06/29	FOIA
8310140170	8310140132	83/09/27	50-320 Q	8310170175	8310170170	83/10/04	71-5595

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8310140174	8310140163	83/10/11	TOPREP
8310140175	8310140173	83/10/06	50-295 Q
8310140182	8310140176	83/09/13	50-508 A
8310140188	8310140181	83/10/11	70-36
8310140192	8310140179	83/09/29	50-454 Q
8310140199	8310140194	83/10/06	50-348 P
8310140202	8310140196	83/10/11	50-333 P
8310140207	8310140205	83/10/07	50-369 P
8310140215	8310140213	83/09/29	50-373 Q
8310140216	8310140212	83/09/29	70-1308
8310140229	8310140226	83/10/06	50-348 S
8310140235	8310140226	83/10/06	50-348 S
8310140236	8310140234	83/09/26	50-271 Q
8310140244	8310140239	83/09/30	TOPREP
8310140245	8310140240	83/09/27	50-271 Q
8310140258	8310140254	83/09/30	50-331 R
8310140264	8310140261	83/09/29	50-234 Q
8310140266	8310140243	83/10/11	50-302 R
8310140267	8310140262	83/09/30	50-237 Q
8310140268	8310140243	83/10/11	50-302 R
8310140271	8310140261	83/09/29	50-234 Q
8310140273	8310140270	83/10/06	50-329 A
8310140274	8310140269	83/09/23	50-329 S
8310140279	8310140276	83/09/26	50-272 Q
8310140277	8310140275	83/08/22	40-4492
8310170002	8310170001	83/09/09	50-289 P
8310170003	8310170003	83/10/06	50-317 F
8310170007	8310170006	83/10/06	50-289 F
8310170033	8310170029	83/06/29	FOIA
8310170037	8310170029	83/06/29	FOIA
8310170044	8310170029	83/06/29	FOIA
8310170047	8310170029	83/06/29	FOIA
8310170050	8310170029	83/06/29	FOIA
8310170055	8310170029	83/06/29	FOIA
8310170057	8310170029	83/06/29	FOIA
8310170059	8310170029	83/06/29	FOIA
8310170062	8310170029	83/06/29	FOIA
8310170066	8310170029	83/06/29	FOIA
8310170067	8310170060	83/09/30	CONTRACT
8310170072	8310170029	83/06/29	FOIA
8310170084	8310170082	83/09/30	CONTRACT
8310170090	8310170029	83/06/29	FOIA
8310170092	8310170088	83/10/06	50-335 P
8310170094	8310170029	83/06/29	FOIA
8310170098	8310170091	83/10/05	50-338 S
8310170100	8310170096	83/10/07	50-313 P
8310170102	8310170029	83/06/29	FOIA
8310170106	8310170096	83/10/07	50-313 P
8310170107	8310170091	83/10/05	50-338 S
8310170110	8310170029	83/06/29	FOIA
8310170116	8310170029	83/06/29	FOIA
8310170118	8310170112	83/10/11	CONTRACT
8310170120	8310170029	83/06/29	FOIA
8310170123	8310170029	83/06/29	FOIA
8310170125	8310170119	83/09/26	50-331 P
8310170128	8310170029	83/06/29	FOIA
8310170130	8310170029	83/06/29	FOIA
8310170132	8310170078	83/06/07	FOIA
8310170136	8310170029	83/06/29	FOIA
8310170140	8310170029	83/06/29	FOIA
8310170142	8310170078	83/06/07	FOIA
8310170144	8310170029	83/06/29	FOIA
8310170147	8310170078	83/06/07	FOIA
8310170148	8310170145	83/10/12	50-388 A
8310170149	8310170141	83/10/11	50-416 Q
8310170150	8310170029	83/06/29	FOIA
8310170151	8310170143	83/09/23	40-86
8310170154	8310170078	83/06/07	FOIA
8310170156	8310170078	83/06/07	FOIA
8310170157	8310170143	83/09/23	40-86
8310170158	8310170155	83/10/03	70-1113
8310170160	8310170078	83/06/07	FOIA
8310170161	8310170029	83/06/29	FOIA
8310170164	8310170029	83/06/29	FOIA
8310170165	8310170143	83/09/23	40-86
8310170166	8310170029	83/06/29	FOIA
8310170168	8310170163	83/10/07	50-309 Q
8310170169	8310170029	83/06/29	FOIA
8310170171	8310170029	83/06/29	FOIA
8310170175	8310170170	83/10/04	71-5595

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

563

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8310170176	8310170029	83/06/29	FOIA
8310170180	8310170029	83/06/29	FOIA
8310170182	8310170029	83/06/29	FOIA
8310170184	8310170078	83/06/07	FOIA
8310170191	8310170078	83/06/07	FOIA
8310170194	8310170078	83/06/07	FOIA
8310170195	8310170192	83/09/30	71-9105
8310170196	8310170078	83/06/07	FOIA
8310170198	8310170190	83/09/30	50-423 A
8310170202	8310170078	83/06/07	FOIA
8310170203	8310170197	83/09/23	70-698
8310170205	8310170078	83/06/07	FOIA
8310170208	8310170078	83/06/07	FOIA
8310170210	8310170078	83/06/07	FOIA
8310170213	8310170078	83/06/07	FOIA
8310170217	8310170078	83/06/07	FOIA
8310170220	8310170078	83/06/07	FOIA
8310170223	8310170078	83/06/07	FOIA
8310170224	8310170222	83/10/07	50-335 F
8310170226	8310170078	83/06/07	FOIA
8310170227	8310170214	83/10/10	50-275 R
8310170230	8310170222	83/10/07	50-335 F
8310170231	8310170078	83/06/07	FOIA
8310170236	8310170233	83/09/29	70-1257
8310170237	8310170029	83/06/29	FOIA
8310170238	8310170189	83/10/12	50-259 Q
8310170241	8310170078	83/06/07	FOIA
8310170242	8310170029	83/06/29	FOIA
8310170244	8310170240	83/10/07	50-250 F
8310170245	8310170078	83/06/07	FOIA
8310170246	8310170239	83/10/11	70-27
8310170247	8310170029	83/06/29	FOIA
8310170250	8310170078	83/06/07	FOIA
8310170252	8310170029	83/06/29	FOIA
8310170253	8310170249	83/08/17	70-1113
8310170254	8310170133	83/10/11	50-327 P
8310170256	8310170078	83/06/07	FOIA
8310170259	8310170029	83/06/29	FOIA
8310170265	8310170029	83/06/29	FOIA
8310170267	8310170078	83/06/07	FOIA
8310170269	8310170029	83/06/29	FOIA
8310170274	8310170078	83/06/07	FOIA
8310170275	8310170029	83/06/29	FOIA
8310170277	8310170078	83/06/07	FOIA
8310170279	8310170078	83/06/07	FOIA
8310170280	8310170029	83/06/29	FOIA
8310170282	8310170078	83/06/07	FOIA
8310170284	8310170029	83/06/29	FOIA
8310170286	8310170078	83/06/07	FOIA
8310170288	8310170029	83/06/29	FOIA
8310170290	8310170078	83/06/07	FOIA
8310170293	8310170078	83/06/07	FOIA
8310170294	8310170029	83/06/29	FOIA
8310170296	8310170289	83/10/12	50-395 P
8310170297	8310170078	83/06/07	FOIA
8310170300	8310170029	83/06/29	FOIA
8310170301	8310170289	83/10/12	50-395 P
8310170303	8310170029	83/06/29	FOIA
8310170305	8310170029	83/06/29	FOIA
8310170307	8310170304	83/10/03	50-289 P
8310170309	8310170029	83/06/29	FOIA
8310170311	8310170304	83/10/03	50-289 P
8310170314	8310170029	83/06/29	FOIA
8310170316	8310170078	83/06/07	FOIA
8310170318	8308300766	83/10/07	50-275 T
8310170319	8310170029	83/06/29	FOIA
8310170320	8310170078	83/06/07	FOIA
8310170323	8310170029	83/06/29	FOIA
8310170324	8310170078	83/06/07	FOIA
8310170325	8310170222	83/10/07	50-335 F
8310170326	8310170029	83/06/29	FOIA
8310170328	8310170029	83/06/29	FOIA
8310170331	8310170078	83/06/07	FOIA
8310170332	8310170029	83/06/29	FOIA
8310170336	8310170029	83/06/29	FOIA
8310170340	8310170029	83/06/29	FOIA
8310170343	8310170029	83/06/29	FOIA
8310170345	8310170078	83/06/07	FOIA
8310170347	8310170029	83/06/29	FOIA
8310170349	8310170344	83/10/03	71-9182

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8310170350	8310170078	83/06/07	FOIA
8310170352	8310170029	83/06/29	FOIA
8310170354	8310170078	83/06/07	FOIA
8310170356	8310170346	83/10/10	50-454 Q
8310170358	8310170029	83/06/29	FOIA
8310170359	8310170078	83/06/07	FOIA
8310170362	8310170029	83/06/29	FOIA
8310170363	8310170078	83/06/07	FOIA
8310170367	8310170078	83/06/07	FOIA
8310170370	8310170029	83/06/29	FOIA
8310170372	8310170078	83/06/07	FOIA
8310170374	8310170029	83/06/29	FOIA
8310170376	8310170078	83/06/07	FOIA
8310170378	8310170373	83/10/14	50-244 S
8310170379	8310170029	83/06/29	FOIA
8310170381	8310170078	83/06/07	FOIA
8310170385	8310170078	83/06/07	FOIA
8310170386	8310170029	83/06/29	FOIA
8310170388	8310170078	83/06/07	FOIA
8310170391	8310170029	83/06/29	FOIA
8310170392	8310170029	83/06/29	FOIA
8310170396	8310170029	83/06/29	FOIA
8310170399	8310170078	83/06/07	FOIA
8310170402	8310170029	83/06/29	FOIA
8310170403	8310170078	83/06/07	FOIA
8310170406	8310170029	83/06/29	FOIA
8310170410	8310170029	83/06/29	FOIA
8310170413	8310170029	83/06/29	FOIA
8310170415	8310170029	83/06/29	FOIA
8310170417	8310170412	83/10/11	50-445 Q
8310170418	8310170029	83/06/29	FOIA
8310170422	8310170029	83/06/29	FOIA
8310170423	8310170416	83/10/10	50-348 P
8310170425	8310170078	83/06/07	FOIA
8310170429	8310170029	83/06/29	FOIA
8310170431	8310170029	83/06/29	FOIA
8310170432	8310170428	83/09/21	50-397 Q
8310170433	8310170078	83/06/07	FOIA
8310170434	8310170029	83/06/29	FOIA
8310170437	8310170078	83/06/07	FOIA
8310170438	8310170029	83/06/29	FOIA
8310170439	8310170436	83/10/11	50-329 A
8310170441	8310170078	83/06/07	FOIA
8310170444	8310170029	83/06/29	FOIA
8310170445	8310170029	83/06/29	FOIA
8310170447	8310170078	83/06/07	FOIA
8310170449	8310170078	83/06/07	FOIA
8310170450	8310170029	83/06/29	FOIA
8310170452	8310170029	83/06/29	FOIA
8310170453	8310170078	83/06/07	FOIA
8310170454	8310170451	83/10/11	50-358 Q
8310170455	8310170078	83/06/07	FOIA
8310170457	8310170029	83/06/29	FOIA
8310170460	8310170078	83/06/07	FOIA
8310170461	8310170029	83/06/29	FOIA
8310170462	8310170078	83/06/07	FOIA
8310170463	8310170029	83/06/29	FOIA
8310170464	8310170459	83/09/30	50-329 Q
8310170466	8310170459	83/09/30	50-329 Q
8310170467	8310170078	83/06/07	FOIA
8310170470	8310170468	83/09/28	50-328 Q
8310170472	8310170078	83/06/07	FOIA
8310170473	8310170078	83/06/07	FOIA
8310170477	8310170078	83/06/07	FOIA
8310170479	8310170473	83/09/22	50-275 Q
8310170482	8310170078	83/06/07	FOIA
8310170483	8310170476	83/09/29	50-263 Q
8310170484	8310170478	83/10/07	50-382 Q
8310170487	8310170078	83/06/07	FOIA
8310170494	8310170078	83/06/07	FOIA
8310170497	8310170078	83/06/07	FOIA
8310170499	8310170495	83/10/10	50-397 A
8310170502	8310170078	83/06/07	FOIA
8310170503	8310170492	83/10/11	50-346 P
8310170505	8310170078	83/06/07	FOIA
8310170507	8310170481	83/10/07	50-397 Q
8310170508	8310170504	83/10/04	50-245 P
8310170510	8310170078	83/06/07	FOIA
8310170516	8310170078	83/06/07	FOIA
8310170518	8310170515	83/10/03	50-358 A

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8310170521	8310170078	83/06/07	FOIA
8310170522	8310170520	83/10/13	50-261 Q
8310170527	8310170078	83/06/07	FOIA
8310170528	8310170078	83/06/07	FOIA
8310170529	8310170525	83/09/01	50-454 Q
8310170532	8310170078	83/06/07	FOIA
8310170534	8310170513	83/10/03	50-329 Q
8310170535	8310170078	83/06/07	FOIA
8310170537	8310170078	83/06/07	FOIA
8310170538	8310170513	83/10/03	50-329 Q
8310170542	8310170539	83/10/11	50-275 Q
8310170544	8310170513	83/10/03	50-329 Q
8310170546	8310170078	83/06/07	FOIA
8310170549	8310170513	83/10/03	50-329 Q
8310170550	8310170111	83/09/29	CONTRACT
8310170555	8310170513	83/10/03	50-329 Q
8310170559	8310170513	83/10/03	50-329 Q
8310170560	8310170513	83/10/03	50-329 Q
8310170562	8310170538	83/09/29	50-329 Q
8310170564	8310170513	83/10/03	50-329 Q
8310170567	8310170513	83/10/03	50-329 Q
8310170570	8310170078	83/06/07	FOIA
8310170571	8310170513	83/10/03	50-329 Q
8310170572	8310170538	83/09/29	50-329 Q
8310170574	8310170078	83/06/07	FOIA
8310170575	8310170513	83/10/03	50-329 Q
8310170578	8310170078	83/06/07	FOIA
8310170580	8310170078	83/06/07	FOIA
8310170585	8310170078	83/06/07	FOIA
8310170587	8310170078	83/06/07	FOIA
8310170590	8310170078	83/06/07	FOIA
8310170591	8310170583	83/10/03	50-329 Q
8310170593	8310170078	83/06/07	FOIA
8310170594	8310170589	83/10/14	50-341 K
8310170598	8310170583	83/10/03	50-329 Q
8310170600	8310170589	83/10/14	50-341 K
8310170602	8310170583	83/10/03	50-329 Q
8310170606	8310170583	83/10/03	50-329 Q
8310170608	8310170543	83/10/12	50-400 Q
8310170610	8310170583	83/10/03	50-329 Q
8310170611	8310170607	83/10/10	50-316 E
8310170615	8310170078	83/06/07	FOIA
8310170616	8310170583	83/10/03	50-329 Q
8310170618	8310170078	83/06/07	FOIA
8310170619	8310170607	83/10/10	50-316 E
8310170620	8310170543	83/10/12	50-400 Q
8310170621	8310170612	83/09/29	50-397 Q
8310170622	8310170583	83/10/03	50-329 Q
8310170625	8310170078	83/06/07	FOIA
8310170627	8310170583	83/10/03	50-329 Q
8310170628	8310170078	83/06/07	FOIA
8310170630	8310170543	83/10/12	50-400 Q
8310170632	8310170626	83/10/12	50-400 Q
8310170633	8310170623	83/09/30	40-3392
8310170634	8310170583	83/10/03	50-329 Q
8310170635	8310170078	83/06/07	FOIA
8310170636	8310170629	83/09/28	50-341 Q
8310170637	8310170078	83/06/07	FOIA
8310170640	8310170078	83/06/07	FOIA
8310170643	8310170629	83/09/28	50-341 Q
8310170645	8310170078	83/06/07	FOIA
8310170647	8310170639	83/10/11	50-320 P
8310170650	8310170078	83/06/07	FOIA
8310170651	8310170646	83/10/10	50-275 R
8310170652	8310170078	83/06/07	FOIA
8310170654	8310170644	83/09/23	70-2960
8310170655	8310170533	83/01/04	50-333 F
8310170659	8310170533	83/01/04	50-333 F
8310170660	8310170078	83/06/07	FOIA
8310170663	8310170653	83/09/28	50-308 Q
8310170665	8310170078	83/06/07	FOIA
8310170667	8310170662	83/09/28	50-440 Q
8310170668	8310170078	83/06/07	FOIA
8310170670	8310170662	83/09/28	50-440 Q
8310170671	8310170666	83/10/13	50-436 Q
8310170673	8310170078	83/06/07	FOIA
8310170675	8310170669	83/08/29	70-984
8310170676	8310170078	83/06/07	FOIA
8310170677	8310170078	83/06/07	FOIA
8310170678	8310170674	83/09/16	50-312 Q

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8310170681	8310170078	83/06/07	FOIA
8310170684	8310170078	83/06/07	FOIA
8310170688	8310170683	83/10/12	50-445 T
8310170690	8310170686	83/10/03	50-320 U
8310170693	8310170691	83/10/06	70-143
8310170699	8310170694	83/09/29	COMMISSION
8310170711	8310170707	83/10/13	50-373 F
8310170719	8310170710	83/10/06	50-369 P
8310170736	8310170710	83/10/06	50-369 P
8310170738	8310170735	83/10/06	50-148 F
8310170743	8310170741	83/10/06	50-321 F
8310170746	8310170741	83/10/06	50-321 F
8310170750	8310170748	79/11/19	71-6601
8310180015	8310180011	83/10/05	70-143
8310180016	8310180010	83/09/29	COMMISSION
8310180031	8310180027	83/10/05	70-1100
8310180034	8310180029	83/10/13	50-341 F
8310180037	8310180029	83/10/13	50-341 F
8310180042	8310180029	83/10/13	50-341 F
8310180099	8310180092	83/10/07	50-289 P
8310180102	8310180098	83/09/30	50-220 P
8310180105	8310180101	83/09/30	CONTRACT
8310180123	8310180120	83/10/12	70-734
8310180139	8310180132	83/10/12	50-352 Q
8310180146	8310180132	83/10/12	50-352 Q
8310180148	8310180143	83/10/07	XPORTLIC
8310180149	8310180144	83/09/27	50-458 Q
8310180152	8310180132	83/10/12	50-352 Q
8310180153	8310180150	83/10/12	50-443 Q
8310180155	8310180151	83/10/05	XPORTLIC
8310180157	8310180147	83/10/13	CONTRACT
8310180161	8310180156	83/07/08	50-298 Q
8310180163	8310180158	83/10/14	50-445 Q
8310180170	8310180165	83/10/13	50-443 Q
8310180175	8310180168	83/10/13	CONTRACT
8310180177	8310180173	83/10/04	50-361 P
8310180183	8310180179	83/08/12	50-445 K
8310180209	8310180204	83/09/27	50-213 Q
8310180211	8310180208	83/10/12	50-333 P
8310180219	8310180214	83/09/29	50-445 Q
8310180223	8310180214	83/09/29	50-445 Q
8310180224	8310180222	83/10/15	50-155 Q
8310180227	8310180218	83/10/03	50-445 Q
8310180228	8310180225	83/09/22	50-298 Q
8310180229	8310180214	83/09/29	50-445 Q
8310180232	8310180225	83/09/22	50-298 Q
8310180237	8310180234	83/10/14	50-352 Q
8310180246	8310180242	83/09/20	50-285 Q
8310180253	8310180251	83/10/12	50-272 K
8310180257	8310180250	83/10/04	50-373 Q
8310180279	8310180275	83/10/14	50-454 Q
8310180299	8310180291	83/10/06	QA999
8310180313	8310180216	83/10/07	QA999
8310180314	8310180312	83/09/30	QA999
8310180318	8310180312	83/09/30	QA999
8310180321	8310180317	83/10/14	50-482 E
8310180322	8310180316	83/10/11	50-334 Q
8310180323	8310180316	83/10/07	QA999
8310180325	8310180317	83/10/14	50-482 E
8310180326	8310180312	83/09/30	QA999
8310180327	8310180324	83/10/13	50-250 P
8310180332	8310180216	83/10/07	QA999
8310180340	8310180216	83/10/07	QA999
8310180341	8310180331	83/10/03	50-397 Q
8310180342	8310180339	83/10/13	50-445 Q
8310180350	8310180346	83/09/30	QA999
8310180351	8310180252	83/10/14	50-456 C
8310180353	8310180346	83/09/30	QA999
8310180356	8310180349	83/10/07	50-387 Q
8310180358	8310180346	83/09/30	QA999
8310180361	8310180354	83/10/14	50-275 T
8310180365	8310180360	83/10/03	QA999
8310180367	8310180362	83/10/14	50-344 Q
8310180369	8310180354	83/10/14	50-275 T
8310180371	8310180360	83/10/03	QA999
8310180372	8310180366	83/10/05	50-289 Q
8310180373	8310180368	83/10/12	50-443 Q
8310180375	8310180354	83/10/14	50-275 T
8310180378	8310180360	83/10/03	QA999
8310180380	8310180377	83/10/07	50-199 Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

568

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8310180383	8310180377	83/10/07	50-199 Q	8310180624	8310180610	83/09/01	50-275 P
8310180386	8310180382	83/10/03	50-5 Q	8310180626	8310180610	83/09/01	50-275 P
8310180398	8310180391	83/10/03	50-272 Q	8310180627	8310180610	83/09/01	50-275 P
8310180400	8310180395	83/09/30	QA999	8310180628	8310180625	83/09/01	50-329 Q
8310180401	8310180396	83/10/06	QA999	8310180629	8310180625	83/09/01	50-329 Q
8310180404	8310180396	83/10/06	QA999	8310180630	8310180625	83/09/01	50-329 A
8310180406	8310180396	83/10/06	QA999	8310190034	8310180625	83/09/01	50-329 A
8310180407	8310180396	83/10/06	QA999	8310190036	8310180625	83/09/01	50-329 A
8310180408	8310180403	83/09/30	50-285 Q	8310190038	8310180625	83/09/01	50-329 A
8310180410	8310180403	83/09/30	50-285 Q	8310190042	8310180625	83/09/01	50-329 A
8310180411	8310180396	83/10/06	QA999	8310190044	8310190040	83/10/12	50-352 Q
8310180414	8310180412	83/09/22	50-498 Q	8310190047	8310180625	83/09/01	50-329 A
8310180415	8310180396	83/10/06	QA999	8310190053	8310190049	83/09/13	FOIA
8310180431	8310180429	83/09/30	QA999	8310190057	8310190043	83/10/14	50-280 P
8310180434	8310180432	83/10/03	50-334 F	8310190105	8310190097	83/10/12	50-29 P
8310180438	8310180435	83/10/14	50-293 F	8310190126	8310190125	83/10/14	50-424 A
8310180442	8310180441	83/09/20	QA999	8310190130	8310190112	83/10/13	50-338 P
8310180445	8310180441	83/09/20	QA999	8310190135	8310190128	83/10/04	50-410 Q
8310180447	8310180439	83/09/28	50-213 Q	8310190136	8310190133	83/10/05	50-443 Q
8310180450	8310180441	83/09/20	QA999	8310190142	8310190133	83/10/05	50-443 Q
8310180453	8310180449	83/10/13	50-397 A	8310190143	8310190139	83/10/04	50-309 Q
8310180455	8310180431	83/09/19	QA999	8310190154	8310190152	83/10/11	50-308 A
8310180459	8310180452	83/10/04	50-155 P	8310190159	8310190139	83/10/04	50-309 Q
8310180465	8310180456	83/10/13	50-329 Q	8310190167	8310190166	83/09/08	50-346 R
8310180472	8310180466	83/09/27	50-445 Q	8310190168	8310190157	83/10/05	50-333 Q
8310180481	8310180480	83/10/14	50-387 P	8310190170	8310190166	83/09/08	50-346 R
8310180483	8310180479	83/10/13	50-293 P	8310190175	8310190172	83/10/05	50-443 Q
8310180484	8310180478	83/10/13	50-445 Q	8310190180	8310190172	83/10/05	50-443 Q
8310180485	8310180480	83/10/14	50-387 P	8310190185	8310190176	83/10/05	50-352 Q
8310180486	8310180477	83/10/07	50-361 S	8310190188	8310190182	83/10/03	50-423 Q
8310180488	8310180478	83/10/13	50-445 Q	8310190203	8310190176	83/10/05	50-352 Q
8310180492	8310180490	83/10/07	50-266 P	8310190208	8310190199	83/09/30	50-327 P
8310180493	8310180480	83/10/14	50-387 P	8310190240	8310190237	83/10/13	71-5595
8310180495	8310180490	83/10/07	50-266 P	8310190251	8310190246	83/10/05	50-334 Q
8310180497	8310180480	83/10/14	50-387 P	8310190270	8310190266	83/09/30	50-454 Q
8310180498	8310180480	83/10/14	50-387 P	8310190281	8310190276	83/09/21	CONTRACT
8310180499	8310180490	83/10/07	50-266 P	8310190288	8310190285	80/09/19	71-9145
8310180501	8310180480	83/10/14	50-387 P	8310190292	8310190291	83/10/14	50-313 F
8310180502	8310180490	83/10/07	50-266 P	8310190295	8310190294	83/10/14	50-313 F
8310180504	8310180480	83/10/14	50-387 P	8310190313	8310190309	83/09/12	FOIA
8310180505	8308300775	83/10/14	50-275 P	8310190326	8310190322	83/09/13	FOIA
8310180506	8310180500	83/10/13	50-283 Q	8310190329	8310190322	83/09/13	FOIA
8310180509	8310180507	83/10/14	50-387 P	8310190344	8310190340	83/09/15	50-282 S
8310180510	8310180507	83/10/14	50-387 P	8310190358	8310190340	83/09/15	50-282 S
8310180511	8308300775	83/10/14	50-275 P	8310190360	8310190340	83/09/15	50-282 S
8310180514	8310180507	83/10/14	50-387 P	8310190361	8310190340	83/09/15	50-282 S
8310180517	8308300775	83/10/14	50-275 P	8310200005	8310200003	83/10/14	50-409 P
8310180518	8310180507	83/10/14	50-387 P	8310200006	8310200003	83/10/14	50-409 P
8310180519	8310180515	83/09/22	QA999	8310200010	8310200007	83/10/03	50-334 Q
8310180520	8310180507	83/10/14	50-387 P	8310200021	8310200007	83/10/03	50-334 Q
8310180521	8308300775	83/10/14	50-275 P	8310200038	8310200032	83/09/15	50-289 P
8310180523	8310180507	83/10/14	50-387 P	8310200042	8310200036	83/10/06	50-412 H
8310180525	8310180507	83/10/14	50-387 P	8310200044	8310200032	83/09/15	50-289 P
8310180527	8310180526	83/09/30	QA999	8310200048	8310200032	83/09/15	50-289 P
8310180528	8310180526	83/09/30	QA999	8310200049	8310200045	83/10/03	50-440 Q
8310180530	8310180526	83/09/30	QA999	8310200053	8310200045	83/10/05	50-440 Q
8310180532	8310180526	83/09/30	QA999	8310200055	8310200051	83/10/13	50-225 P
8310180538	8310180534	83/09/06	50-333 P	8310200057	8310200045	83/10/05	50-440 Q
8310180548	8310180537	83/05/27	50-320 P	8310200068	8310200062	83/10/07	COMMISSION
8310180557	8310180554	83/10/12	CONTRACT	8310200073	8310200062	83/10/07	50-445 U
8310180565	8310180562	83/10/05	XPORTLIC	8310200082	8310200079	83/10/14	50-254 F
8310180570	8310180567	83/09/22	50-346 P	8310200090	8310200088	83/09/30	50-271 Q
8310180572	8310180569	83/10/03	50-298 P	8310200092	8310200088	83/09/30	50-271 Q
8310180575	8310180571	83/09/06	FOIA	8310200103	8310200099	83/10/03	50-317 Q
8310180576	8310180573	83/10/12	CONTRACT	8310200107	8310200099	83/10/03	50-317 Q
8310180580	8310180577	83/10/05	XPORTLIC	8310200148	8310200124	83/10/04	50-10 Q
8310180585	8310180581	83/07/11	CONTRACT	8310200159	8310200159	83/10/05	50-373 A
8310180589	8310180583	83/10/06	50-305 P	8310200168	8310200166	83/10/12	50-324 Q
8310180596	8310180592	83/10/13	CONTRACT	8310200169	8310200163	83/09/30	70-820
8310180598	8310180583	83/10/06	50-305 P	8310200172	8310200162	83/10/13	50-277
8310180602	8310180595	83/09/06	FOIA	8310200181	8310200179	83/09/06	State Prog
8310180605	8310180601	83/09/30	PR	8310200183	8310200180	83/10/14	50-275 Q
8310180606	8310180604	83/10/11	50-424 A	8310200184	8310200178	83/10/16	50-275 Y
8310180607	8310180601	83/09/30	PR	8310200186	8310200182	83/10/17	50-331 P
8310180613	8310180610	83/09/01	50-275 P	8310200190	8310200178	83/10/16	50-275 Y
8310180615	8310180610	83/09/01	50-275 P	8310200192	8310200188	83/10/14	50-344 P
8310180617	8310180610	83/09/01	50-275 P	8310200195	8310200178	83/10/16	50-275 Y
8310180619	8310180610	83/09/01	50-275 P	8310200196	8310200162	83/10/13	50-277 Q
8310180621	8310180610	83/09/01	50-275 P	8310200198	8310200188	83/10/14	50-344 P
8310180623	8310180610	83/09/01	50-275 P	8310200199	8310200193	83/09/30	TOPREP

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8310200200	8310200194	83/10/04	50-397 Q
8310200203	8310200194	83/10/04	50-397 Q
8310200205	8310200201	83/10/11	50-461 K
8310200212	8310200209	83/10/06	50-358 A
8310200214	8310200208	83/10/04	50-206 Q
8310200215	8310200209	83/10/06	50-358 A
8310200222	8310200209	83/10/06	50-358 A
8310200224	8310200220	83/10/14	50-206 Q
8310200227	8310200209	83/10/06	50-358 A
8310200228	8310200220	83/10/14	50-206 Q
8310200230	8310200209	83/10/06	50-358 A
8310200232	8310200220	83/10/14	50-206 Q
8310200233	8310200229	83/10/12	50-336 P
8310200234	8310200209	83/10/06	50-358 A
8310200237	8310200218	83/09/14	50-289 Q
8310200244	8308300777	83/10/17	50-454 Q
8310200245	8310200241	83/10/14	50-317 P
8310200248	8308300777	83/10/17	50-454 Q
8310200250	8310200242	83/10/07	50-123 Q
8310200255	8310200242	83/10/07	50-123 Q
8310200261	8310200257	83/10/13	50-277 R
8310200263	8310200257	83/10/13	50-277 R
8310200264	8310200257	83/10/13	50-277 R
8310200268	8310200242	83/10/07	50-123 Q
8310200270	8310200218	83/09/14	50-289 Q
8310200280	8310200276	83/10/07	50-358 A
8310200323	8310200318	83/10/13	50-311 P
8310200357	8310200356	83/09/23	FOIA
8310200359	8310200356	83/09/23	FOIA
8310200364	8310200356	83/09/23	FOIA
8310200373	8310200371	83/09/30	40-7869
8310200380	8310200375	83/10/06	50-329 A
8310200383	8310200379	83/09/15	FOIA
8310200386	8310200375	83/10/06	50-329 A
8310200387	8310200379	83/09/15	FOIA
8310200391	8310200379	83/09/15	FOIA
8310200392	8310200375	83/10/06	50-329 A
8310200394	8310200379	83/09/15	FOIA
8310200397	8310200395	83/10/07	50-440 A
8310200398	8310200379	83/09/15	FOIA
8310200400	8310200395	83/10/07	50-440 A
8310200401	8310200379	83/09/15	FOIA
8310200404	8310200395	83/10/07	50-440 A
8310200407	8310200395	83/10/07	50-440 A
8310200415	8310200408	83/10/06	71-9184
8310200417	8310200410	83/10/17	50-155 F
8310200423	8310200410	83/10/17	50-155 F
8310200424	8310200416	83/10/17	50-373 F
8310200430	8310200426	83/10/17	50-289 F
8310200443	8310200437	83/10/17	50-320 F
8310200449	8310200442	83/10/07	COMMISSION
8310200455	8310200442	83/10/07	50-424 U
8310200457	8310200442	83/10/07	COMMISSION
8310200459	8310200442	83/10/07	COMMISSION
8310200461	8310200442	83/10/07	COMMISSION
8310200462	8310200458	83/07/12	CONTRACT
8310200463	8310200442	83/10/07	COMMISSION
8310200464	8310200442	83/10/07	COMMISSION
8310200466	8310200442	83/10/07	COMMISSION
8310200467	8310200442	83/10/07	COMMISSION
8310200469	8310200442	83/10/07	50-275 U
8310210001	8310200379	83/09/15	FOIA
8310210013	8310210008	83/09/26	50-285 Q
8310210034	8310210032	83/09/01	50-259 Q
8310210045	8310210043	83/10/13	50-397 Q
8310210048	8310210046	83/10/14	50-261 P
8310210060	8310210055	83/10/04	50-397 Q
8310210061	8310210053	83/10/07	50-10 Q
8310210069	8310210065	83/10/13	50-358 R
8310210070	8310210064	83/10/17	50-324 Q
8310210074	8310210053	83/10/07	50-10 Q
8310210078	8310210071	83/10/17	50-259 Q
8310210087	8310210086	83/10/18	CONTRACT
8310210093	8310210091	83/10/06	CONTRACT
8310210097	8310210083	83/09/30	CONTRACT
8310210100	8310210095	83/09/23	70-2960
8310210107	8310210102	83/09/28	40-8902
8310210109	8310210106	83/10/13	50-424 M
8310210110	8310210105	83/10/17	50-358 Q
8310210113	8310210105	83/10/17	50-358 Q

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8310210119	8310210116	83/09/20	50-302 P
8310210129	8310210126	83/10/07	50-333 F
8310210132	8310210124	83/10/17	50-2 P
8310210142	8310210134	83/10/12	50-329 A
8310210155	8310210150	83/10/17	CONTRACT
8310210163	8310210158	83/10/07	50-186 F
8310210173	8310210168	83/10/14	50-397 A
8310210180	8310210164	83/09/12	CONTRACT
8310210191	8310210187	83/10/12	50-315 S
8310210192	8310210186	83/10/17	50-413 T
8310210194	8310210185	83/10/17	50-309 Q
8310210196	8310210184	83/10/19	50-445 Q
8310210197	8310210187	83/10/12	50-315 S
8310210198	8310210189	83/10/12	CONTRACT
8310210199	8310210187	83/10/12	50-315 S
8310210202	8310210187	83/10/12	50-315 S
8310210208	8310210185	83/10/17	50-309 Q
8310210210	8310210207	83/10/05	50-317 Q
8310210211	8310210205	83/10/05	CONTRACT
8310210212	8310210206	83/10/12	50-316 B
8310210215	8310210206	83/10/12	50-316 B
8310210217	8310210214	83/10/05	50-244 Q
8310210219	8310210204	83/10/18	50-454 Q
8310210220	8310210214	83/10/05	50-244 Q
8310210225	8310210224	83/09/28	50-460 A
8310210229	8310210227	83/10/13	50-275 P
8310210235	8310210233	83/10/14	50-275 R
8310210236	8310210234	83/10/13	50-454 F
8310210239	8310210237	83/10/11	50-148 F
8310210240	8310210238	83/10/11	50-334 P
8310210241	8310210228	83/10/15	50-275 T
8310210242	8310210228	83/10/15	50-275 T
8310210246	8310210245	83/10/14	50-261 P
8310210250	8310210243	83/10/17	50-443 Q
8310210256	8310210254	83/10/07	50-228 Q
8310210261	8310210259	83/10/13	50-348 P
8310210266	8310210265	83/10/07	50-309 Q
8310210268	8310210264	83/10/17	50-324 P
8310210274	8310210269	83/10/03	50-277 Q
8310210275	8310210272	83/10/17	50-329 R
8310210277	8310210270	83/10/17	50-321 P
8310210278	8310210269	83/10/03	50-277 Q
8310210279	8310210270	83/10/17	50-321 P
8310210283	8310210280	83/10/14	50-289 Q
8310210288	8310210284	83/10/14	50-275 R
8310210294	8310210286	83/10/17	50-309 Q
8310210319	8310210316	83/10/05	50-329 Q
8310210333	8310210331	83/09/09	71-9181
8310210344	8310210341	83/09/30	50-328 P
8310210347	8310210341	83/09/30	50-328 P
8310210355	8310210350	83/10/14	50-275 T
8310210357	8310210350	83/10/14	50-275 T
8310210358	8310210350	83/10/14	50-275 T
8310210363	8310210359	83/10/18	50-346 F
8310210370	8310210366	83/10/17	50-285 F
8310210371	8310210350	83/10/14	50-275 T
8310210377	8310210374	83/10/17	50-295 F
8310210378	8310210350	83/10/14	50-275 T
8310210381	8310210350	83/10/14	50-275 T
8310210382	8310210350	83/10/14	50-275 T
8310210383	8310210362	83/10/17	50-259 F
8310210385	8310210350	83/10/14	50-275 T
8310210386	8310210362	83/10/17	50-259 F
8310210387	8310210350	83/10/14	50-275 T
8310210390	8310210384	83/10/17	50-289 F
8310210391	8310210350	83/10/14	50-275 T
8310210392	8310210350	83/10/14	50-275 T
8310210394	8310210389	83/10/17	50-305 F
8310210396	8310210389	83/10/17	50-305 F
8310210398	8310210350	83/10/14	50-275 T
8310210413	8310210412	83/10/17	50-170 F
8310210415	8310210414	83/10/17	50-482 F
8310240002	8310240001	83/10/05	50-301 Q
8310240003	8310240001	83/10/05	50-301 Q
8310240014	8310240012	83/08/10	50-413 T
8310240017	8310240012	83/08/10	50-413 T
8310240018	8310240012	83/08/10	50-413 T
8310240021	8310240012	83/08/10	50-413 T
8310240022	8310240012	83/08/10	50-413 T
8310240024	8310240012	83/08/10	50-413 T

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

567

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8310240030	8310240012	83/08/10	50-413 T	8310240271	8310240267	83/10/05	WASTE MGT
8310240032	8310240012	83/08/10	50-413 T	8310240286	8310240281	83/07/11	FOIA
8310240038	8310240012	83/08/10	50-413 T	8310240302	8310240301	83/10/13	XPORTLIC
8310240040	8310240012	83/08/10	50-413 T	8310240303	8310240299	83/10/18	71-9852
8310240043	8310240012	83/08/10	50-413 T	8310240307	8310240305	83/10/18	71-503
8310240047	8310240012	83/08/10	50-413 T	8310240309	8310240306	83/10/17	XPORTLIC
8310240049	8310240012	83/08/10	50-413 T	8310240319	8310240317	83/10/18	71-504
8310240051	8310240042	83/10/18	50-266 Q	8310280006	8310230005	83/10/06	GA999
8310240053	8310240012	83/08/10	50-413 T	8310280008	8310230005	83/10/06	GA999
8310240055	8310240012	83/08/10	50-413 T	8310280011	8310230010	83/10/20	GA999
8310240056	8310240012	83/08/10	50-413 T	8310250014	8310250009	83/07/01	FOIA
8310240057	8310240012	83/08/10	50-413 T	8310250017	8310250007	83/07/01	FOIA
8310240058	8310240012	83/08/10	50-413 T	8310250018	8310250013	83/07/01	FOIA
8310240059	8310240012	83/08/10	50-413 T	8310250019	8310250009	83/07/01	FOIA
8310240060	8310240012	83/08/10	50-413 T	8310250021	8310250013	83/10/17	TOPREP
8310240061	8310240012	83/08/10	50-413 T	8310250024	8310250007	83/07/01	FOIA
8310240062	8310240012	83/08/10	50-413 T	8310250025	8310250007	83/07/01	FOIA
8310240065	8310240012	83/08/10	50-413 T	8310250030	8310250028	83/07/15	FOIA
8310240068	8310240012	83/08/10	50-413 T	8310250076	8310250074	83/10/14	50-367 S
8310240073	8310240012	83/08/10	50-413 T	8310250080	8310250074	83/10/14	50-367 S
8310240076	8310240012	83/08/10	50-413 T	8310250093	8310250088	83/10/19	50-397 A
8310240077	8310240069	83/10/19	50-456 Q	8310250097	8310250088	83/10/19	50-397 A
8310240081	8310240066	83/10/19	50-546 Q	8310250107	8310250102	83/10/07	WASTE MGT
8310240085	8310240082	83/10/07	70-1100	8310250119	8310250116	83/10/19	State Prog
8310240091	8310240087	83/10/07	50-295 Q	8310250127	8310250123	83/09/21	GA999
8310240093	8310240090	83/09/12	40-8681	8310250128	8310250124	83/10/17	50-206 P
8310240096	8310240087	83/10/07	50-295 Q	8310250130	8310250123	83/09/21	GA999
8310240098	8310240097	83/10/12	CONTRACT	8310250136	8310250123	83/09/21	GA999
8310240100	8310240093	83/10/05	50-315 Q	8310250138	8310250131	83/10/07	50-259 Q
8310240102	8310240086	83/10/05	50-282 Q	8310250148	8310250140	83/10/13	GA999
8310240106	8310240104	83/10/19	CONTRACT	8310250152	8310250147	83/09/16	ORG
8310240108	8310240103	83/10/07	50-336 P	8310250170	8310250166	83/10/04	50-259 Q
8310240109	8310240103	83/10/07	50-336 P	8310250174	8310250166	83/10/04	50-259 Q
8310240113	8310240103	83/10/07	50-336 P	8310250179	8310250166	83/10/04	50-259 Q
8310240115	8310240110	83/10/04	50-225 Q	8310250182	8310250176	83/10/20	50-275 T
8310240122	8310240116	83/10/05	50-266 P	8310250185	8310250166	83/10/04	50-259 Q
8310240125	8310240116	83/10/05	50-266 P	8310250190	8310250166	83/10/04	50-259 Q
8310240130	8310240127	83/10/19	CONTRACT	8310250193	8310250191	83/10/20	50-255 Q
8310240132	8310240128	83/10/19	50-155 Q	8310250195	8310250188	83/10/21	50-237 P
8310240137	8310240121	83/10/04	50-440 Q	8310250197	8310250191	83/10/20	50-255 Q
8310240141	8310240139	83/10/12	50-259 F	8310250200	8310250180	83/10/21	50-237 P
8310240144	8310240138	83/10/05	50-324 F	8310250201	8310250197	83/10/07	GA999
8310240145	8310240143	83/10/17	50-354 F	8310250203	8310250191	83/10/20	50-255 Q
8310240152	8310240149	83/10/05	50-263 P	8310250206	8310250197	83/10/07	GA999
8310240173	8310240171	83/07/06	FOIA	8310250211	8310250208	83/10/13	50-400 Q
8310240175	8310240171	83/07/06	FOIA	8310250216	8310250214	83/10/04	50-416 Q
8310240176	8310240171	83/07/06	FOIA	8310250230	8310250225	83/10/06	50-413 Q
8310240177	8310240178	83/09/30	50-546 A	8310250235	8310250226	83/10/11	50-346 P
8310240181	8310240171	83/07/06	FOIA	8310250236	8310250231	83/09/22	50-537 Q
8310240182	8310240178	83/09/30	50-546 A	8310250240	8310250234	83/10/07	50-259 Q
8310240185	8310240171	83/07/06	FOIA	8310250241	8310250226	83/10/11	50-346 P
8310240194	8310240193	83/07/01	FOIA	8310250247	8310250234	83/10/07	50-259 Q
8310240195	8310240193	83/07/01	FOIA	8310250251	8310250234	83/10/07	50-259 Q
8310240199	8310240197	83/09/08	50-528 Q	8310250252	8310250246	83/10/20	50-387 P
8310240201	8310240197	83/09/08	50-528 A	8310250256	8310250248	83/09/27	50-269 Q
8310240203	8310240197	83/09/08	50-528 A	8310250258	8310250246	83/10/20	50-387 P
8310240207	8310240197	83/09/08	FOIA	8310250259	8310250234	83/10/07	50-259 Q
8310240209	8310240197	83/09/08	FOIA	8310250267	8310250265	83/10/06	GA999
8310240212	8310240197	83/09/08	50-528 Q	8310250268	8310250262	83/08/26	50-416 Q
8310240215	8310240197	83/09/08	50-528 Q	8310250269	8310250262	83/08/26	50-416 Q
8310240217	8310240197	83/09/08	50-528 U	8310250270	8310250265	83/10/06	GA999
8310240218	8310240197	83/09/08	50-528 Q	8310250271	8310250262	83/08/26	50-416 Q
8310240219	8310240197	83/09/08	50-528 A	8310250278	8310250275	83/10/20	50-282 Q
8310240220	8310240197	83/09/08	50-528 A	8310250284	8310250275	83/10/20	50-282 Q
8310240221	8310240197	83/09/08	50-528 Q	8310250288	8310250275	83/10/20	50-282 Q
8310240222	8310240197	83/09/08	50-528 Q	8310250292	8310250289	83/10/18	50-352 P
8310240223	8310240197	83/09/08	50-528 Q	8310250298	8310250293	83/10/21	50-254 P
8310240227	8310240197	83/09/08	50-528 Q	8310250300	8310250299	83/09/28	50-327 Q
8310240236	8310240197	83/09/08	50-528 A	8310250302	8310250293	83/10/21	50-254 P
8310240238	8310240234	83/07/08	FOIA	8310250304	8310250303	83/09/29	50-390 Q
8310240239	8310240197	83/09/08	50-528 Q	8310250306	8310250301	83/10/19	50-438 Q
8310240241	8310240197	83/09/08	50-528 Q	8310250313	8310250301	83/10/19	50-438 Q
8310240246	8310240197	83/09/08	50-528 U	8310250318	8310250301	83/10/19	50-438 Q
8310240249	8310240245	83/10/14	50-413 A	8310250324	8310250301	83/10/19	50-438 Q
8310240250	8310240248	83/10/04	70-1143	8310250328	8310250320	83/09/23	50-280 Q
8310240251	8310240197	83/09/08	50-528 Q	8310250329	8310250322	83/08/31	50-261 Q
8310240259	8310240257	83/10/13	71-5450	8310250332	8310250326	83/10/19	50-278 T
8310240261	8310240258	83/10/14	50-250 P	8310250333	8310250301	83/10/19	50-438 Q
8310240264	8310240258	83/10/14	50-250 P	8310250339	8310250322	83/08/31	50-261 Q
8310240268	8310240263	83/07/11	FOIA	8310250340	8310250336	83/10/06	70-143

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8310250344	8310250336	83/10/04	70-143	8310250549	8310250544	83/10/11	50-293 K
8310250347	8310250336	83/10/04	70-143	8310250550	8310250538	83/10/20	50-263 Q
8310250348	8308310029	83/10/18	50-275 P	8310250551	8310250545	83/10/18	50-498 Q
8310250351	8308310029	83/10/18	50-275 P	8310250554	8310250547	83/09/26	70-1113
8310250352	8310250336	83/10/06	70-143	8310250558	8310250545	83/10/18	50-498 Q
8310250359	8310250357	83/10/20	GA999	8310250560	8310250519	83/09/19	50-321 Q
8310250361	8310250356	83/10/20	50-373 Q	8310250561	8310250538	83/10/20	50-263 Q
8310250363	8310250354	83/10/05	50-269 Q	8310250569	8310250563	83/10/06	50-327 Q
8310250364	8310250342	83/10/17	50-352 Q	8310250570	8310250566	83/10/18	50-409 P
8310250368	8310250362	83/09/23	GA999	8310250578	8310250565	83/09/21	50-324 Q
8310250374	8310250350	83/10/13	50-302 Q	8310250582	8310250575	83/10/21	70-2977
8310250380	8310250373	83/10/03	50-438 Q	8310250586	8310250576	83/10/21	50-358 Q
8310250381	8310250375	83/10/13	50-322 T	8310250596	8310250588	83/10/17	50-261 Q
8310250384	8310250375	83/10/13	50-322 T	8310250600	8310250591	83/09/16	50-312 P
8310250385	8310250377	83/10/06	GA999	8310250601	8310250588	83/10/17	50-261 Q
8310250387	8310250376	83/09/19	50-348 Q	8310250602	8310250593	83/10/19	50-327 Q
8310250392	8310250383	83/09/30	50-413 Q	8310250603	8310250597	83/10/04	50-193 Q
8310250394	8310250388	83/09/20	50-280 Q	8310250604	8310250592	83/10/12	GA999
8310250399	8310250395	83/10/07	GA999	8310250608	8310250588	83/10/17	50-261 Q
8310250401	8310250391	83/10/21	50-315 F	8310250610	8310250592	83/10/12	GA999
8310250404	8310250398	83/09/26	50-413 Q	8310250611	8310250593	83/10/19	50-327 Q
8310250406	8310250397	83/10/04	50-390 Q	8310250613	8310250605	83/10/18	50-254 Q
8310250408	8310250405	83/10/12	GA999	8310250616	8310250592	83/10/12	GA999
8310250409	8310250400	83/10/05	50-335 Q	8310250617	8310250593	83/10/19	50-327 Q
8310250420	8310250413	83/10/12	GA999	8310250618	8310250588	83/10/17	50-261 Q
8310250423	8310250416	83/09/16	50-275 Q	8310250620	8310250588	83/10/17	50-261 Q
8310250424	8310250417	83/09/15	50-313 Q	8310250621	8310250615	83/09/27	50-355 Q
8310250428	8310250414	83/10/05	50-338 Q	8310250624	8310250593	83/10/19	50-327 Q
8310250431	8310250426	83/10/11	50-250 Q	8310250625	8310250591	83/09/16	50-312 P
8310250435	8310250432	83/10/06	GA999	8310250627	8310250588	83/10/17	50-261 Q
8310250436	8310250403	83/10/05	50-327 Q	8310250631	8310250591	83/09/16	50-312 P
8310250437	8310250426	83/10/11	50-250 Q	8310250632	8310250628	83/10/05	50-400 Q
8310250438	8310250429	83/10/04	50-280 Q	8310250642	8310250636	83/09/30	50-461 Q
8310250441	8310250432	83/10/06	GA999	8310250646	8310250635	83/10/17	50-269 Q
8310250442	8310250426	83/10/11	50-250 Q	8310250652	8310250635	83/10/17	50-269 Q
8310250445	8310250440	83/10/18	70-820	8310250661	8310250656	83/10/20	50-483 F
8310250446	8310250426	83/10/11	50-250 Q	8310250664	8310250656	83/10/20	50-483 F
8310250447	8310250432	83/10/06	GA999	8310250665	8310250635	83/10/17	50-269 Q
8310250449	8310250426	83/10/11	50-250 Q	8310250667	8310250660	83/10/20	50-285 F
8310250452	8310250439	83/09/21	50-416 Q	8310250669	8310250668	83/10/27	50-331 F
8310250454	8310250403	83/10/05	50-327 Q	8310250670	8310250668	83/10/27	50-331 F
8310250457	8310250451	83/10/17	50-324 Q	8310250682	8310250681	83/10/14	50-244 P
8310250460	8310250451	83/10/17	50-324 Q	8310250683	8310250673	83/10/21	50-59 F
8310250464	8310250459	83/09/22	50-280 Q	8310260006	8310260003	83/09/26	40-2259
8310250466	8310250403	83/10/05	50-327 Q	8310260021	8310260019	83/07/15	FOIA
8310250468	8310250451	83/10/17	50-324 Q	8310260073	8310260019	83/07/15	FOIA
8310250473	8310250451	83/10/17	50-324 Q	8310260025	8310260019	83/07/15	FOIA
8310250477	8310250451	83/10/17	50-324 Q	8310260026	8310260019	83/07/15	FOIA
8310250479	8310250472	83/10/06	50-348 Q	8310260027	8310260008	83/06/23	50-270 B
8310250480	8310250474	83/10/11	50-324 Q	8310260028	8310260019	83/07/15	FOIA
8310250484	8310250475	83/10/03	50-327 Q	8310260030	8310260019	83/07/15	FOIA
8310250485	8310250472	83/10/06	50-348 Q	8310260031	8310260008	83/06/23	FOIA
8310250488	8310250474	83/10/11	50-324 Q	8310260032	8310260019	83/07/15	FOIA
8310250490	8310250472	83/10/06	50-348 Q	8310260033	8310260019	83/07/15	FOIA
8310250492	8310250403	83/10/05	50-327 Q	8310260034	8310260008	83/06/23	FOIA
8310250493	8310250474	83/10/11	50-324 Q	8310260035	8310260019	83/07/15	FOIA
8310250494	8310250475	83/10/03	50-327 Q	8310260037	8310260008	83/06/23	FOIA
8310250498	8310250472	83/10/06	50-348 Q	8310260038	8310260019	83/07/15	FOIA
8310250501	8310250474	83/10/11	50-324 Q	8310260040	8310260019	83/07/15	FOIA
8310250502	8310250475	83/10/03	50-327 Q	8310260041	8310260008	83/06/23	FOIA
8310250504	8310250486	83/10/17	50-454 Q	8310260042	8310260036	83/10/05	XPORTLIC
8310250507	8310250499	83/10/19	50-329 A	8310260043	8310260019	83/07/15	FOIA
8310250509	8310250475	83/10/03	50-327 Q	8310260044	8310260019	83/07/15	FOIA
8310250510	8310250503	83/10/12	GA999	8310260047	8310260019	83/07/15	FOIA
8310250515	8310250503	83/10/12	GA999	8310260048	8310260019	83/07/15	FOIA
8310250517	8310250475	83/10/03	50-327 Q	8310260049	8310260008	83/06/23	FOIA
8310250518	8310250511	83/10/06	GA999	8310260050	8310260008	83/06/23	FOIA
8310250520	8310250513	83/10/18	50-454 Q	8310260051	8310260019	83/07/15	FOIA
8310250524	8310250514	83/10/07	50-369 Q	8310260052	8310260019	83/07/15	FOIA
8310250525	8310250503	83/10/12	GA999	8310260053	8310260008	83/06/23	FOIA
8310250526	8310250511	83/10/06	GA999	8310260054	8310260045	83/09/22	70-1143
8310250528	8310250516	83/10/06	50-335 Q	8310260055	8310260019	83/07/15	FOIA
8310250529	8310250512	83/10/04	50-272 Q	8310260056	8310260019	83/07/15	FOIA
8310250530	8310250514	83/10/07	50-369 Q	8310260058	8310260008	83/06/23	FOIA
8310250534	8310250514	83/10/07	50-369 Q	8310260059	8310260019	83/07/15	FOIA
8310250535	8310250522	83/10/20	50-155 Q	8310260061	8310260008	83/06/23	FOIA
8310250540	8310250514	83/10/07	50-369 Q	8310260062	8310260019	83/07/15	FOIA
8310250541	8310250537	83/06/13	GA999	8310260065	8310260019	83/07/15	FOIA
8310250542	8310250538	83/10/20	50-263 Q	8310260066	8310260008	83/06/23	FOIA
8310250548	8310250522	83/10/20	50-155 Q	8310260067	8310260019	83/07/15	FOIA

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

569

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8310260069	8310260008	83/06/23	FOIA	8310260173	8310260019	83/07/15	FOIA
8310260070	8310260019	83/07/15	FOIA	8310260174	8310260019	83/07/15	FOIA
8310260071	8310260008	83/06/23	FOIA	8310260175	8310260019	83/07/15	FOIA
8310260072	8310260019	83/07/15	FOIA	8310260176	8310260019	83/07/15	FOIA
8310260073	8310260068	83/10/06	XPORTL IC	8310260177	8310260019	83/07/15	FOIA
8310260075	8310260008	83/06/23	FOIA	8310260178	8310260019	83/07/15	FOIA
8310260076	8310260019	83/07/15	FOIA	8310260179	8310260154	83/10/12	70-27
8310260077	8310260019	83/07/15	FOIA	8310260180	8310260019	83/07/15	FOIA
8310260078	8310260008	83/06/23	FOIA	8310260182	8310260019	83/07/15	FOIA
8310260080	8310260008	83/06/23	FOIA	8310260183	8310260019	83/07/15	FOIA
8310260081	8310260019	83/07/15	FOIA	8310260184	8310260019	83/07/15	FOIA
8310260082	8310260008	83/06/23	FOIA	8310260185	8310260019	83/07/15	FOIA
8310260083	8310260074	83/09/30	WASTE MOT	8310260188	8310260019	83/07/15	FOIA
8310260084	8310260019	83/07/15	FOIA	8310260191	8310260019	83/07/15	FOIA
8310260085	8310260008	83/06/23	FOIA	8310260193	8310260019	83/07/15	FOIA
8310260086	8310260008	83/06/23	FOIA	8310260194	8310260190	83/10/05	70-1113
8310260087	8310260019	83/07/15	FOIA	8310260195	8310260019	83/07/15	FOIA
8310260089	8310260008	83/06/23	FOIA	8310260197	8310260019	83/07/15	FOIA
8310260090	8310260019	83/07/15	FOIA	8310260199	8310260019	83/07/15	FOIA
8310260091	8310260008	83/06/23	FOIA	8310260201	8310260187	83/10/17	50-443 A
8310260092	8310260008	83/06/23	FOIA	8310260204	8310260019	83/07/15	FOIA
8310260093	8310260019	83/07/15	FOIA	8310260207	8310260019	83/07/15	FOIA
8310260095	8310260019	83/07/15	FOIA	8310260208	8310260187	83/10/17	50-443 A
8310260096	8310260008	83/06/23	50-10 B	8310260209	8310260202	83/10/21	50-400 Q
8310260099	8310260019	83/07/15	FOIA	8310260210	8310260019	83/07/15	FOIA
8310260100	8310260019	83/07/15	FOIA	8310260211	8310260206	83/10/04	50-447 K
8310260102	8310260019	83/07/15	FOIA	8310260213	8310260019	83/07/15	FOIA
8310260103	8310260008	83/06/23	FOIA	8310260218	8310260019	83/07/15	FOIA
8310260105	8310260019	83/07/15	FOIA	8310260221	8310260215	83/10/05	70-1113
8310260107	8310260019	83/07/15	FOIA	8310260223	8310260019	83/07/15	FOIA
8310260108	8310260019	83/07/15	FOIA	8310260226	8310260019	83/07/15	FOIA
8310260111	8310260019	83/07/15	FOIA	8310260229	8310260019	83/07/15	FOIA
8310260112	8310260019	83/07/15	FOIA	8310260234	8310260019	83/07/15	FOIA
8310260114	8310260104	83/10/12	70-1151	8310260238	8310260019	83/07/15	FOIA
8310260115	8310260019	83/07/15	FOIA	8310260239	8310260212	83/10/19	50-277 P
8310260116	8310260019	83/07/15	FOIA	8310260240	8310260019	83/07/15	FOIA
8310260119	8310260019	83/07/15	70-1144	8310260242	8310260237	83/10/14	50-344 P
8310260120	8310260019	83/07/15	FOIA	8310260243	8310260019	83/07/15	FOIA
8310260121	8310260019	83/07/15	FOIA	8310260246	8310260237	83/10/14	50-344 P
8310260122	8310260113	83/10/17	50-397 A	8310260250	8310260019	83/07/15	70-1144
8310260124	8310260019	83/07/15	FOIA	8310260252	8310260019	83/07/15	FOIA
8310260125	8310260019	83/07/15	FOIA	8310260258	8310260019	83/07/15	FOIA
8310260126	8310260019	83/07/15	FOIA	8310260261	8310260254	83/10/24	50-443 Q
8310260127	8310260019	83/07/15	FOIA	8310260264	8310260260	83/10/14	50-275 R
8310260128	8310260019	83/07/15	70-1144	8310260265	8310260019	83/07/15	70-1144
8310260129	8310260019	83/07/15	FOIA	8310260266	8310260254	83/10/24	50-443 Q
8310260130	8310260019	83/07/15	FOIA	8310260267	8310260259	83/10/14	50-400 E
8310260131	8310260019	83/07/15	FOIA	8310260271	8310260019	83/07/15	FOIA
8310260132	8310260019	83/07/15	FOIA	8310260272	8310260254	83/10/24	50-443 Q
8310260133	8310260019	83/07/15	FOIA	8310260275	8310260019	83/07/15	FOIA
8310260135	8310260019	83/07/15	FOIA	8310260278	8310260019	83/07/15	FOIA
8310260136	8310260019	83/07/15	FOIA	8310260280	8310260019	83/07/15	FOIA
8310260137	8310260019	83/07/15	FOIA	8310260281	8310260279	83/08/26	50-443 A
8310260138	8310260019	83/07/15	FOIA	8310260282	8310260019	83/07/15	FOIA
8310260139	8310260019	83/07/15	FOIA	8310260283	8310260259	83/10/14	50-400 E
8310260140	8310260019	83/07/15	FOIA	8310260284	8310260279	83/08/26	50-445 A
8310260142	8310260019	83/07/15	FOIA	8310260285	8308310032	83/10/24	50-329 A
8310260144	8310260019	83/07/15	FOIA	8310260286	8310260279	83/08/26	50-445 A
8310260145	8310260141	83/10/20	50-324 P	8310260287	8310260019	83/07/15	70-1144
8310260146	8310260019	83/07/15	70-1144	8310260288	8310260019	83/07/15	FOIA
8310260148	8310260141	83/10/20	50-324 P	8310260295	8310260019	83/07/15	FOIA
8310260149	8310260019	83/07/15	70-1144	8310260296	8310260290	83/10/19	CONTRACT
8310260153	8310260019	83/07/15	FOIA	8310260298	8310260019	83/07/15	FOIA
8310260155	8310260019	83/07/15	FOIA	8310260300	8310260019	83/07/15	FOIA
8310260157	8310260019	83/07/15	FOIA	8310260303	8310260019	83/07/15	FOIA
8310260158	8310260019	83/07/15	FOIA	8310260307	8310260297	83/10/05	70-1113
8310260159	8310260019	83/07/15	FOIA	8310260308	8310260306	83/10/24	50-289 Q
8310260160	8310260156	83/10/13	50-328 A	8310260317	8310260019	83/07/15	FOIA
8310260161	8310260019	83/07/15	FOIA	8310260321	8310260019	83/07/15	FOIA
8310260162	8310260019	83/07/15	FOIA	8310260325	8310260019	83/07/15	FOIA
8310260163	8310260019	83/07/15	FOIA	8310260327	8310260019	83/07/15	FOIA
8310260164	8310260019	83/07/15	FOIA	8310260329	8310260019	83/07/15	FOIA
8310260165	8310260019	83/07/15	70-1144	8310260332	8310260019	83/07/15	FOIA
8310260166	8310260154	83/10/12	70-27	8310260335	8310260331	83/10/19	50-329 A
8310260167	8310260019	83/07/15	FOIA	8310260337	8310260019	83/07/15	FOIA
8310260168	8310260019	83/07/15	FOIA	8310260338	8310260019	83/07/15	FOIA
8310260169	8310260019	83/07/15	FOIA	8310260339	8310260334	83/10/14	50-289 P
8310260170	8310260019	83/07/15	FOIA	8310260340	8310260331	83/10/19	50-329 A
8310260171	8310260019	83/07/15	FOIA	8310260341	8310260019	83/07/15	FOIA
8310260172	8310260019	83/07/15	FOIA	8310260342	8310260334	83/10/14	50-289 P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8310260344	8310260331	83/10/19	50-329 A	8310270174	8310270074	83/10/11	FOIA
8310260345	8310260019	83/07/15	FOIA	8310270176	8310270165	83/10/21	50-329 Q
8310260347	8310260019	83/07/15	FOIA	8310270177	8310270074	83/10/11	FOIA
8310260351	8310260019	83/07/15	FOIA	8310270178	8310270164	83/10/13	70-371
8310260352	8310260348	83/09/27	40-6659	8310270182	8310270074	83/10/11	FOIA
8310260354	8310260019	83/07/15	FOIA	8310270186	8310270074	83/10/11	FOIA
8310260356	8310260019	83/07/15	FOIA	8310270189	8310270074	83/10/11	FOIA
8310260359	8310260019	83/07/15	FOIA	8310270194	8310270184	83/10/07	50-29 Q
8310260361	8310260019	83/07/15	FOIA	8310270196	8310270190	83/10/24	50-315 F
8310260366	8310260019	83/07/15	FOIA	8310270206	8310270200	83/08/08	50-309
8310260372	8310260019	83/07/15	FOIA	8310270212	8310270207	83/10/18	50-220 Q
8310260374	8310260019	83/07/15	FOIA	8310270213	8310270204	83/10/18	50-315 S
8310260375	8310260371	83/10/13	CONTRACT	8310270216	8310270200	83/08/08	50-309
8310260378	8310260019	83/07/15	FOIA	8310270217	8310270207	83/10/18	50-220 Q
8310260384	8310260019	83/07/15	FOIA	8310270221	8310270219	83/10/24	50-155 P
8310260388	8310260019	83/07/15	FOIA	8310270223	8310270204	83/10/18	50-315 S
8310260394	8310260019	83/07/15	FOIA	8310270230	8310270225	83/10/20	50-273 Q
8310260418	8310260414	83/09/29	40-8783	8310270243	8310270232	83/10/13	50-57 P
8310260432	8310260428	83/10/21	50-280 F	8310270246	8310270237	83/10/21	50-329 Q
8310260433	8310260431	83/10/21	50-263 F	8310270271	8310270204	83/10/18	50-315 S
8310260436	8310260428	83/10/21	50-280 F	8310270286	8310270281	83/07/18	FOIA
8310260438	8310260431	83/10/21	50-263 F	8310270295	8310270291	83/10/11	50-134 Q
8310270015	8310270005	83/10/27	50-331 F	8310270303	8310270294	83/10/14	50-266 Q
8310270017	8310270009	83/10/21	50-10 F	8310270313	8310270294	83/10/14	50-266 Q
8310270019	8310270005	83/10/27	50-331 F	8310270324	8310270304	83/10/03	50-289 Q
8310270021	8310270018	83/10/21	50-213 F	8310270334	8310270327	83/10/20	50-366 P
8310270023	8310270012	83/10/20	50-321 Q	8310270348	8310270338	83/10/17	50-275 Q
8310270028	8310270024	83/10/21	50-254 F	8310270352	8310270341	83/10/21	50-329 Q
8310270032	8310270024	83/10/21	50-254 F	8310270354	8310270347	83/09/29	50-263 S
8310270041	8310270040	83/07/06	50-320 P	8310270356	8310270268	83/10/24	50-352 Q
8310270042	8310270039	83/10/20	50-309 F	8310270359	8310270347	83/09/29	50-263 S
8310270044	8310270040	83/07/06	50-320 P	8310270361	8310270358	83/10/25	50-275 Q
8310270045	8310270040	83/07/06	FOIA	8310270362	8310270268	83/10/24	50-352 Q
8310270050	8310270038	83/10/03	TOPREP	8310270364	8310270347	83/09/29	50-263 S
8310270053	8310270049	83/10/27	50-389 F	8310270368	8310270268	83/10/24	50-352 Q
8310270055	8310270038	83/10/03	TOPREP	8310270377	8310270338	83/10/17	50-275 Q
8310270058	8310270052	83/10/11	50-334 Q	8310270378	8310270374	83/10/21	50-348 P
8310270067	8310270049	83/10/27	50-389 F	8310270380	8310270347	83/09/29	50-266 S
8310270075	8310270071	83/07/14	FOIA	8310270390	8310270347	83/09/29	50-263 S
8310270080	8310270074	83/10/11	FOIA	8310270395	8310270393	83/10/21	50-289 F
8310270084	8310270074	83/10/11	FOIA	8310270410	8310270347	83/09/29	50-263 S
8310270086	8310270076	83/10/20	50-244 F	8310270414	8310270347	83/09/29	50-263 S
8310270092	8310270074	83/10/11	FOIA	8310270415	8310270347	83/09/29	50-282 S
8310270094	8310270076	83/10/20	50-244 F	8310270418	8310270347	83/09/29	50-282 S
8310270097	8310270074	83/10/11	FOIA	8310270421	8310270347	83/09/29	50-282 S
8310270100	8310270074	83/10/11	FOIA	8310270423	8310270422	83/10/14	50-440 Q
8310270105	8310270074	83/10/11	FOIA	8310270425	8310270347	83/09/29	50-282 S
8310270107	8310270104	83/07/19	FOIA	8310270426	8310270422	83/10/14	50-440 Q
8310270108	8310270061	83/10/18	50-364 S	8310270427	8310270347	83/09/29	50-282 S
8310270109	8310270074	83/10/11	FOIA	8310270429	8310270347	83/09/29	50-306 S
8310270110	8310270104	83/07/19	FOIA	8310270440	8310270438	83/10/13	50-305 Q
8310270113	8310270074	83/10/11	FOIA	8310270450	8310270446	83/10/14	50-255 Q
8310270115	8310270061	83/10/18	50-364 S	8310270453	8310270449	83/10/24	50-387 P
8310270116	8310270074	83/10/11	FOIA	8310270457	8310270449	83/10/24	50-387 P
8310270122	8310270074	83/10/11	FOIA	8310270462	8310270445	83/10/13	50-443 Q
8310270125	8310270119	83/10/21	50-289 F	8310270470	8310270468	83/10/04	FOIA
8310270127	8310270074	83/10/11	FOIA	8310270474	8310270445	83/10/13	50-443 Q
8310270133	8310270074	83/10/11	FOIA	8310270485	8310270481	83/10/21	50-317 F
8310270134	8310270128	83/10/11	50-454 Q	8310270505	8310270501	83/07/28	FOIA
8310270136	8310270026	83/10/20	50-369 F	8310270510	8310270491	83/10/21	50-155 F
8310270138	8310270132	83/07/15	FOIA	8310270521	8310270518	83/10/21	50-344 F
8310270139	8310270074	83/10/11	FOIA	8310270524	8310270519	83/09/27	40-8698
8310270140	8310270128	83/10/11	50-454 Q	8310270534	8310270532	83/10/21	50-29 F
8310270144	8310270074	83/10/11	FOIA	8310270537	8310270526	83/10/21	50-10 F
8310270145	8310270132	83/07/15	FOIA	8310270547	8310270541	83/07/22	50-277 S
8310270146	8310270024	83/10/20	50-369 F	8310270569	8310270552	83/10/21	50-461 F
8310270147	8310270074	83/10/11	FOIA	8310270572	8310270566	83/10/25	50-275 F
8310270149	8310270143	83/10/25	50-244 Q	8310270574	8310270552	83/10/21	50-461 F
8310270151	8310270074	83/10/11	FOIA	8310270575	8310270566	83/10/25	50-275 F
8310270153	8310270129	83/10/14	50-250 P	8310270577	8310270567	83/10/21	CONTRACT
8310270156	8310270074	83/10/11	FOIA	8310270580	8310270566	83/10/25	50-275 F
8310270157	8310270141	83/09/30	40-8781	8310270585	8310270581	83/10/06	50-220 Q
8310270158	8310270135	83/10/21	50-219 Q	8310270586	8310270582	83/10/25	50-275 F
8310270159	8310270074	83/10/11	FOIA	8310270588	8310270582	83/10/25	50-275 F
8310270161	8310270129	83/10/14	50-250 P	8310270593	8310270590	83/10/25	50-155 F
8310270163	8310270074	83/10/11	FOIA	8310270597	8310270590	83/10/25	50-155 F
8310270168	8310270074	83/10/11	FOIA	8310270598	8310270594	83/10/21	TOPREP
8310270169	8310270164	83/10/13	70-371	8310270606	8310270594	83/10/19	CONTRACT
8310270170	8310270074	83/10/11	FOIA	8310270639	8310270635	83/10/03	40-672
8310270171	8310270165	83/10/21	50-329 Q	8310270644	8310270635	83/10/03	40-672

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

571

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8310270647	8310270635	83/10/03	40-672	8310280322	8310280321	83/09/06	40-1341
8310270652	8310270635	83/10/03	40-672	8310310032	8310310027	83/10/25	50-261 P
8310270656	8310270635	83/10/03	40-672	8310310046	8310310043	83/10/26	50-333 P
8310280006	8310280002	83/10/20	50-382	8310310056	8310310031	83/07/06	50-298 P
8310280017	8310280007	83/10/10	TOPREP	8310310058	8310310031	83/07/06	50-333 P
8310280019	8310280014	83/10/21	50-400 E	8310310061	8310310031	83/07/06	50-271 P
8310280020	8310280016	83/10/21	50-142 T	8310310064	8310310031	83/07/06	50-278 P
8310280027	8310280022	83/10/24	50-327 P	8310310065	8310310062	83/10/26	50-412 K
8310280033	8310280024	83/10/13	XPORTLIC	8310310067	8310310031	83/07/06	50-250 P
8310280040	8310280021	83/10/24	50-327 P	8310310068	8310310031	83/07/06	50-250 P
8310280048	8310280036	83/10/21	50-275 Q	8310310070	8310310031	83/07/06	50-250 P
8310280054	8310280044	83/10/24	50-333 F	8310310072	8310310031	83/07/06	50-245 P
8310280067	8310280060	83/10/21	50-275 Q	8310310073	8310310031	83/07/06	50-244 P
8310280068	8310280062	83/10/19	CONTRACT	8310310076	8310310031	83/07/06	50-244 P
8310280078	8310280073	83/10/28	50-329 Q	8310310077	8310310031	83/07/06	50-315 P
8310280092	8310280085	83/10/14	50-348 P	8310310080	8310310031	83/07/06	50-316 P
8310280104	8310280074	83/10/20	CONTRACT	8310310116	8310310097	83/09/19	FOIA
8310280107	8310280103	83/09/21	WASTE MGT	8310310130	8310310126	83/10/24	50-416 Q
8310280110	8310280106	83/10/24	PROJ	8310310131	8310310097	83/09/19	50-289 P
8310280114	8310280085	83/10/14	50-348 P	8310310133	8310310128	83/10/20	50-322 Q
8310280115	8310280108	83/10/21	50-289 P	8310310136	8310310097	83/09/19	FOIA
8310280116	8310280111	83/09/19	WASTE MGT	8310310140	8310310097	83/09/19	FOIA
8310280122	8310280119	83/10/20	50-311 Q	8310310151	8310310149	83/10/21	50-508 A
8310280132	8310280079	83/07/28	FOIA	8310310154	8310310149	83/10/21	50-508 A
8310280134	8310280128	83/10/27	50-409 P	8310310163	8310310158	83/10/25	50-409 Q
8310280136	8310280079	83/07/28	50-344 S	8310310164	8310310161	83/10/25	50-320 Q
8310280137	8310280133	83/10/25	CONTRACT	8310310176	8310310173	83/10/12	50-282 Q
8310280138	8310280079	83/07/28	50-344 S	8310310177	8310310173	83/10/12	50-282 Q
8310280142	8310280140	83/10/12	50-334 F	8310310184	8310310181	83/10/27	50-275 Q
8310280146	8310280144	83/10/25	50-322 U	8310310214	8310310213	83/10/19	50-320 P
8310280149	8310280148	83/10/19	50-259 P	8310310224	8310310222	83/10/25	50-322 Q
8310280150	8310280148	83/10/19	50-259 P	8310310229	8310310223	83/09/21	50-311 Q
8310280151	8310280148	83/10/19	50-259 P	8310310230	8310310227	83/10/13	50-317 Q
8310280163	8310280161	83/10/27	50-409 P	8310310238	8310310229	83/10/24	50-410 C
8310280167	8310280165	83/09/21	40-299	8310310241	8310310239	83/10/14	50-27 Q
8310280168	8310280079	83/07/28	50-266 S	8310310243	8310310228	83/10/24	50-410 K
8310280170	8310280165	83/09/21	40-299	8310310249	8310310233	83/10/17	50-73 Q
8310280171	8310280079	83/07/28	50-266 S	8310310251	8310310246	83/10/14	50-275 Q
8310280175	8310280165	83/09/21	40-299	8310310264	8310310256	83/10/07	50-445 Q
8310280177	8310280165	83/09/21	40-299	8310310281	8310310274	83/10/26	50-275 Q
8310280178	8310280165	83/09/21	40-299	8310310286	8310310279	83/10/14	50-298 Q
8310280179	8310280172	83/10/14	50-289 P	8310310287	8310310282	83/10/20	70-1100
8310280193	8310280176	83/09/23	50-400 Q	8310310293	8310310289	83/10/12	50-461 Q
8310280197	8310280176	83/09/23	50-400 A	8310310301	8310310299	83/10/17	50-344 P
8310280199	8310280189	83/10/18	50-458 A	8310310302	8310310294	83/10/18	50-267 Q
8310280202	8310280176	83/09/23	50-400 A	8310310304	8310310296	83/10/13	50-312 Q
8310280207	8310280176	83/09/23	50-400 A	8310310312	8310310309	83/10/27	50-412 F
8310280209	8310280191	83/10/26	50-10 F	8310310333	8310310325	83/10/18	50-305 Q
8310280211	8310280176	83/09/23	50-400 A	8310310341	8310310332	83/10/13	50-275 Q
8310280214	8310280176	83/09/23	50-400 A	8310310343	8310310338	83/10/13	50-410 Q
8310280215	8310280204	83/10/25	50-373 F	8310310346	8310310332	83/10/13	50-275 Q
8310280218	8310280176	83/09/23	50-400 A	8310310347	8310310342	83/10/26	50-341 Q
8310280220	8310280212	83/08/24	50-358 Q	8310310353	8310310336	83/10/21	50-352 Q
8310280222	8310280176	83/09/23	50-400 A	8310310354	8310310332	83/10/13	50-275 Q
8310280224	8310280212	83/08/24	50-358 A	8310310357	8310310332	83/10/13	50-139 Q
8310280225	8310280176	83/09/23	50-400 A	8310310362	8310310356	83/10/26	40-2061
8310280229	8310280212	83/08/24	50-358 A	8310310371	8310310336	83/10/21	50-352 Q
8310280231	8310280212	83/08/24	50-358 A	8310310379	8310310376	83/10/25	50-155 P
8310280236	8310280176	83/09/23	50-400 A	8310310380	8310310375	83/07/19	40-8084
8310280238	8310280176	83/09/23	50-400 A	8310310383	8310310376	83/10/25	50-155 P
8310280242	8310280176	83/09/23	50-400 A	8310310388	8310310384	83/08/10	50-267 P
8310280244	8310280176	83/09/23	50-400 A	8310310393	8310310384	83/08/10	50-267 P
8310280246	8310280176	83/09/23	50-400 A	8310310398	8310310396	83/10/13	50-528 Q
8310280248	8310280176	83/09/23	50-400 A	8310310400	8310310397	83/10/17	50-409 Q
8310280250	8310280176	83/09/23	50-400 A	8310310405	8310310401	83/10/12	50-312 Q
8310280254	8310280176	83/09/23	50-400 A	8310310407	8310310397	83/10/17	50-409 Q
8310280256	8310280176	83/09/23	50-400 A	8310310408	8310310402	83/10/05	50-382 Q
8310280257	8310280252	83/10/25	50-277 F	8310310413	8310310410	83/10/21	50-289 P
8310280259	8310280176	83/09/23	50-400 A	8310310417	8310310411	83/10/17	50-329 Q
8310280261	8310280253	83/10/25	50-3 F	8310310418	8310310414	83/10/25	70-2430
8310280263	8310280176	83/09/23	50-400 A	8310310425	8310310419	83/10/25	70-2319
8310280265	8310280176	83/09/23	50-400 A	8310310430	8310310428	83/10/14	71-9086
8310280267	8310280253	83/10/25	50-3 F	8310310435	8310310433	83/10/13	50-267 P
8310280270	8310280176	83/09/23	50-400 A	8310310438	8310310429	83/10/24	50-327 P
8310280271	8310280252	83/10/25	50-277 F	8310310440	8310310439	83/10/14	50-321 P
8310280295	8310280283	83/10/13	WASTE MGT	8310310454	8308310050	83/10/14	50-322 S
8310280299	8310280176	83/09/23	50-400 A				
8310280303	8310280176	83/09/23	50-400 A				
8310280313	8310280311	83/10/25	50-213 F				
8310280314	8310280307	83/10/25	50-10 F				

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are

1. Application for construction permit.
2. General Information submitted with construction permit application
3. Amendments and changes to items 1 and 2.
4. NRC questions, requests for additional information, and applicant responses.
5. Correspondence and documents relating to unresolved design and construction issues.
6. Meeting announcements and summaries of meeting discussions on issues of item 5.
7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
9. Construction Permit, amendments, and correspondence relating to the construction permit.
10. Scheduling of license application submission or review.
11. Environmental review information.
12. Application for operating license.
13. General Information submitted with operating license application.
14. Amendments and changes to items 12 and 13.
15. Correspondence regarding the Final Safety Analysis Report (FSAR).
16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
17. Reports of site visits.
18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
2. Amendments and changes to the PSAR.

3. Transmittal and acknowledgement letters.
4. Certificates of service to the PSAR

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

1. Environmental Report (ER) submitted by the utility.
2. Amendments and supplements to the ER.
3. Transmittal and acknowledgement letters.
4. Information on scheduling of submittal or review of ER.
5. NRC questions, requests for additional information, and applicant responses.
6. Federal register notices citing the availability of items 1 and 2.
7. Correspondence relating to the review of ER.
8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
2. Supplements to the DES and FES.
3. Correspondence relating to the DES and FES.
4. Comments from other federal, state and local government agencies.
5. Transmittal and acknowledgement letters.
6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
7. Backup technical documents submitted in connection with above
8. Federal register notice citing availability of items 1 and 2.
9. Site visits to obtain information for DES or FES.
10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
2. Supplements to SER.
3. Correspondence relating to SER.
4. Federal register notices citing availability of items 1 and 2.
5. Information on scheduling of SER submittals and review.
6. Requests for additional information for use in preparing SER; responses to such requests.
7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

1. Fire Hazard Protection Plan and surveys.
2. Plant evacuation correspondence.
3. Safeguards Contingency Plans.
4. Review of Health Physics Program.
5. Correspondence relating to aforementioned plans.
6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
2. Federal register notices regarding hearings.
3. Requests to make appearances at hearings.
4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
6. Correspondence to and from intervenors.
7. Board orders and decisions.
8. Petitions for Commission action.
9. Legal filings and Commission orders and decisions resulting from item 8.

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

1. Change of address notifications.
2. Changes in structure of organization.
3. Changes in service lists.
4. NRC requests to applicant for additional copies of documents.
5. Correspondence from the public requesting information about the facility and NRC responses.
6. Correspondence on strictly administrative matters.
7. Letters of support, concern or opposition to the facility.
8. Correspondence regarding the Local Public Document Rooms (LPDRs).
9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

1. Company annual reports.
2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

1. Indemnity agreements and amendments.
2. Endorsements insurance policies.
3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
2. Amendments and changes to the FSAR.
3. Federal register notices citing availability of items 1 and 2.
4. Transmittal and acknowledgement letters.
5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

1. Limited Work Authorizations (LWA) and amendments.
2. Correspondence pertaining to work performed under LWA s.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review"
2. Correspondence where the primary topic of discussion is antitrust matters.
3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
2. Correspondence from ACRS.
3. Announcement of ACRS meetings.
4. Transmittal and acknowledgement letters.
5. ACRS reports.
6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
7. Minutes at ACRS Subcommittee Meetings

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

1. Operating license, amendments, proposed amendments, changes
2. Technical specifications and changes.

3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2
4. Federal register notices citing availability of items 1 and 2.
5. Correspondence regarding the Final Safety Analysis Report (FSAR)
6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
8. Information on the Standard Review Plan (STP)
9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
11. Owner's group meeting announcements and reports.
12. Quality assurance information.
13. Environmental matters (technical).
14. Emergency core cooling system documents.
15. Radioactive waste information.
16. Correspondence regarding expansion of spent fuel storage pool.
17. Start-up test reports.
18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

1. Inspection reports.
2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
3. Responses by applicant to IE correspondence.
4. Applicant's determination of proprietary nature of inspection reports.
5. Letters concerning areas of noncompliance.
6. Pre-service and in-service inspections and procedures.
7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (ENs).
8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature

- 1 Monthly, semiannual, or annual operating reports (other than financial).
- 2 Periodic environmental monitoring, effluent testing, or similar reports
- 3 Periodic personnel exposure reports
- 4 Operational Logbooks
 - Logbooks on Environmental Data
 - Logbooks on Radiological Data
 - Operations Log on Plant Systems Core
 - Plant Status Summary Sheets
- 5 Correspondence or other documents relating to the above listed items

S REPORTABLE OCCURRENCES, PNOs, PNSs, AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

1. All 24-hour, 10-day, 30-day interim and final Licensee Event Reports (LERs) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences)
2. Potential or possible reportable deficiency reports and related correspondence.
3. Personnel exposure reports
4. Construction deficiency reports submitted under 10 CFR 50.55e.
5. Preliminary Notification of Occurrence (PNOs) and Preliminary Notification of Safeguards Events (PNs)
6. Environmental Technical Specifications violation reports and Environmental Event reports
7. Part 21 Reports of defects and noncompliance
8. Correspondence or other documents relating to items 1-7

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
2. Testimony and statements submitted to ASLB and ASLAB
3. Commission meeting transcripts
4. NRC staff briefings to the Commission.
5. Statements and written testimony submitted at Commission meeting or hearings.
6. Transcripts of utility briefs to NRC staff.
7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.
8. Corrections to above items.

U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
2. Preparatory and backup documents for item 1.
3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

1. Operator licenses or administrative information bearing on licensing of operators.
2. NRC examination results.
3. Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

1. Application for authority to voluntarily surrender license.
2. Application to dismantle the facility and dispose of component parts.
3. Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
4. Documents relating to disposal of radioactive material and decontamination of the site.
5. Other correspondence relating to above items.
6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

Y. INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS (ISFSI)

This category contains documents with an NMSS license and/or a Docket-72 number. For installations on a reactor site, the associated Docket-50 number will also be identified.

1. License applications, licenses, amendments and proposed amendments to possess power reactor spent fuel and other radioactive materials associated with spent storage in an independent spent fuel storage installation. (Such spent fuel storage installations may be on a reactor site or at a separate site.)
2. All related correspondence and reports to the above.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR – Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes

1. Sunshine Act Federal Register notices.
2. Full, written explanation of closed meetings.
3. Certification of General Counsel on closed meetings.
4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings

ACRS – Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
2. ACRS meeting announcements; description of meeting agendas.
3. ACRS-generated reports, memoranda and correspondence that are publicly available
4. ACRS consultant reports, comments and related correspondence.
5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

ADVCM – NRC Advisory Committees

This category contains documentation pertaining to the responsibilities of all NRC advisory committees, other than the Advisory Committee on Reactor Safeguards. The documents in this category are:

1. Charters of each advisory committee.
2. Verbatim transcripts of committee meetings.

3. Meeting announcements; description of meeting agendas.
4. Committee generated reports, memoranda, and correspondence that are publicly available.
5. Committee related correspondence.

COMMISSION – NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.
2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners
3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT – NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
2. Solicitations (RFP or IFB) issued by the NRC.
3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
4. Contractual documents and contract modifications, if any.

DISCLOSURE – Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA – Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year-numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS – Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

1. Draft reports of action plans to accomplish generic tasks in the regulatory program
2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.
3. Meeting notifications and minutes
4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E – Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs)

1. I&E Circulars, which describe an event at a licensed facility and are informational in nature
2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC – Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG – NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions
 - b. They present the results of Commission licensing and policy decisions
 - c. They present the results of technical research conducted for the Commission
2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation
3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG – Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR – Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
2. Text of the Proposed Rule (PR).
3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM – Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
2. Federal Register cause notices of the filing of the petition.

3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ -- Projects--Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities, and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

A. Application/Construction Stage

1. Application submitted by the utility.
2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
3. Applicant's Quality Assurance Manual.
4. Early site review information.
5. Backup technical documents submitted in support of the application.
6. Early site visits.

B. Utility PSAR and Amendments

1. PSARs submitted by the utility.
2. Amendments and changes to the PSAR.
3. Transmittal letters.
4. Letters acknowledging receipt of the PSAR.

G. Adjudicatory Correspondence

1. Motions, briefs, orders, *et al.* pertaining to pre-hearing conferences, if any.

M. Antitrust Correspondence

1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

1. Inspection reports of the applicant's quality assurance program.
2. Notices of deviations.
3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 — Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include.

1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
3. NRC inspection reports of defects cited.
4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 — Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
2. Notices of deviations.
3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD — Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
2. Revised or newly issued Regulatory Guides.
3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES — Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

1. Project description documents.
2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
3. Pre-test prediction reports.
4. "Quick look" reports.
5. Informal experimental data reports and post-irradiation examination analyses.
6. Conceptual design descriptions.
7. Letter reports of foreign travel and site visits by contractors.
8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP — NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

1. Agendas for quarterly review group meetings.
2. Summary minutes of review group meetings representing views expressed, including dissenting views.
3. Research plans and predicted results of major experiments; presentations by research contractors.
4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
5. Internal memoranda relating to topics under discussion.

RM -- Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include

1. Designations of the presiding officer and any special directions for the conduct of the hearing.
2. Notifications of hearing board meetings.
3. Petitions, motions, testimony and statements submitted by parties to the hearings.
4. Hearing board orders and rulings.
5. Technical reports submitted as evidence in the proceeding.
6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY -- Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
2. Consent Calendar items and Policy Session items.

NOTE. For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG -- State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding,
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting
3. State Legislative Reports.
4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP – Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
2. Revisions, modifications and amendments to topical reports.
3. Correspondence between NRC and vendors pertaining to the review of submittals.
4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT – Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC – Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
3. Commission letters requesting Executive Branch views.
4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
5. Correspondence from foreign governments, international organizations, and members of the public.
6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
7. Filings pursuant to hearing requests or intervention petitions, if any.
8. Hearing records and decisions.
9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE. For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

NRC FORM 335 U.S. NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET		1 REPORT NUMBER (Assigned by DDC) NUREG-0540 Vol. 5, No. 10	
4 TITLE AND SUBTITLE (Add Volume No., if appropriate) Title List of Documents Made Publicly Available October 1-31, 1983		2 (Leave blank) 3 RECIPIENT'S ACCESSION NO	
7. AUTHOR(S)		5. DATE REPORT COMPLETED MONTH YEAR	
9. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code) Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, DC 20555		DATE REPORT ISSUED MONTH YEAR December 1983	
12 SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code) Same as 9, above.		6 (Leave blank) 8 (Leave blank)	
		10 PROJECT/TASK/WORK UNIT NO 11 FIN NO	
13. TYPE OF REPORT Monthly		PERIOD COVERED (Inclusive dates) October 1-31, 1983	
15 SUPPLEMENTARY NOTES		14 (Leave blank)	
16 ABSTRACT (200 words or less)			

This document is a monthly publication containing descriptions of information received and generated by the U.S. NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials, and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The following indexes are included: Personal Author Index, Corporate Source Index, Report Number Index, and Cross Reference to Principal Documents Index.

17. KEY WORDS AND DOCUMENT ANALYSIS		17a DESCRIPTORS	
17b IDENTIFIERS/OPEN-ENDED TERMS			
18 AVAILABILITY STATEMENT Unlimited		19 SECURITY CLASS (This report) Unclassified	21 NO OF PAGES
		20 SECURITY CLASS (This page) Unclassified	22 PRICE \$